



Status Report

560 - CITATION ULTRA

S/N 560-0347 N50LQ

OWNER: PREMIER AIR, INC.

ADDRESS: 2580 SE AVIATION WAY
STUART FL 34996

OFFICE: 561-847-5130

FAX:

OPERATOR: PREMIER AIR, INC.

ADDRESS: 2580 SE AVIATION WAY
STUART FL 34996

OFFICE: 561-847-5130

FAX:

ANALYST: DAMOND POLLOCK

EMAIL: DPOLLOCK@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)

316-462-2442 (FAX)

WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)

631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT **SERIAL/REGNO:** 560-0347/N50LQ **MODEL:** 560 - CITATION ULTRA **MANUFACTURER:** TEXTRON AVIATION INC.

CERTIFICATION DATE: 11-MAR-1996

LAST ACTUALS:

5409.2 A/C HRS as of 27-APR-2023

4636 AFL as of 27-APR-2023

407.1 ACH as of 12-DEC-2022

ENGINE NO. 1 **SERIAL/PART:** PCE-500183/3051700 **MODEL:** JT15D-5D **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 11-MAR-1996

12 ENG. HRS 12 A/C HRS
ENC

LAST ACTUALS:

5299.4 ENG. HRS as of 30-DEC-2022

4459 ENC as of 30-DEC-2022

ENGINE NO. 2 **SERIAL/PART:** PCE-500179/3051700 **MODEL:** JT15D-5D **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 11-MAR-1996

12 ENG. HRS 12 A/C HRS
ENC

LAST ACTUALS:

5312.2 ENG. HRS as of 27-APR-2023

4468 ENC as of 27-APR-2023



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 00 - INFORMATION										
007267 ^U		INSPECT GVI RIGHT HAND NOSE BAGGAGE CLOSEOUT PANEL AND COMPONENTS FROM ICA DOC NO. CERTCDOC-007267							Service	ATA:00
	MOS	20-Apr-23	48		30-Apr-27		1464 d	ICA		
	HRS	5396.4								
	AFL	4627								
ATA 01 - LIMITATIONS										
010992 ^U		EDDY CURRENT GPS ANTENNA CONNECTOR HOLE & FASTENER HOLES ICA UNS-1							Service	ATA:01
	MOS							ICA		
	HRS									
	AFL	0	T:10922 (+50/-50)		10922	10972	6286 (+50)			
ATA 02 - RESERVED FOR AIRLINE USE										
029667 ^U		EDDY CURRENT BULKHEAD FEED-THRU CONNECTOR HOLE ICA UNS-1							Service	ATA:02
	MOS							ICA		
	HRS									
	AFL	0	T:29667 (+50/-50)		29667	29717	25031 (+50)			
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
050102 ^U		MONTHLY EMERGENCY EQUIPMENT VISUAL INSPECTION							Service	ATA:05
	MOS	20-Apr-23	1		31-May-23		34 d			
	HRS	5396.4								
	AFL	4627								
051204		NO. 1 ENGINE - MINOR INSPECTION							Package	ATA:05
	MOS	02-Feb-23	24 (+2m)		28-Feb-25	30-Apr-25	673 d (+61)			
	HRS	5299.4	300 (+30)		(5599.4) 5709.2	5629.4	300 (+30)			
	ENC	4459								
					PROC. REF: MM 72-00-00					
051204		NO. 2 ENGINE - MINOR INSPECTION							Package	ATA:05
	MOS	08-Jun-22	24 (+2m)		30-Jun-24	31-Aug-24	430 d (+62)			
	HRS	5132.6	300 (+30)		(5432.6) 5529.6	5462.6	120.4 (+30)			
	ENC	4334								
					PROC. REF: MM 72-00-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
053445 ^U		LEVEL 2 SELF-TEST (KGP-860)							Service	ATA:05
	MOS	12-Dec-22	12		31-Dec-23		248 d			
	HRS	5341.7	100		5441.7		32.5			
	AFL	4588								
053446 ^U		LEVEL 3 SELF-TEST (KGP-860)							Service	ATA:05
	MOS	12-Dec-22	12		31-Dec-23		248 d			
	HRS	5341.7	100		5441.7		32.5			
	AFL	4588								
055013		EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK							Service	ATA:05
	MOS/MSC	11-Mar-96	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: TLMC 5-50-00, TLMC 5-50-00										
055601 ^U		INSPECT LEFT WINDSHIELD INSPECTION							Service	ATA:05
	MOS	08-Jun-22	24		30-Jun-24		430 d			
	HRS	5229.6	300		5529.6		120.4			
	AFL	4502								
055604 ^U		INSPECT LEFT COCKPIT SIDE WINDOW INSPECTION							Service	ATA:05
	MOS	08-Jun-22	24		30-Jun-24		430 d			
	HRS	5229.6	300		5529.6		120.4			
	AFL	4502								
055604 ^U		INSPECT RIGHT COCKPIT SIDE WINDOW INSPECTION							Service	ATA:05
	MOS	08-Jun-22	24		30-Jun-24		430 d			
	HRS	5229.6	300		5529.6		120.4			
	AFL	4502								
5-12-01		PHASE 1							Package	ATA:05
	MOS	08-Jun-22	24 (+2m)		30-Jun-24	31-Aug-24	430 d (+62)			
	HRS	5229.6	300 (+30)		5529.6	5559.6	120.4 (+30)			
	AFL	4502								
PROC. REF: TLMC 5-12-01										
										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-02	PHASE 2									Package ATA:05
	MOS	08-Jun-22	24 (+2m)		30-Jun-24	31-Aug-24	430 d (+62)			
	HRS	5229.6	300 (+30)		5529.6	5559.6	120.4 (+30)			
	AFL	4502								
PROC. REF: TLMC 5-12-02										PKG:2
5-12-03	PHASE 3									Package ATA:05
	MOS	08-Jun-22	24 (+2m)		30-Jun-24	31-Aug-24	430 d (+62)			
	HRS	5229.6	300 (+30)		5529.6	5559.6	120.4 (+30)			
	AFL	4502								
PROC. REF: TLMC 5-12-03										PKG:3
5-12-04	PHASE 4									Package ATA:05
	MOS	08-Jun-22	24 (+2m)		30-Jun-24	31-Aug-24	430 d (+62)			
	HRS	5229.6	300 (+30)		5529.6	5559.6	120.4 (+30)			
	AFL	4502								
PROC. REF: TLMC 5-12-04										PKG:4
5-12-05	PHASE 5									Package ATA:05
	MOS	24-May-21	36 (+2m)		31-May-24	31-Jul-24	400 d (+61)			
	HRS	5149.5	1200 (+100)		6349.5	6449.5	940.3 (+100)			
	AFL	4442								
PROC. REF: TLMC 5-12-05										PKG:7
5-12-0B	PHASE B									Package ATA:05
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)		5546.4	5576.4	137.2 (+30)			
	AFL	4627								
PROC. REF: TLMC 5-12-0B										PKG:15
5-12-11	PHASE 11									Package ATA:05
	MOS	20-Apr-23	6 (+1m)		31-Oct-23	30-Nov-23	187 d (+30)			
	HRS	5396.4								
	AFL	4627								
PROC. REF: TLMC 5-12-11										PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-13		PHASE 13								Package ATA:05
	MOS	16-Jan-18								
	HRS	4985.7	5000 (+10)		9985.7	9995.7	4576.5 (+10)			
	AFL	4323								
					PROC. REF: TLMC 5-12-13					PKG:17
5-12-14		PHASE 14								Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:12000 (+10)		12000	12010	6590.8 (+10)			
	AFL	0								
					PROC. REF: TLMC 5-12-14					PKG:18
5-12-15		PHASE 15								Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:10000 (+10)		10000	10010	4590.8 (+10)			
	AFL	0								
					PROC. REF: TLMC 5-12-15					PKG:19
5-12-16		PHASE 16								Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:10000 (+10)		10000	10010	4590.8 (+10)			
	AFL	0								
					PROC. REF: TLMC 5-12-16					PKG:20
5-12-17		PHASE 17								Package ATA:05
	MOS	11-Mar-96								
	HRS	0	10000 (+10)		10000	10010	4590.8 (+10)			
	AFL	0								
					PROC. REF: TLMC 5-12-17					PKG:21
5-12-18		PHASE 18								Package ATA:05
	MOS	08-Jun-22	12 (+1m)		30-Jun-23	31-Jul-23	64 d (+31)			
	HRS	5229.6								
	AFL	4502								
					PROC. REF: TLMC 5-12-18					PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-20 ^S		PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								Package ATA:05
	MOS	22-Dec-21	24							
	HRS	5180								
	AFL	4468								
PROC. REF: TLMC 5-12-20										PKG:24
5-12-21 ^S		PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								Package ATA:05
	MOS	22-Dec-21	24 (+1m)							
	HRS	5180								
	AFL	4468								
PROC. REF: TLMC 5-12-21										PKG:35
5-12-28 ^S		PHASE 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								Package ATA:05
	MOS	24-May-21	12 (+1m)							
	HRS	5149.5	100 (+10)							
	AFL	4442								
PROC. REF: TLMC 5-12-28										PKG:44
5-12-30		PHASE 30								Package ATA:05
	MOS	29-Dec-22								
	HRS	5391.7	600 (+10)		5991.7	6001.7	582.5 (+10)			
	AFL	4624								
PROC. REF: TLMC 5-12-30										PKG:45
5-12-32		PHASE 32								Package ATA:05
	MOS	11-Mar-96								
	HRS	0								
	AFL	0	T:15000		15000		10364			
PROC. REF: TLMC 5-12-32										PKG:46
5-12-33		PHASE 33								Package ATA:05
	MOS	11-Mar-96								
	HRS	0								
	AFL	0	T:15000		15000		10364			
PROC. REF: TLMC 5-12-33										PKG:47

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-34	PHASE 34									Package ATA:05
	MOS	11-Mar-96								
	HRS	0	6725 (+10)		6725	6735	1315.8 (+10)			
	AFL	0								
PROC. REF: TLMC 5-12-34										PKG:48
5-12-48 ^S	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									Package ATA:05
	MOS	11-Mar-96	72							
	HRS	0								
	AFL	0								
PROC. REF: TLMC 5-12-48										PKG:54
5-12-49	PHASE 49									Package ATA:05
	MOS	22-Dec-21	36 (+2m)		31-Dec-24	28-Feb-25	614 d (+59)			
	HRS	5180	1200 (+100)		6380	6480	970.8 (+100)			
	AFL	4468								
PROC. REF: TLMC 5-12-49										PKG:57
5-12-54	PHASE 54									Package ATA:05
	MOS/MSC	30-Sep-15	N/A							
	HRS	4804.6								
	AFL	4218								
PROC. REF: TLMC 5-12-54										PKG:62
5-12-55	PHASE 55 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									Package ATA:05
	MOS	05-Oct-22	T:18 (+1m)		30-Apr-24	31-May-24	369 d (+31)			
	HRS	5243.1	T:1800 (+50/-50)		7043.1	7093.1	1633.9 (+50)			
	AFL	4518								
PROC. REF: TLMC 5-12-55										PKG:64
5-12-56	PHASE 56									Package ATA:05
	MOS	20-Apr-23	12		30-Apr-24		369 d			
	HRS	5396.4								
	AFL	4627								
PROC. REF: TLMC 5-12-56										PKG:65

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									Package ATA:05
	MOS/MSC	11-Mar-96	A/R							
	HRS	0								
	AFL	0								
PROC. REF: TLMC 5-12-59										PKG:112
5-12-61	PHASE 61									Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:13200 (+10)		13200	13210	7790.8 (+10)			
	AFL	0								
PROC. REF: TLMC 5-12-61										PKG:246
5-12-62	PHASE 62									Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:15600 (+10)		15600	15610	10190.8 (+10)			
	AFL	0								
PROC. REF: TLMC 5-12-62										PKG:247
5-12-63	PHASE 63									Package ATA:05
	MOS	11-Mar-96								
	HRS	0	T:15600 (+10)		15600	15610	10190.8 (+10)			
	AFL	0								
PROC. REF: TLMC 5-12-63										PKG:248
5-12-64	PHASE 64									Package ATA:05
	MOS	20-Apr-23	6 (+1m)		31-Oct-23	30-Nov-23	187 d (+30)			
	HRS	5396.4								
	AFL	4627								
PROC. REF: TLMC 5-12-64										PKG:503
5-12-65	PHASE 65									Package ATA:05
	MOS	EFF								
	HRS									
	AFL									
	ACH	EFF	500		733 *		325.9			
PROC. REF: TLMC 5-12-65										PKG:501

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-66		PHASE 66								Package ATA:05
	MOS	EFF								
	HRS	EFF	6000 (+10)		6000 *	6010	590.8 (+10)			
	AFL									
					PROC. REF: TLMC 5-12-66					PKG:502
5-12-67		PHASE 67								Package ATA:05
	MOS	EFF								
	HRS	EFF	T:10000 (+10)		10000 * (M)	10010	4590.8 (+10)			
	AFL									
					PROC. REF: TLMC 5-12-67					PKG:504
5-12-68		PHASE 68								Package ATA:05
	MOS	EFF								
	HRS	EFF	1200 (+10)		6285.5 *	6295.5	876.3 (+10)			
	AFL	EFF								
					PROC. REF: TLMC 5-12-68					PKG:505
5-12-MC		PHASE MC								Package ATA:05
	MOS	16-Feb-14						AIRWORTHINESS		
	HRS	4624.7	1456		6080.7		671.5			
	AFL	4085								
					PROC. REF: TLMC 5-12-MC					PKG:70
5-12-MD		PHASE MD								Package ATA:05
	MOS	15-Jan-13								
	HRS	4248.3	2523		6771.3		1362.1			
	AFL	3834								
					PROC. REF: TLMC 5-12-MD					PKG:71
5-12-ME		PHASE ME								Package ATA:05
	MOS	17-Jul-02						AIRWORTHINESS		
	HRS	1740	4450		6190		780.8			
	AFL									
					PROC. REF: TLMC 5-12-ME					PKG:72

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
5-12-MF		PHASE MF							Package	ATA:05
	MOS	17-Jul-02						AIRWORTHINESS		
	HRS	1740	5000		6740		1330.8			
	AFL									
PROC. REF: TLMC 5-12-MF										PKG:73
5-12-MG ^S		PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)							Package	ATA:05
	MOS	11-Mar-96						AIRWORTHINESS		
	HRS	0								
	AFL	0	T:10000							
PROC. REF: TLMC 5-12-MG										PKG:74
5-12-MI		PHASE MI							Package	ATA:05
	MOS	03-Feb-09						AIRWORTHINESS		
	HRS	3186	5130		8316		2906.8			
	AFL									
PROC. REF: TLMC 5-12-MI										PKG:76
5-12-MJ		PHASE MJ							Package	ATA:05
	MOS	11-Mar-96						AIRWORTHINESS		
	HRS	0	5900		5900		490.8			
	AFL	0								
PROC. REF: TLMC 5-12-MJ										PKG:77
5-12-MK		PHASE MK							Package	ATA:05
	MOS	11-Mar-96						AIRWORTHINESS		
	HRS	0	6725		6725		1315.8			
	AFL	0								
PROC. REF: TLMC 5-12-MK										PKG:78
5-12-ML		PHASE ML							Package	ATA:05
	MOS	21-Nov-22								
	HRS	5281.3	300		5581.3		172.1			
	AFL	4547								
PROC. REF: TLMC 5-12-ML										PKG:249

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
A361103 ^S	VISUAL INSPECTION PRECOOLER/HEAT EXCHANGER (AIRPLANES -0539 AND ON)									Service ATA:05
	MOS/MSC	30-Sep-15	N/A							
	HRS	4804.6								
	AFL	4218								
PROC. REF: AMM 36-11-05										PKG:62
ATA 08 - LEVELING AND WEIGHING										
081251	WEIGHT AND BALANCE EMPTY AIRCRAFT									Service ATA:08
	MOS	19-Sep-22	36	TAC 0	30-Sep-25		887 d			
	HRS			TAC 0						
WC#: 08.010	AFL			TAC 0						
PROC. REF: GENERIC NO REF										
ATA 11 - PLACARDS AND MARKINGS										
A113001 ^S	INSPECT INTERIOR PLACARDS, EXTERIOR PLACARDS, DECALS, MARKINGS AND IDENTIFICATION PLATE									Service ATA:11
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 11.010	AFL	4442								
PROC. REF: AMM 11-00-00										PKG:7,101

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 12 - SERVICING										
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH									Service ATA:12
	DAYS/MSC	11-Mar-96	A/R	TAC 0				OPERATOR REQUEST		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 12-26-00										
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH									Service ATA:12
	DAYS/MSC	11-Mar-96	A/R	TAC 0				OPERATOR REQUEST		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 12-26-00										
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH									Service ATA:12
	DAYS/MSC	11-Mar-96	A/R	TAC 0				OPERATOR REQUEST		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 12-26-00										
120000 ^U	SERVICE CHECK									Service ATA:12
	DAYS	20-Apr-23	15 (+15/-15)		05-May-23	20-May-23	8 d (+15)			
	HRS	5396.4								
	AFL	4627								
C122100 ^S	LUBRICATE NOSE GEAR TORQUE LINKS AND UPLOCK ROLLERS									Service ATA:12
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 12.005	AFL	4502								
PROC. REF: AMM 12-21-02										PKG:2
C122101 ^S	LUBRICATE MAIN LANDING GEAR									Service ATA:12
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 12.005	AFL	4502								
PROC. REF: AMM 12-21-02										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 14 - HARDWARE										
140903 ^U		INSPECT GVI ADS-B WIRING / CABLES / RACKS / CONNECTORS FROM ICA REPORT NO. DB1409003							Service	ATA:14
	MOS	20-Apr-23	60		30-Apr-28		1830 d	ICA		
	HRS	5396.4								
	AFL	4627								
ATA 21 - AIR CONDITIONING										
211002		EMERGENCY PRESSURE VALVE							Component	ATA:21
PN:27441482-06	MOS/MSC	11-Mar-96	O/C							
SN:8AL41	HRS	0		TSN 0						
WC#: 21.020	AFL	0		TSN 0						
PROC. REF: AMM 21-11-00										
211004		S243 PRIMARY PRESSURE SWITCH							Component	ATA:21
PN:1103P240-1	MOS/MSC	11-Mar-96	O/C							
SN:817	HRS	0		TSN 0						
WC#: 21.010	AFL	0		TSN 0						
PROC. REF: AMM 21-11-00										
211005		S244 SECONDARY PRESSURE SWITCH							Component	ATA:21
PN:1103P240-2	MOS/MSC	11-Mar-96	O/C							
SN:797	HRS	0		TSN 0						
WC#: 21.010	AFL	0		TSN 0						
PROC. REF: AMM 21-11-00										
212001		INSTRUMENT PANEL FAN							Component	ATA:21
PN:4124X	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.040	AFL	0		TSN 0						
PROC. REF: AMM 21-24-00										
212002		AVIONICS BAY COOLING BOX FAN							Component	ATA:21
PN:032105	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.050	AFL	0		TSN 0						
PROC. REF: AMM 21-25-01										
212004		OVERHEAD CABIN FAN							Component	ATA:21
PN:BC61A901-2	MOS	07-Nov-14								
SN:3025A	HRS	4711.9	1000	TSO 0	5711.9		302.7			
WC#: 21.060	AFL	4146								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
212006	COCKPIT DEFOGGER FAN									Component ATA:21
PN:5703-4	MOS	06-Aug-09						REPLACE/OVERHAUL		
SN:0520	HRS	3290	T:3500	TSO 0	6790		1380.8			
WC#: 21.070	AFL									
PROC. REF: GENERIC NO REF										
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR									Component ATA:21
PN:NYLC50466	MOS/MSC	11-Mar-96	O/C							
SN:1293	HRS	0		TSN 0						
WC#: 21.030	AFL	0		TSN 0						
PROC. REF: AMM 21-21-01										
212010	AVIONICS BAY VANE AXIAL BLOWER									Component ATA:21
PN:19A827	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.050	AFL	0		TSN 0						
PROC. REF: AMM 21-25-00										
212011	TEMP DUCT SENSOR									Component ATA:21
PN:27221274	MOS/MSC	11-Mar-96	O/C							
SN:6AL101	HRS	0		TSN 0						
WC#: 21.450	AFL	0		TSN 0						
PROC. REF: AMM 21-60-00										
213001	CABIN PRESSURE INDICATOR									Component ATA:21
PN:C668511-0103	MOS/MSC	11-Mar-96	O/C							
SN:20121	HRS	0		TSN 0						
WC#: 21.090	AFL	0		TSN 0						
PROC. REF: AMM 21-31-03										
213003	RATE OF CHANGE INDICATOR									Component ATA:21
PN:C668513-0101	MOS/MSC	11-Mar-96	O/C							
SN:347032	HRS	0		TSN 0						
WC#: 21.090	AFL	0		TSN 0						
PROC. REF: AMM 21-31-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
213006	CABIN ALTITUDE CONTROLLER									Component ATA:21
PN:130620-2	MOS/MSC	11-Mar-96	O/C							
SN:85C0112	HRS	0			TSN 0					
WC#: 21.080	AFL	0			TSN 0					
PROC. REF: AMM 21-31-01										
213007	NO. 1 PRIMARY OUTFLOW VALVE									Component ATA:21
PN:103648-14	MOS/MSC	11-Mar-96	O/C							
SN:15L0205	HRS	0			TSN 0					
WC#: 21.130	AFL	0			TSN 0					
PROC. REF: AMM 21-31-01, AMM 21-32-00, AMM 21-32-00										
213007	NO. 2 SECONDARY OUTFLOW VALVE									Component ATA:21
PN:103648-14	MOS/MSC	11-Mar-96	O/C							
SN:15L0177	HRS	0			TSN 0					
WC#: 21.130	AFL	0			TSN 0					
PROC. REF: AMM 21-31-01, AMM 21-32-00, AMM 21-32-00										
213009	NO. 1 FLOW CONTROL PRESSURE REGULATOR VALVE									Component ATA:21
PN:1988-00-1	MOS/MSC	23-Feb-15	O/C		TSO 1					
SN:0479	HRS	4731.9			TSO 0					
WC#: 21.120	AFL	4166								
PROC. REF: GENERIC NO REF										
213009	NO. 2 FLOW CONTROL PRESSURE REGULATOR VALVE									Component ATA:21
PN:1988-00-1	MOS/MSC	07-Mar-15	O/C		TSO 0					
SN:0499	HRS	4742			TSO 0					
WC#: 21.120	AFL	4173								
PROC. REF: GENERIC NO REF										
213013	PNEUMATIC RELAY									Component ATA:21
PN:130358-1	MOS/MSC	11-Mar-96	O/C							
SN:352153	HRS	0			TSN 0					
WC#: 21.110	AFL	0			TSN 0					
PROC. REF: AMM 21-31-02										
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY									Component ATA:21
PN:782343-3	MOS/MSC	11-Mar-96	O/C							
SN:951075	HRS	0			TSN 0					
WC#: 21.180	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215004	AIR CYCLE MACHINE									Component ATA:21
PN:738384-26	MOS	29-Mar-18		TSO 0				OVERHAUL		
SN:960533	HRS	4999	5000	TSO 0	9999		4589.8			
WC#: 21.140	AFL	4329		TSO 0						
PROC. REF: AMM 21-51-00										
215005	ACM BYPASS VALVE									Component ATA:21
PN:754751-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.150	AFL	0		TSN 0						
PROC. REF: AMM 21-51-00										
215007	COMPRESSION ACTUATOR									Component ATA:21
PN:BYLB50907	MOS/MSC	17-Dec-04	O/C							
SN:1254	HRS	2347		TSN 0						
WC#: 21.480	AFL									
PROC. REF: GENERIC NO REF										
215008	DUCT OVERHEAT SENSOR									Component ATA:21
PN:1173T42-1	MOS/MSC	11-Mar-96	O/C							
SN:2496	HRS	0		TSN 0						
WC#: 21.150	AFL	0		TSN 0						
PROC. REF: AMM 21-60-00										
215009	ACM OVERHEAT SWITCH 410									Component ATA:21
PN:1173T0635	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.150	AFL	0		TSN 0						
PROC. REF: AMM 21-51-00										
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)									Service ATA:21
PN:1134104-1	MOS	12-Jul-13								
SN:283	HRS	4381.5								
	AFL	3927								
	ACH	233	500		733		325.9			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215016		AC COMPRESSOR							Component	ATA:21
PN:1134160	MOS/MSC	11-Mar-96	O/C							
SN:307	HRS	0		TSN 0						
WC#: 21.160	AFL	0		TSN 0						
PROC. REF: AMM 21-52-00										
215017		AC CONDENSER							Component	ATA:21
PN:1134400-9	MOS/MSC	11-Mar-96	O/C							
SN:163	HRS	0		TSN 0						
WC#: 21.160	AFL	0		TSN 0						
PROC. REF: AMM 21-52-00										
215018		ACM CONTROL UNIT							Component	ATA:21
PN:C35020A	MOS/MSC	11-Mar-96	O/C							
SN:2002	HRS	0		TSN 0						
WC#: 21.170	AFL	0		TSN 0						
PROC. REF: AMM 21-51-00										
215021		MOTOR							Component	ATA:21
PN:1134104-1	MOS/MSC	11-Mar-96	O/C							
SN:283	HRS	0		TSN 0						
WC#: 21.140	AFL	0		TSN 0						
PROC. REF: AMM 21-21-04										
215022		AFT EVAPORATOR							Component	ATA:21
PN:1134240-3	MOS/MSC	11-Mar-96	O/C							
SN:162	HRS	0		TSN 0						
WC#: 21.200	AFL	0		TSN 0						
PROC. REF: AMM 21-52-00										
215023		FWD EVAPORATOR							Component	ATA:21
PN:1134240-2	MOS/MSC	11-Mar-96	O/C							
SN:161	HRS	0		TSN 0						
WC#: 21.200	AFL	0		TSN 0						
PROC. REF: AMM 21-52-00										
215024		PRESSURE SWITCH							Component	ATA:21
PN:1250232-4	MOS/MSC	11-Mar-96	O/C							
SN:2255	HRS	0		TSN 0						
WC#: 21.190	AFL	0		TSN 0						
PROC. REF: AMM 21-11-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
215025	BAROMETRIC SWITCH									Component ATA:21
PN:GBC300-140	MOS/MSC	11-Mar-96	O/C							
SN:9536064	HRS	0		TSN 0						
WC#: 21.190	AFL	0		TSN 0						
PROC. REF: AMM 21-31-05										
216001	CABIN TEMPERATURE SENSOR									Component ATA:21
PN:1942T100-11	MOS/MSC	31-Jul-98	O/C							
SN:314	HRS	731		TSN 0						
WC#: 21.220	AFL									
PROC. REF: AMM 21-60-00										
216002	CABIN TEMPERATURE CONTROLLER									Component ATA:21
PN:754661-5	MOS/MSC	11-Mar-96	O/C							
SN:95090299	HRS	0		TSN 0						
WC#: 21.220	AFL	0		TSN 0						
PROC. REF: AMM 21-60-00										
216003	DUCT TEMPERATURE SENSOR									Component ATA:21
PN:754691-1	MOS/MSC	11-Mar-96	O/C							
SN:6AL101	HRS	0		TSN 0						
WC#: 21.220	AFL	0		TSN 0						
PROC. REF: AMM 21-60-00										
216005	CENTRIFUGAL BLOWER									Component ATA:21
PN:3A1003-10	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.210	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
216010	DOOR ACTUATOR MOTOR ASSEMBLY									Component ATA:21
PN:5A3032	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 21.500	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
217001	WATER SEPARATOR									Component ATA:21
PN:738386-3	MOS/MSC	11-Mar-96	O/C							
SN:951010	HRS	0		TSN 0						
WC#: 21.230	AFL	0		TSN 0						
PROC. REF: AMM 21-70-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
A215001 ^S		CHECK AIR CYCLE MACHINE								Service ATA:21
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 21.240	AFL	4627								
PROC. REF: AMM 21-51-00										PKG:2,4,15
A215200 ^S		PERFORM VAPOR CYCLE COOLING SYSTEM HOUR METER CHECK (COMPRESSOR MOTORS 1134104-1, -5 OR FWA1134104-1, -5 ONLY)								Service ATA:21
	MOS	21-Nov-22								
	HRS	5281.3	300							
	AFL	4547								
PROC. REF: AMM 21-52-00										PKG:249
A215201 ^S		PERFORM 500 COMPRESSOR HOUR MAINTENANCE CHECK ON VAPOR CYCLE COOLING SYSTEM								Service ATA:21
	MOS	11-Mar-96		TAC 0						
	HRS	0		TAC 0						
	AFL	0		TAC 0						
	ACH		500							
PROC. REF: AMM 21-52-00										PKG:501
A215202 ^S		PERFORM 12 MONTH MAINTENANCE CHECK OF VAPOR CYCLE COOLING SYSTEM								Service ATA:21
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 21-52-00										PKG:22
A217001 ^S		INSPECT HUMIDITY REGULATOR								Service ATA:21
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 21.270	AFL	4502								
PROC. REF: AMM 21-70-00										PKG:2
B210000 ^S		OPERATIONAL CHECK ENVIRONMENTAL SYSTEM								Service ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.280	AFL	4442								
PROC. REF: AMM 21-00-00										PKG:7,102

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
B211001 ^S		OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE							Service	ATA:21
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 21.290	AFL	4502								
PROC. REF: AMM 21-11-00										PKG:4
B211002 ^S		OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.300	AFL	4442								
PROC. REF: AMM 21-11-00										PKG:7,104
B211003 ^S		OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES							Service	ATA:21
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 21.310	AFL	4627								
PROC. REF: AMM 21-11-00										PKG:2,4,15
B211004 ^S		OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE							Service	ATA:21
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 21.320	AFL	4502								
PROC. REF: AMM 21-11-00										PKG:4
B212001 ^S		LEAK CHECK TAILCONE BLEED AIR LINES							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.330	AFL	4442								
PROC. REF: AMM 36-11-00										PKG:7,106
B212002 ^S		OPERATIONAL CHECK VERTICAL SCALE INSTRUMENT PANEL COOLING FAN							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.340	AFL	4442								
PROC. REF: AMM 21-24-00										PKG:7,108
B212003 ^S		OPERATIONAL CHECK AVIONICS BAY COOLING FANS							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.350	AFL	4442								
PROC. REF: AMM 21-25-00										PKG:7,102

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
B213000 ^S		OPERATIONAL CHECK PRESSURIZATION							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.360	AFL	4442								
						PROC. REF: AMM 21-31-00		PKG:7,102		
B213001 ^S		FUNCTIONAL TEST BAROMETRIC CABIN ALTITUDE PRESSURE SWITCH							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.370	AFL	4442								
						PROC. REF: AMM 21-31-05		PKG:7,102		
B213005 ^S		OPERATIONAL CHECK PRESSURIZATION SYSTEM							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.380	AFL	4442								
						PROC. REF: AMM 21-32-00		PKG:7,102		
B213006 ^S		FUNCTIONAL TEST OUTFLOW VALVE CABIN ALTITUDE LIMITER							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.390	AFL	4442								
						PROC. REF: AMM 21-32-00		PKG:7,110		
C215001 ^S		CHANGE OIL AIR CYCLE MACHINE							Service	ATA:21
	MOS	29-Dec-22								
	HRS	5391.7	600 (+10)							
WC#: 21.400	AFL	4624								
						PROC. REF: AMM 21-51-00		PKG:45		
D213001 ^S		CLEAN/REPLACE PRESSURIZATION CONTROLLER							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.410	AFL	4442								
						PROC. REF: AMM 21-31-00		PKG:7,102		
D213003 ^S		REPLACE PNEUMATIC RELAY CARTRIDGE FILTER							Service	ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.420	AFL	4442								
						PROC. REF: AMM 21-31-00		PKG:7,110		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 21 - AIR CONDITIONING										
D213004 ^S		CLEAN/REPLACE SOLENOID VALVE FILTER								Service ATA:21
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 21.430	AFL	4442								
PROC. REF: AMM 21-31-00										PKG:7,110
ATA 22 - AUTO FLIGHT										
221009		AUTOPILOT CONTROL								Component ATA:22
PN:7003897-923	MOS/MSC	22-Aug-97	O/C							
SN:95040816	HRS	440		TSO 1717						
WC#: 22.040	AFL									
PROC. REF: AMM 22-11-03										
221010		AILERON SERVO								Component ATA:22
PN:4006719-906	MOS/MSC	11-Mar-96	O/C							
SN:95087913	HRS	0		TSN 0						
WC#: 22.010	AFL	0		TSN 0						
PROC. REF: AMM 22-11-01										
221010		ELEVATOR SERVO								Component ATA:22
PN:4006719-904	MOS/MSC	13-Nov-09	O/C							
SN:83039113	HRS	3357		TSO 8834						
WC#: 22.020	AFL									
PROC. REF: AMM 22-11-01										
221010		RUDDER SERVO								Component ATA:22
PN:4006719-906	MOS/MSC	11-Mar-96	O/C							
SN:95098061	HRS	0		TSN 0						
WC#: 22.030	AFL	0		TSN 0						
PROC. REF: AMM 22-11-01										
A221001 ^S		INSPECT AILERON SERVO ACTUATOR AND MOUNT								Service ATA:22
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 22.010	AFL	4442								
PROC. REF: AMM 22-11-01										PKG:7,104

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 22 - AUTO FLIGHT										
A222001 ^S		INSPECT RUDDER SERVO ACTUATOR AND MOUNT							Service	ATA:22
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 22.030	AFL	4442								
PROC. REF: AMM 22-11-01										PKG:7,109
A223001 ^S		INSPECT ELEVATOR SERVO ACTUATOR AND MOUNT							Service	ATA:22
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 22.020	AFL	4442								
PROC. REF: AMM 22-11-01										PKG:7,110
B221002 ^S		PERFORM AUTOPILOT AND DISENGAGEMENT AND WARNING TEST							Service	ATA:22
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 22.050	AFL	4442								
PROC. REF: AMM 22-11-03										PKG:7,102
B221003 ^S		PERFORM AUTOPILOT DISENGAGEMENT AND WARNING TEST							Service	ATA:22
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 22.080	AFL	4442								
PROC. REF: AMM 22-11-03										PKG:7,102
ATA 23 - COMMUNICATIONS										
232002		NO. 2 VHF COMM ANTENNA							Component	ATA:23
PN:VF10-108-6	MOS/MSC	05-Jan-14	O/C	TSN 0						
SN:0175	HRS	4566.4		TSN 0						
WC#: 23.040	AFL	4081								
PROC. REF: AMM 23-13-01										
232003		NO. 1 VHF COMM ANTENNA							Component	ATA:23
PN:VF10-108-6	MOS/MSC	06-Feb-17	O/C	TSN 0						
SN:0283	HRS	4913.3		TSN 0						
WC#: 23.040	AFL	4280		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232004	TRANSCEIVER PHONE									Component ATA:23
PN:400-0125-2000	MOS/MSC	21-Apr-00	O/C							
SN:4535	HRS	1213			TSO 1213					
WC#: 23.050	AFL									
PROC. REF: GENERIC NO REF										
232005	CABIN HANDSET PHONE									Component ATA:23
PN:300-2291-012	MOS/MSC	21-Apr-00	O/C							
SN:10176	HRS	1213			TSO 1213					
WC#: 23.060	AFL									
PROC. REF: GENERIC NO REF										
232006	COCKPIT HANDSET PHONE									Component ATA:23
PN:400-0123-212	MOS/MSC	11-Mar-96	O/C							
SN:10134	HRS	0			TSN 0					
WC#: 23.060	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										
232007	PHONE ANTENNA									Component ATA:23
PN:50-95-01	MOS/MSC	11-Mar-96	O/C							
SN:2945	HRS	0			TSN 0					
WC#: 23.070	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										
232009	NO. 1 COMM CONTROL									Component ATA:23
PN:622-6520-005	MOS/MSC	09-May-07	O/C							
SN:15453	HRS	2810			TSO 2810					
WC#: 23.340	AFL									
PROC. REF: GENERIC NO REF										
232009	NO. 2 COMM CONTROL									Component ATA:23
PN:622-6520-005	MOS/MSC	13-Feb-13	O/C							
SN:15453	HRS	4265.4								
WC#: 23.340	AFL	3843								
PROC. REF: GENERIC NO REF										
232010	NO. 1 VHF COMMUNICATION TRANSCEIVER									Component ATA:23
PN:622-6152-011	MOS/MSC	16-Oct-18	O/C		TSR 0					
SN:33483	HRS	5024			TSR 0					
WC#: 23.090	AFL	4342			TSR 0					
PROC. REF: AMM 23-12-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
232010	NO. 2 VHF COMMUNICATION TRANSCEIVER									Component ATA:23
PN:622-6152-011	MOS/MSC	16-Oct-18	O/C	TSR 0						
SN:22883	HRS	5024		TSR 0						
WC#: 23.090	AFL	4342		TSR 0						
PROC. REF: AMM 23-12-00										
235001	NO. 1 AUDIO AMPLIFIER									Component ATA:23
PN:5636-1	MOS/MSC	28-Nov-18	O/C	TSO 0						
SN:253	HRS	5024.8		TSO 0						
WC#: 23.100	AFL	4345		TSO 0						
PROC. REF: AMM 23-51-01										
235001	NO. 2 AUDIO AMPLIFIER									Component ATA:23
PN:5636-1	MOS/MSC	28-Nov-18	O/C	TSO 0						
SN:193	HRS	5024.8		TSO 0						
WC#: 23.100	AFL	4345		TSO 0						
PROC. REF: AMM 23-51-01										
237001	COCKPIT VOICE RECORDER									Component ATA:23
PN:S200-0012-00	MOS/MSC	21-Apr-00	O/C							
SN:335	HRS	1213		TSO 1213						
WC#: 23.120	AFL									
PROC. REF: AMM 23-71-02										
237004	CVR CONTROLLER									Component ATA:23
PN:S251-1120-00	MOS/MSC	11-Mar-96	O/C							
SN:238	HRS	0		TSN 0						
WC#: 23.110	AFL	0		TSN 0						
PROC. REF: AMM 23-71-03										
237006	CVR UNDERWATER LOCATOR BEACON									Component ATA:23
PN:DK100	MOS/MSC	13-Oct-08	O/C	TSN 8						
SN:SC27777	HRS	3101								
WC#: 23.120	AFL									
PROC. REF: AMM 23-71-02										
237006A	REPLACE ULB (CVR) BATTERY									Component ATA:23
PN:DK 120/90	MOS/MSC	03-Feb-20	DUE	TSN 0	31-May-26 (M)		1130 d			
SN:AT136476	HRS	5085.5		TSN 0						
WC#: 23.290	AFL	4402		TSN 0						
Expiry Date: : 31-May-26 PROC. REF: AMM 23-71-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
23FO-04 560/T		COMM KHF-950 W/COLNS PKG-SMALL CNTL HEAD FACTORY OPTION							Component	ATA:23
PN:631T	MOS/MSC	11-Mar-96	-							
SN:FO	HRS	0								
	AFL	0								
PROC. REF: GENERIC NO REF										
A231001 ^S		INSPECT HIGH FREQUENCY ANTENNA AND TENSION UNIT							Service	ATA:23
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 23.130	AFL	4442								
PROC. REF: AMM 23-10-01										
										PKG:7,107
A236002 ^S		INSPECT CONTROL SURFACE BOND JUMPER							Service	ATA:23
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 23.140	AFL	4442								
PROC. REF: AMM 20-21-02										
										PKG:7,110
A237001 ^S		INSPECT COCKPIT VOICE RECORDER							Service	ATA:23
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 23.120	AFL	4442								
PROC. REF: AMM 23-70-00										
										PKG:7,106
A237003		INSPECT CVR UNDERWATER LOCATOR BEACON							Service	ATA:23
PN:DK100	MOS	22-Dec-21	24 (+1m)		31-Dec-23	31-Jan-24	248 d (+31)			
SN:SC27777	HRS	5180								
WC#: 23.120	AFL	4468								
PROC. REF: AMM 23-70-00										
										PKG:35
B236001 ^S		INSPECT STATIC DISCHARGE WICK							Service	ATA:23
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 23.160	AFL	4442								
PROC. REF: AMM 23-61-00										
										PKG:7,108
B237002 ^S		OPERATIONAL CHECK COCKPIT VOICE RECORDER							Service	ATA:23
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 23.120	AFL	4502								
PROC. REF: AMM 23-70-00										
										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 23 - COMMUNICATIONS										
B237004	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON									Service ATA:23
PN:DK100	MOS	22-Dec-21	24 (+1m)		31-Dec-23	31-Jan-24	248 d (+31)			
SN:SC27777	HRS	5180								
WC#: 23.120	AFL	4468								
PROC. REF: AMM 23-70-00										PKG:35
ATA 24 - ELECTRICAL POWER										
242001	NO. 1 STATIC INVERTER									Component ATA:24
PN:PC251-123E	MOS/MSC	30-Sep-98	O/C							
SN:8309	HRS	784		TSO 0						
WC#: 24.010	AFL									
PROC. REF: AMM 24-20-01, AMM 24-20-02, AMM 24-25-01										
242001	NO. 2 STATIC INVERTER									Component ATA:24
PN:PC251-123E	MOS/MSC	30-Sep-98	O/C							
SN:8567	HRS	784		TSO 0						
WC#: 24.010	AFL									
PROC. REF: AMM 24-20-01, AMM 24-20-02, AMM 24-25-01										
243001	LEFT STARTER/GENERATOR									Component ATA:24
PN:23085-004-1	MOS	08-May-14						OVERHAUL		
SN:695	HRS	4692.3	1000	TSO 0	5692.3		283.1			
WC#: 24.070	AFL	4126								
PROC. REF: AMM 80-11-01										
243001	RIGHT STARTER/GENERATOR									Component ATA:24
PN:23085-004-1	MOS	20-Apr-23		TSO 0				OVERHAUL		
SN:92109	HRS	5396.4	1000	TSO 0	6396.4		987.2			
WC#: 24.075	AFL	4627		TSO 0						
PROC. REF: AMM 80-11-01										
243003	NO. 1 GENERATOR CONTROL UNIT									Component ATA:24
PN:51525-001F	MOS/MSC	11-Nov-99	O/C							
SN:94050	HRS	1108		TSO 0						
WC#: 24.050	AFL									
PROC. REF: AMM 24-31-00, AMM 24-31-01, AMM 24-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243003	NO. 2 GENERATOR CONTROL UNIT									Component ATA:24
PN:51525-001F	MOS/MSC	20-Nov-15	O/C							
SN:P3776	HRS	4819.1								
WC#: 24.050	AFL	4224								
	ACH	302.5								
PROC. REF: AMM 24-31-00, AMM 24-31-01, AMM 24-31-02										
243004	NO. 1 AMMETER									Component ATA:24
PN:C662501-0104	MOS/MSC	11-Mar-96	O/C							
SN:1023	HRS	0		TSN 0						
WC#: 24.020	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
243004	NO. 2 AMMETER									Component ATA:24
PN:C662501-0104	MOS/MSC	11-Mar-96	O/C							
SN:1027	HRS	0		TSN 0						
WC#: 24.020	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
243005	DC VOLTMETER									Component ATA:24
PN:C662502-0101	MOS/MSC	11-Mar-96	O/C							
SN:1086	HRS	0		TSN 0						
WC#: 24.080	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
243007	MAIN SHIP BATTERY									Component ATA:24
PN:7638-44	MOS/MSC	05-Oct-22	O/C	TSN 0						
SN:G03155215	HRS	5243.1		TSN 0						
WC#: 24.030	AFL	4518		TSN 0						
PROC. REF: AMM 24-32-00										
243008	BATTERY TEMP MONITOR-									Component ATA:24
PN:1529-1	MOS/MSC	11-Mar-96	O/C							
SN:2399	HRS	0		TSN 0						
WC#: 24.060	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
243009	BATTERY TEMP GAGE									Component ATA:24
PN:1229-1	MOS/MSC	10-May-10	O/C	TSO 0						
SN:2916	HRS	3502.4		TSO 0						
WC#: 24.060	AFL	3151								
PROC. REF: AMM 24-32-03										
243010	BATTERY TEMP SENSOR									Component ATA:24
PN:1166-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.060	AFL	0		TSN 0						
PROC. REF: AMM 24-32-02										
243015	BATTERY DISCONNECT RELAY									Component ATA:24
PN:A876K	MOS/MSC	11-Mar-96	O/C							
SN:CL61691	HRS	0		TSN 0						
WC#: 24.090	AFL	0		TSN 0						
PROC. REF: AMM 24-41-01										
243016	CURRENT/VOLTAGE SENSOR									Component ATA:24
PN:1645-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 24.040	AFL	0		TSN 0						
PROC. REF: AMM 24-41-01										
245002	CABIN ALTITUDE SWITCH									Component ATA:24
PN:GB300NA161	MOS/MSC	11-Mar-96	O/C							
SN:9527847	HRS	0		TSN 0						
WC#: 24.200	AFL	0		TSN 0						
PROC. REF: AMM 21-32-00										
A242001 ^S	INSPECT NOSE AREA ELECTRICAL COMPONENTS									Service ATA:24
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 24.110	AFL	4442								
PROC. REF: AMM 24-00-00										PKG:7,100
A245001 ^S	INSPECT CIRCUIT BREAKER PANELS									Service ATA:24
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 24.120	AFL	4442								
PROC. REF: AMM 24-45-00										PKG:7,102

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 24 - ELECTRICAL POWER										
A245002 ^S		INSPECT COCKPIT SIDE CONSOLE							Service	ATA:24
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 24.130	AFL	4442								
					PROC. REF: AMM 24-45-00		PKG:7,102			
A245003 ^S		INSPECT AVIONICS RELAY JUNCTION BOX							Service	ATA:24
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 24.140	AFL	4442								
					PROC. REF: AMM 24-00-00		PKG:7,100			
A245004 ^S		INSPECT AFT POWER JUNCTION BOX							Service	ATA:24
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 24.150	AFL	4442								
					PROC. REF: AMM 24-45-00		PKG:7,105			
B243001 ^S		OPERATIONAL TEST DC GENERATOR SYSTEM							Service	ATA:24
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 24.160	AFL	4502								
					PROC. REF: AMM 24-30-00		PKG:4			
B244001 ^S		FUNCTIONAL TEST OVERVOLTAGE SYSTEM							Service	ATA:24
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 24.170	AFL	4502								
					PROC. REF: AMM 24-41-02		PKG:1			
D243003		INSPECT 44 AMP-HOUR GILL LAMSB: PHASE 55							Service	ATA:24
PN:7638-44	MOS	05-Oct-22	T:18 (+1m)		30-Apr-24	31-May-24	369 d (+31)			
SN:G03155215	HRS	5243.1	T:1800 (+50/-50)		7043.1	7093.1	1633.9 (+50)			
WC#: 24.190	AFL	4518								
					PROC. REF: AMM 24-35-00		PKG:64			
ATA 25 - EQUIPMENT/FURNISHINGS										
256002		EMERGENCY LOCATOR TRANSMITTER							Component	ATA:25
PN:453-5000-999	MOS/MSC	28-Nov-18	O/C	TSN 95						
SN:170-09351	HRS	5024.8		TSN 1320.5						
WC#: 25.020	AFL	4345								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
PROC. REF: AMM 25-61-02, AMM 25-61-03, AMM 25-61-05, AMM 25-61-07										
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY									Component ATA:25
PN:452-0133	MOS/MSC	14-Mar-19	DUE	TSN 0	29-Feb-24 (M)		308 d			
SN:379974-014	HRS	5027.6		TSN 0						
WC#: 25.020	AFL	4350		TSN 0						
PROC. REF: GENERIC NO REF										
256004	NO. 1 ELT ANTENNA									Component ATA:25
PN:110-328-01	MOS/MSC	03-Dec-10	O/C	TSN 0						
SN:4720	HRS	3704.3		TSN 0						
WC#: 25.030	AFL	3298								
PROC. REF: AMM 25-61-02, AMM 25-61-03, AMM 25-61-05, AMM 25-61-07										
256010	NO. 1 LIFE VEST									Component ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140001	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010	NO. 10 LIFE VEST									Component ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140037	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010	NO. 2 LIFE VEST									Component ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140003	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010	NO. 3 LIFE VEST									Component ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140018	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256010		NO. 4 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140014	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010		NO. 5 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140020	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010		NO. 6 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140019	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010		NO. 7 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140033	HRS	5105.1		TSN 0						
	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010		NO. 8 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140028	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										
256010		NO. 9 LIFE VEST							Component	ATA:25
PN:P01202-101	MOS	26-Apr-20	120	TSN 8	31-Aug-29		2318 d			
SN:19081140038	HRS	5105.1		TSN 0						
WC#: 25.300	AFL	4413		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
256016 ^U	AED								Component	ATA:25
PN:350-BTC-US10	MOS/MSC	05-Oct-22	DUE	TSN 0	31-Oct-26 (M)		1283 d			
SN:UNKNOWN	HRS	5243.1		TSN 0						
	AFL	4518		TSN 0						
Expiry Date: : 31-Oct-26										
A251001 ^S	INSPECT PILOT AND COPILOT CREW SEAT								Service	ATA:25
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 25.010	AFL	4442								
PROC. REF: AMM 25-11-01										PKG:7,110
A251002 ^S	INSPECT PILOT AND COPILOT SEAT TRACK STOPS								Service	ATA:25
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 25.040	AFL	4442								
PROC. REF: AMM 25-11-01										PKG:7,110
A251004 ^S	INSPECT COCKPIT INSTRUMENT PANELS AND COMPONENTS								Service	ATA:25
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 25.050	AFL	4442								
PROC. REF: AMM 25-10-00										PKG:7,108
A252001 ^S	INSPECT PASSENGER SEAT								Service	ATA:25
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 25.060	AFL	4442								
PROC. REF: AMM 25-20-00										PKG:7,110
A252002 ^S	INSPECT PASSENGER SEAT TRACK STOPS								Service	ATA:25
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 25.070	AFL	4442								
PROC. REF: AMM 25-20-00										PKG:7,110
A256001 ^S	INSPECT EMERGENCY EQUIPMENT								Service	ATA:25
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
WC#: 25.080	AFL	4502								
PROC. REF: AMM 25-60-00										PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 25 - EQUIPMENT/FURNISHINGS										
A256003 ^S		INSPECT LIFE PRESERVER								Service ATA:25
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
WC#: 25.090	AFL	4502								
PROC. REF: AMM 25-60-00										PKG:22
A256004 ^S		DETAILED INSPECTION SMOKE GOGGLE ASSEMBLY								Service ATA:25
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
WC#: 25.310	AFL	4502								
PROC. REF: AMM 25-60-00										PKG:22
A256107 ^S		DETAILED INSPECTION C406-2 (ELT) 91.207								Service ATA:25
	MOS	20-Apr-23	12							
	HRS	5396.4								
WC#: 26.120	AFL	4627								
PROC. REF: AMM 25-61-07										PKG:65
B256001 ^S		VISUALLY INSPECT EMERGENCY LOCATOR BEACON SYSTEM								Service ATA:25
	MOS	20-Apr-23	12					AIRWORTHINESS		
	HRS	5396.4								
WC#: 25.100	AFL	4627								
PROC. REF: AMM 25-60-00										PKG:65
B256107 ^S		FUNCTIONAL TEST C406-2 (ELT) 91.207								Service ATA:25
	MOS	20-Apr-23	12							
	HRS	5396.4								
WC#: 26.120	AFL	4627								
PROC. REF: AMM 25-61-07										PKG:65
ATA 26 - FIRE PROTECTION										
261001		NO. 1 ENGINE FIRE DETECTOR SENSOR								Component ATA:26
PN:244-18882	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 26.020	AFL	0			TSN 0					
PROC. REF: AMM 26-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
261001	NO. 2 ENGINE FIRE DETECTOR SENSOR									Component ATA:26
PN:244-18882	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 26.020	AFL	0			TSN 0					
PROC. REF: AMM 26-11-01										
261002	NO. 1 FIRE DETECTOR CONTROL									Component ATA:26
PN:377-02830	MOS/MSC	11-Mar-96	O/C							
SN:9533007	HRS	0			TSN 0					
WC#: 26.010	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										
261002	NO. 2 FIRE DETECTOR CONTROL									Component ATA:26
PN:377-02830	MOS/MSC	11-Mar-96	O/C							
SN:9533002	HRS	0			TSN 0					
WC#: 26.010	AFL	0			TSN 0					
PROC. REF: GENERIC NO REF										
262001	AFT ENGINE FIRE BOTTLE									Component ATA:26
PN:32700015	MOS/MSC	26-Apr-20	O/C		TSN 296, TSO 0					
SN:14430C1	HRS	5105.1			TSO 0					
WC#: 26.040	AFL	4413			TSO 0					
PROC. REF: AMM 26-21-01										
262001	FORWARD ENGINE FIRE BOTTLE									Component ATA:26
PN:32700015	MOS/MSC	26-Apr-20	O/C		TSN 319, TSO 0					
SN:12872C1	HRS	5105.1			TSO 0					
WC#: 26.030	AFL	4413			TSO 0					
PROC. REF: AMM 26-21-01										
262002	CABIN PORTABLE HALON FIRE EXTINGUISHER									Component ATA:26
PN:C352TS	MOS/MSC	16-Oct-18	O/C		TSN 9					
SN:E-68635833	HRS	5024			TSN 0					
WC#: 26.060	AFL	4342			TSN 0					
PROC. REF: GENERIC NO REF										
262002	COCKPIT PORTABLE HALON FIRE EXTINGUISHER									Component ATA:26
PN:C352TS	MOS/MSC	16-Oct-18	O/C		TSN 9					
SN:E-68635832	HRS	5024			TSN 0					
WC#: 26.050	AFL	4342			TSN 0					
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
262002.0 ^U		30 DAY INSPECTION OF CABIN FIRE EXTINGUISHER							Service	ATA:26
	MOS	20-Apr-23	1		31-May-23		34 d			
	HRS	5396.4								
	AFL	4627								
262002.0 ^U		30 DAY INSPECTION OF COCKPIT FIRE EXTINGUISHER							Service	ATA:26
	MOS	20-Apr-23	1		31-May-23		34 d			
	HRS	5396.4								
	AFL	4627								
262003		AFT LEFT (MAX LIFE) CARTRIDGE							Component	ATA:26
PN:AE13083-5	MOS	08-Jun-22	120		31-Oct-30		2744 d	LIFE LIMIT		
SN:2853	HRS	5229.6								
WC#: 26.030	AFL	4502								
				Manufacture Date::	31-Oct-20	PROC. REF: AMM 26-21-01				
262003		AFT RIGHT (MAX LIFE) CARTRIDGE							Component	ATA:26
PN:AE13083-5	MOS	08-Jun-22	120		31-Oct-30		2744 d	LIFE LIMIT		
SN:2888	HRS	5229.6								
WC#: 26.040	AFL	4502								
				Manufacture Date::	31-Oct-20	PROC. REF: AMM 26-21-01				
262003		FORWARD LEFT (MAX LIFE) CARTRIDGE							Component	ATA:26
PN:AE13083-5	MOS	20-May-15	120	TSN 8	30-Sep-24		522 d	LIFE LIMIT		
SN:A5N1-180	HRS	4778.6								
WC#: 26.030	AFL	4192								
				Manufacture Date::	30-Sep-14	PROC. REF: AMM 26-21-01				
262003		FORWARD RIGHT (MAX LIFE) CARTRIDGE							Component	ATA:26
PN:AE13083-5	MOS	20-May-15	120		30-Sep-24		522 d	LIFE LIMIT		
SN:A5N1-180	HRS	4778.6								
WC#: 26.040	AFL	4192								
				Manufacture Date::	30-Sep-14	PROC. REF: AMM 26-21-01				
263005		REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE							Service	ATA:26
PN:AE13083-5	MOS	20-May-15	120	TAC 8	30-Sep-24		522 d	REPLACE		
SN:A5N1-180	HRS	4778.6								
WC#: 26.030	AFL	4192								
				PROC. REF: AMM 26-21-01						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
263007		REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE								Service ATA:26
PN:AE13083-5	MOS	20-May-15	120	TAC 8	30-Sep-24		522 d	REPLACE		
SN:A5N1-180	HRS	4778.6								
WC#: 26.040	AFL	4192								
PROC. REF: AMM 26-21-01										
263009		REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE								Service ATA:26
PN:AE13083-5	MOS	08-Jun-22	120		30-Jun-32		3352 d	REPLACE		
SN:2853	HRS	5229.6								
WC#: 26.030	AFL	4502								
PROC. REF: AMM 26-21-01										
263011		REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE								Service ATA:26
PN:AE13083-5	MOS	08-Jun-22	120		30-Jun-32		3352 d	REPLACE		
SN:2888	HRS	5229.6								
WC#: 26.040	AFL	4502								
PROC. REF: AMM 26-21-01										
A262003		INSPECT/WEIGH CABIN PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	25-May-22	12 (+1m)		31-May-23	30-Jun-23	34 d (+30)	05-10-25 AIRWORTHINESS		
SN:E-68635833	HRS									
WC#: 26.060	AFL									
PROC. REF: AMM 26-22-00										PKG:22
A262003		INSPECT/WEIGH COCKPIT PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	25-May-22	12 (+1m)		31-May-23	30-Jun-23	34 d (+30)	05-10-25 AIRWORTHINESS		
SN:E-68635832	HRS									
WC#: 26.050	AFL									
PROC. REF: AMM 26-22-00										PKG:22
B262002		HYDROSTATIC TEST AFT ENGINE FIRE BOTTLE								Service ATA:26
PN:32700015	MOS	24-Apr-20	60		30-Apr-25		734 d			
SN:14430C1	HRS									
WC#: 26.040	AFL									
PROC. REF: AMM 26-22-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 26 - FIRE PROTECTION										
B262002		HYDROSTATIC TEST FORWARD ENGINE FIRE BOTTLE								Service ATA:26
PN:32700015	MOS	24-Apr-20	60		30-Apr-25		734 d			
SN:12872C1	HRS									
WC#: 26.030	AFL									
PROC. REF: AMM 26-22-00										
B262003		HYDROSTATIC TEST CABIN PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	01-Jan-18	144		31-Jan-30		2471 d	05-10-25 AIRWORTHINESS		
SN:E-68635833	HRS									
WC#: 26.060	AFL									
PROC. REF: AMM 26-22-00										
B262003		HYDROSTATIC TEST COCKPIT PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	01-Jan-18	144		31-Jan-30		2471 d	05-10-25 AIRWORTHINESS		
SN:E-68635832	HRS									
WC#: 26.050	AFL									
PROC. REF: AMM 26-22-00										
B262004		EMPTY/INSPECT/RECHARGE CABIN PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	16-Oct-18	72	TAC 9	31-Jan-24		279 d	05-10-25 AIRWORTHINESS		
SN:E-68635833	HRS	5024								
WC#: 26.060	AFL	4342								
PROC. REF: AMM 26-22-00										PKG:54
B262004		EMPTY/INSPECT/RECHARGE COCKPIT PORTABLE HALON FIRE EXTINGUISHER								Service ATA:26
PN:C352TS	MOS	16-Oct-18	72	TAC 9	31-Jan-24		279 d	05-10-25 AIRWORTHINESS		
SN:E-68635832	HRS	5024								
WC#: 26.050	AFL	4342								
PROC. REF: AMM 26-22-00										PKG:54
B262005 ^S		FUNCTIONAL TEST ENGINE FIRE EXTINGUISHER SYSTEM								Service ATA:26
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 26.110	AFL	4442								
PROC. REF: AMM 26-21-00										PKG:7,102

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
271001		AILERON TRIM ACTUATOR							Component	ATA:27
PN:5565450-72	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.010	AFL	0		TSN 0						
PROC. REF: AMM 27-11-07										
272001		RUDDER TRIM ACTUATOR							Component	ATA:27
PN:5565450-71	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.020	AFL	0		TSN 0						
PROC. REF: AMM 27-21-05										
273002		TRIM MIXER ACTUATOR							Component	ATA:27
PN:44430-3657	MOS/MSC	03-Apr-97	O/C							
SN:T502	HRS	308		TSO 0						
WC#: 27.030	AFL									
PROC. REF: AMM 27-31-07										
273003		LEFT ELEVATOR TRIM ACTUATOR							Component	ATA:27
PN:5565450-81	MOS/MSC	07-Nov-97	O/C							
SN:UNKNOWN	HRS	530		TSN 0						
WC#: 27.040	AFL									
PROC. REF: AMM 27-31-05										
273003		RIGHT ELEVATOR TRIM ACTUATOR							Component	ATA:27
PN:5565450-82	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 27.040	AFL	0		TSN 0						
PROC. REF: AMM 27-31-05										
275001		FLAP CONTROL VALVE							Component	ATA:27
PN:66720	MOS/MSC	11-Mar-96	O/C							
SN:1237	HRS	0		TSN 0						
WC#: 27.050	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04										
275003		NO. 1 FLAP ACTUATOR							Component	ATA:27
PN:1535000-1	MOS/MSC	11-Mar-96	O/C							
SN:477	HRS	0		TSN 0						
WC#: 27.060	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275003	NO. 2 FLAP ACTUATOR									Component ATA:27
PN:1535000-1	MOS/MSC	11-Mar-96	O/C							
SN:480	HRS	0		TSN 0						
WC#: 27.060	AFL	0		TSN 0						
PROC. REF: AMM 27-51-04										
275004	LEFT WING LEFT INBOARD AFT FLAP ROLLER									Component ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.070	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004	LEFT WING LEFT OUTBOARD AFT FLAP ROLLER									Component ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.070	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004	LEFT WING RIGHT INBOARD AFT FLAP ROLLER									Component ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.075	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004	LEFT WING RIGHT OUTBOARD AFT FLAP ROLLER									Component ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.075	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004	RIGHT WING LEFT INBOARD AFT FLAP ROLLER									Component ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.080	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
275004		RIGHT WING LEFT OUTBOARD AFT FLAP ROLLER							Component	ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.080	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004		RIGHT WING RIGHT INBOARD AFT FLAP ROLLER							Component	ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.085	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
275004		RIGHT WING RIGHT OUTBOARD AFT FLAP ROLLER							Component	ATA:27
PN:CC50380	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 27.085	AFL	0	5000	TSN 0	5000		364			
PROC. REF: GENERIC NO REF										
276001		NO. 1 SPEED BRAKE ACTUATOR							Component	ATA:27
PN:1535500-1	MOS/MSC	11-Mar-96	O/C							
SN:414	HRS	0		TSN 0						
WC#: 27.090	AFL	0		TSN 0						
PROC. REF: AMM 27-61-04										
276001		NO. 2 SPEED BRAKE ACTUATOR							Component	ATA:27
PN:1535500-1	MOS/MSC	11-Mar-96	O/C							
SN:420	HRS	0		TSN 0						
WC#: 27.090	AFL	0		TSN 0						
PROC. REF: AMM 27-61-04										
276002		SPEED BRAKE FLAP CONTROL VALVE							Component	ATA:27
PN:66720	MOS/MSC	11-Mar-96	O/C							
SN:1239	HRS	0		TSN 0						
WC#: 27.100	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
276003		SAFETY SPDBK VALVE							Component	ATA:27
PN:68930	MOS/MSC	11-Mar-96	O/C							
SN:497	HRS	0		TSN 0						
WC#: 27.110	AFL	0		TSN 0						
PROC. REF: AMM 27-61-05										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
A271003 ^S		INSPECT AILERON AND AILERON TRIM TAB								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.120	AFL	4502								
PROC. REF: AMM 27-11-00										PKG:2
A271004 ^S		INSPECT CONTROL WHEEL								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.130	AFL	4502								
PROC. REF: AMM 27-11-00										PKG:1
A271005 ^S		INSPECT AILERON, RUDDER AND ELEVATOR TRIM TAB CONTROL AND INDICATOR								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.140	AFL	4502								
PROC. REF: AMM 27-11-00										PKG:1
A271006 ^S		INSPECT AILERON CONTROL CABLE								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.150	AFL	4442								
PROC. REF: AMM 27-11-00										PKG:7,111
A271007 ^S		INSPECT AILERON TRIM CABLE								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.160	AFL	4442								
PROC. REF: AMM 27-11-00										PKG:7,111
A271008 ^S		INSPECT AILERON TRIM TAB ACTUATOR DISASSEMBLY								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.170	AFL	4442								
PROC. REF: AMM 27-11-00										PKG:7,111
A271014 ^S		INSPECT AILERON DRIVE BRACKET								Service ATA:27
	MOS	11-Mar-96		TAC 0						
	HRS	0		TAC 0						
WC#: 27.180	AFL	0	T:15000	TAC 0						
PROC. REF: AMM 27-11-00										PKG:46

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
A271015 ^S		INSPECT AILERON YOKE								Service ATA:27
	MOS	11-Mar-96		TAC 0						
	HRS	0		TAC 0						
WC#: 27.190	AFL	0	T:15000	TAC 0						
PROC. REF: AMM 27-11-00										PKG:47
A272002 ^S		INSPECT RUDDER AND RUDDER TRIM TAB								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.200	AFL	4502								
PROC. REF: AMM 27-21-00										PKG:2
A272003 ^S		INSPECT RUDDER PEDALS								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.210	AFL	4442								
PROC. REF: AMM 27-21-03										PKG:7,111
A272005 ^S		INSPECT RUDDER CABLE								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.220	AFL	4442								
PROC. REF: AMM 27-21-06										PKG:7,111
A272006 ^S		INSPECT RUDDER TRIM CABLE								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.230	AFL	4442								
PROC. REF: AMM 27-21-06										PKG:7,111
A272007 ^S		INSPECT RUDDER TRIM TAB ACTUATOR DISASSEMBLY								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.240	AFL	4442								
PROC. REF: AMM 27-21-00										PKG:7,111
A273002 ^S		EXTERNAL INSPECTION ELEVATOR								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.250	AFL	4502								
PROC. REF: AMM 27-31-00										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
A273005 ^S		INSPECT CONTROL COLUMNS							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200							
WC#: 27.260	AFL	4442								
						PROC. REF: AMM 27-31-02		PKG:7,111		
A273006 ^S		INSPECT ELEVATOR LINKAGE							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.270	AFL	4442								
						PROC. REF: AMM 27-31-00		PKG:7,107		
A273007 ^S		INSPECT FLAP/ELEVATOR ELECTRIC TRIM MIXER							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.280	AFL	4442								
						PROC. REF: AMM 27-51-00		PKG:7,105		
A273008 ^S		INSPECT ELEVATOR CABLE							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.290	AFL	4442								
						PROC. REF: AMM 27-31-00		PKG:7,111		
A273009 ^S		INSPECT ELEVATOR TRIM CABLE							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.300	AFL	4442								
						PROC. REF: AMM 27-31-00		PKG:7,111		
A273010 ^S		INSPECT ELEVATOR TRIM TAB ACTUATOR DISASSEMBLY							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.310	AFL	4442								
						PROC. REF: AMM 27-31-00		PKG:7,111		
A275003 ^S		INSPECT FLAP PRESELECT CABLE							Service	ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.320	AFL	4442								
						PROC. REF: AMM 27-51-00		PKG:7,111		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
A275004 ^S		INSPECT FLAP								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.330	AFL	4502								
PROC. REF: AMM 27-51-00										PKG:2
A275007 ^S		INSPECT FLAP BELL CRANKS								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.340	AFL	4442								
PROC. REF: AMM 27-51-00										PKG:7,111
A275021 ^S		INSPECT FLAP CROSSTIE SYSTEM								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.350	AFL	4442								
PROC. REF: AMM 27-51-00										PKG:7,111
A275022 ^S		INSPECT FLAP/ELEVATOR TRIM MIXER INTERCONNECT CABLE SYSTEM								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.360	AFL	4442								
PROC. REF: AMM 27-31-07										PKG:7,111
A276001 ^S		INSPECT SPEED BRAKE SYSTEM								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.370	AFL	4442								
PROC. REF: AMM 27-61-00										PKG:7,109
B271001 ^S		CHECK AILERON TRIM TAB								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.380	AFL	4442								
PROC. REF: AMM 27-11-00										PKG:7,111
B271002 ^S		CHECK AILERON AND AILERON TRIM TAB								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.390	AFL	4442								
PROC. REF: AMM 27-11-00										PKG:7,111

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
B272001 ^S	CHECK RUDDER TRIM TAB									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.400	AFL	4442								
PROC. REF: AMM 27-21-00										PKG:7,107
B272004 ^S	CHECK RUDDER AND RUDDER TRIM TAB TRAVEL									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.410	AFL	4442								
PROC. REF: AMM 27-21-00										PKG:7,111
B273003 ^S	CHECK ELEVATOR AND ELEVATOR TRIM TAB									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.420	AFL	4442								
PROC. REF: AMM 27-31-00										PKG:7,111
B273004 ^S	CHECK ELEVATOR TRIM TAB FREE PLAY									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.430	AFL	4442								
PROC. REF: AMM 27-31-00										PKG:7,107
B273015 ^S	OPERATIONAL CHECK ELEVATOR ELECTRICAL TRIM MIXER SYSTEM									Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.440	AFL	4502								
PROC. REF: AMM 27-31-07										PKG:1
B275004 ^S	OPERATIONAL CHECK FLAP APPROACH WARNING SWITCH									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.450	AFL	4442								
PROC. REF: AMM 27-51-00										PKG:7,102
B275006 ^S	CHECK FLAP TRAVEL									Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.460	AFL	4442								
PROC. REF: AMM 27-51-00										PKG:7,109

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 27 - FLIGHT CONTROLS										
B275009 ^S		LEAK CHECK FLAP HYDRAULIC ACTUATORS								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.470	AFL	4442								
PROC. REF: AMM 27-51-04										PKG:7,111
B277001 ^S		INSPECT/OPERATIONAL CHECK CONTROL LOCK SYSTEM								Service ATA:27
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 27.480	AFL	4442								
PROC. REF: AMM 27-71-00										PKG:7,102
C271001 ^S		LUBRICATE/CHECK AILERON TRIM TAB ACTUATOR								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.490	AFL	4502								
PROC. REF: AMM 27-11-00										PKG:2
C272001 ^S		LUBRICATE/CHECK RUDDER TRIM TAB ACTUATOR								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.500	AFL	4502								
PROC. REF: AMM 27-21-00										PKG:2
C273001 ^S		LUBRICATE/CHECK ELEVATOR TRIM TAB ACTUATOR								Service ATA:27
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 27.510	AFL	4502								
PROC. REF: AMM 27-31-00										PKG:2
ATA 28 - FUEL										
28-00-02-220		MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)								Service ATA:28
	MOS/MSC	11-Mar-96	A/R	TAC 0				OPERATOR REQUEST		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 28-00-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
28-00-02-221		MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)							Service	ATA:28
	MOS/MSC	11-Mar-96	A/R	TAC 0				OPERATING TIME LIMIT		
	HRS	0		TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 28-00-02										
280001		LEFT FUEL FLOAT VALVE							Component	ATA:28
PN:9033-201	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.260	AFL	0		TSN 0						
PROC. REF: AMM 28-11-03										
280001		RIGHT FUEL FLOAT VALVE							Component	ATA:28
PN:9033-201	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.260	AFL	0		TSN 0						
PROC. REF: AMM 28-11-03										
280002		LEFT FUEL VENT FLOAT VALVE							Component	ATA:28
PN:35C10D	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.010	AFL	0		TSN 0						
PROC. REF: AMM 28-11-03										
280002		RIGHT FUEL VENT FLOAT VALVE							Component	ATA:28
PN:35C10D	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.010	AFL	0		TSN 0						
PROC. REF: AMM 28-11-03										
280003		LEFT PRESSURE RELIEF VALVE							Component	ATA:28
PN:840203-101	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.100	AFL	0		TSN 0						
PROC. REF: AMM 28-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
280003		RIGHT PRESSURE RELIEF VALVE							Component	ATA:28
PN:840203-101	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.100	AFL	0			TSN 0					
PROC. REF: AMM 28-11-10										
280004		LEFT PILOT HIGH LEVEL VALVE							Component	ATA:28
PN:61087	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.130	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										
280004		RIGHT PILOT HIGH LEVEL VALVE							Component	ATA:28
PN:61087	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.130	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										
280006		LEFT SINGLE POINT REFUEL VALVE							Component	ATA:28
PN:80002-51	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.140	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										
280006		RIGHT SINGLE POINT REFUEL VALVE							Component	ATA:28
PN:80002-51	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.140	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										
280007		LEFT DEFUEL SINGLE PT VALVE							Component	ATA:28
PN:61084	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.150	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										
280007		RIGHT DEFUEL SINGLE PT VALVE							Component	ATA:28
PN:61084	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 28.150	AFL	0			TSN 0					
PROC. REF: AMM 28-22-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
280008	LEFT MANUAL FUEL SHUTOFF VALVE									Component ATA:28
PN:61086	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.190	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
280008	RIGHT MANUAL FUEL SHUTOFF VALVE									Component ATA:28
PN:61086	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 28.190	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
282001	NO. 1 ELECTRIC FUEL BOOST PUMP									Component ATA:28
PN:1C7-12	MOS/MSC	11-Mar-96	O/C							
SN:8AL79	HRS	0		TSN 0						
WC#: 28.060	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
282001	NO. 2 ELECTRIC FUEL BOOST PUMP									Component ATA:28
PN:1C7-12	MOS/MSC	11-Mar-96	O/C							
SN:7AL75	HRS	0		TSN 0						
WC#: 28.060	AFL	0		TSN 0						
PROC. REF: AMM 28-21-01										
282010	LEFT MOTIVE FUEL VALVE									Component ATA:28
PN:3244850-1	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:C29179	HRS			TSO 0						
WC#: 28.120	AFL			TSO 0						
PROC. REF: AMM 28-21-06										
282010	RIGHT MOTIVE FUEL VALVE									Component ATA:28
PN:3244850-1	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:C29168	HRS			TSO 0						
WC#: 28.120	AFL			TSO 0						
PROC. REF: AMM 28-21-06										
284001	NO. 1 FUEL LOW LEVEL SWITCH									Component ATA:28
PN:L15H-3	MOS/MSC	11-Mar-96	O/C							
SN:4629	HRS	0		TSN 0						
WC#: 28.170	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
284001	NO. 2 FUEL LOW LEVEL SWITCH									Component ATA:28
PN:L15H-3	MOS/MSC	11-Mar-96	O/C							
SN:4636	HRS	0		TSN 0						
WC#: 28.170	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
284002	LEFT FUEL QTY COMPENSATOR									Component ATA:28
PN:300047-13001 - 9912019-4	MOS/MSC	20-Apr-23	O/C	TSO 0						
SN:17232T	HRS	5396.4		TSO 0						
WC#: 28.160	AFL	4627		TSO 0						
PROC. REF: AMM 28-41-01										
284002	RIGHT FUEL QTY COMPENSATOR									Component ATA:28
PN:300047-13001	MOS/MSC	11-Mar-96	O/C							
SN:17013	HRS	0		TSN 0						
WC#: 28.160	AFL	0		TSN 0						
PROC. REF: AMM 28-41-01										
A281001 ^S	INSPECT WING FUEL STORAGE AREA									Service ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.200	AFL	4442								
PROC. REF: AMM 28-10-00										PKG:7,109
A282002 ^S	INSPECT WING FUEL SYSTEM COMPONENT									Service ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.210	AFL	4442								
PROC. REF: AMM 28-20-00										PKG:7,109
B282003 ^S	OPERATIONAL CHECK FUEL SYSTEM									Service ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.220	AFL	4442								
PROC. REF: AMM 28-20-00										PKG:7,104

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 28 - FUEL										
B282004 ^S		OPERATIONAL CHECK FUEL SYSTEM							Service	ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.230	AFL	4442								
PROC. REF: AMM 28-20-00										PKG:7,103
B284001 ^S		OPERATIONAL CHECK LOW FUEL WARNING SYSTEM							Service	ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.240	AFL	4442								
PROC. REF: AMM 28-42-00										PKG:7,104
D282002 ^S		CHANGE FUEL FILTER ELEMENT							Service	ATA:28
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 28.250	AFL	4442								
PROC. REF: AMM 28-21-05										PKG:7,109
ATA 29 - HYDRAULIC POWER										
291001		MAIN HYD RESERVOIR							Component	ATA:29
PN:40500-7	MOS/MSC	04-Aug-13	O/C	TSO 0						
SN:84S	HRS	4405.9		TSO 0						
WC#: 29.010	AFL	3945								
PROC. REF: AMM 29-11-01										
291002		LEFT HYDRAULIC PUMP							Component	ATA:29
PN:24195-LAA	MOS/MSC	17-Jul-02	O/C							
SN:3204	HRS	1740		TSN 0						
WC#: 29.050	AFL									
PROC. REF: AMM 29-11-03										
291002		RIGHT HYDRAULIC PUMP							Component	ATA:29
PN:24195-LAA	MOS/MSC	11-Mar-96	O/C							
SN:1848	HRS	0		TSN 0						
WC#: 29.050	AFL	0		TSN 0						
PROC. REF: AMM 29-11-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291005	NO. 1 CK VALVE HYDRAULIC FLOW SWITCH									Component ATA:29
PN:3520020100-4	MOS/MSC	11-Mar-96	O/C							
SN:3729	HRS	0		TSN 0						
WC#: 29.020	AFL	0		TSN 0						
PROC. REF: AMM 29-11-05										
291005	NO. 2 CK VALVE HYDRAULIC FLOW SWITCH									Component ATA:29
PN:3520020100-4	MOS/MSC	11-Mar-96	O/C							
SN:3714	HRS	0		TSN 0						
WC#: 29.020	AFL	0		TSN 0						
PROC. REF: AMM 29-11-05										
291007	NO. 1 MOTOR ACTUATOR VALVE									Component ATA:29
PN:AV24B1325C5	MOS/MSC	11-Mar-96	O/C							
SN:P65811	HRS	0		TSN 0						
WC#: 29.120	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
291007	NO. 2 MOTOR ACTUATOR VALVE									Component ATA:29
PN:AV24B1325C5	MOS/MSC	11-Mar-96	O/C							
SN:P66060	HRS	0		TSN 0						
WC#: 29.120	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
291008	THERMAL RELIEF VALVE									Component ATA:29
PN:OAS5322-3-1700	MOS/MSC	11-Mar-96	O/C							
SN:398	HRS	0		TSN 0						
WC#: 29.030	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
291009	PRESSURE RELIEF VALVE									Component ATA:29
PN:4614	MOS/MSC	11-Mar-96	O/C							
SN:1440A	HRS	0		TSN 0						
WC#: 29.030	AFL	0		TSN 0						
PROC. REF: AMM 28-11-10										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 29 - HYDRAULIC POWER										
291012	SOLENOID BYPASS VALVE									Component ATA:29
PN:61510-1	MOS/MSC	11-Mar-96	O/C							
SN:1184A	HRS	0		TSN 0						
WC#: 29.040	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
A291002 ^S	INSPECT HYDRAULIC SUB-PANEL									Service ATA:29
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 29.100	AFL	4627								
PROC. REF: AMM 29-11-06										
										PKG:1,3,15
D291001 ^S	INSPECT/REPLACE HYDRAULIC FILTERS AND FILTER ELEMENT									Service ATA:29
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 29.110	AFL	4442								
PROC. REF: AMM 29-11-04										
										PKG:7,105
ATA 30 - ICE AND RAIN PROTECTION										
301001	LEFT TEMP CONTROL SL002 SWITCH									Component ATA:30
PN:1173T42-3	MOS/MSC	11-Mar-96	O/C							
SN:1825	HRS	0		TSN 0						
WC#: 30.060	AFL	0		TSN 0						
PROC. REF: AMM 30-11-00										
301001	NO. 1 OUTBRD WING DEICE BOOT									Component ATA:30
PN:P35-5D5230-01	MOS/MSC	29-Mar-14	O/C	TSN 0						
SN:NBX7460	HRS	4673.3		TSN 0						
WC#: 30.020	AFL	4115								
PROC. REF: AMM 30-12-01										
301001	NO. 2 OUTBRD WING DEICE BOOT									Component ATA:30
PN:35-5D5230-02	MOS/MSC	21-Dec-01	O/C							
SN:MU93100	HRS	1572		TSN 0						
WC#: 30.020	AFL									
PROC. REF: AMM 30-12-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301001	RIGHT TEMP CONTROL SR002 SWITCH									Component ATA:30
PN:1173T42-3	MOS/MSC	11-Mar-96	O/C							
SN:1814	HRS	0		TSN 0						
WC#: 30.060	AFL	0		TSN 0						
PROC. REF: AMM 30-11-00										
301001	WING ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE									Component ATA:30
PN:1H123-1	MOS/MSC	23-Feb-15	O/C	TSN 0						
SN:1BE14	HRS	4731.9		TSN 0						
WC#: 30.125	AFL	4166								
PROC. REF: AMM 30-14-00										
301002	NO. 1 HORIZONTAL STABILIZER DEICE BOOT									Component ATA:30
PN:29S-5D5225-03	MOS/MSC	16-Aug-03	O/C							
SN:MU88560	HRS	2034		TSN 0						
WC#: 30.010	AFL									
PROC. REF: AMM 30-12-01, AMM 30-12-01										
301002	NO. 2 HORIZONTAL STABILIZER DEICE BOOT									Component ATA:30
PN:29S-5D5225-04	MOS/MSC	16-Aug-03	O/C							
SN:MU88590	HRS	2034		TSN 0						
WC#: 30.010	AFL									
PROC. REF: AMM 30-12-01, AMM 30-12-01										
301004	LEFT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV									Component ATA:30
PN:67410-2	MOS/MSC	11-Mar-96	O/C							
SN:2849	HRS	0		TSN 0						
WC#: 30.090	AFL	0		TSN 0						
PROC. REF: AMM 30-14-00										
301004	RIGHT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV									Component ATA:30
PN:67410-2	MOS/MSC	11-Mar-96	O/C							
SN:2852	HRS	0		TSN 0						
WC#: 30.090	AFL	0		TSN 0						
PROC. REF: AMM 30-14-00										
301007	LEFT RAM AIR MODULATING TEMP CONTROL VLV									Component ATA:30
PN:27441500-01	MOS/MSC	11-Mar-96	O/C							
SN:10AL91	HRS	0		TSN 0						
WC#: 30.080	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
301007 RIGHT RAM AIR MODULATING TEMP CONTROL VLV									Component	ATA:30
PN:27441500-01	MOS/MSC	11-Mar-96	O/C							
SN:10A102	HRS	0		TSN 0						
WC#: 30.080	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
301008 LEFT DEICE CONTROL SLV19 VLV									Component	ATA:30
PN:3D2353-06	MOS/MSC	11-Mar-96	O/C							
SN:N13281	HRS	0		TSN 0						
WC#: 30.040	AFL	0		TSN 0						
PROC. REF: AMM 30-12-02										
301008 RIGHT DEICE CONTROL SLV18 VLV									Component	ATA:30
PN:3D2353-06	MOS/MSC	11-Mar-96	O/C							
SN:N13270	HRS	0		TSN 0						
WC#: 30.040	AFL	0		TSN 0						
PROC. REF: AMM 30-12-02										
301009 LEFT TEMP CONTROL S95 SENSOR									Component	ATA:30
PN:27431501-04	MOS/MSC	11-Mar-96	O/C							
SN:8AL101	HRS	0		TSN 0						
WC#: 30.070	AFL	0		TSN 0						
PROC. REF: AMM 30-11-00										
301009 RIGHT TEMP CONTROL S94 SENSOR									Component	ATA:30
PN:27431501-04	MOS/MSC	11-Mar-96	O/C							
SN:8AL100	HRS	0		TSN 0						
WC#: 30.070	AFL	0		TSN 0						
PROC. REF: AMM 30-11-00										
302003 LEFT ENGINE ANTI-ICE SOLENOID VALVE									Component	ATA:30
PN:67410-1	MOS/MSC	17-Jul-02	O/C							
SN:591ABCDEG	HRS	1740		TSO 0						
WC#: 30.170	AFL									
PROC. REF: AMM 30-21-00										
302003 RIGHT ENGINE ANTI-ICE SOLENOID VALVE									Component	ATA:30
PN:67410-1	MOS/MSC	17-Jul-02	O/C							
SN:1749BCDEGK	HRS	1740		TSO 0						
WC#: 30.170	AFL									
PROC. REF: AMM 30-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
302005	LEFT ANTI ICING VALVE									Component ATA:30
PN:540-0406-3	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:1033	HRS			TSO 0						
WC#: 30.490	AFL			TSO 0						
PROC. REF: AMM 30-21-01										
302005	RIGHT ANTI ICING VALVE									Component ATA:30
PN:540-0406-3	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:1041	HRS			TSO 0						
WC#: 30.490	AFL			TSO 0						
PROC. REF: AMM 30-21-01										
302006	LEFT BLEED VALVE ACTUATOR									Component ATA:30
PN:800888-1	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:F34451	HRS			TSO 0						
WC#: 30.500	AFL			TSO 0						
PROC. REF: AMM 30-41-01										
302006	RIGHT BLEED VALVE ACTUATOR									Component ATA:30
PN:800888-1	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:F33956	HRS			TSO 0						
WC#: 30.500	AFL			TSO 0						
PROC. REF: AMM 30-41-01										
303001	LEFT PITOT TUBE									Component ATA:30
PN:PH502	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.210	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
303001	RIGHT PITOT TUBE									Component ATA:30
PN:PH502	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.210	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
304001	BLEED AIR MONITOR-									Component ATA:30
PN:1169-1	MOS/MSC	11-Mar-96	O/C							
SN:2275	HRS	0		TSN 0						
WC#: 30.520	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
304002 ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER Component ATA:30										
PN:10663A	MOS/MSC	11-Mar-96	O/C							
SN:849	HRS	0		TSN 0						
WC#: 30.270	AFL	0		TSN 0						
PROC. REF: AMM 30-41-02										
304004 ALCOHOL WINDSHIELD ANTI-ICE PUMP Component ATA:30										
PN:476411	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 30.290	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
304005 TEMP CONTROL VALVE Component ATA:30										
PN:27241287	MOS/MSC	11-Mar-96	O/C							
SN:7AL77	HRS	0		TSN 0						
WC#: 30.530	AFL	0		TSN 0						
PROC. REF: AMM 30-41-02										
304006 ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR Component ATA:30										
PN:27231272-20A	MOS/MSC	11-Mar-96	O/C							
SN:7AL39	HRS	0		TSN 0						
WC#: 30.280	AFL	0		TSN 0						
PROC. REF: AMM 30-41-03										
304007 ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH Component ATA:30										
PN:1115P25	MOS/MSC	11-Mar-96	O/C							
SN:2354A	HRS	0		TSN 0						
WC#: 30.250	AFL	0		TSN 0						
PROC. REF: AMM 30-41-03										
304009 WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE Component ATA:30										
PN:67410-2	MOS/MSC	17-Dec-04	O/C							
SN:3417ABCDEGK	HRS	2347		TSO 0						
WC#: 30.260	AFL									
PROC. REF: AMM 30-41-01										
A301001 ^S INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES Service ATA:30										
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.300	AFL	4502								
PROC. REF: AMM 30-11-00										
										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
A301002 ^S		INSPECT WING HEATED LEADING EDGE AND PLUMBING								Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.310	AFL	4442								
PROC. REF: AMM 30-11-00										PKG:7,109
A301003 ^S		INSPECT WING HEATED LEADING EDGE BLEED AIR COMPONENTS								Service ATA:30
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.320	AFL	4502								
PROC. REF: AMM 30-11-00										PKG:3
A301004 ^S		INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS								Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+30)							
WC#: 30.330	AFL	4442								
PROC. REF: AMM 30-11-00										PKG:7,105
A301005 ^S		INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES								Service ATA:30
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.340	AFL	4502								
PROC. REF: AMM 30-14-00										PKG:2
A301006 ^S		INSPECT WING HEATED LEADING EDGE AND PLUMBING								Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.350	AFL	4442								
PROC. REF: AMM 30-14-00										PKG:7,109
A301008 ^S		INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS								Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.360	AFL	4442								
PROC. REF: AMM 30-14-00										PKG:7,105
A304001 ^S		INSPECT WINDSHIELD BLEED AIR AUGMENTER DOOR AND SHROUD								Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.380	AFL	4442								
PROC. REF: AMM 30-41-00										PKG:7,101

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
A304003 ^S		INSPECT WINDSHIELD BLEED AIR CONTROL							Service	ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.390	AFL	4442								
					PROC. REF: AMM 30-41-04			PKG:7,108		
A304004 ^S		INSPECT WINDSHIELD ALCOHOL RESERVOIR							Service	ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.290	AFL	4442								
					PROC. REF: AMM 30-42-00			PKG:7,100		
B301001 ^S		OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS							Service	ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.400	AFL	4442								
					PROC. REF: AMM 30-11-00			PKG:7,104		
B301003 ^S		OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM							Service	ATA:30
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.420	AFL	4502								
					PROC. REF: AMM 30-12-00			PKG:4		
B301005 ^S		OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS							Service	ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.430	AFL	4442								
					PROC. REF: AMM 30-14-00			PKG:7,104		
B301006 ^S		OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM							Service	ATA:30
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.440	AFL	4502								
					PROC. REF: AMM 30-12-00			PKG:4		
B304001 ^S		OPERATIONAL CHECK WINDSHIELD ANTI-ICE							Service	ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.450	AFL	4442								
					PROC. REF: AMM 30-41-00			PKG:7,102		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 30 - ICE AND RAIN PROTECTION										
B304004 ^S	OPERATIONAL TEST WINDSHIELD ALCOHOL PUMP									Service ATA:30
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 30.460	AFL	4502								
PROC. REF: AMM 30-42-00										PKG:1
D304004 ^S	INSPECT/CLEAN WINDSHIELD ALCOHOL RESERVOIR FILTER									Service ATA:30
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 30.470	AFL	4442								
PROC. REF: AMM 30-42-00										PKG:7,100
ATA 31 - INDICATING/RECORDING SYSTEMS										
312001	COPILOT DIGITAL CLOCK									Component ATA:31
PN:M877A5V	MOS/MSC	11-Mar-96	O/C							
SN:6682	HRS	0		TSN 0						
WC#: 31.010	AFL	0		TSN 0						
PROC. REF: AMM 31-20-01										
312001	PILOT DIGITAL CLOCK									Component ATA:31
PN:M877A5V	MOS/MSC	11-Mar-96	O/C							
SN:6681	HRS	0		TSN 0						
WC#: 31.010	AFL	0		TSN 0						
PROC. REF: AMM 31-20-01										
313001	FLIGHT HOUR RECORDER									Component ATA:31
PN:C664503-0104	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 31.050	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
313003	NO. 1 ACCELEROMETER									Component ATA:31
PN:7000992	MOS/MSC	11-Mar-96	O/C							
SN:7220	HRS	0		TSN 0						
WC#: 31.070	AFL	0		TSN 0						
PROC. REF: AMM 31-30-01, AMM 31-30-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 31 - INDICATING/RECORDING SYSTEMS										
313003	NO. 2 ACCELEROMETER									Component ATA:31
PN:7000992	MOS/MSC	11-Mar-96	O/C							
SN:7221	HRS	0		TSN 0						
WC#: 31.070	AFL	0		TSN 0						
PROC. REF: AMM 31-30-01, AMM 31-30-02										
313008	FDR IMPACT SWITCH									Component ATA:31
PN:6895-D-2-X-5-5	MOS/MSC	11-Mar-96	O/C							
SN:974	HRS	0		TSN 0						
WC#: 31.040	AFL	0		TSN 0						
PROC. REF: AMM 31-30-02, AMM 31-30-03										
315001	MASTER WARNING ANNUNCIATOR									Component ATA:31
PN:465-1-17	MOS/MSC	11-Mar-96	O/C							
SN:597	HRS	0		TSN 0						
WC#: 31.060	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
A313001 ^S	INSPECT FLIGHT DATA RECORDER									Service ATA:31
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 31.020	AFL	4442								
PROC. REF: AMM 31-30-00										PKG:7,106
ATA 32 - LANDING GEAR										
321001	LEFT MAIN LANDING GEAR ASSEMBLY									Component ATA:32
PN:6641000-35	MOS	11-Mar-96						LIFE LIMIT		
SN:180	HRS	0								
WC#: 32.010	AFL	0	11425	TSN 0	11425		6789			
PROC. REF: AMM 32-11-01										
321002	RIGHT MAIN LANDING GEAR ASSEMBLY									Component ATA:32
PN:6641000-36	MOS	11-Mar-96						LIFE LIMIT		
SN:180	HRS	0								
WC#: 32.020	AFL	0	11425	TSN 0	11425		6789			
PROC. REF: AMM 32-11-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
321003		LEFT MAIN LANDING GEAR TORQUE LINK BOLT							Component	ATA:32
PN:5541220-2	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 32.030	AFL	0	9510	TSN 0	9510		4874			
PROC. REF: AMM 32-11-01										
321003		RIGHT MAIN LANDING GEAR TORQUE LINK BOLT							Component	ATA:32
PN:5541220-2	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 32.030	AFL	0	9510	TSN 0	9510		4874			
PROC. REF: AMM 32-11-01										
322001		NOSE LANDING GEAR ASSEMBLY							Component	ATA:32
PN:6642000-34	MOS	11-Mar-96						LIFE LIMIT		
SN:76	HRS	0								
WC#: 32.080	AFL	0	23100	TSN 0	23100		18464			
PROC. REF: AMM 32-21-01										
322002		NOSE SHIMMY DAMPER							Component	ATA:32
PN:5543001-12	MOS/MSC	06-Feb-17	O/C	TSR 0						
SN:710-12X	HRS	4913.3		TSR 0						
WC#: 32.100	AFL	4280		TSR 0						
PROC. REF: AMM 32-21-02										
322004		NOSE GEAR FORK/PISTON							Component	ATA:32
PN:6642000-3	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 32.090	AFL	0	13380	TSN 0	13380		8744			
PROC. REF: AMM 32-21-01										
323001		LEFT MAIN LANDING GEAR ACTUATOR							Component	ATA:32
PN:1523100-7	MOS	13-Nov-09						LIFE LIMIT		
SN:468	HRS	3357								
WC#: 32.160	AFL	3031	15000	TSN 2299	15732		11096			
PROC. REF: AMM 32-31-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323002 RIGHT MAIN LANDING GEAR ACTUATOR										
PN:1523100-8	MOS	13-Feb-13						LIFE LIMIT		Component ATA:32
SN:468	HRS	4265.4								
WC#: 32.160	AFL	3843	15000	TSN 3834	15009		10373			
PROC. REF: AMM 32-31-04										
323003 NOSE LANDING GEAR ACTUATOR										
PN:1523200-9	MOS	06-Jan-06						LIFE LIMIT		Component ATA:32
SN:1613	HRS	2497								
WC#: 32.170	AFL	2299	15000	TSN 0	17299		12663			
PROC. REF: AMM 32-31-03										
323004 LEFT MLG UPLOCK ACTUATOR										
PN:5527504-2	MOS/MSC	08-Feb-07	O/C							Component ATA:32
SN:WMP3573	HRS	2763								
WC#: 32.110	AFL	2507		TSN 0						
PROC. REF: AMM 32-31-05										
323004 NOSE UPLOCK ACTUATOR										
PN:5527504-2	MOS/MSC	11-Mar-96	O/C							Component ATA:32
SN:1658	HRS	0								
WC#: 32.120	AFL	0		TSN 0						
PROC. REF: AMM 32-31-05										
323004 RIGHT MLG UPLOCK ACTUATOR										
PN:5527504-2	MOS/MSC	09-Mar-10	O/C							Component ATA:32
SN:WMP3576	HRS	3449								
WC#: 32.110	AFL	3110		TSN 0						
PROC. REF: AMM 32-31-05										
323006 PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE										
PN:9912103-3	MOS	07-Jan-21	288	TSO 0	31-Oct-23		187 d			Component ATA:32
SN:2547	HRS	5121.9		TSO 0						
WC#: 32.180	AFL	4427		TSO 0						
Manufacture Date:: 01-Oct-99 PROC. REF: AMM GENERIC										
323007 LANDING GEAR CONTROL VALVE										
PN:66710	MOS/MSC	11-Mar-96	O/C							Component ATA:32
SN:696	HRS	0								
WC#: 32.200	AFL	0		TSN 0						
PROC. REF: AMM 32-31-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
323008	DUMP VALVE									Component ATA:32
PN:OAS5319-1	MOS/MSC	11-Mar-96	O/C							
SN:433	HRS	0		TSN 0						
WC#: 32.130	AFL	0		TSN 0						
PROC. REF: AMM 32-31-06										
323019	EMERGENCY AIR BOTTLE GAUGE									Component ATA:32
PN:2341128	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:57219A	HRS	0								
WC#: 32.190	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
324001	LEFT MLG WHEEL ASSEMBLY									Component ATA:32
PN:3-1490-1	MOS/MSC	30-Nov-22	O/C							
SN:1360	HRS	5294.9		TSN 1000						
WC#: 32.340	AFL	4559		TSN 150						
PROC. REF: AMM 32-41-01, AMM 32-41-01										
324001	RIGHT MLG WHEEL ASSEMBLY									Component ATA:32
PN:3-1490-1	MOS/MSC	11-Mar-96	O/C							
SN:2449	HRS	0								
WC#: 32.350	AFL	0								
PROC. REF: AMM 32-41-01, AMM 32-41-01										
324002	NOSE WHEEL ASSEMBLY									Component ATA:32
PN:3-1418	MOS/MSC	20-Apr-23	O/C							
SN:5425	HRS	5396.4								
WC#: 32.360	AFL	4627								
PROC. REF: AMM 32-41-02										
324003	LEFT MLG BRAKE ASSEMBLY									Component ATA:32
PN:2-1529-7	MOS/MSC	01-Feb-16	O/C	TSO 0						
SN:2922	HRS	4835.1		TSO 0						
WC#: 32.230	AFL	4233		TSO 0						
PROC. REF: AMM 32-42-01										
324004	RIGHT MLG BRAKE ASSEMBLY									Component ATA:32
PN:2-1529-7	MOS/MSC	01-Feb-16	O/C	TSO 0						
SN:3974P	HRS	4835.1		TSO 0						
WC#: 32.230	AFL	4233		TSO 0						
PROC. REF: AMM 32-42-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324005	LEFT MLG TIRE									Component ATA:32
PN:220K28-1	MOS/MSC	01-Dec-22	O/C							
SN:80402670	HRS	5294.9		TSN 1000						
WC#: 32.340	AFL	4559		TSN 150						
PROC. REF: AMM 32-41-01										
324005	RIGHT MLG TIRE									Component ATA:32
PN:220K28-1	MOS/MSC	25-Jul-22	O/C	TSN 0						
SN:12870462	HRS	5230		TSN 0						
WC#: 32.350	AFL	4503		TSN 0						
PROC. REF: AMM 32-41-01										
324006	NOSE TIRE									Component ATA:32
PN:031613-8	MOS/MSC	20-Apr-23	O/C	TSN 0						
SN:2295T00371	HRS	5396.4		TSN 0						
WC#: 32.360	AFL	4627		TSN 0						
PROC. REF: AMM 32-41-02										
324010	LEFT MLG SHUTTLE VALVE									Component ATA:32
PN:195-183	MOS/MSC	11-Mar-96	O/C							
SN:3226	HRS	0								
WC#: 32.210	AFL	0		TSN 0						
PROC. REF: AMM 32-31-08										
324010	RIGHT MLG SHUTTLE VALVE									Component ATA:32
PN:195-183	MOS/MSC	11-Mar-96	O/C							
SN:3233	HRS	0								
WC#: 32.210	AFL	0		TSN 0						
PROC. REF: AMM 32-31-08										
324011	LEFT MLG INBOARD BRAKE MASTER CYLINDER									Component ATA:32
PN:95367-9	MOS/MSC	11-Mar-96	O/C							
SN:1063	HRS	0								
WC#: 32.280	AFL	0		TSN 0						
PROC. REF: AMM 32-42-02										
324011	RIGHT MLG INBOARD BRAKE MASTER CYLINDER									Component ATA:32
PN:95367-9	MOS/MSC	31-Jul-98	O/C							
SN:1140	HRS	731								
WC#: 32.290	AFL	702		TSN 0						
PROC. REF: AMM 32-42-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324012	LEFT MLG OUTBOARD MASTER BRAKE CYLINDER									Component ATA:32
PN:95367-10	MOS/MSC	11-Mar-96	O/C							
SN:1265	HRS	0								
WC#: 32.280	AFL	0		TSN 0						
PROC. REF: AMM 32-42-02										
324012	RIGHT MLG OUTBOARD MASTER BRAKE CYLINDER									Component ATA:32
PN:12A085-12	MOS/MSC	01-Jul-01	O/C							
SN:2457	HRS	1467								
WC#: 32.290	AFL	1379		TSN 0						
PROC. REF: AMM 32-42-02										
324014	EMERGENCY AIR BRAKE VALVE									Component ATA:32
PN:895232-04	MOS/MSC	30-Apr-12	O/C							
SN:V141	HRS	4013								
WC#: 32.330	AFL	3688								
PROC. REF: AMM GENERIC										
324019	BRAKE PRESS PUMP ASSEMBLY									Component ATA:32
PN:634343	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 32.310	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
324021	POWER BRAKE ANTISKID VALVE									Component ATA:32
PN:38-707-2	MOS/MSC	11-Mar-96	O/C							
SN:888	HRS	0		TSN 0						
WC#: 32.240	AFL	0		TSN 0						
PROC. REF: AMM 32-42-05										
324022	BRAKE CONTROL BOX									Component ATA:32
PN:42-927-1	MOS/MSC	31-Jul-98	O/C							
SN:179	HRS	731		TSO 0						
WC#: 32.250	AFL									
PROC. REF: AMM GENERIC										
324023	ANTISKID ACCUMULATOR									Component ATA:32
PN:57C57652	MOS/MSC	11-Mar-96	O/C							
SN:RH0877	HRS	0		TSN 0						
WC#: 32.260	AFL	0		TSN 0						
PROC. REF: AMM 32-42-06										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324024	LEFT MLG WHEEL TRANSDUCER									Component ATA:32
PN:40-955	MOS/MSC	11-Mar-96	O/C							
SN:3454	HRS	0		TSN 0						
WC#: 32.220	AFL	0		TSN 0						
PROC. REF: AMM 32-42-07										
324024	RIGHT MLG WHEEL TRANSDUCER									Component ATA:32
PN:40-955	MOS/MSC	11-Mar-96	O/C							
SN:3457	HRS	0		TSN 0						
WC#: 32.220	AFL	0		TSN 0						
PROC. REF: AMM 32-42-07										
324025	PRESSURE SWITCH									Component ATA:32
PN:1206P27	MOS/MSC	11-Mar-96	O/C							
SN:2369	HRS	0								
WC#: 32.320	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
324026	POWER BRAKE ASSEMBLY MOTOR									Component ATA:32
PN:MP50B1	MOS/MSC	11-Mar-96	O/C							
SN:482	HRS	0		TSN 0						
WC#: 32.300	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
324027	FAULT DISPLAY UNIT									Component ATA:32
PN:42-92750	MOS/MSC	11-Mar-96	O/C							
SN:208A	HRS	0		TSN 0						
WC#: 32.270	AFL	0		TSN 0						
PROC. REF: AMM 32-42-00										
324101	PARKING BRAKE VALVE									Component ATA:32
PN:95905	MOS/MSC	11-Mar-96	O/C							
SN:283A	HRS	0		TSN 0						
WC#: 32.330	AFL	0		TSN 0						
PROC. REF: AMM 32-42-03										
324201	NON DESTRUCTIVE TEST RIGHT MLG WHEEL ASSEMBLY									Service ATA:32
PN:3-1490-1	MOS/MSC	25-Jul-22	T/C							
SN:2449	HRS	5230								
WC#: 32.350	AFL	4503								
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
324202	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY									Service ATA:32
PN:3-1418	MOS/MSC	20-Apr-23	T/C							
SN:5425	HRS	5396.4								
WC#: 32.360	AFL	4627								
PROC. REF: AMM GENERIC										
325001	NOSE STEERING BUNGEE ASSEMBLY									Component ATA:32
PN:5565624-19	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.370	AFL	0		TSN 0						
PROC. REF: AMM 32-51-00										
326003	LEFT MAIN GEAR DOWN & LOCK SWITCH									Component ATA:32
PN:1EN118-6	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.380	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
326003	NOSE GEAR DOWN & LOCK SWITCH									Component ATA:32
PN:1EN118-6	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.390	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
326003	RIGHT MAIN GEAR DOWN & LOCK SWITCH									Component ATA:32
PN:1EN118-6	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.380	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
326005	LEFT MAIN GEAR UP & LOCKED SWITCH									Component ATA:32
PN:65-430087	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.400	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
326005	NOSE GEAR UP & LOCKED SWITCH									Component ATA:32
PN:65-430087	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.410	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
326005	RIGHT MAIN GEAR UP & LOCKED SWITCH									Component ATA:32
PN:65-430087	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0								
WC#: 32.400	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
A320001 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR									Service ATA:32
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 32-00-00										PKG:503
A320002 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR									Service ATA:32
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 32-00-00										PKG:22
A321001 ^S	INSPECT MAIN LANDING GEAR									Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.460	AFL	4502								
PROC. REF: AMM 32-11-01										PKG:2
A321002 ^S	CHECK MAIN GEAR STRUT EXTENSION									Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.470	AFL	4502								
PROC. REF: AMM 32-11-01										PKG:2
A321003 ^S	INSPECT MAIN LANDING GEAR									Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.480	AFL	4502								
PROC. REF: AMM 32-11-02										PKG:2
A322001 ^S	INSPECT SHIMMY DAMPER									Service ATA:32
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 32.100	AFL	4627								
PROC. REF: AMM 32-21-02										PKG:2,4,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
A322002 ^S		INSPECT NOSE GEAR ASSEMBLY							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.080	AFL	4502								
						PROC. REF: AMM 32-21-01		PKG:2		
A323002 ^S		INSPECT NOSE GEAR UPLOCK							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.490	AFL	4502								
						PROC. REF: AMM 32-31-05		PKG:2		
A323003 ^S		INSPECT EMERGENCY GEAR EXTENSION SYSTEM CABLE							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.500	AFL	4442								
						PROC. REF: AMM 32-31-08		PKG:7,111		
A323004 ^S		INSPECT MAIN GEAR UPLOCK							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.510	AFL	4502								
						PROC. REF: AMM 32-31-05		PKG:2		
A323005 ^S		INSPECT MAIN GEAR UPLOCK							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.510	AFL	4502								
						PROC. REF: AMM 32-31-05		PKG:2		
A324001 ^S		INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.520	AFL	4502								
						PROC. REF: AMM 32-41-01		PKG:2		
A324002 ^S		INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.360	AFL	4502								
						PROC. REF: AMM 32-41-02		PKG:2		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
A324003 ^S		INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING (WITH GRAVEL RUNWAY)								Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.360	AFL	4502								
PROC. REF: AMM 32-41-02										PKG:2
A324004 ^S		INSPECT BRAKE MASTER CYLINDER								Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.360	AFL	4502								
PROC. REF: AMM 32-42-02										PKG:1
A324005 ^S		INSPECT EMERGENCY BRAKE CONTROL VALVE								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.530	AFL	4442								
PROC. REF: AMM 32-42-09										PKG:7,101
A324007 ^S		INSPECT BRAKE RESERVOIR AND ANTISKID SYSTEM COMPONENTS								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.540	AFL	4442								
PROC. REF: AMM 32-42-00										PKG:7,100
A324012 ^S		INSPECT MAIN LANDING GEAR WHEEL BRAKE								Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.550	AFL	4502								
PROC. REF: AMM 32-42-01										PKG:2
A324013 ^S		INSPECT BRAKE METERING VALVE								Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.560	AFL	4502								
PROC. REF: AMM 32-42-10										PKG:2
A324014 ^S		INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING								Service ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.520	AFL	4502								
PROC. REF: AMM 32-41-01										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
A325001 ^S		INSPECT NOSE STEERING ARM SUPPORT BRACKET, BUNGEE AND BELLCRANK							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.570	AFL	4442								
					PROC. REF: AMM 32-51-00			PKG:7,103		
A325002 ^S		INSPECT NOSE STEERING SYSTEM CABLE							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.580	AFL	4442								
					PROC. REF: AMM 32-51-00			PKG:7,111		
A325003 ^S		INSPECT GRAVEL RUNWAY/NOSE WHEEL SPIN-UP COMPONENTS							Service	ATA:32
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 32.590	AFL	4627								
					PROC. REF: AMM 32-43-00			PKG:2,4,15		
A325004 ^S		INSPECT NOSE WHEEL SPIN-UP CONTROL							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.600	AFL	4502								
					PROC. REF: AMM 32-43-00			PKG:2		
A325009		INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK							Service	ATA:32
PN:6642000-3	MOS	11-Mar-96						AIRWORTHINESS		
SN:UNKNOWN	HRS	0								
WC#: 32.090	AFL	0	T:10000		10000		5364			
					PROC. REF: AMM 32-21-01			PKG:74		
B324006 ^S		CHECK MAIN GEAR WHEEL BRAKES WEAR							Service	ATA:32
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 32.620	AFL	4627								
					PROC. REF: AMM 32-42-01			PKG:2,4,15		
B324008 ^S		OPERATIONAL CHECK ANTISKID BRAKE SYSTEM							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.630	AFL	4442								
					PROC. REF: AMM 32-42-00			PKG:7,104		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
B324009 ^S		OPERATIONAL TEST EMERGENCY BRAKE SYSTEM							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.640	AFL	4442								
					PROC. REF: AMM 32-42-09			PKG:7,104		
B325001 ^S		FUNCTIONAL TEST NOSE WHEEL SPIN-UP SYSTEM							Service	ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.650	AFL	4442								
					PROC. REF: AMM 32-43-00			PKG:7,104		
B326001 ^S		ADJUSTMENT/TEST LANDING GEAR HYDRAULIC SYSTEMS							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.660	AFL	4502								
					PROC. REF: AMM 32-01-00			PKG:2		
B326002 ^S		CYCLE TEST LANDING GEAR							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.670	AFL	4502								
					PROC. REF: AMM 32-01-00			PKG:2		
B326003		HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE							Service	ATA:32
PN:9912103-3	MOS	04-Jan-21	36		31-Jan-24		279 d			
SN:2547	HRS									
WC#: 32.180	AFL									
					PROC. REF: AMM 32-31-09					
B326004 ^S		PERFORM LANDING GEAR HYDRAULIC SYSTEMS TEST							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.680	AFL	4502								
					PROC. REF: AMM 32-01-00			PKG:2		
C325013 ^S		INSPECT NOSE WHEEL INNER AXLE							Service	ATA:32
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 32.700	AFL	4502								
					PROC. REF: AMM 32-41-02			PKG:2		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 32 - LANDING GEAR										
D324007 ^S		REPLACE ANTISKID SYSTEM MOTOR/PUMP FILTER								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.710	AFL	4442								
PROC. REF: AMM 32-42-00										PKG:7,100
D324010 ^S		REPLACE BRAKE RESERVOIR AIR FILTER								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.720	AFL	4442								
PROC. REF: AMM 32-42-00										PKG:7,100
D324011 ^S		CLEAN BRAKE RESERVOIR SUPPLY LINE FILTER								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.730	AFL	4442								
PROC. REF: AMM 32-42-00										PKG:7,100
D324012 ^S		CLEAN MASTER CYLINDER IN-LINE FILTER								Service ATA:32
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 32.760	AFL	4442								
PROC. REF: AMM 32-42-02										PKG:7,100
ATA 33 - LIGHTS										
331001		NO. 1 LIGHT PANEL DIMMER								Component ATA:33
PN:273-1	MOS/MSC	11-Mar-96	O/C							
SN:3627	HRS	0		TSN 0						
WC#: 33.150	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
331001		NO. 2 LIGHT PANEL DIMMER								Component ATA:33
PN:273-1	MOS/MSC	11-Mar-96	O/C							
SN:3641	HRS	0		TSN 0						
WC#: 33.150	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
331001	NO. 3 LIGHT PANEL DIMMER									Component ATA:33
PN:273-1	MOS/MSC	11-Mar-96	O/C							
SN:3659	HRS	0		TSN 0						
WC#: 33.150	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
331011	INVT-115V EL PANEL									Component ATA:33
PN:EM2044-1	MOS/MSC	07-Apr-99	O/C							
SN:2470A	HRS	913		TSN 0						
WC#: 33.160	AFL									
PROC. REF: AMM 33-11-01										
332001	NO. 1 CU31 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.030	AFL	0		TSN 0						
PROC. REF: AMM 33-21-01										
332001	NO. 10 CF001 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.070	AFL	0		TSN 0						
PROC. REF: AMM 33-21-01										
332001	NO. 2 CU30 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.030	AFL	0		TSN 0						
PROC. REF: AMM 33-21-01										
332001	NO. 3 CU29 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.040	AFL	0		TSN 0						
PROC. REF: AMM 33-21-01										
332001	NO. 4 CU28 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 33.040	AFL	0		TSN 0						
PROC. REF: AMM 33-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
332001	NO. 5 CU27 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 33.050	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332001	NO. 6 CU26 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 33.050	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332001	NO. 7 CU25 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 33.060	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332001	NO. 8 CU24 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 33.060	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332001	NO. 9 CF002 INDIRECT LIGHT POWER UNIT									Component ATA:33
PN:AL-5112	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 33.070	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332002	AFT INDIRECT LIGHTING INVERTER									Component ATA:33
PN:AL0581	MOS/MSC	11-Mar-96	O/C							
SN:9028	HRS	0			TSN 0					
WC#: 33.020	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										
332002	FORWARD INDIRECT LIGHTING INVERTER									Component ATA:33
PN:AL5114	MOS/MSC	11-Mar-96	O/C							
SN:5762	HRS	0			TSN 0					
WC#: 33.010	AFL	0			TSN 0					
PROC. REF: AMM 33-21-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
334002	ROTATING/FLASHING BEACON									Component ATA:33
PN:30-2140-5	MOS/MSC	13-Oct-08	O/C							
SN:0076	HRS	3101		TSO 0						
WC#: 33.080	AFL									
PROC. REF: AMM 33-42-02										
334003	NO. 1 STROBE POWER SUPPLY									Component ATA:33
PN:60-2799-1	MOS/MSC	11-Mar-96	O/C							
SN:16998	HRS	0		TSN 0						
WC#: 33.090	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
334003	NO. 2 STROBE POWER SUPPLY									Component ATA:33
PN:60-2799-1	MOS/MSC	11-Mar-96	O/C							
SN:16976	HRS	0		TSN 0						
WC#: 33.090	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
335001	EMERGENCY BATTERY PACK									Component ATA:33
PN:CBS28-1	MOS/MSC	08-Jun-22	O/C	TSO 0						
SN:4695M	HRS	5229.6		TSO 0						
WC#: 33.080	AFL	4502								
PROC. REF: AMM 33-51-01										
A332001 ^S	INSPECT INDIRECT CABIN FLUORESCENT LIGHTING									Service ATA:33
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 33.100	AFL	4442								
PROC. REF: AMM 33-21-01										
										PKG:7,103
A335001 ^S	INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES									Service ATA:33
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 33.110	AFL	4442								
PROC. REF: AMM 33-51-01										
										PKG:7,101
A335002 ^S	INSPECT EMERGENCY EXIT LIGHTS									Service ATA:33
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 33.120	AFL	4502								
PROC. REF: AMM 33-51-01										
										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 33 - LIGHTS										
A335003 ^S		INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES							Service	ATA:33
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 33.130	AFL	4442								
					PROC. REF: AMM 33-51-01			PKG:7,101		
B335001 ^S		OPERATIONAL CHECK EMERGENCY LIGHTS							Service	ATA:33
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 33.140	AFL	4502								
					PROC. REF: AMM 33-51-01			PKG:1		
ATA 34 - NAVIGATION										
340201 ^U		FMS NAV DATABASE UPDATES							Service	ATA:34
	MOS/MSC	20-Apr-23	DUE		18-May-23 (M)		21 d			
	HRS	5396.4								
	AFL	4627								
341006		PITOT PRESSURE SWITCH							Component	ATA:34
PN:D45C31	MOS/MSC	23-Feb-15	O/C	TSN 0						
SN:1054	HRS	4731.9		TSN 0						
WC#: 34.751	AFL	4166								
					PROC. REF: AMM 34-11-10					
341010		ANGLE OF ATTACK INDICATOR							Component	ATA:34
PN:C11605-1	MOS/MSC	11-Mar-96	O/C							
SN:494	HRS	0		TSN 0						
WC#: 34.050	AFL	0		TSN 0						
					PROC. REF: AMM 34-13-06					
341011		ANGLE OF ATTACK STALL WARNING COMPUTER							Component	ATA:34
PN:C11606-8	MOS/MSC	21-Jan-98	O/C							
SN:299	HRS	595		TSN 0						
WC#: 34.070	AFL									
					PROC. REF: AMM 34-13-06					
341013		ANGLE OF ATTACK TRANSMITTER							Component	ATA:34
PN:1703-15	MOS/MSC	16-Dec-10	O/C							
SN:516	HRS	3716.2		TSO 0						
WC#: 34.080	AFL	3311								
					PROC. REF: AMM 34-13-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
341014		ANGLE OF ATTACK INDEXER							Component	ATA:34
PN:965-0113-008	MOS/MSC	11-Mar-96	O/C							
SN:1399	HRS	0			TSN 0					
WC#: 34.060	AFL	0			TSN 0					
PROC. REF: AMM 34-13-06										
341015		PILOT RADIO ALTIMETER ALT-55B INDICATOR							Component	ATA:34
PN:622-2937-009	MOS/MSC	11-Mar-96	O/C							
SN:AJ691	HRS	0			TSN 0					
WC#: 34.100	AFL	0			TSN 0					
PROC. REF: AMM 34-12-02										
341019		STANDBY ALTIMETER							Component	ATA:34
PN:WL102AMS6	MOS/MSC	12-Feb-15	O/C		TSO 1					
SN:AJ399	HRS	4731.9			TSO 0					
WC#: 34.160	AFL	4166								
PROC. REF: AMM 34-11-02										
341022		OAT INDICATOR							Component	ATA:34
PN:C307FCL	MOS/MSC	21-Jun-12	O/C		TSN 0					
SN:A11137	HRS	4052.7			TSN 0					
WC#: 34.200	AFL	3702								
PROC. REF: AMM 34-11-05										
341035		ANGLE OF ATTACK HEAT MONITOR-							Component	ATA:34
PN:1703-147-2	MOS/MSC	16-Dec-10	O/C							
SN:504	HRS	3716.2			TSO 0					
WC#: 34.030	AFL	3311								
PROC. REF: AMM GENERIC										
342001		MAGNETIC COMPASS							Component	ATA:34
PN:C660501-0301	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 34.220	AFL	0			TSN 0					
PROC. REF: AMM 34-21-01										
342023		RADAR CONTROLLER							Component	ATA:34
PN:7008471-607	MOS/MSC	11-Mar-96	O/C							
SN:95092230	HRS	0			TSN 0					
WC#: 34.897	AFL	0			TSN 0					
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342042	NO. 1 MODE FLIGHT DIRECTOR SELECTOR									Component ATA:34
PN:7018341-909	MOS/MSC	21-Dec-01	O/C							
SN:95090479	HRS	1572			TSO 1572					
WC#: 34.250	AFL									
PROC. REF: AMM 34-22-01										
342042	NO. 2 MODE FLIGHT DIRECTOR SELECTOR									Component ATA:34
PN:7018341-909	MOS/MSC	21-Dec-01	O/C							
SN:95080432	HRS	1572			TSO 1572					
WC#: 34.250	AFL									
PROC. REF: AMM 34-22-01										
342043	NO. 1 VERTICAL FLIGHT DIRECTOR GYRO									Component ATA:34
PN:7000622-901 - VG-14A	MOS/MSC	20-Apr-23	O/C							
SN:89066422	HRS	5396.4								
WC#: 34.360	AFL	4627								
PROC. REF: AMM 34-22-01										
342043	NO. 2 VERTICAL FLIGHT DIRECTOR GYRO									Component ATA:34
PN:7000622-901	MOS/MSC	06-Feb-17	O/C		TSO 0					
SN:98048531	HRS	4913.3			TSO 0					
WC#: 34.360	AFL	4280			TSO 0					
PROC. REF: AMM 34-22-01										
342044	NO. 1 RATE OF TURN GYRO									Component ATA:34
PN:7007453-903	MOS/MSC	11-Nov-08	O/C							
SN:08065881	HRS	3134			TSN 0					
WC#: 34.350	AFL									
PROC. REF: AMM 34-22-01										
342048	NO. 1 AIR DATA COMPUTER									Component ATA:34
PN:7014700-905	MOS/MSC	17-Dec-04	O/C							
SN:95050410	HRS	2347			TSO 5585					
WC#: 34.140	AFL									
PROC. REF: AMM 34-14-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342048	NO. 2 AIR DATA COMPUTER									Component ATA:34
PN:7014700-601	MOS/MSC	16-Jan-18	O/C							
SN:96100949	HRS	4985.7								
WC#: 34.140	AFL	4323								
PROC. REF: AMM 34-14-04										
342049	NO. 1 DIRECTIONAL GYRO									Component ATA:34
PN:4020577-3	MOS/MSC	27-Jun-06	O/C							
SN:97056192	HRS	2613		TSO 0						
WC#: 34.340	AFL									
PROC. REF: AMM 34-21-05										
342049	NO. 2 DIRECTIONAL GYRO									Component ATA:34
PN:4020577-3	MOS/MSC	07-Oct-03	O/C							
SN:84103441	HRS	2063		TSO 0						
WC#: 34.340	AFL									
PROC. REF: AMM 34-21-05										
342050	NO. 1 FLUX DETECTOR									Component ATA:34
PN:2594484	MOS/MSC	13-Oct-08	O/C							
SN:93030424	HRS	3101		TSO 2785						
WC#: 34.390	AFL									
PROC. REF: AMM 34-21-16										
342050	NO. 2 FLUX DETECTOR									Component ATA:34
PN:2594484	MOS/MSC	29-Mar-18	O/C	TSR 0						
SN:94050909	HRS	4999		TSR 0						
WC#: 34.390	AFL	4329		TSR 0						
PROC. REF: AMM 34-21-16										
342052	REMOTE COMPENSATOR									Component ATA:34
PN:2593379-1	MOS/MSC	11-Mar-96	O/C							
SN:95091599	HRS	0		TSN 0						
WC#: 34.230	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
342053	STANDBY HSI INDICATOR									Component ATA:34
PN:520-3150-002	MOS/MSC	09-May-07	O/C							
SN:23814	HRS	2810		TSO 342						
WC#: 34.270	AFL									
PROC. REF: AMM 34-23-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 34 - NAVIGATION											
342063		NO. 1 REMOTE COURSE CONTROL								Component	ATA:34
PN:7016954-903	MOS/MSC	24-May-21	O/C	TSR 0							
SN:95030301	HRS	5149.5	TSN 5149.5, TSR 0								
WC#: 34.260	AFL	4442	TSN 4442, TSR 0								
PROC. REF: AMM GENERIC											
342065		STANDBY GYRO								Component	ATA:34
PN:501-1197-05	MOS/MSC	26-Dec-14	O/C	TSO 0							
SN:5276	HRS	4714.9	TSO 0								
WC#: 34.380	AFL	4159									
PROC. REF: AMM 34-21-12											
342069		MULTIFUNCTION DISPLAY CONTROLLER								Component	ATA:34
PN:7007062-941	MOS/MSC	11-Mar-96	O/C								
SN:95111590	HRS	0	TSN 0								
WC#: 34.300	AFL	0	TSN 0								
PROC. REF: AMM 34-23-02											
342072		STATIC CONVERTER								Component	ATA:34
PN:501-1318-01	MOS/MSC	11-Mar-96	O/C								
SN:4265	HRS	0	TSN 0								
WC#: 34.330	AFL	0	TSN 0								
PROC. REF: GENERIC NO REF											
342078		NO. 1 DISPLAY GUIDANCE COMPUTER								Component	ATA:34
PN:7017000-80162	MOS/MSC	15-Dec-09	O/C								
SN:97051082	HRS	3387	TSO 2359								
WC#: 34.791	AFL										
PROC. REF: AMM 34-23-02											
342078		NO. 2 DISPLAY GUIDANCE COMPUTER								Component	ATA:34
PN:7017000-81162	MOS/MSC	21-Dec-01	O/C								
SN:95120672	HRS	1572	TSO 1572								
WC#: 34.791	AFL										
PROC. REF: AMM 34-23-02											
342079		COPILOT PRIMARY FLIGHT DISPLAY CONTROLLER								Component	ATA:34
PN:7016986-707	MOS/MSC	11-Mar-96	O/C								
SN:95090572	HRS	0	TSN 0								
WC#: 34.290	AFL	0	TSN 0								
PROC. REF: AMM 34-20-02											

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342079	PILOT PRIMARY FLIGHT DISPLAY CONTROLLER									Component ATA:34
PN:7016986-707	MOS/MSC	11-Mar-96	O/C							
SN:95090583	HRS	0		TSN 0						
WC#: 34.290	AFL	0		TSN 0						
PROC. REF: AMM 34-20-02										
342080	CNTR EFIS DISPLAY									Component ATA:34
PN:7014300-901	MOS/MSC	13-Aug-11	O/C							
SN:98063389	HRS	3943.3								
WC#: 34.793	AFL	3512								
PROC. REF: AMM 34-20-02										
342080	NO. 1 EFIS DISPLAY									Component ATA:34
PN:7014300-901	MOS/MSC	27-Apr-23	O/C							
SN:98022779	HRS	5409.2		TSN 10031.2						
WC#: 34.793	AFL	4636		TSN 8028						
PROC. REF: AMM 34-20-02										
342080	NO. 2 EFIS DISPLAY									Component ATA:34
PN:7014300-901	MOS/MSC	13-Aug-08	O/C							
SN:0202B110	HRS	3065		TSO 0						
WC#: 34.793	AFL									
PROC. REF: AMM 34-20-02										
342081	MFD BEZEL DISPLAY UNIT									Component ATA:34
PN:7014332-841	MOS/MSC	21-Nov-22	O/C							
SN:06027859	HRS	5281.3		TSR 0						
WC#: 34.797	AFL	4547		TSR 0						
PROC. REF: AMM 34-23-02										
342081	NO. 1 BEZEL DISPLAY UNIT									Component ATA:34
PN:7014331-921	MOS/MSC	11-Mar-96	O/C							
SN:95030353	HRS	0		TSN 0						
WC#: 34.795	AFL	0		TSN 0						
PROC. REF: AMM 34-23-02										
342081	NO. 2 BEZEL DISPLAY UNIT									Component ATA:34
PN:7014331-921	MOS/MSC	11-Mar-96	O/C							
SN:95050404	HRS	0		TSN 0						
WC#: 34.795	AFL	0		TSN 0						
PROC. REF: AMM 34-23-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
342176		PS-835 EMERGENCY POWER SUPPLY							Component	ATA:34
PN:501-1228-03	MOS/MSC	08-Jun-22	O/C							
SN:7181	HRS	5229.6								
WC#: 34.370	AFL	4502								
PROC. REF: AMM 34-21-12										
344003		PRIMUS 650 RADAR RECEIVER/TRANSMITTER							Component	ATA:34
PN:7008470-822	MOS/MSC	11-Mar-96	O/C							
SN:95091563	HRS	0		TSN 0						
WC#: 34.410	AFL	0		TSN 0						
PROC. REF: AMM 34-40-03										
344022		RADIO ALT TRANSCEIVER							Component	ATA:34
PN:622-2855-011	MOS/MSC	11-Mar-96	O/C							
SN:10058	HRS	0		TSN 0						
WC#: 34.110	AFL	0		TSN 0						
PROC. REF: AMM 34-12-02, AMM 34-12-03, AMM 34-12-10										
344023		AFT RECEIVER RADIO ALT ANTENNA							Component	ATA:34
PN:622-0954-001	MOS/MSC	11-Mar-96	O/C							
SN:6111	HRS	0		TSN 0						
WC#: 34.120	AFL	0		TSN 0						
PROC. REF: AMM 34-12-10										
344023		FORWARD TRANSMITTER RADIO ALT ANTENNA							Component	ATA:34
PN:622-0954-001	MOS/MSC	11-Mar-96	O/C							
SN:6109	HRS	0		TSN 0						
WC#: 34.120	AFL	0		TSN 0						
PROC. REF: AMM 34-12-10										
344024		GROUND PROXIMITY WARNING SYS COMPUTER							Component	ATA:34
PN:965-1199-005	MOS/MSC	17-Dec-04	O/C							
SN:2386	HRS	2347		TSN 0						
WC#: 34.430	AFL									
PROC. REF: AMM 34-41-01, AMM 34-41-03										
345004		AFT TRANSPONDER ANTENNA							Component	ATA:34
PN:DMNI50-2-2	MOS/MSC	11-Mar-96	O/C							
SN:60749	HRS	0		TSN 0						
WC#: 34.420	AFL	0		TSN 0						
PROC. REF: AMM 34-42-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345004	FORWARD TRANSPONDER ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	11-Mar-96	O/C							
SN:60747	HRS	0			TSN 0					
WC#: 34.420	AFL	0			TSN 0					
PROC. REF: AMM 34-42-01										
345005	TEMPERATURE PROBE									Component ATA:34
PN:102DB1AG	MOS/MSC	11-Mar-96	O/C							
SN:A7826	HRS	0			TSN 0					
WC#: 34.150	AFL	0			TSN 0					
PROC. REF: AMM 34-14-12										
345007	AFT DME ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	11-Mar-96	O/C							
SN:60754	HRS	0			TSN 0					
WC#: 34.520	AFL	0			TSN 0					
PROC. REF: AMM 34-53-02										
345007	FORWARD DME ANTENNA									Component ATA:34
PN:DMNI50-2-2	MOS/MSC	11-Mar-96	O/C							
SN:60752	HRS	0			TSN 0					
WC#: 34.520	AFL	0			TSN 0					
PROC. REF: AMM 34-53-02										
345010	NO. 1 NAVIGATION ANTENNA									Component ATA:34
PN:CI120-1-L	MOS/MSC	17-Jul-02	O/C							
SN:1073916	HRS	1740			TSN 0					
WC#: 34.420	AFL									
PROC. REF: AMM 34-52-03										
345010	NO. 2 NAVIGATION ANTENNA									Component ATA:34
PN:CI120-1-L	MOS/MSC	17-Jul-02	O/C							
SN:1073917	HRS	1740			TSN 0					
WC#: 34.815	AFL									
PROC. REF: AMM 34-52-03										
345011	NO. 1 ADF RECEIVER									Component ATA:34
PN:622-7382-101	MOS/MSC	11-Mar-96	O/C							
SN:3354	HRS	0			TSN 0					
WC#: 34.450	AFL	0			TSN 0					
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345012		NO. 1 ADF CONTROL								Component ATA:34
PN:622-6522-005	MOS/MSC	09-May-07	O/C							
SN:10705	HRS	2810			TSO 2810					
WC#: 34.450	AFL									
PROC. REF: AMM 34-51-01										
345014		NO. 1 ADF ANTENNA								Component ATA:34
PN:622-7383-001	MOS/MSC	11-Mar-96	O/C							
SN:2331	HRS	0			TSN 0					
WC#: 34.450	AFL	0			TSN 0					
PROC. REF: AMM 34-51-01										
345015 ^U		LP/LPV MONITOR-								Component ATA:34
PN:3116-52-1110	MOS/MSC	16-Jan-18	O/C		TSN 0					
SN:2284	HRS	4985.7			TSN 0					
	AFL	4323			TSN 0					
345017		MARKER BEACON ANTENNA								Component ATA:34
PN:31-10-01	MOS/MSC	11-Mar-96	O/C							
SN:2419	HRS	0			TSN 0					
WC#: 34.400	AFL	0			TSN 0					
PROC. REF: AMM 25-61-01										
345018		GLIDESLOPE ANTENNA								Component ATA:34
PN:RGS10-48	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 34.400	AFL	0			TSN 0					
PROC. REF: AMM 34-32-00										
345031		NAVIGATION(FMS) COMPUTER								Component ATA:34
PN:3019-41-201	MOS/MSC	16-Jan-18	O/C		TSN 0					
SN:1049	HRS	4985.7			TSN 0					
WC#: 34.835	AFL	4323			TSN 0					
PROC. REF: AMM 34-14-02										
345032		NO. 1 VHF NAV RECEIVER								Component ATA:34
PN:622-7194-201	MOS/MSC	11-Mar-96	O/C							
SN:2654	HRS	0			TSN 0					
WC#: 34.825	AFL	0			TSN 0					
PROC. REF: AMM 34-52-04										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345032		NO. 2 VHF NAV RECEIVER							Component	ATA:34
PN:622-7194-201	MOS/MSC	11-Mar-96	O/C							
SN:2629	HRS	0		TSN 0						
WC#: 34.825	AFL	0		TSN 0						
PROC. REF: AMM 34-52-04										
345033		BOTTOM VHF NAV CONTROL							Component	ATA:34
PN:622-6521-013	MOS/MSC	09-May-07	O/C							
SN:16424	HRS	2810		TSO 2810						
WC#: 34.911	AFL									
PROC. REF: AMM GENERIC										
345033		VHF NAV CONTROL							Component	ATA:34
PN:622-6521-013	MOS/MSC	09-May-07	O/C							
SN:16421	HRS	2810		TSO 2810						
WC#: 34.911	AFL									
PROC. REF: AMM GENERIC										
345034		NO. 1 ATC TRANSPONDER							Component	ATA:34
PN:622-9352-501	MOS/MSC	16-Jan-18	O/C	TSN 0						
SN:485V77	HRS	4985.7		TSN 0						
WC#: 34.550	AFL	4323		TSN 0						
PROC. REF: AMM 34-54-01										
345034		NO. 2 ATC TRANSPONDER							Component	ATA:34
PN:622-9352-501	MOS/MSC	16-Jan-18	O/C	TSN 0						
SN:485VGR	HRS	4985.7		TSN 0						
WC#: 34.550	AFL	4323		TSN 0						
PROC. REF: AMM 34-54-01										
345035		NO. 1 DME INDICATOR							Component	ATA:34
PN:7513006-911	MOS/MSC	11-Mar-96	O/C							
SN:6514	HRS	0		TSN 0						
WC#: 34.500	AFL	0		TSN 0						
PROC. REF: AMM 34-53-02										
345035		NO. 2 DME INDICATOR							Component	ATA:34
PN:622-7318-001	MOS/MSC	31-Mar-97	O/C							
SN:6453	HRS	308		TSO 308						
WC#: 34.500	AFL									
PROC. REF: AMM 34-53-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345036		NO. 1 DME RECEIVER TRANSMITTER								Component ATA:34
PN:622-7309-101	MOS/MSC	11-Mar-96	O/C							
SN:2346	HRS	0			TSN 0					
WC#: 34.530	AFL	0			TSN 0					
PROC. REF: AMM 34-53-01										
345036		NO. 2 DME RECEIVER TRANSMITTER								Component ATA:34
PN:622-7309-101	MOS/MSC	04-Oct-01	O/C							
SN:2341	HRS	1508			TSO 1492					
WC#: 34.530	AFL									
PROC. REF: AMM 34-53-01										
345040		TRANSPONDER CONTROL								Component ATA:34
PN:822-1807-003	MOS/MSC	16-Jan-18	O/C		TSN 0					
SN:486M4C	HRS	4985.7			TSN 0					
WC#: 34.869	AFL	4323			TSN 0					
PROC. REF: AMM 34-54-01, AMM 34-54-03										
345042		NO. 1 LOOP VLF COUPLER								Component ATA:34
PN:30490-1	MOS/MSC	11-Mar-96	O/C							
SN:2372	HRS	0			TSN 0					
WC#: 34.833	AFL	0			TSN 0					
PROC. REF: AMM 34-55-01, AMM 34-55-02										
345053		VLF ANTENNA								Component ATA:34
PN:11455-2	MOS/MSC	11-Mar-96	O/C							
SN:8421	HRS	0			TSN 0					
WC#: 34.837	AFL	0			TSN 0					
PROC. REF: AMM 34-55-01, AMM 34-55-02										
345062		LORAN ANTENNA								Component ATA:34
PN:121-014379-01	MOS/MSC	11-Mar-96	O/C							
SN:1467	HRS	0			TSN 0					
WC#: 34.841	AFL	0			TSN 0					
PROC. REF: AMM 34-61-00, AMM 34-61-01										
345064		FMS-CONFIGURATION MODULE								Component ATA:34
PN:17680-01	MOS/MSC	11-Mar-96	O/C							
SN:743	HRS	0			TSN 0					
WC#: 34.843	AFL	0			TSN 0					
PROC. REF: AMM 34-42-03										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
345077		DATA TRANSFER UNIT							Component	ATA:34
PN:1408-00-1	MOS/MSC	16-Jan-18	O/C	TSN 0						
SN:3969	HRS	4985.7		TSN 0						
WC#: 34.919	AFL	4323		TSN 0						
PROC. REF: AMM 34-61-05										
345081		NO. 1 CONFIGURATION MODULE							Component	ATA:34
PN:30191	MOS/MSC	16-Jan-18	O/C	TSN 0						
SN:1167	HRS	4985.7		TSN 0						
WC#: 34.470	AFL	4323		TSN 0						
PROC. REF: AMM 34-61-05										
345082		NO. 1 GNS/FMS DISPLAY							Component	ATA:34
PN:17450-0406-0702	MOS/MSC	25-Apr-14	O/C							
SN:124	HRS	4692.3								
WC#: 34.857	AFL	4126								
PROC. REF: AMM 34-61-03										
345093		GPS ANTENNA							Component	ATA:34
PN:S67-1575-39	MOS/MSC	17-Dec-04	O/C							
SN:14987	HRS	2347		TSN 0						
WC#: 34.490	AFL									
PROC. REF: AMM 34-61-01										
345093		NO. 1 GPS ANTENNA							Component	ATA:34
PN:10708	MOS/MSC	16-Jan-18	O/C	TSN 0						
SN:10338	HRS	4985.7		TSN 0						
WC#: 34.865	AFL	4323		TSN 0						
PROC. REF: AMM 34-61-01										
345093		NO. 2 GPS ANTENNA							Component	ATA:34
PN:10708	MOS/MSC	16-Jan-18	O/C							
SN:10520	HRS	4985.7								
WC#: 34.865	AFL	4323								
PROC. REF: AMM 34-61-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
346001		TCAS PROCESSOR							Component	ATA:34
PN:066-01145-0101	MOS/MSC	29-Nov-22	O/C	TSR 0						
SN:2172	HRS	5291.5		TSR 0						
WC#: 34.560	AFL	4557		TSR 0						
PROC. REF: AMM 34-42-01										
346002		BOTTOM TCAS ANTENNA							Component	ATA:34
PN:071-01548-0100	MOS/MSC	11-Mar-96	O/C							
SN:6060	HRS	0		TSN 0						
WC#: 34.570	AFL	0		TSN 0						
PROC. REF: AMM 34-40-05, AMM 34-42-00, AMM 34-42-01										
346002		TOP TCAS ANTENNA							Component	ATA:34
PN:071-01548-0100	MOS/MSC	11-Mar-96	O/C							
SN:6371	HRS	0		TSN 0						
WC#: 34.570	AFL	0		TSN 0						
PROC. REF: AMM 34-40-05, AMM 34-42-00, AMM 34-42-01										
346004		CONTROL TCAS							Component	ATA:34
PN:071-01568-0901	MOS/MSC	21-Jun-12	O/C							
SN:2259	HRS	4052.7								
WC#: 34.690	AFL	3702								
PROC. REF: AMM 34-42-01										
34FO-06 560/C		FMS DATA LOADER(PORTABLE) GLOBAL GNS-X FACTORY OPTION							Component	ATA:34
PN:695C	MOS/MSC	11-Mar-96	-							
SN:FO	HRS	0								
	AFL	0								
PROC. REF: AMM GENERIC										
A341008		PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0260 AND ON CERTIFIED FOR RVSM)							Service	ATA:34
	MOS	22-Dec-21	24		31-Dec-23		248 d			
	HRS	5180								
WC#: 34.590	AFL	4468								
PROC. REF: AMM 34-11-10										PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
A341009 ^S		PERFORM SAFE FLIGHT ANGLE-OF-ATTACK SYSTEM CHECK							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.600	AFL	4442								
					PROC. REF: AMM 34-13-06					PKG:7,101
A342001 ^S		INSPECT MAGNETIC COMPASS AND COMPASS CARD							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.620	AFL	4442								
					PROC. REF: AMM 34-21-01					PKG:7,101
B341002 ^S		OPERATIONAL TEST TELEDYNE ANGLE-OF-ATTACK SYSTEM							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.640	AFL	4442								
					PROC. REF: AMM 34-13-00					PKG:7,105
B341003		CALIBRATION TEST STANDBY ALTIMETER (91.411)							Service	ATA:34
PN:WL102AMS6	MOS	21-Dec-21	24		31-Dec-23		248 d			
SN:AJ399	HRS									
WC#: 34.761	AFL									
					PROC. REF: AMM 34-14-00					PKG:24
B341010		CALIBRATION TEST NO. 1 AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643							Service	ATA:34
PN:7014700-905	MOS	21-Dec-21	24		31-Dec-23		248 d			
SN:95050410	HRS									
WC#: 34.939	AFL									
					PROC. REF: AMM 34-11-25					PKG:24
B341010		CALIBRATION TEST NO. 2 AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643							Service	ATA:34
PN:7014700-601	MOS	21-Dec-21	24		31-Dec-23		248 d			
SN:96100949	HRS									
WC#: 34.939	AFL									
					PROC. REF: AMM 34-11-25					PKG:24
B341301 ^S		OPERATIONAL CHECK TELEDYNE PRIMARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.879	AFL	4442								
					PROC. REF: AMM 34-13-00					PKG:7,101

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
B341302 ^S		OPERATIONAL CHECK TELEDYNE SECONDARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.879	AFL	4442								
PROC. REF: AMM 34-13-00										PKG:7,101
B341303 ^S		PERFORM TELEDYNE ANGLE-OF-ATTACK SYSTEM FLIGHT CALIBRATION							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.881	AFL	4442								
PROC. REF: AMM 34-13-00										PKG:7,101
B341304 ^S		OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM CHECK(AIRPLANES -0056 THRU -0538)							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.881	AFL	4442								
PROC. REF: AMM 34-13-02										PKG:7,101
B341305 ^S		OPERATIONAL CHECK SAFE FLIGHT SECONDARY ANGLE OF ATTACK SYSTEM CHECK(AIRPLANES -0400 THRU -0538. IF INSTALLED)							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.883	AFL	4442								
PROC. REF: AMM 34-13-05										PKG:7,101
B341306 ^S		OPERATIONAL CHECK TELEDYNE PRIMARY ANGLE OF ATTACK SYSTEM ANTI-ICE MODE TEST(AIRPLANES 0001 THRU -0055 INCORPORATING SB560-34-70)							Service	ATA:34
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 34.883	AFL	4627								
PROC. REF: AMM 34-13-00										PKG:2,4,15
B341307 ^S		OPERATIONAL CHECK TELEDYNE SECONDARY ANGLE OF ATTACK SYSTEM ANTI-ICE MODE TEST(AIRPLANES 0001 THRU -0055 INCORPORATING SB560-34-70)							Service	ATA:34
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 34.885	AFL	4627								
PROC. REF: AMM 34-13-00										PKG:2,4,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
B341308 ^S		OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM ICE MODE CHECK(AIRPLANES -0056 THRU -0538)							Service	ATA:34
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 34.885	AFL	4627								
PROC. REF: AMM 34-13-02										PKG:2,4,15
B341309 ^S		OPERATIONAL CHECK SAFE FLIGHT SECONDARY ANGLE OF ATTACK SYSTEM ICE MODE CHECK(AIRPLANES -0400 THRU -0538, IF INSTALLED)							Service	ATA:34
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 34.887	AFL	4627								
PROC. REF: AMM 34-13-05										PKG:2,4,15
B341310 ^S		PERFORM SAFE FLIGHT ANGLE OF ATTACK SYSTEM FLIGHT CALIBRATION(AIRPLANES -0056 THRU -0538)							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+2)							
WC#: 34.680	AFL	4442								
PROC. REF: AMM 34-13-02										PKG:7,101
B341311 ^S		PERFORM SAFE FLIGHT SECONDARY ANGLE OF ATTACK SYSTEM FLIGHT CALIBRATION(AIRPLANES -0400 THU -0538,IF INSTALLED)							Service	ATA:34
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 34.680	AFL	4442								
PROC. REF: AMM 34-13-05										PKG:7,101
B342001 ^S		OPERATIONAL TEST MAGNETIC COMPASS SYSTEMS AND ADF BEARING							Service	ATA:34
PN:C660501-0301	MOS	24-May-21	36 (+2m)							
SN:UNKNOWN	HRS	5149.5	1200 (+100)							
WC#: 34.710	AFL	4442								
PROC. REF: AMM 34-21-05										PKG:7,105
B342003 ^S		CAPACITY TEST PS-835 EMERGENCY POWER SUPPLY							Service	ATA:34
PN:501-1228-03	MOS	24-May-21	12 (+1m)							
SN:7181	HRS	5149.5								
WC#: 34.370	AFL	4442								
PROC. REF: AMM 34-21-12										PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 34 - NAVIGATION										
B342004 ^S		PERIODIC CHECK PS-835 EMERGENCY POWER SUPPLY								Service ATA:34
PN:501-1228-03	MOS	20-Apr-23	6 (+1m)							
SN:7181	HRS	5396.4								
WC#: 34.370	AFL	4627								
PROC. REF: AMM 34-21-12										PKG:16
B345001		CALIBRATION TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								Service ATA:34
PN:622-9352-501	MOS	21-Dec-21	24		31-Dec-23		248 d			
SN:485V77	HRS									
WC#: 34.550	AFL									
PROC. REF: AMM 34-54-00										PKG:24
B345001		CALIBRATION TEST NO. 2 ATC TRANSPONDER (FAR 91.413)								Service ATA:34
PN:622-9352-501	MOS	21-Dec-21	24		31-Dec-23		248 d			
SN:485VGR	HRS									
WC#: 34.550	AFL									
PROC. REF: AMM 34-54-00										PKG:24
ATA 35 - OXYGEN										
350004		HYDROSTATIC TEST OXYGEN CYLINDER								Service ATA:35
PN:176176-64	MOS	24-May-21	60		31-May-26		1130 d			
SN:828813	HRS									
WC#: 35.010	AFL									
PROC. REF: AMM 35-10-00										
351001		OXYGEN PRESSURE GAUGE								Component ATA:35
PN:C668512-0101	MOS/MSC	07-Apr-99	O/C	TSO 0						
SN:252	HRS	913								
WC#: 35.020	AFL									
PROC. REF: AMM 35-10-00										
351002		OXYGEN PRESSURE SWITCH								Component ATA:35
PN:P24031	MOS/MSC	07-Apr-99	O/C							
SN:1982	HRS	913		TSN 0						
WC#: 35.100	AFL									
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
351004	COPILOT OXYGEN MASK									Component ATA:35
PN:174252-17	MOS/MSC	24-May-21	O/C	TSR 0						
SN:01929	HRS	5149.5		TSR 0						
WC#: 35.030	AFL	4442		TSR 0						
PROC. REF: AMM 35-10-01										
351004	PILOT OXYGEN MASK									Component ATA:35
PN:174252-17	MOS/MSC	24-May-21	O/C	TSR 0						
SN:02491	HRS	5149.5		TSR 0						
WC#: 35.030	AFL	4442		TSR 0						
PROC. REF: AMM 35-10-01										
351005	OXYGEN SUPPLY REGULATOR									Component ATA:35
PN:172170-01	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:1693	HRS	0								
WC#: 35.050	AFL	0		TSN 0						
PROC. REF: AMM 35-10-00										
351006	OXYGEN CYLINDER									Component ATA:35
PN:176176-64	MOS	24-May-21	288		31-Oct-29		2379 d	LIFE LIMIT		
SN:828813	HRS	5149.5								
WC#: 35.010	AFL	4442								
Manufacture Date:: 01-Oct-05 PROC. REF: AMM 35-10-00										
A351001 ^S	INSPECT OXYGEN SYSTEM									Service ATA:35
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 35.040	AFL	4442								
PROC. REF: AMM 35-00-05										
										PKG:7,108
A351007 ^S	INSPECT PASSENGER OXYGEN MASKS									Service ATA:35
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
WC#: 35.060	AFL	4502								
PROC. REF: AMM 35-20-00										
										PKG:22
B350006 ^S	FUNCTIONAL TEST OXYGEN SYSTEM, FLOW FUSES AND SHUTTLE VALVES									Service ATA:35
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 35.070	AFL	4442								
PROC. REF: AMM 35-10-00										
										PKG:7,108

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 35 - OXYGEN										
B351002 ^S		FUNCTIONAL TEST OXYGEN SYSTEM								Service ATA:35
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 35.080	AFL	4442								
PROC. REF: AMM 35-10-00										PKG:7,108
B351003 ^S		OPERATIONAL CHECK CREW OXYGEN MASK INSPECTION, FLOW CHECK AND MICROPHONE								Service ATA:35
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 35.090	AFL	4442								
PROC. REF: AMM 35-10-01										PKG:7,107
ATA 36 - PNEUMATIC										
361003		PNEUMATIC REGULATOR								Component ATA:36
PN:38E85-5C	MOS/MSC	07-Apr-99	O/C							
SN:B2438	HRS	913		TSN 0						
WC#: 36.100	AFL									
PROC. REF: AMM 36-11-00										
361008		NO. 1 VALVE CHECK								Component ATA:36
PN:1553-00-18	MOS/MSC	11-Mar-96	O/C							
SN:1102	HRS	0		TSN 0						
WC#: 36.080	AFL	0		TSN 0						
PROC. REF: AMM 36-11-00										
361008		NO. 2 VALVE CHECK								Component ATA:36
PN:1553-00-18	MOS/MSC	11-Mar-96	O/C							
SN:1068	HRS	0		TSN 0						
WC#: 36.080	AFL	0		TSN 0						
PROC. REF: AMM 36-11-00										
A361004 ^S		INSPECT BLEED AIR CHECK VALVES (PART NUMBER 07E54-2, 1H95-2 AND 1H95-3) - INSPECT (AIRPLANES -0001 THRU -0259, NOT INCORPORATING SB560-36-01)								Service ATA:36
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 36.030	AFL	4502								
PROC. REF: AMM 36-11-00										PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 36 - PNEUMATIC											
A361005 ^S		LEAK CHECK ENGINE BLEED AIR BELLOWS								Service	ATA:36
	MOS	08-Jun-22	24 (+2m)								
	HRS	5229.6	300 (+30)								
WC#: 36.040	AFL	4502									
						PROC. REF: AMM 36-10-00		PKG:4			
A361101 ^S		LEAK CHECK TAILCONE BLEED AIR LINES								Service	ATA:36
	MOS	08-Jun-22	24 (+2m)								
	HRS	5229.6	300 (+30)								
WC#: 36.160	AFL	4502									
						PROC. REF: AMM 36-11-00		PKG:4			
A361102 ^S		DETAILED INSPECTION TAILCONE BLEED AIR LINE PERI-SEALS								Service	ATA:36
	MOS	08-Jun-22	24 (+2m)								
	HRS	5229.6	300 (+30)								
WC#: 36.160	AFL	4502									
						PROC. REF: AMM 36-11-01		PKG:4			
D361100 ^S		REPLACEMENT OF SERVICE AIR SYSTEM PERI-SEAL								Service	ATA:36
	MOS	24-May-21	36 (+2m)								
	HRS	5149.5	1200 (+100)								
WC#: 36.170	AFL	4442									
						PROC. REF: AMM 36-11-01		PKG:7,106			
ATA 37 - VACUUM											
D371001 ^S		CLEAN/REPLACE VACUUM REGULATOR (PRESSURE LINE)								Service	ATA:37
	MOS	24-May-21	36 (+2m)								
	HRS	5149.5	1200 (+100)								
WC#: 37.010	AFL	4442									
						PROC. REF: AMM 37-11-00		PKG:7,106			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 38 - WATER/WASTE										
383002	MOTOR AND PUMP TOILET									Component ATA:38
PN:17200-382	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 38.010	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
B383001 ^S	OPERATIONAL CHECK REFRESHMENT CENTER DRAINS									Service ATA:38
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 38.020	AFL	4442								
PROC. REF: AMM 38-30-00										PKG:7,110
ATA 51 - STD PRACTICES AND STRUCT-GENRL										
A510001 ^S	INSPECT EXTERIOR MOISTURE DRAIN HOLES									Service ATA:51
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 51.010	AFL	4502								
PROC. REF: AMM 51-10-00										PKG:1
ATA 52 - DOORS										
521001	CABIN DOOR SEAL									Component ATA:52
PN:S15501-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 52.010	AFL	0		TSN 0						
PROC. REF: AMM 52-10-01										
521002	EMERGENCY EXIT SEAL									Component ATA:52
PN:R881204	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 52.010	AFL	0		TSN 0						
PROC. REF: AMM 52-20-01										
A521001 ^S	INSPECT STANDARD CABIN DOOR INFLATABLE SEAL									Service ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.030	AFL	4442								
PROC. REF: AMM 52-10-01										PKG:7,101

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
A521003 ^S		INSPECT STANDARD CABIN DOOR								Service ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.040	AFL	4442								
PROC. REF: AMM 52-10-01										PKG:7,101
A521004 ^S		INSPECT STANDARD CABIN DOOR LOCKING PINS								Service ATA:52
	MOS	16-Jan-18								
	HRS	4985.7	5000 (+10)							
WC#: 52.050	AFL	4323								
PROC. REF: AMM 52-10-02										PKG:17
A521005 ^S		INSPECT STANDARD CABIN DOOR LOCKING COMPONENTS BEARING PLATES								Service ATA:52
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:10000 (+10)	TAC 0						
WC#: 52.060	AFL	0		TAC 0						
PROC. REF: AMM 52-10-02										PKG:20
A521006 ^S		INSPECT OPTIONAL ROTARY LATCHING CARGO CABIN DOOR								Service ATA:52
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 52.070	AFL	4502								
PROC. REF: AMM 52-10-04										PKG:1
A521007 ^S		VISUAL INSPECTION OPTIONAL PIN LATCHING CARGO CABIN DOOR								Service ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.080	AFL	4442								
PROC. REF: AMM 52-10-05										PKG:7,101
A521008 ^S		INSPECT ENTRANCE DOOR SECONDARY SEAL								Service ATA:52
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 52.090	AFL	4627								
PROC. REF: AMM 52-10-01										PKG:1,3,15
A522002 ^S		INSPECT EMERGENCY EXIT DOOR								Service ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.100	AFL	4442								
PROC. REF: AMM 52-20-01										PKG:7,100

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 52 - DOORS										
A523001 ^S		INSPECT NOSE BAGGAGE DOOR AND LATCHES							Service	ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.110	AFL	4442								
						PROC. REF: AMM 52-30-01		PKG:7,100		
A523002 ^S		INSPECT TAILCONE DOORS							Service	ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.120	AFL	4442								
						PROC. REF: AMM 52-30-01		PKG:7,105		
A526001 ^S		INSPECT STANDARD CABIN DOOR STEP							Service	ATA:52
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 52.130	AFL	4502								
						PROC. REF: AMM 52-60-01		PKG:1		
A526002 ^S		INSPECT STANDARD CABIN DOOR COMPOSITE STEP							Service	ATA:52
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 52.140	AFL	4502								
						PROC. REF: AMM 52-60-01		PKG:1		
B521008 ^S		OPERATIONAL TEST CABIN ENTRANCE DOOR SECONDARY SEAL							Service	ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.150	AFL	4442								
						PROC. REF: AMM 21-30-00		PKG:7,101		
B527001 ^S		INSPECT/OPERATIONAL CHECK DOOR WARNING SYSTEM							Service	ATA:52
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 52.160	AFL	4502								
						PROC. REF: AMM 52-70-01		PKG:1		
C521002 ^S		LUBRICATE CABIN DOOR HINGE							Service	ATA:52
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 52.170	AFL	4442								
						PROC. REF: AMM 52-10-01		PKG:7,101		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
531001		LEFT NOSE LANDING GEAR TRUNNION SUPPORT							Component	ATA:53
PN:6613056-3	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 53.080	AFL	0	11820	TSN 0	11820		7184			
PROC. REF: AMM GENERIC										
531001		RIGHT NOSE LANDING GEAR TRUNNION SUPPORT							Component	ATA:53
PN:6613056-4	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 53.080	AFL	0	11820	TSN 0	11820		7184			
PROC. REF: AMM GENERIC										
531202		NOSE LANDING GEAR ACTUATOR FITTING							Component	ATA:53
PN:6511105-1	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 53.070	AFL	0	23100	TSN 0	23100		18464			
PROC. REF: AMM GENERIC										
535000		RADOME							Component	ATA:53
PN:6313101-829-1	MOS/MSC	13-Oct-08	O/C							
SN:251	HRS	3101		TSO 0						
WC#: 53.020	AFL									
PROC. REF: AMM 53-50-02										
539001. ^U		PERFORM STRUCTURAL INSPECTION OF THE UNS-1LW CDU, UNS-1 ESPW CDU, LP/LPV MONITOR AND INSTALLATION EQUIPMENT							Service	ATA:53
	MOS	22-Sep-22	36		30-Sep-25		887 d	ICA		
	HRS	5240.1	1200		6440.1		1030.9			
	AFL	4514								
539002 ^U		PERFORM VISUAL INSPECTION OF THE UNS-1LW CDU, UNS-1 ESPW CDU, LP/LPV MONITOR AND INSTALLATION EQUIPMENT							Service	ATA:53
	MOS	22-Sep-22	36		30-Sep-25		887 d	ICA		
	HRS	5240.1	1200		6440.1		1030.9			
	AFL	4514								
539003 ^U		INSPECT UNS-1 WIRING INSTALLATION FOR SECURITY, SIGNS OF WEAR, CHAFING AND ARCING							Service	ATA:53
	MOS	23-Sep-22	36		30-Sep-25		887 d	ICA		
	HRS	5240.1	1200		6440.1		1030.9			
	AFL	4514								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
539004 ^U		INSPECT FULLY EXPOSED UNS-1 ESPW WIRING								Service ATA:53
	MOS		360		15-Jan-48 (M)		9029 d	ICA		
	HRS		12000		16985.7 (M)		11576.5			
	AFL									
A530001 ^S		INSPECT NOSE LANDING GEAR WHEEL WELL GENERAL VISUAL (CORROSION INSPECTION)								Service ATA:53
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 53-00-00										PKG:22
A530002 ^S		NOSE LANDING GEAR WHEEL WELL GENERAL VISUALINSPECTION (CORROSION INSPECTION)								Service ATA:53
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 53-00-00										PKG:503
A531001 ^S		INSPECT FORWARD SIDE OF PRESSURE BULKHEAD								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.140	AFL	4442								
PROC. REF: AMM 53-10-00										PKG:7,100
A531002 ^S		INSPECT UNDERFLOOR								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.150	AFL	4442								
PROC. REF: AMM 53-20-08										PKG:7,111
A531003 ^S		GENERAL INSPECTION AFT PRESSURE BULKHEAD TAILCONE								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.160	AFL	4442								
PROC. REF: AMM 53-20-04										PKG:7,105
A531004 ^S		INSPECT FRONT AND REAR SPAR CARRY-THRU								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.170	AFL	4442								
PROC. REF: AMM 53-10-09										PKG:7,111

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
A531006 ^S		INSPECT EMERGENCY EXIT DOOR FRAME							Service	ATA:53
	MOS	16-Feb-14						AIRWORTHINESS		
	HRS	4624.7	1456							
WC#: 53.190	AFL	4085								
PROC. REF: AMM 53-10-09										PKG:70
A531007 ^S		INSPECT WINDSHIELD, COCKPIT SIDE WINDOW AND CABIN WINDOW FRAMES							Service	ATA:53
	MOS	03-Feb-09		TAC 0				AIRWORTHINESS		
	HRS	3186	5130	TAC 0						
WC#: 53.200	AFL			TAC 0						
PROC. REF: AMM 53-30-00										PKG:76
A531008 ^S		INSPECT FUSELAGE INTERIOR CABIN STRUCTURE							Service	ATA:53
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 53.210	AFL	4502								
PROC. REF: AMM 53-10-09										PKG:1
A531009 ^S		INSPECT CABIN STRUCTURE							Service	ATA:53
	MOS	11-Mar-96		TAC 0						
	HRS	0	10000 (+10)	TAC 0						
WC#: 53.220	AFL	0		TAC 0						
PROC. REF: AMM 53-10-00										PKG:21
A531010 ^S		INSPECT OPTIONAL CARGO DOOR AND DOOR FRAME							Service	ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.230	AFL	4442								
PROC. REF: AMM 53-10-09										PKG:7
A531011 ^S		INSPECT MAIN CARRY-THRU TO WING SPAR LUGS							Service	ATA:53
	MOS	05-Jan-14								
	HRS	4566.4	T:10000 (+10)							
WC#: 53.240	AFL	4081								
PROC. REF: AMM 53-10-00										PKG:504
A531012 ^S		INSPECT CABIN DOOR THRESHOLD							Service	ATA:53
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 53.250	AFL	4502								
PROC. REF: AMM 53-10-09										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
A531013 ^S	INSPECT FORWARD PRESSURE BULKHEAD ATTACH ANGLES									Service ATA:53
	MOS	11-Mar-96		TAC 0				AIRWORTHINESS		
	HRS	0	6725	TAC 0						
WC#: 53.260	AFL	0		TAC 0						
PROC. REF: AMM 53-10-00										PKG:78
A531014 ^S	INSPECT AFT PRESSURE BULKHEAD ATTACH ANGLES									Service ATA:53
	MOS	11-Mar-96		TAC 0				AIRWORTHINESS		
	HRS	0	6725	TAC 0						
WC#: 53.270	AFL	0		TAC 0						
PROC. REF: AMM 53-10-00										PKG:78
A531015 ^S	INSPECT AFT PRESSURE BULKHEAD WEB									Service ATA:53
	MOS	11-Mar-96		TAC 0						
	HRS	0	6725 (+10)	TAC 0						
WC#: 53.280	AFL	0		TAC 0						
PROC. REF: AMM 53-10-04										PKG:48
A531016 ^S	INSPECT CABIN DOORFRAME									Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.290	AFL	4442								
PROC. REF: AMM 53-10-00										PKG:7,103
A531017 ^S	INSPECT MAIN SPAR CARRY-THRU ASSEMBLY									Service ATA:53
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:12000 (+10)	TAC 0						
WC#: 53.300	AFL	0		TAC 0						
PROC. REF: AMM 53-10-09										PKG:18
A531019 ^S	INSPECT WING ATTACH BOLT AND LUG									Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.310	AFL	4442								
PROC. REF: AMM 53-10-09										PKG:7,109
A531020 ^S	INSPECT FORWARD SIDE OF FORWARD PRESSURE BULKHEAD WEB									Service ATA:53
	MOS	17-Jul-02		TAC 0				AIRWORTHINESS		
	HRS	1740	4450	TAC 0						
WC#: 53.320	AFL			TAC 0						
PROC. REF: AMM 53-10-00										PKG:72

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
A531021 ^S		INSPECT AFT SIDE OF AFT PRESSURE BULKHEAD WEB								Service ATA:53
	MOS	17-Jul-02		TAC 0				AIRWORTHINESS		
	HRS	1740	4450	TAC 0						
WC#: 53.330	AFL			TAC 0						
PROC. REF: AMM 53-10-04										PKG:72
A531023 ^S		INSPECT CABIN DOOR FRAME (AIRPLANES -0046 AND ON)								Service ATA:53
	MOS	17-Jul-02						AIRWORTHINESS		
	HRS	1740	5000							
WC#: 53.460	AFL									
PROC. REF: AMM 53-10-10										PKG:73
A531037 ^S		INSPECT STUB WING SHEAR ATTACH FITTING BOLT								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.350	AFL	4442								
PROC. REF: AMM 53-10-02										PKG:7,109
A532001 ^S		INSPECT CONTROL PEDESTAL AREA								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.360	AFL	4442								
PROC. REF: AMM 53-20-02										PKG:7,102
A532002 ^S		INSPECT NOSE GEAR WHEEL WELL								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.370	AFL	4442								
PROC. REF: AMM 53-10-09										PKG:7,103
A532003 ^S		INSPECT AFT CABIN UNDERFLOOR FOR CORROSION								Service ATA:53
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
WC#: 53.380	AFL	4502								
PROC. REF: AMM 53-10-09										PKG:22
A533001 ^S		INSPECT FUSELAGE EXTERIOR SKIN								Service ATA:53
	MOS	15-Jan-13						AIRWORTHINESS		
	HRS	4248.3	2523							
WC#: 53.390	AFL	3834								
PROC. REF: AMM 53-30-00										PKG:71

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 53 - FUSELAGE										
A533003 ^S		INSPECT CABIN LOWER SKIN LONGITUDINAL SPLICE								Service ATA:53
	MOS	11-Mar-96		TAC 0				AIRWORTHINESS		
	HRS	0	5900	TAC 0						
WC#: 53.400	AFL	0		TAC 0						
PROC. REF: AMM 53-30-00										PKG:77
A533006 ^S		INSPECT FUSELAGE EXTERIOR SKIN CORROSION								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.410	AFL	4442								
PROC. REF: AMM 53-30-00										PKG:7,100
A533010 ^S		EDDY CURRENT INSPECTION FUSELAGE SKIN JOINT								Service ATA:53
	MOS	03-Feb-20								
	HRS	5085.5	1200 (+10)							
WC#: 53.420	AFL	4402								
PROC. REF: AMM 53-30-00										PKG:505
A535001 ^S		INSPECT NOSE CAP (RADOME)								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.430	AFL	4442								
PROC. REF: AMM 53-50-00										PKG:7,100
A535002 ^S		INSPECT STINGER ASSEMBLY								Service ATA:53
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 53.440	AFL	4442								
PROC. REF: AMM 53-50-10										PKG:7,107
A553001 ^S		EXTERNAL INSPECTION VERTICAL STABILIZER								Service ATA:53
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 55.030	AFL	4502								
PROC. REF: AMM 55-30-01										PKG:2
B535001 ^S		CHECK RADOME								Service ATA:53
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 53.450	AFL	4502								
PROC. REF: AMM 53-50-00										PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 54 - NACELLES/PYLONS										
541001	LEFT INLET ASSEMBLY									Component ATA:54
PN:6552500-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 54.010	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
541001	RIGHT INLET ASSEMBLY									Component ATA:54
PN:6552500-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 54.010	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
A541001 ^S	INSPECT ENGINE NACELLE, PYLON AND FIREWALL									Service ATA:54
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 54.020	AFL	4442								
PROC. REF: AMM 54-50-01										PKG:7,107
A541002 ^S	INSPECT ENGINE SUPPORT STRUCTURES									Service ATA:54
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:10000 (+10)	TAC 0						
WC#: 54.030	AFL	0		TAC 0						
PROC. REF: AMM 54-50-01										PKG:20
ATA 55 - STABILIZERS										
A551001 ^S	EXTERNAL INSPECTION HORIZONTAL STABILIZER									Service ATA:55
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 55.010	AFL	4502								
PROC. REF: AMM 55-10-01										PKG:2
A551002 ^S	INSPECT VERTICAL STABILIZER AFT EDGE									Service ATA:55
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 55.020	AFL	4502								
PROC. REF: AMM 55-30-01										PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 55 - STABILIZERS										
A551003 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA									Service ATA:55
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 55-10-01										PKG:503
A551004 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY									Service ATA:55
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 55-30-01										PKG:503
A551005 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA									Service ATA:55
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 55-10-01										PKG:22
A551006 ^S	BORESCOPE INSPECTION OF HORIZONTAL STABILIZER RIB LOCATION									Service ATA:55
	MOS	11-Mar-96		TAC 0						
	HRS	0	6000 (+10)	TAC 0						
	AFL	0		TAC 0						
PROC. REF: AMM 55-10-01										PKG:502
A553003 ^S	INSPECT VERTICAL STABILIZER FORWARD SPAR CAP STRAP									Service ATA:55
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:10000 (+10)	TAC 0						
WC#: 55.050	AFL	0		TAC 0						
PROC. REF: AMM 55-30-01										PKG:19
A553005 ^S	INSPECT VERTICAL STABILIZER AFT SPAR FLANGE									Service ATA:55
	MOS	11-Mar-96								
	HRS	0	T:10000 (+10)							
WC#: 55.040	AFL	0								
PROC. REF: AMM 55-30-01										PKG:19
A553006 ^S	INTERNAL INSPECTION VERTICAL STABILIZER									Service ATA:55
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 55.070	AFL	4442								
PROC. REF: AMM 55-30-01										PKG:7,107

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty	
ATA 55 - STABILIZERS											
A553007 ^S		INSPECT VERTICAL STABILIZER AFT SPAR								Service	ATA:55
	MOS	11-Mar-96		TAC 0							
	HRS	0	T:10000 (+10)	TAC 0							
WC#: 55.060	AFL	0		TAC 0							
						PROC. REF: AMM 55-30-01		PKG:19			
A553008 ^S		GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY								Service	ATA:55
	MOS	08-Jun-22	12 (+1m)								
	HRS	5229.6									
	AFL	4502									
						PROC. REF: AMM 55-30-01		PKG:22			
A555001 ^S		INTERNAL INSPECTION HORIZONTAL STABILIZER								Service	ATA:55
	MOS	24-May-21	36 (+2m)								
	HRS	5149.5	1200 (+100)								
WC#: 55.080	AFL	4442									
						PROC. REF: AMM 55-10-01		PKG:7,107			
ATA 56 - WINDOWS											
561001		NO. 1 LEFTHAND MAIN WINDSHIELD ASSY, (LH)								Component	ATA:56
PN:E149000-101	MOS/MSC	11-Mar-96	O/C								
SN:3671	HRS	0		TSN 0							
WC#: 56.010	AFL	0		TSN 0							
						PROC. REF: AMM 56-10-01					
561002		NO. 2 RIGHTHAND MAIN WINDSHIELD ASSY, (RH)								Component	ATA:56
PN:E149000-102	MOS/MSC	17-Dec-04	O/C								
SN:3408	HRS	2347		TSO 2347							
WC#: 56.010	AFL										
						PROC. REF: AMM 56-10-01					
561003		FOUL WEATHER WINDOW								Component	ATA:56
PN:5511275-17	MOS/MSC	17-Dec-04	O/C								
SN:1904	HRS	2347		TSN 0							
WC#: 56.015	AFL										
						PROC. REF: AMM 56-10-03					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
561005	LEFT INBOARD PILOTS INNER WINDOW									Component ATA:56
PN:5511285-5	MOS/MSC	03-Nov-11	O/C	TSN 0						
SN:NSN	HRS	3990.5		TSN 0						
WC#: 56.015	AFL	3550								
PROC. REF: AMM 56-10-02										
561005	LEFT OUTBOARD PILOTS OUTER WINDOW									Component ATA:56
PN:5511285-3	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.020	AFL	0		TSN 0						
PROC. REF: AMM 56-10-02										
561005	RIGHT INBOARD CO-PILOTS INNER WINDOW									Component ATA:56
PN:5511285-6	MOS/MSC	03-Nov-11	O/C	TSN 0						
SN:NSN	HRS	3990.5		TSN 0						
WC#: 56.015	AFL	3550								
PROC. REF: AMM 56-10-02										
561005	RIGHT OUTBOARD CO-PILOTS OUTER WINDOW									Component ATA:56
PN:5511285-48	MOS/MSC	17-Dec-04	O/C							
SN:11-21-01	HRS	2347		TSO 0						
WC#: 56.020	AFL									
PROC. REF: AMM 56-10-02										
562001	L1 CABIN DOOR WINDOW									Component ATA:56
PN:5512207-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.025	AFL	0		TSN 0						
PROC. REF: AMM 56-30-01										
562001	L2 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.030	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01										
562001	L3 CABIN WINDOW									Component ATA:56
PN:6311123-203	MOS/MSC	03-Feb-09	O/C							
SN:2475	HRS	3186		TSN 0						
WC#: 56.040	AFL									
PROC. REF: AMM 56-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
562001	L4 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.050	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	L5 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.060	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	L6 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.070	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	L7 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.080	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	R 7 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.080	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	R1 EMERGENCY DOOR WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.025	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										
562001	R2 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0			TSN 0					
WC#: 56.030	AFL	0			TSN 0					
PROC. REF: AMM 56-20-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
562001	R3 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.040	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01										
562001	R4 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.050	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01										
562001	R5 CABIN WINDOW									Component ATA:56
PN:5511260-8	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 56.060	AFL	0		TSN 0						
PROC. REF: AMM 56-20-01										
562001	R6 CABIN WINDOW									Component ATA:56
PN:6311123-203	MOS/MSC	03-Feb-09	O/C							
SN:3775	HRS	3186		TSN 0						
WC#: 56.070	AFL									
PROC. REF: AMM 56-20-01										
A561001 ^S	INSPECT AIRPLANE WINDOWS									Service ATA:56
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 56.100	AFL	4502								
PROC. REF: AMM 56-10-00										PKG:1
A561002 ^S	PRISM CHECK WINDSHIELD AND FLIGHT COMPARTMENT SIDE WINDOWS									Service ATA:56
	MOS	22-Dec-21	36 (+2m)							
	HRS	5180	1200 (+100)							
WC#: 56.110	AFL	4468								
PROC. REF: AMM 56-10-00										PKG:57
A561004 ^S	PERFORM RIGHT INBOARD CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION									Service ATA:56
PN:5511285-6	MOS/MSC	10-Sep-12	A/R							
SN:NSN	HRS	4130.1								
WC#: 56.130	AFL	3758								
PROC. REF: AMM 56-10-00										PKG:112

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 56 - WINDOWS										
A561004	PERFORM RIGHT OUTBOARD CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION									Service ATA:56
PN:5511285-48	MOS/MSC	11-Mar-96	A/R	TAC 0						
SN:11-21-01	HRS	0		TAC 0						
WC#: 56.130	AFL	0		TAC 0						
PROC. REF: AMM 56-10-00										PKG:112
ATA 57 - WINGS										
572001	LEFT AFT MLG TRUNNION FITTING ASSEMBLY									Component ATA:57
PN:5522710-15	MOS	11-Mar-96								
SN:UNKNOWN	HRS	0								
WC#: 57.010	AFL	0	22900	TSN 0	22900		18264			
PROC. REF: AMM GENERIC										
572001	LEFT FORWARD MLG TRUNNION FITTING ASSEMBLY									Component ATA:57
PN:6522057-5	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 57.030	AFL	0	22900	TSN 0	22900		18264			
PROC. REF: AMM GENERIC										
572001	RIGHT AFT MLG TRUNNION FITTING ASSEMBLY									Component ATA:57
PN:5522710-15	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 57.020	AFL	0	22900	TSN 0	22900		18264			
PROC. REF: AMM GENERIC										
572001	RIGHT FORWARD MLG TRUNNION FITTING ASSEMBLY									Component ATA:57
PN:6522057-6	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 57.040	AFL	0	22900	TSN 0	22900		18264			
PROC. REF: AMM GENERIC										
574003	LEFT MLG SIDE BRACE SUPPORT FITTING									Component ATA:57
PN:6522047-1	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 57.050	AFL	0	24700	TSN 0	24700		20064			
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
574004	RIGHT MLG SIDE BRACE SUPPORT FITTING									Component ATA:57
PN:6522047-2	MOS	11-Mar-96						LIFE LIMIT		
SN:UNKNOWN	HRS	0								
WC#: 57.060	AFL	0	24700	TSN 0	24700		20064			
PROC. REF: AMM GENERIC										
A570001 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL									Service ATA:57
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 57-00-00										PKG:503
A570002 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL									Service ATA:57
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 57-00-00										PKG:22
A570003 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA									Service ATA:57
	MOS	20-Apr-23	6 (+1m)							
	HRS	5396.4								
	AFL	4627								
PROC. REF: AMM 57-00-00										PKG:503
A570004 ^S	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA									Service ATA:57
	MOS	08-Jun-22	12 (+1m)							
	HRS	5229.6								
	AFL	4502								
PROC. REF: AMM 57-00-00										PKG:22
A571004 ^S	INSPECT WING LOWER LEADING EDGE OUTBOAD OF WS 91.073									Service ATA:57
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 57.090	AFL	4442								
PROC. REF: AMM 57-00-00										PKG:7,109
A571005 ^S	INSPECT INBOARD LOWER MAIN WING SPAR CAP AND STRAP INSPECTION (AIRPLANES -0001 THRU -0538)									Service ATA:57
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:13200 (+10)	TAC 0						
WC#: 57.150	AFL	0		TAC 0						
PROC. REF: AMM 57-00-00										PKG:246

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 57 - WINGS										
A571007 ^S	INSPECT OUTBOARD LOWER MAIN WING SPAR CAP AND STRAP									Service ATA:57
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:15600 (+10)	TAC 0						
WC#: 57.170	AFL	0		TAC 0						
PROC. REF: AMM 57-00-00										PKG:247
A571008 ^S	INSPECT INBOARD LOWER REAR WING SPAR CAP									Service ATA:57
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:15600 (+10)	TAC 0						
WC#: 57.180	AFL	0		TAC 0						
PROC. REF: AMM 57-00-00										PKG:248
A571009 ^S	INSPECT OUTBOARD LOWER REAR WING SPAR CAP									Service ATA:57
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:15600 (+10)	TAC 0						
WC#: 57.190	AFL	0		TAC 0						
PROC. REF: AMM 57-00-00										PKG:248
A573001 ^S	INSPECT WINGS									Service ATA:57
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 57.110	AFL	4442								
PROC. REF: AMM 57-00-00										PKG:7,109
A573003 ^S	INSPECT JACK PADS									Service ATA:57
	MOS	11-Mar-96		TAC 0						
	HRS	0	T:12000 (+10)	TAC 0						
WC#: 57.120	AFL	0		TAC 0						
PROC. REF: AMM 57-00-00										PKG:18
A574005 ^S	INSPECT FLAP BELL CRANK ATTACH POINTS									Service ATA:57
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 57.130	AFL	4502								
PROC. REF: AMM 57-20-01										PKG:2
A575001 ^S	INSPECT FLAPS									Service ATA:57
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 57.140	AFL	4442								
PROC. REF: AMM 57-00-00										PKG:7,109

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
710020		NO. 1 ENGINE - HOT SECTION INSPECTION								Service ATA:71
	MOS	31-Jan-23								
	HRS	5299.4	1750 (+50/-50)		(7049.4) 7146.4	7099.4	1750 (+50)			
	ENC	4459								
PROC. REF: MM 72-00-00										
710020		NO. 2 ENGINE - HOT SECTION INSPECTION								Service ATA:71
	MOS	20-Apr-23								
	HRS	5299.4	1750 (+50/-50)		(7049.4) 7146.4	7099.4	1737.2 (+50)			
	ENC	4459								
PROC. REF: MM 72-00-00										
712001		LEFT ENGINE AFT ISOLATOR								Component ATA:71
PN:LM420SA6-1	MOS	09-Aug-10		TSO 0						
SN:2352	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.010	AFL	3320								
PROC. REF: AMM 71-21-00										
712001		RIGHT ENGINE AFT ISOLATOR								Component ATA:71
PN:LM420SA6-1	MOS	09-Aug-10		TSO 0						
SN:2299	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.010	AFL	3320								
PROC. REF: AMM 71-21-00										
712002		LEFT BOTTOM FORWARD ENGINE ISOLATOR								Component ATA:71
PN:LM420SA5-1	MOS	09-Aug-10		TSO 0						
SN:3283	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.030	AFL	3320								
PROC. REF: AMM 71-21-00										
712002		LEFT TOP FORWARD ENGINE ISOLATOR								Component ATA:71
PN:LM420SA5-1	MOS	09-Aug-10		TSO 0						
SN:3282	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.020	AFL	3320								
PROC. REF: AMM 71-21-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
712002		RIGHT BOTTOM FORWARD ENGINE ISOLATOR								Component ATA:71
PN:LM420SA5-1	MOS	09-Aug-10		TSO 0						
SN:3231	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.030	AFL	3320								
PROC. REF: AMM 71-21-00										
712002		RIGHT TOP FORWARD ENGINE ISOLATOR								Component ATA:71
PN:LM420SA5-1	MOS	09-Aug-10		TSO 0						
SN:3228	HRS	3586.6	3500	TSO 0	7086.6		1677.4			
WC#: 71.020	AFL	3320								
PROC. REF: AMM 71-21-00										
71EN1		NO. 1 ENGINE								Component ATA:71
PN:3051700	MOS/MSC	11-Mar-96	E/C							
SN:PCE-500183	HRS	0		TSN 0						
WC#: 71.EN1	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
71EN2		NO. 2 ENGINE								Component ATA:71
PN:3051700	MOS/MSC	11-Mar-96	E/C							
SN:PCE-500179	HRS	0		TSN 0						
WC#: 71.EN2	AFL	0		TSN 0						
PROC. REF: GENERIC NO REF										
720010		NO. 1 ENGINE - OVERHAUL								Service ATA:71
	MOS	09-Aug-10								
	HRS	3502.6	3500 (+50/-50)		(7002.6) 7112.4	7052.6	1703.2 (+50)			
	ENC	3151								
PROC. REF: GENERIC NO REF										
720010		NO. 2 ENGINE - OVERHAUL								Service ATA:71
	MOS	09-Aug-10								
	HRS	3502.6	3500 (+50/-50)		(7002.6) 7099.6	7052.6	1690.4 (+50)			
	ENC	3151								
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 71 - POWER PLANT										
A711000 ^S	GENERAL INSPECTION ENGINE									Service ATA:71
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 71.050	AFL	4502								
PROC. REF: AMM 71-01-04										PKG:4
A711001 ^S	GENERAL INSPECTION ENGINE									Service ATA:71
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 71.060	AFL	4502								
PROC. REF: AMM 71-01-05										PKG:4
A711006 ^S	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES -0001 THRU -0538)									Service ATA:71
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 71.080	AFL	4502								
PROC. REF: AMM 71-11-00										PKG:4
A711007 ^S	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES 0539 AND ON)									Service ATA:71
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 71.110	AFL	4502								
PROC. REF: AMM 71-11-00										PKG:4
ATA 72 - ENGINE										
720020	NO. 1 ENGINE - OIL ANALYSIS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R		TAC 0					
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00										
720020	NO. 2 ENGINE - OIL ANALYSIS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R		TAC 0					
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720050	NO. 1 ENGINE - REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720050	NO. 2 ENGINE - REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720051	NO. 1 ENGINE - REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00, MM 72-00-00										
720051	NO. 2 ENGINE - REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00, MM 72-00-00										
720052	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720052	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720053	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	DAYS/MSC	11-Mar-96	A/R							
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720053	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	DAYS/MS	11-Mar-96	A/R							
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00										
720054	NO. 1 ENGINE - DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MS	11-Mar-96	A/R		TAC 0					
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00										
720054	NO. 2 ENGINE - DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS									Service ATA:72
	MOS/MS	11-Mar-96	A/R		TAC 0					
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00										
720055	NO. 1 ENGINE - DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	DAYS/MS	11-Mar-96	A/R							
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00, MM 72-00-00										
720055	NO. 2 ENGINE - DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS									Service ATA:72
	DAYS/MS	11-Mar-96	A/R							
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00, MM 72-00-00										
720056	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 0 TO 90 DAYS									Service ATA:72
	MOS/MS	11-Mar-96	A/R		TAC 0					
	HRS	0			TAC 0					
	ENC	0			TAC 0					
PROC. REF: MM 72-00-00, MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720056	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 0 TO 90 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00, MM 72-00-00										
720057	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 91 DAYS AND OVER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720057	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 91 DAYS AND OVER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720058	NO. 1 ENGINE - DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 0 TO 90 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00, MM 72-00-00										
720058	NO. 2 ENGINE - DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 0 TO 90 DAYS									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00, MM 72-00-00										
720059	NO. 1 ENGINE - DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 91 DAYS AND OVER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720059	NO. 2 ENGINE - DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 91 DAYS AND OVER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720100	NO. 1 ENGINE - ENGINE OVERTEMPERATURE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720100	NO. 2 ENGINE - ENGINE OVERTEMPERATURE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720110	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720110	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720120	NO. 1 ENGINE - LOSS OF OIL									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720120	NO. 2 ENGINE - LOSS OF OIL									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720130	NO. 1 ENGINE - ENGINE OVERSPEED									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720130	NO. 2 ENGINE - ENGINE OVERSPEED									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720140	NO. 1 ENGINE - ENGINE WINDMILLING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720140	NO. 2 ENGINE - ENGINE WINDMILLING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720150	NO. 1 ENGINE - ENGINE IMMERSION IN WATER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720150	NO. 2 ENGINE - ENGINE IMMERSION IN WATER									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720160	NO. 1 ENGINE - ENGINE DROPPED DURING HANDLING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720160	NO. 2 ENGINE - ENGINE DROPPED DURING HANDLING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720170	NO. 1 ENGINE - LIGHTNING STRIKE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720170	NO. 2 ENGINE - LIGHTNING STRIKE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720180	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720180	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720190	NO. 1 ENGINE - HEAVY/HARD LANDING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
720190	NO. 2 ENGINE - HEAVY/HARD LANDING									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720200	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720200	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720210	NO. 1 ENGINE - STARTER GENERATOR FAIL INDICATION									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720210	NO. 2 ENGINE - STARTER GENERATOR FAIL INDICATION									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720220	NO. 1 ENGINE - HYDRAULIC PUMP FAILURE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										
720220	NO. 2 ENGINE - HYDRAULIC PUMP FAILURE									Service ATA:72
	MOS/MSC	11-Mar-96	A/R	TAC 0						
	HRS	0		TAC 0						
	ENC	0		TAC 0						
PROC. REF: MM 72-00-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
721010	NO. 1 ENGINE - ACESSORY DRIVE GEARBOX									Component ATA:72
PN:3031170	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
721010	NO. 2 ENGINE - ACESSORY DRIVE GEARBOX									Component ATA:72
PN:3031170	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
722001	NO. 1 ENGINE - OIL PUMP									Component ATA:72
PN:3104289-01	MOS/MSC	21-Oct-10	O/C							
SN:OP1085	HRS	3576.7								
	ENC	3209								
PROC. REF: GENERIC NO REF										
722001	NO. 2 ENGINE - OIL PUMP									Component ATA:72
PN:3104289-01	MOS/MSC	21-Oct-10	O/C							
SN:OP1081	HRS	3576.7								
	ENC	3209								
PROC. REF: GENERIC NO REF										
722608	NO. 1 ENGINE - FAN LOW COMPRESSOR ROTOR									Component ATA:72
PN:3041231	MOS	30-Jun-10						LIFE LIMIT		
SN:13B255	HRS	3502		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	30000	TSN 3151			25541			
PROC. REF: GENERIC NO REF										
722608	NO. 2 ENGINE - FAN LOW COMPRESSOR ROTOR									Component ATA:72
PN:3041231	MOS	27-Jul-10						LIFE LIMIT		
SN:13B118	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	30000	TSN 3151			25532			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
722609		NO. 1 ENGINE - LOW BOOST COMPRESSOR ROTOR							Component	ATA:72
PN:3070232-01	MOS	30-Jun-10						LIFE LIMIT		
SN:55B539	HRS	3502		TSN 3546.1						
	ENC	3151		TSN 3466						
	ACCCYC	0	30000	TSN 3466			25226			
PROC. REF: GENERIC NO REF										
722609		NO. 2 ENGINE - LOW BOOST COMPRESSOR ROTOR							Component	ATA:72
PN:3070232-01	MOS	27-Jul-10						LIFE LIMIT		
SN:12B963	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	30000	TSN 3151			25532			
PROC. REF: GENERIC NO REF										
723001		NO. 1 ENGINE - LC ROTOR FAN BALANCING ASSEMBLY							Component	ATA:72
PN:3118976-01	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723001		NO. 2 ENGINE - LC ROTOR FAN BALANCING ASSEMBLY							Component	ATA:72
PN:3118976-01	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
723705		NO. 1 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK							Component	ATA:72
PN:3022212	MOS	30-Jun-10						LIFE LIMIT		
SN:14B327	HRS	3502		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	14000	TSN 4191			8069			
PROC. REF: GENERIC NO REF										
723705		NO. 2 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK							Component	ATA:72
PN:3022212	MOS	27-Jul-10						LIFE LIMIT		
SN:15B312	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 4191						
	ACCCYC	0	14000	TSN 4191			8057			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
724001	NO. 1 ENGINE - COMBUSTOR LINER									Component ATA:72
PN:3119770-01	MOS/MSC	02-Feb-23	O/C	TSR 0						
SN:6K028	HRS	5299.4		TSR 0						
	ENC	4459		TSR 0						
PROC. REF: GENERIC NO REF										
724001	NO. 2 ENGINE - COMBUSTOR LINER									Component ATA:72
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
724006	NO. 1 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK									Component ATA:72
PN:3041593	MOS	30-Jun-10						LIFE LIMIT		
SN:14B894	HRS	3502		TSN 3502.4						
	ENC	3151		TSN 4191						
	ACCCYC	0	14000	TSN 4191			8069			
PROC. REF: GENERIC NO REF										
724006	NO. 2 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK									Component ATA:72
PN:3041593	MOS	27-Jul-10						LIFE LIMIT		
SN:14B889	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 4191						
	ACCCYC	0	14000	TSN 4191			8057			
PROC. REF: GENERIC NO REF										
724706	NO. 1 ENGINE - HIGH TURBINE ROTOR DISK									Component ATA:72
PN:3036411	MOS	30-Jun-10						LIFE LIMIT		
SN:15B755	HRS	3502		TSN 3502.4						
	ENC	3151		TSN 4191						
	ACCCYC	0	14000	TSN 4191			8069			
PROC. REF: GENERIC NO REF										
724706	NO. 2 ENGINE - HIGH TURBINE ROTOR DISK									Component ATA:72
PN:3036411	MOS	27-Jul-10						LIFE LIMIT		
SN:15B749	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 4191						
	ACCCYC	0	14000	TSN 4191			8057			
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 72 - ENGINE										
724707	NO. 1 ENGINE - HIGH TURBINE BLADES									Component ATA:72
PN:3117501-01	MOS/MSC	30-Jun-10	O/C							
SN:NSN	HRS	3502								
	ENC	3151								
PROC. REF: GENERIC NO REF										
724707	NO. 2 ENGINE - HIGH TURBINE BLADES									Component ATA:72
PN:3117501-01	MOS/MSC	27-Jul-10	O/C							
SN:NSN	HRS	3502.4								
	ENC	3151								
PROC. REF: GENERIC NO REF										
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER									Component ATA:72
PN:3040939	MOS	30-Jun-10						LIFE LIMIT		
SN:3F602	HRS	3502		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	12000	TSN 3151		7541				
PROC. REF: GENERIC NO REF										
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER									Component ATA:72
PN:3040939	MOS	27-Jul-10						LIFE LIMIT		
SN:3F480	HRS	3502.4		TSN 3502.4						
	ENC	3151		TSN 3151						
	ACCCYC	0	12000	TSN 3151		7532				
PROC. REF: GENERIC NO REF										
ATA 73 - ENGINE FUEL AND CONTROL										
731001	NO. 1 ENGINE - FUEL PUMP									Component ATA:73
PN:717101-1	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:0747	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-02										
731001	NO. 2 ENGINE - FUEL PUMP									Component ATA:73
PN:717101-1	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:0752	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-02										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731002	NO. 1 ENGINE - FLOW DIVIDER VALVE									Component ATA:73
PN:26395-2	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:0828	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-04										
731002	NO. 2 ENGINE - FLOW DIVIDER VALVE									Component ATA:73
PN:26395-2	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:0830	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-04										
731004	NO. 1 LOW FUEL PRESSURE SWITCH									Component ATA:73
PN:1103P92	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 73.030	AFL	0		TSN 0						
PROC. REF: AMM 73-30-02, AMM 73-30-02										
731004	NO. 2 LOW FUEL PRESSURE SWITCH									Component ATA:73
PN:1103P0448	MOS/MSC	17-Jul-02	O/C							
SN:5230	HRS	1740		TSN 0						
WC#: 73.030	AFL									
PROC. REF: AMM 73-30-02, AMM 73-30-02										
731005	NO. 1 ENGINE - BLEED CONTROL VALVE									Component ATA:73
PN:815625-1-002	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:C96031937	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-13										
731005	NO. 2 ENGINE - BLEED CONTROL VALVE									Component ATA:73
PN:815625-1-002	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:C95081852	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-13										
731006	NO. 1 ENGINE - EFCU WIRING HARNESS									Component ATA:73
PN:3119566-01	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:AA4925	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731006	NO. 2 ENGINE - EFCU WIRING HARNESS									Component ATA:73
PN:3119566-01	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:AA4893	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
731020	NO. 1 ENGINE - FUEL-OIL COOLER									Component ATA:73
PN:D2397-10A	MOS/MSC	15-Jan-13	O/C	TSO 0						
SN:M45351	HRS	4152.6		TSO 0						
	ENC	3677								
PROC. REF: MM 73-10-01										
731020	NO. 2 ENGINE - FUEL-OIL COOLER									Component ATA:73
PN:14438-000	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:892	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-10-01										
731025	NO. 1 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER									Service ATA:73
PN:D2397-10A	MOS	15-Jan-13								
SN:M45351	HRS	4152.6	3500 (+50/-50)		(7652.6) 7748.3	7702.6	2353.2 (+50)			
	ENC	3677								
PROC. REF: MM 73-10-01										
731025	NO. 2 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER									Service ATA:73
PN:14438-000	MOS	11-Mar-96		TAC 0						
SN:892	HRS	0	3500 (+50/-50)		(7002.6) 7099.6 (M)	7052.6	1690.4 (+50)			
	ENC	0		TAC 0						
PROC. REF: MM 73-10-01										
731030	NO. 1 ENGINE - MOTIVE FLOW VALVE									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-08										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731030	NO. 2 ENGINE - MOTIVE FLOW VALVE									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-08										
731035	NO. 1 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE									Service ATA:73
PN:PN	MOS	11-Mar-96		TAC 0						
SN:UNKNOWN	HRS	0	3500 (+50/-50)		(7002.6) 7112.4 (M)	7052.6	1703.2 (+50)			
	ENC	0		TAC 0						
PROC. REF: GENERIC NO REF										
731035	NO. 2 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE									Service ATA:73
PN:PN	MOS	11-Mar-96		TAC 0						
SN:UNKNOWN	HRS	0	3500 (+50/-50)		(7002.6) 7099.6 (M)	7052.6	1690.4 (+50)			
	ENC	0		TAC 0						
PROC. REF: GENERIC NO REF										
731065	NO. 1 ENGINE - BLEED VALVE ACTUATOR									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-12										
731065	NO. 2 ENGINE - BLEED VALVE ACTUATOR									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-10-12										
731085	NO. 1 ENGINE - SCHEDULE MODULATOR									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
731085	NO. 2 ENGINE - SCHEDULE MODULATOR									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
731090	NO. 1 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE									Service ATA:73
PN:26395-2	MOS	11-Mar-96		TAC 0						
SN:0828	HRS	0	3500 (+50/-50)		(7002.6) 7112.4 (M)	7052.6	1703.2 (+50)			
	ENC	0		TAC 0						
PROC. REF: GENERIC NO REF										
731090	NO. 2 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE									Service ATA:73
PN:26395-2	MOS	11-Mar-96		TAC 0						
SN:0830	HRS	0	3500 (+50/-50)		(7002.6) 7099.6 (M)	7052.6	1690.4 (+50)			
	ENC	0		TAC 0						
PROC. REF: GENERIC NO REF										
732001	NO. 1 ENGINE - FUEL CONTROL UNIT									Component ATA:73
PN:3244880-9-8	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:C4202	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-20-01										
732001	NO. 2 ENGINE - FUEL CONTROL UNIT									Component ATA:73
PN:3244880-9-8	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:C4201	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 73-20-01										
732005	NO. 1 ENGINE - N1 SPEED SENSOR									Component ATA:73
PN:3118403-01	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:A210	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732005	NO. 2 ENGINE - N1 SPEED SENSOR									Component ATA:73
PN:3118403-01	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:A188	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
732006	NO. 1 ENGINE - BOTTOM N2 SPEED SENSOR									Component ATA:73
PN:3032997	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:D418	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
732006	NO. 1 ENGINE - TOP N2 SPEED SENSOR									Component ATA:73
PN:3032997	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:D477	HRS	3502		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
732006	NO. 2 ENGINE - BOTTOM N2 SPEED SENSOR									Component ATA:73
PN:3032997	MOS/MSC	31-Oct-22	O/C	TSN 91						
SN:D040	HRS	5154		TSN 2885.2						
	ENC	4357		TSN 2238						
PROC. REF: GENERIC NO REF										
732006	NO. 2 ENGINE - TOP N2 SPEED SENSOR									Component ATA:73
PN:3032997	MOS/MSC	31-Oct-22	O/C	TSN 91						
SN:D026	HRS	5154		TSN 2285.2						
	ENC	4357		TSN 2238						
PROC. REF: GENERIC NO REF										
732020	NO. 1 ENGINE - ELECTRONIC CONTROL COMPUTER									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732020	NO. 2 ENGINE - ELECTRONIC CONTROL COMPUTER									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
732030	NO. 1 ENGINE - ELECTRONIC BLEED VALVE CONTROL									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732030	NO. 2 ENGINE - ELECTRONIC BLEED VALVE CONTROL									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
732065	NO. 1 ENGINE - MAIN WIRING HARNESS									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-04										
732065	NO. 2 ENGINE - MAIN WIRING HARNESS									Component ATA:73
PN:PN	MOS/MSC	11-Mar-96	O/C	TSN 0						
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: MM 73-20-04										
733002	FUEL FLOW/QUANTITY INDICATOR									Component ATA:73
PN:10537N01M01	MOS/MSC	13-Oct-08	O/C							
SN:B263	HRS	3101		TSO 0						
WC#: 73.010	AFL									
PROC. REF: AMM 73-30-00										
733003	NO. 1 FUEL FLOW TRANSMITER									Component ATA:73
PN:9-231-28	MOS/MSC	11-Mar-96	O/C							
SN:5793	HRS	0		TSN 0						
WC#: 73.040	AFL	0		TSN 0						
PROC. REF: AMM 73-30-00										
733003	NO. 2 FUEL FLOW TRANSMITER									Component ATA:73
PN:9-231-28	MOS/MSC	11-Mar-96	O/C							
SN:5830	HRS	0		TSN 0						
WC#: 73.040	AFL	0		TSN 0						
PROC. REF: AMM 73-30-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 73 - ENGINE FUEL AND CONTROL										
734001	NO. 1 ENGINE - FUEL SURGE ACCUMULATOR									Component ATA:73
PN:3041669-01	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:0650	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
734001	NO. 2 ENGINE - FUEL SURGE ACCUMULATOR									Component ATA:73
PN:3041669-01	MOS/MSC	27-Jul-10	O/C	TSO 0						
SN:0812	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: GENERIC NO REF										
ATA 74 - IGNITION										
741001	NO. 1 ENGINE - INBOARD IGNITION EXCITER									Component ATA:74
PN:9049770-3	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:99032369	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 74-10-01										
741001	NO. 1 ENGINE - OUTBOARD IGNITION EXCITER									Component ATA:74
PN:9049770-3	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:NSN	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 74-10-01										
741001	NO. 2 ENGINE - INBOARD IGNITION EXCITER									Component ATA:74
PN:9049770-3	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:98106353	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 74-10-01										
741001	NO. 2 ENGINE - OUTBOARD IGNITION EXCITER									Component ATA:74
PN:9049770-3	MOS/MSC	30-Jun-10	O/C	TSO 0						
SN:NNA03425068	HRS	3502.4		TSO 0						
	ENC	3151		TSO 0						
PROC. REF: MM 74-10-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742001	NO. 1 ENGINE - INBOARD IGNITER PLUG									Component ATA:74
PN:CH34659-3	MOS/MSC	01-Nov-13	O/C	TSN 0						
SN:NA	HRS	4425.8		TSN 0						
	ENC	3862								
PROC. REF: GENERIC NO REF										
742001	NO. 1 ENGINE - OUTBOARD IGNITER PLUG									Component ATA:74
PN:CH34659-3	MOS/MSC	05-Jan-14	O/C	TSN 0						
SN:NSN	HRS	4469.6		TSN 0						
	ENC	3890								
PROC. REF: GENERIC NO REF										
742001	NO. 2 ENGINE - INBOARD IGNITER PLUG									Component ATA:74
PN:CH34659-3	MOS/MSC	23-Feb-15	O/C	TSN 0						
SN:NSN	HRS	4634.1		TSN 0						
	ENC	3998								
PROC. REF: GENERIC NO REF										
742001	NO. 2 ENGINE - OUTBOARD IGNITER PLUG									Component ATA:74
PN:CH34659-3	MOS/MSC	01-Nov-13	O/C	TSN 0						
SN:NA	HRS	4425.8		TSN 0						
	ENC	3862								
PROC. REF: GENERIC NO REF										
742002	NO. 1 ENGINE - INBOARD IGNITER PLUG CABLE									Component ATA:74
PN:53300-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
742002	NO. 2 ENGINE - INBOARD IGNITER PLUG CABLE									Component ATA:74
PN:53300-1	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
742003	NO. 1 ENGINE - OUTBOARD IGNITER PLUG CABLE									Component ATA:74
PN:53300-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 74 - IGNITION										
742003	NO. 2 ENGINE - OUTBOARD IGNITER PLUG CABLE									Component ATA:74
PN:53300-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
	ENC	0		TSN 0						
PROC. REF: GENERIC NO REF										
B742001 ^S	OPERATIONAL CHECK ENGINE IGNITERS									Service ATA:74
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 74.010	AFL	4627								
PROC. REF: AMM 74-31-00										PKG:2,4,15
B742002 ^S	OPERATIONAL CHECK ENGINE IGNITERS (AIRPLANES -0539 THRU -0750)									Service ATA:74
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 74.020	AFL	4627								
PROC. REF: AMM 74-31-00										PKG:2,4,15
B742003 ^S	OPERATIONAL CHECK ENGINE IGNITERS (AIRPLANES -0751 AND ON)									Service ATA:74
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 74.030	AFL	4627								
PROC. REF: AMM 74-31-00										PKG:2,4,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 76 - ENGINE CONTROLS										
761002		SYNCHRONIZER CONTROL BOX							Component	ATA:76
PN:213693	MOS/MSC	11-Nov-99	O/C							
SN:11435658	HRS	1108		TSO 0						
WC#: 76.100	AFL									
PROC. REF: AMM 76-12-00										
761003		ENGINE SYNC ACTUATOR							Component	ATA:76
PN:5485-066	MOS/MSC	11-Mar-96	O/C							
SN:11454653	HRS	0		TSN 0						
WC#: 76.050	AFL	0		TSN 0						
PROC. REF: AMM 76-12-00										
B761500 ^S		OPERATIONAL CHECK THROTTLE SWITCH							Service	ATA:76
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 76.075	AFL	4502								
PROC. REF: AMM 76-15-00										PKG:2
ATA 77 - ENGINE INDICATING										
771010		N1 FAN TACHOMETER INDICATOR							Component	ATA:77
PN:10535N01M00	MOS/MSC	21-Jul-06	O/C							
SN:207	HRS	2634		TSO 0						
WC#: 77.010	AFL									
PROC. REF: AMM 77-11-01										
771011		N2 TURBINE TACHOMETER INDICATOR							Component	ATA:77
PN:10536N01M00	MOS/MSC	13-Oct-08	O/C							
SN:223	HRS	3101		TSO 0						
WC#: 77.020	AFL									
PROC. REF: AMM 77-12-01										
ATA 78 - EXHAUST										
783001		LEFT ENGINE THRUST REVERSER ASSEMBLY							Component	ATA:78
PN:262-0001-501	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.040	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783001		RIGHT ENGINE THRUST REVERSER ASSEMBLY							Component	ATA:78
PN:262-0001-503	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.040	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783002		LEFT ENGINE THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:65680	MOS/MSC	11-Mar-96	O/C							
SN:2133	HRS	0								
WC#: 78.050	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783002		RIGHT ENGINE THRUST REVERSER CONTROL VALVE							Component	ATA:78
PN:65680	MOS/MSC	11-Mar-96	O/C							
SN:2132	HRS	0								
WC#: 78.050	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783003		LEFT ENGINE THRUST REVERSER ISOLATION VALVE							Component	ATA:78
PN:13027-4	MOS/MSC	11-Mar-96	O/C							
SN:2900	HRS	0								
WC#: 78.060	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783003		RIGHT ENGINE THRUST REVERSER ISOLATION VALVE							Component	ATA:78
PN:13027-4	MOS/MSC	11-Mar-96	O/C							
SN:2882	HRS	0								
WC#: 78.060	AFL	0		TSN 0						
PROC. REF: AMM 78-31-01										
783005		LEFT THRUST REVERSER UPPER DOOR ASSEMBLY							Component	ATA:78
PN:202-0001-503	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.200	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783005		RIGHT THRUST REVERSER UPPER DOOR ASSEMBLY							Component	ATA:78
PN:202-0001-504	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.200	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783006		LEFT THRUST REVERSER LOWER DOOR ASSEMBLY							Component	ATA:78
PN:202-0002-505	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.210	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783006		RIGHT THRUST REVERSER LOWER DOOR ASSEMBLY							Component	ATA:78
PN:202-0002-506	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.210	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783007		LEFT THRUST REVERSER UPPER MECHANISM							Component	ATA:78
PN:225-0007-513	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.220	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783007		RIGHT THRUST REVERSER UPPER MECHANISM							Component	ATA:78
PN:225-0007-513	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.220	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783008		LEFT THRUST REVERSER LOWER MECHANISM							Component	ATA:78
PN:225-0007-515	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.230	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783008		RIGHT THRUST REVERSER LOWER MECHANISM							Component	ATA:78
PN:225-0007-515	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.230	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783009		LEFT THRUST REVERSER FAN DUCT							Component	ATA:78
PN:225-0014-507	MOS/MSC	11-Mar-96	O/C							
SN:3244	HRS	0								
WC#: 78.240	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
783009		RIGHT THRUST REVERSER FAN DUCT							Component	ATA:78
PN:225-0014-508	MOS/MSC	11-Mar-96	O/C							
SN:3245	HRS	0								
WC#: 78.240	AFL	0		TSN 0						
PROC. REF: AMM GENERIC										
783010		LEFT INBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:62270	MOS/MSC	11-Mar-96	O/C							
SN:4173	HRS	0								
WC#: 78.020	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783010		LEFT OUTBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:62270	MOS/MSC	11-Mar-96	O/C							
SN:4182	HRS	0								
WC#: 78.030	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783010		RIGHT INBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:62270	MOS/MSC	11-Mar-96	O/C							
SN:4202	HRS	0								
WC#: 78.020	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783010		RIGHT OUTBOARD THRUST REVERSER ACTUATOR							Component	ATA:78
PN:62270	MOS/MSC	11-Mar-96	O/C							
SN:4209	HRS	0								
WC#: 78.030	AFL	0		TSN 0						
PROC. REF: AMM 78-31-00, AMM 78-31-00										
783012		LEFT ENGINE EXHAUST NOZZLE							Component	ATA:78
PN:9912377-V7.5	MOS/MSC	09-Aug-10	O/C	TSN 0						
SN:NSN	HRS	3586.6		TSN 0						
WC#: 78.010	AFL	3320								
PROC. REF: AMM 78-11-01										
783012		RIGHT ENGINE EXHAUST NOZZLE							Component	ATA:78
PN:9912377-13V7	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 78.010	AFL	0		TSN 0						
PROC. REF: AMM 78-11-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
A783002 ^S		INSPECT THRUST REVERSER								Service ATA:78
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 78.070	AFL	4502								
PROC. REF: AMM 78-31-00										PKG:4
A783003 ^S		INSPECT THRUST REVERSER ELECTRICAL JUNCTION BOX								Service ATA:78
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 78.080	AFL	4442								
PROC. REF: AMM 78-31-02										PKG:7,105
B783002 ^S		OPERATIONAL CHECK THRUST REVERSERS (AIRCRAFT -0001 THRU -0538)								Service ATA:78
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 78.090	AFL	4502								
PROC. REF: AMM 78-31-00										PKG:2
B783101 ^S		FUNCTIONAL TEST THRUST REVERSER STOW LIMIT SWITCH(AIRPLANES -0002 THRU -0538)								Service ATA:78
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 78.270	AFL	4502								
PROC. REF: AMM 78-31-00										PKG:4
B783102 ^S		FUNCTIONAL TEST THRUST REVERSER STOW LIMIT SWITCHES (AIRPLANES -0539 AND ON)								Service ATA:78
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 78.100	AFL	4502								
PROC. REF: AMM 78-31-00										PKG:4
C783002 ^S		LUBRICATE THRUST REVERSER ACTUATING MECHANISM								Service ATA:78
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 78.290	AFL	4627								
PROC. REF: AMM 78-31-00										PKG:2,4,15
C783003 ^S		LUBRICATE THRUST REVERSER ACTUATING MECHANISM(USE D-5100NS LUBRICATION METHOD)								Service ATA:78
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 78.300	AFL	4627								
PROC. REF: AMM 78-31-00										PKG:2,4,15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 78 - EXHAUST										
C783004 ^S		LUBRICATE THRUST REVERSER ACTUATING MECHANISM -PIVOT BALL(USE THE C5A LUBRICATION METHOD FOR SLIDER)								Service ATA:78
	MOS	29-Dec-22								
	HRS	5391.7	600 (+10)							
WC#: 78.310	AFL	4624								
PROC. REF: AMM 78-31-00										PKG:45
ATA 79 - OIL										
792010		NO. 1 ENGINE - DRAIN & REFILL OIL SYSTEM								Service ATA:79
	MOS/MSC	03-Nov-11	O/C							
	HRS	3895.2								
	ENC	3480								
PROC. REF: MM 72-00-00										
792010		NO. 2 ENGINE - DRAIN & REFILL OIL SYSTEM								Service ATA:79
	MOS/MSC	03-Nov-11	O/C							
	HRS	3895.2								
	ENC	3480								
PROC. REF: MM 72-00-00										
793002		LEFT ENGINE OIL TEMPERATURE TRANSMITTER								Component ATA:79
PN:102-00083	MOS/MSC	11-Mar-96	O/C							
SN:1873	HRS	0		TSN 0						
WC#: 79.030	AFL	0		TSN 0						
PROC. REF: AMM 79-31-02										
793002		RIGHT ENGINE OIL TEMPERATURE TRANSMITTER								Component ATA:79
PN:102-00083	MOS/MSC	11-Mar-96	O/C							
SN:1879	HRS	0		TSN 0						
WC#: 79.030	AFL	0		TSN 0						
PROC. REF: AMM 79-31-02										
793004		LEFT ENGINE OIL PRESSURE TRANSMITTER								Component ATA:79
PN:123479	MOS/MSC	11-Mar-96	O/C							
SN:49937	HRS	0		TSN 0						
WC#: 79.020	AFL	0		TSN 0						
PROC. REF: AMM 79-31-01										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: 560 - CITATION ULTRA Serial: 560-0347 RegNo: N50LQ HRS: 5409.2 AFL: 4636 As Of: 27-Apr-2023

27-Apr-2023 04:58 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	MOC	Warranty
ATA 79 - OIL										
793004	RIGHT ENGINE OIL PRESSURE TRANSMITTER									Component ATA:79
PN:123479	MOS/MSC	14-Nov-09	O/C							
SN:57020-26	HRS	3357		TSN 0						
WC#: 79.020	AFL									
PROC. REF: AMM 79-31-01										
793006	LEFT ENGINE LOW OIL PRESSURE SWITCH									Component ATA:79
PN:1103P89-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.040	AFL	0		TSN 0						
PROC. REF: AMM 79-31-01										
793006	RIGHT ENGINE LOW OIL PRESSURE SWITCH									Component ATA:79
PN:1103P89-2	MOS/MSC	11-Mar-96	O/C							
SN:UNKNOWN	HRS	0		TSN 0						
WC#: 79.040	AFL	0		TSN 0						
PROC. REF: AMM 79-31-01										
A793001 ^S	INSPECT ENGINE OIL FILTER									Service ATA:79
	MOS	20-Apr-23								
	HRS	5396.4	150 (+30)							
WC#: 79.050	AFL	4627								
PROC. REF: AMM 79-31-00										PKG:2,4,15
ATA 80 - STARTING										
A801001 ^S	INSPECT LUCAS AEROSPACE STARTER-GENERATOR BRUSHES									Service ATA:80
	MOS	08-Jun-22	24 (+2m)							
	HRS	5229.6	300 (+30)							
WC#: 80.010	AFL	4502								
PROC. REF: AMM 80-11-01										PKG:4
B801002 ^S	OPERATIONAL CHECK STARTER DISENGAGE SYSTEM									Service ATA:80
	MOS	24-May-21	36 (+2m)							
	HRS	5149.5	1200 (+100)							
WC#: 80.020	AFL	4442								
PROC. REF: AMM 80-11-01										PKG:7,106

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task