



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055013	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK		MTH	16-Jun-1993		A/R			
5-12-01 051201	PHASE 1	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24 300		30-Nov-2023 9200.8	6 m 8 d 7.5
5-12-02 051202	PHASE 2	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24 300		30-Nov-2023 9200.8	6 m 8 d 7.5
5-12-03 051203	PHASE 3	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24 300		30-Nov-2023 9200.8	6 m 8 d 7.5
5-12-04 051204	PHASE 4	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24 300		30-Nov-2023 9200.8	6 m 8 d 7.5
5-12-05 051205	PHASE 5	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		36 1200		30-Nov-2024 10100.8	18 m 8 d 907.5
5-12-0B 051200B	PHASE B	KSWF	MTH HRS LDG	07-Jul-2022 9066.4 8317		150		9216.4	23.1
5-12-11 051211	PHASE 11	KSCH	MTH HRS LDG	22-Nov-2022 9132.8 8366		6		31-May-2023	9 d
5-12-13 051213	PHASE 13		MTH HRS	07-Nov-2003 4993		5000		9993	799.7
5-12-14 051214	PHASE 14	*CF	MTH HRS	16-Jun-1993 0		12000		12000	2806.7
5-12-15 051215	PHASE 15	*CF	MTH HRS	16-Jun-1993 0		10000		10000	806.7
5-12-16 051216	PHASE 16	*CF	MTH HRS	16-Jun-1993 0		10000		10000	806.7
5-12-17 051217	PHASE 17	*CF	MTH HRS	16-Jun-1993 0		10000		10000	806.7
5-12-18 051218	PHASE 18	KSCH	MTH HRS LDG	22-Nov-2022 9132.8 8366		12		30-Nov-2023	6 m 8 d
PHASE 56 SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH THE PHASE 18. PHASE 56 ADDED PER REV 21 TO 560 MM. OCTOBER 2005									
A262003 CABIN	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER	KSCH	C352 F-60590348	MTH	22-Nov-2022	12		30-Nov-2023	6 m 8 d
A262003 COCKPIT	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER	KSCH	C352 F-60591225	MTH	22-Nov-2022	12		30-Nov-2023	6 m 8 d
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24			
A341012 051220	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM)	KSYR	MTH HRS LDG	19-Nov-2021 8900.8 8218		24		30-Nov-2023	6 m 8 d
B341003 STANDBY 051220 : STDBY	CALIBRATION TEST ALTIMETER (91.411)	KSYR	C661072-0101 18049	MTH	19-Nov-2021	24		30-Nov-2023	6 m 8 d
B345001 NO. 1 051220 : XPDR1	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413)	KSYR	622-9352-501 4DKLY5	MTH	19-Nov-2021	24		30-Nov-2023	6 m 8 d



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B345001 NO. 2 <i>051220 : XPDR2</i>	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413)	KSYR		622-9352-501 4DKLY7	MTH 19-Nov-2021		24		30-Nov-2023	6 m 8 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		24			
A237003 <i>051221 : CVR</i>	INSPECT CVR UNDERWATER LOCATOR BEACON	KSYR		DK 120/90 AT164157	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		24		30-Nov-2023	6 m 8 d
B237004 <i>051221 : CVR</i>	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON	KSYR		DK 120/90 AT164157	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		24		30-Nov-2023	6 m 8 d
5-12-30 <i>051230</i>	PHASE 30	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		600		9500.8	307.5
5-12-32 <i>051232</i>	PHASE 32	*CF			MTH 16-Jun-1993 LDG 0		15000		15000	6600
5-12-33 <i>051233</i>	PHASE 33	*CF			MTH 16-Jun-1993 LDG 0		15000		15000	6600
5-12-34 <i>051234</i>	PHASE 34	GSO			MTH 20-Sep-2006 HRS 6704		6725		13429	4235.7
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 16-Jun-1993		72			
B262004 CABIN <i>051248 : A</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER	KPDK		C352 F-60590348	MTH 29-Aug-2019 HRS 8651 LDG 7926		72		31-Aug-2025	27 m 9 d
B262004 COCKPIT <i>051248 : F</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER	KPDK		C352 F-60591225	MTH 29-Aug-2019 HRS 8651 LDG 7926		72		31-Aug-2025	27 m 9 d
5-12-49 <i>051249</i>	PHASE 49	KPDK			MTH 24-Jul-2020 HRS 8776.3 LDG 8060		36 1200		31-Jul-2023 9976.3	2 m 9 d 783
5-12-54 <i>051254</i>	PHASE 54						N/A			
5-12-55	PHASE 55 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		18 1800			
D243003	INSPECT 44 AMP-HOUR GILL LEAD ACID MAIN SHIP BATTERY: PHASE 55	KSYR		7638-44T G03134959	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		18 1800		31-May-2023 10700.8	9 d 1507.5
5-12-56 <i>051256</i>	PHASE 56	KSCH			MTH 01-Jun-2022 HRS 9052.8 LDG 8304		12		30-Jun-2023	1 m 8 d
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 16-Jun-1993 HRS 0 LDG 0		A/R			
A561004 RIGHT INBOARD	PERFORM CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION			5511285-6 62498	MTH 16-Jun-1993		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A561004 RIGHT OUTBOARD	PERFORM CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION			5511285-4 SN-UNKNOWN	MTH 16-Jun-1993		A/R			
5-12-61	PHASE 61				MTH 16-Jun-1993 HRS 0		13200		13200	4006.7
5-12-62	PHASE 62				MTH 16-Jun-1993 HRS 0		15600		15600	6406.7
5-12-63	PHASE 63				MTH 16-Jun-1993 HRS 0		15600		15600	6406.7
5-12-64 051264	PHASE 64	KSCH			MTH 22-Nov-2022 HRS 9132.8 LDG 8366		6		31-May-2023	9 d
5-12-65	PHASE 65	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218 ACH 5410.1		500		5910.1	417.8
5-12-66	PHASE 66				MTH HRS		6000		13552.68	4359.38
5-12-67	PHASE 67				MTH HRS		10000		10000	806.7
5-12-68	PHASE 68				MTH HRS		1200		9473.5	280.2
5-12-MC 0512MC	PHASE MC	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		1456		10356.8	1163.5
5-12-MD 0512MD	PHASE MD	MCO			MTH 07-Jun-2012 HRS 7395.7 LDG 6744		2523		9918.7	725.4
5-12-ME 0512ME	PHASE ME	MCO			MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		4450		12532.3	3339
5-12-MF 0512MF	PHASE MF				MTH 15-Sep-2003 HRS 4884		5000		9884	690.7
5-12-MG	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 16-Jun-1993 LDG 0		10000			
A325009 0512MG	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK	*CF		6642000-3 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		10000		10000	1600
5-12-MI 0512MI	PHASE MI				MTH 15-Sep-2003 HRS 4884	-10	5130		10004	810.7
5-12-MJ 0512MJ	PHASE MJ				MTH 06-Apr-2005 HRS 5885	-10	5900		11775	2581.7
5-12-MK 0512MK	PHASE MK	GSO			MTH 26-Feb-2007 HRS 6721		6725		13446	4252.7
5-12-ML	PHASE ML	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		300		9200.8	7.5
057110 E1	MINOR INSPECTION	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		24 300		30-Nov-2023 (9026.6)9200.8	6 m 8 d 7.5
057110 E2	MINOR INSPECTION	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		24 300		30-Nov-2023 (8930)9200.8	6 m 8 d 7.5
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH				DAYS 16-Jun-1993		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH				DAYS 16-Jun-1993		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH				DAYS 16-Jun-1993		A/R			
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)	KPDK		1250151 1377R	MTH		N/R			
263005 FORWARD LEFT 262003 : FL	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE	KPDK		873364-1 0319023421	MTH 24-Jul-2020		N/A			
263007 FORWARD RIGHT 262003 : FR	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE	KPDK		873364-1 0319023422	MTH 24-Jul-2020		N/A			
263009 AFT LEFT 262003 : AL	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE	KPDK		873364-1 0419033437	MTH 24-Jul-2020		N/A			
263011 AFT RIGHT 262003 : AR	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE	KPDK		873364-1 0419033429	MTH 24-Jul-2020		N/A			
B262002 AFT 051223 : A	HYDROSTATIC TEST ENGINE FIRE BOTTLE	KPDK		898066-2 71016EK	MTH 24-Apr-2019		60		30-Apr-2024	11 m 8 d
B262002 FORWARD 051223 : F	HYDROSTATIC TEST ENGINE FIRE BOTTLE	KMCO		9912048-3 58064 EJ	MTH 30-Jun-2018		60		30-Jun-2023	1 m 8 d
B262003 CABIN 051247 : A	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	KPDK		C352 F-60590348	MTH 28-Aug-2019		144		31-Aug-2031	99 m 9 d
B262003 COCKPIT 051247 : F	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	KPDK		C352 F-60591225	MTH 28-Aug-2019		144		31-Aug-2031	99 m 9 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 16-Jun-1993		A/R			
324201 LEFT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	KPDK		3-1490-1 3141/0604	MTH 02-Oct-2018 HRS 8469.7 LDG 7762		T/C			
324201 RIGHT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	KPDK		3-1490-1 3141	MTH 02-Oct-2018 HRS 8469.7 LDG 7762		T/C			
324202	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY	KPDK		3-1403 7290	MTH 02-Oct-2018 HRS 8469.7 LDG 7762		T/C			
B326003 051222 : GEAR	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	KPDK		212940-2 4354	MTH 23-Jul-2020		36		31-Jul-2023	2 m 9 d
342048A NO. 1 051220I : ADDU	CALIBRATION TEST AIR DATA DISPLAY UNIT (91.411)	KSWF		9D-80130-16 29125	MTH 07-Jul-2022 HRS 9066.4 LDG 8317		24		31-Jul-2024	14 m 9 d



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342048A NO. 2 <i>0512201 : ADDU2</i>	CALIBRATION TEST AIR DATA DISPLAY UNIT (91.411)	KSWF		9D-80130-16 29227	MTH 07-Jul-2022 HRS 9066.4 LDG 8317		24		31-Jul-2024	14 m 9 d
350004 <i>051222 : OXY</i>	HYDROSTATIC TEST OXYGEN CYLINDER	KPDK		176202-77 ALT281-22024	MTH 23-Jul-2020		60		31-Jul-2025	26 m 9 d
710010 E1	OVERHAUL	MCO			MTH 12-May-2010 HRS 7181.5 LDG 6540		3500		(10507.3)10681.5	1488.2
710010 E2	OVERHAUL	MCO			MTH 12-May-2010 HRS 7184.3 LDG 6540		3500		(10413.5)10684.3	1491
710020 E1	HOT SECTION INSPECTION	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		1750		(10476.6)10650.8	1457.5
710020 E2	HOT SECTION INSPECTION	KSYR			MTH 19-Nov-2021 HRS 8900.8 LDG 8218		1750		(10380)10650.8	1457.5
710030 E1	TURBINE WASH				DAYS 16-Jun-1993		A/R			
710030 E2	TURBINE WASH				DAYS		A/R			
720010 E1	OIL ANALYSIS				MTH 16-Jun-1993		A/R			
720010 E2	OIL ANALYSIS						A/R			
720100 E1	ENGINE OVERTEMPERATURE				MTH 16-Jun-1993		A/R			
720100 E2	ENGINE OVERTEMPERATURE						A/R			
720110 E1	FOREIGN OBJECT DAMAGE (FOD)				MTH 16-Jun-1993		A/R			
720110 E2	FOREIGN OBJECT DAMAGE (FOD)						A/R			
720120 E1	LOSS OF OIL				MTH 16-Jun-1993		A/R			
720120 E2	LOSS OF OIL						A/R			
720130 E1	ENGINE OVERSPEED				MTH 16-Jun-1993		A/R			
720130 E2	ENGINE OVERSPEED						A/R			
720140 E1	ENGINE WINDMILLING				MTH 16-Jun-1993		A/R			
720140 E2	ENGINE WINDMILLING						A/R			
720150 E1	ENGINE IMMERSION IN WATER				MTH 16-Jun-1993		A/R			
720150 E2	ENGINE IMMERSION IN WATER						A/R			
720160 E1	ENGINE DROPPED DURING HANDLING				MTH 16-Jun-1993		A/R			
720160 E2	ENGINE DROPPED DURING HANDLING						A/R			
720170 E1	LIGHTNING STRIKE				MTH 16-Jun-1993		A/R			
720170 E2	LIGHTNING STRIKE						A/R			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720180 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT			MTH	16-Jun-1993		A/R			
720180 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT						A/R			
720190 E1	HEAVY/HARD LANDING			MTH	16-Jun-1993		A/R			
720190 E2	HEAVY/HARD LANDING						A/R			
720200 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH	16-Jun-1993		A/R			
720200 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH						A/R			
720210 E1	STARTER GENERATOR FAIL INDICATION			MTH	16-Jun-1993		A/R			
720210 E2	STARTER GENERATOR FAIL INDICATION						A/R			
720220 E1	HYDRAULIC PUMP FAILURE			MTH	16-Jun-1993		A/R			
720220 E2	HYDRAULIC PUMP FAILURE						A/R			
721045 E1	REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 14 DAYS			MTH	16-Jun-1993		A/R			
721045 E2	REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 14 DAYS						A/R			
721050 E1	REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 28 DAYS			MTH	16-Jun-1993		A/R			
721050 E2	REGULAR OPERATION PRESERVATION SCHEDULE FOR INACTIVE ENGINES - 1 TO 28 DAYS						A/R			
721055 E1	PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS			DAYS	16-Jun-1993		A/R			
721055 E2	PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS			DAYS			A/R			
721060 E1	PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS			DAYS	16-Jun-1993		A/R			
721060 E2	PRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS			DAYS			A/R			
721065 E1	DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS			MTH	16-Jun-1993		A/R			
721065 E2	DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 14 DAYS						A/R			
721070 E1	DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS			MTH	16-Jun-1993		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
721070 E2	DEPRESERVATION RECOMMENDATIONS FOR REGULAR OPERATION FOR INACTIVE ENGINES - 1 TO 28 DAYS						A/R			
721075 E1	PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 0 TO 90 DAYS			MTH	16-Jun-1993		A/R			
721075 E2	PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 0 TO 90 DAYS						A/R			
721080 E1	PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 91 DAYS AND OVER			MTH	16-Jun-1993		A/R			
721080 E2	PRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS FOR ENGINES UNDERGOING MAINTENANCE - 91 DAYS AND OVER						A/R			
721085 E1	DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS			MTH	16-Jun-1993		A/R			
721085 E2	DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS						A/R			
721090 E1	DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 91 DAYS AND OVER			MTH	16-Jun-1993		A/R			
721090 E2	DEPRESERVATION RECOMMENDATIONS AT OEM'S (AIRFRAME ORIGINAL MANUFACTURER), P&WC DELEGATED OVERHAUL FACILITIES AND FINISHING CENTERS - 91 DAYS AND OVER						A/R			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER			14438-000 1083	MTH 16-Jun-1993 HRS 174.2		3500		(10507.3)10681.5	1488.2
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER			14438-000 1125	HRS 270.8		3500		(10413.5)10684.3	1491
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 16-Jun-1993 HRS 174.2		3500		(10507.3)10681.5	1488.2
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE			PN SN-UNKNOWN	HRS 270.8		3500		(10413.5)10684.3	1491
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE			26395-2 0306	MTH 16-Jun-1993 HRS 174.2		3500		(10507.3)10681.5	1488.2
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE			26395-2 0163	HRS 270.8		3500		(10413.5)10684.3	1491
792010 E1	CHANGE OIL	MCO			MTH 12-May-2010 HRS 7181.5 LDG 6540		O/C			
792010 E2	CHANGE OIL	MCO			MTH 12-May-2010 HRS 7181.5 LDG 6540		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE *CF			27441482-06 10AH27	MTH 16-Jun-1993		O/C			
211004	S243 PRIMARY PRESSURE SWITCH *CF			1103P240-1 630	MTH 16-Jun-1993		O/C			
211005	S244 SECONDARY PRESSURE SWITCH *CF			1103P240-2 651	MTH 16-Jun-1993		O/C			
212001	INSTRUMENT PANEL FAN *CF			4124X SN-UNKNOWN	MTH 16-Jun-1993		O/C			
212002	AVIONICS BAY COOLING BOX FAN *CF			032105 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
212004	OVERHEAD CABIN FAN KSYR			BC61A-901-2EX 3021	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		1000	0	9900.8	707.5
212006	COCKPIT DEFOGGER FAN KSCH			5703-4 0085	MTH 22-Nov-2022 HRS 9132.8 LDG 8366		3500	1 0	12632.8	3439.5
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 1004	MTH 16-Jun-1993		O/C			
212010	AVIONICS BAY VANE AXIAL BLOWER *CF			19A827 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
212011	TEMP DUCT SENSOR 9912085-3	*CF		27221274 2AH1	MTH 16-Jun-1993		O/C			
213001	CABIN PRESSURE INDICATOR 3001J50	*CF		C668511-0103 19636	MTH 16-Jun-1993		O/C			
213003	RATE OF CHANGE INDICATOR 35060-1128	*CF		C668513-0101 W30275	MTH 16-Jun-1993		O/C			
213006	CABIN ALTITUDE CONTROLLER KSCH			130620-2 57-C0215	MTH 28-Dec-2022 HRS 9146.3 LDG 8374		O/C			
213007 NO. 1	PRIMARY OUTFLOW VALVE *CF			103648-14 112577	MTH 16-Jun-1993		O/C			
213007 NO. 2	SECONDARY OUTFLOW VALVE *CF			103648-14 112587	MTH 16-Jun-1993		O/C			
213009 NO. 1	FLOW CONTROL PRESSURE REGULATOR VALVE MCO			1988-00-1 2063A	MTH 28-Jul-2005 HRS 6134		O/C	0		
213009 NO. 2	FLOW CONTROL PRESSURE REGULATOR VALVE 9912162-1	*CF		34E16-4 GWD03844	MTH 16-Jun-1993		O/C			
213013	PNEUMATIC RELAY KSCH			130358-1 51-1104	MTH 28-Dec-2022 HRS 9146.3 LDG 8374		O/C	0 0		
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY 9912069-26	*CF		782343-2 920933	MTH 16-Jun-1993		O/C			
215004	AIR CYCLE MACHINE			738384-26 880754	MTH 06-Nov-2003 HRS 4988		5000	0	9988	794.7
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	ACM BYPASS VALVE *CF			754751-2 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
215007	COMPRESSION ACTUATOR 9912294-1	*CF		BYLB50907 587	MTH 16-Jun-1993		O/C			
215008	DUCT OVERHEAT SENSOR *CF			1173T42-1 2392	MTH 16-Jun-1993		O/C			
215009 NO. 1	ACM OVERHEAT SWITCH 410 *CF			1173T0635 SN-UNKNOWN	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215016	AC COMPRESSOR	MCO		1250160-11 3046	MTH 02-Jul-2017 HRS 8273.5 LDG 7581 ACH 5177.1		O/C	0 0		
215017	AC CONDENSER	*CF		1250180-7 792	MTH 16-Jun-1993		O/C			
215018	ACM CONTROL UNIT	*CF		C35020A SN-UNKNOWN	MTH 16-Jun-1993		O/C			
215021	MOTOR	KSYR		1250151 1377R	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C			
215022	AFT EVAPORATOR	MCO		1250240-23 124	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
215023	FWD EVAPORATOR	MCO		1134240-23 349	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		O/C	0 0		
215024	PRESSURE SWITCH	MCO		1250232-4 2142	MTH 10-Jun-1996 HRS 1233		O/C	0		
216001	CABIN TEMPERATURE SENSOR			1942T100-7 1391	MTH 25-Jan-2006 HRS 6432		O/C	0		
216002	CABIN TEMPERATURE CONTROLLER 9912069-22	KMCO		754661-5 C95110318	MTH 01-Mar-2014 HRS 7638.6 LDG 6943		O/C			
216003	DUCT TEMPERATURE SENSOR 9912069-14			754691-1 N0025	MTH 25-Jan-2006 HRS 6432		O/C	0		
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
216006	CABIN TEMP INDICATOR CAE			0221-007 14073	MTH 25-Mar-2008 HRS 6866		O/C	0		
216007	CABIN TEMP PROBE -	CAE		0221-100 SN-UNKNOWN	MTH 25-Mar-2008 HRS 6866		O/C	0		
216010	DOOR ACTUATOR MOTOR ASSEMBLY 9910059-3	MCO		5A3032 SN-UNKNOWN	MTH 21-Jul-1998 HRS 1924		O/C	0		
217001	WATER SEPARATOR 9912069-13	*CF		738386-3 920511	MTH 16-Jun-1993		O/C			
221001 NO. 1	ROLL RATE MONITOR- RZ-220	*CF		4015901-920 92121961	MTH 16-Jun-1993		O/C			
221001 NO. 2	ROLL RATE MONITOR- RZ-220	*CF		4015901-920 92111960	MTH 16-Jun-1993		O/C			
221008	AUTOPILOT COMPUTER SP-200	MCO		4008519-952 91064575	MTH 03-Oct-2012 HRS 7423.8 LDG 6767		O/C			
221009	AUTOPILOT CONTROL PC-500	*CF		4018639-933 92103652	MTH 16-Jun-1993		O/C			
221010 AILERON	SERVO SM-200	*CF		4006719-906 92106161	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
 Aircraft Model: **560 - CITATION V**
 Aircraft Serial: **560-0217**
 Unit: **0217** Reg No: **N802AB**
 Airworthiness: **16-Jun-1993**
 Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
221010 ELEVATOR	SERVO SM-200	KMCO		4006719-914 93026365	MTH 29-Jul-2015 HRS 7886.9 LDG 7175		O/C			
221010 RUDDER	SERVO SM-200	*CF		4006719-906 92116181	MTH 16-Jun-1993		O/C			
232002 NO. 2	VHF COMM ANTENNA	MCO		VFS10-90-7 1725	MTH 02-Jul-2017 HRS 8273.5 LDG 7581 ACH 5177.1		O/C	0 0		
232003 NO. 1	VHF COMM ANTENNA			VFS10-90-5 1206	MTH 06-Jun-2006 HRS 6602		O/C	0		
232004	TRANSCEIVER PHONE	PDK		400-0125-000 3489	MTH 17-Dec-1998 HRS 2044		O/C	2044		
232005 CABIN	HANDSET PHONE	*CF		400-0123-212 7779	MTH 16-Jun-1993		O/C			
232005	SATELITE ANTENNA			S67-1575-165 449-3800	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
232006 COCKPIT	HANDSET PHONE	*CF		400-0123-212 7752	MTH 16-Jun-1993		O/C			
232007	PHONE ANTENNA	*CF		121-0011 2419	MTH 16-Jun-1993		O/C			
232009 NO. 1	COMM CONTROL CTL-22	KSCH		622-6520-005 12584	MTH 22-Nov-2022 HRS 9132.8 LDG 8366		O/C			
232009 NO. 2	COMM CONTROL CTL-22	KSCH		622-6520-005 13204	MTH 28-Mar-2023 HRS 9193.3 LDG 8400		O/C			
232010 NO. 1	VHF COMMUNICATION TRANSCEIVER VHF-22A	RYR		622-6152-001 31587	MTH 07-Mar-2001 HRS 3392		O/C	3389		
232010 NO. 2	VHF COMMUNICATION TRANSCEIVER VHF-22A	*CF		622-6152-001 31592	MTH 16-Jun-1993		O/C			
235001 NO. 1	AUDIO AMPLIFIER	PDK		5630-1 917	MTH 27-Jan-2020 HRS 8749 LDG 8030		O/C			
235001 NO. 2	AUDIO AMPLIFIER	KPDK		5630-1 564	MTH 18-Oct-2019 HRS 8683 LDG 7969		O/C			
237001	COCKPIT VOICE RECORDER GA-100	KPDK		GA100-0000 2153	MTH 14-Apr-2017 HRS 8225.6 LDG 7536		O/C	8225.6 7536		
237006	CVR UNDERWATER LOCATOR BEACON	KPDK		DK 120/90 AT164157	MTH 15-Feb-2021 HRS 8862.6 LDG 8172		O/C	0		
237006A	REPLACE ULB (CVR) BATTERY			PN SN-UNKNOWN	MTH 15-Feb-2021 HRS 8862.6 LDG 8172		DUE DUE DUE DUE	0 0 0	31-Jan-2028	56 m 9 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
237042	HEADSUP CABIN BRIEFER BHM			HUCAB-1-SF-C560 602JH	MTH 22-Apr-1994 HRS 480		O/C	0		
237043	HEADSUP CONTROL UNIT *CF			HUCAB-2-GP 7779	MTH 16-Jun-1993		O/C			
242001 NO. 1	STATIC INVERTER RYY			SPC38B 1353	MTH 14-Jul-2003 HRS 4809		O/C	0		
242001 NO. 2	STATIC INVERTER KMCO			SPC38B 1488	MTH 10-Oct-2015 HRS 7935.3 LDG 7233		O/C	0 0 0		
243001 LEFT	STARTER/GENERATOR KSYR			9912125-3 98085	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		1000	0	9900.8	707.5
243001 RIGHT	STARTER/GENERATOR 9912125-3 KPKD			23085-004-1 92125	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		1000	0	9472.8	279.5
243003 NO. 1	GENERATOR CONTROL UNIT 9912039-6 *CF			51539-006F 92112B	MTH 16-Jun-1993		O/C			
243003 NO. 2	GENERATOR CONTROL UNIT 9912039-6 *CF			51539-006F 92123B	MTH 16-Jun-1993		O/C			
243004 NO. 1	AMMETER *CF			C662501-0104 795	MTH 16-Jun-1993		O/C			
243004 NO. 2	AMMETER *CF			C662501-0104 796	MTH 16-Jun-1993		O/C			
243005	DC VOLTMETER *CF			C662502-0101 1960	MTH 16-Jun-1993		O/C			
243007	MAIN SHIP BATTERY KSYR			7638-44T G03134959	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0		
243008	BATTERY TEMP MONITOR- *CF			1529-1 2103	MTH 16-Jun-1993		O/C			
243009	BATTERY TEMP GAGE *CF			1229-1 1787	MTH 16-Jun-1993		O/C			
243010	BATTERY TEMP SENSOR *CF			1166-1 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
243011	CURRENT/VOLTAGE CONTROLLER *CF			1301-1 1984	MTH 16-Jun-1993		O/C			
243015	BATTERY DISCONNECT RELAY *CF			A876K CK79868	MTH 16-Jun-1993		O/C			
243016	CURRENT/VOLTAGE SENSOR *CF			1302-1 1833	MTH 16-Jun-1993		O/C			
245002	CABIN ALTITUDE SWITCH 9910095-6 *CF			GB300NA161 9251356	MTH 16-Jun-1993		O/C			
256002	EMERGENCY LOCATOR TRANSMITTER MCO			3000-11 336303	MTH 04-Sep-2012 HRS 7410.4 LDG 6757		O/C	0 0		
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY KSWF			2020BATTERY NSN	MTH 07-Jul-2022 HRS 9066.4 LDG 8317		DUE DUE DUE DUE	0 0 0 0	30-Jun-2023	1 m 8 d
Expiration Date: 30-Jun-2023										
256004 NO. 1	ELT ANTENNA *CF			ELT10-177-1 1109	MTH 16-Jun-1993		O/C			
256004 NO. 2	ELT ANTENNA *CF			ELT10-177-2 1065	MTH 16-Jun-1993		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256010 10A	LIFE VEST	KPDK		S-51850-6300 10898	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	19	30-Jun-2028	61 m 8 d
256010 NO. 10	LIFE VEST	KPDK		S-51850-6300 10906	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	19	30-Jun-2028	61 m 8 d
256010 NO. 1	LIFE VEST	MCO		P01074-207 17022310060	MTH 02-Jul-2017 HRS 8273.5 LDG 7581 ACH 5177.1		120	4	31-Mar-2027	46 m 9 d
256010 NO. 2	LIFE VEST	KPDK		S-51850-6300 10903	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	18	31-Jul-2028	62 m 9 d
256010 NO. 3	LIFE VEST			AV-35 SN-UNKNOWN	MTH 13-Apr-2015 HRS 7826.8 LDG 7113		120	13 0 0	31-Mar-2024	10 m 9 d
256010 NO. 4	LIFE VEST			AV-35 SN-UNKNOWN	MTH 13-Apr-2015 HRS 7826.8 LDG 7113		120	13 0 0	31-Mar-2024	10 m 9 d
256010 NO. 5	LIFE VEST	KPDK		S-51850-6300 10911	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	19	30-Jun-2028	61 m 8 d
256010 NO. 6	LIFE VEST	KPDK		S-51850-6300 10896	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	19	30-Jun-2028	61 m 8 d
256010 NO. 7	LIFE VEST	KPDK		S-51850-6300 10907	MTH 24-Jan-2020 HRS 8749 LDG 8030		120	19	30-Jun-2028	61 m 8 d
256010 NO. 8	LIFE VEST			AV-35 SN-UNKNOWN	MTH 13-Apr-2015 HRS 7826.8 LDG 7113		120	13 0 0	31-Mar-2024	10 m 9 d
256010 TOILET	LIFE VEST	KPDK		P0723E105P 10010990014	MTH 24-Jan-2020 HRS 8749 LDG 8030		60	1	31-Dec-2024	19 m 9 d
261001 NO. 1 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
261001 NO. 2 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
261002 NO. 1	FIRE DETECTOR CONTROL 9912036-2	*CF		377-02808 9247003	MTH 16-Jun-1993		O/C			
261002 NO. 2	FIRE DETECTOR CONTROL 9912036-2	*CF		377-02808 9247007	MTH 16-Jun-1993		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9912048-3	MCO		898066-2 71016EK	MTH 03-Dec-2014 HRS 7789.8 LDG 7071		O/C			
262001 FORWARD	ENGINE FIRE BOTTLE	KMCO		9912048-3 58064 EJ	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C	1 0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KPDK		C352 F-60590348	MTH 29-Aug-2019 HRS 8651 LDG 7926		O/C	0 0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KPDK		C352 F-60591225	MTH 29-Aug-2019 HRS 8651 LDG 7926		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
262003 AFT LEFT	(MAX LIFE) CARTRIDGE KPKD	873364-1 0419033437	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		120		30-Apr-2029	71 m 8 d
Manufacture Date: 30-Apr-2019								
262003 AFT RIGHT	(MAX LIFE) CARTRIDGE KPKD	873364-1 0419033429	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		120		30-Apr-2029	71 m 8 d
Manufacture Date: 30-Apr-2019								
262003 FORWARD LEFT	(MAX LIFE) CARTRIDGE KPKD	873364-1 0319023421	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		120		31-Mar-2029	70 m 9 d
Manufacture Date: 31-Mar-2019								
262003 FORWARD RIGHT	(MAX LIFE) CARTRIDGE KPKD	873364-1 0319023422	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		120		31-Mar-2029	70 m 9 d
Manufacture Date: 31-Mar-2019								
271001	AILERON TRIM ACTUATOR *CF	5565450-72 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
272001	RUDDER TRIM ACTUATOR *CF	5565450-71 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
273002	TRIM MIXER ACTUATOR MCO	1U662-001 T344	MTH 03-Oct-2012 HRS 7423.8 LDG 6767		O/C	4 0 0		
273003 LEFT	ELEVATOR TRIM ACTUATOR *CF	5565450-81 SN-UNKNOWN	MTH 01-Oct-1997 HRS 1650		O/C	0		
273003 RIGHT	ELEVATOR TRIM ACTUATOR *CF	5565450-82 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
275001	FLAP CONTROL VALVE *CF	66720 913	MTH 16-Jun-1993		O/C			
275003 NO. 1	FLAP ACTUATOR 9912007-1	1535000 288	MTH 16-Jun-1993		O/C			
275003 NO. 2	FLAP ACTUATOR 9912007-1	1535000 232	MTH 16-Jun-1993		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER KMCO	CC50380 NSN	MTH 23-Sep-2015 HRS 7929.8 LDG 7223		5000	0	12223	3823
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER KMCO	CC50380 NSN	MTH 23-Sep-2015 HRS 7929.8 LDG 7223		5000	0	12223	3823
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER RYY	CC50380 SN-UNKNOWN	MTH 17-May-2004 HRS 5298 LDG 4969		5000	0	9969	1569
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER RYY	CC50380 SN-UNKNOWN	MTH 17-May-2004 HRS 5298 LDG 4969		5000	0	9969	1569
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER RYY	CC50380 SN-UNKNOWN	MTH 17-May-2004 HRS 5298 LDG 4969		5000	0	9969	1569
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER RYY	CC50380 SN-UNKNOWN	MTH 17-May-2004 HRS 5298 LDG 4969		5000	0	9969	1569
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER KMCO	CC50380 NSN	MTH 23-Sep-2015 HRS 7929.8 LDG 7223		5000	0	12223	3823
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER RYY	CC50380 SN-UNKNOWN	MTH 17-May-2004 HRS 5298 LDG 4969		5000	0	9969	1569

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
276001 NO. 1	SPEED BRAKE ACTUATOR 9912344-1 *CF	1535500-1 91	MTH 16-Jun-1993		O/C			
276001 NO. 2	SPEED BRAKE ACTUATOR 9912344-1 *CF	1535500-1 101	MTH 16-Jun-1993		O/C			
276002	SPEED BRAKE FLAP CONTROL VALVE *CF	66720 954	MTH 16-Jun-1993		O/C			
276003	SAFETY SPDBK VALVE *CF	68930 340	MTH 16-Jun-1993		O/C			
282001 NO. 1	ELECTRIC FUEL BOOST PUMP 9912017-2 MCO	1C7-12 2J27	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	24 0		
282001 NO. 2	ELECTRIC FUEL BOOST PUMP 9912017-2 MCO	1C7-12 7BB25	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C			
282010 LEFT	MOTIVE FUEL VALVE 3037075 UNK	3244850-1 B28450	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
282010 RIGHT	MOTIVE FUEL VALVE UNK	3244850-1 B28466	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
284001 NO. 1	FUEL LOW LEVEL SWITCH MCO	L15H-3 7195	MTH 24-Sep-2010 HRS 7206 LDG 6566		O/C	0 0		
284001 NO. 2	FUEL LOW LEVEL SWITCH *CF	L15H-3 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
284002 LEFT	FUEL QTY COMPENSATOR MCO	9912019-28 1992B	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
284002 RIGHT	FUEL QTY COMPENSATOR MCO	9912019-28 2077B	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0		
284007	FUEL QTY INDICATOR 9912147-26 *CF	VSDL-OC403F-1 562	MTH 16-Jun-1993		O/C			
291001	MAIN HYD RESERVOIR 9912052-12 *CF	40500-7 431	MTH 16-Jun-1993		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-4	24195-LAA 1381	MTH 10-Sep-1993 HRS 163		O/C	0		
291002 RIGHT	HYDRAULIC PUMP 9912062-4 *CF	24195-LAA 1440	MTH 16-Jun-1993		O/C			
291005 NO. 1	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3 BHM	3520020100-4 3189	MTH 20-Aug-1993 HRS 125		O/C	0		
291005 NO. 2	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3 *CF	3520020100-4 3329	MTH 16-Jun-1993		O/C			
291007 NO. 1	MOTOR ACTUATOR VALVE *CF	AV24B1325C5 P21100	MTH 16-Jun-1993		O/C			
291007 NO. 2	MOTOR ACTUATOR VALVE *CF	AV24B1325C5 P21104	MTH 16-Jun-1993		O/C			
291008	THERMAL RELIEF VALVE *CF	OAS5322-3-1700 261	MTH 16-Jun-1993		O/C			
291009	PRESSURE RELIEF VALVE *CF	4614 1284A	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291012	SOLENOID BYPASS VALVE *CF			61510-1 1051A	MTH 16-Jun-1993		O/C			
301001 LEFT	TEMP CONTROL SL002 SWITCH UVA			35-5D5230-01 340AF	MTH 24-Aug-2001 HRS 3657		O/C	0		
301001 NO. 1	OUTBRD WING DEICE BOOT MCO			35-5D5230-01 MYCYG30	MTH 28-Jul-2005 HRS 6134		O/C	0		
SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.										
301001 NO. 2	OUTBRD WING DEICE BOOT MCO			35-5D5230-02 MYC0TJ0	MTH 28-Jul-2005 HRS 6134		O/C	0		
SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.										
301001 RIGHT	TEMP CONTROL SR002 SWITCH UVA			35-5D5230-02 341AF	MTH 24-Aug-2001 HRS 3657		O/C	0		
301001 WING	ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 9914121-1 *CF			1H123-1 4AJ39	MTH 16-Jun-1993		O/C			
301002 NO. 1	HORIZONTAL STABILIZER DEICE BOOT MCO			29S-5D5225-05 MYC0J50	MTH 28-Jul-2005 HRS 6134		O/C	0		
301002 NO. 2	HORIZONTAL STABILIZER DEICE BOOT MCO			29S-5D5225-06 MYCV4N0	MTH 28-Jul-2005 HRS 6134		O/C	0		
301004 LEFT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 9912086-4 *CF			67410-2 2285ABC	MTH 16-Jun-1993		O/C			
301004 RIGHT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 9912086-4 *CF			67410-2 2234ABC	MTH 16-Jun-1993		O/C			
301007 LEFT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1 *CF			27441500-01 9AH49	MTH 16-Jun-1993		O/C			
301007 RIGHT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1 *CF			27441500-01 6AH26	MTH 16-Jun-1993		O/C			
301008 LEFT	DEICE CONTROL SLV19 VLV *CF			3D2353-06 N12113	MTH 16-Jun-1993		O/C			
301008 RIGHT	DEICE CONTROL SLV18 VLV *CF			3D2353-06 N12110	MTH 16-Jun-1993		O/C			
301009 LEFT	TEMP CONTROL S95 SENSOR 9912362-3 *CF			27431501-04 12AH112	MTH 16-Jun-1993		O/C			
301009 RIGHT	TEMP CONTROL S94 SENSOR 9912362-3 *CF			27431501-04 7AH100	MTH 16-Jun-1993		O/C			
302003 LEFT ENGINE	LEFT ENGINE ANTI-ICE SOLENOID VALVE 9912086-7 SAT			67410-1 2537ABCDEG	MTH 22-Oct-2002 HRS 4429		O/C	0		
302003 RIGHT ENGINE	RIGHT ENGINE ANTI-ICE SOLENOID VALVE 9912086-7			67410-1 2332ABCDEGK	MTH 22-Feb-2006 HRS 6471		O/C	0		
302004 LEFT ENGINE	INLET TEMPERATURE S95 SWITCH KMCO			M1002-505 000201	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		O/C	0 0		
302004 RIGHT ENGINE	INLET TEMPERATURE S94 SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 16-Jun-1993		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
302005 LEFT	ANTI ICING VALVE	UNK	10018200A 925	MTH HRS LDG	30-Apr-2010 7181.5 6540	O/C	0 0 0		
302005 RIGHT	ANTI ICING VALVE 3033057	UNK	10018200A 912	MTH HRS LDG	03-May-2010 7181.5 6540	O/C	0 0 0		
302006 LEFT	BLEED VALVE ACTUATOR 3037074	UNK	800888-1 F26022	MTH HRS LDG	30-Apr-2010 7181.5 6540	O/C	0 0 0		
302006 RIGHT	BLEED VALVE ACTUATOR 3037074	UNK	800888-1 F24172	MTH HRS LDG	03-May-2010 7181.5 6540	O/C	0 0 0		
303001 LEFT	PITOT TUBE	CAE	PH502 SN-UNKNOWN	MTH HRS	11-Sep-1998 1933	O/C	0		
303001 RIGHT	PITOT TUBE	CAE	PH502 SN-UNKNOWN	MTH HRS	11-Sep-1998 1933	O/C	0		
304001	BLEED AIR MONITOR- *CF		1169-1 1997	MTH	16-Jun-1993	O/C			
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 9912041-4	*CF	10663A 699	MTH	16-Jun-1993	O/C			
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP *CF		476411 SN-UNKNOWN	MTH	16-Jun-1993	O/C			
304005	TEMP CONTROL VALVE 9912085-1	*CF	27241287 11AH64	MTH	16-Jun-1993	O/C			
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR 9912085-6	*CF	27231272-20A 1AJ13	MTH	16-Jun-1993	O/C			
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH *CF		1115P25 1773A	MTH	16-Jun-1993	O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 9912086-4	KMCO	67410-2 3727ABCDEGK	MTH HRS LDG	29-Jul-2015 7886.9 7175	O/C	0 0		
312001 PILOT	DIGITAL CLOCK	KSCH	6420093-5 A22-12713	MTH HRS LDG	17-Feb-2022 8958.4 8253	O/C	0 0		
313001	FLIGHT HOUR RECORDER 15136	*CF	C664503-0102 SN-UNKNOWN	MTH	16-Jun-1993	O/C			
313003 NO. 1	ACCELEROMETER AG-222	*CF	7000992 6507	MTH	16-Jun-1993	O/C			
313003 NO. 2	ACCELEROMETER AG-222	*CF	7000992 6508	MTH	16-Jun-1993	O/C			
315001	MASTER WARNING ANNUNCIATOR 9912119-14	*CF	465-1-14 513	MTH	16-Jun-1993	O/C			
321001 LEFT	MAIN LANDING GEAR ASSEMBLY *CF		6641000-35 48	MTH LDG	16-Jun-1993 0	11425	0	11425	3025
321002 RIGHT	MAIN LANDING GEAR ASSEMBLY *CF		6641000-36 48	MTH LDG	16-Jun-1993 0	11425	0	11425	3025



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT *CF			5541220-2 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		9510	0	9510	1110
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT *CF			5541220-2 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		9510	0	9510	1110
322001	NOSE LANDING GEAR ASSEMBLY *CF			6642000-26 4	MTH 16-Jun-1993 LDG 0		23100	0	23100	14700
322002	NOSE SHIMMY DAMPER BHM			5543001-8 169038	MTH 21-Mar-1994 HRS 450 LDG 585		O/C	0		
322004	NOSE GEAR FORK/PISTON *CF			6642000-3 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		13380	0	13380	4980
323001 LEFT	MAIN LANDING GEAR ACTUATOR 9912111-1	MCO		1523100-3 310B	MTH 29-Nov-2012 HRS 7454.1 LDG 6798		15000	6757	15041	6641
323002 RIGHT	MAIN LANDING GEAR ACTUATOR 9912111-4	KMCO		1523100-8 721	MTH 12-Feb-2017 HRS 8194.4 LDG 7500		15000	0	22500	14100
323003	NOSE LANDING GEAR ACTUATOR 9912120-4	MCO		1523200-9 1890	MTH 04-Sep-2009 HRS 7042 LDG 6437		15000	0	21437	13037
323004 LEFT	MLG UPLOCK ACTUATOR *CF			5527504-2 1015	MTH 16-Jun-1993		O/C			
323004 NOSE	UPLOCK ACTUATOR *CF			5527504-2 1145	MTH 16-Jun-1993		O/C			
323004 RIGHT	MLG UPLOCK ACTUATOR *CF			5527504-2 1082	MTH 16-Jun-1993		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3	MCO		212940-2 4354	MTH 17-Jun-2008 HRS 6904		288	40	28-Feb-2029	69 m 6 d
323007	LANDING GEAR CONTROL VALVE *CF			66710 555	MTH 16-Jun-1993		O/C			
323008	DUMP VALVE *CF			OAS5319-1 284	MTH 16-Jun-1993		O/C			
323019	EMERGENCY AIR BOTTLE GAUGE *CF			2341128 51395A	MTH 16-Jun-1993		O/C	0		
324001 LEFT	MLG WHEEL ASSEMBLY 9912222-11	KSCH		3-1490-1 3141/0604	MTH 01-Jun-2022 HRS 9052.8 LDG 8304		O/C	0 0		
324001 RIGHT	MLG WHEEL ASSEMBLY 9912222-11	KPKD		3-1490-1 3141	MTH 02-Mar-2018 HRS 8355.4 LDG 7656		O/C			
324002	NOSE WHEEL ASSEMBLY 9914069-1	MCO		3-1403 7290	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		O/C	0 0 0		
324003 LEFT	MLG BRAKE ASSEMBLY 9912222-17	KPKD		2-1529-7 0842	MTH 15-Sep-2020 HRS 8797.1 LDG 8088		O/C	1 0		
324004 RIGHT	MLG BRAKE ASSEMBLY 9912222-17	KSCH		2-1529-7 3022	MTH 30-Mar-2023 HRS 9193.3 LDG 8400		O/C	4 0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
 Aircraft Model: **560 - CITATION V**
 Aircraft Serial: **560-0217**
 Unit: **0217** Reg No: **N802AB**
 Airworthiness: **16-Jun-1993**
 Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324005 LEFT	MLG TIRE	KSCH		220K28-1 20390576	MTH 01-Jun-2022 HRS 9052.8 LDG 8304		O/C	1 0		
324005 RIGHT	MLG TIRE	KSYR		220K28-1 11730458	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0 0		
324006	NOSE TIRE 9914070-1	KPDK		031-613-8 9176S00361	MTH 12-Feb-2021 HRS 8862.6 LDG 8172		O/C	19 0		
324010 LEFT	MLG SHUTTLE VALVE	KSCH		195-183 3452	MTH 01-Jun-2022 HRS 9052.8 LDG 8304		O/C	25 0		
324010 RIGHT	MLG SHUTTLE VALVE	KSCH		195-183 1543R	MTH 01-Jun-2022 HRS 9052.8 LDG 8304		O/C	17 0		
324011 LEFT	MLG INBOARD BRAKE MASTER CYLINDER 9912050-11	*CF		95367-9 622	MTH 16-Jun-1993		O/C			
324011 RIGHT	MLG INBOARD BRAKE MASTER CYLINDER 9912050-11	*CF		95367-9 585	MTH 16-Jun-1993		O/C			
324012 LEFT	MLG OUTBOARD MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 1075	MTH 16-Jun-1993		O/C			
324012 RIGHT	MLG OUTBOARD MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 1027	MTH 16-Jun-1993		O/C			
324014	EMERGENCY AIR BRAKE VALVE *CF			895232-0875 270	MTH 16-Jun-1993		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-2	*CF		634343 8142	MTH 16-Jun-1993		O/C			
324021	POWER BRAKE ANTISKID VALVE 9912305-7	*CF		38-707-1 759	MTH 16-Jun-1993		O/C			
324022	BRAKE CONTROL BOX 9912305-6	*CF		42-707-1 815	MTH 16-Jun-1993		O/C			
324023	ANTISKID ACCUMULATOR *CF			57C57652 RH0691	MTH 16-Jun-1993		O/C			
324024 LEFT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 2769	MTH 16-Jun-1993		O/C			
324024 RIGHT	MLG WHEEL TRANSDUCER 9912305-2	*CF		40-955 2777	MTH 16-Jun-1993		O/C			
324025	PRESSURE SWITCH 38-581501	*CF		1206P27 2045	MTH 16-Jun-1993		O/C			
324026	POWER BRAKE ASSEMBLY MOTOR *CF			MP50B1 81	MTH 16-Jun-1993		O/C			
324101	PARKING BRAKE VALVE 9912388-2	MCO		95905 554A	MTH 29-Jul-1998 HRS 1924		O/C	0		
325001	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-19 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
326003 LEFT	MAIN GEAR DOWN & LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
326003 RIGHT	MAIN GEAR DOWN & LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
326003	NOSE GEAR DOWN & LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED SWITCH PDK			65-430087 SN-UNKNOWN	MTH 29-Oct-1999 HRS 2628 LDG 2838		O/C	0		
326005 RIGHT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
326005	NOSE GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
331001 NO. 1	LIGHT PANEL DIMMER *CF			273-1 2046	MTH 16-Jun-1993		O/C			
331001 NO. 2	LIGHT PANEL DIMMER			273-1 149	MTH 07-Jul-2006 HRS 6678		O/C	71		
331001 NO. 3	LIGHT PANEL DIMMER *CF			273-1 2050	MTH 16-Jun-1993		O/C			
331011	INVT-115V EL PANEL *CF			EM2044-1 1627	MTH 16-Jun-1993		O/C			
332001 NO. 2	CU30 INDIRECT LIGHT POWER UNIT MCO			AL-5112 43846	MTH 04-Sep-2009 HRS 7042		O/C	0		
332001 NO. 3	CU29 INDIRECT LIGHT POWER UNIT KMCO			AL-5112 48516	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C	0 0		
332001 NO. 4	CU28 INDIRECT LIGHT POWER UNIT KMCO			AL-5112 48621	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C	0 0		
332001	INDIRECT LIGHT POWER UNIT MCO			AL-5112 43847	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0		
332002 AFT	INDIRECT LIGHTING INVERTER MCO			AL0581 11340	MTH 04-Sep-2009 HRS 7042		O/C	0		
332002 FORWARD	INDIRECT LIGHTING INVERTER *CF			AL5114 4988	MTH 16-Jun-1993		O/C			
334002	ROTATING/FLASHING BEACON KPKD			01-0790044-33 00669	MTH 06-Oct-2020 HRS 8809.2 LDG 8104		O/C	0 0		
334003 NO. 1	STROBE POWER SUPPLY KPKD			01-0790101-04 00550	MTH 21-Jun-2019 HRS 8624.6 LDG 7898		O/C			
334003 NO. 2	STROBE POWER SUPPLY KSCH			01-0790101-04 1168634001	MTH 04-Apr-2022 HRS 9018.9 LDG 8282		O/C	0 0		
335001	EMERGENCY BATTERY PACK			41B020BA01301 SN-UNKNOWN	MTH 16-Apr-2003 HRS 4691		O/C	0		
341005	S262 MACH/AIRSPEED WARNING SWITCH KSWF			9912076-14 140AM	MTH 07-Jul-2022 HRS 9066.4 LDG 8317		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341007 STANDBY	AIR SPEED INDICATOR			C661063-0107 289ABC	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C			
341010	ANGLE OF ATTACK INDICATOR *CF			C11605-1 347	MTH 16-Jun-1993		O/C			
341011	ANGLE OF ATTACK STALL WARNING COMPUTER MCO			C11606-8 332	MTH 21-Jul-1998 HRS 1924		O/C	0		
341013	ANGLE OF ATTACK TRANSMITTER *CF			1703-15 372	MTH 16-Jun-1993		O/C			
341019 STANDBY	ALTIMETER 10450-11110	PDK		C661072-0101 18049	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		O/C			
341022 341025	OAT INDICATOR 162BL507D	*CF		C668510-0401 2628	MTH 16-Jun-1993		O/C			
341035	ANGLE OF ATTACK HEAT MONITOR- *CF			1703-147-1 349	MTH 16-Jun-1993		O/C			
342001	MAGNETIC COMPASS *CF			C660501-0301 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
342021 NO. 1	VERTICAL SPEED INDICATOR *CF			C661006-0101 W30458	MTH 16-Jun-1993		O/C			
342021 NO. 2	VERTICAL SPEED INDICATOR ICT			80-5181-10-5 25102	MTH 16-Oct-2005 HRS 6289		O/C	0		
342041 NO. 1	FLIGHT DIRECTOR COMPUTER FZ-500	MCO		4018369-905 92016625	MTH 05-Sep-2014 HRS 7732.3 LDG 7024		O/C			
342041 NO. 2	FLIGHT DIRECTOR COMPUTER FZ-500	MCO		4018369-905 87025340	MTH 05-Sep-2014 HRS 7732.3 LDG 7024		O/C			
342042 NO. 1	MODE FLIGHT DIRECTOR SELECTOR MS-205	MCO		4020570-905 90081881	MTH 07-Jun-2012 HRS 7395.7 LDG 6744		O/C			
342042 NO. 2	MODE FLIGHT DIRECTOR SELECTOR MS-205	CAE		4020570-905 89021709	MTH 03-Apr-2008 HRS 6869		O/C	5842		
342043 NO. 1	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	KPDK		7000622-901 85105473	MTH 26-Apr-2019 HRS 8583.3 LDG 7863		O/C			
342043 NO. 2	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	MCO		7000622-901 80091938	MTH 03-Oct-2012 HRS 7423.8 LDG 6767		O/C			
342048I NO. 1	AIR DATA DISPLAY UNIT PDK			9D-80130-16 29125	MTH 23-Feb-2009 HRS 6955		O/C	0		
342048I NO. 2	AIR DATA DISPLAY UNIT PDK			9D-80130-16 29227	MTH 23-Feb-2009 HRS 6955		O/C	0		
342049 NO. 1	DIRECTIONAL GYRO C-14D	MCO		4020577-3 86043763	MTH 12-Mar-2010 HRS 7162		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342049 NO. 2	DIRECTIONAL GYRO C-14D			4020577-3 81112528	MTH 25-Nov-2005 HRS 6362		O/C	0		
342050 NO. 1	FLUX DETECTOR FX-220	KMCO		2594484 00094285	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C			
342050 NO. 2	FLUX DETECTOR FX-220	MCO		2594484 81055527	MTH 10-Jun-1996 HRS 1233		O/C	0		
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 92090851	MTH 16-Jun-1993		O/C			
342063 NO. 1	REMOTE COURSE CONTROL RI-206S	*CF		4026206-974 92114866	MTH 16-Jun-1993		O/C			
342064 STANDBY	GYRO POWER SUPPLY PS-835C	KMCO		501-1228-03 8868	MTH 01-Mar-2014 HRS 7638.6 LDG 6943		O/C			
342065	STANDBY GYRO AI-804	*CF		501-1197-05 4692	MTH 16-Jun-1993		O/C			
342069 NO. 1	INCLINOMETER AY-03	*CF		7005400-901 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
342069 NO. 2	INCLINOMETER AY-03	*CF		7005400-901 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
342069	MULTIFUNCTION DISPLAY CONTROLLER MC-800	*CF		7007062-927 92091172	MTH 16-Jun-1993		O/C			
342071	MFD SYMBOL GENERATOR MG-605	RYY		7011673-660 92120469	MTH 28-May-2003 HRS 4748		O/C	2675		
342072	STATIC CONVERTER	*CF		501-1318-01 3777	MTH 16-Jun-1993		O/C			
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER RDR-2100	MCO		071-01550-0101 1429	MTH 07-Nov-2013 HRS 7580.5 LDG 6895		O/C			
344022	RADIO ALT TRANSCEIVER ALT-55B	*CF		622-2855-001 8427	MTH 16-Jun-1993		O/C			
344023 AFT	RECEIVER RADIO ALT ANTENNA	*CF		622-0954-001 5721	MTH 16-Jun-1993		O/C			
344023 FORWARD	TRANSMITTER RADIO ALT ANTENNA	*CF		622-0954-001 5719	MTH 16-Jun-1993		O/C			
345004 AFT	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 53401	MTH 16-Jun-1993		O/C			
345004 FORWARD	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 53348	MTH 16-Jun-1993		O/C			
345005	TEMPERATURE PROBE	MCO		102DB1AG A68158	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0		
345007 AFT	DME ANTENNA 85226	*CF		DMNI50-2-2 53310	MTH 16-Jun-1993		O/C			
345007 FORWARD	DME ANTENNA 85226	*CF		DMNI50-2-2 51983	MTH 16-Jun-1993		O/C			
345010 NO. 1	NAVIGATION ANTENNA	*CF		DMN4-17-1B 3962	MTH 16-Jun-1993		O/C			
345011 NO. 1	ADF RECEIVER ADF-462	*CF		622-7382-101 1979	MTH 16-Jun-1993		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
 Aircraft Model: **560 - CITATION V**
 Aircraft Serial: **560-0217**
 Unit: **0217** Reg No: **N802AB**
 Airworthiness: **16-Jun-1993**
 Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345012 NO. 1	ADF CONTROL CTL-62			622-6522-005 3452	MTH 13-Jun-2006 HRS 6628		O/C	0		
345014 NO. 1	ADF ANTENNA ANT-462A	*CF		622-7383-001 1045	MTH 16-Jun-1993		O/C			
345015	LP/LPV MONITOR-	KSYR		3116-52-1110 610	MTH 31-Aug-2022 HRS 9097.8 LDG 8339		O/C			
345017	MARKER BEACON ANTENNA *CF			CI164 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
345018	GLIDESLOPE ANTENNA *CF			RGS10-48 A2813	MTH 16-Jun-1993		O/C			
345031	NAVIGATION(FMS) COMPUTER KPKD			3116-42-1116 609	MTH 30-Nov-2020 HRS 8828.7 LDG 8130		O/C			
345032 NO. 1	VHF NAV RECEIVER VIR-32	KMCO		622-6137-201 12027	MTH 10-Oct-2015 HRS 7935.3 LDG 7233		O/C			
345032 NO. 2	VHF NAV RECEIVER VIR-32	*CF		622-6137-001 13634	MTH 16-Jun-1993		O/C			
345033 BOTTOM	VHF NAV CONTROL CTL-32	UVA		622-6521-013 13915	MTH 24-Aug-2001 HRS 3657		O/C	3657		
345033	VHF NAV CONTROL CTL-32	*CF		622-6521-013 13916	MTH 16-Jun-1993		O/C			
345034 NO. 1	ATC TRANSPONDER	KMCO		622-9352-501 4DKLY5	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C	0 0		
345034 NO. 2	ATC TRANSPONDER	KMCO		622-9352-501 4DKLY7	MTH 18-Jul-2018 HRS 8420.4 LDG 7719		O/C	0 0		
345036 NO. 1	DME RECEIVER TRANSMITTER DME-42	*CF		622-6263-003 11937	MTH 16-Jun-1993		O/C			
345036 NO. 2	DME RECEIVER TRANSMITTER DME-42	*CF		622-6263-003 11913	MTH 16-Jun-1993		O/C			
345037	MFD CHECKLIST			7990302-130 90030633	MTH 25-Jun-1993 HRS 7		O/C	0		
345040	TRANSPONDER CONTROL MCO			071-01542-2401 1160	MTH 07-Nov-2013 HRS 7580.5 LDG 6895		O/C			
345069	XM WEATHER RECEIVER MCO			XMD075-01 805000736	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
345075 NO. 2 345078 : 2	GPS RECEIVER NAV UNIT *CF			19100-0101 178	MTH 16-Jun-1993		O/C			
345077	DATA TRANSFER UNIT			1408-00-1 955	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
345081 NO. 1	CONFIGURATION MODULE CMU-GNSX	*CF		31990-1 3387	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345082 NO. 1	GNS/FMS DISPLAY	MCO		1018-2-113 2565	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0		
345083	NAV MANAGEMENT PROCESSOR GSO			14141-0624-1465 M1354	MTH 20-Sep-2006 HRS 6704		O/C	0		
345093	GPS ANTENNA	MCO		10708 6282	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0		
345094	GPS CONVERTER	BHM		400-014135-01 2090	MTH 13-Nov-1996 HRS 1445		O/C	0		
346001	TCAS PROCESSOR TPU-66A	SAV		066-01145-0101 2713	MTH 27-Oct-2010 HRS 7220.8 LDG 6582		O/C			
346002	XM SATELLITE ANTENNA MCO			XMRANT-01 121497	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
348000 CENTER	INTEGRATED FLAT PANEL DISPLAY -- KPKD			9D-84095-1 62535	MTH 24-Jul-2019 HRS 8637.6 LDG 7912		O/C			
348000 LEFT	INTEGRATED FLAT PANEL DISPLAY -- KSYR			9D-84095-1 64489	MTH 07-Dec-2021 HRS 8900.8 LDG 8218		O/C			
348000 RIGHT	INTEGRATED FLAT PANEL DISPLAY -- KSYR			9D-84095-1 62839	MTH 07-Dec-2021 HRS 8900.8 LDG 8218		O/C			
348001 NO. 1	ENGINE DATA CONCENTRATOR UNIT -- MCO			9B-84097-1 62819	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
348001 NO. 2	ENGINE DATA CONCENTRATOR UNIT -- MCO			9B-84097-1 62821	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
348002 NO. 1	RADIO NAV CONVERSION UNIT -- MCO			9B-81111-1 62633	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
348002 NO. 2	RADIO NAV CONVERSION UNIT -- KMCO			9B-81111-1 62635	MTH 01-Nov-2016 HRS 8144.1 LDG 7448		O/C			
348004	ELECTRONIC CHART SERVER UNIT -- MCO			9B-87006-1 62629	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
348005 NO. 1	INST CONFIG MODULE-RCU (ICM) -- MCO			9B-07035-1 62727	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
348005 NO. 2	INST CONFIG MODULE-RCU (ICM) -- MCO	9B-07035-1 62729	MTH 13-Sep-2010 HRS 7184.6 LDG 6562		O/C	0 0 0		
351001	OXYGEN PRESSURE GAUGE MD-97 *CF	C668512-0101 559	MTH 16-Jun-1993		O/C	0		
351002	OXYGEN PRESSURE SWITCH 9912057-5 GSO	P24031 2892	MTH 20-Sep-2006 HRS 6704		O/C	0		
351004 COPILOT	OXYGEN MASK 9914067-41 KPDK	MC10-15-109 41671	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		72	1	30-Sep-2024	16 m 8 d
351004 PILOT	OXYGEN MASK 9914067-41 KSYR	MC10-15-109 105844	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		72	0	30-Nov-2027	54 m 8 d
351005	OXYGEN SUPPLY REGULATOR *CF	172170-01 411	MTH 16-Jun-1993		O/C	0		
351006	OXYGEN CYLINDER 9914067-42 MCO	176202-77 ALT281-22024	MTH 17-Jun-2008 HRS 6904		180	0	30-Jun-2023	1 m 8 d
Manufacture Date: 01-Jun-2008								
361003	PNEUMATIC REGULATOR 9912043-2 *CF	38E85-5C RF1972	MTH 16-Jun-1993		O/C			
361008 NO. 1	VALVE CHECK MCO	1553-00-18 787	MTH 10-Jun-1996 HRS 1233		O/C	0		
361008 NO. 2	VALVE CHECK MCO	1553-00-18 789	MTH 10-Jun-1996 HRS 1233		O/C	0		
383002	MOTOR AND PUMP TOILET *CF	17200-382 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
521001	CABIN DOOR SEAL 9912075-4 MCO	S15501-4 NSN	MTH 28-Jul-2005 HRS 6134		O/C	0		
521002	EMERGENCY EXIT SEAL BHM	R881204 SN-UNKNOWN	MTH 03-Nov-1994 HRS 667		O/C	0		
531001 LEFT	NOSE LANDING GEAR TRUNNION SUPPORT *CF	6613056-3 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		11820	0	11820	3420
531001 RIGHT	NOSE LANDING GEAR TRUNNION SUPPORT *CF	6613056-4 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		11820	0	11820	3420
531202 NOSE LANDING GEAR	ACTUATOR FITTING *CF	6511105-1 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		23100	0	23100	14700
541001 LEFT	INLET ASSEMBLY KPDK	5552250-119 802AB	MTH 03-Apr-2020 HRS 8771.7 LDG 8053		O/C			
541001 RIGHT	INLET ASSEMBLY MCO	6595120-2W SN-UNKNOWN	MTH 10-Sep-1993 HRS 163		O/C	0		
561001 NO. 1	LEFTHAND MAIN WINDSHIELD ASSY, (LH) 9912064-11 MCO	E149000-9 2441	MTH 25-Jul-2010 HRS 7200.8 LDG 6560		O/C			
561002 NO. 2	RIGHTHAND MAIN WINDSHIELD ASSY, (RH) 9912064-16 GSO	E149000-102 930	MTH 20-Sep-2006 HRS 6704		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561003	FOUL WEATHER WINDOW GSO			5511275-17 12-05	MTH 20-Sep-2006 HRS 6704		O/C	0		
561005 LEFT INBOARD	PILOTS INNER WINDOW MCO			5511285-5 71998	MTH 29-Jul-1998 HRS 1924		O/C	0		
561005 LEFT OUTBOARD	PILOTS OUTER WINDOW *CF			5511285-3 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
561005 RIGHT INBOARD	CO-PILOTS INNER WINDOW MCO			5511285-6 62498	MTH 29-Jul-1998 HRS 1924		O/C	0		
561005 RIGHT OUTBOARD	CO-PILOTS OUTER WINDOW UVA			5511285-4 SN-UNKNOWN	MTH 11-Sep-2003 HRS 4884		O/C	0		
562001 L1 562002 : L1	CABIN DOOR WINDOW *CF			5512207-1 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L2	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L3	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L4	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L5	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L6	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 L7	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R1	EMERGENCY DOOR WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R2	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R3	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R4	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R5	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R6	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
562001 R 7	CABIN WINDOW *CF			5511260-8 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
572001 LEFT AFT 572003 : LA	MLG TRUNNION FITTING ASSEMBLY *CF			5522710-15 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		22900	0	22900	14500
572001 LEFT FORWARD	MLG TRUNNION FITTING ASSEMBLY *CF			6522057-5 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		22900	0	22900	14500
572001 RIGHT AFT 572003 : RA	MLG TRUNNION FITTING ASSEMBLY *CF			5522710-15 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		22900	0	22900	14500
572001 RIGHT FORWARD 572002 : R	MLG TRUNNION FITTING ASSEMBLY *CF			6522057-6 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		22900	0	22900	14500
574003 LEFT	MLG SIDE BRACE SUPPORT FITTING *CF			6522047-1 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		24700	0	24700	16300
574004 RIGHT	MLG SIDE BRACE SUPPORT FITTING *CF			6522047-2 SN-UNKNOWN	MTH 16-Jun-1993 LDG 0		24700	0	24700	16300



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712001 LEFT	ENGINE AFT ISOLATOR 9912455-2	MCO		LM420SA6-1 R0744	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
712001 RIGHT	ENGINE AFT ISOLATOR 9912455-2	MCO		LM420SA6-1 2337	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912455-1	MCO		LM420SA5-1 3254	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
712002 LEFT TOP	FORWARD ENGINE ISOLATOR 9912455-1	MCO		LM420SA5-1 3256	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912455-1	MCO		LM420SA5-1 3255	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
712002 RIGHT TOP	FORWARD ENGINE ISOLATOR 9912455-1	MCO		LM420SA5-1 3257	MTH 12-May-2010 HRS 7181.5 LDG 6540		3500	0	10681.5	1488.2
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	MCO		3042000 PCE-108444	MTH 12-May-2010 HRS 7181.5 LDG 6540		E/C	7007.3		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	MCO		3042000 PCE-108440	MTH 12-May-2010 HRS 7181.5 LDG 6540		E/C	6913.5		
724001 E1	COMBUSTOR LINER	UNK		3119770-01 PWV030987JT	MTH 29-Jun-2021 HRS 8900.8 LDG 8218		O/C	4 0 0		
724001 E2	COMBUSTOR LINER	UNK		3116031-01 0471	MTH 29-Jun-2021 HRS 8900.8 LDG 8218		O/C			
721010 E1	ACESSORY DRIVE GEAR BOX RYY			3031170 SN-UNKNOWN	MTH 04-Aug-2001 HRS 3647		O/C	0		
721010 E2	ACESSORY DRIVE GEAR BOX RYY			3031170 SN-UNKNOWN	MTH 04-Aug-2001 HRS 3647		O/C	0		
722001 E1	OIL PUMP	UNK		3104289-01 OP0530	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
722001 E2	OIL PUMP	UNK		3104289-01 OP1076	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
722607 E1	LOW COMPRESSOR HUB 3037911	UNK		3037911 56A806	MTH 30-Apr-2010 HRS 7181.5 LDG 6540 ACCC YC		12000	7007.3 6418 6418		3752
722607 E2	LOW COMPRESSOR HUB 3037911	UNK		3037911 59A541	MTH 03-May-2010 HRS 7181.5 LDG 6540 ACCC YC		12000	6913.5 6312 6312		3859
723001 E1	LP COMPRESSOR ROTOR BALANCE ASSEMBLY ICT			3117459-01 56A806	MTH 16-Oct-2005 HRS 6289		O/C	2642		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723001 E2	LP COMPRESSOR ROTOR BALANCE ASSEMBLY RYY			3102814-01 SN-UNKNOWN	MTH 04-Aug-2001 HRS 3647		O/C	0		
723020 E1	LOW BOOST COMPRESSOR HUB 3038312	UNK		3038312 57A049	MTH 30-Apr-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	7007.3 6418 6418		5752
723020 E2	LOW BOOST COMPRESSOR HUB 3038312	UNK		3038312 57A042	MTH 03-May-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	6913.5 6312 6312		5859
723705 E1	2ND-STAGE LOW TURBINE ROTOR DISK UNK			3022212 62A225	MTH 30-Apr-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	7007.3 6418 6418		5752
723705 E2	2ND-STAGE LOW TURBINE ROTOR DISK UNK			3022212 61A093	MTH 03-May-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	6913.5 6312 6312		5859
724006 E1	3RD-STAGE LOW TURBINE ROTOR DISK UNK			3036113 61A427	MTH 30-Apr-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	7007.3 6418 6418		5752
724006 E2	3RD-STAGE LOW TURBINE ROTOR DISK UNK			3036113 61A544	MTH 03-May-2010 HRS 7181.5 LDG 6540 ACCC YC		14000	6913.5 6312 6312		5859
724706 E1	HIGH TURBINE ROTOR DISK UNK			3036411 60A991	MTH 29-Jun-2021 HRS 8900.8 LDG 8218 ACCC YC		14000	8726.6 8066 8066		5752
724706 E2	HIGH TURBINE ROTOR DISK UNK			3036411 61A489	MTH 29-Jun-2021 HRS 8900.8 LDG 8218 ACCC YC		14000	8630 7959 7959		5859
724707 E1	HIGH TURBINE BLADES UNK			3055021-01 SN-UNKNOWN	MTH 29-Jun-2021 HRS 8900.8 LDG 8218		O/C	1576.7 1335		
724707 E2	HIGH TURBINE BLADES UNK			3055021-01 SN-UNKNOWN	MTH 29-Jun-2021 HRS 8900.8 LDG 8218		O/C	1576.7 1335		
724825 E1	CENTRIFUGAL IMPELLER 3039555	UNK		3039555 6E001	MTH 30-Apr-2010 HRS 7181.5 LDG 6540 ACCC YC		12000	7007.3 6418 6418		3752
724825 E2	CENTRIFUGAL IMPELLER 3039555	UNK		3039555 5E824	MTH 03-May-2010 HRS 7181.5 LDG 6540 ACCC YC		12000	6913.5 6312 6312		3859



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731004 NO. 1	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH 16-Jun-1993		O/C			
731004 NO. 2	LOW FUEL PRESSURE SWITCH 9912033-2	RYY		1103P0448 4258	MTH 09-May-2001 HRS 3492		O/C	0		
733003 NO. 1	FUEL FLOW TRANSMITER 9912031-6	KSCH		3268014-0201 1953D	MTH 29-Jul-2022 HRS 9080.8 LDG 8329		O/C			
733003 NO. 2	FUEL FLOW TRANSMITER 9912031-6	KSCH		3268014-0201 003369D	MTH 29-Jul-2022 HRS 9080.8 LDG 8329		O/C			
731001 E1	FUEL PUMP 3037078	UNK		717101-1 0475	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731001 E2	FUEL PUMP 3037078	UNK		717101-1 0463	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731002 E1	FLOW DIVIDER VALVE 3119573-01	UNK		26395-2 0306	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731002 E2	FLOW DIVIDER VALVE 3119573-01	UNK		26395-2 0163	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731005 E1	BLEED CONTROL VALVE UNK	UNK		800831-1-001 92080477	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C			
731005 E2	BLEED CONTROL VALVE UNK	UNK		800831-1-001 C95050060	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C			
731006 E1	EFCU WIRING HARNESS KPKD			3119094-01 NSN	MTH 27-Feb-2016 HRS 8016.8 LDG 7320		O/C	0 0		
731006 E2	EFCU WIRING HARNESS UNK	UNK		3112429-01 AA1694	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731020 E1	FUEL-OIL COOLER UNK	UNK		14438-000 1083	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731020 E2	FUEL-OIL COOLER UNK	UNK		14438-000 1125	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
731030 E1	MOTIVE FLOW VALVE UNK			PN SN-UNKNOWN	MTH 16-Jun-1993		O/C	0		
731030 E2	MOTIVE FLOW VALVE UNK			PN SN-UNKNOWN			O/C			
731065 E1	BLEED VALVE ACTUATOR UNK			PN SN-UNKNOWN	MTH 16-Jun-1993		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
731065 E2	BLEED VALVE ACTUATOR		PN SN-UNKNOWN			O/C			
731085 E1	SCHEDULE MODULATOR		PN SN-UNKNOWN	MTH 16-Jun-1993		O/C	0		
731085 E2	SCHEDULE MODULATOR		PN SN-UNKNOWN			O/C			
732001 E1	FUEL CONTROL UNIT	UNK	3244851-10-9 B29357	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732001 E2	FUEL CONTROL UNIT	UNK	3244851-10 B29454	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732005 E1	N1 SPEED SENSOR	UNK	3100335-01 A934	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732005 E2	N1 SPEED SENSOR	UNK	3100335-01 A931	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732006 E1 BOTTOM	N2 SPEED SENSOR	UNK	3032997 C143	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732006 E1 TOP	N2 SPEED SENSOR	UNK	3032997 C145	MTH 30-Apr-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732006 E2 BOTTOM	N2 SPEED SENSOR	UNK	3032997 C146	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732006 E2 TOP	N2 SPEED SENSOR	UNK	3032997 C156	MTH 03-May-2010 HRS 7181.5 LDG 6540		O/C	0 0 0		
732045 E1	ELECTRONIC BLEED VALVE CONTROL		PN SN-UNKNOWN	MTH 16-Jun-1993		O/C	0		
732045 E2	ELECTRONIC BLEED VALVE CONTROL		PN SN-UNKNOWN			O/C			
732065 E1	MAIN WIRING HARNESS		PN SN-UNKNOWN	MTH 16-Jun-1993		O/C	0		
732065 E2	MAIN WIRING HARNESS		PN SN-UNKNOWN			O/C			
741001 E1 INBOARD	IGNITION EXCITER	RYY	NB01201 U6199	MTH 04-Aug-2001 HRS 3647		O/C	0		
741001 E1 OUTBOARD	IGNITION EXCITER	RYY	NB01201 U5699	MTH 04-Aug-2001 HRS 3647		O/C	0		
741001 E2 INBOARD	IGNITION EXCITER	RYY	CH92028 99101326	MTH 04-Aug-2001 HRS 3647		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER	RYY	CH92028 99088754	MTH 04-Aug-2001 HRS 3647		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description		Part Number		C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
742001 E1 INBOARD	IGNITER PLUG 3030595	KSYR		FHE-246-4 N/A	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0		
742001 E1 OUTBOARD	IGNITER PLUG 3030595	KSYR		FHE-246-4 N/A	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0		
742001 E2 INBOARD	IGNITER PLUG 3030595	KSYR		FHE-246-4 N/A	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0		
742001 E2 OUTBOARD	IGNITER PLUG 3030595	KSYR		FHE-246-4 N/A	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		O/C	0 0		
742002 E1 INBOARD	IGNITER PLUG CABLE	KPDK		53067-21 N/A	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		O/C	0 0		
742002 E2 INBOARD	IGNITER PLUG CABLE 3027939	KPDK		3107371-01 N/A	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		O/C	0 0		
742003 E1 OUTBOARD	IGNITER PLUG CABLE	KPDK		53067-38.5 N/A	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		O/C	0 0		
742003 E2 OUTBOARD	IGNITER PLUG CABLE	KPDK		53067-38.5 N/A	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		O/C	0 0		
761002	SYNCHRONIZER CONTROL BOX MCO	E		213693 2489857D	MTH 15-Jun-1999 HRS 2425		O/C		2425	
761003	ENGINE SYNC ACTUATOR MCO			5485-066 2247590H	MTH 29-Jul-1993 HRS 76		O/C		0	
783001 LEFT ENGINE	THRUST REVERSER ASSEMBLY 9912377-1	MCO		262-0001-501 2870	MTH 05-Sep-2014 HRS 7732.3 LDG 7024		O/C			
783001 RIGHT ENGINE	THRUST REVERSER ASSEMBLY 9912377-2	MCO		262-0001-503 2871	MTH 05-Sep-2014 HRS 7732.3 LDG 7024		O/C			
783002 LEFT ENGINE	THRUST REVERSER CONTROL VALVE *CF			65680 1812	MTH 16-Jun-1993		O/C			
783002 RIGHT ENGINE	THRUST REVERSER CONTROL VALVE *CF			65680 1877	MTH 16-Jun-1993		O/C			
783003 LEFT ENGINE	THRUST REVERSER ISOLATION VALVE *CF			13027-4 2585	MTH 16-Jun-1993		O/C			
783003 RIGHT ENGINE	THRUST REVERSER ISOLATION VALVE *CF			13027-4 2593	MTH 16-Jun-1993		O/C			
783005 LEFT	THRUST REVERSER UPPER DOOR ASSEMBLY *CF			202-0001-503 2870	MTH 16-Jun-1993		O/C			
783005 RIGHT	THRUST REVERSER UPPER DOOR ASSEMBLY *CF			202-0001-504 2871	MTH 16-Jun-1993		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
783006 LEFT	THRUST REVERSER LOWER DOOR ASSEMBLY				MTH	16-Jun-1993		O/C		
		*CF		202-0002-505 2870						
783006 RIGHT	THRUST REVERSER LOWER DOOR ASSEMBLY				MTH	16-Jun-1993		O/C		
		*CF		202-0002-506 2871						
783007 LEFT	THRUST REVERSER UPPER MECHANISM				MTH	16-Jun-1993		O/C		
		*CF		225-0007-513 2870						
783007 RIGHT	THRUST REVERSER UPPER MECHANISM				MTH	16-Jun-1993		O/C		
		*CF		225-0007-513 2871						
783008 LEFT	THRUST REVERSER LOWER MECHANISM				MTH	16-Jun-1993		O/C		
		*CF		225-0007-515 2870						
783008 RIGHT	THRUST REVERSER LOWER MECHANISM				MTH	16-Jun-1993		O/C		
		*CF		225-0007-515 2871						
783009 LEFT	THRUST REVERSER FAN DUCT				MTH	16-Jun-1993		O/C		
		*CF		225-0014-507 2870						
783009 RIGHT	THRUST REVERSER FAN DUCT				MTH	16-Jun-1993		O/C		
		*CF		225-0014-508 2871						
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR				MTH	16-Jun-1993		O/C		
		*CF		62270 3704						
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR				MTH	16-Jun-1993		O/C		
		*CF		62270 3707						
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR				MTH	16-Jun-1993		O/C		
		*CF		62270 3706						
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR				MTH	16-Jun-1993		O/C		
		*CF		62270 3702						
783011 RIGHT	EXHAUST NOZZLE CONE				MTH	16-Jun-1993		O/C		
	9912377-3	*CF		225-0016-513-V4 SN-UNKNOWN						
783012 LEFT ENGINE	EXHAUST NOZZLE	MCO			MTH	12-Mar-2010		O/C		
	9912377-3			225-0016-513-V4 NSN	HRS	7162			0	
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER				MTH	20-Aug-1993		O/C		
		BHM		MS28034-3 51382	HRS	125			0	
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER				MTH	16-Jun-1993		O/C		
		*CF		102-00083 150						
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER				MTH	16-Jun-1993		O/C		
	9912164-1	*CF		123479 47992						
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER				MTH	16-Jun-1993		O/C		
	9912164-1	*CF		123479 47988						
793006 LEFT ENGINE	LOW OIL PRESSURE SWITCH				MTH	16-Jun-1993		O/C		
	9912178-3	*CF		1103P89-2 SN-UNKNOWN						
793006 RIGHT ENGINE	LOW OIL PRESSURE SWITCH				MTH	31-Oct-1994		O/C		
	9912178-3	BHM		1103P89-2 SN-UNKNOWN	HRS	663			0	



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-03-02 R01	SUPPLEMENTAL TYPE CERTIFICATE (STC) (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SB 560-03-06 R01	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL			-			
	MOC :									
SB 560-03-06	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION (SUPERSEDED BY 560-03-06 R01)			OPTIONAL			-			
	MOC :									
SL CIL-03-01	SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560-99-02 R06	CESCOM PRICES (THIS SL CANCELS SL560-99-02 R5 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 560-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SB 560-11-04 11SB-04	FIRE EXTINGUISHER PLACARD INSTALLATION			OPTIONAL MTH			-			
	MOC :									
SB 560-12-01	ADDITIONAL APPROVED FUEL ANTI-ICE ADDITIVES (SUPERSEDED BY 560-12-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									
SL 560-20-01 R25	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560-20-01 R26)			INFORMATIONAL			A/R			
	MOC :									
SL 560-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 560-21-10 <i>21SB-10</i>	ADDITIONAL OUTFLOW VALVE REPLACEMENT (SUPERSEDED BY 560-21-10 R01)	BHM		MANDATORY	MTH 12-Jul-1995 HRS 880		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-21-12 R01 <i>21SB-12 : 560R1</i>	RAM AIR DUCT IMPROVEMENT (SUPERSEDED BY 560-21-12 R02)			OPTIONAL	MTH		-			
	MOC :									
SB 560-21-12 R02	RAM AIR DUCT IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SB 560-21-15 <i>21SB-15</i>	COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			OPTIONAL	MTH		-			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 560-21-16 R01 <i>21SB-16 : 560R1</i>	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			DISCRETIONARY	MTH		-			
	MOC :									
SB 560-21-30 R01	AIR CONDITIONING - CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT			OPTIONAL			-			
	MOC :									
SB 560-21-30 <i>21SB-30</i>	CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT				MTH		-			
	MOC :									
SB 560-21-34	AIR CONDITIONING FAN MOTOR WIRING MODIFICATION	MCO		OPTIONAL	MTH 14-Jun-2016 HRS 8082.3 LDG 7380		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB560-21-34 BY PERFORMING WIRING MODIFICATION TO FORWARD VAP ASSY AS REQUIRED WHEN REPLACING WITH BRUSHLESS MOTOR PER THE BULLETIN INSTRUCTIONS. OPERATIONAL CHECK GOOD.									
SB 560-21-35	TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL	MTH		A/R			
	MOC :									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION	MCO		MANDATORY	MTH 29-Jul-2015 HRS 7886.9 LDG 7175		-			N/A
	MOC : NOT APPLICABLE - CIL-21-02R1 IS NOT APPLICABLE, AS THE ORIGINAL ISSUE OF THIS SERVICE LETTER WAS NOT ACCOMPLISHED									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION (SUPERSEDED BY CIL-21-02 R01) OPTIONAL									
MOC :										
SL 560-21-06 R01 21SL-06 : 560R1	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR (SUPERSEDED BY SL560-21-06 R02) BHM RECOMMENDED MTH 10-Apr-1996 A/R HRS 1180									
MOC : COMPLIED WITH										
SL 560-21-06 R02 21SL-06 : 560R2	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR (SUPERSEDED BY SL560-21-06 R03) MCO RECOMMENDED MTH 10-Jun-1996 A/R HRS 1233									
MOC : COMPLIED WITH										
SL 560-21-06 R03 21SL-06 : 560R3	VENTILATION BOX ASSEMBLY FORWARD FLANGE INSPECTION/REPAIR MCO RECOMMENDED MTH 15-Jun-1999 HRS 2425									
MOC : COMPLIED WITH										
SL 560-21-09 21SL-09	EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES RECOMMENDED MTH									
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-21-10 21SL-10	OUTFLOW VALVE STATIC PRESSURE LINE INSPECTION/REPLACEMENT XA RECOMMENDED MTH 18-Mar-2002 HRS 4097									
MOC : COMPLIED WITH										
SL 560-21-11 R01 21SL-11 : 560R1	RAM AIR INLET DRAIN LINE INSPECTION RECOMMENDED MTH									
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-21-16 21SL-16	AIR CONDITIONING - AIR CONDITIONING EXHAUST DOOR SHAFT SPACER INSPECTION DISCRETIONARY MTH									
MOC :										
SB 560-23-14 23SB-14	FLITEPHONE VI ANTENNA CABLE REPLACEMENT (SUPERSEDED BY 560-23-14 R01) MCO RECOMMENDED MTH									
NOT APPLICABLE										
MOC :										
SB 560-23-16 23SB-16	STATIC WICK REPLACEMENT BHM OPTIONAL MTH									
MOC : - OPERATOR WILL NOT ACCOMPLISH REMOVED FROM CESCOM REPORTS										
SB 560-23-25 R01 23SB-25 : 560R1	HONEYWELL 8.33 KHZ COMMUNICATION RADIO INSTALLATION OPTIONAL MTH									
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-23-26 R01 23SB-26 : 560R1	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION OPTIONAL MTH									
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-23-30 23SB-30	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT (SUPERSEDED BY 560-23-30 R01)	PDK		MANDATORY	MTH 01-Oct-1999 HRS 2583		A/R			Complete
MOC : COMPLIED WITH										
SB 560-23-32 R01 23SB-32 : 560R1	RNZ-850 NAVIGATION RADIO UPGRADE	PDK		MANDATORY	MTH 26-Jan-2007 HRS 6719		-			N/A
MOC : NOT APPLICABLE										
SB 560-23-38 R02	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION OPTIONAL						-			
MOC :										
SB 560-23-38	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560-23-38 R01) OPTIONAL				MTH		A/R			
MOC :										
SL 560-23-15 23SL-15	TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT	PDK		RECOMMENDED	MTH 19-Apr-2000 HRS 2879		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-23-16 R01 23SL-16 : 560R1	AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-24-10 R01 24SB-10 : 560R1	NOSE AVIONICS GROUND BLOCK MODIFICATION	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-24-12 R03 24SB-12 : 560R3	AVIONICS POWER RELAYS REPLACEMENT			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-24-14 24SB-14	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	MCO		RECOMMENDED	MTH		-			
NOT APPLICABLE										
MOC :										
SB 560-24-16 24SB-16	TRIM PC BOARD MODIFICATION AND ELEVATOR ELECTRIC TRIM MOTOR MODIFICATION (SUPERSEDED BY 560-24-16 R01)	MCO		SUPERSEDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-24-19 R01 24SB-19 : 560R1	OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-24-20 24SB-20	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-24-22 24SB-22	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT (SUPERSEDED BY 560-24-22 R01)			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-24-27 R01 24SB-27 : 560R1	WING WIRE ROUTING IMPROVEMENT/FLAP			HYDRAULIC LINE INSPECTION RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-24-29 24SB-29	NO SMOKING LIGHT WIRING MODIFICATION			OPTIONAL	MTH		-			
MOC :										
SB 560-24-30 24SB-30	CIRCUIT BREAKER INSULATORS INSTALLATION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-24-37 R01 24SB-37 : 560R1	MAIN POWER WIRE ANCHOR IMPROVEMENT (SUPERSEDED BY 560-24-37 R02)	UH		RECOMMENDED	MTH 11-Sep-2002 HRS 4401		-			Complete
MOC : COMPLIED WITH										
SB 560-24-39 24SB-39	SEALED LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-24-42 24SB-42	RELAY SHIELD INSTALLATION			MANDATORY	MTH 15-Apr-2004 HRS 5212		-			Complete
MOC : COMPLIED WITH										
SB 560-24-45	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
MOC :										
SL 560-24-07 24SL-07	HARTMAN BATTERY DISCONNECT RELAY PART NUMBER A876K INSPECTION/REPLACE	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-25-08 25SB-08	AFT JUMP SEAT INSTALLATION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-25-16 R01 25SB-16 : 560R1	WINDOW TRIM INSULATION IMPROVEMENTS	MCO		RECOMMENDED	MTH 30-Apr-1997 HRS 1569		-			Complete
MOC : COMPLIED WITH										
SB 560-25-16 25SB-16	WINDOW TRIM INSULATION IMPROVEMENTS (SUPERSEDED BY 560-25-16 R01)	BHM		RECOMMENDED	MTH 12-Feb-1996 HRS 1080		A/R			Complete
MOC : COMPLIED WITH										
SB 560-25-19 25SB-19	TSO C91A EMERGENCY LOCATOR TRANSMITTER INSTALLATION (CANCELLED)			CANCELLED	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-25-21 25SB-21	OVERHEAD CONSOLE RETAINER MODIFICATION	MCO		RECOMMENDED	MTH 15-Jun-1999 HRS 2425		-			Complete
MOC : COMPLIED WITH										
SB 560-25-23 25SB-23	FLIGHT CREW SEAT PAN REINFORCEMENT			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-25-25 25SB-25	ESCAPE HATCH SIDEWALL PANEL INSTALL	MCO		RECOMMENDED	MTH 15-Jun-1999 HRS 2425		-			Complete
MOC : COMPLIED WITH										
SB 560-25-26 R01 25SB-26 : 560R1	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560-25-26 R02)			OPTIONAL			A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 560-25-26 R03	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										
SB 560-25-29 R01 25SB-29 : 560R1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-25-32 R01 25SB-32 : 560R1	EQUIPMENT/FURNISHINGS - TOILET TRAY AND PAD INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SL 560-25-03 25SL-03	LIFE PRESERVERS AND INDIVIDUAL FLotation DEVICES REPLACEMENT			MANDATORY	MTH 01-Oct-1997 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SL 560-25-04 25SL-04	GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-25-09 25SL-09	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	MCO		MANDATORY	MTH 17-Jun-2008 HRS 6904		A/R			Complete
MOC : COMPLIED WITH										
SB 560-26-01 26SB-01	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION			MANDATORY	DAYS 24-May-2005 HRS 6015		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-26-01 26ASL-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	MCO		MANDATORY	MTH 17-Jun-2008 HRS 6904		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KPDK		MANDATORY	MTH 24-Jul-2020 HRS 8776.3 LDG 8060		-			N/A
MOC : NOT APPLICABLE - SERVICE LETTER DOES NOT APPLY BY MANUFACTURE, WALTER KIDDE CARTRIDGES INSTALLED.										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)			MANDATORY	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-27-07 R02 27SB-07 : 560R2	ELEVATOR SERVO CABLE INSTALLATION MODIFICATION (SUPERSEDED BY 560-27-07 R03)	*CF		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-27-09 27SB-09	IMPROVED ELEVATOR TRIM SECTOR INSTALLATION (SUPERSEDED BY 560-27-09 R01)	BHM		SUPERSEDED	MTH 12-Feb-1996 HRS 1080		A/R			Complete
MOC : COMPLIED WITH										
SB 560-27-10 27SB-10	ELEVATOR TRIM SECTOR ADJUSTABLE FRICTION BLOCK INSTALLATION	MCO		RECOMMENDED	MTH 03-Nov-1997 HRS 1700		-			Complete
MOC : COMPLIED WITH										
SB 560-27-11 27SB-11	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION	MCO		RECOMMENDED	MTH 21-Jul-1998 HRS 1924		-			Complete
MOC : COMPLIED WITH										
SB 560-27-13 27SB-13	TRIM TAB ACTUATOR GREASE FITTING INSTALLATION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-27-18 27SB-18	TRIM PCB REPLACEMENT			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-27-22 27SB-22	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-27-23	FLIGHT CONTROLS - ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION AND REPAIR			MANDATORY	MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS -0539 THRU -0815.										
SL 560-27-03 27SL-03	FLAP HYDRAULIC HOSE FITTING CLOCKING INSPECTION/ADJUSTMENT	MCO		RECOMMENDED	MTH 24-Nov-1993 HRS 310		-			Complete
MOC : COMPLIED WITH										
SL 560-27-05 27SL-05	AILERON/RUDDER INTERCONNECT RIGGING INSPECTION	MCO		RECOMMENDED	MTH 30-Apr-1997 HRS 1569		A/R			Complete
MOC : COMPLIED WITH										
SL 560-27-06 27SL-06	RUDDER/AILERON INTERCONNECT BOLT INSPECTION (SUPERSEDED BY SL560-27-06 R01)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SL 560-27-08 27SL-08	LOWER CABLE GUARD INSPECTION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-28-04 28SB-04	FUEL SYS PLUMBING CLAMP ADDITIONS	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-28-05 28SB-05	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY	BHM		OPTIONAL	MTH 16-Nov-1995 HRS 1008		-			Complete
MOC : COMPLIED WITH										
SB 560-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-28-10 28SB-10	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	S3		MANDATORY	MTH 16-Dec-2004 HRS 5597		-			Complete
MOC : COMPLIED WITH										
SB 560-28-14 R01	FUEL - FUEL CHECK VALVE MODIFICATION			RECOMMENDED			-			
MOC :										
SB 560-28-14 28SB-14	FUEL - FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY 560-28-14 R01)	MCO		RECOMMENDED	MTH 06-Jan-2011 HRS 7249.8 LDG 6606		A/R			
MOC : DEFERRED - CUSTOMER ELECTS TO NOT ACCOMPLISH THIS SERVICE BULLETIN AT THIS TIME.										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
MOC :										
SLA 560-28-03 28SLA03	TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS (SUPERSEDED BY SLA560-28-03 R01)	BHM		SUPERSEDED	MTH 24-Jun-1996 HRS 1250		A/R			Complete
MOC : COMPLIED WITH										
SB 560-29-02 29SB-02	IMPROVED HYDRAULIC PUMP PRESSURE HOSE INSTALLATION	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-29-04 R01 29SB-04 : 560R1	HYDRAULIC TUBE REPLACEMENT			MANDATORY	MTH 10-Jun-2003		-			Complete
MOC : COMPLIED WITH										
SB 560-29-04 29SB-04	HYDRAULIC TUBE REPLACEMENT (SUPPLEMENTAL DATA REVISION) (SUPERSEDED BY 560-29-04 R01)	RYY		SUPERSEDED	MTH 10-Jun-2003 HRS 4773		A/R			Complete
MOC : COMPLIED WITH										
SB 560-29-08 R01	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT	MCO		RECOMMENDED	MTH 04-Sep-2012 HRS 7410.4 LDG 6757		A/R			N/A
MOC : NOT APPLICABLE - SERVICE BULLETIN IS N/A DUE TO NO HF SYSTEM INSTALLED IN AIRCRAFT. PLEASE CLEAR CESCOM.										
SB 560-29-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT (SUPERSEDED BY 560-29-08 R01)			RECOMMENDED			A/R			
MOC :										
SL 560-29-04 R01 29SL-04 : 560R1	HYDRAULIC LINE INSTALLATION INSPECTION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-30-10 30SB-10	WINDSHIELD ANTI-ICE BLEED AIR SWITCH INSPECTION/REPLACEMENT	RYY		MANDATORY	MTH 04-Feb-2002 HRS 3990		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 560-30-15 30SB-15	ICE AND RAIN PROTECTION - ENGINE INLET ANTI-ICE VALVE SUPPORT BRACKET INSTALLATION	MCO		RECOMMENDED	MTH 06-Jan-2011 HRS 7249.8 LDG 6606		A/R			
MOC : DEFERRED - CUSTOMER ELECTS TO NOT ACCOMPLISH THIS SERVICE BULLETIN AT THIS TIME.										
SL CIL-30-01 R01	APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 560-30-05 R01 30SL-05 : 560R1	ENGINE ANTI-ICE VALVE INSPECTION			RECOMMENDED	MTH 04-Apr-1995 HRS 808		A/R			Complete
MOC : COMPLIED WITH										
SL 560-30-05 30SL-05	ENGINE ANTI-ICE VALVE INSPECTION (SUPERSEDED BY SL560-30-05 R01)	BHM		SUPERSEDED	MTH 12-Jul-1995 HRS 880		A/R			Complete
MOC : COMPLIED WITH										
SB 560-31-06 31SB-06	FLIGHT DATA RECORDER COVER INSTALLATION (SUPERSEDED BY 560-31-06 R01)	MCO		SUPERSEDED	MTH		A/R			
NOT APPLICABLE										
MOC :										
SB 560-31-09 31SB-09	INADVERTENT POWER BRAKE LOW PRESSURE ANNUNCIATION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-31-15 31SB-15	INDICATING/RECORDING SYSTEMS - INSTRUMENT PANEL MODIFICATION FOR AOA TEST SWITCH			OPTIONAL	MTH		A/R			
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SB 560-32-03 R05 32SB-03 : 560R5	GRAVEL RUNWAY PROTECTION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-32-15 32SB-15	ANTI-SKID DRIVE CLIP REPLACEMENT	BHM		RECOMMENDED	MTH 12-Jan-1998 HRS 1768		-			Complete
MOC : COMPLIED WITH										
SB 560-32-16 32SB-16	TRANSMITTAL OF BFGOODRICH SB195-183-32-1, MAIN BRAKE SHUTTLE VALVE IMPROVEMENTS	BHM		RECOMMENDED	MTH 12-Jan-1998 HRS 1768		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-32-17 32SB-17	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT (SUPERSEDED BY 560-32-17 R01)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SB 560-32-18 32SB-18	ANTI-SKID SYSTEM DIODE REMOVAL			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-32-19 32SB-19	BRAKE MOTOR COUPLING REPLACEMENT	MCO		RECOMMENDED	MTH 15-Jun-1999 HRS 2425		-			Complete
MOC : COMPLIED WITH										
SB 560-32-20 R01 32SB-20 : 560R1	BRAKE LINE REPLACEMENT			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-32-22 R03 32SB-22 : 560R3	LANDING GEAR ON GROUND OPERATION AND MODIFICATION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-32-31 R01 32SB-31 : 560R1	PARKING BRAKE CABLE REPLACEMENT			OPTIONAL	MTH		A/R			
MOC :										
SB 560-32-39 32SB-39	LANDING GEAR - NLG ACTUATOR REPLACEMENT	MCO		MANDATORY	MTH 04-Sep-2009 HRS 7042		A/R			Complete
MOC : COMPLIED WITH										
SB 560-32-42 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS			RECOMMENDED			-			
MOC : DEFERRED										
SB 560-32-42	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY 560-32-42 R01)			RECOMMENDED			-			
MOC :										
SB 560-32-43	LANDING GEAR - LANDING GEAR WARNING HORN REPLACEMENT			OPTIONAL			-			
MOC :										
SL CIL-32-01	IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	MCO		RECOMMENDED	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CIL-32-03 BY INSPECTING THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET FOR CORRECT INSTALLATION PER THE SERVICE LETTER INSTRUCTIONS. FOUND TO BE INSTALLED CORRECTLY.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560-32-25 R01 32SL-25 : 560R1	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/REPLACEMENT (SUPERSEDED BY SL560-32-25 R02)	*CF		SUPERSEDED	MTH 16-Jun-1993		A/R			Complete
MOC : COMPLIED WITH										
SL 560-32-29 32SL-29	NOSE LANDING GEAR WHEEL WELL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION/REPLACEMENT	BHM		RECOMMENDED	MTH 12-Jul-1995 HRS 880		-			Complete
MOC : COMPLIED WITH										
SL 560-32-31 R01 32SL-31 : 560R1	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		A/R			Complete
MOC : COMPLIED WITH										
SL 560-32-34 32SL-34	NOSE GEAR STEERING BUNGEE INSPECTION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-32-40 R01 32SL-40 : 560R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SL 560-32-41 32SL-41	GOODRICH NOSE WHEEL INSPECTION/REPLACEMENT			MANDATORY	MTH 18-May-2006 HRS 6581		A/R			Complete
MOC : COMPLIED WITH										
SL 560-32-50 32SL-50	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	MCO		MANDATORY	MTH 04-Sep-2009 HRS 7042		A/R			Complete
MOC : COMPLIED WITH										
SL 560-32-51	LANDING GEAR - UNAPPROVED NOSE LANDING GEAR TIRE INSPECTION			RECOMMENDED			A/R			
MOC :										
SB 560-33-04 R01 33SB-04 : 560R1	LANDING LIGHT BULB PROTECTION	BHM		OPTIONAL	MTH		-			
MOC : - OPERATOR WILL NOT ACCOMPLISH REMOVED FROM CESCOM REPORTS										
SB 560-33-08 R01 33SB-08 : 560R1	WINGTIP NAV/COLLISION LIGHT MODIFICATION	*CF		OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-33-09 33SB-09	WING TIP LANDING LIGHT INSTALLATION (SUPERSEDED BY 560-33-09 R01)	BHM		SUPERSEDED	MTH		A/R			
MOC : - OPERATOR WILL NOT ACCOMPLISH REMOVED FROM CESCOM REPORTS										
SB 560-33-14 33SB-14	TAIL NAVIGATION LIGHT SOCKET MODIFICATION (SUPERSEDED BY 560-33-14 R01)	BHM		SUPERSEDED	MTH 12-Feb-1996 HRS 1080		A/R			Complete
MOC : COMPLIED WITH										
SB 560-33-16 R03 33SB-16 : 560R3	EMERGENCY LIGHTING BATTERY PACK UPGRADE (SUPERSEDED BY 560-33-16 R04)			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-33-16 R04 <i>33SB-22</i>	EMERGENCY LIGHTING BATTERY PACK UPGRADE OPTIONAL MOC :						-			
SB 560-33-22 <i>33SB-22</i>	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION OPTIONAL MOC :			MTH			A/R			
SB 560-33-31 <i>33SB-31</i>	LED TAIL FLOODLIGHT UPGRADE OPTIONAL MOC :			MTH			A/R			
SB 560-33-32	LED REPLACEMENT LIGHT FOR THE BAGGAGE COMPARTMENT OPTIONAL MOC :						A/R			
SB 560-33-33 R01	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY OPTIONAL MOC :						-			
SB 560-33-35	LED LANDING GEAR INDICATION LIGHT INSTALLATION OPTIONAL MOC :						A/R			
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY INFORMATIONAL MOC :						-			
SB 560-34-109 <i>34SB-109</i>	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION OPTIONAL MOC :			MTH			-			
SB 560-34-112 R03 <i>34SB-112 : 560R3</i>	MARK VIII ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) INSTALLATION OPTIONAL MOC :			MTH			-			
SB 560-34-113 R01 <i>34SB-113 : 560R1</i>	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE OPTIONAL MOC :			MTH			A/R			
SB 560-34-116 <i>34SB-116</i>	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER FOR ELEMENTARY SURVEILLANCE (SUPERSEDED BY 560-34-116 R01) SUPERSEDED MOC :			MTH			A/R			
SB 560-34-121 <i>34SB-121</i>	SANDEL ST3400 TAWS INSTALLATION OPTIONAL MOC :			MTH			-			
SB 560-34-143 R01 <i>34SB-143 : 560R1</i>	NAVIGATION - SPEED LIMITATION PLACARD INSTALLATION MCO MANDATORY MOC : COMPLIED WITH			MTH	04-Sep-2009 HRS 7042		A/R			Complete
SB 560-34-143 <i>34SB-143</i>	NAVIGATION - SPEED LIMITATION PLACARD INSTALLATION (SUPERSEDED BY 560-34-143 R01) SUPERSEDED MOC : COMPLIED WITH			MTH	18-Dec-2007 HRS 6832		A/R			Complete
SB 560-34-156 R01	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE OPTIONAL MOC :						-			
SB 560-34-156	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE MOC :						-			



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-34-162	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SB 560-34-168	NAVIGATION - STALL WARNING HORN REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 560-34-22 34SB-22	NAVIGATION - 12,200 POUND (5533 KILOGRAM) ZERO FUEL WEIGHT (SUPERSEDED BY 560-34-22 R01)	RYY		SUPERSEDED	MTH 09-Jul-2000 HRS 2971		A/R			Complete
	MOC :	COMPLIED WITH								
SB 560-34-36 34SB-36	HONEYWELL PRIMUS RADIO RACK COAX CONNECTOR REPLACEMENT (SUPERSEDED BY 560-34-36 R01)	MCO		SUPERSEDED	MTH		A/R			
	NOT APPLICABLE									
	MOC :									
SB 560-34-37 34SB-37	HONEYWELL PRIMUS RADIO ADF SYSTEM IMPROVEMENTS	MCO		RECOMMENDED	MTH		-			
	NOT APPLICABLE									
	MOC :									
SB 560-34-39 R01 34SB-39 : 560R1	P650 RADAR RECEIVER/TRANSMITTER REPLACEMENT (FOR REDUCED COMM RADIO INTERFERENCE)	*CF		OPTIONAL	MTH		-			
	MOC :	- OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME								
SB 560-34-50 34SB-50	INTERMITTENT RUDDER KICK CORRECTION MODIFICATION (SUPERSEDED BY 560-34-50 R01)	BHM		SUPERSEDED	MTH 12-Feb-1996 HRS 1080		A/R			Complete
	MOC :	COMPLIED WITH								
SB 560-34-54 34SB-54	AIRSPED INDICATOR WITH OVERSPEED/LOW SPEED WARNING SWITCHES INSTALLATION			OPTIONAL	MTH		-			
	MOC :	- OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME								
SB 560-34-59 34SB-59	COPILOT ALTIMETER INSTALLATION - KOLLSMAN			OPTIONAL	MTH		-			
	MOC :	- OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME								
SB 560-34-60 34SB-60	PRIMUS 870 RADAR GERMAN CERTIFICATIOON UPGRADE			OPTIONAL	MTH		-			
	MOC :	- OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME								
SB 560-34-69 34SB-69	SAFE FLIGHT ANGLE-OF-ATTACK COMPUTER MODIFICATION (SUPERSEDED BY 560-34-69 R01)	MCO		SUPERSEDED	MTH 21-Jul-1998 HRS 1924		A/R			Complete
	MOC :	COMPLIED WITH								
SB 560-34-75 R01 34SB-75 : 560R1	STATIC PORT INSPECTION/MODIFICATION			OPTIONAL	MTH		-			
	MOC :									
SB 560-34-89 34SB-89	UNS-1K 603.4 SOFTWARE UPGRADE			RECOMMENDED	MTH		-			
	OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-34-97 R01 34SB-97 : 560R1	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MODIFICATION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
ASL 560-34-21 34ASL21	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	PDK		MANDATORY	MTH 26-Jan-2007 HRS 6719		A/R			N/A
MOC : NOT APPLICABLE										
ASL 560-34-34 R02 34ASL-34 : 560R2	NAVIGATION - STALL WARNING SYSTEM CALIBRATION, ADJUSTMENT, AND IN-FLIGHT TEST PROCEDURES (SUPERSEDED BY ASL560-34-34 R03)			SUPERSEDED	MTH 25-Mar-2008 HRS 6866		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-34-35 R04 34ASL-35 : 560R4	NAVIGATION - STALL WARNING SYSTEM CALIBRATION, ADJUSTMENT, AND IN-FLIGHT TEST PROCEDURES	MCO		MANDATORY	MTH 04-Sep-2009 HRS 7042		A/R			N/A
MOC : NOT APPLICABLE										
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	MCO		MANDATORY	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO AFFECTED EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT.										
SL 560-34-23 R01	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE			RECOMMENDED			-			
MOC :										
SL 560-34-23 34SL-23	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE (SUPERSEDED BY SL560-34-23 R01)			RECOMMENDED	MTH 17-Jun-2004 HRS 5350		-			Complete
MOC : COMPLIED WITH										
SL 560-34-28 34SL-28	HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8			DISCRETIONARY	MTH		-			
MOC :										
SL 560-34-36 34SL-36	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5	MCO		RECOMMENDED	MTH 04-Sep-2009 HRS 7042		A/R			N/A
MOC : NOT APPLICABLE										
SL 560-34-40	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION			INFORMATIONAL			-			
MOC :										
SL 560-34-42	NAVIGATION - IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES			MANDATORY	MTH		-			
MOC :										
SB 560-35-01 35SB-01	EROS OXYGEN MASK INSTALLATION (SUPERSEDED BY 560-35-01R01)			SUPERSEDED	MTH 25-Sep-2000 HRS 3113		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-35-04 35SB-04	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES	BHM		RECOMMENDED	MTH 12-Feb-1996 HRS 1080		-			Complete
MOC : COMPLIED WITH										
SB 560-35-09 R01 35SB-09 : 560R1	EROS MLD20-506 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-35-12 35SB-12	EROS MLD20-510 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KMCO		MANDATORY	MTH 02-Feb-2016 DAYS 8009.8 HRS 7308 LDG		-			N/A
MOC : NOT APPLICABLE - CREW MASKS P/N MC10-16-101, S/N 90296 AND P/N MC10-15-109, S/N 44695 ARE NOT APPLICABLE BY PART NUMBER. REFERENCE THE ZODIAC SB MCF-SBU-35-001.										
SL 560-35-04 35SL-04	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 560-35-07 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	MCO		MANDATORY	MTH 04-Sep-2012 HRS 7410.4 LDG 6757		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSPECTING CREW OXYGEN MASKS FOR SUSPECTED FAULTY HARNESSSES IAW THE SERVICE LETTER INSTRUCTIONS. FOUND MASKS OK FOR CONTINUED SERVICE. PILOT'S MASK P/N:MC10-16-101, S/N: 76938. COPILOT'S MASK P/N: MC10-15-109, S/N: 44695.										
SL 560-35-07 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 560-35-07	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560-35-07 R01)			MANDATORY			-			
MOC :										
SB 560-36-01 36SB-01	TAILCONE BLEED AIR CHECK VALVE REPLACEMENT	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-36-02 R01 36SB-02 : 560R1	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-36-03 R03 36SB-03 : 560R3	PNEUMATIC - WIDE CARGO DOOR SEAL LINE WATER TRAP INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560-52-02 52SB-02	ENTRY DOOR STEP CATCH COVER (W/STD DOOR & STEP INSTL)	BHM		RECOMMENDED	MTH 06-Jun-1994 HRS 512		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-52-04 R01 52SB-04 : 560R1	WIDE DOOR MODIFICATION INSTALLATION (SUPERSEDED BY 560-52-04 R02)			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-52-04 R02	WIDE DOOR MODIFICATION INSTALLATION			OPTIONAL			-			
MOC :										
SB 560-52-08 R04	COMPOSITE DOOR STEP INSTALLATION			OPTIONAL			-			
MOC :										
SB 560-52-12 R02 52SB-12 : 560R2	DOORS - RAIN GUTTER FASTENER INSPECTION/REPLACEMENT	XA		RECOMMENDED	MTH 26-Aug-2002 HRS 4395		A/R			Complete
MOC : COMPLIED WITH										
SB 560-52-18 52SB-18	INSTALLATION OF NOSE LANDING GEAR DOOR DEFLECTORS			OPTIONAL	MTH		-			
MOC :										
ASL 560-52-05	DOORS - EMERGENCY EXIT INSPECTION	MCO		MANDATORY	DAYS 01-Jul-2011 HRS 7310.8 LDG 6662		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH INSPECTION IN ACCORDANCE WITH SERVICE LETTER INSTRUCTIONS. NO DEFECTS NOTED.										
SB 560-53-07 R03 53SB-07 : 560R3	TAILCONE BALLAST INSTALLATION			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-53-16 53SB-16	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT	BHM		RECOMMENDED	MTH 12-Feb-1996 HRS 1080		-			Complete
MOC : COMPLIED WITH										
SB 560-53-18 53SB-18	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-53-20 53SB-20	AN3-5A BOLT INSPECTION/REPLACEMENT	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		A/R			Complete
MOC : COMPLIED WITH										
SB 560-53-21 R01 53SB-21 : 560R1	COCKPIT LEFT SIDE WINDOW RIVET INSPECTION (SUPERSEDED BY 560-53-21 R02)	MCO		SUPERSEDED	MTH 21-Jul-1998 HRS 1924		A/R			Complete
MOC : COMPLIED WITH										
SB 560-53-21 53SB-21	COCKPIT LEFT SIDE WINDOW RIVET INSPECTION (SUPERSEDED BY 560-53-21 R01)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-53-23 R01 53SB-23 : 560R1	WING MAIN SPAR CARRY THRU LUGS INSPECTION/REPAIR	MCO		RECOMMENDED	MTH 21-Jul-1998 HRS 1924		-			Complete
MOC : COMPLIED WITH										
SB 560-53-25 R01 53SB-25 : 560R1	TAILCONE BAGGAGE COMPARTMENT SUPPORT IMPROVEMENT			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-53-26 R02 53SB-26 : 560R2	LOWER STUB WING SKIN INSPECTION/REPAIR	MCO		RECOMMENDED	MTH 06-Jan-2011 HRS 7249.8 LDG 6606		-			
MOC : DEFERRED - CUSTOMER ELECTS TO NOT ACCOMPLISH THIS SERVICE BULLETIN AT THIS TIME.										
SB 560-53-26 53SB-26	LOWER STUB WING SKIN INSPECTION/REPAIR (SUPERSEDED BY 560-53-26 R01)	MCO		SUPERSEDED	MTH 15-Jun-1999 HRS 2425		A/R			Complete
MOC : COMPLIED WITH										
SB 560-53-27 53SB-27	CABIN ENTRANCE AFT DOORPOST INSPECTION/REPAIR	MCO		RECOMMENDED	MTH 15-Jun-1999 HRS 2425		-			Complete
MOC : COMPLIED WITH										
SB 560-53-28 53SB-28	FUSELAGE MOISTURE DRAIN INSTALLATION			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 560-53-29 R02 53SB-29 : 560R2	NOSE WHEEL STEERING BRACKET REPLACEMENT			MANDATORY	MTH 06-Sep-2001 HRS 3667		-			Complete
MOC : COMPLIED WITH										
SB 560-53-29 53SB-29	NOSE WHEEL STEERING BRACKET REPLACEMENT (SUPERSEDED BY 560-53-29 R01)	UVA		SUPERSEDED	MTH 23-Aug-2001 HRS 3657		A/R			Complete
MOC : COMPLIED WITH										
SB 560-53-34 53SB-34	WHEEL WELL BOX/SKIN GAP IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SL 560-53-05 53SL-05	DORSAL FIN VANE INSPECTION			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 560-53-06 R01 53SL-06 : 560R1	INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 560-54-01 54SB-01	NEW DESIGN INLET INSTALLATION (SUPERSEDED BY 560-54-01 R01)	MCO		SUPERSEDED	MTH 15-Jun-1999 HRS 2425		A/R			Complete
MOC : COMPLIED WITH										
SB 560-54-03 R02 54SB-03 : 560R2	ENGINE INLET DOUBLER INSTALLATION	ICT		RECOMMENDED	MTH 08-Feb-2000 HRS 2783		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-55-04 55SB-04	STABILIZERS - ELEVATOR TIP BONDING STRIP INSTALLATION			DISCRETIONARY	MTH		A/R			
MOC :										
SL 560-55-02 55SL-02	HORIZONTAL STABILIZER ATTACH BOLT/NUT TORQUE VERIFICATION	MCO		RECOMMENDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SL 560-55-03 R01	STABILIZERS - HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R02)	KMCO		MANDATORY	MTH 22-Jun-2015 HRS 7865.6 LDG 7145		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560-55-03 R1 BY INSPECTION ONLY. OK FOR CONTINUED SERVICE.										
SL 560-55-03 R02	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION			MANDATORY	MTH		-			
MOC :										
SL 560-55-03	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R01)			MANDATORY	MTH		-			
MOC :										
SB 560-57-07 57SB-07	FLAP VENT HOLES INSTALL	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SL 560-57-01 57SL-01	NOTIFICATION OF LEADING EDGE SKIN REWORK REQUIREMENT WHEN A DEICE BOOT IS REMOVED (SUPERSEDED BY SL560-57-01 R01)	UVA		SUPERSEDED	MTH 30-Aug-2001 HRS 3657		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-30-07 30SLA07	APPROACH AND LANDING IN ICING CONDITIONS ADDITION TO FLIGHT MANUAL (SUPERSEDED BY ASL560-30-07 R01)	BHM		SUPERSEDED	MTH 14-Feb-1997 HRS 1500		A/R			Complete
MOC : COMPLIED WITH										
SB 560-71-03 71SB-03	LOWER COWL DOOR FIRESEAL INSPECTION/INSTALLATION (SUPERSEDED BY 560-71-03 R01)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SB 560-72-01 R01 72SB-01 : 560R1	ENGINE COWLING MODIFICATION TO ACCOMODATE PRATT & WHITNEY CANADA ENGINE FUEL ACCUMULATOR INSTALLATION (SUPERSEDED BY 560-72-01 R02)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SB 560-72-01 R02 72SB-01 : 560R2	ENGINE COWLING MODIFICATION TO ACCOMODATE PRATT & WHITNEY CANADA ENGINE FUEL ACCUMULATOR INSTALLATION (SUPERSEDED BY 560-72-01 R03)	MCO		SUPERSEDED	MTH 03-Nov-1997 HRS 1700		A/R			Complete
MOC : COMPLIED WITH										
SB 560-72-01 R03 72SB-01 : 560R3	ENGINE COWLING MODIFICATION TO ACCOMODATE PRATT & WHITNEY CANADA ENGINE FUEL ACCUMULATOR INSTALLATION	MCO		RECOMMENDED	MTH 21-Jul-1998 HRS 1924		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560-72-01 72SB-01	ENGINE COWLING MODIFICATION TO ACCOMMODATE PRATT & WHITNEY CANADA ENGINE FUEL ACCUMULATOR INSTALLATION (SUPERSEDED BY 560-72-01 R01)	MCO		SUPERSEDED	MTH 30-Apr-1997 HRS 1569		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-05 R01 72SL-05 : 560R1	TRANSMITTAL OF P&WC SB JT15D-72-7458, REVISION 3, INSPECTION OF FCU - MINIMUM FUEL FLOW, AND SERVICE LETTER 7077 JT15D-012, FCU METERING VALVE (SB7458) CLARIFICATION (SUPERSEDED BY SL560-72-05 R02)	MCO		SUPERSEDED	MTH 10-Jun-1996 HRS 1233		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-16 72SL-16	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023			MTH RECOMMENDED			A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R26)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R26)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R27)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R27)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
MOC :										
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY JT15D-72-7002 R43)			CATEGORY 3			A/R			
MOC :										
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY JT15D-72-7002 R43)			CATEGORY 3			A/R			
MOC :										
SB JT15D-72-7002 R43 E1	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
MOC :										
SB JT15D-72-7002 R43 E2	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
MOC :										
SB JT15D-72-7002 R44 E1	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7002 R44 E2	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R45 E1	ROTOR COMPONENTS - SERVICE LIVES			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R45 E2	ROTOR COMPONENTS - SERVICE LIVES			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R39)						-			
	MOC :									
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R39)						-			
	MOC :									
SB JT15D-72-7003 R39 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R40)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7003 R39 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R40)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			-			
MOC :										
SB JT15D-72-7003 R41 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
MOC :										
SB JT15D-72-7003 R41 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
MOC :										
SB JT15D-72-7003 R42 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
MOC :										
SB JT15D-72-7003 R42 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
MOC :										
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
MOC :										
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
MOC :										
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
MOC :										
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
MOC :										
SB JT15D-72-7288 R04 E1	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7288 R04 E2	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7292 R01 E1	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
MOC :										
SB JT15D-72-7292 R01 E2	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
MOC :										
SB JT15D-72-7315 R01 E1	TURBINE SHAFT LOCKING BOLT - REPLACEMENT/MODIFICATION OF			CATEGORY 5			A/R			
MOC :										
SB JT15D-72-7315 R01 E2	TURBINE SHAFT LOCKING BOLT - REPLACEMENT/MODIFICATION OF			CATEGORY 5			A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7368	REPLACEMENT/MODIFICATION OF FAN BLADES						-			
R03				CATEGORY 8						
E1										
	MOC :									
SB JT15D-72-7368	REPLACEMENT/MODIFICATION OF FAN BLADES						-			
R03				CATEGORY 8						
E2										
	MOC :									
SB JT15D-72-7369	LOW COMPRESSOR STATOR/CASE ASSEMBLY - IMPROVED RETENTION									
R02				CATEGORY 6			A/R			
E1										
	MOC :									
SB JT15D-72-7369	LOW COMPRESSOR STATOR/CASE ASSEMBLY - IMPROVED RETENTION									
R02				CATEGORY 6			A/R			
E2										
	MOC :									
SB JT15D-72-7459	REPLACEMENT OF IGNITER (SUPERSEDED BY JT15D-72-7459 R02)									
R01				CATEGORY 8			A/R			
E1										
	MOC :									
SB JT15D-72-7459	REPLACEMENT OF IGNITER (SUPERSEDED BY JT15D-72-7459 R02)									
R01				CATEGORY 8			A/R			
E2										
	MOC :									
SB JT15D-72-7493	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R05)									
R04				CATEGORY 8			-			
E1										
	MOC :									
SB JT15D-72-7493	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R05)									
R04				CATEGORY 8			-			
E2										
	MOC :									
SB JT15D-72-7493	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R06)									
R05				CATEGORY 8			-			
E1										
	MOC :									
SB JT15D-72-7493	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R06)									
R05				CATEGORY 8			-			
E2										
	MOC :									
SB JT15D-72-7493	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R04)									
R06				CATEGORY 8			-			
E1										
	MOC :									
SB JT15D-72-7493	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R04)									
R06				CATEGORY 8			-			
E2										
	MOC :									
SB JT15D-72-7526	MODIFICATION/REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R03)									
R02				CATEGORY 7			-			
E1										
	MOC :									
SB JT15D-72-7526	MODIFICATION/REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R03)									
R02				CATEGORY 7			-			
E2										
	MOC :									
SB JT15D-72-7526	MODIFICATION / REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R04)									
R03				CATEGORY 7			-			
E1										
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7526 R03 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R04)									
				CATEGORY 7			-			
	MOC :									
SB JT15D-72-7526 R04 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLES						-			
				CATEGORY 7						
	MOC :									
SB JT15D-72-7526 R04 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLES						-			
				CATEGORY 7						
	MOC :									
SB JT15D-72-7565 R01 E1	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING						-			
				CATEGORY 5						
	MOC :									
SB JT15D-72-7565 R01 E2	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING						-			
				CATEGORY 5						
	MOC :									
SB JT15D-72-7571 R02 E1	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF						A/R			
				CATEGORY 9						
	MOC :									
SB JT15D-72-7571 R02 E2	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF						A/R			
				CATEGORY 9						
	MOC :									
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR						-			
				CATEGORY 8						
	MOC :									
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR						-			
				CATEGORY 8						
	MOC :									
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL						-			
				CATEGORY 6						
	MOC :									
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL						-			
				CATEGORY 6						
	MOC :									
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL						-			
				CATEGORY 6						
	MOC :									
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL						-			
				CATEGORY 6						
	MOC :									
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT						-			
				CATEGORY 7						
	MOC :									
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT						-			
				CATEGORY 7						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
MOC :										
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
MOC :										
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY JT15D-72-7625 R01)			CATEGORY 6			A/R			
MOC :										
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY JT15D-72-7625 R01)			CATEGORY 6			A/R			
MOC :										
SB JT15D-72-7627 E1	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7627 E2	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R01 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R02)			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R01 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R02)			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R02 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R03)			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R02 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R03)			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R03 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 R03 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB JT15D-72-7628 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R01)			CATEGORY 7			-			
MOC :										
SB JT15D-72-7628 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R01)			CATEGORY 7			-			
MOC :										
SB JT15D-72-7630 E1	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER	MCO		CATEGORY 3	MTH 03-Jul-2013 HRS 7541.5 LDG 6883		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSPECTION AND FOUND FUEL COOLED OIL COOLER FCOC NOT AFFECTED BY PART NUMBER AND SERIAL NUMBER NOT IN TABLE 1 OF THIS SERVICE BULLETIN. NO FURTHER ACTION REQUIRED										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7630 E2	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER	MCO	CATEGORY 3	MTH 03-Jul-2013 HRS 7544.3 LDG 6884		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSPECTION AND FOUND FUEL COOLED OIL COOLER FCOC NOT AFFECTED BY PART NUMBER AND SERIAL NUMBER NOT IN TABLE 1 OF THIS SERVICE BULLETIN. NO FURTHER ACTION REQUIRED										
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS		CATEGORY 3			-				
MOC :										
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS		CATEGORY 3			-				
MOC :										
SB JT15D-72-7636 R01 E1	REPLACEMENT OF CADMIUM PLATED BOLTS		CATEGORY 7			-				
MOC :										
SB JT15D-72-7636 R01 E2	REPLACEMENT OF CADMIUM PLATED BOLTS		CATEGORY 7			-				
MOC :										
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS		CATEGORY 7			-				
MOC :										
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS		CATEGORY 7			-				
MOC :										
SB JT15D-72-7639 R01 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)		CATEGORY 3			-				
MOC :										
SB JT15D-72-7639 R01 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)		CATEGORY 3			-				
MOC :										
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 3			-				
MOC :										
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 3			-				
MOC :										
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 7			-				
MOC :										
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 7			-				
MOC :										
SB JT15D-72-7639 R04 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 7			-				
MOC :										
SB JT15D-72-7639 R04 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY		CATEGORY 7			-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)									
				CATEGORY 4			-			
MOC :										
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)									
				CATEGORY 4			-			
MOC :										
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
MOC :										
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
MOC :										
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
MOC :										
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
MOC :										
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS (SUPERSEDED BY JT15D-72-7642 R01)									
				CATEGORY 9			-			
MOC :										
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS (SUPERSEDED BY JT15D-72-7642 R01)									
				CATEGORY 9			-			
MOC :										
SB JT15D-72-7643 E1	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB JT15D-72-7643 E2	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
SL 560-73-04 73SL-04	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE INFORMATION LETTER SIL 7067 FLOW DIVIDER VALVE									
	BHM		RECOMMENDED	MTH 12-Jul-1995 HRS 880			A/R			Complete
MOC : COMPLIED WITH										
SL 560-73-05 73SL-05	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN JT15D-72-7467 FLOW DIVIDER VALVE - REPLACEMENT/MODIFICATION OF									
	MCO		RECOMMENDED	MTH 30-Apr-1997 HRS 1569			A/R			Complete
MOC : COMPLIED WITH										
SL 560-73-06 73SL-06	ENGINE FUEL CONTROL - TRANSMITTAL OF SL JT15D-021 AND P&WC SB JT15D-72-7561, TURBOFAN ENGINE FUEL CONTROL UNIT (OVERSPEED VALVE) - FIELD INSPECTION AND CLEANING									
	MCO		RECOMMENDED	MTH 15-Jun-1999 HRS 2425			-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R02)	MCO		MANDATORY	DAYS 03-Jul-2013 HRS 7541.5 LDG 6863		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSPECTING THE IGNITION LEAD ELBOW AND CORRECT INSTALLATION AS NECESSARY IAW SERVICE LETTER'S INSTRUCTIONS. OPERATIONAL CHECK GOOD.										
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)	MCO		MANDATORY	DAYS 03-Jul-2013 HRS 7541.5 LDG 6863		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSPECTING THE IGNITION LEAD ELBOW AND CORRECT INSTALLATION AS NECESSARY IAW SERVICE LETTER'S INSTRUCTIONS. OPERATIONAL CHECK GOOD.										
SL 560-74-02 74SL-02	IGNITION - TRANSMITTAL OF P&WC SB 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF			RECOMMENDED	MTH		-			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8			A/R			
MOC :										
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8			A/R			
MOC :										
SB 560-76-01 76SB-01	ENGINE CONTROLS - ENGINE SYNCHRONIZER CONTROLLER MODIFICATION (SUPERSEDED BY 560-76-01 R01)	MCO		SUPERSEDED	MTH 15-Jun-1999 HRS 2425		A/R			Complete
MOC : COMPLIED WITH										
SB 560-78-03 78SB-03	UPPER THRUST REVERSER DOOR MODIFICATION	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										
SB 560-78-04 78SB-04	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SL 560-78-01 R02 78SL-01 : 560R2	THRUST REVERSER SYSTEM OPERATIONAL TEST	BHM		RECOMMENDED	MTH 12-Feb-1996 HRS 1080		A/R			Complete
MOC : COMPLIED WITH										
SL 560-78-04 R01 78SL-04 : 560R1	EXHAUST NOZZLE I. D. INSPECTION/REPLACEMENT	MCO		RECOMMENDED	MTH 10-Jun-1996 HRS 1233		A/R			Complete
MOC : COMPLIED WITH										
SL 560-78-06 78SL-06	TRANSMITTAL OF NORDAM CITV 78-2, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER (SUPERSEDED BY SL560-78-06 R01)	MCO		SUPERSEDED	MTH 10-Jun-1996 HRS 1233		A/R			Complete
MOC : COMPLIED WITH										
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
MOC :										
SB 560-80-03 R02 80SB-03 : 560R2	APC P/N 9912125-2 STARTER/GENERATOR INSPECTION/REPLACEMENT	MCO		RECOMMENDED	MTH 21-Jul-1998 HRS 1924		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
SB 560-80-04 80SB-04	REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB			OPTIONAL	MTH		-			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1996-24-06 30AD-01	ICING COND ADDITION TO FM (SUPERSEDED BY 2006-22-05)	BHM		SUPERSEDED	MTH 14-Feb-1997 HRS 1500		-			Complete
MOC : COMPLIED WITH										
FAA 1997-05-03 34AD-07	APPLIANCE AD - GNS-XLS AND GNS-XL GPS (SUPERSEDED BY 1997-05-03 R01)			SUPERSEDED	MTH 27-Mar-1997 HRS 1547		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 1998-04-38 30AD-02	SEVERE ICING PROCEDURES	BHM		MANDATORY	MTH 07-Jul-1998 HRS 1921		-			Complete
MOC : COMPLIED WITH										
FAA 1998-25-10 25AD-02	APPLIANCE AD - AIRCRAFT BELTS, INC. (SUPERSEDED BY 1998-25-10 R01)	PDK		SUPERSEDED	MTH 17-Dec-1998 HRS 2044		-			Complete
MOC : COMPLIED WITH										
FAA 1999-08-21 35AD-03	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM CO	PDK		MANDATORY	MTH 08-May-1999 HRS 2320		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2000-03-09 34AD-09	ICING COND FM INFORMATION	PDK		MANDATORY	MTH 02-May-2000 HRS 2906		-			Complete
MOC : COMPLIED WITH										
FAA 2006-04-10 26AD-02	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.			MANDATORY	MTH 16-May-2006 HRS 6581		-			Complete
MOC : COMPLIED WITH										
FAA 2006-06-03 28AD-01	PREVENT FUEL VAPOR IGNITION			MANDATORY	MTH 16-May-2006 HRS 6581		-			Complete
MOC : COMPLIED WITH										
FAA 2006-16-18 34AD-16	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	PDK		MANDATORY	MTH 26-Jan-2007 HRS 6719		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2006-19-04 PARA(F) 34AD-17	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM)			MANDATORY	MTH 26-Jan-2007 HRS 6719		A/R			N/A
MOC : NOT APPLICABLE										
FAA 1995-25-10 21AD-01	OUTFLOW AND SAFETY VALUES	MCO		MANDATORY	MTH 10-Jun-1996 HRS 1233		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	MCO	MANDATORY	DAYS 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	MCO	MANDATORY	DAYS 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	MCO	MANDATORY	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	MCO	MANDATORY	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	MCO	MANDATORY	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	MCO	MANDATORY	DAYS 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	MCO	MANDATORY	MTH 03-Jul-2013 HRS 7541.5 LDG 6863		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY INSPECTION AND FOUND NOT APPLICABLE DUE TO COMPONENT PART NUMBER 1250151 INSTALLED NOT AFFECTED BY THIS AD.									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	KMCO	MANDATORY	MTH 03-Dec-2015 DAYS 7978.9 HRS 7274 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	KMCO	MANDATORY	MTH 03-Dec-2015 DAYS 7978.9 HRS 7274 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	KMCO	MANDATORY	MTH 03-Dec-2015 HRS 7978.9 LDG 7274		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	KMCO	MANDATORY	MTH 03-Dec-2015 HRS 7978.9 LDG 7274		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	KMCO	MANDATORY	MTH 03-Dec-2015 HRS 7978.9 LDG 7274		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	KMCO	MANDATORY	MTH 03-Dec-2015 DAYS 7978.9 HRS 7274 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	KMCO	MANDATORY	MTH 03-Dec-2015 HRS 7978.9 LDG 7274		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-17-12 BY VISUAL VERIFICATION OF PART NUMBER. PART NUMBER INSTALLED IS NOT AFFECTED BY THIS AD. NO ACTION REQUIRED AD 2015-17-12 DOES NOT APPLY									



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
 Aircraft Model: **560 - CITATION V**
 Aircraft Serial: **560-0217**
 Unit: **0217** Reg No: **N802AB**
 Airworthiness: **16-Jun-1993**
 Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1995-22-01 33AD-03	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING	BHM		MANDATORY	MTH 12-Feb-1996 HRS 1080		A/R			Complete
MOC : COMPLIED WITH										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			Complete
MOC : COMPLIED WITH - COMPLIED AD 1974-08-09 R3 EFFECTIVE DATE MAR 28, 2012, PARAGRAPH (K) RECURRING INSPECTION, BY VISUAL INSPECTION OF THE LAVATORY PAPER AND LINEN WASTE RECEPTACLE ENCLOSURE ACCESSDOOR AND DISPOSAL DOORS IAW WITH THE AD INSTRUCTIONS. NO DEFECTS NOTED AT THIS TIME.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-02 BY INSPECTION AND FOUND EQUIPMENT IS NOT INSTALLED ON AIRCRAFT AND NO FURTHER ACTION IS REQUIRED PER THE AD INSTRUCTIONS.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KPKD			MTH 16-Oct-2018 HRS 8472.8 LDG 7767		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY, AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KSYR		MANDATORY	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		-			N/A
MOC : NOT APPLICABLE										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KSYR		MANDATORY	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		-			N/A
MOC : NOT APPLICABLE										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	KSYR		MANDATORY	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		-			N/A
MOC : NOT APPLICABLE										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	KSYR		MANDATORY	MTH 19-Nov-2021 HRS 8900.8 LDG 8218		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PNS.										
FAA 2007-11-17 26AD-03	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES	DAL		MANDATORY	MTH 20-Feb-2008 HRS 6851		A/R			Complete
MOC : COMPLIED WITH										
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS 03-Jul-2010 HRS 7200 LDG 6560		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2010-04-16 BY INSPECTION OF THE PORTABLE FIRE EXTINGUISHERS AND FOUND NOT TO APPLY DUE TO NOT BEING MANUFACTURED BY SICLI IAW THE AD INSTRUCTIONS.										
FAA 2010-04-16 26AD-07	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	MCO		MANDATORY	DAYS 03-Jul-2010 HRS 7200.8 LDG 6560		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2010-04-16 BY INSPECTION OF THE PORTABLE FIRE EXTINGUISHERS AND FOUND NOT TO APPLY DUE TO NOT BEING MANUFACTURED BY SICLI IAW THE AD INSTRUCTIONS.										
FAA 2007-23-13 34AD-19	INSPECT - ADJUSTMENT OF STALL WARNING SYSTEM (SUPERSEDED BY FAA 2008-26-04)	DAL		SUPERSEDED	MTH 20-Feb-2008 HRS 6851		A/R			Complete
MOC : COMPLIED WITH										
FAA 2008-26-04 34AD-24	INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED.	MCO		AIRWORTHINESS	MTH 04-Sep-2009 HRS 7042		A/R			Complete
MOC : COMPLIED WITH										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KSWF		MANDATORY	MTH 07-Jul-2022 HRS 9066.4 LDG 8317		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA AD 2021-23-12 PER AD PARAGRAPH (G) INSTRUCTIONS. INSERTED AD IN AFM.										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1994-01-04 <i>34AD-03</i>	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES	BHM		MANDATORY	MTH 12-Jul-1995 HRS 880		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 1998-25-02 <i>34AD-08</i>	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	PDK		MANDATORY	MTH 04-Jun-1999 HRS 2397		A/R			Complete
MOC : COMPLIED WITH										
FAA 2001-23-17 <i>34AD-10</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	RYY		MANDATORY	MTH 02-Jan-2002 HRS 3886		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-04-06 <i>34AD-13</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2006-22-05)	PDK		SUPERSEDED	MTH 26-Jan-2007 HRS 6719		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2006-22-05 <i>34AD-18</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2010-07-02)	MCO		MANDATORY	MTH 04-Sep-2009 HRS 7042		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	MCO		MANDATORY	MTH 04-Sep-2012 HRS 7410.4 LDG 6757		A/R			N/A
MOC : NOT APPLICABLE - NAV UNITS INSTALLED ARE NOT AFFECTED BY THIS AD IAW THE AD INSTRUCTIONS. NO FURTHER ACTION REQUIRED.										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	MCO		MANDATORY	MTH 04-Sep-2012 HRS 7410.4 LDG 6757		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO PART NUMBER OF INSTALLED TCAS UNIT ON THIS AIRCRAFT IAW THE AD INSTRUCTIONS. NO FURTHER ACTION REQUIRED.										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2014-18-01 BY INSPECTION AND FOUND EQUIPMENT IS NOT INSTALLED ON AIRCRAFT AND NO FURTHER ACTION IS REQUIRED PER THE AD INSTRUCTIONS.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-51 BY INSPECTION AND FOUND EQUIPMENT IS NOT INSTALLED ON AIRCRAFT AND NO FURTHER ACTION IS REQUIRED PER THE AD INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MCO		MANDATORY	MTH 14-Jun-2016 HRS 8082.3 LDG 7380 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-51 BY INSPECTION AND FOUND EQUIPMENT IS NOT INSTALLED ON AIRCRAFT AND NO FURTHER ACTION IS REQUIRED PER THE AD INSTRUCTIONS.										
FAA 1994-19-06 35AD-01	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	BHM		MANDATORY	MTH 12-Jul-1995 HRS 880		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KMCO		MANDATORY	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KMCO		MANDATORY	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KMCO		MANDATORY	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		-			N/A
MOC : NOT APPLICABLE - CREW MASK P/N MC10-16-101, S/N 90296 NOT APPLICABLE BY SERIAL NUMBER.MASK P/N MC10-15-109, S/N 44695, NOT APPLICABLE BY PART NUMBER. REFERENCE THE ZODIAC SB MXH-35-240.										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KMCO		MANDATORY	MTH 02-Feb-2016 DAYS 8009.8 HRS 7308 LDG		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KMCO		MANDATORY	MTH 02-Feb-2016 DAYS 8009.8 HRS 7308 LDG		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KMCO		MANDATORY	MTH 02-Feb-2016 DAYS 8009.8 HRS 7308 LDG		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KMCO		MANDATORY	MTH 02-Feb-2016 DAYS 8009.8 HRS 7308 LDG		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KMCO		MANDATORY	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KMCO		MANDATORY	MTH 02-Feb-2016 HRS 8009.8 LDG 7308		-			N/A
MOC : NOT APPLICABLE - CREW MASKS P/N MC10-16-101, S/N 90296 AND P/N MC10-15-109, S/N 44695 ARE NOT APPLICABLE BY PART NUMBER. REFERENCE THE ZODIAC SB MCF-SBU-35-001.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 07-Aug-2016 HRS 8100 LDG 7396 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 07-Aug-2016 HRS 8100 LDG 7396 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 07-Aug-2016 HRS 8100 LDG 7396 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12	KMCO		MANDATORY	MTH 07-Aug-2016 HRS 8100 LDG 7396 ACH 5039.8		-			N/A
MOC : NOT APPLICABLE - AD2016-11-20 EFFECTIVE DATE JULY 15 2016 NOT APPLICABLE. BE AEROSPACE PBE NOT INSTALLED IN AIRCRAFT										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KPDK		MANDATORY	MTH 16-Oct-2018 HRS 8472.8 LDG 7767		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY, AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES			MANDATORY			-			
MOC :										
FAA 1993-19-03 73AD-02	TO PREVENT DETERIORATION OF THE FLOW DIVIDER START VALVE DIAPHRAGM DUE TO HIGHT TEMPERATURE	MCO		MANDATORY	MTH 24-Nov-1993 HRS 310		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **VANDERPOOL AVIATION LLC**
Aircraft Model: **560 - CITATION V**
Aircraft Serial: **560-0217**
Unit: **0217** Reg No: **N802AB**
Airworthiness: **16-Jun-1993**
Print Date: **22-May-2023 10:11AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	9193.3	8400	30-Mar-2023	.5
ENG 1	9019.1	8248	30-Mar-2023	.5
ENG 2	8922.5	8141	30-Mar-2023	.5
AIR COND	5492.3		30-Mar-2023	.23

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
21FO-02 560 <i>21FO-02 : 560</i>	COOLING/FREON SUPPLEMENTAL FACTORY OPTION	*CF		15A FO	MTH 16-Jun-1993		-			
21FO-03 560 <i>21FO-03 : 560</i>	CABIN TEMP INDICATOR FACTORY OPTION	*CF		06A FO	MTH 16-Jun-1993		-			
23FO-07 560/K <i>23FO-07 : 560/K</i>	CVR-FAIRCHILD GA-100 FACTORY OPTION	*CF		634K FO	MTH 16-Jun-1993		-			
25FO-01 560 <i>25FO-01 : 560</i>	LOCATOR BEACON-EMERG FACTORY OPTION	*CF		175 FO	MTH 16-Jun-1993		-			
33FO-01 560 <i>33FO-01 : 560</i>	LIGHT-TAIL FLOOD FACTORY OPTION	*CF		54 FO	MTH 16-Jun-1993		-			
34FO-02 560 <i>34FO-02 : 560</i>	INDEXER-PILOTS ANGLE OF ATTACK FACTORY OPTION	*CF		11A FO	MTH 16-Jun-1993		-			
34FO-08 560/J <i>34FO-08 : 560/J</i>	DME 2-COLLINS DME 42 ONLY W/STD PACKAGE FACTORY OPTION	*CF		681J FO	MTH 16-Jun-1993		-			
34FO-09 560/X <i>34FO-09 : 560/X</i>	FM SYS-5TUBE HONEYWL EFIS FACTORY OPTION	*CF		685X FO	MTH 16-Jun-1993		-			