



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                | Description<br>Drawing # / Task #                                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------|--------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PPPP1                                | PAINT AIRCRAFT                                                                                         | KICT |         |                               | MTH 06-Sep-2017<br>HRS 6.1<br>LDG 3     |                | O/C            |                |                            |                    |
| E083-160920<br>E1                    | REVIEW FJ44-3A/-3A-24 LM REV 34                                                                        |      |         |                               |                                         |                | -              |                |                            |                    |
| E083-160920<br>E2                    | REVIEW FJ44-3A/-3A-24 LM REV 34                                                                        |      |         |                               |                                         |                | -              |                |                            |                    |
| E083-161216<br>E1                    | REVIEW FJ44-3A/3A-24 LMM REV 35                                                                        |      |         |                               |                                         |                | -              |                |                            |                    |
| E083-161216<br>E2                    | REVIEW FJ44-3A/3A-24 LMM REV 35                                                                        |      |         |                               |                                         |                | -              |                |                            |                    |
| 4-12-MA                              | INSPECTION DOCUMENT MA<br>KSDL                                                                         |      |         |                               | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | 500            |                | 978.6                      | 454.5              |
| 4-12-MB                              | INSPECTION DOCUMENT MB                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 15000          |                | 15000                      | 14475.9            |
| 4-12-MC                              | INSPECTION DOCUMENT MC                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 2000           |                | 2000                       | 1475.9             |
| 4-12-MD                              | INSPECTION DOCUMENT MD                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 1500           |                | 1500                       | 975.9              |
| 4-12-ME                              | INSPECTION DOCUMENT ME (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                             |      |         |                               | MTH 07-Sep-2017<br>LDG 0                |                | 5000           |                |                            |                    |
| 32-20-00-250<br>NOSE LANDING<br>GEAR | NOSE LANDING GEAR FORK AND PISTON ASSEMBLY (EDDY CURRENT OR DYE PENETRANT) SPECIAL DETAILED INSPECTION |      |         | 6342350-4<br>26774312         | MTH 07-Sep-2017<br>LDG 0                |                | 5000           |                | 5000                       | 4595               |
| 4-12-MF                              | INSPECTION DOCUMENT MF                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 2500           |                | 2500                       | 1975.9             |
| 4-12-MG                              | INSPECTION DOCUMENT MG                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 5000           |                | 5000                       | 4475.9             |
| 4-12-MH                              | INSPECTION DOCUMENT MH                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 5050           |                | 5050                       | 4525.9             |
| 4-12-MI                              | INSPECTION DOCUMENT MI                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 6000           |                | 6000                       | 5475.9             |
| 4-12-MJ                              | INSPECTION DOCUMENT MJ                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 3000           |                | 3000                       | 2475.9             |
| 4-12-MK                              | INSPECTION DOCUMENT MK<br>KSDL                                                                         |      |         |                               | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | 12<br>330      |                | 31-Oct-2023<br>808.6       | 5 m 13 d<br>284.5  |
| 4-12-ML                              | INSPECTION DOCUMENT ML                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 9000           |                | 9000                       | 8475.9             |
| 4-12-MO                              | INSPECTION DOCUMENT MO                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 15000          |                | 15000                      | 14475.9            |
| 4-12-MQ                              | INSPECTION DOCUMENT MQ                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 15000          |                | 15000                      | 14475.9            |
| 4-12-MR                              | INSPECTION DOCUMENT MR                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 11500          |                | 11500                      | 10975.9            |
| 4-12-MS                              | INSPECTION DOCUMENT MS                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 12000          |                | 12000                      | 11475.9            |
| 4-12-MT                              | INSPECTION DOCUMENT MT                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 7400           |                | 7400                       | 6875.9             |
| 4-12-MU                              | INSPECTION DOCUMENT MU                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 12000          |                | 12000                      | 11475.9            |
| 4-12-MV                              | INSPECTION DOCUMENT MV                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 9000           |                | 9000                       | 8475.9             |
| 4-12-MW                              | INSPECTION DOCUMENT MW                                                                                 |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 9000           |                | 9000                       | 8475.9             |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 4-12-MX               | INSPECTION DOCUMENT MX                                                                             |      |         | MTH                           | 07-Sep-2017              |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | HRS                           | 0                        |                | 6000           |                | 6000                       | 5475.9             |
| 4-12-MY               | INSPECTION DOCUMENT MY                                                                             |      |         | MTH                           | 07-Sep-2017              |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | HRS                           | 0                        |                | 12000          |                | 12000                      | 11475.9            |
| 4-12-MZ               | INSPECTION DOCUMENT MZ                                                                             |      |         | MTH                           | 07-Sep-2017              |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | HRS                           | 0                        |                | 24600          |                | 24600                      | 24075.9            |
| 055001                | CHECK AFTER HARD/OVERWEIGHT LANDING                                                                |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 055002                | CHECK AFTER OVERSPEED CONDITION                                                                    |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 055003                | CHECK AFTER DANGEROUS AIR TURBULENCE OR UNAPPROVED MANEUVERS                                       |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 055004                | CHECK AFTER LIGHTNING STRIKE                                                                       |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 055005                | CHECK FOREIGN OBJECT DAMAGE                                                                        |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 055006                | CHECK AFTER TOWING WITH LARGE FUEL UNBALANCE OR A HIGH DRAG/SIDE LOAD DUE TO GROUND HANDLING CHECK |      |         | MTH                           | 07-Sep-2017              |                | A/R            |                |                            |                    |
| 5-12-01               | INSPECTION DOCUMENT 1<br>KIWA                                                                      |      |         | MTH                           | 13-Apr-2023              |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | HRS                           | 524.1                    |                | 300            |                | 824.1                      | 300                |
|                       |                                                                                                    |      |         | LDG                           | 402                      |                |                |                |                            |                    |
| 5-12-05               | INSPECTION DOCUMENT 5<br>KSDL                                                                      |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         | HRS                           | 478.6                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 374                      |                |                |                |                            |                    |
| B243801               | AUXILIARY BATTERY FUNCTIONAL CHECK (CAPACITY CHECK), (AIRPLANES -0057 AND -0451 AND ON)            |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         | HRS                           | 478.6                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 374                      |                |                |                |                            |                    |
| B262002<br>CABIN      | CABIN PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK                                                |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| B262002<br>COCKPIT    | COCKPIT PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK                                              |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| B342100               | CAPACITY TEST STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID)                                         |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         | HRS                           | 478.6                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 374                      |                |                |                |                            |                    |
| 5-12-06               | INSPECTION DOCUMENT 6 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                          |      |         | MTH                           | 07-Sep-2017              |                | 24             |                |                            |                    |
| 5-12-07               | INSPECTION DOCUMENT 7 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                          |      |         | MTH                           | 01-Oct-2020              |                | 36             |                |                            |                    |
|                       |                                                                                                    |      |         | HRS                           | 261.3                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 212                      |                |                |                |                            |                    |
| B236001               | FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM                                                           |      |         | MTH                           | 01-Oct-2020              |                | 36             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         | HRS                           | 261.3                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 212                      |                |                |                |                            |                    |
| 5-12-08               | INSPECTION DOCUMENT 8<br>KIWA                                                                      |      |         | MTH                           | 01-Oct-2021              |                | 48             |                | 31-Oct-2025                | 29 m 13 d          |
|                       |                                                                                                    |      |         | HRS                           | 373.5                    |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | LDG                           | 304                      |                |                |                |                            |                    |
| 5-12-09               | INSPECTION DOCUMENT 9                                                                              |      |         | MTH                           | 07-Sep-2017              |                | 72             |                | 30-Sep-2023                | 4 m 12 d           |
| 5-12-11               | INSPECTION DOCUMENT 11<br>KSDL                                                                     |      |         | MTH                           | 28-Oct-2022              |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                       |                                                                                                    |      |         | HRS                           | 478.6                    |                | 300            |                | 778.6                      | 254.5              |
|                       |                                                                                                    |      |         | LDG                           | 374                      |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                  | City | Mod Lvl | Part Number<br>Part Serial No           | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains  |
|-----------------------|----------------------------------------------------------------------------------------------------|------|---------|-----------------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|---------------------|
| 5-12-12               | INSPECTION DOCUMENT 12                                                                             | KIWA |         | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                                         |                | 24<br>600      |                | 31-Oct-2023<br>973.5       | 5 m 13 d<br>449.4   |
| 5-12-14               | INSPECTION DOCUMENT 14                                                                             | KIWA |         | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                                         |                | 24<br>1200     |                | 31-Oct-2023<br>1573.5      | 5 m 13 d<br>1049.4  |
| 5-12-16               | INSPECTION DOCUMENT 16                                                                             | KIWA |         | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                                         |                | 48<br>2400     |                | 31-Oct-2025<br>2773.5      | 29 m 13 d<br>2249.4 |
| 5-12-17               | INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)   |      |         |                                         | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | 12             |                |                            |                     |
| A256001               | ELT TRANSMITTER DETAILED INSPECTION (INTERVAL CFR 91.207)                                          | KSDL |         | 453-5060<br>252-01846                   | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 | -27            | 12             |                | 31-Oct-2023                | 5 m 13 d            |
| B256001               | OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (INTERVAL CFR 91.207) | KSDL |         | 453-5060<br>252-01846                   | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 | -27            | 12             |                | 31-Oct-2023                | 5 m 13 d            |
| 5-12-18               | INSPECTION DOCUMENT 18 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                         |      |         |                                         | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | 24             |                |                            |                     |
| 341055<br>NO. 1       | NO. 1 AIR DATA COMPUTER CALIBRATION TEST                                                           | KIWA |         | 011-02337-01<br>146101624               | MTH 21-Sep-2021                         | -14            | 24             |                | 30-Sep-2023                | 4 m 12 d            |
| 341056<br>NO. 2       | NO. 2 AIR DATA COMPUTER CALIBRATION TEST                                                           | KIWA |         | 011-02337-01<br>146101614               | MTH 21-Sep-2021                         | -14            | 24             |                | 30-Sep-2023                | 4 m 12 d            |
| 341060                | INSPECT RVSM SKIN WAVINESS                                                                         | KIWA |         |                                         | MTH 01-Oct-2021                         | -24            | 24             |                | 30-Sep-2023                | 4 m 12 d            |
| B341101<br>LEFT       | FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES -0057 AND -0451 AND ON)                            | KIWA |         |                                         | MTH 21-Sep-2021                         |                | 24             |                | 30-Sep-2023                | 4 m 12 d            |
| B341101<br>RIGHT      | FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES -0057 AND -0451 AND ON)                            | KIWA |         |                                         | MTH 21-Sep-2021                         |                | 24             |                | 30-Sep-2023                | 4 m 12 d            |
| B345701<br>NO. 1      | FUNCTIONAL CHECK TRANSPONDER TRANSPONDER SYSTEM (AIRPLANES -0057 AND -0451 AND ON)                 | KIWA |         | 011-01997-00<br>20S008039               | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | 24             |                | 31-Oct-2023                | 5 m 13 d            |
| B345701<br>NO. 2      | FUNCTIONAL CHECK TRANSPONDER TRANSPONDER SYSTEM (AIRPLANES -0057 AND -0451 AND ON)                 | KIWA |         | 011-01997-00<br>20S008010               | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | 24             |                | 31-Oct-2023                | 5 m 13 d            |
| 5-12-22               | INSPECTION DOCUMENT 22                                                                             | KIWA |         | MTH 01-Oct-2020<br>HRS 261.3<br>LDG 212 |                                         |                | 36<br>1200     |                | 31-Oct-2023<br>1461.3      | 5 m 13 d<br>937.2   |
| 5-12-23               | INSPECTION DOCUMENT 23                                                                             | KIWA |         | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                                         |                | 24<br>300      |                | 31-Oct-2023<br>673.5       | 5 m 13 d<br>149.4   |
| 5-12-24               | INSPECTION DOCUMENT 24 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                         |      |         |                                         | MTH 07-Sep-2017<br>HRS 0                |                | 72<br>2400     |                |                            |                     |
| A561001               | WINDSHIELD OPTICAL PRISM INSPECTION                                                                |      |         |                                         | MTH 07-Sep-2017<br>HRS 0                |                | 72<br>2400     |                | 30-Sep-2023<br>2400        | 4 m 12 d<br>1875.9  |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                 | Description<br>Drawing # / Task #                                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------|-------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 5-12-29                               | INSPECTION DOCUMENT 29 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 28-Oct-2022          |                | 12             |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 478.6                |                | 100            |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 374                  |                |                |                |                            |                    |
| D243201                               | CAPACITY CHECK BATTERY (NICKEL-CADMIUM)                                                   |      |         |                               | MTH 28-Oct-2022          |                | 12             |                | 31-Oct-2023                | 5 m 13 d           |
|                                       |                                                                                           |      |         | 30978-002                     | HRS 478.6                |                | 100            |                | 578.6                      | 54.5               |
|                                       |                                                                                           |      |         | 11700340                      | LDG 374                  |                |                |                |                            |                    |
| 5-12-32                               | INSPECTION DOCUMENT 32 (NDI INTERVAL) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 07-Sep-2017          |                | T/C            |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 0                    |                |                |                |                            |                    |
| A324103<br>LEFT MAIN<br>LANDING GEAR  | LEFT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)          | KIWA |         | 3-1607-1<br>T0034             | MTH 02-Jan-2022          |                | T/C            |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 394.9                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 322                  |                |                |                |                            |                    |
| A324103<br>NOSE LANDING<br>GEAR       | NOSE MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)          | KIWA |         | 3-1418OPT-4<br>T0026          | MTH 27-Sep-2019          |                | T/C            |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 218.4                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 174                  |                |                |                |                            |                    |
| A324103<br>RIGHT MAIN<br>LANDING GEAR | RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)         | KIWA |         | 3-1607-1<br>T0029             | MTH 02-Jan-2022          |                | T/C            |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 394.9                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 322                  |                |                |                |                            |                    |
| 5-12-35                               | INSPECTION DOCUMENT 35 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 07-Sep-2017          |                | 12             |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                | 600            |                |                            |                    |
| 5-12-38                               | INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 29-Mar-2023          |                | 6              |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 523.9                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 405                  |                |                |                |                            |                    |
| B342101                               | PS-855 (LEAD ACID) STANDBY GYRO BATTERY PACK PERIODIC TEST                                |      |         | 501-1712-01<br>81968          | MTH 29-Mar-2023          |                | 6              |                | 30-Sep-2023                | 4 m 12 d           |
|                                       |                                                                                           |      |         |                               | HRS 523.9                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 405                  |                |                |                |                            |                    |
| 5-12-39                               | INSPECTION DOCUMENT 39                                                                    |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 07-Sep-2017          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                | 5000           |                | 5000                       | 4475.9             |
| 5-12-40                               | INSPECTION DOCUMENT 40<br>KSDL                                                            |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 29-Mar-2023          |                | 6              |                | 30-Sep-2023                | 4 m 12 d           |
|                                       |                                                                                           |      |         |                               | HRS 523.9                |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | LDG 405                  |                |                |                |                            |                    |
| 5-12-41                               | INSPECTION DOCUMENT 41                                                                    |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 07-Sep-2017          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | ACH 0                    |                | 500            |                | 500                        | 203                |
| 5-12-42                               | INSPECTION DOCUMENT 42                                                                    |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH 07-Sep-2017          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                | 11950          |                | 11950                      | 11425.9            |
| 5-12-43                               | INSPECTION DOCUMENT 43                                                                    |      |         |                               |                          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | MTH                      |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS                      |                | 7200           |                | 7200                       | 6675.9             |
| 052001<br>E1                          | FJ44 CHECK 1                                                                              | KIWA |         |                               | MTH 13-Apr-2023          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 524.1                | -5.7           | 300            |                | (818.4)818.4               | 294.3              |
|                                       |                                                                                           |      |         |                               | LDG 402                  |                |                |                |                            |                    |
| 052001<br>E2                          | FJ44 CHECK 1                                                                              | KIWA |         |                               | MTH 13-Apr-2023          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 524.1                | -5.7           | 300            |                | (818.4)818.4               | 294.3              |
|                                       |                                                                                           |      |         |                               | LDG 402                  |                |                |                |                            |                    |
| 052002<br>E1                          | FJ44 CHECK 2                                                                              |      |         |                               | MTH 07-Sep-2017          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                | 600            |                | (600)600                   | 75.9               |
| 052002<br>E2                          | FJ44 CHECK 2                                                                              |      |         |                               | MTH 07-Sep-2017          |                |                |                |                            |                    |
|                                       |                                                                                           |      |         |                               | HRS 0                    |                | 600            |                | (600)600                   | 75.9               |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position  | Description<br>Drawing # / Task #                                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 723003<br>E1           | CLEAN FAN ROTOR AND PHYSICALLY INSPECT FOR DEFECTS (FEEL WITH FINGERS). |      |         | 115810<br>HW45371             | MTH 07-Sep-2017<br>HRS 0 |                | 600            |                | (600)600                   | 75.9               |
| 723003<br>E2           | CLEAN FAN ROTOR AND PHYSICALLY INSPECT FOR DEFECTS (FEEL WITH FINGERS). |      |         | 115810<br>HW43696             | MTH 07-Sep-2017<br>HRS 0 |                | 600            |                | (600)600                   | 75.9               |
| 052003<br>E1           | FJ44 CHECK 3                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -10000         | 12000          |                | (2000)2000                 | 1475.9             |
| 052003<br>E2           | FJ44 CHECK 3                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -10000         | 12000          |                | (2000)2000                 | 1475.9             |
| 052004<br>E1           | FJ44 CHECK 4                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -8000          | 12000          |                | (4000)4000                 | 3475.9             |
| 052004<br>E2           | FJ44 CHECK 4                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -8000          | 12000          |                | (4000)4000                 | 3475.9             |
| 052005<br>E1           | FJ44 CHECK 5                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -6000          | 12000          |                | (6000)6000                 | 5475.9             |
| 052005<br>E2           | FJ44 CHECK 5                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -6000          | 12000          |                | (6000)6000                 | 5475.9             |
| 052006<br>E1           | FJ44 CHECK 6                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -4000          | 12000          |                | (8000)8000                 | 7475.9             |
| 052006<br>E2           | FJ44 CHECK 6                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -4000          | 12000          |                | (8000)8000                 | 7475.9             |
| 052007<br>E1           | FJ44 CHECK 7                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -2000          | 12000          |                | (10000)10000               | 9475.9             |
| 052007<br>E2           | FJ44 CHECK 7                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 | -2000          | 12000          |                | (10000)10000               | 9475.9             |
| 052008<br>E1           | FJ44 CHECK 8                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 |                | 12000          |                | (12000)12000               | 11475.9            |
| 052008<br>E2           | FJ44 CHECK 8                                                            |      |         |                               | MTH 07-Sep-2017<br>HRS 0 |                | 12000          |                | (12000)12000               | 11475.9            |
| 12-23-00-601           | 15 DAY HIGH EXPOSURE AREA WASH -AIRPLANE ZONE 1 WASH                    |      |         |                               |                          |                | A/R            |                |                            |                    |
| 12-23-00-602           | 45 DAY MEDIUM EXPOSURE AREA WASH -AIRPLANE ZONE 2 WASH                  |      |         |                               |                          |                | A/R            |                |                            |                    |
| 12-23-00-603           | 90 DAY LOW EXPOSURE AREA WASH -AIRPLANE ZONE 3 WASH                     |      |         |                               |                          |                | A/R            |                |                            |                    |
| 215018                 | REPLACE COMPRESSOR DRIVE MOTOR BRUSHES                                  |      |         |                               | MTH 07-Sep-2017<br>ACH 0 |                | 800            |                | 800                        | 503                |
| 236000                 | MAINTENANCE PRACTICES STATIC WICKS STATIC DISCHARGER(WICK)              |      |         |                               | MTH 07-Sep-2017          |                | O/C            |                |                            |                    |
| 262002A<br>ENGINE NO.1 | REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)                      | KSDL |         | M13083-5<br>48504             | MTH 29-Mar-2023          |                | 72             |                | 31-Mar-2029                | 70 m 13 d          |
| 262002A<br>ENGINE NO.2 | REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)                      | KSDL |         | M13083-5<br>48505             | MTH 29-Mar-2023          |                | 72             |                | 31-Mar-2029                | 70 m 13 d          |
| 262002B<br>ENGINE NO.1 | REPLACE ENGINE NO.1 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)  | KSDL |         | M13083-5<br>48504             | MTH 29-Mar-2023          |                | 72             |                | 29-Mar-2029                | 70 m 11 d          |
| 262002B<br>ENGINE NO.2 | REPLACE ENGINE NO.2 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)  | KSDL |         | M13083-5<br>48505             | MTH 29-Mar-2023          |                | 72             |                | 29-Mar-2029                | 70 m 11 d          |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                      | Description<br>Drawing # / Task #                                                                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------|----------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| A262002<br>CABIN                           | CABIN PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION                                       | ICT  |         | C352<br>D-03568232            | MTH 01-Aug-2017                         |                | 72             |                | 31-Aug-2023                | 3 m 13 d           |
| A262002<br>COCKPIT                         | COCKPIT PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION                                     | ICT  |         | C352TS<br>D-03568233          | MTH 01-Aug-2017                         |                | 72             |                | 31-Aug-2023                | 3 m 13 d           |
| D262001                                    | ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)                                     | KSDL |         | 30401102-2<br>75406B1         | MTH 09-Jun-2022                         |                | 60             |                | 30-Jun-2027                | 49 m 12 d          |
| D262003<br>CABIN                           | HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER                                                        | ICT  |         | C352<br>D-03568232            | MTH 01-Aug-2017                         |                | 144            |                | 31-Aug-2029                | 75 m 13 d          |
| D262003<br>COCKPIT                         | HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER                                                        | ICT  |         | C352TS<br>D-03568233          | MTH 01-Aug-2017                         |                | 144            |                | 31-Aug-2029                | 75 m 13 d          |
| 28-00-02-220                               | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT) | P19  |         |                               | MTH 25-May-2020<br>HRS 246.1<br>LDG 204 |                | A/R            |                |                            |                    |
| 28-00-02-221                               | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)     | KIWA |         |                               | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | 12             |                | 30-Apr-2024                | 11 m 12 d          |
| B323101                                    | HYDROSTATIC TEST EMERGENCY PNEUMATIC STORAGE BOTTLE                                                | KSDL |         | 40005320-2<br>4146            | MTH 10-Nov-2022                         |                | 36             |                | 30-Nov-2025                | 30 m 12 d          |
| 33-50-00-960<br>LEFT                       | AFT LEFT EMERGENCY LIGHTING BATTERY PACK RESTORATION                                               | KSDL |         | CBS28-1<br>008117             | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | 48             |                | 31-Oct-2026                | 41 m 13 d          |
| 33-50-00-960<br>RIGHT                      | FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK RESTORATION                                          | KSDL |         | CBS28-1<br>7134M              | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | 48             |                | 31-Oct-2026                | 41 m 13 d          |
| B351002                                    | RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER AND REGULATOR ASSEMBLY                              | KSDL |         | 176276-50<br>837741002        | MTH 02-Mar-2022                         |                | 60             |                | 31-Mar-2027                | 46 m 13 d          |
| 571050<br>LEFT WING                        | INSPECT MAIN SPAR, WS 183.50                                                                       |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 10000          |                | 10000                      | 9475.9             |
| 571055<br>RIGHT WING                       | INSPECT MAIN SPAR, WS 183.50                                                                       |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 10000          |                | 10000                      | 9475.9             |
| 571080<br>LEFT WING                        | INSPECT MAIN SPAR SPLICE, WS 132.00                                                                |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 9500           |                | 9500                       | 8975.9             |
| 571085<br>RIGHT WING                       | INSPECT MAIN SPAR SPLICE, WS 132.00                                                                |      |         |                               | MTH 07-Sep-2017<br>HRS 0                |                | 9500           |                | 9500                       | 8975.9             |
| 711000                                     | MAINTENANCE PRACTICES ENGINE ENGINE COWLING                                                        |      |         |                               | MTH 07-Sep-2017                         |                | O/C            |                |                            |                    |
| 712003<br>LEFT ENGINE AFT                  | LEFT ENGINE AFT ISOLATOR MOUNT (INSPECTION)                                                        |      |         | LM-605-SA11<br>LK3924         | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |
| 712003<br>LEFT ENGINE<br>FORWARD<br>BOTTOM | LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)                                             |      |         | LM-605-SA8<br>LK3149          | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Maintenance Inspections

| Item Code<br>Position                       | Description<br>Drawing # / Task #                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------|---------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 712003<br>LEFT ENGINE<br>FORWARD TOP        | LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)     |      |         | LM-605-SA8<br>LK3150          | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |
| 712003<br>RIGHT ENGINE<br>AFT               | RIGHT ENGINE AFT ISOLATOR MOUNT (INSPECTION)            |      |         | LM-605-SA10<br>LK3937         | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |
| 712003<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM | RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION) |      |         | LM-605-SA8<br>LK3152          | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |
| 712003<br>RIGHT ENGINE<br>FORWARD TOP       | RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)    |      |         | LM-605-SA8<br>LK3151          | HRS                                     |                | 5000           |                | 5000                       | 4475.9             |
| 710003<br>E1                                | RINSE DESALINIZATION                                    |      |         |                               | MTH 07-Sep-2017                         |                | A/R            |                |                            |                    |
| 710003<br>E2                                | RINSE DESALINIZATION                                    |      |         |                               | MTH 07-Sep-2017                         |                | A/R            |                |                            |                    |
| 710005<br>E1                                | COMPRESSOR CLEANING<br>KIWA                             |      |         |                               | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | A/R            |                |                            |                    |
| 710005<br>E2                                | COMPRESSOR CLEANING<br>KIWA                             |      |         |                               | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | A/R            |                |                            |                    |
| 710030<br>E1                                | POLISH FAN ROTOR                                        |      |         |                               | MTH 07-Sep-2017                         |                | A/R            |                |                            |                    |
| 710030<br>E2                                | POLISH FAN ROTOR                                        |      |         |                               | MTH 07-Sep-2017                         |                | A/R            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No    | C/W Time 1<br>C/W Time 2               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|----------------------------------|----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 211001<br>LEFT        | PRESS SHUTOFF VALVE               | KIWA |         | 5253-00-3<br>3437B               | MTH 20-May-2018<br>HRS 104.3<br>LDG 93 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 211001<br>RIGHT       | PRESS SHUTOFF VALVE               | KIWA |         | 5253-00-3<br>2474B               | MTH 20-May-2018<br>HRS 104.3<br>LDG 93 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 211002<br>LEFT        | VARIABLE VALVE                    |      |         | 2601-32<br>1023                  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211002<br>RIGHT       | VARIABLE VALVE                    |      |         | 2601-32<br>1024                  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211003                | HEAT PRESS EXCHANGER              |      |         | 10905A<br>561                    | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211005                | EMER PRESS SHUTOFF VALVE          |      |         | 2601-23<br>9912422-2<br>1550     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211006<br>NO.1        | A/C CHECK VALVE                   |      |         | 7125-320101<br>9912078-9<br>NSN  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211006<br>NO.2        | A/C CHECK VALVE                   |      |         | 7125-320101<br>9912078-9<br>NSN  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 211006<br>NO.3        | A/C CHECK VALVE                   |      |         | 7125-320101<br>9912078-9<br>NSN  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 212001                | BAGGAGE CMPT BLOWER               |      |         | 0113-12<br>2576                  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 212003                | THERMO AIR DIST SWITCH            |      |         | 1173T42-1<br>4313                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 212302                | W/S AIR BLOWER MOTOR              |      |         | 7003-200<br>2143                 | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 212303                | BLDC MOTOR ASSEMBLY BLOWER        |      |         | 1133270-2<br>1587                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 213003                | PRESSURIZATION CONTROLLER         |      |         | 52811-103<br>5343                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 213004<br>NO.1        | SOLENOID BAGGAGE VALVE            |      |         | 5060-00-1<br>4753                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 213004<br>NO.2        | SOLENOID BAGGAGE VALVE            |      |         | 5060-00-1<br>4767                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 213006                | OUTFLOW VALVE - 4 IN VALVE        |      |         | 52812-106<br>9912661-10<br>5080  | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 213010                | PRESSURE OUTFLOW VALVE VALVE      |      |         | 52812-105<br>9912661-9<br>5079   | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215000<br>AFT         | EVAPORATOR BLOWER MOTOR           |      |         | 1133210-7<br>1997                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215000<br>FWD         | EVAPORATOR BLOWER MOTOR           |      |         | 1133260-3<br>245                 | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215001                | FWD EVAPORATOR MODULE             |      |         | 1134300-4<br>9912583-11<br>244   | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215002                | AFT EVAPORATOR MODULE             |      |         | 1134820-15<br>9912583-10<br>1243 | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215003                | COMPRESSOR DRIVE MOTOR            |      |         | 1134146-1<br>2067A               | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215004                | COMPRESSOR DRIVE ASSEMBLY         |      |         | 1134610-1<br>9912583-6<br>1112   | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215005                | CONDENSER ASSEMBLY                |      |         | 1134620-5<br>9912660-3<br>831    | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215006                | BINARY SWITCH                     |      |         | 1250232-10<br>NSN                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215007                | DRYER ASSY RECEIVER               |      |         | 1134275-1<br>9912583-3<br>NSN    | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------|------|---------|-------------------------------|----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 215008                | COMPRESSOR ASSEMBLY                   |      |         | 1134130-5<br>1604             | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215009                | VANE AXIAL BLOWER ASSY                |      |         | 1250435-10<br>925             | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215010                | A/C FLIGHT HOURMETER                  |      |         | 1250703-3<br>NSN              | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 215011                | AIR CONDITIONER DRIVE BELT            |      |         | 225L100<br>NSN                | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 216001                | RAM AIR MOD VALVE                     |      |         | 27241287-24<br>5BP29          | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 216002                | TEMP CONTROLLER                       |      |         | 1E86-1<br>4BP272              | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 216003<br>AFT         | CABIN TC007 SENSOR<br>9912085-3       |      |         | 27221274<br>5BP128            | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 216003<br>FORWARD     | COCKPIT UT006 SENSOR<br>9912085-3     |      |         | 27221274<br>5BP127            | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221002<br>AILERON     | SERVO MOUNT<br>GSM 86                 |      |         | 011-02490-18<br>1GK018707     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221002<br>ELEVATOR    | SERVO MOUNT<br>GSM 86                 |      |         | 011-02490-16<br>1GK018760     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221002<br>RUDDER      | SERVO MOUNT<br>GSM 86                 |      |         | 011-02490-19<br>1GK018725     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221003<br>AILERON     | SERVO<br>GSA80                        |      |         | 011-00877-20<br>19Z010603     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221003<br>ELEVATOR    | SERVO<br>GSA80                        |      |         | 011-00877-20<br>19Z010615     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221003<br>RUDDER      | SERVO<br>GSA80                        |      |         | 011-00877-20<br>19Z010613     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 221005                | TORQUE SERVO<br>GSA81                 | KIWA |         | 011-00878-20<br>1A1015990     | MTH 20-May-2018<br>HRS 104.3<br>LDG 93 |                | O/C            |                |                            |                    |
| 230098<br>CABIN       | USB PORT                              | ICT  |         | MSP100-01<br>560000347        | MTH 21-Aug-2017                        |                | O/C            | 0              |                            |                    |
| 230098<br>CO-PILOT    | USB PORT                              | ICT  |         | PED050-01<br>566000537        | MTH 21-Aug-2017                        |                | O/C            | 0              |                            |                    |
| 230098<br>PILOT       | USB PORT                              | ICT  |         | PED050-01<br>566000540        | MTH 21-Aug-2017                        |                | O/C            | 0              |                            |                    |
| 231007<br>NO.1        | COMM ANTENNA                          |      |         | VHF10-829<br>2696             | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 231007<br>NO.2        | COMM ANTENNA                          |      |         | VHF10-829<br>2683             | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 231009<br>AFT         | AIRCELL AIR-TO-GROUND ANTENNA         |      |         | P12949<br>530654              | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 231009<br>FWD         | AIRCELL AIR-TO-GROUND ANTENNA         |      |         | P12949<br>530649              | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 232007<br>CABIN       | AIRCELL FLITEFONE HANDSET<br>ICT      |      |         | 744000-10-72<br>4C5902        | MTH 21-Aug-2017                        |                | O/C            | 0              |                            |                    |
| 232018                | ATG 5000 AIRCELL CONFIGURATION MODULE |      |         | P14126<br>1412617281          | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 232021                | ATG 5000 HIGH SPEED LRU               |      |         | P15864-001<br>1586418618      | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 235001                | AUDIO AMPLIFIER                       |      |         | 102025-1<br>5970317           | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 235003<br>LEFT        | REMOTE AUDIO PROCESSOR<br>GMA36       |      |         | 011-01793-00<br>1HF007663     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |
| 235003<br>RIGHT       | REMOTE AUDIO PROCESSOR                |      |         | 011-01793-00<br>1HF007662     | MTH 07-Sep-2017                        |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position          | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 237003                         | CVR MICROPHONE                    |      |         | S055-0067-00<br>121881        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 243003<br>LEFT                 | GENERATOR CONTROL UNIT            |      |         | 51525-001F<br>P7806           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 243003<br>RIGHT                | GENERATOR CONTROL UNIT            |      |         | 51525-001F<br>P7824           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 243007                         | BATTERY<br>9914058-6              | *CF  |         | 30978-002<br>11700340         | MTH 06-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 243015                         | 14 AHR BATTERY ASSEMBLY<br>KIWA   |      |         | 7243-16T<br>G03040382         | MTH 27-Sep-2019<br>HRS 218.4<br>LDG 174 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 245001<br>LEFT                 | START CONTROL PCB                 |      |         | 6318038-1<br>1749             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245001<br>RIGHT                | START CONTROL PCB                 |      |         | 6318038-1<br>1748             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245002<br>LEFT                 | FUEL CONTROL PCB                  |      |         | 6318037-6<br>1484             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245002<br>RIGHT                | FUEL CONTROL PCB                  |      |         | 6318037-6<br>1334             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245003<br>LEFT                 | IGNITOR CNTRL PCB                 |      |         | 6318388-7<br>1065             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245003<br>RIGHT                | IGNITOR CNTRL PCB                 |      |         | 6318388-7<br>1064             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245004<br>LEFT                 | ANTI ICE PCB                      |      |         | 6318342-29<br>1131            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245004<br>RIGHT                | ANTI ICE PCB                      |      |         | 6318342-29<br>1135            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245006                         | ENVIRONMENTAL PCB                 |      |         | 6318358-20<br>709             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245007                         | HYDRAULIC PCB                     |      |         | 6318035-7<br>818              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245010                         | GEAR LOGIC 1 PCB                  |      |         | 6318398-6<br>849              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245011                         | FUEL FLOW PCB<br>9912417-3        |      |         | 85-230-2<br>1649213           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245012                         | SPEEDBRAKE PCB                    |      |         | 6318034-6<br>854              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245014                         | GEAR LOGIC 2 PCB                  |      |         | 6318399-11<br>827             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245015                         | GEAR MONITOR PCB                  |      |         | 6318397-21<br>928             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245016                         | TAIL DEICE CONTROL PCB            |      |         | 6318044-1<br>908              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245017                         | TAIL DEICE MONITOR PCB            |      |         | 6318043-1<br>918              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245018                         | PRESSURIZATION PCB                |      |         | 6318349-26<br>593             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245019                         | DIAGNOSTICS PCB ASSY              |      |         | 6318046-9<br>592              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 245201                         | CABIN ALT MODULE ASSEMBLY         |      |         | 7018119-1<br>1822             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 251099<br>CO PILOT<br>106300-9 | AC OUTLET ASSEMBLY<br>ICT         |      |         | 106300-12<br>10380517         | MTH 21-Aug-2017                         |                | O/C            | 0              |                            |                    |
| 251099<br>NO. 5<br>106300-9    | AC OUTLET ASSEMBLY<br>ICT         |      |         | 106300-15<br>1420517          | MTH 21-Aug-2017                         |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position              | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2           | TSO 1<br>TSO 2   | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|--------------------------|------------------|----------------------------|--------------------|
| 251099<br>NO. 6<br><i>106300-9</i> | AC OUTLET ASSEMBLY                | ICT  |         | 106300-13<br>3211216          | MTH 21-Aug-2017                         |                | O/C                      | 0                |                            |                    |
| 252099<br>ENTRY                    | SWITCH PANEL                      | ICT  |         | 101015-1<br>5150617           | MTH 21-Aug-2017                         |                | O/C                      | 0                |                            |                    |
| 256001                             | ELT TRANSMITTER<br>C406-N         |      |         | 453-5060<br>252-01846         | MTH 07-Sep-2017                         |                | O/C                      | 0                |                            |                    |
| 256002                             | ELT BEACON BATTERY PACK           | KSDL |         | 452-0133<br>395080-031        | MTH 15-Jun-2022<br>HRS 433.8<br>LDG 351 |                | DUE<br>DUE<br>DUE<br>DUE | 0<br>0<br>0<br>0 | 31-May-2027                | 48 m 13 d          |
| Expiration Date: 31-May-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256004                             | ELT ANTENNA<br>C406-N             |      |         | 110-340<br>542219             | MTH 07-Sep-2017                         |                | O/C                      | 0                |                            |                    |
| 256006<br>LAVATORY                 | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820042     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 1                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17022020055     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 24-Feb-2027                | 45 m 6 d           |
| Expiration Date: 24-Feb-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 2                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820031     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 3                    | LIFE JACKET                       | KIWA |         | P01074-207<br>170618200262    | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 4                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17022020058     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 24-Feb-2027                | 45 m 6 d           |
| Expiration Date: 24-Feb-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 5                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820033     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 6                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820048     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 7                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820046     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |
| 256006<br>NO. 8                    | LIFE JACKET                       | KIWA |         | P01074-207<br>17061820027     | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | DUE<br>DUE<br>DUE<br>DUE |                  | 22-Jun-2027                | 49 m 4 d           |
| Expiration Date: 22-Jun-2027       |                                   |      |         |                               |                                         |                |                          |                  |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position        | Description<br>Drawing # / Task #            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2           | TSO 1<br>TSO 2     | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|----------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|--------------------------|--------------------|----------------------------|--------------------|
| 256055                       | FIRST AID KIT                                | KIWA |         | FAK<br>00172853               | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | DUE<br>DUE<br>DUE<br>DUE | 0<br>0<br>0<br>0   | 01-Jul-2025                | 25 m 13 d          |
| Expiration Date: 01-Jul-2025 |                                              |      |         |                               |                                         |                |                          |                    |                            |                    |
| 261001<br>LEFT               | ENGINE FIRE DETECTOR<br>9912416-1            |      |         | 3001-212-1004/455-9<br>215311 | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 261001<br>RIGHT              | ENGINE FIRE DETECTOR<br>9912416-1            |      |         | 3001-212-1004/455-9<br>215004 | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 261002<br>AFT                | SMOKE DETECTOR                               |      |         | 473597-17<br>SEA0570          | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 261002<br>FORWARD            | SMOKE DETECTOR                               |      |         | 474716<br>TCA0146             | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 262001                       | ENGINE FIRE EXTINGUISHER BOTTLE<br>9912048-6 |      |         | 30401102-2<br>75406B1         | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 262002<br>ENGINE NO.1        | FIRE EXTINGUISHER CARTRIDGE<br>KSDL          |      |         | M13083-5<br>48504             | MTH 29-Mar-2023<br>HRS 523.9<br>LDG 405 |                | H/T<br>H/T<br>H/T<br>H/T | 0<br>0<br>0<br>0   |                            |                    |
| 262002<br>ENGINE NO.2        | FIRE EXTINGUISHER CARTRIDGE<br>KSDL          |      |         | M13083-5<br>48505             | MTH 29-Mar-2023<br>HRS 523.9<br>LDG 405 |                | H/T<br>H/T<br>H/T<br>H/T | 0<br>0<br>0<br>0   |                            |                    |
| 262003<br>CABIN              | PORTABLE FIRE EXTINGUISHER<br>P19            |      |         | C352<br>D-03568232            | MTH 23-May-2019<br>HRS 183.4<br>LDG 151 |                | O/C                      | 21<br>183.4<br>151 |                            |                    |
| 262003<br>COCKPIT            | PORTABLE FIRE EXTINGUISHER<br>P19            |      |         | C352TS<br>D-03568233          | MTH 23-May-2019<br>HRS 183.4<br>LDG 151 |                | O/C                      | 21<br>183.4<br>151 |                            |                    |
| 270001<br>LEFT               | SPEED BRAKE FILTER FITTING                   |      |         | 20666-6-250<br>NSN            | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 270001<br>RIGHT              | SPEED BRAKE FILTER FITTING                   |      |         | 20666-6-250<br>NSN            | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 272001                       | RUDDER BIAS SHUTOFF VALVE                    |      |         | 5307-1<br>1977C               | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 273001                       | CONTROL SHAKER                               |      |         | 201<br>169582-06              | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 273003                       | ACTUATOR MOUNT ASSEMBLY                      |      |         | 011-02490-20<br>1GJ006111     | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 275001                       | SHUTOFF VALVE                                |      |         | 4083-1<br>1434                | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 275002<br>LEFT               | FLAP ACTUATOR<br>9912365-6                   |      |         | 2-8210-2<br>1340              | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 275002<br>RIGHT              | FLAP ACTUATOR<br>9912365-6                   |      |         | 2-8210-2<br>1337              | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 276001<br>LEFT               | SPEED BRAKE ACTUATOR<br>9912375-5            |      |         | 2-8209-2<br>1346              | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 276001<br>RIGHT              | SPEED BRAKE ACTUATOR<br>9912375-5            |      |         | 2-8209-2<br>1348              | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 281001<br>LEFT               | SURGE TANK FLOAT VALVE<br>9912016-2          |      |         | 35C10D<br>6440                | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 281001<br>RIGHT              | SURGE TANK FLOAT VALVE<br>9912016-2          |      |         | 35C10D<br>6531                | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 282001<br>LEFT               | FUEL BOOST PUMP<br>9912553-1                 |      |         | 1C7-23<br>1BP1                | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |
| 282001<br>RIGHT              | FUEL BOOST PUMP<br>9912553-1                 |      |         | 1C7-23<br>1BP10               | MTH 07-Sep-2017                         |                | O/C                      | 0                  |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code               | Description                                | Part Number             | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-------------------------|--------------------------------------------|-------------------------|-----------------|--------|-------|-------|-------------|---------|
| Position                | Drawing # / Task # City Mod Lvl            | Part Serial No          | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 282002<br>LEFT AFT      | EJECTOR FUEL AFT/SCAVENG PUMP<br>9912190-3 | RG45880<br>B4848        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282002<br>LEFT FORWARD  | EJECTOR FUEL FWD/SCAVENG PUMP<br>9912190-3 | RG45880<br>B4573        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282002<br>RIGHT AFT     | EJECTOR FUEL AFT/SCAVENG PUMP<br>9912190-3 | RG45880<br>B4860        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282002<br>RIGHT FORWARD | EJECTOR FUEL FWD/SCAVENG PUMP<br>9912190-3 | RG45880<br>B4871        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282004<br>LEFT          | FUEL MOTOR VALVE<br>9912014-3              | AV24B1507<br>AA622422   | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282004<br>RIGHT         | FUEL MOTOR VALVE<br>9912014-3              | AV24B1507<br>AA622441   | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282005<br>LEFT          | EJECTOR FUEL PRIMARY PUMP<br>9912190-2     | RG45310<br>C4294        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282005<br>RIGHT         | EJECTOR FUEL PRIMARY PUMP<br>9912190-2     | RG45310<br>C4312        | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 282006                  | TRANSFER VALVE<br>9914103-6                | ZSV57<br>17-050214      | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284001<br>LEFT          | #5 UL005 FUEL PROBE                        | 10664T06Y00<br>MN42263  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284001<br>RIGHT         | #5 UR005 FUEL PROBE                        | 10664T06Y00<br>MN41983  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284002<br>LEFT          | #6 UL006 FUEL PROBE<br>9912589-6           | 10664T06Y00<br>MN39285  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284002<br>RIGHT         | #6 UR006 FUEL PROBE<br>9912589-6           | 10664T06Y00<br>MN39286  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284003                  | FUEL QTY SIGNAL CONDITIONER<br>9912619-1   | 10713B01Y01<br>17030604 | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284004<br>LEFT          | #3 UL003 FUEL PROBE<br>9912589-3           | 10664T03Y00<br>MN42147  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284004<br>RIGHT         | #3 UR003 FUEL PROBE<br>9912589-3           | 10664T03Y00<br>MN38986  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284005<br>LEFT          | #4 UL004 FUEL PROBE<br>9912589-4           | 10664T04Y00<br>MN40731  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284005<br>RIGHT         | #4 UR004 FUEL PROBE<br>9912589-4           | 10664T04Y00<br>MN38991  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284006<br>LEFT          | #2 UL002 FUEL PROBE<br>9912589-2           | 10664T02Y00<br>MN42350  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284006<br>RIGHT         | #2 UR002 FUEL PROBE<br>9912589-2           | 10664T02Y00<br>MN40605  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284007<br>LEFT          | #1 UL001 FUEL PROBE<br>9912589-1           | 10664T01Y00<br>MN42397  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284007<br>RIGHT         | #1 UR001 FUEL PROBE<br>9912589-1           | 10664T01Y00<br>MN42401  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284008<br>LEFT          | FUEL LOW LEVEL SWITCH<br>3465              | L16H-14<br>3465         | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284008<br>RIGHT         | FUEL LOW LEVEL SWITCH<br>3469              | L16H-14<br>3469         | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284010<br>LEFT          | FUEL QUANTITY TRANSMITTER<br>9912556-6     | 10634T11Y00<br>MN42460  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 284010<br>RIGHT         | FUEL QUANTITY TRANSMITTER<br>9912556-6     | 10634T11Y00<br>MN42463  | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 291002<br>LEFT          | HYDRAULIC PUMP<br>9912062-8                | 4120-046000<br>0705B    | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 291002<br>RIGHT         | HYDRAULIC PUMP<br>9912062-8                | 4120-046000<br>0704B    | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |
| 291005                  | HYDRAULIC RESERVOIR ASSEMBLY               | 6317500-16-1<br>399     | MTH 07-Sep-2017 |        | O/C   | 0     |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code       | Description                                     | Part Number              | C/W Time 1                             | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-----------------|-------------------------------------------------|--------------------------|----------------------------------------|--------|-------|-------------|-------------|---------|
| Position        | Drawing # / Task #                              | Part Serial No           | C/W Time 2                             | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 291006          | LOADING VALVE<br>9912423-39                     | 4134-4<br>1938           | MTH 22-May-2018<br>HRS 104.3<br>LDG 93 |        | O/C   | 0<br>0<br>0 |             |         |
| 291007          | PRESSURE SWITCH GAUGE<br>9912373-6              | GPP1250-301<br>1648959   | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291008          | HYD MANIFOLD ASSEMBLY<br>9912423-48             | 8250-3<br>1024           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291009          | RELIEF VALVE                                    | 2R4120<br>NSN            | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291010<br>LEFT  | SHUTOFF VALVE<br>9912400-4                      | AV24B1388-2<br>AA625242  | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291010<br>RIGHT | SHUTOFF VALVE<br>9912400-4                      | AV24B1388-2<br>AA627569  | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291011<br>LEFT  | FLOW SWITCH VALVE<br>9912194-5                  | V10F75<br>2295A          | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291011<br>RIGHT | FLOW SWITCH VALVE<br>9912194-5                  | V10F75<br>2299A          | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291012          | SPDBK DUMP VALVE<br>9912423-33                  | 4082-6<br>1464           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291013          | RELIEF, SYSTEM VALVE<br>9912423-46              | 2576-2<br>1739A          | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291014          | VALVE-GEAR<br>9912423-44                        | 4051-4<br>1426           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291016<br>LEFT  | SPDBK CHECK VALVE<br>9912423-31                 | 9505-1<br>2901           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291016<br>RIGHT | SPDBK CHECK VALVE<br>9912423-31                 | 9505-1<br>2902           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291017          | THERM REL VALVE<br>9912423-32                   | 2577-1<br>1467           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291018          | PNEUMATIC DUMP VALVE<br>9912423-34              | 9503-2<br>1473           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291020          | SPEED BRAKE VALVE<br>9912423-30                 | 4052-3<br>1495           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291021          | FLAP VALVE<br>9912423-29                        | 4052-4<br>1522           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291022          | CHECK VALVE                                     | CV02-193<br>NSN          | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 291023          | GEAR VALVE SOLENOID                             | 4051-4<br>NSN            | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301002<br>LEFT  | PRESSURE SWITCH                                 | 1106P55-1<br>11458A      | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301002<br>RIGHT | PRESSURE SWITCH                                 | 1106P55-1<br>11448A      | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301003<br>LEFT  | ANTI-ICE PRESSURE REGULATING VALVE<br>9914710-3 | 1H148-1<br>5BP22         | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301003<br>RIGHT | ANTI-ICE PRESSURE REGULATING VALVE<br>9914710-3 | 1H148-1<br>5BP23         | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301004<br>LEFT  | TEMPERATURE SWITCH                              | 1050C<br>N5188           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301004<br>RIGHT | TEMPERATURE SWITCH                              | 1050C<br>N3246           | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301006<br>LEFT  | HORIZONTAL STAB BOOT                            | 29S-4D5244-15<br>NDX8710 | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |
| 301006<br>RIGHT | HORIZONTAL STAB BOOT                            | 29S-4D5244-16<br>NDX5570 | MTH 07-Sep-2017                        |        | O/C   | 0           |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 301007                | ENG BLEED SHUTOFF VALVE<br>9914552-2  |      |         | 2602-43<br>759                | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 302001<br>LEFT        | PRESS REG VALVE                       |      |         | 5285-00-3<br>3524             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 302001<br>RIGHT       | PRESS REG VALVE                       |      |         | 5285-00-3<br>3522             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 302002<br>LEFT        | INLET TEMP SWITCH                     |      |         | 1173T0759<br>7869             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 302002<br>RIGHT       | INLET TEMP SWITCH                     |      |         | 1173T0759<br>7874             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 303002<br>LEFT        | PITOT TUBE                            |      |         | PH1100-1-VBW<br>AS03179717    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 303002<br>RIGHT       | PITOT TUBE                            |      |         | PH1100-1-VBW<br>AS03179911    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 303003<br>STANDBY     | PITOT TUBE<br>S2800-493               |      |         | PH1100-RW-RIGHT<br>AS02178880 | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304001                | B/A TEMP MONITOR-                     |      |         | 1169-1<br>4945                | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304002                | HEAT EXCHANGER<br>9912041-3           |      |         | 10653A<br>2517                | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304003                | PRESS REG VALVE<br>9912402-14         |      |         | 1962-00-3<br>6096             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304004<br>AFT         | FLOORBD TF006 SENSOR<br>9912085-3     |      |         | 27221274<br>5BP129            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304004<br>FORWARD     | T/C TT002 SENSOR<br>9912085-3         |      |         | 27221274<br>1BP33             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304005                | TEMP CONTROLLER<br>9912085-6          |      |         | 1E58-1<br>3BP9                | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304006                | TEMP CONTROL VALVE<br>9912085-1       |      |         | 27241287<br>5BP29P            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304007                | ALCOHOL PUMP                          |      |         | 40279N<br>NSN                 | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304009                | PRESSURE SWITCH                       |      |         | 1115P25<br>5460AB             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 1       | UC038 CURRENT SENSOR                  |      |         | 76250-6<br>12940              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 2       | UC039 CURRENT SENSOR                  |      |         | 76250-6<br>13835              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 3       | UC040 CURRENT SENSOR                  |      |         | 76552-1<br>11341              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 4       | UC041 CURRENT SENSOR                  |      |         | 76552-1<br>11392              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 5       | UC042 CURRENT SENSOR                  |      |         | 76552-1<br>11470              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304010<br>NO. 6       | UC043 CURRENT SENSOR                  |      |         | 76250-6<br>13867              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304011<br>LEFT        | SOLENOID DEICE VALVE                  |      |         | 3D2353-06<br>N170460          | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304011<br>RIGHT       | SOLENOID DEICE VALVE                  |      |         | 3D2353-06<br>N170480          | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304012<br>LEFT        | WINDSHIELD BLEED AIR CONTROL ASSEMBLY |      |         | 16-0550-28<br>6039            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 304012<br>RIGHT       | WINDSHIELD BLEED AIR CONTROL ASSEMBLY |      |         | 16-0550-27<br>6033            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 313001                | FLIGHT HOURMETER<br>85071                          | KIWA |         | C664503-0104<br>NSN           | MTH 28-Sep-2018<br>HRS 135.3<br>LDG 108 |                | O/C            | 0<br>70.2<br>0 |                            |                    |
| 313500                | ARES RECORDER UNIT ASSEMBLY<br>KHND                |      |         | 6918236-20<br>1759            | MTH 22-Oct-2019<br>HRS 221.1<br>LDG 178 |                | O/C            |                |                            |                    |
| 32-10-00-960          | LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD   |      |         | 6341321-5<br>26574524         | MTH 07-Sep-2017<br>LDG 0                |                |                | 0<br>0         |                            |                    |
| 32-10-00-960          | RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD  |      |         | 6341321-6<br>26580536         | MTH 07-Sep-2017<br>LDG 0                |                | 15000          | 0<br>0         | 15000                      | 14595              |
| 32-10-00-961          | LEFT TRAILING LINK AND AXLE ASSEMBLY DISCARD       |      |         | 6341341-3<br>26500743         | MTH 07-Sep-2017<br>LDG 0                |                | 15000          | 0<br>0         | 15000                      | 14595              |
| 32-10-00-961          | RIGHT TRAILING LINK AND AXLE ASSEMBLY DISCARD      |      |         | 6341341-4<br>26500753         | MTH 07-Sep-2017<br>LDG 0                |                | 15000          | 0<br>0         | 15000                      | 14595              |
| 32-10-00-962          | LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD       |      |         | 6341301-16<br>26580487        | MTH 07-Sep-2017<br>LDG 0                |                | 15000          | 0<br>0         | 15000                      | 14595              |
| 32-10-00-962          | RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD      |      |         | 6341301-16<br>26580489        | MTH 07-Sep-2017<br>LDG 0                |                | 15000          | 0<br>0         | 15000                      | 14595              |
| 32-20-00-960          | NOSE LANDING GEAR STRUT ASSEMBLY DISCARD           |      |         | 6342350-8<br>26774312         | MTH 07-Sep-2017<br>LDG 0                |                | 22500          | 0<br>0         | 22500                      | 22095              |
| 32-20-00-961          | NOSE LANDING GEAR FORK AND PISTON ASSEMBLY DISCARD |      |         | 6342350-4<br>26774312         | MTH 07-Sep-2017<br>LDG 0                |                | 12500          | 0<br>0         | 12500                      | 12095              |
| 32-31-01-960          | NOSE LANDING GEAR ACTUATOR ASSEMBLY DISCARD        |      |         | 1541900-7<br>2319             | MTH 07-Sep-2017<br>LDG 0                |                | 7500           | 0<br>0         | 7500                       | 7095               |
| 32-31-02-960          | LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD   |      |         | 2-8207-2<br>1037              | MTH 07-Sep-2017<br>LDG 0                |                | 12000          | 0<br>0         | 12000                      | 11595              |
| 32-31-02-960          | RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD  |      |         | 2-8207-2<br>1038              | MTH 07-Sep-2017<br>LDG 0                |                | 12000          | 0<br>0         | 12000                      | 11595              |
| 321001                | MAIN LANDING GEAR<br>LEFT                          |      |         | 6341350-5<br>26517797         | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 321001                | MAIN LANDING GEAR<br>RIGHT                         |      |         | 6341350-6<br>26464168C        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 321011                | ANTISKID CONTROL VALVE<br>9912621-3                |      |         | 39-913<br>602                 | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 322001                | SHIMMY DAMPER<br>NOSE LANDING GEAR                 | KHND |         | 6343001-10<br>62-9X           | MTH 23-Oct-2020<br>HRS 278<br>LDG 231   |                | O/C            | 1<br>0<br>0    |                            |                    |
| 322002                | NOSE LANDING GEAR ASSEMBLY                         |      |         | 6342350-9<br>NSN              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 322003                | NLG FORK                                           |      |         | 5542300-1<br>NSN              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323002                | UPLOCK MAIN GEAR<br>LEFT                           |      |         | 6327504-6<br>4101             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323002                | UPLOCK MAIN GEAR<br>RIGHT                          |      |         | 6327504-6<br>4098             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position                | Description<br>Drawing # / Task #               | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------|-------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 323005                               | NOSE LANDING GEAR UPLOCK ACTUATOR               |      |         | 6327504-7<br>1939             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323006                               | HYD SHUTTLE VALVE                               |      |         | 98312<br>3119A                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323007<br>NO.1                       | SHUTTLE, REGEN VALVE<br>9914689-2               |      |         | 5128-6<br>1007                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323007<br>NO.2                       | SHUTTLE, REGEN VALVE<br>9914689-2               |      |         | 5128-6<br>1006                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 323020                               | EMERGENCY PNEUMATIC STORAGE BOTTLE<br>9912368-2 | KSDL |         | 40005320-2<br>4146            | MTH 26-Jan-2023<br>HRS 495.8<br>LDG 387 |                | 288            | 2              | 31-May-2028                | 60 m 13 d          |
| Manufacture Date: 01-May-2004        |                                                 |      |         |                               |                                         |                |                |                |                            |                    |
| 323021                               | EMER GEAR BOTTLE GAUGE                          |      |         | 19940932-1<br>64686           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324001<br>LEFT MAIN<br>LANDING GEAR  | WHEEL ASSEMBLY<br>9912561-5                     |      |         | 3-1607-1<br>T0034             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324001<br>RIGHT MAIN<br>LANDING GEAR | WHEEL ASSEMBLY<br>9912561-5                     |      |         | 3-1607-1<br>T0029             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324002<br>NOSE LANDING<br>GEAR       | WHEEL ASSEMBLY<br>9914069-4                     |      |         | 3-1418OPT-4<br>T0026          | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324003<br>LEFT MAIN<br>LANDING GEAR  | TIRE<br>9912622-1                               | KIWA |         | 026-618-0<br>1224P00090       | MTH 02-Jan-2022<br>HRS 394.9<br>LDG 322 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 324003<br>RIGHT MAIN<br>LANDING GEAR | TIRE<br>9912622-1                               | KIWA |         | 026-618-0<br>1228P00143       | MTH 02-Jan-2022<br>HRS 394.9<br>LDG 322 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 324004<br>NOSE LANDING<br>GEAR       | TIRE<br>9914070-1                               | KIWA |         | 031-613-8<br>9044S00355       | MTH 27-Sep-2019<br>HRS 218.4<br>LDG 174 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 324005<br>LEFT MAIN<br>LANDING GEAR  | BRAKE ASSEMBLY<br>9912617-2                     |      |         | 2-1695<br>1211                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324005<br>RIGHT MAIN<br>LANDING GEAR | BRAKE ASSEMBLY<br>9912617-2                     |      |         | 2-1695<br>1192                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324101                               | BRK ANTISKID/METERING VALVE<br>9912621-2        |      |         | 32-107-1<br>602               | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324102<br>LEFT                       | ANTISKID TRANSDUCER<br>9912305-2                |      |         | 40-955<br>10854               | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324102<br>RIGHT                      | ANTISKID TRANSDUCER<br>9912305-2                |      |         | 40-955<br>10913               | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324103                               | DIG ANTISKID CNTRL BOX<br>9912621-1             |      |         | 142-103<br>601B*              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324104                               | BRAKE PRESSURE SWITCH                           |      |         | GPP1250-69<br>1719801         | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324105                               | PARKING BRAKE VALVE<br>9912388-1                |      |         | 95853<br>2026A                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324106                               | HYDRAULIC PUMP MOTOR                            |      |         | MP50B1<br>5218                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324107                               | BRAKE ANTISKID ACCUMULATOR<br>9912644-2         | *CF  |         | 7550-2<br>1557                | MTH 06-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324108                               | LOW PRESSURE SWITCH                             |      |         | GPP1250-79<br>1650813         | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 324109                | BRAKE PRESSURE PUMP<br>9912364-2                                                                          |      |         | 640929<br>3245A               | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324110                | EMERGENCY BRAKE VALVE<br>9912387-5                                                                        |      |         | 878208-05<br>V644             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324113                | THERMAL RELIEF VALVE                                                                                      |      |         | 1785-3<br>793                 | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 324204                | BRAKE HYDRAULIC PACK ASSEMBLY FILTER ELEMENT DISCARD (REPLACE)<br>TASK# 32-42-05-960                      | KIWA |         | 9912372-1<br>SN-UNKNOWN       | MTH 01-Oct-2020<br>HRS 261.3<br>LDG 212 |                | 36<br>1200     | 0<br>0         | 31-Oct-2023<br>1461.3      | 5 m 13 d<br>937.2  |
| 324205                | BRAKE RESERVOIR AIR FILTER AND BRAKE RESERVOIR SUPPLY LINE FILTER DISCARD (REPLACE)<br>TASK# 32-42-04-960 | KIWA |         | AN6237-1<br>SN-UNKNOWN        | MTH 01-Oct-2020<br>HRS 261.3<br>LDG 212 |                | 36<br>1200     | 0<br>0         | 31-Oct-2023<br>1461.3      | 5 m 13 d<br>937.2  |
| 326001<br>LEFT        | MLG UPLOCK SWITCH                                                                                         |      |         | 65-430087<br>NSN              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 326001<br>NOSE        | NLG UPLOCK SWITCH                                                                                         |      |         | 65-430087<br>NSN              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 326001<br>RIGHT       | MLG UPLOCK SWITCH                                                                                         |      |         | 65-430087<br>NSN              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 331001                | LIGHT UB001 DIMMER                                                                                        |      |         | 273-1<br>230                  | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 331003                | INDIRECT LIGHTING CONTROL BOX                                                                             |      |         | CLC500-01<br>5895             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 331004                | MULTI-FUNCTION MODULE ASSEMBLY                                                                            |      |         | 9118009-4<br>587              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334001                | GROUND REC LIGHT<br>9912679-4                                                                             |      |         | 84003-3<br>882                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334004<br>LEFT        | LANDING LAMP HOUSING<br>KIWA                                                                              |      |         | LDL100-02<br>206000463        | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | O/C            |                |                            |                    |
| 334004<br>RIGHT       | LANDING LAMP HOUSING<br>KIWA                                                                              |      |         | LDL100-02<br>206002085        | MTH 27-Sep-2019<br>HRS 218.4<br>LDG 174 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 334005<br>LEFT        | ANTI-COLLISION LIGHT ASSEMBLY                                                                             |      |         | 84056-1<br>503                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334005<br>RIGHT       | ANTI-COLLISION LIGHT ASSEMBLY                                                                             |      |         | 84056-2<br>523                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334006<br>LEFT        | FLOOD TAIL LIGHT ASSEMBLY                                                                                 |      |         | TIL100-02<br>207001550        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334006<br>RIGHT       | FLOOD TAIL LIGHT ASSEMBLY                                                                                 |      |         | TIL100-02<br>207001555        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 334007                | TAIL LIGHT ASSEMBLY                                                                                       |      |         | 01-0770966-00<br>06072A       | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 335000<br>LEFT        | AFT LEFT EMERGENCY LIGHTING BATTERY PACK<br>KSDL                                                          |      |         | CBS28-1<br>008117             | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | O/C            |                |                            |                    |
| 335000<br>RIGHT       | FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK<br>KSDL                                                     |      |         | CBS28-1<br>7134M              | MTH 28-Oct-2022<br>HRS 478.6<br>LDG 374 |                | O/C            |                |                            |                    |
| 335001                | EMERGENCY LIGHTS FWD 2G SWITCH                                                                            |      |         | 7212-2-000<br>1736            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 341001<br>NO. 1       | AIR DATA COMPUTER<br>GDC7400                                                                              |      |         | 011-02337-01<br>146101624     | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                               | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2     | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|--------------------|----------------------------|--------------------|
| 341001<br>NO. 2       | AIR DATA COMPUTER<br>GDC7400                                    |      |         | 011-02337-01<br>146101614     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341004                | AOA COMPUTER                                                    |      |         | C-13406-1<br>1695611-04       | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341007                | AOA SENSOR                                                      |      |         | C-12717-1<br>170256-03        | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341008                | BAROMETRIC SWITCH                                               |      |         | GBC300-82<br>1719956          | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341010<br>AFT         | RADIO ALT ANTENNA                                               |      |         | S67-2002<br>543-87909         | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341010<br>FORWARD     | RADIO ALT ANTENNA                                               |      |         | S67-2002<br>543-87915         | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341030                | TEMP PROBE SENSOR                                               |      |         | 0129G<br>B44048               | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 341034                | RADIO ALT TRANSMITTER<br>ALT-4000                               |      |         | 822-0615-206<br>4C57F0        | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342002<br>LEFT        | AHRS COMPUTER<br>S3100-511                                      | KIWA |         | 011-00868-10<br>42035788      | MTH 02-Jul-2021<br>HRS 346.9<br>LDG 284 |                | O/C            | 46<br>346.9<br>284 |                            |                    |
| 342002<br>RIGHT       | AHRS COMPUTER<br>S3100-511                                      | KIWA |         | 011-00868-10<br>42035786      | MTH 02-Jul-2021<br>HRS 346.9<br>LDG 284 |                | O/C            | 46<br>346.9<br>284 |                            |                    |
| 342013<br>LEFT        | CTC 570 CONTROLLER<br>GTC 570                                   |      |         | 011-01924-10<br>1MB506911     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342013<br>RIGHT       | CTC 570 CONTROLLER<br>GTC 570                                   |      |         | 011-01924-10<br>1MB506929     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342031                | STANDBY GYRO POWER SUPPLY<br>PS-855A                            |      |         | 501-1712-01<br>81968          | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342034<br>LEFT        | GEA 71 ENGINE AND AIRFRAME IO UNIT<br>KHND                      |      |         | 11-00831-05<br>1Z1006532      | MTH 22-Oct-2019<br>HRS 221.1<br>LDG 178 |                | O/C            |                    |                            |                    |
| 342034<br>RIGHT       | GEA 71 ENGINE AND AIRFRAME IO UNIT<br>KHND                      |      |         | 11-00831-05<br>1Z1006703      | MTH 22-Oct-2019<br>HRS 221.1<br>LDG 178 |                | O/C            |                    |                            |                    |
| 342036<br>CENTER      | GDU 1400 DISPLAY<br>GDU1400                                     |      |         | 011-01910-00<br>1F1005845     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342036<br>LEFT        | GDU 1400 DISPLAY<br>GDU1400                                     |      |         | 011-01910-00<br>1F1005847     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342036<br>RIGHT       | GDU 1400 DISPLAY<br>GDU1400                                     |      |         | 011-01910-00<br>1F1005549     | MTH 07-Sep-2017                         |                | O/C            | 0                  |                            |                    |
| 342037                | WEATHER RADAR<br>GWX70                                          | KIWA |         | 011-01768-00<br>1DP005083     | MTH 03-Nov-2017<br>HRS 39.9<br>LDG 32   |                | O/C            | 0<br>0<br>0        |                            |                    |
| 342038<br>LEFT        | GIA INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT<br>GIA 63W | KHND |         | 011-01105-40<br>2DC003422     | MTH 05-Jul-2018<br>HRS 115.4<br>LDG 99  |                | O/C            |                    |                            |                    |
| 342038<br>RIGHT       | GIA INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT<br>GIA 63W | KHND |         | 011-01105-40<br>2DC003429     | MTH 05-Jul-2018<br>HRS 115.4<br>LDG 99  |                | O/C            |                    |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #                 | City | Mod Lvl | Part Number<br>Part Serial No         | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------------------|------|---------|---------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 342055<br>LEFT        | DATA CONCENTRATOR UNIT<br>GSD41                   |      |         | 011-01457-01<br>2JH006310             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342055<br>RIGHT       | DATA CONCENTRATOR UNIT<br>GSD41                   |      |         | 011-01457-01<br>2JH006313             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342059<br>NO. 1       | GSR 56 IRRIDIUM TRANSCEIVER<br>GSR 56             |      |         | 011-02268-01<br>2H4005813             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342082                | ELECTRONIC STANDBY (4 IN 1) INDICATOR<br>ESI-1000 |      |         | 9200-32100-0201<br>3384               | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342305                | AFCS MODE CONTROLLER<br>GMC710                    |      |         | 011-01020-10<br>22008348              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342801<br>LEFT        | MAGNET OMETER --<br>GMU44                         |      |         | 011-00870-10<br>1CM020501             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 342801<br>RIGHT       | MAGNET OMETER --<br>GMU44                         |      |         | 011-00870-10<br>1CM020504             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 343001                | MARKER BEACON ANTENNA                             |      |         | MB10-754<br>2320                      | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 343003                | GLIDESLOPE ANTENNA                                |      |         | RGS10-48<br>19260                     | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 343004                | ANTENNA GLIDESLOPE COUPLER                        |      |         | DGSC20-02<br>7616                     | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 344002                | WEATHER RADAR REC/XMTR ANTENNA                    |      |         | 117-00254-01<br>2013                  | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 344011                | STORMSCOPE PROCESSOR<br>WX-1000E *CF              |      |         | 78-8060-6086-5<br>82491               | MTH 06-Sep-2017          |                | O/C            |                |                            |                    |
| 344012                | STORMSCOPE ANTENNA<br>WX-1000E *CF                |      |         | 78-8051-9200-8<br>84232               | MTH 06-Sep-2017          |                | O/C            |                |                            |                    |
| 344017<br>1           | GPS XM ANTENNA<br>9154079-85                      |      |         | CI428-410<br>542852                   | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 344017<br>2           | GPS XM ANTENNA<br>9154079-85                      |      |         | CI428-410<br>540467                   | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 344019                | SATELLITE DATA LINK TRANSCEIVER                   |      |         | 011-00987-00<br>47769720              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 344401                | FLIGHT PARAMETER RECORDER AND WI-FI               |      |         | DATALINK<br>011-01746-00<br>1EJ006092 | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345001<br>NO.1        | FORWARD DME ANTENNA                               |      |         | L10-611-14<br>9774                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345002<br>NO.1        | LEFT DME TRANSCEIVER<br>DME-4000                  |      |         | 822-1466-001<br>4TF1N                 | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345005<br>LEFT        | NAVIGATION ANTENNA                                |      |         | VT10-767-3<br>1902                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345005<br>RIGHT       | NAVIGATION ANTENNA                                |      |         | VT10-767-3<br>SN-UNKNOWN              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345040<br>LEFT        | DIVERSITY TRANSPONDER ANTENNA                     |      |         | L10-611-14<br>9800                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345040<br>NO.1        | TRANSPONDER ANTENNA                               |      |         | L10-611-14<br>9776                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345040<br>NO.2        | TRANSPONDER ANTENNA                               |      |         | L10-611-14<br>9804                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345040<br>RIGHT       | DIVERSITY TRANSPONDER ANTENNA                     |      |         | L10-611-14<br>9792                    | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345041<br>NO. 1       | TRANSPONDER<br>GTX3000                            |      |         | 011-01997-00<br>20S008039             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345041<br>NO. 2       | TRANSPONDER<br>GTX3000                            |      |         | 011-01997-00<br>20S008010             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 345051                | IRIDIUM/GPS PASSIVE ANTENNA<br>IRIDIUM            |      |         | S67-1575-165<br>449-8626              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position         | Description<br>Drawing # / Task #       | City | Mod Lvl | Part Number<br>Part Serial No          | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------|-----------------------------------------|------|---------|----------------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 345061                        | TCAS PROCESSOR<br>GTS                   |      |         | 011-02571-00<br>28P007004              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 345062<br>BOTTOM              | TCAS II ANTENNA                         |      |         | S72-1735-26<br>874-1152                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 345062<br>TOP                 | TCAS II ANTENNA                         |      |         | S72-1735-26<br>874-1151                | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 345069                        | DUAL VOR COUPLER                        |      |         | DRC20-35-5<br>1901                     | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 346102<br>LEFT                | PFD CONTROLER<br>GCU 275                |      |         | 011-01983-01<br>147106544              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 346102<br>RIGHT               | PFD CONTROLLER<br>GCU 275               |      |         | 011-01983-01<br>147106545              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 350005                        | OXYGEN REGULATOR                        |      |         | 172234-02<br>3851                      | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 350006                        | OXYGEN CYLINDER<br>DOT E-10945          | KSDL |         | 176276-50<br>837741002                 | MTH 07-Mar-2022<br>HRS 408.6<br>LDG 329 |                | 180            | 62             | 31-Jan-2032                | 104 m 13 d         |
| Manufacture Date: 01-Jan-2017 |                                         |      |         |                                        |                                         |                |                |                |                            |                    |
| 350007                        | OXYGEN PRESSURE GAGE                    |      |         | P24140<br>508                          | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 351001                        | OXYGEN CONTROL VALVE                    |      |         | P21007<br>2878                         | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 351002<br>COPILOT             | OXYGEN MASK<br>9914771-1                | ICT  |         | 174252-96<br>42119                     | MTH 21-Aug-2017                         |                | O/C            | 4              |                            |                    |
| 351002<br>PILOT               | OXYGEN MASK<br>9914771-1                | KIWA |         | 174252-96<br>46946                     | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 351004                        | OXYGEN PRESSURE TRANSDUCER<br>S2800-902 |      |         | APT-389-1000-<br>2400SG<br>8373-10-693 | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361001<br>LEFT                | PRECOOL TEMP SENSOR<br>9912584-3        |      |         | 27431501-10<br>5BP64                   | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361001<br>RIGHT               | PRECOOL TEMP SENSOR<br>9912584-3        |      |         | 27431501-10<br>5BP25                   | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361002<br>LEFT                | B/A PRECOOLER ASSEMBLY<br>9912624-10    |      |         | 8292-1<br>T1302                        | MTH 07-Sep-2017<br>HRS 0                |                | 3200           | 0              | 3200                       | 2675.9             |
| 361002<br>RIGHT               | B/A PRECOOLER ASSEMBLY<br>9912624-1     |      |         | 8292-1<br>T1305                        | MTH 07-Sep-2017<br>HRS 0                |                | 3200           | 0              | 3200                       | 2675.9             |
| 361003<br>LEFT                | MODULATING VALVE<br>9912584-1           |      |         | 1H139-1<br>11BK87                      | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361003<br>RIGHT               | MODULATING VALVE<br>9912584-2           |      |         | 1H139-2<br>4BP23                       | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361005                        | PRESSURE SWITCH                         |      |         | P18M30<br>6074                         | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361006<br>LEFT                | OVERTEMP SWITCH<br>9914149-2            |      |         | 1173T181-2<br>8247                     | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361006<br>RIGHT               | OVERTEMP SWITCH<br>9914149-2            |      |         | 1173T181-2<br>8249                     | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 361007                        | B/A PRESSURE REGULATOR<br>9912510-1     |      |         | 1H75-18<br>1BP4                        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 383001                        | TOILET ASSY-FLUSHING --<br>ICT          |      |         | 17010-042<br>1564                      | MTH 21-Aug-2017                         |                | O/C            | 0              |                            |                    |
| 442000                        | WIRELESS MEDIA SERVER<br>KIWA           |      |         | DMS650-01<br>587000019                 | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |                | O/C            |                |                            |                    |
| 522001                        | INFLATABLE DOOR SEAL<br>9912075-4       |      |         | S15501-4<br>NSN                        | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position                            | Description<br>Drawing # / Task # City Mod Lvl                                       | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 53-00-00-960<br>NOSE LANDING<br>GEAR             | NOSE LANDING GEAR ACTUATOR FITTING DISCARD<br>6511105-1<br>NSN                       | MTH 07-Sep-2017<br>LDG 0      |                          |                | 23900          | 0              | 23900                      | 23495              |
| 53-00-00-961<br>LEFT NOSE<br>LANDING GEAR        | LEFT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD<br>5513056-7<br>NSN          | MTH 07-Sep-2017<br>LDG 0      |                          |                | 12000          | 0              | 12000                      | 11595              |
| 53-00-00-961<br>RIGHT NOSE<br>LANDING GEAR       | RIGHT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD<br>5513056-8<br>NSN         | MTH 07-Sep-2017<br>LDG 0      |                          |                | 12000          | 0              | 12000                      | 11595              |
| 530000                                           | RADOME ASSEMBLY<br>6313101-47<br>NSN                                                 | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561001<br>LEFT                                   | LEFT WINDSHIELD ASSEMBLY<br>9912064-15                                               | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561001<br>RIGHT                                  | RIGHT WINDSHIELD ASSEMBLY<br>9912064-16                                              | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>CABIN DOOR                             | WINDOW<br>9912207-8                                                                  | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 2                             | CABIN WINDOW<br>6311323-9<br>1637                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 3                             | CABIN WINDOW<br>6311323-9<br>1662                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 4                             | CABIN WINDOW<br>6311323-9<br>1640                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 5                             | CABIN WINDOW<br>6311323-9<br>1641                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 6                             | CABIN WINDOW<br>6311323-9<br>1660                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>LEFT NO. 7                             | CABIN WINDOW<br>6311323-9<br>1663                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 1                            | CABIN WINDOW<br>6311323-9<br>1654                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 2                            | CABIN WINDOW<br>6311323-9<br>1636                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 3                            | CABIN WINDOW<br>6311323-9<br>1658                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 4                            | CABIN WINDOW<br>6311323-9<br>1639                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 5                            | CABIN WINDOW<br>6311323-9<br>1638                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 6                            | CABIN WINDOW<br>6311323-9<br>1655                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561002<br>RIGHT NO. 7                            | CABIN WINDOW<br>6311323-9<br>1661                                                    | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561003<br>COPILOT                                | SIDE WINDOW<br>6311263-2<br>3966                                                     | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 561003<br>PILOT                                  | SIDE WINDOW<br>6311263-1<br>3965                                                     | MTH 07-Sep-2017               |                          |                | O/C            | 0              |                            |                    |
| 57-00-00-960<br>LEFT MAIN GEAR                   | LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD<br>6341324-1<br>ATE-0131  | MTH 07-Sep-2017<br>LDG 0      |                          |                | 15000          | 0              | 15000                      | 14595              |
| 57-00-00-960<br>RIGHT MAIN GEAR                  | RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD<br>6341324-2<br>ATE-0122 | MTH 07-Sep-2017<br>LDG 0      |                          |                | 15000          | 0              | 15000                      | 14595              |
| 57-00-00-961<br>LEFT MAIN<br>LANDING GEAR<br>AFT | LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD<br>6341326-5<br>ATE-0121         | MTH 07-Sep-2017<br>LDG 0      |                          |                | 12000          | 0              | 12000                      | 11595              |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                        | City | Mod Lvl | Part Number<br>Part Serial No      | C/W Time 1<br>C/W Time 2  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|----------------------------------------------------------|------|---------|------------------------------------|---------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 57-00-00-961<br>LEFT MAIN<br>LANDING GEAR<br>FORWARD  | LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD  |      |         | 6341325-1<br>ATE-0121              | MTH 07-Sep-2017<br>LDG 0  |                | 12000          | 0              | 12000                      | 11595              |
| 57-00-00-961<br>RIGHT MAIN<br>LANDING GEAR<br>AFT     | RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD     |      |         | 6341326-6<br>ATE-0102              | MTH 07-Sep-2017<br>LDG 0  |                | 12000          | 0              | 12000                      | 11595              |
| 57-00-00-961<br>RIGHT MAIN<br>LANDING GEAR<br>FORWARD | RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD |      |         | 6341325-2<br>ATE-0111              | MTH 07-Sep-2017<br>LDG 0  |                | 12000          | 0              | 12000                      | 11595              |
| 712002<br>LEFT ENGINE AFT                             | LEFT ENGINE AFT ISOLATOR MOUNT (OVERHAUL)                |      |         | 9912623-7<br>LM-605-SA11<br>LK3924 | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 712002<br>LEFT ENGINE<br>FORWARD<br>BOTTOM            | LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL)     |      |         | 9912623-6<br>LM-605-SA8<br>LK3149  | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 712002<br>LEFT ENGINE<br>FORWARD TOP                  | LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL)        |      |         | 9912623-6<br>LM-605-SA8<br>LK3150  | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 712002<br>RIGHT ENGINE<br>AFT                         | RIGHT ENGINE AFT ISOLATOR MOUNT (OVERHAUL)               |      |         | 9912623-8<br>LM-605-SA10<br>LK3937 | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 712002<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM           | RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL)    |      |         | 9912623-6<br>LM-605-SA8<br>LK3152  | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 712002<br>RIGHT ENGINE<br>FORWARD TOP                 | RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL)       |      |         | 9912623-6<br>LM-605-SA8<br>LK3151  | MTH 07-Sep-2017<br>HRS 0  |                | 8000           | 0              | 8000                       | 7475.9             |
| 71EN1<br>NO. 1                                        | ENGINE<br>FJ44-3A/9912614-1                              |      |         | 67000-200<br>142027                |                           |                | E/C            |                |                            |                    |
| 71EN2<br>NO. 2                                        | ENGINE<br>FJ44-3A/9912614-1                              |      |         | 67000-200<br>142026                |                           |                | E/C            |                |                            |                    |
| 725503<br>E1                                          | LPT MOD ASSY (-2 CONFIG2, -3) KIT                        |      |         | 111748<br>AU45033                  | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725503<br>E2                                          | LPT MOD ASSY (-2 CONFIG2, -3) KIT                        |      |         | 111748<br>AU45028                  | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720001<br>E1                                          | FAN ROTOR                                                |      |         | 115810<br>HW45371                  | MTH 07-Sep-2017<br>LDG 17 |                | 10000          | 0              | (10000)10017               | 9612               |
| 720001<br>E2                                          | FAN ROTOR                                                |      |         | 115810<br>HW43696                  | MTH 07-Sep-2017<br>LDG 20 |                | 10000          | 0              | (10000)10020               | 9615               |
| 720002<br>E1                                          | IP COMPRESSOR ROTOR                                      |      |         | 115553<br>HW44913                  | MTH 07-Sep-2017<br>LDG 17 |                | 10000          | 0              | (10000)10017               | 9612               |
| 720002<br>E2                                          | IP COMPRESSOR ROTOR                                      |      |         | 115553<br>HW44170                  | MTH 07-Sep-2017<br>LDG 20 |                | 10000          | 0              | (10000)10020               | 9615               |
| 720003<br>E1                                          | COMPLETE LP SHAFT ASSEMBLY                               |      |         | 118440<br>RX17TK1000               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720003<br>E2                                          | COMPLETE LP SHAFT ASSEMBLY                               |      |         | 118440<br>RX17TK1002               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720004<br>E1                                          | HIGH PRESSURE SHAFT                                      |      |         | 118924<br>RX17RT3389               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720004<br>E2                                          | HIGH PRESSURE SHAFT                                      |      |         | 118924<br>RX17RT3383               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720005<br>E1                                          | HP COMPRESSOR COVER                                      |      |         | 69885<br>AU22513                   | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 720005<br>E2                                          | HP COMPRESSOR COVER                                      |      |         | 69885<br>AU22501                   | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # City Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 720006<br>E1          | DIFFUSER CASE ASSEMBLY                         | 117702<br>AU20136             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720006<br>E2          | DIFFUSER CASE ASSEMBLY                         | 117702<br>AU20133             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720007<br>E1          | 1ST STAGE LP TURBINE NOZZLE                    | 122141<br>AU22722             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720007<br>E2          | 1ST STAGE LP TURBINE NOZZLE                    | 122141<br>AU22730             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720008<br>E1          | ACCESS DRIVE GEARBOX                           | 120746<br>MX21624             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720008<br>E2          | ACCESS DRIVE GEARBOX                           | 120746<br>MX21638             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720011<br>E1          | TBC COATED COMBUSTOR ASSY                      | 118731<br>AU20386             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 720011<br>E2          | TBC COATED COMBUSTOR ASSY                      | 118731<br>AU20388             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 722010<br>E1          | IP (STAGE 1 & 2) VANE ASSEMBLY                 | 115569<br>AU21356             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 722010<br>E2          | IP (STAGE 1 & 2) VANE ASSEMBLY                 | 115569<br>AU21357             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723019<br>E1          | INTERSTAGE HOUSING ASSEMBLY                    | 117624<br>AU44439             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723019<br>E2          | INTERSTAGE HOUSING ASSEMBLY                    | 117624<br>AU44438             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723028<br>E1          | BEARING NO.1 HOUSING                           | 67305<br>AU21916              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723028<br>E2          | BEARING NO.1 HOUSING                           | 67305<br>AU21921              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723036<br>E1          | STAGE 3 IP ROTOR STATOR                        | 68067<br>AU21353              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723036<br>E2          | STAGE 3 IP ROTOR STATOR                        | 68067<br>AU21348              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723037<br>E1          | FAN STATOR VANE ASSEMBLY                       | 70563<br>MX20533              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723037<br>E2          | FAN STATOR VANE ASSEMBLY                       | 70563<br>MX20531              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723094<br>E1          | #4 INNER RACE BEARING                          | 79029<br>JT-129200            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723094<br>E2          | #4 INNER RACE BEARING                          | 79029<br>JT-129149            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723096<br>E1          | CASE & INSERT ASSEMBLY                         | 110979<br>FRM10488            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723096<br>E2          | CASE & INSERT ASSEMBLY                         | 110979<br>FRM3233             | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723097<br>E1          | HP SHAFT, FRONT BEARING HOUSING ASSEMBLY       | 56195<br>JDM-01897            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723097<br>E2          | HP SHAFT, FRONT BEARING HOUSING ASSEMBLY       | 56195<br>JDM-01887            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723098<br>E1          | ROLLER-OUTER GDE BEARING ASSEMBLY              | 78301<br>JT-127897            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723098<br>E2          | ROLLER-OUTER GDE BEARING ASSEMBLY              | 78301<br>JT-127864            | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |
| 723099<br>E1          | ROLLER-OUTER GDE BEARING ASSEMBLY              | 78301<br>JT83544              | MTH 07-Sep-2017          |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------|------|---------|-------------------------------|---------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 723099<br>E2          | ROLLER-OUTER GDE BEARING ASSEMBLY        |      |         | 78301<br>JT83545              | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723155<br>E1          | 1ST REDUCTION BEVEL GEAR SUPPORT BEARING |      |         | 118847<br>AU22892             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723155<br>E2          | 1ST REDUCTION BEVEL GEAR SUPPORT BEARING |      |         | 118847<br>AU22888             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723160<br>E1          | DAMPED 1ST REDUCTION BEVEL GEAR          |      |         | 50349<br>BG5960               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723160<br>E2          | DAMPED 1ST REDUCTION BEVEL GEAR          |      |         | 50349<br>BG5964               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723165<br>E1          | DEEP GROOVE-103 BALL BEARING             |      |         | 78321<br>JT-125878            | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723165<br>E2          | DEEP GROOVE-103 BALL BEARING             |      |         | 78321<br>JT-122828            | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723175<br>E1          | SPLIT INNER RING - 104 BALL BEARING      |      |         | 56172<br>MW3409               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 723175<br>E2          | SPLIT INNER RING - 104 BALL BEARING      |      |         | 56172<br>MW3416               | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 724401<br>E1          | DUAL FADEC ENGINE HARNESS ASSEMBLY       |      |         | 125794<br>BW0049              | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 724401<br>E2          | DUAL FADEC ENGINE HARNESS ASSEMBLY       |      |         | 125794<br>BW0050              | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725101<br>E1          | HP COMPRESSOR ROTOR                      |      |         | 122725<br>HW45208             | MTH 07-Sep-2017<br>LDG 17 |                | 10000          | 0              | (10000)10017               | 9612               |
| 725101<br>E2          | HP COMPRESSOR ROTOR                      |      |         | 122725<br>HW45199             | MTH 07-Sep-2017<br>LDG 20 |                | 10000          | 0              | (10000)10020               | 9615               |
| 725102<br>E1          | HP TURBINE ROTOR                         |      |         | 111414<br>HW43033             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725102<br>E2          | HP TURBINE ROTOR                         |      |         | 111414<br>HW43032             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725103<br>E1          | HP TURBINE DISK                          |      |         | 67093<br>HW43033              | MTH 07-Sep-2017<br>LDG 17 |                | 8000           | 0              | (8000)8017                 | 7612               |
| 725103<br>E2          | HP TURBINE DISK                          |      |         | 67093<br>HW43032              | MTH 07-Sep-2017<br>LDG 20 |                | 8000           | 0              | (8000)8020                 | 7615               |
| 725125<br>E1          | AXIAL COMPRESSOR RETAINER NUT            |      |         | 45785<br>AU20770              | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725125<br>E2          | AXIAL COMPRESSOR RETAINER NUT            |      |         | 45785<br>AU20817              | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 725501<br>E1          | 1ST LP TURBINE DISK                      |      |         | 72704<br>HW46147              | MTH 07-Sep-2017<br>LDG 17 |                | 10000          | 0              | (10000)10017               | 9612               |
| 725501<br>E2          | 1ST LP TURBINE DISK                      |      |         | 72704<br>HW45619              | MTH 07-Sep-2017<br>LDG 20 |                | 10000          | 0              | (10000)10020               | 9615               |
| 725502<br>E1          | 2ND LP TURBINE DISK                      |      |         | 66993<br>HW45741              | MTH 07-Sep-2017<br>LDG 17 |                | 10000          | 0              | (10000)10017               | 9612               |
| 725502<br>E2          | 2ND LP TURBINE DISK                      |      |         | 66993<br>HW45742              | MTH 07-Sep-2017<br>LDG 20 |                | 10000          | 0              | (10000)10020               | 9615               |
| 726025<br>E1          | CARBON FACE SEAL ASSEMBLY                |      |         | 57657<br>SBC914B4             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |
| 726025<br>E2          | CARBON FACE SEAL ASSEMBLY                |      |         | 57657<br>SBC898B6             | MTH 07-Sep-2017           |                | O/C            | 0              |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code              | Description                                 | Part Number           | C/W Time 1                              | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|------------------------|---------------------------------------------|-----------------------|-----------------------------------------|--------|-------|-------|-------------|---------|
| Position               | Drawing # / Task # City Mod Lvl             | Part Serial No        | C/W Time 2                              | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 726030<br>E1           | CARBON FACE SEAL ASSEMBLY                   | 68937<br>SBC657B5     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726030<br>E2           | CARBON FACE SEAL ASSEMBLY                   | 68937<br>SBC668B6     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726035<br>E1           | RING SEAL ASSEMBLY                          | 45075<br>SBC774B8     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726035<br>E2           | RING SEAL ASSEMBLY                          | 45075<br>SBC774B9     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726040<br>E1           | RING SEAL ASSEMBLY                          | 45075<br>SBC776B8     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726040<br>E2           | RING SEAL ASSEMBLY                          | 45075<br>SBC777B0     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726045<br>E1           | RING SEAL ASSEMBLY                          | 64771<br>SBC881B6     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 726045<br>E2           | RING SEAL ASSEMBLY                          | 64771<br>SBC878B3     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729902<br>E1           | CARBON RING SEAL & BEARING RETAINER HOUSING | 76881<br>AU20877      | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729902<br>E2           | CARBON RING SEAL & BEARING RETAINER HOUSING | 76881<br>AU20876      | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729904<br>E1           | HP SHAFT SEAL FRONT RUNNER                  | 123497<br>SBC686B1    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729904<br>E2           | HP SHAFT SEAL FRONT RUNNER                  | 123497<br>SBC690B3    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729905<br>E1           | INNER GUIDED ROLLER BEARING                 | 79027<br>JT-128350    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729905<br>E2           | INNER GUIDED ROLLER BEARING                 | 79027<br>JT-128369    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729906<br>E1           | LP SHAFT SEAL FRONT RUNNER                  | 78639<br>SBC847B5     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729906<br>E2           | LP SHAFT SEAL FRONT RUNNER                  | 78639<br>SBC849B0     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729981<br>E1           | TOWER SHAFT                                 | 123069<br>ABK975      | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 729981<br>E2           | TOWER SHAFT                                 | 123069<br>ABK931      | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 730001<br>LEFT ENGINE  | FUEL PRESS SWITCH                           | 1103P0448<br>11372    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 730001<br>RIGHT ENGINE | FUEL PRESS SWITCH                           | 1103P0448<br>11325    | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 732500<br>LEFT ENGINE  | FADEC                                       | 121188<br>CL15AW2917  | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 732500<br>RIGHT ENGINE | FADEC                                       | 121188<br>CL16AW3013  | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 733001<br>LEFT ENGINE  | FUEL FLOW TRANSMITTER                       | 1573-4<br>AAT4041     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 733001<br>RIGHT ENGINE | FUEL FLOW TRANSMITTER                       | 1573-4<br>AAT4032     | MTH 07-Sep-2017                         |        | O/C   | 0     |             |         |
| 730002<br>E1           | FUEL NOZZLE ASSY                            | 50817<br>BCC-00011403 | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |        | O/C   |       |             |         |
| 730002<br>E2           | FUEL NOZZLE ASSY                            | 50817<br>BCC-1AEC2538 | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |        | O/C   |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|-----------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 730003<br>E1          | SEAL AND FUEL SLINGER ASSEMBLY    |      |         | 115471<br>AU201201            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 730003<br>E1 REAR     | SEAL AND FUEL SLINGER ASSEMBLY    |      |         | 115094<br>AU21306             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 730003<br>E2          | SEAL AND FUEL SLINGER ASSEMBLY    |      |         | 115471<br>AU201198            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 730003<br>E2 REAR     | SEAL AND FUEL SLINGER ASSEMBLY    |      |         | 115094<br>AU21371             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 730303<br>E1          | FUEL MANIFOLD ASSEMBLY            |      |         | 120223<br>AU22652             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 730303<br>E2          | FUEL MANIFOLD ASSEMBLY            |      |         | 120223<br>AU22651             | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 732101<br>E1          | FUEL DELIVERY UNIT                |      |         | 119148<br>CL7ATW1241          | MTH 07-Sep-2017<br>HRS 0                |                | 8000           | 0              | (8000)8000                 | 7475.9             |
| 732101<br>E2          | FUEL DELIVERY UNIT                |      |         | 119148<br>CL7ATW1246          | MTH 07-Sep-2017<br>HRS 0                |                | 8000           | 0              | (8000)8000                 | 7475.9             |
| 732301<br>E1          | ELEC FUEL FILTER INDICATOR        |      |         | 57847<br>GE-6224              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 732301<br>E2          | ELEC FUEL FILTER INDICATOR        |      |         | 57847<br>GE-6225              | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741001<br>E1 INBOARD  | IGNITION EXCITER                  |      |         | 68145<br>CK1601621            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741001<br>E1 OUTBOARD | IGNITION EXCITER                  |      |         | 68145<br>CK1601239            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741001<br>E2 INBOARD  | IGNITION EXCITER                  |      |         | 68145<br>CK1601618            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741001<br>E2 OUTBOARD | IGNITION EXCITER                  |      |         | 68145<br>CK1601616            | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741002<br>E1          | SHORT IGNITOR LEAD                |      |         | 50852<br>NSN                  | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741002<br>E2          | SHORT IGNITOR LEAD                |      |         | 50852<br>NSN                  | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741003<br>E1          | LONG IGNITOR LEAD                 |      |         | 50853<br>NSN                  | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741003<br>E2          | LONG IGNITOR LEAD                 |      |         | 50853<br>NSN                  | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 741004<br>E1 INBOARD  | IGNITOR                           | KIWA |         | 68032<br>CK-1800551           | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | O/C            |                |                            |                    |
| 741004<br>E1 OUTBOARD | IGNITOR                           | KIWA |         | 68032<br>CK-1903687           | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | O/C            |                |                            |                    |
| 741004<br>E2 INBOARD  | IGNITOR                           | KIWA |         | 68032<br>CK-0802032           | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | O/C            |                |                            |                    |
| 741004<br>E2 OUTBOARD | IGNITOR                           | KIWA |         | 68032<br>CK-1500727           | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402 |                | O/C            |                |                            |                    |
| 771001<br>E1          | N1 DUAL MAGNETIC SPEED SENSOR     |      |         | 57355<br>MD-0188210           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 771001<br>E2          | N1 DUAL MAGNETIC SPEED SENSOR     |      |         | 57355<br>MD-0187971           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |
| 771002<br>E1          | N2 DUAL MAGNETIC SPEED SENSOR     |      |         | 54831<br>MD-0190116           | MTH 07-Sep-2017                         |                | O/C            | 0              |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0523**  
 Unit: Reg No: **N523HD**  
 Airworthiness: **07-Sep-2017**  
 Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Components

| Item Code<br>Position  | Description<br>Drawing # / Task #   | City | Mod Lvl | Part Number<br>Part Serial No     | C/W Time 1<br>C/W Time 2              | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2   | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-------------------------------------|------|---------|-----------------------------------|---------------------------------------|----------------|----------------|------------------|----------------------------|--------------------|
| 771002<br>E2           | N2 DUAL MAGNETIC SPEED SENSOR       |      |         | 54831<br>MD-0189540               | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 771003<br>E1           | TT2 SENSOR                          |      |         | 114944<br>AXT0201741              | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 771003<br>E2           | TT2 SENSOR                          |      |         | 114944<br>AXT0201756              | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 771005<br>E1           | P2 SENSOR                           |      |         | 113762<br>AXT0101587              | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 771005<br>E2           | P2 SENSOR                           |      |         | 113762<br>AXT0101582              | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 772002<br>E1           | ITT HARNESS ASSEMBLY                |      |         | 75378<br>YYF002072                | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 772002<br>E2           | ITT HARNESS ASSEMBLY                |      |         | 75378<br>YYF003392                | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 793002<br>LEFT ENGINE  | OIL PRESS SWITCH<br>9912178-4       |      |         | S1103P89-3<br>4189                | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 793002<br>RIGHT ENGINE | OIL PRESS SWITCH<br>9912178-4       |      |         | S1103P89-3<br>4174                | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 793003<br>LEFT ENGINE  | OIL PRESS TRANSMITTER<br>S2800-1128 |      |         | APTE-598-1000-200G<br>8448-11-248 | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 793003<br>RIGHT ENGINE | OIL PRESS TRANSMITTER<br>S2800-1128 |      |         | APTE-598-1000-200G<br>8375-8-173  | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 791001<br>E1           | OIL TANK COVER                      |      |         | 54879<br>WL22672                  | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 791001<br>E2           | OIL TANK COVER                      |      |         | 54879<br>WL22712                  | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 792201<br>E1           | LUBE OIL COOLER                     |      |         | 121535<br>PP2253                  | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 792201<br>E2           | LUBE OIL COOLER                     |      |         | 121535<br>PP2252                  | MTH 07-Sep-2017                       |                | O/C            | 0                |                            |                    |
| 792401<br>E1           | LUBE AND SCAVENGE PUMP              |      |         | 125142<br>MX20291                 | MTH 07-Sep-2017<br>HRS 0              |                | 5000           | 0                | (5000)5000                 | 4475.9             |
| 792401<br>E2           | LUBE AND SCAVENGE PUMP              |      |         | 125142<br>MX20289                 | MTH 07-Sep-2017<br>HRS 0              |                | 5000           | 0                | (5000)5000                 | 4475.9             |
| 801101<br>LEFT         | STARTER GENERATOR<br>9912125-2      | KIWA |         | 300SGL129Q<br>7925XL2             | MTH 27-Oct-2017<br>HRS 33.8<br>LDG 30 |                | 1000           | 0                | 1033.8                     | 509.7              |
| 801101<br>RIGHT        | STARTER GENERATOR<br>9912125-2      | KIWA |         | 300SGL129Q<br>500414              | MTH 24-Sep-2017<br>HRS 26.3<br>LDG 17 |                | 1000           | 12<br>26.3<br>17 | 1000                       | 475.9              |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                | Description                                                                                                   | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|--------------------------|---------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position                 | Drawing # / Task #                                                                                            | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SL CIL-99-03 R01         | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                               |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | RECOMMENDED    | MTH        |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-99-01 R03        | CESCOME PRICES (THIS SL CANCELS SL525B-99-01 R2 AND PREVIOUS)                                                 |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-99-04            | MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS                                          |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | A/R         |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-99-05            | MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION                                                   |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | A/R         |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL CIL-03-01             | CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)                                              |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL CIL-99-04             | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW                                                       |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-99-03 R02        | MISCELLANEOUS - TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE       |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  | MTH        |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-05-01            | CORROSIVE ENVIRONMENT INSPECTION                                                                              |             |            |                | MTH        |        | -           |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        |             |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SL 525B-05-03            | TIME LIMITS/MAINTENANCE CHECKS - WING INSPECTION INTERVAL IMPLEMENTATION GRACE PERIOD                         |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R04 E1    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |             |            |                |            |        | -           |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        |             |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R04 E2    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |             |            |                |            |        | -           |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        |             |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R05-CN E1 | SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000) |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | CANCELLED      |            |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R05-CN E2 | SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000) |             |            |                |            |        |             |         |             |         |
|                          |                                                                                                               |             |            | CANCELLED      |            |        | -           |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R05 E1    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |             |            |                |            |        | -           |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        |             |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R05 E2    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |             |            |                |            |        | -           |         |             |         |
|                          |                                                                                                               |             |            | INFORMATIONAL  |            |        |             |         |             |         |
|                          | MOC :                                                                                                         |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position        | Description<br>Drawing # / Task #                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PSID WI-05-1000<br>R04<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION                                                                               |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R04<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION                                                                               |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>E1        | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>E2        | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007-CN<br>E1       | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL   |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007-CN<br>E2       | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL   |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1020<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1020<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1022<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL                       |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1022<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL                       |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045-CN<br>E1       | CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045-CN<br>E2       | CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL          |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position  | Description<br>Drawing # / Task #                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL WI-05-1045<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL                                        |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1095-CN<br>E1 | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                    |      |         |                               |                          |                |                |                |                            |                    |
|                        | CANCELED                                                                                                                                       |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1095-CN<br>E2 | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                    |      |         |                               |                          |                |                |                |                            |                    |
|                        | CANCELED                                                                                                                                       |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1095<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                               |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1095<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                               |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1149<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL                                            |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1149<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL                                            |      |         |                               |                          |                |                |                |                            |                    |
|                        | -                                                                                                                                              |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-01 R02       | USE OF CORROSION INHIBITING COMPOUNDS                                                                                                          |      |         |                               | MTH                      |                |                |                | -                          |                    |
|                        | INFORMATIONAL                                                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-02           | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS |      |         |                               | MTH                      |                |                |                | -                          |                    |
|                        | RECOMMENDED                                                                                                                                    |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-20-01 R02       | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL                                                       |      |         |                               |                          |                |                |                |                            |                    |
|                        | INFORMATIONAL                                                                                                                                  |      |         | MTH                           |                          |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-20-01 R07      | SUPERSEDED BY CIL-20-01 R2                                                                                                                     |      |         | INFORMATIONAL                 | MTH                      |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-20-05          | STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL                                                                                          |      |         | INFORMATIONAL                 |                          |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| COM MC 525B-002        | 500 COMPRESSOR HOUR INSPECTION                                                                                                                 |      |         | INFORMATIONAL                 |                          |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-21-04          | AIR CONDITIONING - PRESSURIZATION PRINTED CIRCUIT BOARD REPLACEMENT                                                                            |      |         |                               |                          |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-21-05          | AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT                                                                                 |      |         |                               | MTH                      |                |                |                | -                          |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-21-06          | AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT                                                                           |      |         |                               |                          |                |                |                | -                          |                    |
|                        | OPTIONAL                                                                                                                                       |      |         |                               |                          |                |                |                |                            |                    |
|                        | MOC :                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code         | Description                                                                                                                                                                                                                                                                                                                                                         | Part Number | C/W Time 1    | Adj.                                    | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------|-----------------------------------------|------------|--------|-------------|---------|-------------|----------|
| Position          | Drawing # / Task #                                                                                                                                                                                                                                                                                                                                                  | City        | Mod Lvl       | Part Serial No                          | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB 525B-23-05     | COMMUNICATIONS - AIRCELL ATG ANTENNA BONDING IMPROVEMENTS                                                                                                                                                                                                                                                                                                           | KIWA        | RECOMMENDED   | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |            | -      |             |         |             | Complete |
|                   | MOC : COMPLIED WITH - COMPLIED WITH SB 525B-23-05 COMMUNICATIONS - AIRCELL ATG ANTENNA BONDING IMPROVEMENTS IN ACCORDANCE WITH THE CESSNA SERVICE BULLETIN SB525B-23-05 DATED OCTOBER 27, 2017.                                                                                                                                                                     |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-06     | COMMUNICATIONS - AVIATOR 300 SATCOM ANTENNA REPLACEMENT                                                                                                                                                                                                                                                                                                             |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-07     | COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) OPTION                                                                                                                                                                                                                                                                             |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-08     | COMMUNICATIONS - LINK 2000+ CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION                                                                                                                                                                                                                                                                          |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-09     | COMMUNICATIONS - FAA DATACOMM INSTALLATION                                                                                                                                                                                                                                                                                                                          |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-10     | COMMUNICATIONS - GARMIN GDR 66 VHF DATA LINK RADIO INSTALLATION                                                                                                                                                                                                                                                                                                     |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-23-11     | COMMUNICATIONS - AUDIO WIRING MODIFICATION                                                                                                                                                                                                                                                                                                                          |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SL 525B-23-02     | COMMUNICATIONS - LINK 2000+ CPDLC AND VHF ACARS CONFIGURATION VERIFICATION                                                                                                                                                                                                                                                                                          | KICT        | RECOMMENDED   | MTH 06-Sep-2017<br>HRS 6.1<br>LDG 3     |            | -      |             |         |             | N/A      |
|                   | MOC : NOT APPLICABLE - DOES NOT APPLY DUE TO COMPONENTS NOT INSTALLED.                                                                                                                                                                                                                                                                                              |             |               |                                         |            |        |             |         |             |          |
| SL 525B-23-05     | COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8                                                                                                                                                                                                                                                                                                            |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-24-10 R01 | ELECTRICAL POWER - POWER JUNCTION BOX (J-BOX) START RELAY MODIFICATION                                                                                                                                                                                                                                                                                              | KIWA        | RECOMMENDED   | MTH 01-Oct-2021<br>HRS 373.5<br>LDG 304 |            | -      |             |         |             | Complete |
|                   | MOC : COMPLIED WITH - COMPLIED WITH SB 525B-24-10 R01 ELECTRICAL POWER - POWER JUNCTION BOX (J-BOX) START RELAY MODIFICATION IN ACCORDANCE WITH THE CESSNA SERVICE BULLETIN SB525B-24-10 R01 DATED JANUARY 12, 2018. RELAYS PART NO: 76505-5YD SERIAL NO: 1938 AND PART NO: 76505-5YD SERIAL NO: 1878 WERE INSTALLED AS A RESULT OF ACCOMPLISHING SB525B-24-10 R01. |             |               |                                         |            |        |             |         |             |          |
| SB 525B-24-12     | ELECTRICAL POWER - JUMPER INSTALLATION IN THE COMPRESSOR ASSEMBLY                                                                                                                                                                                                                                                                                                   |             | RECOMMENDED   | MTH                                     |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-24-13     | ELECTRICAL POWER - RG24-15M CONCORDE LEAD ACID AUXILIARY BATTERY INSTALLATION                                                                                                                                                                                                                                                                                       |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| COM MC 525B-013   | GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES                                                                                                                                                                                                                                                                                                                   |             | INFORMATIONAL |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |
| SB 525B-25-09     | EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK                                                                                                                                                                                                                                                                                                              |             | OPTIONAL      |                                         |            | -      |             |         |             |          |
|                   | MOC :                                                                                                                                                                                                                                                                                                                                                               |             |               |                                         |            |        |             |         |             |          |





## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                                                                       | Description<br>Drawing # / Task #                                                                                                                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 525B-31-01                                                                                                                                                                                               | R01 INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER INSTALLATION<br>OPTIONAL                                                                                          |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-31-01                                                                                                                                                                                                | INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION<br>INFORMATIONAL                                            |      |         |                               |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-32-01                                                                                                                                                                                                | LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL<br>INFORMATIONAL                                                                                                           |      |         | MTH                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-32-04                                                                                                                                                                                                | WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION<br>INFORMATIONAL                                                                                                    |      |         | MTH                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-32-06                                                                                                                                                                                                | LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION<br>INFORMATIONAL                                                                              |      |         |                               |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-32-01                                                                                                                                                                                               | R01 NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION<br>OPTIONAL                                                                                                        |      |         | MTH                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-32-02                                                                                                                                                                                               | MAIN LANDING GEAR SIMULATIOR TEST BOX<br>INFORMATIONAL                                                                                                                    |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-32-07                                                                                                                                                                                               | TRANSMITTAL OF GOODRICH SERVICE LETTER SL2060, LANDING GEAR - MAIN WHEEL ASSEMBLY - INTRODUCTION OF AN IMPROVED OPTIONAL<br>THERMAL RELIEF PLUG ASSEMBLY<br>INFORMATIONAL |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-32-14                                                                                                                                                                                               | LANDING GEAR - MAIN LANDING GEAR REPAIR<br>INFORMATIONAL                                                                                                                  |      |         |                               |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-33-01                                                                                                                                                                                                | TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY<br>BATTERY<br>INFORMATIONAL                           |      |         | MTH                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-03                                                                                                                                                                                               | ENHANCED SURVEILLANCE TRANSPONDER UPGRADE<br>OPTIONAL                                                                                                                     |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-19                                                                                                                                                                                               | R03 NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES<br>OPTIONAL                                                          |      |         |                               |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-27                                                                                                                                                                                               | NAVIGATION - GARMIN G3000 SURFACEWATCH INSTALLATION<br>OPTIONAL                                                                                                           |      |         | MTH                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-32                                                                                                                                                                                               | R01 NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11<br>KIWA                                                                                                         |      |         | MANDATORY                     | MTH                      | 01-Oct-2021    | -              |                |                            | Complete           |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB 525B-34-32 R01 NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11 IN<br>ACCORDANCE WITH THE CESSNA SERVICE BULLETIN SB525B-34-32 R01 DATED AUGUST 25, 2021 |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-32                                                                                                                                                                                               | R02 NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11<br>MANDATORY                                                                                                    |      |         |                               |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                |                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 525B-34-32         | NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11                                                                                    |      |         | MTH                           |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-33         | NAVIGATION - GROUND CLUTTER SUPPRESSION (GCS) AND TURBULENCE DETECTION SYSTEM (TDS) OPTION                                               |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-34         | NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) 1/A INSTALLATION                                                                        |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-35         | NAVIGATION - GARMIN SURFACEWATCH INSTALLATION                                                                                            |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-36         | NAVIGATION - SYNTHETIC VISION SYSTEM INSTALLATION                                                                                        |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-37         | NAVIGATION - TERRAIN AWARENESS WARNING SYSTEM (TAWS) CLASS A INSTALLATION                                                                |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-38 R01     | NAVIGATION - REACTIVE WINDSHEAR INSTALLATION                                                                                             |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-38         | NAVIGATION - REACTIVE WINDSHEAR INSTALLATION                                                                                             |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-39         | NAVIGATION - GDL 69 SXM DATA LINK UPDATE                                                                                                 |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-40 R01     | NAVIGATION - GARMIN HARDWARE AND SOFTWARE UPDATE TO VERSION 4.8.9                                                                        |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB 525B-34-40 R02     | NAVIGATION - GARMIN HARDWARE AND SOFTWARE UPDATE TO VERSION 4.8.9                                                                        |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-34-05 R01      | TRANSMITTAL OF GARMIN SERVICE ALERT 1478, LP AND LPV APPROACHES                                                                          |      |         | CANCELLED                     | MTH                      |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-34-07          | NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE                                                   |      |         | INFORMATIONAL                 | MTH                      |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-34-10          | NAVIGATION - TRANSMITTAL OF GARMIN SB 19102 GSR 56 MOD 1                                                                                 |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB CIL-34-11          | NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-34-01         | TRANSMITTAL OF GARMIN SERVICE ALERT, DIRECT-TO-WAYPOINT SELECTION SERVICE ALERT: 050721-00                                               |      |         | INFORMATIONAL                 | MTH                      |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-34-04         | TRANSMITTAL OF L-3 COMMUNICATIONS AVIONICS SYSTEMS' SERVICE LETTER SL-230 (REV. A)                                                       |      |         | INFORMATIONAL                 | MTH                      |                | A/R            |                |                            |                    |
|                       | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                                                                                                                                                                 | Description                                                                                                                                         | Part Number | C/W Time 1    | Adj.           | TBO 1            | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------|----------------|------------------|--------|-------------|---------|-------------|----------|
| Position                                                                                                                                                                  | Drawing # / Task #                                                                                                                                  | City        | Mod Lvl       | Part Serial No | C/W Time 2       | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SL 525B-34-05 R01 CONFIGURATION FOR AUSTRALIA, SINGAPORE FIR, AND HONG KONG ADS-B OUT (CANCELLED BY SL525B-34-05 R02)                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | OPTIONAL      |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-05 R02 CONFIGURATION FOR AUSTRALIA, SINGAPORE FIR, AND HONG KONG ADS-B OUT (CANCELS THIS SERVICE LETTER AND REPLACES IT WITH SB 525B-34-26)                    |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | CANCELLED     |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-06                                                                                                                                                             | TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1433 POTENTIAL GWX 70 POWER AMPLIFIER FAILURE IN GROUND MAP MODE                                         |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-07                                                                                                                                                             | NAVIGATIONAL - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1529, PROCEDURE LEGS IN TERMINAL PROCEDURES                                               |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-08                                                                                                                                                             | NAVIGATIONAL - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1514, POTENTIAL ERRONEOUS LATERAL GUIDANCE                                                |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-10 R01                                                                                                                                                         | NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONALGEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL               |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-10 R02                                                                                                                                                         | NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1612 REVISION F, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-13                                                                                                                                                             | NAVIGATION - TRANSMITTAL OF GARMIN SB 1994, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE                                  |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-15                                                                                                                                                             | NAVIGATION - STORMSCOPE PROCESSOR MODIFICATION (MOD) LEVEL INSPECTION                                                                               |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | RECOMMENDED   |                | MTH              |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL 525B-34-16                                                                                                                                                             | NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY LETTER NO. 22037 REV A FALSE GPS NEEDS SERVICE SYSTEM MESSAGE                                   |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL CIL-35-05                                                                                                                                                              | OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001                                                                                          |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           | KICT                                                                                                                                                |             | MANDATORY     |                | DAYS 11-Sep-2017 |        | -           |         |             | N/A      |
|                                                                                                                                                                           |                                                                                                                                                     |             |               |                | HRS 7.7          |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             |               |                | LDG 4            |        |             |         |             |          |
| MOC : NOT APPLICABLE - CIL-35-05 DOES NOT APPLY DUE TO PARTS NOT INSTALLED IN AIRCRAFT.                                                                                   |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL CIL-52-02                                                                                                                                                              | DOORS - EMERGENCY EXIT DOOR INSPECTION                                                                                                              |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | INFORMATIONAL |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SL CIL-52-03                                                                                                                                                              | DOORS - EMERGENCY ESCAPE HATCH INSPECTION                                                                                                           |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           | KIWA                                                                                                                                                |             | MANDATORY     |                | MTH 01-Oct-2021  |        | -           |         |             | Complete |
|                                                                                                                                                                           |                                                                                                                                                     |             |               |                | HRS 373.5        |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             |               |                | LDG 304          |        |             |         |             |          |
| MOC : COMPLIED WITH - COMPLIED WITH SL CIL-52-03 DOORS - EMERGENCY ESCAPE HATCH INSPECTION IN ACCORDANCE WITH THE CESSNA SERVICE LETTER CIL-52-03 DATED NOVEMBER 4, 2020. |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |
| SB 525B-53-03                                                                                                                                                             | FUSELAGE - RADOME LATCH IMPROVEMENT                                                                                                                 |             |               |                |                  |        |             |         |             |          |
|                                                                                                                                                                           |                                                                                                                                                     |             | OPTIONAL      |                |                  |        | -           |         |             |          |
| MOC :                                                                                                                                                                     |                                                                                                                                                     |             |               |                |                  |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code             | Description                                                                               | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-----------------------|-------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position              | Drawing # / Task #                                                                        | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SL 525B-55-03 R01     | STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION                                  |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | RECOMMENDED    |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL 525B-55-03         | STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION                                  |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | RECOMMENDED    |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-70-1008 E1      | STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL      |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-70-1008 E2      | STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL      |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL 525B-71-07         | DESALINIZATION RINSE - REMOVE BLEED CAP REQUIREMENT                                       |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | INFORMATIONAL  | MTH        |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1064-CN E1   | CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL           |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1064-CN E2   | CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL           |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1064 E1      | POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                      |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1064 E2      | POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                      |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1129 E1      | CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1129 E2      | CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1319-CN E1   | CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL            |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1319-CN E2   | CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL            |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | CANCELLED      |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1319 E1      | POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                       |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1319 E2      | POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                       |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1541 E1      | POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL         |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SL WI-71-1541 E2      | POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL         |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            |                |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |
| SB FJ44-05-002 R03 E1 | UNSERVICEABLE PARTS - NOTIFICATION                                                        |             |            |                |            |        |             |         |             |         |
|                       |                                                                                           |             |            | INFORMATIONAL  |            |        | -           |         |             |         |
|                       | MOC :                                                                                     |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                                  | Description<br>Drawing # / Task #                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-05-002<br>R03<br>E2                                            | UNSERVICEABLE PARTS - NOTIFICATION                                                          |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-105<br>R05<br>E1                                            | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-105<br>R05<br>E2                                            | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-105<br>R06<br>E1                                            | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                |      |         | OPTIONAL MTH                  |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-105<br>R06<br>E2                                            | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                |      |         | OPTIONAL MTH                  |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-106<br>R03<br>E1                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-106<br>R03<br>E2                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-107<br>R02<br>E1                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | DUE            |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-107<br>R02<br>E2                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | DUE            |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-107<br>R05<br>E1                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-107<br>R05<br>E2                                            | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01-CN<br>E1                                         | SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01-CN<br>E2                                         | SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-122-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE |                                                                                             |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
| E1                                                                     |                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-122-CNSUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE |                                                                                             |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
| E2                                                                     |                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
|                                                                        | <b>MOC :</b>                                                                                |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position          | Description<br>Drawing # / Task # City Mod Lvl                                         | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|----------------------------------------------------------------------------------------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-124<br>R03<br>E1    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R03<br>E2    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R06<br>E1    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R06<br>E2    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R07<br>E1    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R07<br>E2    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R08<br>E1    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R08<br>E2    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R09<br>E1    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-124<br>R09<br>E2    | HP TURBINE BLADES - REPLACE                                                            | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01-CN<br>E1 | CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE<br>CANCELLED |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01-CN<br>E2 | CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE<br>CANCELLED |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-150<br>R02<br>E1    | LP REAR BEARING SEAL RETAINER - REPLACE                                                |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-150<br>R02<br>E2    | LP REAR BEARING SEAL RETAINER - REPLACE                                                |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                           |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position        | Description<br>Drawing # / Task #          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|--------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-151<br>R05<br>E1  | BEARING AND PINION ASSEMBLY - INSTALL      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-151<br>R05<br>E2  | BEARING AND PINION ASSEMBLY - INSTALL      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-151<br>R06<br>E1  | BEARING AND PINION ASSEMBLY - INSTALL      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-72-151<br>R06<br>E2  | BEARING AND PINION ASSEMBLY - INSTALL      |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SL 44-72-325 R06<br>E1       | ENGINE - 1ST LP TURBINE DISK - INSPECTION  |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SL 44-72-325 R06<br>E2       | ENGINE - 1ST LP TURBINE DISK - INSPECTION  |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SL 44-72-325 R07<br>E1       | 1ST LP TURBINE DISK - INSPECTION           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SL 44-72-325 R07<br>E2       | 1ST LP TURBINE DISK - INSPECTION           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R02<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION         |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R02<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION         |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R03<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION         |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R03<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION         |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-72-1026<br>E1        | FAN CASE - RUB INDICATIONS                 |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-72-1026<br>E2        | FAN CASE - RUB INDICATIONS                 |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R01<br>E1      | HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R01<br>E2      | HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                               |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position                                              | Description<br>Drawing # / Task # | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------|-----------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1 |                                   |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2 |                                   |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1 |                                   |      |         | MANDATORY                     | MTH                      |                | MPI<br>MPI     |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2 |                                   |      |         | MANDATORY                     | MTH                      |                | MPI<br>MPI     |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1 |                                   |      |         | MANDATORY                     | MTH<br>LDG               |                | 8000           |                | (8000)8017                 | New Req            |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2 |                                   |      |         | MANDATORY                     | MTH<br>LDG               |                | 8000           |                | (8000)8020                 | New Req            |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1     |                                   |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1034 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2     |                                   |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E1       |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E2       |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E1       |                                   |      |         |                               | MTH                      |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E2       |                                   |      |         |                               | MTH                      |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E1       |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E2       |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E1       |                                   |      |         | RECOMMENDED                   |                          |                | CSI            |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>E2       |                                   |      |         | RECOMMENDED                   |                          |                | CSI            |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E1    |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E2    |                                   |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                       |                                   |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                                                                           | Description        | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-------------------------------------------------------------------------------------|--------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                            | Drawing # / Task # | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E1                     |                    |             |            |                | MTH        |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E2                     |                    |             |            |                | MTH        |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E1                     |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E2                     |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E1                     |                    |             |            |                |            |        | MPI         |         |             |         |
| RECOMMENDED                                                                         |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E2                     |                    |             |            |                |            |        | MPI         |         |             |         |
| RECOMMENDED                                                                         |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E1                         |                    |             |            |                |            |        | -           |         |             |         |
| RECOMMENDED                                                                         |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>E2                         |                    |             |            |                |            |        | -           |         |             |         |
| RECOMMENDED                                                                         |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R01 BALANCE PISTON - REPLACE<br>E1                                    |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R01 BALANCE PISTON - REPLACE<br>E2                                    |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R02 BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09)<br>E1 |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R02 BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09)<br>E2 |                    |             |            |                |            |        | -           |         |             |         |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R03 BALANCE PISTON - REPLACE<br>E1                                    |                    |             |            |                |            |        | RECOMMENDED |         |             | CSI     |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 R03 BALANCE PISTON - REPLACE<br>E2                                    |                    |             |            |                |            |        | RECOMMENDED |         |             | CSI     |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 ENGINE - BALANCE PISTON - REPLACE<br>E1                               |                    |             |            |                |            |        | MTH         |         |             | -       |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SB WI-72-1044 ENGINE - BALANCE PISTON - REPLACE<br>E2                               |                    |             |            |                |            |        | MTH         |         |             | -       |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SL WI-72-1032-CN APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL<br>E1  |                    |             |            |                |            |        | CANCELLED   |         |             | -       |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |
| SL WI-72-1032-CN APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL<br>E2  |                    |             |            |                |            |        | CANCELLED   |         |             | -       |
| MOC :                                                                               |                    |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                             | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|-----------------------------------------------------------------------------------------------|------|---------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL WI-72-1128<br>E1            | FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL                                               |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1128<br>E2            | FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL                                               |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1132-CN<br>E1         | CANCELLED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1132-CN<br>E2         | CANCELLED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1132<br>E1            | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                                   |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1132<br>E2            | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                                   |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1140<br>E1            | INDUCTION HEATING - REVISION TO ENGINE MANUAL                                                 |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1140<br>E2            | INDUCTION HEATING - REVISION TO ENGINE MANUAL                                                 |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1262<br>E1            | APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL                                    |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SL WI-72-1262<br>E2            | APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL                                    |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SB 525B-73-01                  | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) FIELD REPLACEMENT<br>OPTIONAL               |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| PSID WI-73-1008<br>R01<br>E1   | FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG                                     |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| PSID WI-73-1008<br>R01<br>E2   | FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG                                     |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>-CN<br>E1 | CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>CANCELLED             |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>-CN<br>E2 | CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>CANCELLED             |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>E1        | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)<br>MANDATORY             |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>E2        | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)<br>MANDATORY             |      |                                       |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                  |      |                                       |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code               | Description                                                                                             | Part Number | C/W Time 1  | Adj.            | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------------|---------------------------------------------------------------------------------------------------------|-------------|-------------|-----------------|------------|--------|-------------|---------|-------------|----------|
| Position                | Drawing # / Task #                                                                                      | City        | Mod Lvl     | Part Serial No  | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB WI-73-1002<br>E1     | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)               |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | MANDATORY       |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1002<br>E2     | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)               |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | MANDATORY       |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1007 R01<br>E1 | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED) |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             |                 |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1007 R01<br>E2 | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED) |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             |                 |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R01<br>E1 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R01<br>E2 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R02<br>E1 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R02<br>E2 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R03<br>E1 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R03<br>E2 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R04<br>E1 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         | KIWA                                                                                                    |             | RECOMMENDED | MTH 27-Sep-2019 |            |        | -           |         |             | Complete |
|                         |                                                                                                         |             |             | HRS 218.4       |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | LDG 176         |            |        |             |         |             |          |
|                         | MOC : COMPLIED WITH - OPERATIONAL AND LEAK CHECK GOOD AT THIS TIME.                                     |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008 R04<br>E2 | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         | KIWA                                                                                                    |             | RECOMMENDED | MTH 27-Sep-2019 |            |        | -           |         |             | Complete |
|                         |                                                                                                         |             |             | HRS 218.4       |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | LDG 174         |            |        |             |         |             |          |
|                         | MOC : COMPLIED WITH - OPERATIONAL AND LEAK CHECK GOOD AT THIS TIME.                                     |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008<br>E1     | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1008<br>E2     | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             | RECOMMENDED     |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1009 R01<br>E1 | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                                |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             |                 |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |
| SB WI-73-1009 R01<br>E2 | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                                |             |             |                 |            |        |             |         |             |          |
|                         |                                                                                                         |             |             |                 |            |        | -           |         |             |          |
|                         | MOC :                                                                                                   |             |             |                 |            |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code                                                                  | Description                                                                                                                              | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1       | Remains |             |         |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------------|---------|-------------|---------|
| Position                                                                   | Drawing # / Task #                                                                                                                       | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2             | TSO 2   | (ENG) DUE 2 | Remains |
| SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            | RECOMMENDED    | MTH<br>HRS |        | CSI<br>CSI<br>CSI |         | (4000)4000  | 3475.9  |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            | RECOMMENDED    | MTH<br>HRS |        | CSI<br>CSI<br>CSI |         | (4000)4000  | 3475.9  |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009                                                              | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                                                                 |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            | RECOMMENDED    |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1009                                                              | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                                                                 |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            | RECOMMENDED    |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1019-CN                                                           | SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1019-CN                                                           | SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1019                                                              | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)                 |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1019                                                              | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)                 |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            |                |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1022                                                              | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            | NOT APPLICABLE |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1022                                                              | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            | NOT APPLICABLE |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE    |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E1                                                                         |                                                                                                                                          |             |            | MANDATORY      |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE    |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |
| E2                                                                         |                                                                                                                                          |             |            | MANDATORY      |            |        | -                 |         |             |         |
| MOC :                                                                      |                                                                                                                                          |             |            |                |            |        |                   |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position  | Description<br>Drawing # / Task #                                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|-------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB WI-73-1027<br>E1    | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE<br><b>MOC :</b>                                       |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| SB WI-73-1027<br>E2    | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE<br><b>MOC :</b>                                       |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
| SB WI-73-1031<br>E1    | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01<br><b>MOC :</b> |      |         |                               |                          |                | -              |                |                            |                    |
| SB WI-73-1031<br>E2    | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01<br><b>MOC :</b> |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1018-CN<br>E1 | CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG<br><b>MOC :</b>                  |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
| SL WI-73-1018-CN<br>E2 | CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG<br><b>MOC :</b>                  |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
| SL WI-73-1018<br>E1    | ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG<br><b>MOC :</b>                             |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1018<br>E2    | ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG<br><b>MOC :</b>                             |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1026<br>E1    | ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL<br><b>MOC :</b>       |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1026<br>E2    | ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL<br><b>MOC :</b>       |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1037<br>E1    | ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL<br><b>MOC :</b>                               |      |         |                               |                          |                | -              |                |                            |                    |
| SL WI-73-1037<br>E2    | ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL<br><b>MOC :</b>                               |      |         |                               |                          |                | -              |                |                            |                    |
| SB WI-75-1001<br>E1    | R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| SB WI-75-1001<br>E2    | R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                              |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| SB WI-75-1001<br>E1    | R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                              |      |         | RECOMMENDED                   | MTH<br>HRS               |                | -              |                | (4000)4000                 | 3475.9             |
| SB WI-75-1001<br>E2    | R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                              |      |         | RECOMMENDED                   | MTH<br>HRS               |                | -              |                | (4000)4000                 | 3475.9             |
| SB WI-75-1001<br>E1    | AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                                  |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
| SB WI-75-1001<br>E2    | AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br><b>MOC :</b>                                                  |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                                                                                                                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 525B-76-04               | ENGINE CONTROLS - UPDATED FJ44-3A FULL AUTHORITY ENGINE CONTROL (FADEC) FIELD REPLACEMENT                                                                                                                             |      |         | OPTIONAL                      |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-76-1001-CN<br>E1      | CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                                                                                               |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-76-1001-CN<br>E2      | CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                                                                                               |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-76-1001<br>E1         | ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                                                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-76-1001<br>E2         | ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                                                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-77-013<br>R09<br>E1 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                                                                                                                                            |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-77-013<br>R09<br>E2 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                                                                                                                                            |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-011<br>R05<br>E1 | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                                                                                                                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-011<br>R05<br>E2 | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                                                                                                                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-80-01 R01           | STARTING - STARTER-GENERATOR EXHAUST DUCT INSTALLATION VERIFICATION                                                                                                                                                   |      |         | RECOMMENDED                   | MTH 01-Oct-2021          |                | -              |                |                            | Complete           |
|                             |                                                                                                                                                                                                                       |      |         |                               | HRS 373.5                |                |                |                |                            |                    |
|                             |                                                                                                                                                                                                                       |      |         |                               | LDG 304                  |                |                |                |                            |                    |
|                             | <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SL 525B-80-01 R01 STARTING - STARTER-GENERATOR EXHAUST DUCT INSTALLATION VERIFICATION IN ACCORDANCE WITH THE CESSNA SERVICE LETTER SL 525B-80-01 R01 DATED OCTOBER 5, 2018 |      |         |                               |                          |                |                |                |                            |                    |
| SL 525B-80-01               | STARTING - STARTER-GENERATOR EXHAUST DUCT INSTALLATION VERIFICATION (SUPERSEDED BY SL525B-80-01 R01)                                                                                                                  |      |         | RECOMMENDED                   | MTH                      |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-01 R03            | MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS                                                                                                                                                                 |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-02 R01            | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS                                                                        |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-03 R02            | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                                                                                       |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                          |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Service Bulletins

| Item Code        | Description                                             |      |         | Part Number    | C/W Time 1 | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|------------------|---------------------------------------------------------|------|---------|----------------|------------|--------|-------|-------|-------------|---------|
| Position         | Drawing # / Task #                                      | City | Mod Lvl | Part Serial No | C/W Time 2 | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| SL CIL-99-04 R01 | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW |      |         |                |            |        |       |       |             |         |
|                  | CANCELLED                                               |      |         |                |            |        | -     |       |             |         |
|                  | MOC :                                                   |      |         |                |            |        |       |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                   | Description<br>Drawing # / Task #                                                                                                                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2007-23-16                                                                                                                                          | INCORPORATE ELECTRICAL POWER RELAY CIRCUIT PROTECTION KIT                                                                                                                                   | KICT |         | MANDATORY                     | MTH 06-Sep-2017<br>HRS 6.1<br>LDG 3     |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2007-23-16: ELECTRICAL CIRCUIT POWER PROTECTION, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.                          |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2017-16-01<br>PARA (G)                                                                                                                              | PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS    | KIWA |         |                               | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH AMERI-KING ELT. AIRCRAFT IS EQUIPPED WITH A ARTEX C406-N ELT. AD 2017-16-01 DOES NOT APPLY. |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2017-16-01<br>PARA (J)                                                                                                                              | OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT                                                                                                                | KIWA |         | MANDATORY                     | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH AMERI-KING ELT. AIRCRAFT IS EQUIPPED WITH A ARTEX C406-N ELT. AD 2017-16-01 DOES NOT APPLY. |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2017-16-01                                                                                                                                          | APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS | KIWA |         | MANDATORY                     | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH AMERI-KING ELT. AIRCRAFT IS EQUIPPED WITH A ARTEX C406-N ELT. AD 2017-16-01 DOES NOT APPLY. |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(1)                                                                                                                           | INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE                                                                            | P19  |         | MANDATORY                     | MTH 03-May-2021<br>HRS 329.8<br>LDG 255 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APPLICABLE DUE TO SEAT BELT PART NUMBER, NO FURTHER ACTION REQUIRED                                                    |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(2)                                                                                                                           | MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE       | P19  |         | MANDATORY                     | MTH 03-May-2021<br>HRS 329.8<br>LDG 255 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APPLICABLE DUE TO SEAT BELT PART NUMBER, NO FURTHER ACTION REQUIRED                                                    |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(3)                                                                                                                           | DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER                                   | P19  |         | MANDATORY                     | MTH 03-May-2021                         |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APPLICABLE DUE TO SEAT BELT PART NUMBER                                                                                |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2021-07-13                                                                                                                                          | APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT                                                                       | P19  |         | MANDATORY                     | MTH 03-May-2021                         |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NO APPLICABLE DUE TO SEAT BELT PART NUMBER                                                                                |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| FAA 2005-17-11                                                                                                                                          | PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES                                                                                                             | KICT |         | MANDATORY                     | MTH 06-Sep-2017<br>HRS 6.1<br>LDG 3     |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2005-17-11: INSTALLATION OF ID SLEEVES ON ENGINE FIRE BOTTLES, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.            |                                                                                                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                                                                                                                                                       | Description<br>Drawing # / Task # City Mod Lvl Part Serial No                                                                                                                                                                                                                                                                        | Part Number | C/W Time 1<br>C/W Time 2                 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2019-08-13                                                                                                                                                                                                                                                                                                                                                                              | FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06) | MANDATORY   |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-23-12                                                                                                                                                                                                                                                                                                                                                                              | APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS                                                                                                                                                                                                               | MANDATORY   | MTH 02-Jan-2022<br>HRS 394.9<br>LDG 322  |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH FAA 2021-23-12 APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS                                                                                                                                                                                                            |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2019-12-09                                                                                                                                                                                                                                                                                                                                                                              | APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)                                                                                                                                                                                     | SUPERSEDED  | DAYS 27-Sep-2019<br>HRS 218.4<br>LDG 174 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH FAA 2019-12-09 NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION IN ACCORDANCE WITH FAA AIRWORTHINESS DIRECTIVE FAA 2019-12-09 BY VERIFYING THAT THIS AD DOES NOT APPLY DUE TO AFFECTED EQUIPMENT ROCKWELL COLLINS PRO-LINE FUSION FLIGHT MANAGEMENT SYSTEM NOT BEING INSTALLED ON THIS AIRCRAFT. |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-05-17<br>PARA (G)(1) & (G)(2)                                                                                                                                                                                                                                                                                                                                                      | REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)                                                                                                  | MANDATORY   | MTH 13-May-2022<br>HRS 426.3<br>LDG 342  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND AD NOT APPLICABLE, GARMIN AVIONICS INSTALLED.                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-05-17<br>PARA (G)(3)                                                                                                                                                                                                                                                                                                                                                               | UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE                                                                                                                                                                                                                                                                                        | MANDATORY   | MTH 13-May-2022<br>HRS 426.3<br>LDG 342  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND AD NOT APPLICABLE, GARMIN AVIONICS INSTALLED.                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-05-17<br>PARA (G)(5)                                                                                                                                                                                                                                                                                                                                                               | AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE                                                                      | MANDATORY   | MTH 13-May-2022<br>HRS 426.3<br>LDG 342  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND AD NOT APPLICABLE, GARMIN AVIONICS INSTALLED.                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-05-17                                                                                                                                                                                                                                                                                                                                                                              | APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE                                                                                                                                                                                                              | MANDATORY   | MTH 13-May-2022<br>HRS 426.3<br>LDG 342  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - FOUND AD NOT APPLICABLE, GARMIN AVIONICS INSTALLED.                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |
| FAA 2021-08-15                                                                                                                                                                                                                                                                                                                                                                              | APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE                                                                                                                                                                                                           | MANDATORY   | MTH 13-Apr-2023<br>HRS 524.1<br>LDG 402  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2021-08-15, APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPDATE, EFFECTIVE DATE: MAY 17, 2021, IS NOT APPLICABLE. CURRENT SOFTWARE LEVEL IS 3.14.1.                                                                                                           |                                                                                                                                                                                                                                                                                                                                      |             |                                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **MOTORSPORTS MANAGEMENT, INC.**  
Aircraft Model: **525B - CJ3+**  
Aircraft Serial: **525B-0523**  
Unit: Reg No: **N523HD**  
Airworthiness: **07-Sep-2017**  
Print Date: **18-May-2023 12:59PM**

| Tracking Rate   | Hours        | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|--------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>524.1</b> | <b>405</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 1</b>    | <b>524.1</b> | <b>388</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>ENG 2</b>    | <b>524.1</b> | <b>385</b>          | <b>13-Apr-2023</b>  | <b>.27</b>                   |
| <b>AIR COND</b> | <b>297</b>   |                     | <b>13-Apr-2023</b>  | <b>.9</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                          | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                                     | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2              | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------------------------------------|---------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2015-23-09                                                                                                                                 | APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS                                                                                                                        | KICT | MANDATORY                             | MTH 06-Sep-2017<br>HRS 6.1<br>LDG 3   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A SUSPECT PARTS NOT INSTALLED ON THIS AIRCRAFT.                                                                |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (G)                                                                                                                     | INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                                                                                               | KIWA | MANDATORY                             | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2017-18-12 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED ON AIRCRAFT AT THIS TIME. NO FURTHER ACTION TAKEN. |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (H)                                                                                                                     | REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                                                                                              | KIWA | MANDATORY                             | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2017-18-12 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED ON AIRCRAFT AT THIS TIME. NO FURTHER ACTION TAKEN. |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (I) & (J)                                                                                                               | INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.                                                                                              | KIWA | MANDATORY                             | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2017-18-12 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED ON AIRCRAFT AT THIS TIME. NO FURTHER ACTION TAKEN. |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2017-18-12                                                                                                                                 | APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES                                                                                                                         | KIWA | MANDATORY                             | MTH 27-Oct-2017<br>HRS 38.3<br>LDG 30 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2017-18-12 IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED ON AIRCRAFT AT THIS TIME. NO FURTHER ACTION TAKEN. |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2008-03-10                                                                                                                                 | INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE | KICT | AIRWORTHINESS                         | DAYS 06-Sep-2017<br>HRS 6.1<br>LDG 3  |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2008-03-10: FUSELAGE LOWER SKIN INSPECT, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER.                         |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2022-13-15<br>E1                                                                                                                           | TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE                                                                                                                                                                                                                                          |      | MANDATORY                             | MTH                                   |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                   |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |
| FAA 2022-13-15<br>E2                                                                                                                           | TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE                                                                                                                                                                                                                                          |      | MANDATORY                             | MTH                                   |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                   |                                                                                                                                                                                                                                                                                                       |      |                                       |                                       |                |                |                |                            |                    |