



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PPPP1	PAINT AIRCRAFT	ICT			MTH 20-Aug-2011 HRS 7.8 LDG 4		O/C			
4-12-MA	INSPECTION DOCUMENT MA	KTPA			MTH 15-May-2023 HRS 3189.4 LDG 2358		500		3689.4	276.3
4-12-MB	INSPECTION DOCUMENT MB				DAYS 20-Aug-2011 HRS 0		15000		15000	11586.9
4-12-MC	INSPECTION DOCUMENT MC	KSWF			MTH 28-Jul-2018 HRS 1982.8 LDG 1578		2000		3982.8	569.7
4-12-MD	INSPECTION DOCUMENT MD	KTPA			MTH 05-Jan-2023 HRS 2989.5 LDG 2209		1500		4489.5	1076.4
4-12-ME	INSPECTION DOCUMENT ME (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 20-Aug-2011 LDG 0		5000			
32-20-00-250 NOSE LANDING GEAR	NOSE LANDING GEAR FORK AND PISTON ASSEMBLY (EDDY CURRENT OR DYE PENETRANT) SPECIAL DETAILED INSPECTION				MTH 20-Aug-2011 LDG 0		5000		5000	2475
4-12-MF	INSPECTION DOCUMENT MF	UNK		6342350-4 413	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		2500		4859.4	1446.3
4-12-MG	INSPECTION DOCUMENT MG				MTH 20-Aug-2011 HRS 0		5000		5000	1586.9
4-12-MH	INSPECTION DOCUMENT MH				MTH 20-Aug-2011 HRS 0		5050		5050	1636.9
4-12-MI	INSPECTION DOCUMENT MI				MTH 20-Aug-2011 HRS 0		6000		6000	2586.9
4-12-MJ	INSPECTION DOCUMENT MJ	KTPA			MTH 05-Jan-2023 HRS 2989.5 LDG 2209		3000		5989.5	2576.4
4-12-MK	INSPECTION DOCUMENT MK	KTPA			MTH 06-Nov-2023 HRS 3390.4 LDG 2503		12 330		30-Nov-2024 3720.4	12 m 13 d 307.3
4-12-ML	INSPECTION DOCUMENT ML				HRS		9000		9000	5586.9
4-12-MO	INSPECTION DOCUMENT MO				MTH 20-Aug-2011 HRS 0		15000		15000	11586.9
4-12-MQ	INSPECTION DOCUMENT MQ				MTH 20-Aug-2011 HRS 0		15000		15000	11586.9
4-12-MR	INSPECTION DOCUMENT MR				MTH 20-Aug-2011 HRS 0		11500		11500	8086.9
4-12-MS	INSPECTION DOCUMENT MS				MTH 20-Aug-2011 HRS 0		12000		12000	8586.9
4-12-MT	INSPECTION DOCUMENT MT				HRS		7400		7400	3986.9
4-12-MU	INSPECTION DOCUMENT MU				MTH 20-Aug-2011 HRS 0		12000		12000	8586.9
4-12-MV	INSPECTION DOCUMENT MV				MTH 20-Aug-2011 HRS 0		9000		9000	5586.9
4-12-MW	INSPECTION DOCUMENT MW				MTH 20-Aug-2011 HRS 0		9000		9000	5586.9
4-12-MX	INSPECTION DOCUMENT MX				MTH 20-Aug-2011 HRS 0		6000		6000	2586.9
4-12-MY	INSPECTION DOCUMENT MY				MTH 20-Aug-2011 HRS 0		12000		12000	8586.9



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
4-12-MZ	INSPECTION DOCUMENT MZ			MTH 20-Aug-2011 HRS 0		24600		24600	21186.9
050001	PERFORM CAMP AUDIT	KTPA		MTH 31-Aug-2023 HRS 3313.3 LDG 2449		6		29-Feb-2024	3 m 12 d
052501	PERFORM EMERGENCY FLARE INSPECTION	KTPA		MTH 13-Dec-2022 HRS 2932.8 LDG 2182		12		31-Dec-2023	1 m 14 d
055001	CHECK AFTER HARD/OVERWEIGHT LANDING			MTH 20-Aug-2011		A/R			
055002	CHECK AFTER OVERSPEED CONDITION			MTH 20-Aug-2011		A/R			
055003	CHECK AFTER DANGEROUS AIR TURBULENCE OR UNAPPROVED MANEUVERS			MTH 20-Aug-2011		A/R			
055004	CHECK AFTER LIGHTNING STRIKE			MTH 20-Aug-2011		A/R			
055005	CHECK FOREIGN OBJECT DAMAGE			MTH 20-Aug-2011		A/R			
055006	CHECK AFTER TOWING WITH LARGE FUEL UNBALANCE OR A HIGH DRAG/SIDE LOAD DUE TO GROUND HANDLING CHECK			MTH 20-Aug-2011		A/R			
5-12-01	INSPECTION DOCUMENT 1	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		300		3599.4	186.3
5-12-05	INSPECTION DOCUMENT 5	KTPA		MTH 13-Dec-2022 HRS 2932.8 LDG 2182		12		31-Dec-2023	1 m 14 d
B262002 CABIN	CABIN PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK	KTPA	C352TS X-690022	MTH 13-Dec-2022		12		31-Dec-2023	1 m 14 d
B262002 COCKPIT	COCKPIT PORTABLE FIRE EXTINGUISHER - FUNCTIONAL CHECK	KTPA	C352TS X-690031	MTH 13-Dec-2022		12		31-Dec-2023	1 m 14 d
B342100	CAPACITY TEST STANDBY GYRO POWER SUPPLY PS-855 (LEAD ACID)	KTPA	501-1712-01 80029	MTH 13-Dec-2022 HRS 2932.8 LDG 2182		12		31-Dec-2023	1 m 14 d
5-12-06	INSPECTION DOCUMENT 6 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 20-Aug-2011		24			
5-12-07	INSPECTION DOCUMENT 7 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		36			
B236001	FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		36		31-Aug-2026	33 m 14 d
5-12-08	INSPECTION DOCUMENT 8	KTPA		MTH 19-Jun-2023 HRS 3245.9 LDG 2395		48		30-Jun-2027	43 m 13 d
5-12-09	INSPECTION DOCUMENT 9	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		72		31-Aug-2029	69 m 14 d
5-12-11	INSPECTION DOCUMENT 11	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		12 300		31-Aug-2024 3599.4	9 m 14 d 186.3



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-12	INSPECTION DOCUMENT 12	KTPA			MTH 15-May-2023		24		31-May-2025	18 m 14 d
					HRS 3189.4		600		3789.4	376.3
					LDG 2358					
5-12-14	INSPECTION DOCUMENT 14	KTPA			MTH 25-Aug-2023		24		31-Aug-2025	21 m 14 d
					HRS 3299.4		1200		4499.4	1086.3
					LDG 2439					
5-12-16	INSPECTION DOCUMENT 16	KTPA			MTH 28-Jun-2023		48		30-Jun-2027	43 m 13 d
					HRS 3245.9		2400		5645.9	2232.8
					LDG 2295					
5-12-17	INSPECTION DOCUMENT 17 (INTERVAL CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA			MTH 25-Aug-2023		12			
					HRS 3299.4					
					LDG 2439					
A256001	ELT TRANSMITTER DETAILED INSPECTION (INTERVAL CFR 91.207)	KTPA		453-5060	MTH 25-Aug-2023		12		31-Aug-2024	9 m 14 d
				09678	HRS 3299.4					
					LDG 2439					
B256001	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (INTERVAL CFR 91.207)	KTPA		453-5060	MTH 25-Aug-2023		12		31-Aug-2024	9 m 14 d
				09678	HRS 3299.4					
					LDG 2439					
5-12-18	INSPECTION DOCUMENT 18 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA			MTH 28-Mar-2023		24			
341055	NO. 1 AIR DATA COMPUTER CALIBRATION TEST	KTPA		822-1109-143	MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
NO. 1				4815W						
341056	NO. 2 AIR DATA COMPUTER CALIBRATION TEST	KTPA		822-1109-143	MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
NO. 2				4818B						
341057	STANDBY AIR DATA COMPUTER CALIBRATION TEST	KTPA		9200-30000-068	MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
STANDBY				5016						
341060	INSPECT RVSM SKIN WAVINESS	KTPA			MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
B341001	FUNCTIONAL CHECK PITOT STATIC SYSTEM (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	KTPA			MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
LEFT										
B345001	CALIBRATION CHECK TRANSPONDER (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	KTPA		622-9210-501	MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
NO. 1				3V40J						
B345001	CALIBRATION CHECK TRANSPONDER (AIRPLANES -0001 THRU -0056 AND -0058 THRU -0450)	KTPA		622-9210-501	MTH 28-Mar-2023		24		31-Mar-2025	16 m 14 d
NO. 2				491CF						
5-12-22	INSPECTION DOCUMENT 22	KTPA			MTH 25-Aug-2023		36		31-Aug-2026	33 m 14 d
					HRS 3299.4		1200		4499.4	1086.3
					LDG 2439					
5-12-23	INSPECTION DOCUMENT 23	KTPA			MTH 25-Aug-2023		24		31-Aug-2025	21 m 14 d
					HRS 3299.4		300		3599.4	186.3
					LDG 2439					
5-12-24	INSPECTION DOCUMENT 24 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA			MTH 25-Aug-2023		36			
					HRS 3299.4		1200			
					LDG 2439					
A561001	WINDSHIELD OPTICAL PRISM INSPECTION	KTPA			MTH 25-Aug-2023		36		31-Aug-2026	33 m 14 d
					HRS 3299.4		1200		4499.4	1086.3
					LDG 2439					



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-32	INSPECTION DOCUMENT 32 (NDI INTERVAL) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA		MTH 01-Dec-2022 HRS 2914 LDG 2171		T/C			
A324103 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	KTPA	3-1607-1 2714	MTH 01-Dec-2022 HRS 2914 LDG 2171		T/C			
A324103 NOSE LANDING GEAR	NOSE MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	KTPA	3-1418 8648	MTH 15-Nov-2023 HRS 3404.9 LDG 2516		T/C			
A324103 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY SPECIAL DETAILED INSPECTION (NDI INTERVAL)	KTPA	3-1607-1 2515	MTH 01-Dec-2022 HRS 2914 LDG 2171		T/C			
5-12-35	INSPECTION DOCUMENT 35 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA		MTH 17-Nov-2022 HRS 2891.9 LDG 2154		12 600			
A243301	CAPACITY CHECK BATTERY (LEAD ACID)	KTPA	S3597-8 70020449	MTH 17-Nov-2022 HRS 2891.9 LDG 2154		12 600		30-Nov-2023 3491.9	13 d 78.8
5-12-38	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439		6			
B342101	PS-855 (LEAD ACID) STANDBY GYRO BATTERY PACK PERIODIC TEST	KTPA	501-1712-01 80029	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		6		29-Feb-2024	3 m 12 d
5-12-39	INSPECTION DOCUMENT 39			MTH 20-Aug-2011 HRS 0		5000		5000	1586.9
5-12-40	INSPECTION DOCUMENT 40	KTPA		MTH 19-Jun-2023 HRS 3245.9 LDG 2395		6		31-Dec-2023	1 m 14 d
5-12-41	INSPECTION DOCUMENT 41	KTPA		MTH 25-Aug-2023 HRS 3299.4 LDG 2439 ACH 1327.7		500		1827.7	500
5-12-42	INSPECTION DOCUMENT 42					N/A			
5-12-43	INSPECTION DOCUMENT 43			MTH HRS		7200		9007	5593.9
052001 E1	FJ44 CHECK 1	KTPA		MTH 16-Jun-2023 HRS 3242.8 LDG 2393		300		(3542.8)3542.8	129.7
052001 E2	FJ44 CHECK 1	KTPA		MTH 16-Jun-2023 HRS 3242.8 LDG 2393		300		(3542.8)3542.8	129.7
052002 E1	FJ44 CHECK 2	KTPA		MTH 06-Dec-2022 HRS 2923.3 LDG 2176		600		(3523.3)3523.3	110.2
052002 E2	FJ44 CHECK 2	KTPA		MTH 06-Dec-2022 HRS 2923.3 LDG 2176		600		(3523.3)3523.3	110.2



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052003 E1	FJ44 CHECK 3			MTH HRS	20-Aug-2011 0		3500		(3500)3500	86.9
052003 E2	FJ44 CHECK 3			MTH HRS	20-Aug-2011 0		3500		(3500)3500	86.9
052004 E1	FJ44 CHECK 4			MTH HRS	20-Aug-2011 0		5000		(5000)5000	1586.9
052004 E2	FJ44 CHECK 4			MTH HRS	20-Aug-2011 0		5000		(5000)5000	1586.9
052005 E1	FJ44 CHECK 5			MTH HRS	20-Aug-2011 0		8500		(8500)8500	5086.9
052005 E2	FJ44 CHECK 5			MTH HRS	20-Aug-2011 0		8500		(8500)8500	5086.9
052006 E1	FJ44 CHECK 6			MTH HRS	20-Aug-2011 0		10000		(10000)10000	6586.9
052006 E2	FJ44 CHECK 6			MTH HRS	20-Aug-2011 0		10000		(10000)10000	6586.9
052007 E1	FJ44 CHECK 7			MTH HRS	20-Aug-2011 0		13500		(13500)13500	10086.9
052007 E2	FJ44 CHECK 7			MTH HRS	20-Aug-2011 0		13500		(13500)13500	10086.9
052008 E1	FJ44 CHECK 8			MTH HRS	20-Aug-2011 0		15000		(15000)15000	11586.9
052008 E2	FJ44 CHECK 8			MTH HRS	20-Aug-2011 0		15000		(15000)15000	11586.9
052009 E1	FJ44 CHECK 9			MTH HRS	20-Aug-2011 0		18500		(18500)18500	15086.9
052009 E2	FJ44 CHECK 9			MTH HRS	20-Aug-2011 0		18500		(18500)18500	15086.9
052010 E1	FJ44 CHECK 10			MTH HRS	20-Aug-2011 0		20000		(20000)20000	16586.9
052010 E2	FJ44 CHECK 10			MTH HRS	20-Aug-2011 0		20000		(20000)20000	16586.9
057199 E2	INSPECTION OF THE CHIP DETECTOR KTPA			MTH HRS LDG	12-Jul-2023 3264.6 2411		-			
050800	PERFORM AIRCRAFT WEIGH TPA			MTH HRS LDG	10-Jan-2022 2603.1 1948		36		31-Jan-2025	14 m 14 d
12-23-00-601	15 DAY HIGH EXPOSURE AREA WASH -AIRPLANE ZONE 1 WASH KSWF			MTH HRS LDG	22-Apr-2020 2264.4 1754		A/R			
12-23-00-602	45 DAY MEDIUM EXPOSURE AREA WASH -AIRPLANE ZONE 2 WASH KSWF			MTH HRS LDG	22-Apr-2020 2264.4 1754		A/R			
12-23-00-603	90 DAY LOW EXPOSURE AREA WASH -AIRPLANE ZONE 3 WASH KSWF			MTH HRS LDG	22-Apr-2020 2264.4 1754		A/R			
215018	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES KTPA			MTH HRS LDG ACH	01-Nov-2022 2880.9 2146 755		800		1555	227.3



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052500	REPLACE D-CELL LED FLASHLIGHT BATTERIES	KTPA			MTH 13-Dec-2022 HRS 2932.8 LDG 2182		12		31-Dec-2023	1 m 14 d
052560 CABIN	PERFORM PORTABLE FIRE EXTINGUISHER INSPECTION	KMCO			DAYS 30-Oct-2023 HRS 3373.8 LDG 2491		30		29-Nov-2023	12 d
052560 COCKPIT	PERFORM PORTABLE FIRE EXTINGUISHER INSPECTION	KMCO			DAYS 30-Oct-2023 HRS 3373.8 LDG 2491		30		29-Nov-2023	12 d
262002A LEFT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KTPA		AE13083-5 8752	MTH 21-Jul-2022		96		31-Jul-2030	80 m 14 d
262002A LEFT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KTPA		AE13083-5 8753	MTH 21-Jul-2022		96		31-Jul-2030	80 m 14 d
262002A RIGHT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KTPA		AE13083-5 8750	MTH 21-Jul-2022		96		31-Jul-2030	80 m 14 d
262002A RIGHT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KTPA		AE13083-5 8755	MTH 21-Jul-2022		96		31-Jul-2030	80 m 14 d
262002B LEFT ENGINE NO.1	REPLACE LEFT ENGINE NO.1 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KTPA		AE13083-5 8752	MTH 01-Mar-2022		72		01-Mar-2028	51 m 13 d
262002B LEFT ENGINE NO.2	REPLACE LEFT ENGINE NO. 2 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KTPA		AE13083-5 8753	MTH 13-Jun-2022		72		13-Jun-2028	54 m 27 d
262002B RIGHT ENGINE NO.1	REPLACE RIGHT ENGINE NO.1 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KTPA		AE13083-5 8750	MTH 01-Mar-2022		72		01-Mar-2028	51 m 13 d
262002B RIGHT ENGINE NO.2	REPLACE RIGHT ENGINE NO.2 FIRE EXTINGUISHER (REPLACE) CARTRIDGE (TOTAL LIFE)	KTPA		AE13083-5 8755	MTH 01-Mar-2022		72		01-Mar-2028	51 m 13 d
A262002 CABIN	CABIN PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION	KSWF		C352TS X-690022	MTH 30-Jan-2020		72		31-Jan-2026	26 m 14 d
A262002 COCKPIT	COCKPIT PORTABLE FIRE EXTINGUISHER SPECIAL DETAILED INSPECTION	KSWF		C352TS X-690031	MTH 30-Jan-2020		72		31-Jan-2026	26 m 14 d
D262001 LEFT	LEFT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)	UNK		30401102-2 65126B1	MTH 31-Aug-2020		60		31-Aug-2025	21 m 14 d
D262001 RIGHT	RIGHT ENGINE FIRE EXTINGUISHER BOTTLE RESTORATION (HYDROSTATIC TEST)	UNK		30401102-2 65125B1	MTH 31-Aug-2020		60		31-Aug-2025	21 m 14 d
D262003 CABIN	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER	KSWF		C352TS X-690022	MTH 30-Jan-2020		144		31-Jan-2032	98 m 14 d
D262003 COCKPIT	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER	KSWF		C352TS X-690031	MTH 30-Jan-2020		144		31-Jan-2032	98 m 14 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)	KTPA			MTH 25-Aug-2023 HRS 3299.4 LDG 2439		3		30-Nov-2023	13 d
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				A/R					



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
312001A LEFT	REPLACE DIGITAL CLOCK BATTERY	KTPA		M877A5V 20651	MTH 21-Jul-2022 HRS 2732.3 LDG 2033		12		01-Mar-2031	87 m 12 d
B323101	HYDROSTATIC TEST EMERGENCY PNEUMATIC STORAGE BOTTLE	KTPA		40005320-2 5471	MTH 18-Jul-2023		36		31-Jul-2026	32 m 14 d
33-50-00-960 LEFT	AFT LEFT EMERGENCY LIGHTING BATTERY PACK RESTORATION			CBS28-1 2132M	MTH 20-Aug-2011		48		30-Jun-2026	31 m 13 d
33-50-00-960 RIGHT	FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK RESTORATION			CBS28-1 006245	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		48		30-Jun-2026	31 m 13 d
B351002	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER AND REGULATOR ASSEMBLY	UNK		176276-50 435729703	MTH 28-Aug-2020		60		31-Aug-2025	21 m 14 d
571050 LEFT WING	INSPECT MAIN SPAR, WS 183.50				MTH 20-Aug-2011 HRS 0		10000		10000	6586.9
571055 RIGHT WING	INSPECT MAIN SPAR, WS 183.50				MTH 20-Aug-2011 HRS 0		10000		10000	6586.9
571080 LEFT WING	INSPECT MAIN SPAR SPLICE, WS 132.00				MTH 20-Aug-2011 HRS 0		9500		9500	6086.9
571085 RIGHT WING	INSPECT MAIN SPAR SPLICE, WS 132.00				MTH 20-Aug-2011 HRS 0		9500		9500	6086.9
057102 ENG1	COMPRESSOR WASH	KTPA			MTH 16-Jun-2023 HRS 3242.8 LDG 2393		200		3442.8	29.7
057102 ENG2	COMPRESSOR WASH	KTPA			MTH 16-Jun-2023 HRS 3242.8 LDG 2393		200		3442.8	29.7
712003 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT (INSPECTION)			LM-605-SA11 LK3081	HRS		5000		5000	1586.9
712003 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK2499	HRS		5000		5000	1586.9
712003 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK2475	HRS		5000		5000	1586.9
712003 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (INSPECTION)			LM-605-SA10 LK3147	HRS		5000		5000	1586.9
712003 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK2476	HRS		5000		5000	1586.9
712003 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (INSPECTION)			LM-605-SA8 LK2464	HRS		5000		5000	1586.9
710003 E1	RINSE DESALINIZATION	KSWF			MTH 18-Jul-2021 HRS 2547.2 LDG 1915		A/R			
710003 E2	RINSE DESALINIZATION	KSWF			MTH 18-Jul-2021 HRS 2547.2 LDG 1915		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
710030 E1	POLISH FAN ROTOR				MTH 20-Aug-2011		A/R			
710030 E2	POLISH FAN ROTOR				MTH 20-Aug-2011		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211001 LEFT	PRESS SHUTOFF VALVE	KTPA		5253-00-3 1927B	MTH 17-Nov-2022 HRS 2891.9 LDG 2145		O/C	0 0 0		
211001 RIGHT	PRESS SHUTOFF VALVE	KTPA		5253-00-3 4177B	MTH 17-Nov-2022 HRS 2891.9 LDG 2145		O/C	0 0 0		
211002 LEFT	VARIABLE VALVE	KTPA		2601-32 1229	MTH 17-Nov-2022 HRS 2891.9 LDG 2145		O/C	0 0 0		
211002 RIGHT	VARIABLE VALVE	KTPA		2601-32 0666	MTH 17-Nov-2022 HRS 2891.9 LDG 2145		O/C	0 0 0		
211003	HEAT PRESS EXCHANGER			10905A 453	MTH 20-Aug-2011		O/C	0		
211005	EMER PRESS SHUTOFF VALVE			2601-23 9912422-2 1184	MTH 20-Aug-2011		O/C	0		
211006 NO.1	A/C CHECK VALVE			7125-320101 9912078-9 NSN	MTH 20-Aug-2011		O/C	0		
211006 NO.2	A/C CHECK VALVE			7125-320101 9912078-9 NSN	MTH 20-Aug-2011		O/C	0		
211006 NO.3	A/C CHECK VALVE			7125-320101 9912078-9 NSN	MTH 20-Aug-2011		O/C	0		
212001	BAGGAGE CMPT BLOWER			0113-12 1956	MTH 20-Aug-2011		O/C	0		
212003	THERMO AIR DIST SWITCH			1173T42-1 4177	MTH 20-Aug-2011		O/C	0		
212302	W/S AIR BLOWER MOTOR			7003-200 1723	MTH 20-Aug-2011		O/C	0		
212303	BLDC MOTOR ASSEMBLY BLOWER			1133270-2 SN-UNKNOWN	MTH 20-Aug-2011		O/C	0		
213001	PRIMARY OUTFLOW VALVE			52771-339 9912409-21 1148B	MTH 20-Aug-2011		O/C	0		
213002	SEC OUTFLOW VALVE			52772-339 9912409-22 1166B	MTH 20-Aug-2011		O/C	0		
213003	PRESSURIZATION CONTROLLER			52770-116 9912409-13 3316	MTH 20-Aug-2011		O/C	0		
213004 NO.1	SOLENOID BAGGAGE VALVE			5060-00-1 4072	MTH 20-Aug-2011		O/C	0		
213004 NO.2	SOLENOID BAGGAGE VALVE			5060-00-1 4084	MTH 20-Aug-2011		O/C	0		
213005	DIFF PRESS INDICATOR			C668511-0106 3001J73 24751	MTH 20-Aug-2011		O/C	0		
213008	MANUAL PRESSURE SWITCH			52773-001 9912409-4 2513	MTH 20-Aug-2011		O/C	0		
215000 AFT	EVAPORATOR BLOWER MOTOR			1133210-7 1327	MTH 20-Aug-2011		O/C	0		
215000 FWD	EVAPORATOR BLOWER MOTOR	KTPA		1260185-1 2327	MTH 03-Apr-2023 HRS 3094.2 LDG 2283		O/C	0 0 0		
215001	FWD EVAPORATOR MODULE			1134300-3 9912583-9 860	MTH 20-Aug-2011		O/C	0		
215002	AFT EVAPORATOR MODULE			1134820-15 9912583-10 976	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215003	COMPRESSOR DRIVE MOTOR KTPA			1134146-1 994A	MTH 01-Nov-2022 HRS 2880.9 LDG 2146		O/C	0 0 0		
215004	COMPRESSOR DRIVE ASSEMBLY 9912583-6	KTPA		1134610-1 722	MTH 01-Nov-2022 HRS 2880.9 LDG 2146		O/C	0 0 0		
215005	CONDENSER ASSEMBLY 9912583-7			1134620-3 563	MTH 20-Aug-2011		O/C	0		
215006	BINARY SWITCH			1250232-10 NSN	MTH 20-Aug-2011		O/C	0		
215007	DRYER ASSY RECEIVER 9912583-3			1134275-1 NSN	MTH 20-Aug-2011		O/C	0		
215008	COMPRESSOR ASSEMBLY			1134130-5 1061	MTH 20-Aug-2011		O/C	0		
215009	VANE AXIAL BLOWER ASSY KTPA			1250435-10 556B	MTH 16-Jun-2023 HRS 3242.8 LDG 2393		O/C	0 0 0		
215010	A/C FLIGHT HOURMETER			1250703-3 NSN	MTH 20-Aug-2011		O/C	0		
215011	AIR CONDITIONER DRIVE BELT KTPA			225L100 NSN	MTH 01-Nov-2022 HRS 2880.9 LDG 2146		O/C			
216001	RAM AIR MOD VALVE			27241287-24 3BG11	MTH 20-Aug-2011		O/C	0		
216002	TEMP CONTROLLER	KSWF		1E58-7 1BR6	MTH 12-Oct-2018 HRS 2011.9 LDG 1596		O/C	0 0 0		
216003 AFT	CABIN TC007 SENSOR 9912085-3			27221274 3BE19	MTH 20-Aug-2011		O/C	0		
216003 FORWARD	COCKPIT UT006 SENSOR 9912085-3			27221274 11BF24	MTH 20-Aug-2011		O/C	0		
221002 AILERON	SERVO MOUNT SMT-65			622-5735-021 46LFY	MTH 20-Aug-2011		O/C	0		
221002 ELEVATOR	SERVO MOUNT			622-5735-023 46LCL	MTH 20-Aug-2011		O/C	0		
221002 RUDDER	SERVO MOUNT SMT-65			622-5735-022 46N7H	MTH 20-Aug-2011		O/C	0		
221003 AILERON	SERVO SVO-3000			822-1168-002 46MBR	MTH 20-Aug-2011		O/C	0		
221003 ELEVATOR	SERVO SVO-3000			822-1168-001 46LGP	MTH 20-Aug-2011		O/C	0		
221003 RUDDER	SERVO SVO-3000			822-1168-001 46L2Y	MTH 20-Aug-2011		O/C	0		
221004	AUTOPILOT PANEL			622-6208-223 3YF2N	MTH 20-Aug-2011		O/C	0		
231006 NO.1	VHF COMM TRANSCEIVER			822-1468-110 45WTW	MTH 20-Aug-2011		O/C	0		
231006 NO.2	VHF COMM TRANSCEIVER			822-1468-110 45WTT	MTH 20-Aug-2011		O/C	0		
231007 NO.1	COMM ANTENNA			VC10-126-1 0757	MTH 20-Aug-2011		O/C	0		
231007 NO.2	COMM ANTENNA			VFS10-90-2 8313	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232001 #2	AIRCELL ATG ANTENNA --	KMCO		P12949 703903	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
232001	AIRCELL ATG ANTENNA --	KMCO		P12949 703902	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
232003	TELEPHONE TRANSCEIVER ST-3100 AIRCELL			400-10680-002 1068021919	MTH 20-Aug-2011		O/C	0		
232007 CABIN	AIRCELL FLITEFONE HANDSET *CF			P12199-002 1219953158	MTH 30-Jun-2011		O/C	0		
232007 CREW	AIRCELL FLITEFONE HANDSET KSWF			P12199-002 1219910576	MTH 20-Dec-2013 HRS 753.8 LDG 592		O/C			
232012	AIRCELL CONFIGURATION MODULE --	KMCO		P14126 1412627872	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233201	ADVANCE GOGO PROCESSOR KTPA			P34110-003 341100030241E	MTH 19-Sep-2023 HRS 3329.8 LDG 2460		O/C	3 0		
233203 AFT	MODEM ANTENNA	KMCO		P18350-001 1835010708	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233203 FWD	MODEM ANTENNA	KMCO		P18350-001 1835009107	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 1	WIFI ANTENNA	KMCO		P16917-001 1691700125247	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 2	WIFI ANTENNA	KMCO		P16917-001 1691700125239	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 3	WIFI ANTENNA	KMCO		P16917-001 1691700124415	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 4	WIFI ANTENNA	KMCO		P16917-001 1691700124412	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 5	WIFI ANTENNA	KMCO		P16917-001 1691700124432	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
233204 NO. 6	WIFI ANTENNA	KMCO		P16917-001 1691700123911	MTH 10-Feb-2023 HRS 3017.6 LDG 2225		O/C	0 0 0		
235001	AUDIO AMPLIFIER			102025-2 5630111	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
235068 NO.1	AUDIO CONTROL PANEL RADIO ACP-4130 W/HF & ADF 1KSWF			822-2381-230 48PXK	MTH 07-Apr-2018 HRS 1918.7 LDG 1547		O/C			
235068 NO.2	AUDIO CONTROL PANEL RADIO ACP-4130 W/HF & ADF 1KTPA			822-2381-230 4T0XH	MTH 24-Jul-2023 HRS 3285.7 LDG 2428		O/C	0 0		
237003	CVR MICROPHONE			S055-0067-00 000595876	MTH 20-Aug-2011		O/C	0		
237004	IMPACT CVR SWITCH			6895-D-2-X-5-5 8546	MTH 20-Aug-2011		O/C	0		
243003 LEFT	GENERATOR CONTROL UNIT KTPA			51525-001F P4332	MTH 06-Mar-2023 HRS 3048.1 LDG 2249		O/C			
243003 RIGHT	GENERATOR CONTROL UNIT			51525-001F P5343	MTH 20-Aug-2011		O/C	0		
243004	BATTERY TEMP MONITOR-			1529-1-1 A365	MTH 20-Aug-2011		O/C	0		
243006 LEFT	GEN LOAD AMMETER C662501-0107			MD130-7 L1011103	MTH 20-Aug-2011		O/C	0		
243006 RIGHT	GEN LOAD AMMETER C662501-0107			MD130-7 L1011105	MTH 20-Aug-2011		O/C	0		
243007	BATTERY	KTPA		S3597-8 70020449	MTH 17-Nov-2022 HRS 2891.9 LDG 2154		O/C	0 0		
243008	RELAY-BATTERY			A931F 1257	MTH 20-Aug-2011		O/C	0		
243010	BATTERY TEMP SENSOR KMCO			29783-003 100721-013	MTH 09-Dec-2021 HRS 2602 LDG 1946		O/C	0 0 0		
243011	DC POWER VOLTMETER C662502-0101			MD129-1 L1010385	MTH 20-Aug-2011		O/C	0		
245001 LEFT	START CONTROL PCB			6318038-1 1026	MTH 20-Aug-2011		O/C	0		
245001 RIGHT	START CONTROL PCB KMSN			6318038-1 1976	MTH 26-May-2019 HRS 2103 LDG 1650		O/C	0 0 0		
245002 LEFT	FUEL CONTROL PCB			6318037-6 8075	MTH 20-Aug-2011		O/C	0		
245002 RIGHT	FUEL CONTROL PCB			6318037-6 8076	MTH 20-Aug-2011		O/C	0		
245003 LEFT	IGNITOR CNTRL PCB			6318388-7 0376	MTH 20-Aug-2011		O/C	0		
245003 RIGHT	IGNITOR CNTRL PCB KBUR			6318388-7 0473	MTH 27-Jul-2012 HRS 317.7 LDG 233		O/C	0 0 0		
245004 LEFT	ANTI ICE PCB KSWF			6318342-30 856	MTH 18-Feb-2014 HRS 810.3 LDG 641		O/C	810.3 641		
245004 RIGHT	ANTI ICE PCB KSWF			6318342-30 855	MTH 18-Feb-2014 HRS 810.3 LDG 641		O/C	810.3 641		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245006	ENVIRONMENTAL PCB	KTPA		6318358-20 32180533-3	MTH 21-Oct-2022 HRS 2859.2 LDG 2127		O/C	0 0		
245007	HYDRAULIC PCB			6318035-7 0475	MTH 20-Aug-2011		O/C	0		
245008	TRIM RELAY PCB			6518351-9 1282	MTH 20-Aug-2011		O/C	0		
245010	GEAR LOGIC 1 PCB			6318398-6 0487	MTH 20-Aug-2011		O/C	0		
245011	FUEL FLOW PCB 9912417-3			85-230-2 0550359	MTH 20-Aug-2011		O/C	0		
245012	SPEEDBRAKE PCB	UNK		6318034-6 1071	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		O/C	0 0 0		
245014	GEAR LOGIC 2 PCB	KMSP		6318399-11 0267	MTH 03-Jan-2015 HRS 1076.8 LDG 891		O/C	0 0 0		
245015	GEAR MONITOR PCB			6318397-21 0558	MTH 20-Aug-2011		O/C	0		
245016	TAIL DEICE CONTROL PCB *CF			6318044-1 0561	MTH 19-Aug-2011		O/C	0		
245017	TAIL DEICE MONITOR PCB			6318043-1 0557	MTH 20-Aug-2011		O/C	0		
245018	PRESSURIZATION PCB			6318349-26 0240	MTH 20-Aug-2011		O/C	0		
245019	DIAGNOSTICS PCB ASSY			6318046-9 0237	MTH 20-Aug-2011		O/C	0		
250006	B&D CABIN DISPLAY	*CF		15003-00300 154970	MTH 30-Jun-2011		O/C	0		
250007	AVVISOR PROCESSOR UNIT *CF			90008-0031 43B00299	MTH 30-Jun-2011		O/C	0		
252099	ENTRY SWITCH PANEL *CF			101015-1 3830411	MTH 30-Jun-2011		O/C	0		
253099 101015-2	SWITCH PANEL *CF			101015-2 2350807	MTH 30-Jun-2011		O/C	0		
256001	ELT TRANSMITTER C406-N	UNK		453-5060 09678	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		O/C	109 2359.4 1805		
256002	ELT BEACON BATTERY PACK UNK			452-0133 384405-003	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		DUE DUE DUE DUE	9 0 0 0	01-Mar-2025	15 m 12 d
Expiration Date: 01-Mar-2025										
256003	REMOTE SWITCH			452-0010 NSN	MTH 20-Aug-2011		O/C	0		
256004	ELT ANTENNA C406-N			110-340 332432	MTH 20-Aug-2011		O/C	0		
256006 CO-PILOT	LIFE JACKET			P01074-207 21070650211	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 LAVATORY	LIFE JACKET			P01074-207 21070650218	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256006 NO. 3	LIFE JACKET			P01074-207 21070650212	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 NO. 4	LIFE JACKET			P01074-207 21070650213	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 NO. 5	LIFE JACKET			P01074-207 21070650214	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 NO. 6	LIFE JACKET			P01074-207 21070650215	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 NO. 7	LIFE JACKET			P01074-207 21070650216	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 NO. 8	LIFE JACKET			P01074-207 21070650217	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256006 PILOT	LIFE JACKET			P01074-207 21070650210	MTH 30-Aug-2021		DUE DUE	0	30-Aug-2031	93 m 13 d
Expiration Date: 30-Aug-2031										
256008	EMERGENCY FLARE -			ORION 865 SN-UNKNOWN	MTH		36		12-Dec-2024	12 m 25 d
261001 LEFT	ENGINE FIRE DETECTOR 9912416-1			3001-212-1004/455-9 211673	MTH 20-Aug-2011		O/C	0		
261001 RIGHT	ENGINE FIRE DETECTOR 9912416-1			3001-212-1004/455-9 211678	MTH 20-Aug-2011		O/C	0		
261002 AFT	SMOKE DETECTOR			473597-17 2129	MTH 20-Aug-2011		O/C	0		
261002 FORWARD	SMOKE DETECTOR			473597-17 2131	MTH 20-Aug-2011		O/C	0		
261002	SMOKE DETECTOR HEATER 9914772-1			76847-1 1353	MTH 20-Aug-2011		O/C	0		
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-6	UNK		30401102-2 65126B1	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		O/C	0 0 0		
262001 RIGHT	FIRE EXTINGUISHER BOTTLE 9912048-6	UNK		30401102-2 65125B1	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		O/C	0 0 0		
262002 LEFT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KTPA			AE13083-5 8752	MTH 21-Jul-2022 HRS 2732.3 LDG 2033		H/T H/T H/T	0 0		
262002 LEFT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KTPA			AE13083-5 8753	MTH 21-Jul-2022 HRS 2732.3 LDG 2033		H/T H/T H/T	0 0		
262002 RIGHT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KTPA			AE13083-5 8750	MTH 21-Jul-2022 HRS 2732.3 LDG 2033		H/T H/T H/T	0 0		
262002 RIGHT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KTPA			AE13083-5 8755	MTH 21-Jul-2022 HRS 2732.3 LDG 2033		H/T H/T H/T	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003 CABIN	PORTABLE FIRE EXTINGUISHER	KSWF		C352TS X-690022	MTH 31-Jan-2020 HRS 2237.4 LDG 1740		O/C	101 2228 1733		
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER			C352TS X-690031	MTH 31-Jan-2020 HRS 2237.4 LDG 1740		O/C	101 2228 1733		
270001 LEFT	SPEED BRAKE FILTER FITTING			20666-6-250 NSN	MTH 20-Aug-2011		O/C	0		
270001 RIGHT	SPEED BRAKE FILTER FITTING			20666-6-250 NSN	MTH 20-Aug-2011		O/C	0		
271003 LEFT	AILERON ASSEMBLY	KTPA		6324301-3 SN-UNKNOWN	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		O/C			
272001	RUDDER BIAS SHUTOFF VALVE			5307-1 1668C	MTH 20-Aug-2011		O/C	0		
273001	CONTROL SHAKER			201 8687	MTH 20-Aug-2011		O/C	0		
273002	ELEV TRIM SERVO			44430-3548 T1604	MTH 20-Aug-2011		O/C	0		
273003	ACTUATOR MOUNT ASSEMBLY			44575-3415 T2580	MTH 20-Aug-2011		O/C	0		
273007 LEFT	ELEVATOR ASSEMBLY	KTPA		6334400-3 SN-UNKNOWN	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		O/C			
273008 RIGHT	ELEVATOR ASSEMBLY	KTPA		6334400-4 0000348	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		O/C	143 3299		
275001	SHUTOFF VALVE			4083-1 997	MTH 20-Aug-2011		O/C	0		
275002 LEFT	FLAP ACTUATOR			2-8210-2 9912365-6 1064	MTH 20-Aug-2011		O/C	0		
275002 RIGHT	FLAP ACTUATOR			2-8210-2 9912365-6 1074	MTH 20-Aug-2011		O/C	0		
276001 LEFT	SPEED BRAKE ACTUATOR			2-8209-2 9912375-5 1081	MTH 20-Aug-2011		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR			2-8209-2 9912375-5 1082	MTH 20-Aug-2011		O/C	0		
281001 LEFT	SURGE TANK FLOAT VALVE			35C10D 9912016-2 5182	MTH 20-Aug-2011		O/C	0		
281001 RIGHT	SURGE TANK FLOAT VALVE			35C10D 9912016-2 5143	MTH 20-Aug-2011		O/C	0		
282001 LEFT	FUEL BOOST PUMP			1C7-23 9912553-1 1BF14	MTH 20-Aug-2011		O/C	0		
282001 RIGHT	FUEL BOOST PUMP			1C7-23 9912553-1 11BE201	MTH 20-Aug-2011		O/C	0		
282002 LEFT AFT	EJECTOR FUEL AFT/SCAVENG PUMP			RG45880 9912190-3 B3123	MTH 20-Aug-2011		O/C	0		
282002 LEFT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP			RG45880 9912190-3 B3129	MTH 20-Aug-2011		O/C	0		
282002 RIGHT AFT	EJECTOR FUEL AFT/SCAVENG PUMP			RG45880 9912190-3 B3130	MTH 20-Aug-2011		O/C	0		
282002 RIGHT FORWARD	EJECTOR FUEL FWD/SCAVENG PUMP			RG45880 9912190-3 B3127	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282004 LEFT	FUEL MOTOR VALVE 9912014-3			AV24B1507 AA273878	MTH 20-Aug-2011		O/C	0		
282004 RIGHT	FUEL MOTOR VALVE 9912014-3			AV24B1507 AA273874	MTH 20-Aug-2011		O/C	0		
282005 LEFT	EJECTOR FUEL PRIMARY PUMP 9912190-2			RG45310 C2624	MTH 20-Aug-2011		O/C	0		
282005 RIGHT	EJECTOR FUEL PRIMARY PUMP 9912190-2			RG45310 C2636	MTH 20-Aug-2011		O/C	0		
282006	TRANSFER VALVE 9914103-6			ZSV57 100521388	MTH 20-Aug-2011		O/C	0		
284001 LEFT	#5 UL005 FUEL PROBE 9912589-5			10664T05Y00 MN17011	MTH 20-Aug-2011		O/C	0		
284001 RIGHT	#5 UR005 FUEL PROBE 9912589-5			10664T05Y00 MN17010	MTH 20-Aug-2011		O/C	0		
284002 LEFT	#6 UL006 FUEL PROBE 9912589-6			10664T06Y00 MN25875	MTH 20-Aug-2011		O/C	0		
284002 RIGHT	#6 UR006 FUEL PROBE 9912589-6			10664T06Y00 MN17946	MTH 20-Aug-2011		O/C	0		
284003	FUEL QTY SIGNAL CONDITIONER 9912619-1			10713B01Y01 99030454	MTH 20-Aug-2011		O/C	0		
284004 LEFT	#3 UL003 FUEL PROBE 9912589-3			10664T03Y00 MN23871	MTH 20-Aug-2011		O/C	0		
284004 RIGHT	#3 UR003 FUEL PROBE 9912589-3			10664T03Y00 MN23098	MTH 20-Aug-2011		O/C	0		
284005 LEFT	#4 UL004 FUEL PROBE 9912589-4			10664T04Y00 MN25332	MTH 20-Aug-2011		O/C	0		
284005 RIGHT	#4 UR004 FUEL PROBE 9912589-4			10664T04Y00 MN24872	MTH 20-Aug-2011		O/C	0		
284006 LEFT	#2 UL002 FUEL PROBE 9912589-2			10664T02Y00 MN25936	MTH 20-Aug-2011		O/C	0		
284006 RIGHT	#2 UR002 FUEL PROBE 9912589-2			10664T02Y00 MN25993	MTH 20-Aug-2011		O/C	0		
284007 LEFT	#1 UL001 FUEL PROBE 9912589-1			10664T01Y00 MN26006	MTH 20-Aug-2011		O/C	0		
284007 RIGHT	#1 UR001 FUEL PROBE 9912589-1			10664T01Y00 MN26007	MTH 20-Aug-2011		O/C	0		
284008 LEFT	FUEL LOW LEVEL SWITCH 1521			L16H-14 1521	MTH 20-Aug-2011		O/C	0		
284008 RIGHT	FUEL LOW LEVEL SWITCH 1486			L16H-14 1486	MTH 20-Aug-2011		O/C	0		
284010 LEFT	FUEL QUANTITY TRANSMITTER 9912556-6			10634T11Y00 MN19605	MTH 20-Aug-2011		O/C	0		
284010 RIGHT	FUEL QUANTITY TRANSMITTER 9912556-6			10634T11Y00 MN26006	MTH 20-Aug-2011		O/C	0		
291002 LEFT	HYDRAULIC PUMP 9912062-6			24195-LAC 1886	MTH 20-Aug-2011		O/C	0		
291002 RIGHT	HYDRAULIC PUMP 9912062-6			24195-LAC 2354	MTH 20-Aug-2011		O/C	0		
291005	HYDRAULIC RESERVOIR ASSEMBLY			6317500-16-1 044	MTH 20-Aug-2011		O/C	0		
291006	LOADING VALVE 9912423-39			4134-4 1522	MTH 20-Aug-2011		O/C	0		
291007	PRESSURE SWITCH GAUGE 9912373-6			GPP1250-301 1024265	MTH 20-Aug-2011		O/C	0		
291008	HYD MANIFOLD ASSEMBLY 9912423-48			8250-3 0681	MTH 20-Aug-2011		O/C	0		
291009	RELIEF VALVE			2R4120 NSN	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
291010 LEFT	SHUTOFF VALVE 9912400-4			AV24B1388-2 AA268466	MTH 20-Aug-2011		O/C	0		
291010 RIGHT	SHUTOFF VALVE 9912400-4			AV24B1388-2 AA268467	MTH 20-Aug-2011		O/C	0		
291011 LEFT	FLOW SWITCH VALVE 9912194-5			V10F75 1160A	MTH 20-Aug-2011		O/C	0		
291011 RIGHT	FLOW SWITCH VALVE	KTPA		9912194-6 431	MTH 17-Nov-2022 HRS 2891.9 LDG 2145		O/C	0 0 0		
291012	SPDBK DUMP VALVE 9912423-33			4082-6 1118	MTH 20-Aug-2011		O/C	0		
291013	RELIEF, SYSTEM VALVE 9912423-46			2576-2 1255A	MTH 20-Aug-2011		O/C	0		
291014	VALVE-GEAR 9912423-44			4051-4 1083	MTH 20-Aug-2011		O/C	0		
291016 LEFT	SPDBK CHECK VALVE 9912423-31			9505-1 2211	MTH 20-Aug-2011		O/C	0		
291016 RIGHT	SPDBK CHECK VALVE 9912423-31			9505-1 2212	MTH 20-Aug-2011		O/C	0		
291017	THERM REL VALVE 9912423-32			2577-1 1129	MTH 20-Aug-2011		O/C	0		
291018	PNUEMATIC DUMP VALVE 9912423-34			9503-2 1118	MTH 20-Aug-2011		O/C	0		
291020	SPEED BRAKE VALVE 9912423-30			4052-3 1151	MTH 20-Aug-2011		O/C	0		
291021	FLAP VALVE 9912423-29			4052-4 1159	MTH 20-Aug-2011		O/C	0		
291022	CHECK VALVE			CV02-193 NSN	MTH 20-Aug-2011		O/C	0		
291023	GEAR VALVE SOLENOID			4051-4 NSN	MTH 20-Aug-2011		O/C	0		
301002 LEFT	PRESSURE SWITCH			1106P55-1 9022A	MTH 20-Aug-2011		O/C	0		
301002 RIGHT	PRESSURE SWITCH			1106P55-1 9017A	MTH 20-Aug-2011		O/C	0		
301003 LEFT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	KSWF		1H148-1 1BG10	MTH 22-Feb-2014 HRS 811 LDG 642		O/C	811 642		
301003 RIGHT	ANTI-ICE PRESSURE REGULATING VALVE 9914710-3	KSWF		1H148-1 1BG9	MTH 22-Feb-2014 HRS 811 LDG 642		O/C	811 642		
301004 LEFT	TEMPERATURE SWITCH			1050C H7539	MTH 20-Aug-2011		O/C	0		
301004 RIGHT	TEMPERATURE SWITCH			1050C H8034	MTH 20-Aug-2011		O/C	0		
301006 LEFT	HORIZONTAL STAB BOOT	KALN		P29S-4D5244-15 NDW7710	MTH 22-Sep-2017 HRS 1807 LDG 1479 ACH 478		O/C	0 0		
301006 RIGHT	HORIZONTAL STAB BOOT	KSWF		29S4D5244-16 NCZ3220	MTH 13-Nov-2016 HRS 1633.1 LDG 1375 ACH 416		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301007	ENG BLEED SHUTOFF VALVE 9914552-2			2602-43 0442	MTH 20-Aug-2011		O/C	0		
302001 LEFT	PRESS REG VALVE			5285-00-3 2629	MTH 20-Aug-2011		O/C	0		
302001 RIGHT	PRESS REG VALVE			5285-00-3 2632	MTH 20-Aug-2011		O/C	0		
302002 LEFT	INLET TEMP SWITCH			1173T0759 6253	MTH 20-Aug-2011		O/C	0		
302002 RIGHT	INLET TEMP SWITCH			1173T0759 6250	MTH 20-Aug-2011		O/C	0		
303002 LEFT	PITOT TUBE			PH1100-1-VBW 1590303	MTH 20-Aug-2011		O/C	0		
303002 RIGHT	PITOT TUBE			PH1100-1-VBW 1590307	MTH 20-Aug-2011		O/C	0		
303003 STANDBY	PITOT TUBE S2800-493			PH1100-RW-RIGHT 1482007	MTH 20-Aug-2011		O/C	0		
304001	B/A TEMP MONITOR-			1169-1 3754	MTH 20-Aug-2011		O/C	0		
304002	HEAT EXCHANGER 9912041-3			10653A 2022	MTH 20-Aug-2011		O/C	0		
304003	PRESS REG VALVE 9912402-14			1962-00-3 5038	MTH 20-Aug-2011		O/C	0		
304004 AFT	FLOORBD TF006 SENSOR 9912085-3			27221274 10BF13	MTH 20-Aug-2011		O/C	0		
304004 FORWARD	T/C TT002 SENSOR 9912085-3			27221274 12BF32	MTH 20-Aug-2011		O/C	0		
304005	TEMP CONTROLLER 9912085-6			1E58-1 2BE52	MTH 20-Aug-2011		O/C	0		
304006	TEMP CONTROL VALVE 9912085-1			27241287 4BE51P	MTH 20-Aug-2011		O/C	0		
304007	ALCOHOL PUMP			476411E NSN	MTH 20-Aug-2011		O/C	0		
304008 LEFT	W/S BLEED AIR VALVE BYLB50168			1403-25 5308	MTH 20-Aug-2011		O/C	0		
304008 RIGHT	W/S BLEED AIR VALVE BYLB50168			1403-25 5311	MTH 20-Aug-2011		O/C	0		
304009	PRESSURE SWITCH			1115P25 5004AB	MTH 20-Aug-2011		O/C	0		
304010 NO. 1	UC038 CURRENT SENSOR			76250-6 9001	MTH 20-Aug-2011		O/C	0		
304010 NO. 2	UC039 CURRENT SENSOR			76250-6 9005	MTH 20-Aug-2011		O/C	0		
304010 NO. 3	UC040 CURRENT SENSOR			76552-1 8963	MTH 20-Aug-2011		O/C	0		
304010 NO. 4	UC041 CURRENT SENSOR			76552-1 8973	MTH 20-Aug-2011		O/C	0		
304010 NO. 5	UC042 CURRENT SENSOR			76552-1 8966	MTH 20-Aug-2011		O/C	0		
304010 NO. 6	UC043 CURRENT SENSOR			76250-6 9006	MTH 20-Aug-2011		O/C	0		
304011 LEFT	SOLENOID DEICE VALVE			3D2353-06 N092346	MTH 20-Aug-2011		O/C	0		
304011 RIGHT	SOLENOID DEICE VALVE			3D2353-06 N102530	MTH 20-Aug-2011		O/C	0		
312001 LEFT	DIGITAL CLOCK			M877A5V 20651	MTH 20-Aug-2011		O/C	0		
313001	FLIGHT HOURMETER 85071			C664503-0104 NSN	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
313500	ARES RECORDER UNIT ASSEMBLY	KSWF		6918231-1 1251	MTH 28-Mar-2015 HRS 1140.8 LDG 952		O/C			
315002	ANNUNCIATOR PANEL	KSWF		9912618-8 618000630	MTH 06-Jul-2013 HRS 604 LDG 454		O/C			
32-10-00-960	LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD			6341321-5 366	MTH 20-Aug-2011 LDG 0			0 0		12475
32-10-00-960	RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD			6341321-6 368	MTH 20-Aug-2011 LDG 0		15000	0 0	15000	12475
32-10-00-961	LEFT TRAILING LINK AND AXLE ASSEMBLY DISCARD			6341341-1 368	MTH 20-Aug-2011 LDG 0		15000	0 0	15000	12475
32-10-00-961	RIGHT TRAILING LINK AND AXLE ASSEMBLY DISCARD			6341341-2 371	MTH 20-Aug-2011 LDG 0		15000	0 0	15000	12475
32-10-00-962	LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD	KALN		6341301-16 742	MTH 31-Jul-2015 HRS 1263.6 LDG 1064		15000	47 1263.6 1064	15000	12475
32-10-00-962	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD	KALN		6341301-16 739	MTH 31-Jul-2015 HRS 1263.6 LDG 1064		15000	47 1263.6 1064	15000	12475
32-20-00-960	NOSE LANDING GEAR STRUT ASSEMBLY DISCARD			6342350-8 411	MTH 20-Aug-2011 LDG 0		22500	0 0	22500	19975
32-20-00-961	NOSE LANDING GEAR FORK AND PISTON ASSEMBLY DISCARD			6342350-4 413	MTH 20-Aug-2011 LDG 0		12500	0 0	12500	9975
32-31-01-960	NOSE LANDING GEAR ACTUATOR ASSEMBLY DISCARD			9912370-5 1541900-7 1353	MTH 20-Aug-2011 LDG 0		7500	0 0	7500	4975
32-31-02-960	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			9912573-3 2-8207-1 0781	MTH 20-Aug-2011 LDG 0		12000	0 0	12000	9475
32-31-02-960	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			9912573-3 2-8207-1 0782	MTH 20-Aug-2011 LDG 0		12000	0 0	12000	9475
321001	MAIN LANDING GEAR			6341350-5 377	MTH 20-Aug-2011		O/C	0		
321001	MAIN LANDING GEAR			6341350-6 375	MTH 20-Aug-2011		O/C	0		
321011	ANTISKID CONTROL VALVE			39-913 465	MTH 20-Aug-2011		O/C	0		
322001	SHIMMY DAMPER			6343001-10 601	MTH 20-Aug-2011		O/C	0		
322002	NOSE LANDING GEAR ASSEMBLY			6342350-9 NSN	MTH 20-Aug-2011		O/C	0		
322003	NLG FORK			5542300-1 NSN	MTH 20-Aug-2011		O/C	0		
322006	NLG CYLINDER BRAZE ASSEMBLY			5542100-3 NSN	MTH 20-Aug-2011		O/C	0		
323002	UPLOCK MAIN GEAR			6327504-6 3088	MTH 20-Aug-2011		O/C	0		
323002	UPLOCK MAIN GEAR			6327504-6 3055	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323005	NOSE LANDING GEAR UPLOCK ACTUATOR			6327504-7 1525	MTH 20-Aug-2011		O/C	0		
323006	HYD SHUTTLE VALVE			98312 1845A	MTH 20-Aug-2011		O/C	0		
323007 NO.1	SHUTTLE, REGEN VALVE 9914689-2			5128-6 763	MTH 20-Aug-2011		O/C	0		
323007 NO.2	SHUTTLE, REGEN VALVE 9914689-2			5128-6 762	MTH 20-Aug-2011		O/C	0		
323008 L/H	SHUTTLE VALVE	SWF		211-121 1031	MTH 10-Jun-2013 HRS 586.4 LDG 441		O/C	0 0 0		
323020	EMERGENCY PNEUMATIC STORAGE BOTTLE 9912368-2	KTPA		40005320-2 5471	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		288	1	01-Jun-2031	90 m 15 d
Manufacture Date: 18-Jul-2023										
323021	EMER GEAR BOTTLE GAUGE			19940932-1 034497	MTH 20-Aug-2011		O/C	0		
324001 LEFT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912561-5	KMCO		3-1607-1 2714	MTH 24-Mar-2021 HRS 2456.9 LDG 1863		O/C	70 1263.8 858		
324001 RIGHT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912561-5			3-1607-1 2515	MTH 24-Mar-2021 HRS 2456.9 LDG 1863		O/C	115 2456.9 1863		
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY	KMCO		3-1418 8648	MTH 09-Dec-2021 HRS 2602 LDG 1946		O/C			
324003 LEFT MAIN LANDING GEAR	LEFT MAIN LANDING GEAR TIRE 9912622-1	KTPA		026-618-0 3052P00045	MTH 16-Jun-2023 HRS 3242.8 LDG 2393		O/C	0 0 0		
324003 RIGHT MAIN LANDING GEAR	RIGHT MAIN LANDING GEAR TIRE 9912622-1	KTPA		026-618-0 3049P00076	MTH 16-Jun-2023 HRS 3242.8 LDG 2393		O/C	0 0 0		
324004 NOSE LANDING GEAR	TIRE	KTPA		31-613-8 2214T00398	MTH 15-Nov-2023 HRS 3404.9 LDG 2516		O/C	0 0		
324005 LEFT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912617-2	KTPA		2-1695 0996	MTH 08-Mar-2023 HRS 3048.1 LDG 2249		O/C	0 0 0		
324005 RIGHT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912617-2	KTPA		2-1695 0547	MTH 18-Oct-2022 HRS 2859.2 LDG 2127		O/C	0 0 0		
324101	BRK ANTISKID/METERING VALVE 9912621-2			32-107-1 486	MTH 20-Aug-2011		O/C	0		
324102 LEFT	ANTISKID TRANSDUCER 9912305-2			40-955 9506	MTH 20-Aug-2011		O/C	0		
324102 RIGHT	ANTISKID TRANSDUCER 9912305-2			40-955 9494	MTH 20-Aug-2011		O/C	0		
324103	DIG ANTISKID CNTRL BOX 9912621-1			142-103 483A	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324104	BRAKE PRESSURE SWITCH			GPP1250-69 1103444	MTH 20-Aug-2011		O/C	0		
324105	PARKING BRAKE VALVE 9912388-1			95853 1676A	MTH 20-Aug-2011		O/C	0		
324106	HYDRAULIC PUMP MOTOR			MP50B1 4337	MTH 20-Aug-2011		O/C	0		
324107	BRAKE ANTISKID ACCUMULATOR 9912644-2			7550-2 0756	MTH 20-Aug-2011		O/C	0		
324108	LOW PRESSURE SWITCH			GPP1250-79 1107462	MTH 20-Aug-2011		O/C	0		
324109	BRAKE PRESSURE PUMP 9912364-2			640929 2665A	MTH 20-Aug-2011		O/C	0		
324110	EMERGENCY BRAKE VALVE 9912387-5			878208-05 V090	MTH 20-Aug-2011		O/C	0		
324111	FAULT DISPLAY UNIT 9912305-9			42-92750 2555A	MTH 20-Aug-2011		O/C	0		
324113	THERMAL RELIEF VALVE			1785-3 0450	MTH 20-Aug-2011		O/C	0		
324204	BRAKE HYDRAULIC PACK ASSEMBLY FILTER ELEMENT DISCARD (REPLACE) TASK# 32-42-05-960	KTPA		9912372-1 NSN	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		36 1200	0 0	31-Aug-2026 4499.4	33 m 14 d 1086.3
324205	BRAKE RESERVOIR AIR FILTER AND BRAKE RESERVOIR SUPPLY LINE FILTER DISCARD (REPLACE) TASK# 32-42-04-960	KTPA		AN6237-1 NSN	MTH 25-Aug-2023 HRS 3299.4 LDG 2439		36 1200	0 0	31-Aug-2026 4499.4	33 m 14 d 1086.3
326001 LEFT	MLG UPLOCK SWITCH			65-430087 NSN	MTH 20-Aug-2011		O/C	0		
326001 NOSE	NLG UPLOCK SWITCH			65-430087 NSN	MTH 20-Aug-2011		O/C	0		
326001 RIGHT	MLG UPLOCK SWITCH			65-430087 NSN	MTH 20-Aug-2011		O/C	0		
330001 FWD	OVERWING LIGHT ASSY KALN			OWL100-03 115006599	MTH 31-Jul-2015 HRS 1263.6 LDG 1064 ACH 303		O/C	0 0		
331001 LEFT	LIGHT UB001 DIMMER			273-1 3686C	MTH 20-Aug-2011		O/C	0		
331001 RIGHT	LIGHT UB002 DIMMER			273-1 3686K	MTH 20-Aug-2011		O/C	0		
331003	INDIRECT LIGHTING CONTROL BOX			CLC500-01 3607	MTH 20-Aug-2011		O/C	0		
331004	MULTI-FUNCTION MODULE ASSEMBLY			9118009-4 0238	MTH 20-Aug-2011		O/C	0		
334001	GROUND REC LIGHT 9912679-3			84003-2 03558A	MTH 20-Aug-2011		O/C	0		
334004 LEFT	LANDING LAMP HOUSING			LDL100-01 206000429	MTH 20-Aug-2011		O/C	0		
334004 RIGHT	LANDING LAMP HOUSING KHPN			LDL100-01 206000349	MTH 09-Aug-2013 HRS 637.3 LDG 484		O/C	0 0 0		
334005 LEFT	ANTI-COLLISION LIGHT ASSEMBLY 9912679-1			84005-1 000720	MTH 20-Aug-2011		O/C	0		
334005 RIGHT	ANTI-COLLISION LIGHT ASSEMBLY			84005-2 000691	MTH 20-Aug-2011		O/C	0		
334006 LEFT	FLOOD TAIL LIGHT ASSEMBLY			TIL100-02 207000465	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
334006 RIGHT	FLOOD TAIL LIGHT ASSEMBLY ICT	TIL100-02 207000523	MTH 23-Aug-2011 HRS 9.4 LDG 7		O/C	0 0 0		
334007	TAIL LIGHT ASSEMBLY	01-0770966-00 644	MTH 20-Aug-2011		O/C	0		
335000 LEFT	AFT LEFT EMERGENCY LIGHTING BATTERY PACK KALN	CBS28-1 2132M	MTH 22-Sep-2017 HRS 1807 LDG 1479 ACH 478		O/C			
335000 RIGHT	FORWARD RIGHT EMERGENCY LIGHTING BATTERY PACK UNK	CBS28-1 006245	MTH 11-Sep-2020 HRS 2359.4 LDG 1805		O/C			
335001	EMERGENCY LIGHTS FWD 2G SWITCH	7212-2-000 1043	MTH 20-Aug-2011		O/C	0		
341001 NO. 1	AIR DATA COMPUTER ADC-3000	822-1109-143 4815W	MTH 20-Aug-2011		O/C	0		
341001 NO. 2	AIR DATA COMPUTER ADC-3000	822-1109-143 4818B	MTH 20-Aug-2011		O/C	0		
341001 STANDBY	AIR DATA COMPUTER	9200-30000-068 5016	MTH 20-Aug-2011		O/C	0		
341004	AOA COMPUTER	C-13406-1 915	MTH 20-Aug-2011		O/C	0		
341006	AOA INDICATOR	C12405-1 85149	MTH 20-Aug-2011		O/C	0		
341007	AOA SENSOR	C-12717-1 139900A-003	MTH 20-Aug-2011		O/C	0		
341008	BAROMETRIC SWITCH	GBC300-156 1030812	MTH 20-Aug-2011		O/C	0		
341010 AFT	RADIO ALT ANTENNA	S67-2002 54357138	MTH 20-Aug-2011		O/C	0		
341010 FORWARD	RADIO ALT ANTENNA	S67-2002 54357149	MTH 20-Aug-2011		O/C	0		
341030	TEMP PROBE SENSOR	0129G B2350	MTH 20-Aug-2011		O/C	0		
341034	RADIO ALT TRANSMITTER ALT-4000	822-0615-206 3Y9JX	MTH 20-Aug-2011		O/C	0		
341103 NO.1	CONFIG CNTRL STRAPPING UNIT	822-1363-002 480XT	MTH 20-Aug-2011		O/C	0		
341103 NO.2	CONFIG CNTRL STRAPPING UNIT	822-1363-002 480XY	MTH 20-Aug-2011		O/C	0		
342002 LEFT	AHRS COMPUTER AHC-3000	822-1110-002 46K4G	MTH 20-Aug-2011		O/C	0		
342002 RIGHT	AHRS COMPUTER AHC-3000	822-1110-002 46K4P	MTH 20-Aug-2011		O/C	0		
342004	DATA BASE UNIT	822-2215-602 48R6W	MTH 20-Aug-2011		O/C	0		
342005 LEFT	FLT GUIDANCE COMPUTER	822-1108-033 4669L	MTH 20-Aug-2011		O/C	0		
342005 RIGHT	FLT GUIDANCE COMPUTER	822-1108-033 46GHM	MTH 20-Aug-2011		O/C	0		
342006 LEFT	FLUX DETECTOR UNIT FDU-3000	822-1193-001 300531	MTH 20-Aug-2011		O/C	0		
342006 RIGHT	FLUX DETECTOR UNIT FDU-3000	822-1193-001 300467	MTH 20-Aug-2011		O/C	0		
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	822-1200-003 46K6L	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000			822-1200-003 46K1J	MTH 20-Aug-2011		O/C	0		
342008 LEFT	IAPS POWER SUPPLY PWR-3000			822-1137-001 480YF	MTH 20-Aug-2011		O/C	0		
342008 RIGHT	IAPS POWER SUPPLY PWR-3000			822-1137-001 480YG	MTH 20-Aug-2011		O/C	0		
342009	ENVIRONMENTAL CONTROL IEC-3001			822-1167-001 480WY	MTH 20-Aug-2011		O/C	0		
342010 LEFT	OPER CONFIG MODULE			822-1484-228 47YTN	MTH 20-Aug-2011		O/C	0		
342010 RIGHT	OPER CONFIG MODULE			822-1484-228 47YTM	MTH 20-Aug-2011		O/C	0		
342011 LEFT	I/O CONCENTRATOR IAPS MODULE IOC-4100			822-2065-001 48D1L	MTH 20-Aug-2011		O/C	0		
342011 RIGHT	I/O CONCENTRATOR IAPS MODULE IOC-4100			822-2065-001 48CTG	MTH 20-Aug-2011		O/C	0		
342011	DETACHABLE CONFIG MODULE			501-1803-153 4989	MTH 20-Aug-2011		O/C	0		
342012 RIGHT	IAPS - ICC CARD CAGE			822-2191-001 48LDH	MTH 20-Aug-2011		O/C	0		
342031	STANDBY GYRO POWER SUPPLY PS-855A	KMCO		501-1712-01 80029	MTH 09-Dec-2021 HRS 2602 LDG 1946		O/C			
342032	SECONDARY FLIGHT DISPLAY GH-3000			501-1741-2103 2725B	MTH 20-Aug-2011		O/C	0		
342033	MAINTENANCE DIAGNOSTIC COMPUTER MDC3110			822-1987-007 45L7H	MTH 20-Aug-2011		O/C	0		
342055 LEFT	DATA CONCENTRATOR UNIT DCU-3001			822-1483-250 3YBVL	MTH 20-Aug-2011		O/C	0		
342055 RIGHT	DATA CONCENTRATOR UNIT DCU-3001			822-1483-250 3YBVV	MTH 20-Aug-2011		O/C	0		
342056 LEFT	AFD CONTROL DISPLAY PANEL DCP-3030			822-1828-102 4629V	MTH 20-Aug-2011		O/C	0		
342056 RIGHT	AFD CONTROL DISPLAY PANEL DCP-3030			822-1828-102 4620G	MTH 20-Aug-2011		O/C	0		
342057	AFD CRSR CONTROL PANEL CCP-3000			822-1746-102 461TT	MTH 20-Aug-2011		O/C	0		
342301 LEFT	MODE SELECTOR			622-6209-020 3YFDG	MTH 20-Aug-2011		O/C	0		
342301 RIGHT	MODE SELECTOR			622-6209-020 3YFDH	MTH 20-Aug-2011		O/C	0		
342301	COURSE/HEADING PANEL SWF			822-1279-002 1L6LY	MTH 06-Jul-2013 HRS 604 LDG 454		O/C	0 0 0		
342302 CENTER	ADAPTIVE FLIGHT DISPLAY AFD-3010E	KTPA		822-1753-131 48627T	MTH 22-Nov-2022 HRS 2897.2 LDG 2160		O/C	0 0		
342302 LEFT	ADAPTIVE FLIGHT DISPLAY *CF			822-1084-131 46H9N	MTH 19-Aug-2011		O/C	0		
342302 RIGHT	ADAPTIVE FLIGHT DISPLAY *CF			822-1084-131 46H8Y	MTH 19-Aug-2011		O/C	0		
342303	COURSE PANEL CKP-3000			822-1281-002 461RR	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
 Aircraft Model: **525B - CJ3**
 Aircraft Serial: **525B-0364**
 Unit: Reg No: **N7578K**
 Airworthiness: **20-Aug-2011**
 Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342304 CENTER	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY			822-1140-101 485CC	MTH 20-Aug-2011		O/C	0		
342304 LEFT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY			822-1140-101 485CB	MTH 20-Aug-2011		O/C	0		
342304 RIGHT	ADAPTIVE FLIGHT DISPLAY MOUNTING TRAY			822-1140-101 485BY	MTH 20-Aug-2011		O/C	0		
343001	MARKER BEACON ANTENNA *CF			MB10-754 1381	MTH 19-Aug-2011		O/C	0		
343002	DUAL GLIDESLOPE COUPLER			82-70-01 2279	MTH 20-Aug-2011		O/C	0		
343003	GLIDESLOPE ANTENNA			RGS10-48 15241	MTH 20-Aug-2011		O/C	0		
344001	EGPWS COMPUTER MARK(V111) HONEYWELL			965-1206-011 EWK808061	MTH 20-Aug-2011		O/C	0		
344002	WEATHER RADAR REC/XMTR ANTENNA RTA-800			822-1050-004 3PTKP	MTH 20-Aug-2011		O/C	0		
344014	SATELLITE DATALNK WT RECEIVER XMWR-1000			822-2031-002 459KY	MTH 20-Aug-2011		O/C	0		
344017 1	GPS XM ANTENNA 9154079-85			CI428-410 354828	MTH 20-Aug-2011		O/C	0		
344017 2	GPS XM ANTENNA 9154079-85	*CF		CI428-410 363302	MTH 19-Aug-2011		O/C	0		
345001 NO.1	FORWARD DME ANTENNA			DMNI50-2-2 120163	MTH 20-Aug-2011		O/C	0		
345002 NO.1	LEFT DME TRANSCEIVER DME-4000			822-1466-001 485FN	MTH 20-Aug-2011		O/C	0		
345005 LEFT	NAVIGATION ANTENNA			VT11-767-3 2271	MTH 20-Aug-2011		O/C	0		
345005 RIGHT	NAVIGATION ANTENNA			VT11-767-3 2272	MTH 20-Aug-2011		O/C	0		
345020 NO.1	ADF 1 ANTENNA			622-7383-101 4641F	MTH 20-Aug-2011		O/C	0		
345040 LEFT	DIVERSITY TRANSPONDER ANTENNA			DMNI50-2-2 120086	MTH 20-Aug-2011		O/C	0		
345040 NO.1	TRANSPONDER ANTENNA			DMNI50-2-2 122235	MTH 20-Aug-2011		O/C	0		
345040 NO.2	TRANSPONDER ANTENNA			DMNI50-2-2 119108	MTH 20-Aug-2011		O/C	0		
345040 RIGHT	DIVERSITY TRANSPONDER ANTENNA			DMNI50-2-2 120082	MTH 20-Aug-2011		O/C	0		
345041 NO. 1	TRANSPONDER	KSWF		622-9210-501 3V40J	MTH 12-Oct-2018 HRS 2011.9 LDG 1596		O/C			
345041 NO. 2	TRANSPONDER	KSWF		622-9210-501 491CF	MTH 12-Oct-2018 HRS 2011.9 LDG 1596		O/C			
345046 NO.1	FMS COMPUTER FMC-3000			822-0883-038 48LWR	MTH 20-Aug-2011		O/C	0		
345047 NO. 1	FMS CONTROL DISPLAY UNIT CDU-3000			822-0884-364 4680T	MTH 20-Aug-2011		O/C	0		
345050	FMS GPS DISPLAY GPS-500W			011-01062-10 23651161	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345051	IRIDIUM/GPS PASSIVE ANTENNA IRIDIUM	S67-1575-165 4494451	MTH 20-Aug-2011		O/C	0		
345056 NO.1	GPS RECEIVER KALN GPS-4000S	822-2189-002 46D3L	MTH 09-Sep-2014 LDG 777		O/C			
345057 NO. 1	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4000	822-1465-001 3XG7C	MTH 20-Aug-2011		O/C	0		
345057 NO. 2	VOR/ADF/MRK BEACON/ILS RECEIVER NAV-4500	822-1579-001 3XGBT	MTH 20-Aug-2011		O/C	0		
345058 NO.1	RADIO TUNING UNIT	822-0730-442 467TT	MTH 20-Aug-2011		O/C	0		
345058 NO.2	RADIO TUNING UNIT	822-0730-442 3R8RK	MTH 20-Aug-2011		O/C	0		
345061	TCAS PROCESSOR KTPA	822-1294-002 139948	MTH 25-Apr-2023 LDG 2330		O/C	0 0		
345062 BOTTOM	TCAS II ANTENNA TCAS II ANTENNA	622-8973-001 3TRHN	MTH 20-Aug-2011		O/C	0		
345062 TOP	TCAS II ANTENNA TCAS II ANTENNA	622-8973-001 3TRHP	MTH 20-Aug-2011		O/C	0		
345065	EXTERNAL - FSU COMPENSATION UNIT ECU-3000	822-1200-998 46K8Y	MTH 20-Aug-2011		O/C	0		
345066	FSU UNIT	822-1543-101 48VVR	MTH 20-Aug-2011		O/C	0		
345067 NO.1	RADIO INTERFACE UNIT RIU-4110	822-1864-002 3XFJF	MTH 20-Aug-2011		O/C	0		
345067 NO.2	RADIO INTERFACE UNIT RIU-4110	822-1864-002 3XG8R	MTH 20-Aug-2011		O/C	0		
345068 NO.1	AUDIO CONTROL PANEL RADIO	822-2381-230 48PXX	MTH 20-Aug-2011		O/C	0		
345068 NO.2	AUDIO CONTROL PANEL RADIO	822-2381-230 459RX	MTH 20-Aug-2011		O/C	0		
346050	E.L. PANEL KMCO	9912770-1 0165	MTH 10-Feb-2023 LDG 2225		O/C			
350005	OXYGEN REGULATOR	172270-01 2402	MTH 20-Aug-2011		O/C	0		
350006	OXYGEN CYLINDER UNK DOT E-10945	176276-50 435729703	MTH 11-Sep-2020 LDG 1805		180	991 635	31-Dec-2025	25 m 14 d
Manufacture Date: 30-Dec-2010								
350007	OXYGEN PRESSURE GAGE MD-97	C668512-0101 L1010604	MTH 20-Aug-2011		O/C	0		
351001	OXYGEN CONTROL VALVE	P21007 1953	MTH 20-Aug-2011		O/C	0		
351002 COPILOT	OXYGEN MASK BUR 9914771-1	174252-96 25475	MTH 30-Nov-2011 LDG 88		O/C	0 0 0		
351002 PILOT	OXYGEN MASK *CF 9914771-1	174252-96 30325	MTH 30-Jun-2011		O/C	3		
361001 LEFT	PRECOOL TEMP SENSOR KSWF	9912584-3 11BF51	MTH 17-Feb-2014 LDG 640		O/C	810 640		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
361001 RIGHT	PRECOOL TEMP SENSOR KSWF	9912584-3 3BG17	MTH 17-Feb-2014 HRS 810 LDG 640		O/C	810 640		
361002 LEFT	B/A PRECOOLER ASSEMBLY KMCO	9912624-1 HX-01477	MTH 30-Oct-2023 HRS 3373.8 LDG 2491		3200	0 0	6573.8	3160.7
361002 RIGHT	B/A PRECOOLER ASSEMBLY KMCO	9912624-1 HX-01549	MTH 30-Oct-2023 HRS 3373.8 LDG 2491		3200	0 0	6573.8	3160.7
361003 LEFT	MODULATING VALVE 9912584-1	1H139-1 3BC38	MTH 22-Feb-2014 HRS 811 LDG 642		O/C	21 0 0		
361003 RIGHT	MODULATING VALVE 9912584-2	1H139-2 9BF21	MTH 20-Aug-2011		O/C	0		
361005	PRESSURE SWITCH	P18M30 5185	MTH 20-Aug-2011		O/C	0		
361006 LEFT	OVERTEMP SWITCH 9914149-2	1173T181-2 7048	MTH 17-Feb-2014 HRS 809.6 LDG 639		O/C	809.6 639		
361006 RIGHT	OVERTEMP SWITCH 9914149-2	1173T181-2 7047	MTH 17-Feb-2014 HRS 809.6 LDG 639		O/C	809.6 639		
361007	B/A PRESSURE REGULATOR 9912510-1	1H75-18 11BF32	MTH 20-Aug-2011		O/C	0		
522001	INFLATABLE DOOR SEAL 9912075-4	S15501-4 NSN	MTH 20-Aug-2011		O/C	0		
522002	SECONDARY SEAL	5511230-96 SN-UNKNOWN	MTH 26-Sep-2011 HRS 46.4 LDG 38		O/C	0 0 0		
53-00-00-960 NOSE LANDING GEAR	NOSE LANDING GEAR ACTUATOR FITTING DISCARD	6511105-1 431	MTH 20-Aug-2011 LDG 0		23900	0 0	23900	21375
53-00-00-961 LEFT NOSE LANDING GEAR	LEFT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD	5513056-7 357	MTH 20-Aug-2011 LDG 0		12000	0 0	12000	9475
53-00-00-961 RIGHT NOSE LANDING GEAR	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD	5513056-8 285	MTH 20-Aug-2011 LDG 0		12000	0 0	12000	9475
530000	RADOME ASSEMBLY	6313101-47 NSN	MTH 20-Aug-2011		O/C	0		
561001 LEFT	LEFT WINDSHIELD ASSEMBLY 9912064-15	93200-15 2545	MTH 20-Aug-2011		O/C	0		
561001 RIGHT	RIGHT WINDSHIELD ASSEMBLY 9912064-16	93200-16 2438	MTH 20-Aug-2011		O/C	0		
561002 CABIN DOOR	WINDOW 9912207-8	93105-8 6281	MTH 20-Aug-2011		O/C	0		
561002 LEFT NO. 2	CABIN WINDOW 9912207-8	93105-8 6273	MTH 20-Aug-2011		O/C	0		
561002 LEFT NO. 3	CABIN WINDOW 9912207-8	93105-8 6274	MTH 20-Aug-2011		O/C	0		
561002 LEFT NO. 4	CABIN WINDOW 9912207-8	93105-8 6199	MTH 20-Aug-2011		O/C	0		
561002 LEFT NO. 5	CABIN WINDOW 9912207-8	93105-8 6275	MTH 20-Aug-2011		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561002 LEFT NO. 6	CABIN WINDOW 9912207-8			93105-8 6276	MTH 20-Aug-2011		O/C	0		
561002 LEFT NO. 7	CABIN WINDOW 9912207-8			93105-8 6325	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 1	CABIN WINDOW 9912207-8			93105-8 6330	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 2	CABIN WINDOW 9912207-8			93105-8 6266	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 3	CABIN WINDOW 9912207-8			93105-8 6259	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 4	CABIN WINDOW 9912207-8			93105-8 6033	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 5	CABIN WINDOW 9912207-8			93105-8 5731	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 6	CABIN WINDOW 9912207-8			93105-8 5653	MTH 20-Aug-2011		O/C	0		
561002 RIGHT NO. 7	CABIN WINDOW 9912207-8			93105-8 6036	MTH 20-Aug-2011		O/C	0		
561003 COPILOT	SIDE WINDOW			6311263-2 2164	MTH 20-Aug-2011		O/C	0		
561003 PILOT	SIDE WINDOW			6311263-1 2139	MTH 20-Aug-2011		O/C	0		
57-00-00-960 LEFT MAIN GEAR	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD			6341324-1 643016E	MTH 20-Aug-2011 LDG 0			0 0		12475
57-00-00-960 RIGHT MAIN GEAR	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD			6341324-2 643017C	MTH 20-Aug-2011 LDG 0			0 0	15000	12475
57-00-00-961 LEFT MAIN LANDING GEAR AFT	LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD			6341326-5 644977C	MTH 20-Aug-2011 LDG 0			0 0	12000	9475
57-00-00-961 LEFT MAIN LANDING GEAR FORWARD	LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD			6341325-1 643018A	MTH 20-Aug-2011 LDG 0			0 0	12000	9475
57-00-00-961 RIGHT MAIN LANDING GEAR AFT	RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD			6341326-6 644978H	MTH 20-Aug-2011 LDG 0			0 0	12000	9475
57-00-00-961 RIGHT MAIN LANDING GEAR FORWARD	RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD			6341325-2 643019C	MTH 20-Aug-2011 LDG 0			0 0	12000	9475
712002 LEFT ENGINE AFT	LEFT ENGINE AFT ISOLATOR MOUNT (OVERHAUL) 9912623-7			LM-605-SA11 LK3081	MTH 20-Aug-2011 HRS 0		8000	0 0	8000	4586.9
712002 LEFT ENGINE FORWARD BOTTOM	LEFT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL) 9912623-6			LM-605-SA8 LK2499	MTH 20-Aug-2011 HRS 0		8000	0 0	8000	4586.9
712002 LEFT ENGINE FORWARD TOP	LEFT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL) 9912623-6			LM-605-SA8 LK2475	MTH 20-Aug-2011 HRS 0		8000	0 0	8000	4586.9
712002 RIGHT ENGINE AFT	RIGHT ENGINE AFT ISOLATOR MOUNT (OVERHAUL) 9912623-8			LM-605-SA10 LK3147	MTH 20-Aug-2011 HRS 0		8000	0 0	8000	4586.9
712002 RIGHT ENGINE FORWARD BOTTOM	RIGHT ENGINE FORWARD BOTTOM ISOLATOR MOUNT (OVERHAUL) 9912623-6			LM-605-SA8 LK2476	MTH 20-Aug-2011 HRS 0		8000	0 0	8000	4586.9

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712002 RIGHT ENGINE FORWARD TOP	RIGHT ENGINE FORWARD TOP ISOLATOR MOUNT (OVERHAUL) 9912623-6			LM-605-SA8 LK2464	MTH 20-Aug-2011 HRS 0		8000	0	8000	4586.9
71EN1 NO. 1	ENGINE FJ44-3A/9912614-1			67000-200 141765			E/C			
71EN2 NO. 2	ENGINE FJ44-3A/9912614-1			67000-200 141764			E/C			
720001 E1	FAN ROTOR HW32616			115810 LDG 0	MTH 20-Aug-2011		10000	0	(10000)10000	7475
720001 E2	FAN ROTOR HW32398			115810 LDG 0	MTH 20-Aug-2011		10000	0	(10000)10000	7475
720002 E1	IP COMPRESSOR ROTOR HW31253			115553 LDG 0	MTH 20-Aug-2011		10000	0	(10000)10000	7475
720002 E2	IP COMPRESSOR ROTOR HW31228			115553 LDG 0	MTH 20-Aug-2011		10000	0	(10000)10000	7475
720003 E1	COMPLETE LP SHAFT ASSEMBLY RX08TK0465			111423 MTH 20-Aug-2011			O/C	0		
720003 E2	COMPLETE LP SHAFT ASSEMBLY RX08TK0485			111423 MTH 20-Aug-2011			O/C	0		
720004 E1	HIGH PRESSURE SHAFT RX08RT2283			64711 MTH 20-Aug-2011			O/C	0		
720004 E2	HIGH PRESSURE SHAFT RX08RT2320			64711 MTH 20-Aug-2011			O/C	0		
720005 E1	HP COMPRESSOR COVER AU21532			69885 MTH 20-Aug-2011			O/C	0		
720005 E2	HP COMPRESSOR COVER AU21524			69885 MTH 20-Aug-2011			O/C	0		
720006 E1	DIFFUSER CASE ASSEMBLY AU21237			116087 MTH 20-Aug-2011			O/C	0		
720006 E2	DIFFUSER CASE ASSEMBLY AU21243			116087 MTH 20-Aug-2011			O/C	0		
720007 E1	1ST STAGE LP TURBINE NOZZLE AU21346			118307 MTH 20-Aug-2011			O/C	0		
720007 E2	1ST STAGE LP TURBINE NOZZLE AU21435			118307 MTH 20-Aug-2011			O/C	0		
720008 E1	ACCESS DRIVE GEARBOX MX20838			78823 MTH 20-Aug-2011			O/C	0		
720008 E2	ACCESS DRIVE GEARBOX MX20840			78823 MTH 20-Aug-2011			O/C	0		
722010 E1	IP (STAGE 1 & 2) VANE ASSEMBLY AU20944			115569 MTH 20-Aug-2011			O/C	0		
722010 E2	IP (STAGE 1 & 2) VANE ASSEMBLY AU20950			115569 MTH 20-Aug-2011			O/C	0		
723019 E1	INTERSTAGE HOUSING ASSEMBLY AU42466			117624 MTH 20-Aug-2011			O/C	0		
723019 E2	INTERSTAGE HOUSING ASSEMBLY AU42469			117624 MTH 20-Aug-2011			O/C	0		
723028 E1	BEARING NO.1 HOUSING AU21308			67305 MTH 20-Aug-2011			O/C	0		
723028 E2	BEARING NO.1 HOUSING AU21310			67305 MTH 20-Aug-2011			O/C	0		
723036 E1	STAGE 3 IP ROTOR STATOR AU20957			68067 MTH 20-Aug-2011			O/C	0		
723036 E2	STAGE 3 IP ROTOR STATOR AU20959			68067 MTH 20-Aug-2011			O/C	0		
723037 E1	FAN STATOR VANE ASSEMBLY MX20138			70563 MTH 20-Aug-2011			O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
723037 E2	FAN STATOR VANE ASSEMBLY	70563 MX20137	MTH 20-Aug-2011		O/C	0		
724035 E1	HP TURBINE COMBUSTER ASSEMBLY	113636 AU21401	MTH 20-Aug-2011		O/C	0		
724035 E2	HP TURBINE COMBUSTER ASSEMBLY	113636 AU21326	MTH 20-Aug-2011		O/C	0		
725101 E1	HP COMPRESSOR ROTOR	115563 HW32281	MTH 20-Aug-2011 LDG 0			0	(10000)10000	7475
725101 E2	HP COMPRESSOR ROTOR	115563 HW32260	MTH 20-Aug-2011 LDG 0		10000	0	(10000)10000	7475
725102 E1	HP TURBINE ROTOR	111414 HW32326	MTH 20-Aug-2011		O/C	0		
725102 E2	HP TURBINE ROTOR	111414 HW32351	MTH 20-Aug-2011		O/C	0		
725103 E1	HP TURBINE DISK	67093 HW32326	MTH 20-Aug-2011 LDG 0		8000	0	(8000)8000	5475
725103 E2	HP TURBINE DISK	67093 HW32351	MTH 20-Aug-2011 LDG 0		8000	0	(8000)8000	5475
725501 E1	1ST LP TURBINE DISK	72037 HW31884	MTH 20-Aug-2011 LDG 0		10000	0	(10000)10000	7475
725501 E2	1ST LP TURBINE DISK	72037 HW32134	MTH 20-Aug-2011 LDG 0		10000	0	(10000)10000	7475
725502 E1	2ND LP TURBINE DISK	66993 HW31756	MTH 20-Aug-2011 LDG 0		10000	0	(10000)10000	7475
725502 E2	2ND LP TURBINE DISK	66993 HW31698	MTH 20-Aug-2011 LDG 0		10000	0	(10000)10000	7475
730001 LEFT ENGINE	FUEL PRESS SWITCH 9912033-2 KSWF	1103P0448 9671	MTH 28-Mar-2015 HRS 1140.8 LDG 952		O/C			
730001 RIGHT ENGINE	FUEL PRESS SWITCH 9912033-2 KHPN	1103P0448 10275	MTH 03-Jun-2015 HRS 1212 LDG 1025		O/C	0 0 0		
732500 LEFT ENGINE	FADEC SWF	115180 CL10AW1685	MTH 09-Jul-2012 HRS 303.1 LDG 225		O/C			
732500 RIGHT ENGINE	FADEC SWF	115180 CL10AW1680	MTH 09-Jul-2012 HRS 303.1 LDG 225		O/C			
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1 KHPN	1573-4 AAA8541	MTH 03-Jun-2015 HRS 1212 LDG 1025		O/C	46 1212 1025		
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1 KTPA	1573-4 0718-020	MTH 16-Jan-2023 HRS 3005.5 LDG 2217		O/C			
730002 E1	FUEL NOZZLE ASSY KTPA	50817 BCC-00012459	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			
730002 E2	FUEL NOZZLE ASSY KTPA	50817 BCC-00011093	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
730003 E1	SEAL AND FUEL SLINGER ASSEMBLY			115471 AU200220	MTH 20-Aug-2011		O/C	0		
730003 E1 REAR	SEAL AND FUEL SLINGER ASSEMBLY			115094 AU20210	MTH 20-Aug-2011		O/C	0		
730003 E2	SEAL AND FUEL SLINGER ASSEMBLY			115471 AU200230	MTH 20-Aug-2011		O/C	0		
730003 E2 REAR	SEAL AND FUEL SLINGER ASSEMBLY			115094 AU20215	MTH 20-Aug-2011		O/C	0		
732101 E1	FUEL DELIVERY UNIT 119149	KSWF		116190-01A10 CL7APU0619	MTH 04-Aug-2014 HRS 951 LDG 758		8000	0	(8951)8951	5537.9
732101 E2	FUEL DELIVERY UNIT 119149	KSWF		116190-01A10 CL8ATW0280	MTH 04-Aug-2014 HRS 951 LDG 759		8000	4100	(4851)4851	1437.9
732301 E1	ELEC FUEL FILTER INDICATOR			57847 GE4565	MTH 20-Aug-2011		O/C	0		
732301 E2	ELEC FUEL FILTER INDICATOR			57847 GE4564	MTH 20-Aug-2011		O/C	0		
741001 E1 INBOARD	IGNITION EXCITER			68145 CK1000548	MTH 20-Aug-2011		O/C	0		
741001 E1 OUTBOARD	IGNITION EXCITER	KSWF		68145 CK-1201823	MTH 05-Mar-2015 HRS 1122.6 LDG 930		O/C	0 0 0		
741001 E2 INBOARD	IGNITION EXCITER			68145 CK1000559	MTH 20-Aug-2011		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER			68145 CK1000560	MTH 20-Aug-2011		O/C	0		
741002 E1	SHORT IGNITOR LEAD			50852 NSN	MTH 20-Aug-2011		O/C	0		
741002 E2	SHORT IGNITOR LEAD			50852 NSN	MTH 20-Aug-2011		O/C	0		
741003 E1	LONG IGNITOR LEAD			50853 NSN	MTH 20-Aug-2011		O/C	0		
741003 E2	LONG IGNITOR LEAD			50853 NSN	MTH 20-Aug-2011		O/C	0		
741004 E1 INBOARD	IGNITOR	KTPA		68032 CK-1902652	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			
741004 E1 OUTBOARD	IGNITOR	KTPA		68032 CK-1700101	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			
741004 E2 INBOARD	IGNITOR	KTPA		68032 CK-2100264	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			
741004 E2 OUTBOARD	IGNITOR	KTPA		68032 CK-1601786	MTH 06-Dec-2022 HRS 2923.3 LDG 2176		O/C			
771001 E1	N1 DUAL MAGNETIC SPEED SENSOR			57355 MD0124994	MTH 20-Aug-2011		O/C	0		
771001 E2	N1 DUAL MAGNETIC SPEED SENSOR			57355 MD0124995	MTH 20-Aug-2011		O/C	0		
771002 E1	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD0138535	MTH 20-Aug-2011		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
771002 E2	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD0138400	MTH 20-Aug-2011		O/C	0		
771003 E1	TT2 SENSOR	KTPA		79646 GST5110	MTH 19-Sep-2022 HRS 2803.3 LDG 2086		O/C			
771003 E2	TT2 SENSOR	KTPA		79646 GST4794	MTH 19-Sep-2022 HRS 2803.3 LDG 2086		O/C			
772002 E1	ITT HARNESS ASSEMBLY			75378 YYF001914	MTH 20-Aug-2011		O/C	0		
772002 E2	ITT HARNESS ASSEMBLY			75378 YYF001915	MTH 20-Aug-2011		O/C	0		
793002 LEFT ENGINE	OIL PRESS SWITCH 9912178-4			S1103P89-3 3358	MTH 20-Aug-2011		O/C	0		
793002 RIGHT ENGINE	OIL PRESS SWITCH 9912178-4			S1103P89-3 3352	MTH 20-Aug-2011		O/C	0		
793003 LEFT ENGINE	OIL PRESS TRANSMITTER			APTE-304A-200G 78338710	MTH 20-Aug-2011		O/C	0		
793003 RIGHT ENGINE	OIL PRESS TRANSMITTER			APTE-304A-200G 783311485	MTH 20-Aug-2011		O/C	0		
792201 E1	LUBE OIL COOLER	KALN		121535 PP2101	MTH 20-Oct-2016 HRS 1626.1 LDG 1370		O/C	0 0 0		
792201 E2	LUBE OIL COOLER	KALN		121535 PP1370	MTH 16-Jun-2016 HRS 1491.1 LDG 1275		O/C			
792401 E1	LUBE AND SCAVENGE PUMP KSWF			120932 MX30017	MTH 06-Jul-2013 HRS 604 LDG 454		5000	0 0 0	(5604)5604	2190.9
792401 E2	LUBE AND SCAVENGE PUMP			114520 MX21010	MTH 20-Aug-2011 HRS 0		5000	0 0	(5000)5000	1586.9
801101 LEFT	STARTER GENERATOR 9912125-2	KTPA		300SGL129Q S00239	MTH 06-Mar-2023 HRS 3048.1 LDG 2249		1000	0	4048.1	635
801101 RIGHT	STARTER GENERATOR 9912125-2	KTPA		300SGL129Q 7083XL2	MTH 21-Nov-2022 HRS 2893.4 LDG 2156		1000	0	3893.4	480.3



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525B-99-01 R03	CESCOME PRICES (THIS SL CANCELS SL525B-99-01 R2 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03 R01	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PERSONAL ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525B-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525B-99-03 R02	MISCELLANEOUS - TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 525B-99-08	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525B-05-03	TIME LIMITS/MAINTENANCE CHECKS - WING INSPECTION INTERVAL IMPLEMENTATION GRACE PERIOD			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R06 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R06 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1003 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS					-			
	MOC :								
SL WI-05-1007-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-05-1007-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-05-1007 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1007 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1045-CN E1	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-05-1045-CN E2	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-05-1045 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1045 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-05-1095-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-05-1095-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-05-1095 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SL WI-05-1095 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									-
	MOC :									
SL WI-05-1155 E1	TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION									-
	MOC :									
SL WI-05-1155 E2	TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION									-
	MOC :									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS									-
	INFORMATIONAL									
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS									-
	INFORMATIONAL									
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS									-
	INFORMATIONAL									
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									-
	MTH									
	RECOMMENDED									
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									-
	INFORMATIONAL									
	MOC :									
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									-
	CANCELLED									
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL									-
	INFORMATIONAL									
	MOC :									
SL 525B-20-05	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									-
	INFORMATIONAL									
	MOC :									
COM MC 525B-002	500 COMPRESSOR HOUR INSPECTION									-
	INFORMATIONAL									
	MOC :									
SL 525B-21-04	AIR CONDITIONING - PRESSURIZATION PRINTED CIRCUIT BOARD REPLACEMENT									-
	MOC :									
SL 525B-21-06	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT									-
	OPTIONAL									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-23-06	COMMUNICATIONS - AVIATOR 300 SATCOM ANTENNA REPLACEMENT OPTIONAL						-			
	MOC :									
SL 525B-23-03	COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA INFORMATIONAL						-			
	MOC :									
SL 525B-23-04	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE OPTIONAL						-			
	MOC :									
SL 525B-23-05	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8 OPTIONAL						-			
	MOC :									
SB 525B-24-09	GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING KSWF MANDATORY			MTH 06-Jul-2013 HRS 604 LDG 454			-			Complete
	MOC : COMPLIED WITH									
SB 525B-24-12	ELECTRICAL POWER - JUMPER INSTALLATION IN THE COMPRESSOR ASSEMBLY RECOMMENDED MTH						-			
	MOC :									
COM MC 525B-013	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES INFORMATIONAL						-			
	MOC :									
SB 525B-25-09	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK OPTIONAL						-			
	MOC :									
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION OPTIONAL						-			
	MOC :									
SB CIB-25-02	EQUIPMENT/FURNISHINGS - BELTED TOILET SEAT INERTIA REEL MODIFICATION RECOMMENDED						-			
	MOC :									
SL 525B-25-05	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION OPTIONAL						-			
	MOC :									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING KSWF MANDATORY			MTH 17-Apr-2019 HRS 2095.3 LDG 1646			-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CIL-26-01 R1 FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING PER ACCOMPLISHMENT INSTRUCTIONS.									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING MANDATORY MTH						-			
	MOC :									
SB CIB-28-01	FIREWALL SHUTOFF VALVE GROUND IMPROVEMENT KALN RECOMMENDED			MTH 09-Sep-2014 HRS 979.3 LDG 777			-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CIB-28-01 FUEL SHUTOFF VALVE GROUND IMPROVEMENT.									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 525B-29-03 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT			MANDATORY	MTH		A/R			
	MOC :									
SB 525B-29-04	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
	MOC :									
SL 525B-29-02	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION									
	KSWF			RECOMMENDED	MTH 17-Apr-2019		-			Complete
					HRS 2095.3					
					LDG 1646					
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB525B-29-02 ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION PER ACCOMPLISHMENT INSTRUCTIONS. PUMP P/N'S; 9912062-6 INSTALLED LEFT AND RIGHT NO FUTHER ACTION REQUIRED.									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
	INFORMATIONAL						-			
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION									
	INFORMATIONAL						-			
	MOC :									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL						-			
	INFORMATIONAL									
	MOC :									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION				MTH 29-Dec-2014		-			Complete
	KSWF			RECOMMENDED	HRS 1072.4					
					LDG 888					
	MOC :									
	COMPLIED WITH - ACCOMPLISHED SERVICE LETTER CIL 32-03 NLG UPLOCK ROLLER BRACKET INSPECTION PER CIL-32-03 ACCOMPLISHMENT INSTRUCTIONS.									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
	INFORMATIONAL						-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
	INFORMATIONAL						-			
	MOC :									
SL 525B-32-01 R01	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION									
	OPTIONAL						-			
	MOC :									
SL 525B-32-14	LANDING GEAR - MAIN LANDING GEAR REPAIR									
	INFORMATIONAL						-			
	MOC :									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY									
	INFORMATIONAL						-			
	MOC :									
ICA 525B-34-00000A	GARMIN GNS 500W ELECTRICAL BONDING CHECK				MTH 01-Feb-2022		120		01-Feb-2032	98 m 15 d
	KTPA				HRS 2618.2		2000		4618.2	1205.1
					LDG 1957					Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH GARMIN GNS 500W 10 YEAR/2000 HOURS ELECTRICAL BONDING CHECKS IAW GARMIN MANUAL 190-00357-65.									
ICA 525B-34-00000	GARMIN GNS 500W VISUAL INSPECTION				MTH 10-Feb-2023		12		10-Feb-2024	2 m 24 d
	KMCO				HRS 3017.6					Complete
					LDG 2225					
	MOC :									
	COMPLIED WITH - COMPLIED WITH THE GARMIN GNS 500W VISUAL INSPECTION IAW GARMIN 500W SERIES ICA MANUAL 190-00357-65 REV D.									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525B-34-03	ENHANCED SURVEILLANCE TRANSPONDER UPGRADE			OPTIONAL			A/R			
MOC :										
SB 525B-34-19 R03	NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES			OPTIONAL			-			
MOC :										
SB 525B-34-21	NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) SOFTWARE 7.1 UPGRADE			OPTIONAL			-			
MOC :										
SB 525B-34-26 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	KSWF		OPTIONAL	MTH 10-Oct-2018 HRS 2011.9 LDG 1596		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB525B-34-26 REV. 1 AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION PER ACCOMPLISHMENT INSTRUCTIONS.										
SB 525B-34-26 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-34-26	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-34-30	NAVIGATION - ADS-B OUT WIRING MODIFICATION			MANDATORY			-			
MOC :										
SB 525B-34-38 R01	NAVIGATION - REACTIVE WINDSHEAR INSTALLATION			OPTIONAL			-			
MOC :										
SB CIB-34-02	GPS-4000S SOFTWARE UPDATE	KALN		RECOMMENDED	MTH 09-Sep-2014 HRS 979.3 LDG 777		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CIB-34-02. SEE BELOW FOR 8130-3. PART IS ALSO LISTED ON THE "AIRFRAME MAINTENANCE" MTR.										
SB CIB-34-03 R01	NAVIGATION - TEMPERATURE COMPENSATION FOR LNAV/VNAV - CANCELED			CANCELLED			-			
MOC :										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
MOC :										
SB CIL-34-11	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT			OPTIONAL			-			
MOC :										
SL 525B-34-09	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION			INFORMATIONAL			-			
MOC :										
SL 525B-34-14	NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV			MANDATORY	MTH 18-Jul-2021 HRS 2547.2 LDG 1915		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL525B-34-14 NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV PER ACCOMPLISHMENT INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-35-01	TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01	KALN		MANDATORY	MTH 09-Sep-2014 HRS 979.3 LDG 777		-			N/A
MOC : NOT APPLICABLE - CESCOM TRACKING // NOT APPLICABLE DUE TO LOT CODE NUMBER. COMPLIED WITH CESSNA CIL-35-01 PER INSTRUCTIONS DOES NOT APPLY TO INSTALLED SMOKE GOGGLES.										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KALN		MANDATORY	MTH 16-Jun-2016 DAYS 1491.1 HRS 1275 LDG		-			N/A
MOC : NOT APPLICABLE - CIL-35-05 OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001, SERVICE LETTER. DOES NOT APPLY. AIRCRAFT HAS B/E AEROSPACE QUICK DONNING CREW MASKS.										
SL 525B-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	SWF		MANDATORY	MTH 09-Jul-2012 HRS 303.1 LDG 225		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY MANUFACTURE, B/E AEROSPACE INSTALLED.										
SL 525B-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 525B-35-02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SB 525B-36-03 R01	PNEUMATIC - MOISTURE TRAP INSTALLATION			OPTIONAL			-			
MOC :										
SB 525B-36-03	PNEUMATIC - MOISTURE TRAP INSTALLATION			OPTIONAL			-			
MOC :										
SL 525B-36-01 R01	PNEUMATIC - PRECOOLER LIFE LIMIT	KTPA		INFORMATIONAL	MTH 17-May-2023 HRS 3195 LDG 2361		-			
MOC : DEFERRED - PRECOOLER LIFE LIMIT SERVICE LETTER 525B-36-01 R01 COMPLIED WITH, PARTS NOT AVAILABLE, PARTS ON ORDER WITH MANUFACTURER. CREW REQUIRED TO MONITOR AND CHANGES IN ITT										
SL 525B-36-01	PRECOOLER LIFE LIMIT			INFORMATIONAL			-			
MOC :										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	SWF		MANDATORY	MTH 09-Feb-2013 HRS 481.3 LDG 349		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH THE SERVICE LETTER CIL-52-01 PER THE SERVICE LETTER ACCOMPLISHMENT INSTRUCTIONS WITH NO DEFECTS FOUND.										
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION			INFORMATIONAL			-			
MOC :										
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION	DXR		MANDATORY	MTH 08-Nov-2021 HRS 2598.8 LDG 1944		-			Complete
MOC : COMPLIED WITH										
SB 525B-54-02	NACELLES/PYLONS - FORWARD ENGINE BEAM INSPECTION ACCESS PANEL INSTALLATION			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525B-55-03 R01	STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION									
				RECOMMENDED			-			
	MOC :									
SL 525B-55-03	STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION									
				RECOMMENDED			-			
	MOC :									
SB 525B-57-02 R01	ANTI-ICE EXHAUST OUTLET IMPROVEMENT									
				RECOMMENDED			-			
	MOC :									
SB 525B-57-02	WINGS - ANTI-ICE EXHAUST OUTLET IMPROVEMENT				MTH 09-Sep-2014					Complete
		KALN		RECOMMENDED	HRS 979.3		-			
					LDG 777					
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB525B-57-02 AS PER INSTRUCTIONS.									
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SB 525B-71-03	COWL STIFFENER INSTALLATION				MTH 15-Nov-2013					Complete
		KSWF		MANDATORY	HRS 733.1		-			
					LDG 564					
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB525B-71-03 COWL STIFFENER INSTALLATION. ADDED STIFFENERS TO LEFT AND RIGHT LOWER COWLS PER ACCOMPLISHMENT INSTRUCTIONS.									
SL 525B-71-08 R01	POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT									
				MANDATORY			-			
	MOC :									
SL 525B-71-08 R02	POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT				MTH 16-Jun-2016					Complete
		KALN		MANDATORY	HRS 1491.1		-			
					LDG 1275					
	MOC :									
	COMPLIED WITH - COMPLIED WITH SL525B-71-08 R2 POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT, SERVICE LETTER.									
SL 525B-71-08	POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT				MTH					
				MANDATORY			-			
	MOC :									
SL 525B-71-09 R01	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION									
				OPTIONAL			-			
	MOC :									
SL 525B-71-09	POWER PLANT - ENGINE ISOLATOR MOUNTS INSPECTION EXTENSION (SUPERSEDED BY SL525B-71-09 R01)									
				OPTIONAL			-			
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									
							-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL					-			
	MOC :								
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-71-1319-CN E1	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-71-1319-CN E2	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-71-1319 E1	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-71-1319 E2	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-71-1541 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-71-1541 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
SB FJ44-72-066 R03 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)		RECOMMENDED			-			
	MOC :								
SB FJ44-72-066 R03 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)		RECOMMENDED			-			
	MOC :								
SB FJ44-72-066 R06 E1	CARBON RING SEAL AND BEARING HOUSING - REPLACE		RECOMMENDED			-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-066 R06 E2	CARBON RING SEAL AND BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-075 R01 E1	GEARBOX P/N 78823 - INSPECTION			MANDATORY			A/R			
	MOC :									
SB FJ44-72-075 R01 E2	GEARBOX P/N 78823 - INSPECTION			MANDATORY			A/R			
	MOC :									
SB FJ44-72-078 R03 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK OPTIONAL						-			
	MOC :									
SB FJ44-72-078 R03 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK OPTIONAL						-			
	MOC :									
SB FJ44-72-085 R05 E1	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06) RECOMMENDED						-			
	MOC :									
SB FJ44-72-085 R05 E2	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06) RECOMMENDED						-			
	MOC :									
SB FJ44-72-085 R08 E1	IP BLEED VALVE - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-085 R08 E2	IP BLEED VALVE - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-097 E1	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01) MANDATORY						-			
	MOC :									
SB FJ44-72-097 E2	ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01) MANDATORY						-			
	MOC :									
SB FJ44-72-104 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01) OPTIONAL						-			
	MOC :									
SB FJ44-72-104 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01) OPTIONAL						-			
	MOC :									
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04) OPTIONAL						-			
	MOC :									
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04) OPTIONAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-105 R05 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL						-			
	MOC :									
SB FJ44-72-105 R05 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL						-			
	MOC :									
SB FJ44-72-105 R06 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL			MTH			-			
	MOC :									
SB FJ44-72-105 R06 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL			MTH			-			
	MOC :									
SB FJ44-72-106 R03 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-106 R03 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R02 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R02 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R03 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R03 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R04 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R04 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R05 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R05 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 E1	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01) RECOMMENDED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-107 E2	ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)			CANCELLED			-			
	MOC :									
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)			CANCELLED			-			
	MOC :									
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		(5000)5000	1586.9
	MOC :									
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		(5000)5000	1586.9
	MOC :									
SB FJ44-72-110 E1	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE			MANDATORY	HRS		DUE DUE		(5000)5000	1586.9
	MOC :									
SB FJ44-72-110 E2	ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE			MANDATORY	HRS		DUE DUE		(5000)5000	1586.9
	MOC :									
SB FJ44-72-122-CNS E1	SUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-122-CNS E2	SUPERSEDED - ENGINE - ACCESSORY DRIVE SHAFT - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-124 R06 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-124 R06 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R07 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R07 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R08 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R08 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R09 E1	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-124 R09 E2	HP TURBINE BLADES - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-129 R01-CN E1	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-129 R01-CN E2	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-133 R01 E1	REPLACE 1ST LP TURBINE NOZZLE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-133 R01 E2	REPLACE 1ST LP TURBINE NOZZLE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE			RECOMMENDED	HRS		CSI CSI		(5000)5000	1586.9
	MOC :									
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE			RECOMMENDED	HRS		CSI CSI		(5000)5000	1586.9
	MOC :									
SB FJ44-72-133 E1	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-133 E2	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-140 R01 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH HRS		-		(5000)5000	1586.9
	MOC :									
SB FJ44-72-140 R01 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH HRS		-		(5000)5000	1586.9
	MOC :									
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			-			
	MOC :									
SB FJ44-72-140 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY			-			
	MOC :									
SB FJ44-72-151 R05 E1	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
	MOC :									
SB FJ44-72-151 R05 E2	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
	MOC :									
SB FJ44-72-151 R06 E1	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
	MOC :									
SB FJ44-72-151 R06 E2	BEARING AND PINION ASSEMBLY - INSTALL			MANDATORY			-			
	MOC :									
SB FJ44-72-154 R01 E1	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-154 R01 E2	1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-154 E1	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-154 E2	1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)			RECOMMENDED			-			
	MOC :									
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS						-			
	MOC :									
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS						-			
	MOC :									
SB WI-72-1004 R04 -CN E1	1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1004 R04 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)										
-CN				CANCELLED			-			
E2										
MOC :										
SB WI-72-1034 R01 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E1				MANDATORY			-			
MOC :										
SB WI-72-1034 R01 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E2				MANDATORY			-			
MOC :										
SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E1				MANDATORY			-			
MOC :										
SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E2				MANDATORY			-			
MOC :										
SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E1				MANDATORY	MTH		MPI			
MOC :										
SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E2				MANDATORY	MTH		MPI			
MOC :										
SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E1				MANDATORY	MTH					
MOC :										
SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E2				MANDATORY	LDG		8000		(8000)8000	5475
MOC :										
SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK										
E2				MANDATORY	MTH		8000		(8000)8000	5475
MOC :										
SB WI-72-1034	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK						-			
E1				MANDATORY						
MOC :										
SB WI-72-1034	HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK						-			
E2				MANDATORY						
MOC :										
SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E1				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R01 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E2				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E1					MTH		-			
MOC :										
SB WI-72-1037 R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E2					MTH		-			
MOC :										
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E1				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E2				RECOMMENDED			-			
MOC :										
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE										
E1				RECOMMENDED			CSI			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2				RECOMMENDED			CSI			
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							-			
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							-			
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E1							-			
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E2							-			
MOC :										
SB WI-72-1044 R02 BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09) E1							-			
MOC :										
SB WI-72-1044 R02 BALANCE PISTON - REPLACE (SUPERSEDED BY SB FJ44-72-124 R09) E2							-			
MOC :										
SB WI-72-1044 R03 BALANCE PISTON - REPLACE E1				RECOMMENDED			CSI			
MOC :										
SB WI-72-1044 R03 BALANCE PISTON - REPLACE E2				RECOMMENDED			CSI			
MOC :										
SB WI-72-1044 ENGINE - BALANCE PISTON - REPLACE E1				RECOMMENDED	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-72-1044 E2	ENGINE - BALANCE PISTON - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SL WI-72-1032-CN E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1032-CN E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1262 E1	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1262 E2	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB 525B-73-01	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) FIELD REPLACEMENT			OPTIONAL			-			
	MOC :									
SB FJ44-73-030 R10 E1	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R11)	KALN		MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275		-			N/A
	MOC : NOT APPLICABLE - FJ44-73-030 R10 NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06, SERVIC... HAS BEEN CANCELLED DUE TO ALL FADECs BEING UPGRADED. NO FURTHER ACTION IS REQUIRED.									
SB FJ44-73-030 R10 E2	ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R11)	KALN		MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275		-			N/A
	MOC : NOT APPLICABLE - FJ44-73-030 R10 NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06, SERVIC... HAS BEEN CANCELLED DUE TO ALL FADECs BEING UPGRADED. NO FURTHER ACTION IS REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-039 R02 E1	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
	MOC :									
SB FJ44-73-039 R02 E2	ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03)			MANDATORY			A/R			
	MOC :									
SB FJ44-73-042 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-73-042 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-73-043 R02 E1	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD			RECOMMENDED			-			
	MOC :									
SB FJ44-73-043 R02 E2	ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD			RECOMMENDED			-			
	MOC :									
SB FJ44-73-044 R03 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04)	KSWF		MANDATORY	MTH 04-Aug-2014 HRS 951 LDG 759		-			Complete
	MOC :									
SB FJ44-73-044 R03 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04)	KHPN		MANDATORY	MTH 04-Aug-2014 HRS 951 LDG 759		-			Complete
	MOC :									
SB FJ44-73-044 R07 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB FJ44-73-044 R07 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB FJ44-73-044 R08 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB FJ44-73-044 R08 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB FJ44-73-044 R09 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-044 R09 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE			MANDATORY			-			
	MOC :									
SB FJ44-73-061 E1	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)			RECOMMENDED			-			
	MOC :									
SB FJ44-73-061 E2	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)			RECOMMENDED			-			
	MOC :									
PSID WI-73-1008 R01 E1	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
PSID WI-73-1008 R01 E2	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG						-			
	MOC :									
SB WI-73-1002 R02 -CN E1	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
	MOC :									
SB WI-73-1002 R02 -CN E2	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
	MOC :									
SB WI-73-1002 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)			MANDATORY			-			
	MOC :									
SB WI-73-1002 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)			MANDATORY			-			
	MOC :									
SB WI-73-1002 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)			MANDATORY			-			
	MOC :									
SB WI-73-1002 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)			MANDATORY			-			
	MOC :									
SB WI-73-1007 R01 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
	MOC :									
SB WI-73-1007 R01 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
	MOC :									
SB WI-73-1008 R01 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R01 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-73-1008 R02 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1008 R02 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-73-1008 R03 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-73-1008 R03 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-73-1008 R04 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE E1		KTPA		RECOMMENDED	MTH 16-Jun-2023 HRS 3242.8 LDG 2393		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN WISB 73-1008-R04 - ENGINE FUEL AND CONTROL-OIL COOLER TO FDU FUEL TUBE REPLACEMENT ON #1 ENGINE S/N 141765 IN ACCORDANCE WITH WILLIAMS INTERNATIONAL WISB 73-1008-R04 DATED FEB 19/19.										
SB WI-73-1008 R04 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE E2		KTPA		RECOMMENDED	MTH 16-Jun-2023 HRS 3242.8 LDG 2393		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN WISB 73-1008-R04 - ENGINE FUEL AND CONTROL-OIL COOLER TO FDU FUEL TUBE REPLACEMENT ON #@ ENGINE S/N 141764 IN ACCORDANCE WITH WILLIAMS INTERNATIONAL WISB 73-1008-R04 DATED FEB 19/19.										
SB WI-73-1008 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1008 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1009 R01 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E1							-			
MOC :										
SB WI-73-1009 R01 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E2							-			
MOC :										
SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E1							-			
MOC :										
SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E2		KMSN			MTH 26-May-2019 HRS 2103 LDG 1652		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WILLIAMS INTERNATIONAL FJ44 SERVICE BULLETIN WISB-73-1009 REVISION 2 DATED AUGUST 6, 2018, FUEL TUBE ASSEMBLIES - REPLACE.										
SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E1							-			
MOC :										
SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E2							-			
MOC :										
SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E1				RECOMMENDED	MTH HRS		CSI CSI CSI		(5000)5000	1586.9
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1009 R04 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
	MOC :									
SB WI-73-1009 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
	RECOMMENDED									
	MOC :									
SB WI-73-1009 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
	RECOMMENDED									
	MOC :									
SB WI-73-1019-CN E1	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)									
	SUPERSEDED									
	MOC :									
SB WI-73-1019-CN E2	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)									
	SUPERSEDED									
	MOC :									
SB WI-73-1019 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)									
	MOC :									
SB WI-73-1019 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)									
	MOC :									
SB WI-73-1022 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
	NOT APPLICABLE									
	MOC :									
SB WI-73-1022 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
	NOT APPLICABLE									
	MOC :									
SB WI-73-1027 R01 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MANDATORY									
	MOC :									
SB WI-73-1027 R01 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MANDATORY									
	MOC :									
SB WI-73-1027 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MANDATORY									
	MOC :									
SB WI-73-1027 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
	MANDATORY									
	MOC :									
SB WI-73-1031 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
	MOC :									
SB WI-73-1031 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01									
	MOC :									
SL WI-73-1018-CN E1	CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG									
	CANCELLED									
	MOC :									
SL WI-73-1018-CN E2	CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG									
	CANCELLED									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-73-1018 E1	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG					-			
	MOC :								
SL WI-73-1018 E2	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG					-			
	MOC :								
SL WI-73-1026 E1	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1026 E2	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1037 E1	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1037 E2	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SB WI-74-1000 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KSWF	MANDATORY	MTH 07-Apr-2018 HRS 1918.7 LDG 1546		-			Complete
	MOC :								
	COMPLIED WITH - COMPLIED WITH WISB-74-1000 IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT PER ACCOMPLISHMENT INSTRUCTIONS.								
SB WI-74-1000 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KSWF	MANDATORY	MTH 07-Apr-2018 HRS 1918.7 LDG 1546		-			Complete
	MOC :								
	COMPLIED WITH - COMPLIED WITH WISB-74-1000 IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT PER ACCOMPLISHMENT INSTRUCTIONS.								
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1			RECOMMENDED			-			
	MOC :								
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2			RECOMMENDED			-			
	MOC :								
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1			RECOMMENDED	MTH HRS		-		(5000)5000	1586.9
	MOC :								
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2			RECOMMENDED	MTH HRS		-		(5000)5000	1586.9
	MOC :								
SB WI-75-1001 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-75-1001 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE		RECOMMENDED			-			
	MOC :								
SB 525B-76-04	ENGINE CONTROLS - UPDATED FJ44-3A FULL AUTHORITY ENGINE CONTROL (FADEC) FIELD REPLACEMENT		OPTIONAL			-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL									
				CANCELLED			-			

MOC :

SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
------------------------	---	--	--	-----------	--	--	---	--	--	--

MOC :

SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
---------------------	--	--	--	--	--	--	---	--	--	--

MOC :

SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
---------------------	--	--	--	--	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R01 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R01 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R02 E1	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED	MTH		-			
-----------------------------	--	--	--	-------------	-----	--	---	--	--	--

MOC :

SB FJ44-77-013 R02 E2	FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)			RECOMMENDED	MTH		-			
-----------------------------	--	--	--	-------------	-----	--	---	--	--	--

MOC :

SB FJ44-77-013 R04 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R04 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R05 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R05 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R06 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :

SB FJ44-77-013 R06 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07)			RECOMMENDED			-			
-----------------------------	--	--	--	-------------	--	--	---	--	--	--

MOC :



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-013 R07 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED						-			
MOC :										
SB FJ44-77-013 R07 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED						-			
MOC :										
SB FJ44-77-013 R09 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED			MTH HRS			DUE DUE DUE		(5000)5000	1586.9
MOC :										
SB FJ44-77-013 R09 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED			MTH HRS			DUE DUE DUE		(5000)5000	1586.9
MOC :										
SB FJ44-77-013 E1	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01) RECOMMENDED						-			
MOC :										
SB FJ44-77-013 E2	FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01) RECOMMENDED						-			
MOC :										
SB FJ44-79-009 R02 E1	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03) RECOMMENDED						-			
MOC :										
SB FJ44-79-009 R02 E2	ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03) RECOMMENDED						-			
MOC :										
SB FJ44-79-009 R05 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06) RECOMMENDED						-			
MOC :										
SB FJ44-79-009 R05 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06) RECOMMENDED						-			
MOC :										
SB FJ44-79-011 R01 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02) MANDATORY						-			
MOC :										
SB FJ44-79-011 R01 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02) MANDATORY						-			
MOC :										
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04) MANDATORY						-			
MOC :										
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04) MANDATORY						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		-		(5000)5000	1586.9
MOC :										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		-		(5000)5000	1586.9
MOC :										
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	1586.9
MOC :										
SB FJ44-79-012 R01 E2	OIL - LUBE OIL COOLER - REWORK OR REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		(5000)5000	1586.9
MOC :										
SB FJ44-79-012 E1	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-012 E2	LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R01 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 R01 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 R02 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-013 R02 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R03 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R03 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R04 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		-		(3500)3500	86.9
MOC :										
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		-		(3500)3500	86.9
MOC :										
SB FJ44-79-013 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
MOC :										
SB FJ44-79-013 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
MOC :										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R01 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R02 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R03)			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R03 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R04)			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-016 R04 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE	KTPA		RECOMMENDED	MTH 11-Jul-2022 HRS 2719.9 LDG 2022		-			Complete
MOC : COMPLIED WITH - FOUND OIL RELIEF VALVE SPLIT AND LEAKING. COMPLIED WITH WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-79-016. SYSTEM LEAK CHECK IS GOOD. WORK DONE PER WILLIAMS SB FJ44-79-016.										
SB FJ44-79-016 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R01)	KSWF		RECOMMENDED	MTH 01-Aug-2016 HRS 1543.4 LDG 1307		-			N/A
MOC : NOT APPLICABLE - S.B FJ44-79-16, OIL-RELIEF VALVE REPLACEMENT IS NOT APPLICABLE. EFFECTED P/N OF UNIT NOT INSTALLED ON THIS ENGINE.										
SB FJ44-79-T017 R01 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST			RECOMMENDED			-			
MOC :										
SB FJ44-79-T017 R01 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST			RECOMMENDED			-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2007-23-16	INCORPORATE ELECTRICAL POWER RELAY CIRCUIT PROTECTION KIT	ICT	MANDATORY	MTH 20-Aug-2011 HRS 7.8 LDG 4			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER AD2007-23-16: ELECTRICAL CIRCUIT POWER PROTECTION, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	KALN	MANDATORY	MTH 09-Sep-2014 HRS 979.3 LDG 777			-			N/A
MOC : NOT APPLICABLE - CESCOM TRACKING // AD 1974-08-09 REV 3 DOES NOT APPLY DUE TO CATEGORY OF AIRCRAFT. AD IS FOR TRANSPORT CATEGORY AIRCRAFT. THS AIRCRAFT IS A COMMUTER CATEGORY AIRCRAFT AS PER THE REGISTRATION / AIRWORTHINESS CERTIFICATE.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KALN	MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275			-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-02 APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT. DOES NOT APPLY. AIRCRAFT MODULAR SEATS ARE INSTALLED.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KALN	MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275			-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-02 APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT. DOES NOT APPLY. AIRCRAFT MODULAR SEATS ARE INSTALLED.										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KALN	MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275			-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-02 APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT. DOES NOT APPLY. AIRCRAFT MODULAR SEATS ARE INSTALLED.										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KALN	MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275			-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-02 APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT. DOES NOT APPLY. AIRCRAFT MODULAR SEATS ARE INSTALLED.										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KSWF		MTH 10-Oct-2018 HRS 2011.9 LDG 1596			-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01 PARA (G) EFFECTIVE DATE OCTOBER 24, 2017 IS NOT APPLICABLE BY PART NUMBER OF INSTALLED UNIT. 453-5060 (C406-N)										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT		MANDATORY				-			
MOC :										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS		MANDATORY				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KHPN	MANDATORY	MTH 23-Nov-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - BOTH CREW ROTARY BUCKLES MADE BY AMSAFE, NO ACTION REQUIRED									
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KHPN	MANDATORY	MTH 23-Nov-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - BOTH CREW ROTARY BUCKLES MADE BY AMSAFE, NO ACTION REQUIRED									
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	KHPN	MANDATORY	MTH 23-Nov-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - BOTH CREW ROTARY BUCKLES MADE BY AMSAFE, NO ACTION REQUIRED									
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	KHPN	MANDATORY	MTH 23-Nov-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - BOTH CREW ROTARY BUCKLES MADE BY AMSAFE, NO ACTION REQUIRED									
FAA 2005-17-11	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES	ICT	MANDATORY	MTH 20-Aug-2011 HRS 7.8 LDG 4		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER AD2005-17-11: INSTALLATION OF ID SLEEVES ON ENGINE FIRE BOTTLES, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER									
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLET'S INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06)	KMCO	MANDATORY	MTH 09-Dec-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - AD 2019-08-13 ATLAS WINGLET MOD DOES NOT APPLY TO AIRCRAFT 525B-0364 DUE TO EFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KTPA	MANDATORY	MTH 03-Jan-2022 HRS 2603 LDG 1948		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2021-23-12 BY MEANS OF PLACING FIGURE 1 IN AFM AS REQUIRED									
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)		MANDATORY			-			
MOC :									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	KTPA	MANDATORY	MTH 29-Jun-2023 HRS 3245.9 LDG 2395		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SECTION "I" OF THIS AD BY ADDING INTO THE AFM FIGURE 3 INTO THE LIMITATIONS SECTION.									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION			MANDATORY			-			
MOC :										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	SWF		MANDATORY	MTH 09-Jul-2012 HRS 303.1 LDG 225		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE. COLLINS TCAS II P/N; 822-1294-002 INSTALLED.										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KALN		MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275		-			Complete
MOC : COMPLIED WITH - FAA 2014-18-01 NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION. UNITS INSTALLED ARE -409. NO FURTHER ACTION REQUIRED AT THIS TIME.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KALN		MANDATORY	MTH 16-Jun-2016 HRS 1491.1 LDG 1275		-			N/A
MOC : NOT APPLICABLE - FAA 2015-10-51 APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIM... NOT REQUIRED DUE TO EQUIPMENT INSTALLED IN AIRCRAFT.										
FAA 2019-12-09	APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)	KSWF		SUPERSEDED	DAYS 26-Oct-2019 HRS 2208.7 LDG 1722		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD-2109-12-09. AIRCRAFT IS NOT EQUIPED WITH THE EFFECTIVE FLIGHT DISPLAY SYSTEM.										
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	KSWF		MANDATORY	MTH 18-Jul-2021 HRS 2547.2 LDG 1915		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2020-10-05 EFFECTIVE DATE JUNE 24, 2020 PARA'S (F)(G)(H) BY COMPLETING ROCKWELL COLLINS CSU-XX00-18-1 DATED JUNE 27, 2018 AND SIL FMC-XX00-18-1 DATED FEBRUARY 5, 2019.										
FAA 2021-05-17 PARA (G)(1) & (G)(2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)	KMCO		MANDATORY	MTH 09-Dec-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - AD2021-05-17 ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM DOES NOT APPLY TO AIRCRAFT 525B-0364 DUE TO EFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE	KMCO		MANDATORY	MTH 09-Dec-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - AD2021-05-17 ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM DOES NOT APPLY TO AIRCRAFT 525B-0364 DUE TO EFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE	KMCO	MANDATORY	MTH 09-Dec-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - AD2021-05-17 ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM DOES NOT APPLY TO AIRCRAFT 525B-0364 DUE TO EFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE	KMCO	MANDATORY	MTH 09-Dec-2021 HRS 2602 LDG 1946		-			N/A
MOC : NOT APPLICABLE - AD2021-05-17 ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM DOES NOT APPLY TO AIRCRAFT 525B-0364 DUE TO EFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KALN	MANDATORY	MTH 31-Jul-2015 HRS 1263.6 LDG 1064		-			N/A
MOC : NOT APPLICABLE - FAA 2015-08-07 OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTE... DOES NOT APPLY. AIRCRAFT IS EQUIPPED WITH BE AEROSPACE CREW OXYGENMASKS.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KALN	MANDATORY	MTH 31-Jul-2015 HRS 1263.6 LDG 1064		-			N/A
MOC : NOT APPLICABLE - FAA 2015-08-07 OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTE... DOES NOT APPLY. AIRCRAFT IS EQUIPPED WITH BE AEROSPACE CREW OXYGENMASKS.									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KALN	MANDATORY	MTH 31-Jul-2015 HRS 1263.6 LDG 1064		-			N/A
MOC : NOT APPLICABLE - FAA 2015-08-07 OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTE... DOES NOT APPLY. AIRCRAFT IS EQUIPPED WITH BE AEROSPACE CREW OXYGENMASKS.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	MCO	MANDATORY	MTH 30-Dec-2015 DAYS 1368.4 HRS 1170 LDG		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	MCO	MANDATORY	MTH 30-Dec-2015 DAYS 1368.4 HRS 1170 LDG		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1		MANDATORY	MTH 30-Dec-2015 DAYS 1368.4 HRS 1170 LDG		-			N/A
	MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.								
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."		MANDATORY	MTH 30-Dec-2015 DAYS 1368.4 HRS 1170 LDG		-			N/A
	MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.								
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	MCO	MANDATORY	MTH 30-Dec-2015 HRS 1368.4 LDG 1170		-			N/A
	MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.								
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	MCO	MANDATORY	MTH 30-Dec-2015 HRS 1368.4 LDG 1170		-			N/A
	MOC : NOT APPLICABLE - AD2015-23-09 IS NOT APPLICABLE DUE TO PART/SERIAL NUMBER AFFECTIVITY. NO FURTHER ACTION REQUIRED.								
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KSWF	MANDATORY	MTH 01-Aug-2016 HRS 1543.4 LDG 1308 ACH 384.7		-			N/A
	MOC : NOT APPLICABLE - AD 2016-11-20 PARA (G) EFFECTIVE DATE; JULY 15, 2016 IS NOT APPLICEABLE, EQUIPMENT NOT INSTALLED.								
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KSWF	MANDATORY	MTH 01-Aug-2016 HRS 1543.4 LDG 1308 ACH 384.7		-			N/A
	MOC : NOT APPLICABLE - AD 2016-11-20 PARA (H)(1) EFFECTIVE DATE; JULY 15, 2016 IS NOT APPLICEABLE, EQUIPMENT NOT INSTALLED.								
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KSWF	MANDATORY	MTH 01-Aug-2016 HRS 1543.4 LDG 1308 ACH 384.7		-			N/A
	MOC : NOT APPLICABLE - AD 2016-11-20 PARA (H)(2) EFFECTIVE DATE; JULY 15, 2016 IS NOT APPLICEABLE, EQUIPMENT NOT INSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KSWF		MANDATORY	MTH 01-Aug-2016 HRS 1543.4 LDG 1308 ACH 384.7		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 EFFECTIVE DATE; JULY 15, 2016 IS NOT APPLICABLE, EQUIPMENT NOT INSTALLED.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KSWF		MANDATORY	MTH 07-Apr-2018 HRS 1918.7 LDG 1547		-			N/A
MOC : NOT APPLICABLE - FAA 2017-18-12 PARA (I) & (J), EFFECTIVE DATE: OCTOBER 16, 2017, IS NOT APPLICABLE. AIRCRAFT IS NOT EQUIPPED.										
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES			MANDATORY			-			
MOC :										
FAA 2008-03-10	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	ICT		AIRWORTHINESS	DAYS 20-Aug-2011 HRS 7.8 LDG 4		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER AD2008-03-10: FUSELAGE LOWER SKIN INSPECT, DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER										
FAA 2022-13-15 E1	TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE			MANDATORY	MTH		-			
MOC :										
FAA 2022-13-15 E2	TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE			MANDATORY	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FORTUNATO AIR LLC**
Aircraft Model: **525B - CJ3**
Aircraft Serial: **525B-0364**
Unit: Reg No: **N7578K**
Airworthiness: **20-Aug-2011**
Print Date: **17-Nov-2023 1:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3413.1	2525	17-Nov-2023	1.03
ENG 1	3413.1	2525	17-Nov-2023	1.03
ENG 2	3413.1	2525	17-Nov-2023	1.03
AIR COND	1327.7		17-Nov-2023	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
00FO790	CONFIGURATION TYPE C FACTORY OPTION			790 FO	MTH 20-Aug-2011		-	0		
23FO36	LOCKING FUEL CAPS (EXCHANGE) FACTORY OPTION			36 FO	MTH 20-Aug-2011		-	0		
23FO501	MOBIL JET II OIL FACTORY OPTION			501 FO	MTH 20-Aug-2011		-	0		
23FO631	HF 9000 HIGH FREQUENCY COMM(PROV) COLLINS FACTORY OPTION			631 FO	MTH 20-Aug-2011		-	0		
23FO650	VOICE ANNUNCIATOR FACTORY OPTION			650 FO	MTH 20-Aug-2011		-	0		
23FO675G	AIRCELL ST-3100 FACTORY OPTION			675G FO	MTH 20-Aug-2011		-	0		
24FO655	ELECTRONIC CHARTS - JEPPESEN FACTORY OPTION			655 FO	MTH 20-Aug-2011		-	0		
25FO119E	SIDE FACING SEAT & CABINET FACTORY OPTION			119E FO	MTH 20-Aug-2011		-	0		
25FO728C	MONTEREY COLORED CKP/CABIN DOOR TRIM FACTORY OPTION			728C FO	MTH 20-Aug-2011		-	0		
34FO11A	PILOT'S ANGLE OF ATTACK INDEX-SAFELIGHT FACTORY OPTION			11A FO	MTH 20-Aug-2011		-	0		
34FO658C	SINGLE ADF-COLLINS FACTORY OPTION			658C FO	MTH 20-Aug-2011		-	0		
34FO686Q	FMS 2 GARMIN GPS-500 FACTORY OPTION			686Q FO	MTH 20-Aug-2011		-	0		
34FO691H	MARK VIII EGPWS -HONEYWELL (EX) FACTORY OPTION			691H FO	MTH 20-Aug-2011		-	0		
34FO692Y	CABIN DISPLAY POWER FACTORY OPTION			692Y FO	MTH 20-Aug-2011		-	0		
56FO900	REPL STND ENTRY DR STEPS W/BRAVO/ENCORE STYLE ENTR STPS FACTORY OPTION			900 FO	MTH 20-Aug-2011		-	0		