



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                                          | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------------------------------------------------------------------------------------------|------|---------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PPPP1                 | PAINT AIRCRAFT                                                                                                             | KIWA |                                       | MTH 20-Mar-2015<br>HRS 921.3<br>LDG 879   |                | O/C            |                |                            |                    |
| 4-12-MA<br>05120MA    | INSPECTION DOCUMENT MA<br>KCRQ                                                                                             |      |                                       | MTH 30-Dec-2022<br>HRS 2492.9<br>LDG 1916 |                | 300            |                | 2792.9                     | 158                |
| 4-12-MC<br>05120MC    | INSPECTION DOCUMENT MC<br>KCRQ                                                                                             |      |                                       | MTH 26-May-2022<br>HRS 2369.1<br>LDG 1846 |                | 1200           |                | 3569.1                     | 934.2              |
| 4-12-MD<br>05120MD    | INSPECTION DOCUMENT MD<br>KEUG                                                                                             |      |                                       | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | 1425           |                | 2857.2                     | 222.3              |
| 4-12-ME<br>05120ME    | INSPECTION DOCUMENT ME (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)<br>*CF                                          |      |                                       | MTH 05-Nov-2008<br>HRS 0<br>LDG 0         |                | 5000           |                |                            |                    |
| 32-20-00-250          | NOSE LANDING GEAR FORK AND PISTON ASSEMBLY (EDDY CURRENT OR DYE PENETRANT) SPECIAL DETAILED INSPECTION<br>6342200-4<br>NSN |      |                                       | MTH 05-Nov-2008<br>LDG 0                  |                | 5000           |                | 5000                       | 2992               |
| 4-12-MF<br>05120MF    | INSPECTION DOCUMENT MF<br>KCRQ                                                                                             |      |                                       | MTH 29-Mar-2023<br>HRS 2556.5<br>LDG 1955 | -6.5           | 2550           |                | 5100                       | 2465.1             |
| 4-12-MG<br>05120MG    | INSPECTION DOCUMENT MG<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 2800           |                | 2800                       | 165.1              |
| 4-12-MH<br>05120MH    | INSPECTION DOCUMENT MH<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 3100           |                | 3100                       | 465.1              |
| 4-12-MI<br>05120MI    | INSPECTION DOCUMENT MI<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 4950           |                | 4950                       | 2315.1             |
| 4-12-MJ<br>05120MJ    | INSPECTION DOCUMENT MJ<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 5000           |                | 5000                       | 2365.1             |
| 4-12-MK<br>05120MK    | INSPECTION DOCUMENT MK<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 5050           |                | 5050                       | 2415.1             |
| 4-12-ML<br>05120ML    | INSPECTION DOCUMENT ML<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 5050           |                | 5050                       | 2415.1             |
| 4-12-MM<br>05120MM    | INSPECTION DOCUMENT MM<br>*CF                                                                                              |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 6000           |                | 6000                       | 3365.1             |
| 4-12-MN               | INSPECTION DOCUMENT MN<br>KCRQ                                                                                             |      |                                       | MTH 29-Sep-2023<br>HRS 2622.7<br>LDG 1998 |                | 12<br>330      |                | 30-Sep-2024<br>2952.7      | 8 m 26 d<br>317.8  |
| 4-12-MO               | INSPECTION DOCUMENT MO                                                                                                     |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 5300           |                | 5300                       | 2665.1             |
| 4-12-MQ               | INSPECTION DOCUMENT MQ                                                                                                     |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 11250          |                | 11250                      | 8615.1             |
| 4-12-MR               | INSPECTION DOCUMENT MR                                                                                                     |      |                                       | MTH<br>HRS                                |                | 11400          |                | 11400                      | 8765.1             |
| 4-12-MS               | INSPECTION DOCUMENT MS                                                                                                     |      |                                       | MTH<br>HRS                                |                | 12000          |                | 12000                      | 9365.1             |
| 4-12-MT               | INSPECTION DOCUMENT MT                                                                                                     |      |                                       | MTH                                       |                | N/A            |                |                            |                    |
| 4-12-MU               | INSPECTION DOCUMENT MU                                                                                                     |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 13000          |                | 13000                      | 10365.1            |
| 4-12-MV               | INSPECTION DOCUMENT MV                                                                                                     |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 14000          |                | 14000                      | 11365.1            |
| 4-12-MW               | INSPECTION DOCUMENT MW                                                                                                     |      |                                       | MTH 05-Nov-2008<br>HRS 0                  |                | 15000          |                | 15000                      | 12365.1            |
| 4-12-MX               | INSPECTION DOCUMENT MX                                                                                                     |      |                                       | MTH 05-Nov-2008                           |                | N/A            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position               | Description<br>Drawing # / Task #                                                                                                                                                    | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains  |
|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|---------------------|
| 052105D                             | INSPECT 12 MONTHS ENVIRO SYSTEM CHECK                                                                                                                                                | KCRQ |                                       | MTH 10-Feb-2023<br>HRS 2510.8<br>LDG 1931 |                | 12             |                | 29-Feb-2024                | 1 m 25 d            |
| 055007                              | ACCOMPLISH INTERIOR CABIN/TAILCONE FLUID SPILL                                                                                                                                       |      |                                       | MTH                                       |                | A/R            |                |                            |                     |
| 055008                              | ACCOMPLISH EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED                                                                                                                       |      |                                       | MTH                                       |                | A/R            |                |                            |                     |
| 5-12-01<br>0512001                  | INSPECTION DOCUMENT 1                                                                                                                                                                | SMF  |                                       | MTH 17-Nov-2023<br>HRS 2633.1<br>LDG 2005 |                | 300            |                | 2933.1                     | 298.2               |
| 5-12-02<br>0512002                  | INSPECTION DOCUMENT 2                                                                                                                                                                | KCRQ |                                       | MTH 10-Feb-2023<br>HRS 2510.8<br>LDG 1931 |                | 12             |                | 29-Feb-2024                | 1 m 25 d            |
| B262201<br>CABIN<br>0512016 : CABIN | CABIN PORTABLE FIRE EXTINGUISHER (WEIGHT) FUNCTIONAL CHECK TASK 26-22-00-720                                                                                                         | KCRQ | C352<br>X-467662                      | MTH 09-Feb-2023                           |                | 12             |                | 29-Feb-2024                | 1 m 25 d            |
| B262201<br>COCKPIT<br>0512016       | COCKPIT PORTABLE FIRE EXTINGUISHER (WEIGHT) FUNCTIONAL CHECK TASK 26-22-00-720                                                                                                       | KCRQ | A352TS<br>F-60590241                  | MTH 09-Feb-2023                           |                | 12             |                | 29-Feb-2024                | 1 m 25 d            |
| 5-12-03<br>0512003                  | INSPECTION DOCUMENT 3                                                                                                                                                                |      |                                       | MTH 31-Mar-2022<br>HRS 2355.7<br>LDG 1836 |                | 24             |                | 31-Mar-2024                | 2 m 27 d            |
| 5-12-06                             | INSPECTION DOCUMENT 6 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                                                                                                            | EDDV |                                       | MTH 07-Oct-2013<br>HRS 873.92<br>LDG 823  |                | 72             |                |                            |                     |
| A262201<br>CABIN<br>0512006 : CABIN | CABIN PORTABLE FIRE EXTINGUISHER (BOREScope) SPECIAL DETAILED INSPECTION TASK 26-22-00-610                                                                                           | SMF  | C352<br>X-467662                      | MTH 01-Dec-2020                           |                | 72             |                | 31-Dec-2026                | 35 m 27 d           |
| A262201<br>COCKPIT<br>0512006       | COCKPIT PORTABLE FIRE EXTINGUISHER (BOREScope) SPECIAL DETAILED INSPECTION TASK 26-22-00-610                                                                                         |      | A352TS<br>F-60590241                  | MTH 16-Aug-2019                           |                | 72             |                | 31-Aug-2025                | 19 m 27 d           |
| 5-12-08<br>0512008                  | INSPECTION DOCUMENT 8                                                                                                                                                                | KCRQ |                                       | MTH 30-Dec-2022<br>HRS 2492.9<br>LDG 1916 |                | 24<br>300      |                | 31-Dec-2024<br>2792.9      | 11 m 27 d<br>158    |
| 5-12-09                             | INSPECTION DOCUMENT 9 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                                                                                                            |      |                                       | MTH 06-Sep-2023<br>HRS 2609.3<br>LDG 1989 |                | 4<br>200       |                |                            |                     |
| A243301                             | LEAD ACID BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK NOTE: THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED BASED ON OPERATIONS TASK 24-33-00-720 | KCRQ | S3597-4<br>40883382                   | MTH 06-Sep-2023<br>HRS 2609.3<br>LDG 1989 |                | 6<br>500       |                | 31-Mar-2024<br>3109.3      | 2 m 27 d<br>474.4   |
| 5-12-10<br>0512010                  | INSPECTION DOCUMENT 10                                                                                                                                                               | SMF  |                                       | MTH 17-Nov-2023<br>HRS 2633.1<br>LDG 2005 |                | 36<br>1200     |                | 30-Nov-2026<br>3833.1      | 34 m 26 d<br>1198.2 |
| 5-12-11<br>0512011                  | INSPECTION DOCUMENT 11                                                                                                                                                               | SMF  |                                       | MTH 17-Nov-2023<br>HRS 2633.1<br>LDG 2005 |                | 36<br>1200     |                | 30-Nov-2026<br>3833.1      | 34 m 26 d<br>1198.2 |
| 5-12-12<br>0512012                  | INSPECTION DOCUMENT 12 (14 CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                                                                                           | SMF  |                                       | MTH 17-Nov-2023<br>HRS 2633.1<br>LDG 2005 |                | 12             |                |                            |                     |
| A256002                             | EMERGENCY LOCATOR TRANSMITTER DETAILED INSPECTION TASK 25-60-00-210                                                                                                                  | SMF  | 453-5060<br>05843                     | MTH 17-Nov-2023                           |                | 12             |                | 30-Nov-2024                | 10 m 26 d           |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position                                     | Description<br>Drawing # / Task #                                                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| B256003                                                   | OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR BEACON SYSTEM (14 CFR 91.207)                         | SMF  |         | 453-5060<br>05843             | MTH 17-Nov-2023                           |                | 12             |                | 30-Nov-2024                | 10 m 26 d          |
| 5-12-13                                                   | INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) | KCRQ |         |                               | MTH 04-Nov-2022<br>HRS 2468<br>LDG 1902   |                | 24             |                |                            |                    |
| 341060<br><i>0512013 : RVSM</i>                           | FUNCTIONAL CHECK RVSM SKIN WAVINESS (CFR 91.411, 91.413, AND RVSM)                                        | KCRQ |         |                               | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| 341066<br>LEFT<br><i>0512013 : L-ADC</i>                  | CALIBRATION TEST AIR DATA COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)                              | KCRQ |         | 822-1109-014<br>357JF         | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| 341068<br>RIGHT<br><i>0512013 : R-ADC</i>                 | CALIBRATION TEST AIR DATA COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)                              | KCRQ |         | 822-1109-014<br>357MW         | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| 341070<br>STANDBY<br><i>0512013 : STDBY</i>               | CALIBRATION TEST ADC COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)                                   | KCRQ |         | 501-1890-04<br>3311           | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| B341001<br>LEFT<br><i>0512013 : L</i>                     | FUNCTIONAL CHECK PITOT-STATIC SYSTEM (CFR 91.411, 91.413, AND RVSM)                                       | KCRQ |         |                               | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| B341001<br>RIGHT<br><i>0512013 : R</i>                    | FUNCTIONAL CHECK PITOT STATIC SYSTEM (CFR 91.411, 91.413, AND RVSM)                                       | KCRQ |         |                               | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| B345001<br>NO. 1<br><i>0512013 : 1</i>                    | NO. 1 TRANSPONDER SYSTEM 14 CFR PART 91.413 (CALIBRATION) FUNCTIONAL CHECK TASK 34-50-06-720              | KCRQ |         | 622-9210-501<br>4DVHRR        | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| B345001<br>NO. 2<br><i>0512013 : 2</i>                    | NO. 2 TRANSPONDER SYSTEM 14 CFR PART 91.413 (CALIBRATION) FUNCTIONAL CHECK TASK 34-50-06-720              | KCRQ |         | 622-9210-501<br>290YK         | MTH 04-Nov-2022                           | -22            | 24             |                | 31-Oct-2024                | 9 m 27 d           |
| 5-12-14                                                   | INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                                | MSC  |         |                               | MTH 22-Sep-2017<br>HRS 1372.8<br>LDG 1096 |                | T/C            |                |                            |                    |
| A324103<br>LEFT MAIN GEAR<br><i>0512014C : L</i>          | SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI)                                      | KCRQ |         | 3-1601-3<br>1093              | MTH 29-Jun-2022<br>HRS 2375.6<br>LDG 1854 |                | T/C            |                |                            |                    |
| A324103<br>NOSE LANDING<br>GEAR<br><i>0512014C : NOSE</i> | SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI)                                      | SMF  |         | 3-1418<br>8260                | MTH 13-Oct-2020<br>HRS 1919.3<br>LDG 1392 |                | T/C            |                |                            |                    |
| A324103<br>RIGHT MAIN GEAR<br><i>0512014C : R</i>         | SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI)                                      | KCRQ |         | 3-1601-3<br>1098              | MTH 29-Jun-2022<br>HRS 2375.6<br>LDG 1854 |                | T/C            |                |                            |                    |
| 5-12-17                                                   | INSPECTION DOCUMENT 17 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)                                | EDDV |         |                               | MTH 12-Nov-2012<br>HRS 798<br>LDG 730     |                | 12<br>100      |                |                            |                    |
| 5-12-19                                                   | INSPECTION DOCUMENT 19                                                                                    |      |         |                               | MTH 05-Nov-2008<br>HRS 0                  |                | 5000           |                | 5000                       | 2365.1             |
| 5-12-21<br><i>0512021</i>                                 | INSPECTION DOCUMENT 21                                                                                    | KCRQ |         |                               | MTH 01-Dec-2022<br>HRS 2468<br>LDG 1902   |                | 24<br>600      |                | 31-Dec-2024<br>3068        | 11 m 27 d<br>433.1 |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code          | Description                                       | Part Number | C/W Time 1        | Adj.                          | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |                       |                    |
|--------------------|---------------------------------------------------|-------------|-------------------|-------------------------------|------------|--------|-------------|---------|-----------------------|--------------------|
| Position           | Drawing # / Task #                                | City        | Mod Lvl           | Part Serial No                | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2           | Remains            |
| 5-12-24<br>0512024 | INSPECTION DOCUMENT 24<br>SMF                     |             | MTH<br>HRS<br>LDG | 17-Nov-2023<br>2633.1<br>2005 |            |        | 12<br>300   |         | 30-Nov-2024<br>2933.1 | 10 m 26 d<br>298.2 |
| 5-12-26            | INSPECTION DOCUMENT 26<br>KCRQ                    |             | MTH<br>HRS<br>LDG | 06-Sep-2023<br>2609.3<br>1989 | -30        |        | 6           |         | 29-Feb-2024           | 1 m 25 d           |
| 052001<br>E1       | FJ44 CHECK 1<br>KCRQ                              |             | MTH<br>HRS<br>LDG | 29-Sep-2022<br>2447.5<br>1886 | -42.5      |        | 300         |         | (2631.4)2705          | 70.1               |
| 052001<br>E2       | FJ44 CHECK 1<br>KCRQ                              |             | MTH<br>HRS<br>LDG | 29-Sep-2022<br>2447.5<br>1886 | -42.5      |        | 300         |         | (2631.4)2705          | 70.1               |
| 052002<br>E1       | FJ44 CHECK 2<br>UNK                               |             | MTH<br>HRS<br>LDG | 22-Jun-2021<br>2105<br>1699   |            |        | 600         |         | (2631.4)2705          | 70.1               |
| 052002<br>E2       | FJ44 CHECK 2<br>UNK                               |             | MTH<br>HRS<br>LDG | 17-Jun-2021<br>2105<br>1699   |            |        | 600         |         | (2631.4)2705          | 70.1               |
| 052003<br>E1       | FJ44 CHECK 3<br>UNK                               |             | MTH<br>HRS<br>LDG | 22-Jun-2021<br>2105.1<br>1699 |            |        | -           |         |                       |                    |
| 052003<br>E2       | FJ44 CHECK 3<br>UNK                               |             | MTH<br>HRS<br>LDG | 17-Jun-2021<br>2105.1<br>1699 |            |        | -           |         |                       |                    |
| 052004<br>E1       | FJ44 CHECK 4                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 4000        |         | (4000)4073.7          | 1438.8             |
| 052004<br>E2       | FJ44 CHECK 4                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 4000        |         | (4000)4073.7          | 1438.8             |
| 052005<br>E1       | FJ44 CHECK 5                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 6000        |         | (6000)6073.7          | 3438.8             |
| 052005<br>E2       | FJ44 CHECK 5                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 6000        |         | (6000)6073.7          | 3438.8             |
| 052006<br>E1       | FJ44 CHECK 6                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 8000        |         | (8000)8073.7          | 5438.8             |
| 052006<br>E2       | FJ44 CHECK 6                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 8000        |         | (8000)8073.7          | 5438.8             |
| 052007<br>E1       | FJ44 CHECK 7                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 10000       |         | (10000)10073.7        | 7438.8             |
| 052007<br>E2       | FJ44 CHECK 7                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 10000       |         | (10000)10073.7        | 7438.8             |
| 052008<br>E1       | FJ44 CHECK 8                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 12000       |         | (12000)12073.7        | 9438.8             |
| 052008<br>E2       | FJ44 CHECK 8                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 12000       |         | (12000)12073.7        | 9438.8             |
| 052009<br>E1       | FJ44 CHECK 9                                      |             | MTH<br>HRS        | 06-Nov-2008<br>73.7           |            |        | 14000       |         | (14000)14073.7        | 11438.8            |
| 052009<br>E2       | FJ44 CHECK 9                                      |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 14000       |         | (14000)14073.7        | 11438.8            |
| 052010<br>E1       | FJ44 CHECK 10                                     |             | MTH<br>HRS        | 06-Nov-2008<br>73.7           |            |        | 16000       |         | (16000)16073.7        | 13438.8            |
| 052010<br>E2       | FJ44 CHECK 10                                     |             | MTH<br>HRS        | 05-Nov-2008<br>73.7           |            |        | 16000       |         | (16000)16073.7        | 13438.8            |
| 12-26-00-600       | 15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH |             | MTH               | 05-Nov-2008                   |            |        | A/R         |         |                       |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position                                 | Description<br>Drawing # / Task #                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------|------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 12-26-00-601                                          | 45 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 2 WASH                                              |      |         |                               | MTH 05-Nov-2008                                        |                | A/R            |                |                            |                    |
| 12-26-00-602                                          | 90 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 3 WASH                                              |      |         |                               | MTH 05-Nov-2008                                        |                | A/R            |                |                            |                    |
| 052101                                                | INSPECTION ENVIROSYSTEMS 500 HR<br>KCRQ                                                        |      |         |                               | MTH 30-Dec-2022<br>HRS 2492.9<br>LDG 1916<br>ACH 737.2 |                | 500            |                | 1237.2                     | 447.2              |
| 21-50-00-960                                          | COMPRESSOR DRIVE MOTOR BRUSHES DISCARD<br>1251171-6<br>NSN                                     |      |         |                               | MTH<br>ACH                                             |                | 800            |                | 1098.6                     | 308.6              |
| 23-70-00-960                                          | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD<br>DK120/90<br>AT166526       |      |         |                               | MTH                                                    |                | DUE<br>DUE     |                | 31-Mar-2028                | 50 m 27 d          |
| 25-60-00-960                                          | EMERGENCY LOCATOR TRANSMITTER BATTERY DISCARD<br>KCRQ                                          |      |         | 452-0133<br>399355-027        | MTH 01-Mar-2023                                        |                | 60             |                | 31-Mar-2028                | 50 m 27 d          |
| 26-20-00-961<br>LEFT ENGINE<br>0512005 : L            | LEFT ENGINE FIRE EXTINGUISHER BOTTLES (HYDROSTATIC TEST) FUNCTIONAL CHECK<br>KCRQ              |      |         | 30401102-2<br>59362B1         | MTH 22-Sep-2022                                        |                | 60             |                | 30-Sep-2027                | 44 m 26 d          |
| 26-20-00-961<br>RIGHT ENGINE<br>0512005 : R           | RIGHT ENGINE FIRE EXTINGUISHER BOTTLES (HYDROSTATIC TEST) FUNCTIONAL CHECK<br>KCRQ             |      |         | 30401102-2<br>60193B1         | MTH 22-Sep-2022                                        |                | 60             |                | 30-Sep-2027                | 44 m 26 d          |
| 26-20-00-962.1<br>LEFT ENGINE<br>NO.1<br>262002 : L1  | LEFT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (SERVICE LIFE)<br>*CF              |      |         | M13083-5<br>42941             | MTH                                                    |                | 96             |                | 31-Jan-2028                | 48 m 27 d          |
| 26-20-00-962.1<br>LEFT ENGINE<br>NO.2<br>262002 : L2  | LEFT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (SERVICE LIFE)<br>*CF              |      |         | M13083-5<br>43073             | MTH                                                    |                | 96             |                | 31-Jan-2028                | 48 m 27 d          |
| 26-20-00-962.1<br>RIGHT ENGINE<br>NO.1<br>262002 : R1 | RIGHT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (SERVICE LIFE)<br>*CF             |      |         | M13083-5<br>43057             | MTH                                                    |                | 96             |                | 31-Jan-2028                | 48 m 27 d          |
| 26-20-00-962.1<br>RIGHT ENGINE<br>NO.2<br>262002 : R2 | RIGHT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (SERVICE LIFE)<br>*CF             |      |         | M13083-5<br>42957             | MTH                                                    |                | 96             |                | 31-Jan-2028                | 48 m 27 d          |
| 26-20-00-962<br>LEFT ENGINE<br>NO.1                   | LEFT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (MAX LIFE)<br>M13083-5<br>42941    |      |         |                               | MTH                                                    |                | 120            |                | 31-Oct-2029                | 69 m 27 d          |
| 26-20-00-962<br>LEFT ENGINE<br>NO.2                   | LEFT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (MAX LIFE)<br>M13083-5<br>43073    |      |         |                               | MTH                                                    |                | 120            |                | 31-Oct-2029                | 69 m 27 d          |
| 26-20-00-962<br>RIGHT ENGINE<br>NO.1                  | RIGHT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (MAX LIFE)<br>M13083-5<br>43057   |      |         |                               | MTH                                                    |                | 120            |                | 31-Oct-2029                | 69 m 27 d          |
| 26-20-00-962<br>RIGHT ENGINE<br>NO.2                  | RIGHT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE DISCARD (MAX LIFE)<br>M13083-5<br>42957   |      |         |                               | MTH                                                    |                | 120            |                | 31-Oct-2029                | 69 m 27 d          |
| 26-22-00-961<br>CABIN<br>0512007 : CABIN              | CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK<br>SMF                    |      |         | C352<br>X-467662              | MTH 01-Dec-2020                                        |                | 144            |                | 31-Dec-2032                | 107 m 27 d         |
| 26-22-00-961<br>COCKPIT<br>0512007                    | COCKPIT PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK<br>A352TS<br>F-60590241 |      |         |                               | MTH 16-Aug-2019                                        |                | 144            |                | 31-Aug-2031                | 91 m 27 d          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position | Description<br>Drawing # / Task #                                                                  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 28-00-02-220          | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT) |      |         |                               |                          |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| 28-00-02-221          | MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)     |      |         |                               |                          |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | MTH                           |                          |                | A/R            |                |                            |                    |
| 32-10-00-960          | LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD                                                   |      |         |                               |                          |                |                |                |                            |                    |
| LEFT MAIN GEAR        |                                                                                                    |      |         | 6341221-7                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 26788659                      | LDG                      |                | 35812          |                | 36935                      | 34927              |
| 32-10-00-960          | RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY DISCARD                                                  |      |         |                               |                          |                |                |                |                            |                    |
| RIGHT MAIN GEAR       |                                                                                                    |      |         | 6341221-8                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 27218261                      | LDG                      |                | 35812          |                | 36935                      | 34927              |
| 32-10-00-961          | LEFT TRAILING LINK AND AXLE ASSEMBLY DISCARD                                                       |      |         |                               | MTH                      |                |                |                |                            |                    |
| LEFT                  |                                                                                                    |      |         | 6341241-3                     | LDG                      |                | 37312          |                | 38199                      | 36191              |
|                       |                                                                                                    |      |         | 24207772                      |                          |                |                |                |                            |                    |
| 32-10-00-961          | RIGHT TRAILING LINK AND AXLE ASSEMBLY DISCARD                                                      |      |         |                               | MTH                      |                |                |                |                            |                    |
| RIGHT                 |                                                                                                    |      |         | 6341241-4                     | LDG                      |                | 37312          |                | 38199                      | 36191              |
|                       |                                                                                                    |      |         | 24536478                      |                          |                |                |                |                            |                    |
| 32-10-00-962.1        | LEFT MAIN LANDING GEAR OLEO UPPER BEARING ASSEMBLIES DISCARD                                       |      |         |                               |                          |                |                |                |                            |                    |
| LEFT MAIN GEAR        |                                                                                                    |      |         | 6341133-9                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | NSN                           | LDG                      |                | 17653          |                | 17653                      | 15645              |
| 32-10-00-962.1        | RIGHT MAIN LANDING GEAR OLEO UPPER BEARING ASSEMBLIES DISCARD                                      |      |         |                               |                          |                |                |                |                            |                    |
| RIGHT MAIN GEAR       |                                                                                                    |      |         | 6341133-9                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | NSN                           | LDG                      |                | 17653          |                | 17653                      | 15645              |
| 32-10-00-962.2        | LEFT MAIN LANDING GEAR OLEO ASSEMBLY LOWER BARRELS DISCARD                                         |      |         |                               |                          |                |                |                |                            |                    |
| LEFT MAIN GEAR        |                                                                                                    |      |         | 6341135-3                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | NSN                           | LDG                      |                | 14529          |                | 14529                      | 12521              |
| 32-10-00-962.2        | RIGHT MAIN LANDING GEAR OLEO ASSEMBLY LOWER BARRELS DISCARD                                        |      |         |                               |                          |                |                |                |                            |                    |
| RIGHT MAIN GEAR       |                                                                                                    |      |         | 6341135-3                     | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | NSN                           | LDG                      |                | 14529          |                | 14529                      | 12521              |
| 32-10-00-962          | LEFT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD                                                       |      |         |                               | MTH                      |                |                |                |                            |                    |
| LEFT MAIN GEAR        |                                                                                                    |      |         | 6341201-5                     | LDG                      |                | 25141          |                | 25141                      | 23133              |
|                       |                                                                                                    |      |         | 133                           |                          |                |                |                |                            |                    |
| 32-10-00-962          | RIGHT MAIN LANDING GEAR OLEO ASSEMBLY DISCARD                                                      |      |         |                               | MTH                      | 17-Nov-2023    |                |                |                            |                    |
| RIGHT MAIN GEAR       |                                                                                                    | SMF  |         | 6390037-5                     | HRS                      | 2633.1         |                |                |                            |                    |
|                       |                                                                                                    |      |         | 325348876C                    | LDG                      | 2005           | 25141          |                | 27146                      | 25138              |
| 32-20-00-960          | NOSE LANDING GEAR STRUT ASSEMBLY DISCARD                                                           |      |         |                               | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 6342350-8                     | LDG                      |                | 22500          |                | 22500                      | 20492              |
|                       |                                                                                                    |      |         | 258                           |                          |                |                |                |                            |                    |
| 32-20-00-961          | NOSE LANDING GEAR FORK AND PISTON ASSEMBLY DISCARD                                                 |      |         |                               | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 6342200-4                     | LDG                      |                | 12500          |                | 12500                      | 10492              |
|                       |                                                                                                    |      |         | NSN                           |                          |                |                |                |                            |                    |
| 32-31-01-960          | NOSE LANDING GEAR ACTUATOR ASSEMBLY DISCARD                                                        |      |         |                               | MTH                      |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 1541900-7                     | LDG                      |                | 7500           |                | 8362                       | 6354               |
|                       |                                                                                                    |      |         | 1670                          |                          |                |                |                |                            |                    |
| 32-31-02-960          | LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD                                                   |      |         |                               | MTH                      |                |                |                |                            |                    |
| LEFT MAIN GEAR        |                                                                                                    |      |         | 1556700-3                     | LDG                      |                | 37312          |                | 37312                      | 35304              |
|                       |                                                                                                    |      |         | 0780                          |                          |                |                |                |                            |                    |
| 32-31-02-960          | RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD                                                  |      |         |                               | MTH                      |                |                |                |                            |                    |
| RIGHT MAIN GEAR       |                                                                                                    |      |         | 1556700-3                     | LDG                      |                | 37312          |                | 37312                      | 35304              |
|                       |                                                                                                    |      |         | 0778                          |                          |                |                |                |                            |                    |
| 32-31-03-780          | EMERGENCY PNEUMATIC STORAGE BOTTLE (HYDROSTATIC TEST) FUNCTIONAL CHECK                             |      |         |                               | MTH                      | 26-Jul-2023    | 36             |                | 31-Jul-2026                | 30 m 27 d          |
| 0512004 : GEAR        |                                                                                                    |      |         | 40005320-2                    |                          |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 3290                          |                          |                |                |                |                            |                    |
| 32-31-03-960          | EMERGENCY PNEUMATIC STORAGE BOTTLE DISCARD (PART NUMBER 9912368-2/400005320-2)                     |      |         |                               | MTH                      | 26-Jul-2023    | 288            |                | 31-Jul-2047                | 282 m 27 d         |
|                       |                                                                                                    |      |         | 40005320-2                    |                          |                |                |                |                            |                    |
|                       |                                                                                                    |      |         | 3290                          |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code      | Description                                                                                                | Part Number | C/W Time 1   | Adj.           | TBO 1       | TSO 1  | (ENG) DUE 1 | Remains |             |            |
|----------------|------------------------------------------------------------------------------------------------------------|-------------|--------------|----------------|-------------|--------|-------------|---------|-------------|------------|
| Position       | Drawing # / Task #                                                                                         | City        | Mod Lvl      | Part Serial No | C/W Time 2  | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains    |
| 053301         | INSPECTION BOOMBEAM LIGHTING EQUIPMENT AND COMPONENTS                                                      |             |              |                |             |        |             |         |             |            |
|                |                                                                                                            | KCRQ        |              | MTH            | 29-Sep-2023 |        | 12          |         | 30-Sep-2024 | 8 m 26 d   |
|                |                                                                                                            |             |              | HRS            | 2622.7      |        | 600         |         | 3222.7      | 587.8      |
|                |                                                                                                            |             |              | LDG            | 1998        |        |             |         |             |            |
| 33-50-00-960   | LEFT EMERGENCY BATTERY PACK RESTORATION                                                                    |             |              | MTH            | 10-Feb-2023 |        | 48          |         | 28-Feb-2027 | 37 m 24 d  |
| LEFT           |                                                                                                            | KCRQ        |              | HRS            | 2510.8      |        |             |         |             |            |
|                |                                                                                                            |             | CBS28-1      | LDG            | 1931        |        |             |         |             |            |
|                |                                                                                                            |             | 005214       |                |             |        |             |         |             |            |
| 35-00-00-780   | OXYGEN BOTTLE AND REGULATOR ASSEMBLY (HYDROSTATIC TEST) RESTORATION                                        |             |              |                |             |        |             |         |             |            |
|                |                                                                                                            | KCRQ        |              | MTH            | 06-Dec-2022 |        | 60          |         | 31-Dec-2027 | 47 m 27 d  |
|                |                                                                                                            |             | 176276-50    |                |             |        |             |         |             |            |
|                |                                                                                                            |             | ALT279-35746 |                |             |        |             |         |             |            |
| 35-00-00-960   | OXYGEN CYLINDER ASSEMBLY DISCARD                                                                           |             |              | MTH            | 09-Dec-2022 |        | 180         | 4       | 31-Aug-2037 | 163 m 27 d |
|                |                                                                                                            |             | 176276-50    | HRS            | 2482.9      |        |             |         |             |            |
|                |                                                                                                            |             | ALT279-35746 | LDG            | 1911        |        |             |         |             |            |
| 35-10-01-960   | COPILOT CREW OXYGEN MASK RESTORATION                                                                       |             |              | MTH            |             |        | 72          |         | 31-Mar-2028 | 50 m 27 d  |
| COPILOT        |                                                                                                            |             | MC-10-16-101 |                |             |        |             |         |             |            |
|                |                                                                                                            |             | S108157      |                |             |        |             |         |             |            |
| 35-10-01-960   | PILOT CREW OXYGEN MASK RESTORATION                                                                         |             |              | MTH            |             |        | 72          |         | 31-Mar-2028 | 50 m 27 d  |
| PILOT          |                                                                                                            |             | MC10-16-01   |                |             |        |             |         |             |            |
|                |                                                                                                            |             | 122468       |                |             |        |             |         |             |            |
| 36-10-00-960   | LEFT BLEED AIR PRECOOLER DISCARD (CESSNA P/N 9914402-4 OR SUPPLIER P/N 8161-2, NICKEL)                     |             |              |                |             |        |             |         |             |            |
| LEFT           |                                                                                                            |             | 8161-2       | MTH            | 17-Nov-2017 |        | 108         |         | 17-Nov-2026 | 34 m 13 d  |
|                |                                                                                                            |             | S4883T2168   | HRS            | 1387        |        | 3500        |         | 4887        | 2252.1     |
|                |                                                                                                            |             |              | LDG            | 1103        |        |             |         |             |            |
|                |                                                                                                            |             |              | ACH            | 266         |        |             |         |             |            |
| 36-10-00-960   | RIGHT BLEED AIR PRECOOLER DISCARD (CESSNA P/N 9914402-4 OR SUPPLIER P/N 8161-2, NICKEL)                    |             |              |                |             |        |             |         |             |            |
| RIGHT          |                                                                                                            |             | 8161-2       | MTH            | 17-Nov-2017 |        | 108         |         | 17-Nov-2026 | 34 m 13 d  |
|                |                                                                                                            |             | S4883T2019   | HRS            | 1387        |        | 3500        |         | 4887        | 2252.1     |
|                |                                                                                                            |             |              | LDG            | 1103        |        |             |         |             |            |
|                |                                                                                                            |             |              | ACH            | 266         |        |             |         |             |            |
| 51-05-00-0010  | A/C EXT INSPECTION FOR ANTI-ICE FLUIDS RESIDUES AND A/C CLEANING - CHK CLN LUB (ADDED BY MP TEMP. REV. 01) |             |              |                |             |        |             |         |             |            |
|                |                                                                                                            |             |              | MTH            |             |        | 1           |         |             |            |
| 53-00-00-960   | LEFT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD                                                    |             |              |                |             |        |             |         |             |            |
| LEFT           |                                                                                                            |             | 5513056-7    | MTH            | 05-Nov-2008 |        |             |         |             |            |
|                |                                                                                                            |             | 262          | LDG            | 0           |        | 22500       |         | 22500       | 20492      |
| 53-00-00-960   | RIGHT NOSE LANDING GEAR TRUNNION SUPPORT FITTING DISCARD                                                   |             |              |                |             |        |             |         |             |            |
| RIGHT          |                                                                                                            |             | 5513056-8    | MTH            | 05-Nov-2008 |        |             |         |             |            |
|                |                                                                                                            |             | 234          | LDG            | 0           |        | 22500       |         | 22500       | 20492      |
| 53-00-00-961   | NOSE LANDING GEAR ACTUATOR FITTING DISCARD                                                                 |             |              |                |             |        |             |         |             |            |
|                |                                                                                                            |             | 6511105-1    | MTH            | 05-Nov-2008 |        |             |         |             |            |
|                |                                                                                                            |             | 256          | LDG            | 0           |        | 23900       |         | 23900       | 21892      |
| 57-00-00-960   | LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD                                                 |             |              |                |             |        |             |         |             |            |
| LEFT           |                                                                                                            |             | 6321080-1    | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0117         | LDG            |             |        | 31343       |         | 31343       | 29335      |
| 57-00-00-960   | RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING DISCARD                                                |             |              |                |             |        |             |         |             |            |
| RIGHT          |                                                                                                            |             | 6321080-2    | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0162         | LDG            |             |        | 31343       |         | 31343       | 29335      |
| 57-00-00-961.1 | LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD                                                    |             |              |                |             |        |             |         |             |            |
| LEFT           |                                                                                                            |             | 6321060-9    | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0073         | LDG            |             |        | 18340       |         | 18340       | 16332      |
| 57-00-00-961.1 | RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD                                                   |             |              |                |             |        |             |         |             |            |
| RIGHT          |                                                                                                            |             | 6321060-10   | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0085         | LDG            |             |        | 18340       |         | 18340       | 16332      |
| 57-00-00-961   | LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD                                                        |             |              |                |             |        |             |         |             |            |
| LEFT           |                                                                                                            |             | 6321070-9    | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0113         | LDG            |             |        | 18340       |         | 18340       | 16332      |
| 57-00-00-961   | RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD                                                       |             |              |                |             |        |             |         |             |            |
| RIGHT          |                                                                                                            |             | 6321070-10   | MTH            |             |        |             |         |             |            |
|                |                                                                                                            |             | 0083         | LDG            |             |        | 18340       |         | 18340       | 16332      |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Maintenance Inspections

| Item Code<br>Position                             | Description<br>Drawing # / Task #                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2      | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------|------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 571100<br>045710                                  | INSPECT LEFT WING FRONT STRINGER SPLICE, WS 111.00<br>*CF                    |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              | 1              |                | 12000          | 12001                      | 9366.1             |
| 571105<br>045710                                  | INSPECT RIGHT WING FRONT STRINGER SPLICE, WS 111.00<br>*CF                   |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              | 1              |                | 12000          | 12001                      | 9366.1             |
| 71-20-00-960<br>LEFT ENGINE AFT                   | LEFT ENGINE AFT MOUNT ASSEMBLY RESTORATION<br>LM605SA11<br>LK2620            |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 71-20-00-960<br>LEFT ENGINE<br>FORWARD<br>BOTTOM  | LEFT ENGINE FORWARD BOTTOM MOUNT ASSEMBLY RESTORATION<br>LM605SA3<br>LK1790  |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 71-20-00-960<br>LEFT ENGINE<br>FORWARD TOP        | LEFT ENGINE FORWARD TOP MOUNT ASSEMBLY RESTORATION<br>LM605SA3<br>LK1750     |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 71-20-00-960<br>RIGHT ENGINE<br>AFT               | RIGHT ENGINE AFT MOUNT ASSEMBLY RESTORATION<br>LM605SA10<br>LK2648           |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 71-20-00-960<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM | RIGHT ENGINE FORWARD BOTTOM MOUNT ASSEMBLY RESTORATION<br>LM605SA3<br>LK1958 |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 71-20-00-960<br>RIGHT ENGINE<br>FORWARD TOP       | RIGHT ENGINE FORWARD TOP MOUNT ASSEMBLY RESTORATION<br>LM605SA3<br>LK1967    |      |         | MTH<br>HRS                    | 05-Nov-2008<br>0              |                |                | 9000           | 9000                       | 6365.1             |
| 710030<br>E1                                      | POLISH FAN ROTOR                                                             |      |         | MTH                           | 06-Nov-2008                   |                |                | A/R            |                            |                    |
| 710030<br>E2                                      | POLISH FAN ROTOR                                                             |      |         | MTH                           | 05-Nov-2008                   |                |                | A/R            |                            |                    |
| 731025<br>E1                                      | FUEL FILTER REPLACEMENT<br>UNK                                               |      |         | MTH<br>HRS<br>LDG             | 22-Jun-2021<br>2105<br>1699   |                |                | 1200           | (3231.4)3305               | 670.1              |
| 731025<br>E2                                      | FUEL FILTER REPLACEMENT<br>UNK                                               |      |         | MTH<br>HRS<br>LDG             | 17-Jun-2021<br>2105<br>1699   |                |                | 1200           | (3231.4)3305               | 670.1              |
| 80-10-00-960<br>LEFT ENGINE                       | LEFT ENGINE STARTER-GENERATOR RESTORATION<br>SMF<br>9912125-2<br>92324       |      |         | MTH<br>HRS<br>LDG             | 17-Nov-2023<br>2633.1<br>2005 |                |                | 1000           | 3633.1                     | 998.2              |
| 80-10-00-960<br>RIGHT ENGINE                      | RIGHT STARTER-GENERATOR RESTORATION<br>KCRQ<br>300SGL129Q<br>S00017          |      |         | MTH<br>HRS<br>LDG             | 15-Aug-2023<br>2608.4<br>1987 |                |                | 1000           | 3608.4                     | 973.5              |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code         | Description                                          | Part Number           | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-------------------|------------------------------------------------------|-----------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position          | Drawing # / Task #                                   | Part Serial No        | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 211001<br>LEFT    | PRESSURE SHUTOFF VALVE<br>*CF                        | 5253-00-3<br>2398     | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 211001<br>RIGHT   | PRESSURE SHUTOFF VALVE<br>*CF                        | 5253-00-3<br>2400     | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 211002<br>LEFT    | VARIABLE VALVE<br>*CF                                | 2601-21<br>1409       | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 211002<br>RIGHT   | VARIABLE VALVE<br>*CF                                | 2601-21<br>1411       | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 211003            | PRESSURE HEAT EXCHANGER<br>*CF                       | 10840A<br>1136        | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 211005            | EMERGENCY PRESSURE SHUTOFF VALVE<br>9912422-2<br>*CF | 2601-23<br>1056       | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 212001            | BAGGAGE COMPARTMENT BLOWER<br>*CF                    | 0113-12<br>1525       | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 212003            | (STO29) TEMPERATURE SWITCH<br>*CF                    | 1173T42-5<br>0138     | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 212302            | WINDSHIELD AIR BLOWER MOTOR<br>*CF                   | 7003-200<br>1597      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 213001            | PRIMARY OUTFLOW VALVE<br>9912409-20<br>KIWA          | 52771-316<br>1154A    | MTH 01-Dec-2021<br>HRS 2250.3<br>LDG 1781 |        | O/C   | 0<br>0<br>0 |             |         |
| 213002            | SECONDARY OUTFLOW VALVE<br>9912409-15<br>EDDL        | 52772-116<br>1035A    | MTH 11-Nov-2011<br>HRS 646.88<br>LDG 560  |        | O/C   | 0<br>0<br>0 |             |         |
| 213003            | PRESSURE CONTROLLER<br>9912409-13<br>KCRQ            | 52770-116<br>05202    | MTH 04-Apr-2022<br>HRS 2355.7<br>LDG 1836 |        | O/C   | 0<br>0<br>0 |             |         |
| 213005            | DIFFERENTIAL PRESSURE INDICATOR<br>3001J73<br>*CF    | C668511-0106<br>24446 | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 213008            | MANUAL PRESSURE SWITCH<br>9912409-4<br>*CF           | 52773-001<br>2376     | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 215000<br>AFT     | EVAPORATOR BLOWER MOTOR<br>*CF                       | 1133210-7<br>943      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 215000<br>FORWARD | EVAPORATOR BLOWER MOTOR<br>*CF                       | 1260185-1<br>2769     | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 215001            | FORWARD EVAPORATOR<br>9912583-9<br>*CF               | 1134300-3<br>812      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 215002            | AFT EVAPORATOR<br>9912583-10<br>ZRH                  | 1134820-15<br>647     | MTH 28-Aug-2009<br>ACH 26                 |        | O/C   | 0           |             |         |
| 215003            | VAPOR CYCLE COMPRESSOR DRIVE MOTOR                   | 1134146-1<br>587A     | MTH 29-Aug-2018<br>HRS 1472<br>LDG 1168   |        | O/C   | 0<br>0<br>0 |             |         |
| 215004            | COMPRESSOR DRIVE<br>9912583-6<br>KIWA                | 1134610-1<br>114      | MTH 29-Apr-2015<br>HRS 986.4<br>LDG 909   |        | O/C   | 2<br>0<br>0 |             |         |
| 215005A<br>215005 | CONDENSOR ASSEMBLY<br>9912583-7<br>*CF               | 1134620-3<br>770      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 215007            | RECEIVER DRYER ASSEMBLY<br>9912583-3<br>KIWA         | 1134275-1<br>NSN      | MTH 26-Apr-2015<br>HRS 980.6<br>LDG 907   |        | A/R   | 0<br>0      |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code          | Description                              | Part Number                               | C/W Time 1                                           | Adj.   | TBO 1                    | TSO 1            | (ENG) DUE 1 | Remains |
|--------------------|------------------------------------------|-------------------------------------------|------------------------------------------------------|--------|--------------------------|------------------|-------------|---------|
| Position           | Drawing # / Task # City Mod Lvl          | Part Serial No                            | C/W Time 2                                           | + or - | TBO 2                    | TSO 2            | (ENG) DUE 2 | Remains |
| 215008             | COMPRESSOR ASSEMBLY<br>KIWA              | 1134130-5<br>1370                         | MTH 29-Apr-2015<br>HRS 986.4<br>LDG 909              |        | O/C                      | 2<br>0<br>0      |             |         |
| 215009             | VANE AXIAL BLOWER ASSY<br>KCRQ           | 1250435-10<br>1362                        | MTH 18-Nov-2021<br>HRS 2237.5<br>LDG 1776            |        | O/C                      | 0<br>0           |             |         |
| 215010             | AIR CONDITIONING FLIGHT HOURMETER<br>*CF | 1250703-3<br>NSN                          | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 215011             | COMPRESSOR DRIVE BELT<br>KIWA            | 225L100<br>NSN                            | MTH 29-Apr-2015<br>HRS 986.4<br>LDG 909              |        | O/C                      | 0<br>0<br>0      |             |         |
| 215012             | COMPRESSOR DRIVE MOTOR BRUSHES           | 1251171-6<br>NSN                          | MTH 29-Aug-2018<br>HRS 1472<br>LDG 1168<br>ACH 298.6 |        | H/T<br>H/T<br>H/T<br>H/T | 0<br>0<br>0<br>0 |             |         |
| 216001             | RAM AIR MODULATING VALVE<br>*CF          | 27241287-15<br>7BD78                      | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 216002             | TEMPERATURE CONTROLLER<br>*CF            | 1E58-7<br>12BC187                         | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 216003<br>AFT      | (TC007) SENSOR<br>9912085-3              | *CF 27221274<br>7BD500                    | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 216003<br>FORWARD  | (UT006) SENSOR<br>9912085-3              | *CF 27221274<br>7BD516                    | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221002<br>AILERON  | SERVO MOUNT<br>*CF                       | 1 622-5735-021<br>35BD9                   | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221002<br>ELEVATOR | SERVO MOUNT<br>*CF                       | 1 622-5735-022<br>35BNY                   | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221002<br>RUDDER   | SERVO MOUNT<br>*CF                       | 1 622-5735-022<br>35C0H                   | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221003<br>AILERON  | SERVO<br>SVO-3000                        | *CF 3 822-1168-002<br>35BJB               | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221003<br>ELEVATOR | SERVO<br>SVO-3000                        | *CF 3 822-1168-001<br>36WMT               | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221003<br>RUDDER   | SERVO<br>SVO-3000                        | *CF 3 822-1168-001<br>36WMT               | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 221004             | AUTOPILOT PANEL<br>*CF                   | 8 622-6208-223<br>355GJ                   | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |
| 230093             | SINGLE-INDIUM CHANNEL INMARSAT<br>SMF    | 090-11201-002<br>AP24                     | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140            |        | O/C                      | 0<br>0<br>0      |             |         |
| 230094             | AEROWAVE 100 ANTENNA<br>SMF              | AT1675-180W-TNCF-<br>000-00-00-NM<br>5464 | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140            |        | O/C                      | 0<br>0<br>0      |             |         |
| 230095             | HIGH SPEED DATA 100 UNIT<br>SMF          | 90402045<br>249                           | MTH 01-Mar-2019<br>HRS 1591<br>LDG 1280              |        | O/C                      | 1<br>0           |             |         |
| 230096             | ECSM -<br>SMF                            | 1252-A-4120-01<br>817                     | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140            |        | O/C                      | 0<br>0<br>0      |             |         |
| 231006<br>BOTTOM   | VHF COMM 2 CONTROL<br>*CF                | 3 822-1468-102<br>3437R                   | MTH 05-Nov-2008                                      |        | O/C                      |                  |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code        | Description                                   | Part Number                      | C/W Time 1                                | Adj.   | TBO 1                    | TSO 1            | (ENG) DUE 1 | Remains |
|------------------|-----------------------------------------------|----------------------------------|-------------------------------------------|--------|--------------------------|------------------|-------------|---------|
| Position         | Drawing # / Task #                            | Part Serial No                   | C/W Time 2                                | + or - | TBO 2                    | TSO 2            | (ENG) DUE 2 | Remains |
| 231006<br>TOP    | VHF COMM 1 CONTROL<br>*CF                     | 3<br>822-1468-102<br>3438K       | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 231007<br>BOTTOM | COMM 2 ANTENNA<br>*CF                         | VC10-126-1<br>0598               | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 231007<br>TOP    | COMM 1 ANTENNA<br>*CF                         | VFS10-90-2<br>7284               | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 232003           | TELEPHONE TRANSCEIVER<br>ST-3100<br>*CF       | T<br>400-10680-001<br>1068021594 | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 232007           | HANDSET FLITEPHONE<br>*CF                     | B<br>P12199-001<br>1219952121    | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 232019           | AIRCELL CABIN ROUTER<br>SMF                   | P12083-001<br>1208374103         | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140 |        | O/C                      | 0<br>0<br>0      |             |         |
| 235005           | PA AMPLIFIER<br>*CF                           | 102025-1<br>2330308              | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 235006<br>NO. 2  | GPS/XM ANTENNA<br>9154081-79                  | KIWA<br>CI428-410<br>462595      | MTH 20-Mar-2015<br>HRS 921.3<br>LDG 879   |        | O/C                      | 0<br>0<br>0      |             |         |
| 235006           | GPS/XM ANTENNA<br>9154081-78                  | KIWA<br>CI428-410<br>462393      | MTH 20-Mar-2015<br>HRS 921.3<br>LDG 879   |        | O/C                      | 0<br>0<br>0      |             |         |
| 237000           | CVR UNDERWATER LOCATOR BEACON<br>C            | DK120<br>SC81183                 | MTH 12-Sep-2011<br>HRS 629.8<br>LDG 543   |        | O/C                      |                  |             |         |
| 237000A          | CVR LOCATOR BEACON BATTERY<br>KCRQ            | DK120/90<br>AT166526             | MTH 02-Apr-2021<br>HRS 2016<br>LDG 1651   |        | H/T<br>H/T<br>H/T<br>H/T | 0<br>0<br>0<br>0 |             |         |
| 237001           | COCKPIT VOICE RECORDER                        | 08<br>2100-1020-02<br>000528005  | MTH 12-Sep-2011<br>HRS 629.8<br>LDG 543   |        | O/C                      |                  |             |         |
| 237002           | CVR CONTROLLER<br>*CF                         | 04<br>S251-1120-00<br>000564331  | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 237003           | CVR MICROPHONE<br>*CF                         | S055-0067-00<br>000493338        | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 237004           | CVR IMPACT SWITCH<br>*CF                      | 6895D2-X-5-5<br>7873             | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 240001           | INTERGRATED HI PWR/LOW NOISE AMPLIFIER<br>SMF | 1541-A-2000<br>145               | MTH 01-Mar-2019<br>HRS 1591<br>LDG 1280   |        | O/C                      | 3<br>0           |             |         |
| 243003<br>LEFT   | GENERATOR CONTROL UNIT<br>*CF                 | 51525-001F<br>P4069              | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 243003<br>RIGHT  | GENERATOR CONTROL UNIT<br>*CF                 | 51525-001F<br>P4070              | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 243004           | BATTERY TEMP MONITOR-<br>*CF                  | 1529-1-1<br>5210                 | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 243006<br>LEFT   | GENERATOR LOAD AMMETER<br>*CF                 | C662501-0107<br>G0810194         | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 243006<br>RIGHT  | GENERATOR LOAD AMMETER<br>*CF                 | C662501-0107<br>F0810736         | MTH 05-Nov-2008                           |        | O/C                      |                  |             |         |
| 243007           | BATTERY<br>MOT                                | S3597-4<br>40883382              | MTH 31-Oct-2017<br>HRS 1384<br>LDG 1101   |        | O/C                      | 0<br>0<br>0      |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code | Description                    |      |         | Part Number              | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains   |
|-----------|--------------------------------|------|---------|--------------------------|-----------------|--------|-------|-------|-------------|-----------|
| Position  | Drawing # / Task #             | City | Mod Lvl | Part Serial No           | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains   |
| 243008    | BATTERY RELAY                  | *CF  |         | A931F<br>96053           | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| 243011    | DC POWER VOLTMETER             | *CF  |         | C662502-0101<br>E0810133 | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| 245001    | START CONTROL P.C.B.           | *CF  |         | 6318324-6                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| LEFT      |                                |      |         | NSN                      |                 |        |       |       |             |           |
| 245001    | START CONTROL P.C.B.           | *CF  |         | 6318324-6                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| RIGHT     |                                |      |         | NSN                      |                 |        |       |       |             |           |
| 245002    | FUEL CONTROL P.C.B.            | *CF  |         | 6318341-11               | MTH 18-Jun-2010 |        | O/C   |       |             |           |
| LEFT      |                                |      |         | 0747                     |                 |        |       |       |             |           |
| 245002    | FUEL CONTROL P.C.B.            | *CF  |         | 6318341-11               | MTH 18-Jun-2010 |        | O/C   |       |             |           |
| RIGHT     |                                |      |         | 0748                     |                 |        |       |       |             |           |
| 245003    | IGNITOR CONTROL P.C.B.         | *CF  |         | 6318388-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| LEFT      |                                |      |         | 0514                     |                 |        |       |       |             |           |
| 245003    | IGNITOR CONTROL P.C.B.         | *CF  |         | 6318388-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| RIGHT     |                                |      |         | 0529                     |                 |        |       |       |             |           |
| 245004    | ANTI-ICE P.C.B.                | *CF  |         | 6318343-6                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| LEFT      |                                |      |         | 0867                     |                 |        |       |       |             |           |
| 245004    | ANTI-ICE P.C.B.                | *CF  |         | 6318343-6                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
| RIGHT     |                                |      |         | 0868                     |                 |        |       |       |             |           |
| 245006    | ENVIRONMENTAL P.C.B.           | *CF  |         | 6318356-2                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | NSN                      |                 |        |       |       |             |           |
| 245007    | HYDRAULIC P.C.B.               | *CF  |         | 6318344-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0488                     |                 |        |       |       |             |           |
| 245008    | TRIM RELAY P.C.B.              | *CF  |         | 6518351-9                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0502A                    |                 |        |       |       |             |           |
| 245009    | DIMMING P.C.B.                 | *CF  |         | 6518366-2                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0671                     |                 |        |       |       |             |           |
| 245010    | GEAR LOGIC 1 P.C.B.            | *CF  |         | 6318345-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0677                     |                 |        |       |       |             |           |
| 245011    | FUEL FLOW PCB                  | *CF  |         | 85-230-2                 | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           | 9912417-3                      |      |         | 0808-802M2               |                 |        |       |       |             |           |
| 245012    | SPEEDBRAKE P.C.B.              | *CF  |         | 6318347-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0485                     |                 |        |       |       |             |           |
| 245014    | GEAR LOGIC 2 P.C.B.            | *CF  |         | 6318392-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0489                     |                 |        |       |       |             |           |
| 245015    | GEAR MONITOR P.C.B.            | *CF  |         | 6318394-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 0486A                    |                 |        |       |       |             |           |
| 245016    | TAIL DEICE P.C.B               | *CF  |         | 6318395-1                | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 1107                     |                 |        |       |       |             |           |
| 245020    | OVERVOLTAGE DETECTOR           | *CF  |         | 1645-1-3                 | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 4583                     |                 |        |       |       |             |           |
| 256001    | ELT TRANSMITTER                | *CF  |         | 453-5060                 | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           | C406N                          |      |         | 05843                    |                 |        |       |       |             |           |
| 256002    | ELT BEACON BATTERY PACK        |      |         | 452-0133                 | MTH 30-Jun-2023 |        | H/T   | 0     |             |           |
|           |                                |      |         | 399355-027               | HRS 2584.4      |        | H/T   | 0     |             |           |
|           |                                |      |         |                          | LDG 1977        |        | H/T   | 0     |             |           |
|           |                                |      |         |                          |                 |        | H/T   |       |             |           |
| 256003    | REMOTE SWITCH                  | *CF  |         | 452-0010                 | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | NSN                      |                 |        |       |       |             |           |
| 256004    | ELT ANTENNA                    | *CF  |         | 110-340                  | MTH 05-Nov-2008 |        | O/C   |       |             |           |
|           |                                |      |         | 245728                   |                 |        |       |       |             |           |
| 256005    | PROGRAMMING ADAPTER C406-N ELT | SMF  |         | 453-5068                 | MTH 04-Apr-2019 |        | O/C   |       |             |           |
|           |                                |      |         | 4032019                  | HRS 1619.9      |        |       |       |             |           |
|           |                                |      |         |                          | LDG 1310        |        |       |       |             |           |
| 256006    | LIFE VEST                      | KIWA |         | P01074-207               | MTH 16-Nov-2015 |        | 120   | 1     | 01-Oct-2025 | 20 m 27 d |
| CO-PILOT  | XF-35                          |      |         | 1059190031               | HRS 1061        |        |       | 0     |             |           |
|           |                                |      |         |                          | LDG 946         |        |       | 0     |             |           |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position                        | Description<br>Drawing # / Task #                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                           | Adj.<br>+ or - | TBO 1<br>TBO 2           | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------------------|-------------------------------------------------------------|------|---------|-------------------------------|----------------------------------------------------|----------------|--------------------------|----------------|----------------------------|--------------------|
| 256006<br>LAVATORY                           | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520362     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>NO. 1                              | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520363     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>NO. 2                              | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520364     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>NO. 3                              | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520366     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>NO. 4                              | LIFE VEST<br>XF-35                                          | KIWA |         | P01074-207<br>17022310153     | MTH 17-Nov-2017<br>HRS 1387<br>LDG 1103<br>ACH 266 |                | 60                       |                | 04-May-2027                | 40 m 0 d           |
| 256006<br>NO. 5                              | LIFE VEST<br>XF-35                                          | KIWA |         | P01074-207<br>107022310154    | MTH 17-Nov-2017<br>HRS 1387<br>LDG 1103<br>ACH 266 |                | 60                       |                | 04-May-2027                | 40 m 0 d           |
| 256006<br>NO. 6                              | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520369     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>NO. 7                              | LIFE VEST<br>XF-35                                          | KEUG |         | P01074-207<br>18081520367     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226          |                | 120                      | 3              | 31-Aug-2028                | 55 m 27 d          |
| 256006<br>PILOT                              | LIFE VEST<br>XF-35                                          | KIWA |         | P01074-207<br>105091960030    | MTH 16-Nov-2015<br>HRS 1061<br>LDG 946             |                | 120                      | 1<br>0<br>0    | 01-Oct-2025                | 20 m 27 d          |
| 261001<br>LEFT                               | FIRE DETECTOR SENSOR<br>9912416-1                           | *CF  |         | 3001-212-1004/455-9<br>209422 | MTH 05-Nov-2008                                    |                | O/C                      |                |                            |                    |
| 261001<br>RIGHT                              | FIRE DETECTOR SENSOR<br>9912416-1                           | *CF  |         | 3001-212-1004/455-9<br>209402 | MTH 05-Nov-2008                                    |                | O/C                      |                |                            |                    |
| 262001<br>LEFT ENGINE                        | FIRE EXTINGUISHER BOTTLE<br>9912048-6                       | KIWA |         | 30401102-2<br>59362B1         | MTH 17-Nov-2017<br>HRS 1387<br>LDG 1103<br>ACH 266 |                | O/C                      | 0<br>0         |                            |                    |
| 262001<br>RIGHT ENGINE                       | FIRE EXTINGUISHER BOTTLE<br>9912048-6                       | KIWA |         | 30401102-2<br>60193B1         | MTH 17-Nov-2017<br>HRS 1387<br>LDG 1103<br>ACH 266 |                | O/C                      | 0<br>0         |                            |                    |
| 262003<br>CABIN                              | PORTABLE FIRE EXTINGUISHER<br>SMF                           |      |         | C352<br>X-467662              | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596            |                | O/C                      |                |                            |                    |
| 262003<br>COCKPIT                            | PORTABLE FIRE EXTINGUISHER                                  |      |         | A352TS<br>F-60590241          | MTH 21-Aug-2019<br>HRS 1722.4<br>LDG 1403          |                | O/C                      | 0<br>0<br>0    |                            |                    |
| 262010<br>LEFT ENGINE<br>NO.1<br>262002 : L1 | LEFT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE<br>KEUG |      |         | M13083-5<br>42941             | MTH 13-Jan-2020<br>HRS 1843.8<br>LDG 1510          |                | H/T<br>H/T<br>H/T<br>H/T |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code    | Description                                          |      |         | Part Number    | C/W Time 1 | Adj.        | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|--------------|------------------------------------------------------|------|---------|----------------|------------|-------------|-------|-------|-------------|---------|
| Position     | Drawing # / Task #                                   | City | Mod Lvl | Part Serial No | C/W Time 2 | + or -      | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 262011       | LEFT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE  |      |         |                |            |             |       |       |             |         |
| LEFT ENGINE  |                                                      | KEUG |         | M13083-5       | MTH        | 13-Jan-2020 |       | H/T   |             |         |
| NO.2         |                                                      |      |         | 43073          | HRS        | 1843.8      |       | H/T   |             |         |
| 262002 : L2  |                                                      |      |         |                | LDG        | 1510        |       | H/T   |             |         |
|              |                                                      |      |         |                |            |             |       | H/T   |             |         |
| 262012       | RIGHT ENGINE NO.1 FIRE EXTINGUISHER BOTTLE CARTRIDGE |      |         |                |            |             |       |       |             |         |
| RIGHT ENGINE |                                                      | KEUG |         | M13083-5       | MTH        | 13-Jan-2020 |       | H/T   |             |         |
| NO.1         |                                                      |      |         | 43057          | HRS        | 1843.8      |       | H/T   |             |         |
| 262002 : R1  |                                                      |      |         |                | LDG        | 1510        |       | H/T   |             |         |
|              |                                                      |      |         |                |            |             |       | H/T   |             |         |
| 262013       | RIGHT ENGINE NO.2 FIRE EXTINGUISHER BOTTLE CARTRIDGE |      |         |                |            |             |       |       |             |         |
| RIGHT ENGINE |                                                      | KEUG |         | M13083-5       | MTH        | 13-Jan-2020 |       | H/T   |             |         |
| NO.2         |                                                      |      |         | 42957          | HRS        | 1843.8      |       | H/T   |             |         |
| 262002 : R2  |                                                      |      |         |                | LDG        | 1510        |       | H/T   |             |         |
|              |                                                      |      |         |                |            |             |       | H/T   |             |         |
| 272001       | RUDDER BIAS VALVE                                    |      |         | 5307-1         | MTH        | 24-Aug-2012 |       | O/C   | 0           |         |
|              |                                                      | EDDV |         | 1620C          | HRS        | 774         |       |       | 0           |         |
|              |                                                      |      |         |                | LDG        | 701         |       |       |             |         |
| 273001       | SHAKER CONTROL                                       | *CF  |         | 201            | MTH        | 05-Nov-2008 |       | O/C   |             |         |
|              |                                                      |      |         | 8124           |            |             |       |       |             |         |
| 273002       | ELEVATOR TRIM SERVO                                  |      | 1       | 44430-3548     | MTH        | 05-Nov-2008 |       | O/C   |             |         |
|              |                                                      | *CF  |         | T1455          |            |             |       |       |             |         |
| 275001       | SHUTOFF VALVE                                        | *CF  |         | 4083-1         | MTH        | 05-Nov-2008 |       | O/C   |             |         |
|              |                                                      |      |         | 939            |            |             |       |       |             |         |
| 275002       | FLAP ACTUATOR                                        | *CF  |         | 1542000-9      | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      |      |         | 2143           |            |             |       |       |             |         |
| 275002       | FLAP ACTUATOR                                        | *CF  |         | 1542000-9      | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      |      |         | 2196           |            |             |       |       |             |         |
| 276001       | SPEED BRAKE ACTUATOR                                 |      |         | 1542100-5      | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      | *CF  |         | 2113           |            |             |       |       |             |         |
| 276001       | SPEED BRAKE ACTUATOR                                 |      |         | 1542100-5      | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      | *CF  |         | 2126           |            |             |       |       |             |         |
| 281001       | SURGE TANK FLOAT VALVE                               |      |         | 35C10D         | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      | *CF  |         | 4079           |            |             |       |       |             |         |
| 281001       | SURGE TANK FLOAT VALVE                               |      |         | 35C10D         | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      | *CF  |         | 4085           |            |             |       |       |             |         |
| 282001       | FUEL BOOST PUMP                                      | *CF  |         | 1C7-13         | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      |      |         | 7BD87          |            |             |       |       |             |         |
| 282001       | FUEL BOOST PUMP                                      | *CF  |         | 1C7-13         | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      |      |         | 7BD90          |            |             |       |       |             |         |
| 282002       | EJECTOR FUEL AFT PUMP                                |      |         | RG45310        | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      | *CF  |         | C1186          |            |             |       |       |             |         |
| 282002       | EJECTOR FUEL AFT PUMP                                |      |         | RG45310        | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      | *CF  |         | C1197          |            |             |       |       |             |         |
| 282004       | FUEL MOTOR VALVE                                     |      |         | AV24B1507      | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      | *CF  |         | AA161523       |            |             |       |       |             |         |
| 282004       | FUEL MOTOR VALVE                                     |      |         | AV24B1507      | MTH        | 24-Nov-2014 |       | O/C   | 0           |         |
| RIGHT        |                                                      |      |         | AV52023        | HRS        | 921         |       |       | 0           |         |
|              |                                                      |      |         |                | LDG        | 879         |       |       | 0           |         |
| 282005       | EJECTOR FUEL FORWARD PUMP                            |      |         | RG45310        | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      | *CF  |         | C1339          |            |             |       |       |             |         |
| 282005       | EJECTOR FUEL FORWARD PUMP                            |      |         | RG45310        | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| RIGHT        |                                                      | *CF  |         | C1353          |            |             |       |       |             |         |
| 282006       | TRANSFER VALVE                                       | *CF  |         | ZSV57          | MTH        | 05-Nov-2008 |       | O/C   |             |         |
|              |                                                      |      |         | 08071443       |            |             |       |       |             |         |
| 284001       | #5 FUEL PROBE                                        | *CF  |         | 10664T05Y00    | MTH        | 05-Nov-2008 |       | O/C   |             |         |
| LEFT         |                                                      |      |         | MN19039        |            |             |       |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code       | Description                                   | Part Number                    | C/W Time 1                               | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-----------------|-----------------------------------------------|--------------------------------|------------------------------------------|--------|-------|-------------|-------------|---------|
| Position        | Drawing # / Task #                            | Part Serial No                 | C/W Time 2                               | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 284001<br>RIGHT | #5 FUEL PROBE<br>9912589-5                    | *CF<br>10664T05Y00<br>MN19037  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284002<br>LEFT  | #6 FUEL PROBE<br>9912589-6                    | *CF<br>10664T06Y00<br>MN08009  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284002<br>RIGHT | #6 FUEL PROBE<br>9912589-6                    | *CF<br>10664T06Y00<br>MN18725  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284003          | FUEL QUANTITY SIGNAL CONDITIONER<br>9912589-9 | *CF<br>10663B01Y02<br>08070899 | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284004<br>LEFT  | #3 FUEL PROBE<br>9912589-3                    | *CF<br>10664T03Y00<br>MN16591  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284004<br>RIGHT | #3 FUEL PROBE<br>9912589-3                    | *CF<br>10664T03Y00<br>MN16598  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284005<br>LEFT  | #7 FUEL PROBE<br>9912589-4                    | *CF<br>10664T04Y00<br>MN16879  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284005<br>RIGHT | #7 FUEL PROBE<br>9912589-4                    | *CF<br>10664T04Y00<br>MN10915  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284006<br>LEFT  | #2 FUEL PROBE<br>9912589-2                    | *CF<br>10664T02Y00<br>MN19392  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284006<br>RIGHT | #2 FUEL PROBE<br>9912589-2                    | *CF<br>10664T02Y00<br>MN19394  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284007<br>LEFT  | #1 FUEL PROBE<br>9912589-1                    | DUS<br>10664T01Y00<br>MN19127  | MTH 12-Dec-2011<br>HRS 660.97<br>LDG 573 |        | O/C   | 660         |             |         |
| 284007<br>RIGHT | #1 FUEL PROBE<br>9912589-1                    | DUS<br>10664T01Y00<br>MN18782  | MTH 12-Dec-2011<br>HRS 660.97<br>LDG 573 |        | O/C   | 0           |             |         |
| 284008<br>LEFT  | FUEL LOW LEVEL SWITCH<br>EDDL                 | L16H-14<br>1357                | MTH 12-Sep-2011<br>HRS 629.8<br>LDG 543  |        | O/C   | 6<br>0<br>0 |             |         |
| 284008<br>RIGHT | FUEL LOW LEVEL SWITCH<br>*CF                  | L16H-14<br>789                 | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284009<br>LEFT  | #4 FUEL PROBE<br>9912589-4                    | *CF<br>10664T04Y00<br>MN04922  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 284009<br>RIGHT | #4 FUEL PROBE<br>9912589-4                    | *CF<br>10664T04Y00<br>MN16964  | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291002<br>LEFT  | HYDRAULIC PUMP<br>9912062-6                   | *CF<br>24195-LAC<br>2301       | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291002<br>RIGHT | HYDRAULIC PUMP<br>9912062-6                   | *CF<br>24195-LAC<br>2302       | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291005          | HYDRAULIC RESERVOIR ASSEMBLY<br>*CF           | 6317500-16<br>501              | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291006          | LOADING VALVE<br>9912423-39                   | *CF<br>4134-4<br>1382          | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291007          | PRESSURE SWITCH GAUGE<br>9912373-6            | ZRH<br>GPP1250-301<br>0935036  | MTH 22-Feb-2010<br>HRS 238<br>LDG 212    |        | O/C   | 0<br>0<br>0 |             |         |
| 291008          | HYDRAULIC MANIFOLD ASSY<br>9912423-47         | *CF<br>8250-2<br>0534          | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291009          | RELIEF VALVE<br>9912423-46                    | *CF<br>2576-2<br>1109A         | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291010<br>LEFT  | SHUTOFF VALVE<br>9912400-4                    | *CF<br>AV24B1388-2<br>AA163096 | MTH 05-Nov-2008                          |        | O/C   |             |             |         |
| 291010<br>RIGHT | SHUTOFF VALVE<br>9912400-4                    | *CF<br>AV24B1388-2<br>AA165257 | MTH 05-Nov-2008                          |        | O/C   |             |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code | Description                | City | Mod Lvl | Part Number    | C/W Time 1      | Adj.   | TBO 1 | TSO 1  | (ENG) DUE 1 | Remains |
|-----------|----------------------------|------|---------|----------------|-----------------|--------|-------|--------|-------------|---------|
| Position  | Drawing # / Task #         |      |         | Part Serial No | C/W Time 2      | + or - | TBO 2 | TSO 2  | (ENG) DUE 2 | Remains |
| 291011    | FLOW SWITCH VALVE          |      |         | V10F75         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      | 9912194-5                  | *CF  |         | 550            |                 |        |       |        |             |         |
| 291011    | FLOW SWITCH VALVE          |      |         | V10F75         | MTH 23-Jan-2019 |        | O/C   | 0      |             |         |
| RIGHT     | 9912194-5                  | KPDX |         | 2590A          | HRS 1560.3      |        |       | 0      |             |         |
|           |                            |      |         |                | LDG 1258        |        |       | 0      |             |         |
| 291012    | SPEEDBRAKE DUMP VALVE      |      |         | 4082-6         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-33                 | *CF  |         | 976            |                 |        |       |        |             |         |
| 291014    | GEAR VALVE                 | *CF  |         | 4051-4         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-44                 |      |         | 941            |                 |        |       |        |             |         |
| 291016    | SPEEDBRAKE CHECK VALVE     |      |         | 9505-1         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      | 9912423-31                 | *CF  |         | 1889           |                 |        |       |        |             |         |
| 291016    | SPEEDBRAKE CHECK VALVE     |      |         | 9505-1         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| RIGHT     | 9912423-31                 | *CF  |         | 1888           |                 |        |       |        |             |         |
| 291017    | THERMAL RELIEF VALVE       |      |         | 2577-1         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-32                 | *CF  |         | 999            |                 |        |       |        |             |         |
| 291018    | PNEUMATIC DUMP VALVE       |      |         | 9503-2         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-34                 | *CF  |         | 985            |                 |        |       |        |             |         |
| 291020    | SPEED BRAKE VALVE          |      |         | 4052-3         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-30                 | *CF  |         | 1004           |                 |        |       |        |             |         |
| 291021    | FLAP VALVE                 | *CF  |         | 4052-4         | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912423-29                 |      |         | 1012           |                 |        |       |        |             |         |
| 301001    | ISOLATION VALVE            | *CF  |         | 2602-36        | MTH 05-Nov-2008 |        | O/C   |        |             |         |
|           | 9912403-2                  |      |         | 2022           |                 |        |       |        |             |         |
| 301002    | PRESSURE SWITCH            | *CF  |         | 1106P55-1      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      |                            |      |         | 6272A          |                 |        |       |        |             |         |
| 301002    | PRESSURE SWITCH            | *CF  |         | 1106P55-1      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| RIGHT     |                            |      |         | 6274A          |                 |        |       |        |             |         |
| 301003    | PRESS REGULATOR VALVE      |      |         | 1962-00-9      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      | 9912495-5                  | *CF  |         | 4413           |                 |        |       |        |             |         |
| 301003    | PRESS REGULATOR VALVE      |      |         | 1962-00-9      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| RIGHT     | 9912495-5                  | *CF  |         | 4422           |                 |        |       |        |             |         |
| 301004    | TEMPERATURE SWITCH         |      |         | 1173T42-4      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      |                            | *CF  |         | 4053           |                 |        |       |        |             |         |
| 301004    | TEMPERATURE SWITCH         |      |         | 1173T42-4      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| RIGHT     |                            | *CF  |         | 3982           |                 |        |       |        |             |         |
| 301005    | SOLENOID VALVE             | *CF  |         | 3D2353-06      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| LEFT      |                            |      |         | N081467        |                 |        |       |        |             |         |
| 301005    | SOLENOID VALVE             | *CF  |         | 3D2353-06      | MTH 05-Nov-2008 |        | O/C   |        |             |         |
| RIGHT     |                            |      |         | N082968        |                 |        |       |        |             |         |
| 301006    | HORIZONTAL STABILIZER BOOT |      |         | P29S4D5244-15  | MTH 22-Oct-2016 |        | O/C   | 0      |             |         |
| LEFT      | KIWA                       |      |         | NDE6500        | HRS 1249.6      |        |       | 0      |             |         |
|           |                            |      |         |                | LDG 1040        |        |       |        |             |         |
| 301006    | HORIZONTAL STABILIZER BOOT |      |         | P29S4D5244-16  | MTH 04-Nov-2016 |        | O/C   | 0      |             |         |
| RIGHT     | KIWA                       |      |         | NDB1590        | HRS 1261.9      |        |       | 0      |             |         |
|           |                            |      |         |                | LDG 1046        |        |       |        |             |         |
|           |                            |      |         |                | ACH 210.6       |        |       |        |             |         |
| 302001    | PRESS REG VALVE            | KEUG |         | 5285-00-3      | MTH 29-Nov-2018 |        | O/C   | 120.8  |             |         |
| LEFT      |                            |      |         | 1840           | HRS 1531.5      |        |       | 1531.5 |             |         |
|           |                            |      |         |                | LDG 1234        |        |       | 1234   |             |         |
| 302001    | PRESS REG VALVE            | KEUG |         | 5285-00-3      | MTH 29-Nov-2018 |        | O/C   | 120.8  |             |         |
| RIGHT     |                            |      |         | 1827           | HRS 1531.5      |        |       | 1531.5 |             |         |
|           |                            |      |         |                | LDG 1234        |        |       | 1234   |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #     | City | Mod Lvl | Part Number<br>Part Serial No   | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|---------------------------------------|------|---------|---------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 302002<br>LEFT        | INLET TEMP SWITCH                     | KEUG |         | 1173T0759<br>8192               | MTH 29-Nov-2018<br>HRS 1531.5<br>LDG 1234 |                | O/C            | 0<br>0         |                            |                    |
| 302002<br>RIGHT       | INLET TEMP SWITCH                     | *CF  |         | 1173T0759<br>4893               | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 303002<br>LEFT        | TUBE PITOT                            | *CF  |         | PH502<br>SN-UNKNOWN             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 303002<br>RIGHT       | TUBE PITOT                            | *CF  |         | PH502<br>SN-UNKNOWN             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304001                | B/A TEMP MONITOR-                     | *CF  |         | 1169-1<br>4319                  | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304002                | HEAT EXCHANGER                        | *CF  |         | 10653A<br>1939                  | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304003                | PRESSURE REGULATING CHECK VALVE       | *CF  |         | 9912402-14<br>1962-00-3<br>4401 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304004<br>AFT         | FLOORBOARD TF006 SENSOR               | *CF  |         | 27221274<br>6BD386              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304004<br>FORWARD     | T/C TT002 SENSOR                      | *CF  |         | 27221274<br>7BD529              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304005                | TEMP CONTROLLER                       | *CF  |         | 1E58-1<br>6BD126                | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304006                | TEMP CONTROL VALVE                    | *CF  |         | 27241287<br>8BD125T             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304007                | ALCOHOL PUMP ASSY                     | *CF  |         | 476411E<br>NSN                  | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304008<br>LEFT        | W/S BLEED AIR VALVE                   | *CF  |         | 1403-25<br>4905                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304008<br>RIGHT       | W/S BLEED AIR VALVE                   | *CF  |         | 1403-25<br>4901                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304009                | PRESSURE SWITCH                       | *CF  |         | 1115P25<br>4833                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304011<br>LEFT        | SENSOR                                | *CF  |         | 76552-1<br>7384                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304011<br>RIGHT       | SENSOR                                | *CF  |         | 76552-1<br>7395                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304012<br>LEFT        | CURRENT SENSOR J BOX                  | *CF  |         | 76796-2<br>2221                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304012<br>RIGHT       | CURRENT SENSOR J BOX                  | *CF  |         | 76796-2<br>2225                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304013<br>LEFT        | PITOT STATIC CURRENT SENSOR           | *CF  |         | 76250-6<br>7648                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 304013<br>RIGHT       | PITOT STATIC CURRENT SENSOR           | *CF  |         | 76250-6<br>7647                 | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 312001<br>LEFT        | DIGITAL CLOCK                         | *CF  |         | M877A5V<br>19302                | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 313001                | FLIGHT HOUR METER                     | *CF  |         | C664503-0104<br>NSN             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 315001                | CABIN ALT SWITCH                      | *CF  |         | GB300NA161<br>0830333           | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 315003                | ANNUNCIATOR PANEL                     | KCRQ |         | 9912618-3<br>618000619          | MTH 09-Apr-2021<br>HRS 2021.7<br>LDG 1651 |                | O/C            | 0<br>0         |                            |                    |
| 321001<br>LEFT MAIN   | (AND ATTACHING HARDWARE) LANDING GEAR | *CF  |         | 6341200-23<br>66                | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code       | Description                                         | Part Number | C/W Time 1 | Adj.             | TBO 1           | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-----------------|-----------------------------------------------------|-------------|------------|------------------|-----------------|--------|-------------|---------|-------------|---------|
| Position        | Drawing # / Task #                                  | City        | Mod Lvl    | Part Serial No   | C/W Time 2      | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| 321001          | (AND ATTACHING HARDWARE) LANDING GEAR               |             |            |                  | MTH 05-Nov-2008 |        | O/C         |         |             |         |
| RIGHT MAIN      |                                                     | *CF         |            | 6341200-24<br>67 |                 |        |             |         |             |         |
| 321003          | LEFT MAIN LANDING GEAR TRUNNION ASSEMBLY            |             |            |                  | MTH 11-May-2018 |        | H/T         | 0       |             |         |
| LEFT MAIN GEAR  |                                                     | SMF         |            | 6341221-7        | HRS 1432.2      |        | H/T         | 0       |             |         |
| 321003B : L     |                                                     |             |            | 26788659         | LDG 1123        |        | H/T         | 0       |             |         |
|                 |                                                     |             |            |                  |                 |        | H/T         |         |             |         |
| 321003          | RIGHT MAIN LANDING GEAR TRUNNION ASSEMBLY           |             |            |                  | MTH 11-May-2018 |        | H/T         | 0       |             |         |
| RIGHT MAIN GEAR |                                                     | SMF         |            | 6341221-8        | HRS 1432.2      |        | H/T         | 0       |             |         |
| 321004B : R     |                                                     |             |            | 27218261         | LDG 1123        |        | H/T         | 0       |             |         |
|                 |                                                     |             |            |                  |                 |        | H/T         |         |             |         |
| 321004          | NOSE LANDING GEAR FORK AND PISTON ASSEMBLY          |             |            |                  | MTH 05-Nov-2008 |        | H/T         |         |             |         |
|                 |                                                     | *CF         |            | 6342200-4<br>NSN |                 |        | H/T         |         |             |         |
| 321005          | LEFT MAIN LANDING GEAR OLEO ASSEMBLY                |             |            |                  | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| LEFT MAIN GEAR  |                                                     | *CF         |            | 6341201-5        |                 |        | H/T         |         |             |         |
| 321005B : L     |                                                     |             |            | 133              |                 |        |             |         |             |         |
| 321005          | OLEO ASSEMBLY                                       | SMF         |            | 6390037-5        | MTH 17-Nov-2023 |        | H/T         | 0       |             |         |
| RIGHT MAIN GEAR |                                                     |             |            | 325348876C       | HRS 2633.1      |        | H/T         | 0       |             |         |
| 321005B : R     |                                                     |             |            |                  | LDG 2005        |        | H/T         | 0       |             |         |
|                 |                                                     |             |            |                  |                 |        | H/T         |         |             |         |
| 321007          | TRAILING LINK AND AXLE ASSEMBLY                     |             |            | 6341241-3        | MTH 20-Mar-2015 |        | H/T         | 0       |             |         |
| LEFT            |                                                     | KIWA        |            | 24207772         | HRS 937.2       |        | H/T         | 0       |             |         |
| 321007B : L     |                                                     |             |            |                  | LDG 887         |        | H/T         | 0       |             |         |
|                 |                                                     |             |            |                  |                 |        | H/T         |         |             |         |
| 321007          | TRAILING LINK AND AXLE ASSEMBLY                     |             |            | 6341241-4        | MTH 20-Mar-2015 |        | H/T         | 0       |             |         |
| RIGHT           |                                                     | KIWA        |            | 24536478         | HRS 937.2       |        | H/T         | 0       |             |         |
| 321007B : R     |                                                     |             |            |                  | LDG 887         |        | H/T         | 0       |             |         |
|                 |                                                     |             |            |                  |                 |        | H/T         |         |             |         |
| 321011          | LEFT MAIN LANDING GEAR OLEO ASSEMBLY LOWER BARREL   |             |            |                  |                 |        |             |         |             |         |
| LEFT MAIN GEAR  |                                                     | *CF         |            | 6341135-3        | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| 321011B : L     |                                                     |             |            | NSN              |                 |        | H/T         |         |             |         |
| 321011          | RIGHT MAIN LANDING GEAR OLEO ASSEMBLY LOWER BARREL  |             |            |                  |                 |        |             |         |             |         |
| RIGHT MAIN GEAR |                                                     | *CF         |            | 6341135-3        | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| 321011B : R     |                                                     |             |            | NSN              |                 |        | H/T         |         |             |         |
| 321012          | LEFT MAIN LANDING GEAR OLEO UPPER BEARING ASSEMBLY  |             |            |                  |                 |        |             |         |             |         |
| LEFT MAIN GEAR  |                                                     | *CF         |            | 6341133-9        | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| 321012B : L     |                                                     |             |            | NSN              |                 |        | H/T         |         |             |         |
| 321012          | RIGHT MAIN LANDING GEAR OLEO UPPER BEARING ASSEMBLY |             |            |                  |                 |        |             |         |             |         |
| RIGHT MAIN GEAR |                                                     | *CF         |            | 6341133-9        | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| 321012B : R     |                                                     |             |            | NSN              |                 |        | H/T         |         |             |         |
| 322001          | NOSE LANDING GEAR SHIMMY DAMPER                     |             |            |                  | MTH 17-Nov-2023 |        | O/C         | 0       |             |         |
|                 |                                                     | SMF         |            | 6343001-10       | HRS 2633.1      |        |             | 0       |             |         |
|                 |                                                     |             |            | 30030559A        | LDG 2005        |        |             | 0       |             |         |
| 322002          | NOSE LANDING GEAR STRUT ASSEMBLY                    |             |            |                  | MTH 05-Nov-2008 |        | H/T         |         |             |         |
|                 |                                                     | *CF         |            | 6342350-8<br>258 |                 |        | H/T         |         |             |         |
| 322003          | NOSE LANDING GEAR FORK                              |             |            | 5542300-1        | MTH 05-Nov-2008 |        | O/C         |         |             |         |
|                 |                                                     | *CF         |            | NSN              |                 |        |             |         |             |         |
| 322004          | NOSE GEAR PISTON WELD ASSEMBLY                      |             |            | 5542105-3        | MTH 05-Nov-2008 |        | O/C         |         |             |         |
|                 |                                                     | *CF         |            | NSN              |                 |        |             |         |             |         |
| 322005          | NOSE LANDING GEAR ASSEMBLY                          |             |            | 6342350-9        | MTH 05-Nov-2008 |        | O/C         |         |             |         |
|                 |                                                     | *CF         |            | NSN              |                 |        |             |         |             |         |
| 323001          | LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY            |             |            |                  | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| LEFT MAIN GEAR  | 9912573-2                                           | *CF         |            | 1556700-3        |                 |        | H/T         |         |             |         |
| 323001B : L     |                                                     |             |            | 0780             |                 |        |             |         |             |         |
| 323001          | RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY           |             |            |                  | MTH 05-Nov-2008 |        | H/T         |         |             |         |
| RIGHT MAIN GEAR | 9912573-2                                           | *CF         |            | 1556700-3        |                 |        | H/T         |         |             |         |
| 323001B : R     |                                                     |             |            | 0778             |                 |        |             |         |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code         | Description                         | City | Mod Lvl | Part Number    | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-------------------|-------------------------------------|------|---------|----------------|-----------------|--------|-------|-------|-------------|---------|
| Position          | Drawing # / Task #                  |      |         | Part Serial No | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 323002            | UPLOCK                              | *CF  |         | 6327504-6      | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT MAIN GEAR    |                                     |      |         | 2355           |                 |        |       |       |             |         |
| 323002            | UPLOCK                              | *CF  |         | 6327504-6      | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT MAIN GEAR   |                                     |      |         | 2359           |                 |        |       |       |             |         |
| 323004            | NOSE LANDING GEAR ACTUATOR ASSEMBLY |      |         |                | MTH 27-May-2014 |        | H/T   |       |             |         |
|                   | 9912370-5                           | EDDV |         | 1541900-7      | HRS 905         |        | H/T   | 0     |             |         |
|                   |                                     |      |         | 1670           | LDG 862         |        | H/T   |       |             |         |
|                   |                                     |      |         |                |                 |        | H/T   |       |             |         |
| 323005            | NOSE LANDING GEAR UPLOCK ACTUATOR   |      |         |                | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|                   |                                     | *CF  |         | 6327504-7      |                 |        |       |       |             |         |
|                   |                                     |      |         | 1143           |                 |        |       |       |             |         |
| 323006            | HYDRAULIC SHUTTLE VALVE             |      |         | 98312          | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|                   |                                     | *CF  |         | 1361           |                 |        |       |       |             |         |
| 323020            | EMERGENCY PNEUMATIC STORAGE BOTTLE  |      |         |                | MTH 15-Aug-2023 |        | H/T   | 0     |             |         |
|                   | 9912368-2                           |      |         | 40005320-2     | HRS 2608.4      |        | H/T   | 0     |             |         |
|                   |                                     |      |         | 3290           | LDG 1987        |        | H/T   | 0     |             |         |
|                   |                                     |      |         |                |                 |        | H/T   |       |             |         |
| 323021            | EMERGENCY GEAR BOTTLE GAUGE         |      |         | 18225901       | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|                   |                                     | *CF  |         | 040173         |                 |        |       |       |             |         |
| 324001            | WHEEL ASSEMBLY                      | MSC  |         | 3-1601-3       | MTH 22-Sep-2017 |        | O/C   |       |             |         |
| LEFT MAIN GEAR    | 9912743-6                           |      |         | 1093           | HRS 1372.8      |        |       |       |             |         |
|                   |                                     |      |         |                | LDG 1096        |        |       |       |             |         |
| 324001            | WHEEL ASSEMBLY                      | MSC  |         | 3-1601-3       | MTH 22-Sep-2017 |        | O/C   |       |             |         |
| RIGHT MAIN GEAR   | 9912743-6                           |      |         | 1098           | HRS 1372.8      |        |       |       |             |         |
|                   |                                     |      |         |                | LDG 1096        |        |       |       |             |         |
| 324002            | WHEEL ASSEMBLY                      | MSC  |         | 3-1418         | MTH 22-Sep-2017 |        | O/C   |       |             |         |
| NOSE LANDING GEAR |                                     |      |         | 8260           | HRS 1372.8      |        |       |       |             |         |
|                   |                                     |      |         |                | LDG 1096        |        |       |       |             |         |
| 324003            | LEFT MAIN GEAR TIRE                 |      |         | 026-528-0      | MTH 29-Jun-2022 |        | O/C   | 0     |             |         |
| LEFT MAIN GEAR    | 9912576-1                           | KCRQ |         | 2028T0242      | HRS 2375.6      |        |       | 0     |             |         |
|                   |                                     |      |         |                | LDG 1854        |        |       |       |             |         |
| 324003            | RIGHT MAIN GEAR TIRE                |      |         | 026-528-0      | MTH 29-Jun-2022 |        | O/C   | 0     |             |         |
| RIGHT MAIN GEAR   | 9912576-1                           | KCRQ |         | 2028T00411     | HRS 2375.6      |        |       | 0     |             |         |
|                   |                                     |      |         |                | LDG 1854        |        |       |       |             |         |
| 324004            | NOSE LANDING GEAR TIRE              |      |         | 031-613-8      | MTH 22-Dec-2022 |        | O/C   | 0     |             |         |
|                   | 9914070-1                           | KCRQ |         | 2292T00364     | HRS 2492.9      |        |       | 0     |             |         |
|                   |                                     |      |         |                | LDG 1916        |        |       |       |             |         |
| 324005            | BRAKE ASSEMBLY                      | KEUG |         | 2-1651-1       | MTH 23-Jul-2020 |        | O/C   | 0     |             |         |
| LEFT MAIN GEAR    | 9912743-5                           |      |         | 0730           | HRS 1898.4      |        |       | 0     |             |         |
|                   |                                     |      |         |                | LDG 1569        |        |       |       |             |         |
| 324005            | BRAKE ASSEMBLY                      | KEUG |         | 2-1651-1       | MTH 23-Jul-2020 |        | O/C   | 0     |             |         |
| RIGHT MAIN GEAR   | 9912743-5                           |      |         | 0434           | HRS 1898.4      |        |       | 0     |             |         |
|                   |                                     |      |         |                | LDG 1569        |        |       |       |             |         |
| 324007            | SHUTTLE VALVE                       | *CF  |         | 211-121        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT              |                                     |      |         | NSN            |                 |        |       |       |             |         |
| 324007            | SHUTTLE VALVE                       | *CF  |         | 211-121        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT             |                                     |      |         | NSN            |                 |        |       |       |             |         |
| 324102            | ANTISKID TRANSDUCER                 |      |         | 40-955         | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT              | 9912305-2                           | *CF  |         | 8852           |                 |        |       |       |             |         |
| 324102            | ANTISKID TRANSDUCER                 |      |         | 40-955         | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT             | 9912305-2                           | *CF  |         | 8857           |                 |        |       |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code                      | Description                                 | Part Number            | C/W Time 1                                | Adj.   | TBO 1                    | TSO 1  | (ENG) DUE 1 | Remains |
|--------------------------------|---------------------------------------------|------------------------|-------------------------------------------|--------|--------------------------|--------|-------------|---------|
| Position                       | Drawing # / Task # City Mod Lvl             | Part Serial No         | C/W Time 2                                | + or - | TBO 2                    | TSO 2  | (ENG) DUE 2 | Remains |
| 324102                         | ANTI-SKID CONTROL VALVE<br>9912636-3 *CF    | 39-919<br>254          | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324104                         | BRAKE PRESSURE SWITCH<br>*CF                | GPP1250-77<br>0827385  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324105                         | PARKING BRAKE VALVE<br>9912388-1 *CF        | 95853<br>1590A         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324106                         | HYDRAULIC PUMP MOTOR<br>*CF                 | MP50B1<br>4057         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324107                         | BRAKE ANTISKID ACCUMULATOR<br>9912644-2 *CF | 7550-2<br>0511         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324108                         | LOW PRESSURE SWITCH<br>9912373-1 *CF        | GPP1250-29<br>0827134  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324109                         | BRAKE PRESSURE PUMP<br>9912364-2 *CF        | 640929<br>2361A        | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324110                         | EMERGENCY BRAKE VALVE<br>SMF                | 878208-05<br>V610      | MTH 01-Mar-2019<br>HRS 1591<br>LDG 1280   |        | O/C                      | 3<br>0 |             |         |
| 324111                         | FAULT DISPLAY UNIT<br>9912305-9 *CF         | 42-92750<br>2328A      | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324112                         | ANTI-SKID CONTROL BOX<br>9912636-1 *CF      | 142-031-3<br>518A      | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324113                         | RELIEF VALVE *CF                            | 1785-1<br>1080         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 324114                         | METERING BRAKE VALVE<br>9912636-2 *CF       | 32-109<br>256          | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 326001<br>LEFT MAIN GEAR       | UPLOCK SWITCH *CF                           | 65-430087<br>NSN       | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 326001<br>NOSE LANDING<br>GEAR | UPLOCK SWITCH *CF                           | 65-430087<br>NSN       | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 326001<br>RIGHT MAIN GEAR      | UPLOCK SWITCH *CF                           | 65-430087<br>NSN       | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 331001<br>CENTER               | LIGHT DIMMER *CF                            | 273-1<br>32V3N         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 331001<br>LEFT                 | LIGHT DIMMER *CF                            | 273-1<br>32V9F         | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 331002                         | ELECTRICAL PANEL INVERTER<br>*CF            | EM2044-1<br>6066A      | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 331003                         | INDIRECT LIGHTING CNTRL BOX<br>*CF          | CLC500-01<br>500002585 | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334001                         | GROUND RECOGNITION RED LIGHT<br>*CF         | 90033-13<br>18556      | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334003<br>LEFT                 | COLLISION LIGHT POWER SUPPLY<br>*CF         | 04-1502-1408<br>33755  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334003<br>RIGHT                | COLLISION LIGHT POWER SUPPLY<br>*CF         | 04-1502-1408<br>33673  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334004<br>LEFT                 | LANDING LAMP HOUSING<br>*CF                 | 50033025-1<br>2425     | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334004<br>RIGHT                | LANDING LAMP HOUSING<br>*CF                 | 50033025-1<br>2478     | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334005<br>LEFT                 | COLLISION LIGHT ASSEMBLY<br>*CF             | 03-1302-1003<br>35522  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 334005<br>RIGHT                | COLLISION LIGHT ASSEMBLY<br>*CF             | 03-1302-1004<br>34604  | MTH 05-Nov-2008                           |        | O/C                      |        |             |         |
| 335000<br>LEFT                 | LEFT EMERGENCY BATTERY PACK<br>KCRQ         | CBS28-1<br>005214      | MTH 10-Feb-2023<br>HRS 2510.8<br>LDG 1931 |        | H/T<br>H/T<br>H/T<br>H/T | 0<br>0 |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code         | Description                            |      |         | Part Number            | C/W Time 1                                | Adj.   | TBO 1 | TSO 1       | (ENG) DUE 1 | Remains |
|-------------------|----------------------------------------|------|---------|------------------------|-------------------------------------------|--------|-------|-------------|-------------|---------|
| Position          | Drawing # / Task #                     | City | Mod Lvl | Part Serial No         | C/W Time 2                                | + or - | TBO 2 | TSO 2       | (ENG) DUE 2 | Remains |
| 341001<br>LEFT    | AIR DATA COMPUTER                      | *CF  | 6       | 822-1109-014<br>357JF  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341001<br>RIGHT   | AIR DATA COMPUTER                      | *CF  | 6       | 822-1109-014<br>357MW  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341004            | AOA COMPUTER                           | *CF  |         | C-13206-1<br>803       | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341006            | AOA INDICATOR                          | *CF  |         | C12405-1<br>83753      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341007            | AOA SENSOR                             | *CF  |         | C-12717-1<br>2067      | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341008            | BAROMETRIC SWITCH                      | *CF  |         | GBC300-156<br>0832709  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341010<br>AFT     | RADIO ALT ANTENNA                      | *CF  |         | S67-2002<br>54345090   | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341010<br>FORWARD | RADIO ALT ANTENNA                      | *CF  |         | S67-2002<br>54345092   | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341030            | TEMPERATURE PROBE SENSOR               | *CF  |         | 0129G<br>A80119        | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341101            | IAPS CARD CAGE<br>ICC-3001             | *CF  |         | 822-1459-001<br>31TWW  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341103<br>NO. 1   | CONFIGURATION CONTROL STRAPPING UNIT   | *CF  |         | 822-1363-002<br>31TVK  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 341103<br>NO. 2   | CONFIGURATION CONTROL STRAPPING UNIT   | *CF  |         | 822-1363-002<br>31TVL  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342001            | MAGNETIC COMPASS<br>C2400-L4V2W-5B     | SMF  |         | C660501-0301<br>NSN    | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596   |        | O/C   | 0<br>0<br>0 |             |         |
| 342002<br>LEFT    | AHRS COMPUTER<br>AHC-3000              | *CF  | 3       | 822-1110-002<br>34L6H  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342002<br>RIGHT   | AHRS COMPUTER<br>AHC-3000              | *CF  | 3       | 822-1110-002<br>34L6X  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342005<br>LEFT    | FLIGHT GUIDANCE COMPUTER<br>FGC-3000   | *CF  | 1       | 822-1108-222<br>351CL  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342005<br>RIGHT   | FLIGHT GUIDANCE COMPUTER<br>FGC-3000   | *CF  | 1       | 822-1108-222<br>33MBM  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342005            | DATA BASE UNIT<br>DBU-5000             | SMF  |         | 822-2215-602<br>4F1K65 | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140 |        | O/C   | 0<br>0<br>0 |             |         |
| 342006<br>LEFT    | FLUX DETECTION UNIT<br>FDU-3000        | *CF  |         | 822-1193-001<br>41241  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342006<br>RIGHT   | FLUX DETECTION UNIT<br>FDU-3000        | *CF  |         | 822-1193-001<br>41242  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342007<br>LEFT    | EXTERNAL COMPENSATION UNIT<br>ECU-3000 | *CF  |         | 822-1200-998<br>34PHJ  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342007<br>RIGHT   | EXTERNAL COMPENSATION UNIT<br>ECU-3000 | *CF  |         | 822-1200-003<br>34PJK  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342008<br>LEFT    | IAPS POWER SUPPLY<br>PWR-3000          | *CF  | 6       | 822-1137-001<br>31TXD  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342008<br>RIGHT   | IAPS POWER SUPPLY<br>PWR-3000          | *CF  | 7       | 822-1137-001<br>31TXP  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |
| 342009            | ENVIROMENTAL CONTROL<br>IEC-3001       | *CF  | 3       | 822-1167-001<br>31TKP  | MTH 05-Nov-2008                           |        | O/C   |             |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code | Description                     |      |         | Part Number    |     | C/W Time 1  | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-----------|---------------------------------|------|---------|----------------|-----|-------------|--------|-------|-------|-------------|---------|
| Position  | Drawing # / Task #              | City | Mod Lvl | Part Serial No |     | C/W Time 2  | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 342010    | OPERATION CONFIGURATION MODULE  |      |         |                | MTH | 20-Mar-2015 |        | O/C   | 0     |             |         |
| LEFT      | OCM-3100                        | KIWA |         | 822-1484-228   | HRS | 921.3       |        |       | 0     |             |         |
|           |                                 |      |         | 45N3T9         | LDG | 879         |        |       |       |             |         |
| 342010    | OPERATION CONFIGURATION MODULE  |      |         |                | MTH | 20-Mar-2015 |        | O/C   | 0     |             |         |
| RIGHT     | OCM-3100                        | KIWA |         | 822-1484-228   | HRS | 921.3       |        |       | 0     |             |         |
|           |                                 |      |         | 45N3VP         | LDG | 879         |        |       |       |             |         |
| 342011    | CONCENTRATOR MODULE             | 5    |         | 822-1361-412   | MTH | 20-Mar-2015 |        | O/C   |       |             |         |
| LEFT      |                                 | KIWA |         | 3514K          | HRS | 921.3       |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 879         |        |       |       |             |         |
| 342011    | CONCENTRATOR MODULE             | 5    |         | 822-1361-412   | MTH | 20-Mar-2015 |        | O/C   |       |             |         |
| RIGHT     |                                 | KIWA |         | 28JLF          | HRS | 921.3       |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 879         |        |       |       |             |         |
| 342032    | SECONDARY FLIGHT DISPLAY        |      |         | 501-1741-2103  | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
|           | GH-3000                         | *CF  |         | 2157A          |     |             |        |       |       |             |         |
| 342033    | MAINTENANCE DIAGNOSTIC COMPUTER |      |         |                | MTH | 01-Mar-2019 |        | O/C   | 1     |             |         |
|           | MDC-3110                        | SMF  | 7       | 822-1987-005   | HRS | 1591        |        |       | 0     |             |         |
|           |                                 |      |         | 2RXJK          | LDG | 1280        |        |       |       |             |         |
| 342055    | DATA CONCENTRATOR UNIT          |      |         | 822-1483-250   | MTH | 22-Feb-2010 |        | O/C   |       |             |         |
| LEFT      | DCU-3001                        | ZRH  |         | 2TDDV          | HRS | 238         |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 212         |        |       | 410   |             |         |
| 342055    | DATA CONCENTRATOR UNIT          |      |         | 822-1483-250   | MTH | 22-Feb-2010 |        | O/C   |       |             |         |
| RIGHT     | DCU-3001                        | ZRH  |         | 2TG7G          | HRS | 238         |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 212         |        |       | 410   |             |         |
| 342056    | AFD-DISPLAY CONTROL PANEL       |      |         | 822-1828-102   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT      | DCP-3030                        | *CF  |         | 349VH          |     |             |        |       |       |             |         |
| 342056    | AFD-DISPLAY CONTROL PANEL       |      |         | 822-1828-102   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT     | DCP-3030                        | *CF  |         | 349VM          |     |             |        |       |       |             |         |
| 342057    | AFD-CRSR CONTROL PANEL          | 1    |         | 822-1746-102   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
|           | CCP-3000                        | *CF  |         | 34B5W          |     |             |        |       |       |             |         |
| 342065    | AHRS BATTERY PACK               | 08   |         | 501-1712-01    | MTH | 17-Nov-2023 |        | O/C   | 0     |             |         |
|           | PS-855A                         | SMF  |         | 81006          | HRS | 2633.1      |        |       | 0     |             |         |
|           |                                 |      |         |                | LDG | 2005        |        |       | 0     |             |         |
| 342301    | MODE SELECTOR                   | *CF  | 14      | 622-6209-020   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT      | MSP-85                          |      |         | 24KKN          |     |             |        |       |       |             |         |
| 342301    | MODE SELECTOR                   | *CF  | 14      | 622-6209-020   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT     | MSP-85                          |      |         | 2YKJD          |     |             |        |       |       |             |         |
| 342302    | ADAPTIVE FLT DISPLAY            | 27   |         | 822-1753-124   | MTH | 08-Feb-2019 |        | O/C   | 0     |             |         |
| CENTER    |                                 |      |         | 33TCX          | HRS | 1572.1      |        |       | 0     |             |         |
|           |                                 |      |         |                | LDG | 1270        |        |       | 0     |             |         |
| 342302    | ADAPTIVE FLT DISPLAY            | 26   |         | 822-1084-124   | MTH | 20-Mar-2015 |        | O/C   |       |             |         |
| LEFT      |                                 | KIWA |         | 34NHP          | HRS | 921.3       |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 879         |        |       |       |             |         |
| 342302    | MULTI-FUNCTION FLT DISPLAY      |      |         | 822-1084-124   | MTH | 20-Mar-2015 |        | O/C   |       |             |         |
| RIGHT     |                                 | KIWA | 26      | 34NHM          | HRS | 921.3       |        |       |       |             |         |
|           |                                 |      |         |                | LDG | 879         |        |       |       |             |         |
| 342303    | COURSE PANEL                    | *CF  | 01      | 822-1281-002   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
|           | CKP-3000                        |      |         | 34MKB          |     |             |        |       |       |             |         |
| 342305    | COURSE/HEADING PANEL            | 1    |         | 822-1279-002   | MTH | 05-Nov-2008 |        | O/C   |       |             |         |
|           | CHP-3000                        | *CF  |         | 349T           |     |             |        |       |       |             |         |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|----------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 343001                | MARKER BEACON ANTENNA<br>*CF           |      |         | MB10-754<br>0939              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 343002                | DUAL GLIDESCOPE COUPLER<br>*CF         |      |         | 82-70-01<br>1993              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 343003                | GLIDESCOPE ANTENNA<br>*CF              |      |         | RGS10-48<br>13756             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 344001                | EGPWS COMPUTER<br>S2800-871            |      |         | 965-0976-040-222-222<br>23921 | MTH 11-Nov-2011<br>HRS 646.88<br>LDG 560  |                | O/C            |                |                            |                    |
| 344002                | RADAR TRANSCEIVER<br>RTA-800<br>*CF    | 38   |         | 822-1050-004<br>33KNJ         | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 344003                | CONFIGURATION MODULE<br>GH-3000<br>*CF |      |         | 501-1803-185<br>3289          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 344024                | RADIO ALT INDICATOR<br>*CF             | 12   |         | 822-0615-206<br>33NHP         | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345001<br>AFT         | DME 2 ANTENNA<br>85226                 | *CF  |         | DMNI50-2-2<br>121182          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345001<br>FORWARD     | DME 1 ANTENNA<br>*CF                   |      |         | DMNI50-2-2<br>121308          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345002<br>LEFT        | DME 1 TRANSCEIVER<br>DME-4000<br>*CF   | 3    |         | 822-1466-001<br>346GN         | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345002<br>RIGHT       | DME 2 TRANSCEIVER<br>DME-4000          |      |         | 822-1466-001<br>346GY         | MTH 25-Oct-2011                           |                | O/C            |                |                            |                    |
| 345005<br>LEFT        | NAVIGATION ANTENNA                     |      |         | VT11-767-3<br>3113            | MTH 24-Nov-2014<br>HRS 921<br>LDG 879     |                | O/C            | 0<br>0<br>0    |                            |                    |
| 345005<br>RIGHT       | NAVIGATION ANTENNA                     |      |         | VT11-767-3<br>3114            | MTH 24-Nov-2014<br>HRS 921<br>LDG 879     |                | O/C            | 0<br>0<br>0    |                            |                    |
| 345020<br>TOP         | ADF 1 ANTENNA<br>ANT-462A<br>*CF       |      |         | 622-7383-001<br>34T8X         | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345040<br>AFT         | TRANSPONDER 2 ANTENNA<br>85226<br>*CF  |      |         | DMNI50-2-2<br>121179          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345040<br>FORWARD     | TRANSPONDER 1 ANTENNA<br>85226<br>SMF  |      |         | DMNI50-2-2<br>141211          | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | O/C            | 0<br>0         |                            |                    |
| 345040<br>LEFT TOP    | -DIVERSITY TRANSPONDER ANTENNA<br>*CF  |      |         | DMNI50-2-2<br>121208          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345040<br>RIGHT TOP   | -DIVERSITY TRANSPONDER ANTENNA<br>*CF  |      |         | DMNI50-2-2<br>121206          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 345041<br>NO. 1       | TRANSPONDER<br>SMF                     | 29   |         | 622-9210-501<br>4DVHRR        | MTH 26-Jul-2018<br>HRS 1446.5<br>LDG 1140 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 345041<br>NO. 2       | TRANSPONDER<br>UNK                     | 29   |         | 622-9210-501<br>290YK         | MTH 23-Jul-2020<br>HRS 1898.4<br>LDG 1569 |                | O/C            | 2<br>0<br>0    |                            |                    |
| 345046<br>NO. 1       | FMS COMPUTER<br>FMC-3000               | 23   |         | 822-0883-038<br>412DPX        | MTH 05-Feb-2019<br>HRS 1572.1<br>LDG 1270 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 345046<br>NO. 2       | FMS COMPUTER<br>KCRQ                   |      |         | 822-0883-038<br>2NRKM         | MTH 29-Jun-2021<br>HRS 2093<br>LDG 1692   |                | O/C            | 0<br>0<br>0    |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code         | Description                                        | Part Number       | C/W Time 1                | Adj.              | TBO 1                         | TSO 1 | (ENG) DUE 1       | Remains     |
|-------------------|----------------------------------------------------|-------------------|---------------------------|-------------------|-------------------------------|-------|-------------------|-------------|
| Position          | Drawing # / Task #                                 | Part Serial No    | C/W Time 2                | + or -            | TBO 2                         | TSO 2 | (ENG) DUE 2       | Remains     |
| 345047            | FMS CONTROL DISPLAY UNIT<br>CDU-3000               | 07<br>*CF<br>2YVX | 822-0884-364              | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345051            | IRIDIUM/GPS PASSIVE ANTENNA<br>IRIDIUM             | *CF<br>4493156    | S67-1575-165              | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345056<br>NO. 1   | GPS RECEIVER                                       | KIWA              | 822-2189-010<br>3483L     | MTH<br>HRS<br>LDG | 20-Mar-2015<br>921.3<br>879   |       | O/C               |             |
| 345056<br>NO. 2   | GPS RECEIVER                                       | KIWA              | 822-2189-010<br>2X22F     | MTH<br>HRS<br>LDG | 20-Mar-2015<br>921.3<br>879   |       | O/C               |             |
| 345057<br>NO. 1   | VOR/ILS MARKER BEACON<br>NAV-4000                  | *CF<br>35CJL      | 822-1465-001              | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345057<br>NO. 2   | VOR/ILS MARKER BEACON<br>NAV-4500                  | *CF<br>3434T      | 822-1579-001              | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345058<br>NO. 1   | RADIO TUNING UNIT<br>RTU-4220                      | *CF<br>33YYC      | 822-0730-442              | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345058<br>NO. 2   | RADIO TUNING UNIT<br>RTU-4220                      | KFFZ<br>2CPFG     | 822-0730-442              | MTH<br>HRS<br>LDG | 01-Feb-2016<br>1131.3<br>985  |       | O/C<br>0<br>0     |             |
| 345061            | TCAS PROCESSOR                                     | *CF<br>14         | 822-1294-002<br>162895    | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345062<br>BOTTOM  | TCAS ANTENNA                                       | *CF               | 622-8973-001<br>2WM7T     | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345062<br>TOP     | TCAS ANTENNA                                       | *CF               | 622-8973-001<br>2WM7R     | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345068<br>NO. 1   | CONTROL AUDIO PANEL<br>ACP-3110                    | *CF<br>03         | 866-0018-010<br>1470      | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345068<br>NO. 2   | CONTROL AUDIO PANEL<br>ACP-3110                    | *CF<br>03         | 866-0018-010<br>1471      | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 345068            | FILE SERVER UNIT (FSU)<br>FSU-5010                 | BOI               | 822-1543-101<br>2G2MW     | MTH<br>HRS<br>LDG | 01-Aug-2018<br>1449.3<br>1143 |       | O/C               |             |
| 346009<br>STANDBY | ADC COMPUTER                                       | *CF               | 501-1890-04<br>3311       | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 350006            | OXYGEN CYLINDER<br>DOT E-10945 50 CU.FT.<br>BOTTLE | KCRQ              | 176276-50<br>ALT279-35746 | MTH<br>HRS<br>LDG | 09-Dec-2022<br>2482.9<br>1911 |       | H/T<br>H/T<br>H/T | 0<br>0      |
| 350007            | OXYGEN PRESSURE GAUGE<br>MD-97                     | *CF               | C668512-0101<br>G0811283  | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 351001            | OXYGEN 3 POSITION VALVE                            | *CF               | P21007<br>2288            | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 351002<br>COPILOT | OXYGEN MASK                                        | KCRQ              | MC-10-16-101<br>S108157   | MTH<br>HRS<br>LDG | 23-Mar-2022<br>2346.3<br>1832 |       | H/T<br>H/T<br>H/T | 0           |
| 351002<br>PILOT   | OXYGEN MASK                                        | KCRQ              | MC10-16-01<br>122468      | MTH<br>HRS<br>LDG | 02-Mar-2022<br>2321.5<br>1817 |       | H/T<br>H/T<br>H/T | 0<br>0<br>0 |
| 361001<br>LEFT    | PRECOOL TEMPERATURE SENSOR<br>9912584-3            | *CF               | 27431501-10<br>8BD206     | MTH               | 05-Nov-2008                   |       | O/C               |             |
| 361001<br>RIGHT   | PRECOOL TEMPERATURE SENSOR<br>9912584-3            | *CF               | 27431501-10<br>8BD208     | MTH               | 05-Nov-2008                   |       | O/C               |             |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code | Description                                      |      |         | Part Number    | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1 | Remains |
|-----------|--------------------------------------------------|------|---------|----------------|-----------------|--------|-------|-------|-------------|---------|
| Position  | Drawing # / Task #                               | City | Mod Lvl | Part Serial No | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2 | Remains |
| 361002    | B/A PRECOOLER ASSEMBLY                           |      |         | 8161-2         | MTH 17-Nov-2017 |        | H/T   | 0     |             |         |
| LEFT      | 9914402-4                                        | KIWA |         | S4883T2168     | HRS 1387        |        | H/T   | 0     |             |         |
|           |                                                  |      |         |                | LDG 1103        |        | H/T   | 0     |             |         |
|           |                                                  |      |         |                | ACH 266         |        | H/T   |       |             |         |
|           |                                                  |      |         |                |                 |        | H/T   |       |             |         |
| 361002    | B/A PRECOOLER ASSEMBLY                           |      |         | 8161-2         | MTH 17-Nov-2017 |        | H/T   | 0     |             |         |
| RIGHT     | 9914402-4                                        | KIWA |         | S4883T2019     | HRS 1387        |        | H/T   | 0     |             |         |
|           |                                                  |      |         |                | LDG 1103        |        | H/T   |       |             |         |
|           |                                                  |      |         |                | ACH 266         |        | H/T   |       |             |         |
|           |                                                  |      |         |                |                 |        | H/T   |       |             |         |
| 361003    | MODULATING VALVE                                 |      |         | 1H139-1        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT      | 9912584-1                                        | *CF  |         | 6BD102         |                 |        |       |       |             |         |
| 361003    | MODULATING VALVE                                 |      |         | 1H139-2        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT     | 9912584-2                                        | *CF  |         | 7BD129         |                 |        |       |       |             |         |
| 361005    | PRESSURE SWITCH                                  | *CF  |         | P18M30         | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|           |                                                  |      |         | 4847           |                 |        |       |       |             |         |
| 361006    | OVERTEMPERATURE SWITCH                           |      |         | 1173T181-2     | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| LEFT      | 9914149-2                                        | *CF  |         | 6283           |                 |        |       |       |             |         |
| 361006    | OVERTEMPERATURE SWITCH                           |      |         | 1173T181-2     | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT     | 9914149-2                                        | *CF  |         | 6402           |                 |        |       |       |             |         |
| 361007    | B/A PRESSURE REGULATOR                           |      |         | 1H75-18        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|           | 9912510-1                                        | *CF  |         | 7BD176         |                 |        |       |       |             |         |
| 521001    | CABIN DOOR ASSEMBLY                              |      |         | PN             | MTH 05-Nov-2008 |        | O/C   | 0     |             |         |
|           |                                                  |      |         | SN-UNKNOWN     |                 |        |       |       |             |         |
| 522001    | INFLATABLE DOOR SEAL                             |      |         | S15501-4       | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|           | 9912075-4                                        | *CF  |         | NSN            |                 |        |       |       |             |         |
| 522002    | SECONDARY SEAL                                   | ZRH  |         | 5511230-96     | MTH 11-Nov-2011 |        | O/C   |       |             |         |
|           |                                                  |      |         | NSN            | HRS 645         |        |       |       |             |         |
| 530000    | RADOME ASSEMBLY                                  |      |         | 6313101-47     | MTH 05-Nov-2008 |        | O/C   |       |             |         |
|           |                                                  | *CF  |         | NSN            |                 |        |       |       |             |         |
| 531000    | LEFT NOSE LANDING GEAR TRUNNION SUPPORT FITTING  |      |         |                | MTH 05-Nov-2008 |        | H/T   |       |             |         |
| LEFT      |                                                  | *CF  |         | 5513056-7      |                 |        | H/T   |       |             |         |
|           |                                                  |      |         | 262            |                 |        |       |       |             |         |
| 531000    | RIGHT NOSE LANDING GEAR TRUNNION SUPPORT FITTING |      |         |                | MTH 05-Nov-2008 |        | H/T   |       |             |         |
| RIGHT     |                                                  | *CF  |         | 5513056-8      |                 |        | H/T   |       |             |         |
|           |                                                  |      |         | 234            |                 |        | H/T   |       |             |         |
| 531001    | NOSE LANDING GEAR ACTUATOR FITTING               |      |         |                | MTH 05-Nov-2008 |        | H/T   |       |             |         |
|           |                                                  | *CF  |         | 6511105-1      |                 |        | H/T   |       |             |         |
|           |                                                  |      |         | 256            |                 |        |       |       |             |         |
| 561001    | WINDSHIELD ASSY, (LH)                            |      |         | 93200-15       | MTH 20-Mar-2015 |        | O/C   |       |             |         |
| LEFT      | 9912064-15                                       | KIWA |         | 2235           | HRS 937.2       |        |       | 937.2 |             |         |
|           |                                                  |      |         |                | LDG 887         |        |       | 887   |             |         |
| 561001    | WINDSHIELD ASSY, (LH)                            |      |         | 93200-16       | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| RIGHT     | 9912064-16                                       | *CF  |         | 2168           |                 |        |       |       |             |         |
| 561002    | CABIN DOOR WINDOW                                |      |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L1        | 9912207-8                                        | *CF  |         | 3328           |                 |        |       |       |             |         |
| 561002    | CABIN WINDOW                                     | *CF  |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L2        | 9912207-8                                        |      |         | 3487           |                 |        |       |       |             |         |
| 561002    | CABIN WINDOW                                     | *CF  |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L3        | 9912207-8                                        |      |         | 3195           |                 |        |       |       |             |         |
| 561002    | CABIN WINDOW                                     | *CF  |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L4        | 9912207-8                                        |      |         | 3406           |                 |        |       |       |             |         |
| 561002    | CABIN WINDOW                                     | *CF  |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L5        | 9912207-8                                        |      |         | 3154           |                 |        |       |       |             |         |
| 561002    | CABIN DOOR WINDOW                                |      |         | 93105-8        | MTH 05-Nov-2008 |        | O/C   |       |             |         |
| L6        | 9912207-8                                        | *CF  |         | 3129           |                 |        |       |       |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position                                              | Description<br>Drawing # / Task #                          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------|------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 561002<br>R1                                                       | CABIN WINDOW<br>9912207-8                                  | *CF  |         | 93105-8<br>3162               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561002<br>R2                                                       | CABIN WINDOW<br>9912207-8                                  | *CF  |         | 93105-8<br>3295               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561002<br>R3                                                       | CABIN WINDOW<br>9912207-8                                  | *CF  |         | 93105-8<br>1816               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561002<br>R4                                                       | CABIN WINDOW<br>9912207-8                                  | *CF  |         | 93105-8<br>3098               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561002<br>R5                                                       | CABIN WINDOW<br>9912207-8                                  | *CF  |         | 93105-8<br>1800               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561002<br>R6                                                       | CABIN DOOR WINDOW<br>9912207-8                             | *CF  |         | 93105-8<br>1810               | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561003<br>LEFT                                                     | PILOT SIDE WINDOW<br>*CF                                   |      |         | 6311263-1<br>1843             | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 561004<br>RIGHT                                                    | CO-PILOT SIDE WINDOW<br>*CF                                |      |         | 6311263-2<br>1490             | MTH 05-Nov-2008          |                | O/C            |                |                            |                    |
| 571000<br>LEFT<br><i>571000B : L</i>                               | LEFT MAIN LANDING GEAR AFT TRUNNION FITTING<br>*CF         |      |         | 6321070-9<br>0113             | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 571000<br>RIGHT<br><i>571000B : R</i>                              | RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING<br>*CF        |      |         | 6321070-10<br>0083            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 571001<br>LEFT<br><i>571001B : L</i>                               | LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING<br>*CF     |      |         | 6321060-9<br>0073             | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 571001<br>RIGHT<br><i>571001B : R</i>                              | FORWARD TRUNNION ATTACH FITTING<br>*CF                     |      |         | 6321060-10<br>0085            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 571002<br>LEFT<br><i>571002B : L</i>                               | LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING<br>*CF  |      |         | 6321080-1<br>0117             | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 571002<br>RIGHT<br><i>571002B : R</i>                              | RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR FITTING<br>*CF |      |         | 6321080-2<br>0162             | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712001<br>LEFT ENGINE<br>FORWARD<br>BOTTOM<br><i>712001B : LB</i>  | MOUNT ASSEMBLY<br>*CF                                      |      |         | LM605SA3<br>LK1790            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712001<br>LEFT ENGINE<br>FORWARD TOP<br><i>712001B : LT</i>        | MOUNT ASSEMBLY<br>*CF                                      |      |         | LM605SA3<br>LK1750            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712001<br>RIGHT ENGINE<br>FORWARD<br>BOTTOM<br><i>712001B : RB</i> | MOUNT ASSEMBLY<br>*CF                                      |      |         | LM605SA3<br>LK1958            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712001<br>RIGHT ENGINE<br>FORWARD TOP<br><i>712001B : RT</i>       | MOUNT ASSEMBLY<br>*CF                                      |      |         | LM605SA3<br>LK1967            | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712002<br>LEFT ENGINE AFT<br><i>712002A : L</i>                    | MOUNT ASSEMBLY<br>9912623-7<br>*CF                         |      |         | LM605SA11<br>LK2620           | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |
| 712002<br>RIGHT ENGINE<br>AFT<br><i>712002A : R</i>                | MOUNT ASSEMBLY<br>9912623-8<br>*CF                         |      |         | LM605SA10<br>LK2648           | MTH 05-Nov-2008          |                | H/T<br>H/T     |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position                   | Description<br>Drawing # / Task #     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------|---------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 71EN1<br>NO. 1<br><i>710001 : E1**L</i> | ENGINE<br>FJ44-3A-24                  | KCRQ |         | 75000-200<br>216297           | MTH 10-Jul-2021<br>HRS 2105<br>LDG 1699 |                | E/C            | 2031.4         |                            |                    |
| 71EN2<br>NO. 2<br><i>710001 : E2**R</i> | ENGINE<br>FJ44-3A-24                  | KCRQ |         | 75000-200<br>216266           | MTH 10-Jul-2021<br>HRS 2105<br>LDG 1699 |                | E/C            | 2031.4         |                            |                    |
| 720001<br>E1                            | FAN ROTOR<br>*CF                      |      |         | 72036<br>AU21978              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 9              | (9991)10031                | 8023               |
| 720001<br>E2                            | FAN ROTOR<br>*CF                      |      |         | 72036<br>AU21881              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 0              | (10000)10040               | 8032               |
| 720002<br>E1                            | IP COMPRESSOR ROTOR<br>*CF            |      |         | 69026<br>HW27915              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 9              | (9991)10031                | 8023               |
| 720002<br>E2                            | IP COMPRESSOR ROTOR<br>*CF            |      |         | 69026<br>HW28444              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 0              | (10000)10040               | 8032               |
| 720003<br>E1                            | COMPLETE LP SHAFT ASSEMBLY<br>*CF     |      |         | 111423<br>RX07TK0273          | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720003<br>E2                            | COMPLETE LP SHAFT ASSEMBLY<br>*CF     |      |         | 111423<br>RX07TK0231          | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720004<br>E1                            | HIGH PRESSURE SHAFT<br>*CF            |      |         | 64711<br>RX07RT1839           | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720004<br>E2                            | HIGH PRESSURE SHAFT<br>*CF            |      |         | 64711<br>RX07RT1792           | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720005<br>E1                            | HP COMPRESSOR COVER<br>*CF            |      |         | 69885<br>AU21200              | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720005<br>E2                            | HP COMPRESSOR COVER<br>*CF            |      |         | 69885<br>AU21051              | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 720006<br>E1                            | DIFFUSER CASE ASSEMBLY                |      |         | 117777<br>AU20451             | MTH 23-Jan-2013<br>HRS 882.7<br>LDG 782 |                | O/C            | 699.5<br>586   |                            |                    |
| 720006<br>E2                            | DIFFUSER CASE ASSEMBLY                |      |         | 117777<br>AU20495             | MTH 23-Jan-2013<br>HRS 882.7<br>LDG 782 |                | O/C            | 699.5<br>586   |                            |                    |
| 720007<br>E1                            | 1ST STAGE LP TURBINE NOZZLE<br>UNK    |      |         | 126873<br>AU20871             | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 1967.6<br>1574 |                            |                    |
| 720007<br>E2                            | 1ST STAGE LP TURBINE NOZZLE<br>UNK    |      |         | 126873<br>AU20976             | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 3879.3<br>3632 |                            |                    |
| 720008<br>E1                            | ACCESS DRIVE GEARBOX<br>UNK           |      |         | 120746<br>AU20714             | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 2013.4<br>1657 |                            |                    |
| 720008<br>E2                            | ACCESS DRIVE GEARBOX<br>UNK           |      |         | 120746<br>AU20635             | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 2031.4<br>1657 |                            |                    |
| 722010<br>E1                            | IP (STAGE 1 & 2) VANE ASSEMBLY<br>UNK |      |         | 115569<br>AU20578             | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 1967.6<br>1557 |                            |                    |
| 722010<br>E2                            | IP (STAGE 1 & 2) VANE ASSEMBLY<br>UNK |      |         | 115569<br>AU20694             | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 2029.4<br>1574 |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position | Description<br>Drawing # / Task #        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------|------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 723037<br>E1          | FAN STATOR VANE ASSEMBLY                 | UNK  |         | 70563<br>MX20242              | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 5063.4<br>3187 |                            |                    |
| 725101<br>E1          | HP COMPRESSOR ROTOR                      | *CF  |         | 66055<br>HW29959              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 9              | (9991)10031                | 8023               |
| 725101<br>E2          | HP COMPRESSOR ROTOR                      | *CF  |         | 66055<br>HW28689              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 0              | (10000)10040               | 8032               |
| 725102<br>E1          | HP TURBINE ROTOR                         | UNK  |         | 223803<br>HW29517             | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 2031.4<br>1657 |                            |                    |
| 725102<br>E2          | HP TURBINE ROTOR                         | UNK  |         | 223803<br>HW28836             | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 2031.4<br>1657 |                            |                    |
| 725103<br>E1          | HP TURBINE DISK                          | UNK  |         | 223804<br>HW29517             | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | 8000           | 2031.4<br>1657 | (8000)8042                 | 6034               |
| 725103<br>E2          | HP TURBINE DISK                          | UNK  |         | 223804<br>HW28836             | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | 8000           | 2031.4<br>1657 | (8000)8042                 | 6034               |
| 725501<br>E1          | 1ST LP TURBINE DISK                      | *CF  |         | 72037<br>HW28981              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 9              | (9991)10031                | 8023               |
| 725501<br>E2          | 1ST LP TURBINE DISK                      | *CF  |         | 72037<br>HW28615              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 0              | (10000)10040               | 8032               |
| 725502<br>E1          | 2ND LP TURBINE DISK                      | *CF  |         | 66993<br>HW29075              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 9              | (9991)10031                | 8023               |
| 725502<br>E2          | 2ND LP TURBINE DISK                      | *CF  |         | 66993<br>HW28253              | MTH 05-Nov-2008<br>LDG 40               |                | 10000          | 0              | (10000)10040               | 8032               |
| 726011<br>E1          | ACCESSORY DRIVE GEARBOX HOUSING ASSEMBLY |      |         | PN<br>SN-UNKNOWN              |                                         |                | O/C            |                |                            |                    |
| 726011<br>E2          | ACCESSORY DRIVE GEARBOX HOUSING ASSEMBLY |      |         | PN<br>SN-UNKNOWN              | MTH 05-Nov-2008                         |                | O/C            | 0              |                            |                    |
| 729953<br>E1          | BEARING AND PINION ASSEMBLY              | UNK  |         | 125105<br>21135               | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 729953<br>E2          | BEARING AND PINION ASSEMBLY              | UNK  |         | 125105<br>21152               | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | O/C            | 0<br>0<br>0    |                            |                    |
| 729966<br>E2          | OIL PRESSURE REGULATING VALVE            |      |         | 77795<br>1116                 | MTH 11-Feb-2009                         |                | O/C            | 0              |                            |                    |
| 730001<br>LEFT        | FUEL PRESSURE SWITCH                     | *CF  |         | 1103P0448<br>8601             | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 730001<br>RIGHT       | FUEL PRESSURE SWITCH                     | *CF  |         | 1103P0448<br>8586             | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |
| 732500<br>LEFT        | FADEC                                    |      |         | 115182<br>CL6APW0596          | MTH 22-Feb-2010<br>HRS 238<br>LDG 212   |                | O/C            | 552.7<br>467   |                            |                    |
| 732500<br>RIGHT       | FADEC                                    | EDDV |         | 117780<br>CL8APW1458          | MTH 24-Aug-2012<br>HRS 774<br>LDG 701   |                | O/C            |                |                            |                    |
| 732501<br>LEFT        | FADEC INTERFACE PCB                      | *CF  |         | 6318387-11<br>0216            | MTH 05-Nov-2008                         |                | O/C            |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code             | Description                                | Part Number           | C/W Time 1                                         | Adj.   | TBO 1 | TSO 1          | (ENG) DUE 1    | Remains |
|-----------------------|--------------------------------------------|-----------------------|----------------------------------------------------|--------|-------|----------------|----------------|---------|
| Position              | Drawing # / Task #                         | Part Serial No        | C/W Time 2                                         | + or - | TBO 2 | TSO 2          | (ENG) DUE 2    | Remains |
| 732501<br>RIGHT       | FADEC INTERFACE PCB<br>*CF                 | 6318387-11<br>0218    | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 733001<br>LEFT        | FUEL FLOW TRANSMITTER<br>9912417-1<br>*CF  | 1573-4<br>0827045     | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 733001<br>RIGHT       | FUEL FLOW TRANSMITTER<br>9912417-1<br>KIWA | 1573-4<br>0850-008    | MTH 17-Nov-2017<br>HRS 1387<br>LDG 1103<br>ACH 266 |        | O/C   | 6<br>0         |                |         |
| 730002<br>E1          | FUEL NOZZLE ASSY<br>KCRQ                   | 50817<br>BCC-1ALL1955 | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886          |        | O/C   |                |                |         |
| 730002<br>E2          | FUEL NOZZLE ASSY<br>KCRQ                   | 50817<br>BCC-00002997 | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886          |        | O/C   |                |                |         |
| 730003<br>E1          | SEAL AND FUEL SLINGER ASSEMBLY<br>UNK      | 55608<br>AU03017      | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699            |        | O/C   | 2317.5<br>1928 |                |         |
| 730003<br>E2          | SEAL AND FUEL SLINGER ASSEMBLY<br>*CF      | 55608<br>AU21196      | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 732101<br>E1          | FUEL DELIVERY UNIT<br>KIWA                 | 119148<br>CL8ATW0201  | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147          |        | 8000  | 1170<br>1002   | (8228.5)8302.2 | 5667.3  |
| 732101<br>E2          | FUEL DELIVERY UNIT<br>KIWA                 | 119148<br>CL9ATW0338  | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147          |        | 8000  | 1723.9<br>1277 | (7674.6)7748.3 | 5113.4  |
| 732301<br>E1          | ELEC FUEL FILTER INDICATOR<br>UNK          | 57847<br>GE-7813      | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699            |        | O/C   | 0<br>0<br>0    |                |         |
| 732301<br>E2          | ELEC FUEL FILTER INDICATOR<br>*CF          | 57847<br>GE3654       | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741001<br>E1 INBOARD  | IGNITION EXCITER<br>*CF                    | 68145<br>CK0800662    | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741001<br>E1 OUTBOARD | IGNITION EXCITER<br>*CF                    | 68145<br>CK0800665    | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741001<br>E2 INBOARD  | IGNITION EXCITER<br>*CF                    | 68145<br>CK0800691    | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741001<br>E2 OUTBOARD | IGNITION EXCITER<br>*CF                    | 68145<br>CK0800698    | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741002<br>E1          | SHORT IGNITOR LEAD<br>*CF                  | 53279<br>NSN          | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741002<br>E2          | SHORT IGNITOR LEAD<br>*CF                  | 53279<br>NSN          | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741003<br>E1          | LONG IGNITOR LEAD<br>*CF                   | 53221<br>NSN          | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741003<br>E2          | LONG IGNITOR LEAD<br>*CF                   | 53221<br>NSN          | MTH 05-Nov-2008                                    |        | O/C   |                |                |         |
| 741004<br>E1 INBOARD  | IGNITOR<br>KCRQ                            | 68032<br>CK-1600336   | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886          |        | O/C   |                |                |         |
| 741004<br>E1 OUTBOARD | IGNITOR<br>KCRQ                            | 68032<br>CK-1800405   | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886          |        | O/C   |                |                |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code<br>Position                         | Description<br>Drawing # / Task #    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------|--------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 741004<br>E2 INBOARD                          | IGNITOR                              | KCRQ |         | 68032<br>CK-2001499           | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886 |                | O/C            |                |                            |                    |
| 741004<br>E2 OUTBOARD                         | IGNITOR                              | KCRQ |         | 68032<br>CK-1800621           | MTH 29-Sep-2022<br>HRS 2447.5<br>LDG 1886 |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 1                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020399            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 2                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020400            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 3                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020401            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 4                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020402            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 5                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020403            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772001<br>LEFT NO. 6                          | ITT PROBE                            | *CF  |         | 62141<br>YYF020404            | MTH 06-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 1<br><i>772001 : E2-1</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020081            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 2<br><i>772001 : E2-2</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020082            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 3<br><i>772001 : E2-3</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020083            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 4<br><i>772001 : E2-4</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020084            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 5<br><i>772001 : E2-5</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020085            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>RIGHT NO. 6<br><i>772001 : E2-6</i> | ITT PROBE                            | *CF  |         | 62141<br>YYF020086            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 774001                                        | N1 STANDBY INDICATOR<br>*CF          |      |         | 10645N02R03<br>1016A          | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771001<br>E1                                  | N1 DUAL MAGNETIC SPEED SENSOR<br>*CF |      |         | 57355<br>MD0118775            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771001<br>E2                                  | N1 DUAL MAGNETIC SPEED SENSOR<br>*CF |      |         | 57355<br>MD0115373            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771002<br>E1                                  | N2 DUAL MAGNETIC SPEED SENSOR<br>*CF |      |         | 54831<br>MD0119193            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771002<br>E2                                  | N2 DUAL MAGNETIC SPEED SENSOR<br>*CF |      |         | 54831<br>MD116357             | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771003<br>E1                                  | TT2 SENSOR                           | *CF  |         | 79646<br>GST4059              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 771003<br>E2                                  | TT2 SENSOR                           | *CF  |         | 79646<br>GST3667              | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |
| 772002<br>E1                                  | ITT HARNESS --                       | UNK  |         | 75378<br>EMX004818            | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | O/C            | 0<br>0<br>0    |                            |                    |
| 772002<br>E2                                  | ITT HARNESS --                       | *CF  |         | 75378<br>YYF001350            | MTH 05-Nov-2008                           |                | O/C            |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Components

| Item Code    | Description              | Part Number    | C/W Time 1      | Adj.   | TBO 1 | TSO 1 | (ENG) DUE 1  | Remains |
|--------------|--------------------------|----------------|-----------------|--------|-------|-------|--------------|---------|
| Position     | Drawing # / Task #       | Part Serial No | C/W Time 2      | + or - | TBO 2 | TSO 2 | (ENG) DUE 2  | Remains |
| 793002       | OIL PRESSURE SWITCH      | S1103P89-3     | MTH 21-Oct-2021 |        | O/C   |       |              |         |
| LEFT ENGINE  | 9912178-4 CRQ            | 2923           | HRS 2211.1      |        |       |       |              |         |
|              |                          |                | LDG 1755        |        |       |       |              |         |
| 793002       | OIL PRESSURE SWITCH      | S1103P89-3     | MTH 21-Oct-2021 |        | O/C   |       |              |         |
| RIGHT ENGINE | 9912178-4 CRQ            | 2936           | HRS 2211.1      |        |       |       |              |         |
|              |                          |                | LDG 1755        |        |       |       |              |         |
| 793003       | OIL PRESSURE TRANSMITTER | APTE-304A-200G | MTH 15-May-2023 |        | O/C   | 0     |              |         |
| LEFT ENGINE  | KCRQ                     | 8828-6-358     | HRS 2568.7      |        |       | 0     |              |         |
|              |                          |                | LDG 1966        |        |       | 0     |              |         |
| 793003       | OIL PRESSURE TRANSMITTER | APTE-304A-200G | MTH 21-Oct-2021 |        | O/C   |       |              |         |
| RIGHT ENGINE | CRQ                      | 8780-5-277     | HRS 2211.1      |        |       |       |              |         |
|              |                          |                | LDG 1755        |        |       |       |              |         |
| 792201       | LUBE OIL COOLER          | 110718         | MTH 05-Nov-2008 |        | O/C   |       |              |         |
| E1           |                          | PP0217         |                 |        |       |       |              |         |
| 792201       | LUBE OIL COOLER          | 110718         | MTH 05-Nov-2008 |        | O/C   |       |              |         |
| E2           |                          | PP0096         |                 |        |       |       |              |         |
| 792401       | LUBE AND SCAVENGE PUMP   | 110590         | MTH 05-Nov-2008 |        |       |       |              |         |
| E1           | *CF                      | MX20284        | HRS 73.7        |        | 5000  | 12    | (4988)5061.7 | 2426.8  |
| 792401       | LUBE AND SCAVENGE PUMP   | 114520         | MTH 28-Aug-2009 |        |       |       |              |         |
| E2           | ZRH                      | MX20285        | HRS 217.7       |        | 5000  | 0     | (5144)5217.7 | 2582.8  |
| 801101       | STARTER GENERATOR        | 9912125-2      | MTH 17-Nov-2023 |        | H/T   | 0     |              |         |
| LEFT ENGINE  | 300SGL129Q SMF           | 92324          | HRS 2633.1      |        | H/T   | 0     |              |         |
|              |                          |                | LDG 2005        |        | H/T   | 0     |              |         |
|              |                          |                |                 |        | H/T   |       |              |         |
| 801101       | STARTER GENERATOR        | 300SGL129Q     | MTH 15-Aug-2023 |        | H/T   |       |              |         |
| RIGHT ENGINE | 9912125-2 KCRQ           | S00017         | HRS 2608.4      |        | H/T   |       |              |         |
|              |                          |                | LDG 1987        |        | H/T   |       |              |         |
|              |                          |                |                 |        | H/T   |       |              |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                                                                                                                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL CIL-99-03 R01            | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                                                                                        |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-03                | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                                                                                        |      |         | RECOMMENDED MTH               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-01 R04           | CESCOM PRICES (THIS SL CANCELS SL525A-99-01 R3 AND PREVIOUS)                                                                                                                                                           |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-02 R01           | TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE                                                                                                                                |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-02               | TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PERSONAL ELECTRONIC DEVICE USAGE                                                                                                                                |      |         | INFORMATIONAL                 |                          |                | A/R            |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-03               | MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS                                                                                                                                                   |      |         | INFORMATIONAL                 |                          |                | A/R            |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-04               | MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION                                                                                                                                                            |      |         | INFORMATIONAL                 |                          |                | A/R            |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-03-01                | CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)                                                                                                                                                       |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL CIL-99-04                | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW                                                                                                                                                                |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-03-01 R01           | SUPPLEMENTAL TYPE CERTIFICATION (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)                                                                                                                           |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-99-06               | MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-05-02               | PRECOOLER LIFE LIMIT                                                                                                                                                                                                   |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-05-03 R01           | TIME LIMITS/MAINTENANCE CHECKS - NEW CABIN DOOR ASSEMBLY HINGE PIN REPLACEMENT INTERVAL IMPLEMENTATION GRACE PERIOD CANCELLED                                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SL 525A-05-03               | TIME LIMITS/MAINTENANCE CHECKS - NEW CABIN DOOR ASSEMBLY HINGE PIN REPLACEMENTINTERVAL IMPLEMENTATION GRACE PERIOD                                                                                                     |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R01<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)                                                                                                                                                     |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R01<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)                                                                                                                                                     |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                                                                                                                           |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                                             | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|---------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-05-002<br>R04<br>E1    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R04<br>E2    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R05-CN<br>E1 | SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000) |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R05-CN<br>E2 | SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000) |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R05<br>E1    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>R05<br>E2    | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>E1           | UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-05-002<br>E2           | UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R04<br>E1   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R04<br>E2   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R05<br>E1   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R05<br>E2   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R06<br>E1   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1000<br>R06<br>E2   | UNSERVICEABLE PARTS - NOTIFICATION                                                                            |      |         | INFORMATIONAL                 |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>R01<br>E1   | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                        |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                  |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position        | Description<br>Drawing # / Task #                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------|------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PSID WI-05-1003<br>R01<br>E2 | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>E1        | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-05-1003<br>E2        | TIME LIMITS/MAINTENANCE CHECKS - FORMS                                                                           |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007-CN<br>E1       | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL   |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007-CN<br>E2       | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL   |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1007<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1020<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1020<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL              |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1022<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL                       |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1022<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL                       |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045-CN<br>E1       | CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045-CN<br>E2       | CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045<br>E1          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL          |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-05-1045<br>E2          | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO THE LINE MAINTENANCE MANUAL          |      |         |                               |                          |                | -              |                |                            |                    |
|                              | <b>MOC :</b>                                                                                                     |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code              | Description                                                                                                                                           | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position               | Drawing # / Task #                                                                                                                                    | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SL WI-05-1095-CN<br>E1 | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED                              |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1095-CN<br>E2 | CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL<br>CANCELLED                              |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1095<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                                      |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1095<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL                                                      |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1149<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL                                                   |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1149<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL                                                   |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1155<br>E1    | TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION                                                                          |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL WI-05-1155<br>E2    | TIME LIMITS/MAINTENANCE CHECKS - TIME EXTENSION OF MAJOR PERIODIC INSPECTION                                                                          |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-99-01 R01       | USE OF CORROSION INHIBITING COMPOUNDS<br>INFORMATIONAL                                                                                                |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-99-01 R02       | USE OF CORROSION INHIBITING COMPOUNDS<br>INFORMATIONAL                                                                                                |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-99-01           | USE OF CORROSION INHIBITING COMPOUNDS<br>INFORMATIONAL                                                                                                |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-99-02           | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS<br>MTH |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-20-01 R02       | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL<br>INFORMATIONAL                                             |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-20-01 R03-CN    | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL<br>CANCELLED                                                 |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL CIL-20-01           | STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL<br>INFORMATIONAL                                             |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL 525A-20-01 R09      | CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL<br>INFORMATIONAL                                                                  |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |
| SL 525A-20-03          | STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL<br>INFORMATIONAL                                                                                |             |            |                |            |        |             |         |             |         |
| MOC :                  |                                                                                                                                                       |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                 | Description<br>Drawing # / Task #                                                                      | City | Mod Lvl   | Part Number<br>Part Serial No            | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|------|-----------|------------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB 525A-21-06                                                                                                                         | AIR CONDITIONING - AFT EVAPORATOR DRAIN HOSE IMPROVEMENT<br>DISCRETIONARY                              |      |           |                                          |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL 525A-21-03                                                                                                                         | AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT<br>OPTIONAL                       |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL 525A-23-02                                                                                                                         | COMMUNICATIONS - SITA DATALINK FREQUENCY CHANGE FOR NORTH AMERICA<br>INFORMATIONAL                     |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB 525A-24-06                                                                                                                         | GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING<br>MANDATORY                                                |      |           | MTH 10-Feb-2014<br>LDG 839               |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                            |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| COM MC 525A-007                                                                                                                       | GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES                                                      |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL 525A-24-03                                                                                                                         | ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION<br>OPTIONAL          |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB 525A-25-04 R01                                                                                                                     | THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION<br>OPTIONAL |      |           |                                          |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB 525A-25-05 R01                                                                                                                     | GLARESHIELD LEATHER STRIP INSTALLATION                                                                 |      |           | MTH                                      |                          |                | -              |                |                            |                    |
| 25SB-05 : 525A1                                                                                                                       | *CF                                                                                                    |      | OPTIONAL  |                                          |                          |                |                |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB CIB-25-01                                                                                                                          | EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION<br>OPTIONAL                      |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL 525A-25-04                                                                                                                         | EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION<br>OPTIONAL                                      |      |           |                                          |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                          |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL CIL-26-01 R01                                                                                                                      | FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING<br>KEUG                      |      | MANDATORY | MTH 03-May-2019<br>HRS 1648<br>LDG 1336  |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH IAW INSTRUCTIONS WITHIN. NO DEFECTS NOTED                                                  |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SL CIL-26-01                                                                                                                          | FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING<br>SMF                       |      | MANDATORY | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596  |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - INTENT OF SL CIL-26-01 WAS PREVIOUSLY COMPLIED WITH ON 5/3/19 DURING ACCOMPLISHMENT OF SL CIL-26-01 R01. |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB 525A-27-13 R01                                                                                                                     | VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION<br>MANDATORY                                           |      |           | MTH 15-Nov-2013<br>HRS 881<br>LDG 833    |                          |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH ORIGINAL ISSUE 11.NOV.12011                                                                |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |
| SB 525A-27-13                                                                                                                         | FLIGHT CONTROLS - VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION<br>EDDL                              |      | MANDATORY | MTH 11-Nov-2011<br>HRS 646.88<br>LDG 560 |                          |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                            |                                                                                                        |      |           |                                          |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                         | Description<br>Drawing # / Task #                                                                             | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 525A-27-06                                                                                                 | AILERON CABLE GUARD REPLACEMENT                                                                               | EDDL |         | MANDATORY                     | MTH 03-Jul-2014<br>HRS 908<br>LDG 865     |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PERFORMED                                                                        |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-27-07                                                                                                 | FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT                                                      |      |         | OPTIONAL                      |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB CIB-28-01                                                                                                  | FIREWALL SHUTOFF VALVE GROUND IMPROVEMENT                                                                     |      |         | RECOMMENDED                   | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-28-01                                                                                                  | FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS                                  |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-29-06 R01                                                                                             | HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT                                                  |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 881<br>LDG 833     |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLETE COMPLIED WITH ORIGINAL ISSUE                                            |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-29-06                                                                                                 | HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT                                                                    |      |         | MANDATORY                     | MTH                                       |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - AT MANUFACTURE INCORPORATED IN PRODUCTION ON AIRPLANES -0424 AND ON.             |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-29-07                                                                                                 | HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION                                                  |      |         | OPTIONAL                      |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-29-03                                                                                                 | HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION                                                   | KEUG |         | RECOMMENDED                   | MTH 07-Jun-2019<br>HRS 1661.1<br>LDG 1352 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH IAW INSTRUCTIONS WITHIN. FOUND EFFECTED PART NUMBER NOT INSTALLED |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-30-01 R01                                                                                              | ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES                                                    |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-30-01                                                                                                  | ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES                                                    |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-31-01                                                                                                  | INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-31-05                                                                                                 | TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETINNO. CESSNA SB 001                                             |      |         | MANDATORY                     | MTH 12-Sep-2011<br>HRS 629.8<br>LDG 543   |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY EFFECTIVITY                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-32-01                                                                                                  | LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL                                                                |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                  |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-32-03                                                                                                  | NLG UPLOCK ROLLER BRACKET INSPECTION                                                                          | KIWA |         | RECOMMENDED                   | MTH 21-Apr-2016<br>HRS 1186<br>LDG 1005   |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH "NLG UPLOCK ROLLER BRACKET INSPECTION" I.A.W. CIL-32-03.           |                                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                                                   | Description<br>Drawing # / Task #                                                                                                                                                  | City | Mod Lvl   | Part Number<br>Part Serial No             | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|-------------------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL CIL-32-04                                                                                                                                                                            | WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION<br>INFORMATIONAL                                                                                                             |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL CIL-32-06                                                                                                                                                                            | LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION<br>INFORMATIONAL                                                                                       |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL 525A-32-08 R01<br>32SL-08 : 525A1                                                                                                                                                    | NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION<br>EDDL                                                                                                                         |      | OPTIONAL  | MTH 11-Nov-2011<br>HRS 646.88<br>LDG 560  |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                                                              |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL 525A-32-17<br>32SL-17                                                                                                                                                                | EMERGENCY GEAR RELEASE INSPECTION<br>ZRH                                                                                                                                           |      | MANDATORY | MTH 22-Feb-2010<br>HRS 238<br>LDG 212     |                          |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                                                              |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL 525A-32-18                                                                                                                                                                           | LANDING GEAR- TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1651-32-2, LANDING GEAR- BRAKE ASSEMBLY- REPLACEMENT OF BLEEDER<br>SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS<br>EDDL |      | MANDATORY | MTH 11-Nov-2011<br>HRS 646.88<br>LDG 560  |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                                                              |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL 525A-32-20                                                                                                                                                                           | LANDING GEAR - MAIN LANDING GEAR REPAIR<br>INFORMATIONAL                                                                                                                           |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-33-05                                                                                                                                                                           | LIGHTS - ELECTROLUMINESCENT PANEL MOUNTING IMPROVEMENT<br>EDDV                                                                                                                     |      | MANDATORY | MTH 12-Nov-2012<br>HRS 798<br>LDG 730     |                          |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - FOUND SB PRIOR C/W                                                                                                                                         |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-33-06 R01                                                                                                                                                                       | LIGHTS - WING TIP LED LIGHT MODIFICATION<br>OPTIONAL                                                                                                                               |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-33-06                                                                                                                                                                           | LIGHTS - WING TIP LED LIGHT MODIFICATION<br>OPTIONAL                                                                                                                               |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SL CIL-33-01                                                                                                                                                                            | TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY<br>BATTERY<br>INFORMATIONAL                                    |      |           |                                           |                          |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-34-26<br>34SB-26                                                                                                                                                                | DIVERSITY ANTENNA INSTALLATION FOR ENHANCED SURVEILLANCE TRANSPONDERS<br>*CF                                                                                                       |      | OPTIONAL  | MTH<br>HRS<br>LDG                         |                          |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                            |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-34-34<br>34SB-34                                                                                                                                                                | COLLINS IFIS 6.0 SYSTEM SOFTWARE UPDATES<br>KIWA                                                                                                                                   |      | OPTIONAL  | MTH 20-Mar-2015<br>HRS 937.2<br>LDG 887   |                          |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - ACCOMPLISHED COLLINS IFIS 6.0 SYSTEM SOFTWARE UPDATES IAW SB525A-34-34.                                                                                    |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |
| SB 525A-34-35 R01                                                                                                                                                                       | NAVIGATION - DBU 5000 DATABASE UNIT (FLASH MEMORY) SOFTWARE DATABASE LOADER<br>SMF                                                                                                 |      | OPTIONAL  | MTH 25-Jul-2018<br>HRS 1446.5<br>LDG 1140 |                          |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB525A-34-35 BY INSTALLATION OF DBU-5000 DATABASE LOADER AND MODIFICATION OF THE WIRING AND IAPS CARD CAGE. AMENDED WEIGHT AND BALANCE DATA. |                                                                                                                                                                                    |      |           |                                           |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                                                                                     | Description        | Part Number | C/W Time 1 | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|-----------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------|------------|----------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                                                                                      | Drawing # / Task # | City        | Mod Lvl    | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SB 525A-34-36 R01 COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE                                                 |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-36 R02 COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE                                                 |                    |             |            |                |            |        |             |         |             |         |
| KIWA RECOMMENDED MTH 20-Mar-2015 - Complete                                                                                                   |                    |             |            |                |            |        |             |         |             |         |
| HRS 937.2                                                                                                                                     |                    |             |            |                |            |        |             |         |             |         |
| LDG 887                                                                                                                                       |                    |             |            |                |            |        |             |         |             |         |
| MOC : COMPLIED WITH - ACCOMPLISHED COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPGRADE IAW SB525A-34-36 R2.   |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-36 R03 NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES                            |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-36 34SB-36 COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE                                             |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL MTH A/R                                                                                                                              |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-38 NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) SOFTWARE 7.1 UPGRADE                                        |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-39 NAVIGATION - TDR-94D TRANSPONDER UPGRADE                                                                                        |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-40 NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE                    |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-41 R01 NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION                                |                    |             |            |                |            |        |             |         |             |         |
| SMF OPTIONAL MTH 25-Jul-2018 - Complete                                                                                                       |                    |             |            |                |            |        |             |         |             |         |
| HRS 1446.5                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| LDG 1140                                                                                                                                      |                    |             |            |                |            |        |             |         |             |         |
| MOC : COMPLIED WITH - COMPLIED WITH SB525A-34--41 R01, BY INSTALLATION OF ADS-B OUT CAPABLE COMPONENTS THAT MEET THE REGULATORY REQUIREMENTS. |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-41 R02 NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION                                |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-41 NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION                                    |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-42 NAVIGATION - ADS-B OUT WIRING MODIFICATION                                                                                      |                    |             |            |                |            |        |             |         |             |         |
| SMF MANDATORY MTH 11-May-2018 - N/A                                                                                                           |                    |             |            |                |            |        |             |         |             |         |
| HRS 1432.2                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| LDG 1123                                                                                                                                      |                    |             |            |                |            |        |             |         |             |         |
| MOC : NOT APPLICABLE - SB525A-34-42 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.                                                              |                    |             |            |                |            |        |             |         |             |         |
| SB 525A-34-44 NAVIGATION - NAV ANTENNA REPLACEMENT                                                                                            |                    |             |            |                |            |        |             |         |             |         |
| OPTIONAL -                                                                                                                                    |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |
| SB CIB-34-01 ENHANCED SURVEILLANCE TRANSPONDER STRAPPING MODIFICATION                                                                         |                    |             |            |                |            |        |             |         |             |         |
| DISCRETIONARY MTH -                                                                                                                           |                    |             |            |                |            |        |             |         |             |         |
| MOC :                                                                                                                                         |                    |             |            |                |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                   | Description<br>Drawing # / Task #                                                                                                                                                            | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB CIB-34-02                                                                                                                                            | GPS-4000S SOFTWARE UPDATE<br>KIWA                                                                                                                                                            |      |         | RECOMMENDED                   | MTH 04-Nov-2016<br>HRS 1261.9<br>LDG 1046<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH BY CONFIRMING CIB-34-02 DOES NOT APPLY DUE TO P/N 822-2189-010 GPS4000S IS INSTALLED. PLEASE UPDATE CESCOM. |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SB CIB-34-03 R01                                                                                                                                        | NAVIGATION - TEMPERATURE COMPENSATION FOR LNAV/VNAV - CANCELED<br>CANCELLED                                                                                                                  |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SB CIB-34-04                                                                                                                                            | ROCKWELL COLLINS ADAPTIVE FLIGHT DISPLAY UPGRADE<br>OPTIONAL                                                                                                                                 |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL CIL-34-04                                                                                                                                            | TDR-94/94D TRANSPONDER ALL-CALL                                                                                                                                                              |      |         | INFORMATIONAL                 |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL CIL-34-07                                                                                                                                            | NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE<br>INFORMATIONAL                                                                                      |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL CIL-34-10                                                                                                                                            | NAVIGATION - TRANSMITTAL OF GARMIN SB 19102 GSR 56 MOD 1<br>INFORMATIONAL                                                                                                                    |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SB CIL-34-11                                                                                                                                            | NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS<br>IMPROVEMENT                                                  |      |         | OPTIONAL                      |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL 525A-34-13                                                                                                                                           | CONFIGURATION FOR AUSTRALIA, SINGAPORE FIR, AND HONG KONG ADS-B OUT (SUPERSEDED BY SL525A-34-13 R01)<br>OPTIONAL                                                                             |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL 525A-34-14                                                                                                                                           | NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM<br>WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION<br>INFORMATIONAL |      |         |                               |                                                        |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL 525A-34-16                                                                                                                                           | NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV<br>KCRQ                                                                   |      |         | MANDATORY                     | MTH 26-Aug-2021<br>HRS 2178.8<br>LDG 1734              |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                              |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL CIL-35-01                                                                                                                                            | TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01<br>EDDL                                                                                                                            |      |         | MANDATORY                     | MTH 03-Jul-2014<br>HRS 908<br>LDG 865                  |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A                                                                                                                       |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SL CIL-35-05                                                                                                                                            | OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001<br>KFFZ                                                                                                                           |      |         | MANDATORY                     | MTH 01-Feb-2016<br>DAYS 1131.3<br>HRS 985<br>LDG       |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH CIL-35-05 OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001, SERVICE LETTER.                        |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
| SB 525A-36-04                                                                                                                                           | PNEUMATIC - MOISTURE TRAP INSTALLATION<br>OPTIONAL                                                                                                                                           |      |         |                               |                                                        |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                                            |                                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                                                                                                                     | Description<br>Drawing # / Task #                                                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL CIL-52-01                                                                                                                                                                                                                                              | DOORS - EMERGENCY DOOR INSPECTION<br>AW                                                                                          |      |         | MANDATORY                     | MTH 12-Nov-2013<br>HRS 881<br>LDG 833     |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLETE                                                                                                                                                                                                                     |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-52-02                                                                                                                                                                                                                                              | DOORS - EMERGENCY EXIT DOOR INSPECTION<br>INFORMATIONAL                                                                          |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                              |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-52-03                                                                                                                                                                                                                                              | DOORS - EMERGENCY ESCAPE HATCH INSPECTION<br>KCRQ                                                                                |      |         | MANDATORY                     | MTH 08-Nov-2021<br>HRS 2226.3<br>LDG 1767 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SL CIL-52-03, PERFORMED EMERGENCY ESCAPE HATCH INSPECTION, ESCAPE HATCH SEAL WAS LUBRICATED & FOUND WAS FOUND IN GOOD CONDITION. IN ACCORDANCE WITH CESSNA MODEL 525 SL CIL-52-03 ACCOMPLISHMENT INSTRUCTIONS. |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-53-09<br>53SL-09                                                                                                                                                                                                                                  | INTERCOSTAL DRAINAGE PATH INSPECTION<br>ZRH                                                                                      |      |         | RECOMMENDED                   | MTH 22-Feb-2010<br>HRS 238<br>LDG 212     |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                                                                                                                                |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-53-10                                                                                                                                                                                                                                             | UPPER TAILCONE SKIN INSPECTION<br>LOWW                                                                                           |      |         | MANDATORY                     | MTH 17-Jan-2011<br>HRS 471.43<br>LDG 422  |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - NO DAMAGE OR BARE MATERIAL FOUND                                                                                                                                                                                             |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-54-01 R01                                                                                                                                                                                                                                         | FIREWALL BOX                                                                                                                     | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB525A-54-01 R1 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.                                                                                                                                                                |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-54-02                                                                                                                                                                                                                                             | NACELLES/PYLONS - FORWARD ENGINE BEAM INSPECTION ACCESS PANEL INSTALLATION<br>OPTIONAL                                           |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                              |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-54-01                                                                                                                                                                                                                                              | NACELLES/PYLONS - ACCESS PANEL SEALANT INSPECTION<br>SMF                                                                         |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - CIL-54-01 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.                                                                                                                                                                      |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL 525A-55-03                                                                                                                                                                                                                                             | STABILIZERS - VERTICAL STABILIZER BOLT TORQUE INSPECTION<br>RECOMMENDED                                                          |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                              |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL WI-70-1008<br>E1                                                                                                                                                                                                                                       | STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL                                             |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                              |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL WI-70-1008<br>E2                                                                                                                                                                                                                                       | STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL                                             |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                              |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB 525A-71-06                                                                                                                                                                                                                                             | COWL STIFFENER INSTALLATION<br>EDDL                                                                                              |      |         | MANDATORY                     | MTH 03-Jul-2014<br>HRS 908<br>LDG 865     |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PERFORMED                                                                                                                                                                                                                    |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-71-02<br>LEFT ENGINE                                                                                                                                                                                                                               | TRANSMITTAL OF WILLIAMS INTERNATIONAL FJ44 SERVICE BULLETIN FJ44-72-128, ENGINE - SPLIT INNER RING BALL BEARING - REPLACE<br>SMF |      |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SL CIL-71-02 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.                                                                                                                                                                   |                                                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                            | Description                                                                                                              | Part Number | C/W Time 1 | Adj.                                      | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-------------|------------|-------------------------------------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                             | Drawing # / Task #                                                                                                       | City        | Mod Lvl    | Part Serial No                            | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SL CIL-71-02<br>RIGHT ENGINE                                                         | TRANSMITTAL OF WILLIAMS INTERNATIONAL FJ44 SERVICE BULLETIN FJ44-72-128,ENGINE - SPLIT INNER RING BALL BEARING - REPLACE | SMF         | MANDATORY  | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596   |            | -      |             |         |             | N/A     |
| MOC : NOT APPLICABLE - SL CIL-71-02 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.     |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL 525A-71-03 R01                                                                    | POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT                                                                        | SMF         | MANDATORY  | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |            | -      |             |         |             | N/A     |
| MOC : NOT APPLICABLE - SL525A-71-03 R01 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL 525A-71-03 R02                                                                    | POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT                                                                         | SMF         | MANDATORY  | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |            | -      |             |         |             | N/A     |
| MOC : NOT APPLICABLE - SL525A-71-03 R02 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL 525A-71-03                                                                        | POWER PLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT                                                                        | SMF         | MANDATORY  | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |            | -      |             |         |             | N/A     |
| MOC : NOT APPLICABLE - SL525A-71-03 IS NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER.     |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL 44-71-385<br>E1                                                                   | START ITT EXCEEDANCE - BORESCOPE INSPECTION & HIGH POWER CHECK RUN                                                       |             |            |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL 44-71-385<br>E2                                                                   | START ITT EXCEEDANCE - BORESCOPE INSPECTION & HIGH POWER CHECK RUN                                                       |             |            |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1064-CN<br>E1                                                               | CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                                          |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1064-CN<br>E2                                                               | CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                                          |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1064<br>E1                                                                  | POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                                                     |             |            |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1064<br>E2                                                                  | POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL                                                     |             |            |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1129<br>E1                                                                  | CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL                                |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1129<br>E2                                                                  | CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL                                |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1319-CN<br>E1                                                               | CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                                           |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1319-CN<br>E2                                                               | CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                                           |             | CANCELLED  |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |
| SL WI-71-1319<br>E1                                                                  | POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                                                      |             |            |                                           |            | -      |             |         |             |         |
| MOC :                                                                                |                                                                                                                          |             |            |                                           |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                                                 | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL WI-71-1319<br>E2         | POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL                                               |      |         |                               |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL WI-71-1541<br>E1         | POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL                                 |      |         |                               |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SL WI-71-1541<br>E2         | POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL                                 |      |         |                               |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-05-002<br>R02<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION                                                                                |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-05-002<br>R02<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION                                                                                |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-05-002<br>R03<br>E1 | UNSERVICEABLE PARTS - NOTIFICATION                                                                                |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-05-002<br>R03<br>E2 | UNSERVICEABLE PARTS - NOTIFICATION                                                                                |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R02<br>E1 | ENGINE - HOUSING, CARBON RING SEAL AND BEARING (NO. 3 BEARING RETAINER) - REPLACE (SUPERSEDED BY FJ44-72-066 R03) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R02<br>E2 | ENGINE - HOUSING, CARBON RING SEAL AND BEARING (NO. 3 BEARING RETAINER) - REPLACE (SUPERSEDED BY FJ44-72-066 R03) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R03<br>E1 | ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)                           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R03<br>E2 | ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)                           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R05<br>E1 | ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R06)                           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R05<br>E2 | ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R06)                           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R06<br>E1 | CARBON RING SEAL AND BEARING HOUSING - REPLACE                                                                    | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-066<br>R06<br>E2 | CARBON RING SEAL AND BEARING HOUSING - REPLACE                                                                    | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
|                             | <b>MOC :</b>                                                                                                      |      |         |                               |                                           |                |                |                |                            |                    |

**MOC :** NOT APPLICABLE - SB FJ44-72-066 R06 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                         | Description<br>Drawing # / Task #                                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-068<br>R03<br>E1                                                   | ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04)        |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-068<br>R03<br>E2                                                   | ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-068 R04)        |      |         | OPTIONAL                      | MTH                                     |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-070<br>R02<br>E1                                                   | CANCELLED - UPGRADE GEARBOX (4K SPRING-LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY SB FJ44-72-105 R05) |      |         | CANCELLED                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-070<br>R02<br>E2                                                   | CANCELLED - UPGRADE GEARBOX (4K SPRING-LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY SB FJ44-72-105 R05) |      |         | CANCELLED                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-075<br>R01<br>E1                                                   | GEARBOX P/N 78823 - INSPECTION                                                                              |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | A/R            |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLETE COMPLIED WITH ORIGINAL ISSUE21.JUN.2010 |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-075<br>R01<br>E2                                                   | GEARBOX P/N 78823 - INSPECTION                                                                              |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - BY ENGINE S/N                                   |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-075<br>E1                                                          | GEARBOX P/N 78823 - INSPECTION (SUPERSEDED BY FJ44-72-075 R01)                                              |      |         | MANDATORY                     | MTH 21-Jun-2010<br>HRS 394.7            |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                    |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R01<br>E1                                                   | ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R02)                          |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R01<br>E2                                                   | ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R02)                          |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R02<br>E1                                                   | IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)                                   |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R02<br>E2                                                   | IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-078 R03)                                   |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                  |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R03<br>E1                                                   | IP COMPRESSOR STATOR (STAGE 1-2) - REWORK                                                                   | UNK  |         | OPTIONAL                      | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                    |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-078<br>R03<br>E2                                                   | IP COMPRESSOR STATOR (STAGE 1-2) - REWORK                                                                   | UNK  |         | OPTIONAL                      | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                    |                                                                                                             |      |         |                               |                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                         | Description<br>Drawing # / Task #                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-080<br>R01<br>E1                                                                                                   | ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-080<br>R01<br>E2                                                                                                   | ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-080<br>R02<br>E1                                                                                                   | 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE          | UNK  |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                                    |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-080<br>R02<br>E2                                                                                                   | 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE          | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                                    |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R05<br>E1                                                                                                   | ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R05<br>E2                                                                                                   | ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R06<br>E1                                                                                                   | IP BLEED VALVE - REPLACE<br>SMF                                             |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-72-085 R06 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.</b> |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R06<br>E2                                                                                                   | IP BLEED VALVE - REPLACE<br>SMF                                             |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-72-085 R06 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.</b> |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R08<br>E1                                                                                                   | IP BLEED VALVE - REPLACE                                                    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-085<br>R08<br>E2                                                                                                   | IP BLEED VALVE - REPLACE                                                    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-086<br>R02<br>E1                                                                                                   | ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-086 R03)        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-086<br>R02<br>E2                                                                                                   | ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-086 R03)        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                             |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                      | Description<br>Drawing # / Task #                                         | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-086<br>R03<br>E1                                                                                                                | ENGINE - BLEED VALVE SHAFT - REPLACE<br>SMF                               |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-086 R03 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-086<br>R03<br>E2                                                                                                                | ENGINE - BLEED VALVE SHAFT - REPLACE<br>SMF                               |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-086 R03 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R02<br>E1                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R02<br>E2                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R03) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R03<br>E1                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R04) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R03<br>E2                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R04) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R05<br>E1                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R06) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R05<br>E2                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R06) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R06<br>E1                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R07) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R06<br>E2                                                                                                                | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R07) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 11                                                                                           |                                                                           |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                            | Description<br>Drawing # / Task #                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------|------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-093<br>R07<br>E1                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R08)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R07<br>E2                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R08)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R08<br>E1                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R09)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R08<br>E2                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R09)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R09<br>E1                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY (SUPERSEDED BY FJ44-72-093 R10) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R09<br>E2                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY (SUPERSEDED BY FJ44-72-093 R10) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R10<br>E1                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R11)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R10<br>E2                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R11)                |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 11</b> |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R11<br>E1                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R12)                | EDDW |         | MANDATORY                     | MTH 13-Feb-2013<br>HRS 882.7<br>LDG 782 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - CARRIED OUT</b>         |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-093<br>R11<br>E2                      | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R12)                | EDDW |         | MANDATORY                     | MTH 13-Feb-2013<br>HRS 882.7<br>LDG 782 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - CARRIED OUT</b>         |                                                                                          |      |         |                               |                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                           | Description<br>Drawing # / Task #                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-093<br>R12<br>E1                                                                                                                                     | DIFFUSER CASE ASSEMBLY - REPLACE<br>SMF                                          |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-093 R11 WAS PREVIOUSLY COMPLIED WITH ON 2/13/13, ENGINE IS NOT AFFECTED BY R12 OF THIS SB. NO FURTHER ACTION REQUIRED. |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R12<br>E2                                                                                                                                     | DIFFUSER CASE ASSEMBLY - REPLACE<br>SMF                                          |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-093 R11 WAS PREVIOUSLY COMPLIED WITH ON 2/13/13, ENGINE IS NOT AFFECTED BY R12 OF THIS SB. NO FURTHER ACTION REQUIRED. |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R13<br>E1                                                                                                                                     | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE                                        |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>R13<br>E2                                                                                                                                     | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE                                        |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>E1                                                                                                                                            | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)        |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-093<br>E2                                                                                                                                            | ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-72-093 R01)        |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R01<br>E1                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 3                                                                                                                 |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R01<br>E2                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R02) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 3                                                                                                                 |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R02<br>E1                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 3                                                                                                                 |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R02<br>E2                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R03) |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SUPERSEDED BY R 3                                                                                                                 |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R03<br>E1                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-097<br>R03<br>E2                                                                                                                                     | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                    |                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                                    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-097<br>R04<br>E1 | CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151 R06)                  |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-097<br>R04<br>E2 | CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-151 R06)                  |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-097<br>E1        | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)                     |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
|                             | <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 3</b>                                                      |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-097<br>E2        | ENGINE - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-097 R01)                     |      |         | MANDATORY                     | MTH 15-Nov-2013<br>HRS 954.7<br>LDG 873 |                | -              |                |                            | N/A                |
|                             | <b>MOC : NOT APPLICABLE - SUPERSEDED BY R 3</b>                                                      |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-104<br>E1        | ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01) |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-104<br>E2        | ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01) |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R02<br>E1 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R02<br>E2 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R03)         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R03<br>E1 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R03<br>E2 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R04<br>E1 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R04<br>E2 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-72-105<br>R05<br>E1 | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION                                         |      |         | OPTIONAL                      |                                         |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                                         |      |         |                               |                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                           | Description<br>Drawing # / Task #                                                             | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-105<br>R05<br>E2                                                                     | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION<br>OPTIONAL                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-105<br>R06<br>E1                                                                     | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION<br>OPTIONAL                      |      |         | MTH                           |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-105<br>R06<br>E2                                                                     | UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION<br>OPTIONAL                      |      |         | MTH                           |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-106<br>R01<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>SMF                                         |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-106 R01 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER. |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-106<br>R01<br>E2                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>SMF                                         |      |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-106 R01 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER. |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-106<br>R03<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-106<br>R03<br>E2                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R01<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R02)<br>RECOMMENDED |      |         |                               |                                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - - N/A PER S/N EFFECTIVITY                                         |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R01<br>E2                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R02)<br>RECOMMENDED |      |         |                               |                                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - - N/A PER S/N EFFECTIVITY                                         |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R02<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R02<br>E2                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R03<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R03<br>E2                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>RECOMMENDED                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                    |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R04<br>E1                                                                     | 2ND REDUCTION PINION BEARING HOUSING - REPLACE<br>UNK                                         |      |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                      |                                                                                               |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position            | Description<br>Drawing # / Task #                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------|---------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-107<br>R04<br>E2      | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>       |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R05<br>E1      | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>R05<br>E2      | 2ND REDUCTION PINION BEARING HOUSING - REPLACE                                              |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>E1             | ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)     |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-107<br>E2             | ENGINE - 2ND REDUCTION PINION BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-107 R01)     |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01-CN<br>E1   | SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01-CN<br>E2   | SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01<br>E1      | ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)                         |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>R01<br>E2      | ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)                         |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>E1             | ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)                             |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-108<br>E2             | ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)                             |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                     |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-109<br>E1             | ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE                                    | UNK  |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>       |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-109<br>E2             | ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE                                    | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PCW</b> |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-110<br>E1             | ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE                                                | UNK  |         | MANDATORY                     | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>       |                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                         | Description<br>Drawing # / Task #                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-110<br>E2                                                                                                          | ENGINE - DAMPENER BRACKET ASSEMBLY - REPLACE                                          | UNK  |         | MANDATORY                     | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                    |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-111<br>R01<br>E1                                                                                                   | ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-111<br>R01<br>E2                                                                                                   | ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)           |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-111<br>R02<br>E1                                                                                                   | ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION                                           | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-111 R02 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE PART/MODEL NUMBER. |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-111<br>R02<br>E2                                                                                                   | ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION                                           | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-111 R02 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE PART/MODEL NUMBER. |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-122-CNSUPERSEDED<br>E1                                                                                             | ENGINE - ACCESSORY DRIVE SHAFT - REPLACE                                              |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-122-CNSUPERSEDED<br>E2                                                                                             | ENGINE - ACCESSORY DRIVE SHAFT - REPLACE                                              |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-122<br>E1                                                                                                          | ACCESSORY DRIVE SHAFT - REPLACE                                                       | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-122 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                                       |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-122<br>E2                                                                                                          | ACCESSORY DRIVE SHAFT - REPLACE                                                       | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-122 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                                       |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-123<br>R01<br>E1                                                                                                   | CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE                     |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-123<br>R01<br>E2                                                                                                   | CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE                     |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-123<br>E1                                                                                                          | INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE (SUPERSEDED BY FJ44-72-123 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-123<br>E2                                                                                                          | INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE (SUPERSEDED BY FJ44-72-123 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R01<br>E1                                                                                                   | REPLACE HP TURBINE BLADES                                                             |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                  |                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #  | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-124<br>R01<br>E2 | REPLACE HP TURBINE BLADES          |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R02<br>E1 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R02<br>E2 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R03<br>E1 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R03<br>E2 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R04<br>E1 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R04<br>E2 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R05<br>E1 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R05<br>E2 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R06<br>E1 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R06<br>E2 | HP TURBINE BLADES - REPLACE        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R07<br>E1 | HP TURBINE BLADES - REPLACE        |      |         |                               | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R07<br>E2 | HP TURBINE BLADES - REPLACE        |      |         |                               | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                    |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R08<br>E1 | HP TURBINE BLADES - REPLACE<br>UNK |      |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH  |                                    |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                       | Description<br>Drawing # / Task #                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-124<br>R08<br>E2                                                                 | HP TURBINE BLADES - REPLACE<br>UNK                                                     |      |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                  |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R09<br>E1                                                                 | HP TURBINE BLADES - REPLACE                                                            |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>R09<br>E2                                                                 | HP TURBINE BLADES - REPLACE                                                            |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>E1                                                                        | HP TURBINE BLADES - REPLACE                                                            |      |         | RECOMMENDED                   | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-124<br>E2                                                                        | HP TURBINE BLADES - REPLACE                                                            |      |         | RECOMMENDED                   | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-128<br>R01<br>E1                                                                 | CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY SB FJ44-72-152 R02) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-128<br>R01<br>E2                                                                 | CANCELLED - SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY SB FJ44-72-152 R02) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-128<br>E1                                                                        | SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-128 R01)                |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-128<br>E2                                                                        | SPLIT INNER RING BALL BEARING - REPLACE (SUPERSEDED BY FJ44-72-128 R01)                |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01-CN<br>E1                                                              | CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE              |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01-CN<br>E2                                                              | CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE              |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01<br>E1                                                                 | INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE                                  | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-129 R01 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-129<br>R01<br>E2                                                                 | INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE                                  | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-129 R01 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-129<br>E1                                                                        | REPLACE INNER GUIDED ROLLER BEARING (NO. 3 BEARING)                                    | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-129 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.     |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                     | Description<br>Drawing # / Task #                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-129<br>E2                                                                                                      | REPLACE INNER GUIDED ROLLER BEARING (NO. 3 BEARING)              | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-129 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                                   |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>R01<br>E1                                                                                               | HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>R01<br>E2                                                                                               | HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>R02<br>E1                                                                                               | HP COMPRESSOR ROTOR - INSPECTION                                 |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>R02<br>E2                                                                                               | HP COMPRESSOR ROTOR - INSPECTION                                 |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>E1                                                                                                      | HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-130<br>E2                                                                                                      | HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>R01<br>E1                                                                                               | REPLACE 1ST LP TURBINE NOZZLE                                    | UNK  |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>R01<br>E2                                                                                               | REPLACE 1ST LP TURBINE NOZZLE                                    | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>R02<br>E1                                                                                               | REPLACE 1ST LP TURBINE NOZZLE                                    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>R02<br>E2                                                                                               | REPLACE 1ST LP TURBINE NOZZLE                                    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>E1                                                                                                      | REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-133<br>E2                                                                                                      | REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-135<br>R01<br>E1                                                                                               | IDENTIFICATION PLATE - REPLACE                                   | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-135 R01 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                                                          | Description                                                    | Part Number | C/W Time 1                                | Adj.           | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|--------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-------------|-------------------------------------------|----------------|------------|--------|-------------|---------|-------------|----------|
| Position                                                                                                           | Drawing # / Task #                                             | City        | Mod Lvl                                   | Part Serial No | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB FJ44-72-135<br>R01<br>E2                                                                                        | IDENTIFICATION PLATE - REPLACE<br>SMF                          | MANDATORY   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-72-135 R01 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-135<br>E1                                                                                               | IDENTIFICATION PLATE - REPLACE (SUPERSEDED BY FJ44-72-135 R01) | MANDATORY   |                                           |                |            | -      |             |         |             |          |
| MOC :                                                                                                              |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-135<br>E2                                                                                               | IDENTIFICATION PLATE - REPLACE (SUPERSEDED BY FJ44-72-135 R01) | MANDATORY   |                                           |                |            | -      |             |         |             |          |
| MOC :                                                                                                              |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-140<br>R01<br>E1                                                                                        | GEARBOX HOUSING ASSEMBLY - INSPECTION                          | RECOMMENDED |                                           |                |            | -      |             |         |             |          |
| MOC :                                                                                                              |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-140<br>R01<br>E2                                                                                        | GEARBOX HOUSING ASSEMBLY - INSPECTION                          | RECOMMENDED |                                           |                |            | -      |             |         |             |          |
| MOC :                                                                                                              |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-140<br>E1                                                                                               | GEARBOX HOUSING ASSEMBLY - INSPECTION<br>UNK                   | MANDATORY   | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                |            | -      |             |         |             | Complete |
| MOC : COMPLIED WITH                                                                                                |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-140<br>E2                                                                                               | GEARBOX HOUSING ASSEMBLY - INSPECTION<br>UNK                   | MANDATORY   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                |            | -      |             |         |             | Complete |
| MOC : COMPLIED WITH                                                                                                |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-142<br>R01<br>E1                                                                                        | NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE<br>SMF      | RECOMMENDED | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-72-142 R01 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.                           |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-142<br>R01<br>E2                                                                                        | NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE<br>SMF      | RECOMMENDED | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-72-142 R01 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.                           |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-142<br>E1                                                                                               | NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE<br>SMF      | RECOMMENDED | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-72-142 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.                               |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-142<br>E2                                                                                               | NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE<br>SMF      | RECOMMENDED | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-72-142 IS NOT APPLICABLE BY ENGINE PART/MODEL NUMBER.                               |                                                                |             |                                           |                |            |        |             |         |             |          |
| SB FJ44-72-143<br>R01<br>E1                                                                                        | BLEED VALVE SHAFT - REPLACE<br>UNK                             | RECOMMENDED | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                |            | -      |             |         |             | Complete |
| MOC : COMPLIED WITH                                                                                                |                                                                |             |                                           |                |            |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|-------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-143<br>R01<br>E2 | BLEED VALVE SHAFT - REPLACE<br>UNK                                      |      |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>  |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-143<br>E1        | BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)             |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-143<br>E2        | BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)             |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R01<br>E1 | LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R01<br>E2 | LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R02<br>E1 | LP REAR BEARING SEAL RETAINER - REPLACE                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R02<br>E2 | LP REAR BEARING SEAL RETAINER - REPLACE                                 |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R03<br>E1 | LP REAR BEARING SEAL RETAINER - REPLACE<br>UNK                          |      |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>  |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>R03<br>E2 | LP REAR BEARING SEAL RETAINER - REPLACE<br>UNK                          |      |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>  |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>E1        | LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-150<br>E2        | LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R01<br>E1 | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R02)   |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R01<br>E2 | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R02)   |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R02<br>E1 | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R03)   |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R02<br>E2 | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R03)   |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                |                                                                         |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                             | Description<br>Drawing # / Task #                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-151<br>R03<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R03<br>E2                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R04<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R04<br>E2                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R05<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 | UNK  |         | MANDATORY                     | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| MOC : COMPLIED WITH                                                                                               |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R05<br>E2                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 | UNK  |         | MANDATORY                     | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| MOC : COMPLIED WITH                                                                                               |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R06<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     | MTH                                       |                | MPI<br>MPI     |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>R06<br>E2                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 |      |         | MANDATORY                     | MTH                                       |                | MPI<br>MPI     |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>E1                                                                                              | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R01) |      |         |                               | MANDATORY                                 |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-151<br>E2                                                                                              | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-151 R01) |      |         |                               | MANDATORY                                 |                | -              |                |                            |                    |
| MOC :                                                                                                             |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-152<br>R01<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| MOC : NOT APPLICABLE - SB FJ44-72-152 R01 (AND ALL PREVIOUS REVISION) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-152<br>R01<br>E2                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| MOC : NOT APPLICABLE - SB FJ44-72-152 R01 (AND ALL PREVIOUS REVISION) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-152<br>R02<br>E1                                                                                       | BEARING AND PINION ASSEMBLY - INSTALL                                 | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| MOC : NOT APPLICABLE - SB FJ44-72-152 R02 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                              |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                       | Description<br>Drawing # / Task #                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-72-152<br>R02<br>E2                                                                 | BEARING AND PINION ASSEMBLY - INSTALL                                 | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-72-152 R02 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-152<br>E1                                                                        | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-152 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-152<br>E2                                                                        | BEARING AND PINION ASSEMBLY - INSTALL (SUPERSEDED BY FJ44-72-152 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-154<br>R01<br>E1                                                                 | 1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)                        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-154<br>R01<br>E2                                                                 | 1ST LP TURBINE NOZZLE - INSPECTION (CANCELLED)                        |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-154<br>E1                                                                        | 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-72-154<br>E2                                                                        | 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-154 R01)    |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R04<br>E1                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R04<br>E2                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R05<br>E1                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R05<br>E2                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R06<br>E1                                                                      | ENGINE - 1ST LP TURBINE DISK - INSPECTION                             |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R06<br>E2                                                                      | ENGINE - 1ST LP TURBINE DISK - INSPECTION                             |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R07<br>E1                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | CSI            |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| SL 44-72-325 R07<br>E2                                                                      | 1ST LP TURBINE DISK - INSPECTION                                      |      |         |                               |                                           |                | CSI            |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-05-1000<br>R02<br>E1                                                                | UNSERVICEABLE PARTS - NOTIFICATION                                    |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-05-1000<br>R02<br>E2                                                                | UNSERVICEABLE PARTS - NOTIFICATION                                    |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                |                                                                       |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                      | Description<br>Drawing # / Task #                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------|------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| PSID WI-05-1000<br>R03<br>E1                                                               | UNSERVICEABLE PARTS - NOTIFICATION                               |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-05-1000<br>R03<br>E2                                                               | UNSERVICEABLE PARTS - NOTIFICATION                               |      |         | INFORMATIONAL                 |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-72-1022<br>R01<br>E1                                                               | OPERATING IN AREAS OF SMOKE                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-72-1022<br>R01<br>E2                                                               | OPERATING IN AREAS OF SMOKE                                      |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-72-1026<br>E1                                                                      | FAN CASE - RUB INDICATIONS                                       |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| PSID WI-72-1026<br>E2                                                                      | FAN CASE - RUB INDICATIONS                                       |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R03<br>E1                                                                    | ENGINE - 1ST LP TURBINE NOZZLE - REPLACE                         |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R03<br>E2                                                                    | ENGINE - 1ST LP TURBINE NOZZLE - REPLACE                         |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R04<br>-CN<br>E1                                                             | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)  |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R04<br>-CN<br>E2                                                             | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)  |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R04<br>E1                                                                    | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)  | UNK  |         |                               | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                 |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004 R04<br>E2                                                                    | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY SB WISB-72-1054)  | UNK  |         |                               | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                 |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004<br>E1                                                                        | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01) |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1004<br>E2                                                                        | 1ST LP TURBINE NOZZLE - REPLACE (SUPERSEDED BY WISB-72-1004 R01) |      |         |                               |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                               |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB WI-72-1032 R01<br>E1                                                                    | HIGH PRESSURE TURBINE DISK - REPLACE                             | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB WI-72-1032 R01 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.</b> |                                                                  |      |         |                               |                                           |                |                |                |                            |                    |

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                           | Description        | Part Number | C/W Time 1                                | Adj.           | TBO 1      | TSO 1      | (ENG) DUE 1 | Remains    |             |          |
|-------------------------------------------------------------------------------------|--------------------|-------------|-------------------------------------------|----------------|------------|------------|-------------|------------|-------------|----------|
| Position                                                                            | Drawing # / Task # | City        | Mod Lvl                                   | Part Serial No | C/W Time 2 | + or -     | TBO 2       | TSO 2      | (ENG) DUE 2 | Remains  |
| SB WI-72-1032 R01 HIGH PRESSURE TURBINE DISK - REPLACE<br>E2                        | SMF                | MANDATORY   | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -          |            |             |            |             | N/A      |
| MOC : NOT APPLICABLE - SB WI-72-1032 R01 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1032 R02 HIGH PRESSURE TURBINE DISK - REPLACE<br>E1                        | SMF                | MANDATORY   | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -          |            |             |            |             | N/A      |
| MOC : NOT APPLICABLE - SB WI-72-1032 R02 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1032 R02 HIGH PRESSURE TURBINE DISK - REPLACE<br>E2                        | SMF                | MANDATORY   | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -          |            |             |            |             | N/A      |
| MOC : NOT APPLICABLE - SB WI-72-1032 R02 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1032 HIGH PRESSURE TURBINE DISK - REPLACE<br>E1                            | SMF                | MANDATORY   | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -          |            |             |            |             | N/A      |
| MOC : NOT APPLICABLE - SB WI-72-1032 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.     |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1032 HIGH PRESSURE TURBINE DISK - REPLACE<br>E2                            | SMF                | MANDATORY   | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -          |            |             |            |             | N/A      |
| MOC : NOT APPLICABLE - SB WI-72-1032 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.     |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R01 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1                  |                    | MANDATORY   |                                           |                | -          |            |             |            |             |          |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R01 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2                  |                    | MANDATORY   |                                           |                | -          |            |             |            |             |          |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1                  | UNK                | MANDATORY   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -          |            |             |            |             | Complete |
| MOC : COMPLIED WITH                                                                 |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R02 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2                  | UNK                | MANDATORY   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -          |            |             |            |             | Complete |
| MOC : COMPLIED WITH                                                                 |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1                  |                    | MANDATORY   | MTH                                       |                |            | MPI<br>MPI |             |            |             |          |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R03 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2                  |                    | MANDATORY   | MTH                                       |                |            | MPI<br>MPI |             |            |             |          |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1                  |                    | MANDATORY   | MTH<br>LDG                                |                |            | 8000       |             | (8000)8040 |             | 6032     |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E2                  |                    | MANDATORY   | MTH<br>LDG                                |                |            | 8000       |             | (8000)8040 |             | 6032     |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |
| SB WI-72-1034 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>E1                      |                    | MANDATORY   |                                           |                | -          |            |             |            |             |          |
| MOC :                                                                               |                    |             |                                           |                |            |            |             |            |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code               | Description                                                   | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-------------------------|---------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------|---------|-------------|----------|
| Position                | Drawing # / Task #                                            | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB WI-72-1034<br>E2     | HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK<br>MANDATORY       |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R01<br>E1 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R01<br>E2 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R02<br>E1 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>UNK<br>RECOMMENDED    |             |            |                | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
| MOC : COMPLIED WITH     |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R02<br>E2 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>UNK<br>RECOMMENDED    |             |            |                | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
| MOC : COMPLIED WITH     |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R03<br>E1 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R03<br>E2 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R04<br>E1 | ACCESSORY DRIVE TOWERSHAFT - REPLACE                          |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R04<br>E2 | ACCESSORY DRIVE TOWERSHAFT - REPLACE                          |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R05<br>E1 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | CSI         |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1037 R05<br>E2 | ACCESSORY DRIVE TOWERSHAFT - REPLACE<br>RECOMMENDED           |             |            |                |                                           |        | CSI         |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1041 R01<br>E1 | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>UNK<br>RECOMMENDED |             |            |                | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
| MOC : COMPLIED WITH     |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1041 R01<br>E2 | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>UNK<br>RECOMMENDED |             |            |                | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
| MOC : COMPLIED WITH     |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1041 R03<br>E1 | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE                       |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1041 R03<br>E2 | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE                       |             |            |                |                                           |        | -           |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |
| SB WI-72-1041 R04<br>E1 | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE<br>RECOMMENDED        |             |            |                |                                           |        | MPI         |         |             |          |
| MOC :                   |                                                               |             |            |                |                                           |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position  | Description<br>Drawing # / Task #                                               | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------|---------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB WI-72-1041<br>E2    | R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE                                     |      |         | RECOMMENDED                   |                          |                | MPI            |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1041<br>E1    | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1041<br>E2    | HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1044<br>E1    | R03 BALANCE PISTON - REPLACE                                                    |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-72-1044<br>E2    | R03 BALANCE PISTON - REPLACE                                                    |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1032-CN<br>E1 | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                     |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1032-CN<br>E2 | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                     |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1128<br>E1    | FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL                                 |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1128<br>E2    | FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL                                 |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1132-CN<br>E1 | CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1132-CN<br>E2 | CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1132<br>E1    | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                     |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1132<br>E2    | APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL                     |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1140<br>E1    | INDUCTION HEATING - REVISION TO ENGINE MANUAL                                   |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1140<br>E2    | INDUCTION HEATING - REVISION TO ENGINE MANUAL                                   |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1262<br>E1    | APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL                      |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-72-1262<br>E2    | APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL                      |      |         |                               |                          |                | -              |                |                            |                    |
|                        | <b>MOC :</b>                                                                    |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                    | Description<br>Drawing # / Task #                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                                                                                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------------------------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL 525A-73-02<br>73SL-02                                                                                 | TRANSMITTAL OF WILLIAMS INTERNATIONAL SERVICE BULLETIN CP294.03.01                             | ZRH  |         | RECOMMENDED                   | FJ44-73-034, ENGINE AND FUEL CONTROL - FADEC SOFTWARE UPLOAD OF<br>DAYS 22-Feb-2010<br>HRS 238<br>LDG 212 |                | A/R            |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                               |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-030<br>R07<br>E1                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R08) | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163                                                                 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-73-030 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED.</b> |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-030<br>R07<br>E2                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP219.11.06 (SUPERSEDED BY FJ44-73-030 R08) | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163                                                                 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-73-030 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED.</b> |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-034<br>R02<br>E1                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP294.03.01 (SUPERSEDED BY FJ44-73-034 R03) | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163                                                                 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-73-034 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED.</b> |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-034<br>R02<br>E2                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP294.03.01 (SUPERSEDED BY FJ44-73-034 R03) | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163                                                                 |                | A/R            |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SB FJ44-73-034 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED.</b> |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-034<br>R05<br>E1                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP294.03.01 (NO LONGER ACTIVE)              | EDDW |         | MANDATORY                     | MTH 31-Jan-2013<br>HRS 882.7<br>LDG 782                                                                   |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - ALREADY PERFORMED.</b>                                                          |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-034<br>R05<br>E2                                                                              | ENGINE FUEL AND CONTROL - FADEC SOFTWARE UPLOAD OF CP294.03.01 (NO LONGER ACTIVE)              | EDDW |         | MANDATORY                     | MTH 31-Jan-2013<br>HRS 882.7<br>LDG 782                                                                   |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - ALREADY PERFORMED.</b>                                                          |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R01<br>E1                                                                              | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R02)         |      |         | MANDATORY                     |                                                                                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                             |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R01<br>E2                                                                              | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R02)         |      |         | MANDATORY                     |                                                                                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                             |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R02<br>E1                                                                              | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R03)         |      |         | MANDATORY                     |                                                                                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                             |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R02<br>E2                                                                              | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R03)         |      |         | MANDATORY                     |                                                                                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                             |                                                                                                |      |         |                               |                                                                                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                      | Description<br>Drawing # / Task #                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-038<br>R06<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R06<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-038 R07) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R07<br>E1                                                                                                                | DUAL CHANNEL FADEC - REPLACE<br>SMF                                                    |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-038 R07 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-038<br>R07<br>E2                                                                                                                | DUAL CHANNEL FADEC - REPLACE<br>SMF                                                    |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-038 R07 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R01<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R02) |      |         | MANDATORY                     |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R01<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R02) |      |         | MANDATORY                     |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R02<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03) |      |         | MANDATORY                     |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R02<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R03) |      |         | MANDATORY                     |                                           |                | A/R            |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R03<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R03<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R04) | EDDV |         | MANDATORY                     | MTH 24-Aug-2012<br>HRS 847.7<br>LDG 741   |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                 |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R04<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R05) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R04<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R05) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R05<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R06) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                      | Description<br>Drawing # / Task #                                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-039<br>R05<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - DUAL CHANNEL FADEC - REPLACE (SUPERSEDED BY FJ44-73-039 R06)           |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R06<br>E1                                                                                                                | DUAL CHANNEL FADEC - REPLACE<br>SMF                                                              |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-039 R06 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-039<br>R06<br>E2                                                                                                                | DUAL CHANNEL FADEC - REPLACE<br>SMF                                                              |      |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-039 R06 (AND ALL PREVIOUS REVISIONS) HAVE BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R01<br>E1                                                                                                                | REPLACE - ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET (SUPERSEDED BY FJ44-73-042 R02) | SMF  |         | RECOMMENDED                   | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB FJ44-73-042 REV 5 BY REPLACEMENT OF THE FUEL TUBE LOOP CLAMP BRACKET WITH AN UPGRADE DESIGN. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R01<br>E2                                                                                                                | REPLACE - ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET (SUPERSEDED BY FJ44-73-042 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R02<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03) | SMF  |         | RECOMMENDED                   | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB FJ44-73-042 REV 5 BY REPLACEMENT OF THE FUEL TUBE LOOP CLAMP BRACKET WITH AN UPGRADE DESIGN. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R02<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R03) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R03<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04) | SMF  |         | RECOMMENDED                   | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB FJ44-73-042 REV 5 BY REPLACEMENT OF THE FUEL TUBE LOOP CLAMP BRACKET WITH AN UPGRADE DESIGN. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R03<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R04) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R04<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05) | SMF  |         | RECOMMENDED                   | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB FJ44-73-042 REV 5 BY REPLACEMENT OF THE FUEL TUBE LOOP CLAMP BRACKET WITH AN UPGRADE DESIGN. |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R04<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R05) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                  |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                      | Description<br>Drawing # / Task #                                                                           | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-042<br>R05<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE                                            | UNK  |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - PCW                                                                                                           |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>R05<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE                                            | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH                                                                                                                 |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>E1                                                                                                                       | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R01)            | SMF  |         | RECOMMENDED                   | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SB FJ44-73-042 REV 5 BY REPLACEMENT OF THE FUEL TUBE LOOP CLAMP BRACKET WITH AN UPGRADE DESIGN. |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-042<br>E2                                                                                                                       | ENGINE FUEL AND CONTROL - FUEL TUBE LOOP CLAMP BRACKET - REPLACE (SUPERSEDED BY FJ44-73-042 R01)            |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-043<br>R01<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD (SUPERSEDED BY FJ44-73-043 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-043<br>R01<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD (SUPERSEDED BY FJ44-73-043 R02) |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-043<br>R02<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD                                 |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-043<br>R02<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FADEC REPLACEMENT AND APPLICATION SOFTWARE UPLOAD                                 |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R01<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R02)                      |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R01<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R02)                      |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R02<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)                      |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R02<br>E2                                                                                                                | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R03)                      |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R03<br>E1                                                                                                                | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04)                      |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                               |                                                                                                             |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                     | Description<br>Drawing # / Task #                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-044<br>R03<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R04<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R05) |      |         | MANDATORY                     | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R04<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R05) |      |         | MANDATORY                     | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R05<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R06) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R05<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R06) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R06<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R07) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R06<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R07) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R07<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | KIWA |         | MANDATORY                     | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN FJ44-73-044 REV 7. PERFORMED ENGINE RUNS AND LEAK CHECKS, CHECKS GOOD.        |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R07<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | KIWA |         | MANDATORY                     | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN FJ44-73-044 REV 7. PERFORMED ENGINE RUNS AND LEAK CHECKS, CHECKS GOOD.        |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R08<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-044 R07 WAS PREVIOUSLY COMPLIED WITH ON 1/9/18, ENGINE IS NOT AFFECTED BY REVISION 8 OF THIS SB. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R08<br>E2                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1996.7<br>LDG 1636 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-044 R07 WAS PREVIOUSLY COMPLIED WITH ON 1/9/18, ENGINE IS NOT AFFECTED BY REVISION 8 OF THIS SB. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>R09<br>E1                                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                     | Description<br>Drawing # / Task #                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-044<br>R09<br>E2                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>E1                                                                                                      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-044<br>E2                                                                                                      | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-044 R01) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R02<br>E1                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-046 R03) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R02<br>E2                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-046 R03) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R03<br>E1                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-046 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R03<br>E2                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE (SUPERSEDED BY FJ44-73-046 R04) |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R04<br>E1                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-046 R04 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R04<br>E2                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-046 R04 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R05<br>E1                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-046<br>R05<br>E2                                                                                               | ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE                                 |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-049<br>E1                                                                                                      | ENGINE FUEL AND CONTROL - FUEL FILTER & FILTER BOWL - INSPECTION                       | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-049 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                                   |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-73-049<br>E2                                                                                                      | ENGINE FUEL AND CONTROL - FUEL FILTER & FILTER BOWL - INSPECTION                       | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-73-049 IS NOT APPLICABLE BY ENGINE SERIAL NUMBER.                                   |                                                                                        |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                                       | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|---------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-73-061<br>E1           | CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)                    |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-73-061<br>E2           | CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO)                    |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-73-1008<br>R01<br>E1   | FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG                                               |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| PSID WI-73-1008<br>R01<br>E2   | FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG                                               |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>-CN<br>E1 | CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                    |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>-CN<br>E2 | CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE                                    |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>E1        | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002 R02<br>E2        | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002<br>E1            | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)               |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1002<br>E2            | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)               |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1007 R01<br>E1        | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED) |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1007 R01<br>E2        | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED) |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1008 R01<br>E1        | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1008 R01<br>E2        | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1008 R02<br>E1        | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1008 R02<br>E2        | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1008 R03<br>E1        | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE                                         |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                            |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                                                                              | Description                                                     | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1       | Remains |              |          |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------------|---------|--------------|----------|
| Position                                                                                                                               | Drawing # / Task #                                              | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2             | TSO 2   | (ENG) DUE 2  | Remains  |
| SB WI-73-1008 R03 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE<br>E2                                                |                                                                 |             |            | RECOMMENDED    |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1008 R04 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE<br>E1                                                |                                                                 | KEUG        |            | RECOMMENDED    | MTH 07-Jun-2019<br>HRS 1734.8<br>LDG 1392 |        | -                 |         |              | Complete |
| MOC : COMPLIED WITH - COMPLIED WITH IAW INSTRUCTIONS WITHIN. NO LEAKS NOTED                                                            |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1008 R04 ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE<br>E2                                                |                                                                 | KEUG        |            | RECOMMENDED    | MTH 07-Jun-2019<br>HRS 1734.8<br>LDG 1392 |        | -                 |         |              | Complete |
| MOC : COMPLIED WITH - COMPLIED WITH IAW INSTRUCTIONS WITHIN. NO LEAKS NOTED                                                            |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1008<br>E1                                                                                                                    | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE |             |            | RECOMMENDED    |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1008<br>E2                                                                                                                    | ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE |             |            | RECOMMENDED    |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R01 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E1                                                       |                                                                 |             |            |                |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R01 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E2                                                       |                                                                 |             |            |                |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E1                                                       |                                                                 | SMF         |            |                | MTH 21-Jun-2019<br>HRS 1745.3<br>LDG 1403 |        | -                 |         |              | Complete |
| MOC : COMPLIED WITH - COMPLIED WITH WISB-73-1009 REV 2 DATED AUG. 6/18 BY REPLACEMENT OF ENGINE FUEL AND CONTROL FUEL TUBE ASSEMBLIES. |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R02 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E2                                                       |                                                                 |             |            |                |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E1                                                       |                                                                 |             |            |                |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R03 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E2                                                       |                                                                 |             |            |                |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E1                                                       |                                                                 |             |            | RECOMMENDED    | MTH                                       |        | CSI<br>CSI        |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE<br>E2                                                       |                                                                 |             |            | RECOMMENDED    | MTH<br>HRS                                |        | CSI<br>CSI<br>CSI |         | (4000)4073.7 | 1438.8   |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009<br>E1                                                                                                                    | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE        |             |            | RECOMMENDED    |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |
| SB WI-73-1009<br>E2                                                                                                                    | ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE        |             |            | RECOMMENDED    |                                           |        | -                 |         |              |          |
| MOC :                                                                                                                                  |                                                                 |             |            |                |                                           |        |                   |         |              |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position          | Description<br>Drawing # / Task #                                                                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB WI-73-1019-CN<br>E1         | SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) |      |         | SUPERSEDED                    |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1019-CN<br>E2         | SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022) |      |         | SUPERSEDED                    |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1019<br>E1            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)                 |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1019<br>E2            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)                 |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1022<br>E1            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |      |         | NOT APPLICABLE                |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1022<br>E2            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |      |         | NOT APPLICABLE                |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027 R01<br>-CN<br>E1 | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027 R01<br>-CN<br>E2 | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027 R01<br>E1        | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027 R01<br>E2        | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027<br>E1            | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1027<br>E2            | ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE                                                                                    |      |         | MANDATORY                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1031<br>E1            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SB WI-73-1031<br>E2            | ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01                                              |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-73-1018-CN<br>E1         | CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG                                                               |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-73-1018-CN<br>E2         | CANCELED - ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG                                                               |      |         | CANCELLED                     |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |
| SL WI-73-1018<br>E1            | ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG                                                                          |      |         |                               |                          |                | -              |                |                            |                    |
|                                | <b>MOC :</b>                                                                                                                             |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                              | Description<br>Drawing # / Task #                                                     | City | Part Number<br>Mod Lvl Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|--------------------------------------------------------------------|---------------------------------------------------------------------------------------|------|---------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SL WI-73-1018<br>E2                                                | ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG                       |      |                                       |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SL WI-73-1026<br>E1                                                | ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL |      |                                       |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SL WI-73-1026<br>E2                                                | ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL |      |                                       |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SL WI-73-1037<br>E1                                                | ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL                         |      |                                       |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SL WI-73-1037<br>E2                                                | ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL                         |      |                                       |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-74-1000<br>E1                                                | IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT                           | KIWA | MANDATORY                             | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147 |                | -              |                |                            | Complete           |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-74-1000<br>E2                                                | IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT                           | KIWA | MANDATORY                             | MTH 09-Jan-2018<br>HRS 1472.2<br>LDG 1147 |                | -              |                |                            | Complete           |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br>E1 |                                                                                       |      | RECOMMENDED                           |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br>E2 |                                                                                       |      | RECOMMENDED                           |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br>E1 |                                                                                       | UNK  | RECOMMENDED                           | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE<br>E2 |                                                                                       | UNK  | RECOMMENDED                           | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |                | -              |                |                            | Complete           |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001<br>E1                                                | AIR - I.P. BLEED VALVE LEVER PIN - REPLACE                                            |      | RECOMMENDED                           |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB WI-75-1001<br>E2                                                | AIR - I.P. BLEED VALVE LEVER PIN - REPLACE                                            |      | RECOMMENDED                           |                                           |                | -              |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB 525A-76-03                                                      | ENGINE CONTROLS - REMOVAL OF TRIM BOX WIRING                                          |      | OPTIONAL                              |                                           |                | A/R            |                |                            |                    |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |
| SB 525A-76-04                                                      | ENGINE CONTROLS - FADEC CONNECTOR WASHER REMOVAL                                      |      | RECOMMENDED                           | MTH 21-Jan-2011<br>HRS 471.43<br>LDG 422  |                | A/R            |                |                            | Complete           |
|                                                                    | <b>MOC :</b>                                                                          |      |                                       |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                                         | Description                                                                                                                          | Part Number | C/W Time 1  | Adj.                                      | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |         |
|---------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------|-------------------------------------------|------------|--------|-------------|---------|-------------|---------|
| Position                                                                                          | Drawing # / Task #                                                                                                                   | City        | Mod Lvl     | Part Serial No                            | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains |
| SL WI-76-1001-CN<br>E1                                                                            | CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL<br>CANCELLED |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SL WI-76-1001-CN<br>E2                                                                            | CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL<br>CANCELLED |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SL WI-76-1001<br>E1                                                                               | ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                         |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SL WI-76-1001<br>E2                                                                               | ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL                         |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-009<br>R01<br>E1                                                                       | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)<br>RECOMMENDED                         |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-009<br>R01<br>E2                                                                       | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY SB FJ44-77-011 R18)<br>RECOMMENDED                         |             |             |                                           |            |        |             |         |             |         |
| MOC :                                                                                             |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-010<br>E1                                                                              | ENGINE INDICATING - AIRFRAME FADEC ENGINE HARNESS ASSEMBLIES - REWORK OR REPLACE                                                     | SMF         | RECOMMENDED | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |            | -      |             |         | N/A         |         |
| MOC : NOT APPLICABLE - SB FJ44-77-010 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-010<br>E2                                                                              | ENGINE INDICATING - AIRFRAME FADEC ENGINE HARNESS ASSEMBLIES - REWORK OR REPLACE                                                     | SMF         | RECOMMENDED | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |            | -      |             |         | N/A         |         |
| MOC : NOT APPLICABLE - SB FJ44-77-010 HAS BEEN CANCELLED BY WILLIAMS, NO FURTHER ACTION REQUIRED. |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-011<br>R02<br>E1                                                                       | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R03)<br>RECOMMENDED                        |             |             |                                           |            | -      |             |         | N/A         |         |
| MOC : NOT APPLICABLE - SUPERSEDED PER REVISION 3                                                  |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-011<br>R02<br>E2                                                                       | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R03)<br>RECOMMENDED                        |             |             |                                           |            | -      |             |         | N/A         |         |
| MOC : NOT APPLICABLE - SUPERSEDED PER REVISION 3                                                  |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-011<br>R03<br>E1                                                                       | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R04)<br>RECOMMENDED                        |             |             |                                           |            | -      |             |         |             |         |
| MOC : - SUPERSEDED BY REVISION 4                                                                  |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-011<br>R03<br>E2                                                                       | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R04)<br>RECOMMENDED                        |             |             |                                           |            | -      |             |         |             |         |
| MOC : - SUPERSEDED BY REVISION 4                                                                  |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |
| SB FJ44-77-011<br>R04<br>E1                                                                       | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R05)<br>MANDATORY                          |             |             |                                           |            | A/R    |             |         |             |         |
| MOC : - SUPERSEDED BY REVISION 5.                                                                 |                                                                                                                                      |             |             |                                           |            |        |             |         |             |         |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                    | Description<br>Drawing # / Task #                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------|------------------------------------------------------------------------------------------------|------|---------|-------------------------------|------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-77-011<br>R04<br>E2              | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R05) |      |         | MANDATORY                     |                                          |                | A/R            |                |                            |                    |
| <b>MOC :</b> - SUPERSEDED BY REVISION 5. |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R05<br>E1              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R06) |      |         | MANDATORY                     | MTH 21-Jan-2011<br>HRS 545.13<br>LDG 466 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH               |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R05<br>E2              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R06) |      |         | MANDATORY                     | MTH 21-Jan-2011<br>HRS 545.13<br>LDG 466 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH               |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R06<br>E1              | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R07) | LOWW |         | MANDATORY                     | MTH 19-Jan-2011<br>HRS 545.13<br>LDG 465 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - IAW THE SB  |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R06<br>E2              | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R07) | LOWW |         | MANDATORY                     | MTH 19-Jan-2011<br>HRS 545.13<br>LDG 465 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - IAW THE SB  |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R07<br>E1              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R08) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R07<br>E2              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R08) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R08<br>E1              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R09) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R08<br>E2              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R09) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R09<br>E1              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R10) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R09<br>E2              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R10) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R10<br>E1              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R11) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |
| SB FJ44-77-011<br>R10<br>E2              | ENGINE INDICATING & FADEC ENGINE HARNESS ASSEMBLY & INSPECTION (SUPERSEDED BY FJ44-77-011 R11) |      |         | MANDATORY                     |                                          |                | -              |                |                            |                    |
| <b>MOC :</b>                             |                                                                                                |      |         |                               |                                          |                |                |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                                                                                          | Description<br>Drawing # / Task #                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-77-011<br>R11<br>E1                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R12) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R11<br>E2                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R12) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R12<br>E1                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R13) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R12<br>E2                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R13) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R13<br>E1                                                                                                                                                                    | FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R14)                     |      |         | MANDATORY                     | MTH                                     |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R13<br>E2                                                                                                                                                                    | FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R14)                     |      |         | MANDATORY                     | MTH                                     |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R14<br>E1                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R15) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R14<br>E2                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R15) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R15<br>E1                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R16) | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>HRS 1205<br>LDG 1025 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - FJ44-77-011 R15 NO. 1 ENGINE - ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION, SERVICE BULLETIN HAS BEEN PREVIOUSLY COMPLIED WITH ON 19-JAN-2011. |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R15<br>E2                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R16) | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>HRS 1205<br>LDG 1025 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - FJ44-77-011 R15 NO. 2 ENGINE - ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION, SERVICE BULLETIN HAS BEEN PREVIOUSLY COMPLIED WITH ON 19-JAN-2011. |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R16<br>E1                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |
| SB FJ44-77-011<br>R16<br>E2                                                                                                                                                                    | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17) |      |         | MANDATORY                     |                                         |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                   |                                                                                                |      |         |                               |                                         |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                                                                                                                                               | Description                                                                                    | Part Number | C/W Time 1  | Adj.                                      | TBO 1      | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------|-------------|-------------------------------------------|------------|--------|-------------|---------|-------------|----------|
| Position                                                                                                                                                | Drawing # / Task #                                                                             | City        | Mod Lvl     | Part Serial No                            | C/W Time 2 | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB FJ44-77-011<br>R17<br>E1                                                                                                                             | ENGINE INDICATING – FADEC ENGINE HARNESS ASSEMBLY – INSPECTION (SUPERSEDED BY FJ44-77-011 R18) | SMF         | MANDATORY   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-77-011 R15 WAS PREVIOUSLY COMPLIED WITH ON 2/1/16, ENGINE IS NOT AFFECTED BY R17 OF THIS SB. NO FURTHER ACTION REQUIRED. |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-011<br>R17<br>E2                                                                                                                             | ENGINE INDICATING – FADEC ENGINE HARNESS ASSEMBLY – INSPECTION (SUPERSEDED BY FJ44-77-011 R18) | SMF         | MANDATORY   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |            | -      |             |         |             | N/A      |
| MOC : NOT APPLICABLE - SB FJ44-77-011 R15 WAS PREVIOUSLY COMPLIED WITH ON 2/1/16, ENGINE IS NOT AFFECTED BY R17 OF THIS SB. NO FURTHER ACTION REQUIRED. |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-011<br>R18<br>E1                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION                                 | UNK         | MANDATORY   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699   |            | -      |             |         |             | Complete |
| MOC : COMPLIED WITH                                                                                                                                     |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-011<br>R18<br>E2                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION                                 | UNK         | MANDATORY   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699   |            | -      |             |         |             | Complete |
| MOC : COMPLIED WITH                                                                                                                                     |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R01<br>E1                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R01<br>E2                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R02)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R02<br>E1                                                                                                                             | FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)                         |             | RECOMMENDED | MTH                                       |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R02<br>E2                                                                                                                             | FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R03)                         |             | RECOMMENDED | MTH                                       |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R03<br>E1                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R04)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R03<br>E2                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R04)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R04<br>E1                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |
| SB FJ44-77-013<br>R04<br>E2                                                                                                                             | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R05)     |             | RECOMMENDED |                                           |            | -      |             |         |             |          |
| MOC :                                                                                                                                                   |                                                                                                |             |             |                                           |            |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code                   | Description                                                                                | Part Number | C/W Time 1 | Adj.           | TBO 1                                     | TSO 1  | (ENG) DUE 1 | Remains |             |          |
|-----------------------------|--------------------------------------------------------------------------------------------|-------------|------------|----------------|-------------------------------------------|--------|-------------|---------|-------------|----------|
| Position                    | Drawing # / Task #                                                                         | City        | Mod Lvl    | Part Serial No | C/W Time 2                                | + or - | TBO 2       | TSO 2   | (ENG) DUE 2 | Remains  |
| SB FJ44-77-013<br>R05<br>E1 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06) |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R05<br>E2 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R06) |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R06<br>E1 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07) |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R06<br>E2 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK (SUPERSEDED BY FJ44-77-013 R07) |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R07<br>E1 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                 |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R07<br>E2 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                 |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R09<br>E1 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                 | UNK         |            | RECOMMENDED    | MTH 22-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
|                             | MOC : COMPLIED WITH                                                                        |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>R09<br>E2 | ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK                                 | UNK         |            | RECOMMENDED    | MTH 17-Jun-2021<br>HRS 2105.1<br>LDG 1697 |        | -           |         |             | Complete |
|                             | MOC : COMPLIED WITH                                                                        |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>E1        | FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)                    |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-77-013<br>E2        | FADEC ENGINE HARNESS ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-77-013 R01)                    |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-79-009<br>R01<br>E1 | ADJUST - LUBRICATION - OIL PRESSURE RELIEF VALVE (SUPERSEDED BY FJ44-79-009 R02)           |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-79-009<br>R01<br>E2 | ADJUST - LUBRICATION - OIL PRESSURE RELIEF VALVE (SUPERSEDED BY FJ44-79-009 R02)           |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-79-009<br>R02<br>E1 | ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)                      |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |
| SB FJ44-79-009<br>R02<br>E2 | ADJUST-LUBRICATION-OIL PRESSURE VALVE (SUPERSEDED BY FJ44-79-009 R03)                      |             |            |                |                                           |        |             |         |             |          |
|                             |                                                                                            |             |            | RECOMMENDED    |                                           | -      |             |         |             |          |
|                             | MOC :                                                                                      |             |            |                |                                           |        |             |         |             |          |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|----------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-79-009<br>R03<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R04) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R03<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R04) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R04<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R05) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R04<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R05) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R05<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R05<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R06) |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R06<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R07) |      |         | RECOMMENDED MTH               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R06<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R07) |      |         | RECOMMENDED MTH               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R07<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R08) |      |         | RECOMMENDED MTH               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R07<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST (SUPERSEDED BY FJ44-79-009 R08) |      |         | RECOMMENDED MTH               |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R08<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                 |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R08<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                 |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R09<br>E1 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                 |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |
| SB FJ44-79-009<br>R09<br>E2 | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                 |      |         | RECOMMENDED                   |                          |                | -              |                |                            |                    |
|                             | <b>MOC :</b>                                                                     |      |         |                               |                          |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position            | Description<br>Drawing # / Task #                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------|-----------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| SB FJ44-79-011<br>R01<br>E1      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R01<br>E2      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R02<br>E1      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R02<br>E2      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R03<br>E1      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R03<br>E2      | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R04<br>E1      | MAGNETIC SELF-CLOSING VALVE - REPLACE                                 |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R04<br>E2      | MAGNETIC SELF-CLOSING VALVE - REPLACE                                 |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R05<br>E1      | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                           |      |         |                               |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R05<br>E2      | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                           | UNK  |         |                               | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PCW</b> |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R06<br>E1      | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                           |      |         | MANDATORY                     | MTH<br>HRS                              |                | MPI<br>MPI<br>MPI |                | (4000)4073.7               | 1438.8             |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>R06<br>E2      | OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE                           |      |         | MANDATORY                     | MTH<br>HRS                              |                | MPI<br>MPI<br>MPI |                | (4000)4073.7               | 1438.8             |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>E1             | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-011<br>E2             | MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01) |      |         | MANDATORY                     |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-012<br>R01<br>E1      | OIL - LUBE OIL COOLER - REWORK OR REPLACE                             |      |         | RECOMMENDED                   | MTH<br>HRS                              |                | DUE<br>DUE<br>DUE |                | (4000)4073.7               | 1438.8             |
| <b>MOC :</b>                     |                                                                       |      |         |                               |                                         |                |                   |                |                            |                    |

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position       | Description<br>Drawing # / Task #                                                                                                   | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                | Adj.<br>+ or - | TBO 1<br>TBO 2    | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-----------------------------------------|----------------|-------------------|----------------|----------------------------|--------------------|
| SB FJ44-79-012<br>R01<br>E2 | OIL - LUBE OIL COOLER - REWORK OR REPLACE                                                                                           |      |         | MTH<br>RECOMMENDED<br>HRS     |                                         |                | DUE<br>DUE<br>DUE |                | (4000)4073.7               | 1438.8             |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-012<br>E1        | LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)                                                                 |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-012<br>E2        | LUBE OIL COOLER - REWORK OR REPLACE (SUPERSEDED BY FJ44-79-012 R01)                                                                 |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R01<br>E1 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)                                                             |      |         | OPTIONAL                      |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R01<br>E2 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02)                                                             |      |         | OPTIONAL                      |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R02<br>E1 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)                                                             |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R02<br>E2 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03)                                                             |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R03<br>E1 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)                                                             |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R03<br>E2 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04)                                                             |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R05<br>E1 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE                                                                                             | UNK  |         | RECOMMENDED                   | MTH 22-Jun-2021<br>HRS 2105<br>LDG 1699 |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>R05<br>E2 | OIL - OIL FILLER CAP ASSEMBLY - REPLACE                                                                                             | UNK  |         | RECOMMENDED                   | MTH 17-Jun-2021<br>HRS 2105<br>LDG 1699 |                | -                 |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>  |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>E1        | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)                                                             |      |         | OPTIONAL                      |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-013<br>E2        | OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)                                                             |      |         | OPTIONAL                      |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-015<br>E1        | CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP) |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |
| SB FJ44-79-015<br>E2        | CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP) |      |         | RECOMMENDED                   |                                         |                | -                 |                |                            |                    |
| <b>MOC :</b>                |                                                                                                                                     |      |         |                               |                                         |                |                   |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Service Bulletins

| Item Code<br>Position                                                                                                     | Description<br>Drawing # / Task #                                                                                                              | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| SB FJ44-79-016<br>R02<br>E1                                                                                               | OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R03)                                                                          |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-016<br>R02<br>E2                                                                                               | OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R03)                                                                          |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-016<br>R04<br>E1                                                                                               | OIL - RELIEF VALVE ASSEMBLY - REPLACE                                                                                                          | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-79-016 R04 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-016<br>R04<br>E2                                                                                               | OIL - RELIEF VALVE ASSEMBLY - REPLACE                                                                                                          | SMF  |         | RECOMMENDED                   | MTH 11-May-2018<br>HRS 1505.9<br>LDG 1163 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - SB FJ44-79-016 R04 (AND ALL PREVIOUS REVISIONS) ARE NOT APPLICABLE BY ENGINE SERIAL NUMBER. |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-016<br>E1                                                                                                      | OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R01)                                                                          |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-016<br>E2                                                                                                      | OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R01)                                                                          |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-T017<br>R01<br>E1                                                                                              | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                                                                               |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SB FJ44-79-T017<br>R01<br>E2                                                                                              | LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST                                                                                               |      |         | RECOMMENDED                   |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-01 R03                                                                                                          | MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS                                                                                          |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-02 R01                                                                                                          | MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-03 R02                                                                                                          | MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)                                                                                |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |
| SL CIL-99-04 R01                                                                                                          | MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW                                                                                        |      |         | CANCELLED                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                              |                                                                                                                                                |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                           | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                                                                                                        | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1998-25-10<br>R01<br><i>25AD-01 : 525R1</i> | APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY LOCKING MECHANISM NOT ENGAGING PROPERLY<br><b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | A/R            |                |                            | N/A                |
| FAA 1999-08-21<br>35AD-01 : 525                 | APPLIANCE AD - PURITAN-BENNETT AERO SYSTEMS CO.<br><b>MOC : NOT APPLICABLE - NOT APPLICABLE BY DATE OF MANUFACTURE</b>                                                                                                                                                                                                                                                   | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | A/R            |                |                            | N/A                |
| FAA 2001-23-17<br>34AD-03                       | APPLIANCE AD - GARMIN GNS 430<br><b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                                                                                                                    | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | A/R            |                |                            | N/A                |
| FAA 2004-08-15<br>34AD-02                       | TAWS 8000 TERRAIN AWARENESS<br><b>MOC : NOT APPLICABLE - N/A PER MOD OR SOFTWARE LEVEL</b>                                                                                                                                                                                                                                                                               | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | A/R            |                |                            | N/A                |
| FAA 2006-16-18<br>34AD-12 : 525                 | SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI)<br><b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                                    | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | A/R            |                |                            | N/A                |
| FAA 2015-10-02<br>PARA (G)                      | GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2<br><b>MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-02 DATED 6/12/15 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH ZODIAC PASSENGER SEATS. AD IS NOT APPLICABLE PER PARAGRAPH (C).</b> | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| FAA 2015-10-02<br>PARA (H)                      | CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK<br><b>MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-02 DATED 6/12/15 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH ZODIAC PASSENGER SEATS. AD IS NOT APPLICABLE PER PARAGRAPH (C).</b>                                                                                                                       | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| FAA 2015-10-02<br>PARA (I)                      | REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS<br><b>MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-02 DATED 6/12/15 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH ZODIAC PASSENGER SEATS. AD IS NOT APPLICABLE PER PARAGRAPH (C).</b>                            | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| FAA 2015-10-02                                  | EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT<br><b>MOC : NOT APPLICABLE - COMPLIED WITH AD2015-10-02 DATED 6/12/15 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH ZODIAC PASSENGER SEATS. AD IS NOT APPLICABLE PER PARAGRAPH (C).</b>                                                                                                     | SMF  |         | MANDATORY                     | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| FAA 2017-16-01<br>PARA (G)                      | PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS<br><b>MOC : NOT APPLICABLE - N/A EQUIPMENT NOT INSTALLED</b>                                                                                                                    | KEUG |         |                               | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226 |                | -              |                |                            | N/A                |
| FAA 2017-16-01<br>PARA (J)                      | OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT<br><b>MOC : NOT APPLICABLE - N/A EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                                                                                | KEUG |         | MANDATORY                     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226 |                | -              |                |                            | N/A                |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                 | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                                                                     | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2017-16-01                                                                                                                                                                                                                                        | EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS                                                                                                                                                          | KEUG |         | MANDATORY                     | MTH 16-Nov-2018<br>HRS 1523.3<br>LDG 1226 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - N/A EQUIPMENT NOT INSTALLED                                                                                                                                                                                             |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(1)                                                                                                                                                                                                                         | INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE                                                                                                                                                                                                                      | KCRQ |         | MANDATORY                     | MTH 08-Nov-2021<br>HRS 2226.3<br>LDG 1767 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH CAMP FAA 2021-07-13 PARA (E)(1), PERFORMED VISUAL INSPECTION OF PILOT & COPILOT BUCKLE HANDLE VANE, NO CRACKS WERE FOUND. IN ACCORDANCE WITH FAA 2021-07-13 PARA(E)(1) & PACIFIC SCIENTIFIC SB 25-1111432. |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(2)                                                                                                                                                                                                                         | MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE                                                                                                                                                 | KCRQ |         | MANDATORY                     | MTH 16-May-2022<br>HRS 2367.2<br>LDG 1844 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD 2021-07-13 SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE INSPECTION DOES NOT APPLY, PART NOT INSTALLED.                                                                                                         |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13<br>PARA (E)(3)                                                                                                                                                                                                                         | DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER                                                                                                                                                                             |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2021-07-13                                                                                                                                                                                                                                        | EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT                                                                                                                                                                                                                                |      |         | MANDATORY                     |                                           |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2019-08-13                                                                                                                                                                                                                                        | FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETTS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06) | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2019-08-13 DATED 5/24/19 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETTS. AD IS NOT APPLICABLE PER PARAGRAPH (C).                       |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2020-24-06                                                                                                                                                                                                                                        | FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT                                                                                                                                                                                             | SMF  |         | MANDATORY                     | MTH 11-Dec-2020<br>HRS 1923<br>LDG 1596   |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2020-24-06 DATED 12/28/20 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETTS. AD IS NOT APPLICABLE PER PARAGRAPH (C).                      |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2021-23-12                                                                                                                                                                                                                                        | INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS                                                                                                                                                                                                                               | KCRQ |         | MANDATORY                     | MTH 06-Jan-2022<br>HRS 2281.9<br>LDG 1795 |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLY WITH APPLIANCE AD 2021-23-12 RADAR ALTIMETER AFM REVISION TO INCORPORATE LIMITATIONS.                                                                                                                             |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |
| AD 34-01                                                                                                                                                                                                                                              | ALLIEDSIGNAL GNS-XLS & GNS-XL<br>*CF                                                                                                                                                                                                                                                                                                  |      |         |                               | MTH 05-Nov-2008                           |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                                                                       |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Description<br>Drawing # / Task #                                                                                                                                                                          | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 1998-25-02<br>34AD-02 : 525                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | NAVIGATION - BFGOODRICH SKYWATCH SKY497 - INCORPORATE INFORMATION INTO THE AFM THAT SPECIFIES VERIFYING CORRECT ANTENNA CONFIGURATION EACH TIME AIRCRAFT EQUIPPED WITH A TOP-MOUNTED ANTENNA IS POWERED-UP | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2002-20-09<br>31AD-01                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | NAVIGATION - COLLINS AFD-3010 AFD UNITS - INSPECT AND MODIFY CERTAIN AFD-3010 AFD UNITS                                                                                                                    | *CF  |         | MANDATORY                     | MTH 05-Nov-2008                           |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2014-05-27                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION                                                                                                         |      |         | MANDATORY                     | MTH 06-May-2014<br>HRS 901<br>LDG 854     |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - SUBJECT EQUIPMENT NOT INSTALLED</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2014-18-01                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION                                                                                                                        | AMS  |         | MANDATORY                     | MTH 07-Oct-2014<br>HRS 921<br>LDG 878     |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH EASA 2010-0003R1</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2015-10-51-E                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.                                                                                  | KIWA |         | MANDATORY                     | MTH 16-Nov-2015<br>HRS 1061<br>LDG 946    |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2015-10-51 BY VERIFYING THAT THE EQUIPMENT CALLED OUT IN THE AD IS NOT INSTALLED ON THE AIRCRAFT. AD EFFECTIVE DATE IS 5/18/2015.</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2015-10-51                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS                                                                    | KIWA |         | MANDATORY                     | MTH 16-Nov-2015<br>HRS 1061<br>LDG 946    |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2015-10-51 BY VERIFYING THAT THE EQUIPMENT CALLED OUT IN THE AD IS NOT INSTALLED ON THE AIRCRAFT. AD EFFECTIVE DATE IS 5/18/2015.</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2020-10-05                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS                                                                                                                         | KCRQ |         | MANDATORY                     | MTH 26-Aug-2021<br>HRS 2178.8<br>LDG 1734 |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH ROCKWELL COLLINS AIRWORTHINESS DIRECTIVE 2020-10-05 AND CESSNA MODEL 525A SERVICE LETTER SL525A-34-16 DISABLE AUTOMATIC TEMPERATURE COMPENSATION ON PRO LINE 4 AND PRO LINE 21 SYSTEMS AIRCRAFT AND IMPLEMENT AIRPLANE FLIGHT MANUAL CHANGES FOR LNAV/VNAV REFERENCING ROCKWELL COLLINS OPERATIONAL SERVICE BULLETIN 0166-17, SERVICE INFORMATION LETTER FMC--XX00-18-1, AND SERVICE INFORMATION LETTER CSU-XX00-18-1 PROCEDURES. TESTED SYSTEM FOR PROPER OPERATION IN ACCORDANCE WITH CESSNA MODEL 525A MAINTENANCE MANUAL SECTION 34-60 WITH NO DEFECTS NOTED. REVISED THE AIRPLANE FLIGHT MANUAL LIMITATIONS BY ADDING THE INFORMATION FROM SIL FMC-XX00-18-1 SECTION C.(2) AIRCRAFT FLIGHT MANUAL RECOMMENDATION AS DIRECTED IN AD 2020-10-05 SECTION (H) INSTRUCTIONS.</b> |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |
| FAA 2011-14-08                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY                                                                                                                                                             | EDDV |         | MANDATORY                     | MTH 10-Aug-2012<br>HRS 755<br>LDG 685     |                | A/R            |                |                            | Complete           |
| <b>MOC : COMPLIED WITH</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                                                                                                                                                                            |      |         |                               |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                                                                                                                                                          | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                      | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2015-08-07<br>PARA (G)                                                                                                                                                                                                                                                                                                                                                                     | INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011 |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | MOT  |         | MANDATORY                     | MTH 15-Jun-2017<br>HRS 1346.1<br>LDG 1078<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER</b>                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-08-07<br>PARA (H)                                                                                                                                                                                                                                                                                                                                                                     | REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES                                                                                                                                                                                         |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | MOT  |         | MANDATORY                     | MTH 15-Jun-2017<br>HRS 1346.1<br>LDG 1078<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER</b>                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-08-07                                                                                                                                                                                                                                                                                                                                                                                 | OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES                                                                                                                           |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | MOT  |         | MANDATORY                     | MTH 15-Jun-2017<br>HRS 1346.1<br>LDG 1078<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER</b>                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (G)                                                                                                                                                                                                                                                                                                                                                                     | INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER                                                                                                                                                                                            |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>DAYS 1131.3<br>HRS 985<br>LDG       |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH FAA 2015-23-09 PARA (G) OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926.</b>                                                                                           |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (H.1)                                                                                                                                                                                                                                                                                                                                                                   | REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).                                                                                                                                                                              |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>DAYS 1131.3<br>HRS 985<br>LDG       |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH FAA 2015-23-09 PARA (H)(1) OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926. NO REPLACEMENT NECESSARY DUE TO PART NUMBER AND SERIAL NUMBER OF UNITS INSTALLED.</b>      |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (H.2.I)                                                                                                                                                                                                                                                                                                                                                                 | REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1                                                                                                                                                            |      |         |                               |                                                        |                |                |                |                            |                    |
|                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                        | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>DAYS 1131.3<br>HRS 985<br>LDG       |                | -              |                |                            | Complete           |
| <b>MOC : COMPLIED WITH - COMPLIED WITH FAA 2015-23-09 PARA (H)(2)(I) OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926. NO FURTHER ACTION REQUIRED DUE TO PART NUMBER AND SERIAL NUMBER OF UNITS INSTALLED.</b> |                                                                                                                                                                                                                                                                                        |      |         |                               |                                                        |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                                                                                                                                                                                          | Description<br>Drawing # / Task #                                                                                                                                                                                                 | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2                               | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|---------|-------------------------------|--------------------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2015-23-09<br>PARA (H.2.II)                                                                                                                                                                                                                                                                                                                                                                | FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."                                                                                                    | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>DAYS 1131.3<br>HRS 985<br>LDG       |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH FAA 2015-23-09 (H)(2)(II) OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926. NO FURTHER ACTION IS NECESSARY DUE TO PART NUMBER AND SERIAL NUMBER OF UNITS INSTALLED. |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-23-09<br>PARA (I)                                                                                                                                                                                                                                                                                                                                                                     | REGULATOR REPLACEMENT                                                                                                                                                                                                             | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>HRS 1131.3<br>LDG 985               |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - COMPLIED WITH FAA 2015-23-09 PARA (I) OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS. PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926. NO FURTHER ACTION REQUIRED DUE TO PART NUMBER AND SERIAL NUMBER OF UNITS INSTALLED.       |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2015-23-09                                                                                                                                                                                                                                                                                                                                                                                 | OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS                                                                   | KFFZ |         | MANDATORY                     | MTH 01-Feb-2016<br>HRS 1131.3<br>LDG 985               |                | -              |                |                            | Complete           |
| <b>MOC :</b> COMPLIED WITH - FAA 2015-23-09 OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION/REPLACEMENT OF OXYGEN MASK REGULATORS.PILOT PN MC10-16-101, SN 117122. COPILOT PN MC10-16-101, SN 87926.                                                                                                                   |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2016-11-20<br>PARA (G)                                                                                                                                                                                                                                                                                                                                                                     | PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12 | KFFZ |         | MANDATORY                     | MTH 18-Oct-2016<br>HRS 1243.2<br>LDG 1037<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - VERIFIED BY VISUAL INSPECTION, AD 2016-11-20 NOT APPLICABLE BY NO PBE'S INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2016-11-20<br>PARA (H.1)                                                                                                                                                                                                                                                                                                                                                                   | REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12                                                                    | KFFZ |         | MANDATORY                     | MTH 18-Oct-2016<br>HRS 1243.2<br>LDG 1037<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - VERIFIED BY VISUAL INSPECTION, AD 2016-11-20 NOT APPLICABLE BY NO PBE'S INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2016-11-20<br>PARA (H.2)                                                                                                                                                                                                                                                                                                                                                                   | REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12                                                                             | KFFZ |         | MANDATORY                     | MTH 18-Oct-2016<br>HRS 1243.2<br>LDG 1037<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - VERIFIED BY VISUAL INSPECTION, AD 2016-11-20 NOT APPLICABLE BY NO PBE'S INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |
| FAA 2016-11-20                                                                                                                                                                                                                                                                                                                                                                                 | OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. (SUPERSEDED BY FAA AD 2017-18-12)                                               | KFFZ |         | MANDATORY                     | MTH 18-Oct-2016<br>HRS 1243.2<br>LDG 1037<br>ACH 210.6 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - VERIFIED BY VISUAL INSPECTION, AD 2016-11-20 NOT APPLICABLE BY NO PBE'S INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                   |      |         |                               |                                                        |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Airworthiness Directives

| Item Code<br>Position                                                                                                                                                                                                     | Description<br>Drawing # / Task #                                                                                                                                                                                                                                                                     | City | Part Number<br>Mod Lvl<br>Part Serial No | C/W Time 1<br>C/W Time 2                  | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------------------------------------|-------------------------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| FAA 2017-18-12<br>PARA (G)                                                                                                                                                                                                | INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                                                                                               | SMF  | MANDATORY                                | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2017-18-12 DATED 10/16/17 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE). AD IS NOT APPLICABLE PER PARAGRAPH (C). |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (H)                                                                                                                                                                                                | REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED                                                                                                                                                                                                              | SMF  | MANDATORY                                | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2017-18-12 DATED 10/16/17 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE). AD IS NOT APPLICABLE PER PARAGRAPH (C). |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2017-18-12<br>PARA (I) & (J)                                                                                                                                                                                          | INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.                                                                                              | SMF  | MANDATORY                                | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2017-18-12 DATED 10/16/17 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE). AD IS NOT APPLICABLE PER PARAGRAPH (C). |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2017-18-12                                                                                                                                                                                                            | OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES                                                                                                                                        | SMF  | MANDATORY                                | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | -              |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2017-18-12 DATED 10/16/17 BY INSPECTION OF AIRCRAFT, VERIFIED NOT EQUIPPED WITH B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE). AD IS NOT APPLICABLE PER PARAGRAPH (C). |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2008-03-10<br>53AD-01                                                                                                                                                                                                 | INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE |      | AIRWORTHINESS                            | MTH 30-Dec-2009<br>HRS 219                |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE BY AIRCRAFT MODEL SERIAL AND/OR UNIT NUMBER.                                                                                                                                 |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2010-12-01                                                                                                                                                                                                            | DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS, AND CRACKS IN THRUST ATTENUATOR PADDLES                                                                                                                                                                                                               | SMF  | MANDATORY                                | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD2010-12-01 DATED 7/22/10, FOUND THIS AD IS ONLY APPLICABLE TO AIRCRAFT SERIAL NUMBERS 0001 THROUGH 0244. AD IS NOT APPLICABLE PER PARAGRAPH (C).                            |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2022-13-15<br>E1                                                                                                                                                                                                      | TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE                                                                                                                                                                                                                                          |      | MANDATORY                                | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                              |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2022-13-15<br>E2                                                                                                                                                                                                      | TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE                                                                                                                                                                                                                                          |      | MANDATORY                                | MTH                                       |                | -              |                |                            |                    |
| <b>MOC :</b>                                                                                                                                                                                                              |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |
| FAA 2009-24-13<br>78AD-01                                                                                                                                                                                                 | DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS AND CRACKS IN THE THRUST ATTENUATOR PADDLES - SUPERSEDED BY AD 2010-12-01                                                                                                                                                                              | SMF  | SUPERSEDED                               | MTH 11-May-2018<br>HRS 1432.2<br>LDG 1123 |                | A/R            |                |                            | N/A                |
| <b>MOC :</b> NOT APPLICABLE - AD2009-24-13 HAS BEEN SUPERSEDED BY AD2010-12-01, NO FURTHER ACTION REQUIRED.                                                                                                               |                                                                                                                                                                                                                                                                                                       |      |                                          |                                           |                |                |                |                            |                    |



## CESCOM 10 - Aircraft Status Report

Owner: **JET AMG SERVICES**  
Aircraft Model: **525A - CJ2**  
Aircraft Serial: **525A-0428**  
Unit: **0428** Reg No: **N711RC**  
Airworthiness: **05-Nov-2008**  
Print Date: **04-Jan-2024 11:58AM**

| Tracking Rate   | Hours         | Events/<br>Landings | Last Actual<br>Date | Average Daily<br>Utilization |
|-----------------|---------------|---------------------|---------------------|------------------------------|
| <b>AIRCRAFT</b> | <b>2634.9</b> | <b>2008</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 1</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>ENG 2</b>    | <b>2561.2</b> | <b>1968</b>         | <b>30-Nov-2023</b>  | <b>.28</b>                   |
| <b>AIR COND</b> | <b>790</b>    |                     | <b>30-Nov-2023</b>  | <b>.1</b>                    |

### Factory Installed

| Item Code<br>Position            | Description<br>Drawing # / Task #                                    | City | Mod Lvl | Part Number<br>Part Serial No | C/W Time 1<br>C/W Time 2 | Adj.<br>+ or - | TBO 1<br>TBO 2 | TSO 1<br>TSO 2 | (ENG) DUE 1<br>(ENG) DUE 2 | Remains<br>Remains |
|----------------------------------|----------------------------------------------------------------------|------|---------|-------------------------------|--------------------------|----------------|----------------|----------------|----------------------------|--------------------|
| 00FO900                          | RPLC STD ENTRY DOOR STEPS W/ BRAVO/ENCORE STYLE STEPS FACTORY OPTION | *CF  |         | 900<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 23FO634 CJ2+<br>23FO634 : CJ2+   | RECORDER-COCKPIT VOICE LORAL/FAIRCHILD A200S FACTORY OPTION          | *CF  |         | 634K<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 23FO655                          | ELECTRONIC CHARTS - JEPPESEN FACTORY OPTION                          | *CF  |         | 655<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 23FO675G                         | ST-3100 AIRCELL TELEPHONE W/ INTERCOM FACTORY OPTION                 | *CF  |         | 675G<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 25FO120R                         | DUAL AFT DIVIDERS W/ SLIDING DOORS FACTORY OPTION                    | *CF  |         | 120R<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 25FO121U CJ2+<br>25FO121U : CJ2+ | RH FWD SIDE FACING SEAT (EXCHANGE) FACTORY OPTION                    | *CF  |         | 121U<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 25FO501 CJ2+<br>25FO501 : CJ2+   | MOBIL JET II FACTORY OPTION                                          | *CF  |         | 501<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 25FO999                          | W/A INTERIOR CONFIGURATION FACTORY OPTION                            | *CF  |         | 999<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 27FO-16C<br>27FO-16 : C          | STEEP APPROACH OPTION FACTORY OPTION                                 | *CF  |         | 16C<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 28FO-36 CJ2+<br>28FO-36 : CJ2+   | FUEL CAPS-LOCKING (EXCHANGE) FACTORY OPTION                          | *CF  |         | 36<br>FO                      | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 31FO650                          | ANNUNCIATOR-VOICE FACTORY OPTION                                     | *CF  |         | 650<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO011A<br>34FO011 : A          | INDEXER-AOA FACTORY OPTION                                           | *CF  |         | 11A<br>FO                     | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO635N                         | TTR-4000 TCAS 11-COLLINS FACTORY OPTION                              | *CF  |         | 635N<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO658C                         | SINGLE ADF-COLLINS FACTORY OPTION                                    | *CF  |         | 658C<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO673B<br>34FO673 : B          | GROUND COMM DISPATCH SWITCH FACTORY OPTION                           | *CF  |         | 673B<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO686S                         | SECOND FMS-3000 COLLINS FACTORY OPTION                               | *CF  |         | 686S<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |
| 34FO691B<br>34FO691 : B          | EGPWS-AMERICAN DATA BASE FACTORY OPTION                              | *CF  |         | 691B<br>FO                    | MTH 05-Nov-2008          |                | -              |                |                            |                    |