

Master AD/SI Report

525B - CJ3 S/N 525B-0098 N87VM

ENC

as of

OWNER: SWIFT PROPERTIES L.L.C. **ADDRESS:** 7352 AUTOPARK DRIVE

HUNTINGTON BEACH CA 92648

OPERATOR: SWIFT PROPERTIES L.L.C.
ADDRESS: 7352 AUTOPARK DRIVE

HUNTINGTON BEACH CA 92648

PHONE: FAX:

EMAIL:

PHONE: FAX:

ENC

ANALYST: CJ03 ANALYST

KDUMCUM@CAMPSYSTEMS.COM

1-316-462-2483 (DIRECT) 1-866-581-2267 (OFFICE) WWW.CAMPSYSTEMS.COM 800-787-9749 (EFAX-CARDS) 631-980-4222 (EFAX-CARDS)

as of 24-OCT-2023

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO

CAMP.

Filter Criteria: Task Type In: ('SB','SBP'); Group by Profile or Bulletin: Bulletin Type; Mode: With Compliance or Next Due; Print Only Due Items: CHECKED; For: Airframe, Engine, APU Etc;

AIRCRAFT SERIAL/REGNO: 525B-0098/N87VM MODEL: 525B - CJ3 MANUFACTURER: TEXTRON AVIATION INC.

ENGINE NO. 1 SERIAL/PART: 141203/67000-200 MODEL: FJ44-3A/-3A-24 **MANUFACTURER: WILLIAMS INTERNATIONAL** LAST ACTUALS **CURRENT ACTUAL INSTALLED ON 04-AUG-2006** 1 ENG. HRS 1 A/C HRS 2435.8 ENG. HRS as of 24-OCT-2023 ENG. HRS as of **ENC** 2054 ENC ENC as of 24-OCT-2023 as of

2054 ENC



Master AD/SI Report

525B - CJ3 S/N 525B-0098 (N87VM): 2435.8HRS, 2054 AFL as of 24-Oct-2023

AIRCRAFT SI with Compliance or Due Report Date: 05-Dec-2023

Tas	sk No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
BUL	LETIN TYPE -	SB						
SB	FJ44-79-011 R06	NO. 1 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN					MANDATORY	
	06-AUG-2021		MOS HRS/MSC ENC	-	(EFF)	4000 M		
SB	FJ44-79-011 R06	NO. 2 ENGINE - OIL - MAGNETIC S	SELF-CLOSIN	IG VALVE - REPLACE	E, SERVICE BULLETIN		MANDATORY	
	06-AUG-2021		MOS HRS/MSC ENC	-	(EFF)	4000 M		
SB	WISB-72-1034 R04	NO. 1 ENGINE - HP TURBINE - RE		SSEMBLY AND DISK,	SERVICE BULLETIN		MANDATORY	
	19-APR-2023		MOS HRS/MSC ENC	8000		8742 M		
SB	WISB-72-1034 R04	NO. 2 ENGINE - HP TURBINE - RE		SSEMBLY AND DISK,	SERVICE BULLETIN		MANDATORY	
	19-APR-2023		MOS HRS/MSC ENC	8000		8528 M		
SB	WISB-73-1009 R04	NO. 1 ENGINE - ENGINE FUEL AN	D CONTROL	- FUEL TUBE ASSEM	BLIES - REPLACE, SERVIO	CE BULLETIN	RECOMMENDED	
	05-AUG-2019		MOS HRS/MSC ENC	CSI	(EFF)	4000 M		
SB	WISB-73-1009 R04	NO. 2 ENGINE - ENGINE FUEL AN		- FUEL TUBE ASSEM		CE BULLETIN	RECOMMENDED	
	05-AUG-2019		MOS HRS/MSC ENC	CSI	(EFF)	4000 M		
SB	WISB-75-1001 R02	NO. 1 ENGINE - AIR - I.P. BLEED \	ALVE LEVER	R PIN - REPLACE, SEF	RVICE BULLETIN		RECOMMENDED	
	20-MAY-2021		MOS HRS/MSC ENC	-	(EFF)	4000 M		
SB	WISB-75-1001 R02	NO. 2 ENGINE - AIR - I.P. BLEED \	ALVE LEVER	R PIN - REPLACE, SEF	RVICE BULLETIN		RECOMMENDED	
	20-MAY-2021		MOS HRS/MSC ENC	-	(EFF)	4000 M		