



Status Report

SUPER KING AIR B200 S/N BB-1645 N777HF

|                                                                                                              |                                               |                                                                                                                 |                                                                                             |
|--------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|
| <b>OWNER: PARR AVIATION LLC</b><br>ADDRESS: PO BOX 140<br>DEMOPOLIS AL 36732<br>OFFICE: 334-287-1006<br>FAX: |                                               | <b>OPERATOR: PARR AVIATION LLC</b><br>ADDRESS: PO BOX 140<br>DEMOPOLIS AL 36732<br>OFFICE: 334-287-1006<br>FAX: |                                                                                             |
| ANALYST: MATT PHONGVILAI                                                                                     | 316-462-2416 (DIRECT)                         | 800-787-9749 (EFAX-CARDS)                                                                                       | PLEASE REACH OUT TO YOUR ANALYST TO<br>RECORD CHANGES TO ADDRESS, LAST ACTUALS<br>(IF ANY). |
| EMAIL: MPHONGVILAI@CAMPSYSTEMS.COM                                                                           | +1-631-588-3200 (MAIN)<br>WWW.CAMPSYSTEMS.COM | 631-980-4222 (EFAX-CARDS)                                                                                       |                                                                                             |

**FILTER CRITERIA :** Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

| AIRCRAFT                        | SERIAL/REGNO: BB-1645/N777HF   | MODEL: SUPER KING AIR B200     | MANUFACTURER: TEXTRON AVIATION INC.        |                 |
|---------------------------------|--------------------------------|--------------------------------|--------------------------------------------|-----------------|
| CERTIFICATION DATE: 29-DEC-1998 |                                |                                |                                            |                 |
| ENGINE NO. 1                    | SERIAL/PART: PCE-94718/3030700 | MODEL: PT6A-42                 | MANUFACTURER: PRATT & WHITNEY CANADA CORP. |                 |
|                                 | INSTALLED ON: 13-FEB-2019      |                                | LAST ACTUALS:                              |                 |
|                                 | 3688.3<br>3688                 | ENG. HRS 0 A/C HRS<br>ENC      | 4291.1<br>4184                             | ENG. HRS<br>ENC |
| ENGINE NO. 2                    | SERIAL/PART: PCE-94709/3030700 | MODEL: PT6A-42                 | MANUFACTURER: PRATT & WHITNEY CANADA CORP. |                 |
|                                 | INSTALLED ON: 13-FEB-2019      |                                | LAST ACTUALS:                              |                 |
|                                 | 3688.3<br>3688                 | ENG. HRS 0 A/C HRS<br>ENC      | 4291.1<br>4184                             | ENG. HRS<br>ENC |
| PROPELLER NO. 1                 | SERIAL/PART: HH561/HC-E4N-3G   | MODEL: HC-E4N-3G               | MANUFACTURER: HARTZELL PROPELLER INC.      |                 |
|                                 | INSTALLED ON: 14-DEC-2005      |                                | LAST ACTUALS:                              |                 |
|                                 | 1743<br>0                      | PROP HRS 1919.1 A/C HRS<br>PRC | 5158.2                                     | PROP HRS        |
| PROPELLER NO. 2                 | SERIAL/PART: HH3625/HC-E4N-3G  | MODEL: HC-E4N-3G               | MANUFACTURER: HARTZELL PROPELLER INC.      |                 |
|                                 | INSTALLED ON: 10-FEB-2012      |                                | LAST ACTUALS:                              |                 |
|                                 | 2770.7<br>0                    | PROP HRS 0 A/C HRS<br>PRC      | 5158.2                                     | PROP HRS        |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining           | Disposition              |
|----------------------|---------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------|--------------------------|
| ATA 00 - INFORMATION |                                                                                       |           |          |          |                           |           |                     |                          |
| 000010 <sup>U</sup>  | AIRCRAFT PAINT                                                                        |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | 25-Jun-20 | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   | 5172.4    |          |          |                           |           |                     |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |                     |                          |
| 000015 <sup>U</sup>  | AIRCRAFT INTERIOR                                                                     |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | 29-Dec-98 | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   | 0         |          |          |                           |           |                     |                          |
|                      | AFL                                                                                   | 0         |          |          |                           |           |                     |                          |
| BC50-160501A         | REVIEW SUPER KING AIR 200 SERIES AMM REV. D3                                          |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   |           |          |          |                           |           |                     | REQUIREMENT CHANGE FORMS |
|                      | AFL                                                                                   |           |          |          |                           |           |                     |                          |
|                      |                                                                                       |           |          |          |                           |           | PROC. REF: RCF BC50 |                          |
| BC50-160501B         | REVIEW BEECHCRAFT CORPORATION STRUCTURAL INSPECTION AND REPAIR MANUAL (SIRM) REV. C11 |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   |           |          |          |                           |           |                     | REQUIREMENT CHANGE FORMS |
|                      | AFL                                                                                   |           |          |          |                           |           |                     |                          |
|                      |                                                                                       |           |          |          |                           |           | PROC. REF: RCF BC50 |                          |
| BC50-161101          | REVIEW SUPER KING AIR 200 SERIES AMM REV. D4                                          |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   |           |          |          |                           |           |                     | REQUIREMENT CHANGE FORMS |
|                      | AFL                                                                                   |           |          |          |                           |           |                     |                          |
|                      |                                                                                       |           |          |          |                           |           | PROC. REF: RCF BC50 |                          |
| BC50-170201          | REVIEW SUPER KING AIR 200 SERIES AMM REV. D5                                          |           |          |          |                           |           |                     |                          |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |                     | Service    ATA:00        |
|                      | HRS                                                                                   |           |          |          |                           |           |                     | REQUIREMENT CHANGE FORMS |
|                      | AFL                                                                                   |           |          |          |                           |           |                     |                          |
|                      |                                                                                       |           |          |          |                           |           | PROC. REF: RCF BC50 |                          |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                                                  | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                                   |
|----------------------|---------------------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|-----------------------------------------------|
| ATA 00 - INFORMATION |                                                                                       |     |          |          |                           |           |           |                                               |
| BC50-170201A         | REVIEW BEECHCRAFT CORPORATION STRUCTURAL INSPECTION AND REPAIR MANUAL (SIRM) REV. C12 |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | AFL                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF BC50  |                                                                                       |     |          |          |                           |           |           |                                               |
| E015-160720          | NO. 1 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 51.1                                  |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF E015  |                                                                                       |     |          |          |                           |           |           |                                               |
| E015-160720          | NO. 2 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 51.1                                  |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF E015  |                                                                                       |     |          |          |                           |           |           |                                               |
| E015-160722          | NO. 1 ENGINE - REVIEW PT6A-38/1/42/42A EMM REV 51.2                                   |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF E015  |                                                                                       |     |          |          |                           |           |           |                                               |
| E015-160722          | NO. 2 ENGINE - REVIEW PT6A-38/1/42/42A EMM REV 51.2                                   |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF E015  |                                                                                       |     |          |          |                           |           |           |                                               |
| E015-170710          | NO. 1 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 53.0                                  |     |          |          |                           |           |           |                                               |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE<br>FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                                               |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                                               |
| PROC. REF: RCF E015  |                                                                                       |     |          |          |                           |           |           |                                               |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                                        | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|----------------------|-----------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |                                                                             |     |          |          |                           |           |           |                          |
| E015-170710          | NO. 2 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 53.0                        |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | ENC                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF E015       |           |           |                          |
| P005-160801          | NO. 1 PROPELLER - REVIEW HC-E4N-3G SL REV 10 REVISION SUMMARY CHANGE FORM   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |
| P005-160801          | NO. 2 PROPELLER - REVIEW HC-E4N-3G SL REV 10 REVISION SUMMARY CHANGE FORM   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |
| P005-171001          | NO. 1 PROPELLER - REVIEW HARTZELL HC-E4N-3G POM 149 REV 23                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |
| P005-171001          | NO. 2 PROPELLER - REVIEW HARTZELL HC-E4N-3G POM 149 REV 23                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |
| P005-210201          | NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35 |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |
| P005-210201          | NO. 2 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35 |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      |                                                                             |     |          |          | PROC. REF: RCF P005       |           |           |                          |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                 | Unit                                               | C/W       | Interval      | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-----------------------------------------|----------------------------------------------------|-----------|---------------|-------------------------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                    |           |               |                         |                           |           |           |                |
| 050001U                                 | RENEWAL OF AIRCRAFT REGISTRATION                   |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 24-Mar-22 | 36 (-6m)      |                         | 31-Jul-25 (M)             |           | 381 d     | Service ATA:05 |
|                                         | HRS                                                | 5331.5    |               |                         |                           |           |           |                |
|                                         | AFL                                                | 6250      |               |                         |                           |           |           |                |
| 050010                                  | ACCOMPLISH PHASE 1 INSPECTION                      |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 22-May-24 | 24            |                         | 22-May-26                 |           | 676 d     | Service ATA:05 |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |                         | 6486.2                    | 6506.2    | 800 (+20) |                |
|                                         | AFL                                                | 6495      |               | PROC. REF: AMM 05-20-01 |                           |           |           |                |
| 050010R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 1 INSPECTION |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 22-May-24 | 24            |                         | 22-May-26                 |           | 676 d     | Service ATA:05 |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |                         | 6486.2                    | 6506.2    | 800 (+20) |                |
|                                         | AFL                                                | 6495      |               | PROC. REF: ICA 05-20-00 |                           |           |           |                |
| 050020                                  | ACCOMPLISH PHASE 2 INSPECTION                      |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 22-May-24 | 24            |                         | 22-May-26                 |           | 676 d     | Service ATA:05 |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |                         | 6486.2                    | 6506.2    | 800 (+20) |                |
|                                         | AFL                                                | 6495      |               | PROC. REF: AMM 05-20-02 |                           |           |           |                |
| 050020R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 2 INSPECTION |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 22-May-24 | 24            |                         | 22-May-26                 |           | 676 d     | Service ATA:05 |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |                         | 6486.2                    | 6506.2    | 800 (+20) |                |
|                                         | AFL                                                | 6495      |               | PROC. REF: ICA 05-20-00 |                           |           |           |                |
| 050030                                  | ACCOMPLISH PHASE 3 INSPECTION                      |           |               |                         |                           |           |           |                |
|                                         | MOS                                                | 12-Apr-23 | 24            |                         | 12-Apr-25                 |           | 271 d     | Service ATA:05 |
|                                         | HRS                                                | 5500.3    | 800 (+20/-20) |                         | 5886.2 (M)                | 5906.2    | 200 (+20) |                |
|                                         | AFL                                                | 6358      |               | PROC. REF: AMM 05-20-03 |                           |           |           |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                           | Unit                                               | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|---------------------------------------------------|----------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                                                    |           |               |          |                           |           |             |                |
| 050030R                                           | ACCOMPLISH RAISBECK ENGINEERING PHASE 3 INSPECTION |           |               |          |                           |           |             |                |
|                                                   | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 271 d       | Service ATA:05 |
|                                                   | HRS                                                | 5500.3    | 800 (+20/-20) |          | 6300.3                    | 6320.3    | 614.1 (+20) |                |
|                                                   | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                           |                                                    |           |               |          |                           |           |             |                |
| 050040                                            | ACCOMPLISH PHASE 4 INSPECTION                      |           |               |          |                           |           |             |                |
|                                                   | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 271 d       | Service ATA:05 |
|                                                   | HRS                                                | 5500.3    | 800 (+20/-20) |          | 5886.2 (M)                | 5906.2    | 200 (+20)   |                |
|                                                   | AFL                                                | 6358      |               |          |                           |           |             |                |
| WC#: 05.040 PROC. REF: AMM 05-20-04               |                                                    |           |               |          |                           |           |             |                |
| 050040R                                           | ACCOMPLISH RAISBECK ENGINEERING PHASE 4 INSPECTION |           |               |          |                           |           |             |                |
|                                                   | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 271 d       | Service ATA:05 |
|                                                   | HRS                                                | 5500.3    | 800 (+20/-20) |          | 6300.3                    | 6320.3    | 614.1 (+20) |                |
|                                                   | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                           |                                                    |           |               |          |                           |           |             |                |
| 050060                                            | INITIAL LEFT ENGINE 100 HOUR INSPECTION            |           |               |          |                           |           |             |                |
|                                                   | MOS/MSC                                            | 29-Dec-98 | -             |          |                           |           |             | Service ATA:05 |
|                                                   | HRS                                                | 0         |               |          |                           |           |             |                |
|                                                   | AFL                                                | 0         |               |          |                           |           |             |                |
| PROC. REF: GENERIC NO REF                         |                                                    |           |               |          |                           |           |             |                |
| 050070                                            | INITIAL RIGHT ENGINE 100 HOUR INSPECTION           |           |               |          |                           |           |             |                |
|                                                   | MOS/MSC                                            | 29-Dec-98 | -             |          |                           |           |             | Service ATA:05 |
|                                                   | HRS                                                | 0         |               |          |                           |           |             |                |
|                                                   | AFL                                                | 0         |               |          |                           |           |             |                |
| PROC. REF: GENERIC NO REF                         |                                                    |           |               |          |                           |           |             |                |
| 052900                                            | ACCOMPLISH CONTINUOUS CORROSION CONTROL INSPECTION |           |               |          |                           |           |             |                |
|                                                   | MOS/MSC                                            | 29-Dec-98 | A/R           |          |                           |           |             | Service ATA:05 |
|                                                   | HRS                                                | 0         |               |          |                           |           |             |                |
|                                                   | AFL                                                | 0         |               |          |                           |           |             |                |
| WC#: 05.060 PROC. REF: AMM 05-29-00, AMM 05-29-00 |                                                    |           |               |          |                           |           |             |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                                 | Unit                                                | C/W       | Interval      | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-----------------------------------------|-----------------------------------------------------|-----------|---------------|-------------------------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                     |           |               |                         |                           |           |           |                |
| 057010                                  | NO. 1 ENGINE - MINOR                                |           |               |                         |                           |           |           |                |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |           | Package ATA:05 |
|                                         | HRS                                                 | 4291.1    | 200 (+20/-20) |                         | (4491.1)<br>5886.2        | 4511.1    | 200 (+20) |                |
|                                         | ENC                                                 | 4184      |               |                         |                           |           |           |                |
|                                         |                                                     |           |               | PROC. REF: EMM 72-00-00 |                           |           |           | PKG:1          |
| 057010                                  | NO. 2 ENGINE - MINOR                                |           |               |                         |                           |           |           |                |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |           | Package ATA:05 |
|                                         | HRS                                                 | 4291.1    | 200 (+20/-20) |                         | (4491.1)<br>5886.2        | 4511.1    | 200 (+20) |                |
|                                         | ENC                                                 | 4184      |               |                         |                           |           |           |                |
|                                         |                                                     |           |               | PROC. REF: EMM 72-00-00 |                           |           |           | PKG:1          |
| ATA 08 - LEVELING AND WEIGHING          |                                                     |           |               |                         |                           |           |           |                |
| 080005 <sup>U</sup>                     | PERFORM WEIGHT AND BALANCE OF AIRCRAFT              |           |               |                         |                           |           |           |                |
|                                         | MOS/MSC                                             | 22-Oct-19 | O/C           |                         |                           |           |           | Service ATA:08 |
|                                         | HRS                                                 | 5128      |               |                         |                           |           |           |                |
|                                         | AFL                                                 |           |               |                         |                           |           |           |                |
| ATA 12 - SERVICING                      |                                                     |           |               |                         |                           |           |           |                |
| 122020                                  | LUBRICATION 200 HOUR                                |           |               |                         |                           |           |           |                |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |           | Service ATA:12 |
|                                         | HRS                                                 | 5686.2    | 200           |                         | 5886.2                    |           | 200       |                |
|                                         | WC#: 12.020                                         | AFL       | 6495          |                         |                           |           |           |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |           |                |
| 122040                                  | LUBRICATION 400 HOUR                                |           |               |                         |                           |           |           |                |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |           | Service ATA:12 |
|                                         | HRS                                                 | 5686.2    | 400           |                         | 6086.2                    |           | 400       |                |
|                                         | WC#: 12.030                                         | AFL       | 6495          |                         |                           |           |           |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |           |                |
| 122060                                  | LUBRICATION OF DOWNLOCK HOOKS AND PIN CONTACT AREAS |           |               |                         |                           |           |           |                |
|                                         | MOS                                                 | 12-Apr-23 | 24            |                         | 12-Apr-25                 |           | 271 d     | Service ATA:12 |
|                                         | HRS                                                 | 5500.3    | 800           |                         | 6300.3                    |           | 614.1     |                |
|                                         | WC#: 12.040                                         | AFL       | 6358          |                         |                           |           |           |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |           |                |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN            | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition       |
|--------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------------|
| ATA 12 - SERVICING |                                        |           |          |          |                           |           |           |                   |
| 122065             | LUBRICATION 800 HOUR                   |           |          |          |                           |           |           |                   |
|                    | MOS                                    | 12-Apr-23 |          |          |                           |           |           | Service    ATA:12 |
|                    | HRS                                    | 5500.3    | 800      |          | 6300.3                    |           | 614.1     |                   |
| WC#: 12.060        | AFL                                    | 6358      |          |          |                           |           |           |                   |
|                    | PROC. REF: AMM 12-20-53                |           |          |          |                           |           |           |                   |
|                    |                                        |           |          |          |                           |           |           |                   |
| 122070             | LUBRICATION 1200 HOUR                  |           |          |          |                           |           |           |                   |
|                    | MOS                                    | 12-Apr-23 |          |          |                           |           |           | Service    ATA:12 |
|                    | HRS                                    | 5500.3    | 1200     |          | 6700.3                    |           | 1014.1    |                   |
| WC#: 12.050        | AFL                                    | 6358      |          |          |                           |           |           |                   |
|                    | PROC. REF: AMM 12-20-53                |           |          |          |                           |           |           |                   |
|                    |                                        |           |          |          |                           |           |           |                   |
| 122120             | LUBRICATION - 12 MONTH LEFT WING BOLT  |           |          |          |                           |           |           |                   |
|                    | MOS                                    | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service    ATA:12 |
|                    | HRS                                    | 5686.2    |          |          |                           |           |           |                   |
| WC#: 12.090        | AFL                                    | 6495      |          |          |                           |           |           |                   |
|                    | PROC. REF: AMM 12-20-53                |           |          |          |                           |           |           |                   |
|                    |                                        |           |          |          |                           |           |           |                   |
| 122620             | LUBRICATION - 12 MONTH RIGHT WING BOLT |           |          |          |                           |           |           |                   |
|                    | MOS                                    | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service    ATA:12 |
|                    | HRS                                    | 5686.2    |          |          |                           |           |           |                   |
| WC#: 12.090        | AFL                                    | 6495      |          |          |                           |           |           |                   |
|                    | PROC. REF: AMM 12-20-53                |           |          |          |                           |           |           |                   |
|                    |                                        |           |          |          |                           |           |           |                   |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                | Unit                                                                                                                                    | C/W              | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit   | Remaining   | Disposition      |
|----------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|------------------|----------------|----------|---------------------------|-------------|-------------|------------------|
| ATA 20 - STANDARD PRACTICES - AIRFRAME |                                                                                                                                         |                  |                |          |                           |             |             |                  |
| 200005                                 | INSPECT PILOT'S FUEL CONTROL PANEL AND LOWER PANEL, COPILOT'S CIRCUIT BREAKER PANEL AND OTHER WIRING CIRCUITRY BELOW THE STORM WINDOWS. |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 22-May-24        | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25   | 311 d (+12) | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5686.2           |                |          |                           |             |             |                  |
| WC#: 33.090                            |                                                                                                                                         |                  |                |          |                           |             |             |                  |
|                                        | AFL                                                                                                                                     | 6495             |                |          |                           |             |             |                  |
| 200010                                 | VISUALLY INSPECT COCKPIT AND CABIN FUSELAGE SKINS AND STRUCTURE (WITH INTERIOR REMOVED).                                                |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 07-Feb-20        |                |          |                           |             |             | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5159.2           |                |          |                           |             |             |                  |
| AFL                                    | 6110                                                                                                                                    | 2500 (+10%/-10%) |                | 8610     | 8860                      | 2115 (+250) |             |                  |
| PROC. REF: AMM GENERIC 1               |                                                                                                                                         |                  |                |          |                           |             |             |                  |
| 200020                                 | VISUALLY INSPECT THE ENVIRONMENTAL DUCTING                                                                                              |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 13-Feb-19        |                |          |                           |             |             | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5082.9           |                |          |                           |             |             |                  |
| AFL                                    | 6044                                                                                                                                    | 2500 (+10%/-10%) |                | 8544     | 8794                      | 2049 (+250) |             |                  |
| 200030                                 | VISUALLY INSPECT THE ELECTRICAL WIRING                                                                                                  |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 13-Feb-19        |                |          |                           |             |             | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5082.9           |                |          |                           |             |             |                  |
| AFL                                    | 6044                                                                                                                                    | 2500 (+10%/-10%) |                | 8544     | 8794                      | 2049 (+250) |             |                  |
| 200040                                 | VISUALLY INSPECT PLUMBING                                                                                                               |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 13-Feb-19        |                |          |                           |             |             | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5082.9           |                |          |                           |             |             |                  |
| AFL                                    | 6044                                                                                                                                    | 2500 (+10%/-10%) |                | 8544     | 8794                      | 2049 (+250) |             |                  |
| 200050                                 | VISUALLY INSPECT OXYGEN SYSTEM COMPONENTS AND PLUMBING FOR DAMAGE AND SECURITY OF ATTACHMENT.                                           |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 13-Feb-19        |                |          |                           |             |             | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5082.9           |                |          |                           |             |             |                  |
| AFL                                    | 6044                                                                                                                                    | 2500 (+10%/-10%) |                | 8544     | 8794                      | 2049 (+250) |             |                  |
| 201400                                 | INSPECT CONTROL LOCK                                                                                                                    |                  |                |          |                           |             |             |                  |
|                                        | MOS                                                                                                                                     | 22-May-24        | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25   | 311 d (+12) | Service ATA:20   |
|                                        | HRS                                                                                                                                     | 5686.2           |                |          |                           |             |             |                  |
| AFL                                    | 6495                                                                                                                                    |                  |                |          |                           |             |             |                  |
| ATA 21 - AIR CONDITIONING              |                                                                                                                                         |                  |                |          |                           |             |             |                  |
| 210101                                 | LEFT FLOW (PNEUMATIC) CONTROL UNIT                                                                                                      |                  |                |          |                           |             |             |                  |
|                                        | PN:101-380013-1                                                                                                                         | MOS/MSC          | 29-Dec-98      | O/C      |                           |             |             | Component ATA:21 |
|                                        |                                                                                                                                         |                  |                |          |                           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 21 - AIR CONDITIONING |                                  |           |          |          |                           |           |           |                     |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.010               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: AMM 21-10-01   |                                  |           |          |          |                           |           |           |                     |
| 210106                    | LEFT FLOW CONTROL PNEUMOSTAT     |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-380013-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                     |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.050               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                     |
| 210111                    | LEFT AMBIENT AIR SHUTOFF VALVE   |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-380018-1           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                     |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.030               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                     |
| 210116                    | LEFT AIR TO AIR HEAT EXCHANGER   |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-381010-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                     |
| SN:1950                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.060               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                     |
| 210121                    | LEFT BLEED AIR BY-PASS VALVE     |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-550087-23          | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                     |
| SN:6586                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.040               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: AMM 21-40-03   |                                  |           |          |          |                           |           |           |                     |
| 210136                    | LEFT FLOW CONTROL SOLENOID VALVE |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-380021-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                     |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.020               | AFL                              | 0         |          |          |                           |           |           |                     |
| PROC. REF: AMM 21-10-07   |                                  |           |          |          |                           |           |           |                     |
| 210137                    | FLAPPER VALVE                    |           |          |          |                           |           |           | Component    ATA:21 |
| PN:101-384173-17          | MOS/MSC                          | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                     |
| SN:3820                   | HRS                              | 5500.3    |          | TSN 0    |                           |           |           |                     |
| WC#: 21.210               | AFL                              | 6358      |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 21-20-01   |                                  |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 21 - AIR CONDITIONING |                                     |           |          |          |                           |           |           |                     |
| 210601                    | RIGHT FLOW (PNEUMATIC) CONTROL UNIT |           |          |          |                           |           |           |                     |
| PN:101-380025-11          | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:6AP76                  | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.010               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: AMM 21-10-01             |           |          |          |                           |           |           |                     |
| 210606                    | RIGHT FLOW CONTROL PNEUMOSTAT       |           |          |          |                           |           |           |                     |
| PN:101-380013-3           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.050               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: GENERIC NO REF           |           |          |          |                           |           |           |                     |
| 210611                    | RIGHT AMBIENT AIR SHUTOFF VALVE     |           |          |          |                           |           |           |                     |
| PN:101-380018-1           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.030               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: GENERIC NO REF           |           |          |          |                           |           |           |                     |
| 210616                    | RIGHT AIR TO AIR HEAT EXCHANGER     |           |          |          |                           |           |           |                     |
| PN:101-381010-1           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.060               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: GENERIC NO REF           |           |          |          |                           |           |           |                     |
| 210621                    | RIGHT BLEED AIR BY-PASS VALVE       |           |          |          |                           |           |           |                     |
| PN:101-550087-25          | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:6665                   | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.040               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: AMM 21-40-03             |           |          |          |                           |           |           |                     |
| 210636                    | RIGHT FLOW CONTROL SOLENOID VALVE   |           |          |          |                           |           |           |                     |
| PN:101-380021-3           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 21.020               | AFL                                 | 0         |          |          |                           |           |           |                     |
|                           | PROC. REF: AMM 21-10-07             |           |          |          |                           |           |           |                     |
| 211101                    | PRESSURIZATION CONTROLLER           |           |          |          |                           |           |           |                     |
| PN:130346-12              | MOS/MSC                             | 03-Oct-19 | O/C      |          |                           |           |           | Component    ATA:21 |
| SN:47-2770                | HRS                                 | 5116.1    |          | TSR 0    |                           |           |           |                     |
| WC#: 21.070               | AFL                                 |           |          | TSR 0    |                           |           |           |                     |
|                           | PROC. REF: AMM 21-30-09             |           |          |          |                           |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                 | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|------------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING |                                                      |           |                           |          |                           |           |             |                  |
| 211105                    | PERFORM CABIN ALTITUDE WARNING PRESSURE SWITCH CHECK |           |                           |          |                           |           |             |                  |
| PN:PN                     | MOS                                                  | 22-May-24 | 12 (+12d/-12d)            |          | 22-May-25                 | 03-Jun-25 | 311 d (+12) | Service ATA:21   |
| SN:UNKNOWN                | HRS                                                  | 5686.2    |                           |          |                           |           |             | MANDATORY        |
| WC#: 21.270               | AFL                                                  | 6495      |                           |          |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM 21-30-11   |          |                           |           |             |                  |
| 211111                    | CABIN PRESET SOLENOID                                |           |                           |          |                           |           |             |                  |
| PN:2297-00-9              | MOS/MSC                                              | 29-Dec-98 | O/C                       |          |                           |           |             | Component ATA:21 |
| SN:UNKNOWN                | HRS                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
| WC#: 21.080               | AFL                                                  | 0         |                           |          |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: GENERIC NO REF |          |                           |           |             |                  |
| 211668                    | CABIN ALTITUDE/DIFFERENTIAL PRESSURE INDICATOR       |           |                           |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                                              | 29-Dec-98 | O/C                       | TSN 0    |                           |           |             | Component ATA:21 |
| SN:UNKNOWN                | HRS                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
|                           | AFL                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM GENERIC 1  |          |                           |           |             |                  |
| 212000                    | PROBE ASSEMBLY, THERMISTOR REPLACE                   |           |                           |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                                              | 29-Dec-98 | O/C                       | TSN 0    |                           |           |             | Component ATA:21 |
| SN:UNKNOWN                | HRS                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
|                           | AFL                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM GENERIC 1  |          |                           |           |             |                  |
| 212101                    | AIR CONDITIONER COMPRESSOR                           |           |                           |          |                           |           |             |                  |
| PN:101-5552111-7          | MOS/MSC                                              | 15-Jul-22 | O/C                       | TSN 0    |                           |           |             | Component ATA:21 |
| SN:1128044                | HRS                                                  | 5350.1    |                           | TSN 0    |                           |           |             |                  |
| WC#: 21.100               | AFL                                                  | 6265      |                           | TSN 0    |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM 21-50-01   |          |                           |           |             |                  |
| 212106                    | AIR CONDITIONER COMPRESSOR BELT                      |           |                           |          |                           |           |             |                  |
| PN:115-389009             | MOS/MSC                                              | 29-Dec-98 | O/C                       |          |                           |           |             | Component ATA:21 |
| SN:UNKNOWN                | HRS                                                  | 0         |                           | TSN 0    |                           |           |             |                  |
| WC#: 21.110               | AFL                                                  | 0         |                           |          |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM 21-50-09   |          |                           |           |             |                  |
| 212111                    | ADJUST AIR CONDITIONER COMPRESSOR BELT TENSION       |           |                           |          |                           |           |             |                  |
|                           | MOS/MSC                                              | 22-May-24 | C/C                       |          |                           |           |             | Service ATA:21   |
|                           | HRS                                                  | 5686.2    |                           |          |                           |           |             |                  |
| WC#: 21.110               | AFL                                                  | 6495      |                           |          |                           |           |             |                  |
|                           |                                                      |           | PROC. REF: AMM 21-50-09   |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                         | Unit    | C/W       | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C             | Max Limit | Remaining | Disposition         |
|-------------------------------------------------|---------|-----------|----------|-----------------|---------------------------------------|-----------|-----------|---------------------|
| ATA 21 - AIR CONDITIONING                       |         |           |          |                 |                                       |           |           |                     |
| 212116      CONDENSOR COIL ASSEMBLY             |         |           |          |                 |                                       |           |           |                     |
| PN:115-384002-9                                 | MOS/MSC | 29-Dec-98 | O/C      |                 |                                       |           |           | Component    ATA:21 |
| SN:198-3167-36                                  | HRS     | 0         |          | TSN 0           |                                       |           |           |                     |
| WC#: 21.090                                     | AFL     | 0         |          |                 |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: GENERIC NO REF             |           |           |                     |
| 212121      CONDENSOR BLOWER MOTOR              |         |           |          |                 |                                       |           |           |                     |
| PN:EM640-1                                      | MOS/MSC | 31-Oct-05 | O/C      | TSO 0           |                                       |           |           | Component    ATA:21 |
| SN:978                                          | HRS     | 1904.8    |          |                 |                                       |           |           |                     |
| WC#: 21.090                                     | AFL     | 1720      |          |                 |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: AMM 21-50-13               |           |           |                     |
| 212136      HOT GAS BY-PASS VALVE               |         |           |          |                 |                                       |           |           |                     |
| PN:101-380019-1                                 | MOS/MSC | 29-Dec-98 | O/C      |                 |                                       |           |           | Component    ATA:21 |
| SN:3590                                         | HRS     | 0         |          | TSN 0           |                                       |           |           |                     |
| WC#: 21.120                                     | AFL     | 0         |          |                 |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: GENERIC NO REF             |           |           |                     |
| 212141      REFRIGERANT OVERPRESSURE SWITCH     |         |           |          |                 |                                       |           |           |                     |
| PN:101-380002-11                                | MOS/MSC | 05-Aug-20 | O/C      | TSN 0           |                                       |           |           | Component    ATA:21 |
| SN:1357                                         | HRS     | 5200      |          | TSN 0           |                                       |           |           |                     |
| WC#: 21.120                                     | AFL     | 6149      |          | TSN 0           |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: GENERIC NO REF             |           |           |                     |
| 212146      REFRIGERANT UNDER PRESSURE SWITCH   |         |           |          |                 |                                       |           |           |                     |
| PN:101-384081-5                                 | MOS/MSC | 07-Feb-20 | O/C      | TSO 4, TSR 0    |                                       |           |           | Component    ATA:21 |
| SN:5709                                         | HRS     | 5159.2    |          | TSO 31.2, TSR 0 |                                       |           |           |                     |
| WC#: 21.120                                     | AFL     | 6110      |          | TSR 0           |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: GENERIC NO REF             |           |           |                     |
| 212151      DRYER RECEIVER                      |         |           |          |                 |                                       |           |           |                     |
| PN:101-384079-1                                 | MOS/MSC | 15-Jul-22 | O/C      | TSN 0           |                                       |           |           | Component    ATA:21 |
| SN:N/A                                          | HRS     | 5350.1    |          | TSN 0           |                                       |           |           |                     |
| WC#: 21.130                                     | AFL     | 6265      |          | TSN 0           |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: AMM 21-50-15, AMM 21-51-17 |           |           |                     |
| 212161      EVAPORATOR FREEZE PROTECTION SWITCH |         |           |          |                 |                                       |           |           |                     |
| PN:20425197-840-759                             | MOS/MSC | 29-Dec-98 | O/C      |                 |                                       |           |           | Component    ATA:21 |
| SN:UNKNOWN                                      | HRS     | 0         |          | TSN 0           |                                       |           |           |                     |
| WC#: 21.130                                     | AFL     | 0         |          |                 |                                       |           |           |                     |
|                                                 |         |           |          |                 | PROC. REF: AMM 21-50-19               |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                         | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING                       |         |           |          |          |                           |           |           |                  |
| 212170 SOLENOID, PRESSURIZATION SAFETY VALVE    |         |           |          |          |                           |           |           |                  |
| PN:PN                                           | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                                      | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                 | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1                        |         |           |          |          |                           |           |           |                  |
| 212176 SAFETY VALVE                             |         |           |          |          |                           |           |           |                  |
| PN:103648-7                                     | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:48-J0495                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150                                     | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                       |         |           |          |          |                           |           |           |                  |
| 212178 AIR CONDITIONING BLOWER ASSEMBLY REPLACE |         |           |          |          |                           |           |           |                  |
| PN:PN                                           | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                                      | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                 | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1                        |         |           |          |          |                           |           |           |                  |
| 212186 OUTFLOW VALVE                            |         |           |          |          |                           |           |           |                  |
| PN:103648-7                                     | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:48-J0561                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150                                     | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                       |         |           |          |          |                           |           |           |                  |
| 212601 CABIN TEMPERATURE SENSOR                 |         |           |          |          |                           |           |           |                  |
| PN:101-364177-1                                 | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                                      | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.170                                     | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                       |         |           |          |          |                           |           |           |                  |
| 212602 DUCT TEMPERATURE SENSOR                  |         |           |          |          |                           |           |           |                  |
| PN:AYLF50304                                    | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                                      | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.170                                     | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                       |         |           |          |          |                           |           |           |                  |
| 212606 CABIN TEMPERATURE INDICATOR              |         |           |          |          |                           |           |           |                  |
| PN:50-380026-1                                  | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:5399                                         | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.180                                     | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                       |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                  |           |          |          |                           |           |           |                  |
| 212616                    | CABIN TEMPERATURE CONTROL BOX    |           |          |          |                           |           |           |                  |
| PN:HYZ50336-1             | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:5232K                  | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.180               | AFL                              | 0         |          |          |                           |           |           |                  |
|                           | PROC. REF: AMM 21-60-03          |           |          |          |                           |           |           |                  |
| 213005                    | DOOR SEAL VALVE                  |           |          |          |                           |           |           |                  |
| PN:101-380018-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:6907                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.240               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 213010                    | VENTURI TUBE                     |           |          |          |                           |           |           |                  |
| PN:50-380053-1            | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:3387                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.260               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 213101                    | CABIN RATE-OF-CLIMB INDICATOR    |           |          |          |                           |           |           |                  |
| PN:50-380045              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:352134                 | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.190               | AFL                              | 0         |          |          |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 214000                    | ENVIRONMENTAL CONTROLLER REPLACE |           |          |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: AMM GENERIC 1         |           |          |          |                           |           |           |                  |
| 214005                    | LEFT HEAT EXCHANGER              |           |          |          |                           |           |           |                  |
| PN:1263                   | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.250               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 214010                    | RIGHT HEAT EXCHANGER             |           |          |          |                           |           |           |                  |
| PN:1301                   | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.250               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                       |           |          |          |                           |           |           |                  |
| 215000                    | MOTOR, EVAPORATOR ASSEMBLY            |           |          |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: AMM GENERIC 1              |           |          |          |                           |           |           |                  |
| 215002                    | FORWARD BLOWER ASSEMBLY               |           |          |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: AMM 21-50-17               |           |          |          |                           |           |           |                  |
| 215004                    | AFT FORWARD BLOWER ASSEMBLY           |           |          |          |                           |           |           |                  |
| PN:101-384176-1           | MOS/MSC                               | 16-Jun-09 | O/C      | TSO 0    |                           |           |           | Component ATA:21 |
| SN:984                    | HRS                                   | 2410      |          | TSO 0    |                           |           |           |                  |
| WC#: 21.160               | AFL                                   | 2388      |          | TSO 0    |                           |           |           |                  |
|                           | PROC. REF: AMM 21-50-17               |           |          |          |                           |           |           |                  |
| 215006                    | AFT AFT BLOWER ASSEMBLY               |           |          |          |                           |           |           |                  |
| PN:101-384135-3           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:1889                   | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.160               | AFL                                   | 0         |          |          |                           |           |           |                  |
|                           | PROC. REF: AMM 21-50-21               |           |          |          |                           |           |           |                  |
| 215007                    | AIR CONDITIONER FORWARD COIL          |           |          |          |                           |           |           |                  |
| PN:101-384003-7           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:G98-2887-75            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.230               | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 215010                    | AIR CONDITIONER AFT COIL              |           |          |          |                           |           |           |                  |
| PN:101-384024-5           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:F98-2880-82            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.230               | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 215101                    | LEFT RADIANT HEAT ELEMENT             |           |          |          |                           |           |           |                  |
| PN:101-530488-3           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.200               | AFL                                   | 0         |          |          |                           |           |           |                  |
|                           | PROC. REF: AMM 21-40-05, AMM 21-40-07 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                               | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING             |                                       |           |          |          |                           |           |           |                  |
| 215106                                | RIGHT RADIANT HEAT ELEMENT            |           |          |          |                           |           |           |                  |
| PN:101-530488-3                       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.200                           | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-40-05, AMM 21-40-07 |                                       |           |          |          |                           |           |           |                  |
| 215135                                | CABIN DIFFERENTIAL PRESSURE INDICATOR |           |          |          |                           |           |           |                  |
| PN:101-380026-13                      | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:21 |
| SN:505221                             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.190                           | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                       |           |          |          |                           |           |           |                  |
| ATA 22 - AUTO FLIGHT                  |                                       |           |          |          |                           |           |           |                  |
| 220005                                | YAW RATE SENSOR                       |           |          |          |                           |           |           |                  |
| PN:270-0930-010                       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.130                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                       |           |          |          |                           |           |           |                  |
| 220101                                | AILERON SERVO                         |           |          |          |                           |           |           |                  |
| PN:792-6781-001                       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.010                           | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-07               |                                       |           |          |          |                           |           |           |                  |
| 220106                                | AILERON SERVO MOUNT                   |           |          |          |                           |           |           |                  |
| PN:792-6782-001                       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.010                           | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-07               |                                       |           |          |          |                           |           |           |                  |
| 220111                                | ELEVATOR SERVO                        |           |          |          |                           |           |           |                  |
| PN:PN-UNKNOWN                         | MOS/MSC                               | 31-May-23 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:6702                               | HRS                                   | 5538.1    |          |          |                           |           |           |                  |
| WC#: 22.020                           | AFL                                   |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-15               |                                       |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                     | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT        |         |           |          |          |                           |           |           |                  |
| 220116 ELEVATOR SERVO MOUNT |         |           |          |          |                           |           |           |                  |
| PN:622-5735-001             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:7929                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-15     |         |           |          |          |                           |           |           |                  |
| 220121 RUDDER SERVO         |         |           |          |          |                           |           |           |                  |
| PN:622-5734-002             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:10287                    | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.030                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-11     |         |           |          |          |                           |           |           |                  |
| 220126 RUDDER SERVO MOUNT   |         |           |          |          |                           |           |           |                  |
| PN:622-5735-002             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:8898                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.030                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-11     |         |           |          |          |                           |           |           |                  |
| 220131 ELEVATOR TRIM SERVO  |         |           |          |          |                           |           |           |                  |
| PN:622-5734-002             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:10389                    | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-17     |         |           |          |          |                           |           |           |                  |
| 220601 AUTOPILOT AMPLIFIER  |         |           |          |          |                           |           |           |                  |
| PN:522-2900-021             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |                  |
| 220606 YAW DAMPER COMPUTER  |         |           |          |          |                           |           |           |                  |
| PN:777-1406-021             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |                  |
| 220616 AUTOPILOT CONTROLLER |         |           |          |          |                           |           |           |                  |
| PN:792-6348-003             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.050                 | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------|--------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT |                                                              |           |          |          |                           |           |           |                  |
| 221005               | LEFT RUDDER SERVO                                            |           |          |          |                           |           |           |                  |
| PN:101-524973-1      | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:833177            | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.110          | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: AMM 22-11-11                                      |           |          |          |                           |           |           |                  |
| 221010               | RIGHT RUDDER SERVO                                           |           |          |          |                           |           |           |                  |
| PN:101-524973-1      | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:837190            | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.110          | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: AMM 22-11-11                                      |           |          |          |                           |           |           |                  |
| 221015               | ELEVATOR MOUNT TRIM SERVO                                    |           |          |          |                           |           |           |                  |
| PN:622-5735-002      | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:8872              | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.120          | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: AMM 22-11-17                                      |           |          |          |                           |           |           |                  |
| 221020               | AUTOPILOT AMPLIFIER                                          |           |          |          |                           |           |           |                  |
| PN:622-9724-130      | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:4049              | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.150          | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF                                    |           |          |          |                           |           |           |                  |
| 221040               | PERFORM AUTOPILOT DISCONNECT AURAL WARNING OPERATION CHECK   |           |          |          |                           |           |           |                  |
|                      | MOS/MSC                                                      | 29-Dec-98 | N/R      |          |                           |           |           | Service ATA:22   |
|                      | HRS                                                          | 0         |          |          |                           |           |           |                  |
|                      | AFL                                                          | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: AMM 22-11-21                                      |           |          |          |                           |           |           |                  |
| 221045               | PERFORM STALL WARNING - AUTOPILOT DISCONNECT OPERATION CHECK |           |          |          |                           |           |           |                  |
|                      | MOS/MSC                                                      | 29-Dec-98 | N/R      |          |                           |           |           | Service ATA:22   |
|                      | HRS                                                          | 0         |          |          |                           |           |           |                  |
|                      | AFL                                                          | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: AMM 22-11-23                                      |           |          |          |                           |           |           |                  |
| 221101               | MODE COUPLER                                                 |           |          |          |                           |           |           |                  |
| PN:792-6255-001      | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN           | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060          | AFL                                                          | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF                                    |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN              | Unit                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------|---------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT |                           |           |          |          |                           |           |           |                  |
| 221105               | AUTOPILOT CONTROL PANEL   |           |          |          |                           |           |           |                  |
| PN:622-6684-002      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:2791              | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.140          | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 221106               | MODE SELECTOR             |           |          |          |                           |           |           |                  |
| PN:622-0945-003      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN           | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060          | AFL                       | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 221111               | ALTITUDE CONTROLLER       |           |          |          |                           |           |           |                  |
| PN:522-4798-003      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN           | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060          | AFL                       | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 221115               | PRESELECTOR/ALERter       |           |          |          |                           |           |           |                  |
| PN:622-9462-024      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:4164              | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.050          | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 221116               | FLIGHT COMPUTER           |           |          |          |                           |           |           |                  |
| PN:792-6703-001      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN           | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.070          | AFL                       | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 221606               | ACCELERATION SENSOR       |           |          |          |                           |           |           |                  |
| PN:229-0324-010      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:4852              | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.080          | AFL                       | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |
| 222101               | AUTOPILOT VERTICAL GYRO   |           |          |          |                           |           |           |                  |
| PN:792-6694-001      | MOS/MSC                   | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:22 |
| SN:UNKNOWN           | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.090          | AFL                       | 0         |          |          |                           |           |           |                  |
|                      | PROC. REF: GENERIC NO REF |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                    | Unit    | C/W       | Interval | TSX/Adj.                                            | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------|---------|-----------|----------|-----------------------------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS                    |         |           |          |                                                     |                           |           |           |                  |
| 230005 VOICE RECORDER CONTROL              |         |           |          |                                                     |                           |           |           |                  |
| PN:93A151-30                               | MOS/MSC | 29-Dec-98 | O/C      |                                                     |                           |           |           | Component ATA:23 |
| SN:77608                                   | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.120                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 23-70-01                             |                           |           |           |                  |
| 230010 IMPACT SWITCH                       |         |           |          |                                                     |                           |           |           |                  |
| PN:28DCLIZ400                              | MOS/MSC | 29-Dec-98 | O/C      |                                                     |                           |           |           | Component ATA:23 |
| SN:5463                                    | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.130                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 23-70-07                             |                           |           |           |                  |
| 230015 NO. 1 IOC-3100 INPUT/OUTPUT         |         |           |          |                                                     |                           |           |           |                  |
| PN:PN                                      | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                               |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                                 | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.060                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 31-40-05                             |                           |           |           |                  |
| 230020 NO. 2 IOC-3100 INPUT/OUTPUT         |         |           |          |                                                     |                           |           |           |                  |
| PN:PN                                      | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                               |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                                 | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.060                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 31-40-05                             |                           |           |           |                  |
| 230025 FSU-5010 FILE SERVER UNIT           |         |           |          |                                                     |                           |           |           |                  |
| PN:PN                                      | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                               |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                                 | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.140                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 31-61-01                             |                           |           |           |                  |
| 230030 ECU-3000 EXTERNAL COMPENSATION UNIT |         |           |          |                                                     |                           |           |           |                  |
| PN:PN                                      | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                               |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                                 | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.150                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: AMM 31-63-07, AMM 34-21-03, AMM 31-61-03 |                           |           |           |                  |
| 230040 PILOT AUDIO SWITCH PANEL            |         |           |          |                                                     |                           |           |           |                  |
| PN:PN                                      | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                               |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                                 | HRS     | 0         |          | TSN 0                                               |                           |           |           |                  |
| WC#: 23.070                                | AFL     | 0         |          | TSN 0                                               |                           |           |           |                  |
|                                            |         |           |          | PROC. REF: GENERIC NO REF                           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                 | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS |                                   |           |          |          |                           |           |           |                  |
| 230045                  | COPILOT AUDIO SWITCH PANEL        |           |          |          |                           |           |           |                  |
| PN:PN                   | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:23 |
| SN:UNKNOWN              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.070             | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 230046 <sup>U</sup>     | GARMIN GMA 35C AUDIO PANEL        |           |          |          |                           |           |           |                  |
| PN:011-0229940          | MOS/MSC                           | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:23 |
| SN:1T6202994            | HRS                               | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                         | AFL                               | 6064      |          | TSN 0    |                           |           |           |                  |
| 230050                  | STATIC INVERTER                   |           |          |          |                           |           |           |                  |
| PN:PN                   | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:23 |
| SN:UNKNOWN              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.160             | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 230116                  | NO. 1 VHF COMM ANTENNA            |           |          |          |                           |           |           |                  |
| PN:90-384036            | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:23 |
| SN:6250                 | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.030             | AFL                               | 0         |          |          |                           |           |           |                  |
|                         | PROC. REF: AMM 23-10-03           |           |          |          |                           |           |           |                  |
| 230200                  | HF RECEIVER / TRANSMITTER REPLACE |           |          |          |                           |           |           |                  |
| PN:PN                   | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:23 |
| SN:UNKNOWN              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | PROC. REF: AMM GENERIC 1          |           |          |          |                           |           |           |                  |
| 230201                  | HF COUPLER REPLACE                |           |          |          |                           |           |           |                  |
| PN:PN                   | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:23 |
| SN:UNKNOWN              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                         | PROC. REF: AMM GENERIC 1          |           |          |          |                           |           |           |                  |
| 230306                  | FLIGHT PHONE                      |           |          |          |                           |           |           |                  |
| PN:400-0125-2000        | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:23 |
| SN:UNKNOWN              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.040             | AFL                               | 0         |          |          |                           |           |           |                  |
|                         | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                 | Unit                                                                       | C/W       | Interval       | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-------------------------|----------------------------------------------------------------------------|-----------|----------------|------------|---------------------------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS |                                                                            |           |                |            |                           |           |             |                  |
| 230616                  | NO. 2 VHF COMM ANTENNA                                                     |           |                |            |                           |           |             |                  |
| PN:90-384036            | MOS/MSC                                                                    | 29-Dec-98 | O/C            |            |                           |           |             | Component ATA:23 |
| SN:6256                 | HRS                                                                        | 0         |                | TSN 0      |                           |           |             |                  |
| WC#: 23.030             | AFL                                                                        | 0         |                |            |                           |           |             |                  |
|                         | PROC. REF: AMM 23-10-03                                                    |           |                |            |                           |           |             |                  |
| 231150                  | COCKPIT VOICE RECORDER                                                     |           |                |            |                           |           |             |                  |
| PN:S100-0080-00         | MOS/MSC                                                                    | 07-Aug-12 | O/C            |            |                           |           |             | Component ATA:23 |
| SN:02328                | HRS                                                                        | 2825.9    |                | TSN 2825.9 |                           |           |             |                  |
| WC#: 23.050             | AFL                                                                        | 2944      |                | TSN 2944   |                           |           |             |                  |
|                         | PROC. REF: AMM 23-70-05                                                    |           |                |            |                           |           |             |                  |
| 231153                  | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON                           |           |                |            |                           |           |             |                  |
| PN:DK120                | MOS/MSC                                                                    | 22-May-24 | O/C            | TSO 0      |                           |           |             | Component ATA:23 |
| SN:SC13232              | HRS                                                                        | 5686.2    |                | TSO 0      |                           |           |             |                  |
| WC#: 23.050             | AFL                                                                        | 6495      |                | TSO 0      |                           |           |             |                  |
|                         | PROC. REF: GENERIC NO REF, CMM SECTION V & VI                              |           |                |            |                           |           |             |                  |
| 231155                  | REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR/ULB) BATTERY |           |                |            |                           |           |             |                  |
|                         | MOS/MSC                                                                    | 22-May-24 | DUE            |            | 01-Apr-30 (M)             |           | 2086 d      | Service ATA:23   |
|                         | HRS                                                                        | 5686.2    |                |            |                           |           |             |                  |
| WC#: 23.050             | AFL                                                                        | 6495      |                |            |                           |           |             |                  |
|                         | PROC. REF: CMM SECTION V & VI                                              |           |                |            |                           |           |             |                  |
| 231162                  | FUNCTIONAL TEST COCKPIT VOICE RECORDER                                     |           |                |            |                           |           |             |                  |
|                         | MOS                                                                        | 12-Apr-23 | 24 (+24d/-24d) |            | 12-Apr-25                 | 06-May-25 | 271 d (+24) | Service ATA:23   |
|                         | HRS                                                                        | 5500.3    |                |            |                           |           |             |                  |
|                         | AFL                                                                        | 6358      |                |            |                           |           |             |                  |
|                         | PROC. REF: AMM 23-70-15                                                    |           |                |            |                           |           |             |                  |
| 231163                  | FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (ULB)                            |           |                |            |                           |           |             |                  |
|                         | MOS                                                                        | 12-Apr-23 | 24 (+24d/-24d) |            | 12-Apr-25                 | 06-May-25 | 271 d (+24) | Service ATA:23   |
|                         | HRS                                                                        | 5500.3    |                |            |                           |           |             |                  |
|                         | AFL                                                                        | 6358      |                |            |                           |           |             |                  |
|                         | PROC. REF: AMM 23-70-17                                                    |           |                |            |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|---------------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS   |                                         |           |          |                                       |                           |           |           |                  |
| 235015                    | NO. 3 AUDIO AMPLIFIER                   |           |          |                                       |                           |           |           |                  |
| PN:MODEL 240              | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           | Component ATA:23 |
| SN:1184                   | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 23.100               | AFL                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
|                           |                                         |           |          | PROC. REF: AMM 23-50-03               |                           |           |           |                  |
| 235016 <sup>U</sup>       | AUDIO MIXING AMPLIFIER                  |           |          |                                       |                           |           |           |                  |
| PN:247-001                | MOS/MSC                                 | 05-Sep-19 | O/C      | TSN 0                                 |                           |           |           | Component ATA:23 |
| SN:P200211                | HRS                                     | 5104.4    |          | TSN 0                                 |                           |           |           |                  |
|                           | AFL                                     | 6064      |          | TSN 0                                 |                           |           |           |                  |
| 235020                    | AURAL WARNING GENERATOR                 |           |          |                                       |                           |           |           |                  |
| PN:600-001                | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           | Component ATA:23 |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 23.110               | AFL                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
|                           |                                         |           |          | PROC. REF: AMM 23-50-05               |                           |           |           |                  |
| ATA 24 - ELECTRICAL POWER |                                         |           |          |                                       |                           |           |           |                  |
| 240101                    | BATTERY                                 |           |          |                                       |                           |           |           |                  |
| PN:RG380E/44K             | MOS/MSC                                 | 22-May-24 | O/C      | TSN 0                                 |                           |           |           | Component ATA:24 |
| SN:70027463               | HRS                                     | 5686.2    |          | TSN 0                                 |                           |           |           |                  |
| WC#: 24.010               | AFL                                     | 6495      |          | TSN 0                                 |                           |           |           |                  |
|                           |                                         |           |          | PROC. REF: AMM 24-33-03, AMM 24-30-01 |                           |           |           |                  |
| 240126                    | BATTERY CURRENT CHARGING MONITOR MODULE |           |          |                                       |                           |           |           |                  |
| PN:101-364180-1           | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           | Component ATA:24 |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 24.020               | AFL                                     | 0         |          |                                       |                           |           |           |                  |
|                           |                                         |           |          | PROC. REF: GENERIC NO REF             |                           |           |           |                  |
| 240132                    | BATTERY MASTER RELAY                    |           |          |                                       |                           |           |           |                  |
| PN:6041H189               | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           | Component ATA:24 |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 24.020               | AFL                                     | 0         |          |                                       |                           |           |           |                  |
|                           |                                         |           |          | PROC. REF: GENERIC NO REF             |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit    | C/W                            | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                  |
|---------------------------|---------|--------------------------------|----------|---------------------------|---------------------------|-----------|-----------|------------------------------|
| ATA 24 - ELECTRICAL POWER |         |                                |          |                           |                           |           |           |                              |
| 241101                    |         | NO. 1 ENGINE STARTER/GENERATOR |          |                           |                           |           |           | Component ATA:24<br>OVERHAUL |
| PN:23048-016              | MOS     | 02-Mar-20                      |          | TSO 13                    |                           |           |           |                              |
| SN:21046                  | HRS     | 5162.6                         | 1000     | TSO 79.7                  | 6082.9                    |           | 396.7     |                              |
| WC#: 24.030               | AFL     | 6113                           |          | TSO 69                    |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: AMM 24-30-03   |                           |           |           |                              |
| 241131                    |         | LEFT VOLTAGE REGULATOR         |          |                           |                           |           |           | Component ATA:24             |
| PN:51538-001A             | MOS/MSC | 29-Dec-98                      | O/C      |                           |                           |           |           |                              |
| SN:98406                  | HRS     | 0                              |          | TSN 0                     |                           |           |           |                              |
| WC#: 24.040               | AFL     | 0                              |          |                           |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: GENERIC NO REF |                           |           |           |                              |
| 241156                    |         | LEFT VOLT METER                |          |                           |                           |           |           | Component ATA:24             |
| PN:101-384106-9           | MOS/MSC | 26-Sep-22                      | O/C      | TSN 0                     |                           |           |           |                              |
| SN:G22-12343              | HRS     | 5358.5                         |          | TSN 0                     |                           |           |           |                              |
| WC#: 24.050               | AFL     | 6274                           |          | TSN 0                     |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: GENERIC NO REF |                           |           |           |                              |
| 241601                    |         | NO. 2 ENGINE STARTER/GENERATOR |          |                           |                           |           |           | Component ATA:24<br>OVERHAUL |
| PN:23048-016              | MOS     | 02-Mar-20                      |          | TSO 13                    |                           |           |           |                              |
| SN:P1895                  | HRS     | 5162.6                         | 1000     | TSO 79.7                  | 6082.9                    |           | 396.7     |                              |
| WC#: 24.030               | AFL     | 6113                           |          | TSO 69                    |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: AMM 24-30-03   |                           |           |           |                              |
| 241631                    |         | RIGHT VOLTAGE REGULATOR        |          |                           |                           |           |           | Component ATA:24             |
| PN:51538-001A             | MOS/MSC | 29-Dec-98                      | O/C      |                           |                           |           |           |                              |
| SN:98373                  | HRS     | 0                              |          | TSN 0                     |                           |           |           |                              |
| WC#: 24.040               | AFL     | 0                              |          |                           |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: GENERIC NO REF |                           |           |           |                              |
| 241656                    |         | RIGHT VOLT METER               |          |                           |                           |           |           | Component ATA:24             |
| PN:101-384106-9           | MOS/MSC | 26-Sep-22                      | O/C      | TSN 0                     |                           |           |           |                              |
| SN:G22-12344              | HRS     | 5358.5                         |          | TSN 0                     |                           |           |           |                              |
| WC#: 24.050               | AFL     | 6274                           |          | TSN 0                     |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: GENERIC NO REF |                           |           |           |                              |
| 242005                    |         | A/C VOLT FREQUENCY METER       |          |                           |                           |           |           | Component ATA:24             |
| PN:101-384107-3           | MOS/MSC | 29-Dec-98                      | O/C      |                           |                           |           |           |                              |
| SN:2227                   | HRS     | 0                              |          | TSN 0                     |                           |           |           |                              |
| WC#: 24.170               | AFL     | 0                              |          | TSN 0                     |                           |           |           |                              |
|                           |         |                                |          | PROC. REF: GENERIC NO REF |                           |           |           |                              |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                        | Unit               | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------------------------|--------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|---------------------|
| ATA 24 - ELECTRICAL POWER      |                    |           |          |                           |                           |           |           |                     |
| 242101                         | NO. 1 INVERTER     |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:KGS ELECT. SPC-60(A)MOS/MSC | HRS                | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:UNKNOWN                     | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.060                    | AFL                | 0         |          |                           |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 242601                         | NO. 2 INVERTER     |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:KGS ELECT. SPC-60(A)MOS/MSC | HRS                | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:UNKNOWN                     | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.060                    | AFL                | 0         |          |                           |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 243005                         | NO. 1 POWER SUPPLY |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:2679                        | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.100                    | AFL                | 0         |          | TSN 0                     |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 243010                         | NO. 2 POWER SUPPLY |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:2691                        | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.110                    | AFL                | 0         |          | TSN 0                     |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 243015                         | NO. 3 POWER SUPPLY |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:2676                        | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.120                    | AFL                | 0         |          | TSN 0                     |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 243020                         | NO. 4 POWER SUPPLY |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:2696                        | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.130                    | AFL                | 0         |          | TSN 0                     |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 243025                         | NO. 5 POWER SUPPLY |           |          |                           |                           |           |           | Component    ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |                           |                           |           |           |                     |
| SN:2623                        | HRS                | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 24.140                    | AFL                | 0         |          | TSN 0                     |                           |           |           |                     |
|                                |                    |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                              | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|-----------------------------------|-----------|-------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 24 - ELECTRICAL POWER |                                   |           |             |          |                           |           |             |                  |
| 243030                    | NO. 6 POWER SUPPLY                |           |             |          |                           |           |             |                  |
| PN:127-384019-3           | MOS/MSC                           | 29-Dec-98 | O/C         |          |                           |           |             | Component ATA:24 |
| SN:2701                   | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.150               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243035                    | BATTERY POWER CIRCUIT BREAKER BOX |           |             |          |                           |           |             |                  |
| PN:101-364462-7           | MOS/MSC                           | 29-Dec-98 | O/C         |          |                           |           |             | Component ATA:24 |
| SN:462-C-98               | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.160               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243040                    | AMMETER INDICATOR                 |           |             |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |             | Component ATA:24 |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.070               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243045                    | NO. 1 DC TO AC POWER CONVERTER    |           |             |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |             | Component ATA:24 |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.080               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243050                    | NO. 2 DC TO AC POWER CONVERTER    |           |             |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |             | Component ATA:24 |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.080               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243100                    | BATTERY CAPACITY TEST (LEAD ACID) |           |             |          |                           |           |             |                  |
| PN:RG380E/44K             | MOS                               | 22-May-24 | 6 (+1m/-1m) |          | 22-Nov-24                 | 22-Dec-24 | 130 d (+30) | Service ATA:24   |
| SN:70027463               | HRS                               | 5686.2    |             |          |                           |           |             |                  |
| WC#: 24.010               | AFL                               | 6495      |             |          |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |
| 243110                    | LEFT HAND GENERATOR CONTROL UNIT  |           |             |          |                           |           |             |                  |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |             | Component ATA:24 |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |             |                  |
| WC#: 24.090               | AFL                               | 0         |             | TSN 0    |                           |           |             |                  |
|                           | PROC. REF: GENERIC NO REF         |           |             |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                        | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER      |                                   |           |          |          |                           |           |           |                  |
| 243115                         | RIGHT HAND GENERATOR CONTROL UNIT |           |          |          |                           |           |           |                  |
| PN:PN                          | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:24 |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.090                    | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| ATA 25 - EQUIPMENT/FURNISHINGS |                                   |           |          |          |                           |           |           |                  |
| 250101                         | PILOT SEAT                        |           |          |          |                           |           |           |                  |
| PN:101-530190-23               | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.010                    | AFL                               | 0         |          |          |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 250106                         | PILOT SEATBELT                    |           |          |          |                           |           |           |                  |
| PN:101-530190-29               | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.020                    | AFL                               | 0         |          |          |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 250111                         | COPILOT SEAT                      |           |          |          |                           |           |           |                  |
| PN:50-534392-38                | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.010                    | AFL                               | 0         |          |          |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 250116                         | COPILOT SEATBELT                  |           |          |          |                           |           |           |                  |
| PN:58-530081-29                | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.020                    | AFL                               | 0         |          |          |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |
| 251005                         | ENVIRONMENTAL TEMPERATURE SENSOR  |           |          |          |                           |           |           |                  |
| PN:AYLF50304                   | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:7326                        | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.060                    | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                | PROC. REF: GENERIC NO REF         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                        | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                                 |           |          |          |                           |           |           |                  |
| 252601                         | ELT EMERGENCY LOCATOR TRANSMITTER               |           |          |          |                           |           |           |                  |
| PN:110-4                       | MOS/MSC                                         | 27-Jan-09 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:61503                       | HRS                                             | 2355.4    |          | TSN 0    |                           |           |           |                  |
| WC#: 25.030                    | AFL                                             | 2317      |          | TSN 0    |                           |           |           |                  |
|                                | PROC. REF: AMM 25-67-01                         |           |          |          |                           |           |           |                  |
| 252605                         | EMERGENCY LOCATOR TRANSMITTER BATTERY           |           |          |          |                           |           |           |                  |
| PN:452-0133                    | MOS/MSC                                         | 12-Apr-23 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:399019-040                  | HRS                                             | 5500.3    |          | TSN 0    |                           |           |           |                  |
| AFL                            |                                                 | 6358      |          | TSN 0    |                           |           |           |                  |
|                                | PROC. REF: AMM GENERIC 1                        |           |          |          |                           |           |           |                  |
| 252606                         | REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY   |           |          |          |                           |           |           |                  |
| PN:452-0133                    | MOS/MSC                                         | 12-Apr-23 | DUE      |          | 01-Mar-28 (M)             |           | 1325 d    | Service ATA:25   |
| SN:399019-040                  | HRS                                             | 5500.3    |          |          |                           |           |           |                  |
| WC#: 25.030                    | AFL                                             | 6358      |          |          |                           |           |           |                  |
|                                | PROC. REF: AMM 25-60-03, AMM 25-60-05           |           |          |          |                           |           |           |                  |
| 252612                         | INSPECT EMERGENCY LOCATOR TRANSMITTER           |           |          |          |                           |           |           |                  |
| PN:110-4                       | MOS                                             | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:25   |
| SN:61503                       | HRS                                             | 5686.2    |          |          |                           |           |           |                  |
| WC#: 25.050                    | AFL                                             | 6495      |          |          |                           |           |           |                  |
|                                | PROC. REF: AMM 25-67-01, FAR FAR PART 91.207(D) |           |          |          |                           |           |           |                  |
| 252616                         | EMERGENCY LOCATOR ANTENNA                       |           |          |          |                           |           |           |                  |
| PN:110-330                     | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:25 |
| SN:7748                        | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.040                    | AFL                                             | 0         |          |          |                           |           |           |                  |
|                                | PROC. REF: AMM 25-60-07                         |           |          |          |                           |           |           |                  |
| 253000 <sup>U</sup>            | JUPITER DUAL USB CHARGING PORT                  |           |          |          |                           |           |           |                  |
| PN:JA74-001                    | MOS/MSC                                         | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:6022                        | HRS                                             | 5104.4    |          | TSN 0    |                           |           |           |                  |
| AFL                            |                                                 | 6064      |          | TSN 0    |                           |           |           |                  |
| 253001 <sup>U</sup>            | TA102 - DUAL USB CHARGING PORT                  |           |          |          |                           |           |           |                  |
| PN:6430102-3                   | MOS/MSC                                         | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:G18-11897                   | HRS                                             | 5104.4    |          | TSN 0    |                           |           |           |                  |
| AFL                            |                                                 | 6064      |          | TSN 0    |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                            | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |         |           |          |          |                           |           |           |                  |
| 253002 <sup>U</sup> TA102 - DUAL USB CHARGING PORT |         |           |          |          |                           |           |           |                  |
| PN:6430102-3                                       | MOS/MSC | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:C18-12264                                       | HRS     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                                    | AFL     | 6064      |          | TSN 0    |                           |           |           |                  |
| 253003 <sup>U</sup> TA102 - DUAL USB CHARGING PORT |         |           |          |          |                           |           |           |                  |
| PN:6430102-3                                       | MOS/MSC | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:C18-11899                                       | HRS     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                                    | AFL     | 6064      |          | TSN 0    |                           |           |           |                  |
| 258000 <sup>U</sup> SEVENTEEN DZUS - GLOVE BOX     |         |           |          |          |                           |           |           |                  |
| PN:JA70-017                                        | MOS/MSC | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:6213                                            | HRS     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                                    | AFL     | 6064      |          | TSN 0    |                           |           |           |                  |
| 258010 LEFT HAND ELECTRONIC CONTROLLER             |         |           |          |          |                           |           |           |                  |
| PN:PN                                              | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.070                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    |         |           |          |          | PROC. REF: AMM 21-11-07   |           |           |                  |
| 258060 RIGHT HAND ELECTRONIC CONTROLLER            |         |           |          |          |                           |           |           |                  |
| PN:PN                                              | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:25 |
| SN:UNKNOWN                                         | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.070                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    |         |           |          |          | PROC. REF: AMM 21-11-07   |           |           |                  |
| 259073 INSPECT FRX AED (DEFIBULATOR) WITH PREP KIT |         |           |          |          |                           |           |           |                  |
|                                                    | MOS/MSC | 29-Dec-98 | N/A      |          |                           |           |           | Service ATA:25   |
|                                                    | HRS     | 0         |          |          |                           |           |           |                  |
|                                                    | AFL     | 0         |          |          |                           |           |           |                  |
|                                                    |         |           |          |          | PROC. REF: AMM GENERIC 1  |           |           |                  |
| ATA 26 - FIRE PROTECTION                           |         |           |          |          |                           |           |           |                  |
| 260005 INBOARD PRESSURE SWITCH                     |         |           |          |          |                           |           |           |                  |
| PN:90-380002-3                                     | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:14559                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.110                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    |         |           |          |          | PROC. REF: AMM 27-21-23   |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                      | Unit    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------------------------------------------------------|---------|-----------|----------|---------------------------|---------------------------|-----------|-----------|---------------------|
| ATA 26 - FIRE PROTECTION                                     |         |           |          |                           |                           |           |           |                     |
| 260010      OUTBOARD PRESSURE SWITCH                         |         |           |          |                           |                           |           |           |                     |
| PN:90-380002-3                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:14906                                                     | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.110                                                  | AFL     | 0         |          | TSN 0                     |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 27-21-23   |                           |           |           |                     |
| 260131      NO. 1 ENGINE FORWARD FIRE DETECTOR               |         |           |          |                           |                           |           |           |                     |
| PN:30-215-8                                                  | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     |           |          |                           |                           |           |           |                     |
| WC#: 26.020                                                  | AFL     |           |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 26-10-03   |                           |           |           |                     |
| 260136      NO. 1 ENGINE UPPER FIRE DETECTOR                 |         |           |          |                           |                           |           |           |                     |
| PN:30-215-8                                                  | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.030                                                  | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 26-10-03   |                           |           |           |                     |
| 260141      NO. 1 ENGINE LOWER FIRE DETECTOR                 |         |           |          |                           |                           |           |           |                     |
| PN:30-215-8                                                  | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.040                                                  | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 26-10-03   |                           |           |           |                     |
| 260146      NO. 1 ENGINE FIRE EXTINGUISHER CONTROL AMPLIFIER |         |           |          |                           |                           |           |           |                     |
| PN:30326-7                                                   | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.050                                                  | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 260631      NO. 2 ENGINE FORWARD FIRE DETECTOR               |         |           |          |                           |                           |           |           |                     |
| PN:30-215-8                                                  | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.020                                                  | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 26-10-03   |                           |           |           |                     |
| 260636      NO. 2 ENGINE UPPER FIRE DETECTOR                 |         |           |          |                           |                           |           |           |                     |
| PN:30-215-8                                                  | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:26 |
| SN:UNKNOWN                                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 26.030                                                  | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                              |         |           |          | PROC. REF: AMM 26-10-03   |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                 | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION                                |         |           |          |          |                           |           |           |                  |
| 260641 NO. 2 ENGINE LOWER FIRE DETECTOR                 |         |           |          |          |                           |           |           |                  |
| PN:30-215-8                                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:UNKNOWN                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.040                                             | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03                                 |         |           |          |          |                           |           |           |                  |
| 260646 NO. 2 ENGINE FIRE EXTINGUISHER CONTROL AMPLIFIER |         |           |          |          |                           |           |           |                  |
| PN:30326-7                                              | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:UNKNOWN                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.050                                             | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                               |         |           |          |          |                           |           |           |                  |
| 261005 NO. 1 ENGINE LEFT FIRE OVERHEAT DETECTOR         |         |           |          |          |                           |           |           |                  |
| PN:3001-129                                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:79973                                                | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.100                                             | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                               |         |           |          |          |                           |           |           |                  |
| 261010 NO. 2 ENGINE RIGHT FIRE OVERHEAT DETECTOR        |         |           |          |          |                           |           |           |                  |
| PN:3001-129                                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:80016                                                | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.100                                             | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                               |         |           |          |          |                           |           |           |                  |
| 261101 NO. 1 ENGINE FIRE EXTINGUISHER MONITOR MODULE    |         |           |          |          |                           |           |           |                  |
| PN:33370005                                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:UNKNOWN                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.060                                             | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-03                                 |         |           |          |          |                           |           |           |                  |
| 261106 NO. 2 ENGINE FIRE EXTINGUISHER MONITOR MODULE    |         |           |          |          |                           |           |           |                  |
| PN:33370005                                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:26 |
| SN:UNKNOWN                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.060                                             | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-03                                 |         |           |          |          |                           |           |           |                  |
| 261110 LEFT HAND BLEED AIR FLOW CONTROL                 |         |           |          |          |                           |           |           |                  |
| PN:PN                                                   | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:26 |
| SN:UNKNOWN                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.120                                             | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                               |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                       | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|--------------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION |                                            |           |          |           |                           |           |           |                  |
| 261115                   | RIGHT HAND BLEED AIR FLOW CONTROL          |           |          |           |                           |           |           |                  |
| PN:PN                    | MOS/MSC                                    | 29-Dec-98 | O/C      | TSN 0     |                           |           |           | Component ATA:26 |
| SN:UNKNOWN               | HRS                                        | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 26.120              | AFL                                        | 0         |          | TSN 0     |                           |           |           |                  |
|                          | PROC. REF: GENERIC NO REF                  |           |          |           |                           |           |           |                  |
| 262049 <sup>U</sup>      | WEIGHT CHECK COCKPIT FIRE EXTINGUISHER     |           |          |           |                           |           |           |                  |
| MOS                      | 22-May-24                                  | 12        |          | 22-May-25 |                           | 311 d     |           | Service ATA:26   |
| HRS                      | 5686.2                                     |           |          |           |                           |           |           |                  |
| AFL                      | 6495                                       |           |          |           |                           |           |           |                  |
| 262050 <sup>U</sup>      | WEIGHT CHECK CABIN FIRE EXTINGUISHER       |           |          |           |                           |           |           |                  |
| MOS                      | 22-May-24                                  | 12        |          | 22-May-25 |                           | 311 d     |           | Service ATA:26   |
| HRS                      | 5686.2                                     |           |          |           |                           |           |           |                  |
| AFL                      | 6495                                       |           |          |           |                           |           |           |                  |
| 263201                   | CABIN FIRE EXTINGUISHER                    |           |          |           |                           |           |           |                  |
| PN:C352TS                | MOS/MSC                                    | 17-Nov-18 | O/C      |           |                           |           |           | Component ATA:26 |
| SN:E92812086             | HRS                                        | 5079.9    |          |           |                           |           |           |                  |
| WC#: 26.070              | AFL                                        | 6043      |          |           |                           |           |           |                  |
|                          | PROC. REF: GENERIC NO REF                  |           |          |           |                           |           |           |                  |
| 263211                   | HYDROSTATIC TEST CABIN FIRE EXTINGUISHER   |           |          |           |                           |           |           |                  |
| PN:C352TS                | MOS                                        | 17-Nov-18 | 144      | 17-Nov-30 |                           | 2316 d    |           | Service ATA:26   |
| SN:E92812086             | HRS                                        | 5079.9    |          |           |                           |           |           |                  |
| WC#: 26.070              | AFL                                        | 6043      |          |           |                           |           |           |                  |
|                          | PROC. REF: GENERIC NO REF                  |           |          |           |                           |           |           |                  |
| 263621                   | COCKPIT FIRE EXTINGUISHER                  |           |          |           |                           |           |           |                  |
| PN:C352TS                | MOS/MSC                                    | 17-Nov-18 | O/C      |           |                           |           |           | Component ATA:26 |
| SN:E92812087             | HRS                                        | 5079.9    |          |           |                           |           |           |                  |
| WC#: 26.080              | AFL                                        | 6043      |          |           |                           |           |           |                  |
|                          | PROC. REF: GENERIC NO REF                  |           |          |           |                           |           |           |                  |
| 263631                   | HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER |           |          |           |                           |           |           |                  |
| PN:C352TS                | MOS                                        | 17-Nov-18 | 144      | 17-Nov-30 |                           | 2316 d    |           | Service ATA:26   |
| SN:E92812087             | HRS                                        | 5079.9    |          |           |                           |           |           |                  |
| WC#: 26.080              | AFL                                        | 6043      |          |           |                           |           |           |                  |
|                          | PROC. REF: AMM GENERIC 1                   |           |          |           |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                           | Unit    | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------------------|---------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS                          |         |           |                  |          |                           |           |              |                  |
| 270010 PERFORM FLIGHT CONTROL CABLE TENSION CHECK |         |           |                  |          |                           |           |              |                  |
|                                                   | MOS     | 22-May-24 | 48 (+48d/-48d)   |          | 22-May-28                 | 09-Jul-28 | 1407 d (+48) | Service ATA:27   |
|                                                   | HRS     | 5686.2    |                  |          |                           |           |              |                  |
|                                                   | AFL     | 6495      |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF                         |         |           |                  |          |                           |           |              |                  |
| 270101 LEFT AILERON                               |         |           |                  |          |                           |           |              |                  |
| PN:101-130001-269                                 | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                        | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.010                                       | AFL     | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-05                           |         |           |                  |          |                           |           |              |                  |
| 270111 AILERON TRIM TAB                           |         |           |                  |          |                           |           |              |                  |
| PN:101-130001-5                                   | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                        | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.020                                       | AFL     | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF                         |         |           |                  |          |                           |           |              |                  |
| 270121 AILERON TRIM TAB ACTUATOR                  |         |           |                  |          |                           |           |              |                  |
| PN:101-521039-1                                   | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:573-D-98                                       | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.020                                       | AFL     | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-13                           |         |           |                  |          |                           |           |              |                  |
| 270601 RIGHT AILERON                              |         |           |                  |          |                           |           |              |                  |
| PN:101-130001-271                                 | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                        | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.010                                       | AFL     | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-05                           |         |           |                  |          |                           |           |              |                  |
| 271000 CHECK AILERON TRIM TAB FREE PLAY           |         |           |                  |          |                           |           |              |                  |
|                                                   | MOS     | 07-Feb-20 |                  |          |                           |           |              | Service ATA:27   |
|                                                   | HRS     | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 673.3 (+120) |                  |
|                                                   | AFL     | 6110      |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-19                           |         |           |                  |          |                           |           |              |                  |
| 271101 RUDDER                                     |         |           |                  |          |                           |           |              |                  |
| PN:101-630000-601                                 | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                        | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.030                                       | AFL     | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-20-01                           |         |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                  | Unit                            | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------------------|---------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 27 - FLIGHT CONTROLS |                                 |           |                 |          |                           |           |           |                     |
| 271116                   | RUDDER TRIM TAB                 |           |                 |          |                           |           |           |                     |
| PN:101-630000-161        | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.040              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: GENERIC NO REF       |           |                 |          |                           |           |           |                     |
| 271126                   | RUDDER TRIM TAB ACTUATOR        |           |                 |          |                           |           |           |                     |
| PN:101-524079-1          | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.040              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: AMM 27-20-09         |           |                 |          |                           |           |           |                     |
| 271166                   | RUDDER BOOST PRESSURE REGULATOR |           |                 |          |                           |           |           |                     |
| PN:101-524179-3          | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.060              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: GENERIC NO REF       |           |                 |          |                           |           |           |                     |
| 271171                   | YAW DAMP PRESSURE REGULATOR     |           |                 |          |                           |           |           |                     |
| PN:101-524179-1          | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:498-A-98              | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.070              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: GENERIC NO REF       |           |                 |          |                           |           |           |                     |
| 271176                   | REPLACE RUDDER BOOST FILTER     |           |                 |          |                           |           |           |                     |
|                          | MOS                             | 22-May-24 |                 |          |                           |           |           | Service    ATA:27   |
|                          | HRS                             | 5686.2    | 200 (+10%/-10%) |          | 5886.2                    | 5906.2    | 200 (+20) |                     |
| WC#: 27.060              | AFL                             | 6495      |                 |          |                           |           |           |                     |
|                          | PROC. REF: AMM 27-21-01         |           |                 |          |                           |           |           |                     |
| 271179                   | LEFT YAW DAMP SERVO             |           |                 |          |                           |           |           |                     |
| PN:1900-7-4-1            | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.080              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: GENERIC NO REF       |           |                 |          |                           |           |           |                     |
| 271182                   | RIGHT YAW DAMP SERVO            |           |                 |          |                           |           |           |                     |
| PN:1900-7-4-1            | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |           | Component    ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                 | TSN 0    |                           |           |           |                     |
| WC#: 27.080              | AFL                             | 0         |                 |          |                           |           |           |                     |
|                          | PROC. REF: GENERIC NO REF       |           |                 |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                            | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|---------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                 |           |                  |          |                           |           |              |                  |
| 271185                   | LEFT YAW DAMP SOLENOID VALVE    |           |                  |          |                           |           |              |                  |
| PN:717                   | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:8175                  | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090              | AFL                             | 0         |                  |          |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF       |           |                  |          |                           |           |              |                  |
| 271188                   | RIGHT YAW DAMP SOLENOID VALVE   |           |                  |          |                           |           |              |                  |
| PN:717                   | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:8237                  | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090              | AFL                             | 0         |                  |          |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF       |           |                  |          |                           |           |              |                  |
| 271191                   | YAW CONTROL SOLENOID VALVE      |           |                  |          |                           |           |              |                  |
| PN:717                   | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090              | AFL                             | 0         |                  |          |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF       |           |                  |          |                           |           |              |                  |
| 272000                   | CHECK RUDDER TRIM TAB FREE PLAY |           |                  |          |                           |           |              |                  |
|                          | MOS                             | 07-Feb-20 |                  |          |                           |           |              | Service ATA:27   |
|                          | HRS                             | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 673.3 (+120) |                  |
|                          | AFL                             | 6110      |                  |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-20-15         |           |                  |          |                           |           |              |                  |
| 272005                   | RUDDER BOOST PRESSURE SWITCH    |           |                  |          |                           |           |              |                  |
| PN:101-384119-1          | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:4956                  | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.300              | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
|                          | PROC. REF: AMM 27-21-23         |           |                  |          |                           |           |              |                  |
| 272010                   | LEFT RUDDER RELIEF VALVE        |           |                  |          |                           |           |              |                  |
| PN:506-1                 | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:5721                  | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.310              | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF       |           |                  |          |                           |           |              |                  |
| 272015                   | RIGHT RUDDER RELIEF VALVE       |           |                  |          |                           |           |              |                  |
| PN:506-1                 | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:5753                  | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.310              | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF       |           |                  |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                 | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit     | Remaining | Disposition      |
|--------------------------|------------------------------------------------------|-----------|------------------|----------|---------------------------|---------------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                      |           |                  |          |                           |               |           |                  |
| 272101                   | LEFT ELEVATOR                                        |           |                  |          |                           |               |           |                  |
| PN:101-610000-605        | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.100              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: GENERIC NO REF                            |           |                  |          |                           |               |           |                  |
| 272111                   | LEFT ELEVATOR TRIM TAB                               |           |                  |          |                           |               |           |                  |
| PN:101-610000-13         | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.110              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: GENERIC NO REF                            |           |                  |          |                           |               |           |                  |
| 272121                   | LEFT ELEVATOR TRIM TAB ACTUATOR                      |           |                  |          |                           |               |           |                  |
| PN:101-524036-1          | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.120              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: AMIM 27-30-13                             |           |                  |          |                           |               |           |                  |
| 272601                   | RIGHT ELEVATOR                                       |           |                  |          |                           |               |           |                  |
| PN:101-610000-606        | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.100              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: GENERIC NO REF                            |           |                  |          |                           |               |           |                  |
| 272611                   | RIGHT ELEVATOR TRIM TAB                              |           |                  |          |                           |               |           |                  |
| PN:101-610000-14         | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.110              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: GENERIC NO REF                            |           |                  |          |                           |               |           |                  |
| 272621                   | RIGHT ELEVATOR TRIM TAB ACTUATOR                     |           |                  |          |                           |               |           |                  |
| PN:101-524072-1          | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |               |           | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                  | 0         |                  | TSN 0    |                           |               |           |                  |
| WC#: 27.120              | AFL                                                  | 0         |                  |          |                           |               |           |                  |
|                          | PROC. REF: AMIM 27-30-13                             |           |                  |          |                           |               |           |                  |
| 273000                   | PERFORM ELEVATOR BOB WEIGHT LINK ASSEMBLY INSPECTION |           |                  |          |                           |               |           |                  |
|                          | MOS                                                  | 20-Jun-19 |                  |          |                           |               |           | Service ATA:27   |
|                          | HRS                                                  | 5100.1    | 5000 (+10%/-10%) | 10100.1  | 10600.1                   | 4413.9 (+500) |           |                  |
|                          | AFL                                                  |           |                  |          |                           |               |           |                  |
|                          | PROC. REF: AMIM 27-30-23                             |           |                  |          |                           |               |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                    | Unit    | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------------------------|---------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS                   |         |           |                  |          |                           |           |              |                  |
| 273006 CHECK ELEVATOR TRIM TAB FREE PLAY   |         |           |                  |          |                           |           |              |                  |
|                                            | MOS     | 07-Feb-20 |                  |          |                           |           |              | Service ATA:27   |
|                                            | HRS     | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 673.3 (+120) |                  |
|                                            | AFL     | 6110      |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: AMM 27-30-21   |           |              |                  |
| 273101 ELEVATOR ELECTRIC TRIM TAB ACTUATOR |         |           |                  |          |                           |           |              |                  |
| PN:50-380124-3                             | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                 | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.130                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: AMM 27-30-15   |           |              |                  |
| 273104 ELEVATOR TRIM MAGNETIC CLUTCH       |         |           |                  |          |                           |           |              |                  |
| PN:50-380125                               | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                 | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.140                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: AMM 27-30-17   |           |              |                  |
| 273601 STALL WARNING LIFT TRANSDUCER       |         |           |                  |          |                           |           |              |                  |
| PN:101-380005-9                            | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:4123                                    | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.150                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: GENERIC NO REF |           |              |                  |
| 273606 STALL WARNING LIFT COMPUTER         |         |           |                  |          |                           |           |              |                  |
| PN:101-380005-19                           | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                 | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.150                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: GENERIC NO REF |           |              |                  |
| 273611 STALL WARNING HORN                  |         |           |                  |          |                           |           |              |                  |
| PN:169-380021-11                           | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                 | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.160                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: GENERIC NO REF |           |              |                  |
| 273616 STALL WARNING TEST SWITCH           |         |           |                  |          |                           |           |              |                  |
| PN:8811K17                                 | MOS/MSC | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN                                 | HRS     | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.160                                | AFL     | 0         |                  |          |                           |           |              |                  |
|                                            |         |           |                  |          | PROC. REF: GENERIC NO REF |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                     | C/W       | Interval         | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|--------------------------|------------------------------------------|-----------|------------------|---------------------------|---------------------------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                          |           |                  |                           |                           |           |             |                  |
| 274116                   | FLAP POSITION TRANSMITTER                |           |                  |                           |                           |           |             |                  |
| PN:559-1                 | MOS/MSC                                  | 11-May-22 | O/C              | TSN 0                     |                           |           |             | Component ATA:27 |
| SN:1285A                 | HRS                                      | 5340.8    |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.180              | AFL                                      | 6259      |                  | TSN 0                     |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: AMM 27-50-01   |                           |           |             |                  |
| 274121                   | FLAP POSITION INDICATOR                  |           |                  |                           |                           |           |             |                  |
| PN:101-384029-1          | MOS/MSC                                  | 29-Dec-98 | O/C              |                           |                           |           |             | Component ATA:27 |
| SN:5041                  | HRS                                      | 0         |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.180              | AFL                                      | 0         |                  |                           |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: GENERIC NO REF |                           |           |             |                  |
| 274136                   | FLAP MOTOR RELAY                         |           |                  |                           |                           |           |             |                  |
| PN:6046H39A              | MOS/MSC                                  | 29-Dec-98 | O/C              |                           |                           |           |             | Component ATA:27 |
| SN:UNKNOWN               | HRS                                      | 0         |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.180              | AFL                                      | 0         |                  |                           |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: GENERIC NO REF |                           |           |             |                  |
| 274601                   | LEFT INBOARD FLAP                        |           |                  |                           |                           |           |             |                  |
| PN:101-160001-17         | MOS/MSC                                  | 29-Dec-98 | O/C              |                           |                           |           |             | Component ATA:27 |
| SN:UNKNOWN               | HRS                                      | 0         |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.190              | AFL                                      | 0         |                  |                           |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: AMM 27-50-01   |                           |           |             |                  |
| 274621                   | LEFT INBOARD FLAP FLEXIBLE SHAFT         |           |                  |                           |                           |           |             |                  |
| PN:101-380000-1          | MOS/MSC                                  | 29-Dec-98 | O/C              |                           |                           |           |             | Component ATA:27 |
| SN:UNKNOWN               | HRS                                      | 0         |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.250              | AFL                                      | 0         |                  |                           |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: AMM 27-50-11   |                           |           |             |                  |
| 274622                   | INSPECT LEFT INBOARD FLAP FLEXIBLE SHAFT |           |                  |                           |                           |           |             |                  |
|                          | MOS                                      | 26-Nov-16 |                  |                           |                           |           |             | Service ATA:27   |
|                          | HRS                                      |           |                  |                           |                           |           |             |                  |
| WC#: 27.250              | AFL                                      | 4987      | 5000 (+10%/-10%) |                           | 9987                      | 10487     | 3492 (+500) |                  |
| 274626                   | LEFT OUTBOARD FLAP                       |           |                  |                           |                           |           |             |                  |
| PN:35-165050-216         | MOS/MSC                                  | 29-Dec-98 | O/C              |                           |                           |           |             | Component ATA:27 |
| SN:UNKNOWN               | HRS                                      | 0         |                  | TSN 0                     |                           |           |             |                  |
| WC#: 27.210              | AFL                                      | 0         |                  |                           |                           |           |             |                  |
|                          |                                          |           |                  | PROC. REF: AMM 27-50-01   |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                                                                                               | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 274646                   | LEFT OUTBOARD FLAP FLEXIBLE SHAFT                                                                                                  |           |                  |          |                           |           |             |                  |
| PN:101-380000-3          | MOS/MSC                                                                                                                            | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                                                                                                | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.250              | AFL                                                                                                                                | 0         |                  |          |                           |           |             |                  |
|                          | PROC. REF: AMM 27-50-11                                                                                                            |           |                  |          |                           |           |             |                  |
| 274647                   | INSPECT LEFT OUTBOARD FLAP FLEXIBLE SHAFT                                                                                          |           |                  |          |                           |           |             |                  |
|                          | MOS                                                                                                                                | 26-Nov-16 |                  |          |                           |           |             | Service ATA:27   |
|                          | HRS                                                                                                                                |           |                  |          |                           |           |             |                  |
| WC#: 27.250              | AFL                                                                                                                                | 4987      | 5000 (+10%/-10%) |          | 9987                      | 10487     | 3492 (+500) |                  |
| 275010                   | REMOVE LH OUTBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR. |           |                  |          |                           |           |             |                  |
|                          | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 252 d (+36) | Service ATA:27   |
|                          | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                          | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2755 (+300) |                  |
|                          | PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01                                                                                |           |                  |          |                           |           |             |                  |
| 275015                   | REMOVE LH INBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR.  |           |                  |          |                           |           |             |                  |
|                          | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 252 d (+36) | Service ATA:27   |
|                          | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                          | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2755 (+300) |                  |
|                          | PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01                                                                                |           |                  |          |                           |           |             |                  |
| 275020                   | REMOVE RH INBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR.  |           |                  |          |                           |           |             |                  |
|                          | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 252 d (+36) | Service ATA:27   |
|                          | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                          | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2755 (+300) |                  |
|                          | PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01                                                                                |           |                  |          |                           |           |             |                  |
| 275025                   | REMOVE RH OUTBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR. |           |                  |          |                           |           |             |                  |
|                          | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 252 d (+36) | Service ATA:27   |
|                          | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                          | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2755 (+300) |                  |
|                          | PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01                                                                                |           |                  |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                               | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                    |           |                   |          |                           |           |              |                  |
| 275101                   | RIGHT INBOARD FLAP                 |           |                   |          |                           |           |              |                  |
| PN:101-160001-20         | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.190              | AFL                                | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-01            |           |                   |          |                           |           |              |                  |
| 275109                   | FLAP MOTOR                         |           |                   |          |                           |           |              |                  |
| PN:100-384040            | MOS/MSC                            | 05-Feb-08 | O/C               | TSO 3    |                           |           |              | Component ATA:27 |
| SN:4679                  | HRS                                | 2235.7    |                   | TSO 0    |                           |           |              |                  |
| WC#: 27.170              | AFL                                | 2141      |                   | TSO 0    |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-03            |           |                   |          |                           |           |              |                  |
| 275110                   | INSPECT/REPLACE FLAP MOTOR         |           |                   |          |                           |           |              |                  |
| PN:PN                    | MOS                                | 29-Dec-98 |                   | TSN 0    |                           |           |              | Service ATA:27   |
| SN:UNKNOWN               | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| AFL                      | 0                                  | 0         | 10000 (+10%/-10%) | TSN 0    | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF          |           |                   |          |                           |           |              |                  |
| 275114                   | FLAP GEARBOX                       |           |                   |          |                           |           |              |                  |
| PN:100-524074-1          | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.170              | AFL                                | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-03            |           |                   |          |                           |           |              |                  |
| 275115                   | INSPECT/REPLACE FLAP MOTOR GEARBOX |           |                   |          |                           |           |              |                  |
| PN:PN                    | MOS                                | 29-Dec-98 |                   | TSN 0    |                           |           |              | Service ATA:27   |
| SN:UNKNOWN               | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| AFL                      | 0                                  | 0         | 10000 (+10%/-10%) | TSN 0    | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF          |           |                   |          |                           |           |              |                  |
| 275119                   | LEFT OUTBOARD FLAP ACTUATOR        |           |                   |          |                           |           |              |                  |
| PN:129-521051-1          | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:610-C-98              | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.200              | AFL                                | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-05            |           |                   |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                      | C/W       | Interval          | TSX/Adj.         | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-------------------------------------------|-----------|-------------------|------------------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                           |           |                   |                  |                           |           |              |                  |
| 275120                   | INSPECT/REPLACE LH OUTBOARD FLAP ACTUATOR |           |                   |                  |                           |           |              |                  |
|                          | MOS                                       | EFF       |                   |                  |                           |           |              | Service ATA:27   |
|                          | HRS                                       |           |                   |                  |                           |           |              |                  |
|                          | AFL                                       | EFF       | 10000 (+10%/-10%) |                  | 10000 *                   | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: AMM GENERIC 1                  |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |
| 275121                   | RIGHT INBOARD FLAP FLEXIBLE SHAFT         |           |                   |                  |                           |           |              |                  |
|                          | PN:101-380000-2                           | MOS/MSC   | 29-Dec-98         | O/C              |                           |           |              | Component ATA:27 |
|                          | SN:UNKNOWN                                | HRS       | 0                 | TSN 0            |                           |           |              |                  |
|                          | WC#: 27.260                               | AFL       | 0                 |                  |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-11                   |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |
| 275122                   | INSPECT RIGHT INBOARD FLAP FLEXIBLE SHAFT |           |                   |                  |                           |           |              |                  |
|                          | MOS                                       | 26-Nov-16 |                   |                  |                           |           |              | Service ATA:27   |
|                          | HRS                                       |           |                   |                  |                           |           |              |                  |
|                          | WC#: 27.260                               | AFL       | 4987              | 5000 (+10%/-10%) | 9987                      | 10487     | 3492 (+500)  |                  |
| 275124                   | LEFT INBOARD FLAP ACTUATOR                |           |                   |                  |                           |           |              |                  |
|                          | PN:101-521016-1                           | MOS/MSC   | 29-Dec-98         | O/C              |                           |           |              | Component ATA:27 |
|                          | SN:UNKNOWN                                | HRS       | 0                 | TSN 0            |                           |           |              |                  |
|                          | WC#: 27.200                               | AFL       | 0                 |                  |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-05                   |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |
| 275125                   | INSPECT/REPLACE LH INBOARD FLAP ACTUATOR  |           |                   |                  |                           |           |              |                  |
|                          | MOS                                       | 29-Dec-98 |                   |                  |                           |           |              | Service ATA:27   |
|                          | HRS                                       | 0         |                   |                  |                           |           |              |                  |
|                          | AFL                                       | 0         | 10000 (+10%/-10%) |                  | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                 |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |
| 275129                   | RIGHT INBOARD FLAP ACTUATOR               |           |                   |                  |                           |           |              |                  |
|                          | PN:101-521016-2                           | MOS/MSC   | 29-Dec-98         | O/C              |                           |           |              | Component ATA:27 |
|                          | SN:UNKNOWN                                | HRS       | 0                 | TSN 0            |                           |           |              |                  |
|                          | WC#: 27.220                               | AFL       | 0                 |                  |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-05                   |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |
| 275130                   | INSPECT/REPLACE RH INBOARD FLAP ACTUATOR  |           |                   |                  |                           |           |              |                  |
|                          | MOS                                       | 29-Dec-98 |                   |                  |                           |           |              | Service ATA:27   |
|                          | HRS                                       | 0         |                   |                  |                           |           |              |                  |
|                          | AFL                                       | 0         | 10000 (+10%/-10%) |                  | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                 |           |                   |                  |                           |           |              |                  |
|                          |                                           |           |                   |                  |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                      | C/W       | Interval                  | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-----------------------------------------------------------|-----------|---------------------------|---------------------------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                           |           |                           |                           |                           |           |              |                  |
| 275134                   | RIGHT OUTBOARD FLAP ACTUATOR                              |           |                           |                           |                           |           |              |                  |
| PN:129-521051-2          | MOS/MSC                                                   | 29-Dec-98 | O/C                       |                           |                           |           |              | Component ATA:27 |
| SN:610-J-98              | HRS                                                       | 0         |                           | TSN 0                     |                           |           |              |                  |
| WC#: 27.220              | AFL                                                       | 0         |                           |                           |                           |           |              |                  |
|                          |                                                           |           |                           | PROC. REF: AMM 27-50-05   |                           |           |              |                  |
| 275135                   | INSPECT/REPLACE RH OUTBOARD FLAP ACTUATOR                 |           |                           |                           |                           |           |              |                  |
|                          | MOS                                                       | 29-Dec-98 |                           |                           |                           |           |              | Service ATA:27   |
|                          | HRS                                                       | 0         |                           |                           |                           |           |              |                  |
|                          | AFL                                                       | 0         | 10000 (+10%/-10%)         |                           | 10000                     | 11000     | 3505 (+1000) |                  |
|                          |                                                           |           | PROC. REF: GENERIC NO REF |                           |                           |           |              |                  |
| 275139                   | LEFT OUTBOARD FLAP 90 DEGREE DRIVE                        |           |                           |                           |                           |           |              |                  |
| PN:50-380153-1           | MOS/MSC                                                   | 29-Dec-98 | O/C                       |                           |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                           | TSN 0                     |                           |           |              |                  |
| WC#: 27.240              | AFL                                                       | 0         |                           |                           |                           |           |              |                  |
|                          |                                                           |           |                           | PROC. REF: GENERIC NO REF |                           |           |              |                  |
| 275140                   | INSPECT/REPLACE LH OUTBOARD FLAP ACTUATOR 90 DEGREE DRIVE |           |                           |                           |                           |           |              |                  |
|                          | MOS                                                       | 29-Dec-98 |                           |                           |                           |           |              | Service ATA:27   |
|                          | HRS                                                       | 0         |                           |                           |                           |           |              |                  |
|                          | AFL                                                       | 0         | 10000 (+10%/-10%)         |                           | 10000                     | 11000     | 3505 (+1000) |                  |
|                          |                                                           |           | PROC. REF: GENERIC NO REF |                           |                           |           |              |                  |
| 275144                   | LEFT INBOARD FLAP 90 DEGREE DRIVE                         |           |                           |                           |                           |           |              |                  |
| PN:50-380153-3           | MOS/MSC                                                   | 29-Dec-98 | O/C                       |                           |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                           | TSN 0                     |                           |           |              |                  |
| WC#: 27.230              | AFL                                                       | 0         |                           |                           |                           |           |              |                  |
|                          |                                                           |           |                           | PROC. REF: GENERIC NO REF |                           |           |              |                  |
| 275145                   | INSPECT/REPLACE LH INBOARD FLAP ACTUATOR 90 DEGREE DRIVE  |           |                           |                           |                           |           |              |                  |
|                          | MOS                                                       | 29-Dec-98 |                           |                           |                           |           |              | Service ATA:27   |
|                          | HRS                                                       | 0         |                           |                           |                           |           |              |                  |
|                          | AFL                                                       | 0         | 10000 (+10%/-10%)         |                           | 10000                     | 11000     | 3505 (+1000) |                  |
|                          |                                                           |           | PROC. REF: GENERIC NO REF |                           |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                      | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-----------------------------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                           |           |                   |          |                           |           |              |                  |
| 275149                   | RIGHT INBOARD FLAP 90 DEGREE DRIVE                        |           |                   |          |                           |           |              |                  |
| PN:50-380153-2           | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.230              | AFL                                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF                                 |           |                   |          |                           |           |              |                  |
| 275150                   | INSPECT/REPLACE RH INBOARD FLAP ACTUATOR 90 DEGREE DRIVE  |           |                   |          |                           |           |              |                  |
|                          | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              | Service ATA:27   |
|                          | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                          | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                                 |           |                   |          |                           |           |              |                  |
| 275154                   | RIGHT OUTBOARD FLAP 90 DEGREE DRIVE                       |           |                   |          |                           |           |              |                  |
| PN:50-380153-4           | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.240              | AFL                                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: GENERIC NO REF                                 |           |                   |          |                           |           |              |                  |
| 275155                   | INSPECT/REPLACE RH OUTBOARD FLAP ACTUATOR 90 DEGREE DRIVE |           |                   |          |                           |           |              |                  |
|                          | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              | Service ATA:27   |
|                          | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                          | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3505 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                                 |           |                   |          |                           |           |              |                  |
| 275601                   | RIGHT OUTBOARD FLAP                                       |           |                   |          |                           |           |              |                  |
| PN:35-165050-217         | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.210              | AFL                                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-01                                   |           |                   |          |                           |           |              |                  |
| 275621                   | RIGHT OUTBOARD FLAP FLEXIBLE SHAFT                        |           |                   |          |                           |           |              |                  |
| PN:101-380000-4          | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              | Component ATA:27 |
| SN:UNKNOWN               | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.260              | AFL                                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-11                                   |           |                   |          |                           |           |              |                  |
| 275622                   | INSPECT RIGHT OUTBOARD FLAP FLEXIBLE SHAFT                |           |                   |          |                           |           |              |                  |
|                          | MOS                                                       | 26-Nov-16 |                   |          |                           |           |              | Service ATA:27   |
|                          | HRS                                                       |           |                   |          |                           |           |              |                  |
| WC#: 27.260              | AFL                                                       | 4987      | 5000 (+10%/-10%)  |          | 9987                      | 10487     | 3492 (+500)  |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                                                                                        | C/W       | Interval            | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------|-----------|---------------------|-------------------------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                                                                                             |           |                     |                         |                           |           |              |                  |
| 276001                   | INSPECT ALL FLIGHT CONTROL PULLEY BRACKETS AND CASTINGS FOR CRACKS CORROSION, WEAR AND ATTACHMENT(PRIORITY AREA INSPECTION) |           |                     |                         |                           |           |              |                  |
|                          | MOS                                                                                                                         | 29-Dec-98 |                     |                         |                           |           |              | Service ATA:27   |
|                          | HRS                                                                                                                         |           |                     |                         |                           |           |              | MANDATORY        |
| WC#: 27.270              | AFL                                                                                                                         | 0         | T:10000 (+10%/-10%) |                         | 10000                     | 11000     | 3505 (+1000) |                  |
| ATA 28 - FUEL            |                                                                                                                             |           |                     |                         |                           |           |              |                  |
| 280101                   | LEFT LEADING EDGE INBOARD FUEL CELL                                                                                         |           |                     |                         |                           |           |              |                  |
| PN:101-381002-11         | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              | Component ATA:28 |
| SN:98-69411              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.010              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-11 |                           |           |              |                  |
| 280106                   | LEFT LEADING EDGE OUTBOARD FUEL CELL                                                                                        |           |                     |                         |                           |           |              |                  |
| PN:002-920013-1          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              | Component ATA:28 |
| SN:98-72552              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.020              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-13 |                           |           |              |                  |
| 280111                   | LEFT AFT INBOARD FUEL CELL                                                                                                  |           |                     |                         |                           |           |              |                  |
| PN:50-389034-17          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              | Component ATA:28 |
| SN:98-71127              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.030              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-17 |                           |           |              |                  |
| 280116                   | LEFT AFT OUTBOARD FUEL CELL                                                                                                 |           |                     |                         |                           |           |              |                  |
| PN:101-381001-7          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              | Component ATA:28 |
| SN:98-67819              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.040              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-15 |                           |           |              |                  |
| 280121                   | LEFT NACELLE FUEL CELL                                                                                                      |           |                     |                         |                           |           |              |                  |
| PN:99-380000-23          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              | Component ATA:28 |
| SN:98-65366              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.050              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-09 |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                      | Unit    | C/W       | Interval | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------|---------|-----------|----------|-------------------------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                |         |           |          |                         |                           |           |           |                  |
| 280126 LEFT AUXILIARY FUEL CELL              |         |           |          |                         |                           |           |           |                  |
| PN:FFC2179-7                                 | MOS/MSC | 05-Apr-22 | O/C      | TSN 0                   |                           |           |           | Component ATA:28 |
| SN:CR1290                                    | HRS     | 5338.1    |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.060                                  | AFL     | 6256      |          | TSN 0                   |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-19 |                           |           |           |                  |
| 280131 RIGHT LEADING EDGE INBOARD FUEL CELL  |         |           |          |                         |                           |           |           |                  |
| PN:101-381002-12                             | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:98-69594                                  | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.010                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-11 |                           |           |           |                  |
| 280136 RIGHT LEADING EDGE OUTBOARD FUEL CELL |         |           |          |                         |                           |           |           |                  |
| PN:002-920013-2                              | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:98-72879                                  | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.020                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-13 |                           |           |           |                  |
| 280139 RIGHT AFT INBOARD FUEL CELL           |         |           |          |                         |                           |           |           |                  |
| PN:50-389034-18                              | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:98-71485                                  | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.030                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-17 |                           |           |           |                  |
| 280141 RIGHT AFT OUTBOARD FUEL CELL          |         |           |          |                         |                           |           |           |                  |
| PN:101-381001-8                              | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:98-68027                                  | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.040                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-15 |                           |           |           |                  |
| 280146 RIGHT NACELLE FUEL CELL               |         |           |          |                         |                           |           |           |                  |
| PN:99-380000-25                              | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:98-65520                                  | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.050                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-09 |                           |           |           |                  |
| 280151 RIGHT AUXILIARY FUEL CELL             |         |           |          |                         |                           |           |           |                  |
| PN:101-381001-2                              | MOS/MSC | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                   | HRS     | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 28.060                                  | AFL     | 0         |          |                         |                           |           |           |                  |
|                                              |         |           |          | PROC. REF: AMM 28-10-19 |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN       | Unit                                                                                             | C/W              | Interval  | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------|--------------------------------------------------------------------------------------------------|------------------|-----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL |                                                                                                  |                  |           |           |                           |           |           |                  |
| 280601        | LEFT NACELLE FUEL CELL FLAPPER VALVE                                                             |                  |           |           |                           |           |           |                  |
| PN:24C189     | MOS/MSC                                                                                          | 29-Dec-98        | O/C       |           |                           |           |           | Component ATA:28 |
| SN:UNKNOWN    | HRS                                                                                              | 0                |           | TSN 0     |                           |           |           |                  |
| WC#: 28.080   | AFL                                                                                              | 0                |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-10-09                                                                          |                  |           |           |                           |           |           |                  |
| 280606        | LEFT INBOARD LEADING EDGE FUEL CELL DRAIN VALVE                                                  |                  |           |           |                           |           |           |                  |
| PN:CCA3400    | MOS/MSC                                                                                          | 29-Dec-98        | O/C       |           |                           |           |           | Component ATA:28 |
| SN:UNKNOWN    | HRS                                                                                              | 0                |           | TSN 0     |                           |           |           |                  |
| WC#: 28.090   | AFL                                                                                              | 0                |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-10-11                                                                          |                  |           |           |                           |           |           |                  |
| 280611        | LEFT WING FUEL DRAIN VALVE                                                                       |                  |           |           |                           |           |           |                  |
| PN:710C4X     | MOS/MSC                                                                                          | 29-Dec-98        | O/C       |           |                           |           |           | Component ATA:28 |
| SN:UNKNOWN    | HRS                                                                                              | 0                |           | TSN 0     |                           |           |           |                  |
| WC#: 28.100   | AFL                                                                                              | 0                |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-10-11                                                                          |                  |           |           |                           |           |           |                  |
| 281000        | INSPECT LEFT NACELLE AND AUX FUEL CELLS AND PROBES - INSPECT FOR MICROBIOLOGICAL SLUDGE BUILDUP  |                  |           |           |                           |           |           |                  |
| MOS           | 22-May-24                                                                                        | 30 (+18d/-18d)   | 22-Nov-26 | 10-Dec-26 | 860 d (+18)               |           |           | Service ATA:28   |
| HRS           | 5686.2                                                                                           | 2400 (+10%/-10%) | 8086.2    | 8326.2    | 2400 (+240)               |           |           |                  |
| AFL           | 6495                                                                                             |                  |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-40-01                                                                          |                  |           |           |                           |           |           |                  |
| 281010        | INSPECT RIGHT NACELLE AND AUX FUEL CELLS AND PROBES - INSPECT FOR MICROBIOLOGICAL SLUDGE BUILDUP |                  |           |           |                           |           |           |                  |
| MOS           | 24-Mar-22                                                                                        | 30 (+18d/-18d)   | 24-Sep-24 | 12-Oct-24 | 71 d (+18)                |           |           | Service ATA:28   |
| HRS           | 5331.5                                                                                           | 2400 (+10%/-10%) | 7731.5    | 7971.5    | 2045.3 (+240)             |           |           |                  |
| AFL           | 6250                                                                                             |                  |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-40-01                                                                          |                  |           |           |                           |           |           |                  |
| 281101        | RIGHT NACELLE FUEL CELL FLAPPER VALVE                                                            |                  |           |           |                           |           |           |                  |
| PN:24C189     | MOS/MSC                                                                                          | 29-Dec-98        | O/C       |           |                           |           |           | Component ATA:28 |
| SN:UNKNOWN    | HRS                                                                                              | 0                |           | TSN 0     |                           |           |           |                  |
| WC#: 28.080   | AFL                                                                                              | 0                |           |           |                           |           |           |                  |
|               | PROC. REF: AMM 28-10-09                                                                          |                  |           |           |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN           | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL     |                                                  |           |          |          |                           |           |           |                  |
| 281106            | RIGHT INBOARD LEADING EDGE FUEL CELL DRAIN VALVE |           |          |          |                           |           |           |                  |
| PN:CCA3400        | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.090       | AFL                                              | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-10-11                          |           |          |          |                           |           |           |                  |
| 281111            | RIGHT WING FUEL DRAIN VALVE                      |           |          |          |                           |           |           |                  |
| PN:710C4X         | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.100       | AFL                                              | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-10-11                          |           |          |          |                           |           |           |                  |
| 281206            | LEFT WING TIP TANK                               |           |          |          |                           |           |           |                  |
| PN:PN             | MOS/MSC                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.070       | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 28-10-25                          |           |          |          |                           |           |           |                  |
| 281256            | RIGHT WING TIP TANK                              |           |          |          |                           |           |           |                  |
| PN:PN             | MOS/MSC                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.070       | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 28-10-25                          |           |          |          |                           |           |           |                  |
| 281601            | LEFT AUXILIARY CELL INBOARD PROBE                |           |          |          |                           |           |           |                  |
| PN:100-380006-151 | MOS/MSC                                          | 07-Jul-20 | O/C      | TSR 0    |                           |           |           | Component ATA:28 |
| SN:3448           | HRS                                              | 5181.7    |          | TSR 0    |                           |           |           |                  |
| WC#: 28.110       | AFL                                              | 6136      |          | TSR 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 28-40-07                          |           |          |          |                           |           |           |                  |
| 281606            | LEFT AUXILIARY CELL OUTBOARD PROBE               |           |          |          |                           |           |           |                  |
| PN:100-380006-171 | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:1527           | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120       | AFL                                              | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-40-07                          |           |          |          |                           |           |           |                  |
| 281611            | LEFT INBOARD WING CELL PROBE                     |           |          |          |                           |           |           |                  |
| PN:100-380006-71  | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.170       | AFL                                              | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN           | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL     |                                        |           |          |          |                           |           |           |                  |
| 281616            | LEFT INBOARD LEADING EDGE CELL PROBE   |           |          |          |                           |           |           |                  |
| PN:100-380006-69  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.150       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-40-03                |           |          |          |                           |           |           |                  |
| 281621            | LEFT OUTBOARD LEADING EDGE CELL PROBE  |           |          |          |                           |           |           |                  |
| PN:100-380006-81  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.160       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |
| 281626            | LEFT OUTBOARD WING CELL INBOARD PROBE  |           |          |          |                           |           |           |                  |
| PN:100-380006-93  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |
| 281631            | LEFT OUTBOARD WING CELL OUTBOARD PROBE |           |          |          |                           |           |           |                  |
| PN:100-380006-95  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.140       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |
| 281636            | RIGHT AUXILIARY CELL INBOARD PROBE     |           |          |          |                           |           |           |                  |
| PN:100-380006-83  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.110       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-40-07                |           |          |          |                           |           |           |                  |
| 281641            | RIGHT AUXILIARY CELL OUTBOARD PROBE    |           |          |          |                           |           |           |                  |
| PN:100-380006-171 | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:1535           | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 28-40-07                |           |          |          |                           |           |           |                  |
| 281646            | RIGHT INBOARD WING CELL PROBE          |           |          |          |                           |           |           |                  |
| PN:100-380006-71  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.170       | AFL                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                        | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                  |         |           |          |          |                           |           |           |                  |
| 281651 RIGHT INBOARD LEADING EDGE CELL PROBE   |         |           |          |          |                           |           |           |                  |
| PN:100-380006-69                               | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.150                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-03                        |         |           |          |          |                           |           |           |                  |
| 281656 RIGHT OUTBOARD LEADING EDGE CELL PROBE  |         |           |          |          |                           |           |           |                  |
| PN:100-380006-81                               | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.160                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                      |         |           |          |          |                           |           |           |                  |
| 281661 RIGHT OUTBOARD WING CELL INBOARD PROBE  |         |           |          |          |                           |           |           |                  |
| PN:100-380006-93                               | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                      |         |           |          |          |                           |           |           |                  |
| 281666 RIGHT OUTBOARD WING CELL OUTBOARD PROBE |         |           |          |          |                           |           |           |                  |
| PN:100-380006-95                               | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.140                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                      |         |           |          |          |                           |           |           |                  |
| 282101 LEFT AUXILIARY FUEL CELL JET PUMP       |         |           |          |          |                           |           |           |                  |
| PN:99-389005-1                                 | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:8096                                        | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.180                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-05                        |         |           |          |          |                           |           |           |                  |
| 282106 LEFT AUXILIARY FUEL CELL CHECK VALVE    |         |           |          |          |                           |           |           |                  |
| PN:869A10BB/030/-0                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.190                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                      |         |           |          |          |                           |           |           |                  |
| 282111 LEFT AUXILIARY FUEL CELL DRAIN VALVE    |         |           |          |          |                           |           |           |                  |
| PN:CCA4850                                     | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.200                                    | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                      |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                      | Unit    | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------|---------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                |         |           |          |            |                           |           |           |                  |
| 282116 RIGHT AUXILIARY FUEL CELL JET PUMP    |         |           |          |            |                           |           |           |                  |
| PN:99-389005-1                               | MOS/MSC | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:8144                                      | HRS     | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.180                                  | AFL     | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-05                      |         |           |          |            |                           |           |           |                  |
| 282121 RIGHT AUXILIARY FUEL CELL CHECK VALVE |         |           |          |            |                           |           |           |                  |
| PN:869A10BB/030/-0                           | MOS/MSC | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                   | HRS     | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.190                                  | AFL     | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |            |                           |           |           |                  |
| 282126 RIGHT AUXILIARY FUEL CELL DRAIN VALVE |         |           |          |            |                           |           |           |                  |
| PN:CCA4850                                   | MOS/MSC | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                   | HRS     | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.200                                  | AFL     | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |            |                           |           |           |                  |
| 282131 LEFT NACELLE FUEL QUANTITY PROBE      |         |           |          |            |                           |           |           |                  |
| PN:100-380006-119                            | MOS/MSC | 07-Jul-20 | O/C      | TSR 0      |                           |           |           | Component ATA:28 |
| SN:105214                                    | HRS     | 5181.7    |          | TSR 0      |                           |           |           |                  |
| WC#: 28.330                                  | AFL     | 6136      |          | TSR 0      |                           |           |           |                  |
| PROC. REF: AMM 28-40-01                      |         |           |          |            |                           |           |           |                  |
| 282136 RIGHT NACELLE FUEL QUANTITY PROBE     |         |           |          |            |                           |           |           |                  |
| PN:100-380006-77                             | MOS/MSC | 21-Oct-09 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                   | HRS     | 2449.4    |          | TSN 2449.4 |                           |           |           |                  |
| WC#: 28.330                                  | AFL     | 2445      |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-40-01                      |         |           |          |            |                           |           |           |                  |
| 282601 LEFT FUEL CONTROL PURGE VALVE         |         |           |          |            |                           |           |           |                  |
| PN:50-389109-9                               | MOS/MSC | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:13454                                     | HRS     | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.260                                  | AFL     | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-11                      |         |           |          |            |                           |           |           |                  |
| 282606 RIGHT FUEL CONTROL PURGE VALVE        |         |           |          |            |                           |           |           |                  |
| PN:50-389109-9                               | MOS/MSC | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:28 |
| SN:13492                                     | HRS     | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.260                                  | AFL     | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-11                      |         |           |          |            |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                      | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                |         |           |          |          |                           |           |           |                  |
| 283101 LEFT STAND-BY FUEL PUMP               |         |           |          |          |                           |           |           |                  |
| PN:50-380177-5                               | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:8AP177                                    | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.210                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-03                      |         |           |          |          |                           |           |           |                  |
| 283106 RIGHT STAND-BY FUEL PUMP              |         |           |          |          |                           |           |           |                  |
| PN:50-380177-5                               | MOS/MSC | 17-Aug-05 | O/C      | TSO 0    |                           |           |           | Component ATA:28 |
| SN:8BA92                                     | HRS     | 1834.8    |          | TSO 0    |                           |           |           |                  |
| WC#: 28.210                                  | AFL     | 1645      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-03                      |         |           |          |          |                           |           |           |                  |
| 283111 FUEL CROSSFEED VALVE                  |         |           |          |          |                           |           |           |                  |
| PN:50-389095                                 | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:T27047                                    | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.270                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |          |                           |           |           |                  |
| 283601 LEFT FUEL PRESSURE SWITCH             |         |           |          |          |                           |           |           |                  |
| PN:100-389018-23                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:10855                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.220                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |          |                           |           |           |                  |
| 283606 LEFT AUXILIARY FUEL CELL FLOAT SWITCH |         |           |          |          |                           |           |           |                  |
| PN:101-389034-7                              | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.230                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |          |                           |           |           |                  |
| 283611 LEFT MOTIVE FLOW PRESSURE SWITCH      |         |           |          |          |                           |           |           |                  |
| PN:101-389004-3                              | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:9089                                      | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.240                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-13                      |         |           |          |          |                           |           |           |                  |
| 283616 RIGHT FUEL PRESSURE SWITCH            |         |           |          |          |                           |           |           |                  |
| PN:100-389018-23                             | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:28 |
| SN:10898                                     | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.220                                  | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                       | Unit    | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------|---------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                 |         |           |          |                   |                           |           |           |                  |
| 283621 RIGHT AUXILIARY FUEL CELL FLOAT SWITCH |         |           |          |                   |                           |           |           |                  |
| PN:101-389034-7                               | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.230                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 283626 RIGHT MOTIVE FLOW PRESSURE SWITCH      |         |           |          |                   |                           |           |           |                  |
| PN:101-389004-3                               | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:9082                                       | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.240                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-20-13                       |         |           |          |                   |                           |           |           |                  |
| 284005 LEFT FUEL FLOW INDICATOR               |         |           |          |                   |                           |           |           |                  |
| PN:90-380037-1                                | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:521061                                     | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.340                                   | AFL     | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 284010 RIGHT FUEL FLOW INDICATOR              |         |           |          |                   |                           |           |           |                  |
| PN:90-380037-1                                | MOS/MSC | 07-Feb-20 | O/C      | TSR 0             |                           |           |           | Component ATA:28 |
| SN:520004                                     | HRS     | 5159.5    |          | TSN 5159.5, TSR 0 |                           |           |           |                  |
| WC#: 28.340                                   | AFL     | 6110      |          | TSN 6110, TSR 0   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 284101 LEFT WING FUEL VENT FLOAT VALVE        |         |           |          |                   |                           |           |           |                  |
| PN:100-920048-19                              | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.290                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-10-31                       |         |           |          |                   |                           |           |           |                  |
| 284106 RIGHT WING FUEL VENT FLOAT VALVE       |         |           |          |                   |                           |           |           |                  |
| PN:100-920048-20                              | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.290                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-10-31                       |         |           |          |                   |                           |           |           |                  |
| 284116 LEFT FIREWALL FUEL SHUTOFF VALVE       |         |           |          |                   |                           |           |           |                  |
| PN:101-389025-5                               | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:28 |
| SN:2324                                       | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.280                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-20-07                       |         |           |          |                   |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                       | Unit    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------------------------------------|---------|-----------|----------|---------------------------|---------------------------|-----------|-----------|---------------------|
| ATA 28 - FUEL                                 |         |           |          |                           |                           |           |           |                     |
| 284121      RIGHT FIREWALL FUEL SHUTOFF VALVE |         |           |          |                           |                           |           |           |                     |
| PN:101-389025-5                               | MOS/MSC | 22-May-24 | O/C      | TSO 0                     |                           |           |           | Component    ATA:28 |
| SN:23-051                                     | HRS     | 5686.2    |          | TSO 0                     |                           |           |           |                     |
| WC#: 28.280                                   | AFL     | 6495      |          | TSO 0                     |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: AMM 28-20-07   |                           |           |           |                     |
| 284126      LEFT TRANSFER MOTIVE FLOW VALVE   |         |           |          |                           |                           |           |           |                     |
| PN:100-389020-1                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:80331767                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.250                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: AMM 28-20-13   |                           |           |           |                     |
| 284131      RIGHT TRANSFER MOTIVE FLOW VALVE  |         |           |          |                           |                           |           |           |                     |
| PN:100-389020-1                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:60503159                                   | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.250                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: AMM 28-20-13   |                           |           |           |                     |
| 284601      LEFT WING FUEL HEATED VENT        |         |           |          |                           |                           |           |           |                     |
| PN:112633                                     | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.300                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: AMM 28-10-29   |                           |           |           |                     |
| 284606      RIGHT WING FUEL HEATED VENT       |         |           |          |                           |                           |           |           |                     |
| PN:112633                                     | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.300                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: AMM 28-10-29   |                           |           |           |                     |
| 284623      LEFT FUEL QUANTITY INDICATOR      |         |           |          |                           |                           |           |           |                     |
| PN:101-380006-47                              | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.310                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 284626      RIGHT FUEL QUANTITY INDICATOR     |         |           |          |                           |                           |           |           |                     |
| PN:117-384019-3                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:28 |
| SN:9836-1675                                  | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 28.310                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                    |                                          |           |          |          |                           |           |           |                  |
| 284631                           | TIP TANK FUEL QUANTITY GAUGE             |           |          |          |                           |           |           |                  |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.310                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: AMM 28-40-09                  |           |          |          |                           |           |           |                  |
| 284636                           | LEFT TIP TANK FUEL QUANTITY TRANSMITTER  |           |          |          |                           |           |           |                  |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.320                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: AMM 28-40-09                  |           |          |          |                           |           |           |                  |
| 284646                           | RIGHT TIP TANK FUEL QUANTITY TRANSMITTER |           |          |          |                           |           |           |                  |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.320                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: AMM 28-40-09                  |           |          |          |                           |           |           |                  |
| 572210                           | LEFT HAND LEADING EDGE CAP               |           |          |          |                           |           |           |                  |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.350                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: AMM GENERIC 1                 |           |          |          |                           |           |           |                  |
| 572211                           | RH LEADING EDGE CAP ASSEM REPLACE        |           |          |          |                           |           |           |                  |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:28 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF                |           |          |          |                           |           |           |                  |
| ATA 30 - ICE AND RAIN PROTECTION |                                          |           |          |          |                           |           |           |                  |
| 300101                           | LEFT BLEED AIR PRESSURE SHUTOFF VALVE    |           |          |          |                           |           |           |                  |
| PN:101-380013-13                 | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.010                      | AFL                                      | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: AMM 36-10-03                  |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|----------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                        |           |          |          |                           |           |           |                     |
| 300106                           | RIGHT BLEED AIR PRESSURE SHUTOFF VALVE |           |          |          |                           |           |           |                     |
| PN:3206310013-13                 | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:30 |
| SN:UNKNOWN                       | HRS                                    | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 30.010                      | AFL                                    | 0         |          |          |                           |           |           |                     |
|                                  | PROC. REF: AMM 36-10-03                |           |          |          |                           |           |           |                     |
| 300111                           | LEFT BLEED AIR PRESSURE CHECK VALVE    |           |          |          |                           |           |           |                     |
| PN:101-381000-9                  | MOS/MSC                                | 14-Apr-05 | O/C      | TSO 0    |                           |           |           | Component    ATA:30 |
| SN:2425A                         | HRS                                    | 1744.9    |          | TSO 0    |                           |           |           |                     |
| WC#: 30.020                      | AFL                                    | 1501      |          | TSO 0    |                           |           |           |                     |
|                                  | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                     |
| 300116                           | RIGHT BLEED AIR PRESSURE CHECK VALVE   |           |          |          |                           |           |           |                     |
| PN:101-381000-9                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:30 |
| SN:12554                         | HRS                                    | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 30.020                      | AFL                                    | 0         |          |          |                           |           |           |                     |
|                                  | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                     |
| 300121                           | DE-ICER DISTRIBUTION VALVE             |           |          |          |                           |           |           |                     |
| PN:101-384144-3                  | MOS/MSC                                | 23-Aug-05 | O/C      | TSO 1    |                           |           |           | Component    ATA:30 |
| SN:B1940                         | HRS                                    | 1838.7    |          | TSO 0    |                           |           |           |                     |
| WC#: 30.030                      | AFL                                    | 1654      |          | TSO 0    |                           |           |           |                     |
|                                  | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                     |
| 300126                           | DE-ICE DIFFERENTIAL PRESSURE SWITCH    |           |          |          |                           |           |           |                     |
| PN:101-360035-7                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:30 |
| SN:UNKNOWN                       | HRS                                    | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 30.030                      | AFL                                    | 0         |          |          |                           |           |           |                     |
|                                  | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                     |
| 300131                           | DE-ICE EJECTOR                         |           |          |          |                           |           |           |                     |
| PN:101-384149-1                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:30 |
| SN:9AP110                        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 30.030                      | AFL                                    | 0         |          |          |                           |           |           |                     |
|                                  | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                     |
| 300601                           | LEFT HORIZONTAL STABILIZER DE-ICE BOOT |           |          |          |                           |           |           |                     |
| PN:SMR5041-05                    | MOS/MSC                                | 13-Feb-19 | O/C      | TSN 4    |                           |           |           | Component    ATA:30 |
| SN:3016                          | HRS                                    | 5082.9    |          | TSN 0    |                           |           |           |                     |
| WC#: 30.040                      | AFL                                    | 6044      |          | TSN 0    |                           |           |           |                     |
|                                  | PROC. REF: AMM 30-10-01                |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                         |           |          |                           |                           |           |           |                  |
| 300606                           | RIGHT HORIZONTAL STABILIZER DE-ICE BOOT |           |          |                           |                           |           |           |                  |
| PN:SMR5041-5                     | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 13                    |                           |           |           | Component ATA:30 |
| SN:2911                          | HRS                                     | 5082.9    |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.040                      | AFL                                     | 6044      |          | TSN 0                     |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: AMM 30-10-01   |                           |           |           |                  |
| 300611                           | LEFT WING CENTER SECTION DE-ICE BOOT    |           |          |                           |                           |           |           |                  |
| PN:101-380001-25                 | MOS/MSC                                 | 12-Apr-23 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 5500.3    |          |                           |                           |           |           |                  |
| WC#: 30.050                      | AFL                                     | 6358      |          |                           |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: AMM 30-10-01   |                           |           |           |                  |
| 300616                           | LEFT OUTBOARD WING DE-ICE BOOT          |           |          |                           |                           |           |           |                  |
| PN:SMR5041-01                    | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:30 |
| SN:2262                          | HRS                                     | 5082.9    |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.060                      | AFL                                     | 6044      |          | TSN 0                     |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: AMM 30-10-01   |                           |           |           |                  |
| 300621                           | RIGHT WING CENTER SECTION DE-ICE BOOT   |           |          |                           |                           |           |           |                  |
| PN:101-380001-25                 | MOS/MSC                                 | 12-Apr-23 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 5500.3    |          |                           |                           |           |           |                  |
| WC#: 30.050                      | AFL                                     | 6358      |          |                           |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: AMM 30-10-01   |                           |           |           |                  |
| 300626                           | RIGHT OUTBOARD WING DE-ICE BOOT         |           |          |                           |                           |           |           |                  |
| PN:SMR5041-02                    | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:30 |
| SN:2442                          | HRS                                     | 5082.9    |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.060                      | AFL                                     | 6044      |          | TSN 0                     |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: AMM 30-10-01   |                           |           |           |                  |
| 300631                           | DE-ICE PRESSURE GAUGE                   |           |          |                           |                           |           |           |                  |
| PN:50-380105-1                   | MOS/MSC                                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:F98230                        | HRS                                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.070                      | AFL                                     | 0         |          |                           |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 301015                           | LEFT PNEUMATIC VALVE                    |           |          |                           |                           |           |           |                  |
| PN:101-381011-11                 | MOS/MSC                                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:11228                         | HRS                                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 36.030                      | AFL                                     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                  |                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                       |           |          |          |                           |           |           |                  |
| 301020                           | RIGHT PNEUMATIC VALVE                 |           |          |          |                           |           |           |                  |
| PN:101-381011-11                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:11248                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 36.030                      | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 301101                           | LEFT INERTIAL VANE ACTUATOR           |           |          |          |                           |           |           |                  |
| PN:114-389039-23                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:1981F                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.090                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: AMM 30-20-13               |           |          |          |                           |           |           |                  |
| 301106                           | RIGHT INERTIAL VANE ACTUATOR          |           |          |          |                           |           |           |                  |
| PN:114-389039-23                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:1947F                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.090                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: AMM 30-20-13               |           |          |          |                           |           |           |                  |
| 301601                           | WINDSHIELD HEAT CONTROLLER            |           |          |          |                           |           |           |                  |
| PN:100-364295-3                  | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.100                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 302101                           | LEFT WINDSHIELD WIPER BLADE ASSEMBLY  |           |          |          |                           |           |           |                  |
| PN:50-384082-1                   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.110                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 302106                           | RIGHT WINDSHIELD WIPER BLADE ASSEMBLY |           |          |          |                           |           |           |                  |
| PN:50-384082-1                   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.110                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 302111                           | LEFT WINDSHIELD WIPER ARM ASSEMBLY    |           |          |          |                           |           |           |                  |
| PN:99-384026                     | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.120                      | AFL                                   | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: AMM 30-40-03               |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                     |           |          |                           |                           |           |           |                  |
| 302116                           | RIGHT WINDSHIELD WIPER ARM ASSEMBLY |           |          |                           |                           |           |           |                  |
| PN:99-384026                     | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.120                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: AMM 30-40-03   |                           |           |           |                  |
| 302121                           | LEFT WINDSHIELD WIPER CONVERTER     |           |          |                           |                           |           |           |                  |
| PN:50-380070-3                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: AMM 30-40-03   |                           |           |           |                  |
| 302126                           | RIGHT WINDSHIELD WIPER CONVERTER    |           |          |                           |                           |           |           |                  |
| PN:50-380070-4                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: AMM 30-40-03   |                           |           |           |                  |
| 302131                           | WINDSHIELD WIPER MOTOR              |           |          |                           |                           |           |           |                  |
| PN:101-384165-1                  | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:01372                         | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: AMM 30-40-01   |                           |           |           |                  |
| 302136                           | FLEXIBLE DRIVE ASSEMBLY             |           |          |                           |                           |           |           |                  |
| PN:50-384083-5                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.140                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 302141                           | CENTER FLEXIBLE DRIVE ASSEMBLY      |           |          |                           |                           |           |           |                  |
| PN:50-384083-7                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.140                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 302601                           | PROPELLER DE-ICE AMMETER            |           |          |                           |                           |           |           |                  |
| PN:90-380007-13                  | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:30 |
| SN:759                           | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 30.150                      | AFL                                 | 0         |          |                           |                           |           |           |                  |
|                                  |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                         |           |          |          |                           |           |           |                  |
| 302606                           | PROPELLER DE-ICE TIMER ASSEMBLY         |           |          |          |                           |           |           |                  |
| PN:B-45018                       | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:980043                        | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.160                      | AFL                                     | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302611                           | NO. 1 PROPELLER DE-ICE BRUSH BLOCK      |           |          |          |                           |           |           |                  |
| PN:3E2090-1                      | MOS/MSC                                 | 12-Apr-23 | O/C      | TSN 0    |                           |           |           | Component ATA:30 |
| SN:N3002135                      | HRS                                     | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.170                      | AFL                                     | 6358      |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302616                           | NO. 2 PROPELLER DE-ICE BRUSH BLOCK      |           |          |          |                           |           |           |                  |
| PN:3E2090-1                      | MOS/MSC                                 | 12-Apr-23 | O/C      | TSN 0    |                           |           |           | Component ATA:30 |
| SN:N3002139                      | HRS                                     | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.170                      | AFL                                     | 6358      |          | TSN 0    |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302636                           | NO. 1 PROP DE-ICE MANUAL OVERRIDE RELAY |           |          |          |                           |           |           |                  |
| PN:KCJ2A                         | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.180                      | AFL                                     | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302641                           | NO. 2 PROP DE-ICE MANUAL OVERRIDE RELAY |           |          |          |                           |           |           |                  |
| PN:KCJ2A                         | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.180                      | AFL                                     | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302646                           | NO. 1 PROP DE-ICE SLIP RING ASSEMBLY    |           |          |          |                           |           |           |                  |
| PN:4E1555-2                      | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.190                      | AFL                                     | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |
| 302651                           | NO. 2 PROP DE-ICE SLIP RING ASSEMBLY    |           |          |          |                           |           |           |                  |
| PN:4E1555-3                      | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.190                      | AFL                                     | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                             |           |          |          |                           |           |           |                  |
| 302656                           | NO. 1 PROP NO.1 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302657                           | NO. 1 PROP NO.2 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302658                           | NO. 1 PROP NO.3 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302659                           | NO. 1 PROP NO.4 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.220                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302661                           | NO. 2 PROP NO.1 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302662                           | NO. 2 PROP NO.2 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |
| 302663                           | NO. 2 PROP NO.3 DE-ICE BOOT |           |          |          |                           |           |           |                  |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
|                                  | PROC. REF: GENERIC NO REF   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                               | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION      |                                  |           |          |          |                           |           |           |                  |
| 302664                                | NO. 2 PROP NO.4 DE-ICE BOOT      |           |          |          |                           |           |           |                  |
| PN:4E1188-5                           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:30 |
| SN:UNKNOWN                            | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.220                           | AFL                              | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                  |           |          |          |                           |           |           |                  |
| 310005                                | ROSEMONT O.A.T. PROBE            |           |          |          |                           |           |           |                  |
| PN:0129F                              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:31 |
| SN:A20994                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.060                           | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 310101                                | PILOT CLOCK                      |           |          |          |                           |           |           |                  |
| PN:6420093-1                          | MOS/MSC                          | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:31 |
| SN:D19-11196                          | HRS                              | 5104.4    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.010                           | AFL                              | 6064      |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 310106                                | COPILOT CLOCK                    |           |          |          |                           |           |           |                  |
| PN:101-384092-1                       | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:31 |
| SN:840428                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.010                           | AFL                              | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 310111                                | FLIGHT HOURMETER                 |           |          |          |                           |           |           |                  |
| PN:101-3292-0001                      | MOS/MSC                          | 13-Feb-19 | O/C      | TSN 0    |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                            | HRS                              | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.020                           | AFL                              | 6044      |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |
| 310116                                | FLIGHT HOURMETER PRESSURE SWITCH |           |          |          |                           |           |           |                  |
| PN:M4006                              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                            | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.020                           | AFL                              | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF        |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                             | Unit    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|---------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS               |         |           |          |                           |                           |           |           |                  |
| 311005 STALL LIFT COMPUTER                          |         |           |          |                           |                           |           |           |                  |
| PN:101-380005-41                                    | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:31 |
| SN:3189                                             | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 31.030                                         | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 311010 FLIGHT CONTROL PANEL                         |         |           |          |                           |                           |           |           |                  |
| PN:622-5798-008                                     | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:31 |
| SN:4781                                             | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 31.040                                         | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 311020 RIGHT ATTITUDE GYRO                          |         |           |          |                           |                           |           |           |                  |
| PN:1U149-001-6                                      | MOS/MSC | 10-Nov-06 | O/C      |                           |                           |           |           | Component ATA:31 |
| SN:T75919P                                          | HRS     | 2076.4    |          |                           |                           |           |           |                  |
| WC#: 31.070                                         | AFL     |           |          |                           |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 314000 <sup>U</sup> GARMIN GCU 485 MODE CONTROLLER  |         |           |          |                           |                           |           |           |                  |
| PN:011-03582-02                                     | MOS/MSC | 05-Sep-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:31 |
| SN:3QR20045                                         | HRS     | 5104.4    |          | TSN 0                     |                           |           |           |                  |
|                                                     | AFL     | 6064      |          | TSN 0                     |                           |           |           |                  |
| 314001 NO. 1 IN/OUT CONCENTRATOR, IOC-3100 REPLACE  |         |           |          |                           |                           |           |           |                  |
| PN:PN                                               | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: AMM 31-40-05   |                           |           |           |                  |
| 314002 NO. 2 IN/OUT CONCENTRATOR, IOC-3100 REPLACE  |         |           |          |                           |                           |           |           |                  |
| PN:PN                                               | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: AMM 31-40-05   |                           |           |           |                  |
| 314004 NO. 1 OCM-3100 OPTION CONTROL MODULE REPLACE |         |           |          |                           |                           |           |           |                  |
| PN:PN                                               | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                     |         |           |          | PROC. REF: AMM GENERIC 1  |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                               | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                              |           |          |          |                           |           |           |                  |
| 314005                                | NO. 2 OCM-3100 OPTION CONTROL MODULE REPLACE |           |          |          |                           |           |           |                  |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:31 |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: AMM GENERIC 1                     |           |          |          |                           |           |           |                  |
| 315000 <sup>U</sup>                   | MAP 65 MODE ANNUNCIATOR                      |           |          |          |                           |           |           |                  |
| PN:622-5799-001                       | MOS/MSC                                      | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:31 |
| SN:805                                | HRS                                          | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 6064      |          | TSN 0    |                           |           |           |                  |
| ATA 32 - LANDING GEAR                 |                                              |           |          |          |                           |           |           |                  |
| 301080                                | LH BRAKE DEICE VALVE                         |           |          |          |                           |           |           |                  |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: AMM GENERIC 1                     |           |          |          |                           |           |           |                  |
| 301085                                | RH BRAKE DEICE VALVE                         |           |          |          |                           |           |           |                  |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | PROC. REF: AMM GENERIC 1                     |           |          |          |                           |           |           |                  |
| 320141                                | UP LIMIT SWITCH                              |           |          |          |                           |           |           |                  |
| PN:BZ2RQ181A2                         | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.040                           | AFL                                          | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 320146                                | DOWN LIMIT SWITCH                            |           |          |          |                           |           |           |                  |
| PN:BZ2RQ181A2                         | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.040                           | AFL                                          | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 320601                                | LEFT MAIN LANDING GEAR                       |           |          |          |                           |           |           |                  |
| PN:101-810171-601                     | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:647-A-98                           | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.070                           | AFL                                          | 0         |          |          |                           |           |           |                  |
|                                       | PROC. REF: AMM 32-10-03                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                               | Unit                                                                                      | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|-------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                                           |           |                  |          |                           |           |              |                  |
| 320602                                | INSPECT LEFT MAIN LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |          |                           |           |              |                  |
|                                       | MOS                                                                                       | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2137 d (+60) | Service ATA:32   |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.395                           | AFL                                                                                       | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 8000 (+800)  |                  |
| 320605                                | INSPECT LEFT MAIN LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES            |           |                  |          |                           |           |              |                  |
|                                       | MOS                                                                                       | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2137 d (+60) | Service ATA:32   |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.395                           | AFL                                                                                       | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 8000 (+800)  |                  |
| 320631                                | LEFT MAIN LANDING GEAR ACTUATOR                                                           |           |                  |          |                           |           |              |                  |
|                                       | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
|                                       | HRS                                                                                       | 0         |                  |          |                           |           |              |                  |
| SN: UNKNOWN                           |                                                                                           |           |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-30-03               |                                                                                           |           |                  |          |                           |           |              |                  |
| 320641                                | INSPECT LEFT MAIN LANDING GEAR ACTUATOR CLEVIS HOLE                                       |           |                  |          |                           |           |              |                  |
|                                       | MOS                                                                                       | 22-May-24 |                  |          |                           |           |              | Service ATA:32   |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                                       | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 1000 (+100)  |                  |
| 320657                                | LEFT MAIN LANDING GEAR ACTUATOR SUPPORT BEARINGS                                          |           |                  |          |                           |           |              |                  |
|                                       | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
|                                       | HRS                                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| SN: UNKNOWN                           |                                                                                           |           |                  |          |                           |           |              |                  |
| WC#: 32.080                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                                                                           |           |                  |          |                           |           |              |                  |
| 320660                                | LEFT MAIN LANDING GEAR DRAG BRACE ASSEMBLY                                                |           |                  |          |                           |           |              |                  |
|                                       | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          | TSN 0                     |           |              | Component ATA:32 |
|                                       | HRS                                                                                       | 0         |                  |          | TSN 0                     |           |              |                  |
| SN: UNKNOWN                           |                                                                                           |           |                  |          | TSN 0                     |           |              |                  |
| WC#: 32.110                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                           |           |                  |          |                           |           |              |                  |
| 320661                                | LEFT UPPER R/H DRAG BRACE                                                                 |           |                  |          |                           |           |              |                  |
|                                       | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
|                                       | HRS                                                                                       | 0         |                  |          | TSN 0                     |           |              |                  |
| SN: UNKNOWN                           |                                                                                           |           |                  |          |                           |           |              |                  |
| WC#: 32.110                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                           |           |                  |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                                                       | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-----------------------|--------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR |                                                                                            |           |                  |          |                           |           |              |                  |
| 320666                | RIGHT UPPER R/H DRAG BRACE                                                                 |           |                  |          |                           |           |              |                  |
| PN:50-810337-10       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.110           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                                                      |           |                  |          |                           |           |              |                  |
| 320671                | LEFT LOWER DRAG BRACE                                                                      |           |                  |          |                           |           |              |                  |
| PN:101-810035-1       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.130           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                                                      |           |                  |          |                           |           |              |                  |
| 320681                | LEFT MAIN LANDING GEAR UP POSITION INDICATOR SWITCH                                        |           |                  |          |                           |           |              |                  |
| PN:100-381006-1       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.180           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                                                      |           |                  |          |                           |           |              |                  |
| 320691                | LEFT MAIN LANDING GEAR DOWN POSITION INDICATOR SWITCH                                      |           |                  |          |                           |           |              |                  |
| PN:100-381006-1       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.190           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                                                      |           |                  |          |                           |           |              |                  |
| 321101                | RIGHT MAIN LANDING GEAR                                                                    |           |                  |          |                           |           |              |                  |
| PN:101-810171-601     | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              | Component ATA:32 |
| SN:647-B-98           | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.070           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
|                       | PROC. REF: AMM 32-10-03                                                                    |           |                  |          |                           |           |              |                  |
| 321102                | INSPECT RIGHT MAIN LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |          |                           |           |              |                  |
|                       | MOS                                                                                        | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2137 d (+60) | Service ATA:32   |
|                       | HRS                                                                                        | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.400           | AFL                                                                                        | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 8000 (+800)  |                  |
|                       | PROC. REF: AMM 32-10-01                                                                    |           |                  |          |                           |           |              |                  |
| 321105                | INSPECT RIGHT MAIN LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES            |           |                  |          |                           |           |              |                  |
|                       | MOS                                                                                        | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2137 d (+60) | Service ATA:32   |
|                       | HRS                                                                                        | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.400           | AFL                                                                                        | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 8000 (+800)  |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                 | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-----------------------|------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR |                                                      |           |                  |          |                           |           |             |                  |
| 321131                | RIGHT MAIN LANDING GEAR ACTUATOR                     |           |                  |          |                           |           |             |                  |
| PN:99-810057-603      | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  |          |                           |           |             |                  |
| WC#: 32.100           | AFL                                                  | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-30-03                              |           |                  |          |                           |           |             |                  |
| 321141                | INSPECT RIGHT MAIN LANDING GEAR ACTUATOR CLEVIS HOLE |           |                  |          |                           |           |             |                  |
|                       | MOS                                                  | 22-May-24 |                  |          |                           |           |             | Service ATA:32   |
|                       | HRS                                                  | 5686.2    |                  |          |                           |           |             |                  |
| WC#: 32.100           | AFL                                                  | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 1000 (+100) |                  |
| 321157                | RIGHT MAIN LANDING GEAR ACTUATOR SUPPORT BEARINGS    |           |                  |          |                           |           |             |                  |
| PN:115-380102         | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.080           | AFL                                                  | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: GENERIC NO REF                            |           |                  |          |                           |           |             |                  |
| 321160                | RIGHT MAIN LANDING GEAR DRAG BRACE ASSEMBLY          |           |                  |          |                           |           |             |                  |
| PN:PN                 | MOS/MSC                                              | 29-Dec-98 | O/C              | TSN 0    |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
|                       | AFL                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                |           |                  |          |                           |           |             |                  |
| 321161                | LEFT UPPER L/H DRAG BRACE                            |           |                  |          |                           |           |             |                  |
| PN:50-810337-9        | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.120           | AFL                                                  | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                |           |                  |          |                           |           |             |                  |
| 321166                | RIGHT UPPER L/H DRAG BRACE                           |           |                  |          |                           |           |             |                  |
| PN:50-810337-10       | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.120           | AFL                                                  | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                |           |                  |          |                           |           |             |                  |
| 321171                | RIGHT LOWER DRAG BRACE                               |           |                  |          |                           |           |             |                  |
| PN:50-810335-1        | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                  | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.130           | AFL                                                  | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-10-07, AMM 32-11-01                |           |                  |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                                                                                     | Unit      | C/W              | Interval  | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------------------------------------------------------------|-----------|------------------|-----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                                       |           |                  |           |            |                           |           |           |                  |
| 321181 RIGHT MAIN LANDING GEAR UP POSITION INDICATOR SWITCH                                 |           |                  |           |            |                           |           |           |                  |
| PN:100-381006-1                                                                             | MOS/MSC   | 29-Dec-98        | O/C       |            |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                                                                  | HRS       | 0                |           | TSN 0      |                           |           |           |                  |
| WC#: 32.180                                                                                 | AFL       | 0                |           |            |                           |           |           |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01                                                       |           |                  |           |            |                           |           |           |                  |
| 321191 RIGHT MAIN LANDING GEAR DOWN POSITION INDICATOR SWITCH                               |           |                  |           |            |                           |           |           |                  |
| PN:100-381006-1                                                                             | MOS/MSC   | 29-Dec-98        | O/C       |            |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                                                                  | HRS       | 0                |           | TSN 0      |                           |           |           |                  |
| WC#: 32.190                                                                                 | AFL       | 0                |           |            |                           |           |           |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01                                                       |           |                  |           |            |                           |           |           |                  |
| 321601 LEFT LANDING GEAR SAFETY SWITCH                                                      |           |                  |           |            |                           |           |           |                  |
| PN:MC815AS1                                                                                 | MOS/MSC   | 29-Dec-98        | O/C       |            |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                                                                  | HRS       | 0                |           | TSN 0      |                           |           |           |                  |
| WC#: 32.190                                                                                 | AFL       | 0                |           |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                                   |           |                  |           |            |                           |           |           |                  |
| 321610 L/H MLG SAFETY SWITCH                                                                |           |                  |           |            |                           |           |           |                  |
| PN:PN                                                                                       | MOS/MSC   | 29-Dec-98        | O/C       | TSN 0      |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                                                                  | HRS       | 0                |           | TSN 0      |                           |           |           |                  |
| WC#: 32.490                                                                                 | AFL       | 0                |           | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                                   |           |                  |           |            |                           |           |           |                  |
| 322101 NOSE LANDING GEAR                                                                    |           |                  |           |            |                           |           |           |                  |
| PN:101-820020-15                                                                            | MOS/MSC   | 07-Aug-12        | O/C       |            |                           |           |           | Component ATA:32 |
| SN:643-A-98                                                                                 | HRS       | 2825.9           |           | TSN 2825.9 |                           |           |           |                  |
| WC#: 32.140                                                                                 | AFL       | 2944             |           |            |                           |           |           |                  |
| PROC. REF: AMM 32-20-05                                                                     |           |                  |           |            |                           |           |           |                  |
| 322102 INSPECT NOSE LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |           |            |                           |           |           |                  |
| MOS                                                                                         | 22-May-24 | 72 (+60d/-60d)   | 22-May-30 | 21-Jul-30  | 2137 d (+60)              |           |           | Service ATA:32   |
| HRS                                                                                         | 5686.2    |                  |           |            |                           |           |           |                  |
| AFL                                                                                         | 6495      | 8000 (+10%/-10%) | 14495     | 15295      | 8000 (+800)               |           |           |                  |
| PROC. REF: AMM 32-20-01                                                                     |           |                  |           |            |                           |           |           |                  |
| 322105 INSPECT NOSE LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES            |           |                  |           |            |                           |           |           |                  |
| MOS                                                                                         | 22-May-24 | 72 (+60d/-60d)   | 22-May-30 | 21-Jul-30  | 2137 d (+60)              |           |           | Service ATA:32   |
| HRS                                                                                         | 5686.2    |                  |           |            |                           |           |           |                  |
| AFL                                                                                         | 6495      | 8000 (+10%/-10%) | 14495     | 15295      | 8000 (+800)               |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                           | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-----------------------|------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR |                                                |           |                  |          |                           |           |             |                  |
| 322151                | NOSE LANDING GEAR ACTUATOR                     |           |                  |          |                           |           |             |                  |
| PN:112-380022-21      | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  |          |                           |           |             |                  |
| WC#: 32.150           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-30-07                        |           |                  |          |                           |           |             |                  |
| 322161                | INSPECT NOSE LANDING GEAR ACTUATOR CLEVIS HOLE |           |                  |          |                           |           |             |                  |
|                       | MOS                                            | 22-May-24 |                  |          |                           |           |             | Service ATA:32   |
|                       | HRS                                            | 5686.2    |                  |          |                           |           |             |                  |
| WC#: 32.150           | AFL                                            | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 1000 (+100) |                  |
| 322165                | NOSE LANDING GEAR ACTUATOR SUPPORT BEARINGS    |           |                  |          |                           |           |             |                  |
| PN:50-380043          | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.080           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: GENERIC NO REF                      |           |                  |          |                           |           |             |                  |
| 322171                | NOSE LANDING GEAR UPPER DRAG LEG               |           |                  |          |                           |           |             |                  |
| PN:50-820205-17       | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.170           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: AMM 32-20-09                        |           |                  |          |                           |           |             |                  |
| 322176                | NOSE LANDING GEAR LEFT LOWER DRAG LEG          |           |                  |          |                           |           |             |                  |
| PN:50-820205-23       | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.170           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: GENERIC NO REF                      |           |                  |          |                           |           |             |                  |
| 322181                | NOSE LANDING GEAR RIGHT LOWER DRAG LEG         |           |                  |          |                           |           |             |                  |
| PN:50-820205-23       | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.170           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: GENERIC NO REF                      |           |                  |          |                           |           |             |                  |
| 322186                | NOSE LANDING GEAR UP POSITION SWITCH           |           |                  |          |                           |           |             |                  |
| PN:1CH25              | MOS/MSC                                        | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:32 |
| SN:UNKNOWN            | HRS                                            | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 32.200           | AFL                                            | 0         |                  |          |                           |           |             |                  |
|                       | PROC. REF: GENERIC NO REF                      |           |                  |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                       | Unit    | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------|---------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                         |         |           |          |                   |                           |           |           |                  |
| 322191 NOSE LANDING GEAR DOWN POSITION SWITCH |         |           |          |                   |                           |           |           |                  |
| PN:1CH25                                      | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.200                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 322611 NOSE LANDING GEAR SHIMMY DAMPER        |         |           |          |                   |                           |           |           |                  |
| PN:50-820004-1                                | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.210                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 32-20-03                       |         |           |          |                   |                           |           |           |                  |
| 322621 NOSE LANDING GEAR STEERING LINK        |         |           |          |                   |                           |           |           |                  |
| PN:50-820034-3                                | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.220                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 322641 NOSE WHEEL                             |         |           |          |                   |                           |           |           |                  |
| PN:3-1481                                     | MOS/MSC | 22-May-24 | O/C      | TSO 0             |                           |           |           | Component ATA:32 |
| SN:4507                                       | HRS     | 5686.2    |          | TSN 5686.2, TSO 0 |                           |           |           |                  |
| WC#: 32.240                                   | AFL     | 6495      |          | TSN 6495, TSO 0   |                           |           |           |                  |
| PROC. REF: AMM 32-40-19                       |         |           |          |                   |                           |           |           |                  |
| 322643 NOSE TIRE                              |         |           |          |                   |                           |           |           |                  |
| PN:265K08-1                                   | MOS/MSC | 22-May-24 | O/C      | TSN 13            |                           |           |           | Component ATA:32 |
| SN:12790094                                   | HRS     | 5686.2    |          | TSN 185.9         |                           |           |           |                  |
| WC#: 32.240                                   | AFL     | 6495      |          | TSN 137           |                           |           |           |                  |
| PROC. REF: AMM 32-40-19                       |         |           |          |                   |                           |           |           |                  |
| 322651 LANDING GEAR WARNING HORN              |         |           |          |                   |                           |           |           |                  |
| PN:169-380021-9                               | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:32 |
| SN:UNKNOWN                                    | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.230                                   | AFL     | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |
| 323005 LANDING GEAR HANDLE                    |         |           |          |                   |                           |           |           |                  |
| PN:101-384137-7                               | MOS/MSC | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:32 |
| SN:1689A                                      | HRS     | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.430                                   | AFL     | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                     |         |           |          |                   |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                       |           |          |          |                           |           |           |                  |
| 323010                | POWER PACK SENSOR                     |           |          |          |                           |           |           |                  |
| PN:99-388007-3        | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:1931A              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.440           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-31-19, AMM 32-31-01 |           |          |          |                           |           |           |                  |
| 323015                | LANDING GEAR HYDRAULIC SERVICE VALVE  |           |          |          |                           |           |           |                  |
| PN:101-388008-3       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:2729               | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.450           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 323030                | EMERGENCY EXTENSION HAND PUMP         |           |          |          |                           |           |           |                  |
| PN:101-388007-3       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:2739               | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.460           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 323101                | HYDRAULIC BRAKE RESERVOIR             |           |          |          |                           |           |           |                  |
| PN:50-580039          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.290           | AFL                                   | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |
| 323166                | LEFT PARKING BRAKE VALVE              |           |          |          |                           |           |           |                  |
| PN:4500S-A1           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300           | AFL                                   | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-13               |           |          |          |                           |           |           |                  |
| 323176                | RIGHT PARKING BRAKE VALVE             |           |          |          |                           |           |           |                  |
| PN:4500S-A1           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300           | AFL                                   | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-13               |           |          |          |                           |           |           |                  |
| 323186                | LEFT BRAKE SHUTTLE VALVE              |           |          |          |                           |           |           |                  |
| PN:101-580000-13      | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.310           | AFL                                   | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                                                  |           |          |          |                           |           |           |                  |
| 323191                | RIGHT BRAKE SHUTTLE VALVE                                        |           |          |          |                           |           |           |                  |
| PN:101-580000-13      | MOS/MSC                                                          | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.310           | AFL                                                              | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                                        |           |          |          |                           |           |           |                  |
| 323601                | LEFT OUTBOARD (NO. 1) BRAKE                                      |           |          |          |                           |           |           |                  |
| PN:30-146             | MOS/MSC                                                          | 03-Feb-06 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:3106               | HRS                                                              | 1942.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.340           | AFL                                                              | 1774      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-15, AMM 32-40-17                            |           |          |          |                           |           |           |                  |
| 323603                | REPLACE LEFT LEFT BRAKE HOSES (ONLY HOSES EXPOSED IN WHEEL WELL) |           |          |          |                           |           |           |                  |
|                       | MOS                                                              | 26-Jul-22 | 60       |          | 26-Jul-27                 |           | 1106 d    |                  |
|                       | HRS                                                              | 5351.6    |          |          |                           |           |           |                  |
| WC#: 32.090           | AFL                                                              | 6269      |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                                        |           |          |          |                           |           |           |                  |
| 323606                | LEFT INBOARD (NO. 2) BRAKE                                       |           |          |          |                           |           |           |                  |
| PN:30-146             | MOS/MSC                                                          | 03-Feb-06 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:3109               | HRS                                                              | 1942.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.340           | AFL                                                              | 1774      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-15, AMM 32-40-17                            |           |          |          |                           |           |           |                  |
| 323611                | LEFT OUTBOARD MAIN WHEEL                                         |           |          |          |                           |           |           |                  |
| PN:PN-UNKNOWN         | MOS/MSC                                                          | 10-Aug-23 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:1388               | HRS                                                              | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.250           | AFL                                                              | 6398      |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                            |           |          |          |                           |           |           |                  |
| 323613                | LEFT OUTBOARD MAIN TIRE                                          |           |          |          |                           |           |           |                  |
| PN:196K08-9           | MOS/MSC                                                          | 10-Aug-23 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:30540288           | HRS                                                              | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.250           | AFL                                                              | 6398      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                            |           |          |          |                           |           |           |                  |
| 323626                | LEFT INBOARD MAIN WHEEL                                          |           |          |          |                           |           |           |                  |
| PN:PN-UNKNOWN         | MOS/MSC                                                          | 10-Aug-23 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:6094               | HRS                                                              | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.260           | AFL                                                              | 6398      |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                            |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                                                    |           |          |          |                           |           |           |                  |
| 323629                | LEFT INBOARD MAIN TIRE                                             |           |          |          |                           |           |           |                  |
| PN:196K08-9           | MOS/MSC                                                            | 10-Aug-23 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:30140268           | HRS                                                                | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.260           | AFL                                                                | 6398      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                              |           |          |          |                           |           |           |                  |
| 323641                | RIGHT INBOARD (NO. 3) BRAKE                                        |           |          |          |                           |           |           |                  |
| PN:30-146             | MOS/MSC                                                            | 03-Feb-06 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:3103               | HRS                                                                | 1942.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.350           | AFL                                                                | 1774      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-15, AMM 32-40-17                              |           |          |          |                           |           |           |                  |
| 323643                | REPLACE RIGHT RIGHT BRAKE HOSES (ONLY HOSES EXPOSED IN WHEEL WELL) |           |          |          |                           |           |           |                  |
|                       | MOS                                                                | 26-Jul-22 | 60       |          | 26-Jul-27                 |           | 1106 d    |                  |
|                       | HRS                                                                | 5351.6    |          |          |                           |           |           |                  |
| WC#: 32.090           | AFL                                                                | 6269      |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 323646                | RIGHT OUTBOARD (NO. 4) BRAKE                                       |           |          |          |                           |           |           |                  |
| PN:30-146             | MOS/MSC                                                            | 03-Feb-06 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:3108               | HRS                                                                | 1942.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.350           | AFL                                                                | 1774      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-15, AMM 32-40-17                              |           |          |          |                           |           |           |                  |
| 323651                | RIGHT INBOARD MAIN WHEEL                                           |           |          |          |                           |           |           |                  |
| PN:PN-UNKNOWN         | MOS/MSC                                                            | 10-Aug-23 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:2234-1             | HRS                                                                | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.270           | AFL                                                                | 6398      |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                              |           |          |          |                           |           |           |                  |
| 323653                | RIGHT INBOARD MAIN TIRE                                            |           |          |          |                           |           |           |                  |
| PN:196K08-9           | MOS/MSC                                                            | 10-Aug-23 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:30140295           | HRS                                                                | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.270           | AFL                                                                | 6398      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                              |           |          |          |                           |           |           |                  |
| 323666                | RIGHT OUTBOARD MAIN WHEEL                                          |           |          |          |                           |           |           |                  |
| PN:PN-UNKNOWN         | MOS/MSC                                                            | 10-Aug-23 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:3534               | HRS                                                                | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.280           | AFL                                                                | 6398      |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                              |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                                         |           |          |          |                           |           |           |                  |
| 323669                | RIGHT OUTBOARD MAIN TIRE                                |           |          |          |                           |           |           |                  |
| PN:196K08-9           | MOS/MSC                                                 | 10-Aug-23 | O/C      | TSN 0    |                           |           |           | Component ATA:32 |
| SN:30540275           | HRS                                                     | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.280           | AFL                                                     | 6398      |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-25, AMM 32-40-27                   |           |          |          |                           |           |           |                  |
| 324005                | PILOT LEFT BRAKE CYLINDER                               |           |          |          |                           |           |           |                  |
| PN:90-380001-33       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.470           | AFL                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-11                                 |           |          |          |                           |           |           |                  |
| 324010                | PILOT RIGHT BRAKE CYLINDER                              |           |          |          |                           |           |           |                  |
| PN:90-380001-33       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.470           | AFL                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-11                                 |           |          |          |                           |           |           |                  |
| 324015                | COPILOT LEFT BRAKE CYLINDER                             |           |          |          |                           |           |           |                  |
| PN:90-380001-33       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.480           | AFL                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-11                                 |           |          |          |                           |           |           |                  |
| 324020                | COPILOT RIGHT BRAKE CYLINDER                            |           |          |          |                           |           |           |                  |
| PN:90-380001-33       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:UNKNOWN            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.480           | AFL                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                       | PROC. REF: AMM 32-40-11                                 |           |          |          |                           |           |           |                  |
| 324101                | LANDING GEAR HYDRAULIC POWER PACK                       |           |          |          |                           |           |           |                  |
| PN:101-388005-21      | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:MX604894           | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.360           | AFL                                                     | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-31-01                                 |           |          |          |                           |           |           |                  |
| 324103                | REPLACE LANDING GEAR HYDRAULIC POWER PACK SYSTEM FILTER |           |          |          |                           |           |           |                  |
|                       | MOS                                                     | 12-Apr-23 |          |          |                           |           |           | Service ATA:32   |
|                       | HRS                                                     | 5500.3    | 1200     |          | 6700.3                    |           | 1014.1    | SCRAP            |
| WC#: 32.360           | AFL                                                     | 6358      | 1000     |          | 7358                      |           | 863       |                  |
|                       | PROC. REF: AMM 32-31-09, AMM 32-31-11                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                                 |           |          |          |                           |           |           |                  |
| 324111                | LANDING GEAR HYDRAULIC ACCUMULATOR              |           |          |          |                           |           |           |                  |
| PN:101-388009-5       | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:32 |
| SN:2679               | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.370           | AFL                                             | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: AMM 32-31-21                         |           |          |          |                           |           |           |                  |
| 324121                | REPLACE LANDING GEAR RETRACTION/EXTENSION HOSES |           |          |          |                           |           |           |                  |
|                       | MOS                                             | 13-Feb-19 | 120      |          | 13-Feb-29                 |           | 1674 d    | Service ATA:32   |
|                       | HRS                                             | 5082.9    |          |          |                           |           |           | SCRAP            |
| WC#: 32.390           | AFL                                             | 6044      |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                       |           |          |          |                           |           |           |                  |
| ATA 33 - LIGHTS       |                                                 |           |          |          |                           |           |           |                  |
| 330101                | TAIL STROBE LIGHT                               |           |          |          |                           |           |           |                  |
| PN:101-360020-3       | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN            | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010           | AFL                                             | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                       |           |          |          |                           |           |           |                  |
| 330106                | LEFT WING STROBE LIGHT                          |           |          |          |                           |           |           |                  |
| PN:70-1148-7-2        | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN            | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010           | AFL                                             | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                       |           |          |          |                           |           |           |                  |
| 330111                | RIGHT WING STROBE LIGHT                         |           |          |          |                           |           |           |                  |
| PN:70-1148-7-2        | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN            | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010           | AFL                                             | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                       |           |          |          |                           |           |           |                  |
| 330116                | STROBE LIGHT POWER SUPPLY                       |           |          |          |                           |           |           |                  |
| PN:60-1750-3          | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN            | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.020           | AFL                                             | 0         |          |          |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                       |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS |                                      |           |          |          |                           |           |           |                  |
| 330200          | LH WING TIP RECOGNITION LIGHT CHANGE |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: AMM GENERIC 1             |           |          |          |                           |           |           |                  |
| 330201          | RH WING TIP RECOGNITION LIGHT CHANGE |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: AMM GENERIC 1             |           |          |          |                           |           |           |                  |
| 330202          | NAV LIGHT CHANGE                     |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: AMM GENERIC 1             |           |          |          |                           |           |           |                  |
| 330301          | UPPER ANTI-COLLISION LIGHT           |           |          |          |                           |           |           |                  |
| PN:101-360020-3 | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.030     | AFL                                  | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF            |           |          |          |                           |           |           |                  |
| 330306          | LOWER ANTI-COLLISION LIGHT           |           |          |          |                           |           |           |                  |
| PN:90033-4      | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:2119387      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.030     | AFL                                  | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF            |           |          |          |                           |           |           |                  |
| 330601          | LEFT LANDING LIGHT                   |           |          |          |                           |           |           |                  |
| PN:AN-3176-1    | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.040     | AFL                                  | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF            |           |          |          |                           |           |           |                  |
| 330606          | RIGHT LANDING LIGHT                  |           |          |          |                           |           |           |                  |
| PN:AN-3176-1    | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:33 |
| SN:UNKNOWN      | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.040     | AFL                                  | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF            |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                       | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|------------------------------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS     |                                                            |           |          |            |                           |           |           |                  |
| 330611              | TAXI LIGHT                                                 |           |          |            |                           |           |           |                  |
| PN:B4150B           | MOS/MSC                                                    | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:33 |
| SN:UNKNOWN          | HRS                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 33.040         | AFL                                                        | 0         |          |            |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                  |           |          |            |                           |           |           |                  |
| 330615              | CHECK EDGELIGHTED PANELS FOR CONDITION                     |           |          |            |                           |           |           |                  |
|                     | MOS/MSC                                                    | 14-Dec-18 | N/A      |            |                           |           |           | Service ATA:33   |
|                     | HRS                                                        | 5079.9    |          |            |                           |           |           |                  |
| WC#: 33.050         | AFL                                                        | 6043      |          |            |                           |           |           |                  |
|                     | PROC. REF: AMM 33-10-01                                    |           |          |            |                           |           |           |                  |
| 332001 <sup>U</sup> | INSPECT EMERGENCY EXIT SIGN (SELF-ILLUMINATING)            |           |          |            |                           |           |           |                  |
| PN:PN               | MOS                                                        | 22-May-24 | 12       |            | 22-May-25                 |           | 311 d     | Service ATA:33   |
| SN:UNKNOWN          | HRS                                                        | 5686.2    |          |            |                           |           |           |                  |
| WC#: 33.080         | AFL                                                        | 6495      |          |            |                           |           |           |                  |
| 334005              | POWER PACK                                                 |           |          |            |                           |           |           |                  |
| PN:100-384118-21    | MOS/MSC                                                    | 29-Dec-98 | O/C      |            |                           |           |           | Component ATA:33 |
| SN:HTS-03072        | HRS                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 33.060         | AFL                                                        | 0         |          | TSN 0      |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                  |           |          |            |                           |           |           |                  |
| 335000              | REPLACE RIGHT HAND EMERGENCY EXIT SIGN (SELF-ILLUMINATING) |           |          |            |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                    |           | A/R      |            |                           |           |           | Component ATA:33 |
| SN:UNKNOWN          | HRS                                                        |           |          |            |                           |           |           |                  |
|                     | AFL                                                        |           |          |            |                           |           |           |                  |
|                     | PROC. REF: AMM 33-50-01                                    |           |          |            |                           |           |           |                  |
| 335001 <sup>U</sup> | REPLACE EMERGENCY EXIT SIGN (SELF-ILLUMINATING)            |           |          |            |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                    | 07-Feb-20 | A/R      | TSN 254    |                           |           |           | Component ATA:33 |
| SN:UNKNOWN          | HRS                                                        | 5159.5    |          | TSN 5159.5 |                           |           |           |                  |
|                     | AFL                                                        | 6110      |          | TSN 6110   |                           |           |           |                  |
| 335002              | INSPECT RIGHT HAND EMERGENCY EXIT SIGN (SELF-ILLUMINATING) |           |          |            |                           |           |           |                  |
| PN:PN               | MOS                                                        | 22-May-24 | 12       |            | 22-May-25                 |           | 311 d     | Service ATA:33   |
| SN:UNKNOWN          | HRS                                                        | 5686.2    |          |            |                           |           |           |                  |
|                     | AFL                                                        | 6495      |          |            |                           |           |           |                  |
|                     | PROC. REF: AMM 33-50-01                                    |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                                       |           |          |          |                           |           |           |                  |
| 340002 <sup>U</sup>       | GARMIN G600 TXI SYSTEM INSTALLATION IAW STC SA02571SE                 |           |          |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                               | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                | HRS                                                                   | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                   | 6064      |          | TSN 0    |                           |           |           |                  |
| 340002.1 <sup>U</sup>     | GARMIN G600TXI ICA DOCUMENTS                                          |           |          |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                               | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                | HRS                                                                   | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                   | 6064      |          | TSN 0    |                           |           |           |                  |
| 340004 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - 12 MO INSPECTIONS                |           |          |          |                           |           |           |                  |
|                           | MOS                                                                   | 22-May-24 | 12       |          | 31-May-25                 |           | 320 d     | Service ATA:34   |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| 340005 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - RVSM CHECKS                      |           |          |          |                           |           |           |                  |
|                           | MOS                                                                   | 22-May-24 | 24       |          | 31-May-26                 |           | 685 d     | Service ATA:34   |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| 340006                    | NO. 1 DUAL NAVIGATION MARKER BEACON COUPLER                           |           |          |          |                           |           |           |                  |
| PN:101-380042             | MOS/MSC                                                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:34 |
| SN:24115                  | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.440               | AFL                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 340007 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - AHRS MAGNETIC FIELD MODEL UPDATE |           |          |          |                           |           |           |                  |
|                           | MOS                                                                   | 22-May-24 | 60       |          | 31-May-29                 |           | 1781 d    | Service ATA:34   |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| 340008 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE ICA - ELECTRICAL BONDING CHECK           |           |          |          |                           |           |           |                  |
|                           | MOS                                                                   | 05-Sep-19 | 120      |          | 30-Sep-29                 |           | 1903 d    | Service ATA:34   |
|                           | HRS                                                                   | 5104.4    | 2000     |          | 7104.4                    |           | 1418.2    |                  |
|                           | AFL                                                                   | 6064      |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                                                                             | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------|----------------------------------------------------------------------------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 34 - NAVIGATION |                                                                                                                                  |           |           |          |                           |           |           |                     |
| 340009 <sup>U</sup> | GARMIN G600TXI STC SA02571SE - ICA - GDU 1060 COOLING FAN REPLACEMENT (3000 FAN OPERATING HOURS - READ FAN HRS BEFORE COMPLYING) |           |           |          |                           |           |           |                     |
|                     | MOS                                                                                                                              | 05-Sep-19 |           |          |                           |           |           | Service    ATA:34   |
|                     | HRS                                                                                                                              | 5104.4    | 3000      |          | 8104.4                    |           | 2418.2    |                     |
|                     | AFL                                                                                                                              | 6064      |           |          |                           |           |           |                     |
|                     | GARMIN G600TXI STC SA02571SE - ICA - GBB54 BATTERY BACKUP CHECK                                                                  |           |           |          |                           |           |           |                     |
|                     | MOS                                                                                                                              | 22-May-24 | 12        |          | 31-May-25                 |           | 320 d     | Service    ATA:34   |
|                     | HRS                                                                                                                              | 5686.2    |           |          |                           |           |           |                     |
|                     | AFL                                                                                                                              | 6495      |           |          |                           |           |           |                     |
|                     | EQUIPMENT REMOVAL & REPLACEMENT - G600 TXI SYSTEM                                                                                |           |           |          |                           |           |           |                     |
|                     | PN:PN                                                                                                                            | MOS/MSC   | 05-Sep-19 | O/C      | TSN 0                     |           |           | Component    ATA:34 |
| SN:UNKNOWN          | HRS                                                                                                                              | 5104.4    |           |          | TSN 0                     |           |           |                     |
|                     | AFL                                                                                                                              | 6064      |           |          | TSN 0                     |           |           |                     |
|                     | GARMIN G600 TXI STC SA02571SE - ICA - EIS ANNUNCIATOR LAMP CHECK                                                                 |           |           |          |                           |           |           |                     |
| 340013 <sup>U</sup> | MOS                                                                                                                              | 22-May-24 | 12        |          | 31-May-25                 |           | 320 d     | Service    ATA:34   |
|                     | HRS                                                                                                                              | 5686.2    |           |          |                           |           |           |                     |
|                     | AFL                                                                                                                              | 6495      |           |          |                           |           |           |                     |
| 340014 <sup>U</sup> | GARMIN G600TXI STC SA02571SE - ICA - POST LIGHTNING STRIKE INSPECTION (AFTER A SUSPECTED OR ACTUAL STRIKE)                       |           |           |          |                           |           |           |                     |
|                     | MOS/MSC                                                                                                                          | 05-Sep-19 | A/R       |          |                           |           |           |                     |
|                     | HRS                                                                                                                              | 5104.4    |           |          |                           |           |           |                     |
|                     | AFL                                                                                                                              | 6064      |           |          |                           |           |           |                     |
|                     | NO. 2 DUAL NAVIGATION MARKER BEACON COUPLER                                                                                      |           |           |          |                           |           |           |                     |
|                     | PN:101-380042                                                                                                                    | MOS/MSC   | 29-Dec-98 | O/C      | TSN 0                     |           |           | Component    ATA:34 |
| SN:24212            | HRS                                                                                                                              | 0         |           |          | TSN 0                     |           |           |                     |
|                     | AFL                                                                                                                              | 0         |           |          | TSN 0                     |           |           |                     |
|                     | PROC. REF: GENERIC NO REF                                                                                                        |           |           |          |                           |           |           |                     |
| 340020              | GLIDESLOPE COUPLER                                                                                                               |           |           |          |                           |           |           |                     |
|                     | PN:101-380043                                                                                                                    | MOS/MSC   | 29-Dec-98 | O/C      |                           |           |           | Component    ATA:34 |
|                     | SN:13759                                                                                                                         | HRS       | 0         |          | TSN 0                     |           |           |                     |
| WC#: 34.470         | AFL                                                                                                                              | 0         |           |          | TSN 0                     |           |           |                     |
|                     | PROC. REF: GENERIC NO REF                                                                                                        |           |           |          |                           |           |           |                     |
|                     |                                                                                                                                  |           |           |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION |                                                                |           |          |          |                           |           |           |                  |
| 340035              | NAVIGATION MANAGEMENT UNIT                                     |           |          |          |                           |           |           |                  |
| PN:1013-42-001      | MOS/MSC                                                        | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.570         | AFL                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 340037 <sup>U</sup> | # 1 - GARMIN GTN 750 GPS/NAV/COM                               |           |          |          |                           |           |           |                  |
| PN:011-02282-00     | MOS/MSC                                                        | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:34 |
| SN:1ZA025843        | HRS                                                            | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                     | AFL                                                            | 6064      |          | TSN 0    |                           |           |           |                  |
| 340038 <sup>U</sup> | # 2 - GARMIN GTN 750 GPS/NAV/COM                               |           |          |          |                           |           |           |                  |
| PN:011-02282-00     | MOS/MSC                                                        | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component ATA:34 |
| SN:1ZA025861        | HRS                                                            | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                     | AFL                                                            | 6064      |          | TSN 0    |                           |           |           |                  |
| 340039 <sup>U</sup> | GARMIN GTN 6XX/7XX ICA DOCUMENTS                               |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                        | 05-Sep-19 | O/C      |          |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                                                            | 5104.4    |          |          |                           |           |           |                  |
|                     | AFL                                                            | 6064      |          |          |                           |           |           |                  |
|                     | PROC. REF: AMM 31-61-07                                        |           |          |          |                           |           |           |                  |
| 340040              | CCP-3000 CURSOR CONTROL PANEL (IFIS) REPLACE                   |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                        | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                     | AFL                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: AMM 31-61-07                                        |           |          |          |                           |           |           |                  |
| 340041 <sup>U</sup> | GARMIN GTN 750 STC SA02019SE-D - ICA - VISUAL INSPECTION       |           |          |          |                           |           |           |                  |
|                     | MOS                                                            | 22-May-24 | 12       |          | 31-May-25                 |           | 320 d     | Service ATA:34   |
|                     | HRS                                                            | 5686.2    |          |          |                           |           |           |                  |
|                     | AFL                                                            | 6495      |          |          |                           |           |           |                  |
| 340042 <sup>U</sup> | GARMIN GTN/750 STC SA02019SE-D - ICA - ELECTRICAL BONDING TEST |           |          |          |                           |           |           |                  |
|                     | MOS                                                            | 05-Sep-19 | 120      |          | 30-Sep-29                 |           | 1903 d    | Service ATA:34   |
|                     | HRS                                                            | 5104.4    | 2000     |          | 7104.4                    |           | 1418.2    |                  |
|                     | AFL                                                            | 6064      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                          | C/W       | Interval  | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|---------------------------------------------------------------|-----------|-----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION |                                                               |           |           |                           |                           |           |           |                  |
| 340043 <sup>U</sup> | GARMIN GTN 750 STC SA02019SE-D - ICA - LIGHTNING DAMAGE CHECK |           |           |                           |                           |           |           |                  |
|                     | MOS/MSC                                                       | 05-Sep-19 | A/R       |                           |                           |           |           | Service ATA:34   |
|                     | HRS                                                           | 5104.4    |           |                           |                           |           |           |                  |
|                     | AFL                                                           | 6064      |           |                           |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340060              | NO. 1 FLUX DETECTOR (FDU-3000) UNIT                           |           |           |                           |                           |           |           |                  |
|                     | PN:PN                                                         | MOS/MSC   | 29-Dec-98 | O/C                       | TSN 0                     |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | AFL                                                           | 0         |           |                           | TSN 0                     |           |           |                  |
|                     |                                                               |           |           | PROC. REF: AMM 34-21-05   |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340061              | NO. 2 FLUX DETECTOR (FDU-3000) UNIT                           |           |           |                           |                           |           |           |                  |
|                     | PN:PN                                                         | MOS/MSC   | 29-Dec-98 | O/C                       | TSN 0                     |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | AFL                                                           | 0         |           |                           | TSN 0                     |           |           |                  |
|                     |                                                               |           |           | PROC. REF: AMM 34-21-05   |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340062              | NO. 1 ELECTRONIC FLIGHT INSTRUMENT                            |           |           |                           |                           |           |           |                  |
|                     | PN:PN                                                         | MOS/MSC   | 29-Dec-98 | O/C                       | TSN 0                     |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | AFL                                                           | 0         |           |                           | TSN 0                     |           |           |                  |
|                     |                                                               |           |           | PROC. REF: AMM GENERIC 1  |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340063              | NO. 2 ELECTRONIC FLIGHT INSTRUMENT                            |           |           |                           |                           |           |           |                  |
|                     | PN:PN                                                         | MOS/MSC   | 29-Dec-98 | O/C                       | TSN 0                     |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | AFL                                                           | 0         |           |                           | TSN 0                     |           |           |                  |
|                     |                                                               |           |           | PROC. REF: AMM GENERIC 1  |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340101              | LEFT PITOT TUBE                                               |           |           |                           |                           |           |           |                  |
|                     | PN:50-384040-3                                                | MOS/MSC   | 29-Dec-98 | O/C                       |                           |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | WC#: 34.010                                                   | AFL       | 0         |                           |                           |           |           |                  |
|                     |                                                               |           |           | PROC. REF: GENERIC NO REF |                           |           |           |                  |
|                     |                                                               |           |           |                           |                           |           |           |                  |
| 340106              | RIGHT PITOT TUBE                                              |           |           |                           |                           |           |           |                  |
|                     | PN:50-384040-5                                                | MOS/MSC   | 29-Dec-98 | O/C                       |                           |           |           | Component ATA:34 |
|                     | SN:UNKNOWN                                                    | HRS       | 0         |                           | TSN 0                     |           |           |                  |
|                     | WC#: 34.010                                                   | AFL       | 0         |                           |                           |           |           |                  |
|                     |                                                               |           |           | PROC. REF: GENERIC NO REF |                           |           |           |                  |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION |                                                            |           |          |          |                           |           |           |                  |
| 340131              | EMERGENCY STATIC DISTRIBUTION VALVE                        |           |          |          |                           |           |           |                  |
| PN:K-4566-3         | MOS/MSC                                                    | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.020         | AFL                                                        | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 340141              | LEAK CHECK PILOT PITOT/STATIC SYSTEM                       |           |          |          |                           |           |           |                  |
| MOS                 | 10-Jun-24                                                  | 24        |          |          | 10-Jun-26                 |           | 695 d     | Service ATA:34   |
| HRS                 | 5686.2                                                     |           |          |          |                           |           |           | MANDATORY        |
| AFL                 | 6495                                                       |           |          |          |                           |           |           |                  |
| WC#: 34.030         | PROC. REF: AMM 34-00-09, AMM 34-00-05, FAR FAR PART 91.411 |           |          |          |                           |           |           |                  |
| 340142              | LEAK CHECK COPILOT PITOT/STATIC SYSTEM                     |           |          |          |                           |           |           |                  |
| MOS                 | 10-Jun-24                                                  | 24        |          |          | 10-Jun-26                 |           | 695 d     | Service ATA:34   |
| HRS                 | 5686.2                                                     |           |          |          |                           |           |           | MANDATORY        |
| AFL                 | 6495                                                       |           |          |          |                           |           |           |                  |
| WC#: 34.030         | PROC. REF: AMM 34-00-09, AMM 34-00-05, FAR FAR PART 91.411 |           |          |          |                           |           |           |                  |
| 341005              | AIR DATA MODULE                                            |           |          |          |                           |           |           |                  |
| PN:622-8692-014     | MOS/MSC                                                    | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:34 |
| SN:1418             | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.500         | AFL                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 341007              | AIR DATA COUPLER                                           |           |          |          |                           |           |           |                  |
| MOS/MSC             | 29-Dec-98                                                  | O/C       |          |          |                           |           |           | Component ATA:34 |
| HRS                 | 0                                                          |           |          | TSN 0    |                           |           |           |                  |
| AFL                 | 0                                                          |           |          |          |                           |           |           |                  |
| WC#: 34.045         | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 341008              | AIR DATA CONTROL                                           |           |          |          |                           |           |           |                  |
| MOS/MSC             | 29-Dec-98                                                  | O/C       |          |          |                           |           |           | Component ATA:34 |
| HRS                 | 0                                                          |           |          | TSN 0    |                           |           |           |                  |
| AFL                 | 0                                                          |           |          |          |                           |           |           |                  |
| WC#: 34.075         | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 341009 <sup>U</sup> | ADC 600 AIR DATA CONVERTER                                 |           |          |          |                           |           |           |                  |
| PN:99100003         | MOS/MSC                                                    | 05-Sep-19 | O/C      |          | TSN 0                     |           |           | Component ATA:34 |
| SN:280              | HRS                                                        | 5104.4    |          |          | TSN 0                     |           |           |                  |
| AFL                 | 6064                                                       |           |          |          | TSN 0                     |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                  | Unit    | C/W       | Interval | TSX/Adj.                       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------|---------|-----------|----------|--------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                      |         |           |          |                                |                           |           |           |                  |
| 341015 AIR DATA SENSOR                   |         |           |          |                                |                           |           |           |                  |
| PN:622-5797-001                          | MOS/MSC | 20-Oct-23 | O/C      | TSO 0                          |                           |           |           | Component ATA:34 |
| SN:3VCF                                  | HRS     | 5610.6    |          | TSO 0                          |                           |           |           |                  |
| WC#: 34.065                              | AFL     | 6428      |          | TSO 0                          |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: GENERIC NO REF      |                           |           |           |                  |
| 341136 STAND-BY COMPASS                  |         |           |          |                                |                           |           |           |                  |
| PN:50-534453-15                          | MOS/MSC | 29-Dec-98 | O/C      |                                |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                               | HRS     | 0         |          | TSN 0                          |                           |           |           |                  |
| WC#: 34.150                              | AFL     | 0         |          |                                |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: GENERIC NO REF      |                           |           |           |                  |
| 341151 OUTSIDE AIR TEMPERATURE INDICATOR |         |           |          |                                |                           |           |           |                  |
| PN:50-384077-1                           | MOS/MSC | 29-Dec-98 | O/C      |                                |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                               | HRS     | 0         |          | TSN 0                          |                           |           |           |                  |
| WC#: 34.160                              | AFL     | 0         |          |                                |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: AMM 34-00-11        |                           |           |           |                  |
| 341611 NO. 1 VHF/NAV ANTENNA             |         |           |          |                                |                           |           |           |                  |
| PN:100-384125-3                          | MOS/MSC | 29-Dec-98 | O/C      |                                |                           |           |           | Component ATA:34 |
| SN:5186                                  | HRS     | 0         |          | TSN 0                          |                           |           |           |                  |
| WC#: 34.200                              | AFL     | 0         |          |                                |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: AMM 34-30-03        |                           |           |           |                  |
| 341616 NO. 1 AIR DATA COMPUTER           |         |           |          |                                |                           |           |           |                  |
| PN:011-03457-*50                         | MOS/MSC | 08-Oct-21 | O/C      | TSN 25                         |                           |           |           | Component ATA:34 |
| SN:5BF001009                             | HRS     | 5280.3    |          | TSN 175.9                      |                           |           |           |                  |
| WC#: 34.015                              | AFL     | 6215      |          | TSN 150                        |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: AMM 34-11-03        |                           |           |           |                  |
| 341617 NO. 2 AIR DATA COMPUTER           |         |           |          |                                |                           |           |           |                  |
| PN:011-03457-50                          | MOS/MSC | 08-Oct-21 | O/C      | TSN 25                         |                           |           |           | Component ATA:34 |
| SN:5BF000773                             | HRS     | 5280.3    |          | TSN 175.9                      |                           |           |           |                  |
| WC#: 34.025                              | AFL     | 6215      |          | TSN 150                        |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: AMM 34-11-03        |                           |           |           |                  |
| 341618 TEST NO. 1 AIR DATA COMPUTER      |         |           |          |                                |                           |           |           |                  |
| PN:011-03457-*50                         | MOS     | 10-Jun-24 | 24       | 10-Jun-26                      | 695 d                     |           |           | Service ATA:34   |
| SN:5BF001009                             | HRS     | 5686.2    |          |                                |                           |           |           | MANDATORY        |
| WC#: 34.015                              | AFL     | 6495      |          |                                |                           |           |           |                  |
|                                          |         |           |          | PROC. REF: FAR FAR PART 91.411 |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN               | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 34 - NAVIGATION   |                                             |           |          |          |                           |           |           |                     |
| 341618.1 <sup>U</sup> | L-3 COMMUNICATIONS ESI-500 - ICA DOCUMENTS  |           |          |          |                           |           |           |                     |
| PN:PN                 | MOS/MSC                                     | 05-Sep-19 | O/C      |          |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN            | HRS                                         | 5104.4    |          |          |                           |           |           |                     |
|                       | AFL                                         | 6064      |          |          |                           |           |           |                     |
| 341619                | TEST NO. 2 AIR DATA COMPUTER                |           |          |          |                           |           |           |                     |
| PN:011-03457-50       | MOS                                         | 10-Jun-24 | 24       |          | 10-Jun-26                 |           | 695 d     | Service    ATA:34   |
| SN:5BF000773          | HRS                                         | 5686.2    |          |          |                           |           |           |                     |
| WC#: 34.025           | AFL                                         | 6495      |          |          |                           |           |           |                     |
|                       | PROC. REF: FAR FAR PART 91.411              |           |          |          |                           |           |           |                     |
| 341631                | NO. 2 VHF/NAV ANTENNA                       |           |          |          |                           |           |           |                     |
| PN:100-384125-3       | MOS/MSC                                     | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:34 |
| SN:5187               | HRS                                         | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 34.200           | AFL                                         | 0         |          |          |                           |           |           |                     |
|                       | PROC. REF: AMM 34-30-03                     |           |          |          |                           |           |           |                     |
| 341635 <sup>U</sup>   | GDU-1060 DISPLAY - PILOT                    |           |          |          |                           |           |           |                     |
| PN:011-03308-70       | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component    ATA:34 |
| SN:3M5001936          | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                     |
|                       | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                     |
| 341636 <sup>U</sup>   | GDU-1060 DISPLAY - COPILOT                  |           |          |          |                           |           |           |                     |
| PN:011-03308-70       | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component    ATA:34 |
| SN:3M5001771          | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                     |
|                       | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                     |
| 341638 <sup>U</sup>   | L-3 ELECTRONIC STANDBY INSTRUMENT (ESI-500) |           |          |          |                           |           |           |                     |
| PN:9200-15000-0101    | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           | Component    ATA:34 |
| SN:2278               | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                     |
|                       | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                     |
| 341638.1 <sup>U</sup> | L-3 ESI-500 INTERNAL LITHIUM ION BATTERY    |           |          |          |                           |           |           |                     |
| PN:9230-15003-01      | MOS/MSC                                     | 16-May-23 | O/C      | TSN 0    |                           |           |           | Component    ATA:34 |
| SN:N/A                | HRS                                         | 5522.7    |          | TSN 0    |                           |           |           |                     |
|                       | AFL                                         |           |          | TSN 0    |                           |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN             | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 34 - NAVIGATION |                                                 |           |          |          |                           |           |           |                     |
| 341639 <sup>U</sup> | TEST L-3 ESI-500 PRESSURE SYSTEM & ALTIMETER    |           |          |          |                           |           |           |                     |
|                     | MOS                                             | 10-Jun-24 | 24       |          | 30-Jun-26                 |           | 715 d     | Service    ATA:34   |
|                     | HRS                                             | 5686.2    |          |          |                           |           |           |                     |
|                     | AFL                                             | 6495      |          |          |                           |           |           |                     |
| 341640 <sup>U</sup> | ESI-500 SYSTEM INSTALLATION VISUAL INSPECTION   |           |          |          |                           |           |           |                     |
|                     | MOS                                             | 22-May-24 | 12       |          | 31-May-25                 |           | 320 d     | Service    ATA:34   |
|                     | HRS                                             | 5686.2    |          |          |                           |           |           |                     |
|                     | AFL                                             | 6495      |          |          |                           |           |           |                     |
| 341648 <sup>U</sup> | ESI-500 INTERNAL BATTERY CALIBRATION            |           |          |          |                           |           |           |                     |
|                     | MOS                                             | 22-May-24 | 12       |          | 31-May-25                 |           | 320 d     | Service    ATA:34   |
|                     | HRS                                             | 5686.2    |          |          |                           |           |           |                     |
|                     | AFL                                             | 6495      |          |          |                           |           |           |                     |
| 341649 <sup>U</sup> | ESI-500 ACCURACY CHECK OF REAL TIME CLOCK (RTC) |           |          |          |                           |           |           |                     |
|                     | MOS                                             | 22-May-24 | 24       |          | 31-May-26                 |           | 685 d     | Service    ATA:34   |
|                     | HRS                                             | 5686.2    |          |          |                           |           |           |                     |
|                     | AFL                                             | 6495      |          |          |                           |           |           |                     |
| 341651              | NO. 1 ADF LOOP ANTENNA                          |           |          |          |                           |           |           |                     |
|                     | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:34 |
|                     | PN:137A4                                        |           |          |          |                           |           |           |                     |
|                     | SN:UNKNOWN                                      | HRS       | 0        | TSN 0    |                           |           |           |                     |
|                     | WC #: 34.230                                    | AFL       | 0        |          | PROC. REF: GENERIC NO REF |           |           |                     |
| 341652              | NO. 2 ADF LOOP ANTENNA                          |           |          |          |                           |           |           |                     |
|                     | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:34 |
|                     | PN:137A4                                        |           |          |          |                           |           |           |                     |
|                     | SN:UNKNOWN                                      | HRS       | 0        | TSN 0    |                           |           |           |                     |
|                     | WC #: 34.230                                    | AFL       | 0        |          | PROC. REF: GENERIC NO REF |           |           |                     |
| 341656              | NO. 1 ADF SENSE ANTENNA                         |           |          |          |                           |           |           |                     |
|                     | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:34 |
|                     | PN:ANT-60A (101-340422)                         |           |          |          |                           |           |           |                     |
|                     | SN:UNKNOWN                                      | HRS       | 0        | TSN 0    |                           |           |           |                     |
|                     | WC #: 34.240                                    | AFL       | 0        |          | PROC. REF: GENERIC NO REF |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                 | Unit                    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION     |                         |           |          |                           |                           |           |           |                  |
| 341657                  | NO. 2 ADF SENSE ANTENNA |           |          |                           |                           |           |           |                  |
| PN:ANT-60A (101-340422) | MOS/MSC                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN              | HRS                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.240             | AFL                     | 0         |          |                           |                           |           |           |                  |
|                         |                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 341681                  | DME ANTENNA             |           |          |                           |                           |           |           |                  |
| PN:100-384129           | MOS/MSC                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:10845                | HRS                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.290             | AFL                     | 0         |          |                           |                           |           |           |                  |
|                         |                         |           |          | PROC. REF: AMM 34-53-03   |                           |           |           |                  |
| 342005                  | SLIP/SKID SENSOR        |           |          |                           |                           |           |           |                  |
| PN:622-6019-001         | MOS/MSC                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:1964                 | HRS                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.480             | AFL                     | 0         |          | TSN 0                     |                           |           |           |                  |
|                         |                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 342013                  | STANDBY POWER SUPPLY    |           |          |                           |                           |           |           |                  |
| PN:501-1228-04          | MOS/MSC                 | 19-Sep-19 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:10140                | HRS                     | 5104.4    |          |                           |                           |           |           |                  |
| WC#: 34.100             | AFL                     | 6064      |          |                           |                           |           |           |                  |
|                         |                         |           |          | PROC. REF: AMM GENERIC 1  |                           |           |           |                  |
| 342050 <sup>U</sup>     | GMU-44 MAGNETOMETER #1  |           |          |                           |                           |           |           |                  |
| PN:011-00870-10         | MOS/MSC                 | 05-Sep-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:1CM029345            | HRS                     | 5104.4    |          | TSN 0                     |                           |           |           |                  |
|                         | AFL                     | 6064      |          | TSN 0                     |                           |           |           |                  |
| 342051 <sup>U</sup>     | GMU-44 MAGNETOMETER #2  |           |          |                           |                           |           |           |                  |
| PN:011-00870-10         | MOS/MSC                 | 05-Sep-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:1CM018424            | HRS                     | 5104.4    |          | TSN 0                     |                           |           |           |                  |
|                         | AFL                     | 6064      |          | TSN 0                     |                           |           |           |                  |
| 342101                  | RADAR INDICATOR         |           |          |                           |                           |           |           |                  |
| PN:622-5941-001         | MOS/MSC                 | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN              | HRS                     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.260             | AFL                     | 0         |          |                           |                           |           |           |                  |
|                         |                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN               | Unit                                                               | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|--------------------------------------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION   |                                                                    |           |          |           |                           |           |           |                  |
| 342103                | RADAR RECEIVER/TRANSMITTER                                         |           |          |           |                           |           |           |                  |
| PN:RT-1201A           | MOS/MSC                                                            | 29-Dec-98 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN            | HRS                                                                | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.260           | AFL                                                                | 0         |          |           |                           |           |           |                  |
|                       | PROC. REF: AMM 34-40-01                                            |           |          |           |                           |           |           |                  |
| 342104 <sup>U</sup>   | GARMIN GDL69A STC SA01487SE - ICA - VISUAL INSPECTION              |           |          |           |                           |           |           |                  |
| MOS                   | 22-May-24                                                          | 12        |          | 31-May-25 |                           | 320 d     |           | Service ATA:34   |
| HRS                   | 5686.2                                                             |           |          |           |                           |           |           |                  |
| AFL                   | 6495                                                               |           |          |           |                           |           |           |                  |
| 342105 <sup>U</sup>   | GARMIN GDL69A STC SA01487SE - ICA - AUDIO SUPPRESSION VERIFICATION |           |          |           |                           |           |           |                  |
| MOS                   | 22-May-24                                                          | 12        |          | 31-May-25 |                           | 320 d     |           | Service ATA:34   |
| HRS                   | 5686.2                                                             |           |          |           |                           |           |           |                  |
| AFL                   | 6495                                                               |           |          |           |                           |           |           |                  |
| 342106 <sup>U</sup>   | GARMIN GDL69A STC SA01487SE - ICA - ELECTRICAL BONDING CHECK       |           |          |           |                           |           |           |                  |
| MOS                   | 05-Sep-19                                                          | 120       |          | 30-Sep-29 |                           | 1903 d    |           | Service ATA:34   |
| HRS                   | 5104.4                                                             | 2000      |          | 7104.4    |                           | 1418.2    |           |                  |
| AFL                   | 6064                                                               |           |          |           |                           |           |           |                  |
| 342109                | RADAR WAVE GUIDE                                                   |           |          |           |                           |           |           |                  |
| PN:90A11N-7200        | MOS/MSC                                                            | 29-Dec-98 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN            | HRS                                                                | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.270           | AFL                                                                | 0         |          |           |                           |           |           |                  |
|                       | PROC. REF: GENERIC NO REF                                          |           |          |           |                           |           |           |                  |
| 342112 <sup>U</sup>   | GDL-69A XM DATALINK                                                |           |          |           |                           |           |           |                  |
| PN:011-03177-10       | MOS/MSC                                                            | 05-Sep-19 | O/C      | TSN 0     |                           |           |           | Component ATA:34 |
| SN:3NV004194          | HRS                                                                | 5104.4    |          | TSN 0     |                           |           |           |                  |
|                       | AFL                                                                | 6064      |          | TSN 0     |                           |           |           |                  |
| 342112.1 <sup>U</sup> | GARMIN GDL69A - ICA DOCUMENTS                                      |           |          |           |                           |           |           |                  |
| PN:PN                 | MOS/MSC                                                            | 05-Sep-19 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN            | HRS                                                                | 5104.4    |          |           |                           |           |           |                  |
|                       | AFL                                                                | 6064      |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                        | Unit    | C/W       | Interval | TSX/Adj.                                     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|----------------------------------------------------------------|---------|-----------|----------|----------------------------------------------|---------------------------|-----------|-----------|---------------------|
| ATA 34 - NAVIGATION                                            |         |           |          |                                              |                           |           |           |                     |
| 342113 <sup>U</sup> GWX-75 PROCESSOR                           |         |           |          |                                              |                           |           |           |                     |
| PN:011-03997-00                                                | MOS/MSC | 05-Sep-19 | O/C      | TSN 0                                        |                           |           |           | Component    ATA:34 |
| SN:4RR000946                                                   | HRS     | 5104.4    |          | TSN 0                                        |                           |           |           |                     |
|                                                                | AFL     | 6064      |          | TSN 0                                        |                           |           |           |                     |
| 342115 <sup>U</sup> FLIGHT STREAM 510                          |         |           |          |                                              |                           |           |           |                     |
| PN:010-01322-01                                                | MOS/MSC | 28-Apr-20 | O/C      | TSN 7, TSR 5                                 |                           |           |           | Component    ATA:34 |
| SN:402008814                                                   | HRS     | 5167.4    |          | TSR 5167.4                                   |                           |           |           |                     |
|                                                                | AFL     | 6123      |          | TSR 6123                                     |                           |           |           |                     |
| 342117 <sup>U</sup> GARMIN GAD 43E AUTOPILOT INTERFACE ADAPTER |         |           |          |                                              |                           |           |           |                     |
| PN:011-02349-00                                                | MOS/MSC | 05-Sep-19 | O/C      | TSN 0                                        |                           |           |           | Component    ATA:34 |
| SN:1V7052366                                                   | HRS     | 5104.4    |          | TSN 0                                        |                           |           |           |                     |
|                                                                | AFL     | 6064      |          | TSN 0                                        |                           |           |           |                     |
| 342200      TCAS TTR-4000 TRANSCIVER                           |         |           |          |                                              |                           |           |           |                     |
| PN:PN                                                          | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                                        |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                     | HRS     | 0         |          | TSN 0                                        |                           |           |           |                     |
|                                                                | AFL     | 0         |          | TSN 0                                        |                           |           |           |                     |
|                                                                |         |           |          | PROC. REF: AMM 34-45-01                      |                           |           |           |                     |
| 342601      NO. 1 ATC TRANSPONDER                              |         |           |          |                                              |                           |           |           |                     |
| PN:011-03303-00                                                | MOS/MSC | 08-Oct-21 | O/C      |                                              |                           |           |           | Component    ATA:34 |
| SN:3EH024272                                                   | HRS     | 5280.3    |          |                                              |                           |           |           |                     |
| WC#: 34.280                                                    | AFL     | 6215      |          |                                              |                           |           |           |                     |
|                                                                |         |           |          | PROC. REF: GENERIC NO REF                    |                           |           |           |                     |
| 342606      TEST NO. 1 ATC TRANSPONDER                         |         |           |          |                                              |                           |           |           |                     |
| PN:011-03303-00                                                | MOS     | 10-Jun-24 | 24       |                                              | 10-Jun-26                 |           | 695 d     | Service    ATA:34   |
| SN:3EH024272                                                   | HRS     | 5686.2    |          |                                              |                           |           |           | MANDATORY           |
| WC#: 34.280                                                    | AFL     | 6495      |          |                                              |                           |           |           |                     |
|                                                                |         |           |          | PROC. REF: AMM 34-55-01, FAR FAR PART 91.413 |                           |           |           |                     |
| 342610 <sup>U</sup> GARMIN GTX335/345 - ICA DOCUMENTS          |         |           |          |                                              |                           |           |           |                     |
| PN:PN                                                          | MOS/MSC | 05-Sep-19 | O/C      |                                              |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                     | HRS     | 5104.4    |          |                                              |                           |           |           |                     |
|                                                                | AFL     | 6064      |          |                                              |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                 | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|----------------------------------------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION |                                                                      |           |          |           |                           |           |           |                  |
| 342611              | NO. 1 ATC TRANSPONDER ANTENNA                                        |           |          |           |                           |           |           |                  |
| PN:100-384129       | MOS/MSC                                                              | 29-Dec-98 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:10989            | HRS                                                                  | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.290         | AFL                                                                  | 0         |          |           |                           |           |           |                  |
|                     | PROC. REF: AMM 34-55-03                                              |           |          |           |                           |           |           |                  |
| 342612 <sup>U</sup> | GARMIN GTX 335/345 STC SA01714WI - ICA - EQUIPMENT VISUAL INSPECTION |           |          |           |                           |           |           |                  |
| MOS                 | 22-May-24                                                            | 12        |          | 31-May-25 |                           | 320 d     |           | Service ATA:34   |
| HRS                 | 5686.2                                                               |           |          |           |                           |           |           |                  |
| AFL                 | 6495                                                                 |           |          |           |                           |           |           |                  |
| 342613 <sup>U</sup> | GARMIN GTX 335/345 STC SA01714WI - ICA - ELECTRICAL BONDING TEST     |           |          |           |                           |           |           |                  |
| MOS                 | 05-Sep-19                                                            | 120       |          | 30-Sep-29 |                           | 1903 d    |           | Service ATA:34   |
| HRS                 | 5104.4                                                               | 2000      |          | 7104.4    |                           | 1418.2    |           |                  |
| AFL                 | 6064                                                                 |           |          |           |                           |           |           |                  |
| 342614 <sup>U</sup> | GARMIN GTS 335/345 STC SA01714WI ANTENNA VISUAL INSPECTION           |           |          |           |                           |           |           |                  |
| MOS                 | 22-May-24                                                            | 12        |          | 31-May-25 |                           | 320 d     |           | Service ATA:34   |
| HRS                 | 5686.2                                                               |           |          |           |                           |           |           |                  |
| AFL                 | 6495                                                                 |           |          |           |                           |           |           |                  |
| 342621              | NO. 2 ATC TRANSPONDER                                                |           |          |           |                           |           |           |                  |
| PN:011-03301-00     | MOS/MSC                                                              | 08-Oct-21 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:3EF022014        | HRS                                                                  | 5280.3    |          |           |                           |           |           |                  |
| WC#: 34.280         | AFL                                                                  | 6215      |          |           |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                            |           |          |           |                           |           |           |                  |
| 342626              | TEST NO. 2 ATC TRANSPONDER                                           |           |          |           |                           |           |           |                  |
| PN:011-03301-00     | MOS                                                                  | 10-Jun-24 | 24       | 10-Jun-26 |                           | 695 d     |           | Service ATA:34   |
| SN:3EF022014        | HRS                                                                  | 5686.2    |          |           |                           |           |           | MANDATORY        |
| WC#: 34.280         | AFL                                                                  | 6495      |          |           |                           |           |           |                  |
|                     | PROC. REF: FAR FAR PART 91.413                                       |           |          |           |                           |           |           |                  |
| 342631              | NO. 2 ATC TRANSPONDER ANTENNA                                        |           |          |           |                           |           |           |                  |
| PN:100-384129       | MOS/MSC                                                              | 29-Dec-98 | O/C      |           |                           |           |           | Component ATA:34 |
| SN:11036            | HRS                                                                  | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.290         | AFL                                                                  | 0         |          |           |                           |           |           |                  |
|                     | PROC. REF: AMM 34-55-03                                              |           |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                               | Unit    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------|---------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                   |         |           |          |                           |                           |           |           |                  |
| 342639 MARKER BEACON                                  |         |           |          |                           |                           |           |           |                  |
| PN:51Z4                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.300                                           | AFL     | 0         |          |                           |                           |           |           |                  |
|                                                       |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 343000 <sup>U</sup> GARMIN GA 37 GPS ANTENNA          |         |           |          |                           |                           |           |           |                  |
| PN:10710                                              | MOS/MSC | 05-Sep-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:5562                                               | HRS     | 5104.4    |          | TSN 0                     |                           |           |           |                  |
|                                                       | AFL     | 6064      |          | TSN 0                     |                           |           |           |                  |
| 343001 <sup>U</sup> GARMIN GA 36 GPS ANTENNA          |         |           |          |                           |                           |           |           |                  |
| PN:013-00244-00                                       | MOS/MSC | 05-Sep-19 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:18560                                              | HRS     | 5104.4    |          | TSN 0                     |                           |           |           |                  |
|                                                       | AFL     | 6064      |          | TSN 0                     |                           |           |           |                  |
| 343405 COURSE HEADING PANEL                           |         |           |          |                           |                           |           |           |                  |
| PN:622-6899-001                                       | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:951                                                | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.340                                           | AFL     | 0         |          |                           |                           |           |           |                  |
|                                                       |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 343406 GTS-820 TRAFFIC ADVISORY SYSTEM PROCESSOR UNIT |         |           |          |                           |                           |           |           |                  |
| PN:PN                                                 | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                       | AFL     | 0         |          | TSN 0                     |                           |           |           |                  |
|                                                       |         |           |          | PROC. REF: AMIM GENERIC 1 |                           |           |           |                  |
| 343409 RADAR CONTROL                                  |         |           |          |                           |                           |           |           |                  |
| PN:622-8393-003                                       | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.340                                           | AFL     | 0         |          |                           |                           |           |           |                  |
|                                                       |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 343412 PILOT DISPLAY CONTROL                          |         |           |          |                           |                           |           |           |                  |
| PN:622-8680-001                                       | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:UNKNOWN                                            | HRS     | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.350                                           | AFL     | 0         |          |                           |                           |           |           |                  |
|                                                       |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                       | Unit    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------------------------------------------------|---------|-----------|----------|---------------------------|---------------------------|-----------|-----------|---------------------|
| ATA 34 - NAVIGATION                                           |         |           |          |                           |                           |           |           |                     |
| 343418      PILOT ELECTRONIC HORIZONTAL SITUATION INDICATOR   |         |           |          |                           |                           |           |           |                     |
| PN:622-6020-021                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.360                                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 343420      COPILOT DISPLAY PROCESSOR                         |         |           |          |                           |                           |           |           |                     |
| PN:622-8678-001                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.320                                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 343422      COPILOT DISPLAY CONTROL                           |         |           |          |                           |                           |           |           |                     |
| PN:622-8680-001                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.350                                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: AMM 31-60-03   |                           |           |           |                     |
| 343428      COPILOT ELECTRONIC HORIZONTAL SITUATION INDICATOR |         |           |          |                           |                           |           |           |                     |
| PN:622-6020-021                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.360                                                   | AFL     | 0         |          |                           |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 344005      NO. 1 RADAR ALT ANTENNA                           |         |           |          |                           |                           |           |           |                     |
| PN:S67-2002-14                                                | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:4601                                                       | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.430                                                   | AFL     | 0         |          | TSN 0                     |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 344010      NO. 2 RADAR ALT ANTENNA                           |         |           |          |                           |                           |           |           |                     |
| PN:S67-2002-14                                                | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:4609                                                       | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.430                                                   | AFL     | 0         |          | TSN 0                     |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |
| 344015      DATA PROGRAMMER                                   |         |           |          |                           |                           |           |           |                     |
| PN:622-5110-001                                               | MOS/MSC | 29-Dec-98 | O/C      |                           |                           |           |           | Component    ATA:34 |
| SN:UNKNOWN                                                    | HRS     | 0         |          | TSN 0                     |                           |           |           |                     |
| WC#: 34.510                                                   | AFL     | 0         |          | TSN 0                     |                           |           |           |                     |
|                                                               |         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                       | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|----------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION |                            |           |          |                           |                           |           |           |                  |
| 345005              | NAVIGATION ANTENNA COUPLER |           |          |                           |                           |           |           |                  |
| PN:80-37-101        | MOS/MSC                    | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:3919             | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.390         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: AMM 23-11-03   |                           |           |           |                  |
| 345010              | NO. 1 LOOP SENSE ANTENNA   |           |          |                           |                           |           |           |                  |
| PN:622-2363-001     | MOS/MSC                    | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:40228            | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.400         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 345015              | GLIDESLOPE ANTENNA         |           |          |                           |                           |           |           |                  |
| PN:100-384128       | MOS/MSC                    | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:5230             | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.410         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 345020              | AFT DME ANTENNA            |           |          |                           |                           |           |           |                  |
| PN:100-384129       | MOS/MSC                    | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:11048            | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.420         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: AMM 34-53-03   |                           |           |           |                  |
| 345024              | GPS RECEIVER               |           |          |                           |                           |           |           |                  |
| PN:PN               | MOS/MSC                    | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: AMM 34-51-01   |                           |           |           |                  |
| 345025              | GPS ANTENNA                |           |          |                           |                           |           |           |                  |
| PN:10704            | MOS/MSC                    | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:34 |
| SN:4007             | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.515         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: AMM 34-51-03   |                           |           |           |                  |
| 346020              | TCAS COMPUTER              |           |          |                           |                           |           |           |                  |
| PN:PN               | MOS/MSC                    | 29-Dec-98 | O/C      | TSN 0                     |                           |           |           | Component ATA:34 |
| SN:UNKNOWN          | HRS                        | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 34.620         | AFL                        | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                            |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                                              | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|-----------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION       |                                                                                   |           |                |          |                           |           |             |                  |
| 346030                    | PERFORM REDUCED VERTICAL SEPARATION MINIMUM (RVSM) HEIGHT MONITORING REQUIREMENTS |           |                |          |                           |           |             |                  |
|                           | MOS/MSC                                                                           | 29-Dec-98 | -              |          |                           |           |             | Service ATA:34   |
|                           | HRS                                                                               | 0         |                |          |                           |           |             |                  |
|                           | AFL                                                                               | 0         |                |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346060                    | RADIO ALTIMETER                                                                   |           |                |          |                           |           |             |                  |
|                           | PN:PN                                                                             | MOS/MSC   | 29-Dec-98      | O/C      | TSN 0                     |           |             | Component ATA:34 |
|                           | SN:UNKNOWN                                                                        | HRS       | 0              |          | TSN 0                     |           |             |                  |
|                           | WC#: 34.640                                                                       | AFL       | 0              |          | TSN 0                     |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346065                    | AFT RADIO ALTIMETER ANTENNA                                                       |           |                |          |                           |           |             |                  |
|                           | PN:PN                                                                             | MOS/MSC   | 29-Dec-98      | O/C      | TSN 0                     |           |             | Component ATA:34 |
|                           | SN:UNKNOWN                                                                        | HRS       | 0              |          | TSN 0                     |           |             |                  |
|                           | WC#: 34.650                                                                       | AFL       | 0              |          | TSN 0                     |           |             |                  |
| PROC. REF: AMIM 34-41-03  |                                                                                   |           |                |          |                           |           |             |                  |
| 346075                    | MARKER ANTENNA                                                                    |           |                |          |                           |           |             |                  |
|                           | PN:PN                                                                             | MOS/MSC   | 29-Dec-98      | O/C      | TSN 0                     |           |             | Component ATA:34 |
|                           | SN:UNKNOWN                                                                        | HRS       | 0              |          | TSN 0                     |           |             |                  |
|                           | WC#: 34.670                                                                       | AFL       | 0              |          | TSN 0                     |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346080                    | TCAS DIRECTIONAL ANTENNA                                                          |           |                |          |                           |           |             |                  |
|                           | PN:PN                                                                             | MOS/MSC   | 29-Dec-98      | O/C      | TSN 0                     |           |             | Component ATA:34 |
|                           | SN:UNKNOWN                                                                        | HRS       | 0              |          | TSN 0                     |           |             |                  |
|                           | WC#: 34.680                                                                       | AFL       | 0              |          | TSN 0                     |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| ATA 35 - OXYGEN           |                                                                                   |           |                |          |                           |           |             |                  |
| 350000                    | CHECK OXYGEN SYSTEM INSTALLATION FOR DAMAGE AND SECURITY                          |           |                |          |                           |           |             |                  |
|                           | MOS                                                                               | 22-May-24 | 24 (+24d/-24d) |          | 22-May-26                 | 15-Jun-26 | 676 d (+24) | Service ATA:35   |
|                           | HRS                                                                               | 5686.2    |                |          |                           |           |             |                  |
|                           | AFL                                                                               | 6495      |                |          |                           |           |             |                  |
| PROC. REF: AMIM GENERIC 1 |                                                                                   |           |                |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                             | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 35 - OXYGEN                                     |         |           |          |          |                           |           |           |                     |
| 350101      OXYGEN CYLINDER                         |         |           |          |          |                           |           |           |                     |
| PN:1270152-3                                        | MOS     | 22-May-24 | 180      | TSN 0    | 22-May-39                 |           | 5424 d    | Component    ATA:35 |
| SN:ALT281-29380                                     | HRS     | 5686.2    |          |          |                           |           |           | SCRAP               |
| WC#: 35.010                                         | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: AMM 35-00-05, AMM 35-00-07, AMM 35-00-09 |         |           |          |          |                           |           |           |                     |
| 350106      HYDROSTATIC TEST OXYGEN CYLINDER        |         |           |          |          |                           |           |           |                     |
| PN:1270152-3                                        | MOS     | 22-May-24 | 60       |          | 22-May-29                 |           | 1772 d    | Service    ATA:35   |
| SN:ALT281-29380                                     | HRS     | 5686.2    |          | TSN 0    |                           |           |           |                     |
| WC#: 35.010                                         | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF                           |         |           |          |          |                           |           |           |                     |
| 350111      OXYGEN FILLER VALVE                     |         |           |          |          |                           |           |           |                     |
| PN:ZV951                                            | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:35 |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 35.020                                         | AFL     | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF                           |         |           |          |          |                           |           |           |                     |
| 350116      OXYGEN FILLER GAUGE                     |         |           |          |          |                           |           |           |                     |
| PN:99-384042                                        | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:35 |
| SN:01941                                            | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 35.040                                         | AFL     | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF                           |         |           |          |          |                           |           |           |                     |
| 350121      OXYGEN PRESSURE GAUGE                   |         |           |          |          |                           |           |           |                     |
| PN:99-384042                                        | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:35 |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 35.040                                         | AFL     | 0         |          |          |                           |           |           |                     |
| PROC. REF: GENERIC NO REF                           |         |           |          |          |                           |           |           |                     |
| 350146      PILOT OXYGEN MASK                       |         |           |          |          |                           |           |           |                     |
| PN:174260-12                                        | MOS/MSC | 12-Apr-23 | O/C      | TSO 0    | 01-Mar-29 (M)             |           | 1690 d    | Component    ATA:35 |
| SN:04385                                            | HRS     | 5500.3    |          | TSO 0    |                           |           |           |                     |
| WC#: 35.050                                         | AFL     | 6358      |          | TSO 0    |                           |           |           |                     |
| PROC. REF: GENERIC NO REF                           |         |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN          | Unit                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|------------------|-----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 35 - OXYGEN  |                                                     |           |                |          |                           |           |             |                  |
| 350151           | COPILOT OXYGEN MASK                                 |           |                |          |                           |           |             |                  |
| PN:174260-12     | MOS/MSC                                             | 12-Apr-23 | O/C            | TSO 0    | 01-Mar-29 (M)             |           | 1690 d      | Component ATA:35 |
| SN:04293         | HRS                                                 | 5500.3    |                | TSO 0    |                           |           |             |                  |
| WC#: 35.050      | AFL                                                 | 6358      |                | TSO 0    |                           |           |             |                  |
|                  | PROC. REF: GENERIC NO REF                           |           |                |          |                           |           |             |                  |
| 350500           | TEST ALL MASKS FOR OXYGEN FLOW                      |           |                |          |                           |           |             |                  |
|                  | MOS                                                 | 22-May-24 | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25 | 311 d (+12) | Service ATA:35   |
|                  | HRS                                                 | 5686.2    |                |          |                           |           |             |                  |
|                  | AFL                                                 | 6495      |                |          |                           |           |             |                  |
|                  | PROC. REF: AMM 35-00-19                             |           |                |          |                           |           |             |                  |
| 350651           | OXYGEN REGULATOR ASSEMBLY                           |           |                |          |                           |           |             |                  |
| PN:803213-02     | MOS                                                 | 22-May-24 | 60             | TSO 0    | 22-May-29                 |           | 1772 d      | Component ATA:35 |
| SN:6459          | HRS                                                 | 5686.2    |                | TSO 0    |                           |           |             | OVERHAUL         |
| WC#: 35.020      | AFL                                                 | 6495      |                | TSO 0    |                           |           |             |                  |
|                  | PROC. REF: GENERIC NO REF                           |           |                |          |                           |           |             |                  |
| 350660           | OXYGEN SHUT-OFF VALVE                               |           |                |          |                           |           |             |                  |
| PN:PN            | MOS/MSC                                             | 29-Dec-98 | O/C            | TSN 0    |                           |           |             | Component ATA:35 |
| SN:UNKNOWN       | HRS                                                 | 0         |                | TSN 0    |                           |           |             |                  |
|                  | AFL                                                 | 0         |                | TSN 0    |                           |           |             |                  |
|                  | PROC. REF: AMM 35-20-05                             |           |                |          |                           |           |             |                  |
| 350666           | REPLACE PACKINGS, PASSENGER OXYGEN SHUTOFF VALVE    |           |                |          |                           |           |             |                  |
|                  | MOS                                                 | 12-Apr-23 | 48             |          | 12-Apr-27                 |           | 1001 d      | Service ATA:35   |
|                  | HRS                                                 | 5500.3    |                |          |                           |           |             |                  |
| WC#: 35.030      | AFL                                                 | 6358      |                |          |                           |           |             |                  |
|                  | PROC. REF: AMM 35-20-05, AMM 35-20-07, AMM 35-20-07 |           |                |          |                           |           |             |                  |
| 350670           | PERFORM BAROMETRIC PRESSURE SWITCH CHECK            |           |                |          |                           |           |             |                  |
| PN:101-384028-23 | MOS                                                 | 22-May-24 | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25 | 311 d (+12) | Service ATA:35   |
| SN:W48007        | HRS                                                 | 5686.2    |                |          |                           |           |             | MANDATORY        |
| WC#: 35.070      | AFL                                                 | 6495      |                |          |                           |           |             |                  |
|                  | PROC. REF: AMM 35-20-01                             |           |                |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN          | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 35 - OXYGEN  |                                       |           |          |          |                           |           |           |                     |
| 351000           | INSPECT PILOT CREW MASKS              |           |          |          |                           |           |           |                     |
| PN:174260-12     | MOS                                   | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service    ATA:35   |
| SN:04385         | HRS                                   | 5686.2    |          |          |                           |           |           |                     |
|                  | AFL                                   | 6495      |          |          |                           |           |           |                     |
|                  | PROC. REF: AMM 35-10-01, AMM 35-10-00 |           |          |          |                           |           |           |                     |
| 352001           | OXYGEN PRESSURE SWITCH REPLACE        |           |          |          |                           |           |           |                     |
| PN:PN            | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component    ATA:35 |
| SN:UNKNOWN       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                  | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                  | PROC. REF: AMM 35-20-03               |           |          |          |                           |           |           |                     |
| 352005           | BAROMETRIC SWITCH                     |           |          |          |                           |           |           |                     |
| PN:101-384028-23 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:35 |
| SN:W48007        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 35.060      | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                  | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN            | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 36 - PNEUMATIC |                                       |           |          |          |                           |           |           |                     |
| 360651             | DEICE PRESSURE REGULATOR              |           |          |          |                           |           |           |                     |
| PN:90-380000-3     | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:36 |
| SN:UNKNOWN         | HRS                                   |           |          |          |                           |           |           |                     |
| WC#: 36.010        | AFL                                   |           |          |          |                           |           |           |                     |
|                    | PROC. REF: GENERIC NO REF             |           |          |          |                           |           |           |                     |
| 361005             | LEFT BLEED AIR (ELECTRONIC) VALVE     |           |          |          |                           |           |           |                     |
| PN:101-380025-21   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:36 |
| SN:11AP163M        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 36.020        | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | PROC. REF: AMM 36-10-03               |           |          |          |                           |           |           |                     |
| 361007             | LEFT ELECTRONIC FLOW PACK CONTROLLER  |           |          |          |                           |           |           |                     |
| PN:PN              | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                     |
| SN:UNKNOWN         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | PROC. REF: AMM GENERIC 1              |           |          |          |                           |           |           |                     |
| 361010             | RIGHT BLEED AIR (ELECTRONIC) VALVE    |           |          |          |                           |           |           |                     |
| PN:101-380025-21   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:36 |
| SN:11AP175M        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 36.020        | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | PROC. REF: AMM 36-10-03               |           |          |          |                           |           |           |                     |
| 361012             | RIGHT ELECTRONIC FLOW PACK CONTROLLER |           |          |          |                           |           |           |                     |
| PN:PN              | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component    ATA:36 |
| SN:UNKNOWN         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | AFL                                   | 0         |          | TSN 0    |                           |           |           |                     |
|                    | PROC. REF: AMM GENERIC 1              |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN         | Unit                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------|-------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 37 - VACUUM |                               |           |          |          |                           |           |           |                     |
| 370636          | VACUUM REGULATOR VALVE        |           |          |          |                           |           |           |                     |
| PN:133A13       | MOS/MSC                       | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:37 |
| SN:UNKNOWN      | HRS                           |           |          |          |                           |           |           |                     |
| WC#: 37.010     | AFL                           |           |          |          |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF     |           |          |          |                           |           |           |                     |
| 372005          | SUCTION GAUGE                 |           |          |          |                           |           |           |                     |
| PN:101-384133-1 | MOS/MSC                       | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:37 |
| SN:L97171       | HRS                           | 0         |          | TSN 0    |                           |           |           |                     |
| WC#: 37.030     | AFL                           | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF     |           |          |          |                           |           |           |                     |
| 373106          | REPLACE INSTRUMENT AIR FILTER |           |          |          |                           |           |           |                     |
|                 | MOS                           | 22-May-24 |          |          |                           |           |           | Service    ATA:37   |
|                 | HRS                           | 5686.2    | 800      |          | 6486.2                    |           | 800       |                     |
| WC#: 37.020     | AFL                           | 6495      |          |          |                           |           |           |                     |
|                 | PROC. REF: AMM 37-20-01       |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                                 | Unit                                                                                                        | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-----------------------------------------|-------------------------------------------------------------------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 51 - STD PRACTICES AND STRUCT-GENRL |                                                                                                             |           |                           |          |                           |           |              |                  |
| 510101                                  | INSPECT EXTERIOR SKIN(PRIORITY AREA INSPECTION)                                                             |           |                           |          |                           |           |              |                  |
|                                         | MOS                                                                                                         | 29-Dec-98 |                           |          |                           |           |              | Service ATA:51   |
|                                         | HRS                                                                                                         |           |                           |          |                           |           |              | MANDATORY        |
| WC#: 51.010                             | AFL                                                                                                         | 0         | T:10000 (+10%/-10%)       |          | 10000                     | 11000     | 3505 (+1000) |                  |
|                                         |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                  |
| 510106                                  | INSPECT FUSELAGE STATIONS 84 THRU 347.75(PRIORITY AREA INSPECTION)                                          |           |                           |          |                           |           |              |                  |
|                                         | MOS                                                                                                         | 29-Dec-98 |                           |          |                           |           |              | Service ATA:51   |
|                                         | HRS                                                                                                         |           |                           |          |                           |           |              | MANDATORY        |
| WC#: 51.030                             | AFL                                                                                                         | 0         | T:10000 (+10%/-10%)       |          | 10000                     | 11000     | 3505 (+1000) |                  |
|                                         |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                  |
| 510116                                  | INSPECT STRINGERS FROM FS 88 THROUGH FS 125 AND INSTRUMENT PANEL SUPPORT BRACKETS(PRIORITY AREA INSPECTION) |           |                           |          |                           |           |              |                  |
|                                         | MOS                                                                                                         | 29-Dec-98 |                           |          |                           |           |              | Service ATA:51   |
|                                         | HRS                                                                                                         | 0         |                           |          |                           |           |              |                  |
| WC#: 51.050                             | AFL                                                                                                         | 0         | 10000 (+10%/-10%)         |          | 10000                     | 11000     | 3505 (+1000) |                  |
|                                         |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                  |
| 510121                                  | INSPECT FORWARD PRESSURE BULKHEAD(PRIORITY AREA INSPECTION)                                                 |           |                           |          |                           |           |              |                  |
|                                         | MOS                                                                                                         | 14-Dec-18 |                           |          |                           |           |              | Service ATA:51   |
|                                         | HRS                                                                                                         | 5079.9    |                           |          |                           |           |              | MANDATORY        |
| WC#: 51.020                             | AFL                                                                                                         | 6043      | 2500 (+10%/-10%)          |          | 8543                      | 8793      | 2048 (+250)  |                  |
|                                         |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                  |
| ATA 52 - DOORS                          |                                                                                                             |           |                           |          |                           |           |              |                  |
| 520101                                  | CABIN DOOR                                                                                                  |           |                           |          |                           |           |              |                  |
| PN:101-430104-601                       | MOS/MSC                                                                                                     | 29-Dec-98 | O/C                       |          |                           |           |              | Component ATA:52 |
| SN:UNKNOWN                              | HRS                                                                                                         | 0         |                           | TSN 0    |                           |           |              |                  |
| WC#: 52.010                             | AFL                                                                                                         | 0         |                           |          |                           |           |              |                  |
|                                         |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                  |
| 520105                                  | INSPECT AIRSTAIR/CARGO DOORS, ESCAPE HATCHES (PRIORITY AREA INSPECTION)                                     |           |                           |          |                           |           |              |                  |
|                                         | MOS                                                                                                         | 30-Jun-18 |                           |          |                           |           |              | Service ATA:52   |
|                                         | HRS                                                                                                         |           |                           |          |                           |           |              | MANDATORY        |
| WC#: 52.130                             | AFL                                                                                                         | 5984      | 1000 (+10%/-10%)          |          | 6984                      | 7084      | 489 (+100)   |                  |
|                                         |                                                                                                             |           | PROC. REF: AMM 53-10-00   |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN          | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS   |                                              |           |          |          |                           |           |           |                  |
| 520116           | CABIN DOOR DAMPER                            |           |          |          |                           |           |           | Component ATA:52 |
| PN:50-430143-33  | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN       | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.020      | AFL                                          | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: AMM 52-10-17                      |           |          |          |                           |           |           |                  |
| 520126           | CABIN DOOR SEAL                              |           |          |          |                           |           |           | Component ATA:52 |
| PN:50-430061-27  | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN       | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.030      | AFL                                          | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: AMM 52-10-15                      |           |          |          |                           |           |           |                  |
| 520131           | CABIN DOOR CLOSED SWITCH                     |           |          |          |                           |           |           | Component ATA:52 |
| PN:U3-1          | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN       | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.110      | AFL                                          | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 520141           | CABIN DOOR LOCKED SWITCH                     |           |          |          |                           |           |           | Component ATA:52 |
| PN:U3-1          | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN       | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.120      | AFL                                          | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 520146           | EMERGENCY EXIT DOOR                          |           |          |          |                           |           |           | Component ATA:52 |
| PN:115-430100-93 | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN       | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.040      | AFL                                          | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: AMM 52-20-01                      |           |          |          |                           |           |           |                  |
| 520156           | UPPER FORWARD CABIN AIRSTAIR DOOR LATCH-BOLT |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN    | MOS                                          | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN       | HRS                                          |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.050      | AFL                                          | 4987      | 5000     | TSN 0    | 9987                      |           | 3492      |                  |
|                  | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 520161           | UPPER AFT CABIN AIRSTAIR DOOR LATCH-BOLT     |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN    | MOS                                          | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN       | HRS                                          |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.060      | AFL                                          | 4987      | 5000     | TSN 0    | 9987                      |           | 3492      |                  |
|                  | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                                                        | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|-------------------------------------------------------------------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS      |                                                                                                             |           |                           |          |                           |           |           |                  |
| 520166              | LOWER FORWARD CABIN AIRSTAIR DOOR LATCH-BOLT                                                                |           |                           |          |                           |           |           |                  |
| PN:PN-UNKNOWN       | MOS                                                                                                         | 26-Nov-16 |                           | TSN 0    |                           |           |           | Component ATA:52 |
| SN:UNKNOWN          | HRS                                                                                                         |           |                           | TSN 0    |                           |           |           | SCRAP            |
| WC#: 52.050         | AFL                                                                                                         | 4987      | 5000                      | TSN 0    | 9987                      |           | 3492      |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 520171              | LOWER AFT CABIN AIRSTAIR DOOR LATCH-BOLT                                                                    |           |                           |          |                           |           |           |                  |
| PN:PN-UNKNOWN       | MOS                                                                                                         | 26-Nov-16 |                           | TSN 0    |                           |           |           | Component ATA:52 |
| SN:UNKNOWN          | HRS                                                                                                         |           |                           | TSN 0    |                           |           |           | SCRAP            |
| WC#: 52.060         | AFL                                                                                                         | 4987      | 5000                      | TSN 0    | 9987                      |           | 3492      |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 520176              | REPLACE FORWARD CABIN AIRSTAIR DOOR UPPER HOOK MECHANISM (INCLUDING PINS, BRACKETS, SPRING, ARM AND HOOKS). |           |                           |          |                           |           |           |                  |
|                     | MOS                                                                                                         | 29-Dec-98 |                           |          |                           |           |           | Service ATA:52   |
|                     | HRS                                                                                                         | 0         |                           |          |                           |           |           | MANDATORY        |
| WC#: 52.100         | AFL                                                                                                         | 0         | 10000                     |          | 10000                     |           | 3505      |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 520177              | REPLACE AFT CABIN AIRSTAIR DOOR UPPER HOOK MECHANISM (INCLUDING PINS, BRACKETS, SPRING, ARM AND HOOKS).     |           |                           |          |                           |           |           |                  |
| PN:PN               | MOS                                                                                                         | 29-Dec-98 |                           | TSN 0    |                           |           |           | Service ATA:52   |
| SN:UNKNOWN          | HRS                                                                                                         | 0         |                           | TSN 0    |                           |           |           |                  |
|                     | AFL                                                                                                         | 0         | 10000                     | TSN 0    | 10000                     |           | 3505      |                  |
|                     |                                                                                                             |           | PROC. REF: AMM GENERIC 1  |          |                           |           |           |                  |
| 520181              | CABIN DOOR SEAL PNEUMATIC VALVE                                                                             |           |                           |          |                           |           |           |                  |
| PN:MS28056-1        | MOS/MSC                                                                                                     | 29-Dec-98 | O/C                       |          |                           |           |           | Component ATA:52 |
| SN:UNKNOWN          | HRS                                                                                                         | 0         |                           | TSN 0    |                           |           |           |                  |
| WC#: 52.070         | AFL                                                                                                         | 0         |                           |          |                           |           |           |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 520190              | CARGO DOOR                                                                                                  |           |                           |          |                           |           |           |                  |
| PN:101-430139-601   | MOS/MSC                                                                                                     | 29-Dec-98 | O/C                       |          |                           |           |           | Component ATA:52 |
| SN:UNKNOWN          | HRS                                                                                                         | 0         |                           | TSN 0    |                           |           |           |                  |
| WC#: 52.080         | AFL                                                                                                         | 0         |                           |          |                           |           |           |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| ATA 53 - FUSELAGE   |                                                                                                             |           |                           |          |                           |           |           |                  |
| 530099 <sup>U</sup> | RAISBECK DUAL AFT BODY STRAKES - STC SA3519NM                                                               |           |                           |          |                           |           |           |                  |
| PN:PN - UNK         | MOS/MSC                                                                                                     | 02-May-03 | O/C                       | TSN 0    |                           |           |           | Component ATA:53 |
| SN:574              | HRS                                                                                                         | 1320.5    |                           | TSN 0    |                           |           |           |                  |
|                     | AFL                                                                                                         |           |                           | TSN 0    |                           |           |           |                  |
|                     |                                                                                                             |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                                                                                                           | C/W       | Interval            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 53 - FUSELAGE         |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530104                    | INSPECT CABIN DOOR AND FUSELAGE FRAME (PRIORITY AREA INSPECTION)                                                                               |           |                     |          |                           |           |              |                  |
|                           | MOS                                                                                                                                            |           |                     |          |                           |           |              | Service ATA:53   |
|                           | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
|                           | AFL                                                                                                                                            | EFF       | T:10000 (+10%/-10%) |          | 10000 *                   | 11000     | 3505 (+1000) |                  |
| PROC. REF: AMM 53-10-00   |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530105                    | INSPECT LEFT WINDSHIELD DOUBLERS/CLIPS OF THE FUSELAGE AT THE UPPER AND LOWER WINDSHIELD AND STORM WINDOW CORNERS FOR CRACKS AND LOOSE RIVETS  |           |                     |          |                           |           |              |                  |
|                           | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              | Service ATA:53   |
|                           | HRS                                                                                                                                            |           |                     |          |                           |           |              | MANDATORY        |
|                           | AFL                                                                                                                                            |           | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3505 (+1000) |                  |
| PROC. REF: AMM 53-10-00   |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530120                    | INSPECT RIGHT WINDSHIELD DOUBLERS/CLIPS OF THE FUSELAGE AT THE UPPER AND LOWER WINDSHIELD AND STORM WINDOW CORNERS FOR CRACKS AND LOOSE RIVETS |           |                     |          |                           |           |              |                  |
|                           | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              | Service ATA:53   |
|                           | HRS                                                                                                                                            |           |                     |          |                           |           |              | MANDATORY        |
|                           | AFL                                                                                                                                            | 0         | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3505 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530126                    | RADOME                                                                                                                                         |           |                     |          |                           |           |              |                  |
|                           | PN:101-410068-5                                                                                                                                | MOS/MSC   | 29-Dec-98           | O/C      |                           |           |              | Component ATA:53 |
|                           | SN:UNKNOWN                                                                                                                                     | HRS       | 0                   | TSN 0    |                           |           |              |                  |
|                           | WC#: 53.010                                                                                                                                    | AFL       | 0                   |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530160                    | INSPECT AFT FUSELAGE AREA AND REAR PRESSURE BULKHEAD(PRIORITY AREA INSPECTION)                                                                 |           |                     |          |                           |           |              |                  |
|                           | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              | Service ATA:53   |
|                           | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
|                           | AFL                                                                                                                                            |           | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3505 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530161                    | INSPECT STRINGERS 5 THROUGH 11 ON THE AFT SIDE OF THE REAR PRESSURE BULKHEAD                                                                   |           |                     |          |                           |           |              |                  |
|                           | MOS/MSC                                                                                                                                        | 18-Dec-18 | N/R                 |          |                           |           |              | Service ATA:53   |
|                           | HRS                                                                                                                                            | 5079.9    |                     |          |                           |           |              | MANDATORY        |
|                           | AFL                                                                                                                                            | 6043      |                     |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                                |           |                     |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                                                                                     | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|--------------------------|----------------------------------------------------------------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 53 - FUSELAGE        |                                                                                                          |           |                           |          |                           |           |              |                |
| 530162                   | INSPECT FOR CRACKS ABOVE AND BELOW THE STRINGER CUTOUTS IN THE BEND RADIUS OF THE REAR PRESSURE BULKHEAD |           |                           |          |                           |           |              |                |
|                          | MOS                                                                                                      | 29-Dec-98 |                           |          |                           |           |              | Service ATA:53 |
|                          | HRS                                                                                                      | 0         |                           |          |                           |           |              | MANDATORY      |
| WC#: 53.040              | AFL                                                                                                      | 0         | T:10000 (+10%/-10%)       |          | 10000                     | 11000     | 3505 (+1000) |                |
|                          |                                                                                                          |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                |
|                          |                                                                                                          |           |                           |          |                           |           |              |                |
| 530170 <sup>U</sup>      | PERFORM RAISBECK DUAL AFT BODY STRAKES INSPECTION                                                        |           |                           |          |                           |           |              |                |
|                          | MOS                                                                                                      | 22-May-24 |                           |          |                           |           |              | Service ATA:53 |
|                          | HRS                                                                                                      | 5686.2    | 200 (+20/-20)             |          | 5886.2                    | 5906.2    | 200 (+20)    |                |
| 531003                   | AFL                                                                                                      | 6495      |                           |          |                           |           |              |                |
|                          | INSPECT FUSELAGE FRAME WEB FS 179 THROUGH FS 271(PRIORITY AREA INSPECTION)                               |           |                           |          |                           |           |              |                |
|                          | MOS                                                                                                      | 14-Dec-18 |                           |          |                           |           |              | Service ATA:53 |
| WC#: 51.040              | HRS                                                                                                      | 5079.9    |                           |          |                           |           |              |                |
|                          | AFL                                                                                                      | 6043      | 2500 (+10%/-10%)          |          | 8543                      | 8793      | 2048 (+250)  |                |
|                          |                                                                                                          |           | PROC. REF: GENERIC NO REF |          |                           |           |              |                |
| ATA 54 - NACELLES/PYLONS |                                                                                                          |           |                           |          |                           |           |              |                |
| 541001                   | INSPECT NACELLE SPLICE PLATES                                                                            |           |                           |          |                           |           |              |                |
|                          | MOS                                                                                                      | 22-May-24 | 12 (+12d/-12d)            |          | 22-May-25                 | 03-Jun-25 | 311 d (+12)  | Service ATA:54 |
|                          | HRS                                                                                                      | 5686.2    |                           |          |                           |           |              |                |
|                          | AFL                                                                                                      | 6495      |                           |          |                           |           |              |                |
|                          |                                                                                                          |           | PROC. REF: SIRM 57-17-03  |          |                           |           |              |                |
|                          |                                                                                                          |           |                           |          |                           |           |              |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                              | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 55 - STABILIZERS                                 |         |           |          |          |                           |           |           |                  |
| 550010 INSPECTION HORIZONTAL AND VERTICAL STABILIZER |         |           |          |          |                           |           |           |                  |
|                                                      | MOS     | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:55   |
|                                                      | HRS     | 5686.2    |          |          |                           |           |           |                  |
|                                                      | AFL     | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 55-00-11, SIRM 55-00-12              |         |           |          |          |                           |           |           |                  |
| 550101 VERTICAL STABILIZER                           |         |           |          |          |                           |           |           |                  |
| PN:101-640000-601                                    | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:55 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 55.010                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 55-30-01                              |         |           |          |          |                           |           |           |                  |
| 550111 HORIZONTAL STABILIZER                         |         |           |          |          |                           |           |           |                  |
| PN:101-620000-601                                    | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:55 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 55.010                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 55-10-01                              |         |           |          |          |                           |           |           |                  |
| ATA 56 - WINDOWS                                     |         |           |          |          |                           |           |           |                  |
| 560100 WINDSHIELD REPLACE                            |         |           |          |          |                           |           |           |                  |
| PN:PN                                                | MOS/MSC | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:56 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                      | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-01                              |         |           |          |          |                           |           |           |                  |
| 560101 PILOT WINDSHIELD ASSEMBLY                     |         |           |          |          |                           |           |           |                  |
| PN:101-384025-23                                     | MOS/MSC | 16-Jul-19 | O/C      | TSO 0    |                           |           |           | Component ATA:56 |
| SN:19105R0096                                        | HRS     | 5100.9    |          | TSO 0    |                           |           |           |                  |
| WC#: 56.010                                          | AFL     |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-01                              |         |           |          |          |                           |           |           |                  |
| 560104 REPLACE LEFT WINDSHIELD FRAME SCREWS          |         |           |          |          |                           |           |           |                  |
|                                                      | MOS     | 29-Dec-98 |          |          |                           |           |           | Service ATA:56   |
|                                                      | HRS     | 0         |          |          |                           |           |           | LIFE LIMIT       |
|                                                      | AFL     | 0         | 10000    |          | 10000                     |           | 3505      |                  |
| WC#: 56.150                                          |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-10-01                              |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN           | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS  |                                       |           |          |          |                           |           |           |                  |
| 560106            | PILOT STORM WINDOW                    |           |          |          |                           |           |           |                  |
| PN:50-420083-603  | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040       | AFL                                   | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 56-10-05               |           |          |          |                           |           |           |                  |
| 560111            | PILOT SIDE WINDOW                     |           |          |          |                           |           |           |                  |
| PN:50-420066-609  | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050       | AFL                                   | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 56-10-03               |           |          |          |                           |           |           |                  |
| 560116            | COPILOT WINDSHIELD ASSEMBLY           |           |          |          |                           |           |           |                  |
| PN:101-384025-24  | MOS/MSC                               | 13-Oct-04 | O/C      | TSN 0    |                           |           |           | Component ATA:56 |
| SN:04121R3642     | HRS                                   | 1639.2    |          | TSN 0    |                           |           |           |                  |
| WC#: 56.010       | AFL                                   | 1352      |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 56-10-01               |           |          |          |                           |           |           |                  |
| 560119            | REPLACE RIGHT WINDSHIELD FRAME SCREWS |           |          |          |                           |           |           |                  |
|                   | MOS                                   | 13-Oct-04 |          |          |                           |           |           | Service ATA:56   |
|                   | HRS                                   | 1639.2    |          |          |                           |           |           | LIFE LIMIT       |
| WC#: 56.150       | AFL                                   | 1352      | 10000    |          | 11352                     |           | 4857      |                  |
|                   | PROC. REF: AMM 56-10-01               |           |          |          |                           |           |           |                  |
| 560121            | COPILOT STORM WINDOW                  |           |          |          |                           |           |           |                  |
| PN:101-420083-604 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040       | AFL                                   | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 56-10-05               |           |          |          |                           |           |           |                  |
| 560126            | COPILOT SIDE WINDOW                   |           |          |          |                           |           |           |                  |
| PN:101-420081-10  | MOS/MSC                               | 12-Apr-23 | O/C      | TSN 0    |                           |           |           | Component ATA:56 |
| SN:10591          | HRS                                   | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050       | AFL                                   | 6358      |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 56-10-03               |           |          |          |                           |           |           |                  |
| 560201            | NO. 1 POLARIZED WINDOW                |           |          |          |                           |           |           |                  |
| PN:PN             | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:56 |
| SN:UNKNOWN        | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                   | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: AMM 56-20-05               |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN          | Unit                   | C/W       | Interval | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------|------------------------|-----------|----------|-------------------------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS |                        |           |          |                         |                           |           |           |                  |
| 560202           | NO. 2 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560203           | NO. 3 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560204           | NO. 4 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560205           | NO. 5 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560206           | NO. 6 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560207           | NO. 7 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |
| 560208           | NO. 8 POLARIZED WINDOW |           |          |                         |                           |           |           |                  |
| PN:PN            | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0                   |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  | AFL                    | 0         |          | TSN 0                   |                           |           |           |                  |
|                  |                        |           |          | PROC. REF: AMM 56-20-05 |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN          | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS |                                 |           |          |          |                           |           |           |                  |
| 560601           | LEFT NO.1 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           |                  |
| PN:50-440056-17  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.060      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF       |           |          |          |                           |           |           |                  |
| 560606           | LEFT NO.2 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           |                  |
| PN:50-440056-17  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.070      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF       |           |          |          |                           |           |           |                  |
| 560611           | LEFT NO.3 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           |                  |
| PN:50-440056-17  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.080      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF       |           |          |          |                           |           |           |                  |
| 560616           | LEFT NO.4 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           |                  |
| PN:50-440056-17  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.090      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF       |           |          |          |                           |           |           |                  |
| 560621           | LEFT NO.5 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           |                  |
| PN:50-440056-17  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.100      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: GENERIC NO REF       |           |          |          |                           |           |           |                  |
| 560626           | LEFT BAGGAGE COMPARTMENT WINDOW |           |          |          |                           |           |           |                  |
| PN:101-440042-2  | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.110      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: AMM 56-20-13         |           |          |          |                           |           |           |                  |
| 560631           | EMERGENCY EXIT WINDOW           |           |          |          |                           |           |           |                  |
| PN:100-530168-69 | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN       | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.120      | AFL                             | 0         |          |          |                           |           |           |                  |
|                  | PROC. REF: AMM 56-20-09         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS    |                                                                         |           |          |          |                           |           |           |                  |
| 560636              | RIGHT NO.1 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:50-440056-17     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.060         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                  |
| 560641              | RIGHT NO.2 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:50-440056-17     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.070         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                  |
| 560646              | RIGHT NO.3 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:50-440056-17     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.080         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                  |
| 560651              | RIGHT NO.4 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:50-440056-17     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.090         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                  |
| 560656              | RIGHT NO.5 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:50-440056-17     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.100         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                  |
| 560661              | RIGHT BAGGAGE COMPARTMENT WINDOW                                        |           |          |          |                           |           |           |                  |
| PN:101-440042-2     | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:56 |
| SN:UNKNOWN          | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.110         | AFL                                                                     | 0         |          |          |                           |           |           |                  |
|                     | PROC. REF: AMM 56-20-13                                                 |           |          |          |                           |           |           |                  |
| ATA 57 - WINGS      |                                                                         |           |          |          |                           |           |           |                  |
| 570099 <sup>U</sup> | RAISBECK NACELLE OVERWING STORAGE LOCKERS & FLAP FAIRING - STC SA3857NM |           |          |          |                           |           |           |                  |
| PN:PN - UNK         | MOS/MSC                                                                 | 02-May-03 | O/C      |          |                           |           |           | Component ATA:57 |
| SN:KIT 238          | HRS                                                                     | 1320.5    |          | TSN 0    |                           |           |           |                  |
|                     | AFL                                                                     |           |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                                        | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 57 - WINGS                                                                 |         |           |          |          |                           |           |           |                     |
| 570100 <sup>U</sup> REPLACE GAS SHOCK STRUT LH WING LOCKER                     |         |           |          |          |                           |           |           |                     |
| PN:C16-26918                                                                   | MOS/MSC | 15-Jul-22 | O/C      | TSN 0    |                           |           |           | Component    ATA:57 |
| SN:NSN                                                                         | HRS     | 5347.3    |          | TSN 0    |                           |           |           |                     |
|                                                                                | AFL     |           |          |          |                           |           |           |                     |
| 570101    LEFT WING                                                            |         |           |          |          |                           |           |           |                     |
| PN:101-110072-605                                                              | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:57 |
| SN:BB1645                                                                      | HRS     | 0         |          |          |                           |           |           |                     |
| WC#: 57.010                                                                    | AFL     | 0         |          |          |                           |           |           |                     |
| PROC. REF: AMM 57-20-01                                                        |         |           |          |          |                           |           |           |                     |
| 570111    TORQUE CHECK LEFT WING UPPER FORWARD, UPPER AND LOWER AFT WING BOLTS |         |           |          |          |                           |           |           |                     |
|                                                                                | MOS     | 22-May-24 |          |          |                           |           |           | Service    ATA:57   |
|                                                                                | HRS     | 5686.2    | T:200    |          | 5886.2                    |           | 200       |                     |
| WC#: 57.015                                                                    | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                        |         |           |          |          |                           |           |           |                     |
| 570131    REPLACE LEFT WING LOWER FORWARD BOLT AND NUT                         |         |           |          |          |                           |           |           |                     |
|                                                                                | MOS     | 22-May-24 | 60       |          | 22-May-29                 |           | 1772 d    | Service    ATA:57   |
|                                                                                | HRS     | 5686.2    |          |          |                           |           |           | LIFE LIMIT          |
| WC#: 57.010                                                                    | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                        |         |           |          |          |                           |           |           |                     |
| 570133    REPLACE LEFT WING LOWER AFT BOLT AND NUT                             |         |           |          |          |                           |           |           |                     |
|                                                                                | MOS     | 22-May-24 | 240      |          | 22-May-44                 |           | 7251 d    | Service    ATA:57   |
|                                                                                | HRS     | 5686.2    | 20000    |          | 25686.2                   |           | 20000     | LIFE LIMIT          |
| WC#: 57.010                                                                    | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                        |         |           |          |          |                           |           |           |                     |
| 570134    REPLACE LEFT WING UPPER AFT BOLT AND NUT                             |         |           |          |          |                           |           |           |                     |
|                                                                                | MOS     | 22-May-24 | 240      |          | 22-May-44                 |           | 7251 d    | Service    ATA:57   |
|                                                                                | HRS     | 5686.2    | 20000    |          | 25686.2                   |           | 20000     | LIFE LIMIT          |
| WC#: 57.010                                                                    | AFL     | 6495      |          |          |                           |           |           |                     |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                        |         |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN        | Unit                                                                                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570136         | MAGNIFIED VISUAL AND EDDY CURRENT AS SPECIFIED LEFT WING ALL WING-ATTACH FITTING FLAT SURFACES, DEPRESSIONS, COUNTERBORES, BOLT BORES AND BARREL NUT RECESSES, WING BOLTS, AND LOWER FORWARD MAIN SPAR CLEVIS FITTINGS |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1772 d    | MANDATORY      |
|                | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           |                |
| WC#: 57.010    | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-02, SIRM 57-17-01                                                                                                                                                                                |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570137         | REPLACE LEFT WING UPPER FORWARD BOLT AND NUT                                                                                                                                                                           |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    | 06-Dec-13 | 240      |          | 06-Dec-33                 |           | 3431 d    | LIFE LIMIT     |
|                | HRS                                                                                                                                                                                                                    | 3137.1    | 20000    |          | 23137.1                   |           | 17450.9   |                |
| WC#: 57.010    | AFL                                                                                                                                                                                                                    | 3301      |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                                                                                                                                                                |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570160         | EDDY CURRENT LEFT LOWER FORWARD (MAIN) SPAR LUGS                                                                                                                                                                       |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | HRS                                                                                                                                                                                                                    |           | T:15000  |          | 15000                     |           | 9313.8    |                |
| WC#: 57.070    | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-02                                                                                                                                                                                               |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570165         | EDDY CURRENT INSPECT LEFT OUTBOARD WING PANEL LOWER FORWARD SPAR CAP                                                                                                                                                   |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    | 29-Dec-98 |          |          |                           |           |           |                |
|                | HRS                                                                                                                                                                                                                    |           | T:15000  |          | 15000                     |           | 9313.8    |                |
| WC#: 57.080    | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-02                                                                                                                                                                                               |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570185         | EDDY CURRENT INSPECT LEFT CENTER SECTION AND OUTBOARD WING PANEL AFT SPAR LOWER FITTING                                                                                                                                |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    | 29-Dec-98 |          |          |                           |           |           |                |
|                | HRS                                                                                                                                                                                                                    |           | T:27000  |          | 27000                     |           | 21313.8   |                |
| WC#: 57.110    | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-02                                                                                                                                                                                               |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570203         | EDDY CURRENT LEFT WING FORWARD SPAR ANGLE                                                                                                                                                                              |           |          |          |                           |           |           | Service ATA:57 |
|                | MOS                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | HRS                                                                                                                                                                                                                    | EFF       | T:18000  |          | 18000 *                   |           | 12313.8   |                |
|                | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                | PROC. REF: SIRM 57-17-02                                                                                                                                                                                               |           |          |          |                           |           |           |                |
|                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                 | Unit                                                       | C/W     | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|------------------------------------------------------------|---------|-----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                          |                                                            |         |           |          |                           |           |           |                  |
| 570204                                  | EDDY CURRENT RIGHT WING FORWARD SPAR ANGLE                 |         |           |          |                           |           |           |                  |
|                                         | MOS                                                        |         |           |          |                           |           |           | Service ATA:57   |
|                                         | HRS                                                        | EFF     | T:18000   |          | 18000 *                   |           | 12313.8   |                  |
|                                         | AFL                                                        |         |           |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |         |           |          |                           |           |           |                  |
| 570300                                  | CENTER SECTION WING                                        |         |           |          |                           |           |           |                  |
|                                         | PN:RA2000                                                  | MOS/MSC | 29-Dec-98 | O/C      | TSN 0                     |           |           | Component ATA:57 |
|                                         | SN:UNKNOWN                                                 | HRS     | 0         |          | TSN 0                     |           |           |                  |
|                                         | WC#: 57.120                                                | AFL     | 0         |          | TSN 0                     |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                            |         |           |          |                           |           |           |                  |
| 570301                                  | EDDY CURRENT INSPECT CENTER SECTION LOWER FORWARD SPAR CAP |         |           |          |                           |           |           |                  |
|                                         | MOS                                                        |         |           |          |                           |           |           | Service ATA:57   |
|                                         | HRS                                                        |         | T:18000   |          | 18000                     |           | 12313.8   |                  |
|                                         | WC#: 57.090                                                | AFL     |           |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                            |         |           |          |                           |           |           |                  |
| 570305                                  | REPLACE WING-TO-FUSELAGE ATTACH ANGLES                     |         |           |          |                           |           |           |                  |
|                                         | MOS                                                        |         | 29-Dec-98 |          |                           |           |           | Service ATA:57   |
|                                         | HRS                                                        | 0       | 30000     | TAC 0    | 30000                     |           | 24313.8   | LIFE LIMIT       |
|                                         | WC#: 57.130                                                | AFL     | 0         |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                            |         |           |          |                           |           |           |                  |
| 570306                                  | EDDY CURRENT INSPECT CENTER SECTION BELLY SKIN             |         |           |          |                           |           |           |                  |
|                                         | MOS                                                        |         | 29-Dec-98 |          |                           |           |           | Service ATA:57   |
|                                         | HRS                                                        |         | T:22500   |          | 22500                     |           | 16813.8   |                  |
|                                         | WC#: 57.100                                                | AFL     |           |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |         |           |          |                           |           |           |                  |
| 570311                                  | EDDY CURRENT INSPECT CENTER SECTION LOWER AFT SPAR         |         |           |          |                           |           |           |                  |
|                                         | MOS                                                        |         | 29-Dec-98 |          |                           |           |           | Service ATA:57   |
|                                         | HRS                                                        |         | T:27000   |          | 27000                     |           | 21313.8   |                  |
|                                         | WC#: 57.110                                                | AFL     |           |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |         |           |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN           | Unit                                                                                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS    |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570601            | RIGHT WING                                                                                                                                                                                                             |           |          |          |                           |           |           |                  |
| PN:101-110072-606 | MOS/MSC                                                                                                                                                                                                                | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:57 |
| SN:BB1645         | HRS                                                                                                                                                                                                                    | 0         |          |          |                           |           |           |                  |
| WC#: 57.020       | AFL                                                                                                                                                                                                                    | 0         |          |          |                           |           |           |                  |
|                   | PROC. REF: AMM 57-20-01                                                                                                                                                                                                |           |          |          |                           |           |           |                  |
| 570611            | TORQUE CHECK RIGHT WING UPPER FORWARD, UPPER AND LOWER AFT WING BOLTS                                                                                                                                                  |           |          |          |                           |           |           |                  |
|                   | MOS                                                                                                                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                   | HRS                                                                                                                                                                                                                    | 5686.2    | T:200    |          | 5886.2                    |           | 200       |                  |
| WC#: 57.015       | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
|                   | PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                                                                                                                                                                |           |          |          |                           |           |           |                  |
| 570631            | REPLACE RIGHT WING LOWER FORWARD BOLT AND NUT                                                                                                                                                                          |           |          |          |                           |           |           |                  |
|                   | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1772 d    | Service ATA:57   |
|                   | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           | LIFE LIMIT       |
| WC#: 57.020       | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
|                   | PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                                                                                                                                                                |           |          |          |                           |           |           |                  |
| 570633            | REPLACE RIGHT WING LOWER AFT BOLT AND NUT                                                                                                                                                                              |           |          |          |                           |           |           |                  |
|                   | MOS                                                                                                                                                                                                                    | 22-May-24 | 240      |          | 22-May-44                 |           | 7251 d    | Service ATA:57   |
|                   | HRS                                                                                                                                                                                                                    | 5686.2    | 20000    |          | 25686.2                   |           | 20000     | LIFE LIMIT       |
| WC#: 57.020       | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
|                   | PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                                                                                                                                                                |           |          |          |                           |           |           |                  |
| 570634            | REPLACE RIGHT WING UPPER AFT BOLT AND NUT                                                                                                                                                                              |           |          |          |                           |           |           |                  |
|                   | MOS                                                                                                                                                                                                                    | 22-May-24 | 240      |          | 22-May-44                 |           | 7251 d    | Service ATA:57   |
|                   | HRS                                                                                                                                                                                                                    | 5686.2    | 20000    |          | 25686.2                   |           | 20000     | LIFE LIMIT       |
| WC#: 57.020       | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
|                   | PROC. REF: SIRM 57-17-01, SIRM 57-17-02                                                                                                                                                                                |           |          |          |                           |           |           |                  |
| 570636            | MAGNIFIED VISUAL AND EDDY CURRENT AS SPECIFIED RIGHT WING ALL WING-ATTACH FITTING FLAT SURFACES, DEPRESSIONS, COUNTERBORES, BOLT BORES AND BARREL NUT RECESSES, WING BOLTS AND LOWER FORWARD MAIN SPAR CLEVIS FITTINGS |           |          |          |                           |           |           |                  |
|                   | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1772 d    | Service ATA:57   |
|                   | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           | MANDATORY        |
| WC#: 57.020       | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
|                   | PROC. REF: SIRM 57-17-02, SIRM 57-17-01                                                                                                                                                                                |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                                 | Unit                                                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                  |
|-----------------------------------------|------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------------------|
| ATA 57 - WINGS                          |                                                                                          |           |          |          |                           |           |           |                              |
| 570637                                  | REPLACE RIGHT WING UPPER FORWARD BOLT AND NUT                                            |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      | 06-Dec-13 | 240      |          | 06-Dec-33                 |           | 3431 d    | Service ATA:57<br>LIFE LIMIT |
|                                         | HRS                                                                                      | 3137.1    | 20000    |          | 23137.1                   |           | 17450.9   |                              |
| WC#: 57.020                             | AFL                                                                                      | 3301      |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                              |
| 570660                                  | EDDY CURRENT RIGHT LOWER FORWARD (MAIN) SPAR LUGS                                        |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      |           |          |          |                           |           |           | Service ATA:57               |
|                                         | HRS                                                                                      |           | T:15000  |          | 15000                     |           | 9313.8    |                              |
| WC#: 57.070                             | AFL                                                                                      |           |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                              |
| 570665                                  | EDDY CURRENT INSPECT RIGHT OUTBOARD WING PANEL LOWER FORWARD SPAR CAP                    |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      | 29-Dec-98 |          |          |                           |           |           | Service ATA:57               |
|                                         | HRS                                                                                      |           | T:15000  |          | 15000                     |           | 9313.8    |                              |
| WC#: 57.080                             | AFL                                                                                      |           |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                              |
| 570685                                  | EDDY CURRENT INSPECT RIGHT CENTER SECTION AND OUTBOARD WING PANEL AFT SPAR LOWER FITTING |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      | 29-Dec-98 |          |          |                           |           |           | Service ATA:57               |
|                                         | HRS                                                                                      |           | T:27000  |          | 27000                     |           | 21313.8   |                              |
| WC#: 57.110                             | AFL                                                                                      |           |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                              |
| 571101                                  | VISUALLY INSPECT LEFT WING OUTBOARD WING PANEL UPPER AND LOWER MAIN SPAR CAPS            |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:57               |
|                                         | HRS                                                                                      | 5686.2    |          |          |                           |           |           |                              |
| WC#: 57.040                             | AFL                                                                                      | 6495      |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                              |
| 571601                                  | VISUALLY INSPECT RIGHT WING OUTBOARD WING PANEL UPPER AND LOWER MAIN SPAR CAPS           |           |          |          |                           |           |           |                              |
|                                         | MOS                                                                                      | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:57               |
|                                         | HRS                                                                                      | 5686.2    |          |          |                           |           |           |                              |
| WC#: 57.040                             | AFL                                                                                      | 6495      |          |          |                           |           |           |                              |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                              |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                        | C/W       | Interval       | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |
|----------------------------------|-------------------------------------------------------------|-----------|----------------|-----------|---------------------------|-----------|------------|------------------|
| ATA 57 - WINGS                   |                                                             |           |                |           |                           |           |            |                  |
| 572000                           | INSPECT WING CENTER SECTION UPPER SURFACE BONDED PANEL SKIN |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 12-Apr-23 | 18 (+18d/-18d) |           | 12-Oct-24                 | 30-Oct-24 | 89 d (+18) | Service ATA:57   |
|                                  | HRS                                                         | 5500.3    |                |           |                           |           |            |                  |
| WC#: 57.050                      | AFL                                                         | 6358      |                |           |                           |           |            |                  |
|                                  | PROC. REF: AMM 51-10-01, AMM 57-10-01                       |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
| 573040 <sup>U</sup>              | PERFORM RAISBECK NACELLE / WING LOCKERS INSPECTION          |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 22-May-24 |                |           |                           |           |            |                  |
|                                  | HRS                                                         | 5686.2    | 200 (+20/-20)  |           | 5886.2                    | 5906.2    | 200 (+20)  |                  |
|                                  | AFL                                                         | 6495      |                |           |                           |           |            |                  |
|                                  | PROC. REF: MIM GENERIC                                      |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
| ATA 61 - PROPELLERS / PROPELLERS |                                                             |           |                |           |                           |           |            |                  |
| 610000                           | NO. 1 PROPELLER - OVERHAUL                                  |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 13-Feb-19 | 72             |           | 13-Feb-25                 |           | 213 d      | Service ATA:61   |
|                                  | HRS                                                         | 4554.9    | 4000           |           | (8554.9)<br>9082.9        |           | 3396.7     | OVERHAUL         |
|                                  | PROC. REF: MIM GENERIC                                      |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
| 610000                           | NO. 2 PROPELLER - OVERHAUL                                  |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 13-Feb-19 | 72             |           | 13-Feb-25                 |           | 213 d      | Service ATA:61   |
|                                  | HRS                                                         | 4554.9    | 4000           |           | (8554.9)<br>9082.9        |           | 3396.7     | OVERHAUL         |
|                                  | PROC. REF: MIM GENERIC                                      |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
| 610131                           | NO. 1 PROPELLER OVERSPEED GOVERNOR                          |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 31-Jan-19 |                | TSO 0     |                           |           |            | Component ATA:61 |
|                                  | HRS                                                         | 5082.9    | 6500           | TSO 0     | 11582.9                   |           | 5896.7     | OVERHAUL         |
| WC#: 61.020                      | AFL                                                         | 6044      |                | TSO 0     |                           |           |            |                  |
|                                  | PROC. REF: AMM 61-20-09                                     |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |
| 610141                           | NO. 1 PROPELLER GOVERNOR                                    |           |                |           |                           |           |            |                  |
|                                  | MOS                                                         | 13-Feb-19 |                | TSO 87    |                           |           |            | Component ATA:61 |
|                                  | HRS                                                         | 5082.9    | 4500           | TSO 693.3 | 8889.6                    |           | 3203.4     | OVERHAUL         |
| WC#: 61.030                      | AFL                                                         | 6044      |                | TSO 693   |                           |           |            |                  |
|                                  | PROC. REF: AMM 61-20-01                                     |           |                |           |                           |           |            |                  |
|                                  |                                                             |           |                |           |                           |           |            |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                       | Unit                                 | C/W       | Interval | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------|--------------------------------------|-----------|----------|-------------------------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPLSORS |                                      |           |          |                         |                           |           |           |                  |
| 610151                        | NO. 1 PROPELLER TACHOMETER GENERATOR |           |          |                         |                           |           |           |                  |
| PN:50-389057-1                | MOS/MSC                              | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:61 |
| SN:20915                      | HRS                                  | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 61.040                   | AFL                                  | 0         |          |                         |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 77-14-01 |                           |           |           |                  |
| 610156                        | NO. 1 PROPELLER TACH INDICATOR       |           |          |                         |                           |           |           |                  |
| PN:90-380009-2                | MOS/MSC                              | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                    | HRS                                  | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 61.050                   | AFL                                  | 0         |          |                         |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 77-14-01 |                           |           |           |                  |
| 610631                        | NO. 2 PROPELLER OVERSPEED GOVERNOR   |           |          |                         |                           |           |           |                  |
| PN:210638F                    | MOS                                  | 31-Jan-19 |          | TSO 0                   |                           |           |           | Component ATA:61 |
| SN:2167497                    | HRS                                  | 5082.9    | 6500     | TSO 0                   | 11582.9                   |           | 5896.7    | OVERHAUL         |
| WC#: 61.020                   | AFL                                  | 6044      |          | TSO 0                   |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 61-20-09 |                           |           |           |                  |
| 610641                        | NO. 2 PROPELLER GOVERNOR             |           |          |                         |                           |           |           |                  |
| PN:8210-024-01                | MOS                                  | 13-Feb-19 |          | TSO 87                  |                           |           |           | Component ATA:61 |
| SN:10020542                   | HRS                                  | 5082.9    | 4500     | TSO 693.3               | 8889.6                    |           | 3203.4    | OVERHAUL         |
| WC#: 61.030                   | AFL                                  | 6044      |          | TSO 693                 |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 61-20-01 |                           |           |           |                  |
| 610651                        | NO. 2 PROPELLER TACHOMETER GENERATOR |           |          |                         |                           |           |           |                  |
| PN:50-389057-1                | MOS/MSC                              | 29-Dec-98 | O/C      |                         |                           |           |           | Component ATA:61 |
| SN:21012                      | HRS                                  | 0         |          | TSN 0                   |                           |           |           |                  |
| WC#: 61.040                   | AFL                                  | 0         |          |                         |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 77-14-01 |                           |           |           |                  |
| 610656                        | NO. 2 PROPELLER TACH INDICATOR       |           |          |                         |                           |           |           |                  |
| PN:101-380092-3               | MOS/MSC                              | 13-Feb-19 | O/C      | TSO 0                   |                           |           |           | Component ATA:61 |
| SN:110M                       | HRS                                  | 5082.9    |          | TSO 0                   |                           |           |           |                  |
| WC#: 61.050                   | AFL                                  | 6044      |          | TSO 0                   |                           |           |           |                  |
|                               |                                      |           |          | PROC. REF: AMM 77-14-01 |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                        | Unit                                                                | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|---------------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPLUSORS |                                                                     |           |           |          |                           |           |           |                  |
| 611010                         | NO. 1 PROPELLER - PERIODIC INSPECTION                               |           |           |          |                           |           |           |                  |
|                                | MOS                                                                 | 22-May-24 | 12        |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                                | HRS                                                                 | 5158.2    | 400       |          | (5558.2)<br>6086.2        |           | 400       |                  |
| PROC. REF: POM 61-00-49        |                                                                     |           |           |          |                           |           |           |                  |
| 611010                         | NO. 2 PROPELLER - PERIODIC INSPECTION                               |           |           |          |                           |           |           |                  |
|                                | MOS                                                                 | 22-May-24 | 12        |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                                | HRS                                                                 | 5158.2    | 400       |          | (5558.2)<br>6086.2        |           | 400       |                  |
| PROC. REF: POM 61-00-49        |                                                                     |           |           |          |                           |           |           |                  |
| 611020                         | NO. 1 PROPELLER - LUBRICATE                                         |           |           |          |                           |           |           |                  |
|                                | MOS                                                                 | 22-May-24 | 12        |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                                | HRS                                                                 | 5158.2    | 400       |          | (5558.2)<br>6086.2        |           | 400       |                  |
| PROC. REF: MM GENERIC          |                                                                     |           |           |          |                           |           |           |                  |
| 611020                         | NO. 2 PROPELLER - LUBRICATE                                         |           |           |          |                           |           |           |                  |
|                                | MOS                                                                 | 22-May-24 | 12        |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                                | HRS                                                                 | 5158.2    | 400       |          | (5558.2)<br>6086.2        |           | 400       |                  |
| PROC. REF: MM GENERIC          |                                                                     |           |           |          |                           |           |           |                  |
| 611025                         | NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS |           |           |          |                           |           |           |                  |
|                                | MOS/MSC                                                             |           | A/R       |          |                           |           |           | Service ATA:61   |
|                                | HRS                                                                 |           |           |          |                           |           |           | CPCP             |
| PROC. REF: POM 61-00-49        |                                                                     |           |           |          |                           |           |           |                  |
| 611025                         | NO. 2 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS |           |           |          |                           |           |           |                  |
|                                | MOS/MSC                                                             |           | A/R       |          |                           |           |           | Service ATA:61   |
|                                | HRS                                                                 |           |           |          |                           |           |           | CPCP             |
| PROC. REF: POM 61-00-49        |                                                                     |           |           |          |                           |           |           |                  |
| 611101                         | NO. 1 PROPELLER - NO. 1 PROPELLER BLADE                             |           |           |          |                           |           |           |                  |
|                                | PN:D9390SK-1R                                                       | MOS/MSC   | 29-Jan-19 | O/C      | TSO 0                     |           |           | Component ATA:61 |
|                                | SN:J19834                                                           | HRS       | 4554.9    |          | TSO 0                     |           |           |                  |
| PROC. REF: MM GENERIC          |                                                                     |           |           |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                        | Unit                                    | C/W       | Interval | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|-----------------------------------------|-----------|----------|---------------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPLUSORS |                                         |           |          |                                       |                           |           |           |                  |
| 611101                         | NO. 2 PROPELLER - NO. 1 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J20054                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611101                         | PROPELLER SYNCHROPHASER CONTROL BOX     |           |          |                                       |                           |           |           |                  |
| PN:6852-920                    | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                     | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 61.070                    | AFL                                     | 0         |          |                                       |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: AMM 61-23-01, AMM 61-25-01 |                           |           |           |                  |
| 611102                         | NO. 1 PROPELLER - NO. 2 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J19829                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611102                         | NO. 2 PROPELLER - NO. 2 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J20051                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611103                         | NO. 1 PROPELLER - NO. 3 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J19827                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611103                         | NO. 2 PROPELLER - NO. 3 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J99020                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611104                         | NO. 1 PROPELLER - NO. 4 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J19828                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611104                         | NO. 2 PROPELLER - NO. 4 PROPELLER BLADE |           |          |                                       |                           |           |           |                  |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           | Component ATA:61 |
| SN:J20059                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                              | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPLUSORS                       |         |           |          |          |                           |           |           |                  |
| 611106 PROPELLER SYNCHROPHASER ACTUATOR              |         |           |          |          |                           |           |           |                  |
| PN:5485-020                                          | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.070                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01                |         |           |          |          |                           |           |           |                  |
| 611121 PROPELLER SYNCHROSCOPE                        |         |           |          |          |                           |           |           |                  |
| PN:A213796J                                          | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:12117233                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.060                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                            |         |           |          |          |                           |           |           |                  |
| 611126 NO. 1 PROPELLER SYNCHROPHASER PICK-UP         |         |           |          |          |                           |           |           |                  |
| PN:213181                                            | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.080                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01                |         |           |          |          |                           |           |           |                  |
| 611131 NO.2 PROPELLER SYNCHROPHASER PICK-UP          |         |           |          |          |                           |           |           |                  |
| PN:213181                                            | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.080                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01                |         |           |          |          |                           |           |           |                  |
| 611146 NO. 1 PROPELLER AUTO FEATHER HI-PRESS SWITCH  |         |           |          |          |                           |           |           |                  |
| PN:50-389121-19                                      | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:11610                                             | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.090                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                            |         |           |          |          |                           |           |           |                  |
| 611151 NO. 1 PROPELLER AUTO FEATHER LOW-PRESS SWITCH |         |           |          |          |                           |           |           |                  |
| PN:50-389121-25                                      | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:2285                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.100                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                            |         |           |          |          |                           |           |           |                  |
| 611156 NO. 1 PROPELLER AUTO FEATHER DUMP VALVE       |         |           |          |          |                           |           |           |                  |
| PN:3019906                                           | MOS/MSC | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.110                                          | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-21-01                              |         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                       | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPLSORS |                                                    |           |          |          |                           |           |           |                  |
| 611161                        | NO.2 PROPELLER AUTO FEATHER HI-PRESSURE SWITCH     |           |          |          |                           |           |           |                  |
| PN:50-389121-19               | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:11545                      | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.090                   | AFL                                                | 0         |          |          |                           |           |           |                  |
|                               | PROC. REF: GENERIC NO REF                          |           |          |          |                           |           |           |                  |
| 611166                        | NO.2 PROPELLER AUTO FEATHER LOW-PRESSURE SWITCH    |           |          |          |                           |           |           |                  |
| PN:50-389121-25               | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:2298                       | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.100                   | AFL                                                | 0         |          |          |                           |           |           |                  |
|                               | PROC. REF: GENERIC NO REF                          |           |          |          |                           |           |           |                  |
| 611171                        | NO.2 PROPELLER AUTO FEATHER DUMP VALVE             |           |          |          |                           |           |           |                  |
| PN:3019906                    | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                    | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.110                   | AFL                                                | 0         |          |          |                           |           |           |                  |
|                               | PROC. REF: AMIM 61-21-01                           |           |          |          |                           |           |           |                  |
| 611181                        | NO. 1 PROPELLER REVERSE NOT READY SWITCH           |           |          |          |                           |           |           |                  |
| PN:V3-1                       | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                    | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.120                   | AFL                                                | 0         |          |          |                           |           |           |                  |
|                               | PROC. REF: GENERIC NO REF                          |           |          |          |                           |           |           |                  |
| 611191                        | NO. 2 PROPELLER REVERSE NOT READY SWITCH           |           |          |          |                           |           |           |                  |
| PN:V3-1                       | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:61 |
| SN:UNKNOWN                    | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.120                   | AFL                                                | 0         |          |          |                           |           |           |                  |
|                               | PROC. REF: GENERIC NO REF                          |           |          |          |                           |           |           |                  |
| 611230                        | NO. 1 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION |           |          |          |                           |           |           |                  |
|                               | MOS                                                | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                               | HRS                                                | 5158.2    | 200      |          | (5358.2)<br>5886.2        |           | 200       |                  |
|                               | PROC. REF: MM 30-61-80                             |           |          |          |                           |           |           |                  |
| 611230                        | NO. 2 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION |           |          |          |                           |           |           |                  |
|                               | MOS                                                | 22-May-24 | 12       |          | 22-May-25                 |           | 311 d     | Service ATA:61   |
|                               | HRS                                                | 5158.2    | 200      |          | (5358.2)<br>5886.2        |           | 200       |                  |
|                               | PROC. REF: MM 30-61-80                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                       | Unit                                | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|-------------------------------|-------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPLSORS |                                     |           |          |                           |                           |           |           |                                  |
| 612101                        | NO. 1 PROPELLER PITCH STOP SENSOR   |           |          |                           |                           |           |           |                                  |
| PN:101-960015-601             | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:61                 |
| SN:UNKNOWN                    | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.130                   | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                               |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612106                        | NO.2 PROPELLER PITCH STOP SENSOR    |           |          |                           |                           |           |           |                                  |
| PN:101-960015-601             | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:61                 |
| SN:UNKNOWN                    | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.130                   | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                               |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612111                        | NO. 1 PROPELLER PROXIMITY SWITCH    |           |          |                           |                           |           |           |                                  |
| PN:8-090-01                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:61                 |
| SN:UNKNOWN                    | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.140                   | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                               |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612116                        | NO. 2 PROPELLER PROXIMITY SWITCH    |           |          |                           |                           |           |           |                                  |
| PN:8-090-01                   | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:61                 |
| SN:UNKNOWN                    | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.140                   | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                               |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 616010                        | NO. 1 PROPELLER - DAMPER ASSEMBLY   |           |          |                           |                           |           |           |                                  |
|                               | MOS/MSC                             | 29-Dec-98 | N/A      |                           |                           |           |           | Service ATA:61                   |
|                               | HRS                                 | 0         |          |                           |                           |           |           |                                  |
|                               |                                     |           |          | PROC. REF: MM GENERIC     |                           |           |           |                                  |
| 616010                        | NO. 2 PROPELLER - DAMPER ASSEMBLY   |           |          |                           |                           |           |           |                                  |
|                               | MOS/MSC                             | 30-Jan-09 | N/A      |                           |                           |           |           | Service ATA:61                   |
|                               | HRS                                 | 0         |          |                           |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                               |                                     |           |          | PROC. REF: MM GENERIC     |                           |           |           |                                  |
| 619000                        | NO. 1 PROPELLER - PRE-FLIGHT CHECKS |           |          |                           |                           |           |           |                                  |
|                               | MOS/MSC                             | 29-Dec-98 | A/R      |                           |                           |           |           | Service ATA:61                   |
|                               | HRS                                 | 0         |          |                           |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                               |                                     |           |          | PROC. REF: POM 61-00-49   |                           |           |           |                                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                              | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|--------------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPLUSORS       |                                        |           |          |          |                           |           |           |                                  |
| 619000                               | NO. 2 PROPELLER - PRE-FLIGHT CHECKS    |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                        |           |          |          |                           |           |           |                                  |
| 619010                               | NO. 1 PROPELLER - OPERATIONAL CHECKS   |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                        |           |          |          |                           |           |           |                                  |
| 619010                               | NO. 2 PROPELLER - OPERATIONAL CHECKS   |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                        |           |          |          |                           |           |           |                                  |
| 619020                               | NO. 1 PROPELLER - OVERSPEED/OVERTORQUE |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                        |           |          |          |                           |           |           |                                  |
| 619020                               | NO. 2 PROPELLER - OVERSPEED/OVERTORQUE |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                        |           |          |          |                           |           |           |                                  |
| 619030                               | NO. 1 PROPELLER - LIGHTNING STRIKE     |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                        |           |          |          |                           |           |           |                                  |
| 619030                               | NO. 2 PROPELLER - LIGHTNING STRIKE     |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                    | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                        |           |          |          |                           |           |           |                                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                              | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|--------------------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPLUSORS       |                                                       |           |          |          |                           |           |           |                                  |
| 619040                               | NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                                       |           |          |          |                           |           |           |                                  |
| 619040                               | NO. 2 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                                       |           |          |          |                           |           |           |                                  |
| 619050                               | NO. 1 PROPELLER - FIRE/HEAT DAMAGE                    |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                                       |           |          |          |                           |           |           |                                  |
| 619050                               | NO. 2 PROPELLER - FIRE/HEAT DAMAGE                    |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49, MM 30-61-80 |                                                       |           |          |          |                           |           |           |                                  |
| 619060                               | NO. 1 PROPELLER - SUDDEN STOPPAGE                     |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                                       |           |          |          |                           |           |           |                                  |
| 619060                               | NO. 2 PROPELLER - SUDDEN STOPPAGE                     |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                                       |           |          |          |                           |           |           |                                  |
| 619070                               | NO. 1 PROPELLER - ENGINE OIL CONTAMINATION            |           |          |          |                           |           |           |                                  |
|                                      | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                           |           |           | Service ATA:61                   |
|                                      | HRS                                                   | 0         |          |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49              |                                                       |           |          |          |                           |           |           |                                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                        | Unit                                       | C/W       | Interval  | TSX/Adj.                 | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                   |
|--------------------------------|--------------------------------------------|-----------|-----------|--------------------------|---------------------------|-----------|-----------|-------------------------------|
| ATA 61 - PROPELLERS/PROPLUSORS |                                            |           |           |                          |                           |           |           |                               |
| 619070                         | NO. 2 PROPELLER - ENGINE OIL CONTAMINATION |           |           |                          |                           |           |           |                               |
|                                | MOS/MSC                                    | 30-Jan-09 | A/R       |                          |                           |           |           | Service ATA:61                |
|                                | HRS                                        | 0         |           |                          |                           |           |           | UNSCHEDULED MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49        |                                            |           |           |                          |                           |           |           |                               |
| 619080                         | NO. 1 PROPELLER - LONG TERM STORAGE        |           |           |                          |                           |           |           |                               |
|                                | MOS/MSC                                    | 29-Dec-98 | A/R       |                          |                           |           |           | Service ATA:61                |
|                                | HRS                                        | 0         |           |                          |                           |           |           | UNSCHEDULED MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49        |                                            |           |           |                          |                           |           |           |                               |
| 619080                         | NO. 2 PROPELLER - LONG TERM STORAGE        |           |           |                          |                           |           |           |                               |
|                                | MOS/MSC                                    | 30-Jan-09 | A/R       |                          |                           |           |           | Service ATA:61                |
|                                | HRS                                        | 0         |           |                          |                           |           |           | UNSCHEDULED MAINTENANCE CHECK |
| PROC. REF: POM 61-00-49        |                                            |           |           |                          |                           |           |           |                               |
| 61PR1                          | NO. 1 PROPELLER                            |           |           |                          |                           |           |           |                               |
|                                | PN:HC-E4N-3G                               | MOS/MSC   |           | PP/C                     |                           |           |           | Component ATA:61              |
|                                | SN:HH561                                   | HRS       |           |                          |                           |           |           |                               |
| 61PR2                          | NO. 2 PROPELLER                            |           |           |                          |                           |           |           |                               |
|                                | PN:HC-E4N-3G                               | MOS/MSC   | 10-Feb-12 | PP/C                     |                           |           |           | Component ATA:61              |
|                                | SN:HH3625                                  | HRS       | 2770.7    | TSN 2770.7               |                           |           |           |                               |
| 61PR2                          | NO. 2 PROPELLER                            |           |           |                          |                           |           |           |                               |
|                                | WC#: 61.PR2                                | AFL       | 2864      |                          |                           |           |           | Component ATA:61              |
|                                |                                            |           |           | PROC. REF: AMM GENERIC 1 |                           |           |           |                               |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                               | Unit                                                                                             | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------------------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 70 - STANDARD PRACTICES - ENGINES |                                                                                                  |           |           |          |                           |           |           |                  |
| 700010 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT            |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 700010 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT            |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 700020 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 700020 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 700030 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS                                              |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 700030 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS                                              |           |           |          |                           |           |           |                  |
|                                       | MOS                                                                                              | 22-May-24 |           |          |                           |           |           | Service ATA:70   |
|                                       | HRS                                                                                              | 4291.1    | 200       |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |           |          |                           |           |           |                  |
|                                       |                                                                                                  |           |           |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| ATA 71 - POWER PLANT                  |                                                                                                  |           |           |          |                           |           |           |                  |
| 710001                                | LH TORQUE TRANSMITTER REPLACE                                                                    |           |           |          |                           |           |           |                  |
|                                       | PN:PN                                                                                            | MOS/MSC   | 29-Dec-98 | O/C      | TSN 0                     |           |           | Component ATA:71 |
|                                       | SN:UNKNOWN                                                                                       | HRS       | 0         |          | TSN 0                     |           |           |                  |
|                                       | AFL                                                                                              | 0         |           |          | TSN 0                     |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                   | Unit                               | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 71 - POWER PLANT      |                                    |           |            |          |                           |           |              |                  |
| 710002                    | RH TORQUE TRANSMITTER REPLACE      |           |            |          |                           |           |              |                  |
| PN:PN                     | MOS/MSC                            | 29-Dec-98 | O/C        | TSN 0    |                           |           |              | Component ATA:71 |
| SN:UNKNOWN                | HRS                                | 0         |            | TSN 0    |                           |           |              |                  |
|                           | AFL                                | 0         |            | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 77-10-05   |                                    |           |            |          |                           |           |              |                  |
| 710010                    | NO. 1 ENGINE - OVERHAUL            |           |            |          |                           |           |              |                  |
|                           | MOS                                | 21-Nov-11 |            |          |                           |           |              | Service ATA:71   |
|                           | HRS                                | 2995      | 3600       |          | (6595)<br>7990.1          |           | 2303.9       | OVERHAUL         |
|                           | ENC                                | 2995      |            |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                    |           |            |          |                           |           |              |                  |
| 710010                    | NO. 2 ENGINE - OVERHAUL            |           |            |          |                           |           |              |                  |
|                           | MOS                                | 21-Nov-11 |            |          |                           |           |              | Service ATA:71   |
|                           | HRS                                | 2995      | 3600       |          | (6595)<br>7990.1          |           | 2303.9       | OVERHAUL         |
|                           | ENC                                | 2995      |            |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                    |           |            |          |                           |           |              |                  |
| 710020                    | NO. 1 ENGINE - INSPECT HOT SECTION |           |            |          |                           |           |              |                  |
|                           | MOS                                | 26-Sep-22 |            |          |                           |           |              | Service ATA:71   |
|                           | HRS                                | 3963.4    | 1800 (+50) |          | (5763.4)<br>7158.5        | 5813.4    | 1472.3 (+50) |                  |
|                           | ENC                                | 3963      |            |          |                           |           |              |                  |
| PROC. REF: EMM 72-00-00   |                                    |           |            |          |                           |           |              |                  |
| 710020                    | NO. 2 ENGINE - INSPECT HOT SECTION |           |            |          |                           |           |              |                  |
|                           | MOS                                | 26-Sep-22 |            |          |                           |           |              | Service ATA:71   |
|                           | HRS                                | 3963.4    | 1800 (+50) |          | (5763.4)<br>7158.5        | 5813.4    | 1472.3 (+50) |                  |
|                           | ENC                                | 3963      |            |          |                           |           |              |                  |
| PROC. REF: EMM 72-00-00   |                                    |           |            |          |                           |           |              |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN              | Unit                                         | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition    |
|----------------------|----------------------------------------------|-----------|------------|----------|---------------------------|-----------|------------|----------------|
| ATA 71 - POWER PLANT |                                              |           |            |          |                           |           |            |                |
| 710030               | NO. 1 ENGINE - BORESCOPE INSPECT HOT SECTION |           |            |          |                           |           |            |                |
|                      | MOS                                          | 26-Sep-22 |            |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 3963.4    | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | 72.3 (+40) |                |
|                      | ENC                                          | 3963      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 72-00-00, EMM 72-00-00        |           |            |          |                           |           |            |                |
| 710030               | NO. 2 ENGINE - BORESCOPE INSPECT HOT SECTION |           |            |          |                           |           |            |                |
|                      | MOS                                          | 26-Sep-22 |            |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 3963.4    | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | 72.3 (+40) |                |
|                      | ENC                                          | 3963      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 72-00-00, EMM 72-00-00        |           |            |          |                           |           |            |                |
| 710041               | NO. 1 ENGINE - DESALINATION (TURBINE) WASH   |           |            |          |                           |           |            |                |
|                      | DAYS/MSC                                     | 04-Jan-23 | A/R        |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 4066.4    |            |          |                           |           |            |                |
|                      | ENC                                          | 4013      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 71-00-00                      |           |            |          |                           |           |            |                |
| 710041               | NO. 2 ENGINE - DESALINATION (TURBINE) WASH   |           |            |          |                           |           |            |                |
|                      | DAYS/MSC                                     | 04-Jan-23 | A/R        |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 4066.4    |            |          |                           |           |            |                |
|                      | ENC                                          | 4013      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 71-00-00                      |           |            |          |                           |           |            |                |
| 710050               | NO. 1 ENGINE - COMPRESSOR WASH               |           |            |          |                           |           |            |                |
|                      | MOS/MSC                                      | 22-May-24 | A/R        |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 4291.1    |            |          |                           |           |            |                |
|                      | ENC                                          | 4184      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 71-00-00                      |           |            |          |                           |           |            |                |
| 710050               | NO. 2 ENGINE - COMPRESSOR WASH               |           |            |          |                           |           |            |                |
|                      | MOS/MSC                                      | 22-May-24 | A/R        |          |                           |           |            | Service ATA:71 |
|                      | HRS                                          | 4291.1    |            |          |                           |           |            |                |
|                      | ENC                                          | 4184      |            |          |                           |           |            |                |
|                      | PROC. REF: EMM 71-00-00                      |           |            |          |                           |           |            |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                 |
|----------------------|-----------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|-----------|-----------------------------|
| ATA 71 - POWER PLANT |                                                     |           |                           |          |                           |           |           |                             |
| 712001               | NO. 1 ENGINE UPPER UPPER INBOARD ISOLATOR MOUNT     |           |                           |          |                           |           |           |                             |
| PN:PN                | MOS                                                 | 22-Jan-15 |                           | TSN 0    |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                 |           |                           | TSN 0    |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: AMM 71-20-01   |          |                           |           |           |                             |
| 712002               | NO. 1 ENGINE OUTBOARD UPPER OUTBOARD ISOLATOR MOUNT |           |                           |          |                           |           |           |                             |
| PN:PN                | MOS                                                 | 22-Jan-15 |                           | TSN 0    |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                 |           |                           | TSN 0    |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: AMM 71-20-01   |          |                           |           |           |                             |
| 712003               | NO. 1 ENGINE LOWER LOWER INBOARD ISOLATOR MOUNT     |           |                           |          |                           |           |           |                             |
| PN:PN                | MOS                                                 | 22-Jan-15 |                           | TSN 0    |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                 |           |                           | TSN 0    |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: AMM 71-20-01   |          |                           |           |           |                             |
| 712004               | NO. 1 ENGINE OUTBOARD LOWER OUTBOARD ISOLATOR MOUNT |           |                           |          |                           |           |           |                             |
|                      | MOS                                                 | 22-Jan-15 |                           |          |                           |           |           | Component ATA:71<br>REPLACE |
|                      | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
| WC#: 72.030          | AFL                                                 |           |                           |          |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                             |
| 712601               | NO. 2 ENGINE UPPER UPPER INBOARD ISOLATOR MOUNT     |           |                           |          |                           |           |           |                             |
| PN:PN                | MOS                                                 | 22-Jan-15 |                           | TSN 0    |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                 |           |                           | TSN 0    |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: AMM 71-20-01   |          |                           |           |           |                             |
| 712602               | NO. 2 ENGINE OUTBOARD UPPER OUTBOARD ISOLATOR MOUNT |           |                           |          |                           |           |           |                             |
| PN:PN                | MOS                                                 | 22-Jan-15 |                           | TSN 0    |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                 | 3243.3    | 3600                      | TSN 0    | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                 |           |                           | TSN 0    |                           |           |           |                             |
|                      |                                                     |           | PROC. REF: AMM 71-20-01   |          |                           |           |           |                             |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN              | Unit                                                  | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                 |
|----------------------|-------------------------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|-----------------------------|
| ATA 71 - POWER PLANT |                                                       |           |          |                           |                           |           |           |                             |
| 712603               | NO. 2 ENGINE LOWER INBOARD ISOLATOR MOUNT             |           |          |                           |                           |           |           |                             |
| PN:PN                | MOS                                                   | 22-Jan-15 |          | TSN 0                     |                           |           |           | Component ATA:71<br>REPLACE |
| SN:UNKNOWN           | HRS                                                   | 3243.3    | 3600     | TSN 0                     | 6843.3                    |           | 1157.1    |                             |
|                      | AFL                                                   |           |          | TSN 0                     |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: AMM 71-20-01   |                           |           |           |                             |
| 712604               | NO. 2 ENGINE LOWER OUTBOARD ISOLATOR MOUNT            |           |          |                           |                           |           |           |                             |
|                      | MOS                                                   | 22-Jan-15 |          |                           |                           |           |           | Component ATA:71<br>REPLACE |
|                      | HRS                                                   | 3243.3    | 3600     | TSN 0                     | 6843.3                    |           | 1157.1    |                             |
| WC#: 72.030          | AFL                                                   |           |          |                           |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                             |
| 71EN1                | NO. 1 ENGINE                                          |           |          |                           |                           |           |           |                             |
| PN:3030700           | MOS/MSC                                               | 13-Feb-19 | E/C      |                           |                           |           |           | Component ATA:71<br>REPLACE |
| SN:PCE-94718         | HRS                                                   | 5082.9    |          | TSN 3688.3                |                           |           |           |                             |
|                      | AFL                                                   | 6044      |          |                           |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: AMM 71-00-01   |                           |           |           |                             |
| 71EN2                | NO. 2 ENGINE                                          |           |          |                           |                           |           |           |                             |
| PN:3030700           | MOS/MSC                                               | 13-Feb-19 | E/C      |                           |                           |           |           | Component ATA:71<br>REPLACE |
| SN:PCE-94709         | HRS                                                   | 5082.9    |          | TSN 3688.3                |                           |           |           |                             |
|                      | AFL                                                   | 6044      |          |                           |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: AMM 71-00-01   |                           |           |           |                             |
| ATA 72 - ENGINE      |                                                       |           |          |                           |                           |           |           |                             |
| 720010               | NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE |           |          |                           |                           |           |           |                             |
|                      | MOS/MSC                                               | 20-Dec-94 | A/R      |                           |                           |           |           | Service ATA:72              |
|                      | HRS                                                   | 0         |          |                           |                           |           |           |                             |
|                      | ENC                                                   | 0         |          |                           |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: EMM 72-00-00   |                           |           |           |                             |
| 720010               | NO. 2 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE |           |          |                           |                           |           |           |                             |
|                      | MOS/MSC                                               | 20-Dec-94 | A/R      |                           |                           |           |           | Service ATA:72              |
|                      | HRS                                                   | 0         |          |                           |                           |           |           |                             |
|                      | ENC                                                   | 0         |          |                           |                           |           |           |                             |
|                      |                                                       |           |          | PROC. REF: EMM 72-00-00   |                           |           |           |                             |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                               | Unit                                                                                       | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------------------------|--------------------------------------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE                       |                                                                                            |           |           |          |                           |           |           |                     |
| 721000 <sup>S</sup>                   | NO. 1 ENGINE - VISUAL INSPECTION WITH A MIRROR OR A BORESCOPE FIRST-STAGE COMPRESSOR ROTOR |           |           |          |                           |           |           |                     |
|                                       | MOS                                                                                        | 22-May-24 |           |          |                           |           |           | Service    ATA:72   |
|                                       | HRS                                                                                        | 4291.1    | 200       |          |                           |           |           |                     |
|                                       | ENC                                                                                        | 4184      |           |          |                           |           |           |                     |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                                                                            |           |           |          |                           |           |           |                     |
| PKG:1                                 |                                                                                            |           |           |          |                           |           |           |                     |
| 721000 <sup>S</sup>                   | NO. 2 ENGINE - VISUAL INSPECTION WITH A MIRROR OR A BORESCOPE FIRST-STAGE COMPRESSOR ROTOR |           |           |          |                           |           |           |                     |
|                                       | MOS                                                                                        | 22-May-24 |           |          |                           |           |           | Service    ATA:72   |
|                                       | HRS                                                                                        | 4291.1    | 200       |          |                           |           |           |                     |
|                                       | ENC                                                                                        | 4184      |           |          |                           |           |           |                     |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                                                                            |           |           |          |                           |           |           |                     |
| PKG:1                                 |                                                                                            |           |           |          |                           |           |           |                     |
| 721002                                | NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR                                    |           |           |          |                           |           |           |                     |
|                                       | PN:PN                                                                                      | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                                       | SN:UNKNOWN                                                                                 | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                                       | ENC                                                                                        | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |           |          |                           |           |           |                     |
| 721002                                | NO. 2 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR                                    |           |           |          |                           |           |           |                     |
|                                       | PN:PN                                                                                      | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                                       | SN:UNKNOWN                                                                                 | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                                       | ENC                                                                                        | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |           |          |                           |           |           |                     |
| 721003                                | NO. 1 ENGINE - NO. 2 SECOND STAGE REDUCTION PLANET GEAR                                    |           |           |          |                           |           |           |                     |
|                                       | PN:PN                                                                                      | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                                       | SN:UNKNOWN                                                                                 | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                                       | ENC                                                                                        | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |           |          |                           |           |           |                     |
| 721003                                | NO. 2 ENGINE - NO. 2 SECOND STAGE REDUCTION PLANET GEAR                                    |           |           |          |                           |           |           |                     |
|                                       | PN:PN                                                                                      | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                                       | SN:UNKNOWN                                                                                 | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                                       | ENC                                                                                        | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |           |          |                           |           |           |                     |
| 721004                                | NO. 1 ENGINE - NO. 3 SECOND STAGE REDUCTION PLANET GEAR                                    |           |           |          |                           |           |           |                     |
|                                       | PN:PN                                                                                      | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                                       | SN:UNKNOWN                                                                                 | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                                       | ENC                                                                                        | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |           |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                         |           |          |          |                           |           |           |                  |
| 721004          | NO. 2 ENGINE - NO. 3 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721005          | NO. 1 ENGINE - NO. 4 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721005          | NO. 2 ENGINE - NO. 4 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721006          | NO. 1 ENGINE - NO. 5 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721006          | NO. 2 ENGINE - NO. 5 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721007          | NO. 1 ENGINE - FLEX 2ND STAGE REDUCTION COUPLING SHAFT  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |
| 721007          | NO. 2 ENGINE - FLEX 2ND STAGE REDUCTION COUPLING SHAFT  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                               |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                     |           |          |          |                           |           |           |                  |
| 721008          | NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER        |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721008          | NO. 2 ENGINE - FIRST STAGE REDUCTION CARRIER        |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721009          | NO. 1 ENGINE - SECOND STAGE REDUCTION,46 TEETH GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721009          | NO. 2 ENGINE - SECOND STAGE REDUCTION,46 TEETH GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721011          | NO. 1 ENGINE - 1ST STAGE CARRIE ADAPTER             |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721011          | NO. 2 ENGINE - 1ST STAGE CARRIE ADAPTER             |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |
| 721012          | NO. 1 ENGINE - SECOND STAGE REDUCTION CARRIER       |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                           |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                                | Unit    | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------|---------|-----------|---------------------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                        |         |           |                           |          |                           |           |           |                  |
| 721012 NO. 2 ENGINE - SECOND STAGE REDUCTION CARRIER   |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 721013 NO. 1 ENGINE - ROLLER FLANGED BEARING           |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 721013 NO. 2 ENGINE - ROLLER FLANGED BEARING           |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 721014 NO. 1 ENGINE - SECOND STAGE REDUCTION GEAR RING |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 721014 NO. 2 ENGINE - SECOND STAGE REDUCTION GEAR RING |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: GENERIC NO REF |          |                           |           |           |                  |
| 721015 NO. 1 ENGINE - PROPELLER SHAFT                  |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: EMM 72-00-00   |          |                           |           |           |                  |
| 721015 NO. 2 ENGINE - PROPELLER SHAFT                  |         |           |                           |          |                           |           |           |                  |
| PN:PN                                                  | MOS/MSC | 20-Dec-94 | O/C                       | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN                                             | HRS     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        | ENC     | 0         |                           | TSN 0    |                           |           |           |                  |
|                                                        |         |           | PROC. REF: EMM 72-00-00   |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                                |           |          |          |                           |           |           |                  |
| 721016          | NO. 1 ENGINE - NO. 1 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721016          | NO. 2 ENGINE - NO. 1 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721017          | NO. 1 ENGINE - NO. 2 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721017          | NO. 2 ENGINE - NO. 2 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721018          | NO. 1 ENGINE - NO. 3 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721018          | NO. 2 ENGINE - NO. 3 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 721019          | NO. 1 ENGINE - FIRST STAGE REDUCTION GEAR RING                 |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                                    |           |          |          |                           |           |           |                  |
| 721019          | NO. 2 ENGINE - FIRST STAGE REDUCTION GEAR RING                     |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 721020          | NO. 1 ENGINE - BALL2.9528X5.1181X.9843 BEARING                     |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 721020          | NO. 2 ENGINE - BALL2.9528X5.1181X.9843 BEARING                     |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 721021          | NO. 1 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 721021          | NO. 2 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                          |           |          |          |                           |           |           |                  |
| 721022          | NO. 1 ENGINE - TURBINE EXHAUST DUCT ASSEMBLY                       |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-03                                            |           |          |          |                           |           |           |                  |
| 721022          | NO. 2 ENGINE - TURBINE EXHAUST DUCT ASSEMBLY                       |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-03                                            |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                                                                                                                                    | Unit    | C/W       | Interval | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                |
|--------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|-------------------------|---------------------------|-----------|-----------|----------------------------|
| ATA 72 - ENGINE                                                                                                                            |         |           |          |                         |                           |           |           |                            |
| 721023    NO. 1 ENGINE - TURBINE STATOR POWER HOUSING                                                                                      |         |           |          |                         |                           |           |           |                            |
| PN:PN                                                                                                                                      | MOS/MSC | 20-Dec-94 | O/C      | TSN 0                   |                           |           |           | Component    ATA:72        |
| SN:UNKNOWN                                                                                                                                 | HRS     | 0         |          | TSN 0                   |                           |           |           |                            |
|                                                                                                                                            | ENC     | 0         |          | TSN 0                   |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-50-03 |                           |           |           |                            |
| 721023    NO. 2 ENGINE - TURBINE STATOR POWER HOUSING                                                                                      |         |           |          |                         |                           |           |           |                            |
| PN:PN                                                                                                                                      | MOS/MSC | 20-Dec-94 | O/C      | TSN 0                   |                           |           |           | Component    ATA:72        |
| SN:UNKNOWN                                                                                                                                 | HRS     | 0         |          | TSN 0                   |                           |           |           |                            |
|                                                                                                                                            | ENC     | 0         |          | TSN 0                   |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-50-03 |                           |           |           |                            |
| 722000 <sup>S</sup> NO. 1 ENGINE - INSPECT AIR INLET SCREEN FOR CLEANLINESS                                                                |         |           |          |                         |                           |           |           |                            |
|                                                                                                                                            | MOS     | 22-May-24 |          |                         |                           |           |           |                            |
|                                                                                                                                            | HRS     | 4291.1    | 200      |                         |                           |           |           |                            |
|                                                                                                                                            | ENC     | 4184      |          |                         |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-20-00 |                           |           |           | PKG:1    Service    ATA:72 |
| 722000 <sup>S</sup> NO. 2 ENGINE - INSPECT AIR INLET SCREEN FOR CLEANLINESS                                                                |         |           |          |                         |                           |           |           |                            |
|                                                                                                                                            | MOS     | 22-May-24 |          |                         |                           |           |           |                            |
|                                                                                                                                            | HRS     | 4291.1    | 200      |                         |                           |           |           |                            |
|                                                                                                                                            | ENC     | 4184      |          |                         |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-20-00 |                           |           |           | PKG:1    Service    ATA:72 |
| 722010 <sup>S</sup> NO. 1 ENGINE - INSPECT INLET SURFACE AREAS, WITH SCREEN REMOVED, INSPECT OVERALL SURFACE AREA AND STRUTS FOR CORROSION |         |           |          |                         |                           |           |           |                            |
|                                                                                                                                            | MOS     | 22-May-24 |          |                         |                           |           |           |                            |
|                                                                                                                                            | HRS     | 4291.1    | 200      |                         |                           |           |           |                            |
|                                                                                                                                            | ENC     | 4184      |          |                         |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-20-00 |                           |           |           | PKG:1    Service    ATA:72 |
| 722010 <sup>S</sup> NO. 2 ENGINE - INSPECT INLET SURFACE AREAS, WITH SCREEN REMOVED, INSPECT OVERALL SURFACE AREA AND STRUTS FOR CORROSION |         |           |          |                         |                           |           |           |                            |
|                                                                                                                                            | MOS     | 22-May-24 |          |                         |                           |           |           |                            |
|                                                                                                                                            | HRS     | 4291.1    | 200      |                         |                           |           |           |                            |
|                                                                                                                                            | ENC     | 4184      |          |                         |                           |           |           |                            |
|                                                                                                                                            |         |           |          | PROC. REF: EMM 72-20-00 |                           |           |           | PKG:1    Service    ATA:72 |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                             |           |          |          |                           |           |           |                  |
| 723001          | NO. 1 ENGINE - FRONT COMPRESSOR STUB SHAFT  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723001          | NO. 2 ENGINE - FRONT COMPRESSOR STUB SHAFT  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723002          | NO. 1 ENGINE - BALL BEARING                 |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723002          | NO. 2 ENGINE - BALL BEARING                 |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723003          | NO. 1 ENGINE - COMPRESSOR REAR HUB COUPLING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723003          | NO. 2 ENGINE - COMPRESSOR REAR HUB COUPLING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                   |           |          |          |                           |           |           |                  |
| 723004          | NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-30-04                     |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE |                                                            |           |          |          |                           |           |           |                     |
| 723004          | NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY                 |           |          |          |                           |           |           |                     |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                     |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: EMM 72-30-04                                    |           |          |          |                           |           |           |                     |
| 723010          | NO. 1 ENGINE - COMPRESSOR 1ST STAGE HUB / COMPRESSOR ROTOR |           |          |          |                           |           |           |                     |
| PN:3041501      | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:89A368       | HRS                                                        | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                        | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                     | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                     |
| 723010          | NO. 2 ENGINE - COMPRESSOR 1ST STAGE HUB / COMPRESSOR ROTOR |           |          |          |                           |           |           |                     |
| PN:3041501      | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:83A008       | HRS                                                        | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                        | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                     | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                     |
| 723030          | NO. 1 ENGINE - COMPRESSOR 2ND STAGE DISK                   |           |          |          |                           |           |           |                     |
| PN:3023112      | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:89A798       | HRS                                                        | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                        | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15816     |                     |
|                 | ACCCYC                                                     | 0         | 20000    | TSN 0    |                           |           | 15808     |                     |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                     |
| 723030          | NO. 2 ENGINE - COMPRESSOR 2ND STAGE DISK                   |           |          |          |                           |           |           |                     |
| PN:3023112      | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:79A549       | HRS                                                        | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                        | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15816     |                     |
|                 | ACCCYC                                                     | 0         | 20000    | TSN 0    |                           |           | 15808     |                     |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                    |  |
|---------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|--------------------------------|--|
| ATA 72 - ENGINE     |                                                                                                                                    |           |          |          |                           |           |           |                                |  |
| 723040              | NO. 1 ENGINE - COMPRESSOR 3RD STAGE DISK                                                                                           |           |          |          |                           |           |           |                                |  |
| PN:3023113          | MOS                                                                                                                                | 20-Dec-94 |          | TSN 0    |                           |           |           | Component ATA:72<br>LIFE LIMIT |  |
| SN:89A805           | HRS                                                                                                                                | 0         |          | TSN 0    |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15816     |                                |  |
|                     | ACCCYC                                                                                                                             | 0         | 20000    | TSN 0    |                           |           | 15808     |                                |  |
|                     | PROC. REF: GENERIC NO REF                                                                                                          |           |          |          |                           |           |           |                                |  |
| 723040              | NO. 2 ENGINE - COMPRESSOR 3RD STAGE DISK                                                                                           |           |          |          |                           |           |           |                                |  |
| PN:3023113          | MOS                                                                                                                                | 20-Dec-94 |          | TSN 0    |                           |           |           | Component ATA:72<br>LIFE LIMIT |  |
| SN:89A490           | HRS                                                                                                                                | 0         |          | TSN 0    |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15816     |                                |  |
|                     | ACCCYC                                                                                                                             | 0         | 20000    | TSN 0    |                           |           | 15808     |                                |  |
|                     | PROC. REF: GENERIC NO REF                                                                                                          |           |          |          |                           |           |           |                                |  |
| 723050 <sup>S</sup> | NO. 1 ENGINE - INSPECT GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION AND CORROSION |           |          |          |                           |           |           |                                |  |
|                     | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           | Service ATA:72                 |  |
|                     | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                                |  |
|                     | PROC. REF: EMM 72-30-04                                                                                                            |           |          |          |                           |           |           |                                |  |
| 723050 <sup>S</sup> | NO. 2 ENGINE - INSPECT GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION AND CORROSION |           |          |          |                           |           |           |                                |  |
|                     | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           | Service ATA:72                 |  |
|                     | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                                |  |
|                     | PROC. REF: EMM 72-30-04                                                                                                            |           |          |          |                           |           |           |                                |  |
| 723055 <sup>S</sup> | NO. 1 ENGINE - INSPECT FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS                                        |           |          |          |                           |           |           |                                |  |
|                     | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           | Service ATA:72                 |  |
|                     | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                                |  |
|                     | PROC. REF: EMM 72-30-04                                                                                                            |           |          |          |                           |           |           |                                |  |
| 723055 <sup>S</sup> | NO. 2 ENGINE - INSPECT FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS                                        |           |          |          |                           |           |           |                                |  |
|                     | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           | Service ATA:72                 |  |
|                     | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                                |  |
|                     | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                                |  |
|                     | PROC. REF: EMM 72-30-04                                                                                                            |           |          |          |                           |           |           |                                |  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------|--------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE |                                                        |           |          |          |                           |           |           |                     |
| 723060          | NO. 1 ENGINE - CENTRIFUGAL IMPELLER                    |           |          |          |                           |           |           |                     |
| PN:3036793      | MOS                                                    | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:1F004        | HRS                                                    | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                    | 0         |          | TSN 0    | (24000)                   |           | 19816     |                     |
|                 |                                                        |           |          |          | 26311 (M)                 |           |           |                     |
|                 | ACCCYC                                                 | 0         | 24000    | TSN 0    |                           |           | 19808     |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |
| 723060          | NO. 2 ENGINE - CENTRIFUGAL IMPELLER                    |           |          |          |                           |           |           |                     |
| PN:3036793      | MOS                                                    | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:9E700        | HRS                                                    | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                    | 0         |          | TSN 0    | (24000)                   |           | 19816     |                     |
|                 |                                                        |           |          |          | 26311 (M)                 |           |           |                     |
|                 | ACCCYC                                                 | 0         | 24000    | TSN 0    |                           |           | 19808     |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |
| 724000          | NO. 1 ENGINE - COMBUST CHAMBER OUTER LINER ASSEMBLY    |           |          |          |                           |           |           |                     |
| PN:PN           | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:UNKNOWN      | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |
| 724000          | NO. 2 ENGINE - COMBUST CHAMBER OUTER LINER ASSEMBLY    |           |          |          |                           |           |           |                     |
| PN:PN           | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:UNKNOWN      | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |
| 724001          | NO. 1 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY |           |          |          |                           |           |           |                     |
| PN:PN           | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:UNKNOWN      | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |
| 724001          | NO. 2 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY |           |          |          |                           |           |           |                     |
| PN:PN           | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:UNKNOWN      | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF                              |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE     |                                                               |           |          |          |                           |           |           |                  |
| 725000              | NO. 1 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725000              | NO. 2 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725001              | NO. 1 ENGINE - 1ST STAGE REDUCTION, 26 TEETH SUN GEAR         |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725001              | NO. 2 ENGINE - 1ST STAGE REDUCTION, 26 TEETH SUN GEAR         |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725002              | NO. 1 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725002              | NO. 2 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                     | PROC. REF: GENERIC NO REF                                     |           |          |          |                           |           |           |                  |
| 725005 <sup>S</sup> | NO. 1 ENGINE - INSPECT EXHAUST DUCT FOR CRACKS AND DISTORTION |           |          |          |                           |           |           |                  |
|                     | MOS                                                           | 22-May-24 |          |          |                           |           |           | Service ATA:72   |
|                     | HRS                                                           | 4291.1    | 200      |          |                           |           |           |                  |
|                     | ENC                                                           | 4184      |          |          |                           |           |           |                  |
|                     | PROC. REF: EMM 72-50-05                                       |           |          |          |                           |           |           |                  |
|                     | PKG:1                                                         |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                          | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|---------------------------|---------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE           |                                                               |           |           |          |                           |           |           |                     |
| 725005 <sup>S</sup>       | NO. 2 ENGINE - INSPECT EXHAUST DUCT FOR CRACKS AND DISTORTION |           |           |          |                           |           |           |                     |
|                           | MOS                                                           | 22-May-24 |           |          |                           |           |           | Service    ATA:72   |
|                           | HRS                                                           | 4291.1    | 200       |          |                           |           |           |                     |
|                           | ENC                                                           | 4184      |           |          |                           |           |           |                     |
| PROC. REF: EMM 72-50-05   |                                                               |           |           |          |                           |           |           |                     |
| PKG:1                     |                                                               |           |           |          |                           |           |           |                     |
| 725006                    | NO. 1 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY           |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |
| 725006                    | NO. 2 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY           |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |
| 725008                    | NO. 1 ENGINE - POWER TURBINE COUPLING                         |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |
| 725008                    | NO. 2 ENGINE - POWER TURBINE COUPLING                         |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |
| 725009                    | NO. 1 ENGINE - BALL.1,181X2.8345X.743, FLANGE BEARING         |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |
| 725009                    | NO. 2 ENGINE - BALL.1,181X2.8345X.743, FLANGE BEARING         |           |           |          |                           |           |           |                     |
|                           | PN:PN                                                         | MOS/MSC   | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component    ATA:72 |
|                           | SN:UNKNOWN                                                    | HRS       | 0         |          | TSN 0                     |           |           |                     |
|                           | ENC                                                           | 0         |           |          | TSN 0                     |           |           |                     |
| PROC. REF: GENERIC NO REF |                                                               |           |           |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                        |           |          |          |                           |           |           |                  |
| 725010          | NO. 1 ENGINE - COMPRESSOR TURBINE DISK |           |          |          |                           |           |           |                  |
| PN:3049291-01   | MOS                                    | 21-Nov-11 |          | TSN 0    |                           |           |           | Component ATA:72 |
| SN:A0031EAB     | HRS                                    | 2984.9    |          | TSN 0    |                           |           |           | LIFE LIMIT       |
|                 | ENC                                    | 2985      |          | TSN 0    | (12985)<br>15296 (M)      |           | 8801      |                  |
|                 | ACCCYC                                 | 0         | 10000    | TSN 0    |                           |           | 8793      |                  |
|                 | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |
| 725010          | NO. 2 ENGINE - COMPRESSOR TURBINE DISK |           |          |          |                           |           |           |                  |
| PN:3049291-01   | MOS                                    | 21-Nov-11 |          | TSN 0    |                           |           |           | Component ATA:72 |
| SN:A0030CA4     | HRS                                    | 2984.9    |          | TSN 0    |                           |           |           | LIFE LIMIT       |
|                 | ENC                                    | 2985      |          | TSN 0    | (12985)<br>15296 (M)      |           | 8801      |                  |
|                 | ACCCYC                                 | 0         | 10000    | TSN 0    |                           |           | 8793      |                  |
|                 | PROC. REF: GENERIC NO REF              |           |          |          |                           |           |           |                  |
| 725013          | NO. 1 ENGINE - NO. 1 TURBINE VANE-RING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                |           |          |          |                           |           |           |                  |
| 725013          | NO. 2 ENGINE - NO. 1 TURBINE VANE-RING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                |           |          |          |                           |           |           |                  |
| 725014          | NO. 1 ENGINE - NO. 2 TURBINE VANE-RING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                |           |          |          |                           |           |           |                  |
| 725014          | NO. 2 ENGINE - NO. 2 TURBINE VANE-RING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                                |           |          |          |                           |           |           |                  |
| 725015          | NO. 1 ENGINE - TURBINE VANE-RING                               |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                                        |           |          |          |                           |           |           |                  |
| 725015          | NO. 2 ENGINE - TURBINE VANE-RING                               |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: EMM 72-50-01                                        |           |          |          |                           |           |           |                  |
| 725017          | NO. 1 ENGINE - NO. 1 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 725017          | NO. 2 ENGINE - NO. 1 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 725018          | NO. 1 ENGINE - NO. 2 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |
| 725018          | NO. 2 ENGINE - NO. 2 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                      |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|-----------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE |                                                                         |           |          |          |                           |           |           |                     |
| 725030          | NO. 1 ENGINE - POWER TURBINE 1ST STAGE DISK                             |           |          |          |                           |           |           |                     |
| PN:3029312      | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:86A803       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                     |
| 725030          | NO. 2 ENGINE - POWER TURBINE 1ST STAGE DISK                             |           |          |          |                           |           |           |                     |
| PN:3029312      | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:86A102       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                     |
| 725040          | NO. 1 ENGINE - POWER TURBINE 2ND STAGE DISK                             |           |          |          |                           |           |           |                     |
| PN:3029313      | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:86A926       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                     |
| 725040          | NO. 2 ENGINE - POWER TURBINE 2ND STAGE DISK                             |           |          |          |                           |           |           |                     |
| PN:3029313      | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | Component    ATA:72 |
| SN:86A126       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           | LIFE LIMIT          |
|                 | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25816     |                     |
|                 | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           | 25808     |                     |
|                 | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                     |
| 726015          | NO. 1 ENGINE - INSPECT/REPLACE 1ST STAGE REDUCTION PLANET GEAR BEARINGS |           |          |          |                           |           |           |                     |
|                 | MOS                                                                     | 21-Nov-11 |          |          |                           |           |           | Service    ATA:72   |
|                 | HRS                                                                     | 2995      | 3600     |          | (6595)<br>7990.1          |           | 2303.9    |                     |
|                 | ENC                                                                     | 2995      |          |          |                           |           |           |                     |
|                 | PROC. REF: GENERIC NO REF                                               |           |          |          |                           |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                                        | C/W  | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------------|------|-----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                             |      |           |          |                           |           |           |                  |
| 726015                    | NO. 2 ENGINE - INSPECT/REPLACE 1ST STAGE REDUCTION PLANET GEAR BEARINGS     |      |           |          |                           |           |           |                  |
|                           | MOS                                                                         |      | 21-Nov-11 |          |                           |           |           | Service ATA:72   |
|                           | HRS                                                                         | 2995 | 3600      |          | (6595)<br>7990.1          |           | 2303.9    |                  |
|                           | ENC                                                                         | 2995 |           |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |      |           |          |                           |           |           |                  |
| 726040                    | NO. 1 ENGINE - DO A VISUAL INSPECTION OF STARTER GENERATOR SPLINES FOR WEAR |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | A/R      |                           |           |           | Service ATA:72   |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          |                           |           |           |                  |
|                           | ENC                                                                         | 0    |           |          |                           |           |           |                  |
| 726040                    | NO. 2 ENGINE - DO A VISUAL INSPECTION OF STARTER GENERATOR SPLINES FOR WEAR |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | A/R      |                           |           |           | Service ATA:72   |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          |                           |           |           |                  |
|                           | ENC                                                                         | 0    |           |          |                           |           |           |                  |
| 726051                    | NO. 1 ENGINE - NO. 1 ROLLER FLANGE 9451X1.665X4699 BEARING                  |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component ATA:72 |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
|                           | ENC                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |      |           |          |                           |           |           |                  |
| 726051                    | NO. 1 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT                            |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component ATA:72 |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
|                           | ENC                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |      |           |          |                           |           |           |                  |
| 726051                    | NO. 2 ENGINE - NO. 1 ROLLER FLANGE 9451X1.665X4699 BEARING                  |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component ATA:72 |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
|                           | ENC                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |      |           |          |                           |           |           |                  |
| 726051                    | NO. 2 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT                            |      |           |          |                           |           |           |                  |
| PN:PN                     | MOS/MSC                                                                     |      | 20-Dec-94 | O/C      | TSN 0                     |           |           | Component ATA:72 |
| SN:UNKNOWN                | HRS                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
|                           | ENC                                                                         | 0    |           |          | TSN 0                     |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |      |           |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                            |           |          |          |                           |           |           |                  |
| 726052          | NO. 1 ENGINE - NO. 2 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726052          | NO. 2 ENGINE - NO. 2 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726053          | NO. 1 ENGINE - NO. 3 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726053          | NO. 2 ENGINE - NO. 3 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726054          | NO. 1 ENGINE - NO. 4 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726054          | NO. 2 ENGINE - NO. 4 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726055          | NO. 1 ENGINE - NO. 5 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                            |           |          |          |                           |           |           |                  |
| 726055          | NO. 2 ENGINE - NO. 5 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726056          | NO. 1 ENGINE - NO. 6 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726056          | NO. 2 ENGINE - NO. 6 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726057          | NO. 1 ENGINE - NO. 7 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726057          | NO. 2 ENGINE - NO. 7 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726058          | NO. 1 ENGINE - NO. 8 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |
| 726058          | NO. 2 ENGINE - NO. 8 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                  |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|-------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE |                                                             |           |          |          |                           |           |           |                  |
| 726059          | NO. 1 ENGINE - NO. 9 ROLLER FLANGE 9451X1.665X4699 BEARING  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726059          | NO. 2 ENGINE - NO. 9 ROLLER FLANGE 9451X1.665X4699 BEARING  |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726060          | NO. 1 ENGINE - NO. 10 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726060          | NO. 2 ENGINE - NO. 10 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726061          | NO. 1 ENGINE - NO. 11 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726061          | NO. 2 ENGINE - NO. 11 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |
| 726062          | NO. 1 ENGINE - NO. 12 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           |                  |
| PN:PN           | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           | Component ATA:72 |
| SN:UNKNOWN      | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                   |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                                                    | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|-----------------------------------------------------------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE     |                                                                                         |           |          |                           |                           |           |           |                  |
| 726062              | NO. 2 ENGINE - NO. 12 ROLLER FLANGE 945IX1.665X4699 BEARING                             |           |          |                           |                           |           |           |                  |
| PN:PN               | MOS/MSC                                                                                 | 20-Dec-94 | O/C      | TSN 0                     |                           |           |           | Component ATA:72 |
| SN:UNKNOWN          | HRS                                                                                     | 0         |          | TSN 0                     |                           |           |           |                  |
|                     | ENC                                                                                     | 0         |          | TSN 0                     |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 728005 <sup>S</sup> | NO. 1 ENGINE - INSPECT ACCESSORIES FOR ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 728005 <sup>S</sup> | NO. 2 ENGINE - INSPECT ACCESSORIES FOR ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 728015 <sup>S</sup> | NO. 1 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE                 |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 728015 <sup>S</sup> | NO. 2 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE                 |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 731200 <sup>S</sup> | NO. 1 ENGINE - CHECK FUEL PUMP OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION           |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 731200 <sup>S</sup> | NO. 2 ENGINE - CHECK FUEL PUMP OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION           |           |          |                           |                           |           |           |                  |
|                     | MOS                                                                                     | 22-May-24 |          |                           |                           |           |           | Service ATA:72   |
|                     | HRS                                                                                     | 4291.1    | 200      |                           |                           |           |           |                  |
|                     | ENC                                                                                     | 4184      |          |                           |                           |           |           |                  |
|                     |                                                                                         |           |          | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|----------------------------------|-----------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 72 - ENGINE                  |                                                                                                     |           |          |          |                           |           |           |                     |
| 731205 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |          |          |                           |           |           |                     |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           | Service    ATA:72   |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                     |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: EMM 73-10-06   |           |           | PKG:1               |
| 731205 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |          |          |                           |           |           |                     |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           | Service    ATA:72   |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                     |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: EMM 73-10-06   |           |           | PKG:1               |
| 733115 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE   |           |          |          |                           |           |           |                     |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           | Service    ATA:72   |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                     |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: GENERIC NO REF |           |           | PKG:1               |
| 733115 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE   |           |          |          |                           |           |           |                     |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           | Service    ATA:72   |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                     |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: GENERIC NO REF |           |           | PKG:1               |
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                     |           |          |          |                           |           |           |                     |
| 730700                           | LEFT ENGINE FUEL COLLECTOR PUMP                                                                     |           |          |          |                           |           |           |                     |
|                                  | MOS/MSC                                                                                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:73 |
|                                  | PN:476284                                                                                           |           |          |          |                           |           |           |                     |
|                                  | HRS                                                                                                 | 0         |          |          | TSN 0                     |           |           |                     |
|                                  | SN:UNKNOWN                                                                                          |           |          |          |                           |           |           |                     |
|                                  | WC#: 73.070                                                                                         | 0         |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: GENERIC NO REF |           |           |                     |
| 730706                           | RIGHT ENGINE FUEL COLLECTOR PUMP                                                                    |           |          |          |                           |           |           |                     |
|                                  | MOS/MSC                                                                                             | 29-Dec-98 | O/C      |          |                           |           |           | Component    ATA:73 |
|                                  | PN:476284                                                                                           |           |          |          |                           |           |           |                     |
|                                  | HRS                                                                                                 | 0         |          |          | TSN 0                     |           |           |                     |
|                                  | SN:UNKNOWN                                                                                          |           |          |          |                           |           |           |                     |
|                                  | WC#: 73.070                                                                                         | 0         |          |          |                           |           |           |                     |
|                                  |                                                                                                     |           |          |          | PROC. REF: GENERIC NO REF |           |           |                     |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition        |
|----------------------------------|------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|--------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                            |           |             |          |                           |           |               |                    |
| 731001                           | NO. 1 ENGINE - FUEL FLOW DIVIDER                           |           |             |          |                           |           |               |                    |
| PN:PN                            | MOS/MSC                                                    | 20-Dec-94 | O/C         | TSN 0    |                           |           |               | Component ATA:73   |
| SN:UNKNOWN                       | HRS                                                        | 0         |             | TSN 0    |                           |           |               |                    |
|                                  | ENC                                                        | 0         |             | TSN 0    |                           |           |               |                    |
|                                  | PROC. REF: GENERIC NO REF                                  |           |             |          |                           |           |               |                    |
| 731001                           | NO. 2 ENGINE - FUEL FLOW DIVIDER                           |           |             |          |                           |           |               |                    |
| PN:PN                            | MOS/MSC                                                    | 20-Dec-94 | O/C         | TSN 0    |                           |           |               | Component ATA:73   |
| SN:UNKNOWN                       | HRS                                                        | 0         |             | TSN 0    |                           |           |               |                    |
|                                  | ENC                                                        | 0         |             | TSN 0    |                           |           |               |                    |
|                                  | PROC. REF: GENERIC NO REF                                  |           |             |          |                           |           |               |                    |
| 731004                           | NO. 1 ENGINE - STARTING CONTROL INSTALLATION/ FLOW DIVIDER |           |             |          |                           |           |               |                    |
| PN:3036640                       | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | Component OVERHAUL |
| SN:2019                          | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                    |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                    |
|                                  | PROC. REF: EMM 73-10-04                                    |           |             |          |                           |           |               |                    |
| 731004                           | NO. 2 ENGINE - STARTING CONTROL INSTALLATION/ FLOW DIVIDER |           |             |          |                           |           |               |                    |
| PN:3036640                       | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | Component OVERHAUL |
| SN:1997                          | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                    |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                    |
|                                  | PROC. REF: EMM 73-10-04                                    |           |             |          |                           |           |               |                    |
| 731010                           | NO. 1 ENGINE - ENGINE DRIVEN FUEL PUMP                     |           |             |          |                           |           |               |                    |
| PN:025323-300-03                 | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | Component ATA:73   |
| SN:10239                         | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                    |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                    |
|                                  | PROC. REF: EMM 73-10-02                                    |           |             |          |                           |           |               |                    |
| 731010                           | NO. 2 ENGINE - ENGINE DRIVEN FUEL PUMP                     |           |             |          |                           |           |               |                    |
| PN:025323-300-03                 | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | Component OVERHAUL |
| SN:10217                         | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                    |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                    |
|                                  | PROC. REF: EMM 73-10-02                                    |           |             |          |                           |           |               |                    |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                       | C/W                     | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|----------------------------------|----------------------------------------------------------------------------|-------------------------|------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                            |                         |            |          |                           |           |             |                |
| 731020                           | NO. 1 ENGINE - CLEAN FUEL NOZZLES                                          |                         |            |          |                           |           |             |                |
|                                  | MOS                                                                        | 26-Sep-22               |            |          |                           |           |             |                |
|                                  | HRS                                                                        | 3963.4                  | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | 72.3 (+40)  | Service ATA:73 |
| ENC                              | 3963                                                                       | PROC. REF: EMM 73-10-05 |            |          |                           |           |             |                |
|                                  |                                                                            |                         |            |          |                           |           |             |                |
| 731020                           | NO. 2 ENGINE - CLEAN FUEL NOZZLES                                          |                         |            |          |                           |           |             |                |
|                                  | MOS                                                                        | 26-Sep-22               |            |          |                           |           |             |                |
|                                  | HRS                                                                        | 3963.4                  | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | 72.3 (+40)  | Service ATA:73 |
| ENC                              | 3963                                                                       | PROC. REF: EMM 73-10-05 |            |          |                           |           |             |                |
|                                  |                                                                            |                         |            |          |                           |           |             |                |
| 731025                           | NO. 1 ENGINE - LEAK/FUNCTIONAL TEST MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES |                         |            |          |                           |           |             |                |
|                                  | MOS                                                                        | 12-Apr-23               |            |          |                           |           |             |                |
|                                  | HRS                                                                        | 4105.2                  | 400 (+10%) |          | (4505.2)<br>5900.3        | 4545.2    | 214.1 (+40) | Service ATA:73 |
| ENC                              | 4047                                                                       | PROC. REF: EMM 73-10-05 |            |          |                           |           |             |                |
|                                  |                                                                            |                         |            |          |                           |           |             |                |
| 731025                           | NO. 2 ENGINE - LEAK/FUNCTIONAL TEST MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES |                         |            |          |                           |           |             |                |
|                                  | MOS                                                                        | 12-Apr-23               |            |          |                           |           |             |                |
|                                  | HRS                                                                        | 4105.2                  | 400 (+10%) |          | (4505.2)<br>5900.3        | 4545.2    | 214.1 (+40) | Service ATA:73 |
| ENC                              | 4047                                                                       | PROC. REF: EMM 73-10-05 |            |          |                           |           |             |                |
|                                  |                                                                            |                         |            |          |                           |           |             |                |
| 731030                           | NO. 1 ENGINE - INSPECT/REPLACE ENGINE DRIVEN FUEL PUMP OUTLET FILTER       |                         |            |          |                           |           |             |                |
|                                  | MOS                                                                        | 22-May-24               |            |          |                           |           |             |                |
|                                  | SN:10239                                                                   | 4291.1                  | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60)   | Service ATA:73 |
| ENC                              | 4184                                                                       | PROC. REF: EMM 73-10-02 |            |          |                           |           |             |                |
|                                  |                                                                            |                         |            |          |                           |           |             |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                                                                                               | Unit | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-------------------------------------------------------------------------------------------------------|------|-----------|------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                                                      |      |           |            |          |                           |           |           |                |
| NO. 2 ENGINE - INSPECT/REPLACE ENGINE DRIVEN FUEL PUMP OUTLET FILTER                                  |      |           |            |          |                           |           |           |                |
| 731030                                                                                                | MOS  | 22-May-24 |            |          |                           |           |           | Service ATA:73 |
| PN:025323-300-03                                                                                      |      |           |            |          |                           |           |           |                |
| SN:10217                                                                                              | HRS  | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60) |                |
|                                                                                                       | ENC  | 4184      |            |          |                           |           |           |                |
| PROC. REF: EMM 73-10-02                                                                               |      |           |            |          |                           |           |           |                |
| NO. 1 ENGINE - CHECK/CLEAN/REPLACE ENGINE DRIVEN FUEL PUMP INLET SCREEN                               |      |           |            |          |                           |           |           |                |
| 731040                                                                                                | MOS  | 22-May-24 |            |          |                           |           |           | Service ATA:73 |
| PN:025323-300-03                                                                                      |      |           |            |          |                           |           |           |                |
| SN:10239                                                                                              | HRS  | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60) |                |
|                                                                                                       | ENC  | 4184      |            |          |                           |           |           |                |
| PROC. REF: EMM 73-10-02, EMM 73-10-02                                                                 |      |           |            |          |                           |           |           |                |
| NO. 2 ENGINE - CHECK/CLEAN/REPLACE ENGINE DRIVEN FUEL PUMP INLET SCREEN                               |      |           |            |          |                           |           |           |                |
| 731040                                                                                                | MOS  | 22-May-24 |            |          |                           |           |           | Service ATA:73 |
| PN:025323-300-03                                                                                      |      |           |            |          |                           |           |           |                |
| SN:10217                                                                                              | HRS  | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60) |                |
|                                                                                                       | ENC  | 4184      |            |          |                           |           |           |                |
| PROC. REF: EMM 73-10-02, EMM 73-10-02                                                                 |      |           |            |          |                           |           |           |                |
| NO. 1 ENGINE - CHECK ENGINE DRIVEN FUEL PUMP THE FUEL PUMP COUPLING IN-SITU FOR FRETING AND CORROSION |      |           |            |          |                           |           |           |                |
| 731050                                                                                                | MOS  | 22-May-24 |            |          |                           |           |           | Service ATA:73 |
| PN:025323-300-03                                                                                      |      |           |            |          |                           |           |           |                |
| SN:10239                                                                                              | HRS  | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60) |                |
|                                                                                                       | ENC  | 4184      |            |          |                           |           |           |                |
| PROC. REF: EMM 73-10-02                                                                               |      |           |            |          |                           |           |           |                |
| NO. 2 ENGINE - CHECK ENGINE DRIVEN FUEL PUMP THE FUEL PUMP COUPLING IN-SITU FOR FRETING AND CORROSION |      |           |            |          |                           |           |           |                |
| 731050                                                                                                | MOS  | 22-May-24 |            |          |                           |           |           | Service ATA:73 |
| PN:025323-300-03                                                                                      |      |           |            |          |                           |           |           |                |
| SN:10217                                                                                              | HRS  | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60) |                |
|                                                                                                       | ENC  | 4184      |            |          |                           |           |           |                |
| PROC. REF: EMM 73-10-02                                                                               |      |           |            |          |                           |           |           |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                                           | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                  |  |
|----------------------------------|------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------------------|--|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                |           |             |          |                           |           |               |                              |  |
| 731055                           | NO. 1 ENGINE - REMOVE/INSPECT ENGINE DRIVEN FUEL PUMP FUEL PUMP DRIVE COUPLING AND COVER       |           |             |          |                           |           |               |                              |  |
| PN:025323-300-03                 | MOS                                                                                            | 21-Nov-11 |             |          |                           |           |               | Service ATA:73               |  |
| SN:10239                         | HRS                                                                                            | 2995      | 1800 (+100) |          | (4795)<br>6190.1          | 4895      | 503.9 (+100)  |                              |  |
|                                  | ENC                                                                                            | 2995      |             |          |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-02                                                                        |           |             |          |                           |           |               |                              |  |
| 731055                           | NO. 2 ENGINE - REMOVE/INSPECT ENGINE DRIVEN FUEL PUMP FUEL PUMP DRIVE COUPLING AND COVER       |           |             |          |                           |           |               |                              |  |
| PN:025323-300-03                 | MOS                                                                                            | 21-Nov-11 |             |          |                           |           |               | Service ATA:73               |  |
| SN:10217                         | HRS                                                                                            | 2995      | 1800 (+100) |          | (4795)<br>6190.1          | 4895      | 503.9 (+100)  |                              |  |
|                                  | ENC                                                                                            | 2995      |             |          |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-02                                                                        |           |             |          |                           |           |               |                              |  |
| 731060                           | NO. 1 ENGINE - OIL TO FUEL HEATER                                                              |           |             |          |                           |           |               |                              |  |
| PN:10585K                        | MOS                                                                                            | 21-Nov-11 |             | TSO 0    |                           |           |               | Component ATA:73<br>OVERHAUL |  |
| SN:WA4376                        | HRS                                                                                            | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |  |
|                                  | ENC                                                                                            | 2995      |             | TSO 0    |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-01                                                                        |           |             |          |                           |           |               |                              |  |
| 731060                           | NO. 2 ENGINE - OIL TO FUEL HEATER                                                              |           |             |          |                           |           |               |                              |  |
| PN:10585K                        | MOS                                                                                            | 21-Nov-11 |             | TSO 0    |                           |           |               | Component ATA:73<br>OVERHAUL |  |
| SN:WA3822                        | HRS                                                                                            | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |  |
|                                  | ENC                                                                                            | 2995      |             | TSO 0    |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-01                                                                        |           |             |          |                           |           |               |                              |  |
| 731065 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION |           |             |          |                           |           |               |                              |  |
|                                  | MOS                                                                                            | 22-May-24 |             |          |                           |           |               | PKG:1                        |  |
|                                  | HRS                                                                                            | 4291.1    | 200 (+10%)  |          |                           |           |               |                              |  |
|                                  | ENC                                                                                            | 4184      |             |          |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-01                                                                        |           |             |          |                           |           |               |                              |  |
| 731065 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION |           |             |          |                           |           |               |                              |  |
|                                  | MOS                                                                                            | 22-May-24 |             |          |                           |           |               | Service ATA:73               |  |
|                                  | HRS                                                                                            | 4291.1    | 200 (+10%)  |          |                           |           |               |                              |  |
|                                  | ENC                                                                                            | 4184      |             |          |                           |           |               |                              |  |
|                                  | PROC. REF: EMM 73-10-01                                                                        |           |             |          |                           |           |               |                              |  |
|                                  | PKG:1                                                                                          |           |             |          |                           |           |               |                              |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                    |           |          |          |                           |           |           |                  |
| 731066                           | NO. 1 ENGINE - DO A FUNCTIONAL CHECK OF THE OIL-TO-FUEL HEATER     |           |          |          |                           |           |           |                  |
| PN:10585K                        | MOS/MSC                                                            | 21-Nov-11 | N/A      |          |                           |           |           | Service ATA:73   |
| SN:WA4376                        | HRS                                                                | 2995      |          |          |                           |           |           |                  |
|                                  | ENC                                                                | 2995      |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: EMM 73-10-01   |           |           |                  |
| 731066                           | NO. 2 ENGINE - DO A FUNCTIONAL CHECK OF THE OIL-TO-FUEL HEATER     |           |          |          |                           |           |           |                  |
| PN:10585K                        | MOS/MSC                                                            | 21-Nov-11 | N/A      |          |                           |           |           | Service ATA:73   |
| SN:WA3822                        | HRS                                                                | 2995      |          |          |                           |           |           |                  |
|                                  | ENC                                                                | 2995      |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: EMM 73-10-01   |           |           |                  |
| 731075 <sup>S</sup>              | NO. 1 ENGINE - INSPECT ACCESSORIES FOR SECURITY OF PNEUMATIC LINES |           |          |          |                           |           |           |                  |
|                                  | MOS                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                | 4184      |          |          |                           |           |           | PKG:1            |
|                                  |                                                                    |           |          |          | PROC. REF: GENERIC NO REF |           |           |                  |
| 731075 <sup>S</sup>              | NO. 2 ENGINE - INSPECT ACCESSORIES FOR SECURITY OF PNEUMATIC LINES |           |          |          |                           |           |           |                  |
|                                  | MOS                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                | 4291.1    | 200      |          |                           |           |           | Service ATA:73   |
|                                  | ENC                                                                | 4184      |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: GENERIC NO REF |           |           | PKG:1            |
| 731080                           | NO. 1 ENGINE - FUEL BOOST PUMP                                     |           |          |          |                           |           |           |                  |
| PN:91-380003-3                   | MOS/MSC                                                            | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:73 |
| SN:B-8355                        | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | ENC                                                                |           |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: EMM 73-10-02   |           |           |                  |
| 731080                           | NO. 2 ENGINE - FUEL BOOST PUMP                                     |           |          |          |                           |           |           |                  |
| PN:91-380003-3                   | MOS/MSC                                                            | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:73 |
| SN:B-8302                        | HRS                                                                | 0         |          | TSN 0    |                           |           |           | OVERHAUL         |
|                                  | ENC                                                                |           |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: EMM 73-10-02   |           |           |                  |
| 731085 <sup>S</sup>              | NO. 1 ENGINE - CHECK P3 FILTER FOR INSTALLATION                    |           |          |          |                           |           |           |                  |
|                                  | MOS                                                                | 22-May-24 |          |          |                           |           |           | Service ATA:73   |
|                                  | HRS                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                | 4184      |          |          |                           |           |           |                  |
|                                  |                                                                    |           |          |          | PROC. REF: EMM 73-10-07   |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                                                                       | Unit | C/W       | Interval    | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                  |
|-------------------------------------------------------------------------------|------|-----------|-------------|-------------------------|---------------------------|-----------|---------------|------------------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                              |      |           |             |                         |                           |           |               |                              |
| 731085 <sup>S</sup> NO. 2 ENGINE - CHECK P3 FILTER FOR INSTALLATION           |      |           |             |                         |                           |           |               |                              |
|                                                                               | MOS  | 22-May-24 |             |                         |                           |           |               | Service ATA:73               |
|                                                                               | HRS  | 4291.1    | 200         |                         |                           |           |               |                              |
|                                                                               | ENC  | 4184      |             |                         |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-10-07 |                           |           |               | PKG:1                        |
| 731090 NO. 1 ENGINE - FUEL CONTROL UNIT                                       |      |           |             |                         |                           |           |               |                              |
| PN:3244768-13                                                                 | MOS  | 21-Nov-11 | TSO 0       |                         |                           |           |               | Component ATA:73<br>OVERHAUL |
| SN:C20044                                                                     | HRS  | 2995      | 3600 (+500) | TSO 0                   | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |
|                                                                               | ENC  | 2995      |             | TSO 0                   |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-20-00 |                           |           |               |                              |
| 731090 NO. 2 ENGINE - FUEL CONTROL UNIT                                       |      |           |             |                         |                           |           |               |                              |
| PN:3244768-13                                                                 | MOS  | 21-Nov-11 | TSO 0       |                         |                           |           |               | Component ATA:73<br>OVERHAUL |
| SN:C20043                                                                     | HRS  | 2995      | 3600 (+500) | TSO 0                   | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |
|                                                                               | ENC  | 2995      |             | TSO 0                   |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-20-00 |                           |           |               |                              |
| 731095 NO. 1 ENGINE - FCU DRIVEBODY INSPECTION/DRIVESHAFT BEARING REPLACEMENT |      |           |             |                         |                           |           |               |                              |
|                                                                               | MOS  | 22-May-24 | 144         |                         | 22-May-36                 |           | 4329 d        | Service ATA:73               |
|                                                                               | HRS  | 4291.1    |             |                         |                           |           |               |                              |
|                                                                               | ENC  | 4184      |             |                         |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-20-00 |                           |           |               |                              |
| 731095 NO. 2 ENGINE - FCU DRIVEBODY INSPECTION/DRIVESHAFT BEARING REPLACEMENT |      |           |             |                         |                           |           |               |                              |
|                                                                               | MOS  | 22-May-24 | 144         |                         | 22-May-36                 |           | 4329 d        | Service ATA:73               |
|                                                                               | HRS  | 4291.1    |             |                         |                           |           |               |                              |
|                                                                               | ENC  | 4184      |             |                         |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-20-00 |                           |           |               |                              |
| 731110 NO. 1 ENGINE - TORQUE LIMITER                                          |      |           |             |                         |                           |           |               |                              |
| PN:3244707-7                                                                  | MOS  | 21-Nov-11 | TSO 0       |                         |                           |           |               | Component ATA:73<br>OVERHAUL |
| SN:C12058                                                                     | HRS  | 2995      | 3600 (+500) | TSO 0                   | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |
|                                                                               | ENC  | 2995      |             | TSO 0                   |                           |           |               |                              |
|                                                                               |      |           |             | PROC. REF: EMM 73-10-09 |                           |           |               |                              |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                                                            | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                  |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|---------------|------------------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                                 |           |                           |          |                           |           |               |                              |
| 731110                           | NO. 2 ENGINE - TORQUE LIMITER                                                                                   |           |                           |          |                           |           |               |                              |
| PN:3244707-7                     | MOS                                                                                                             | 21-Nov-11 |                           | TSO 0    |                           |           |               | Component ATA:73<br>OVERHAUL |
| SN:C12053                        | HRS                                                                                                             | 2995      | 3600 (+500)               | TSO 0    | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                              |
|                                  | ENC                                                                                                             | 2995      |                           | TSO 0    |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: EMM 73-10-09   |          |                           |           |               |                              |
| 731215 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER/DUMP VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |                           |          |                           |           |               |                              |
|                                  | MOS                                                                                                             | 22-May-24 |                           |          |                           |           |               | Service ATA:73               |
|                                  | HRS                                                                                                             | 4291.1    | 200                       |          |                           |           |               |                              |
|                                  | ENC                                                                                                             | 4184      |                           |          |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: EMM 73-10-04   |          |                           |           |               |                              |
|                                  | PKG:1                                                                                                           |           |                           |          |                           |           |               |                              |
| 731215 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE FLOW DIVIDER/DUMP VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |                           |          |                           |           |               |                              |
|                                  | MOS                                                                                                             | 22-May-24 |                           |          |                           |           |               | Service ATA:73               |
|                                  | HRS                                                                                                             | 4291.1    | 200                       |          |                           |           |               |                              |
|                                  | ENC                                                                                                             | 4184      |                           |          |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: EMM 73-10-04   |          |                           |           |               |                              |
|                                  | PKG:1                                                                                                           |           |                           |          |                           |           |               |                              |
| 732000 <sup>S</sup>              | NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES                                         |           |                           |          |                           |           |               |                              |
|                                  | MOS                                                                                                             | 22-May-24 |                           |          |                           |           |               | Service ATA:73               |
|                                  | HRS                                                                                                             | 4291.1    | 200                       |          |                           |           |               |                              |
|                                  | ENC                                                                                                             | 4184      |                           |          |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: GENERIC NO REF |          |                           |           |               |                              |
|                                  | PKG:1                                                                                                           |           |                           |          |                           |           |               |                              |
| 732000 <sup>S</sup>              | NO. 2 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES                                         |           |                           |          |                           |           |               |                              |
|                                  | MOS                                                                                                             | 22-May-24 |                           |          |                           |           |               | Service ATA:73               |
|                                  | HRS                                                                                                             | 4291.1    | 200                       |          |                           |           |               |                              |
|                                  | ENC                                                                                                             | 4184      |                           |          |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: GENERIC NO REF |          |                           |           |               |                              |
|                                  | PKG:1                                                                                                           |           |                           |          |                           |           |               |                              |
| 732010                           | NO. 1 ENGINE - FUEL FLOW TRANSMITTER                                                                            |           |                           |          |                           |           |               |                              |
| PN:1/2-2-81-306                  | MOS/MSC                                                                                                         | 11-Jul-95 | O/C                       | TSN 0    |                           |           |               | Component ATA:73             |
| SN:211451                        | HRS                                                                                                             | 109       |                           | TSN 0    |                           |           |               |                              |
|                                  | ENC                                                                                                             |           |                           |          |                           |           |               |                              |
|                                  |                                                                                                                 |           | PROC. REF: GENERIC NO REF |          |                           |           |               |                              |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                                                              | C/W       | Interval    | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------|-------------------------------------------------------------------------------------------------------------------|-----------|-------------|---------------------------------------|---------------------------|-----------|--------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                                   |           |             |                                       |                           |           |              |                  |
| 732010                           | NO. 2 ENGINE - FUEL FLOW TRANSMITTER                                                                              |           |             |                                       |                           |           |              |                  |
| PN:1/2-2-81-306                  | MOS/MSC                                                                                                           | 20-Dec-94 | O/C         |                                       |                           |           |              | Component ATA:73 |
| SN:210242                        | HRS                                                                                                               | 0         |             | TSN 0                                 |                           |           |              |                  |
|                                  | ENC                                                                                                               |           |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: GENERIC NO REF             |                           |           |              |                  |
| 733010                           | NO. 1 ENGINE - CLEAN P3 FILTER                                                                                    |           |             |                                       |                           |           |              |                  |
|                                  | MOS                                                                                                               | 22-May-24 |             |                                       |                           |           |              | Service ATA:73   |
|                                  | HRS                                                                                                               | 4291.1    | 200 (+10%)  |                                       | (4491.1)<br>5886.2        | 4511.1    | 200 (+20)    |                  |
|                                  | ENC                                                                                                               | 4184      |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: EMM 73-10-07               |                           |           |              |                  |
| 733010                           | NO. 2 ENGINE - CLEAN P3 FILTER                                                                                    |           |             |                                       |                           |           |              |                  |
|                                  | MOS                                                                                                               | 22-May-24 |             |                                       |                           |           |              | Service ATA:73   |
|                                  | HRS                                                                                                               | 4291.1    | 200 (+10%)  |                                       | (4491.1)<br>5886.2        | 4511.1    | 200 (+20)    |                  |
|                                  | ENC                                                                                                               | 4184      |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: EMM 73-10-07               |                           |           |              |                  |
| 733020                           | NO. 1 ENGINE - CLEAN/REPLACE P3 AIR FILTER                                                                        |           |             |                                       |                           |           |              |                  |
|                                  | MOS                                                                                                               | 12-Apr-23 |             |                                       |                           |           |              | Service ATA:73   |
|                                  | HRS                                                                                                               | 4105.2    | 1000 (+100) |                                       | (5105.2)<br>6500.3        | 5205.2    | 814.1 (+100) |                  |
|                                  | ENC                                                                                                               | 4047      |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: EMM 73-10-07, EMM 73-10-07 |                           |           |              |                  |
| 733020                           | NO. 2 ENGINE - CLEAN/REPLACE P3 AIR FILTER                                                                        |           |             |                                       |                           |           |              |                  |
|                                  | MOS                                                                                                               | 12-Apr-23 |             |                                       |                           |           |              | Service ATA:73   |
|                                  | HRS                                                                                                               | 4105.2    | 1000 (+100) |                                       | (5105.2)<br>6500.3        | 5205.2    | 814.1 (+100) |                  |
|                                  | ENC                                                                                                               | 4047      |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: EMM 73-10-07, EMM 73-10-07 |                           |           |              |                  |
| 733035 <sup>S</sup>              | NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS |           |             |                                       |                           |           |              |                  |
|                                  | MOS                                                                                                               | 22-May-24 |             |                                       |                           |           |              | Service ATA:73   |
|                                  | HRS                                                                                                               | 4291.1    | 200         |                                       |                           |           |              |                  |
|                                  | ENC                                                                                                               | 4184      |             |                                       |                           |           |              |                  |
|                                  |                                                                                                                   |           |             | PROC. REF: GENERIC NO REF             |                           |           |              |                  |
|                                  |                                                                                                                   |           |             |                                       |                           |           |              | PKG:1            |



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN                          | Unit                                                                                                              | C/W       | Interval   | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                     |
|----------------------------------|-------------------------------------------------------------------------------------------------------------------|-----------|------------|-------------|---------------------------|-----------|---------------|---------------------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                                   |           |            |             |                           |           |               |                                 |
| 733035 <sup>S</sup>              | NO. 2 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS |           |            |             |                           |           |               |                                 |
|                                  | MOS                                                                                                               | 22-May-24 |            |             |                           |           |               | Service    ATA:73               |
|                                  | HRS                                                                                                               | 4291.1    | 200        |             |                           |           |               |                                 |
|                                  | ENC                                                                                                               | 4184      |            |             |                           |           |               |                                 |
| PROC. REF: GENERIC NO REF        |                                                                                                                   |           |            |             |                           |           |               |                                 |
| PKG:1                            |                                                                                                                   |           |            |             |                           |           |               |                                 |
| ATA 74 - IGNITION                |                                                                                                                   |           |            |             |                           |           |               |                                 |
| 740010                           | NO. 1 ENGINE - IGNITION EXCITER                                                                                   |           |            |             |                           |           |               |                                 |
|                                  | PN:10-381550-4                                                                                                    | MOS       | 21-Nov-11  | TSO 0       |                           |           |               | Component    ATA:74<br>OVERHAUL |
|                                  | SN:NN99379227                                                                                                     | HRS       | 2995       | 3600 (+500) | TSO 0                     | 7095      | 2303.9 (+500) |                                 |
|                                  |                                                                                                                   | ENC       | 2995       | TSO 0       | (6595)<br>7990.1          |           |               |                                 |
| PROC. REF: EMM 74-10-00          |                                                                                                                   |           |            |             |                           |           |               |                                 |
| 740010                           | NO. 2 ENGINE - IGNITION EXCITER                                                                                   |           |            |             |                           |           |               |                                 |
|                                  | PN:10-381550-4                                                                                                    | MOS       | 21-Nov-11  | TSO 0       |                           |           |               | Component    ATA:74<br>OVERHAUL |
|                                  | SN:NNA05496744                                                                                                    | HRS       | 2995       | 3600 (+500) | TSO 0                     | 7095      | 2303.9 (+500) |                                 |
|                                  |                                                                                                                   | ENC       | 2995       | TSO 0       | (6595)<br>7990.1          |           |               |                                 |
| PROC. REF: EMM 74-10-00          |                                                                                                                   |           |            |             |                           |           |               |                                 |
| 740015                           | NO. 1 ENGINE - EXAMINE THE SPARK IGNITERS FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK                      |           |            |             |                           |           |               |                                 |
|                                  | MOS                                                                                                               | 22-May-24 |            |             |                           |           |               | Service    ATA:74               |
|                                  | HRS                                                                                                               | 4291.1    | 400 (+10%) |             | (4691.1)<br>6086.2        | 4731.1    | 400 (+40)     |                                 |
|                                  | ENC                                                                                                               | 4184      |            |             |                           |           |               |                                 |
| PROC. REF: EMM 74-20-00          |                                                                                                                   |           |            |             |                           |           |               |                                 |
| 740015                           | NO. 2 ENGINE - EXAMINE THE SPARK IGNITERS FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK                      |           |            |             |                           |           |               |                                 |
|                                  | MOS                                                                                                               | 22-May-24 |            |             |                           |           |               | Service    ATA:74               |
|                                  | HRS                                                                                                               | 4291.1    | 400 (+10%) |             | (4691.1)<br>6086.2        | 4731.1    | 400 (+40)     |                                 |
|                                  | ENC                                                                                                               | 4184      |            |             |                           |           |               |                                 |
| PROC. REF: EMM 74-20-00          |                                                                                                                   |           |            |             |                           |           |               |                                 |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN           | Unit                                         | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|----------------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 74 - IGNITION |                                              |           |          |                           |                           |           |           |                  |
| 740020            | NO. 1 ENGINE - 4 O'CLOCK IGNITOR             |           |          |                           |                           |           |           |                  |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0                     |                           |           |           | Component ATA:74 |
| SN:UNKNOWN        | HRS                                          | 4105.4    |          | TSN 0                     |                           |           |           |                  |
|                   | AFL                                          | 4047      |          |                           |                           |           |           |                  |
|                   | ENC                                          |           |          | TSN 0                     |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: EMM 74-20-00   |                           |           |           |                  |
| 740020            | NO. 2 ENGINE - 4 O'CLOCK IGNITOR             |           |          |                           |                           |           |           |                  |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0                     |                           |           |           | Component ATA:74 |
| SN:UNKNOWN        | HRS                                          | 4105.2    |          | TSN 0                     |                           |           |           |                  |
|                   | ENC                                          | 4047      |          | TSN 0                     |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: EMM 74-20-00   |                           |           |           |                  |
| 740040            | NO. 1 ENGINE - 9 O'CLOCK IGNITOR             |           |          |                           |                           |           |           |                  |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0                     |                           |           |           | Component ATA:74 |
| SN:UNKNOWN        | HRS                                          | 4105.4    |          | TSN 0                     |                           |           |           |                  |
|                   | AFL                                          | 4047      |          |                           |                           |           |           |                  |
|                   | ENC                                          |           |          | TSN 0                     |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: EMM 74-20-00   |                           |           |           |                  |
| 740040            | NO. 2 ENGINE - 9 O'CLOCK IGNITOR             |           |          |                           |                           |           |           |                  |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0                     |                           |           |           | Component ATA:74 |
| SN:UNKNOWN        | HRS                                          | 4105.2    |          | TSN 0                     |                           |           |           |                  |
|                   | ENC                                          | 4047      |          | TSN 0                     |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: EMM 74-20-00   |                           |           |           |                  |
| 740070            | NO. 1 ENGINE - AUTO IGNITION PRESSURE SWITCH |           |          |                           |                           |           |           |                  |
| PN:50-389121-19   | MOS/MSC                                      | 18-Feb-99 | O/C      |                           |                           |           |           | Component ATA:74 |
| SN:11599          | HRS                                          | 980       |          | TSN 0                     |                           |           |           |                  |
|                   | ENC                                          |           |          |                           |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 740070            | NO. 2 ENGINE - AUTO IGNITION PRESSURE SWITCH |           |          |                           |                           |           |           |                  |
| PN:MS24658-23D    | MOS/MSC                                      | 20-Dec-94 | O/C      |                           |                           |           |           | Component ATA:74 |
| SN:UNKNOWN        | HRS                                          | 0         |          | TSN 0                     |                           |           |           |                  |
|                   | ENC                                          |           |          |                           |                           |           |           |                  |
|                   |                                              |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                                                   | C/W | Interval  | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|---------------------------|----------------------------------------------------------------------------------------|-----|-----------|------------|---------------------------|-----------|-----------|----------------|
| ATA 74 - IGNITION         |                                                                                        |     |           |            |                           |           |           |                |
| 740080                    | NO. 1 ENGINE - OPERATIONAL CHECK AUTO IGNITION SYSTEM                                  |     |           |            |                           |           |           |                |
|                           | MOS/MSC                                                                                |     | 21-Nov-11 | O/C        |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 2995      |            |                           |           |           |                |
|                           | ENC                                                                                    |     | 2995      |            |                           |           |           |                |
| PROC. REF: GENERIC NO REF |                                                                                        |     |           |            |                           |           |           |                |
| 740080                    | NO. 2 ENGINE - OPERATIONAL CHECK AUTO IGNITION SYSTEM                                  |     |           |            |                           |           |           |                |
|                           | MOS/MSC                                                                                |     | 21-Nov-11 | O/C        |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 2995      |            |                           |           |           |                |
|                           | ENC                                                                                    |     | 2995      |            |                           |           |           |                |
| PROC. REF: GENERIC NO REF |                                                                                        |     |           |            |                           |           |           |                |
| 741000                    | NO. 1 ENGINE - EXAMINE THE IGNITION EXCITER FOR THE CORRECT INSTALLATION AND CONDITION |     |           |            |                           |           |           |                |
|                           | MOS                                                                                    |     | 22-May-24 |            |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 4291.1    | 400 (+10%) | (4691.1)<br>6086.2        | 4731.1    | 400 (+40) |                |
|                           | ENC                                                                                    |     | 4184      |            |                           |           |           |                |
| PROC. REF: GENERIC NO REF |                                                                                        |     |           |            |                           |           |           |                |
| 741000                    | NO. 2 ENGINE - EXAMINE THE IGNITION EXCITER FOR THE CORRECT INSTALLATION AND CONDITION |     |           |            |                           |           |           |                |
|                           | MOS                                                                                    |     | 22-May-24 |            |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 4291.1    | 400 (+10%) | (4691.1)<br>6086.2        | 4731.1    | 400 (+40) |                |
|                           | ENC                                                                                    |     | 4184      |            |                           |           |           |                |
| PROC. REF: GENERIC NO REF |                                                                                        |     |           |            |                           |           |           |                |
| 742000                    | NO. 1 ENGINE - EXAMINE THE IGNITION CABLES FOR CHAFING, WEAR AND CORRECT INSTALLATION  |     |           |            |                           |           |           |                |
|                           | MOS                                                                                    |     | 22-May-24 |            |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 4291.1    | 400 (+10%) | (4691.1)<br>6086.2        | 4731.1    | 400 (+40) |                |
|                           | ENC                                                                                    |     | 4184      |            |                           |           |           |                |
| PROC. REF: EMM 74-20-00   |                                                                                        |     |           |            |                           |           |           |                |
| 742000                    | NO. 2 ENGINE - EXAMINE THE IGNITION CABLES FOR CHAFING, WEAR AND CORRECT INSTALLATION  |     |           |            |                           |           |           |                |
|                           | MOS                                                                                    |     | 22-May-24 |            |                           |           |           | Service ATA:74 |
|                           | HRS                                                                                    |     | 4291.1    | 400 (+10%) | (4691.1)<br>6086.2        | 4731.1    | 400 (+40) |                |
|                           | ENC                                                                                    |     | 4184      |            |                           |           |           |                |
| PROC. REF: EMM 74-20-00   |                                                                                        |     |           |            |                           |           |           |                |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                  | Unit                                     | C/W       | Interval    | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|--------------------------|------------------------------------------|-----------|-------------|-----------------|---------------------------|-----------|---------------|------------------|
| ATA 75 - AIR             |                                          |           |             |                 |                           |           |               |                  |
| 750010                   | NO. 1 ENGINE - HIGH PRESSURE BLEED VALVE |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100922-05            | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:17A768                | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                  |
|                          | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
|                          | PROC. REF: EMM 75-30-00                  |           |             |                 |                           |           |               |                  |
| 750010                   | NO. 2 ENGINE - HIGH PRESSURE BLEED VALVE |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100922-05            | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:4K344                 | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                  |
|                          | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
|                          | PROC. REF: EMM 75-30-00                  |           |             |                 |                           |           |               |                  |
| 750020                   | NO. 1 ENGINE - LOW PRESSURE BLEED VALVE  |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100923-02            | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:9K356                 | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                  |
|                          | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
|                          | PROC. REF: EMM 75-30-00                  |           |             |                 |                           |           |               |                  |
| 750020                   | NO. 2 ENGINE - LOW PRESSURE BLEED VALVE  |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100923-02            | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:3K396                 | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2303.9 (+500) |                  |
|                          | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
|                          | PROC. REF: EMM 75-30-00                  |           |             |                 |                           |           |               |                  |
| ATA 76 - ENGINE CONTROLS |                                          |           |             |                 |                           |           |               |                  |
| 760010                   | NO. 1 ENGINE - RIG CONTROL               |           |             |                 |                           |           |               | Service ATA:76   |
|                          | MOS/MSC                                  | 20-Dec-94 | O/C         |                 |                           |           |               |                  |
|                          | HRS                                      | 0         |             |                 |                           |           |               |                  |
|                          | ENC                                      | 0         |             |                 |                           |           |               |                  |
|                          | PROC. REF: GENERIC NO REF                |           |             |                 |                           |           |               |                  |
| 760010                   | NO. 2 ENGINE - RIG CONTROL               |           |             |                 |                           |           |               | Service ATA:76   |
|                          | MOS/MSC                                  | 20-Dec-94 | O/C         |                 |                           |           |               |                  |
|                          | HRS                                      | 0         |             |                 |                           |           |               |                  |
|                          | ENC                                      | 0         |             |                 |                           |           |               |                  |
|                          | PROC. REF: GENERIC NO REF                |           |             |                 |                           |           |               |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024

15-Jul-2024 11:40 AM

| PN & SN                    | Unit                                            | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------|-------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 76 - ENGINE CONTROLS   |                                                 |           |                  |          |                           |           |             |                  |
| 760301                     | LEFT ENGINE POWER LEVER PIN (PEDESTAL)          |           |                  |          |                           |           |             |                  |
| PN:101-524181-1            | MOS/MSC                                         | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:76 |
| SN:UNKNOWN                 | HRS                                             | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 76.020                | AFL                                             | 0         |                  |          |                           |           |             |                  |
|                            | PROC. REF: GENERIC NO REF                       |           |                  |          |                           |           |             |                  |
| 760302                     | INSPECT LEFT ENGINE POWER LEVER (PEDESTAL) PIN  |           |                  |          |                           |           |             |                  |
|                            | MOS                                             | 22-May-24 |                  |          |                           |           |             | Service ATA:76   |
|                            | HRS                                             | 5686.2    | 1200 (+10%/-10%) |          | 6886.2                    | 7006.2    | 1200 (+120) |                  |
| WC#: 76.020                | AFL                                             | 6495      |                  |          |                           |           |             |                  |
| 760350                     | RIGHT ENGINE POWER LEVER PIN (PEDESTAL)         |           |                  |          |                           |           |             |                  |
| PN:50-524567-3             | MOS/MSC                                         | 29-Dec-98 | O/C              |          |                           |           |             | Component ATA:76 |
| SN:UNKNOWN                 | HRS                                             | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 76.020                | AFL                                             | 0         |                  |          |                           |           |             |                  |
|                            | PROC. REF: GENERIC NO REF                       |           |                  |          |                           |           |             |                  |
| 760351                     | INSPECT RIGHT ENGINE POWER LEVER (PEDESTAL) PIN |           |                  |          |                           |           |             |                  |
|                            | MOS                                             | 22-May-24 |                  |          |                           |           |             | Service ATA:76   |
|                            | HRS                                             | 5686.2    | 1200 (+10%/-10%) |          | 6886.2                    | 7006.2    | 1200 (+120) |                  |
| WC#: 76.020                | AFL                                             | 6495      |                  |          |                           |           |             |                  |
| 761010 <sup>S</sup>        | NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES  |           |                  |          |                           |           |             |                  |
|                            | MOS/MSC                                         | 22-May-24 | A/R              |          |                           |           |             | Service ATA:76   |
|                            | HRS                                             | 4291.1    |                  |          |                           |           |             |                  |
|                            | ENC                                             | 4184      |                  |          |                           |           |             |                  |
|                            | PROC. REF: EMM 72-00-00                         |           |                  |          |                           |           |             |                  |
|                            | PKG:1                                           |           |                  |          |                           |           |             |                  |
| 761010 <sup>S</sup>        | NO. 2 ENGINE - INSPECT ENGINE CONTROL LINKAGES  |           |                  |          |                           |           |             |                  |
|                            | MOS/MSC                                         | 22-May-24 | A/R              |          |                           |           |             | Service ATA:76   |
|                            | HRS                                             | 4291.1    |                  |          |                           |           |             |                  |
|                            | ENC                                             | 4184      |                  |          |                           |           |             |                  |
|                            | PROC. REF: EMM 72-00-00                         |           |                  |          |                           |           |             |                  |
|                            | PKG:1                                           |           |                  |          |                           |           |             |                  |
| ATA 77 - ENGINE INDICATING |                                                 |           |                  |          |                           |           |             |                  |
| 770020                     | NO. 1 ENGINE - TORQUE PRESSURE TRANSMITTER      |           |                  |          |                           |           |             |                  |
| PN:130-389002-1            | MOS/MSC                                         | 20-Dec-94 | O/C              |          |                           |           |             | Component ATA:77 |
| SN:4815-7-203              | HRS                                             | 0         |                  | TSN 0    |                           |           |             |                  |
|                            | ENC                                             |           |                  |          |                           |           |             |                  |
|                            | PROC. REF: GENERIC NO REF                       |           |                  |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                    | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                                       |           |          |          |                           |           |           |                  |
| 770020                     | NO. 2 ENGINE - TORQUE PRESSURE TRANSMITTER            |           |          |          |                           |           |           |                  |
| PN:130-389002-1            | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:4984-4-287              | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |          |                           |           |           |                  |
| 770030                     | NO. 1 ENGINE - TURBINE TEMPERTURE HARNESS             |           |          |          |                           |           |           |                  |
| PN:3022441                 | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
|                            | PROC. REF: EMM 77-20-01                               |           |          |          |                           |           |           |                  |
| 770030                     | NO. 2 ENGINE - TURBINE TEMPERTURE HARNESS             |           |          |          |                           |           |           |                  |
| PN:3022441                 | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
|                            | PROC. REF: EMM 77-20-01                               |           |          |          |                           |           |           |                  |
| 770101                     | NO. 1 ENGINE TURBINE TACH INDICATOR                   |           |          |          |                           |           |           |                  |
| PN:50-380034-3             | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.010                | AFL                                                   | 0         |          |          |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |          |                           |           |           |                  |
| 770111                     | NO. 1 ENGINE TORQUE PRESSURE INDICATOR                |           |          |          |                           |           |           |                  |
| PN:101-384008-3            | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.020                | AFL                                                   | 0         |          |          |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |          |                           |           |           |                  |
| 770121                     | NO. 1 ENGINE TURBINE INTERSTAGE TEMPERATURE INDICATOR |           |          |          |                           |           |           |                  |
| PN:50-389102-15            | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.030                | AFL                                                   | 0         |          |          |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |          |                           |           |           |                  |
| 770150                     | NO. 1 ENGINE N1 TACHOMETER GENERATOR REPLACE          |           |          |          |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | PROC. REF: AMM 77-14-01                               |           |          |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                    | Unit                                                  | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|-------------------------------------------------------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                                       |           |          |                   |                           |           |           |                  |
| 770601                     | NO. 2 ENGINE TURBINE TACH INDICATOR                   |           |          |                   |                           |           |           |                  |
| PN:50-380034-3             | MOS/MSC                                               | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 77.010                | AFL                                                   | 0         |          |                   |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |                   |                           |           |           |                  |
| 770611                     | NO. 2 ENGINE TORQUE PRESSURE INDICATOR                |           |          |                   |                           |           |           |                  |
| PN:130-380044-17           | MOS/MSC                                               | 07-Feb-20 | O/C      | TSR 0             |                           |           |           | Component ATA:77 |
| SN:361                     | HRS                                                   | 5159.5    |          | TSN 5159.5, TSR 0 |                           |           |           |                  |
| WC#: 77.020                | AFL                                                   | 6110      |          | TSR 0             |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |                   |                           |           |           |                  |
| 770621                     | NO. 2 ENGINE TURBINE INTERSTAGE TEMPERATURE INDICATOR |           |          |                   |                           |           |           |                  |
| PN:50-389102-15            | MOS/MSC                                               | 29-Dec-98 | O/C      |                   |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 77.030                | AFL                                                   | 0         |          |                   |                           |           |           |                  |
|                            | PROC. REF: GENERIC NO REF                             |           |          |                   |                           |           |           |                  |
| 770650                     | NO. 2 ENGINE NI TACHOMETER GENERATOR REPLACE          |           |          |                   |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                               | 29-Dec-98 | O/C      | TSN 0             |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | AFL                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | PROC. REF: AMM 77-14-01                               |           |          |                   |                           |           |           |                  |
| 772001                     | NO. 1 ENGINE - NEGATIVE TERMINAL.T5 BUS BAR           |           |          |                   |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | PROC. REF: EMM 77-20-01                               |           |          |                   |                           |           |           |                  |
| 772001                     | NO. 2 ENGINE - NEGATIVE TERMINAL.T5 BUS BAR           |           |          |                   |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | PROC. REF: EMM 77-20-01                               |           |          |                   |                           |           |           |                  |
| 772002                     | NO. 1 ENGINE - POSITIVE TERMINAL BUS BAR              |           |          |                   |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | PROC. REF: EMM 77-20-01                               |           |          |                   |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                    | Unit                                     | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|------------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                          |           |          |                           |                           |           |           |                  |
| 772002                     | NO. 2 ENGINE - POSITIVE TERMINAL BUS BAR |           |          |                           |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                  | 20-Dec-94 | O/C      | TSN 0                     |                           |           |           | Component ATA:77 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
|                            | ENC                                      | 0         |          | TSN 0                     |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: EMM 77-20-01   |                           |           |           |                  |
| ATA 78 - EXHAUST           |                                          |           |          |                           |                           |           |           |                  |
| 780101                     | NO. 1 ENGINE LEFT EXHAUST/WELD ASSY      |           |          |                           |                           |           |           |                  |
| PN:101-950016-23           | MOS/MSC                                  | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:78 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 78.010                | AFL                                      | 0         |          |                           |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 780106                     | NO. 1 ENGINE RIGHT EXHAUST/WELD ASSY     |           |          |                           |                           |           |           |                  |
| PN:101-950016-23           | MOS/MSC                                  | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:78 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 78.010                | AFL                                      | 0         |          |                           |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 780111                     | NO. 2 ENGINE LEFT EXHAUST/WELD ASSY      |           |          |                           |                           |           |           |                  |
| PN:101-950016-25           | MOS/MSC                                  | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:78 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 78.020                | AFL                                      | 0         |          |                           |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 780116                     | NO. 2 ENGINE RIGHT EXHAUST/WELD ASSY     |           |          |                           |                           |           |           |                  |
| PN:101-950016-25           | MOS/MSC                                  | 29-Dec-98 | O/C      |                           |                           |           |           | Component ATA:78 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
| WC#: 78.020                | AFL                                      | 0         |          |                           |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| ATA 79 - OIL               |                                          |           |          |                           |                           |           |           |                  |
| 790010                     | NO. 1 ENGINE - OIL COOLER                |           |          |                           |                           |           |           |                  |
| PN:PN                      | MOS/MSC                                  | 20-Dec-94 | O/C      | TSN 0                     |                           |           |           | Component ATA:79 |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0                     |                           |           |           |                  |
|                            | ENC                                      | 0         |          | TSN 0                     |                           |           |           |                  |
|                            |                                          |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN      | Unit                                                                    | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|--------------|-------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 79 - OIL |                                                                         |           |            |          |                           |           |             |                  |
| 790010       | NO. 2 ENGINE - OIL COOLER                                               |           |            |          |                           |           |             |                  |
| PN:PN        | MOS/MSC                                                                 | 20-Dec-94 | O/C        | TSN 0    |                           |           |             | Component ATA:79 |
| SN:UNKNOWN   | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|              | ENC                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|              | PROC. REF: GENERIC NO REF                                               |           |            |          |                           |           |             |                  |
| 790020       | NO. 1 ENGINE - CHIP DETECTOR                                            |           |            |          |                           |           |             |                  |
| PN:3019373   | MOS/MSC                                                                 | 20-Dec-94 | O/C        |          |                           |           |             | Component ATA:79 |
| SN:UNKNOWN   | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|              | ENC                                                                     |           |            |          |                           |           |             |                  |
|              | PROC. REF: EMM 72-10-00                                                 |           |            |          |                           |           |             |                  |
| 790020       | NO. 2 ENGINE - CHIP DETECTOR                                            |           |            |          |                           |           |             |                  |
| PN:3019373   | MOS/MSC                                                                 | 20-Dec-94 | O/C        |          |                           |           |             | Component ATA:79 |
| SN:UNKNOWN   | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|              | ENC                                                                     |           |            |          |                           |           |             |                  |
|              | PROC. REF: EMM 72-10-00                                                 |           |            |          |                           |           |             |                  |
| 790030       | NO. 1 ENGINE - CHIP DETECTOR CONTINUITY CHECK MAGNETIC CHIP DETECTOR(S) |           |            |          |                           |           |             |                  |
| PN:3019373   | MOS                                                                     | 22-May-24 |            |          |                           |           |             | Service ATA:79   |
| SN:UNKNOWN   | HRS                                                                     | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 400 (+40)   |                  |
|              | ENC                                                                     | 4184      |            |          |                           |           |             | PKG:1            |
|              | PROC. REF: EMM 72-10-00                                                 |           |            |          |                           |           |             |                  |
| 790030       | NO. 2 ENGINE - CHIP DETECTOR CONTINUITY CHECK MAGNETIC CHIP DETECTOR(S) |           |            |          |                           |           |             |                  |
| PN:3019373   | MOS                                                                     | 22-May-24 |            |          |                           |           |             | Service ATA:79   |
| SN:UNKNOWN   | HRS                                                                     | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 400 (+40)   |                  |
|              | ENC                                                                     | 4184      |            |          |                           |           |             | PKG:1            |
|              | PROC. REF: EMM 72-10-00                                                 |           |            |          |                           |           |             |                  |
| 790040       | NO. 1 ENGINE - BRIDGE CHECK CHIP DETECTOR                               |           |            |          |                           |           |             |                  |
| PN:3019373   | MOS                                                                     | 22-May-24 | 12 (+30d)  |          | 22-May-25                 | 21-Jun-25 | 311 d (+30) | Service ATA:79   |
| SN:UNKNOWN   | HRS                                                                     | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60)   |                  |
|              | ENC                                                                     | 4184      |            |          |                           |           |             |                  |
|              | PROC. REF: EMM 72-10-00                                                 |           |            |          |                           |           |             |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN             | Unit                                                           | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition             |
|---------------------|----------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|-------------------------|
| ATA 79 - OIL        |                                                                |           |                  |          |                           |           |              |                         |
| 790040              | NO. 2 ENGINE - BRIDGE CHECK CHIP DETECTOR                      |           |                  |          |                           |           |              |                         |
| PN:3019373          | MOS                                                            | 22-May-24 | 12 (+30d)        |          | 22-May-25                 | 21-Jun-25 | 311 d (+30)  | Service ATA:79          |
| SN:UNKNOWN          | HRS                                                            | 4291.1    | 600 (+10%)       |          | (4891.1)<br>6286.2        | 4951.1    | 600 (+60)    |                         |
|                     | ENC                                                            | 4184      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 72-10-00                                        |           |                  |          |                           |           |              |                         |
| 790045              | NO. 1 ENGINE - CHECK SCAVENGE PUMP INLET SCREEN                |           |                  |          |                           |           |              |                         |
|                     | MOS                                                            | 13-Feb-19 |                  |          |                           |           |              | Service ATA:79          |
|                     | HRS                                                            | 3688.3    | 1000 (+100)      |          | (4688.3)<br>6083.4        | 4788.3    | 397.2 (+100) |                         |
|                     | ENC                                                            | 3688      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 72-60-00                                        |           |                  |          |                           |           |              |                         |
| 790045              | NO. 2 ENGINE - CHECK SCAVENGE PUMP INLET SCREEN                |           |                  |          |                           |           |              |                         |
|                     | MOS                                                            | 13-Feb-19 |                  |          |                           |           |              | Service ATA:79          |
|                     | HRS                                                            | 3688.3    | 1000 (+100)      |          | (4688.3)<br>6083.4        | 4788.3    | 397.2 (+100) |                         |
|                     | ENC                                                            | 3688      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 72-60-00                                        |           |                  |          |                           |           |              |                         |
| 790050              | NO. 1 ENGINE - REPLACE OIL FILTER                              |           |                  |          |                           |           |              |                         |
|                     | MOS                                                            | 12-Apr-23 |                  |          |                           |           |              | Service ATA:79<br>SCRAP |
|                     | HRS                                                            | 4105.2    | 1000 (+100/-100) |          | (5105.2)<br>6500.3        | 5205.2    | 814.1 (+100) |                         |
|                     | ENC                                                            | 4047      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 79-20-02                                        |           |                  |          |                           |           |              |                         |
| 790050              | NO. 2 ENGINE - REPLACE OIL FILTER                              |           |                  |          |                           |           |              |                         |
|                     | MOS                                                            | 12-Apr-23 |                  |          |                           |           |              | Service ATA:79<br>SCRAP |
|                     | HRS                                                            | 4105.2    | 1000 (+100/-100) |          | (5105.2)<br>6500.3        | 5205.2    | 814.1 (+100) |                         |
|                     | ENC                                                            | 4047      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 79-20-02                                        |           |                  |          |                           |           |              |                         |
| 790060 <sup>S</sup> | NO. 1 ENGINE - EXAMINE OIL FILTER ELEMENT AND SECONDARY SCREEN |           |                  |          |                           |           |              |                         |
|                     | MOS                                                            | 22-May-24 |                  |          |                           |           |              | Service ATA:79          |
|                     | HRS                                                            | 4291.1    | 200 (+10%)       |          |                           |           |              |                         |
|                     | ENC                                                            | 4184      |                  |          |                           |           |              |                         |
|                     | PROC. REF: EMM 79-20-02                                        |           |                  |          |                           |           |              |                         |
|                     | PKG:1                                                          |           |                  |          |                           |           |              |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN                   | Unit                                                           | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL              |                                                                |           |            |          |                           |           |           |                  |
| 790060 <sup>S</sup>       | NO. 2 ENGINE - EXAMINE OIL FILTER ELEMENT AND SECONDARY SCREEN |           |            |          |                           |           |           |                  |
|                           | MOS                                                            | 22-May-24 |            |          |                           |           |           | Service ATA:79   |
|                           | HRS                                                            | 4291.1    | 200 (+10%) |          |                           |           |           |                  |
|                           | ENC                                                            | 4184      |            |          |                           |           |           |                  |
| PKG:1                     |                                                                |           |            |          |                           |           |           |                  |
| 790065                    | NO. 1 ENGINE - P8WC OIL ANALYSIS TECHNOLOGY PROGRAM            |           |            |          |                           |           |           |                  |
|                           | MOS/MSC                                                        | 22-May-24 | O/C        |          |                           |           |           | Service ATA:79   |
|                           | HRS                                                            | 4291.1    |            |          |                           |           |           |                  |
|                           | ENC                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |
| 790065                    | NO. 2 ENGINE - P8WC OIL ANALYSIS TECHNOLOGY PROGRAM            |           |            |          |                           |           |           |                  |
|                           | MOS/MSC                                                        | 22-May-24 | O/C        |          |                           |           |           | Service ATA:79   |
|                           | HRS                                                            | 4291.1    |            |          |                           |           |           |                  |
|                           | ENC                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |
| 790075 <sup>S</sup>       | NO. 1 ENGINE - CHECK THE SCAVENGE PUMP HOUSING FOR LEAKS       |           |            |          |                           |           |           |                  |
|                           | MOS                                                            | 22-May-24 |            |          |                           |           |           | Service ATA:79   |
|                           | HRS                                                            | 4291.1    | 200        |          |                           |           |           |                  |
|                           | ENC                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |
| 790075 <sup>S</sup>       | NO. 2 ENGINE - CHECK THE SCAVENGE PUMP HOUSING FOR LEAKS       |           |            |          |                           |           |           |                  |
|                           | MOS                                                            | 22-May-24 |            |          |                           |           |           | Service ATA:79   |
|                           | HRS                                                            | 4291.1    | 200        |          |                           |           |           |                  |
|                           | ENC                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |
| 790080                    | NO. 1 ENGINE - OIL PRESSURE TRANSMITTER                        |           |            |          |                           |           |           |                  |
|                           | MOS/MSC                                                        | 20-Dec-94 | O/C        |          |                           |           |           | Component ATA:79 |
|                           | HRS                                                            | 0         |            | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            |           |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |
| 790080                    | NO. 2 ENGINE - OIL PRESSURE TRANSMITTER                        |           |            |          |                           |           |           |                  |
|                           | MOS/MSC                                                        | 20-Dec-94 | O/C        |          |                           |           |           | Component ATA:79 |
|                           | HRS                                                            | 0         |            | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            |           |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |            |          |                           |           |           |                  |



Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5686.2 AFL: 6495 As Of: 10-Jun-2024 15-Jul-2024 11:40 AM

| PN & SN         | Unit                                                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|-----------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL    |                                                                                   |           |          |          |                           |           |           |                  |
| 790090          | NO. 1 ENGINE - OIL TEMPERATURE BULB                                               |           |          |          |                           |           |           |                  |
| PN:MS28034-3    | MOS/MSC                                                                           | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:UNKNOWN      | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                               |           |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |
| 790090          | NO. 2 ENGINE - OIL TEMPERATURE BULB                                               |           |          |          |                           |           |           |                  |
| PN:MS28034-3    | MOS/MSC                                                                           | 20-Dec-94 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:UNKNOWN      | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                 | ENC                                                                               |           |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |
| 790105          | NO. 1 ENGINE - DO A FILTER PATCH TEST FOR ENGINES INSTALLED WITH PRE-SB3463 GEARS |           |          |          |                           |           |           |                  |
|                 | MOS/MSC                                                                           |           |          |          |                           |           |           | Service ATA:79   |
|                 | HRS                                                                               |           |          |          |                           |           |           |                  |
|                 | ENC                                                                               |           |          |          |                           |           |           |                  |
|                 | PROC. REF: EMM 79-20-02                                                           |           |          |          |                           |           |           |                  |
| 790116          | NO. 1 ENGINE OIL TEMPERATURE/PRESSURE INDICATOR                                   |           |          |          |                           |           |           |                  |
| PN:101-384122-7 | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:UNKNOWN      | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080     | AFL                                                                               | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |
| 790616          | NO. 2 ENGINE OIL TEMPERATURE/PRESSURE INDICATOR                                   |           |          |          |                           |           |           |                  |
| PN:101-384122-7 | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:UNKNOWN      | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080     | AFL                                                                               | 0         |          |          |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |
| 792005          | LEFT OIL PRESSURE TRANSDUCER                                                      |           |          |          |                           |           |           |                  |
| PN:101-389023-5 | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:6120-3A-216  | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.010     | AFL                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |
| 792010          | RIGHT OIL PRESSURE TRANSDUCER                                                     |           |          |          |                           |           |           |                  |
| PN:101-389023-5 | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           | Component ATA:79 |
| SN:6120-3A-228  | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.010     | AFL                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                 | PROC. REF: GENERIC NO REF                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200    Serial: BB-1645    RegNo: N777HF    HRS: 5686.2    AFL: 6495    As Of: 10-Jun-2024    15-Jul-2024 11:40 AM

| PN & SN      | Unit                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|--------------|-------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 79 - OIL |                         |           |          |          |                           |           |           |                     |
| 793115       | L/H OIL COOLER          |           |          |          |                           |           |           |                     |
| PN:PN        | MOS/MSC                 | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component    ATA:79 |
| SN:UNKNOWN   | HRS                     | 0         |          | TSN 0    |                           |           |           |                     |
|              | AFL                     | 0         |          | TSN 0    |                           |           |           |                     |
|              | PROC. REF: AMM 79-10-01 |           |          |          |                           |           |           |                     |
| 793615       | R/H OIL COOLER          |           |          |          |                           |           |           |                     |
| PN:PN        | MOS/MSC                 | 29-Dec-98 | O/C      | TSN 0    |                           |           |           | Component    ATA:79 |
| SN:UNKNOWN   | HRS                     | 0         |          | TSN 0    |                           |           |           |                     |
|              | AFL                     | 0         |          | TSN 0    |                           |           |           |                     |
|              | PROC. REF: AMM 79-10-01 |           |          |          |                           |           |           |                     |