



## Status Report

SUPER KING AIR B200

S/N BB-1645 N777HF

**OWNER: PARR AVIATION LLC**

ADDRESS: PO BOX 140  
DEMOPOLIS AL 36732  
OFFICE: 334-287-1006  
FAX:

**OPERATOR: PARR AVIATION LLC**

ADDRESS: PO BOX 140  
DEMOPOLIS AL 36732  
OFFICE: 334-287-1006  
FAX:

ANALYST: MATT PHONGVILAI  
EMAIL: MPHONGVILAI@CAMPSYSTEMS.COM

316-462-2416 (DIRECT)  
+1-631-588-3200 (MAIN)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO  
RECORD CHANGES TO ADDRESS, LAST ACTUALS  
(IF ANY).

**FILTER CRITERIA :** Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

|                                                                           |                                       |                                                                                         |                                                   |
|---------------------------------------------------------------------------|---------------------------------------|-----------------------------------------------------------------------------------------|---------------------------------------------------|
| <b>AIRCRAFT</b>                                                           | <b>SERIAL/REGNO:</b> BB-1645/N777HF   | <b>MODEL:</b> SUPER KING AIR B200                                                       | <b>MANUFACTURER:</b> TEXTRON AVIATION INC.        |
| <b>CERTIFICATION DATE:</b> 29-DEC-1998                                    |                                       | <b>LAST ACTUALS:</b><br>5777.7 A/C HRS as of 25-SEP-2024<br>6550 AFL as of 25-SEP-2024  |                                                   |
| <b>ENGINE NO. 1</b>                                                       | <b>SERIAL/PART:</b> PCE-94718/3030700 | <b>MODEL:</b> PT6A-42                                                                   | <b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP. |
| <b>INSTALLED ON:</b> 13-FEB-2019<br>3688.3 ENG. HRS 0 A/C HRS<br>3688 ENC |                                       | <b>LAST ACTUALS:</b><br>4382.6 ENG. HRS as of 25-SEP-2024<br>4239 ENC as of 25-SEP-2024 |                                                   |
| <b>ENGINE NO. 2</b>                                                       | <b>SERIAL/PART:</b> PCE-94709/3030700 | <b>MODEL:</b> PT6A-42                                                                   | <b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP. |
| <b>INSTALLED ON:</b> 13-FEB-2019<br>3688.3 ENG. HRS 0 A/C HRS<br>3688 ENC |                                       | <b>LAST ACTUALS:</b><br>4382.6 ENG. HRS as of 25-SEP-2024<br>4239 ENC as of 25-SEP-2024 |                                                   |
| <b>PROPELLER NO. 1</b>                                                    | <b>SERIAL/PART:</b> HH561/HC-E4N-3G   | <b>MODEL:</b> HC-E4N-3G                                                                 | <b>MANUFACTURER:</b> HARTZELL PROPELLER INC.      |
| <b>INSTALLED ON:</b> 14-DEC-2005<br>1743 PROP HRS 1919.1 A/C HRS<br>0 PRC |                                       | <b>LAST ACTUALS:</b><br>5249.7 PROP HRS as of 25-SEP-2024                               |                                                   |
| <b>PROPELLER NO. 2</b>                                                    | <b>SERIAL/PART:</b> HH3625/HC-E4N-3G  | <b>MODEL:</b> HC-E4N-3G                                                                 | <b>MANUFACTURER:</b> HARTZELL PROPELLER INC.      |
| <b>INSTALLED ON:</b> 10-FEB-2012<br>2770.7 PROP HRS 0 A/C HRS<br>0 PRC    |                                       | <b>LAST ACTUALS:</b><br>5249.7 PROP HRS as of 25-SEP-2024                               |                                                   |



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN              | Unit                                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|----------------------|---------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |                                                                                       |           |          |          |                           |           |           |                          |
| 000010 <sup>U</sup>  | AIRCRAFT PAINT                                                                        |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | 25-Jun-20 | -        |          |                           |           |           |                          |
|                      | HRS                                                                                   | 5172.4    |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |           |                          |
| 000015 <sup>U</sup>  | AIRCRAFT INTERIOR                                                                     |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | 29-Dec-98 | -        |          |                           |           |           |                          |
|                      | HRS                                                                                   | 0         |          |          |                           |           |           |                          |
|                      | AFL                                                                                   | 0         |          |          |                           |           |           |                          |
| BC50-160501A         | REVIEW SUPER KING AIR 200 SERIES AMM REV. D3                                          |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |           |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF BC50                                                                   |           |          |          |                           |           |           |                          |
| BC50-160501B         | REVIEW BEECHCRAFT CORPORATION STRUCTURAL INSPECTION AND REPAIR MANUAL (SIRM) REV. C11 |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |           |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF BC50                                                                   |           |          |          |                           |           |           |                          |
| BC50-161101          | REVIEW SUPER KING AIR 200 SERIES AMM REV. D4                                          |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |           |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF BC50                                                                   |           |          |          |                           |           |           |                          |
| BC50-170201          | REVIEW SUPER KING AIR 200 SERIES AMM REV. D5                                          |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |           |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |           |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF BC50                                                                   |           |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN              | Unit                                                                                  | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|----------------------|---------------------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |                                                                                       |     |          |          |                           |           |           |                          |
| BC50-170201A         | REVIEW BEECHCRAFT CORPORATION STRUCTURAL INSPECTION AND REPAIR MANUAL (SIRM) REV. C12 |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | AFL                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF BC50                                                                   |     |          |          |                           |           |           |                          |
| E015-160720          | NO. 1 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 51.1                                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                                   |     |          |          |                           |           |           |                          |
| E015-160720          | NO. 2 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 51.1                                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                                   |     |          |          |                           |           |           |                          |
| E015-160722          | NO. 1 ENGINE - REVIEW PT6A-38/1/42/42A EMM REV 51.2                                   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                                   |     |          |          |                           |           |           |                          |
| E015-160722          | NO. 2 ENGINE - REVIEW PT6A-38/1/42/42A EMM REV 51.2                                   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                                   |     |          |          |                           |           |           |                          |
| E015-170710          | NO. 1 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 53.0                                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                               | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                                   |     |          |          |                           |           |           |                          |
|                      | ENC                                                                                   |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                                   |     |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN              | Unit                                                                        | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|----------------------|-----------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |                                                                             |     |          |          |                           |           |           |                          |
| E015-170710          | NO. 2 ENGINE - REVIEW PT6A-38/41/42/42A EMM REV 53.0                        |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | ENC                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF E015                                                         |     |          |          |                           |           |           |                          |
| P005-160801          | NO. 1 PROPELLER - REVIEW HC-E4N-3G SL REV 10 REVISION SUMMARY CHANGE FORM   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |
| P005-160801          | NO. 2 PROPELLER - REVIEW HC-E4N-3G SL REV 10 REVISION SUMMARY CHANGE FORM   |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |
| P005-171001          | NO. 1 PROPELLER - REVIEW HARTZELL HC-E4N-3G POM 149 REV 23                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |
| P005-171001          | NO. 2 PROPELLER - REVIEW HARTZELL HC-E4N-3G POM 149 REV 23                  |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |
| P005-210201          | NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35 |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |
| P005-210201          | NO. 2 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35 |     |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC                                                                     | EFF | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS                                                                         |     |          |          |                           |           |           |                          |
|                      | PROC. REF: RCF P005                                                         |     |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                               | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|-----------------------------------------|----------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                    |           |               |          |                           |           |             |                |
| 050001 <sup>U</sup>                     | RENEWAL OF AIRCRAFT REGISTRATION                   |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 24-Mar-22 | 36 (-6m)      |          | 31-Jul-25 (M)             |           | 309 d       |                |
|                                         | HRS                                                | 5331.5    |               |          |                           |           |             |                |
|                                         | AFL                                                | 6250      |               |          |                           |           |             |                |
| 050010                                  | ACCOMPLISH PHASE 1 INSPECTION                      |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 22-May-24 | 24            |          | 22-May-26                 |           | 604 d       |                |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |          | 6486.2                    | 6506.2    | 708.5 (+20) |                |
| WC#: 05.010                             | AFL                                                | 6495      |               |          |                           |           |             |                |
| PROC. REF: AMM 05-20-01                 |                                                    |           |               |          |                           |           |             |                |
| 050010R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 1 INSPECTION |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 22-May-24 | 24            |          | 22-May-26                 |           | 604 d       |                |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |          | 6486.2                    | 6506.2    | 708.5 (+20) |                |
|                                         | AFL                                                | 6495      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                 |                                                    |           |               |          |                           |           |             |                |
| 050020                                  | ACCOMPLISH PHASE 2 INSPECTION                      |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 22-May-24 | 24            |          | 22-May-26                 |           | 604 d       |                |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |          | 6486.2                    | 6506.2    | 708.5 (+20) |                |
| WC#: 05.020                             | AFL                                                | 6495      |               |          |                           |           |             |                |
| PROC. REF: AMM 05-20-02                 |                                                    |           |               |          |                           |           |             |                |
| 050020R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 2 INSPECTION |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 22-May-24 | 24            |          | 22-May-26                 |           | 604 d       |                |
|                                         | HRS                                                | 5686.2    | 800 (+20/-20) |          | 6486.2                    | 6506.2    | 708.5 (+20) |                |
|                                         | AFL                                                | 6495      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                 |                                                    |           |               |          |                           |           |             |                |
| 050030                                  | ACCOMPLISH PHASE 3 INSPECTION                      |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 199 d       |                |
|                                         | HRS                                                | 5500.3    | 800 (+20/-20) |          | 5886.2 (M)                | 5906.2    | 108.5 (+20) |                |
| WC#: 05.030                             | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: AMM 05-20-03                 |                                                    |           |               |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                               | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|-----------------------------------------|----------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                    |           |               |          |                           |           |             |                |
| 050030R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 3 INSPECTION |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 199 d       |                |
|                                         | HRS                                                | 5500.3    | 800 (+20/-20) |          | 6300.3                    | 6320.3    | 522.6 (+20) |                |
|                                         | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                 |                                                    |           |               |          |                           |           |             |                |
| 050040                                  | ACCOMPLISH PHASE 4 INSPECTION                      |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 199 d       |                |
|                                         | HRS                                                | 5500.3    | 800 (+20/-20) |          | 5886.2 (M)                | 5906.2    | 108.5 (+20) |                |
| WC#: 05.040                             | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: AMM 05-20-04                 |                                                    |           |               |          |                           |           |             |                |
| 050040R                                 | ACCOMPLISH RAISBECK ENGINEERING PHASE 4 INSPECTION |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS                                                | 12-Apr-23 | 24            |          | 12-Apr-25                 |           | 199 d       |                |
|                                         | HRS                                                | 5500.3    | 800 (+20/-20) |          | 6300.3                    | 6320.3    | 522.6 (+20) |                |
|                                         | AFL                                                | 6358      |               |          |                           |           |             |                |
| PROC. REF: ICA 05-20-00                 |                                                    |           |               |          |                           |           |             |                |
| 050060                                  | INITIAL LEFT ENGINE 100 HOUR INSPECTION            |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS/MSC                                            | 29-Dec-98 | -             |          |                           |           |             |                |
|                                         | HRS                                                | 0         |               |          |                           |           |             |                |
|                                         | AFL                                                | 0         |               |          |                           |           |             |                |
| PROC. REF: GENERIC NO REF               |                                                    |           |               |          |                           |           |             |                |
| 050070                                  | INITIAL RIGHT ENGINE 100 HOUR INSPECTION           |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS/MSC                                            | 29-Dec-98 | -             |          |                           |           |             |                |
|                                         | HRS                                                | 0         |               |          |                           |           |             |                |
|                                         | AFL                                                | 0         |               |          |                           |           |             |                |
| PROC. REF: GENERIC NO REF               |                                                    |           |               |          |                           |           |             |                |
| 052900                                  | ACCOMPLISH CONTINUOUS CORROSION CONTROL INSPECTION |           |               |          |                           |           |             | Service ATA:05 |
|                                         | MOS/MSC                                            | 29-Dec-98 | A/R           |          |                           |           |             |                |
|                                         | HRS                                                | 0         |               |          |                           |           |             |                |
| WC#: 05.060                             | AFL                                                | 0         |               |          |                           |           |             |                |
| PROC. REF: AMM 05-29-00, AMM 05-29-00   |                                                    |           |               |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                | C/W       | Interval      | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|-----------------------------------------|-----------------------------------------------------|-----------|---------------|-------------------------|---------------------------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                     |           |               |                         |                           |           |             |                |
| 057010                                  | NO. 1 ENGINE - MINOR                                |           |               |                         |                           |           |             | Package ATA:05 |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |             |                |
|                                         | HRS                                                 | 4291.1    | 200 (+20/-20) |                         | (4491.1)<br>5886.2        | 4511.1    | 108.5 (+20) |                |
|                                         | ENC                                                 | 4184      |               |                         |                           |           |             |                |
|                                         |                                                     |           |               | PROC. REF: EMM 72-00-00 |                           |           |             | PKG:1          |
| 057010                                  | NO. 2 ENGINE - MINOR                                |           |               |                         |                           |           |             | Package ATA:05 |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |             |                |
|                                         | HRS                                                 | 4291.1    | 200 (+20/-20) |                         | (4491.1)<br>5886.2        | 4511.1    | 108.5 (+20) |                |
|                                         | ENC                                                 | 4184      |               |                         |                           |           |             |                |
|                                         |                                                     |           |               | PROC. REF: EMM 72-00-00 |                           |           |             | PKG:1          |
| ATA 08 - LEVELING AND WEIGHING          |                                                     |           |               |                         |                           |           |             |                |
| 080005 <sup>U</sup>                     | PERFORM WEIGHT AND BALANCE OF AIRCRAFT              |           |               |                         |                           |           |             | Service ATA:08 |
|                                         | MOS/MSC                                             | 22-Oct-19 | O/C           |                         |                           |           |             |                |
|                                         | HRS                                                 | 5128      |               |                         |                           |           |             |                |
|                                         | AFL                                                 |           |               |                         |                           |           |             |                |
| ATA 12 - SERVICING                      |                                                     |           |               |                         |                           |           |             |                |
| 122020                                  | LUBRICATION 200 HOUR                                |           |               |                         |                           |           |             | Service ATA:12 |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |             |                |
|                                         | HRS                                                 | 5686.2    | 200           |                         | 5886.2                    |           | 108.5       |                |
| WC#: 12.020                             | AFL                                                 | 6495      |               |                         |                           |           |             |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |             |                |
| 122040                                  | LUBRICATION 400 HOUR                                |           |               |                         |                           |           |             | Service ATA:12 |
|                                         | MOS                                                 | 22-May-24 |               |                         |                           |           |             |                |
|                                         | HRS                                                 | 5686.2    | 400           |                         | 6086.2                    |           | 308.5       |                |
| WC#: 12.030                             | AFL                                                 | 6495      |               |                         |                           |           |             |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |             |                |
| 122060                                  | LUBRICATION OF DOWNLOCK HOOKS AND PIN CONTACT AREAS |           |               |                         |                           |           |             | Service ATA:12 |
|                                         | MOS                                                 | 12-Apr-23 | 24            |                         | 12-Apr-25                 |           | 199 d       |                |
|                                         | HRS                                                 | 5500.3    | 800           |                         | 6300.3                    |           | 522.6       |                |
| WC#: 12.040                             | AFL                                                 | 6358      |               |                         |                           |           |             |                |
|                                         |                                                     |           |               | PROC. REF: AMM 12-20-53 |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 12 - SERVICING      |                                        |           |          |          |                           |           |           |                |
| 122065                  | LUBRICATION 800 HOUR                   |           |          |          |                           |           |           | Service ATA:12 |
|                         | MOS                                    | 12-Apr-23 |          |          |                           |           |           |                |
|                         | HRS                                    | 5500.3    | 800      |          | 6300.3                    |           | 522.6     |                |
| WC#: 12.060             | AFL                                    | 6358      |          |          |                           |           |           |                |
| PROC. REF: AMM 12-20-53 |                                        |           |          |          |                           |           |           |                |
| 122070                  | LUBRICATION 1200 HOUR                  |           |          |          |                           |           |           | Service ATA:12 |
|                         | MOS                                    | 12-Apr-23 |          |          |                           |           |           |                |
|                         | HRS                                    | 5500.3    | 1200     |          | 6700.3                    |           | 922.6     |                |
| WC#: 12.050             | AFL                                    | 6358      |          |          |                           |           |           |                |
| PROC. REF: AMM 12-20-53 |                                        |           |          |          |                           |           |           |                |
| 122120                  | LUBRICATION - 12 MONTH LEFT WING BOLT  |           |          |          |                           |           |           | Service ATA:12 |
|                         | MOS                                    | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                |
|                         | HRS                                    | 5686.2    |          |          |                           |           |           |                |
| WC#: 12.090             | AFL                                    | 6495      |          |          |                           |           |           |                |
| PROC. REF: AMM 12-20-53 |                                        |           |          |          |                           |           |           |                |
| 122620                  | LUBRICATION - 12 MONTH RIGHT WING BOLT |           |          |          |                           |           |           | Service ATA:12 |
|                         | MOS                                    | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                |
|                         | HRS                                    | 5686.2    |          |          |                           |           |           |                |
| WC#: 12.090             | AFL                                    | 6495      |          |          |                           |           |           |                |
| PROC. REF: AMM 12-20-53 |                                        |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                | Unit                                                                                                                                    | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 20 - STANDARD PRACTICES - AIRFRAME |                                                                                                                                         |           |                  |          |                           |           |             |                  |
| 200005                                 | INSPECT PILOT'S FUEL CONTROL PANEL AND LOWER PANEL, COPILOT'S CIRCUIT BREAKER PANEL AND OTHER WIRING CIRCUITRY BELOW THE STORM WINDOWS. |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 22-May-24 | 12 (+12d/-12d)   |          | 22-May-25                 | 03-Jun-25 | 239 d (+12) |                  |
|                                        | HRS                                                                                                                                     | 5686.2    |                  |          |                           |           |             |                  |
| WC#: 33.090                            | AFL                                                                                                                                     | 6495      |                  |          |                           |           |             |                  |
| 200010                                 | VISUALLY INSPECT COCKPIT AND CABIN FUSELAGE SKINS AND STRUCTURE (WITH INTERIOR REMOVED).                                                |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 07-Feb-20 |                  |          |                           |           |             |                  |
|                                        | HRS                                                                                                                                     | 5159.2    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6110      | 2500 (+10%/-10%) |          | 8610                      | 8860      | 2060 (+250) |                  |
|                                        | PROC. REF: AMM GENERIC 1                                                                                                                |           |                  |          |                           |           |             |                  |
| 200020                                 | VISUALLY INSPECT THE ENVIRONMENTAL DUCTING                                                                                              |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 13-Feb-19 |                  |          |                           |           |             |                  |
|                                        | HRS                                                                                                                                     | 5082.9    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6044      | 2500 (+10%/-10%) |          | 8544                      | 8794      | 1994 (+250) |                  |
| 200030                                 | VISUALLY INSPECT THE ELECTRICAL WIRING                                                                                                  |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 13-Feb-19 |                  |          |                           |           |             |                  |
|                                        | HRS                                                                                                                                     | 5082.9    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6044      | 2500 (+10%/-10%) |          | 8544                      | 8794      | 1994 (+250) |                  |
| 200040                                 | VISUALLY INSPECT PLUMBING                                                                                                               |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 13-Feb-19 |                  |          |                           |           |             |                  |
|                                        | HRS                                                                                                                                     | 5082.9    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6044      | 2500 (+10%/-10%) |          | 8544                      | 8794      | 1994 (+250) |                  |
| 200050                                 | VISUALLY INSPECT OXYGEN SYSTEM COMPONENTS AND PLUMBING FOR DAMAGE AND SECURITY OF ATTACHMENT.                                           |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 13-Feb-19 |                  |          |                           |           |             |                  |
|                                        | HRS                                                                                                                                     | 5082.9    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6044      | 2500 (+10%/-10%) |          | 8544                      | 8794      | 1994 (+250) |                  |
| 201400                                 | INSPECT CONTROL LOCK                                                                                                                    |           |                  |          |                           |           |             | Service ATA:20   |
|                                        | MOS                                                                                                                                     | 22-May-24 | 12 (+12d/-12d)   |          | 22-May-25                 | 03-Jun-25 | 239 d (+12) |                  |
|                                        | HRS                                                                                                                                     | 5686.2    |                  |          |                           |           |             |                  |
|                                        | AFL                                                                                                                                     | 6495      |                  |          |                           |           |             |                  |
| ATA 21 - AIR CONDITIONING              |                                                                                                                                         |           |                  |          |                           |           |             |                  |
| 210101                                 | LEFT FLOW (PNUEMATIC) CONTROL UNIT                                                                                                      |           |                  |          |                           |           |             | Component ATA:21 |
| PN:101-380013-1                        | MOS/MSC                                                                                                                                 | 29-Dec-98 | O/C              |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                  |           |          |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.010               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-01   |                                  |           |          |          |                           |           |           |                  |
| 210106                    | LEFT FLOW CONTROL PNEUMOSTAT     |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380013-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.050               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 210111                    | LEFT AMBIENT AIR SHUTOFF VALVE   |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380018-1           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.030               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 210116                    | LEFT AIR TO AIR HEAT EXCHANGER   |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-381010-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1950                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.060               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 210121                    | LEFT BLEED AIR BY-PASS VALVE     |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-550087-23          | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6586                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.040               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-40-03   |                                  |           |          |          |                           |           |           |                  |
| 210136                    | LEFT FLOW CONTROL SOLENOID VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380021-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.020               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-07   |                                  |           |          |          |                           |           |           |                  |
| 210137                    | FLAPPER VALVE                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-384173-17          | MOS/MSC                          | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:3820                   | HRS                              | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 21.210               | AFL                              | 6358      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-20-01   |                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                     |           |          |          |                           |           |           |                  |
| 210601                    | RIGHT FLOW (PNEUMATIC) CONTROL UNIT |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380025-11          | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6AP76                  | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.010               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-01   |                                     |           |          |          |                           |           |           |                  |
| 210606                    | RIGHT FLOW CONTROL PNEUMOSTAT       |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380013-3           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.050               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                     |           |          |          |                           |           |           |                  |
| 210611                    | RIGHT AMBIENT AIR SHUTOFF VALVE     |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380018-1           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.030               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                     |           |          |          |                           |           |           |                  |
| 210616                    | RIGHT AIR TO AIR HEAT EXCHANGER     |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-381010-1           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.060               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                     |           |          |          |                           |           |           |                  |
| 210621                    | RIGHT BLEED AIR BY-PASS VALVE       |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-550087-25          | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6665                   | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.040               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-40-03   |                                     |           |          |          |                           |           |           |                  |
| 210636                    | RIGHT FLOW CONTROL SOLENOID VALVE   |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380021-3           | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.020               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-07   |                                     |           |          |          |                           |           |           |                  |
| 211101                    | PRESSURIZATION CONTROLLER           |           |          |          |                           |           |           | Component ATA:21 |
| PN:130346-12              | MOS/MSC                             | 03-Oct-19 | O/C      | TSR 0    |                           |           |           |                  |
| SN:47-2770                | HRS                                 | 5116.1    |          | TSR 0    |                           |           |           |                  |
| WC#: 21.070               | AFL                                 |           |          | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 21-30-09   |                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                 | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING |                                                      |           |                |          |                           |           |             |                  |
| 211105                    | PERFORM CABIN ALTITUDE WARNING PRESSURE SWITCH CHECK |           |                |          |                           |           |             | Service ATA:21   |
| PN:PN                     | MOS                                                  | 22-May-24 | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25 | 239 d (+12) | MANDATORY        |
| SN:UNKNOWN                | HRS                                                  | 5686.2    |                |          |                           |           |             |                  |
| WC#: 21.270               | AFL                                                  | 6495      |                |          |                           |           |             |                  |
| PROC. REF: AMM 21-30-11   |                                                      |           |                |          |                           |           |             |                  |
| 211111                    | CABIN PRESET SOLENOID                                |           |                |          |                           |           |             | Component ATA:21 |
| PN:2297-00-9              | MOS/MSC                                              | 29-Dec-98 | O/C            |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 21.080               | AFL                                                  | 0         |                |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                |          |                           |           |             |                  |
| 212000                    | PROBE ASSEMBLY, THERMISTOR REPLACE                   |           |                |          |                           |           |             | Component ATA:21 |
| PN:PN                     | MOS/MSC                                              | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                | TSN 0    |                           |           |             |                  |
|                           | AFL                                                  | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM GENERIC 1  |                                                      |           |                |          |                           |           |             |                  |
| 212101                    | AIR CONDITIONER COMPRESSOR                           |           |                |          |                           |           |             | Component ATA:21 |
| PN:101-555211-7           | MOS/MSC                                              | 15-Jul-22 | O/C            | TSN 0    |                           |           |             |                  |
| SN:I128044                | HRS                                                  | 5350.1    |                | TSN 0    |                           |           |             |                  |
| WC#: 21.100               | AFL                                                  | 6265      |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 21-50-01   |                                                      |           |                |          |                           |           |             |                  |
| 212106                    | AIR CONDITIONER COMPRESSOR BELT                      |           |                |          |                           |           |             | Component ATA:21 |
| PN:115-389009             | MOS/MSC                                              | 29-Dec-98 | O/C            |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 21.110               | AFL                                                  | 0         |                |          |                           |           |             |                  |
| PROC. REF: AMM 21-50-09   |                                                      |           |                |          |                           |           |             |                  |
| 212111                    | ADJUST AIR CONDITIONER COMPRESSOR BELT TENSION       |           |                |          |                           |           |             | Service ATA:21   |
|                           | MOS/MSC                                              | 22-May-24 | C/C            |          |                           |           |             |                  |
|                           | HRS                                                  | 5686.2    |                |          |                           |           |             |                  |
| WC#: 21.110               | AFL                                                  | 6495      |                |          |                           |           |             |                  |
| PROC. REF: AMM 21-50-09   |                                                      |           |                |          |                           |           |             |                  |
| 212116                    | CONDENSOR COIL ASSEMBLY                              |           |                |          |                           |           |             | Component ATA:21 |
| PN:115-384002-9           | MOS/MSC                                              | 29-Dec-98 | O/C            |          |                           |           |             |                  |
| SN:I98-3167-36            | HRS                                                  | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 21.090               | AFL                                                  | 0         |                |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                  | C/W       | Interval        | TSX/Adj.     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------------------------------------|-----------|-----------------|--------------|---------------------------|-----------|-----------|-------------|--------|
| ATA 21 - AIR CONDITIONING             |                                       |           |                 |              |                           |           |           |             |        |
| 212121                                | CONDENSOR BLOWER MOTOR                |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:EM640-1                            | MOS/MSC                               | 31-Oct-05 | O/C             | TSO 0        |                           |           |           |             |        |
| SN:978                                | HRS                                   | 1904.8    |                 |              |                           |           |           |             |        |
| WC#: 21.090                           | AFL                                   | 1720      |                 |              |                           |           |           |             |        |
| PROC. REF: AMM 21-50-13               |                                       |           |                 |              |                           |           |           |             |        |
| 212136                                | HOT GAS BY-PASS VALVE                 |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:101-380019-1                       | MOS/MSC                               | 29-Dec-98 | O/C             |              |                           |           |           |             |        |
| SN:3590                               | HRS                                   | 0         | TSN 0           |              |                           |           |           |             |        |
| WC#: 21.120                           | AFL                                   | 0         |                 |              |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                       |           |                 |              |                           |           |           |             |        |
| 212141                                | REFRIGERANT OVERPRESSURE SWITCH       |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:101-380002-11                      | MOS/MSC                               | 05-Aug-20 | O/C             | TSN 0        |                           |           |           |             |        |
| SN:1357                               | HRS                                   | 5200      | TSN 0           |              |                           |           |           |             |        |
| WC#: 21.120                           | AFL                                   | 6149      | TSN 0           |              |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                       |           |                 |              |                           |           |           |             |        |
| 212146                                | REFRIGERANT UNDER PRESSURE SWITCH     |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:101-384081-5                       | MOS/MSC                               | 07-Feb-20 | O/C             | TSO 4, TSR 0 |                           |           |           |             |        |
| SN:5709                               | HRS                                   | 5159.2    | TSO 31.2, TSR 0 |              |                           |           |           |             |        |
| WC#: 21.120                           | AFL                                   | 6110      | TSR 0           |              |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                       |           |                 |              |                           |           |           |             |        |
| 212151                                | DRYER RECEIVER                        |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:101-384079-1                       | MOS/MSC                               | 15-Jul-22 | O/C             | TSN 0        |                           |           |           |             |        |
| SN:N/A                                | HRS                                   | 5350.1    | TSN 0           |              |                           |           |           |             |        |
| WC#: 21.130                           | AFL                                   | 6265      | TSN 0           |              |                           |           |           |             |        |
| PROC. REF: AMM 21-50-15, AMM 21-51-17 |                                       |           |                 |              |                           |           |           |             |        |
| 212161                                | EVAPORATOR FREEZE PROTECTION SWITCH   |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:20425L97-840-759                   | MOS/MSC                               | 29-Dec-98 | O/C             |              |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                   | 0         | TSN 0           |              |                           |           |           |             |        |
| WC#: 21.130                           | AFL                                   | 0         |                 |              |                           |           |           |             |        |
| PROC. REF: AMM 21-50-19               |                                       |           |                 |              |                           |           |           |             |        |
| 212170                                | SOLENOID, PRESSURIZATION SAFETY VALVE |           |                 |              |                           |           |           | Component   | ATA:21 |
| PN:PN                                 | MOS/MSC                               | 29-Dec-98 | O/C             | TSN 0        |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                   | 0         | TSN 0           |              |                           |           |           |             |        |
|                                       | AFL                                   | 0         | TSN 0           |              |                           |           |           |             |        |
| PROC. REF: AMM GENERIC 1              |                                       |           |                 |              |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                          |           |          |          |                           |           |           |                  |
| 212176                    | SAFETY VALVE                             |           |          |          |                           |           |           | Component ATA:21 |
| PN:103648-7               | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:48-J0495               | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                          |           |          |          |                           |           |           |                  |
| 212178                    | AIR CONDITIONING BLOWER ASSEMBLY REPLACE |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                          |           |          |          |                           |           |           |                  |
| 212186                    | OUTFLOW VALVE                            |           |          |          |                           |           |           | Component ATA:21 |
| PN:103648-7               | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:48-J0561               | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                          |           |          |          |                           |           |           |                  |
| 212601                    | CABIN TEMPERATURE SENSOR                 |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-364177-1           | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.170               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                          |           |          |          |                           |           |           |                  |
| 212602                    | DUCT TEMPERATURE SENSOR                  |           |          |          |                           |           |           | Component ATA:21 |
| PN:AYLF50304              | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.170               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                          |           |          |          |                           |           |           |                  |
| 212606                    | CABIN TEMPERATURE INDICATOR              |           |          |          |                           |           |           | Component ATA:21 |
| PN:50-380026-1            | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:5399                   | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.180               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                          |           |          |          |                           |           |           |                  |
| 212616                    | CABIN TEMPERATURE CONTROL BOX            |           |          |          |                           |           |           | Component ATA:21 |
| PN:HYZ50336-1             | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:5232K                  | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.180               | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-60-03   |                                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                  |           |          |          |                           |           |           |                  |
| 213005                    | DOOR SEAL VALVE                  |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380018-3           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6907                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.240               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 213010                    | VENTURI TUBE                     |           |          |          |                           |           |           | Component ATA:21 |
| PN:50-380053-1            | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:3387                   | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.260               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 213101                    | CABIN RATE-OF-CLIMB INDICATOR    |           |          |          |                           |           |           | Component ATA:21 |
| PN:50-380045              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:352134                 | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.190               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 214000                    | ENVIRONMENTAL CONTROLLER REPLACE |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                  |           |          |          |                           |           |           |                  |
| 214005                    | LEFT HEAT EXCHANGER              |           |          |          |                           |           |           | Component ATA:21 |
| PN:1263                   | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.250               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 214010                    | RIGHT HEAT EXCHANGER             |           |          |          |                           |           |           | Component ATA:21 |
| PN:1301                   | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.250               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 215000                    | MOTOR, EVAPORATOR ASSEMBLY       |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING             |                              |           |          |          |                           |           |           |                  |
| 215002                                | FORWARD BLOWER ASSEMBLY      |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                                 | MOS/MSC                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-50-17               |                              |           |          |          |                           |           |           |                  |
| 215004                                | AFT FORWARD BLOWER ASSEMBLY  |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-384176-1                       | MOS/MSC                      | 16-Jun-09 | O/C      | TSO 0    |                           |           |           |                  |
| SN:984                                | HRS                          | 2410      |          | TSO 0    |                           |           |           |                  |
| WC#: 21.160                           | AFL                          | 2388      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 21-50-17               |                              |           |          |          |                           |           |           |                  |
| 215006                                | AFT AFT BLOWER ASSEMBLY      |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-384135-3                       | MOS/MSC                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1889                               | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.160                           | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-50-21               |                              |           |          |          |                           |           |           |                  |
| 215007                                | AIR CONDITIONER FORWARD COIL |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-384003-7                       | MOS/MSC                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:G98-2887-75                        | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.230                           | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                              |           |          |          |                           |           |           |                  |
| 215010                                | AIR CONDITIONER AFT COIL     |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-384024-5                       | MOS/MSC                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:F98-2880-82                        | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.230                           | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                              |           |          |          |                           |           |           |                  |
| 215101                                | LEFT RADIANT HEAT ELEMENT    |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-530488-3                       | MOS/MSC                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.200                           | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-40-05, AMM 21-40-07 |                              |           |          |          |                           |           |           |                  |
| 215106                                | RIGHT RADIANT HEAT ELEMENT   |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-530488-3                       | MOS/MSC                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.200                           | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-40-05, AMM 21-40-07 |                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                       |           |          |          |                           |           |           |                  |
| 215135                    | CABIN DIFFERENTIAL PRESSURE INDICATOR |           |          |          |                           |           |           | Component ATA:21 |
| PN:101-380026-13          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:505221                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.190               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| ATA 22 - AUTO FLIGHT      |                                       |           |          |          |                           |           |           |                  |
| 220005                    | YAW RATE SENSOR                       |           |          |          |                           |           |           | Component ATA:22 |
| PN:270-0930-010           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.130               | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| 220101                    | AILERON SERVO                         |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6781-001           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.010               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-07   |                                       |           |          |          |                           |           |           |                  |
| 220106                    | AILERON SERVO MOUNT                   |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6782-001           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.010               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-07   |                                       |           |          |          |                           |           |           |                  |
| 220111                    | ELEVATOR SERVO                        |           |          |          |                           |           |           | Component ATA:22 |
| PN:PN-UNKNOWN             | MOS/MSC                               | 31-May-23 | O/C      |          |                           |           |           |                  |
| SN:6702                   | HRS                                   | 5538.1    |          |          |                           |           |           |                  |
| WC#: 22.020               | AFL                                   |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-15   |                                       |           |          |          |                           |           |           |                  |
| 220116                    | ELEVATOR SERVO MOUNT                  |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-5735-001           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:7929                   | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-15   |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT      |                      |           |          |          |                           |           |           |                  |
| 220121                    | RUDDER SERVO         |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-5734-002           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:10287                  | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.030               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-11   |                      |           |          |          |                           |           |           |                  |
| 220126                    | RUDDER SERVO MOUNT   |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-5735-002           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:8898                   | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.030               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-11   |                      |           |          |          |                           |           |           |                  |
| 220131                    | ELEVATOR TRIM SERVO  |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-5734-002           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:10389                  | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-17   |                      |           |          |          |                           |           |           |                  |
| 220601                    | AUTOPILOT AMPLIFIER  |           |          |          |                           |           |           | Component ATA:22 |
| PN:522-2900-021           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                      |           |          |          |                           |           |           |                  |
| 220606                    | YAW DAMPER COMPUTER  |           |          |          |                           |           |           | Component ATA:22 |
| PN:777-1406-021           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                      |           |          |          |                           |           |           |                  |
| 220616                    | AUTOPILOT CONTROLLER |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6348-003           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.050               | AFL                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                      |           |          |          |                           |           |           |                  |
| 221005                    | LEFT RUDDER SERVO    |           |          |          |                           |           |           | Component ATA:22 |
| PN:101-524973-1           | MOS/MSC              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:833177                 | HRS                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.110               | AFL                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-11   |                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT      |                                                              |           |          |          |                           |           |           |                  |
| 221010                    | RIGHT RUDDER SERVO                                           |           |          |          |                           |           |           | Component ATA:22 |
| PN:101-524973-1           | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:837190                 | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.110               | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-11   |                                                              |           |          |          |                           |           |           |                  |
| 221015                    | ELEVATOR MOUNT TRIM SERVO                                    |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-5735-002           | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:8872                   | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.120               | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-17   |                                                              |           |          |          |                           |           |           |                  |
| 221020                    | AUTOPILOT AMPLIFIER                                          |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-9724-130           | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4049                   | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.150               | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                              |           |          |          |                           |           |           |                  |
| 221040                    | PERFORM AUTOPILOT DISCONNECT AURAL WARNING OPERATION CHECK   |           |          |          |                           |           |           | Service ATA:22   |
|                           | MOS/MSC                                                      | 29-Dec-98 | N/R      |          |                           |           |           |                  |
|                           | HRS                                                          | 0         |          |          |                           |           |           |                  |
|                           | AFL                                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-21   |                                                              |           |          |          |                           |           |           |                  |
| 221045                    | PERFORM STALL WARNING - AUTOPILOT DISCONNECT OPERATION CHECK |           |          |          |                           |           |           | Service ATA:22   |
|                           | MOS/MSC                                                      | 29-Dec-98 | N/R      |          |                           |           |           |                  |
|                           | HRS                                                          | 0         |          |          |                           |           |           |                  |
|                           | AFL                                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-23   |                                                              |           |          |          |                           |           |           |                  |
| 221101                    | MODE COUPLER                                                 |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6255-001           | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060               | AFL                                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                              |           |          |          |                           |           |           |                  |
| 221105                    | AUTOPILOT CONTROL PANEL                                      |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-6684-002           | MOS/MSC                                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2791                   | HRS                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.140               | AFL                                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT      |                         |           |          |          |                           |           |           |                  |
| 221106                    | MODE SELECTOR           |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-0945-003           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 221111                    | ALTITUDE CONTROLLER     |           |          |          |                           |           |           | Component ATA:22 |
| PN:522-4798-003           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.060               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 221115                    | PRESELECTOR/ALERter     |           |          |          |                           |           |           | Component ATA:22 |
| PN:622-9462-024           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4164                   | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.050               | AFL                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 221116                    | FLIGHT COMPUTER         |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6703-001           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.070               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 221606                    | ACCELERATION SENSOR     |           |          |          |                           |           |           | Component ATA:22 |
| PN:229-0324-010           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4852                   | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.080               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 222101                    | AUTOPILOT VERTICAL GYRO |           |          |          |                           |           |           | Component ATA:22 |
| PN:792-6694-001           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.090               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| ATA 23 - COMMUNICATIONS   |                         |           |          |          |                           |           |           |                  |
| 230005                    | VOICE RECORDER CONTROL  |           |          |          |                           |           |           | Component ATA:23 |
| PN:93A151-30              | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:77608                  | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.120               | AFL                     | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                             | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS                             |                                     |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-70-01                             |                                     |           |          |          |                           |           |           |                  |
| 230010                                              | IMPACT SWITCH                       |           |          |          |                           |           |           | Component ATA:23 |
| PN:28DCLIZ400                                       | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:5463                                             | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.130                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-70-07                             |                                     |           |          |          |                           |           |           |                  |
| 230015                                              | NO. 1 IOC-3100 INPUT/OUTPUT         |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                                               | MOS/MSC                             | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.060                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-40-05                             |                                     |           |          |          |                           |           |           |                  |
| 230020                                              | NO. 2 IOC-3100 INPUT/OUTPUT         |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                                               | MOS/MSC                             | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.060                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-40-05                             |                                     |           |          |          |                           |           |           |                  |
| 230025                                              | FSU-5010 FILE SERVER UNIT           |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                                               | MOS/MSC                             | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.140                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-01                             |                                     |           |          |          |                           |           |           |                  |
| 230030                                              | ECU-3000 EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                                               | MOS/MSC                             | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.150                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-63-07, AMM 34-21-03, AMM 31-61-03 |                                     |           |          |          |                           |           |           |                  |
| 230040                                              | PILOT AUDIO SWITCH PANEL            |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                                               | MOS/MSC                             | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.070                                         | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                           |                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS   |                                   |           |          |          |                           |           |           |                  |
| 230045                    | COPILOT AUDIO SWITCH PANEL        |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.070               | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |                  |
| 230046 <sup>U</sup>       | GARMIN GMA 35C AUDIO PANEL        |           |          |          |                           |           |           | Component ATA:23 |
| PN:011-0229940            | MOS/MSC                           | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1T6202994              | HRS                               | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                               | 6064      |          | TSN 0    |                           |           |           |                  |
| 230050                    | STATIC INVERTER                   |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.160               | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |                  |
| 230116                    | NO. 1 VHF COMM ANTENNA            |           |          |          |                           |           |           | Component ATA:23 |
| PN:90-384036              | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6250                   | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.030               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-10-03   |                                   |           |          |          |                           |           |           |                  |
| 230200                    | HF RECEIVER / TRANSMITTER REPLACE |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                   |           |          |          |                           |           |           |                  |
| 230201                    | HF COUPLER REPLACE                |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                   |           |          |          |                           |           |           |                  |
| 230306                    | FLIGHT PHONE                      |           |          |          |                           |           |           | Component ATA:23 |
| PN:400-0125-2000          | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.040               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                       | Unit                                                                       | C/W       | Interval       | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-----------------------------------------------|----------------------------------------------------------------------------|-----------|----------------|------------|---------------------------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                       |                                                                            |           |                |            |                           |           |             |                  |
| 230616                                        | NO. 2 VHF COMM ANTENNA                                                     |           |                |            |                           |           |             | Component ATA:23 |
| PN:90-384036                                  | MOS/MSC                                                                    | 29-Dec-98 | O/C            |            |                           |           |             |                  |
| SN:6256                                       | HRS                                                                        | 0         |                | TSN 0      |                           |           |             |                  |
| WC#: 23.030                                   | AFL                                                                        | 0         |                |            |                           |           |             |                  |
| PROC. REF: AMM 23-10-03                       |                                                                            |           |                |            |                           |           |             |                  |
| 231150                                        | COCKPIT VOICE RECORDER                                                     |           |                |            |                           |           |             | Component ATA:23 |
| PN:S100-0080-00                               | MOS/MSC                                                                    | 07-Aug-12 | O/C            |            |                           |           |             |                  |
| SN:02328                                      | HRS                                                                        | 2825.9    |                | TSN 2825.9 |                           |           |             |                  |
| WC#: 23.050                                   | AFL                                                                        | 2944      |                | TSN 2944   |                           |           |             |                  |
| PROC. REF: AMM 23-70-05                       |                                                                            |           |                |            |                           |           |             |                  |
| 231153                                        | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON                           |           |                |            |                           |           |             | Component ATA:23 |
| PN:DK120                                      | MOS/MSC                                                                    | 22-May-24 | O/C            | TSO 0      |                           |           |             |                  |
| SN:SC13232                                    | HRS                                                                        | 5686.2    |                | TSO 0      |                           |           |             |                  |
| WC#: 23.050                                   | AFL                                                                        | 6495      |                | TSO 0      |                           |           |             |                  |
| PROC. REF: GENERIC NO REF, CMM SECTION V & VI |                                                                            |           |                |            |                           |           |             |                  |
| 231155                                        | REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR/ULB) BATTERY |           |                |            |                           |           |             | Service ATA:23   |
|                                               | MOS/MSC                                                                    | 22-May-24 | DUE            |            | 01-Apr-30 (M)             |           | 2014 d      |                  |
|                                               | HRS                                                                        | 5686.2    |                |            |                           |           |             |                  |
| WC#: 23.050                                   | AFL                                                                        | 6495      |                |            |                           |           |             |                  |
| PROC. REF: CMM SECTION V & VI                 |                                                                            |           |                |            |                           |           |             |                  |
| 231162                                        | FUNCTIONAL TEST COCKPIT VOICE RECORDER                                     |           |                |            |                           |           |             | Service ATA:23   |
|                                               | MOS                                                                        | 12-Apr-23 | 24 (+24d/-24d) |            | 12-Apr-25                 | 06-May-25 | 199 d (+24) |                  |
|                                               | HRS                                                                        | 5500.3    |                |            |                           |           |             |                  |
|                                               | AFL                                                                        | 6358      |                |            |                           |           |             |                  |
| PROC. REF: AMM 23-70-15                       |                                                                            |           |                |            |                           |           |             |                  |
| 231163                                        | FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (ULB)                            |           |                |            |                           |           |             | Service ATA:23   |
|                                               | MOS                                                                        | 12-Apr-23 | 24 (+24d/-24d) |            | 12-Apr-25                 | 06-May-25 | 199 d (+24) |                  |
|                                               | HRS                                                                        | 5500.3    |                |            |                           |           |             |                  |
|                                               | AFL                                                                        | 6358      |                |            |                           |           |             |                  |
| PROC. REF: AMM 23-70-17                       |                                                                            |           |                |            |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS               |                                         |           |          |          |                           |           |           |                  |
| 235015                                | NO. 3 AUDIO AMPLIFIER                   |           |          |          |                           |           |           | Component ATA:23 |
| PN:MODEL 240                          | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1184                               | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.100                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-50-03               |                                         |           |          |          |                           |           |           |                  |
| 235016 <sup>U</sup>                   | AUDIO MIXING AMPLIFIER                  |           |          |          |                           |           |           | Component ATA:23 |
| PN:247-001                            | MOS/MSC                                 | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:P200211                            | HRS                                     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                     | 6064      |          | TSN 0    |                           |           |           |                  |
| 235020                                | AURAL WARNING GENERATOR                 |           |          |          |                           |           |           | Component ATA:23 |
| PN:600-001                            | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.110                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-50-05               |                                         |           |          |          |                           |           |           |                  |
| ATA 24 - ELECTRICAL POWER             |                                         |           |          |          |                           |           |           |                  |
| 240101                                | BATTERY                                 |           |          |          |                           |           |           | Component ATA:24 |
| PN:RG380E/44K                         | MOS/MSC                                 | 22-May-24 | O/C      | TSN 0    |                           |           |           |                  |
| SN:70027463                           | HRS                                     | 5686.2    |          | TSN 0    |                           |           |           |                  |
| WC#: 24.010                           | AFL                                     | 6495      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 24-33-03, AMM 24-30-01 |                                         |           |          |          |                           |           |           |                  |
| 240126                                | BATTERY CURRENT CHARGING MONITOR MODULE |           |          |          |                           |           |           | Component ATA:24 |
| PN:101-364180-1                       | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.020                           | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                         |           |          |          |                           |           |           |                  |
| 240132                                | BATTERY MASTER RELAY                    |           |          |          |                           |           |           | Component ATA:24 |
| PN:6041H189                           | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.020                           | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER |                                |           |          |          |                           |           |           |                  |
| 241101                    | NO. 1 ENGINE STARTER/GENERATOR |           |          |          |                           |           |           | Component ATA:24 |
| PN:23048-016              | MOS                            | 02-Mar-20 |          | TSO 13   |                           |           |           | OVERHAUL         |
| SN:21046                  | HRS                            | 5162.6    | 1000     | TSO 79.7 | 6082.9                    |           | 305.2     |                  |
| WC#: 24.030               | AFL                            | 6113      |          | TSO 69   |                           |           |           |                  |
| PROC. REF: AMM 24-30-03   |                                |           |          |          |                           |           |           |                  |
| 241131                    | LEFT VOLTAGE REGULATOR         |           |          |          |                           |           |           | Component ATA:24 |
| PN:51538-001A             | MOS/MSC                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98406                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.040               | AFL                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                |           |          |          |                           |           |           |                  |
| 241156                    | LEFT VOLTMETER                 |           |          |          |                           |           |           | Component ATA:24 |
| PN:101-384106-9           | MOS/MSC                        | 26-Sep-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:G22-12343              | HRS                            | 5358.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 24.050               | AFL                            | 6274      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                |           |          |          |                           |           |           |                  |
| 241601                    | NO. 2 ENGINE STARTER/GENERATOR |           |          |          |                           |           |           | Component ATA:24 |
| PN:23048-016              | MOS                            | 02-Mar-20 |          | TSO 13   |                           |           |           | OVERHAUL         |
| SN:P1895                  | HRS                            | 5162.6    | 1000     | TSO 79.7 | 6082.9                    |           | 305.2     |                  |
| WC#: 24.030               | AFL                            | 6113      |          | TSO 69   |                           |           |           |                  |
| PROC. REF: AMM 24-30-03   |                                |           |          |          |                           |           |           |                  |
| 241631                    | RIGHT VOLTAGE REGULATOR        |           |          |          |                           |           |           | Component ATA:24 |
| PN:51538-001A             | MOS/MSC                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98373                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.040               | AFL                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                |           |          |          |                           |           |           |                  |
| 241656                    | RIGHT VOLTMETER                |           |          |          |                           |           |           | Component ATA:24 |
| PN:101-384106-9           | MOS/MSC                        | 26-Sep-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:G22-12344              | HRS                            | 5358.5    |          | TSN 0    |                           |           |           |                  |
| WC#: 24.050               | AFL                            | 6274      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                |           |          |          |                           |           |           |                  |
| 242005                    | A/C VOLT FREQUENCY METER       |           |          |          |                           |           |           | Component ATA:24 |
| PN:101-384107-3           | MOS/MSC                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2227                   | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.170               | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|--------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER      |                    |           |          |          |                           |           |           |                  |
| 242101                         | NO. 1 INVERTER     |           |          |          |                           |           |           | Component ATA:24 |
| PN:KGS ELECT. SPC-60(A)MOS/MSC |                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.060                    | AFL                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 242601                         | NO. 2 INVERTER     |           |          |          |                           |           |           | Component ATA:24 |
| PN:KGS ELECT. SPC-60(A)MOS/MSC |                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.060                    | AFL                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 243005                         | NO. 1 POWER SUPPLY |           |          |          |                           |           |           | Component ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2679                        | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.100                    | AFL                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 243010                         | NO. 2 POWER SUPPLY |           |          |          |                           |           |           | Component ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2691                        | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.110                    | AFL                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 243015                         | NO. 3 POWER SUPPLY |           |          |          |                           |           |           | Component ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2676                        | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.120                    | AFL                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 243020                         | NO. 4 POWER SUPPLY |           |          |          |                           |           |           | Component ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2696                        | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.130                    | AFL                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |
| 243025                         | NO. 5 POWER SUPPLY |           |          |          |                           |           |           | Component ATA:24 |
| PN:127-384019-3                | MOS/MSC            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2623                        | HRS                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.140                    | AFL                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                              | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |
|---------------------------|-----------------------------------|-----------|-------------|----------|---------------------------|-----------|------------|------------------|
| ATA 24 - ELECTRICAL POWER |                                   |           |             |          |                           |           |            |                  |
| 243030                    | NO. 6 POWER SUPPLY                |           |             |          |                           |           |            | Component ATA:24 |
| PN:127-384019-3           | MOS/MSC                           | 29-Dec-98 | O/C         |          |                           |           |            |                  |
| SN:2701                   | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.150               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243035                    | BATTERY POWER CIRCUIT BREAKER BOX |           |             |          |                           |           |            | Component ATA:24 |
| PN:101-364462-7           | MOS/MSC                           | 29-Dec-98 | O/C         |          |                           |           |            |                  |
| SN:462-C-98               | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.160               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243040                    | AMMETER INDICATOR                 |           |             |          |                           |           |            | Component ATA:24 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |            |                  |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.070               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243045                    | NO. 1 DC TO AC POWER CONVERTER    |           |             |          |                           |           |            | Component ATA:24 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |            |                  |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.080               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243050                    | NO. 2 DC TO AC POWER CONVERTER    |           |             |          |                           |           |            | Component ATA:24 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |            |                  |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.080               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243100                    | BATTERY CAPACITY TEST (LEAD ACID) |           |             |          |                           |           |            | Service ATA:24   |
| PN:RG380E/44K             | MOS                               | 22-May-24 | 6 (+1m/-1m) |          | 22-Nov-24                 | 22-Dec-24 | 58 d (+30) |                  |
| SN:70027463               | HRS                               | 5686.2    |             |          |                           |           |            |                  |
| WC#: 24.010               | AFL                               | 6495      |             |          |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |
| 243110                    | LEFT HAND GENERATOR CONTROL UNIT  |           |             |          |                           |           |            | Component ATA:24 |
| PN:PN                     | MOS/MSC                           | 29-Dec-98 | O/C         | TSN 0    |                           |           |            |                  |
| SN:UNKNOWN                | HRS                               | 0         |             | TSN 0    |                           |           |            |                  |
| WC#: 24.090               | AFL                               | 0         |             | TSN 0    |                           |           |            |                  |
| PROC. REF: GENERIC NO REF |                                   |           |             |          |                           |           |            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER      |                                   |           |          |          |                           |           |           |                  |
| 243115                         | RIGHT HAND GENERATOR CONTROL UNIT |           |          |          |                           |           |           | Component ATA:24 |
| PN:PN                          | MOS/MSC                           | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.090                    | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |
| ATA 25 - EQUIPMENT/FURNISHINGS |                                   |           |          |          |                           |           |           |                  |
| 250101                         | PILOT SEAT                        |           |          |          |                           |           |           | Component ATA:25 |
| PN:101-530190-23               | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.010                    | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |
| 250106                         | PILOT SEATBELT                    |           |          |          |                           |           |           | Component ATA:25 |
| PN:101-530190-29               | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.020                    | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |
| 250111                         | COPILOT SEAT                      |           |          |          |                           |           |           | Component ATA:25 |
| PN:50-534392-38                | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.010                    | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |
| 250116                         | COPILOT SEATBELT                  |           |          |          |                           |           |           | Component ATA:25 |
| PN:58-530081-29                | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.020                    | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |
| 251005                         | ENVIRONMENTAL TEMPERATURE SENSOR  |           |          |          |                           |           |           | Component ATA:25 |
| PN:AYLF50304                   | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:7326                        | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.060                    | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                         | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                  |                                               |           |          |          |                           |           |           |                  |
| 252601                                          | ELT EMERGENCY LOCATOR TRANSMITTER             |           |          |          |                           |           |           | Component ATA:25 |
| PN:110-4                                        | MOS/MSC                                       | 27-Jan-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:61503                                        | HRS                                           | 2355.4    |          | TSN 0    |                           |           |           |                  |
| WC#: 25.030                                     | AFL                                           | 2317      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-67-01                         |                                               |           |          |          |                           |           |           |                  |
| 252605                                          | EMERGENCY LOCATOR TRANSMITTER BATTERY         |           |          |          |                           |           |           | Component ATA:25 |
| PN:452-0133                                     | MOS/MSC                                       | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:399019-040                                   | HRS                                           | 5500.3    |          | TSN 0    |                           |           |           |                  |
|                                                 | AFL                                           | 6358      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1                        |                                               |           |          |          |                           |           |           |                  |
| 252606                                          | REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY |           |          |          |                           |           |           | Service ATA:25   |
| PN:452-0133                                     | MOS/MSC                                       | 12-Apr-23 | DUE      |          | 01-Mar-28 (M)             |           | 1253 d    |                  |
| SN:399019-040                                   | HRS                                           | 5500.3    |          |          |                           |           |           |                  |
| WC#: 25.030                                     | AFL                                           | 6358      |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-60-03, AMM 25-60-05           |                                               |           |          |          |                           |           |           |                  |
| 252612                                          | INSPECT EMERGENCY LOCATOR TRANSMITTER         |           |          |          |                           |           |           | Service ATA:25   |
| PN:110-4                                        | MOS                                           | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
| SN:61503                                        | HRS                                           | 5686.2    |          |          |                           |           |           |                  |
| WC#: 25.050                                     | AFL                                           | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-67-01, FAR FAR PART 91.207(D) |                                               |           |          |          |                           |           |           |                  |
| 252616                                          | EMERGENCY LOCATOR ANTENNA                     |           |          |          |                           |           |           | Component ATA:25 |
| PN:110-330                                      | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:7748                                         | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.040                                     | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-60-07                         |                                               |           |          |          |                           |           |           |                  |
| 253000 <sup>U</sup>                             | JUPITER DUAL USB CHARGING PORT                |           |          |          |                           |           |           | Component ATA:25 |
| PN:JA74-001                                     | MOS/MSC                                       | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:6022                                         | HRS                                           | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                                 | AFL                                           | 6064      |          | TSN 0    |                           |           |           |                  |
| 253001 <sup>U</sup>                             | TA102 - DUAL USB CHARGING PORT                |           |          |          |                           |           |           | Component ATA:25 |
| PN:6430102-3                                    | MOS/MSC                                       | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:G18-11897                                    | HRS                                           | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                                 | AFL                                           | 6064      |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                             |           |          |          |                           |           |           |                  |
| 253002 <sup>U</sup>            | TA102 - DUAL USB CHARGING PORT              |           |          |          |                           |           |           | Component ATA:25 |
| PN:6430102-3                   | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:C18-12264                   | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                  |
| 253003 <sup>U</sup>            | TA102 - DUAL USB CHARGING PORT              |           |          |          |                           |           |           | Component ATA:25 |
| PN:6430102-3                   | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:C18-11899                   | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                  |
| 258000 <sup>U</sup>            | SEVENTEEN DZUS - GLOVE BOX                  |           |          |          |                           |           |           | Component ATA:25 |
| PN:JA70-017                    | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:6213                        | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                  |
| 258010                         | LEFT HAND ELECTRONIC CONTROLLER             |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                                     | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.070                    | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-11-07        |                                             |           |          |          |                           |           |           |                  |
| 258060                         | RIGHT HAND ELECTRONIC CONTROLLER            |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                                     | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.070                    | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-11-07        |                                             |           |          |          |                           |           |           |                  |
| 259073                         | INSPECT FRX AED (DEFIBULATOR) WITH PREP KIT |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS/MSC                                     | 29-Dec-98 | N/A      |          |                           |           |           |                  |
|                                | HRS                                         | 0         |          |          |                           |           |           |                  |
|                                | AFL                                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1       |                                             |           |          |          |                           |           |           |                  |
| ATA 26 - FIRE PROTECTION       |                                             |           |          |          |                           |           |           |                  |
| 260005                         | INBOARD PRESSURE SWITCH                     |           |          |          |                           |           |           | Component ATA:26 |
| PN:90-380002-3                 | MOS/MSC                                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:14559                       | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.110                    | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-21-23        |                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                  |           |          |          |                           |           |           |                  |
| 260010                    | OUTBOARD PRESSURE SWITCH                         |           |          |          |                           |           |           | Component ATA:26 |
| PN:90-380002-3            | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:14906                  | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.110               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-21-23   |                                                  |           |          |          |                           |           |           |                  |
| 260131                    | NO. 1 ENGINE FORWARD FIRE DETECTOR               |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              |           |          |          |                           |           |           |                  |
| WC#: 26.020               | AFL                                              |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |
| 260136                    | NO. 1 ENGINE UPPER FIRE DETECTOR                 |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.030               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |
| 260141                    | NO. 1 ENGINE LOWER FIRE DETECTOR                 |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.040               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |
| 260146                    | NO. 1 ENGINE FIRE EXTINGUISHER CONTROL AMPLIFIER |           |          |          |                           |           |           | Component ATA:26 |
| PN:30326-7                | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.050               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 260631                    | NO. 2 ENGINE FORWARD FIRE DETECTOR               |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.020               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |
| 260636                    | NO. 2 ENGINE UPPER FIRE DETECTOR                 |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.030               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                  |           |          |          |                           |           |           |                  |
| 260641                    | NO. 2 ENGINE LOWER FIRE DETECTOR                 |           |          |          |                           |           |           | Component ATA:26 |
| PN:30-215-8               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.040               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-10-03   |                                                  |           |          |          |                           |           |           |                  |
| 260646                    | NO. 2 ENGINE FIRE EXTINGUISHER CONTROL AMPLIFIER |           |          |          |                           |           |           | Component ATA:26 |
| PN:30326-7                | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.050               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 261005                    | NO. 1 ENGINE LEFT FIRE OVERHEAT DETECTOR         |           |          |          |                           |           |           | Component ATA:26 |
| PN:3001-129               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:79973                  | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.100               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 261010                    | NO. 2 ENGINE RIGHT FIRE OVERHEAT DETECTOR        |           |          |          |                           |           |           | Component ATA:26 |
| PN:3001-129               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:80016                  | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.100               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 261101                    | NO. 1 ENGINE FIRE EXTINGUISHER MONITOR MODULE    |           |          |          |                           |           |           | Component ATA:26 |
| PN:33370005               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.060               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-03   |                                                  |           |          |          |                           |           |           |                  |
| 261106                    | NO. 2 ENGINE FIRE EXTINGUISHER MONITOR MODULE    |           |          |          |                           |           |           | Component ATA:26 |
| PN:33370005               | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.060               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-03   |                                                  |           |          |          |                           |           |           |                  |
| 261110                    | LEFT HAND BLEED AIR FLOW CONTROL                 |           |          |          |                           |           |           | Component ATA:26 |
| PN:PN                     | MOS/MSC                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.120               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                                | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION                               |                                            |           |          |          |                           |           |           |                  |
| 261115                                                 | RIGHT HAND BLEED AIR FLOW CONTROL          |           |          |          |                           |           |           | Component ATA:26 |
| PN:PN                                                  | MOS/MSC                                    | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                             | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.120                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                            |           |          |          |                           |           |           |                  |
| 262049 <sup>U</sup>                                    | WEIGHT CHECK COCKPIT FIRE EXTINGUISHER     |           |          |          |                           |           |           | Service ATA:26   |
|                                                        | MOS                                        | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                                        | HRS                                        | 5686.2    |          |          |                           |           |           |                  |
|                                                        | AFL                                        | 6495      |          |          |                           |           |           |                  |
| 262050 <sup>U</sup>                                    | WEIGHT CHECK CABIN FIRE EXTINGUISHER       |           |          |          |                           |           |           | Service ATA:26   |
|                                                        | MOS                                        | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                                        | HRS                                        | 5686.2    |          |          |                           |           |           |                  |
|                                                        | AFL                                        | 6495      |          |          |                           |           |           |                  |
| 263201                                                 | CABIN FIRE EXTINGUISHER                    |           |          |          |                           |           |           | Component ATA:26 |
| PN:C352TS                                              | MOS/MSC                                    | 17-Nov-18 | O/C      |          |                           |           |           |                  |
| SN:E92812086                                           | HRS                                        | 5079.9    |          |          |                           |           |           |                  |
| WC#: 26.070                                            | AFL                                        | 6043      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                            |           |          |          |                           |           |           |                  |
| 263211                                                 | HYDROSTATIC TEST CABIN FIRE EXTINGUISHER   |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352TS                                              | MOS                                        | 17-Nov-18 | 144      |          | 17-Nov-30                 |           | 2244 d    |                  |
| SN:E92812086                                           | HRS                                        | 5079.9    |          |          |                           |           |           |                  |
| WC#: 26.070                                            | AFL                                        | 6043      |          |          |                           |           |           |                  |
| HydroCheck Date: : 17-Nov-18 PROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 263621                                                 | COCKPIT FIRE EXTINGUISHER                  |           |          |          |                           |           |           | Component ATA:26 |
| PN:C352TS                                              | MOS/MSC                                    | 17-Nov-18 | O/C      |          |                           |           |           |                  |
| SN:E92812087                                           | HRS                                        | 5079.9    |          |          |                           |           |           |                  |
| WC#: 26.080                                            | AFL                                        | 6043      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                            |           |          |          |                           |           |           |                  |
| 263631                                                 | HYDROSTATIC TEST COCKPIT FIRE EXTINGUISHER |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352TS                                              | MOS                                        | 17-Nov-18 | 144      |          | 17-Nov-30                 |           | 2244 d    |                  |
| SN:E92812087                                           | HRS                                        | 5079.9    |          |          |                           |           |           |                  |
| WC#: 26.080                                            | AFL                                        | 6043      |          |          |                           |           |           |                  |
| HydroCheck Date: : 17-Nov-18 PROC. REF: AMM GENERIC 1  |                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                       | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|--------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                            |           |                  |          |                           |           |              |                  |
| 270010                    | PERFORM FLIGHT CONTROL CABLE TENSION CHECK |           |                  |          |                           |           |              | Service ATA:27   |
|                           | MOS                                        | 22-May-24 | 48 (+48d/-48d)   |          | 22-May-28                 | 09-Jul-28 | 1335 d (+48) |                  |
|                           | HRS                                        | 5686.2    |                  |          |                           |           |              |                  |
|                           | AFL                                        | 6495      |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                            |           |                  |          |                           |           |              |                  |
| 270101                    | LEFT AILERON                               |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-130001-269         | MOS/MSC                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.010               | AFL                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-05   |                                            |           |                  |          |                           |           |              |                  |
| 270111                    | AILERON TRIM TAB                           |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-130001-5           | MOS/MSC                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.020               | AFL                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                            |           |                  |          |                           |           |              |                  |
| 270121                    | AILERON TRIM TAB ACTUATOR                  |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-521039-1           | MOS/MSC                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:573-D-98               | HRS                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.020               | AFL                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-13   |                                            |           |                  |          |                           |           |              |                  |
| 270601                    | RIGHT AILERON                              |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-130001-271         | MOS/MSC                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.010               | AFL                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-05   |                                            |           |                  |          |                           |           |              |                  |
| 271000                    | CHECK AILERON TRIM TAB FREE PLAY           |           |                  |          |                           |           |              | Service ATA:27   |
|                           | MOS                                        | 07-Feb-20 |                  |          |                           |           |              |                  |
|                           | HRS                                        | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 581.8 (+120) |                  |
|                           | AFL                                        | 6110      |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-10-19   |                                            |           |                  |          |                           |           |              |                  |
| 271101                    | RUDDER                                     |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-630000-601         | MOS/MSC                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.030               | AFL                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-20-01   |                                            |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                            | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|---------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                 |           |                 |          |                           |           |             |                  |
| 271116                    | RUDDER TRIM TAB                 |           |                 |          |                           |           |             | Component ATA:27 |
| PN:101-630000-161         | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.040               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                 |          |                           |           |             |                  |
| 271126                    | RUDDER TRIM TAB ACTUATOR        |           |                 |          |                           |           |             | Component ATA:27 |
| PN:101-524079-1           | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.040               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: AMM 27-20-09   |                                 |           |                 |          |                           |           |             |                  |
| 271166                    | RUDDER BOOST PRESSURE REGULATOR |           |                 |          |                           |           |             | Component ATA:27 |
| PN:101-524179-3           | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.060               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                 |          |                           |           |             |                  |
| 271171                    | YAW DAMP PRESSURE REGULATOR     |           |                 |          |                           |           |             | Component ATA:27 |
| PN:101-524179-1           | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:498-A-98               | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.070               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                 |          |                           |           |             |                  |
| 271176                    | REPLACE RUDDER BOOST FILTER     |           |                 |          |                           |           |             | Service ATA:27   |
|                           | MOS                             | 22-May-24 |                 |          |                           |           |             |                  |
|                           | HRS                             | 5686.2    | 200 (+10%/-10%) |          | 5886.2                    | 5906.2    | 108.5 (+20) |                  |
| WC#: 27.060               | AFL                             | 6495      |                 |          |                           |           |             |                  |
| PROC. REF: AMM 27-21-01   |                                 |           |                 |          |                           |           |             |                  |
| 271179                    | LEFT YAW DAMP SERVO             |           |                 |          |                           |           |             | Component ATA:27 |
| PN:1900-7-4-1             | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.080               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                 |          |                           |           |             |                  |
| 271182                    | RIGHT YAW DAMP SERVO            |           |                 |          |                           |           |             | Component ATA:27 |
| PN:1900-7-4-1             | MOS/MSC                         | 29-Dec-98 | O/C             |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                             | 0         |                 | TSN 0    |                           |           |             |                  |
| WC#: 27.080               | AFL                             | 0         |                 |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                 |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                            | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|---------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                 |           |                  |          |                           |           |              |                  |
| 271185                    | LEFT YAW DAMP SOLENOID VALVE    |           |                  |          |                           |           |              | Component ATA:27 |
| PN:717                    | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:8175                   | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090               | AFL                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                  |          |                           |           |              |                  |
| 271188                    | RIGHT YAW DAMP SOLENOID VALVE   |           |                  |          |                           |           |              | Component ATA:27 |
| PN:717                    | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:8237                   | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090               | AFL                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                  |          |                           |           |              |                  |
| 271191                    | YAW CONTROL SOLENOID VALVE      |           |                  |          |                           |           |              | Component ATA:27 |
| PN:717                    | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.090               | AFL                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                  |          |                           |           |              |                  |
| 272000                    | CHECK RUDDER TRIM TAB FREE PLAY |           |                  |          |                           |           |              | Service ATA:27   |
|                           | MOS                             | 07-Feb-20 |                  |          |                           |           |              |                  |
|                           | HRS                             | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 581.8 (+120) |                  |
|                           | AFL                             | 6110      |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-20-15   |                                 |           |                  |          |                           |           |              |                  |
| 272005                    | RUDDER BOOST PRESSURE SWITCH    |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-384119-1           | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:4956                   | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.300               | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 27-21-23   |                                 |           |                  |          |                           |           |              |                  |
| 272010                    | LEFT RUDDER RELIEF VALVE        |           |                  |          |                           |           |              | Component ATA:27 |
| PN:506-1                  | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:5721                   | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.310               | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                  |          |                           |           |              |                  |
| 272015                    | RIGHT RUDDER RELIEF VALVE       |           |                  |          |                           |           |              | Component ATA:27 |
| PN:506-1                  | MOS/MSC                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:5753                   | HRS                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.310               | AFL                             | 0         |                  | TSN 0    |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                 |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                 | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|---------------------------|------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                                      |           |                  |          |                           |           |               |                  |
| 272101                    | LEFT ELEVATOR                                        |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-610000-605         | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.100               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                  |          |                           |           |               |                  |
| 272111                    | LEFT ELEVATOR TRIM TAB                               |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-610000-13          | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.110               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                  |          |                           |           |               |                  |
| 272121                    | LEFT ELEVATOR TRIM TAB ACTUATOR                      |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-524036-1           | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.120               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 27-30-13   |                                                      |           |                  |          |                           |           |               |                  |
| 272601                    | RIGHT ELEVATOR                                       |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-610000-606         | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.100               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                  |          |                           |           |               |                  |
| 272611                    | RIGHT ELEVATOR TRIM TAB                              |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-610000-14          | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.110               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                                      |           |                  |          |                           |           |               |                  |
| 272621                    | RIGHT ELEVATOR TRIM TAB ACTUATOR                     |           |                  |          |                           |           |               | Component ATA:27 |
| PN:101-524072-1           | MOS/MSC                                              | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                | HRS                                                  | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 27.120               | AFL                                                  | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 27-30-13   |                                                      |           |                  |          |                           |           |               |                  |
| 273000                    | PERFORM ELEVATOR BOB WEIGHT LINK ASSEMBLY INSPECTION |           |                  |          |                           |           |               | Service ATA:27   |
|                           | MOS                                                  | 20-Jun-19 |                  |          |                           |           |               |                  |
|                           | HRS                                                  | 5100.1    | 5000 (+10%/-10%) |          | 10100.1                   | 10600.1   | 4322.4 (+500) |                  |
|                           | AFL                                                  |           |                  |          |                           |           |               |                  |
| PROC. REF: AMM 27-30-23   |                                                      |           |                  |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|-------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                     |           |                  |          |                           |           |              |                  |
| 273006                    | CHECK ELEVATOR TRIM TAB FREE PLAY   |           |                  |          |                           |           |              | Service ATA:27   |
|                           | MOS                                 | 07-Feb-20 |                  |          |                           |           |              |                  |
|                           | HRS                                 | 5159.5    | 1200 (+10%/-10%) |          | 6359.5                    | 6479.5    | 581.8 (+120) |                  |
|                           | AFL                                 | 6110      |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-30-21   |                                     |           |                  |          |                           |           |              |                  |
| 273101                    | ELEVATOR ELECTRIC TRIM TAB ACTUATOR |           |                  |          |                           |           |              | Component ATA:27 |
| PN:50-380124-3            | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.130               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-30-15   |                                     |           |                  |          |                           |           |              |                  |
| 273104                    | ELEVATOR TRIM MAGNETIC CLUTCH       |           |                  |          |                           |           |              | Component ATA:27 |
| PN:50-380125              | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.140               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 27-30-17   |                                     |           |                  |          |                           |           |              |                  |
| 273601                    | STALL WARNING LIFT TRANSDUCER       |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-380005-9           | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:4123                   | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.150               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                     |           |                  |          |                           |           |              |                  |
| 273606                    | STALL WARNING LIFT COMPUTER         |           |                  |          |                           |           |              | Component ATA:27 |
| PN:101-380005-19          | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.150               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                     |           |                  |          |                           |           |              |                  |
| 273611                    | STALL WARNING HORN                  |           |                  |          |                           |           |              | Component ATA:27 |
| PN:169-380021-11          | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.160               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                     |           |                  |          |                           |           |              |                  |
| 273616                    | STALL WARNING TEST SWITCH           |           |                  |          |                           |           |              | Component ATA:27 |
| PN:8811K17                | MOS/MSC                             | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                 | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 27.160               | AFL                                 | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                     |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                     | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                          |           |                  |          |                           |           |             |                  |
| 274116                    | FLAP POSITION TRANSMITTER                |           |                  |          |                           |           |             | Component ATA:27 |
| PN:559-1                  | MOS/MSC                                  | 11-May-22 | O/C              | TSN 0    |                           |           |             |                  |
| SN:1285A                  | HRS                                      | 5340.8    |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.180               | AFL                                      | 6259      |                  | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 27-50-01   |                                          |           |                  |          |                           |           |             |                  |
| 274121                    | FLAP POSITION INDICATOR                  |           |                  |          |                           |           |             | Component ATA:27 |
| PN:101-384029-1           | MOS/MSC                                  | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:5041                   | HRS                                      | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.180               | AFL                                      | 0         |                  |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                          |           |                  |          |                           |           |             |                  |
| 274136                    | FLAP MOTOR RELAY                         |           |                  |          |                           |           |             | Component ATA:27 |
| PN:6046H39A               | MOS/MSC                                  | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                      | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.180               | AFL                                      | 0         |                  |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                          |           |                  |          |                           |           |             |                  |
| 274601                    | LEFT INBOARD FLAP                        |           |                  |          |                           |           |             | Component ATA:27 |
| PN:101-160001-17          | MOS/MSC                                  | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                      | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.190               | AFL                                      | 0         |                  |          |                           |           |             |                  |
| PROC. REF: AMM 27-50-01   |                                          |           |                  |          |                           |           |             |                  |
| 274621                    | LEFT INBOARD FLAP FLEXIBLE SHAFT         |           |                  |          |                           |           |             | Component ATA:27 |
| PN:101-380000-1           | MOS/MSC                                  | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                      | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.250               | AFL                                      | 0         |                  |          |                           |           |             |                  |
| PROC. REF: AMM 27-50-11   |                                          |           |                  |          |                           |           |             |                  |
| 274622                    | INSPECT LEFT INBOARD FLAP FLEXIBLE SHAFT |           |                  |          |                           |           |             | Service ATA:27   |
|                           | MOS                                      | 26-Nov-16 |                  |          |                           |           |             |                  |
|                           | HRS                                      |           |                  |          |                           |           |             |                  |
| WC#: 27.250               | AFL                                      | 4987      | 5000 (+10%/-10%) |          | 9987                      | 10487     | 3437 (+500) |                  |
| 274626                    | LEFT OUTBOARD FLAP                       |           |                  |          |                           |           |             | Component ATA:27 |
| PN:35-165050-216          | MOS/MSC                                  | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                      | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.210               | AFL                                      | 0         |                  |          |                           |           |             |                  |
| PROC. REF: AMM 27-50-01   |                                          |           |                  |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                             | Unit                                                                                                                               | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                            |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 274646                                              | LEFT OUTBOARD FLAP FLEXIBLE SHAFT                                                                                                  |           |                  |          |                           |           |             | Component ATA:27 |
| PN:101-380000-3                                     | MOS/MSC                                                                                                                            | 29-Dec-98 | O/C              |          |                           |           |             |                  |
| SN:UNKNOWN                                          | HRS                                                                                                                                | 0         |                  | TSN 0    |                           |           |             |                  |
| WC#: 27.250                                         | AFL                                                                                                                                | 0         |                  |          |                           |           |             |                  |
| PROC. REF: AMM 27-50-11                             |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 274647                                              | INSPECT LEFT OUTBOARD FLAP FLEXIBLE SHAFT                                                                                          |           |                  |          |                           |           |             | Service ATA:27   |
|                                                     | MOS                                                                                                                                | 26-Nov-16 |                  |          |                           |           |             |                  |
|                                                     | HRS                                                                                                                                |           |                  |          |                           |           |             |                  |
| WC#: 27.250                                         | AFL                                                                                                                                | 4987      | 5000 (+10%/-10%) |          | 9987                      | 10487     | 3437 (+500) |                  |
| 275010                                              | REMOVE LH OUTBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR. |           |                  |          |                           |           |             | Service ATA:27   |
|                                                     | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 180 d (+36) |                  |
|                                                     | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                                                     | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2700 (+300) |                  |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 275015                                              | REMOVE LH INBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR.  |           |                  |          |                           |           |             | Service ATA:27   |
|                                                     | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 180 d (+36) |                  |
|                                                     | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                                                     | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2700 (+300) |                  |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 275020                                              | REMOVE RH INBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR.  |           |                  |          |                           |           |             | Service ATA:27   |
|                                                     | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 180 d (+36) |                  |
|                                                     | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                                                     | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2700 (+300) |                  |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 |                                                                                                                                    |           |                  |          |                           |           |             |                  |
| 275025                                              | REMOVE RH OUTBOARD FLAP AND INSPECT FLAP ATTACH BRACKETS, FLAP STRUCTURE, TRACKS, ROLLER BEARINGS, & ATTACHMENT HARDWARE FOR WEAR. |           |                  |          |                           |           |             | Service ATA:27   |
|                                                     | MOS                                                                                                                                | 24-Mar-22 | 36 (+36d/-36d)   |          | 24-Mar-25                 | 29-Apr-25 | 180 d (+36) |                  |
|                                                     | HRS                                                                                                                                | 5331.5    |                  |          |                           |           |             |                  |
|                                                     | AFL                                                                                                                                | 6250      | 3000 (+10%/-10%) |          | 9250                      | 9550      | 2700 (+300) |                  |
| PROC. REF: AMM 27-50-01, AMM 27-50-01, AMM 27-50-01 |                                                                                                                                    |           |                  |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                               | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                    |           |                   |          |                           |           |              |                  |
| 275101                    | RIGHT INBOARD FLAP                 |           |                   |          |                           |           |              | Component ATA:27 |
| PN:101-160001-20          | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.190               | AFL                                | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-01   |                                    |           |                   |          |                           |           |              |                  |
| 275109                    | FLAP MOTOR                         |           |                   |          |                           |           |              | Component ATA:27 |
| PN:100-384040             | MOS/MSC                            | 05-Feb-08 | O/C               | TSO 3    |                           |           |              |                  |
| SN:4679                   | HRS                                | 2235.7    |                   | TSO 0    |                           |           |              |                  |
| WC#: 27.170               | AFL                                | 2141      |                   | TSO 0    |                           |           |              |                  |
| PROC. REF: AMM 27-50-03   |                                    |           |                   |          |                           |           |              |                  |
| 275110                    | INSPECT/REPLACE FLAP MOTOR         |           |                   |          |                           |           |              | Service ATA:27   |
| PN:PN                     | MOS                                | 29-Dec-98 |                   | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
|                           | AFL                                | 0         | 10000 (+10%/-10%) | TSN 0    | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                    |           |                   |          |                           |           |              |                  |
| 275114                    | FLAP GEARBOX                       |           |                   |          |                           |           |              | Component ATA:27 |
| PN:100-524074-1           | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.170               | AFL                                | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-03   |                                    |           |                   |          |                           |           |              |                  |
| 275115                    | INSPECT/REPLACE FLAP MOTOR GEARBOX |           |                   |          |                           |           |              | Service ATA:27   |
| PN:PN                     | MOS                                | 29-Dec-98 |                   | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
|                           | AFL                                | 0         | 10000 (+10%/-10%) | TSN 0    | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                    |           |                   |          |                           |           |              |                  |
| 275119                    | LEFT OUTBOARD FLAP ACTUATOR        |           |                   |          |                           |           |              | Component ATA:27 |
| PN:129-521051-1           | MOS/MSC                            | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:610-C-98               | HRS                                | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.200               | AFL                                | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-05   |                                    |           |                   |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                  | Unit                                      | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-------------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                           |           |                   |          |                           |           |              |                  |
| 275120                   | INSPECT/REPLACE LH OUTBOARD FLAP ACTUATOR |           |                   |          |                           |           |              | Service ATA:27   |
|                          | MOS                                       | EFF       |                   |          |                           |           |              |                  |
|                          | HRS                                       |           |                   |          |                           |           |              |                  |
|                          | AFL                                       | EFF       | 10000 (+10%/-10%) |          | 10000 *                   | 11000     | 3450 (+1000) |                  |
|                          | PROC. REF: AMM GENERIC 1                  |           |                   |          |                           |           |              |                  |
| 275121                   | RIGHT INBOARD FLAP FLEXIBLE SHAFT         |           |                   |          |                           |           |              | Component ATA:27 |
| PN:101-380000-2          | MOS/MSC                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN               | HRS                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.260              | AFL                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-11                   |           |                   |          |                           |           |              |                  |
| 275122                   | INSPECT RIGHT INBOARD FLAP FLEXIBLE SHAFT |           |                   |          |                           |           |              | Service ATA:27   |
|                          | MOS                                       | 26-Nov-16 |                   |          |                           |           |              |                  |
|                          | HRS                                       |           |                   |          |                           |           |              |                  |
| WC#: 27.260              | AFL                                       | 4987      | 5000 (+10%/-10%)  |          | 9987                      | 10487     | 3437 (+500)  |                  |
| 275124                   | LEFT INBOARD FLAP ACTUATOR                |           |                   |          |                           |           |              | Component ATA:27 |
| PN:101-521016-1          | MOS/MSC                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN               | HRS                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.200              | AFL                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-05                   |           |                   |          |                           |           |              |                  |
| 275125                   | INSPECT/REPLACE LH INBOARD FLAP ACTUATOR  |           |                   |          |                           |           |              | Service ATA:27   |
|                          | MOS                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                          | HRS                                       | 0         |                   |          |                           |           |              |                  |
|                          | AFL                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                 |           |                   |          |                           |           |              |                  |
| 275129                   | RIGHT INBOARD FLAP ACTUATOR               |           |                   |          |                           |           |              | Component ATA:27 |
| PN:101-521016-2          | MOS/MSC                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN               | HRS                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.220              | AFL                                       | 0         |                   |          |                           |           |              |                  |
|                          | PROC. REF: AMM 27-50-05                   |           |                   |          |                           |           |              |                  |
| 275130                   | INSPECT/REPLACE RH INBOARD FLAP ACTUATOR  |           |                   |          |                           |           |              | Service ATA:27   |
|                          | MOS                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                          | HRS                                       | 0         |                   |          |                           |           |              |                  |
|                          | AFL                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                          | PROC. REF: GENERIC NO REF                 |           |                   |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                      | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|-----------------------------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                                           |           |                   |          |                           |           |              |                  |
| 275134                    | RIGHT OUTBOARD FLAP ACTUATOR                              |           |                   |          |                           |           |              | Component ATA:27 |
| PN:129-521051-2           | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:610-J-98               | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.220               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-05   |                                                           |           |                   |          |                           |           |              |                  |
| 275135                    | INSPECT/REPLACE RH OUTBOARD FLAP ACTUATOR                 |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                           | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                           | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275139                    | LEFT OUTBOARD FLAP 90 DEGREE DRIVE                        |           |                   |          |                           |           |              | Component ATA:27 |
| PN:50-380153-1            | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.240               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275140                    | INSPECT/REPLACE LH OUTBOARD FLAP ACTUATOR 90 DEGREE DRIVE |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                           | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                           | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275144                    | LEFT INBOARD FLAP 90 DEGREE DRIVE                         |           |                   |          |                           |           |              | Component ATA:27 |
| PN:50-380153-3            | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.230               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275145                    | INSPECT/REPLACE LH INBOARD FLAP ACTUATOR 90 DEGREE DRIVE  |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                           | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                           | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                      | C/W       | Interval          | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|-----------------------------------------------------------|-----------|-------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS  |                                                           |           |                   |          |                           |           |              |                  |
| 275149                    | RIGHT INBOARD FLAP 90 DEGREE DRIVE                        |           |                   |          |                           |           |              | Component ATA:27 |
| PN:50-380153-2            | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.230               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275150                    | INSPECT/REPLACE RH INBOARD FLAP ACTUATOR 90 DEGREE DRIVE  |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                           | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                           | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275154                    | RIGHT OUTBOARD FLAP 90 DEGREE DRIVE                       |           |                   |          |                           |           |              | Component ATA:27 |
| PN:50-380153-4            | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.240               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275155                    | INSPECT/REPLACE RH OUTBOARD FLAP ACTUATOR 90 DEGREE DRIVE |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 29-Dec-98 |                   |          |                           |           |              |                  |
|                           | HRS                                                       | 0         |                   |          |                           |           |              |                  |
|                           | AFL                                                       | 0         | 10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
| PROC. REF: GENERIC NO REF |                                                           |           |                   |          |                           |           |              |                  |
| 275601                    | RIGHT OUTBOARD FLAP                                       |           |                   |          |                           |           |              | Component ATA:27 |
| PN:35-165050-217          | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.210               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-01   |                                                           |           |                   |          |                           |           |              |                  |
| 275621                    | RIGHT OUTBOARD FLAP FLEXIBLE SHAFT                        |           |                   |          |                           |           |              | Component ATA:27 |
| PN:101-380000-4           | MOS/MSC                                                   | 29-Dec-98 | O/C               |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                       | 0         |                   | TSN 0    |                           |           |              |                  |
| WC#: 27.260               | AFL                                                       | 0         |                   |          |                           |           |              |                  |
| PROC. REF: AMM 27-50-11   |                                                           |           |                   |          |                           |           |              |                  |
| 275622                    | INSPECT RIGHT OUTBOARD FLAP FLEXIBLE SHAFT                |           |                   |          |                           |           |              | Service ATA:27   |
|                           | MOS                                                       | 26-Nov-16 |                   |          |                           |           |              |                  |
|                           | HRS                                                       |           |                   |          |                           |           |              |                  |
| WC#: 27.260               | AFL                                                       | 4987      | 5000 (+10%/-10%)  |          | 9987                      | 10487     | 3437 (+500)  |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                  | Unit                                                                                                                        | C/W       | Interval            | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------|-----------|---------------------|-------------------------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                                                                                                             |           |                     |                         |                           |           |              |                  |
| 276001                   | INSPECT ALL FLIGHT CONTROL PULLEY BRACKETS AND CASTINGS FOR CRACKS CORROSION, WEAR AND ATTACHMENT(PRIORITY AREA INSPECTION) |           |                     |                         |                           |           |              | Service ATA:27   |
|                          | MOS                                                                                                                         | 29-Dec-98 |                     |                         |                           |           |              | MANDATORY        |
|                          | HRS                                                                                                                         |           |                     |                         |                           |           |              |                  |
| WC#: 27.270              | AFL                                                                                                                         | 0         | T:10000 (+10%/-10%) |                         | 10000                     | 11000     | 3450 (+1000) |                  |
| ATA 28 - FUEL            |                                                                                                                             |           |                     |                         |                           |           |              |                  |
| 280101                   | LEFT LEADING EDGE INBOARD FUEL CELL                                                                                         |           |                     |                         |                           |           |              | Component ATA:28 |
| PN:101-381002-11         | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              |                  |
| SN:98-69411              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.010              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-11 |                           |           |              |                  |
| 280106                   | LEFT LEADING EDGE OUTBOARD FUEL CELL                                                                                        |           |                     |                         |                           |           |              | Component ATA:28 |
| PN:002-920013-1          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              |                  |
| SN:98-72552              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.020              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-13 |                           |           |              |                  |
| 280111                   | LEFT AFT INBOARD FUEL CELL                                                                                                  |           |                     |                         |                           |           |              | Component ATA:28 |
| PN:50-389034-17          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              |                  |
| SN:98-71127              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.030              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-17 |                           |           |              |                  |
| 280116                   | LEFT AFT OUTBOARD FUEL CELL                                                                                                 |           |                     |                         |                           |           |              | Component ATA:28 |
| PN:101-381001-7          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              |                  |
| SN:98-67819              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.040              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-15 |                           |           |              |                  |
| 280121                   | LEFT NACELLE FUEL CELL                                                                                                      |           |                     |                         |                           |           |              | Component ATA:28 |
| PN:99-380000-23          | MOS/MSC                                                                                                                     | 29-Dec-98 | O/C                 |                         |                           |           |              |                  |
| SN:98-65366              | HRS                                                                                                                         | 0         |                     | TSN 0                   |                           |           |              |                  |
| WC#: 28.050              | AFL                                                                                                                         | 0         |                     |                         |                           |           |              |                  |
|                          |                                                                                                                             |           |                     | PROC. REF: AMM 28-10-09 |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL           |                                       |           |          |          |                           |           |           |                  |
| 280126                  | LEFT AUXILIARY FUEL CELL              |           |          |          |                           |           |           | Component ATA:28 |
| PN:FFC2179-7            | MOS/MSC                               | 05-Apr-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:CR1290               | HRS                                   | 5338.1    |          | TSN 0    |                           |           |           |                  |
| WC#: 28.060             | AFL                                   | 6256      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-10-19 |                                       |           |          |          |                           |           |           |                  |
| 280131                  | RIGHT LEADING EDGE INBOARD FUEL CELL  |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-381002-12        | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98-69594             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.010             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-11 |                                       |           |          |          |                           |           |           |                  |
| 280136                  | RIGHT LEADING EDGE OUTBOARD FUEL CELL |           |          |          |                           |           |           | Component ATA:28 |
| PN:002-920013-2         | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98-72879             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.020             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-13 |                                       |           |          |          |                           |           |           |                  |
| 280139                  | RIGHT AFT INBOARD FUEL CELL           |           |          |          |                           |           |           | Component ATA:28 |
| PN:50-389034-18         | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98-71485             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.030             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-17 |                                       |           |          |          |                           |           |           |                  |
| 280141                  | RIGHT AFT OUTBOARD FUEL CELL          |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-381001-8         | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98-68027             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.040             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-15 |                                       |           |          |          |                           |           |           |                  |
| 280146                  | RIGHT NACELLE FUEL CELL               |           |          |          |                           |           |           | Component ATA:28 |
| PN:99-380000-25         | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:98-65520             | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.050             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-09 |                                       |           |          |          |                           |           |           |                  |
| 280151                  | RIGHT AUXILIARY FUEL CELL             |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-381001-2         | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.060             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-19 |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                                                                             | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|-------------------------|--------------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 28 - FUEL           |                                                                                                  |           |                  |          |                           |           |               |                  |
| 280601                  | LEFT NACELLE FUEL CELL FLAPPER VALVE                                                             |           |                  |          |                           |           |               | Component ATA:28 |
| PN:24C189               | MOS/MSC                                                                                          | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN              | HRS                                                                                              | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 28.080             | AFL                                                                                              | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-10-09 |                                                                                                  |           |                  |          |                           |           |               |                  |
| 280606                  | LEFT INBOARD LEADING EDGE FUEL CELL DRAIN VALVE                                                  |           |                  |          |                           |           |               | Component ATA:28 |
| PN:CCA3400              | MOS/MSC                                                                                          | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN              | HRS                                                                                              | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 28.090             | AFL                                                                                              | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-10-11 |                                                                                                  |           |                  |          |                           |           |               |                  |
| 280611                  | LEFT WING FUEL DRAIN VALVE                                                                       |           |                  |          |                           |           |               | Component ATA:28 |
| PN:710C4X               | MOS/MSC                                                                                          | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN              | HRS                                                                                              | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 28.100             | AFL                                                                                              | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-10-11 |                                                                                                  |           |                  |          |                           |           |               |                  |
| 281000                  | INSPECT LEFT NACELLE AND AUX FUEL CELLS AND PROBES - INSPECT FOR MICROBIOLOGICAL SLUDGE BUILDUP  |           |                  |          |                           |           |               | Service ATA:28   |
|                         | MOS                                                                                              | 22-May-24 | 30 (+18d/-18d)   |          | 22-Nov-26                 | 10-Dec-26 | 788 d (+18)   |                  |
|                         | HRS                                                                                              | 5686.2    | 2400 (+10%/-10%) |          | 8086.2                    | 8326.2    | 2308.5 (+240) |                  |
|                         | AFL                                                                                              | 6495      |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-40-01 |                                                                                                  |           |                  |          |                           |           |               |                  |
| 281010                  | INSPECT RIGHT NACELLE AND AUX FUEL CELLS AND PROBES - INSPECT FOR MICROBIOLOGICAL SLUDGE BUILDUP |           |                  |          |                           |           |               | Service ATA:28   |
|                         | MOS                                                                                              | 24-Mar-22 | 30 (+18d/-18d)   |          | 24-Sep-24                 | 12-Oct-24 | TOL (+17 d)   |                  |
|                         | HRS                                                                                              | 5331.5    | 2400 (+10%/-10%) |          | 7731.5                    | 7971.5    | 1953.8 (+240) |                  |
|                         | AFL                                                                                              | 6250      |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-40-01 |                                                                                                  |           |                  |          |                           |           |               |                  |
| 281101                  | RIGHT NACELLE FUEL CELL FLAPPER VALVE                                                            |           |                  |          |                           |           |               | Component ATA:28 |
| PN:24C189               | MOS/MSC                                                                                          | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN              | HRS                                                                                              | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 28.080             | AFL                                                                                              | 0         |                  |          |                           |           |               |                  |
| PROC. REF: AMM 28-10-09 |                                                                                                  |           |                  |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                                  |           |          |          |                           |           |           |                  |
| 281106                    | RIGHT INBOARD LEADING EDGE FUEL CELL DRAIN VALVE |           |          |          |                           |           |           | Component ATA:28 |
| PN:CCA3400                | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.090               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-11   |                                                  |           |          |          |                           |           |           |                  |
| 281111                    | RIGHT WING FUEL DRAIN VALVE                      |           |          |          |                           |           |           | Component ATA:28 |
| PN:710C4X                 | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.100               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-11   |                                                  |           |          |          |                           |           |           |                  |
| 281206                    | LEFT WING TIP TANK                               |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.070               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-10-25   |                                                  |           |          |          |                           |           |           |                  |
| 281256                    | RIGHT WING TIP TANK                              |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.070               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-10-25   |                                                  |           |          |          |                           |           |           |                  |
| 281601                    | LEFT AUXILIARY CELL INBOARD PROBE                |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-151         | MOS/MSC                                          | 07-Jul-20 | O/C      | TSR 0    |                           |           |           |                  |
| SN:3448                   | HRS                                              | 5181.7    |          | TSR 0    |                           |           |           |                  |
| WC#: 28.110               | AFL                                              | 6136      |          | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 28-40-07   |                                                  |           |          |          |                           |           |           |                  |
| 281606                    | LEFT AUXILIARY CELL OUTBOARD PROBE               |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-171         | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1527                   | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-07   |                                                  |           |          |          |                           |           |           |                  |
| 281611                    | LEFT INBOARD WING CELL PROBE                     |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-71          | MOS/MSC                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.170               | AFL                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                        |           |          |          |                           |           |           |                  |
| 281616                    | LEFT INBOARD LEADING EDGE CELL PROBE   |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-69          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.150               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-03   |                                        |           |          |          |                           |           |           |                  |
| 281621                    | LEFT OUTBOARD LEADING EDGE CELL PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-81          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.160               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |
| 281626                    | LEFT OUTBOARD WING CELL INBOARD PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-93          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |
| 281631                    | LEFT OUTBOARD WING CELL OUTBOARD PROBE |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-95          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.140               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |
| 281636                    | RIGHT AUXILIARY CELL INBOARD PROBE     |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-83          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.110               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-07   |                                        |           |          |          |                           |           |           |                  |
| 281641                    | RIGHT AUXILIARY CELL OUTBOARD PROBE    |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-171         | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1535                   | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-07   |                                        |           |          |          |                           |           |           |                  |
| 281646                    | RIGHT INBOARD WING CELL PROBE          |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-71          | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.170               | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                         |           |          |          |                           |           |           |                  |
| 281651                    | RIGHT INBOARD LEADING EDGE CELL PROBE   |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-69          | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.150               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-40-03   |                                         |           |          |          |                           |           |           |                  |
| 281656                    | RIGHT OUTBOARD LEADING EDGE CELL PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-81          | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.160               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 281661                    | RIGHT OUTBOARD WING CELL INBOARD PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-93          | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 281666                    | RIGHT OUTBOARD WING CELL OUTBOARD PROBE |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-380006-95          | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.140               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 282101                    | LEFT AUXILIARY FUEL CELL JET PUMP       |           |          |          |                           |           |           | Component ATA:28 |
| PN:99-389005-1            | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:8096                   | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.180               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-05   |                                         |           |          |          |                           |           |           |                  |
| 282106                    | LEFT AUXILIARY FUEL CELL CHECK VALVE    |           |          |          |                           |           |           | Component ATA:28 |
| PN:869A10BB/030/-0        | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.190               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 282111                    | LEFT AUXILIARY FUEL CELL DRAIN VALVE    |           |          |          |                           |           |           | Component ATA:28 |
| PN:CCA4850                | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.200               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                  | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                       |           |          |            |                           |           |           |                  |
| 282116                    | RIGHT AUXILIARY FUEL CELL JET PUMP    |           |          |            |                           |           |           | Component ATA:28 |
| PN:99-389005-1            | MOS/MSC                               | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:8144                   | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.180               | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-05   |                                       |           |          |            |                           |           |           |                  |
| 282121                    | RIGHT AUXILIARY FUEL CELL CHECK VALVE |           |          |            |                           |           |           | Component ATA:28 |
| PN:869A10BB/030/-0        | MOS/MSC                               | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.190               | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |            |                           |           |           |                  |
| 282126                    | RIGHT AUXILIARY FUEL CELL DRAIN VALVE |           |          |            |                           |           |           | Component ATA:28 |
| PN:CCA4850                | MOS/MSC                               | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.200               | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |            |                           |           |           |                  |
| 282131                    | LEFT NACELLE FUEL QUANTITY PROBE      |           |          |            |                           |           |           | Component ATA:28 |
| PN:100-380006-119         | MOS/MSC                               | 07-Jul-20 | O/C      | TSR 0      |                           |           |           |                  |
| SN:105214                 | HRS                                   | 5181.7    |          | TSR 0      |                           |           |           |                  |
| WC#: 28.330               | AFL                                   | 6136      |          | TSR 0      |                           |           |           |                  |
| PROC. REF: AMM 28-40-01   |                                       |           |          |            |                           |           |           |                  |
| 282136                    | RIGHT NACELLE FUEL QUANTITY PROBE     |           |          |            |                           |           |           | Component ATA:28 |
| PN:100-380006-77          | MOS/MSC                               | 21-Oct-09 | O/C      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 2449.4    |          | TSN 2449.4 |                           |           |           |                  |
| WC#: 28.330               | AFL                                   | 2445      |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-40-01   |                                       |           |          |            |                           |           |           |                  |
| 282601                    | LEFT FUEL CONTROL PURGE VALVE         |           |          |            |                           |           |           | Component ATA:28 |
| PN:50-389109-9            | MOS/MSC                               | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:13454                  | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.260               | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-11   |                                       |           |          |            |                           |           |           |                  |
| 282606                    | RIGHT FUEL CONTROL PURGE VALVE        |           |          |            |                           |           |           | Component ATA:28 |
| PN:50-389109-9            | MOS/MSC                               | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:13492                  | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 28.260               | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 28-20-11   |                                       |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                       |           |          |          |                           |           |           |                  |
| 283101                    | LEFT STAND-BY FUEL PUMP               |           |          |          |                           |           |           | Component ATA:28 |
| PN:50-380177-5            | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:8AP177                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.210               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-03   |                                       |           |          |          |                           |           |           |                  |
| 283106                    | RIGHT STAND-BY FUEL PUMP              |           |          |          |                           |           |           | Component ATA:28 |
| PN:50-380177-5            | MOS/MSC                               | 17-Aug-05 | O/C      | TSO 0    |                           |           |           |                  |
| SN:8BA92                  | HRS                                   | 1834.8    |          | TSO 0    |                           |           |           |                  |
| WC#: 28.210               | AFL                                   | 1645      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-03   |                                       |           |          |          |                           |           |           |                  |
| 283111                    | FUEL CROSSFEED VALVE                  |           |          |          |                           |           |           | Component ATA:28 |
| PN:50-389095              | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:T27047                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.270               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| 283601                    | LEFT FUEL PRESSURE SWITCH             |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-389018-23          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:10855                  | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.220               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| 283606                    | LEFT AUXILIARY FUEL CELL FLOAT SWITCH |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-389034-7           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.230               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| 283611                    | LEFT MOTIVE FLOW PRESSURE SWITCH      |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-389004-3           | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:9089                   | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.240               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-13   |                                       |           |          |          |                           |           |           |                  |
| 283616                    | RIGHT FUEL PRESSURE SWITCH            |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-389018-23          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:10898                  | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.220               | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                   | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                        |           |          |                   |                           |           |           |                  |
| 283621                    | RIGHT AUXILIARY FUEL CELL FLOAT SWITCH |           |          |                   |                           |           |           | Component ATA:28 |
| PN:101-389034-7           | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.230               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 283626                    | RIGHT MOTIVE FLOW PRESSURE SWITCH      |           |          |                   |                           |           |           | Component ATA:28 |
| PN:101-389004-3           | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:9082                   | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.240               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-20-13   |                                        |           |          |                   |                           |           |           |                  |
| 284005                    | LEFT FUEL FLOW INDICATOR               |           |          |                   |                           |           |           | Component ATA:28 |
| PN:90-380037-1            | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:521061                 | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.340               | AFL                                    | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 284010                    | RIGHT FUEL FLOW INDICATOR              |           |          |                   |                           |           |           | Component ATA:28 |
| PN:90-380037-1            | MOS/MSC                                | 07-Feb-20 | O/C      | TSR 0             |                           |           |           |                  |
| SN:520004                 | HRS                                    | 5159.5    |          | TSN 5159.5, TSR 0 |                           |           |           |                  |
| WC#: 28.340               | AFL                                    | 6110      |          | TSN 6110, TSR 0   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 284101                    | LEFT WING FUEL VENT FLOAT VALVE        |           |          |                   |                           |           |           | Component ATA:28 |
| PN:100-920048-19          | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.290               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-10-31   |                                        |           |          |                   |                           |           |           |                  |
| 284106                    | RIGHT WING FUEL VENT FLOAT VALVE       |           |          |                   |                           |           |           | Component ATA:28 |
| PN:100-920048-20          | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.290               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-10-31   |                                        |           |          |                   |                           |           |           |                  |
| 284116                    | LEFT FIREWALL FUEL SHUTOFF VALVE       |           |          |                   |                           |           |           | Component ATA:28 |
| PN:101-389025-5           | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:2324                   | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 28.280               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 28-20-07   |                                        |           |          |                   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                   |           |          |          |                           |           |           |                  |
| 284121                    | RIGHT FIREWALL FUEL SHUTOFF VALVE |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-389025-5           | MOS/MSC                           | 22-May-24 | O/C      | TSO 0    |                           |           |           |                  |
| SN:23-051                 | HRS                               | 5686.2    |          | TSO 0    |                           |           |           |                  |
| WC#: 28.280               | AFL                               | 6495      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-07   |                                   |           |          |          |                           |           |           |                  |
| 284126                    | LEFT TRANSFER MOTIVE FLOW VALVE   |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-389020-1           | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:80331767               | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.250               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-13   |                                   |           |          |          |                           |           |           |                  |
| 284131                    | RIGHT TRANSFER MOTIVE FLOW VALVE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:100-389020-1           | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:60503159               | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.250               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-13   |                                   |           |          |          |                           |           |           |                  |
| 284601                    | LEFT WING FUEL HEATED VENT        |           |          |          |                           |           |           | Component ATA:28 |
| PN:112633                 | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.300               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-29   |                                   |           |          |          |                           |           |           |                  |
| 284606                    | RIGHT WING FUEL HEATED VENT       |           |          |          |                           |           |           | Component ATA:28 |
| PN:112633                 | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.300               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-29   |                                   |           |          |          |                           |           |           |                  |
| 284623                    | LEFT FUEL QUANTITY INDICATOR      |           |          |          |                           |           |           | Component ATA:28 |
| PN:101-380006-47          | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.310               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |                  |
| 284626                    | RIGHT FUEL QUANTITY INDICATOR     |           |          |          |                           |           |           | Component ATA:28 |
| PN:117-384019-3           | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:9836-1675              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.310               | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                    |                                          |           |          |          |                           |           |           |                  |
| 284631                           | TIP TANK FUEL QUANTITY GAUGE             |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.310                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-40-09          |                                          |           |          |          |                           |           |           |                  |
| 284636                           | LEFT TIP TANK FUEL QUANTITY TRANSMITTER  |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.320                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-40-09          |                                          |           |          |          |                           |           |           |                  |
| 284646                           | RIGHT TIP TANK FUEL QUANTITY TRANSMITTER |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.320                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-40-09          |                                          |           |          |          |                           |           |           |                  |
| 572210                           | LEFT HAND LEADING EDGE CAP               |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.350                      | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1         |                                          |           |          |          |                           |           |           |                  |
| 572211                           | RH LEADING EDGE CAP ASSEM REPLACE        |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                            | MOS/MSC                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                  | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                          |           |          |          |                           |           |           |                  |
| ATA 30 - ICE AND RAIN PROTECTION |                                          |           |          |          |                           |           |           |                  |
| 300101                           | LEFT BLEED AIR PRESSURE SHUTOFF VALVE    |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-380013-13                 | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.010                      | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 36-10-03          |                                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                        |           |          |          |                           |           |           |                  |
| 300106                           | RIGHT BLEED AIR PRESSURE SHUTOFF VALVE |           |          |          |                           |           |           | Component ATA:30 |
| PN:3206310013-13                 | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.010                      | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 36-10-03          |                                        |           |          |          |                           |           |           |                  |
| 300111                           | LEFT BLEED AIR PRESSURE CHECK VALVE    |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-381000-9                  | MOS/MSC                                | 14-Apr-05 | O/C      | TSO 0    |                           |           |           |                  |
| SN:2425A                         | HRS                                    | 1744.9    |          | TSO 0    |                           |           |           |                  |
| WC#: 30.020                      | AFL                                    | 1501      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                        |           |          |          |                           |           |           |                  |
| 300116                           | RIGHT BLEED AIR PRESSURE CHECK VALVE   |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-381000-9                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:12554                         | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.020                      | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                        |           |          |          |                           |           |           |                  |
| 300121                           | DE-ICER DISTRIBUTION VALVE             |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-384144-3                  | MOS/MSC                                | 23-Aug-05 | O/C      | TSO 1    |                           |           |           |                  |
| SN:B1940                         | HRS                                    | 1838.7    |          | TSO 0    |                           |           |           |                  |
| WC#: 30.030                      | AFL                                    | 1654      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                        |           |          |          |                           |           |           |                  |
| 300126                           | DE-ICE DIFFERENTIAL PRESSURE SWITCH    |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-360035-7                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.030                      | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                        |           |          |          |                           |           |           |                  |
| 300131                           | DE-ICE EJECTOR                         |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-384149-1                  | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:9AP110                        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.030                      | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                        |           |          |          |                           |           |           |                  |
| 300601                           | LEFT HORIZONTAL STABILIZER DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:SMR5041-05                    | MOS/MSC                                | 13-Feb-19 | O/C      | TSN 4    |                           |           |           |                  |
| SN:3016                          | HRS                                    | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.040                      | AFL                                    | 6044      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                         |           |          |          |                           |           |           |                  |
| 300606                           | RIGHT HORIZONTAL STABILIZER DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:SMR5041-5                     | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 13   |                           |           |           |                  |
| SN:2911                          | HRS                                     | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.040                      | AFL                                     | 6044      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                         |           |          |          |                           |           |           |                  |
| 300611                           | LEFT WING CENTER SECTION DE-ICE BOOT    |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-380001-25                 | MOS/MSC                                 | 12-Apr-23 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 5500.3    |          |          |                           |           |           |                  |
| WC#: 30.050                      | AFL                                     | 6358      |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                         |           |          |          |                           |           |           |                  |
| 300616                           | LEFT OUTBOARD WING DE-ICE BOOT          |           |          |          |                           |           |           | Component ATA:30 |
| PN:SMR5041-01                    | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:2262                          | HRS                                     | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.060                      | AFL                                     | 6044      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                         |           |          |          |                           |           |           |                  |
| 300621                           | RIGHT WING CENTER SECTION DE-ICE BOOT   |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-380001-25                 | MOS/MSC                                 | 12-Apr-23 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 5500.3    |          |          |                           |           |           |                  |
| WC#: 30.050                      | AFL                                     | 6358      |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                         |           |          |          |                           |           |           |                  |
| 300626                           | RIGHT OUTBOARD WING DE-ICE BOOT         |           |          |          |                           |           |           | Component ATA:30 |
| PN:SMR5041-02                    | MOS/MSC                                 | 13-Feb-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:2442                          | HRS                                     | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.060                      | AFL                                     | 6044      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-10-01          |                                         |           |          |          |                           |           |           |                  |
| 300631                           | DE-ICE PRESSURE GAUGE                   |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-380105-1                   | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:F98230                        | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.070                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 301015                           | LEFT PNEUMATIC VALVE                    |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-381011-11                 | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11228                         | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 36.030                      | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                       |           |          |          |                           |           |           |                  |
| 301020                           | RIGHT PNEUMATIC VALVE                 |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-381011-11                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11248                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 36.030                      | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |           |                  |
| 301101                           | LEFT INERTIAL VANE ACTUATOR           |           |          |          |                           |           |           | Component ATA:30 |
| PN:114-389039-23                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1981F                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.090                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-20-13          |                                       |           |          |          |                           |           |           |                  |
| 301106                           | RIGHT INERTIAL VANE ACTUATOR          |           |          |          |                           |           |           | Component ATA:30 |
| PN:114-389039-23                 | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1947F                         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.090                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-20-13          |                                       |           |          |          |                           |           |           |                  |
| 301601                           | WINDSHIELD HEAT CONTROLLER            |           |          |          |                           |           |           | Component ATA:30 |
| PN:100-364295-3                  | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.100                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |           |                  |
| 302101                           | LEFT WINDSHIELD WIPER BLADE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-384082-1                   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.110                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |           |                  |
| 302106                           | RIGHT WINDSHIELD WIPER BLADE ASSEMBLY |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-384082-1                   | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.110                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |           |                  |
| 302111                           | LEFT WINDSHIELD WIPER ARM ASSEMBLY    |           |          |          |                           |           |           | Component ATA:30 |
| PN:99-384026                     | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.120                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-40-03          |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                     |           |          |          |                           |           |           |                  |
| 302116                           | RIGHT WINDSHIELD WIPER ARM ASSEMBLY |           |          |          |                           |           |           | Component ATA:30 |
| PN:99-384026                     | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.120                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-40-03          |                                     |           |          |          |                           |           |           |                  |
| 302121                           | LEFT WINDSHIELD WIPER CONVERTER     |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-380070-3                   | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-40-03          |                                     |           |          |          |                           |           |           |                  |
| 302126                           | RIGHT WINDSHIELD WIPER CONVERTER    |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-380070-4                   | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-40-03          |                                     |           |          |          |                           |           |           |                  |
| 302131                           | WINDSHIELD WIPER MOTOR              |           |          |          |                           |           |           | Component ATA:30 |
| PN:101-384165-1                  | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:01372                         | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.130                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-40-01          |                                     |           |          |          |                           |           |           |                  |
| 302136                           | FLEXIBLE DRIVE ASSEMBLY             |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-384083-5                   | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.140                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                     |           |          |          |                           |           |           |                  |
| 302141                           | CENTER FLEXIBLE DRIVE ASSEMBLY      |           |          |          |                           |           |           | Component ATA:30 |
| PN:50-384083-7                   | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.140                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                     |           |          |          |                           |           |           |                  |
| 302601                           | PROPELLER DE-ICE AMMETER            |           |          |          |                           |           |           | Component ATA:30 |
| PN:90-380007-13                  | MOS/MSC                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:759                           | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.150                      | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                         |           |          |          |                           |           |           |                  |
| 302606                           | PROPELLER DE-ICE TIMER ASSEMBLY         |           |          |          |                           |           |           | Component ATA:30 |
| PN:B-45018                       | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:980043                        | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.160                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302611                           | NO. 1 PROPELLER DE-ICE BRUSH BLOCK      |           |          |          |                           |           |           | Component ATA:30 |
| PN:3E2090-1                      | MOS/MSC                                 | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:N3002135                      | HRS                                     | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.170                      | AFL                                     | 6358      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302616                           | NO. 2 PROPELLER DE-ICE BRUSH BLOCK      |           |          |          |                           |           |           | Component ATA:30 |
| PN:3E2090-1                      | MOS/MSC                                 | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:N3002139                      | HRS                                     | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.170                      | AFL                                     | 6358      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302636                           | NO. 1 PROP DE-ICE MANUAL OVERRIDE RELAY |           |          |          |                           |           |           | Component ATA:30 |
| PN:KCJ2A                         | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.180                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302641                           | NO. 2 PROP DE-ICE MANUAL OVERRIDE RELAY |           |          |          |                           |           |           | Component ATA:30 |
| PN:KCJ2A                         | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.180                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302646                           | NO. 1 PROP DE-ICE SLIP RING ASSEMBLY    |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1555-2                      | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.190                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |
| 302651                           | NO. 2 PROP DE-ICE SLIP RING ASSEMBLY    |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1555-3                      | MOS/MSC                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.190                      | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                             |           |          |          |                           |           |           |                  |
| 302656                           | NO. 1 PROP NO.1 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302657                           | NO. 1 PROP NO.2 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302658                           | NO. 1 PROP NO.3 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.200                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302659                           | NO. 1 PROP NO.4 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.220                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302661                           | NO. 2 PROP NO.1 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302662                           | NO. 2 PROP NO.2 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |
| 302663                           | NO. 2 PROP NO.3 DE-ICE BOOT |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                      | MOS/MSC                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.210                      | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION      |                                  |           |          |          |                           |           |           |                  |
| 302664                                | NO. 2 PROP NO.4 DE-ICE BOOT      |           |          |          |                           |           |           | Component ATA:30 |
| PN:4E1188-5                           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.220                           | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                  |           |          |          |                           |           |           |                  |
| 310005                                | ROSEMONT O.A.T. PROBE            |           |          |          |                           |           |           | Component ATA:31 |
| PN:0129F                              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:A20994                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.060                           | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |
| 310101                                | PILOT CLOCK                      |           |          |          |                           |           |           | Component ATA:31 |
| PN:6420093-1                          | MOS/MSC                          | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19-11196                          | HRS                              | 5104.4    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.010                           | AFL                              | 6064      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |
| 310106                                | COPILOT CLOCK                    |           |          |          |                           |           |           | Component ATA:31 |
| PN:101-384092-1                       | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:840428                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.010                           | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |
| 310111                                | FLIGHT HOURMETER                 |           |          |          |                           |           |           | Component ATA:31 |
| PN:101-3292-0001                      | MOS/MSC                          | 13-Feb-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                              | 5082.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.020                           | AFL                              | 6044      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |
| 310116                                | FLIGHT HOURMETER PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:31 |
| PN:M4006                              | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.020                           | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS  |                                             |           |          |          |                           |           |           |                  |
| 311000                                 | CABIN ALTITUDE WARNING PRESSURE SWITCH      |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                  | MOS/MSC                                     | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                             | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                                        | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1, AMM 21-11-30 |                                             |           |          |          |                           |           |           |                  |
| 311005                                 | STALL LIFT COMPUTER                         |           |          |          |                           |           |           | Component ATA:31 |
| PN:101-380005-41                       | MOS/MSC                                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:3189                                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.030                            | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF              |                                             |           |          |          |                           |           |           |                  |
| 311010                                 | FLIGHT CONTROL PANEL                        |           |          |          |                           |           |           | Component ATA:31 |
| PN:622-5798-008                        | MOS/MSC                                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4781                                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.040                            | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF              |                                             |           |          |          |                           |           |           |                  |
| 311020                                 | RIGHT ATTITUDE GYRO                         |           |          |          |                           |           |           | Component ATA:31 |
| PN:1U149-001-6                         | MOS/MSC                                     | 10-Nov-06 | O/C      |          |                           |           |           |                  |
| SN:T75919P                             | HRS                                         | 2076.4    |          |          |                           |           |           |                  |
| WC#: 31.070                            | AFL                                         |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF              |                                             |           |          |          |                           |           |           |                  |
| 314000 <sup>U</sup>                    | GARMIN GCU 485 MODE CONTROLLER              |           |          |          |                           |           |           | Component ATA:31 |
| PN:011-03582-02                        | MOS/MSC                                     | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:3QR20045                            | HRS                                         | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                        | AFL                                         | 6064      |          | TSN 0    |                           |           |           |                  |
| 314001                                 | NO. 1 IN/OUT CONCENTRATOR, IOC-3100 REPLACE |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                  | MOS/MSC                                     | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                             | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                                        | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-40-05                |                                             |           |          |          |                           |           |           |                  |
| 314002                                 | NO. 2 IN/OUT CONCENTRATOR, IOC-3100 REPLACE |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                  | MOS/MSC                                     | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                             | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                                        | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-40-05                |                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                              |           |          |          |                           |           |           |                  |
| 314004                                | NO. 1 OCM-3100 OPTION CONTROL MODULE REPLACE |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1              |                                              |           |          |          |                           |           |           |                  |
| 314005                                | NO. 2 OCM-3100 OPTION CONTROL MODULE REPLACE |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1              |                                              |           |          |          |                           |           |           |                  |
| 315000 <sup>U</sup>                   | MAP 65 MODE ANNUNCIATOR                      |           |          |          |                           |           |           | Component ATA:31 |
| PN:622-5799-001                       | MOS/MSC                                      | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:805                                | HRS                                          | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 6064      |          | TSN 0    |                           |           |           |                  |
| ATA 32 - LANDING GEAR                 |                                              |           |          |          |                           |           |           |                  |
| 301080                                | LH BRAKE DEICE VALVE                         |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1              |                                              |           |          |          |                           |           |           |                  |
| 301085                                | RH BRAKE DEICE VALVE                         |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                 | MOS/MSC                                      | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1              |                                              |           |          |          |                           |           |           |                  |
| 320141                                | UP LIMIT SWITCH                              |           |          |          |                           |           |           | Component ATA:32 |
| PN:BZ2RQ181A2                         | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.040                           | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                              |           |          |          |                           |           |           |                  |
| 320146                                | DOWN LIMIT SWITCH                            |           |          |          |                           |           |           | Component ATA:32 |
| PN:BZ2RQ181A2                         | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.040                           | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                      | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|-------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                                           |           |                  |          |                           |           |              |                  |
| 320601                                | LEFT MAIN LANDING GEAR                                                                    |           |                  |          |                           |           |              | Component ATA:32 |
| PN:101-810171-601                     | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:647-A-98                           | HRS                                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.070                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-03               |                                                                                           |           |                  |          |                           |           |              |                  |
| 320602                                | INSPECT LEFT MAIN LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                                       | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.395                           | AFL                                                                                       | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 7945 (+800)  |                  |
| 320605                                | INSPECT LEFT MAIN LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES            |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                                       | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.395                           | AFL                                                                                       | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 7945 (+800)  |                  |
| 320631                                | LEFT MAIN LANDING GEAR ACTUATOR                                                           |           |                  |          |                           |           |              | Component ATA:32 |
| PN:99-810057-604                      | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                       | 0         |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-30-03               |                                                                                           |           |                  |          |                           |           |              |                  |
| 320641                                | INSPECT LEFT MAIN LANDING GEAR ACTUATOR CLEVIS HOLE                                       |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                                       | 22-May-24 |                  |          |                           |           |              |                  |
|                                       | HRS                                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                                       | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 945 (+100)   |                  |
| 320657                                | LEFT MAIN LANDING GEAR ACTUATOR SUPPORT BEARINGS                                          |           |                  |          |                           |           |              | Component ATA:32 |
| PN:115-380102                         | MOS/MSC                                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.080                           | AFL                                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                                                                           |           |                  |          |                           |           |              |                  |
| 320660                                | LEFT MAIN LANDING GEAR DRAG BRACE ASSEMBLY                                                |           |                  |          |                           |           |              | Component ATA:32 |
| PN:PN                                 | MOS/MSC                                                                                   | 29-Dec-98 | O/C              | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
|                                       | AFL                                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                           |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                       | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|--------------------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                                            |           |                  |          |                           |           |              |                  |
| 320661                                | LEFT UPPER R/H DRAG BRACE                                                                  |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-810337-9                        | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.110                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                            |           |                  |          |                           |           |              |                  |
| 320666                                | RIGHT UPPER R/H DRAG BRACE                                                                 |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-810337-10                       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.110                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                            |           |                  |          |                           |           |              |                  |
| 320671                                | LEFT LOWER DRAG BRACE                                                                      |           |                  |          |                           |           |              | Component ATA:32 |
| PN:101-810035-1                       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.130                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                            |           |                  |          |                           |           |              |                  |
| 320681                                | LEFT MAIN LANDING GEAR UP POSITION INDICATOR SWITCH                                        |           |                  |          |                           |           |              | Component ATA:32 |
| PN:100-381006-1                       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.180                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                            |           |                  |          |                           |           |              |                  |
| 320691                                | LEFT MAIN LANDING GEAR DOWN POSITION INDICATOR SWITCH                                      |           |                  |          |                           |           |              | Component ATA:32 |
| PN:100-381006-1                       | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.190                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                            |           |                  |          |                           |           |              |                  |
| 321101                                | RIGHT MAIN LANDING GEAR                                                                    |           |                  |          |                           |           |              | Component ATA:32 |
| PN:101-810171-601                     | MOS/MSC                                                                                    | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:647-B-98                           | HRS                                                                                        | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.070                           | AFL                                                                                        | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-03               |                                                                                            |           |                  |          |                           |           |              |                  |
| 321102                                | INSPECT RIGHT MAIN LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                                        | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                                       | HRS                                                                                        | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.400                           | AFL                                                                                        | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 7945 (+800)  |                  |
| PROC. REF: AMM 32-10-01               |                                                                                            |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                            | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|---------------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                                 |           |                  |          |                           |           |              |                  |
| 321105                                | INSPECT RIGHT MAIN LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                             | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                                       | HRS                                                                             | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.400                           | AFL                                                                             | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 7945 (+800)  |                  |
| 321131                                | RIGHT MAIN LANDING GEAR ACTUATOR                                                |           |                  |          |                           |           |              | Component ATA:32 |
| PN:99-810057-603                      | MOS/MSC                                                                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                             | 0         |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-30-03               |                                                                                 |           |                  |          |                           |           |              |                  |
| 321141                                | INSPECT RIGHT MAIN LANDING GEAR ACTUATOR CLEVIS HOLE                            |           |                  |          |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                             | 22-May-24 |                  |          |                           |           |              |                  |
|                                       | HRS                                                                             | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.100                           | AFL                                                                             | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 945 (+100)   |                  |
| 321157                                | RIGHT MAIN LANDING GEAR ACTUATOR SUPPORT BEARINGS                               |           |                  |          |                           |           |              | Component ATA:32 |
| PN:115-380102                         | MOS/MSC                                                                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.080                           | AFL                                                                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                                                                 |           |                  |          |                           |           |              |                  |
| 321160                                | RIGHT MAIN LANDING GEAR DRAG BRACE ASSEMBLY                                     |           |                  |          |                           |           |              | Component ATA:32 |
| PN:PN                                 | MOS/MSC                                                                         | 29-Dec-98 | O/C              | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                             | 0         |                  | TSN 0    |                           |           |              |                  |
|                                       | AFL                                                                             | 0         |                  | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                 |           |                  |          |                           |           |              |                  |
| 321161                                | LEFT UPPER L/H DRAG BRACE                                                       |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-810337-9                        | MOS/MSC                                                                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.120                           | AFL                                                                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                 |           |                  |          |                           |           |              |                  |
| 321166                                | RIGHT UPPER L/H DRAG BRACE                                                      |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-810337-10                       | MOS/MSC                                                                         | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                             | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.120                           | AFL                                                                             | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                 |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                 | C/W       | Interval         | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|--------------------------------------------------------------------------------------|-----------|------------------|------------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                                      |           |                  |            |                           |           |              |                  |
| 321171                                | RIGHT LOWER DRAG BRACE                                                               |           |                  |            |                           |           |              | Component ATA:32 |
| PN:50-810335-1                        | MOS/MSC                                                                              | 29-Dec-98 | O/C              |            |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| WC#: 32.130                           | AFL                                                                                  | 0         |                  |            |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                      |           |                  |            |                           |           |              |                  |
| 321181                                | RIGHT MAIN LANDING GEAR UP POSITION INDICATOR SWITCH                                 |           |                  |            |                           |           |              | Component ATA:32 |
| PN:100-381006-1                       | MOS/MSC                                                                              | 29-Dec-98 | O/C              |            |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| WC#: 32.180                           | AFL                                                                                  | 0         |                  |            |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                      |           |                  |            |                           |           |              |                  |
| 321191                                | RIGHT MAIN LANDING GEAR DOWN POSITION INDICATOR SWITCH                               |           |                  |            |                           |           |              | Component ATA:32 |
| PN:100-381006-1                       | MOS/MSC                                                                              | 29-Dec-98 | O/C              |            |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| WC#: 32.190                           | AFL                                                                                  | 0         |                  |            |                           |           |              |                  |
| PROC. REF: AMM 32-10-07, AMM 32-11-01 |                                                                                      |           |                  |            |                           |           |              |                  |
| 321601                                | LEFT LANDING GEAR SAFETY SWITCH                                                      |           |                  |            |                           |           |              | Component ATA:32 |
| PN:MC815AS1                           | MOS/MSC                                                                              | 29-Dec-98 | O/C              |            |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| WC#: 32.190                           | AFL                                                                                  | 0         |                  |            |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                                                                      |           |                  |            |                           |           |              |                  |
| 321610                                | L/H MLG SAFETY SWITCH                                                                |           |                  |            |                           |           |              | Component ATA:32 |
| PN:PN                                 | MOS/MSC                                                                              | 29-Dec-98 | O/C              | TSN 0      |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| WC#: 32.490                           | AFL                                                                                  | 0         |                  | TSN 0      |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                                                                      |           |                  |            |                           |           |              |                  |
| 322101                                | NOSE LANDING GEAR                                                                    |           |                  |            |                           |           |              | Component ATA:32 |
| PN:101-820020-15                      | MOS/MSC                                                                              | 07-Aug-12 | O/C              |            |                           |           |              |                  |
| SN:643-A-98                           | HRS                                                                                  | 2825.9    |                  | TSN 2825.9 |                           |           |              |                  |
| WC#: 32.140                           | AFL                                                                                  | 2944      |                  |            |                           |           |              |                  |
| PROC. REF: AMM 32-20-05               |                                                                                      |           |                  |            |                           |           |              |                  |
| 322102                                | INSPECT NOSE LANDING GEAR SHOCK ABSORBER, DRAG BRACE, AXLE AND TORQUE KNEES ASSEMBLY |           |                  |            |                           |           |              | Service ATA:32   |
|                                       | MOS                                                                                  | 22-May-24 | 72 (+60d/-60d)   |            | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                                       | HRS                                                                                  | 5686.2    |                  |            |                           |           |              |                  |
| WC#: 32.405                           | AFL                                                                                  | 6495      | 8000 (+10%/-10%) |            | 14495                     | 15295     | 7945 (+800)  |                  |
| PROC. REF: AMM 32-20-01               |                                                                                      |           |                  |            |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                      | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|---------------------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR     |                                                                           |           |                  |          |                           |           |              |                  |
| 322105                    | INSPECT NOSE LANDING GEAR TRUNNION BOLT HOLES AND DRAG BRACE ATTACH HOLES |           |                  |          |                           |           |              | Service ATA:32   |
|                           | MOS                                                                       | 22-May-24 | 72 (+60d/-60d)   |          | 22-May-30                 | 21-Jul-30 | 2065 d (+60) |                  |
|                           | HRS                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.405               | AFL                                                                       | 6495      | 8000 (+10%/-10%) |          | 14495                     | 15295     | 7945 (+800)  |                  |
| 322151                    | NOSE LANDING GEAR ACTUATOR                                                |           |                  |          |                           |           |              | Component ATA:32 |
| PN:112-380022-21          | MOS/MSC                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                                       | 0         |                  |          |                           |           |              |                  |
| WC#: 32.150               | AFL                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-30-07   |                                                                           |           |                  |          |                           |           |              |                  |
| 322161                    | INSPECT NOSE LANDING GEAR ACTUATOR CLEVIS HOLE                            |           |                  |          |                           |           |              | Service ATA:32   |
|                           | MOS                                                                       | 22-May-24 |                  |          |                           |           |              |                  |
|                           | HRS                                                                       | 5686.2    |                  |          |                           |           |              |                  |
| WC#: 32.150               | AFL                                                                       | 6495      | 1000 (+10%/-10%) |          | 7495                      | 7595      | 945 (+100)   |                  |
| 322165                    | NOSE LANDING GEAR ACTUATOR SUPPORT BEARINGS                               |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-380043              | MOS/MSC                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.080               | AFL                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                                           |           |                  |          |                           |           |              |                  |
| 322171                    | NOSE LANDING GEAR UPPER DRAG LEG                                          |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-820205-17           | MOS/MSC                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.170               | AFL                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: AMM 32-20-09   |                                                                           |           |                  |          |                           |           |              |                  |
| 322176                    | NOSE LANDING GEAR LEFT LOWER DRAG LEG                                     |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-820205-23           | MOS/MSC                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.170               | AFL                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                                           |           |                  |          |                           |           |              |                  |
| 322181                    | NOSE LANDING GEAR RIGHT LOWER DRAG LEG                                    |           |                  |          |                           |           |              | Component ATA:32 |
| PN:50-820205-23           | MOS/MSC                                                                   | 29-Dec-98 | O/C              |          |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                                                       | 0         |                  | TSN 0    |                           |           |              |                  |
| WC#: 32.170               | AFL                                                                       | 0         |                  |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                                                           |           |                  |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                   | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR     |                                        |           |          |                   |                           |           |           |                  |
| 322186                    | NOSE LANDING GEAR UP POSITION SWITCH   |           |          |                   |                           |           |           | Component ATA:32 |
| PN:1CH25                  | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.200               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 322191                    | NOSE LANDING GEAR DOWN POSITION SWITCH |           |          |                   |                           |           |           | Component ATA:32 |
| PN:1CH25                  | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.200               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 322611                    | NOSE LANDING GEAR SHIMMY DAMPER        |           |          |                   |                           |           |           | Component ATA:32 |
| PN:50-820004-1            | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.210               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: AMM 32-20-03   |                                        |           |          |                   |                           |           |           |                  |
| 322621                    | NOSE LANDING GEAR STEERING LINK        |           |          |                   |                           |           |           | Component ATA:32 |
| PN:50-820034-3            | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.220               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |
| 322641                    | NOSE WHEEL                             |           |          |                   |                           |           |           | Component ATA:32 |
| PN:3-1481                 | MOS/MSC                                | 22-May-24 | O/C      | TSO 0             |                           |           |           |                  |
| SN:4507                   | HRS                                    | 5686.2    |          | TSN 5686.2, TSO 0 |                           |           |           |                  |
| WC#: 32.240               | AFL                                    | 6495      |          | TSN 6495, TSO 0   |                           |           |           |                  |
| PROC. REF: AMM 32-40-19   |                                        |           |          |                   |                           |           |           |                  |
| 322643                    | NOSE TIRE                              |           |          |                   |                           |           |           | Component ATA:32 |
| PN:265K08-1               | MOS/MSC                                | 22-May-24 | O/C      | TSN 13            |                           |           |           |                  |
| SN:12790094               | HRS                                    | 5686.2    |          | TSN 185.9         |                           |           |           |                  |
| WC#: 32.240               | AFL                                    | 6495      |          | TSN 137           |                           |           |           |                  |
| PROC. REF: AMM 32-40-19   |                                        |           |          |                   |                           |           |           |                  |
| 322651                    | LANDING GEAR WARNING HORN              |           |          |                   |                           |           |           | Component ATA:32 |
| PN:169-380021-9           | MOS/MSC                                | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 32.230               | AFL                                    | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |                   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                 |                                      |           |          |          |                           |           |           |                  |
| 323005                                | LANDING GEAR HANDLE                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-384137-7                       | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1689A                              | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.430                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                      |           |          |          |                           |           |           |                  |
| 323010                                | POWER PACK SENSOR                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:99-388007-3                        | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1931A                              | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.440                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-19, AMM 32-31-01 |                                      |           |          |          |                           |           |           |                  |
| 323015                                | LANDING GEAR HYDRAULIC SERVICE VALVE |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-388008-3                       | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2729                               | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.450                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                      |           |          |          |                           |           |           |                  |
| 323030                                | EMERGENCY EXTENSION HAND PUMP        |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-388007-3                       | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2739                               | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.460                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                      |           |          |          |                           |           |           |                  |
| 323101                                | HYDRAULIC BRAKE RESERVOIR            |           |          |          |                           |           |           | Component ATA:32 |
| PN:50-580039                          | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.290                           | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                      |           |          |          |                           |           |           |                  |
| 323166                                | LEFT PARKING BRAKE VALVE             |           |          |          |                           |           |           | Component ATA:32 |
| PN:4500S-A1                           | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300                           | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-13               |                                      |           |          |          |                           |           |           |                  |
| 323176                                | RIGHT PARKING BRAKE VALVE            |           |          |          |                           |           |           | Component ATA:32 |
| PN:4500S-A1                           | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300                           | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-13               |                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                  |           |          |          |                           |           |           |                  |
| 323186                                | LEFT BRAKE SHUTTLE VALVE                                         |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-580000-13                      | MOS/MSC                                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.310                           | AFL                                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                  |           |          |          |                           |           |           |                  |
| 323191                                | RIGHT BRAKE SHUTTLE VALVE                                        |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-580000-13                      | MOS/MSC                                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.310                           | AFL                                                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                  |           |          |          |                           |           |           |                  |
| 323601                                | LEFT OUTBOARD (NO. 1) BRAKE                                      |           |          |          |                           |           |           | Component ATA:32 |
| PN:30-146                             | MOS/MSC                                                          | 07-Jun-24 | O/C      | TSO 0    |                           |           |           |                  |
| SN:2842                               | HRS                                                              |           |          | TSO 0    |                           |           |           |                  |
| WC#: 32.340                           | AFL                                                              |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-15, AMM 32-40-17 |                                                                  |           |          |          |                           |           |           |                  |
| 323603                                | REPLACE LEFT LEFT BRAKE HOSES (ONLY HOSES EXPOSED IN WHEEL WELL) |           |          |          |                           |           |           | Service ATA:32   |
|                                       | MOS                                                              | 26-Jul-22 | 60       |          | 26-Jul-27                 |           | 1034 d    |                  |
|                                       | HRS                                                              | 5351.6    |          |          |                           |           |           |                  |
| WC#: 32.090                           | AFL                                                              | 6269      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                  |           |          |          |                           |           |           |                  |
| 323606                                | LEFT INBOARD (NO. 2) BRAKE                                       |           |          |          |                           |           |           | Component ATA:32 |
| PN:30-146                             | MOS/MSC                                                          | 07-Jun-24 | O/C      | TSO 0    |                           |           |           |                  |
| SN:2144                               | HRS                                                              |           |          | TSO 0    |                           |           |           |                  |
| WC#: 32.340                           | AFL                                                              |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-15, AMM 32-40-17 |                                                                  |           |          |          |                           |           |           |                  |
| 323611                                | LEFT OUTBOARD MAIN WHEEL                                         |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN-UNKNOWN                         | MOS/MSC                                                          | 10-Aug-23 | O/C      |          |                           |           |           |                  |
| SN:1388                               | HRS                                                              | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.250                           | AFL                                                              | 6398      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                  |           |          |          |                           |           |           |                  |
| 323613                                | LEFT OUTBOARD MAIN TIRE                                          |           |          |          |                           |           |           | Component ATA:32 |
| PN:196K08-9                           | MOS/MSC                                                          | 10-Aug-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:30540288                           | HRS                                                              | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.250                           | AFL                                                              | 6398      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                 |                                                                    |           |          |          |                           |           |           |                  |
| 323626                                | LEFT INBOARD MAIN WHEEL                                            |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN-UNKNOWN                         | MOS/MSC                                                            | 10-Aug-23 | O/C      |          |                           |           |           |                  |
| SN:6094                               | HRS                                                                | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.260                           | AFL                                                                | 6398      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                    |           |          |          |                           |           |           |                  |
| 323629                                | LEFT INBOARD MAIN TIRE                                             |           |          |          |                           |           |           | Component ATA:32 |
| PN:196K08-9                           | MOS/MSC                                                            | 10-Aug-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:30140268                           | HRS                                                                | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.260                           | AFL                                                                | 6398      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                    |           |          |          |                           |           |           |                  |
| 323641                                | RIGHT INBOARD (NO. 3) BRAKE                                        |           |          |          |                           |           |           | Component ATA:32 |
| PN:30-146                             | MOS/MSC                                                            | 07-Jun-24 | O/C      | TSO 0    |                           |           |           |                  |
| SN:534                                | HRS                                                                |           |          | TSO 0    |                           |           |           |                  |
| WC#: 32.350                           | AFL                                                                |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-15, AMM 32-40-17 |                                                                    |           |          |          |                           |           |           |                  |
| 323643                                | REPLACE RIGHT RIGHT BRAKE HOSES (ONLY HOSES EXPOSED IN WHEEL WELL) |           |          |          |                           |           |           | Service ATA:32   |
|                                       | MOS                                                                | 26-Jul-22 | 60       |          | 26-Jul-27                 |           | 1034 d    |                  |
|                                       | HRS                                                                | 5351.6    |          |          |                           |           |           |                  |
| WC#: 32.090                           | AFL                                                                | 6269      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                    |           |          |          |                           |           |           |                  |
| 323646                                | RIGHT OUTBOARD (NO. 4) BRAKE                                       |           |          |          |                           |           |           | Component ATA:32 |
| PN:30-146                             | MOS/MSC                                                            | 07-Jun-24 | O/C      | TSO 0    |                           |           |           |                  |
| SN:535                                | HRS                                                                |           |          | TSO 0    |                           |           |           |                  |
| WC#: 32.350                           | AFL                                                                |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-15, AMM 32-40-17 |                                                                    |           |          |          |                           |           |           |                  |
| 323651                                | RIGHT INBOARD MAIN WHEEL                                           |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN-UNKNOWN                         | MOS/MSC                                                            | 10-Aug-23 | O/C      |          |                           |           |           |                  |
| SN:2234-1                             | HRS                                                                | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.270                           | AFL                                                                | 6398      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                    |           |          |          |                           |           |           |                  |
| 323653                                | RIGHT INBOARD MAIN TIRE                                            |           |          |          |                           |           |           | Component ATA:32 |
| PN:196K08-9                           | MOS/MSC                                                            | 10-Aug-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:30140295                           | HRS                                                                | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.270                           | AFL                                                                | 6398      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                 |                                   |           |          |          |                           |           |           |                  |
| 323666                                | RIGHT OUTBOARD MAIN WHEEL         |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN-UNKNOWN                         | MOS/MSC                           | 10-Aug-23 | O/C      |          |                           |           |           |                  |
| SN:3534                               | HRS                               | 5578.7    |          |          |                           |           |           |                  |
| WC#: 32.280                           | AFL                               | 6398      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                   |           |          |          |                           |           |           |                  |
| 323669                                | RIGHT OUTBOARD MAIN TIRE          |           |          |          |                           |           |           | Component ATA:32 |
| PN:196K08-9                           | MOS/MSC                           | 10-Aug-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:30540275                           | HRS                               | 5578.7    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.280                           | AFL                               | 6398      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-25, AMM 32-40-27 |                                   |           |          |          |                           |           |           |                  |
| 324005                                | PILOT LEFT BRAKE CYLINDER         |           |          |          |                           |           |           | Component ATA:32 |
| PN:90-380001-33                       | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.470                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-11               |                                   |           |          |          |                           |           |           |                  |
| 324010                                | PILOT RIGHT BRAKE CYLINDER        |           |          |          |                           |           |           | Component ATA:32 |
| PN:90-380001-33                       | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.470                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-11               |                                   |           |          |          |                           |           |           |                  |
| 324015                                | COPILOT LEFT BRAKE CYLINDER       |           |          |          |                           |           |           | Component ATA:32 |
| PN:90-380001-33                       | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.480                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-11               |                                   |           |          |          |                           |           |           |                  |
| 324020                                | COPILOT RIGHT BRAKE CYLINDER      |           |          |          |                           |           |           | Component ATA:32 |
| PN:90-380001-33                       | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.480                           | AFL                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-11               |                                   |           |          |          |                           |           |           |                  |
| 324101                                | LANDING GEAR HYDRAULIC POWER PACK |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-388005-21                      | MOS/MSC                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:MX604894                           | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.360                           | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-31-01               |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                 |                                                         |           |          |          |                           |           |           |                  |
| 324103                                | REPLACE LANDING GEAR HYDRAULIC POWER PACK SYSTEM FILTER |           |          |          |                           |           |           | Service ATA:32   |
|                                       | MOS                                                     | 12-Apr-23 |          |          |                           |           |           | SCRAP            |
|                                       | HRS                                                     | 5500.3    | 1200     |          | 6700.3                    |           | 922.6     |                  |
| WC#: 32.360                           | AFL                                                     | 6358      | 1000     |          | 7358                      |           | 808       |                  |
| PROC. REF: AMM 32-31-09, AMM 32-31-11 |                                                         |           |          |          |                           |           |           |                  |
| 324111                                | LANDING GEAR HYDRAULIC ACCUMULATOR                      |           |          |          |                           |           |           | Component ATA:32 |
| PN:101-388009-5                       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2679                               | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.370                           | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-31-21               |                                                         |           |          |          |                           |           |           |                  |
| 324121                                | REPLACE LANDING GEAR RETRACTION/EXTENSION HOSES         |           |          |          |                           |           |           | Service ATA:32   |
|                                       | MOS                                                     | 13-Feb-19 | 120      |          | 13-Feb-29                 |           | 1602 d    | SCRAP            |
|                                       | HRS                                                     | 5082.9    |          |          |                           |           |           |                  |
| WC#: 32.390                           | AFL                                                     | 6044      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                         |           |          |          |                           |           |           |                  |
| ATA 33 - LIGHTS                       |                                                         |           |          |          |                           |           |           |                  |
| 330101                                | TAIL STROBE LIGHT                                       |           |          |          |                           |           |           | Component ATA:33 |
| PN:101-360020-3                       | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010                           | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                         |           |          |          |                           |           |           |                  |
| 330106                                | LEFT WING STROBE LIGHT                                  |           |          |          |                           |           |           | Component ATA:33 |
| PN:70-1148-7-2                        | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010                           | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                         |           |          |          |                           |           |           |                  |
| 330111                                | RIGHT WING STROBE LIGHT                                 |           |          |          |                           |           |           | Component ATA:33 |
| PN:70-1148-7-2                        | MOS/MSC                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.010                           | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS           |                                      |           |          |          |                           |           |           |                  |
| 330116                    | STROBE LIGHT POWER SUPPLY            |           |          |          |                           |           |           | Component ATA:33 |
| PN:60-1750-3              | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.020               | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                      |           |          |          |                           |           |           |                  |
| 330200                    | LH WING TIP RECOGNITION LIGHT CHANGE |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                      |           |          |          |                           |           |           |                  |
| 330201                    | RH WING TIP RECOGNITION LIGHT CHANGE |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                      |           |          |          |                           |           |           |                  |
| 330202                    | NAV LIGHT CHANGE                     |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                              | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                      |           |          |          |                           |           |           |                  |
| 330301                    | UPPER ANTI-COLLISION LIGHT           |           |          |          |                           |           |           | Component ATA:33 |
| PN:101-360020-3           | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.030               | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                      |           |          |          |                           |           |           |                  |
| 330306                    | LOWER ANTI-COLLISION LIGHT           |           |          |          |                           |           |           | Component ATA:33 |
| PN:90033-4                | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2119387                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.030               | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                      |           |          |          |                           |           |           |                  |
| 330601                    | LEFT LANDING LIGHT                   |           |          |          |                           |           |           | Component ATA:33 |
| PN:AN-3176-1              | MOS/MSC                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.040               | AFL                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                       | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS           |                                                            |           |          |            |                           |           |           |                  |
| 330606                    | RIGHT LANDING LIGHT                                        |           |          |            |                           |           |           | Component ATA:33 |
| PN:AN-3176-1              | MOS/MSC                                                    | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 33.040               | AFL                                                        | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |            |                           |           |           |                  |
| 330611                    | TAXI LIGHT                                                 |           |          |            |                           |           |           | Component ATA:33 |
| PN:B4150B                 | MOS/MSC                                                    | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 33.040               | AFL                                                        | 0         |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |            |                           |           |           |                  |
| 330615                    | CHECK EDGELIGHTED PANELS FOR CONDITION                     |           |          |            |                           |           |           | Service ATA:33   |
|                           | MOS/MSC                                                    | 14-Dec-18 | N/A      |            |                           |           |           |                  |
|                           | HRS                                                        | 5079.9    |          |            |                           |           |           |                  |
| WC#: 33.050               | AFL                                                        | 6043      |          |            |                           |           |           |                  |
| PROC. REF: AMM 33-10-01   |                                                            |           |          |            |                           |           |           |                  |
| 332001 <sup>U</sup>       | INSPECT EMERGENCY EXIT SIGN (SELF-ILLUMINATING)            |           |          |            |                           |           |           | Service ATA:33   |
| PN:PN                     | MOS                                                        | 22-May-24 | 12       |            | 22-May-25                 |           | 239 d     |                  |
| SN:UNKNOWN                | HRS                                                        | 5686.2    |          |            |                           |           |           |                  |
| WC#: 33.080               | AFL                                                        | 6495      |          |            |                           |           |           |                  |
| 334005                    | POWER PACK                                                 |           |          |            |                           |           |           | Component ATA:33 |
| PN:100-384118-21          | MOS/MSC                                                    | 29-Dec-98 | O/C      |            |                           |           |           |                  |
| SN:HTS-03072              | HRS                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 33.060               | AFL                                                        | 0         |          | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |            |                           |           |           |                  |
| 335000                    | REPLACE RIGHT HAND EMERGENCY EXIT SIGN (SELF-ILLUMINATING) |           |          |            |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                                    |           | A/R      |            |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        |           |          |            |                           |           |           |                  |
|                           | AFL                                                        |           |          |            |                           |           |           |                  |
| PROC. REF: AMM 33-50-01   |                                                            |           |          |            |                           |           |           |                  |
| 335001 <sup>U</sup>       | REPLACE EMERGENCY EXIT SIGN (SELF-ILLUMINATING)            |           |          |            |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                                    | 07-Feb-20 | A/R      | TSN 254    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 5159.5    |          | TSN 5159.5 |                           |           |           |                  |
|                           | AFL                                                        | 6110      |          | TSN 6110   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS           |                                                                       |           |          |          |                           |           |           |                  |
| 335002                    | INSPECT RIGHT HAND EMERGENCY EXIT SIGN (SELF-ILLUMINATING)            |           |          |          |                           |           |           | Service ATA:33   |
| PN:PN                     | MOS                                                                   | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
| SN:UNKNOWN                | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 33-50-01   |                                                                       |           |          |          |                           |           |           |                  |
| ATA 34 - NAVIGATION       |                                                                       |           |          |          |                           |           |           |                  |
| 340002 <sup>U</sup>       | GARMIN G600 TXI SYSTEM INSTALLATION IAW STC SA02571SE                 |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                               | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                   | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                   | 6064      |          | TSN 0    |                           |           |           |                  |
| 340002.1 <sup>U</sup>     | GARMIN G600TXI ICA DOCUMENTS                                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                               | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                   | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                   | 6064      |          | TSN 0    |                           |           |           |                  |
| 340004 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - 12 MO INSPECTIONS                |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                   | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| 340005 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - RVSM CHECKS                      |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                   | 22-May-24 | 24       |          | 31-May-26                 |           | 613 d     |                  |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |
| 340006                    | NO. 1 DUAL NAVIGATION MARKER BEACON COUPLER                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:101-380042             | MOS/MSC                                                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:24115                  | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.440               | AFL                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 340007 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - AHRS MAGNETIC FIELD MODEL UPDATE |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                   | 22-May-24 | 60       |          | 31-May-29                 |           | 1709 d    |                  |
|                           | HRS                                                                   | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                   | 6495      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                                                                                                  |           |          |          |                           |           |           |                  |
| 340008 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE ICA - ELECTRICAL BONDING CHECK                                                                      |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                                                                              | 05-Sep-19 | 120      |          | 30-Sep-29                 |           | 1831 d    |                  |
|                           | HRS                                                                                                                              | 5104.4    | 2000     |          | 7104.4                    |           | 1326.7    |                  |
|                           | AFL                                                                                                                              | 6064      |          |          |                           |           |           |                  |
| 340009 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - GDU 1060 COOLING FAN REPLACEMENT (3000 FAN OPERATING HOURS - READ FAN HRS BEFORE COMPLYING) |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                                                                              | 05-Sep-19 |          |          |                           |           |           |                  |
|                           | HRS                                                                                                                              | 5104.4    | 3000     |          | 8104.4                    |           | 2326.7    |                  |
|                           | AFL                                                                                                                              | 6064      |          |          |                           |           |           |                  |
| 340011 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - GBB54 BATTERY BACKUP CHECK                                                                  |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                                                                              | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                                                                              | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                                                                              | 6495      |          |          |                           |           |           |                  |
| 340012 <sup>U</sup>       | EQUIPMENT REMOVAL & REPLACEMENT - G600 TXI SYSTEM                                                                                |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                                                                          | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                                                              | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                                                                              | 6064      |          | TSN 0    |                           |           |           |                  |
| 340013 <sup>U</sup>       | GARMIN G600 TXI STC SA02571SE - ICA - EIS ANNUNCIATOR LAMP CHECK                                                                 |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                                                                              | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                                                                              | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                                                                              | 6495      |          |          |                           |           |           |                  |
| 340014 <sup>U</sup>       | GARMIN G600TXI STC SA02571SE - ICA - POST LIGHTNING STRIKE INSPECTION (AFTER A SUSPECTED OR ACTUAL STRIKE)                       |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS/MSC                                                                                                                          | 05-Sep-19 | A/R      |          |                           |           |           |                  |
|                           | HRS                                                                                                                              | 5104.4    |          |          |                           |           |           |                  |
|                           | AFL                                                                                                                              | 6064      |          |          |                           |           |           |                  |
| 340015                    | NO. 2 DUAL NAVIGATION MARKER BEACON COUPLER                                                                                      |           |          |          |                           |           |           | Component ATA:34 |
| PN:101-380042             | MOS/MSC                                                                                                                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:24212                  | HRS                                                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.440               | AFL                                                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                          |           |          |          |                           |           |           |                  |
| 340020                    | GLIDESLOPE COUPLER                                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:101-380043             | MOS/MSC                                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:13759                  | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.470               | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                          |           |          |          |                           |           |           |                  |
| 340035                    | NAVIGATION MANAGEMENT UNIT                               |           |          |          |                           |           |           | Component ATA:34 |
| PN:1013-42-001            | MOS/MSC                                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.570               | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                          |           |          |          |                           |           |           |                  |
| 340037 <sup>U</sup>       | # 1 - GARMIN GTN 750 GPS/NAV/COM                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-02282-00           | MOS/MSC                                                  | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1ZA025843              | HRS                                                      | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                      | 6064      |          | TSN 0    |                           |           |           |                  |
| 340038 <sup>U</sup>       | #2 - GARMIN GTN 750 GPS/NAV/COM                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-02282-00           | MOS/MSC                                                  | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1ZA025861              | HRS                                                      | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                      | 6064      |          | TSN 0    |                           |           |           |                  |
| 340039 <sup>U</sup>       | GARMIN GTN 6XX/7XX ICA DOCUMENTS                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                  | 05-Sep-19 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                      | 5104.4    |          |          |                           |           |           |                  |
|                           | AFL                                                      | 6064      |          |          |                           |           |           |                  |
| 340040                    | CCP-3000 CURSOR CONTROL PANEL (IFIS) REPLACE             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                  | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-07   |                                                          |           |          |          |                           |           |           |                  |
| 340041 <sup>U</sup>       | GARMIN GTN 750 STC SA02019SE-D - ICA - VISUAL INSPECTION |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                      | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                      | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                      | 6495      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                               |           |          |          |                           |           |           |                  |
| 340042 <sup>U</sup>       | GARMIN GTN750 STC SA02019SE-D - ICA - ELECTRICAL BONDING TEST |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                           | 05-Sep-19 | 120      |          | 30-Sep-29                 |           | 1831 d    |                  |
|                           | HRS                                                           | 5104.4    | 2000     |          | 7104.4                    |           | 1326.7    |                  |
|                           | AFL                                                           | 6064      |          |          |                           |           |           |                  |
| 340043 <sup>U</sup>       | GARMIN GTN 750 STC SA02019SE-D - ICA - LIGHTNING DAMAGE CHECK |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS/MSC                                                       | 05-Sep-19 | A/R      |          |                           |           |           |                  |
|                           | HRS                                                           | 5104.4    |          |          |                           |           |           |                  |
|                           | AFL                                                           | 6064      |          |          |                           |           |           |                  |
| 340060                    | NO. 1 FLUX DETECTOR (FDU-3000) UNIT                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                       | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-05   |                                                               |           |          |          |                           |           |           |                  |
| 340061                    | NO. 2 FLUX DETECTOR (FDU-3000) UNIT                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                       | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-05   |                                                               |           |          |          |                           |           |           |                  |
| 340062                    | NO. 1 ELECTRONIC FLIGHT INSTRUMENT                            |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                       | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                                               |           |          |          |                           |           |           |                  |
| 340063                    | NO. 2 ELECTRONIC FLIGHT INSTRUMENT                            |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                       | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                                               |           |          |          |                           |           |           |                  |
| 340101                    | LEFT PITOT TUBE                                               |           |          |          |                           |           |           | Component ATA:34 |
| PN:50-384040-3            | MOS/MSC                                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.010               | AFL                                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                                                           | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                               |                                        |           |          |          |                           |           |           |                  |
| 340106                                                                            | RIGHT PITOT TUBE                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:50-384040-5                                                                    | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                                        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.010                                                                       | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                         |                                        |           |          |          |                           |           |           |                  |
| 340131                                                                            | EMERGENCY STATIC DISTRIBUTION VALVE    |           |          |          |                           |           |           | Component ATA:34 |
| PN:K-4566-3                                                                       | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                                        | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.020                                                                       | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                         |                                        |           |          |          |                           |           |           |                  |
| 340141                                                                            | LEAK CHECK PILOT PITOT/STATIC SYSTEM   |           |          |          |                           |           |           | Service ATA:34   |
|                                                                                   | MOS                                    | 10-Jun-24 | 24       |          | 10-Jun-26                 |           | 623 d     | MANDATORY        |
|                                                                                   | HRS                                    | 5686.2    |          |          |                           |           |           |                  |
| WC#: 34.030                                                                       | AFL                                    | 6495      |          |          |                           |           |           |                  |
| Test Date: : 10-Jun-24 PROC. REF: AMM 34-00-09, AMM 34-00-05, FAR FAR PART 91.411 |                                        |           |          |          |                           |           |           |                  |
| 340142                                                                            | LEAK CHECK COPILOT PITOT/STATIC SYSTEM |           |          |          |                           |           |           | Service ATA:34   |
|                                                                                   | MOS                                    | 10-Jun-24 | 24       |          | 10-Jun-26                 |           | 623 d     | MANDATORY        |
|                                                                                   | HRS                                    | 5686.2    |          |          |                           |           |           |                  |
| WC#: 34.030                                                                       | AFL                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-00-09, AMM 34-00-05, FAR FAR PART 91.411                        |                                        |           |          |          |                           |           |           |                  |
| 341005                                                                            | AIR DATA MODULE                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-8692-014                                                                   | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1418                                                                           | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.500                                                                       | AFL                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                         |                                        |           |          |          |                           |           |           |                  |
| 341007                                                                            | AIR DATA COUPLER                       |           |          |          |                           |           |           | Component ATA:34 |
|                                                                                   | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
|                                                                                   | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.045                                                                       | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                         |                                        |           |          |          |                           |           |           |                  |
| 341008                                                                            | AIR DATA CONTROL                       |           |          |          |                           |           |           | Component ATA:34 |
|                                                                                   | MOS/MSC                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
|                                                                                   | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.075                                                                       | AFL                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                         |                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                              | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                   |           |          |           |                           |           |           |                  |
| 341009 <sup>U</sup>       | ADC 600 AIR DATA CONVERTER        |           |          |           |                           |           |           | Component ATA:34 |
| PN:99100003               | MOS/MSC                           | 05-Sep-19 | O/C      | TSN 0     |                           |           |           |                  |
| SN:280                    | HRS                               | 5104.4    |          | TSN 0     |                           |           |           |                  |
|                           | AFL                               | 6064      |          | TSN 0     |                           |           |           |                  |
| 341015                    | AIR DATA SENSOR                   |           |          |           |                           |           |           | Component ATA:34 |
| PN:622-5797-001           | MOS/MSC                           | 20-Oct-23 | O/C      | TSO 0     |                           |           |           |                  |
| SN:3VCF                   | HRS                               | 5610.6    |          | TSO 0     |                           |           |           |                  |
| WC#: 34.065               | AFL                               | 6428      |          | TSO 0     |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |           |                           |           |           |                  |
| 341136                    | STAND-BY COMPASS                  |           |          |           |                           |           |           | Component ATA:34 |
| PN:50-534453-15           | MOS/MSC                           | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.150               | AFL                               | 0         |          |           |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                   |           |          |           |                           |           |           |                  |
| 341151                    | OUTSIDE AIR TEMPERATURE INDICATOR |           |          |           |                           |           |           | Component ATA:34 |
| PN:50-384077-1            | MOS/MSC                           | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.160               | AFL                               | 0         |          |           |                           |           |           |                  |
| PROC. REF: AMM 34-00-11   |                                   |           |          |           |                           |           |           |                  |
| 341611                    | NO. 1 VHF/NAV ANTENNA             |           |          |           |                           |           |           | Component ATA:34 |
| PN:100-384125-3           | MOS/MSC                           | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:5186                   | HRS                               | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 34.200               | AFL                               | 0         |          |           |                           |           |           |                  |
| PROC. REF: AMM 34-30-03   |                                   |           |          |           |                           |           |           |                  |
| 341616                    | NO. 1 AIR DATA COMPUTER           |           |          |           |                           |           |           | Component ATA:34 |
| PN:011-03457-*50          | MOS/MSC                           | 08-Oct-21 | O/C      |           |                           |           |           |                  |
| SN:5BF001009              | HRS                               | 5280.3    |          |           |                           |           |           |                  |
| WC#: 34.015               | AFL                               | 6215      |          |           |                           |           |           |                  |
| PROC. REF: AMM 34-11-03   |                                   |           |          |           |                           |           |           |                  |
| 341617                    | NO. 2 AIR DATA COMPUTER           |           |          |           |                           |           |           | Component ATA:34 |
| PN:011-03457-50           | MOS/MSC                           | 08-Oct-21 | O/C      | TSN 25    |                           |           |           |                  |
| SN:5BF000773              | HRS                               | 5280.3    |          | TSN 175.9 |                           |           |           |                  |
| WC#: 34.025               | AFL                               | 6215      |          | TSN 150   |                           |           |           |                  |
| PROC. REF: AMM 34-11-03   |                                   |           |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN               | Unit                                        | C/W                    | Interval | TSX/Adj.                       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|---------------------------------------------|------------------------|----------|--------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION   |                                             |                        |          |                                |                           |           |           |                  |
| 341618                | TEST NO. 1 AIR DATA COMPUTER                |                        |          |                                |                           |           |           | Service ATA:34   |
| PN:011-03457-*50      | MOS                                         | 10-Jun-24              | 24       |                                | 10-Jun-26                 |           | 623 d     | MANDATORY        |
| SN:5BF001009          | HRS                                         | 5686.2                 |          |                                |                           |           |           |                  |
| WC#: 34.015           | AFL                                         | 6495                   |          |                                |                           |           |           |                  |
|                       |                                             | Test Date: : 10-Jun-24 |          | PROC. REF: FAR FAR PART 91.411 |                           |           |           |                  |
| 341618.1 <sup>U</sup> | L-3 COMMUNICATIONS ESI-500 - ICA DOCUMENTS  |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:PN                 | MOS/MSC                                     | 05-Sep-19              | O/C      |                                |                           |           |           |                  |
| SN:UNKNOWN            | HRS                                         | 5104.4                 |          |                                |                           |           |           |                  |
|                       | AFL                                         | 6064                   |          |                                |                           |           |           |                  |
| 341619                | TEST NO. 2 AIR DATA COMPUTER                |                        |          |                                |                           |           |           | Service ATA:34   |
| PN:011-03457-50       | MOS                                         | 10-Jun-24              | 24       |                                | 10-Jun-26                 |           | 623 d     |                  |
| SN:5BF000773          | HRS                                         | 5686.2                 |          |                                |                           |           |           |                  |
| WC#: 34.025           | AFL                                         | 6495                   |          |                                |                           |           |           |                  |
|                       |                                             | Test Date: : 10-Jun-24 |          | PROC. REF: FAR FAR PART 91.411 |                           |           |           |                  |
| 341631                | NO. 2 VHF/NAV ANTENNA                       |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:100-384125-3       | MOS/MSC                                     | 29-Dec-98              | O/C      |                                |                           |           |           |                  |
| SN:5187               | HRS                                         | 0                      |          | TSN 0                          |                           |           |           |                  |
| WC#: 34.200           | AFL                                         | 0                      |          |                                |                           |           |           |                  |
|                       |                                             |                        |          | PROC. REF: AMM 34-30-03        |                           |           |           |                  |
| 341635 <sup>U</sup>   | GDU-1060 DISPLAY - PILOT                    |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:011-03308-70       | MOS/MSC                                     | 05-Sep-19              | O/C      | TSN 0                          |                           |           |           |                  |
| SN:3M5001936          | HRS                                         | 5104.4                 |          | TSN 0                          |                           |           |           |                  |
|                       | AFL                                         | 6064                   |          | TSN 0                          |                           |           |           |                  |
| 341636 <sup>U</sup>   | GDU-1060 DISPLAY - COPILOT                  |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:011-03308-70       | MOS/MSC                                     | 05-Sep-19              | O/C      | TSN 0                          |                           |           |           |                  |
| SN:3M5001771          | HRS                                         | 5104.4                 |          | TSN 0                          |                           |           |           |                  |
|                       | AFL                                         | 6064                   |          | TSN 0                          |                           |           |           |                  |
| 341638 <sup>U</sup>   | L-3 ELECTRONIC STANDBY INSTRUMENT (ESI-500) |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:9200-15000-0101    | MOS/MSC                                     | 05-Sep-19              | O/C      | TSN 0                          |                           |           |           |                  |
| SN:2278               | HRS                                         | 5104.4                 |          | TSN 0                          |                           |           |           |                  |
|                       | AFL                                         | 6064                   |          | TSN 0                          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                 |           |          |          |                           |           |           |                  |
| 341638.1 <sup>U</sup>     | L-3 ESI-500 INTERNAL LITHIUM ION BATTERY        |           |          |          |                           |           |           | Component ATA:34 |
| PN:9230-15003-01          | MOS/MSC                                         | 16-May-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:N/A                    | HRS                                             | 5522.7    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                             |           |          | TSN 0    |                           |           |           |                  |
| 341639 <sup>U</sup>       | TEST L-3 ESI-500 PRESSURE SYSTEM & ALTIMETER    |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                             | 10-Jun-24 | 24       |          | 30-Jun-26                 |           | 643 d     |                  |
|                           | HRS                                             | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                             | 6495      |          |          |                           |           |           |                  |
| 341640 <sup>U</sup>       | ESI-500 SYSTEM INSTALLATION VISUAL INSPECTION   |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                             | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                             | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                             | 6495      |          |          |                           |           |           |                  |
| 341648 <sup>U</sup>       | ESI-500 INTERNAL BATTERY CALIBRATION            |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                             | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                             | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                             | 6495      |          |          |                           |           |           |                  |
| 341649 <sup>U</sup>       | ESI-500 ACCURACY CHECK OF REAL TIME CLOCK (RTC) |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                             | 22-May-24 | 24       |          | 31-May-26                 |           | 613 d     |                  |
|                           | HRS                                             | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                             | 6495      |          |          |                           |           |           |                  |
| 341651                    | NO. 1 ADF LOOP ANTENNA                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:137A4                  | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.230               | AFL                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 341652                    | NO. 2 ADF LOOP ANTENNA                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:137A4                  | MOS/MSC                                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.230               | AFL                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                         |           |          |          |                           |           |           |                  |
| 341656                    | NO. 1 ADF SENSE ANTENNA |           |          |          |                           |           |           | Component ATA:34 |
| PN:ANT-60A (101-340422)   | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.240               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 341657                    | NO. 2 ADF SENSE ANTENNA |           |          |          |                           |           |           | Component ATA:34 |
| PN:ANT-60A (101-340422)   | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.240               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 341681                    | DME ANTENNA             |           |          |          |                           |           |           | Component ATA:34 |
| PN:100-384129             | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:10845                  | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.290               | AFL                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-53-03   |                         |           |          |          |                           |           |           |                  |
| 342005                    | SLIP/SKID SENSOR        |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-6019-001           | MOS/MSC                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:1964                   | HRS                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.480               | AFL                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                         |           |          |          |                           |           |           |                  |
| 342013                    | STANDBY POWER SUPPLY    |           |          |          |                           |           |           | Component ATA:34 |
| PN:501-1228-04            | MOS/MSC                 | 19-Sep-19 | O/C      |          |                           |           |           |                  |
| SN:10140                  | HRS                     | 5104.4    |          |          |                           |           |           |                  |
| WC#: 34.100               | AFL                     | 6064      |          |          |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                         |           |          |          |                           |           |           |                  |
| 342050 <sup>U</sup>       | GMU-44 MAGNOMETER #1    |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-00870-10           | MOS/MSC                 | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1CM029345              | HRS                     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                     | 6064      |          | TSN 0    |                           |           |           |                  |
| 342051 <sup>U</sup>       | GMU-44 MAGNETOMETER #2  |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-00870-10           | MOS/MSC                 | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1CM018424              | HRS                     | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                     | 6064      |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                                    |           |          |          |                           |           |           |                  |
| 342101                    | RADAR INDICATOR                                                    |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-5941-001           | MOS/MSC                                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.260               | AFL                                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 342103                    | RADAR RECEIVER/TRANSMITTER                                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:RT-1201A               | MOS/MSC                                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.260               | AFL                                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-40-01   |                                                                    |           |          |          |                           |           |           |                  |
| 342104 <sup>U</sup>       | GARMIN GDL69A STC SA01487SE - ICA - VISUAL INSPECTION              |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                | 6495      |          |          |                           |           |           |                  |
| 342105 <sup>U</sup>       | GARMIN GDL69A STC SA01487SE - ICA - AUDIO SUPPRESSION VERIFICATION |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                | 22-May-24 | 12       |          | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                | 5686.2    |          |          |                           |           |           |                  |
|                           | AFL                                                                | 6495      |          |          |                           |           |           |                  |
| 342106 <sup>U</sup>       | GARMIN GDL69A STC SA01487SE - ICA - ELECTRICAL BONDING CHECK       |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                                | 05-Sep-19 | 120      |          | 30-Sep-29                 |           | 1831 d    |                  |
|                           | HRS                                                                | 5104.4    | 2000     |          | 7104.4                    |           | 1326.7    |                  |
|                           | AFL                                                                | 6064      |          |          |                           |           |           |                  |
| 342109                    | RADAR WAVE GUIDE                                                   |           |          |          |                           |           |           | Component ATA:34 |
| PN:90A11N-7200            | MOS/MSC                                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.270               | AFL                                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 342112 <sup>U</sup>       | GDL-69A XM DATALINK                                                |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-03177-10           | MOS/MSC                                                            | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:3NV004194              | HRS                                                                | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                | 6064      |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                       | C/W       | Interval                                     | TSX/Adj.     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------|-----------|----------------------------------------------|--------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                            |           |                                              |              |                           |           |           |                  |
| 342112.1 <sup>U</sup>     | GARMIN GDL69A - ICA DOCUMENTS              |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                    | 05-Sep-19 | O/C                                          |              |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                        | 5104.4    |                                              |              |                           |           |           |                  |
|                           | AFL                                        | 6064      |                                              |              |                           |           |           |                  |
| 342113 <sup>U</sup>       | GWX-75 PROCESSOR                           |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:011-03997-00           | MOS/MSC                                    | 05-Sep-19 | O/C                                          | TSN 0        |                           |           |           |                  |
| SN:4RR000946              | HRS                                        | 5104.4    |                                              | TSN 0        |                           |           |           |                  |
|                           | AFL                                        | 6064      |                                              | TSN 0        |                           |           |           |                  |
| 342115 <sup>U</sup>       | FLIGHT STREAM 510                          |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:010-01322-01           | MOS/MSC                                    | 28-Apr-20 | O/C                                          | TSN 7, TSR 5 |                           |           |           |                  |
| SN:402008814              | HRS                                        | 5167.4    |                                              | TSR 5167.4   |                           |           |           |                  |
|                           | AFL                                        | 6123      |                                              | TSR 6123     |                           |           |           |                  |
| 342117 <sup>U</sup>       | GARMIN GAD 43E AUTOPILOT INTERFACE ADAPTER |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:011-02349-00           | MOS/MSC                                    | 05-Sep-19 | O/C                                          | TSN 0        |                           |           |           |                  |
| SN:1V7052366              | HRS                                        | 5104.4    |                                              | TSN 0        |                           |           |           |                  |
|                           | AFL                                        | 6064      |                                              | TSN 0        |                           |           |           |                  |
| 342200                    | TCAS TTR-4000 TRANSCEIVER                  |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                    | 29-Dec-98 | O/C                                          | TSN 0        |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                        | 0         |                                              | TSN 0        |                           |           |           |                  |
|                           | AFL                                        | 0         |                                              | TSN 0        |                           |           |           |                  |
| PROC. REF: AMM 34-45-01   |                                            |           |                                              |              |                           |           |           |                  |
| 342601                    | NO. 1 ATC TRANSPONDER                      |           |                                              |              |                           |           |           | Component ATA:34 |
| PN:011-03303-00           | MOS/MSC                                    | 08-Oct-21 | O/C                                          |              |                           |           |           |                  |
| SN:3EH024272              | HRS                                        | 5280.3    |                                              |              |                           |           |           |                  |
| WC#: 34.280               | AFL                                        | 6215      |                                              |              |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                            |           |                                              |              |                           |           |           |                  |
| 342606                    | TEST NO. 1 ATC TRANSPONDER                 |           |                                              |              |                           |           |           | Service ATA:34   |
| PN:011-03303-00           | MOS                                        | 10-Jun-24 | 24                                           |              | 10-Jun-26                 |           | 623 d     | MANDATORY        |
| SN:3EH024272              | HRS                                        | 5686.2    |                                              |              |                           |           |           |                  |
| WC#: 34.280               | AFL                                        | 6495      |                                              |              |                           |           |           |                  |
| Test Date: : 10-Jun-24    |                                            |           | PROC. REF: AMM 34-55-01, FAR FAR PART 91.413 |              |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                 | C/W                    | Interval | TSX/Adj.                       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------------------|------------------------|----------|--------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                                      |                        |          |                                |                           |           |           |                  |
| 342610 <sup>U</sup>       | GARMIN GTX335/345 - ICA DOCUMENTS                                    |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                              | 05-Sep-19              | O/C      |                                |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                  | 5104.4                 |          |                                |                           |           |           |                  |
|                           | AFL                                                                  | 6064                   |          |                                |                           |           |           |                  |
| 342611                    | NO. 1 ATC TRANSPONDER ANTENNA                                        |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:100-384129             | MOS/MSC                                                              | 29-Dec-98              | O/C      |                                |                           |           |           |                  |
| SN:10989                  | HRS                                                                  | 0                      |          | TSN 0                          |                           |           |           |                  |
| WC#: 34.290               | AFL                                                                  | 0                      |          |                                |                           |           |           |                  |
| PROC. REF: AMM 34-55-03   |                                                                      |                        |          |                                |                           |           |           |                  |
| 342612 <sup>U</sup>       | GARMIN GTX 335/345 STC SA01714WI - ICA - EQUIPMENT VISUAL INSPECTION |                        |          |                                |                           |           |           | Service ATA:34   |
|                           | MOS                                                                  | 22-May-24              | 12       |                                | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                  | 5686.2                 |          |                                |                           |           |           |                  |
|                           | AFL                                                                  | 6495                   |          |                                |                           |           |           |                  |
| 342613 <sup>U</sup>       | GARMIN GTX 335/345 STC SA01714WI - ICA - ELECTRICAL BONDING TEST     |                        |          |                                |                           |           |           | Service ATA:34   |
|                           | MOS                                                                  | 05-Sep-19              | 120      |                                | 30-Sep-29                 |           | 1831 d    |                  |
|                           | HRS                                                                  | 5104.4                 | 2000     |                                | 7104.4                    |           | 1326.7    |                  |
|                           | AFL                                                                  | 6064                   |          |                                |                           |           |           |                  |
| 342614 <sup>U</sup>       | GARMIN GTS 335/345 STC SA01714WI ANTENNA VISUAL INSPECTION           |                        |          |                                |                           |           |           | Service ATA:34   |
|                           | MOS                                                                  | 22-May-24              | 12       |                                | 31-May-25                 |           | 248 d     |                  |
|                           | HRS                                                                  | 5686.2                 |          |                                |                           |           |           |                  |
|                           | AFL                                                                  | 6495                   |          |                                |                           |           |           |                  |
| 342621                    | NO. 2 ATC TRANSPONDER                                                |                        |          |                                |                           |           |           | Component ATA:34 |
| PN:011-03301-00           | MOS/MSC                                                              | 08-Oct-21              | O/C      |                                |                           |           |           |                  |
| SN:3EF022014              | HRS                                                                  | 5280.3                 |          |                                |                           |           |           |                  |
| WC#: 34.280               | AFL                                                                  | 6215                   |          |                                |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                      |                        |          |                                |                           |           |           |                  |
| 342626                    | TEST NO. 2 ATC TRANSPONDER                                           |                        |          |                                |                           |           |           | Service ATA:34   |
| PN:011-03301-00           | MOS                                                                  | 10-Jun-24              | 24       |                                | 10-Jun-26                 |           | 623 d     | MANDATORY        |
| SN:3EF022014              | HRS                                                                  | 5686.2                 |          |                                |                           |           |           |                  |
| WC#: 34.280               | AFL                                                                  | 6495                   |          |                                |                           |           |           |                  |
|                           |                                                                      | Test Date: : 10-Jun-24 |          | PROC. REF: FAR FAR PART 91.413 |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                |           |          |          |                           |           |           |                  |
| 342631                    | NO. 2 ATC TRANSPONDER ANTENNA                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:100-384129             | MOS/MSC                                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11036                  | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.290               | AFL                                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-55-03   |                                                |           |          |          |                           |           |           |                  |
| 342639                    | MARKER BEACON                                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:51Z4                   | MOS/MSC                                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.300               | AFL                                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 343000 <sup>U</sup>       | GARMIN GA 37 GPS ANTENNA                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:10710                  | MOS/MSC                                        | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:5562                   | HRS                                            | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                            | 6064      |          | TSN 0    |                           |           |           |                  |
| 343001 <sup>U</sup>       | GARMIN GA 36 GPS ANTENNA                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:013-00244-00           | MOS/MSC                                        | 05-Sep-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:18560                  | HRS                                            | 5104.4    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                            | 6064      |          | TSN 0    |                           |           |           |                  |
| 343405                    | COURSE HEADING PANEL                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-6899-001           | MOS/MSC                                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:951                    | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.340               | AFL                                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 343406                    | GTS-820 TRAFFIC ADVISORY SYSTEM PROCESSOR UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                        | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                                |           |          |          |                           |           |           |                  |
| 343409                    | RADAR CONTROL                                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-8393-003           | MOS/MSC                                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.340               | AFL                                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                   |           |          |          |                           |           |           |                  |
| 343412                    | PILOT DISPLAY CONTROL                             |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-8680-001           | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.350               | AFL                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 343418                    | PILOT ELECTRONIC HORIZONTAL SITUATION INDICATOR   |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-6020-021           | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.360               | AFL                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 343420                    | COPILOT DISPLAY PROCESSOR                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-8678-001           | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.320               | AFL                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 343422                    | COPILOT DISPLAY CONTROL                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-8680-001           | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.350               | AFL                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 31-60-03   |                                                   |           |          |          |                           |           |           |                  |
| 343428                    | COPILOT ELECTRONIC HORIZONTAL SITUATION INDICATOR |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-6020-021           | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.360               | AFL                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 344005                    | NO. 1 RADAR ALT ANTENNA                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-2002-14            | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4601                   | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.430               | AFL                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 344010                    | NO. 2 RADAR ALT ANTENNA                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-2002-14            | MOS/MSC                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4609                   | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.430               | AFL                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                            |           |          |          |                           |           |           |                  |
| 344015                    | DATA PROGRAMMER            |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-5110-001           | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.510               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                            |           |          |          |                           |           |           |                  |
| 345005                    | NAVIGATION ANTENNA COUPLER |           |          |          |                           |           |           | Component ATA:34 |
| PN:80-37-101              | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:3919                   | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.390               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-11-03   |                            |           |          |          |                           |           |           |                  |
| 345010                    | NO. 1 LOOP SENSE ANTENNA   |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-2363-001           | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:40228                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.400               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                            |           |          |          |                           |           |           |                  |
| 345015                    | GLIDESLOPE ANTENNA         |           |          |          |                           |           |           | Component ATA:34 |
| PN:100-384128             | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:5230                   | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.410               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                            |           |          |          |                           |           |           |                  |
| 345020                    | AFT DME ANTENNA            |           |          |          |                           |           |           | Component ATA:34 |
| PN:100-384129             | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11048                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.420               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-53-03   |                            |           |          |          |                           |           |           |                  |
| 345024                    | GPS RECEIVER               |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-51-01   |                            |           |          |          |                           |           |           |                  |
| 345025                    | GPS ANTENNA                |           |          |          |                           |           |           | Component ATA:34 |
| PN:10704                  | MOS/MSC                    | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:4007                   | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.515               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-51-03   |                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                              | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|-----------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION       |                                                                                   |           |                |          |                           |           |             |                  |
| 346020                    | TCAS COMPUTER                                                                     |           |                |          |                           |           |             | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                           | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 34.620               | AFL                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346030                    | PERFORM REDUCED VERTICAL SEPARATION MINIMUM (RVSM) HEIGHT MONITORING REQUIREMENTS |           |                |          |                           |           |             | Service ATA:34   |
|                           | MOS/MSC                                                                           | 29-Dec-98 | -              |          |                           |           |             |                  |
|                           | HRS                                                                               | 0         |                |          |                           |           |             |                  |
|                           | AFL                                                                               | 0         |                |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346060                    | RADIO ALTIMETER                                                                   |           |                |          |                           |           |             | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                           | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 34.640               | AFL                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346065                    | AFT RADIO ALTIMETER ANTENNA                                                       |           |                |          |                           |           |             | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                           | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 34.650               | AFL                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-41-03   |                                                                                   |           |                |          |                           |           |             |                  |
| 346075                    | MARKER ANTENNA                                                                    |           |                |          |                           |           |             | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                           | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 34.670               | AFL                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| 346080                    | TCAS DIRECTIONAL ANTENNA                                                          |           |                |          |                           |           |             | Component ATA:34 |
| PN:PN                     | MOS/MSC                                                                           | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| WC#: 34.680               | AFL                                                                               | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |                |          |                           |           |             |                  |
| ATA 35 - OXYGEN           |                                                                                   |           |                |          |                           |           |             |                  |
| 350000                    | CHECK OXYGEN SYSTEM INSTALLATION FOR DAMAGE AND SECURITY                          |           |                |          |                           |           |             | Service ATA:35   |
|                           | MOS                                                                               | 22-May-24 | 24 (+24d/-24d) |          | 22-May-26                 | 15-Jun-26 | 604 d (+24) |                  |
|                           | HRS                                                                               | 5686.2    |                |          |                           |           |             |                  |
|                           | AFL                                                                               | 6495      |                |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                                | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN                                        |                                  |           |          |          |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1                               |                                  |           |          |          |                           |           |           |                  |
| 350101                                                 | OXYGEN CYLINDER                  |           |          |          |                           |           |           | Component ATA:35 |
| PN:1270152-3                                           | MOS                              | 22-May-24 | 180      | TSN 0    | 22-May-39                 |           | 5352 d    | SCRAP            |
| SN:ALT281-29380                                        | HRS                              | 5686.2    |          |          |                           |           |           |                  |
| WC#: 35.010                                            | AFL                              | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 35-00-05, AMM 35-00-07, AMM 35-00-09    |                                  |           |          |          |                           |           |           |                  |
| 350106                                                 | HYDROSTATIC TEST OXYGEN CYLINDER |           |          |          |                           |           |           | Service ATA:35   |
| PN:1270152-3                                           | MOS                              | 22-May-24 | 60       |          | 22-May-29                 |           | 1700 d    |                  |
| SN:ALT281-29380                                        | HRS                              | 5686.2    |          |          |                           |           |           |                  |
| WC#: 35.010                                            | AFL                              | 6495      |          |          |                           |           |           |                  |
| HydroCheck Date: : 22-May-24 PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 350111                                                 | OXYGEN FILLER VALVE              |           |          |          |                           |           |           | Component ATA:35 |
| PN:ZV951                                               | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.020                                            | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                  |           |          |          |                           |           |           |                  |
| 350116                                                 | OXYGEN FILLER GAUGE              |           |          |          |                           |           |           | Component ATA:35 |
| PN:99-384042                                           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:01941                                               | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.040                                            | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                  |           |          |          |                           |           |           |                  |
| 350121                                                 | OXYGEN PRESSURE GAUGE            |           |          |          |                           |           |           | Component ATA:35 |
| PN:99-384042                                           | MOS/MSC                          | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                             | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.040                                            | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                  |           |          |          |                           |           |           |                  |
| 350146                                                 | PILOT OXYGEN MASK                |           |          |          |                           |           |           | Component ATA:35 |
| PN:174260-12                                           | MOS/MSC                          | 12-Apr-23 | O/C      | TSO 0    | 01-Mar-29 (M)             |           | 1618 d    |                  |
| SN:04385                                               | HRS                              | 5500.3    |          | TSO 0    |                           |           |           |                  |
| WC#: 35.050                                            | AFL                              | 6358      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                              |                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                             | Unit                                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-----------------------------------------------------|------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                     |                                                                        |           |                |          |                           |           |             |                  |
| 350151                                              | COPILOT OXYGEN MASK                                                    |           |                |          |                           |           |             | Component ATA:35 |
| PN:174260-12                                        | MOS/MSC                                                                | 12-Apr-23 | O/C            | TSO 0    | 01-Mar-29 (M)             |           | 1618 d      |                  |
| SN:04293                                            | HRS                                                                    | 5500.3    |                | TSO 0    |                           |           |             |                  |
| WC#: 35.050                                         | AFL                                                                    | 6358      |                | TSO 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF                           |                                                                        |           |                |          |                           |           |             |                  |
| 350500                                              | TEST ALL MASKS FOR OXYGEN FLOW                                         |           |                |          |                           |           |             | Service ATA:35   |
|                                                     | MOS                                                                    | 22-May-24 | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25 | 239 d (+12) |                  |
|                                                     | HRS                                                                    | 5686.2    |                |          |                           |           |             |                  |
|                                                     | AFL                                                                    | 6495      |                |          |                           |           |             |                  |
| PROC. REF: AMM 35-00-19                             |                                                                        |           |                |          |                           |           |             |                  |
| 350651                                              | OXYGEN REGULATOR ASSEMBLY                                              |           |                |          |                           |           |             | Component ATA:35 |
| PN:803213-02                                        | MOS                                                                    | 22-May-24 | 60             | TSO 0    | 22-May-29                 |           | 1700 d      | OVERHAUL         |
| SN:6459                                             | HRS                                                                    | 5686.2    |                | TSO 0    |                           |           |             |                  |
| WC#: 35.020                                         | AFL                                                                    | 6495      |                | TSO 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF                           |                                                                        |           |                |          |                           |           |             |                  |
| 350660                                              | OXYGEN SHUT-OFF VALVE                                                  |           |                |          |                           |           |             | Component ATA:35 |
| PN:PN                                               | MOS/MSC                                                                | 29-Dec-98 | O/C            | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                                          | HRS                                                                    | 0         |                | TSN 0    |                           |           |             |                  |
|                                                     | AFL                                                                    | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 35-20-05                             |                                                                        |           |                |          |                           |           |             |                  |
| 350666                                              | REPLACE PACKINGS, PASSENGER OXYGEN SHUTOFF VALVE                       |           |                |          |                           |           |             | Service ATA:35   |
|                                                     | MOS                                                                    | 12-Apr-23 | 48             |          | 12-Apr-27                 |           | 929 d       |                  |
|                                                     | HRS                                                                    | 5500.3    |                |          |                           |           |             |                  |
| WC#: 35.030                                         | AFL                                                                    | 6358      |                |          |                           |           |             |                  |
| PROC. REF: AMM 35-20-05, AMM 35-20-07, AMM 35-20-07 |                                                                        |           |                |          |                           |           |             |                  |
| 350670                                              | PERFORM BAROMETRIC PRESSURE SWITCH CHECK (AUTODEPLOYMENT OXYGENSYSTEM) |           |                |          |                           |           |             | Service ATA:35   |
| PN:101-384028-23                                    | MOS                                                                    | 22-May-24 | 12 (+12d/-12d) |          | 22-May-25                 | 03-Jun-25 | 239 d (+12) | MANDATORY        |
| SN:W48007                                           | HRS                                                                    | 5686.2    |                |          |                           |           |             |                  |
| WC#: 35.070                                         | AFL                                                                    | 6495      |                |          |                           |           |             |                  |
| PROC. REF: AMM 35-20-01                             |                                                                        |           |                |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN                         |                                |           |          |          |                           |           |           |                  |
| 351000                                  | INSPECT PILOT CREW MASKS       |           |          |          |                           |           |           | Service ATA:35   |
| PN:174260-12                            | MOS                            | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
| SN:04385                                | HRS                            | 5686.2    |          |          |                           |           |           |                  |
|                                         | AFL                            | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 35-10-01, AMM 35-10-00   |                                |           |          |          |                           |           |           |                  |
| 352001                                  | OXYGEN PRESSURE SWITCH REPLACE |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                                   | MOS/MSC                        | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                         | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-20-03                 |                                |           |          |          |                           |           |           |                  |
| 352005                                  | BAROMETRIC PRESSURE SWITCH     |           |          |          |                           |           |           | Component ATA:35 |
| PN:101-384028-23                        | MOS/MSC                        | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:W48007                               | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.060                             | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, AMM 35-20-01 |                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 36 - PNEUMATIC        |                                       |           |          |          |                           |           |           |                  |
| 360651                    | DEICE PRESSURE REGULATOR              |           |          |          |                           |           |           | Component ATA:36 |
| PN:90-380000-3            | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   |           |          |          |                           |           |           |                  |
| WC#: 36.010               | AFL                                   |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                       |           |          |          |                           |           |           |                  |
| 361005                    | LEFT BLEED AIR (ELECTRONIC) VALVE     |           |          |          |                           |           |           | Component ATA:36 |
| PN:101-380025-21          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11AP163M               | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 36.020               | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-10-03   |                                       |           |          |          |                           |           |           |                  |
| 361007                    | LEFT ELECTRONIC FLOW PACK CONTROLLER  |           |          |          |                           |           |           | Component ATA:36 |
| PN:PN                     | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                       |           |          |          |                           |           |           |                  |
| 361010                    | RIGHT BLEED AIR (ELECTRONIC) VALVE    |           |          |          |                           |           |           | Component ATA:36 |
| PN:101-380025-21          | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11AP175M               | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 36.020               | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-10-03   |                                       |           |          |          |                           |           |           |                  |
| 361012                    | RIGHT ELECTRONIC FLOW PACK CONTROLLER |           |          |          |                           |           |           | Component ATA:36 |
| PN:PN                     | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM GENERIC 1  |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 37 - VACUUM           |                               |           |          |          |                           |           |           |                  |
| 370636                    | VACUUM REGULATOR VALVE        |           |          |          |                           |           |           | Component ATA:37 |
| PN:133A13                 | MOS/MSC                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                           |           |          |          |                           |           |           |                  |
| WC#: 37.010               | AFL                           |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                               |           |          |          |                           |           |           |                  |
| 372005                    | SUCTION GAUGE                 |           |          |          |                           |           |           | Component ATA:37 |
| PN:101-384133-1           | MOS/MSC                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:L97171                 | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 37.030               | AFL                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                               |           |          |          |                           |           |           |                  |
| 373106                    | REPLACE INSTRUMENT AIR FILTER |           |          |          |                           |           |           | Service ATA:37   |
|                           | MOS                           | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                           | 5686.2    | 800      |          | 6486.2                    |           | 708.5     |                  |
| WC#: 37.020               | AFL                           | 6495      |          |          |                           |           |           |                  |
| PROC. REF: AMM 37-20-01   |                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                                                                        | C/W       | Interval            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-----------------------------------------|-------------------------------------------------------------------------------------------------------------|-----------|---------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 51 - STD PRACTICES AND STRUCT-GENRL |                                                                                                             |           |                     |          |                           |           |              |                  |
| 510101                                  | INSPECT EXTERIOR SKIN(PRIORITY AREA INSPECTION)                                                             |           |                     |          |                           |           |              | Service ATA:51   |
|                                         | MOS                                                                                                         | 29-Dec-98 |                     |          |                           |           |              | MANDATORY        |
|                                         | HRS                                                                                                         |           |                     |          |                           |           |              |                  |
| WC#: 51.010                             | AFL                                                                                                         | 0         | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                                         | PROC. REF: GENERIC NO REF                                                                                   |           |                     |          |                           |           |              |                  |
| 510106                                  | INSPECT FUSELAGE STATIONS 84 THRU 347.75(PRIORITY AREA INSPECTION)                                          |           |                     |          |                           |           |              | Service ATA:51   |
|                                         | MOS                                                                                                         | 29-Dec-98 |                     |          |                           |           |              | MANDATORY        |
|                                         | HRS                                                                                                         |           |                     |          |                           |           |              |                  |
| WC#: 51.030                             | AFL                                                                                                         | 0         | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                                         | PROC. REF: GENERIC NO REF                                                                                   |           |                     |          |                           |           |              |                  |
| 510116                                  | INSPECT STRINGERS FROM FS 88 THROUGH FS 125 AND INSTRUMENT PANEL SUPPORT BRACKETS(PRIORITY AREA INSPECTION) |           |                     |          |                           |           |              | Service ATA:51   |
|                                         | MOS                                                                                                         | 29-Dec-98 |                     |          |                           |           |              |                  |
|                                         | HRS                                                                                                         | 0         |                     |          |                           |           |              |                  |
| WC#: 51.050                             | AFL                                                                                                         | 0         | 10000 (+10%/-10%)   |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                                         | PROC. REF: GENERIC NO REF                                                                                   |           |                     |          |                           |           |              |                  |
| 510121                                  | INSPECT FORWARD PRESSURE BULKHEAD(PRIORITY AREA INSPECTION)                                                 |           |                     |          |                           |           |              | Service ATA:51   |
|                                         | MOS                                                                                                         | 14-Dec-18 |                     |          |                           |           |              | MANDATORY        |
|                                         | HRS                                                                                                         | 5079.9    |                     |          |                           |           |              |                  |
| WC#: 51.020                             | AFL                                                                                                         | 6043      | 2500 (+10%/-10%)    |          | 8543                      | 8793      | 1993 (+250)  |                  |
|                                         | PROC. REF: GENERIC NO REF                                                                                   |           |                     |          |                           |           |              |                  |
| ATA 52 - DOORS                          |                                                                                                             |           |                     |          |                           |           |              |                  |
| 520101                                  | CABIN DOOR                                                                                                  |           |                     |          |                           |           |              | Component ATA:52 |
| PN:101-430104-601                       | MOS/MSC                                                                                                     | 29-Dec-98 | O/C                 |          |                           |           |              |                  |
| SN:UNKNOWN                              | HRS                                                                                                         | 0         |                     | TSN 0    |                           |           |              |                  |
| WC#: 52.010                             | AFL                                                                                                         | 0         |                     |          |                           |           |              |                  |
|                                         | PROC. REF: GENERIC NO REF                                                                                   |           |                     |          |                           |           |              |                  |
| 520105                                  | INSPECT AIRSTAIR/CARGO DOORS, ESCAPE HATCHES (PRIORITY AREA INSPECTION)                                     |           |                     |          |                           |           |              | Service ATA:52   |
|                                         | MOS                                                                                                         | 30-Jun-18 |                     |          |                           |           |              | MANDATORY        |
|                                         | HRS                                                                                                         |           |                     |          |                           |           |              |                  |
| WC#: 52.130                             | AFL                                                                                                         | 5984      | 1000 (+10%/-10%)    |          | 6984                      | 7084      | 434 (+100)   |                  |
|                                         | PROC. REF: AMM 53-10-00                                                                                     |           |                     |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS            |                                              |           |          |          |                           |           |           |                  |
| 520116                    | CABIN DOOR DAMPER                            |           |          |          |                           |           |           | Component ATA:52 |
| PN:50-430143-33           | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.020               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 52-10-17   |                                              |           |          |          |                           |           |           |                  |
| 520126                    | CABIN DOOR SEAL                              |           |          |          |                           |           |           | Component ATA:52 |
| PN:50-430061-27           | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.030               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 52-10-15   |                                              |           |          |          |                           |           |           |                  |
| 520131                    | CABIN DOOR CLOSED SWITCH                     |           |          |          |                           |           |           | Component ATA:52 |
| PN:U3-1                   | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.110               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                              |           |          |          |                           |           |           |                  |
| 520141                    | CABIN DOOR LOCKED SWITCH                     |           |          |          |                           |           |           | Component ATA:52 |
| PN:U3-1                   | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.120               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                              |           |          |          |                           |           |           |                  |
| 520146                    | EMERGENCY EXIT DOOR                          |           |          |          |                           |           |           | Component ATA:52 |
| PN:115-430100-93          | MOS/MSC                                      | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.040               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 52-20-01   |                                              |           |          |          |                           |           |           |                  |
| 520156                    | UPPER FORWARD CABIN AIRSTAIR DOOR LATCH-BOLT |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN             | MOS                                          | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN                | HRS                                          |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.050               | AFL                                          | 4987      | 5000     | TSN 0    | 9987                      |           | 3437      |                  |
| PROC. REF: GENERIC NO REF |                                              |           |          |          |                           |           |           |                  |
| 520161                    | UPPER AFT CABIN AIRSTAIR DOOR LATCH-BOLT     |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN             | MOS                                          | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN                | HRS                                          |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.060               | AFL                                          | 4987      | 5000     | TSN 0    | 9987                      |           | 3437      |                  |
| PROC. REF: GENERIC NO REF |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS            |                                                                                                             |           |          |          |                           |           |           |                  |
| 520166                    | LOWER FORWARD CABIN AIRSTAIR DOOR LATCH-BOLT                                                                |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN             | MOS                                                                                                         | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN                | HRS                                                                                                         |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.050               | AFL                                                                                                         | 4987      | 5000     | TSN 0    | 9987                      |           | 3437      |                  |
| PROC. REF: GENERIC NO REF |                                                                                                             |           |          |          |                           |           |           |                  |
| 520171                    | LOWER AFT CABIN AIRSTAIR DOOR LATCH-BOLT                                                                    |           |          |          |                           |           |           | Component ATA:52 |
| PN:PN-UNKNOWN             | MOS                                                                                                         | 26-Nov-16 |          | TSN 0    |                           |           |           | SCRAP            |
| SN:UNKNOWN                | HRS                                                                                                         |           |          | TSN 0    |                           |           |           |                  |
| WC#: 52.060               | AFL                                                                                                         | 4987      | 5000     | TSN 0    | 9987                      |           | 3437      |                  |
| PROC. REF: GENERIC NO REF |                                                                                                             |           |          |          |                           |           |           |                  |
| 520176                    | REPLACE FORWARD CABIN AIRSTAIR DOOR UPPER HOOK MECHANISM (INCLUDING PINS, BRACKETS, SPRING, ARM AND HOOKS). |           |          |          |                           |           |           | Service ATA:52   |
|                           | MOS                                                                                                         | 29-Dec-98 |          |          |                           |           |           | MANDATORY        |
|                           | HRS                                                                                                         | 0         |          |          |                           |           |           |                  |
| WC#: 52.100               | AFL                                                                                                         | 0         | 10000    |          | 10000                     |           | 3450      |                  |
| PROC. REF: GENERIC NO REF |                                                                                                             |           |          |          |                           |           |           |                  |
| 520177                    | REPLACE AFT CABIN AIRSTAIR DOOR UPPER HOOK MECHANISM (INCLUDING PINS, BRACKETS, SPRING, ARM AND HOOKS).     |           |          |          |                           |           |           | Service ATA:52   |
| PN:PN                     | MOS                                                                                                         | 29-Dec-98 |          | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                                                         | 0         | 10000    | TSN 0    | 10000                     |           | 3450      |                  |
| PROC. REF: AMM GENERIC 1  |                                                                                                             |           |          |          |                           |           |           |                  |
| 520181                    | CABIN DOOR SEAL PNEUMATIC VALVE                                                                             |           |          |          |                           |           |           | Component ATA:52 |
| PN:MS28056-1              | MOS/MSC                                                                                                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.070               | AFL                                                                                                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                             |           |          |          |                           |           |           |                  |
| 520190                    | CARGO DOOR                                                                                                  |           |          |          |                           |           |           | Component ATA:52 |
| PN:101-430139-601         | MOS/MSC                                                                                                     | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 52.080               | AFL                                                                                                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                             |           |          |          |                           |           |           |                  |
| ATA 53 - FUSELAGE         |                                                                                                             |           |          |          |                           |           |           |                  |
| 530099 <sup>U</sup>       | RAISBECK DUAL AFT BODY STRAKES - STC SA3519NM                                                               |           |          |          |                           |           |           | Component ATA:53 |
| PN:PN - UNK               | MOS/MSC                                                                                                     | 02-May-03 | O/C      | TSN 0    |                           |           |           |                  |
| SN:574                    | HRS                                                                                                         | 1320.5    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                                                         |           |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN           | Unit                                                                                                                                           | C/W       | Interval            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 53 - FUSELAGE |                                                                                                                                                |           |                     |          |                           |           |              |                  |
| 530104            | INSPECT CABIN DOOR AND FUSELAGE FRAME (PRIORITY AREA INSPECTION)                                                                               |           |                     |          |                           |           |              | Service ATA:53   |
|                   | MOS                                                                                                                                            |           |                     |          |                           |           |              |                  |
|                   | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
|                   | AFL                                                                                                                                            | EFF       | T:10000 (+10%/-10%) |          | 10000 *                   | 11000     | 3450 (+1000) |                  |
|                   | PROC. REF: AMM 53-10-00                                                                                                                        |           |                     |          |                           |           |              |                  |
| 530105            | INSPECT LEFT WINDSHIELD DOUBLERS/CLIPS OF THE FUSELAGE AT THE UPPER AND LOWER WINDSHIELD AND STORM WINDOW CORNERS FOR CRACKS AND LOOSE RIVETS  |           |                     |          |                           |           |              | Service ATA:53   |
|                   | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              | MANDATORY        |
|                   | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
| WC#: 53.020       | AFL                                                                                                                                            |           | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                   | PROC. REF: AMM 53-10-00                                                                                                                        |           |                     |          |                           |           |              |                  |
| 530120            | INSPECT RIGHT WINDSHIELD DOUBLERS/CLIPS OF THE FUSELAGE AT THE UPPER AND LOWER WINDSHIELD AND STORM WINDOW CORNERS FOR CRACKS AND LOOSE RIVETS |           |                     |          |                           |           |              | Service ATA:53   |
|                   | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              | MANDATORY        |
|                   | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
| WC#: 53.020       | AFL                                                                                                                                            | 0         | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                   | PROC. REF: GENERIC NO REF                                                                                                                      |           |                     |          |                           |           |              |                  |
| 530126            | RADOME                                                                                                                                         |           |                     |          |                           |           |              | Component ATA:53 |
| PN:101-410068-5   | MOS/MSC                                                                                                                                        | 29-Dec-98 | O/C                 |          |                           |           |              |                  |
| SN:UNKNOWN        | HRS                                                                                                                                            | 0         |                     | TSN 0    |                           |           |              |                  |
| WC#: 53.010       | AFL                                                                                                                                            | 0         |                     |          |                           |           |              |                  |
|                   | PROC. REF: GENERIC NO REF                                                                                                                      |           |                     |          |                           |           |              |                  |
| 530160            | INSPECT AFT FUSELAGE AREA AND REAR PRESSURE BULKHEAD(PRIORITY AREA INSPECTION)                                                                 |           |                     |          |                           |           |              | Service ATA:53   |
|                   | MOS                                                                                                                                            | 29-Dec-98 |                     |          |                           |           |              |                  |
|                   | HRS                                                                                                                                            |           |                     |          |                           |           |              |                  |
| WC#: 53.050       | AFL                                                                                                                                            |           | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                  |
|                   | PROC. REF: GENERIC NO REF                                                                                                                      |           |                     |          |                           |           |              |                  |
| 530161            | INSPECT STRINGERS 5 THROUGH 11 ON THE AFT SIDE OF THE REAR PRESSURE BULKHEAD                                                                   |           |                     |          |                           |           |              | Service ATA:53   |
|                   | MOS/MSC                                                                                                                                        | 18-Dec-18 | N/R                 |          |                           |           |              | MANDATORY        |
|                   | HRS                                                                                                                                            | 5079.9    |                     |          |                           |           |              |                  |
| WC#: 53.030       | AFL                                                                                                                                            | 6043      |                     |          |                           |           |              |                  |
|                   | PROC. REF: GENERIC NO REF                                                                                                                      |           |                     |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                                                     | C/W       | Interval            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|---------------------------|----------------------------------------------------------------------------------------------------------|-----------|---------------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 53 - FUSELAGE         |                                                                                                          |           |                     |          |                           |           |              |                |
| 530162                    | INSPECT FOR CRACKS ABOVE AND BELOW THE STRINGER CUTOUTS IN THE BEND RADIUS OF THE REAR PRESSURE BULKHEAD |           |                     |          |                           |           |              | Service ATA:53 |
|                           | MOS                                                                                                      | 29-Dec-98 |                     |          |                           |           |              | MANDATORY      |
|                           | HRS                                                                                                      | 0         |                     |          |                           |           |              |                |
| WC#: 53.040               | AFL                                                                                                      | 0         | T:10000 (+10%/-10%) |          | 10000                     | 11000     | 3450 (+1000) |                |
| PROC. REF: GENERIC NO REF |                                                                                                          |           |                     |          |                           |           |              |                |
| 530170 <sup>U</sup>       | PERFORM RAISBECK DUAL AFT BODY STRAKES INSPECTION                                                        |           |                     |          |                           |           |              | Service ATA:53 |
|                           | MOS                                                                                                      | 22-May-24 |                     |          |                           |           |              |                |
|                           | HRS                                                                                                      | 5686.2    | 200 (+20/-20)       |          | 5886.2                    | 5906.2    | 108.5 (+20)  |                |
|                           | AFL                                                                                                      | 6495      |                     |          |                           |           |              |                |
| 531003                    | INSPECT FUSELAGE FRAME WEB FS 179 THROUGH FS 271(PRIORITY AREA INSPECTION)                               |           |                     |          |                           |           |              | Service ATA:53 |
|                           | MOS                                                                                                      | 14-Dec-18 |                     |          |                           |           |              |                |
|                           | HRS                                                                                                      | 5079.9    |                     |          |                           |           |              |                |
| WC#: 51.040               | AFL                                                                                                      | 6043      | 2500 (+10%/-10%)    |          | 8543                      | 8793      | 1993 (+250)  |                |
| PROC. REF: GENERIC NO REF |                                                                                                          |           |                     |          |                           |           |              |                |
| ATA 54 - NACELLES/PYLONS  |                                                                                                          |           |                     |          |                           |           |              |                |
| 541001                    | INSPECT NACELLE SPLICE PLATES                                                                            |           |                     |          |                           |           |              | Service ATA:54 |
|                           | MOS                                                                                                      | 22-May-24 | 12 (+12d/-12d)      |          | 22-May-25                 | 03-Jun-25 | 239 d (+12)  |                |
|                           | HRS                                                                                                      | 5686.2    |                     |          |                           |           |              |                |
|                           | AFL                                                                                                      | 6495      |                     |          |                           |           |              |                |
| PROC. REF: SIRM 57-17-03  |                                                                                                          |           |                     |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 55 - STABILIZERS                    |                                               |           |          |          |                           |           |           |                  |
| 550010                                  | INSPECTION HORIZONTAL AND VERTICAL STABILIZER |           |          |          |                           |           |           | Service ATA:55   |
|                                         | MOS                                           | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                         | HRS                                           | 5686.2    |          |          |                           |           |           |                  |
|                                         | AFL                                           | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 55-00-11, SIRM 55-00-12 |                                               |           |          |          |                           |           |           |                  |
| 550101                                  | VERTICAL STABILIZER                           |           |          |          |                           |           |           | Component ATA:55 |
| PN:101-640000-601                       | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 55.010                             | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 55-30-01                 |                                               |           |          |          |                           |           |           |                  |
| 550111                                  | HORIZONTAL STABILIZER                         |           |          |          |                           |           |           | Component ATA:55 |
| PN:101-620000-601                       | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 55.010                             | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 55-10-01                 |                                               |           |          |          |                           |           |           |                  |
| ATA 56 - WINDOWS                        |                                               |           |          |          |                           |           |           |                  |
| 560100                                  | WINDSHIELD REPLACE                            |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                                   | MOS/MSC                                       | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                         | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-01                 |                                               |           |          |          |                           |           |           |                  |
| 560101                                  | PILOT WINDSHIELD ASSEMBLY                     |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-384025-23                        | MOS/MSC                                       | 16-Jul-19 | O/C      | TSO 0    |                           |           |           |                  |
| SN:19105R0096                           | HRS                                           | 5100.9    |          | TSO 0    |                           |           |           |                  |
| WC#: 56.010                             | AFL                                           |           |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-01                 |                                               |           |          |          |                           |           |           |                  |
| 560104                                  | REPLACE LEFT WINDSHIELD FRAME SCREWS          |           |          |          |                           |           |           | Service ATA:56   |
|                                         | MOS                                           | 29-Dec-98 |          |          |                           |           |           | LIFE LIMIT       |
|                                         | HRS                                           | 0         |          |          |                           |           |           |                  |
| WC#: 56.150                             | AFL                                           | 0         | 10000    |          | 10000                     |           | 3450      |                  |
| PROC. REF: AMM 56-10-01                 |                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS        |                                       |           |          |          |                           |           |           |                  |
| 560106                  | PILOT STORM WINDOW                    |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-420083-603        | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-10-05 |                                       |           |          |          |                           |           |           |                  |
| 560111                  | PILOT SIDE WINDOW                     |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-420066-609        | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-10-03 |                                       |           |          |          |                           |           |           |                  |
| 560116                  | COPILOT WINDSHIELD ASSEMBLY           |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-384025-24        | MOS/MSC                               | 13-Oct-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:04121R3642           | HRS                                   | 1639.2    |          | TSN 0    |                           |           |           |                  |
| WC#: 56.010             | AFL                                   | 1352      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-01 |                                       |           |          |          |                           |           |           |                  |
| 560119                  | REPLACE RIGHT WINDSHIELD FRAME SCREWS |           |          |          |                           |           |           | Service ATA:56   |
|                         | MOS                                   | 13-Oct-04 |          |          |                           |           |           | LIFE LIMIT       |
|                         | HRS                                   | 1639.2    |          |          |                           |           |           |                  |
| WC#: 56.150             | AFL                                   | 1352      | 10000    |          | 11352                     |           | 4802      |                  |
| PROC. REF: AMM 56-10-01 |                                       |           |          |          |                           |           |           |                  |
| 560121                  | COPILOT STORM WINDOW                  |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-420083-604       | MOS/MSC                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-10-05 |                                       |           |          |          |                           |           |           |                  |
| 560126                  | COPILOT SIDE WINDOW                   |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-420081-10        | MOS/MSC                               | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:10591                | HRS                                   | 5500.3    |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050             | AFL                                   | 6358      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-10-03 |                                       |           |          |          |                           |           |           |                  |
| 560201                  | NO. 1 POLARIZED WINDOW                |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS        |                        |           |          |          |                           |           |           |                  |
| 560202                  | NO. 2 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560203                  | NO. 3 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560204                  | NO. 4 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560205                  | NO. 5 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560206                  | NO. 6 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560207                  | NO. 7 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |
| 560208                  | NO. 8 POLARIZED WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:PN                   | MOS/MSC                | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-05 |                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS          |                                 |           |          |          |                           |           |           |                  |
| 560601                    | LEFT NO.1 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.060               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                 |           |          |          |                           |           |           |                  |
| 560606                    | LEFT NO.2 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.070               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                 |           |          |          |                           |           |           |                  |
| 560611                    | LEFT NO.3 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.080               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                 |           |          |          |                           |           |           |                  |
| 560616                    | LEFT NO.4 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.090               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                 |           |          |          |                           |           |           |                  |
| 560621                    | LEFT NO.5 CABIN EXTERIOR WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.100               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                 |           |          |          |                           |           |           |                  |
| 560626                    | LEFT BAGGAGE COMPARTMENT WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-440042-2           | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.110               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-13   |                                 |           |          |          |                           |           |           |                  |
| 560631                    | EMERGENCY EXIT WINDOW           |           |          |          |                           |           |           | Component ATA:56 |
| PN:100-530168-69          | MOS/MSC                         | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.120               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-09   |                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS          |                                                                         |           |          |          |                           |           |           |                  |
| 560636                    | RIGHT NO.1 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.060               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 560641                    | RIGHT NO.2 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.070               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 560646                    | RIGHT NO.3 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.080               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 560651                    | RIGHT NO.4 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.090               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 560656                    | RIGHT NO.5 CABIN EXTERIOR WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:50-440056-17           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.100               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 560661                    | RIGHT BAGGAGE COMPARTMENT WINDOW                                        |           |          |          |                           |           |           | Component ATA:56 |
| PN:101-440042-2           | MOS/MSC                                                                 | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.110               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-13   |                                                                         |           |          |          |                           |           |           |                  |
| ATA 57 - WINGS            |                                                                         |           |          |          |                           |           |           |                  |
| 570099 <sup>U</sup>       | RAISBECK NACELLE OVERWING STORAGE LOCKERS & FLAP FAIRING - STC SA3857NM |           |          |          |                           |           |           | Component ATA:57 |
| PN:PN - UNK               | MOS/MSC                                                                 | 02-May-03 | O/C      | TSN 0    |                           |           |           |                  |
| SN:KIT 238                | HRS                                                                     | 1320.5    |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                                                     |           |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|----------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                          |                                                                      |           |          |          |                           |           |           |                  |
| 570100 <sup>U</sup>                     | REPLACE GAS SHOCK STRUT LH WING LOCKER                               |           |          |          |                           |           |           | Component ATA:57 |
| PN:C16-26918                            | MOS/MSC                                                              | 15-Jul-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NSN                                  | HRS                                                                  | 5347.3    |          | TSN 0    |                           |           |           |                  |
|                                         | AFL                                                                  |           |          |          |                           |           |           |                  |
| 570101                                  | LEFT WING                                                            |           |          |          |                           |           |           | Component ATA:57 |
| PN:101-110072-605                       | MOS/MSC                                                              | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:BB1645                               | HRS                                                                  | 0         |          |          |                           |           |           |                  |
| WC#: 57.010                             | AFL                                                                  | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 57-20-01                 |                                                                      |           |          |          |                           |           |           |                  |
| 570111                                  | TORQUE CHECK LEFT WING UPPER FORWARD, UPPER AND LOWER AFT WING BOLTS |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                  | 22-May-24 |          |          |                           |           |           |                  |
|                                         | HRS                                                                  | 5686.2    | T:200    |          | 5886.2                    |           | 108.5     |                  |
| WC#: 57.015                             | AFL                                                                  | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                      |           |          |          |                           |           |           |                  |
| 570131                                  | REPLACE LEFT WING LOWER FORWARD BOLT AND NUT                         |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                  | 22-May-24 | 60       |          | 22-May-29                 |           | 1700 d    | LIFE LIMIT       |
|                                         | HRS                                                                  | 5686.2    |          |          |                           |           |           |                  |
| WC#: 57.010                             | AFL                                                                  | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                      |           |          |          |                           |           |           |                  |
| 570133                                  | REPLACE LEFT WING LOWER AFT BOLT AND NUT                             |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                  | 22-May-24 | 240      |          | 22-May-44                 |           | 7179 d    | LIFE LIMIT       |
|                                         | HRS                                                                  | 5686.2    | 20000    |          | 25686.2                   |           | 19908.5   |                  |
| WC#: 57.010                             | AFL                                                                  | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                      |           |          |          |                           |           |           |                  |
| 570134                                  | REPLACE LEFT WING UPPER AFT BOLT AND NUT                             |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                  | 22-May-24 | 240      |          | 22-May-44                 |           | 7179 d    | LIFE LIMIT       |
|                                         | HRS                                                                  | 5686.2    | 20000    |          | 25686.2                   |           | 19908.5   |                  |
| WC#: 57.010                             | AFL                                                                  | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                                                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-----------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                          |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570136                                  | MAGNIFIED VISUAL AND EDDY CURRENT AS SPECIFIED LEFT WING ALL WING-ATTACH FITTING FLAT SURFACES, DEPRESSIONS, COUNTERBORES, BOLT BORES AND BARREL NUT RECESSES, WING BOLTS, AND LOWER FORWARD MAIN SPAR CLEVIS FITTINGS |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1700 d    | MANDATORY      |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           |                |
| WC#: 57.010                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02, SIRM 57-17-01 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570137                                  | REPLACE LEFT WING UPPER FORWARD BOLT AND NUT                                                                                                                                                                           |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    | 06-Dec-13 | 240      |          | 06-Dec-33                 |           | 3359 d    | LIFE LIMIT     |
|                                         | HRS                                                                                                                                                                                                                    | 3137.1    | 20000    |          | 23137.1                   |           | 17359.4   |                |
| WC#: 57.010                             | AFL                                                                                                                                                                                                                    | 3301      |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570160                                  | EDDY CURRENT LEFT LOWER FORWARD (MAIN) SPAR LUGS                                                                                                                                                                       |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                                         | HRS                                                                                                                                                                                                                    |           | T:15000  |          | 15000                     |           | 9222.3    |                |
| WC#: 57.070                             | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570165                                  | EDDY CURRENT INSPECT LEFT OUTBOARD WING PANEL LOWER FORWARD SPAR CAP                                                                                                                                                   |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    | 29-Dec-98 |          |          |                           |           |           |                |
|                                         | HRS                                                                                                                                                                                                                    |           | T:15000  |          | 15000                     |           | 9222.3    |                |
| WC#: 57.080                             | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570185                                  | EDDY CURRENT INSPECT LEFT CENTER SECTION AND OUTBOARD WING PANEL AFT SPAR LOWER FITTING                                                                                                                                |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    | 29-Dec-98 |          |          |                           |           |           |                |
|                                         | HRS                                                                                                                                                                                                                    |           | T:27000  |          | 27000                     |           | 21222.3   |                |
| WC#: 57.110                             | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |
| 570203                                  | EDDY CURRENT LEFT WING FORWARD SPAR ANGLE                                                                                                                                                                              |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
|                                         | HRS                                                                                                                                                                                                                    | EFF       | T:18000  |          | 18000 *                   |           | 12222.3   |                |
|                                         | AFL                                                                                                                                                                                                                    |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                          |                                                            |           |          |          |                           |           |           |                  |
| 570204                                  | EDDY CURRENT RIGHT WING FORWARD SPAR ANGLE                 |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                        |           |          |          |                           |           |           |                  |
|                                         | HRS                                                        | EFF       | T:18000  |          | 18000 *                   |           | 12222.3   |                  |
|                                         | AFL                                                        |           |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |           |          |          |                           |           |           |                  |
| 570300                                  | CENTER SECTION WING                                        |           |          |          |                           |           |           | Component ATA:57 |
| PN:RA2000                               | MOS/MSC                                                    | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 57.120                             | AFL                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                            |           |          |          |                           |           |           |                  |
| 570301                                  | EDDY CURRENT INSPECT CENTER SECTION LOWER FORWARD SPAR CAP |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                        | 29-Dec-98 |          |          |                           |           |           |                  |
|                                         | HRS                                                        |           | T:18000  |          | 18000                     |           | 12222.3   |                  |
| WC#: 57.090                             | AFL                                                        |           |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                            |           |          |          |                           |           |           |                  |
| 570305                                  | REPLACE WING-TO-FUSELAGE ATTACH ANGLES                     |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                        | 29-Dec-98 |          |          |                           |           |           | LIFE LIMIT       |
|                                         | HRS                                                        | 0         | 30000    | TAC 0    | 30000                     |           | 24222.3   |                  |
| WC#: 57.130                             | AFL                                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                            |           |          |          |                           |           |           |                  |
| 570306                                  | EDDY CURRENT INSPECT CENTER SECTION BELLY SKIN             |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                        | 29-Dec-98 |          |          |                           |           |           |                  |
|                                         | HRS                                                        |           | T:22500  |          | 22500                     |           | 16722.3   |                  |
| WC#: 57.100                             | AFL                                                        |           |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |           |          |          |                           |           |           |                  |
| 570311                                  | EDDY CURRENT INSPECT CENTER SECTION LOWER AFT SPAR         |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                        | 29-Dec-98 |          |          |                           |           |           |                  |
|                                         | HRS                                                        |           | T:27000  |          | 27000                     |           | 21222.3   |                  |
| WC#: 57.110                             | AFL                                                        |           |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02                |                                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                                                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                          |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570601                                  | RIGHT WING                                                                                                                                                                                                             |           |          |          |                           |           |           | Component ATA:57 |
| PN:101-110072-606                       | MOS/MSC                                                                                                                                                                                                                | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:BB1645                               | HRS                                                                                                                                                                                                                    | 0         |          |          |                           |           |           |                  |
| WC#: 57.020                             | AFL                                                                                                                                                                                                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 57-20-01                 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570611                                  | TORQUE CHECK RIGHT WING UPPER FORWARD, UPPER AND LOWER AFT WING BOLTS                                                                                                                                                  |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    | T:200    |          | 5886.2                    |           | 108.5     |                  |
| WC#: 57.015                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570631                                  | REPLACE RIGHT WING LOWER FORWARD BOLT AND NUT                                                                                                                                                                          |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1700 d    | LIFE LIMIT       |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           |                  |
| WC#: 57.020                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570633                                  | REPLACE RIGHT WING LOWER AFT BOLT AND NUT                                                                                                                                                                              |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 | 240      |          | 22-May-44                 |           | 7179 d    | LIFE LIMIT       |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    | 20000    |          | 25686.2                   |           | 19908.5   |                  |
| WC#: 57.020                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570634                                  | REPLACE RIGHT WING UPPER AFT BOLT AND NUT                                                                                                                                                                              |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 | 240      |          | 22-May-44                 |           | 7179 d    | LIFE LIMIT       |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    | 20000    |          | 25686.2                   |           | 19908.5   |                  |
| WC#: 57.020                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |
| 570636                                  | MAGNIFIED VISUAL AND EDDY CURRENT AS SPECIFIED RIGHT WING ALL WING-ATTACH FITTING FLAT SURFACES, DEPRESSIONS, COUNTERBORES, BOLT BORES AND BARREL NUT RECESSES, WING BOLTS AND LOWER FORWARD MAIN SPAR CLEVIS FITTINGS |           |          |          |                           |           |           | Service ATA:57   |
|                                         | MOS                                                                                                                                                                                                                    | 22-May-24 | 60       |          | 22-May-29                 |           | 1700 d    | MANDATORY        |
|                                         | HRS                                                                                                                                                                                                                    | 5686.2    |          |          |                           |           |           |                  |
| WC#: 57.020                             | AFL                                                                                                                                                                                                                    | 6495      |          |          |                           |           |           |                  |
| PROC. REF: SIRM 57-17-02, SIRM 57-17-01 |                                                                                                                                                                                                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                                 | Unit                                                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-----------------------------------------|------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                          |                                                                                          |           |          |          |                           |           |           |                |
| 570637                                  | REPLACE RIGHT WING UPPER FORWARD BOLT AND NUT                                            |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      | 06-Dec-13 | 240      |          | 06-Dec-33                 |           | 3359 d    | LIFE LIMIT     |
|                                         | HRS                                                                                      | 3137.1    | 20000    |          | 23137.1                   |           | 17359.4   |                |
| WC#: 57.020                             | AFL                                                                                      | 3301      |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                |
| 570660                                  | EDDY CURRENT RIGHT LOWER FORWARD (MAIN) SPAR LUGS                                        |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      |           |          |          |                           |           |           |                |
|                                         | HRS                                                                                      |           | T:15000  |          | 15000                     |           | 9222.3    |                |
| WC#: 57.070                             | AFL                                                                                      |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                |
| 570665                                  | EDDY CURRENT INSPECT RIGHT OUTBOARD WING PANEL LOWER FORWARD SPAR CAP                    |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      | 29-Dec-98 |          |          |                           |           |           |                |
|                                         | HRS                                                                                      |           | T:15000  |          | 15000                     |           | 9222.3    |                |
| WC#: 57.080                             | AFL                                                                                      |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                |
| 570685                                  | EDDY CURRENT INSPECT RIGHT CENTER SECTION AND OUTBOARD WING PANEL AFT SPAR LOWER FITTING |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      | 29-Dec-98 |          |          |                           |           |           |                |
|                                         | HRS                                                                                      |           | T:27000  |          | 27000                     |           | 21222.3   |                |
| WC#: 57.110                             | AFL                                                                                      |           |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-02                |                                                                                          |           |          |          |                           |           |           |                |
| 571101                                  | VISUALLY INSPECT LEFT WING OUTBOARD WING PANEL UPPER AND LOWER MAIN SPAR CAPS            |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                |
|                                         | HRS                                                                                      | 5686.2    |          |          |                           |           |           |                |
| WC#: 57.040                             | AFL                                                                                      | 6495      |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                |
| 571601                                  | VISUALLY INSPECT RIGHT WING OUTBOARD WING PANEL UPPER AND LOWER MAIN SPAR CAPS           |           |          |          |                           |           |           | Service ATA:57 |
|                                         | MOS                                                                                      | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                |
|                                         | HRS                                                                                      | 5686.2    |          |          |                           |           |           |                |
| WC#: 57.040                             | AFL                                                                                      | 6495      |          |          |                           |           |           |                |
| PROC. REF: SIRM 57-17-01, SIRM 57-17-02 |                                                                                          |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                        | C/W       | Interval       | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------------------|-------------------------------------------------------------|-----------|----------------|-----------|---------------------------|-----------|-------------|------------------|
| ATA 57 - WINGS                        |                                                             |           |                |           |                           |           |             |                  |
| 572000                                | INSPECT WING CENTER SECTION UPPER SURFACE BONDED PANEL SKIN |           |                |           |                           |           |             | Service ATA:57   |
|                                       | MOS                                                         | 12-Apr-23 | 18 (+18d/-18d) |           | 12-Oct-24                 | 30-Oct-24 | 17 d (+18)  |                  |
|                                       | HRS                                                         | 5500.3    |                |           |                           |           |             |                  |
| WC#: 57.050                           | AFL                                                         | 6358      |                |           |                           |           |             |                  |
| PROC. REF: AMM 51-10-01, AMM 57-10-01 |                                                             |           |                |           |                           |           |             |                  |
| 573040 <sup>U</sup>                   | PERFORM RAISBECK NACELLE / WING LOCKERS INSPECTION          |           |                |           |                           |           |             | Service ATA:57   |
|                                       | MOS                                                         | 22-May-24 |                |           |                           |           |             |                  |
|                                       | HRS                                                         | 5686.2    | 200 (+20/-20)  |           | 5886.2                    | 5906.2    | 108.5 (+20) |                  |
|                                       | AFL                                                         | 6495      |                |           |                           |           |             |                  |
| ATA 61 - PROPELLERS/PROPULSORS        |                                                             |           |                |           |                           |           |             |                  |
| 610000                                | NO. 1 PROPELLER - OVERHAUL                                  |           |                |           |                           |           |             | Service ATA:61   |
|                                       | MOS                                                         | 13-Feb-19 | 72             |           | 13-Feb-25                 |           | 141 d       | OVERHAUL         |
|                                       | HRS                                                         | 4554.9    | 4000           |           | (8554.9)<br>9082.9        |           | 3305.2      |                  |
| PROC. REF: MM GENERIC, POM 61-00-49   |                                                             |           |                |           |                           |           |             |                  |
| 610000                                | NO. 2 PROPELLER - OVERHAUL                                  |           |                |           |                           |           |             | Service ATA:61   |
|                                       | MOS                                                         | 13-Feb-19 | 72             |           | 13-Feb-25                 |           | 141 d       | OVERHAUL         |
|                                       | HRS                                                         | 4554.9    | 4000           |           | (8554.9)<br>9082.9        |           | 3305.2      |                  |
| PROC. REF: MM GENERIC, POM 61-00-49   |                                                             |           |                |           |                           |           |             |                  |
| 610131                                | NO. 1 PROPELLER OVERSPEED GOVERNOR                          |           |                |           |                           |           |             | Component ATA:61 |
| PN:210638F                            | MOS                                                         | 31-Jan-19 |                | TSO 0     |                           |           |             | OVERHAUL         |
| SN:1753507                            | HRS                                                         | 5082.9    | 6500           | TSO 0     | 11582.9                   |           | 5805.2      |                  |
| WC#: 61.020                           | AFL                                                         | 6044      |                | TSO 0     |                           |           |             |                  |
| PROC. REF: AMM 61-20-09               |                                                             |           |                |           |                           |           |             |                  |
| 610141                                | NO. 1 PROPELLER GOVERNOR                                    |           |                |           |                           |           |             | Component ATA:61 |
| PN:8210-024-01                        | MOS                                                         | 13-Feb-19 |                | TSO 87    |                           |           |             | OVERHAUL         |
| SN:11394964                           | HRS                                                         | 5082.9    | 4500           | TSO 693.3 | 8889.6                    |           | 3111.9      |                  |
| WC#: 61.030                           | AFL                                                         | 6044      |                | TSO 693   |                           |           |             |                  |
| PROC. REF: AMM 61-20-01               |                                                             |           |                |           |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                 | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|--------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                      |           |          |           |                           |           |           |                  |
| 610151                         | NO. 1 PROPELLER TACHOMETER GENERATOR |           |          |           |                           |           |           | Component ATA:61 |
| PN:50-389057-1                 | MOS/MSC                              | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:20915                       | HRS                                  | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 61.040                    | AFL                                  | 0         |          |           |                           |           |           |                  |
| PROC. REF: AMM 77-14-01        |                                      |           |          |           |                           |           |           |                  |
| 610156                         | NO. 1 PROPELLER TACH INDICATOR       |           |          |           |                           |           |           | Component ATA:61 |
| PN:90-380009-2                 | MOS/MSC                              | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                  | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 61.050                    | AFL                                  | 0         |          |           |                           |           |           |                  |
| PROC. REF: AMM 77-14-01        |                                      |           |          |           |                           |           |           |                  |
| 610631                         | NO. 2 PROPELLER OVERSPEED GOVERNOR   |           |          |           |                           |           |           | Component ATA:61 |
| PN:210638F                     | MOS                                  | 31-Jan-19 |          | TSO 0     |                           |           |           | OVERHAUL         |
| SN:2167497                     | HRS                                  | 5082.9    | 6500     | TSO 0     | 11582.9                   |           | 5805.2    |                  |
| WC#: 61.020                    | AFL                                  | 6044      |          | TSO 0     |                           |           |           |                  |
| PROC. REF: AMM 61-20-09        |                                      |           |          |           |                           |           |           |                  |
| 610641                         | NO. 2 PROPELLER GOVERNOR             |           |          |           |                           |           |           | Component ATA:61 |
| PN:8210-024-01                 | MOS                                  | 13-Feb-19 |          | TSO 87    |                           |           |           | OVERHAUL         |
| SN:10020542                    | HRS                                  | 5082.9    | 4500     | TSO 693.3 | 8889.6                    |           | 3111.9    |                  |
| WC#: 61.030                    | AFL                                  | 6044      |          | TSO 693   |                           |           |           |                  |
| PROC. REF: AMM 61-20-01        |                                      |           |          |           |                           |           |           |                  |
| 610651                         | NO. 2 PROPELLER TACHOMETER GENERATOR |           |          |           |                           |           |           | Component ATA:61 |
| PN:50-389057-1                 | MOS/MSC                              | 29-Dec-98 | O/C      |           |                           |           |           |                  |
| SN:21012                       | HRS                                  | 0         |          | TSN 0     |                           |           |           |                  |
| WC#: 61.040                    | AFL                                  | 0         |          |           |                           |           |           |                  |
| PROC. REF: AMM 77-14-01        |                                      |           |          |           |                           |           |           |                  |
| 610656                         | NO. 2 PROPELLER TACH INDICATOR       |           |          |           |                           |           |           | Component ATA:61 |
| PN:101-380092-3                | MOS/MSC                              | 13-Feb-19 | O/C      | TSO 0     |                           |           |           |                  |
| SN:110M                        | HRS                                  | 5082.9    |          | TSO 0     |                           |           |           |                  |
| WC#: 61.050                    | AFL                                  | 6044      |          | TSO 0     |                           |           |           |                  |
| PROC. REF: AMM 77-14-01        |                                      |           |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                             | Unit                                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------|---------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPULSORS      |                                                                     |           |          |          |                           |           |           |                  |
| 611010                              | NO. 1 PROPELLER - PERIODIC INSPECTION                               |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS                                                                 | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                     | HRS                                                                 | 5158.2    | 400      |          | (5558.2)<br>6086.2        |           | 308.5     |                  |
| PROC. REF: POM 61-00-49             |                                                                     |           |          |          |                           |           |           |                  |
| 611010                              | NO. 2 PROPELLER - PERIODIC INSPECTION                               |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS                                                                 | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                     | HRS                                                                 | 5158.2    | 400      |          | (5558.2)<br>6086.2        |           | 308.5     |                  |
| PROC. REF: POM 61-00-49             |                                                                     |           |          |          |                           |           |           |                  |
| 611020                              | NO. 1 PROPELLER - LUBRICATE                                         |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS                                                                 | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                     | HRS                                                                 | 5158.2    | 400      |          | (5558.2)<br>6086.2        |           | 308.5     |                  |
| PROC. REF: MM GENERIC, POM 61-00-49 |                                                                     |           |          |          |                           |           |           |                  |
| 611020                              | NO. 2 PROPELLER - LUBRICATE                                         |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS                                                                 | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                     | HRS                                                                 | 5158.2    | 400      |          | (5558.2)<br>6086.2        |           | 308.5     |                  |
| PROC. REF: MM GENERIC, POM 61-00-49 |                                                                     |           |          |          |                           |           |           |                  |
| 611025                              | NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS/MSC                                                             |           | A/R      |          |                           |           |           | CPCP             |
|                                     | HRS                                                                 |           |          |          |                           |           |           |                  |
| PROC. REF: POM 61-00-49             |                                                                     |           |          |          |                           |           |           |                  |
| 611025                              | NO. 2 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS |           |          |          |                           |           |           | Service ATA:61   |
|                                     | MOS/MSC                                                             |           | A/R      |          |                           |           |           | CPCP             |
|                                     | HRS                                                                 |           |          |          |                           |           |           |                  |
| PROC. REF: POM 61-00-49             |                                                                     |           |          |          |                           |           |           |                  |
| 611101                              | NO. 1 PROPELLER - NO. 1 PROPELLER BLADE                             |           |          |          |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                       | MOS/MSC                                                             | 29-Jan-19 | O/C      | TSO 0    |                           |           |           |                  |
| SN:J19834                           | HRS                                                                 | 4554.9    |          | TSO 0    |                           |           |           |                  |
| PROC. REF: MM GENERIC               |                                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                    | C/W       | Interval | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|-----------------------------------------|-----------|----------|---------------------------------------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                         |           |          |                                       |                           |           |           |                  |
| 611101                         | NO. 2 PROPELLER - NO. 1 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J20054                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611101                         | PROPELLER SYNCHROPHASER CONTROL BOX     |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:6852-920                    | MOS/MSC                                 | 29-Dec-98 | O/C      |                                       |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                     | 0         |          | TSN 0                                 |                           |           |           |                  |
| WC#: 61.070                    | AFL                                     | 0         |          |                                       |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: AMM 61-23-01, AMM 61-25-01 |                           |           |           |                  |
| 611102                         | NO. 1 PROPELLER - NO. 2 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J19829                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611102                         | NO. 2 PROPELLER - NO. 2 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J20051                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611103                         | NO. 1 PROPELLER - NO. 3 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J19827                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611103                         | NO. 2 PROPELLER - NO. 3 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J99020                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611104                         | NO. 1 PROPELLER - NO. 4 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J19828                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |
| 611104                         | NO. 2 PROPELLER - NO. 4 PROPELLER BLADE |           |          |                                       |                           |           |           | Component ATA:61 |
| PN:D9390SK-1R                  | MOS/MSC                                 | 29-Jan-19 | O/C      | TSO 0                                 |                           |           |           |                  |
| SN:J20059                      | HRS                                     | 4554.9    |          | TSO 0                                 |                           |           |           |                  |
|                                |                                         |           |          | PROC. REF: MM GENERIC                 |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPULSORS        |                                               |           |          |          |                           |           |           |                  |
| 611106                                | PROPELLER SYNCROPHASER ACTUATOR               |           |          |          |                           |           |           | Component ATA:61 |
| PN:5485-020                           | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.070                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01 |                                               |           |          |          |                           |           |           |                  |
| 611121                                | PROPELLER SYNCHROSCOPE                        |           |          |          |                           |           |           | Component ATA:61 |
| PN:A213796J                           | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:12117233                           | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.060                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                               |           |          |          |                           |           |           |                  |
| 611126                                | NO. 1 PROPELLER SYNCROPHASER PICK-UP          |           |          |          |                           |           |           | Component ATA:61 |
| PN:213181                             | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.080                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01 |                                               |           |          |          |                           |           |           |                  |
| 611131                                | NO.2 PROPELLER SYNCROPHASER PICK-UP           |           |          |          |                           |           |           | Component ATA:61 |
| PN:213181                             | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.080                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-23-01, AMM 61-25-01 |                                               |           |          |          |                           |           |           |                  |
| 611146                                | NO. 1 PROPELLER AUTO FEATHER HI-PRESS SWITCH  |           |          |          |                           |           |           | Component ATA:61 |
| PN:50-389121-19                       | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11610                              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.090                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                               |           |          |          |                           |           |           |                  |
| 611151                                | NO. 1 PROPELLER AUTO FEATHER LOW-PRESS SWITCH |           |          |          |                           |           |           | Component ATA:61 |
| PN:50-389121-25                       | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2285                               | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.100                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                               |           |          |          |                           |           |           |                  |
| 611156                                | NO. 1 PROPELLER AUTO FEATHER DUMP VALVE       |           |          |          |                           |           |           | Component ATA:61 |
| PN:3019906                            | MOS/MSC                                       | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.110                           | AFL                                           | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-21-01               |                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                                    |           |          |          |                           |           |           |                  |
| 611161                         | NO.2 PROPELLER AUTO FEATHER HI-PRESSURE SWITCH     |           |          |          |                           |           |           | Component ATA:61 |
| PN:50-389121-19                | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:11545                       | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.090                    | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                                    |           |          |          |                           |           |           |                  |
| 611166                         | NO.2 PROPELLER AUTO FEATHER LOW-PRESSURE SWITCH    |           |          |          |                           |           |           | Component ATA:61 |
| PN:50-389121-25                | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:2298                        | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.100                    | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                                    |           |          |          |                           |           |           |                  |
| 611171                         | NO.2 PROPELLER AUTO FEATHER DUMP VALVE             |           |          |          |                           |           |           | Component ATA:61 |
| PN:3019906                     | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.110                    | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 61-21-01        |                                                    |           |          |          |                           |           |           |                  |
| 611181                         | NO. 1 PROPELLER REVERSE NOT READY SWITCH           |           |          |          |                           |           |           | Component ATA:61 |
| PN:V3-1                        | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.120                    | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                                    |           |          |          |                           |           |           |                  |
| 611191                         | NO. 2 PROPELLER REVERSE NOT READY SWITCH           |           |          |          |                           |           |           | Component ATA:61 |
| PN:V3-1                        | MOS/MSC                                            | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 61.120                    | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                                    |           |          |          |                           |           |           |                  |
| 611230                         | NO. 1 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION |           |          |          |                           |           |           | Service ATA:61   |
|                                | MOS                                                | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                | HRS                                                | 5158.2    | 200      |          | (5358.2)<br>5886.2        |           | 108.5     |                  |
| PROC. REF: MM 30-61-80         |                                                    |           |          |          |                           |           |           |                  |
| 611230                         | NO. 2 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION |           |          |          |                           |           |           | Service ATA:61   |
|                                | MOS                                                | 22-May-24 | 12       |          | 22-May-25                 |           | 239 d     |                  |
|                                | HRS                                                | 5158.2    | 200      |          | (5358.2)<br>5886.2        |           | 108.5     |                  |
| PROC. REF: MM 30-61-80         |                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                | C/W       | Interval | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|--------------------------------|-------------------------------------|-----------|----------|---------------------------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                     |           |          |                           |                           |           |           |                                  |
| 612101                         | NO. 1 PROPELLER PITCH STOP SENSOR   |           |          |                           |                           |           |           | Component ATA:61                 |
| PN:101-960015-601              | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           |                                  |
| SN:UNKNOWN                     | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.130                    | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612106                         | NO.2 PROPELLER PITCH STOP SENSOR    |           |          |                           |                           |           |           | Component ATA:61                 |
| PN:101-960015-601              | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           |                                  |
| SN:UNKNOWN                     | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.130                    | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612111                         | NO. 1 PROPELLER PROXIMITY SWITCH    |           |          |                           |                           |           |           | Component ATA:61                 |
| PN:8-090-01                    | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           |                                  |
| SN:UNKNOWN                     | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.140                    | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 612116                         | NO. 2 PROPELLER PROXIMITY SWITCH    |           |          |                           |                           |           |           | Component ATA:61                 |
| PN:8-090-01                    | MOS/MSC                             | 29-Dec-98 | O/C      |                           |                           |           |           |                                  |
| SN:UNKNOWN                     | HRS                                 | 0         |          | TSN 0                     |                           |           |           |                                  |
| WC#: 61.140                    | AFL                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: GENERIC NO REF |                           |           |           |                                  |
| 616010                         | NO. 1 PROPELLER - DAMPER ASSEMBLY   |           |          |                           |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                             | 29-Dec-98 | N/A      |                           |                           |           |           |                                  |
|                                | HRS                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: MM GENERIC     |                           |           |           |                                  |
| 616010                         | NO. 2 PROPELLER - DAMPER ASSEMBLY   |           |          |                           |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                             | 30-Jan-09 | N/A      |                           |                           |           |           |                                  |
|                                | HRS                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: MM GENERIC     |                           |           |           |                                  |
| 619000                         | NO. 1 PROPELLER - PRE-FLIGHT CHECKS |           |          |                           |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                             | 29-Dec-98 | A/R      |                           |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                 | 0         |          |                           |                           |           |           |                                  |
|                                |                                     |           |          | PROC. REF: POM 61-00-49   |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                   | C/W       | Interval | TSX/Adj.                             | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|--------------------------------|----------------------------------------|-----------|----------|--------------------------------------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                        |           |          |                                      |                           |           |           |                                  |
| 619000                         | NO. 2 PROPELLER - PRE-FLIGHT CHECKS    |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 30-Jan-09 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: POM 61-00-49              |                           |           |           |                                  |
| 619010                         | NO. 1 PROPELLER - OPERATIONAL CHECKS   |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 29-Dec-98 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: POM 61-00-49              |                           |           |           |                                  |
| 619010                         | NO. 2 PROPELLER - OPERATIONAL CHECKS   |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 30-Jan-09 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: POM 61-00-49              |                           |           |           |                                  |
| 619020                         | NO. 1 PROPELLER - OVERSPEED/OVERTORQUE |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 29-Dec-98 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: POM 61-00-49              |                           |           |           |                                  |
| 619020                         | NO. 2 PROPELLER - OVERSPEED/OVERTORQUE |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 30-Jan-09 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: POM 61-00-49              |                           |           |           |                                  |
| 619030                         | NO. 1 PROPELLER - LIGHTNING STRIKE     |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 29-Dec-98 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: MM 30-61-80, POM 61-00-49 |                           |           |           |                                  |
| 619030                         | NO. 2 PROPELLER - LIGHTNING STRIKE     |           |          |                                      |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                | 30-Jan-09 | A/R      |                                      |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                    | 0         |          |                                      |                           |           |           |                                  |
|                                |                                        |           |          | PROC. REF: MM 30-61-80, POM 61-00-49 |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C            | Max Limit | Remaining | Disposition                      |
|--------------------------------|-------------------------------------------------------|-----------|----------|----------|--------------------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                                       |           |          |          |                                      |           |           |                                  |
| 619040                         | NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: MM 30-61-80, POM 61-00-49 |           |           |                                  |
| 619040                         | NO. 2 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: MM 30-61-80, POM 61-00-49 |           |           |                                  |
| 619050                         | NO. 1 PROPELLER - FIRE/HEAT DAMAGE                    |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: MM 30-61-80, POM 61-00-49 |           |           |                                  |
| 619050                         | NO. 2 PROPELLER - FIRE/HEAT DAMAGE                    |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: MM 30-61-80, POM 61-00-49 |           |           |                                  |
| 619060                         | NO. 1 PROPELLER - SUDDEN STOPPAGE                     |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: POM 61-00-49              |           |           |                                  |
| 619060                         | NO. 2 PROPELLER - SUDDEN STOPPAGE                     |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 30-Jan-09 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: POM 61-00-49              |           |           |                                  |
| 619070                         | NO. 1 PROPELLER - ENGINE OIL CONTAMINATION            |           |          |          |                                      |           |           | Service ATA:61                   |
|                                | MOS/MSC                                               | 29-Dec-98 | A/R      |          |                                      |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                                   | 0         |          |          |                                      |           |           |                                  |
|                                |                                                       |           |          |          | PROC. REF: POM 61-00-49              |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                        | Unit                                       | C/W       | Interval                 | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|--------------------------------|--------------------------------------------|-----------|--------------------------|------------|---------------------------|-----------|-----------|----------------------------------|
| ATA 61 - PROPELLERS/PROPULSORS |                                            |           |                          |            |                           |           |           |                                  |
| 619070                         | NO. 2 PROPELLER - ENGINE OIL CONTAMINATION |           |                          |            |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                    | 30-Jan-09 | A/R                      |            |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                        | 0         |                          |            |                           |           |           |                                  |
|                                |                                            |           | PROC. REF: POM 61-00-49  |            |                           |           |           |                                  |
| 619080                         | NO. 1 PROPELLER - LONG TERM STORAGE        |           |                          |            |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                    | 29-Dec-98 | A/R                      |            |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                        | 0         |                          |            |                           |           |           |                                  |
|                                |                                            |           | PROC. REF: POM 61-00-49  |            |                           |           |           |                                  |
| 619080                         | NO. 2 PROPELLER - LONG TERM STORAGE        |           |                          |            |                           |           |           | Service ATA:61                   |
|                                | MOS/MSC                                    | 30-Jan-09 | A/R                      |            |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                | HRS                                        | 0         |                          |            |                           |           |           |                                  |
|                                |                                            |           | PROC. REF: POM 61-00-49  |            |                           |           |           |                                  |
| 61PR1                          | NO. 1 PROPELLER                            |           |                          |            |                           |           |           | Component ATA:61                 |
| PN:HC-E4N-3G                   | MOS/MSC                                    |           | PP/C                     |            |                           |           |           |                                  |
| SN:HH561                       | HRS                                        |           |                          |            |                           |           |           |                                  |
| WC#: 61.PR1                    | AFL                                        |           |                          |            |                           |           |           |                                  |
|                                |                                            |           | PROC. REF: AMM GENERIC 1 |            |                           |           |           |                                  |
| 61PR2                          | NO. 2 PROPELLER                            |           |                          |            |                           |           |           | Component ATA:61                 |
| PN:HC-E4N-3G                   | MOS/MSC                                    | 10-Feb-12 | PP/C                     |            |                           |           |           |                                  |
| SN:HH3625                      | HRS                                        | 2770.7    |                          | TSN 2770.7 |                           |           |           |                                  |
| WC#: 61.PR2                    | AFL                                        | 2864      |                          |            |                           |           |           |                                  |
|                                |                                            |           | PROC. REF: AMM GENERIC 1 |            |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                             | C / W     | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 70 - STANDARD PRACTICES - ENGINES |                                                                                                  |           |          |          |                           |           |           |                  |
| 700010 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT            |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| 700010 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT            |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| 700020 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| 700020 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| 700030 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS                                              |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| 700030 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS                                              |           |          |          |                           |           |           | Service ATA:70   |
|                                       | MOS                                                                                              | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                              | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                              | 4184      |          |          |                           |           |           |                  |
|                                       | PROC. REF: GENERIC NO REF                                                                        |           |          |          |                           |           |           | PKG:1            |
| ATA 71 - POWER PLANT                  |                                                                                                  |           |          |          |                           |           |           |                  |
| 710001                                | LH TORQUE TRANSMITTER REPLACE                                                                    |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                                 | MOS/MSC                                                                                          | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                               | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------|------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 71 - POWER PLANT      |                                    |           |            |          |                           |           |              |                  |
| PROC. REF: AMM 77-10-05   |                                    |           |            |          |                           |           |              |                  |
| 710002                    | RH TORQUE TRANSMITTER REPLACE      |           |            |          |                           |           |              | Component ATA:71 |
| PN:PN                     | MOS/MSC                            | 29-Dec-98 | O/C        | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                | HRS                                | 0         |            | TSN 0    |                           |           |              |                  |
|                           | AFL                                | 0         |            | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 77-10-05   |                                    |           |            |          |                           |           |              |                  |
| 710010                    | NO. 1 ENGINE - OVERHAUL            |           |            |          |                           |           |              | Service ATA:71   |
|                           | MOS                                | 21-Nov-11 |            |          |                           |           |              | OVERHAUL         |
|                           | HRS                                | 2995      | 3600       |          | (6595)<br>7990.1          |           | 2212.4       |                  |
|                           | ENC                                | 2995      |            |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                    |           |            |          |                           |           |              |                  |
| 710010                    | NO. 2 ENGINE - OVERHAUL            |           |            |          |                           |           |              | Service ATA:71   |
|                           | MOS                                | 21-Nov-11 |            |          |                           |           |              | OVERHAUL         |
|                           | HRS                                | 2995      | 3600       |          | (6595)<br>7990.1          |           | 2212.4       |                  |
|                           | ENC                                | 2995      |            |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF |                                    |           |            |          |                           |           |              |                  |
| 710020                    | NO. 1 ENGINE - INSPECT HOT SECTION |           |            |          |                           |           |              | Service ATA:71   |
|                           | MOS                                | 26-Sep-22 |            |          |                           |           |              |                  |
|                           | HRS                                | 3963.4    | 1800 (+50) |          | (5763.4)<br>7158.5        | 5813.4    | 1380.8 (+50) |                  |
|                           | ENC                                | 3963      |            |          |                           |           |              |                  |
| PROC. REF: EMM 72-00-00   |                                    |           |            |          |                           |           |              |                  |
| 710020                    | NO. 2 ENGINE - INSPECT HOT SECTION |           |            |          |                           |           |              | Service ATA:71   |
|                           | MOS                                | 26-Sep-22 |            |          |                           |           |              |                  |
|                           | HRS                                | 3963.4    | 1800 (+50) |          | (5763.4)<br>7158.5        | 5813.4    | 1380.8 (+50) |                  |
|                           | ENC                                | 3963      |            |          |                           |           |              |                  |
| PROC. REF: EMM 72-00-00   |                                    |           |            |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                         | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|---------------------------------------|----------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 71 - POWER PLANT                  |                                              |           |            |          |                           |           |             |                |
| 710030                                | NO. 1 ENGINE - BORESCOPE INSPECT HOT SECTION |           |            |          |                           |           |             | Service ATA:71 |
|                                       | MOS                                          | 26-Sep-22 |            |          |                           |           |             |                |
|                                       | HRS                                          | 3963.4    | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | TOL (+20.8) |                |
|                                       | ENC                                          | 3963      |            |          |                           |           |             |                |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                              |           |            |          |                           |           |             |                |
| 710030                                | NO. 2 ENGINE - BORESCOPE INSPECT HOT SECTION |           |            |          |                           |           |             | Service ATA:71 |
|                                       | MOS                                          | 26-Sep-22 |            |          |                           |           |             |                |
|                                       | HRS                                          | 3963.4    | 400 (+10%) |          | (4363.4)<br>5758.5        | 4403.4    | TOL (+20.8) |                |
|                                       | ENC                                          | 3963      |            |          |                           |           |             |                |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                              |           |            |          |                           |           |             |                |
| 710041                                | NO. 1 ENGINE - DESALINATION (TURBINE) WASH   |           |            |          |                           |           |             | Service ATA:71 |
|                                       | DAYS/MSC                                     | 04-Jan-23 | A/R        |          |                           |           |             |                |
|                                       | HRS                                          | 4066.4    |            |          |                           |           |             |                |
|                                       | ENC                                          | 4013      |            |          |                           |           |             |                |
| PROC. REF: EMM 71-00-00               |                                              |           |            |          |                           |           |             |                |
| 710041                                | NO. 2 ENGINE - DESALINATION (TURBINE) WASH   |           |            |          |                           |           |             | Service ATA:71 |
|                                       | DAYS/MSC                                     | 04-Jan-23 | A/R        |          |                           |           |             |                |
|                                       | HRS                                          | 4066.4    |            |          |                           |           |             |                |
|                                       | ENC                                          | 4013      |            |          |                           |           |             |                |
| PROC. REF: EMM 71-00-00               |                                              |           |            |          |                           |           |             |                |
| 710050                                | NO. 1 ENGINE - COMPRESSOR WASH               |           |            |          |                           |           |             | Service ATA:71 |
|                                       | MOS/MSC                                      | 22-May-24 | A/R        |          |                           |           |             |                |
|                                       | HRS                                          | 4291.1    |            |          |                           |           |             |                |
|                                       | ENC                                          | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 71-00-00               |                                              |           |            |          |                           |           |             |                |
| 710050                                | NO. 2 ENGINE - COMPRESSOR WASH               |           |            |          |                           |           |             | Service ATA:71 |
|                                       | MOS/MSC                                      | 22-May-24 | A/R        |          |                           |           |             |                |
|                                       | HRS                                          | 4291.1    |            |          |                           |           |             |                |
|                                       | ENC                                          | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 71-00-00               |                                              |           |            |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT      |                                                     |           |          |          |                           |           |           |                  |
| 712001                    | NO. 1 ENGINE UPPER UPPER INBOARD ISOLATOR MOUNT     |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                 | 22-Jan-15 |          | TSN 0    |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                 |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                     |           |          |          |                           |           |           |                  |
| 712002                    | NO. 1 ENGINE OUTBOARD UPPER OUTBOARD ISOLATOR MOUNT |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                 | 22-Jan-15 |          | TSN 0    |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                 |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                     |           |          |          |                           |           |           |                  |
| 712003                    | NO. 1 ENGINE LOWER LOWER INBOARD ISOLATOR MOUNT     |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                 | 22-Jan-15 |          | TSN 0    |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                 |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                     |           |          |          |                           |           |           |                  |
| 712004                    | NO. 1 ENGINE OUTBOARD LOWER OUTBOARD ISOLATOR MOUNT |           |          |          |                           |           |           | Component ATA:71 |
|                           | MOS                                                 | 22-Jan-15 |          |          |                           |           |           | REPLACE          |
|                           | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
| WC#: 72.030               | AFL                                                 |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 712601                    | NO. 2 ENGINE UPPER UPPER INBOARD ISOLATOR MOUNT     |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                 | 22-Jan-15 |          | TSN 0    |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                 |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                     |           |          |          |                           |           |           |                  |
| 712602                    | NO. 2 ENGINE OUTBOARD UPPER OUTBOARD ISOLATOR MOUNT |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                 | 22-Jan-15 |          | TSN 0    |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                 | 3243.3    | 3600     | TSN 0    | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                 |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                  | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT      |                                                       |           |          |            |                           |           |           |                  |
| 712603                    | NO. 2 ENGINE LOWER LOWER INBOARD ISOLATOR MOUNT       |           |          |            |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS                                                   | 22-Jan-15 |          | TSN 0      |                           |           |           | REPLACE          |
| SN:UNKNOWN                | HRS                                                   | 3243.3    | 3600     | TSN 0      | 6843.3                    |           | 1065.6    |                  |
|                           | AFL                                                   |           |          | TSN 0      |                           |           |           |                  |
| PROC. REF: AMM 71-20-01   |                                                       |           |          |            |                           |           |           |                  |
| 712604                    | NO. 2 ENGINE LOWER OUTBOARD ISOLATOR MOUNT            |           |          |            |                           |           |           | Component ATA:71 |
|                           | MOS                                                   | 22-Jan-15 |          |            |                           |           |           | REPLACE          |
|                           | HRS                                                   | 3243.3    | 3600     | TSN 0      | 6843.3                    |           | 1065.6    |                  |
| WC#: 72.030               | AFL                                                   |           |          |            |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |          |            |                           |           |           |                  |
| 71EN1                     | NO. 1 ENGINE                                          |           |          |            |                           |           |           | Component ATA:71 |
| PN:3030700                | MOS/MSC                                               | 13-Feb-19 | E/C      |            |                           |           |           |                  |
| SN:PCE-94718              | HRS                                                   | 5082.9    |          | TSN 3688.3 |                           |           |           |                  |
|                           | AFL                                                   | 6044      |          |            |                           |           |           |                  |
| PROC. REF: AMM 71-00-01   |                                                       |           |          |            |                           |           |           |                  |
| 71EN2                     | NO. 2 ENGINE                                          |           |          |            |                           |           |           | Component ATA:71 |
| PN:3030700                | MOS/MSC                                               | 13-Feb-19 | E/C      |            |                           |           |           |                  |
| SN:PCE-94709              | HRS                                                   | 5082.9    |          | TSN 3688.3 |                           |           |           |                  |
|                           | AFL                                                   | 6044      |          |            |                           |           |           |                  |
| PROC. REF: AMM 71-00-01   |                                                       |           |          |            |                           |           |           |                  |
| ATA 72 - ENGINE           |                                                       |           |          |            |                           |           |           |                  |
| 720010                    | NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE |           |          |            |                           |           |           | Service ATA:72   |
|                           | MOS/MSC                                               | 20-Dec-94 | A/R      |            |                           |           |           |                  |
|                           | HRS                                                   | 0         |          |            |                           |           |           |                  |
|                           | ENC                                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: EMM 72-00-00   |                                                       |           |          |            |                           |           |           |                  |
| 720010                    | NO. 2 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE |           |          |            |                           |           |           | Service ATA:72   |
|                           | MOS/MSC                                               | 20-Dec-94 | A/R      |            |                           |           |           |                  |
|                           | HRS                                                   | 0         |          |            |                           |           |           |                  |
|                           | ENC                                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: EMM 72-00-00   |                                                       |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                       |                                                                                            |           |          |          |                           |           |           |                  |
| 721000 <sup>S</sup>                   | NO. 1 ENGINE - VISUAL INSPECTION WITH A MIRROR OR A BORESCOPE FIRST-STAGE COMPRESSOR ROTOR |           |          |          |                           |           |           | Service ATA:72   |
|                                       | MOS                                                                                        | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                        | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                        | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                                                                            |           |          |          |                           |           | PKG:1     |                  |
| 721000 <sup>S</sup>                   | NO. 2 ENGINE - VISUAL INSPECTION WITH A MIRROR OR A BORESCOPE FIRST-STAGE COMPRESSOR ROTOR |           |          |          |                           |           |           | Service ATA:72   |
|                                       | MOS                                                                                        | 22-May-24 |          |          |                           |           |           |                  |
|                                       | HRS                                                                                        | 4291.1    | 200      |          |                           |           |           |                  |
|                                       | ENC                                                                                        | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-00-00, EMM 72-00-00 |                                                                                            |           |          |          |                           |           | PKG:1     |                  |
| 721002                                | NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                                 | MOS/MSC                                                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | ENC                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |          |          |                           |           |           |                  |
| 721002                                | NO. 2 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                                 | MOS/MSC                                                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | ENC                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |          |          |                           |           |           |                  |
| 721003                                | NO. 1 ENGINE - NO. 2 SECOND STAGE REDUCTION PLANET GEAR                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                                 | MOS/MSC                                                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | ENC                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |          |          |                           |           |           |                  |
| 721003                                | NO. 2 ENGINE - NO. 2 SECOND STAGE REDUCTION PLANET GEAR                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                                 | MOS/MSC                                                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | ENC                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |          |          |                           |           |           |                  |
| 721004                                | NO. 1 ENGINE - NO. 3 SECOND STAGE REDUCTION PLANET GEAR                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                                 | MOS/MSC                                                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                       | ENC                                                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                                                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                         |           |          |          |                           |           |           |                  |
| 721004                    | NO. 2 ENGINE - NO. 3 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721005                    | NO. 1 ENGINE - NO. 4 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721005                    | NO. 2 ENGINE - NO. 4 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721006                    | NO. 1 ENGINE - NO. 5 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721006                    | NO. 2 ENGINE - NO. 5 SECOND STAGE REDUCTION PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721007                    | NO. 1 ENGINE - FLEX 2ND STAGE REDUCTION COUPLING SHAFT  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 721007                    | NO. 2 ENGINE - FLEX 2ND STAGE REDUCTION COUPLING SHAFT  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                     |           |          |          |                           |           |           |                  |
| 721008                    | NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER        |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721008                    | NO. 2 ENGINE - FIRST STAGE REDUCTION CARRIER        |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721009                    | NO. 1 ENGINE - SECOND STAGE REDUCTION,46 TEETH GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721009                    | NO. 2 ENGINE - SECOND STAGE REDUCTION,46 TEETH GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721011                    | NO. 1 ENGINE - 1ST STAGE CARRIE ADAPTER             |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721011                    | NO. 2 ENGINE - 1ST STAGE CARRIE ADAPTER             |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 721012                    | NO. 1 ENGINE - SECOND STAGE REDUCTION CARRIER       |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                             | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                 |           |          |          |                           |           |           |                  |
| 721012                    | NO. 2 ENGINE - SECOND STAGE REDUCTION CARRIER   |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 721013                    | NO. 1 ENGINE - ROLLER FLANGED BEARING           |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 721013                    | NO. 2 ENGINE - ROLLER FLANGED BEARING           |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 721014                    | NO. 1 ENGINE - SECOND STAGE REDUCTION GEAR RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 721014                    | NO. 2 ENGINE - SECOND STAGE REDUCTION GEAR RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           |                  |
| 721015                    | NO. 1 ENGINE - PROPELLER SHAFT                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-00-00   |                                                 |           |          |          |                           |           |           |                  |
| 721015                    | NO. 2 ENGINE - PROPELLER SHAFT                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                         | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-00-00   |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                |           |          |          |                           |           |           |                  |
| 721016                    | NO. 1 ENGINE - NO. 1 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721016                    | NO. 2 ENGINE - NO. 1 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721017                    | NO. 1 ENGINE - NO. 2 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721017                    | NO. 2 ENGINE - NO. 2 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721018                    | NO. 1 ENGINE - NO. 3 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721018                    | NO. 2 ENGINE - NO. 3 1ST STAGE REDUCTION, 45 TEETH PLANET GEAR |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 721019                    | NO. 1 ENGINE - FIRST STAGE REDUCTION GEAR RING                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                    |           |          |          |                           |           |           |                  |
| 721019                    | NO. 2 ENGINE - FIRST STAGE REDUCTION GEAR RING                     |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 721020                    | NO. 1 ENGINE - BALL2.9528X5.1181X.9843 BEARING                     |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 721020                    | NO. 2 ENGINE - BALL2.9528X5.1181X.9843 BEARING                     |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 721021                    | NO. 1 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 721021                    | NO. 2 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 721022                    | NO. 1 ENGINE - TURBINE EXHAUST DUCT ASSEMBLY                       |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-03   |                                                                    |           |          |          |                           |           |           |                  |
| 721022                    | NO. 2 ENGINE - TURBINE EXHAUST DUCT ASSEMBLY                       |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                            | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-03   |                                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE         |                                                                                                                        |           |          |          |                           |           |           |                  |
| 721023                  | NO. 1 ENGINE - TURBINE STATOR POWER HOUSING                                                                            |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                   | MOS/MSC                                                                                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                                                                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | ENC                                                                                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-03 |                                                                                                                        |           |          |          |                           |           |           |                  |
| 721023                  | NO. 2 ENGINE - TURBINE STATOR POWER HOUSING                                                                            |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                   | MOS/MSC                                                                                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                                                                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                         | ENC                                                                                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-03 |                                                                                                                        |           |          |          |                           |           |           |                  |
| 722000 <sup>S</sup>     | NO. 1 ENGINE - INSPECT AIR INLET SCREEN FOR CLEANLINESS                                                                |           |          |          |                           |           |           | Service ATA:72   |
|                         | MOS                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                         | HRS                                                                                                                    | 4291.1    | 200      |          |                           |           |           |                  |
|                         | ENC                                                                                                                    | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-20-00 |                                                                                                                        |           |          |          |                           |           |           | PKG:1            |
| 722000 <sup>S</sup>     | NO. 2 ENGINE - INSPECT AIR INLET SCREEN FOR CLEANLINESS                                                                |           |          |          |                           |           |           | Service ATA:72   |
|                         | MOS                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                         | HRS                                                                                                                    | 4291.1    | 200      |          |                           |           |           |                  |
|                         | ENC                                                                                                                    | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-20-00 |                                                                                                                        |           |          |          |                           |           |           | PKG:1            |
| 722010 <sup>S</sup>     | NO. 1 ENGINE - INSPECT INLET SURFACE AREAS, WITH SCREEN REMOVED, INSPECT OVERALL SURFACE AREA AND STRUTS FOR CORROSION |           |          |          |                           |           |           | Service ATA:72   |
|                         | MOS                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                         | HRS                                                                                                                    | 4291.1    | 200      |          |                           |           |           |                  |
|                         | ENC                                                                                                                    | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-20-00 |                                                                                                                        |           |          |          |                           |           |           | PKG:1            |
| 722010 <sup>S</sup>     | NO. 2 ENGINE - INSPECT INLET SURFACE AREAS, WITH SCREEN REMOVED, INSPECT OVERALL SURFACE AREA AND STRUTS FOR CORROSION |           |          |          |                           |           |           | Service ATA:72   |
|                         | MOS                                                                                                                    | 22-May-24 |          |          |                           |           |           |                  |
|                         | HRS                                                                                                                    | 4291.1    | 200      |          |                           |           |           |                  |
|                         | ENC                                                                                                                    | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-20-00 |                                                                                                                        |           |          |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                             |           |          |          |                           |           |           |                  |
| 723001                    | NO. 1 ENGINE - FRONT COMPRESSOR STUB SHAFT  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723001                    | NO. 2 ENGINE - FRONT COMPRESSOR STUB SHAFT  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723002                    | NO. 1 ENGINE - BALL BEARING                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723002                    | NO. 2 ENGINE - BALL BEARING                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723003                    | NO. 1 ENGINE - COMPRESSOR REAR HUB COUPLING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723003                    | NO. 2 ENGINE - COMPRESSOR REAR HUB COUPLING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                             |           |          |          |                           |           |           |                  |
| 723004                    | NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                            |           |          |          |                           |           |           |                  |
| 723004                    | NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                                            |           |          |          |                           |           |           |                  |
| 723010                    | NO. 1 ENGINE - COMPRESSOR 1ST STAGE HUB / COMPRESSOR ROTOR |           |          |          |                           |           |           | Component ATA:72 |
| PN:3041501                | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:89A368                 | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                     | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 723010                    | NO. 2 ENGINE - COMPRESSOR 1ST STAGE HUB / COMPRESSOR ROTOR |           |          |          |                           |           |           | Component ATA:72 |
| PN:3041501                | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:83A008                 | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                     | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 723030                    | NO. 1 ENGINE - COMPRESSOR 2ND STAGE DISK                   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3023112                | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:89A798                 | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15761     |                  |
|                           | ACCCYC                                                     | 0         | 20000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 723030                    | NO. 2 ENGINE - COMPRESSOR 2ND STAGE DISK                   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3023112                | MOS                                                        | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:79A549                 | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15761     |                  |
|                           | ACCCYC                                                     | 0         | 20000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                                                                                    |           |          |          |                           |           |           |                  |
| 723040                    | NO. 1 ENGINE - COMPRESSOR 3RD STAGE DISK                                                                                           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3023113                | MOS                                                                                                                                | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:89A805                 | HRS                                                                                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                                                                                | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15761     |                  |
|                           | ACCCYC                                                                                                                             | 0         | 20000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                    |           |          |          |                           |           |           |                  |
| 723040                    | NO. 2 ENGINE - COMPRESSOR 3RD STAGE DISK                                                                                           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3023113                | MOS                                                                                                                                | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:89A490                 | HRS                                                                                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                                                                                | 0         |          | TSN 0    | (20000)<br>22311 (M)      |           | 15761     |                  |
|                           | ACCCYC                                                                                                                             | 0         | 20000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                                                    |           |          |          |                           |           |           |                  |
| 723050 <sup>S</sup>       | NO. 1 ENGINE - INSPECT GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION AND CORROSION |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                                                                                                                    |           |          |          |                           |           |           | PKG:1            |
| 723050 <sup>S</sup>       | NO. 2 ENGINE - INSPECT GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION AND CORROSION |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                                                                                                                    |           |          |          |                           |           |           | PKG:1            |
| 723055 <sup>S</sup>       | NO. 1 ENGINE - INSPECT FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS                                        |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                                                                                                                    |           |          |          |                           |           |           | PKG:1            |
| 723055 <sup>S</sup>       | NO. 2 ENGINE - INSPECT FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS                                        |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                                                                | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                                                                | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                                                                | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-30-04   |                                                                                                                                    |           |          |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                        |           |          |          |                           |           |           |                  |
| 723060                    | NO. 1 ENGINE - CENTRIFUGAL IMPELLER                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3036793                | MOS                                                    | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1F004                  | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    | (24000)<br>26311 (M)      |           | 19761     |                  |
|                           | ACCCYC                                                 | 0         | 24000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |
| 723060                    | NO. 2 ENGINE - CENTRIFUGAL IMPELLER                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3036793                | MOS                                                    | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:9E700                  | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    | (24000)<br>26311 (M)      |           | 19761     |                  |
|                           | ACCCYC                                                 | 0         | 24000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |
| 724000                    | NO. 1 ENGINE - COMBUST CHAMBER OUTER LINER ASSEMBLY    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |
| 724000                    | NO. 2 ENGINE - COMBUST CHAMBER OUTER LINER ASSEMBLY    |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |
| 724001                    | NO. 1 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |
| 724001                    | NO. 2 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                               |           |          |          |                           |           |           |                  |
| 725000                    | NO. 1 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725000                    | NO. 2 ENGINE - POWER TURBINE SHAFT                            |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725001                    | NO. 1 ENGINE - 1ST STAGE REDUCTION, 26 TEETH SUN GEAR         |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725001                    | NO. 2 ENGINE - 1ST STAGE REDUCTION, 26 TEETH SUN GEAR         |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725002                    | NO. 1 ENGINE - POWER TURBINE SHAFT SHAFT                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725002                    | NO. 2 ENGINE - POWER TURBINE SHAFT SHAFT                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725005 <sup>S</sup>       | NO. 1 ENGINE - INSPECT EXHAUST DUCT FOR CRACKS AND DISTORTION |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                           | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                           | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                           | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-50-05   |                                                               |           |          |          |                           |           |           |                  |

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                               |           |          |          |                           |           |           |                  |
| 725005 <sup>S</sup>       | NO. 2 ENGINE - INSPECT EXHAUST DUCT FOR CRACKS AND DISTORTION |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                           | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                           | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                           | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-50-05   |                                                               |           |          |          |                           |           | PKG:1     |                  |
| 725006                    | NO. 1 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY           |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725006                    | NO. 2 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY           |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725008                    | NO. 1 ENGINE - POWER TURBINE COUPLING                         |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725008                    | NO. 2 ENGINE - POWER TURBINE COUPLING                         |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725009                    | NO. 1 ENGINE - BALL.1,181X2.8345X.743,FLANGE BEARING          |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |
| 725009                    | NO. 2 ENGINE - BALL.1,181X2.8345X.743,FLANGE BEARING          |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                       | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                        |           |          |          |                           |           |           |                  |
| 725010                    | NO. 1 ENGINE - COMPRESSOR TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3049291-01             | MOS                                    | 21-Nov-11 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A0031EAB               | HRS                                    | 2984.9    |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 2985      |          | TSN 0    | (12985)<br>15296 (M)      |           | 8746      |                  |
|                           | ACCCYC                                 | 0         | 10000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |
| 725010                    | NO. 2 ENGINE - COMPRESSOR TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3049291-01             | MOS                                    | 21-Nov-11 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A0030CA4               | HRS                                    | 2984.9    |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 2985      |          | TSN 0    | (12985)<br>15296 (M)      |           | 8746      |                  |
|                           | ACCCYC                                 | 0         | 10000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                        |           |          |          |                           |           |           |                  |
| 725013                    | NO. 1 ENGINE - NO. 1 TURBINE VANE-RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                        |           |          |          |                           |           |           |                  |
| 725013                    | NO. 2 ENGINE - NO. 1 TURBINE VANE-RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                        |           |          |          |                           |           |           |                  |
| 725014                    | NO. 1 ENGINE - NO. 2 TURBINE VANE-RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                        |           |          |          |                           |           |           |                  |
| 725014                    | NO. 2 ENGINE - NO. 2 TURBINE VANE-RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                |           |          |          |                           |           |           |                  |
| 725015                    | NO. 1 ENGINE - TURBINE VANE-RING                               |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                                                |           |          |          |                           |           |           |                  |
| 725015                    | NO. 2 ENGINE - TURBINE VANE-RING                               |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 72-50-01   |                                                                |           |          |          |                           |           |           |                  |
| 725017                    | NO. 1 ENGINE - NO. 1 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 725017                    | NO. 2 ENGINE - NO. 1 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 725018                    | NO. 1 ENGINE - NO. 2 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |
| 725018                    | NO. 2 ENGINE - NO. 2 ROLLER FLANGE 1.5748X2.6772X.5906 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                        | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                         |           |          |          |                           |           |           |                  |
| 725030                    | NO. 1 ENGINE - POWER TURBINE 1ST STAGE DISK                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3029312                | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:86A803                 | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 725030                    | NO. 2 ENGINE - POWER TURBINE 1ST STAGE DISK                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3029312                | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:86A102                 | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 725040                    | NO. 1 ENGINE - POWER TURBINE 2ND STAGE DISK                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3029313                | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:86A926                 | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 725040                    | NO. 2 ENGINE - POWER TURBINE 2ND STAGE DISK                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3029313                | MOS                                                                     | 20-Dec-94 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:86A126                 | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                     | 0         |          | TSN 0    | (30000)<br>32311 (M)      |           | 25761     |                  |
|                           | ACCCYC                                                                  | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 726015                    | NO. 1 ENGINE - INSPECT/REPLACE 1ST STAGE REDUCTION PLANET GEAR BEARINGS |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                     | 21-Nov-11 |          |          |                           |           |           |                  |
|                           | HRS                                                                     | 2995      | 3600     |          | (6595)<br>7990.1          |           | 2212.4    |                  |
|                           | ENC                                                                     | 2995      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                             |           |          |          |                           |           |           |                  |
| 726015                    | NO. 2 ENGINE - INSPECT/REPLACE 1ST STAGE REDUCTION PLANET GEAR BEARINGS     |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                         | 21-Nov-11 |          |          |                           |           |           |                  |
|                           | HRS                                                                         | 2995      | 3600     |          | (6595)<br>7990.1          |           | 2212.4    |                  |
|                           | ENC                                                                         | 2995      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |           |          |          |                           |           |           |                  |
| 726040                    | NO. 1 ENGINE - DO A VISUAL INSPECTION OF STARTER GENERATOR SPLINES FOR WEAR |           |          |          |                           |           |           | Service ATA:72   |
| PN:PN                     | MOS/MSC                                                                     | 20-Dec-94 | A/R      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                         | 0         |          |          |                           |           |           |                  |
|                           | ENC                                                                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-60-00   |                                                                             |           |          |          |                           |           |           |                  |
| 726040                    | NO. 2 ENGINE - DO A VISUAL INSPECTION OF STARTER GENERATOR SPLINES FOR WEAR |           |          |          |                           |           |           | Service ATA:72   |
| PN:PN                     | MOS/MSC                                                                     | 20-Dec-94 | A/R      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                         | 0         |          |          |                           |           |           |                  |
|                           | ENC                                                                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: EMM 72-60-00   |                                                                             |           |          |          |                           |           |           |                  |
| 726051                    | NO. 1 ENGINE - NO. 1 ROLLER FLANGE 9451X1.665X4699 BEARING                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |           |          |          |                           |           |           |                  |
| 726051                    | NO. 1 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT                            |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |           |          |          |                           |           |           |                  |
| 726051                    | NO. 2 ENGINE - NO. 1 ROLLER FLANGE 9451X1.665X4699 BEARING                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                            |           |          |          |                           |           |           |                  |
| 726051                    | NO. 2 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT           |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726052                    | NO. 1 ENGINE - NO. 2 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726052                    | NO. 2 ENGINE - NO. 2 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726053                    | NO. 1 ENGINE - NO. 3 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726053                    | NO. 2 ENGINE - NO. 3 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726054                    | NO. 1 ENGINE - NO. 4 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726054                    | NO. 2 ENGINE - NO. 4 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                            |           |          |          |                           |           |           |                  |
| 726055                    | NO. 1 ENGINE - NO. 5 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726055                    | NO. 2 ENGINE - NO. 5 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726056                    | NO. 1 ENGINE - NO. 6 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726056                    | NO. 2 ENGINE - NO. 6 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726057                    | NO. 1 ENGINE - NO. 7 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726057                    | NO. 2 ENGINE - NO. 7 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |
| 726058                    | NO. 1 ENGINE - NO. 8 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                    | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                             |           |          |          |                           |           |           |                  |
| 726058                    | NO. 2 ENGINE - NO. 8 ROLLER FLANGE 9451X1.665X4699 BEARING  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726059                    | NO. 1 ENGINE - NO. 9 ROLLER FLANGE 9451X1.665X4699 BEARING  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726059                    | NO. 2 ENGINE - NO. 9 ROLLER FLANGE 9451X1.665X4699 BEARING  |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726060                    | NO. 1 ENGINE - NO. 10 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726060                    | NO. 2 ENGINE - NO. 10 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726061                    | NO. 1 ENGINE - NO. 11 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |
| 726061                    | NO. 2 ENGINE - NO. 11 ROLLER FLANGE 9451X1.665X4699 BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                     | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                                                         |           |          |          |                           |           |           |                  |
| 726062                    | NO. 1 ENGINE - NO. 12 ROLLER FLANGE 9451X1.665X4699 BEARING                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 726062                    | NO. 2 ENGINE - NO. 12 ROLLER FLANGE 9451X1.665X4699 BEARING                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:PN                     | MOS/MSC                                                                                 | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 728005 <sup>S</sup>       | NO. 1 ENGINE - INSPECT ACCESSORIES FOR ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                     | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                     | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                     | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           | PKG:1            |
| 728005 <sup>S</sup>       | NO. 2 ENGINE - INSPECT ACCESSORIES FOR ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                     | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                     | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                     | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           | PKG:1            |
| 728015 <sup>S</sup>       | NO. 1 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE                 |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                     | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                     | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                     | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           | PKG:1            |
| 728015 <sup>S</sup>       | NO. 2 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE                 |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                     | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                     | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                     | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           | PKG:1            |
| 731200 <sup>S</sup>       | NO. 1 ENGINE - CHECK FUEL PUMP OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION           |           |          |          |                           |           |           | Service ATA:72   |
|                           | MOS                                                                                     | 22-May-24 |          |          |                           |           |           |                  |
|                           | HRS                                                                                     | 4291.1    | 200      |          |                           |           |           |                  |
|                           | ENC                                                                                     | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                  |                                                                                                     |           |          |          |                           |           |           |                  |
| 731200 <sup>S</sup>              | NO. 2 ENGINE - CHECK FUEL PUMP OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION                       |           |          |          |                           |           |           | Service ATA:72   |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                     |           |          |          |                           |           |           | PKG:1            |
| 731205 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |          |          |                           |           |           | Service ATA:72   |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-06          |                                                                                                     |           |          |          |                           |           |           | PKG:1            |
| 731205 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |          |          |                           |           |           | Service ATA:72   |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-06          |                                                                                                     |           |          |          |                           |           |           | PKG:1            |
| 733115 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE   |           |          |          |                           |           |           | Service ATA:72   |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                     |           |          |          |                           |           |           | PKG:1            |
| 733115 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE   |           |          |          |                           |           |           | Service ATA:72   |
|                                  | MOS                                                                                                 | 22-May-24 |          |          |                           |           |           |                  |
|                                  | HRS                                                                                                 | 4291.1    | 200      |          |                           |           |           |                  |
|                                  | ENC                                                                                                 | 4184      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                     |           |          |          |                           |           |           | PKG:1            |
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                     |           |          |          |                           |           |           |                  |
| 730700                           | LEFT ENGINE FUEL COLLECTOR PUMP                                                                     |           |          |          |                           |           |           | Component ATA:73 |
| PN:476284                        | MOS/MSC                                                                                             | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                                                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 73.070                      | AFL                                                                                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                            |           |             |          |                           |           |               |                  |
| 730706                           | RIGHT ENGINE FUEL COLLECTOR PUMP                           |           |             |          |                           |           |               | Component ATA:73 |
| PN:476284                        | MOS/MSC                                                    | 29-Dec-98 | O/C         |          |                           |           |               |                  |
| SN:UNKNOWN                       | HRS                                                        | 0         |             | TSN 0    |                           |           |               |                  |
| WC#: 73.070                      | AFL                                                        | 0         |             |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                            |           |             |          |                           |           |               |                  |
| 731001                           | NO. 1 ENGINE - FUEL FLOW DIVIDER                           |           |             |          |                           |           |               | Component ATA:73 |
| PN:PN                            | MOS/MSC                                                    | 20-Dec-94 | O/C         | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN                       | HRS                                                        | 0         |             | TSN 0    |                           |           |               |                  |
|                                  | ENC                                                        | 0         |             | TSN 0    |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                            |           |             |          |                           |           |               |                  |
| 731001                           | NO. 2 ENGINE - FUEL FLOW DIVIDER                           |           |             |          |                           |           |               | Component ATA:73 |
| PN:PN                            | MOS/MSC                                                    | 20-Dec-94 | O/C         | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN                       | HRS                                                        | 0         |             | TSN 0    |                           |           |               |                  |
|                                  | ENC                                                        | 0         |             | TSN 0    |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                            |           |             |          |                           |           |               |                  |
| 731004                           | NO. 1 ENGINE - STARTING CONTROL INSTALLATION/ FLOW DIVIDER |           |             |          |                           |           |               | Component ATA:73 |
| PN:3036640                       | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:2019                          | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-04          |                                                            |           |             |          |                           |           |               |                  |
| 731004                           | NO. 2 ENGINE - STARTING CONTROL INSTALLATION/ FLOW DIVIDER |           |             |          |                           |           |               | Component ATA:73 |
| PN:3036640                       | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:1997                          | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-04          |                                                            |           |             |          |                           |           |               |                  |
| 731010                           | NO. 1 ENGINE - ENGINE DRIVEN FUEL PUMP                     |           |             |          |                           |           |               | Component ATA:73 |
| PN:025323-300-03                 | MOS                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:10239                         | HRS                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                        | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-02          |                                                            |           |             |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|----------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                            |           |             |          |                           |           |               |                  |
| 731010                           | NO. 2 ENGINE - ENGINE DRIVEN FUEL PUMP                                     |           |             |          |                           |           |               | Component ATA:73 |
| PN:025323-300-03                 | MOS                                                                        | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:10217                         | HRS                                                                        | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                        | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-02          |                                                                            |           |             |          |                           |           |               |                  |
| 731020                           | NO. 1 ENGINE - CLEAN FUEL NOZZLES                                          |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                        | 26-Sep-22 |             |          |                           |           |               |                  |
|                                  | HRS                                                                        | 3963.4    | 400 (+10%)  |          | (4363.4)<br>5758.5        | 4403.4    | TOL (+20.8)   |                  |
|                                  | ENC                                                                        | 3963      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-05          |                                                                            |           |             |          |                           |           |               |                  |
| 731020                           | NO. 2 ENGINE - CLEAN FUEL NOZZLES                                          |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                        | 26-Sep-22 |             |          |                           |           |               |                  |
|                                  | HRS                                                                        | 3963.4    | 400 (+10%)  |          | (4363.4)<br>5758.5        | 4403.4    | TOL (+20.8)   |                  |
|                                  | ENC                                                                        | 3963      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-05          |                                                                            |           |             |          |                           |           |               |                  |
| 731025                           | NO. 1 ENGINE - LEAK/FUNCTIONAL TEST MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                        | 12-Apr-23 |             |          |                           |           |               |                  |
|                                  | HRS                                                                        | 4105.2    | 400 (+10%)  |          | (4505.2)<br>5900.3        | 4545.2    | 122.6 (+40)   |                  |
|                                  | ENC                                                                        | 4047      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-05          |                                                                            |           |             |          |                           |           |               |                  |
| 731025                           | NO. 2 ENGINE - LEAK/FUNCTIONAL TEST MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                        | 12-Apr-23 |             |          |                           |           |               |                  |
|                                  | HRS                                                                        | 4105.2    | 400 (+10%)  |          | (4505.2)<br>5900.3        | 4545.2    | 122.6 (+40)   |                  |
|                                  | ENC                                                                        | 4047      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-05          |                                                                            |           |             |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                                                                                  | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|---------------------------------------|-------------------------------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL      |                                                                                                       |           |            |          |                           |           |             |                |
| 731030                                | NO. 1 ENGINE - INSPECT/REPLACE ENGINE DRIVEN FUEL PUMP OUTLET FILTER                                  |           |            |          |                           |           |             | Service ATA:73 |
| PN:025323-300-03                      | MOS                                                                                                   | 22-May-24 |            |          |                           |           |             |                |
| SN:10239                              | HRS                                                                                                   | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                |
|                                       | ENC                                                                                                   | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 73-10-02               |                                                                                                       |           |            |          |                           |           |             |                |
| 731030                                | NO. 2 ENGINE - INSPECT/REPLACE ENGINE DRIVEN FUEL PUMP OUTLET FILTER                                  |           |            |          |                           |           |             | Service ATA:73 |
| PN:025323-300-03                      | MOS                                                                                                   | 22-May-24 |            |          |                           |           |             |                |
| SN:10217                              | HRS                                                                                                   | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                |
|                                       | ENC                                                                                                   | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 73-10-02               |                                                                                                       |           |            |          |                           |           |             |                |
| 731040                                | NO. 1 ENGINE - CHECK/CLEAN/REPLACE ENGINE DRIVEN FUEL PUMP INLET SCREEN                               |           |            |          |                           |           |             | Service ATA:73 |
| PN:025323-300-03                      | MOS                                                                                                   | 22-May-24 |            |          |                           |           |             |                |
| SN:10239                              | HRS                                                                                                   | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                |
|                                       | ENC                                                                                                   | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 73-10-02, EMM 73-10-02 |                                                                                                       |           |            |          |                           |           |             |                |
| 731040                                | NO. 2 ENGINE - CHECK/CLEAN/REPLACE ENGINE DRIVEN FUEL PUMP INLET SCREEN                               |           |            |          |                           |           |             | Service ATA:73 |
| PN:025323-300-03                      | MOS                                                                                                   | 22-May-24 |            |          |                           |           |             |                |
| SN:10217                              | HRS                                                                                                   | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                |
|                                       | ENC                                                                                                   | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 73-10-02, EMM 73-10-02 |                                                                                                       |           |            |          |                           |           |             |                |
| 731050                                | NO. 1 ENGINE - CHECK ENGINE DRIVEN FUEL PUMP THE FUEL PUMP COUPLING IN-SITU FOR FRETING AND CORROSION |           |            |          |                           |           |             | Service ATA:73 |
| PN:025323-300-03                      | MOS                                                                                                   | 22-May-24 |            |          |                           |           |             |                |
| SN:10239                              | HRS                                                                                                   | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                |
|                                       | ENC                                                                                                   | 4184      |            |          |                           |           |             |                |
| PROC. REF: EMM 73-10-02               |                                                                                                       |           |            |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                                                  | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|-------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                       |           |             |          |                           |           |               |                  |
| 731050                           | NO. 2 ENGINE - CHECK ENGINE DRIVEN FUEL PUMP THE FUEL PUMP COUPLING IN-SITU FOR FRETING AND CORROSION |           |             |          |                           |           |               | Service ATA:73   |
| PN:025323-300-03                 | MOS                                                                                                   | 22-May-24 |             |          |                           |           |               |                  |
| SN:10217                         | HRS                                                                                                   | 4291.1    | 600 (+10%)  |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60)   |                  |
|                                  | ENC                                                                                                   | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-02          |                                                                                                       |           |             |          |                           |           |               |                  |
| 731055                           | NO. 1 ENGINE - REMOVE/INSPECT ENGINE DRIVEN FUEL PUMP FUEL PUMP DRIVE COUPLING AND COVER              |           |             |          |                           |           |               | Service ATA:73   |
| PN:025323-300-03                 | MOS                                                                                                   | 21-Nov-11 |             |          |                           |           |               |                  |
| SN:10239                         | HRS                                                                                                   | 2995      | 1800 (+100) |          | (4795)<br>6190.1          | 4895      | 412.4 (+100)  |                  |
|                                  | ENC                                                                                                   | 2995      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-02          |                                                                                                       |           |             |          |                           |           |               |                  |
| 731055                           | NO. 2 ENGINE - REMOVE/INSPECT ENGINE DRIVEN FUEL PUMP FUEL PUMP DRIVE COUPLING AND COVER              |           |             |          |                           |           |               | Service ATA:73   |
| PN:025323-300-03                 | MOS                                                                                                   | 21-Nov-11 |             |          |                           |           |               |                  |
| SN:10217                         | HRS                                                                                                   | 2995      | 1800 (+100) |          | (4795)<br>6190.1          | 4895      | 412.4 (+100)  |                  |
|                                  | ENC                                                                                                   | 2995      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-02          |                                                                                                       |           |             |          |                           |           |               |                  |
| 731060                           | NO. 1 ENGINE - OIL TO FUEL HEATER                                                                     |           |             |          |                           |           |               | Component ATA:73 |
| PN:10585K                        | MOS                                                                                                   | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:WA4376                        | HRS                                                                                                   | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                   | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                       |           |             |          |                           |           |               |                  |
| 731060                           | NO. 2 ENGINE - OIL TO FUEL HEATER                                                                     |           |             |          |                           |           |               | Component ATA:73 |
| PN:10585K                        | MOS                                                                                                   | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:WA3822                        | HRS                                                                                                   | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                   | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                       |           |             |          |                           |           |               |                  |
| 731065 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION        |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                   | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                   | 4291.1    | 200 (+10%)  |          |                           |           |               |                  |
|                                  | ENC                                                                                                   | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                       |           |             |          |                           |           |               |                  |
|                                  |                                                                                                       |           |             |          |                           |           |               | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                                           | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|------------------------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                |           |            |          |                           |           |           |                  |
| 731065 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION |           |            |          |                           |           |           | Service ATA:73   |
|                                  | MOS                                                                                            | 22-May-24 |            |          |                           |           |           |                  |
|                                  | HRS                                                                                            | 4291.1    | 200 (+10%) |          |                           |           |           |                  |
|                                  | ENC                                                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                |           |            |          |                           |           | PKG:1     |                  |
| 731066                           | NO. 1 ENGINE - DO A FUNCTIONAL CHECK OF THE OIL-TO-FUEL HEATER                                 |           |            |          |                           |           |           | Service ATA:73   |
| PN:10585K                        | MOS/MSC                                                                                        | 21-Nov-11 | N/A        |          |                           |           |           |                  |
| SN:WA4376                        | HRS                                                                                            | 2995      |            |          |                           |           |           |                  |
|                                  | ENC                                                                                            | 2995      |            |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                |           |            |          |                           |           |           |                  |
| 731066                           | NO. 2 ENGINE - DO A FUNCTIONAL CHECK OF THE OIL-TO-FUEL HEATER                                 |           |            |          |                           |           |           | Service ATA:73   |
| PN:10585K                        | MOS/MSC                                                                                        | 21-Nov-11 | N/A        |          |                           |           |           |                  |
| SN:WA3822                        | HRS                                                                                            | 2995      |            |          |                           |           |           |                  |
|                                  | ENC                                                                                            | 2995      |            |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-01          |                                                                                                |           |            |          |                           |           |           |                  |
| 731075 <sup>S</sup>              | NO. 1 ENGINE - INSPECT ACCESSORIES FOR SECURITY OF PNEUMATIC LINES                             |           |            |          |                           |           |           | Service ATA:73   |
|                                  | MOS                                                                                            | 22-May-24 |            |          |                           |           |           |                  |
|                                  | HRS                                                                                            | 4291.1    | 200        |          |                           |           |           |                  |
|                                  | ENC                                                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                |           |            |          |                           |           | PKG:1     |                  |
| 731075 <sup>S</sup>              | NO. 2 ENGINE - INSPECT ACCESSORIES FOR SECURITY OF PNEUMATIC LINES                             |           |            |          |                           |           |           | Service ATA:73   |
|                                  | MOS                                                                                            | 22-May-24 |            |          |                           |           |           |                  |
|                                  | HRS                                                                                            | 4291.1    | 200        |          |                           |           |           |                  |
|                                  | ENC                                                                                            | 4184      |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                |           |            |          |                           |           | PKG:1     |                  |
| 731080                           | NO. 1 ENGINE - FUEL BOOST PUMP                                                                 |           |            |          |                           |           |           | Component ATA:73 |
| PN:91-380003-3                   | MOS/MSC                                                                                        | 20-Dec-94 | O/C        |          |                           |           |           |                  |
| SN:B-8355                        | HRS                                                                                            | 0         |            | TSN 0    |                           |           |           |                  |
|                                  | ENC                                                                                            |           |            |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-02          |                                                                                                |           |            |          |                           |           |           |                  |
| 731080                           | NO. 2 ENGINE - FUEL BOOST PUMP                                                                 |           |            |          |                           |           |           | Component ATA:73 |
| PN:91-380003-3                   | MOS/MSC                                                                                        | 20-Dec-94 | O/C        |          |                           |           |           | OVERHAUL         |
| SN:B-8302                        | HRS                                                                                            | 0         |            | TSN 0    |                           |           |           |                  |
|                                  | ENC                                                                                            |           |            |          |                           |           |           |                  |
| PROC. REF: EMM 73-10-02          |                                                                                                |           |            |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                        |           |             |          |                           |           |               |                  |
| 731085 <sup>S</sup>              | NO. 1 ENGINE - CHECK P3 FILTER FOR INSTALLATION                        |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                    | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                    | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                    | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-07          |                                                                        |           |             |          |                           |           | PKG:1         |                  |
| 731085 <sup>S</sup>              | NO. 2 ENGINE - CHECK P3 FILTER FOR INSTALLATION                        |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                    | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                    | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                    | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-07          |                                                                        |           |             |          |                           |           | PKG:1         |                  |
| 731090                           | NO. 1 ENGINE - FUEL CONTROL UNIT                                       |           |             |          |                           |           |               | Component ATA:73 |
| PN:3244768-13                    | MOS                                                                    | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:C20044                        | HRS                                                                    | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                    | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-20-00          |                                                                        |           |             |          |                           |           |               |                  |
| 731090                           | NO. 2 ENGINE - FUEL CONTROL UNIT                                       |           |             |          |                           |           |               | Component ATA:73 |
| PN:3244768-13                    | MOS                                                                    | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:C20043                        | HRS                                                                    | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                    | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-20-00          |                                                                        |           |             |          |                           |           |               |                  |
| 731095                           | NO. 1 ENGINE - FCU DRIVEBODY INSPECTION/DRIVESHAFT BEARING REPLACEMENT |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                    | 22-May-24 | 144         |          | 22-May-36                 |           | 4257 d        |                  |
|                                  | HRS                                                                    | 4291.1    |             |          |                           |           |               |                  |
|                                  | ENC                                                                    | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-20-00          |                                                                        |           |             |          |                           |           |               |                  |
| 731095                           | NO. 2 ENGINE - FCU DRIVEBODY INSPECTION/DRIVESHAFT BEARING REPLACEMENT |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                    | 22-May-24 | 144         |          | 22-May-36                 |           | 4257 d        |                  |
|                                  | HRS                                                                    | 4291.1    |             |          |                           |           |               |                  |
|                                  | ENC                                                                    | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-20-00          |                                                                        |           |             |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                                                            | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                                 |           |             |          |                           |           |               |                  |
| 731110                           | NO. 1 ENGINE - TORQUE LIMITER                                                                                   |           |             |          |                           |           |               | Component ATA:73 |
| PN:3244707-7                     | MOS                                                                                                             | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:C12058                        | HRS                                                                                                             | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                             | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-09          |                                                                                                                 |           |             |          |                           |           |               |                  |
| 731110                           | NO. 2 ENGINE - TORQUE LIMITER                                                                                   |           |             |          |                           |           |               | Component ATA:73 |
| PN:3244707-7                     | MOS                                                                                                             | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:C12053                        | HRS                                                                                                             | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                             | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 73-10-09          |                                                                                                                 |           |             |          |                           |           |               |                  |
| 731215 <sup>S</sup>              | NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER/DUMP VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                             | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                             | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                             | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-04          |                                                                                                                 |           |             |          |                           |           |               | PKG:1            |
| 731215 <sup>S</sup>              | NO. 2 ENGINE - DO A CHECK OF THE FLOW DIVIDER/DUMP VALVE (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                             | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                             | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                             | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 73-10-04          |                                                                                                                 |           |             |          |                           |           |               | PKG:1            |
| 732000 <sup>S</sup>              | NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES                                         |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                             | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                             | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                             | 4184      |             |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                                 |           |             |          |                           |           |               | PKG:1            |
| 732000 <sup>S</sup>              | NO. 2 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES                                         |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                             | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                             | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                             | 4184      |             |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                                 |           |             |          |                           |           |               | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                               | Unit                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|--------------------------------------------|-----------|-------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL      |                                            |           |             |          |                           |           |              |                  |
| 732010                                | NO. 1 ENGINE - FUEL FLOW TRANSMITTER       |           |             |          |                           |           |              | Component ATA:73 |
| PN:1/2-2-81-306                       | MOS/MSC                                    | 11-Jul-95 | O/C         | TSN 0    |                           |           |              |                  |
| SN:211451                             | HRS                                        | 109       |             | TSN 0    |                           |           |              |                  |
|                                       | ENC                                        |           |             |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                            |           |             |          |                           |           |              |                  |
| 732010                                | NO. 2 ENGINE - FUEL FLOW TRANSMITTER       |           |             |          |                           |           |              | Component ATA:73 |
| PN:1/2-2-81-306                       | MOS/MSC                                    | 20-Dec-94 | O/C         |          |                           |           |              |                  |
| SN:210242                             | HRS                                        | 0         |             | TSN 0    |                           |           |              |                  |
|                                       | ENC                                        |           |             |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF             |                                            |           |             |          |                           |           |              |                  |
| 733010                                | NO. 1 ENGINE - CLEAN P3 FILTER             |           |             |          |                           |           |              | Service ATA:73   |
|                                       | MOS                                        | 22-May-24 |             |          |                           |           |              |                  |
|                                       | HRS                                        | 4291.1    | 200 (+10%)  |          | (4491.1)<br>5886.2        | 4511.1    | 108.5 (+20)  |                  |
|                                       | ENC                                        | 4184      |             |          |                           |           |              |                  |
| PROC. REF: EMM 73-10-07               |                                            |           |             |          |                           |           |              |                  |
| 733010                                | NO. 2 ENGINE - CLEAN P3 FILTER             |           |             |          |                           |           |              | Service ATA:73   |
|                                       | MOS                                        | 22-May-24 |             |          |                           |           |              |                  |
|                                       | HRS                                        | 4291.1    | 200 (+10%)  |          | (4491.1)<br>5886.2        | 4511.1    | 108.5 (+20)  |                  |
|                                       | ENC                                        | 4184      |             |          |                           |           |              |                  |
| PROC. REF: EMM 73-10-07               |                                            |           |             |          |                           |           |              |                  |
| 733020                                | NO. 1 ENGINE - CLEAN/REPLACE P3 AIR FILTER |           |             |          |                           |           |              | Service ATA:73   |
|                                       | MOS                                        | 12-Apr-23 |             |          |                           |           |              |                  |
|                                       | HRS                                        | 4105.2    | 1000 (+100) |          | (5105.2)<br>6500.3        | 5205.2    | 722.6 (+100) |                  |
|                                       | ENC                                        | 4047      |             |          |                           |           |              |                  |
| PROC. REF: EMM 73-10-07, EMM 73-10-07 |                                            |           |             |          |                           |           |              |                  |
| 733020                                | NO. 2 ENGINE - CLEAN/REPLACE P3 AIR FILTER |           |             |          |                           |           |              | Service ATA:73   |
|                                       | MOS                                        | 12-Apr-23 |             |          |                           |           |              |                  |
|                                       | HRS                                        | 4105.2    | 1000 (+100) |          | (5105.2)<br>6500.3        | 5205.2    | 722.6 (+100) |                  |
|                                       | ENC                                        | 4047      |             |          |                           |           |              |                  |
| PROC. REF: EMM 73-10-07, EMM 73-10-07 |                                            |           |             |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                          | Unit                                                                                                              | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------|-------------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                                                                   |           |             |          |                           |           |               |                  |
| 733035 <sup>S</sup>              | NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                               | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                               | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                               | 4184      |             |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                                   |           |             |          |                           |           | PKG:1         |                  |
| 733035 <sup>S</sup>              | NO. 2 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS |           |             |          |                           |           |               | Service ATA:73   |
|                                  | MOS                                                                                                               | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                               | 4291.1    | 200         |          |                           |           |               |                  |
|                                  | ENC                                                                                                               | 4184      |             |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF        |                                                                                                                   |           |             |          |                           |           | PKG:1         |                  |
| ATA 74 - IGNITION                |                                                                                                                   |           |             |          |                           |           |               |                  |
| 740010                           | NO. 1 ENGINE - IGNITION EXCITER                                                                                   |           |             |          |                           |           |               | Component ATA:74 |
| PN:10-381550-4                   | MOS                                                                                                               | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:NN99379227                    | HRS                                                                                                               | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                               | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 74-10-00          |                                                                                                                   |           |             |          |                           |           |               |                  |
| 740010                           | NO. 2 ENGINE - IGNITION EXCITER                                                                                   |           |             |          |                           |           |               | Component ATA:74 |
| PN:10-381550-4                   | MOS                                                                                                               | 21-Nov-11 |             | TSO 0    |                           |           |               | OVERHAUL         |
| SN:NNA05496744                   | HRS                                                                                                               | 2995      | 3600 (+500) | TSO 0    | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                                  | ENC                                                                                                               | 2995      |             | TSO 0    |                           |           |               |                  |
| PROC. REF: EMM 74-10-00          |                                                                                                                   |           |             |          |                           |           |               |                  |
| 740015                           | NO. 1 ENGINE - EXAMINE THE SPARK IGNITERS FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK                      |           |             |          |                           |           |               | Service ATA:74   |
|                                  | MOS                                                                                                               | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                               | 4291.1    | 400 (+10%)  |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40)   |                  |
|                                  | ENC                                                                                                               | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 74-20-00          |                                                                                                                   |           |             |          |                           |           |               |                  |
| 740015                           | NO. 2 ENGINE - EXAMINE THE SPARK IGNITERS FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK                      |           |             |          |                           |           |               | Service ATA:74   |
|                                  | MOS                                                                                                               | 22-May-24 |             |          |                           |           |               |                  |
|                                  | HRS                                                                                                               | 4291.1    | 400 (+10%)  |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40)   |                  |
|                                  | ENC                                                                                                               | 4184      |             |          |                           |           |               |                  |
| PROC. REF: EMM 74-20-00          |                                                                                                                   |           |             |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN           | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 74 - IGNITION |                                              |           |          |          |                           |           |           |                  |
| 740020            | NO. 1 ENGINE - 4 O'CLOCK IGNITOR             |           |          |          |                           |           |           | Component ATA:74 |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN        | HRS                                          | 4105.4    |          | TSN 0    |                           |           |           |                  |
|                   | AFL                                          | 4047      |          |          |                           |           |           |                  |
|                   | ENC                                          |           |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: EMM 74-20-00                      |           |          |          |                           |           |           |                  |
| 740020            | NO. 2 ENGINE - 4 O'CLOCK IGNITOR             |           |          |          |                           |           |           | Component ATA:74 |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN        | HRS                                          | 4105.2    |          | TSN 0    |                           |           |           |                  |
|                   | ENC                                          | 4047      |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: EMM 74-20-00                      |           |          |          |                           |           |           |                  |
| 740040            | NO. 1 ENGINE - 9 O'CLOCK IGNITOR             |           |          |          |                           |           |           | Component ATA:74 |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN        | HRS                                          | 4105.4    |          | TSN 0    |                           |           |           |                  |
|                   | AFL                                          | 4047      |          |          |                           |           |           |                  |
|                   | ENC                                          |           |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: EMM 74-20-00                      |           |          |          |                           |           |           |                  |
| 740040            | NO. 2 ENGINE - 9 O'CLOCK IGNITOR             |           |          |          |                           |           |           | Component ATA:74 |
| PN:CH34055        | MOS/MSC                                      | 12-Apr-23 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN        | HRS                                          | 4105.2    |          | TSN 0    |                           |           |           |                  |
|                   | ENC                                          | 4047      |          | TSN 0    |                           |           |           |                  |
|                   | PROC. REF: EMM 74-20-00                      |           |          |          |                           |           |           |                  |
| 740070            | NO. 1 ENGINE - AUTO IGNITION PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:74 |
| PN:50-389121-19   | MOS/MSC                                      | 18-Feb-99 | O/C      |          |                           |           |           |                  |
| SN:11599          | HRS                                          | 980       |          | TSN 0    |                           |           |           |                  |
|                   | ENC                                          |           |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |
| 740070            | NO. 2 ENGINE - AUTO IGNITION PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:74 |
| PN:MS24658-23D    | MOS/MSC                                      | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN        | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                   | ENC                                          |           |          |          |                           |           |           |                  |
|                   | PROC. REF: GENERIC NO REF                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN           | Unit                                                                                   | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|-------------------|----------------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 74 - IGNITION |                                                                                        |           |            |          |                           |           |             |                |
| 740080            | NO. 1 ENGINE - OPERATIONAL CHECK AUTO IGNITION SYSTEM                                  |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS/MSC                                                                                | 21-Nov-11 | O/C        |          |                           |           |             |                |
|                   | HRS                                                                                    | 2995      |            |          |                           |           |             |                |
|                   | ENC                                                                                    | 2995      |            |          |                           |           |             |                |
|                   | PROC. REF: GENERIC NO REF                                                              |           |            |          |                           |           |             |                |
| 740080            | NO. 2 ENGINE - OPERATIONAL CHECK AUTO IGNITION SYSTEM                                  |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS/MSC                                                                                | 21-Nov-11 | O/C        |          |                           |           |             |                |
|                   | HRS                                                                                    | 2995      |            |          |                           |           |             |                |
|                   | ENC                                                                                    | 2995      |            |          |                           |           |             |                |
|                   | PROC. REF: GENERIC NO REF                                                              |           |            |          |                           |           |             |                |
| 741000            | NO. 1 ENGINE - EXAMINE THE IGNITION EXCITER FOR THE CORRECT INSTALLATION AND CONDITION |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS                                                                                    | 22-May-24 |            |          |                           |           |             |                |
|                   | HRS                                                                                    | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                |
|                   | ENC                                                                                    | 4184      |            |          |                           |           |             |                |
|                   | PROC. REF: GENERIC NO REF                                                              |           |            |          |                           |           |             |                |
| 741000            | NO. 2 ENGINE - EXAMINE THE IGNITION EXCITER FOR THE CORRECT INSTALLATION AND CONDITION |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS                                                                                    | 22-May-24 |            |          |                           |           |             |                |
|                   | HRS                                                                                    | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                |
|                   | ENC                                                                                    | 4184      |            |          |                           |           |             |                |
|                   | PROC. REF: GENERIC NO REF                                                              |           |            |          |                           |           |             |                |
| 742000            | NO. 1 ENGINE - EXAMINE THE IGNITION CABLES FOR CHAFING, WEAR AND CORRECT INSTALLATION  |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS                                                                                    | 22-May-24 |            |          |                           |           |             |                |
|                   | HRS                                                                                    | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                |
|                   | ENC                                                                                    | 4184      |            |          |                           |           |             |                |
|                   | PROC. REF: EMM 74-20-00                                                                |           |            |          |                           |           |             |                |
| 742000            | NO. 2 ENGINE - EXAMINE THE IGNITION CABLES FOR CHAFING, WEAR AND CORRECT INSTALLATION  |           |            |          |                           |           |             | Service ATA:74 |
|                   | MOS                                                                                    | 22-May-24 |            |          |                           |           |             |                |
|                   | HRS                                                                                    | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                |
|                   | ENC                                                                                    | 4184      |            |          |                           |           |             |                |
|                   | PROC. REF: EMM 74-20-00                                                                |           |            |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                     | C/W       | Interval    | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|---------------------------|------------------------------------------|-----------|-------------|-----------------|---------------------------|-----------|---------------|------------------|
| ATA 75 - AIR              |                                          |           |             |                 |                           |           |               |                  |
| 750010                    | NO. 1 ENGINE - HIGH PRESSURE BLEED VALVE |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100922-05             | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:17A768                 | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                           | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
| PROC. REF: EMM 75-30-00   |                                          |           |             |                 |                           |           |               |                  |
| 750010                    | NO. 2 ENGINE - HIGH PRESSURE BLEED VALVE |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100922-05             | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:4K344                  | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                           | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
| PROC. REF: EMM 75-30-00   |                                          |           |             |                 |                           |           |               |                  |
| 750020                    | NO. 1 ENGINE - LOW PRESSURE BLEED VALVE  |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100923-02             | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:9K356                  | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                           | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
| PROC. REF: EMM 75-30-00   |                                          |           |             |                 |                           |           |               |                  |
| 750020                    | NO. 2 ENGINE - LOW PRESSURE BLEED VALVE  |           |             |                 |                           |           |               | Component ATA:75 |
| PN:3100923-02             | MOS                                      | 21-Nov-11 |             | TSO 0           |                           |           |               | OVERHAUL         |
| SN:3K396                  | HRS                                      | 2995      | 3600 (+500) | TSN 2995, TSO 0 | (6595)<br>7990.1          | 7095      | 2212.4 (+500) |                  |
|                           | ENC                                      | 2995      |             | TSO 0           |                           |           |               |                  |
| PROC. REF: EMM 75-30-00   |                                          |           |             |                 |                           |           |               |                  |
| ATA 76 - ENGINE CONTROLS  |                                          |           |             |                 |                           |           |               |                  |
| 760010                    | NO. 1 ENGINE - RIG CONTROL               |           |             |                 |                           |           |               | Service ATA:76   |
|                           | MOS/MSC                                  | 20-Dec-94 | O/C         |                 |                           |           |               |                  |
|                           | HRS                                      | 0         |             |                 |                           |           |               |                  |
|                           | ENC                                      | 0         |             |                 |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                          |           |             |                 |                           |           |               |                  |
| 760010                    | NO. 2 ENGINE - RIG CONTROL               |           |             |                 |                           |           |               | Service ATA:76   |
|                           | MOS/MSC                                  | 20-Dec-94 | O/C         |                 |                           |           |               |                  |
|                           | HRS                                      | 0         |             |                 |                           |           |               |                  |
|                           | ENC                                      | 0         |             |                 |                           |           |               |                  |
| PROC. REF: GENERIC NO REF |                                          |           |             |                 |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                    | Unit                                            | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------|-------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 76 - ENGINE CONTROLS   |                                                 |           |                  |          |                           |           |               |                  |
| 760301                     | LEFT ENGINE POWER LEVER PIN (PEDESTAL)          |           |                  |          |                           |           |               | Component ATA:76 |
| PN:101-524181-1            | MOS/MSC                                         | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                 | HRS                                             | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 76.020                | AFL                                             | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF  |                                                 |           |                  |          |                           |           |               |                  |
| 760302                     | INSPECT LEFT ENGINE POWER LEVER (PEDESTAL) PIN  |           |                  |          |                           |           |               | Service ATA:76   |
|                            | MOS                                             | 22-May-24 |                  |          |                           |           |               |                  |
|                            | HRS                                             | 5686.2    | 1200 (+10%/-10%) |          | 6886.2                    | 7006.2    | 1108.5 (+120) |                  |
| WC#: 76.020                | AFL                                             | 6495      |                  |          |                           |           |               |                  |
| 760350                     | RIGHT ENGINE POWER LEVER PIN (PEDESTAL)         |           |                  |          |                           |           |               | Component ATA:76 |
| PN:50-524567-3             | MOS/MSC                                         | 29-Dec-98 | O/C              |          |                           |           |               |                  |
| SN:UNKNOWN                 | HRS                                             | 0         |                  | TSN 0    |                           |           |               |                  |
| WC#: 76.020                | AFL                                             | 0         |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF  |                                                 |           |                  |          |                           |           |               |                  |
| 760351                     | INSPECT RIGHT ENGINE POWER LEVER (PEDESTAL) PIN |           |                  |          |                           |           |               | Service ATA:76   |
|                            | MOS                                             | 22-May-24 |                  |          |                           |           |               |                  |
|                            | HRS                                             | 5686.2    | 1200 (+10%/-10%) |          | 6886.2                    | 7006.2    | 1108.5 (+120) |                  |
| WC#: 76.020                | AFL                                             | 6495      |                  |          |                           |           |               |                  |
| 761010 <sup>S</sup>        | NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES  |           |                  |          |                           |           |               | Service ATA:76   |
|                            | MOS/MSC                                         | 22-May-24 | A/R              |          |                           |           |               |                  |
|                            | HRS                                             | 4291.1    |                  |          |                           |           |               |                  |
|                            | ENC                                             | 4184      |                  |          |                           |           |               |                  |
| PROC. REF: EMM 72-00-00    |                                                 |           |                  |          |                           |           |               | PKG:1            |
| 761010 <sup>S</sup>        | NO. 2 ENGINE - INSPECT ENGINE CONTROL LINKAGES  |           |                  |          |                           |           |               | Service ATA:76   |
|                            | MOS/MSC                                         | 22-May-24 | A/R              |          |                           |           |               |                  |
|                            | HRS                                             | 4291.1    |                  |          |                           |           |               |                  |
|                            | ENC                                             | 4184      |                  |          |                           |           |               |                  |
| PROC. REF: EMM 72-00-00    |                                                 |           |                  |          |                           |           |               | PKG:1            |
| ATA 77 - ENGINE INDICATING |                                                 |           |                  |          |                           |           |               |                  |
| 770020                     | NO. 1 ENGINE - TORQUE PRESSURE TRANSMITTER      |           |                  |          |                           |           |               | Component ATA:77 |
| PN:130-389002-1            | MOS/MSC                                         | 20-Dec-94 | O/C              |          |                           |           |               |                  |
| SN:4815-7-203              | HRS                                             | 0         |                  | TSN 0    |                           |           |               |                  |
|                            | ENC                                             |           |                  |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REF  |                                                 |           |                  |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                    | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                                       |           |          |          |                           |           |           |                  |
| 770020                     | NO. 2 ENGINE - TORQUE PRESSURE TRANSMITTER            |           |          |          |                           |           |           | Component ATA:77 |
| PN:130-389002-1            | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:4984-4-287              | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |          |                           |           |           |                  |
| 770030                     | NO. 1 ENGINE - TURBINE TEMPERTURE HARNESS             |           |          |          |                           |           |           | Component ATA:77 |
| PN:3022441                 | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                                       |           |          |          |                           |           |           |                  |
| 770030                     | NO. 2 ENGINE - TURBINE TEMPERTURE HARNESS             |           |          |          |                           |           |           | Component ATA:77 |
| PN:3022441                 | MOS/MSC                                               | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                                   |           |          |          |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                                       |           |          |          |                           |           |           |                  |
| 770101                     | NO. 1 ENGINE TURBINE TACH INDICATOR                   |           |          |          |                           |           |           | Component ATA:77 |
| PN:50-380034-3             | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.010                | AFL                                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |          |                           |           |           |                  |
| 770111                     | NO. 1 ENGINE TORQUE PRESSURE INDICATOR                |           |          |          |                           |           |           | Component ATA:77 |
| PN:101-384008-3            | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.020                | AFL                                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |          |                           |           |           |                  |
| 770121                     | NO. 1 ENGINE TURBINE INTERSTAGE TEMPERATURE INDICATOR |           |          |          |                           |           |           | Component ATA:77 |
| PN:50-389102-15            | MOS/MSC                                               | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 77.030                | AFL                                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |          |                           |           |           |                  |
| 770150                     | NO. 1 ENGINE N1 TACHOMETER GENERATOR REPLACE          |           |          |          |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                               | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 77-14-01    |                                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                    | Unit                                                  | C/W       | Interval | TSX/Adj.          | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|-------------------------------------------------------|-----------|----------|-------------------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                                       |           |          |                   |                           |           |           |                  |
| 770601                     | NO. 2 ENGINE TURBINE TACH INDICATOR                   |           |          |                   |                           |           |           | Component ATA:77 |
| PN:50-380034-3             | MOS/MSC                                               | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 77.010                | AFL                                                   | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |                   |                           |           |           |                  |
| 770611                     | NO. 2 ENGINE TORQUE PRESSURE INDICATOR                |           |          |                   |                           |           |           | Component ATA:77 |
| PN:130-380044-17           | MOS/MSC                                               | 07-Feb-20 | O/C      | TSR 0             |                           |           |           |                  |
| SN:361                     | HRS                                                   | 5159.5    |          | TSN 5159.5, TSR 0 |                           |           |           |                  |
| WC#: 77.020                | AFL                                                   | 6110      |          | TSR 0             |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |                   |                           |           |           |                  |
| 770621                     | NO. 2 ENGINE TURBINE INTERSTAGE TEMPERATURE INDICATOR |           |          |                   |                           |           |           | Component ATA:77 |
| PN:50-389102-15            | MOS/MSC                                               | 29-Dec-98 | O/C      |                   |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| WC#: 77.030                | AFL                                                   | 0         |          |                   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                       |           |          |                   |                           |           |           |                  |
| 770650                     | NO. 2 ENGINE N1 TACHOMETER GENERATOR REPLACE          |           |          |                   |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                               | 29-Dec-98 | O/C      | TSN 0             |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | AFL                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: AMM 77-14-01    |                                                       |           |          |                   |                           |           |           |                  |
| 772001                     | NO. 1 ENGINE - NEGATIVE TERMINAL.T5 BUS BAR           |           |          |                   |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                                       |           |          |                   |                           |           |           |                  |
| 772001                     | NO. 2 ENGINE - NEGATIVE TERMINAL.T5 BUS BAR           |           |          |                   |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                                       |           |          |                   |                           |           |           |                  |
| 772002                     | NO. 1 ENGINE - POSITIVE TERMINAL BUS BAR              |           |          |                   |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                               | 20-Dec-94 | O/C      | TSN 0             |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                   | 0         |          | TSN 0             |                           |           |           |                  |
|                            | ENC                                                   | 0         |          | TSN 0             |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                                       |           |          |                   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                    | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 77 - ENGINE INDICATING |                                          |           |          |          |                           |           |           |                  |
| 772002                     | NO. 2 ENGINE - POSITIVE TERMINAL BUS BAR |           |          |          |                           |           |           | Component ATA:77 |
| PN:PN                      | MOS/MSC                                  | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: EMM 77-20-01    |                                          |           |          |          |                           |           |           |                  |
| ATA 78 - EXHAUST           |                                          |           |          |          |                           |           |           |                  |
| 780101                     | NO. 1 ENGINE LEFT EXHAUST/WELD ASSY      |           |          |          |                           |           |           | Component ATA:78 |
| PN:101-950016-23           | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.010                | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                          |           |          |          |                           |           |           |                  |
| 780106                     | NO. 1 ENGINE RIGHT EXHAUST/WELD ASSY     |           |          |          |                           |           |           | Component ATA:78 |
| PN:101-950016-23           | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.010                | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                          |           |          |          |                           |           |           |                  |
| 780111                     | NO. 2 ENGINE LEFT EXHAUST/WELD ASSY      |           |          |          |                           |           |           | Component ATA:78 |
| PN:101-950016-25           | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.020                | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                          |           |          |          |                           |           |           |                  |
| 780116                     | NO. 2 ENGINE RIGHT EXHAUST/WELD ASSY     |           |          |          |                           |           |           | Component ATA:78 |
| PN:101-950016-25           | MOS/MSC                                  | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.020                | AFL                                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                          |           |          |          |                           |           |           |                  |
| ATA 79 - OIL               |                                          |           |          |          |                           |           |           |                  |
| 790010                     | NO. 1 ENGINE - OIL COOLER                |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                      | MOS/MSC                                  | 20-Dec-94 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                            | ENC                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                    | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|---------------------------|-------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 79 - OIL              |                                                                         |           |            |          |                           |           |             |                  |
| 790010                    | NO. 2 ENGINE - OIL COOLER                                               |           |            |          |                           |           |             | Component ATA:79 |
| PN:PN                     | MOS/MSC                                                                 | 20-Dec-94 | O/C        | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|                           | ENC                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |            |          |                           |           |             |                  |
| 790020                    | NO. 1 ENGINE - CHIP DETECTOR                                            |           |            |          |                           |           |             | Component ATA:79 |
| PN:3019373                | MOS/MSC                                                                 | 20-Dec-94 | O/C        |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|                           | ENC                                                                     |           |            |          |                           |           |             |                  |
| PROC. REF: EMM 72-10-00   |                                                                         |           |            |          |                           |           |             |                  |
| 790020                    | NO. 2 ENGINE - CHIP DETECTOR                                            |           |            |          |                           |           |             | Component ATA:79 |
| PN:3019373                | MOS/MSC                                                                 | 20-Dec-94 | O/C        |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |            | TSN 0    |                           |           |             |                  |
|                           | ENC                                                                     |           |            |          |                           |           |             |                  |
| PROC. REF: EMM 72-10-00   |                                                                         |           |            |          |                           |           |             |                  |
| 790030                    | NO. 1 ENGINE - CHIP DETECTOR CONTINUITY CHECK MAGNETIC CHIP DETECTOR(S) |           |            |          |                           |           |             | Service ATA:79   |
| PN:3019373                | MOS                                                                     | 22-May-24 |            |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                     | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                  |
|                           | ENC                                                                     | 4184      |            |          |                           |           |             |                  |
| PROC. REF: EMM 72-10-00   |                                                                         |           |            |          |                           |           |             | PKG:1            |
| 790030                    | NO. 2 ENGINE - CHIP DETECTOR CONTINUITY CHECK MAGNETIC CHIP DETECTOR(S) |           |            |          |                           |           |             | Service ATA:79   |
| PN:3019373                | MOS                                                                     | 22-May-24 |            |          |                           |           |             |                  |
| SN:UNKNOWN                | HRS                                                                     | 4291.1    | 400 (+10%) |          | (4691.1)<br>6086.2        | 4731.1    | 308.5 (+40) |                  |
|                           | ENC                                                                     | 4184      |            |          |                           |           |             |                  |
| PROC. REF: EMM 72-10-00   |                                                                         |           |            |          |                           |           |             | PKG:1            |
| 790040                    | NO. 1 ENGINE - BRIDGE CHECK CHIP DETECTOR                               |           |            |          |                           |           |             | Service ATA:79   |
| PN:3019373                | MOS                                                                     | 22-May-24 | 12 (+30d)  |          | 22-May-25                 | 21-Jun-25 | 239 d (+30) |                  |
| SN:UNKNOWN                | HRS                                                                     | 4291.1    | 600 (+10%) |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60) |                  |
|                           | ENC                                                                     | 4184      |            |          |                           |           |             |                  |
| PROC. REF: EMM 72-10-00   |                                                                         |           |            |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit                                                           | C/W       | Interval         | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|-------------------------|----------------------------------------------------------------|-----------|------------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 79 - OIL            |                                                                |           |                  |          |                           |           |              |                |
| 790040                  | NO. 2 ENGINE - BRIDGE CHECK CHIP DETECTOR                      |           |                  |          |                           |           |              | Service ATA:79 |
| PN:3019373              | MOS                                                            | 22-May-24 | 12 (+30d)        |          | 22-May-25                 | 21-Jun-25 | 239 d (+30)  |                |
| SN:UNKNOWN              | HRS                                                            | 4291.1    | 600 (+10%)       |          | (4891.1)<br>6286.2        | 4951.1    | 508.5 (+60)  |                |
|                         | ENC                                                            | 4184      |                  |          |                           |           |              |                |
| PROC. REF: EMM 72-10-00 |                                                                |           |                  |          |                           |           |              |                |
| 790045                  | NO. 1 ENGINE - CHECK SCAVENGE PUMP INLET SCREEN                |           |                  |          |                           |           |              | Service ATA:79 |
|                         | MOS                                                            | 13-Feb-19 |                  |          |                           |           |              |                |
|                         | HRS                                                            | 3688.3    | 1000 (+100)      |          | (4688.3)<br>6083.4        | 4788.3    | 305.7 (+100) |                |
|                         | ENC                                                            | 3688      |                  |          |                           |           |              |                |
| PROC. REF: EMM 72-60-00 |                                                                |           |                  |          |                           |           |              |                |
| 790045                  | NO. 2 ENGINE - CHECK SCAVENGE PUMP INLET SCREEN                |           |                  |          |                           |           |              | Service ATA:79 |
|                         | MOS                                                            | 13-Feb-19 |                  |          |                           |           |              |                |
|                         | HRS                                                            | 3688.3    | 1000 (+100)      |          | (4688.3)<br>6083.4        | 4788.3    | 305.7 (+100) |                |
|                         | ENC                                                            | 3688      |                  |          |                           |           |              |                |
| PROC. REF: EMM 72-60-00 |                                                                |           |                  |          |                           |           |              |                |
| 790050                  | NO. 1 ENGINE - REPLACE OIL FILTER                              |           |                  |          |                           |           |              | Service ATA:79 |
|                         | MOS                                                            | 12-Apr-23 |                  |          |                           |           |              | SCRAP          |
|                         | HRS                                                            | 4105.2    | 1000 (+100/-100) |          | (5105.2)<br>6500.3        | 5205.2    | 722.6 (+100) |                |
|                         | ENC                                                            | 4047      |                  |          |                           |           |              |                |
| PROC. REF: EMM 79-20-02 |                                                                |           |                  |          |                           |           |              |                |
| 790050                  | NO. 2 ENGINE - REPLACE OIL FILTER                              |           |                  |          |                           |           |              | Service ATA:79 |
|                         | MOS                                                            | 12-Apr-23 |                  |          |                           |           |              | SCRAP          |
|                         | HRS                                                            | 4105.2    | 1000 (+100/-100) |          | (5105.2)<br>6500.3        | 5205.2    | 722.6 (+100) |                |
|                         | ENC                                                            | 4047      |                  |          |                           |           |              |                |
| PROC. REF: EMM 79-20-02 |                                                                |           |                  |          |                           |           |              |                |
| 790060 <sup>S</sup>     | NO. 1 ENGINE - EXAMINE OIL FILTER ELEMENT AND SECONDARY SCREEN |           |                  |          |                           |           |              | Service ATA:79 |
|                         | MOS                                                            | 22-May-24 |                  |          |                           |           |              |                |
|                         | HRS                                                            | 4291.1    | 200 (+10%)       |          |                           |           |              |                |
|                         | ENC                                                            | 4184      |                  |          |                           |           |              |                |
| PROC. REF: EMM 79-20-02 |                                                                |           |                  |          |                           |           |              |                |
| PKG:1                   |                                                                |           |                  |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN             | Unit                                                           | C/W       | Interval   | TSX/Adj.                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------|----------------------------------------------------------------|-----------|------------|---------------------------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL        |                                                                |           |            |                           |                           |           |           |                  |
| 790060 <sup>S</sup> | NO. 2 ENGINE - EXAMINE OIL FILTER ELEMENT AND SECONDARY SCREEN |           |            |                           |                           |           |           | Service ATA:79   |
|                     | MOS                                                            | 22-May-24 |            |                           |                           |           |           |                  |
|                     | HRS                                                            | 4291.1    | 200 (+10%) |                           |                           |           |           |                  |
|                     | ENC                                                            | 4184      |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: EMM 79-20-02   |                           |           |           | PKG:1            |
| 790065              | NO. 1 ENGINE - P&WC OIL ANALYSIS TECHNOLOGY PROGRAM            |           |            |                           |                           |           |           | Service ATA:79   |
|                     | MOS/MSC                                                        | 22-May-24 | O/C        |                           |                           |           |           |                  |
|                     | HRS                                                            | 4291.1    |            |                           |                           |           |           |                  |
|                     | ENC                                                            | 4184      |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 790065              | NO. 2 ENGINE - P&WC OIL ANALYSIS TECHNOLOGY PROGRAM            |           |            |                           |                           |           |           | Service ATA:79   |
|                     | MOS/MSC                                                        | 22-May-24 | O/C        |                           |                           |           |           |                  |
|                     | HRS                                                            | 4291.1    |            |                           |                           |           |           |                  |
|                     | ENC                                                            | 4184      |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 790075 <sup>S</sup> | NO. 1 ENGINE - CHECK THE SCAVENGE PUMP HOUSING FOR LEAKS       |           |            |                           |                           |           |           | Service ATA:79   |
|                     | MOS                                                            | 22-May-24 |            |                           |                           |           |           |                  |
|                     | HRS                                                            | 4291.1    | 200        |                           |                           |           |           |                  |
|                     | ENC                                                            | 4184      |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 790075 <sup>S</sup> | NO. 2 ENGINE - CHECK THE SCAVENGE PUMP HOUSING FOR LEAKS       |           |            |                           |                           |           |           | Service ATA:79   |
|                     | MOS                                                            | 22-May-24 |            |                           |                           |           |           |                  |
|                     | HRS                                                            | 4291.1    | 200        |                           |                           |           |           |                  |
|                     | ENC                                                            | 4184      |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           | PKG:1            |
| 790080              | NO. 1 ENGINE - OIL PRESSURE TRANSMITTER                        |           |            |                           |                           |           |           | Component ATA:79 |
| PN:101-389023-5     | MOS/MSC                                                        | 20-Dec-94 | O/C        |                           |                           |           |           |                  |
| SN:5043-3-183       | HRS                                                            | 0         |            | TSN 0                     |                           |           |           |                  |
|                     | ENC                                                            |           |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           |                  |
| 790080              | NO. 2 ENGINE - OIL PRESSURE TRANSMITTER                        |           |            |                           |                           |           |           | Component ATA:79 |
| PN:101-389023-5     | MOS/MSC                                                        | 20-Dec-94 | O/C        |                           |                           |           |           |                  |
| SN:5043-3-162       | HRS                                                            | 0         |            | TSN 0                     |                           |           |           |                  |
|                     | ENC                                                            |           |            |                           |                           |           |           |                  |
|                     |                                                                |           |            | PROC. REF: GENERIC NO REF |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: SUPER KING AIR B200 Serial: BB-1645 RegNo: N777HF HRS: 5777.7 AFL: 6550 As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                   | Unit                                                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL              |                                                                                   |           |          |          |                           |           |           |                  |
| 790090                    | NO. 1 ENGINE - OIL TEMPERATURE BULB                                               |           |          |          |                           |           |           | Component ATA:79 |
| PN:MS28034-3              | MOS/MSC                                                                           | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                               |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |
| 790090                    | NO. 2 ENGINE - OIL TEMPERATURE BULB                                               |           |          |          |                           |           |           | Component ATA:79 |
| PN:MS28034-3              | MOS/MSC                                                                           | 20-Dec-94 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                                                               |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |
| 790105                    | NO. 1 ENGINE - DO A FILTER PATCH TEST FOR ENGINES INSTALLED WITH PRE-SB3463 GEARS |           |          |          |                           |           |           | Service ATA:79   |
|                           | MOS/MSC                                                                           | -         |          |          |                           |           |           |                  |
|                           | HRS                                                                               |           |          |          |                           |           |           |                  |
|                           | ENC                                                                               |           |          |          |                           |           |           |                  |
| PROC. REF: EMM 79-20-02   |                                                                                   |           |          |          |                           |           |           |                  |
| 790116                    | NO. 1 ENGINE OIL TEMPERATURE/PRESSURE INDICATOR                                   |           |          |          |                           |           |           | Component ATA:79 |
| PN:101-384122-7           | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080               | AFL                                                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |
| 790616                    | NO. 2 ENGINE OIL TEMPERATURE/PRESSURE INDICATOR                                   |           |          |          |                           |           |           | Component ATA:79 |
| PN:101-384122-7           | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080               | AFL                                                                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |
| 792005                    | LEFT OIL PRESSURE TRANSDUCER                                                      |           |          |          |                           |           |           | Component ATA:79 |
| PN:BAS-KA-X200G           | MOS/MSC                                                                           | 07-Jun-24 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8643-8-650             | HRS                                                                               |           |          | TSN 0    |                           |           |           |                  |
| WC#: 79.010               | AFL                                                                               |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |
| 792010                    | RIGHT OIL PRESSURE TRANSDUCER                                                     |           |          |          |                           |           |           | Component ATA:79 |
| PN:101-389023-5           | MOS/MSC                                                                           | 29-Dec-98 | O/C      |          |                           |           |           |                  |
| SN:6120-3A-228            | HRS                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.010               | AFL                                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: SUPER KING AIR B200   Serial: BB-1645   RegNo: N777HF   HRS: 5777.7   AFL: 6550   As Of: 25-Sep-2024

25-Sep-2024 09:45 PM

| PN & SN                 | Unit           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition        |
|-------------------------|----------------|-----------|----------|----------|---------------------------|-----------|-----------|--------------------|
| ATA 79 - OIL            |                |           |          |          |                           |           |           |                    |
| 793115                  | L/H OIL COOLER |           |          |          |                           |           |           | Component   ATA:79 |
| PN:PN                   | MOS/MSC        | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                    |
| SN:UNKNOWN              | HRS            | 0         |          | TSN 0    |                           |           |           |                    |
|                         | AFL            | 0         |          | TSN 0    |                           |           |           |                    |
| PROC. REF: AMM 79-10-01 |                |           |          |          |                           |           |           |                    |
| 793615                  | R/H OIL COOLER |           |          |          |                           |           |           | Component   ATA:79 |
| PN:PN                   | MOS/MSC        | 29-Dec-98 | O/C      | TSN 0    |                           |           |           |                    |
| SN:UNKNOWN              | HRS            | 0         |          | TSN 0    |                           |           |           |                    |
|                         | AFL            | 0         |          | TSN 0    |                           |           |           |                    |
| PROC. REF: AMM 79-10-01 |                |           |          |          |                           |           |           |                    |

?-Insufficient Information   S-Suppressed Requirement   \*-Estimated Due(New Requirement)   (EFF)-Effective C/W   (M)-Manual Due   U-User Task   Ex-Excluded Task