



Phone: +1-316-928-7885
Fax: 316-462-2442
Analyst: Luke Ellis

Status Detail Report
Report Created On: 30 Oct 2024

Textron Aviation Inc. 560XL -
CITATION XL (MSG)
N29QA
S/N: 560XL-5277
Regulation: PART 91.409(F)(3)
Airworthiness Date: 20 Sep 2002

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		TEXTRON AVIATION INC. 560XL - CITATION XL (MSG)	560XL-5277	24 Oct 2024	6060.9	4165
Engine	1	PRATT & WHITNEY CANADA CORP. PW545A	PCE-DB0569	24 Oct 2024	6060.9	4140
Engine	2	PRATT & WHITNEY CANADA CORP. PW545A	PCE-DB0582	24 Oct 2024	6060.9	4140
APU		HONEYWELL RE100 (XL)	P-326	24 Oct 2024	1959.3	3272

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* = Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

04 - Limitations											
4-12-MD (0592MD) Airframe	Inspection Document Md	HRS	446.1		2400	5614.8	8014.8				0
		AFL	297			3868					0
		MOS	25	-1	120	29 Sep 2022	30 Sep 2032*				
		[End Of Month Item]									
4-12-ME (0592ME) Airframe	Inspection Document Me	HRS	6060.9		15000	0	15000				0
		AFL	4165			0					0
		MOS	265.3			20 Sep 2002					
		[End Of Month Item]									
4-12-MF (0592MF) Airframe	Inspection Document MF	HRS	6060.9		7500**	0	7500				0
		AFL	4165			0					0
		MOS	265.3			20 Sep 2002					
		[End Of Month Item]									
4-12-MJ (0592MJ) Airframe	Inspection Document Mj	HRS	6060.9		13000	0	13000				0
		AFL	4165			0					0
		MOS	265.3			20 Sep 2002					
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
4-12-ML (0592ML) Airframe	Inspection Document MI		HRS		6060.9		11500**	0	11500		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
4-12-MM (0592MM) Airframe	Inspection Document MM		HRS		6060.9		11000**	0	11000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
4-12-MN (0592MN) Airframe	Inspection Document Mn		HRS		6060.9		9000**	0	9000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
4-12-MO (0592MO) Airframe	Inspection Document Mo		HRS		6060.9		12500**	0	12500		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
4-12-MV Airframe	Inspection Document Mv		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4		24	17 Oct 2024	31 Oct 2026		
			[End Of Month Item]								
05 - Time Limits/Maintenance Checks											
052370 ^U Airframe	Check Xm Radio Audio Mute		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4		12	17 Oct 2024	31 Oct 2025		
			[End Of Month Item]								
053490 ^U Airframe	Inspect RVSM Gmu/Hmu Tst Flight		HRS								0
			AFL								0
			MOS		252.9			03 Oct 2003			
			MSC				O/C				
		[End Of Month Item]									
055000 Engine	No. 1 Engine - FOD		HRS		6060.9			0			0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				A/R				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
055000	No. 2 Engine - FOD		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055005	No. 1 Engine - Bird Strike		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055005	No. 2 Engine - Bird Strike		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055010	No. 1 Engine - Engine Windmilling In Flight		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055010	No. 2 Engine - Engine Windmilling In Flight		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055015	No. 1 Engine - Lightning Strike		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055015	No. 2 Engine - Lightning Strike		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055020	No. 1 Engine - Fuel Filter Impending Bypass		HRS		6060.9			0		0	
			ENC		4140			0	0		
			MOS		265.3		20 Sep 2002				
			MSC			A/R					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
055020	No. 2 Engine - Fuel Filter Impending Bypass		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055025	No. 1 Engine - Engine Exposed to FIRE Extinguishing Agent		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055025	No. 2 Engine - Engine Exposed to FIRE Extinguishing Agent		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055030	No. 1 Engine - Incorrect Engine Shutdown on the Ground		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055030	No. 2 Engine - Incorrect Engine Shutdown on the Ground		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055035	No. 1 Engine - Heavy Landing		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055035	No. 2 Engine - Heavy Landing		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
055040	No. 1 Engine - Sustained Running AT an Oil Temperature Outside of Limits		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055040	No. 2 Engine - Sustained Running AT an Oil Temperature Outside of Limits		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055045	No. 1 Engine - Itt Spike on Engine Start Due to A Frozen Fan		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055045	No. 2 Engine - Itt Spike on Engine Start Due to A Frozen Fan		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055050	No. 1 Engine - Loose High Pressure Compressor Case Bolts		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055050	No. 2 Engine - Loose High Pressure Compressor Case Bolts		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
055055	No. 1 Engine - Data Collection Unit (Dcu) Inoperative		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
055055	No. 2 Engine - Data Collection Unit (Dcu) Inoperative		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055060	No. 1 Engine - Aircraft Flown Through A Cloud of Volcanic ASH		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055060	No. 2 Engine - Aircraft Flown Through A Cloud of Volcanic ASH		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055065	No. 1 Engine - Starter Generator Fail Indication		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055065	No. 2 Engine - Starter Generator Fail Indication		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055070	No. 1 Engine - Hydraulic Pump Unscheduled Removal		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055070	No. 2 Engine - Hydraulic Pump Unscheduled Removal		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055075	No. 1 Engine - Fuel Contamination		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
055075	No. 2 Engine - Fuel Contamination		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
055601 ^U	Inspect Windshield Surface RE-Seal		HRS		5698.9			362			0
			AFL						0		
			MOS		252.9		03 Oct 2003				
			MSC			O/C					
Airframe			[End Of Month Item]								
	055602 ^U	Inspect Hump Seal Repair		HRS		6060.9			0		0
				AFL		4165			0		0
				MOS		265.3		20 Sep 2002			
MSC						O/C					
Airframe			[End Of Month Item]								
	057120	No. 1 Engine - Inspection Low Utilization		HRS		975.6			5085.3		0
				ENC		682			3458		0
				MOS		56.7	120**	08 Feb 2020	28 Feb 2030	31 Mar 2030	
[End Of Month Item] [MOS: +1m]											
Engine											
	057120	No. 2 Engine - Inspection Low Utilization		HRS		975.6			5085.3		0
				ENC		682			3458		0
				MOS		56.6	120**	10 Feb 2020	28 Feb 2030	31 Mar 2030	
[End Of Month Item] [MOS: +1m]											
Engine											
	057159	No. 1 Engine - 800 Hr Inspection		HRS		216.6		800	5844.3	6644.3	0
				ENC		140			4000		0
				MOS		11.8			05 Nov 2023		
[End Of Month Item]											
Engine											
	057159	No. 2 Engine - 800 Hr Inspection		HRS		216.6		800	5844.3	6644.3	0
				ENC		140			4000		0
				MOS		11.8			05 Nov 2023		
[End Of Month Item]											
Engine											
	5-12-01	Inspection Document 1		HRS		34			6026.9		0
				AFL		20			4145		0
				MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025
[MOS: +1m/-1m]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
5-12-03	Inspection Document 3		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[MOS: +1m/-1m]									
5-12-06	Inspection Document 6		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe	[MOS: +1m/-1m]									
5-12-07	Inspection Document 7		HRS		1311.4		1600	4749.5	6349.5	6374.5	0
			AFL		961			3204			0
			MOS		88			30 Jun 2017			
	Airframe	[HRS: +25/-25]									
5-12-08	Inspection Document 8		HRS				2400		7005.3	7030.3	0
			AFL								0
			MOS								
	Airframe	[HRS: +25/-25]									
5-12-11	Inspection Document 11		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe	[MOS: +1m/-1m]									
5-12-12	Inspection Document 12		HRS		216.6			5844.3			0
			AFL		140			4025			0
			MOS		11.8	-14	60	05 Nov 2023	22 Oct 2028*	22 Nov 2028	
	Airframe	[MOS: +1m/-1m]									
5-12-13	Inspection Document 13		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
	Airframe	[MOS: +1m/-1m]									
5-12-16	Inspection Document 16		HRS								0
			AFL								0
			MOS				96		31 Oct 2026	30 Nov 2026	
	Airframe	[MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
5-12-17	Inspection Document 17		HRS		216.6		1600	5844.3	7444.3	7469.3	0
			AFL		140			4025			0
			MOS		11.8			05 Nov 2023			
	Airframe		[HRS: +25/-25]								
5-12-19	Inspection Document 19		HRS		34		300	6026.9	6326.9	6351.9	0
			AFL		20			4145			0
			MOS		.4			17 Oct 2024			
	Airframe		[HRS: +25/-25]								
5-12-21	Inspection Document 21		HRS		34		300	6026.9	0		0
			AFL		20			4145	0		0
			MOS		.4		6	17 Oct 2024			
	Airframe		[MOS: +1m/-1m] [HRS: +25/-25]								
5-12-22	Inspection Document 22		HRS				6600		6600	6625	0
			AFL								0
			MOS								
	Airframe		[HRS: +25/-25]								
5-12-25	Inspection Document 25		HRS				7200		11972.4	11997.4	0
			AFL								0
			MOS								
	Airframe		[HRS: +25/-25]								
5-92-MA (0592MA)	Inspection Document Ma (Not Currently Used)		HRS		6060.9		500	0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
5-92-MC (0592MC)	Inspection Document Mc (Not Currently Used)		HRS		6060.9		180**	0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
12 - Servicing											
12-20-21-1600	Water Separator (Cleaning) Restoration		HRS		365.5		1600	5695.4	6349.5	6374.5	0
			AFL		239			3926			0
			MOS		18.6			11 Apr 2023			
	Airframe		[HRS: +25/-25]								
		5-12-07									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
12-20-21-1601	Ozone Converters (Cleaning) Restoration		HRS		6060.9		6600	0	6600	6625	0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
Airframe	5-12-22	[HRS: +25/-25]									
12-20-27-6400	Flap Roller Lubrication		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01	[MOS: +1m/-1m]									
12-20-27-6401	Trim Actuators Lubrication		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01	[MOS: +1m/-1m]									
12-20-27-6403	Horizontal Stabilizer Scissor Fitting Bolts and Aft Pivot Bolts Lubrication		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
Airframe	5-12-03	[MOS: +1m/-1m]									
12-20-32-6100	Shimmy Damper Servicing		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01	[MOS: +1m/-1m]									
12-20-32-6400	Landing Gear and Landing Gear Doors Lubrication		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01	[MOS: +1m/-1m]									
12-20-52-6400	Cabin Door Hinge Lubrication		HRS		632			5428.9			0
			AFL		628		3537			0	
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06	[MOS: +1m/-1m]									
12-20-52-6401	Door Keyed Cam Lock Lubrication		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01	[MOS: +1m/-1m]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
12-20-78-6400	Thrust Reverser Guide ROD (D-5100NS Aerosol Spray Method) Lubrication		HRS		34		300	6026.9	6326.9	6351.9	0
			AFL		20			4145			0
			MOS		.4			17 Oct 2024			
			[HRS: +25/-25]								
Airframe			5-12-19								
12-20-78-6401	Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and on)		HRS		34		300	6026.9	6326.9	6351.9	0
			AFL		20			4145			0
			MOS		.4			17 Oct 2024			
			[HRS: +25/-25]								
Airframe			5-12-19								
21 - AIR Conditioning											
211002	Emergency Pressurization Flow (UY005) Valve 4713-190243		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe			[End Of Month Item]								
211120 (211120L)	Left Bi Level Valve 1988-00-31779A		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe			[End Of Month Item]								
211120 (211120R)	Right Bi Level Valve 1988-00-31776A		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe			[End Of Month Item]								
212200	Motor and Blower Assembly 7003-4000348		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe			[End Of Month Item]								
21-22-00-2900	Cabin AIR Distribution Check Valves (Borescope) Special Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe			5-12-16								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
21-22-00-9600	Cockpit Side Window Defog Filter Discard		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Airframe											
21-30-00-7200	Pressurization System Operational and Functional Check		HRS		34			6026.9			0
			AFL		20			4145		0	
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
5-12-03											
213005	Manual Toggle Valve 52773-114		957	HRS		6060.9			0		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe											
[End Of Month Item]											
213006	Cabin Altitude (U1005) Controller 52770-114		1751	HRS		422.6			5638.3		0
			AFL		280			3885		0	
			MOS		21.9			03 Jan 2023			
			MSC			O/C					
Airframe											
[End Of Month Item]											
213007 (213007A)	Primary Outflow Valve 52771-314		896B	HRS		411.8			5649.1		0
			AFL		273			3892		0	
			MOS		20.7			07 Feb 2023			
			MSC			O/C					
Airframe											
[End Of Month Item]											
213007 (213007B)	Secondary Outflow Valve 52772-114		995	HRS		6060.9			0		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe											
[End Of Month Item]											
213101	Alt Pressure Switch GB300NA161		0744045	HRS		2352.9			3708		0
			AFL						0		
			MOS		183.5		14 Jul 2009				
			MSC			O/C					
Airframe											
[End Of Month Item]											
21-31-05-7200	Cabin Altitude Pressure Switch Functional Check			HRS		632			5428.9		0
			AFL		628			3537		0	
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe											
5-12-06											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
215001	Environmental Control Unit		HRS		6060.9			0			0
	2215460-2	388	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
215004	Pac Overheat Switch		HRS		4440.9			1620			0
	927223-2-1	1253	AFL								0
			MOS		225.8			06 Jan 2006			
	Airframe		MSC				O/C				
[End Of Month Item]											
215005	Acm Cooling Turbine		HRS		4705.9			1355			0
	2206610-1	382	AFL								0
			MOS		230.9			01 Aug 2005			
	Airframe		MSC				O/C				
[End Of Month Item]											
215006	Heat Exchanger		HRS		6060.9			0			0
	2340594-6	434	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
215100	Water Spray Ecu Aspirator		HRS		6060.9			0			0
	2215605-1	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
215101	Water Separator Temp 1 Sensor		HRS		6060.9			0			0
	1E62-1	3AV41	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
21-52-00-2200	Vapor Cycle Cooling System 12 Month Maintenance		HRS		34			6026.9			0
	(Airplanes Incorporating Vapor Cycle Cooling System)		AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01										
216002	Environmental Temp Controller		HRS		898.1			5162.8			0
	1E64-2	11BM40	AFL		617			3548			0
			MOS		49.6			12 Sep 2020			
	Airframe		MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216003 (216003B) Airframe	No. 2 Cabin Temp Sensor		HRS		6060.9			0			0
	1E47-1	3AV54	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
216003 (216003A) Airframe	No. 1 Cabin Temp Sensor		HRS		6060.9			0			0
	1E47-1	3AV55	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
216009 (216009A) Airframe	Cockpit Zone Temperature (UF029) Sensor		HRS		5948.9			112			0
	1E46-1	SN-UNKNOWN	AFL								0
			MOS		261.8			06 Jan 2003			
			MSC				O/C				
			[End Of Month Item]								
216009 (216009B) Airframe	Cabin Zone Temperature (UC021) Sensor		HRS		1481.8			4579.1			0
	1E46-1	4BK45	AFL		1146			3019			0
			MOS		118			31 Dec 2014			
			MSC				O/C				
			[End Of Month Item]								
216099 (216100) Airframe	Ecu Temp Control Valve		HRS		5454.9			606			0
	27241287-14	8AV140A	AFL								0
			MOS		247.5			13 Mar 2004			
			MSC				O/C				
			[End Of Month Item]								
216100 (216100R) Airframe	Right Cockpit Temperature Control (VT030) Valve		HRS		6060.9			0			0
	27241287-14	12AT251	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
216100 (216100L) Airframe	Left Cabin Temperature Control (VT029) Valve		HRS		6060.9			0			0
	27241287-14	4AV63	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
216101 (216101L) Airframe	Left Cabin Duct Overheat (SC013) Switch		HRS		6060.9			0			0
	1173T42	2133	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
216101 (216101R) Airframe	Right Cockpit Duct Overheat (SF034) Switch		HRS		6060.9			0			0
	1173T42	2150	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
217001 Airframe	Water Separator		HRS		6060.9			0			0
	2341316-2	399	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
217101 (217101L) Airframe	Left Ozone Converter		HRS		6060.9			0			0
	31A437-1	05721069	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
217101 (217101R) Airframe	Right Ozone Converter		HRS		6060.9			0			0
	31A437-1	05761073	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
22 - Auto Flight											
221009 Airframe	Autopilot (PC400) Controller		HRS		6060.9			0			0
	7003897-923	02052717	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
221010 (221010R) Airframe	Rudder Drive Servo		HRS		6060.9			0			0
	4006719-910	02016937	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
221010 (221010A) Airframe	Aileron Drive Servo		HRS		6060.9			0			0
	4006719-906	02026847	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
221010 (221010E) Airframe	Elevator Drive Servo		HRS		959.2			5101.7			0
	4005619-906	04028308	AFL		659			3506			0
			MOS		53.6			12 May 2020			
			MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										

23 - Communications											
23-10-00-7100	Crew Oxygen Mask Microphone and Switch Operational Check		HRS		34			6026.9			0
			AFL		20		4145			0	
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe											
5-12-01											
231500	Satelite SATCOM Data Unit 403068A-UAT		HRS		1614.7			4446.2			0
			AFL		1271		2894			0	
			MOS		131.3		20 Nov 2013				
			MSC				O/C				
Airframe											
[End Of Month Item]											
231501	Flitephone Vi Assembly Antenna 10101-00		HRS		4886.9			1174			0
			AFL							0	
			MOS		235.4		17 Mar 2005				
			MSC				O/C				
Airframe											
[End Of Month Item]											
231501 (231501A)	No. 2 SATCOM Antenna 10101-000		HRS		1614.7			4446.2			0
			AFL		1271		2894			0	
			MOS		131.3		20 Nov 2013				
			MSC				O/C				
Airframe											
[End Of Month Item]											
231503 (231503B)	Handset Phone 405621A-UAW		HRS		2011.1			4049.8			0
			AFL		1626		2539			0	
			MOS		160.5		15 Jun 2011				
			MSC				O/C				
Airframe											
[End Of Month Item]											
231503 (231503A)	Cockpit Handset Phone 405621B-UAB		HRS		2011.1			4049.8			0
			AFL		1626		2539			0	
			MOS		160.5		15 Jun 2011				
			MSC				O/C				
Airframe											
[End Of Month Item]											
231515 ^U	SATCOM High PASS/Low Noise Amplifier 403020H		HRS		1870.3			4190.6			0
			AFL		1492		2673			0	
			MOS		158.2		23 Aug 2011				
			MSC				O/C				
Airframe											
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
232003 (232003B) Airframe	No. 2 Comm Antenna		HRS		4886.9			1174			0
	21-38-1RF/36	21-38-1RF/36	AFL								0
			MOS		235.4			17 Mar 2005			
			MSC				O/C				
	[End Of Month Item]										
232003 (232003A) Airframe	No. 1 Comm Antenna		HRS		6060.9			0			0
	S65-8282-1	1119	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
232008 (232008A) Airframe	No. 1 Honeywell Primus li SRZ850 Integrated (RCZ851)		HRS		1300			4760.9			0
	Communication Unit		AFL		947			3218			0
	7510733-666	02057545	MOS		82.9			03 Dec 2017			
			MSC				O/C				
	[End Of Month Item]										
232008 (232008B) Airframe	No. 2 Honeywell Primus li SRZ850 Integrated (RCZ851)		HRS		1300			4760.9			0
	Communication Unit		AFL		947			3218			0
	7510733-666	02057544	MOS		82.9			03 Dec 2017			
			MSC				O/C				
	[End Of Month Item]										
232010 (232010A) Airframe	No. 1 Comm Transceiver		HRS		6060.9			0			0
	7510763-901	02054933	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
232010 (232010B) Airframe	No. 2 Comm Transceiver		HRS		6060.9			0			0
	7510763-901	02054954	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
232013 (232013B) Airframe	No. 2 Cluster Comm Module		HRS		6060.9			0			0
	7510784-835	02058030	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
232013 (232013A) Airframe	No. 1 Cluster Comm Module		HRS		6060.9			0			0
	7510784-835	02058024	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233002	Video Amplifer 103006-1	1960303	HRS		5912.9			148			0
			AFL						0		
			MOS		259		30 Mar 2003				
			MSC			O/C					
Airframe	[End Of Month Item]										
233003	Audio Amplifer 102008-1	2120602	HRS		6060.9			0			0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe	[End Of Month Item]										
233006 ^U	Gdl-69A Garmin 011-00987-00	47752807	HRS								0
			AFL						0		
			MOS		232.7		07 Jun 2005				
			MSC			O/C					
Airframe	[End Of Month Item]										
233007 ^U	Mx-20 Mfd Garmin PN	NOT INSTALLED	HRS		1706.1			4354.8			0
			AFL		1370		2795		0		
			MOS		145.1		28 Sep 2012				
			MSC			O/C					
Airframe	[End Of Month Item]										
233008 ^U	GPS Antenna CI420-1	5011538	HRS								0
			AFL						0		
			MOS		232.7		07 Jun 2005				
			MSC			O/C					
Airframe	[End Of Month Item]										
233009 ^U	Converter 933612-02	482	HRS								0
			AFL						0		
			MOS		232.7		07 Jun 2005				
			MSC			O/C					
Airframe	[End Of Month Item]										
23-50-00-7100	Audio Amplifier Emergency Switch Operational Check (Airplanes -5001 Thru -6000)		HRS		34			6026.9			0
			AFL		20		4145		0		
			MOS		.4	14	12	17 Oct 2024 31 Oct 2025* 30 Nov 2025			
			[MOS: +1m/-1m]								
Airframe	5-12-01										
235001 (235001B)	No. 2 Audio Control Panel Amplifier 7511001-915	02058174	HRS		6060.9			0			0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
235001 (235001A) Airframe	No. 1 Audio Control Panel Amplifier		HRS		6060.9			0			0
	7511001-915	02058154	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
236000 Airframe	Airshow Unit		HRS		6060.9			0			0
	920040	-	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
23-60-00-7200 Airframe	Static Discharging System Functional Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024 31 Oct 2026* 30 Nov 2026			
			[MOS: +1m/-1m]								
5-12-11											
236002 Airframe	Cockpit Airshow Controller		HRS		6060.9			0			0
	922000-2	2065	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
23-70-00-9600 (237006A) Airframe	Cockpit Voice Recorder Underwater Locator Beacon		HRS		1239.2			4821.7			0
	Battery Discard		AFL		889			3276			0
	DK120/90	AT118230	MOS		72.3			22 Oct 2018 30 Sep 2025			
			MSC				DUE				EXPIRATION
			[End Of Month Item]								
237001 Airframe	Cockpit Voice Recorder		HRS		5598.9			462			0
	2100-1020-02	000152199	AFL								0
			MOS		250.8			05 Dec 2003			
			MSC				O/C				
			[End Of Month Item]								
237002 Airframe	Cvr Gravity Switch		HRS		6060.9			0			0
	6895D1-X-5-5	3834	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
237004 Airframe	Cvr Control Unit		HRS		6060.9			0			0
	S251-1120-00	000176964	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
237006	Cvr Underwater Locator Beacon		HRS		5598.9			462			0
	DK120	DU59722	AFL								0
			MOS		250.8			05 Dec 2003			
	Airframe		MSC				O/C				
			[End Of Month Item]								
238001	Stdbby Control Unit		HRS		6060.9			0			0
	7513000-835	02072343	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
23-90-20-7200	No. 2 Transponder Functional Check (Airplanes -5001 Thru -6000)		HRS		34			6026.9			0
			AFL		20			4145			0
	7517400-902	02056462	MOS		.4		24	17 Oct 2024	31 Oct 2026		
	(B238002)		[End Of Month Item]								
23-90-20-7200	No. 1 Transponder Functional Check (Airplanes -5001 Thru -6000)		HRS		34			6026.9			0
			AFL		20			4145			0
	7517400-902	02056425	MOS		.4		24	17 Oct 2024	31 Oct 2026		
	(B238002)		[End Of Month Item]								
24 - Electrical Power											
240001	Left Power Control (UD015) Unit		HRS		3515.9			2545			0
	91479-1	634	AFL								0
	(240001L)		MOS		207.5			14 Jul 2007			
	Airframe		MSC				O/C				
			[End Of Month Item]								
240001	Right Power Control (UE016) Unit		HRS		3482.9			2578			0
	91479-1	430	AFL								0
	(240001R)		MOS		206.9			02 Aug 2007			
	Airframe		MSC				O/C				
			[End Of Month Item]								
242050	Right AC (UE018) Generator		HRS		3515.9			2545			0
	91372-3	581	AFL								0
	(242050R)		MOS		207.5			14 Jul 2007			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
242050 (242050L) Airframe	Left AC (UD017) Generator 91372-3		HRS		3515.9			2545			0
		574	AFL								0
			MOS		207.5			14 Jul 2007			
			MSC				O/C				
			[End Of Month Item]								
242100 Airframe	Stormscope Inverter SPC5		HRS		6060.9			0			0
		4062	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
243003 (243003L) Airframe	Left Generator (UT007) Control Unit 51525-001F		HRS		6060.9			0			0
		Y2244	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
243003 (243003R) Airframe	Right Generator (UT008) Control Unit 51525-001F		HRS		5074.9			986			0
		Y1421	AFL								0
			MOS		239.6			12 Nov 2004			
			MSC				O/C				
			[End Of Month Item]								
243003 (243003A) Airframe	APU Generator (UT032) Control Unit 51525-001F		HRS		694.7			5366.2			0
		P1393	AFL		467			3698			0
			MOS		38.8			06 Aug 2021			
			MSC				O/C				
			[End Of Month Item]								
243004 (243004L) Airframe	Left Dc (EI011) Ammeter MD144-1		HRS		6060.9			0			0
		D22077	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
243004 (243004R) Airframe	Right Dc (EI010) Ammeter MD144-1		HRS		6060.9			0			0
		D22080	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
243005 Airframe	Dc (EI009) Voltmeter C662502-0101		HRS		6060.9			0			0
		C221191	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
243007	Main Ship (UY006) Battery		HRS		160.5			5900.4			0
	S3597-4		AFL		106			4059			0
	41353613		MOS		8			29 Feb 2024			
	Airframe		MSC				O/C				
			[End Of Month Item]								
243008	Overheat Monitor-		HRS		6060.9			0			0
	1529-1		AFL		4165			0			0
	3736		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
243009	Battery Temp Indicator		HRS		5191.9			869			0
	1229-1		AFL								0
	1848		MOS		241.9			03 Sep 2004			
	Airframe		MSC				O/C				
			[End Of Month Item]								
243015	Battery Disconnect (KY001) Relay		HRS		6060.9			0			0
	A876K		AFL		4165			0			0
	CN18213		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
243016	Overvoltage (UZ003) Monitor-		HRS		6060.9			0			0
	1645-1-3		AFL		4165			0			0
	2997		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
24-32-00-7202	42 AMP-Hour Concorde Lead ACID Main Battery		HRS		34		300	6026.9	6326.9	6351.9	0
	(Capacity Check) Functional Check		AFL		20			4145			0
	S3597-4		MOS		.4		6	17 Oct 2024	30 Apr 2025	31 May 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]								
24-32-00-7203	No. 2 L3 Com Ps-835D Standby Battery Pack (Capacity		HRS		34			6026.9			0
	Check) Functional Check		AFL		20			4145			0
	501-1228-04		MOS		.4		12	17 Oct 2024	31 Oct 2025	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
			5-12-01								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
24-32-00-7203	No. 1 L3 Com Ps-835D Standby Battery Pack (Capacity		HRS		34			6026.9			0
	Check) Functional Check		AFL		20			4145			0
	501-1228-04	11217	MOS		.4		12	17 Oct 2024	31 Oct 2025	30 Nov 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe		5-12-01									
24-32-00-7204	No. 1 L3 Com Ps-855B Standby Battery Pack (Capacity		HRS		34			6026.9			0
	Check) Functional Check		AFL		20			4145			0
	501-1228-04	11217	MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	[MOS: +1m/-1m]										
Airframe		5-12-01									
24-32-00-7204	No. 2 L3 Com Ps-855B Standby Battery Pack (Capacity		HRS		34			6026.9	0		0
	Check) Functional Check		AFL		20			4145	0		0
	501-1228-04	1368	MOS		.4		12	17 Oct 2024			
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe		5-12-01									
24-41-02-7200	External Power Overvoltage System Functional Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
	[MOS: +1m/-1m]										
Airframe		5-12-13									
245079 (245079R)	Right Start Cntl NZ012 PCB		HRS		6060.9			0			0
	6318324-5	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe		[End Of Month Item]									
245079 (245079L)	Left Start Cntl NZ013 PCB		HRS		6060.9			0			0
	6318324-5	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe		[End Of Month Item]									
245080	Trim NZ001 PCB		HRS		6060.9			0			0
	6518351-7	0588	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245081	Press NZ002 PCB		HRS		6060.9			0			0
	6518352-5	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245082	Dimming NZ023 PCB		HRS		6060.9			0			0
	6518353-6	-	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245083 (245083L)	Left Eec Interface NZ021 PCB		HRS		6060.9			0			0
	6618002-3	0671	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245083 (245083R)	Right Eec Interface NZ020 PCB		HRS		6060.9			0			0
	6618002-3	0672	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245084	Landing Gear NZ004 PCB		HRS		6060.9			0			0
	6618704-6	0395	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245085	Tail Deice NZ005 PCB		HRS		3770.9			2290			0
	6618705-6	0607	AFL								0
			MOS		213.4			17 Jan 2007			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245086	Squat Sw NZ006 PCB		HRS		6060.9			0			0
	6618706-1	0384	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245087	Cabin Door NZ007 PCB		HRS		6044.9			16			0
	6618707-21	0155	AFL								0
			MOS		265.2			25 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245091	No Take-Off NZ008 PCB		HRS		6060.9			0			0
	6618708-1		AFL		4165			0			0
	0316		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245092 (245092L)	Left Fuel NZ015 PCB		HRS		6060.9			0			0
	6618714-11		AFL		4165			0			0
	0655		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245092 (245092R)	Right Fuel NZ014 PCB		HRS		6060.9			0			0
	6618714-11		AFL		4165			0			0
	0648		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245094	Hyd NZ016 PCB		HRS		5447.9			613			0
	6618723-1		AFL								0
	0382		MOS		247.2			25 Mar 2004			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245095	Pos Tail NZ017 PCB		HRS		5447.9			613			0
	6618721-1		AFL								0
	0403		MOS		247.2			25 Mar 2004			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245096 (245096L)	Left Anti Ice NZ019 PCB		HRS		6060.9			0			0
	6618718-1		AFL		4165			0			0
	0632		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245096 (245096R)	Right Anti-Ice NZ018 PCB		HRS		6060.9			0			0
	6618718-1		AFL		4165			0			0
	0633		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
245097	Fan Control NZ022 PCB		HRS		6060.9			0			0
	6618722-1		AFL		4165			0			0
	0371		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
245098	Rudder Bias NZ029 PCB		HRS		5435.9			625			0
	6618812-1	0366	AFL								0
			MOS		246.8			04 Apr 2004			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245103	APU NZ025 PCB		HRS		6060.9			0			0
	6618808-18	0229	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
245104	APU NZ026 PCB		HRS		6060.9			0			0
	6618809-1	0323	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
25 - Equipment/Furnishings											
25-11-01-2200	Crew Seats Detailed Inspection		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
		5-12-08									
252003	Temperature Probe		HRS		6060.9			0			0
	102DB1AG	A43786	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats		HRS		632			5428.9			0
	Detailed Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	Airframe										
	5-12-06										
252500 ^U	First AID Kit		HRS		34			6026.9			0
	42 KIT	NA	AFL		20			4145			0
			MOS		.4			17 Oct 2024			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
25-60-00-2200	First AID Kit Detailed Inspection		HRS		34			6026.9			0
	PN	SN-UNKNOWN	AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[End Of Month Item] [MOS: +1m/-1m]								
	5-12-01										
25-60-00-2201	Smoke Goggles Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
	5-12-01										
25-60-00-2202	Life Vest Pouch Detailed Inspection		HRS		216.6			5844.3			0
			AFL		140			4025			0
			MOS		11.8	-14	60	05 Nov 2023	22 Oct 2028*	22 Nov 2028	
	Airframe		[MOS: +1m/-1m]								
	5-12-12										
25-60-00-9600	No. 11 Life Jacket		HRS		245.1			5815.8			0
	P01074-207	23090160418	AFL								0
	(256001)		MOS		13.3		60	21 Sep 2023	30 Sep 2028		
	Airframe		[End Of Month Item]								
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 2		HRS		632			5428.9			0
			AFL		628			3537			0
	P01074-103	21041000090	MOS		35.4		60	19 Nov 2021	30 Nov 2026		
	(256001)		[End Of Month Item]								
	Airframe										
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 10		HRS		245.1			5815.8			0
			AFL								0
	P01074-207	23090160417	MOS		13.3		60	21 Sep 2023	30 Sep 2028		
	(256001)		[End Of Month Item]								
	Airframe										
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 7		HRS		632			5428.9			0
			AFL		628			3537			0
	PO1074-103	21041000085	MOS		35.4		60	19 Nov 2021	30 Nov 2026		
	(256001)		[End Of Month Item]								
	Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 8		HRS		245.1			5815.8			0
	P1074-207		AFL								0
	23090160416		MOS		13.3		60	21 Sep 2023	30 Sep 2028		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 4		HRS		632			5428.9			0
	P01074-103		AFL		628			3537			0
	21041000088		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 6		HRS		632			5428.9			0
	PO1074-103		AFL		628			3537			0
	21041000086		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 1		HRS		632			5428.9			0
	P01074-103		AFL		628			3537			0
	21041000089		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 3		HRS		632			5428.9			0
	P01074-103		AFL		628			3537			0
	21041000087		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 9		HRS		632			5428.9			0
	P01074-207		AFL		628			3537			0
	21100780021		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration - No. 5		HRS		632			5428.9			0
	P01074-103		AFL		628			3537			0
	21041000084		MOS		35.4		60	19 Nov 2021	30 Nov 2026		
			[End Of Month Item]								
(256001)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
25-60-00-9602	Crew Flashlight D-Cell Battery Discard		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01		[MOS: +1m/-1m]								
256002	Emergency Locator Transmitter		HRS		663.1			5397.8			0
	453-5000-999	07465	AFL								0
			MOS		36.9			01 Oct 2021			
Airframe			MSC				O/C				
			[End Of Month Item]								
256004	ELT Antenna		HRS		6060.9			0			0
	110-328-01	3070	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
256007	Digital Interface Unit		HRS		6060.9			0			0
	453-6500	01553	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
25-60-10-7202	Artex C406-2 Emergency Locator Transmitter System		HRS		89.7			5971.2			0
	Detailed Inspection and Functional Test (Airplanes -5501 Thru -5564 and Airplanes -5002 Thru -5372 Incorporating SB560XL-25-11)		AFL		53			4112			0
	453-5000-999		MOS		4.9	-31	12	02 Jun 2024	31 May 2025*		
(A256104)			[End Of Month Item]								
Airframe											
25-60-10-9600	Artex Emergency Locator Transmitter Battery Discard		HRS		663.1			5397.8			0
	452-0133	392634-014	AFL								0
			MOS		36.9		60	01 Oct 2021	01 Jan 2027	01 Feb 2027	
(256003)			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
256063	First AID Kit		HRS		6060.9			0			0
	PN	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				H/T				
			[End Of Month Item]								
26 - FIRE Protection											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
261002 (261002L) Airframe	Left Engine FIRE Detect (UT021) Control Unit		HRS		6060.9			0			0
	377-02838	0208307	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
261002 (261002R) Airframe	Right Engine FIRE Detect (UT020) Control Unit		HRS		6060.9			0			0
	377-02838	0216415	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
26-11-00-7200 Airframe	Optional Baggage Compartment and Lavatory Smoke		HRS		632			5428.9			0
	Detection System Functional Check		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
5-12-06											
262001 (262001F) Airframe	Forward Engine FIRE Bottle		HRS		632			5428.9			0
	30400037-1	53295B1	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				
			[End Of Month Item]								
262001 (262001A) Airframe	Aft Engine FIRE Bottle		HRS		632			5428.9			0
	30400037-1	56330B1	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				
			[End Of Month Item]								
262001 (262001AP) Airframe	APU FIRE Bottle		HRS		632			5428.9			0
	30100033-3	78928A1	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				
			[End Of Month Item]								
262002 (262002R) Airframe	Cabin Portable Halon FIRE Extinguisher		HRS		216.6			5844.3			0
	C352TS	F-95367860	AFL		140			4025			0
			MOS		11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								
262002 (262002L) Airframe	Cockpit Portable Halon FIRE Extinguisher		HRS		216.6			5844.3			0
	C352TS	F-95367859	AFL		140			4025			0
			MOS		11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
26-21-00-2200	Engine FIRE Extinguisher Wiring Detailed Inspection		HRS		34			6026.9	0		0
			AFL		20			4145	0		0
			MOS		.4		24	17 Oct 2024			
Airframe		[End Of Month Item]									
		4-12-MV									
26-21-00-7100	Engine FIRE Extinguishing System Functional Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe		5-12-06									
26-21-01-7100	Aft Engine FIRE Extinguisher Bottle Low Pressure Switch Operational Check		HRS								0
			AFL								0
	30400037-1	56330B1	MOS		37		60	29 Sep 2021	29 Sep 2026		
Airframe		HYDRO CHECK									
26-21-01-7100	Fwd Engine FIRE Extinguisher Bottle Low Pressure Switch Operational Check		HRS								0
			AFL								0
	30400037-1	53295B1	MOS		37		60	29 Sep 2021	29 Sep 2026		
Airframe		HYDRO CHECK									
26-21-01-7800	Forward Engine FIRE Extinguisher Bottle (Hydrostatic Test) Restoration		HRS								0
			AFL								0
	30400037-1	53295B1	MOS		37		60	29 Sep 2021	30 Sep 2026		
(B262008)			[End Of Month Item]								
Airframe		HYDRO CHECK									
26-21-01-7800	Aft Engine FIRE Extinguisher Bottle (Hydrostatic Test) Restoration		HRS								0
			AFL								0
	30400037-1	56330B1	MOS		37		60	29 Sep 2021	30 Sep 2026		
(B262008)			[End Of Month Item]								
Airframe		HYDRO CHECK									
26-21-01-9600	13083-5 Aft Engine FIRE Extinguisher Forward Cartridge Squib Discard - Total Life		HRS								0
			AFL								0
	13083-5	ESD21H842-001	MOS		38.9		108	01 Aug 2021	31 Aug 2030		
Airframe		[End Of Month Item]									
		MANUFACTURE									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
26-21-01-9600	13083-5 Aft Engine FIRE Extinguisher Aft Cartridge Squib Discard - Total Life		HRS								0
			AFL								0
	13083-5	ESD21H842-001	MOS		38.9		108	01 Aug 2021	31 Aug 2030		
			[End Of Month Item]								MANUFACTURE
Airframe											
26-21-01-9600	13083-5 Forward Engine FIRE Extinguisher Forward Cartridge Squib Discard - Total Life		HRS								0
			AFL								0
	13083-5	ESD21H842-001	MOS		38.9		108	01 Aug 2021	31 Aug 2030		
			[End Of Month Item]								MANUFACTURE
Airframe											
26-21-01-9600	13083-5 Forward Engine FIRE Extinguisher Aft Cartridge Squib Discard - Total Life		HRS								0
			AFL								0
	13083-5	ESD21H842-001	MOS		38.9		108	01 Aug 2021	31 Aug 2030		
			[End Of Month Item]								MANUFACTURE
Airframe											
26-21-01-9600.1	13083-5 Aft Engine FIRE Extinguisher Aft Cartridge Squib Discard - Service Life		HRS		632			5428.9			0
			AFL		628			3537			0
	13083-5	ESD21H842-001	MOS		35.4		72	19 Nov 2021	30 Nov 2027		
			[End Of Month Item]								
Airframe											
26-21-01-9600.1	13083-5 Forward Engine FIRE Extinguisher Forward Cartridge Squib Discard - Service Life		HRS		632			5428.9			0
			AFL		628			3537			0
	13083-5	ESD21H842-001	MOS		35.4		72	19 Nov 2021	30 Nov 2027		
			[End Of Month Item]								
Airframe											
26-21-01-9600.1	13083-5 Aft Engine FIRE Extinguisher Forward Cartridge Squib Cartridge - Service Life		HRS		632			5428.9			0
			AFL		628			3537			0
	13083-5	ESD21H842-001	MOS		35.4		72	19 Nov 2021	30 Nov 2027		
			[End Of Month Item]								
Airframe											
26-21-01-9600.1	13083-5 Forward Engine FIRE Extinguisher Aft Cartridge Squib Discard - Service Life		HRS		632			5428.9			0
			AFL		628			3537			0
	13083-5	ESD21H842-001	MOS		35.4		72	19 Nov 2021	30 Nov 2027		
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
26-21-01-9601	13083-5 Auxiliary Power Unit FIRE Extinguisher Cartridge		HRS								0
	Squib Discard - Total Life		AFL								0
	13083-5	ESD21H845-001	MOS		38.9		108	01 Aug 2021	01 Aug 2030		MANUFACTURE
Airframe											
26-21-01-9601.1	13083-5 Auxiliary Power Unit FIRE Extinguisher Cartridge		HRS		632			5428.9			0
	Squib Discard - Service Life		AFL		628			3537			0
	13083-5	ESD21H845-001	MOS		35.4		72	19 Nov 2021	19 Nov 2027		
Airframe											
26-22-00-2200	Cabin Portable FIRE Extinguisher Detailed and (Weight)		HRS		34			6026.9			0
	Functional Check		AFL		20			4145			0
	C352TS	F-95367860	MOS		.4		12	17 Oct 2024	31 Oct 2025		
(B262012)			[End Of Month Item]								
Airframe											
26-22-00-2200	Cockpit Portable FIRE Extinguisher Detailed and (Weight)		HRS		34			6026.9			0
	Functional Check		AFL		20			4145			0
	C352TS	F-95367859	MOS		.4		12	17 Oct 2024	31 Oct 2025		
(B262012)			[End Of Month Item]								
Airframe											
26-22-00-2201	Cockpit Portable FIRE Extinguisher Restoration (Internal		HRS		967.4			5093.5			0
	Inspection)		AFL		671			3494			0
	C352TS	F-95367859	MOS		54.3		72	20 Apr 2020	20 Apr 2026		
Airframe											
26-22-00-2201	Cabin Portable FIRE Extinguisher Restoration (Internal		HRS		967.4			5093.5			0
	Inspection)		AFL		671			3494			0
	C352TS	F-95367860	MOS		54.3		72	20 Apr 2020	20 Apr 2026		
Airframe											
26-22-00-7800	Cockpit Portable FIRE Extinguisher (Hydrostatic Test)		HRS								0
	Functional Check		AFL								0
	C352TS	F-95367859	MOS		54.9		144	01 Apr 2020	30 Apr 2032		
(B262004)			[End Of Month Item]								
											HYDRO CHECK
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
26-22-00-7800 (B262004) Airframe	Cabin Portable FIRE Extinguisher (Hydrostatic Test) Functional Check		HRS								0
			AFL								0
	C352TS	F-95367860	MOS		54.9		144	01 Apr 2020	30 Apr 2032		
			[End Of Month Item]								HYDRO CHECK
26-23-00-2200 Airframe	Auxiliary Power Unit FIRE Extinguisher Wiring Detailed Inspection		HRS		34			6026.9	0		0
			AFL		20			4145	0		0
			MOS		.4		24	17 Oct 2024			
			[End Of Month Item]								
26-23-00-7100 Airframe	4-12-MV										
	Auxiliary Power Unit FIRE Extinguishing System Operational and Functional Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
		[MOS: +1m/-1m]									
26-23-00-7101 (26-21-01-7101) Airframe	5-12-06										
	Auxiliary Power Unit FIRE Extinguisher Bottle Low Pressure Switch Operational Check		HRS								0
			AFL								0
	30100033-3	78928A1	MOS		36.3		60	22 Oct 2021	22 Oct 2026		HYDRO CHECK
26-23-00-7800 (B262005) Airframe	APU FIRE Extinguisher Bottle (Hydrostatic Test) Restoration		HRS								0
			AFL								0
	30100033-3	78928A1	MOS		36.3		60	22 Oct 2021	31 Oct 2026		
			[End Of Month Item]								HYDRO CHECK
263004 (263004) Airframe	Auxiliary Power Unit FIRE Extinguisher Cartridge Squib		HRS		632			5428.9			0
	13083-5	ESD21H845-001	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				MANUFACTURE
		[End Of Month Item]									
263006 (263006) Airframe	Forward Engine FIRE Extinguisher Forward Cartridge Squib		HRS		632			5428.9			0
			AFL		628			3537			0
	13083-5	ESD21H842-001	MOS		35.4			19 Nov 2021			
			MSC				O/C				MANUFACTURE
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
263008 (263008) Airframe	Forward Engine FIRE Extinguisher Aft Cartridge Squib		HRS		632			5428.9			0
	13083-5	ESD21H842-001	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				MANUFACTURE
				[End Of Month Item]							
263010 (263010) Airframe	Aft Engine FIRE Extinguisher Forward Cartridge Squib		HRS		632			5428.9			0
	13083-5	ESD21H842-001	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				MANUFACTURE
				[End Of Month Item]							
263012 (263012) Airframe	Aft Engine FIRE Extinguisher Aft Cartridge Squib		HRS		632			5428.9			0
	13083-5	ESD21H842-001	AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				MANUFACTURE
				[End Of Month Item]							
27 - Flight Controls											
27-10-00-2201	Aileron Wing Cable Detailed Inspection (Airplanes -5556 and on, and Airplanes -5002 Thru -5555 Incorporating SB560XL-27-22)		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
			Airframe	5-12-08							
27-10-00-2202	Aileron Trim Actuator Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
			Airframe	5-12-01							
27-10-00-2203	Aileron and Aileron Trim Detailed Inspection and Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
			Airframe	5-12-08							
27-10-00-7201	Aileron Trim Tab and Pushrod (Free Play) Functional Check		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
			Airframe	5-12-07							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
27-20-00-2200	Rudder Bias Cable Assembly Detailed Inspection		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe	5-12-08		[HRS: +25/-25]								
27-20-00-2201	Rudder Trim Actuator Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-01		[MOS: +1m/-1m]								
27-20-00-2202	Rudder and Rudder Trim Detailed Inspection and Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe	5-12-08		[HRS: +25/-25]								
27-20-00-7201	Rudder Trim Actuator and Pushrod (Free Play)Functional Check		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe	5-12-07		[HRS: +25/-25]								
272001	Rudder Bias Shutoff Valve		HRS		6060.9			0			0
	5307-1	0423C	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
272002 (272002L)	Left Stick Shaker (MC001) Unit		HRS		6060.9			0			0
	201	5574	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
272002 (272002R)	Right Stick Shaker (MF004) Unit		HRS		6060.9			0			0
	201	5566	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
272003	Rudder Bias Actuator		HRS		836.3			5224.6			0
	6660613-12	6209	AFL		581			3584			0
			MOS		46.3			22 Dec 2020			
Airframe			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
273004	Servo Actuator		HRS		6060.9			0			0
	44430-3739	T390	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
273020	Aft Elevator Trim Cable Assembly		HRS		1706.1			4354.8			0
	6660003-1	NSN	AFL		1370			2795			0
			MOS		145.1			28 Sep 2012			
	Airframe		MSC				O/C				
			[End Of Month Item]								
27-31-00-2200	Elevator and Trim Tab System Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
	5-12-06										
27-31-00-2201	Elevator and Elevator Trim Detailed Inspection and Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
	5-12-08										
27-31-00-7201	Elevator Trim Tab and Pushrod (Free Play)Functional Check		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
	5-12-07										
273201	Elev Trim Switch		HRS		6060.9			0			0
	8-405-04	B53612	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
274000	Horizontal Stabilizer Actuator		HRS		5803.9			257			0
	41011680-107	0104	AFL								0
			MOS		255.4			17 Jul 2003			
	Airframe		MSC				O/C				
			[End Of Month Item]								
27-40-00-7200	Two-Position Horizontal Stabilizer Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
	5-12-08										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
274013	Horizontal Stabilizer Isolation (UY015) Valve		HRS		6060.9			0			0
	13027-4	4906	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
274044	Horizontal Stab Valve Assy		HRS		1657.9			4403			0
	65680	1975	AFL		1317			2848			0
			MOS		135.8			06 Jul 2013			
	Airframe		MSC				O/C				
			[End Of Month Item]								
275001	Flap Control (UY024) Valve		HRS		4152.9			1908			0
	66720	2370	AFL								0
			MOS		220			29 Jun 2006			
	Airframe		MSC				O/C				
			[End Of Month Item]								
275003 (275003L)	Left Flap Actuator		HRS		262			5798.9			0
	1535000-3	4019	AFL		177			3988			0
			MOS		14.5			15 Aug 2023			
	Airframe		MSC				O/C				
			[End Of Month Item]								
275003 (275003R)	Right Flap Actuator		HRS		6060.9			0			0
	1535000-1	1612	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
27-51-00-2200	Flap Cables Detailed Inspection and Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
		5-12-08									
276001 (276001L)	Left Speed Brake Actuator		HRS		6060.9			0			0
	1535500-1	2175	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
276001 (276001R)	Right Speed Brake Actuator		HRS		2352.9			3708			0
	1535500-1	2857	AFL								0
			MOS		183.5			14 Jul 2009			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
276002	Speed Brake Control Valve		HRS		6060.9			0			0
	66720	2546	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
276003	Speed Brake Safety Valve		HRS		6060.9			0			0
	68930	1191	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
27-71-00-7100	Control (Gust) Lock System Operational Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
5-12-01											
28 - Fuel											
28-00-02-2200	Microbiological Contamination Inspection (Airplanes Not Using the Biocidal Preventative Treatment)		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4		3	17 Oct 2024	31 Jan 2025		
	Airframe		[End Of Month Item]								
280003 (280003L)	Left Fuel Relief Valve Assy		HRS		6060.9			0			0
	840203-105	2635XP	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
280003 (280003R)	Right Fuel Relief Valve Assy		HRS		6060.9			0			0
	840203-105	2536XP	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
280004 (280004L)	Left High Lvl Fuel Valve		HRS		6060.9			0			0
	61087	3195	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
280004 (280004R) Airframe	Right High Lvl Fuel Valve		HRS		6060.9			0			0
	61087	2984	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
281101 (281101R) Airframe	Right Fuel Vent Float Valve		HRS		6060.9			0			0
	60221-4	783	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
281101 (281101L) Airframe	Left Fuel Vent Float Valve		HRS		6060.9			0			0
	60221-4	758	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
28-11-04-2200 Airframe	Fuel Filler CAP Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	5-12-01										
282011 (282011B) Airframe	Left Forward Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101	1799	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
282011 (282011E) Airframe	Right Forward Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101	1832	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
282011 (282011D) Airframe	Right Aft Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101	1798	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
282011 (282011F) Airframe	Right Mid Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101	1835	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282011 (282011A) Airframe	Left Aft Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101		AFL		4165			0			0
	1796		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282011 (282011C) Airframe	Left Mid Scavenge Fuel Ejector Pump		HRS		6060.9			0			0
	2950024-101		AFL		4165			0			0
	1834		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282012 (282012R) Airframe	Right Wing Boost Fuel Electric Pump		HRS		6060.9			0			0
	LR55540		AFL		4165			0			0
	B695		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282012 (282012A) Airframe	Left Fuel Boost Cartridge		HRS		1644.3			4416.6			0
	LR55505-2		AFL		1289			2876			0
	B616		MOS		132.4			17 Oct 2013			
			MSC				O/C				
			[End Of Month Item]								
282012 (282012L) Airframe	Left Wing Boost Fuel Electric Pump		HRS		6060.9			0			0
	LR55540		AFL		4165			0			0
	B696		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282012 (282012B) Airframe	Right Fuel Boost Cartridge		HRS		6060.9			0			0
	LR55505		AFL		4165			0			0
	B700		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282013 (282013L) Airframe	Left Wing Primary Motive Flow Ejector Pump		HRS		6060.9			0			0
	2950023-101		AFL		4165			0			0
	625		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282013 (282013R) Airframe	Right Wing Primary Motive Flow Ejector Pump		HRS		6060.9			0			0
	2950023-101		AFL		4165			0			0
	621		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282014	Fuel Crossfeed Actuator		HRS		6060.9			0			0
	MA20A1029-1		AFL		4165			0			0
	U14246		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282100	Right Wing Single PT Refuel/Defuel Shutoff Valve		HRS		6060.9			0			0
	80002-101		AFL		4165			0			0
	1274		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282100	Left Wing Single PT Refuel/Defuel Shutoff Valve		HRS		6060.9			0			0
	80002-101		AFL		4165			0			0
	1301		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282106	Fuel Crossfeed Valve		HRS		6060.9			0			0
	125838AW		AFL		4165			0			0
	U22215		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282108	Left Motive Flow Shutoff (UY009) Valve		HRS		6060.9			0			0
	4151		AFL		4165			0			0
	608		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282108	Right Motive Flow Shutoff (UY008) Valve		HRS		6060.9			0			0
	4151		AFL		4165			0			0
	607		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282118	Right Fuel Shut-Off Valve		HRS								0
	31J2944-01		AFL								0
	WV209742		MOS		56.6			10 Feb 2020			
	Airframe		MSC				O/C				
			[End Of Month Item]								
282118	Left Fuel Shut-Off Valve		HRS								0
	31J2944-01		AFL								0
	WV748059		MOS		56.7			08 Feb 2020			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
282200 (282200R) Airframe	Right Low Level Valve Assy		HRS		6060.9			0			0
	726400-1		AFL		4165			0			0
	555		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282200 (282200L) Airframe	Left Low Level Valve Assy		HRS		6060.9			0			0
	726400-1		AFL		4165			0			0
	554		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282201 Airframe	Valve-Refuel/Defuel		HRS		6060.9			0			0
	9036-351-2		AFL		4165			0			0
	0711		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282202 (282202L) Airframe	Left Fuel Valve Assy		HRS		6060.9			0			0
	750800-2		AFL		4165			0			0
	706E		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
282202 (282202R) Airframe	Right Fuel Valve Assy		HRS		6060.9			0			0
	750800-2		AFL		4165			0			0
	708E		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284012 (284012R) Airframe	Right Low Fuel Level Sensor		HRS		632			5428.9			0
	L16H-15		AFL		628			3537			0
	1449		MOS		35.4			19 Nov 2021			
			MSC				O/C				
			[End Of Month Item]								
284012 (284012L) Airframe	Left Low Fuel Level Sensor		HRS		6060.9			0			0
	GIF5400-43		AFL		4165			0			0
	1134		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284013 (284013L) Airframe	Left Wing Fuel Qty W0 Probe		HRS		6060.9			0			0
	10634T07Y00		AFL		4165			0			0
	1046		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284013 (284013R) Airframe	Right Wing Fuel Qty W0 Probe 10634T07Y00		HRS		6060.9			0			0
		1086	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284014 (284014L) Airframe	Left Wing Fuel Qty W1 Probe 10634T02Y00		HRS		6060.9			0			0
		1091	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284014 (284014R) Airframe	Right Wing Fuel Qty W1 Probe 10634T02Y00		HRS		6060.9			0			0
		1098	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284015 (284015L) Airframe	Left Wing Fuel Qty W2 Probe 10634T03Y00		HRS		6060.9			0			0
		1067	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284015 (284015R) Airframe	Right Wing Fuel Qty W2 Probe 10634T03Y00		HRS		6060.9			0			0
		1072	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284016 (284016L) Airframe	Left Wing Fuel Qty W3 Probe 10634T04Y00		HRS		6060.9			0			0
		1192	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284016 (284016R) Airframe	Right Wing Fuel Qty W3 Probe 10634T04Y00		HRS		6060.9			0			0
		1279	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284017 (284017R) Airframe	Right Wing Fuel Qty W4 Probe 10634T05Y00		HRS		6060.9			0			0
		1208	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
284017 (284017L) Airframe	Left Wing Fuel Qty W4 Probe		HRS		6060.9			0			0
	10634T05Y00		AFL		4165			0			0
	1228		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284018 (284018R) Airframe	Right Wing Fuel Qty W5 Probe		HRS		6060.9			0			0
	10634T01Y00		AFL		4165			0			0
	1248		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284018 (284018L) Airframe	Left Wing Fuel Qty W5 Probe		HRS		6060.9			0			0
	10634T01Y00		AFL		4165			0			0
	1206		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284019 (284019R) Airframe	Right Wing Fuel Qty W6 Probe		HRS		6060.9			0			0
	10634T06Y00		AFL		4165			0			0
	1213		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284019 (284019L) Airframe	Left Wing Fuel Qty W6 Probe		HRS		6060.9			0			0
	10634T06Y00		AFL		4165			0			0
	1240		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
284196 Airframe	Fuel Quantity Signal Conditioner		HRS		6060.9			0			0
	10635B01Y01		AFL		4165			0			0
	02040895		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
28-42-00-7100 Airframe	Fuel Low Level Float Switch Operational Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
5-12-06											
29 - Hydraulic Power											
291001 Airframe	Hydraulic Reservoir		HRS		6060.9			0			0
	7470		AFL		4165			0			0
	390		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291002 (291002R) Airframe	Right Hydraulic Pump 24195-LAA	3806	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291002 (291002L) Airframe	Left Hydraulic Pump 24195-LAA	3811	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291005 (291005R) Airframe	Right Hydraulic Flow Switch 3520020100-4	5546	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291005 (291005L) Airframe	Left Hydraulic Flow Switch 3520020100-4	5388	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291008 Airframe	Speed Brake Thermal Relief Valve OAS5322-3-1700	1204	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291009 Airframe	Hyd Relief Valve 4614	2279A	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291010 Airframe	Hyd Press Switch 1106P59	4007	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291012 Airframe	Hyd Bypass Valve 61510-1	2022A	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
291013 (291013R) Airframe	Right Firewall Hyd Shutoff Valve		HRS		6060.9			0			0
	AV24B1325C5		AFL		4165			0			0
	U21709		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
291013 (291013L) Airframe	Left Firewall Hyd Shutoff Valve		HRS		6060.9			0			0
	AV24B1325C5		AFL		4165			0			0
	U21721		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
29-11-04-9600 Airframe	Hydraulic System Filters Discard		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
5-12-13											
30 - Ice and Rain Protection											
301001 (301001L) Airframe	Left Wing Anti-Ice Bleed AIR Under Temp SL013 Switch		HRS		6060.9			0			0
	1173T42-4		AFL		4165			0			0
	1893		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
301001 (301001R) Airframe	Right Wing Anti-Ice Bleed AIR Under Temp SR016 Switch		HRS		6060.9			0			0
	1173T42-4		AFL		4165			0			0
	1002		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
301002 Airframe	Isolation Valve		HRS		6060.9			0			0
	2602-36		AFL		4165			0			0
	0781		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
301008 (301008R) Airframe	Right Deice Tail Valve		HRS		6060.9			0			0
	3D2353-06		AFL		4165			0			0
	N19468		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
301008 (301008L) Airframe	Left Deice Tail Valve		HRS		3891.9			2169			0
	3D2353-06		AFL								0
	N064371		MOS		215.2			23 Nov 2006			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301020	Windshield Rain Removal MN001 Fan		HRS		6060.9			0			0
	011598-501	C02010010	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
30-11-00-7100	Bleed AIR Anti-Ice Systems Operational Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
			5-12-01								
301137	Right Wing Inlet Anti-Ice Pressure Reg Shutoff VE002		HRS		6060.9			0			0
	Valve		AFL		4165			0			0
	1962-00-7	1530	MOS		265.3			20 Sep 2002			
	(301137R)		MSC				O/C				
Airframe			[End Of Month Item]								
301137	Left Wing Inlet Anti-Ice Pressure Reg Shutoff VD001		HRS		6060.9			0			0
	Valve		AFL		4165			0			0
	1962-00-7	1477	MOS		265.3			20 Sep 2002			
	(301137L)		MSC				O/C				
Airframe			[End Of Month Item]								
30-12-00-7100	Horizontal Stabilizer Deice System Operational Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
			5-12-01								
301201	Right Tail Deice Pressure SV004 Switch		HRS		6060.9			0			0
	1106P55-1	2081	AFL		4165			0			0
	(301201R)		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
301201	Left Tail Deice Pressure SV005 Switch		HRS		3891.9			2169			0
	1106P55-1	3980	AFL								0
	(301201L)		MOS		215.2			23 Nov 2006			
	Airframe		MSC				O/C				
			[End Of Month Item]								
301202	Left Horiz Stab Deice Boot		HRS		5153.9			907			0
	29S4D5280-01	MYC63BO	AFL								0
	(301202L)		MOS		241			30 Sep 2004			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
301202 (301202R) Airframe	Right Horiz Stab Deice Boot P29S4D5280-02		HRS		2352.9			3708			0
	MAKG750		AFL								0
			MOS		183.5			15 Jul 2009			
			MSC				O/C				
			[End Of Month Item]								
302005 Engine	No. 1 Engine - Anti-Icing Valve 540-0406-6		HRS		975.6			5085.3			0
	5113		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
			[End Of Month Item]								
302005 Engine	No. 2 Engine - Anti-Icing Valve 540-0406-6		HRS		975.6			5085.3			0
	4677		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				O/C				
			[End Of Month Item]								
302101 (302101L) Airframe	Left Pressure Reg Valve 1946-00-19		HRS		1836.4			4224.5			0
	2796		AFL		1471			2694			0
			MOS		156.4			17 Oct 2011			
			MSC				O/C				
			[End Of Month Item]								
302101 (302101R) Airframe	Right Pressure Reg Valve 1946-00-19		HRS		1836.4			4224.5			0
	2380		AFL		1471			2694			0
			MOS		156.4			17 Oct 2011			
			MSC				O/C				
			[End Of Month Item]								
302104 (302104R) Airframe	Right Nacelle Inlet Switch 1173T0759		HRS		6060.9			0			0
	1701		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
302104 (302104L) Airframe	Left Nacelle Inlet Switch 1173T0759		HRS		6060.9			0			0
	1689		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
303001 (303001R) Airframe	Right Pitot Tube PH1100-1-VCW		HRS		864			5196.9			0
	AS11196986		AFL		791			3374			0
			MOS		47.4			19 Nov 2020			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
303001 (303001L) Airframe	Left Pitot Tube PH1100-1-VCW	B7168	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
303001 (303001S) Airframe	Standby Pitot Tube PH1100-1-RCDW	B7342	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
304100 (304100R) Airframe	Right Windshield Controller 856-1-1	0210206	HRS		3745.9			2315			0
			AFL								0
			MOS		212.6			12 Feb 2007			
			MSC				O/C				
			[End Of Month Item]								
304100 (304100L) Airframe	Left Windshield Controller 856-1-1	0210205	HRS		3745.9			2315			0
			AFL								0
			MOS		212.6			12 Feb 2007			
			MSC				O/C				
			[End Of Month Item]								
31 - Indicating/Recording Systems											
312001 (312001L) Airframe	Left Hand Digital Clock M877A5V	24385	HRS		916			5144.9			0
			AFL		632			3533			0
			MOS		50.9			01 Aug 2020			
			MSC				O/C				
			[End Of Month Item]								
312001 (312001R) Airframe	Right Hand Digital Clock M877A5V	13591	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
31-20-01-9600 Airframe	Digital Clock Aa Long Life Battery Discard		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
						[MOS: +1m/-1m]					
		5-12-01									
313003 (313003L) Airframe	Left Engine Accelerometer 6222SM15	18577	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
313003 (313003R) Airframe	Right Engine Accelerometer		HRS		6060.9			0			0
	6222SM15 18552		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
315001 Airframe	FDR Fail Annunciator		HRS		6060.9			0			0
	1304-1-11 0146177		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
315101 (315101R) Airframe	Right Warning Gen/Mixer Unit		HRS		6060.9			0			0
	1287-1-2 0219013		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
315101 (315101L) Airframe	Left Warning Gen/Mixer Unit		HRS		6060.9			0			0
	1287-1-2 0143228		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
316001 Airframe	Tilt Indicator		HRS		6060.9			0			0
	3001J72 22210		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
32 - Landing Gear											
32-00-00-2101 Airframe	Landing Gear Doors General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021 31 Oct 2025*	30 Nov 2025		
			[MOS: +1m/-1m]								
	5-12-06										
32-00-00-7100 Airframe	Landing Gear System General Visual Inspection, Operational Check and Functional Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021 31 Oct 2025*	30 Nov 2025		
			[MOS: +1m/-1m]								
	5-12-06										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-10-00-2200	Main Landing Gear Detailed Inspection		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
Airframe		[HRS: +25/-25]									
		5-12-08									
32-10-00-2201	Main Landing Gear Actuator ROD End Detailed Inspection (Airplanes Operating In Severe Corrosion Environments)		HRS		34			6026.9			0
			AFL		20		4145		0		
			MOS		.4	48	17 Oct 2024	31 Oct 2028			
Airframe		[End Of Month Item]									
32-10-00-9600	Main Landing Gear Oleo Breather Vent Discard		HRS		34			6026.9			0
			AFL		20		4145		0		
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
Airframe		[MOS: +1m/-1m]									
		5-12-01									
32-10-00-9601 (321003)	Left Main Landing Gear Trunnion Subassembly Discard 6641630-5 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165	6900	0	6900		0	
			MOS		265.3		20 Sep 2002				
Airframe		[End Of Month Item]									
32-10-00-9601 (321003)	Right Main Landing Gear Trunnion Subassembly Discard 6641630-6 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165	6900	0	6900		0	
			MOS		265.3		20 Sep 2002				
Airframe		[End Of Month Item]									
32-10-00-9602 (321004)	Left Main Landing GearTrailing Link Assembly Discard 6641648-15 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165	40300	0	40300		0	
			MOS		265.3		20 Sep 2002				
Airframe		[End Of Month Item]									
32-10-00-9602 (321004)	Right Main Landing GearTrailing Link Assembly Discard 6641648-14 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165	40300	0	40300		0	
			MOS		265.3		20 Sep 2002				
Airframe		[End Of Month Item]									
32-10-00-9603 (321011)	Left Main Landing Gear Trailing Link Spacer Discard 6641533-1 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165	33300	0	33300		0	
			MOS		265.3		20 Sep 2002				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-10-00-9603 (321011) Airframe	Right Main Landing Gear Trailing Link Spacer Discard		HRS		6060.9			0			0
	6641533-1	SN-UNKNOWN	AFL		4165		33300	0	33300		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
32-10-00-9604 (323010) Airframe	Right (Except Upper CAP) Main Landing Gear Oleo Assembly Discard		HRS		632			5428.9			0
	6641615-4	337	AFL	TSN:3537	628		38000	3537	38000		0
			MOS		35.4			19 Nov 2021			
			[End Of Month Item]								
32-10-00-9604 (323010) Airframe	Left (Except Upper CAP) Main Landing Gear Oleo Assembly Discard		HRS		6060.9			0			0
	6641615-4	SN-UNKNOWN	AFL		4165		38000	0	38000		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
32-10-00-9604.1 (323011) Airframe	Right Upper CAP Main Landing Gear Oleo Assembly Discard		HRS		6060.9			0			0
	6641616-3	SN-UNKNOWN	AFL		4165		4600	0	4600		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
32-10-00-9604.1 (323011) Airframe	Left Upper CAP Main Landing Gear Oleo Assembly Discard		HRS		6060.9			0			0
	6641616-3	SN-UNKNOWN	AFL		4165		4600	0	4600		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
32-10-00-9605 (323001) Airframe	Right Main Landing Gear Actuator Assembly Discard		HRS		1255.6			4805.3			0
	9912537-6	2076	AFL		903		70200	3262	73462		0
			MOS		74.5			14 Aug 2018			
			[End Of Month Item]								
32-10-00-9605 (323001) Airframe	Left Main Landing Gear Actuator Assembly Discard		HRS		6060.9			0			0
	1550000-3	537	AFL		4165		70200	0	70200		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-20-00-2200	Nose Landing Gear Detailed Inspection		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
5-12-08											
32-20-00-9600	Nose Landing Gear Assembly Discard		HRS		6060.9			0			0
	6642614-1	68	AFL		4165		33300	0	33300		0
	(322001)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
32-20-00-9601	Nose Landing Gear Actuator Discard		HRS		6060.9			0			0
	1549300-5	0276	AFL		4165		33300	0	33300		0
	(323003)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
322002	Nose Gear Shimmy Damper		HRS		857.6			5203.3			0
	5543001-12	1217-12X	AFL								0
			MOS		47.2			25 Nov 2020			
	Airframe		MSC				O/C				
[End Of Month Item]											
322007	Nose Gear Trunnion		HRS		6060.9			0			0
	6642611-9	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
323004	Nose Uplock Actuator		HRS		6060.9			0			0
	5527504-3	2490	AFL		4165			0			0
	(323004N)		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
323004	Left Uplock Actuator		HRS		6060.9			0			0
	5527504-3	2492	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
323004	Right Uplock Actuator		HRS		6060.9			0			0
	5527504-3	2489	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
323005	Pressure Emer Gear Gauge		HRS		6060.9			0			0
	19940929-1	010214	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
323007	Landing Gear Control (VY047) Valve		HRS		6060.9			0			0
	71839-1	0385	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
323008	Dump Valve		HRS		6060.9			0			0
	OAS5319-1	1142	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
323009	Landing Gear Control		HRS		6060.9			0			0
	049801-001	0238	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
32-30-09-7800	Emergency Gear Extension/Brake Pneumatic Storage		HRS								0
	Bottle(Hydrostatic Test) Restoration		AFL								0
	40005347-3	2371	MOS		12.4	-6	36	19 Oct 2023	31 Oct 2026*		
	(B320900)		[End Of Month Item]								
Airframe											
32-30-09-9600	Emergency Gear Extension / Brake Pneumatic Storage		HRS		216.6			5844.3			0
	Bottle Assembly Discard		AFL		140			4025			0
	40005347-3	2371	MOS		11.8		288	05 Nov 2023	31 Mar 2044		
	(323006)		[End Of Month Item]								
Airframe											
32-40-00-2200	Left Landing Gear Brakes Detailed Inspection, Main		HRS		2185.9			3875			0
	Landing Gear Axle General Visual Inspection, and		AFL								0
	Functional (Wear Pin) Check		MOS		178.7			08 Dec 2009			
	3-1571-6	0980	MSC				WHL/C				
(A324004)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-40-00-2200	Right Landing Gear Brakes Detailed Inspection, Main Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check 3-1571-6										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324001 (324001R) Airframe	Right Main Wheel Assembly 3-1571-6		HRS		160.5			5900.4			0
			AFL		106			4059			0
			MOS		8			29 Feb 2024			
			MSC				O/C				
			[End Of Month Item]								
324002 Airframe	Nose Wheel Assembly 3-1418 - 9914069-2		HRS		94.6			5966.3			0
			AFL		58			4107			0
			MOS		5.2			24 May 2024			
			MSC				O/C				
			[End Of Month Item]								
324003 Airframe	Left Main Brake Assembly 9912487-7		HRS		35			6025.9			0
			AFL		20			4145			0
			MOS		1.5			13 Sep 2024			
			MSC				O/C				
			[End Of Month Item]								
324004 Airframe	Right Main Brake Assembly 9912487-7		HRS		35			6025.9			0
			AFL		20			4145			0
			MOS		1.5			13 Sep 2024			
			MSC				O/C				
			[End Of Month Item]								
324005 (324005L) Airframe	Left Main Tire M13702		HRS		160.5			5900.4			0
			AFL		106			4059			0
			MOS		8			29 Feb 2024			
			MSC				O/C				
			[End Of Month Item]								
324005 (324005R) Airframe	Right Main Tire M13702		HRS		160.5			5900.4			0
			AFL		106			4059			0
			MOS		8			29 Feb 2024			
			MSC				O/C				
			[End Of Month Item]								
324006 Airframe	Nose Tire 031-613-8		HRS		94.6			5966.3			0
			AFL		58			4107			0
			MOS		5.2			24 May 2024			
			MSC				O/C				
			[End Of Month Item]								
324009 Airframe	Power Brake Valve 32-077-1		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324010 (324010L) Airframe	Left Extend/Retract Valve		HRS		6060.9			0			0
	98120	2187	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
324010 (324010N) Airframe	Nose Extend/Retract Valve		HRS		6060.9			0			0
	98120	2259	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
324010 (324010R) Airframe	Right Extend/Retract Valve		HRS		6060.9			0			0
	98120	2182	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
324011 (324011R) Airframe	Right (Pilot Side) Master Brake Cylinder		HRS		6060.9			0			0
	98281-3	735	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
324011 (324011L) Airframe	Left (Pilot Side) Master Brake Cylinder		HRS		4281.9			1779			0
	98281-3	0417	AFL		3069			1096			0
			MOS		222.2			24 Apr 2006			
			MSC				O/C				
[End Of Month Item]											
324012 (324012L) Airframe	Left (Copilot Side) Master Brake Cylinder		HRS		4775.9			1285			0
	98281-4	0887	AFL		3415			750			0
			MOS		232.7			08 Jun 2005			
			MSC				O/C				
[End Of Month Item]											
324012 (324012R) Airframe	Right (Copilot Side) Master Brake Cylinder		HRS		6060.9			0			0
	98281-4	755	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
324014 Airframe	Emergency AIR Brake Control Valve		HRS		6060.9			0			0
	65830-4	0665	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324015 (324015L) Airframe	Left Brake Shuttle Valve 211-114		HRS		6060.9			0			0
		SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324015 (324015R) Airframe	Right Brake Shuttle Valve 211-114		HRS		6060.9			0			0
		SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324019 Airframe	Brake Press Pump Assembly 640931		HRS		5275.9			785			0
		6105	AFL								0
			MOS		243.1			27 Jul 2004			
			MSC				O/C				
	[End Of Month Item]										
324020 Airframe	Antiskid Control (UY009) Valve 39-837		HRS		6060.9			0			0
		481	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324022 Airframe	Antiskid Digital Control 42-985-2		HRS		6060.9			0			0
		394	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324023 Airframe	Power Brake Accumulator 57C57652		HRS		6060.9			0			0
		1700	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324024 (324024R) Airframe	Right Wheel Transducer 40-955		HRS		6060.9			0			0
		SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
324024 (324024L) Airframe	Left Wheel Transducer 40-955		HRS		6060.9			0			0
		SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
324025	Pressure (SN011) Switch		HRS		6060.9			0			0
	GPP1250-52	215453	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
324026	Power Pack Motor		HRS		6060.9			0			0
	MP50B1	2286	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
324027	Antiskid Fault Display		HRS		6060.9			0			0
	42-92750	1106A	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
32-41-00-2101	Optional Nose Wheel Spin Up General Inspection		HRS								0
	3-1418 - 9914069-2	7404	AFL								0
			DATE								
	Airframe		MSC				WHL/C				
32-41-00-2200	Left Main Landing Gear Wheel and Tire Detailed		HRS		160.5			5900.4			0
	Inspection		AFL		106			4059			0
	3-1571-6	0980	MOS		8		24	29 Feb 2024	28 Feb 2026		
	Airframe		MSC				WHL/C				
			[End Of Month Item]								
32-41-00-2200	Right Main Landing Gear Wheel and Tire Detailed		HRS		160.5			5900.4			0
	Inspection		AFL		106			4059			0
	3-1571-6	0969	MOS		8		24	29 Feb 2024	28 Feb 2026		
	Airframe		MSC				WHL/C				
			[End Of Month Item]								
32-41-00-2800	Nose Landing Gear Wheel (Eddy Current) Special		HRS								0
	Detailed Inspection		AFL								0
	3-1418 - 9914069-2	7404	DATE								
	(A324006)		MSC				A/R				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-41-00-2801	Left Main Landing Gear Wheel (Eddy Current) Special		HRS		160.5			5900.4			0
	Detailed Inspection		AFL		106			4059			0
	3-1571-6	0980	MOS		8			29 Feb 2024			
	(A324006)		MSC				A/R				
Airframe	[End Of Month Item]										
32-41-00-2801	Right Main Landing Gear Wheel (Eddy Current) Special		HRS		160.5			5900.4			0
	Detailed Inspection		AFL		106			4059			0
	3-1571-6	0969	MOS		8			29 Feb 2024			
	(A324006)		MSC				A/R				
Airframe	[End Of Month Item]										
32-41-00-7200	Optional Nose Wheel Spin Up Functional Check		HRS								0
	3-1418 - 9914069-2	7404	AFL								0
			MOS								
	Airframe		MSC				WHL/C				
324101	Parking Brake Valve		HRS		1587.1			4473.8			0
	95905	1041A	AFL		1250			2915			0
			MOS		129.4			17 Jan 2014			
	Airframe		MSC				O/C				
	[End Of Month Item]										
324153	Press Antiskid Brk Switch		HRS		1279.6			4781.3			0
	GPP1250-73	1337942R	AFL		920			3245			0
			MOS		75.4			19 Jul 2018			
	Airframe		MSC				O/C				
	[End Of Month Item]										
324200	Antiskid Pressure Gauge		HRS		5544.9			516			0
	19940929-1	013666	AFL								0
			MOS		249.5			14 Jan 2004			
	Airframe		MSC				O/C				
	[End Of Month Item]										
324206	Antiskid Hyd Relief Valve		HRS		6060.9			0			0
	1785-2	417	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
	[End Of Month Item]										
32-50-00-2200	Steering System Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe	[MOS: +1m/-1m]									
	5-12-06										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
32-50-00-7200	Steering Cable System Functional Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								
326005 (326005R)	Right Main Gear Up & Locked (S3) Switch		HRS		6060.9			0			0
	65-430087	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
326005 (326005L)	Left Main Gear Up & Locked (S3) Switch		HRS		6060.9			0			0
	65-430087	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
326005	Nose Gear Up & Locked (SN001) Switch		HRS		6060.9			0			0
	65-430087	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
33 - Lights											
331001 (331001C)	Center 5 Vdc UN004 Dimmer Power Supply		HRS		6060.9			0			0
	273-1	0215138	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
331001 (331001L)	Left 5 Vdc UN002 Dimmer Power Supply		HRS		6060.9			0			0
	273-1	0233045	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
331001 (331001R)	Right 5 Vdc UN006 Dimmer Power Supply		HRS		6060.9			0			0
	273-1	0215145	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
331011	EI Panel Inverter		HRS		6060.9			0			0
	EM2044-1	3767A	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332001 (332001D) Airframe	Left No. 4 Light Power Supply AL750PS	17415	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001P) Airframe	Right No. 7 Light Power Supply AL750PS	16683	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001S) Airframe	Right No. 10 Light Power Supply AL750PS	17241	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001K) Airframe	Right No. 2 Light Power Supply AL750PS	16695	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001Q) Airframe	Right No. 8 Light Power Supply AL750PS	16688	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001M) Airframe	Right No. 4 Light Power Supply AL750PS	16691	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001F) Airframe	Left No. 6 Light Power Supply AL750PS	17416	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001I) Airframe	Left No. 9 Light Power Supply AL750PS	17417	HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332001 (332001H) Airframe	Left No. 8 Light Power Supply AL750PS		17427	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001L) Airframe	Right No. 3 Light Power Supply AL750PS		22120	HRS	5598.9			462		0	
				AFL						0	
				MOS	250.8			05 Dec 2003			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001J) Airframe	Right No. 1 Light Power Supply AL750PS		16693	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001E) Airframe	Left No. 5 Light Power Supply AL750PS		17428	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001C) Airframe	Left No. 3 Light Power Supply AL750PS		17425	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001B) Airframe	Left No. 2 Light Power Supply AL750PS		17409	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001R) Airframe	Right No. 9 Light Power Supply AL750PS		16692	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
332001 (332001G) Airframe	Left No. 7 Light Power Supply AL750PS		17426	HRS	6060.9			0		0	
				AFL	4165			0		0	
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
332001 (332001A) Airframe	Left No. 1 Light Power Supply AL750PS		HRS		6060.9			0		0	
		17421	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001O) Airframe	Right No. 6 Light Power Supply AL750PS		HRS		6060.9			0		0	
		16689	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332001 (332001N) Airframe	Right No. 5 Light Power Supply AL750PS		HRS		6060.9			0		0	
		16694	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
332002 Airframe	Glareshield Inverter 6900173		HRS		6060.9			0		0	
		3464	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
33-40-00-7200 Airframe	Tail Light Navigation Assembly (Nav-Led 72 Segment) Functional Check		HRS		34			6026.9		0	
			AFL		20			4145		0	
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
		5-12-03									
334001 Airframe	Pulse Lite Control 2400-25-4-4C2		HRS		6060.9			0		0	
		KA00547	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
334002 Airframe	Empennage Light Assy 01-0790044-37		HRS		6060.9			0		0	
		SN-UNKNOWN	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
334006 (334006L) Airframe	Left Strobe Power Supply 01-0790101-05		HRS		6060.9			0		0	
		00591	AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
334006 (334006R) Airframe	Right Strobe Power Supply		HRS		6060.9			0			0
	01-0790101-05		AFL		4165			0			0
	00698		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
33-50-00-7100 Airframe	Emergency Lighting System Operational Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
5-12-03											
33-50-00-7200 Airframe	Emergency Lighting Battery Pack(S) (Capacity Check)		HRS		34			6026.9			0
	Functional Check		AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
5-12-01											
33-50-00-9600 Airframe	Forward Emergency Lighting Battery Pack Restoration		HRS		34			6026.9			0
	9913-1		AFL		20			4145			0
	1354		MOS		.4		48	17 Oct 2024	17 Oct 2028	17 Nov 2028	
			[MOS: +1m/-1m]								
33-50-00-9600 Airframe	Aft Emergency Lighting Battery Pack Restoration		HRS		422.6			5638.3			0
	9913-1		AFL		280			3885			0
	265		MOS		22.7	-46	48	07 Dec 2022	22 Oct 2026*	22 Nov 2026	
			[MOS: +1m/-1m]								
335001 (335001L) Airframe	Forward Emergency Lighting UC019 Battery Pack		HRS		34			6026.9			0
	9913-1		AFL		20			4145			0
	1354		MOS		.4			17 Oct 2024			
			MSC				O/C				
			[End Of Month Item]								
335001 (335001R) Airframe	Aft Emergency Lighting UC020 Battery Pack		HRS		1239.2			4821.7			0
	9913-1		AFL		889			3276			0
	265		MOS		72.3			22 Oct 2018			
			MSC				O/C				
			[End Of Month Item]								
34 - Navigation											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341009	Safe Flight AOA UF004 Sensor		HRS		6060.9			0			0
	C-12717-1		AFL		4165			0			0
	866		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341010	Safe Flight AOA EI001 Indicator		HRS		6060.9			0			0
	C12705-1		AFL		4165			0			0
	6914		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341011	Safe Flight AOA UC009 Computer		HRS		6060.9			0			0
	C13006-2		AFL		4165			0			0
	699		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341014	Safe Flight AOA FI003 Indexer		HRS		6060.9			0			0
	C12763-1		AFL		4165			0			0
	590		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341016	Secondary Adu		HRS		1880.5			4180.4			0
	27101-01-01		AFL		1506			2659			0
	M011553		MOS		160.1			27 Jun 2011			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341017	Meggitt Secondary Flight (EI016) Display		HRS		422.6			5638.3			0
	38102-00-01		AFL		280			3885			0
	M011396		MOS		22.7			07 Dec 2022			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341101	Differential Pressure Switch		HRS		3097.9			2963			0
	D45C-24		AFL								0
	1009		MOS		199.9			02 Mar 2008			
	Airframe		MSC				O/C				
			[End Of Month Item]								
341107 (341107R)	No. 2 (Copilot) AIR Data Computer		HRS		5447.9			613			0
	7014700-914		AFL								0
	02056265		MOS		247.2			25 Mar 2004			
	Airframe		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
341107 (341107L) Airframe	No. 1 (Pilot) AIR Data Computer 7014700-914 02056263		HRS		5447.9			613			0
			AFL								0
			MOS		247.2			25 Mar 2004			
			MSC				O/C				
	[End Of Month Item]										
342001 Airframe	Standby Magnetic Compass C660501-0301 SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
342023 Airframe	Radar Controller 7008471-407 02026573		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
342050 (342050R) Airframe	Right Flux Detector 2594484 01104903		HRS		2000.7			4060.2			0
			AFL		1616			2549			0
			MOS		168.6			11 Oct 2010			
			MSC				O/C				
	[End Of Month Item]										
342050 (342050L) Airframe	Left Flux Detector 2594484 83061249		HRS		983.8			5077.1			0
			AFL		692			3473			0
			MOS		59.7			09 Nov 2019			
			MSC				O/C				
	[End Of Month Item]										
342053 Airframe	Aeronetics HSI-15 Standby Horizontal Situation Indicator 520-3151-003 21146		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
342064 Airframe	No. 1 Standby Battery Pack 501-1228-04 11217		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				
	[End Of Month Item]										
342065 Airframe	No. 2 Standby Battery Pack 501-1228-04 1368		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				O/C				
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342069	Honeywell Primus 1000 EFIS MC800 Multifunction Display Controller		HRS		164.2			5896.7			0
			AFL		108			4057			0
	7007062-941	05043116	MOS		8.3			20 Feb 2024			
			MSC				O/C				
Airframe	[End Of Month Item]										
342072	Meggitt Static Converter 501-1318-01		HRS		6060.9			0			0
		5154	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
342082 (342082L)	Left Litef Lcr-93 Ahrs Tray 140691		HRS		6060.9			0			0
		1928	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
342082 (342082R)	Right Litef Lcr-93 Ahrs Tray 140691		HRS		6060.9			0			0
		1929	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
342083 (342083L)	Left Ahrs Computer 145130-6000		HRS		968.3			5092.6			0
		1093	AFL		672			3493			0
			MOS		55.6			12 Mar 2020			
			MSC				O/C				
Airframe	[End Of Month Item]										
342083 (342083R)	Right Ahrs Computer 142185-3100		HRS		767.8			5293.1			0
		1255	AFL		517			3648			0
			MOS		42.1			26 Apr 2021			
			MSC				O/C				
Airframe	[End Of Month Item]										
342104 (342104L)	Left Msu Calibration Prom Unit 124282		HRS		6060.9			0			0
		3161	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
342104 (342104R)	Right Msu Calibration Prom Unit 124282		HRS		6060.9			0			0
		3153	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342500	Honeywell Primus 1000 EFIS RI553 Remote Instrument Controller		HRS		6060.9			0			0
			AFL		4165			0			0
	7016954-907	02051516	MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342502	Honeywell Primus 1000 EFIS BL871 Bezel Controller		HRS		2185.9			3875			0
	7014332-841 02086330		AFL								0
			MOS		178.7			08 Dec 2009			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342503 (342503R)	Copilot Flt Display Controller		HRS		6060.9			0			0
	7014331-931 02054619		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342503 (342503L)	Pilot Honeywell Primus 1000 EFIS BL870 Bezel Controller		HRS		6060.9			0			0
	7014331-931 02054618		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342504 (342504L)	Pilot Honeywell Primus 1000 EFIS DC550 Display Controller		HRS		1706.1			4354.8			0
	7016986-747 04125731		AFL		1370			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342504 (342504R)	Copilot Honeywell Primus 1000 EFIS DC550 Display Controller		HRS		6060.9			0			0
	7016986-747 02054482		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Airframe		[End Of Month Item]								
342505 (342505L)	No.1 Honeywell Primus 1000 EFIS IC600/IC615 Integrated Avionics Computer		HRS		857.6			5203.3			0
	7017000-82360 02055519		AFL								0
			MOS		47.2			24 Nov 2020			
			MSC				O/C				
	Airframe		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342505 (342505R) Airframe	No.2 Honeywell Primus 1000 EFIS IC600/IC615		HRS		3566.9			2494			0
	Integrated Avionics Computer		AFL								0
	7017000-83360	02055519	MOS		208.4			19 Jun 2007			
			MSC				O/C				
				[End Of Month Item]							
342506 Airframe	Honeywell Primus 1000 EFIS MS560 MODE Selector Unit		HRS		267.7			5793.2			0
	7018341-803	05072697	AFL		179			3986			0
			MOS		14.7			09 Aug 2023			
			MSC				O/C				
				[End Of Month Item]							
342509 (342509L) Airframe	Pilot Honeywell Primus 1000 EFIS DU870 Multifunction		HRS		6060.9			0			0
	Display Unit		AFL		4165			0			0
	7014300-901	0205B449	MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
342509 (342509R) Airframe	Copilot Honeywell Primus 1000 EFIS DU870 Multifunction		HRS		6060.9			0			0
	Display Unit		AFL		4165			0			0
	7014300-901	0208B836	MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
342510 Airframe	Center Electronic Display Unit		HRS		6060.9			0			0
	7014300-901	0209B910	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
343001 Airframe	Glideslope Antenna Coupler		HRS		6060.9			0			0
	CI503	2040339	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
343001 (343001A) Airframe	Navigation Antenna Coupler		HRS		4636.9			1424			0
	CI-120-5	5030254	AFL								0
			MOS		229.5			16 Sep 2005			
			MSC				O/C				
				[End Of Month Item]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
343002	Marker Beacon Antenna Coupler CI509	2013418	HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
344005	Radar Transceiver 7021450-801	02043207	HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										
344022	Radio Altimeter Alt-55B Transceiver 622-2855-011	5639	HRS		2106.9			3954			0
			AFL							0	
			MOS		176.8			05 Feb 2010			
			MSC				O/C				
Airframe	[End Of Month Item]										
344023 (344023F)	Forward Radio Alt Transmitter Antenna S67-2002	543-49542	HRS		2158.9			3902			0
			AFL							0	
			MOS		178.4			19 Dec 2009			
			MSC				O/C				
Airframe	[End Of Month Item]										
344023 (344023A)	Aft Radio Alt Receiver Antenna S67-2002	543-46564	HRS		2158.9			3902			0
			AFL							0	
			MOS		178.4			19 Dec 2009			
			MSC				O/C				
Airframe	[End Of Month Item]										
344024	Egpws Computer 965-1206-004	1015	HRS		5772.9			288			0
			AFL							0	
			MOS		255			29 Jul 2003			
			MSC				O/C				
Airframe	[End Of Month Item]										
344032	Wsi Converter 933612-02	703	HRS		4027.9			2033			0
			AFL							0	
			MOS		217.7			08 Sep 2006			
			MSC				O/C				
Airframe	[End Of Month Item]										
344042	Stormscope Antenna 805-10930-001	81395	HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
344043	Stormscope Processor		HRS		6060.9			0			0
	830-10950-002		AFL		4165			0			0
	JPC03100257		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345004	Right No. 2 Xpndr Bottom Antenna		HRS		6060.9			0			0
	DMNI50-2-2		AFL		4165			0			0
	83226		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345004	Left No. 1 Xpndr Bottom Antenna		HRS		6060.9			0			0
	DMNI50-2-2		AFL		4165			0			0
	83943		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345005	Right No. 2 Top Transponder Diversity Antenna		HRS		6060.9			0			0
	DMNI50-2-2		AFL		4165			0			0
	83936		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345005	Left No. 1 Top Transponder Diversity Antenna		HRS		6060.9			0			0
	DMNI50-2-2		AFL		4165			0			0
	83387		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345007	No.1 Distance Measuring Equipment (DME) Antenna		HRS		632			5428.9			0
	DMNI50-2-2		AFL		628			3537			0
	147134		MOS		35.4			19 Nov 2021			
	Airframe		MSC				O/C				
[End Of Month Item]											
345007	No.2 Distance Measuring Equipment (DME) Antenna		HRS		6060.9			0			0
	DMNI50-2-2		AFL		4165			0			0
	83911		MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
345011	No. 1 ADF Receiver Module		HRS		5262.9			798			0
	7510114-901		AFL								0
	01054535		MOS		242.8			04 Aug 2004			
	Airframe		MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345011 (345011B) Airframe	No. 2 ADF Receiver Module		HRS		6060.9			0			0
	7510112-901		AFL		4165			0			0
	02050630		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345014 (345014A) Airframe	No. 1 ADF Antenna		HRS		6060.9			0			0
	7510300-901		AFL		4165			0			0
	02046396		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345017 Airframe	Marker Beacon Antenna		HRS		6060.9			0			0
	31-10-01		AFL		4165			0			0
	4329		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345018 Airframe	Glideslope Antenna		HRS		6060.9			0			0
	RGS10-48		AFL		4165			0			0
	A8508		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345029 (345029B) Airframe	No. 2 Nav Cluster Module		HRS		6060.9			0			0
	7510164-921		AFL		4165			0			0
	02046704		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345029 (345029A) Airframe	No. 1 Nav Cluster Module		HRS		5262.9			798			0
	7510164-921		AFL								0
	01045592		MOS		242.8			04 Aug 2004			
			MSC				O/C				
			[End Of Month Item]								
345032 (345032A) Airframe	No. 1 VHF Nav Receiver		HRS		5262.9			798			0
	7510134-731		AFL								0
	01055710		MOS		242.8			04 Aug 2004			
			MSC				O/C				
			[End Of Month Item]								
345032 (345032B) Airframe	No. 2 VHF Nav Receiver		HRS		5447.9			613			0
	7510134-731		AFL								0
	02056861		MOS		247.2			25 Mar 2004			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345034 (345034B) Airframe	No. 2 ATC Transponder 7517400-902		HRS		4281.9			1779			0
	02056462		AFL								0
			MOS		222.2			24 Apr 2006			
			MSC				O/C				
			[End Of Month Item]								
345034 (345034A) Airframe	No. 1 ATC Transponder 7517400-902		HRS		4281.9			1779			0
	02056425		AFL								0
			MOS		222.2			24 Apr 2006			
			MSC				O/C				
			[End Of Month Item]								
345036 (345036B) Airframe	No. 2 DME Interrogator 7510184-902		HRS		6060.9			0			0
	02056465		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
345036 (345036A) Airframe	No. 1 DME Interrogator 7510184-902		HRS		5262.9			798			0
	01055299		AFL								0
			MOS		242.8			04 Aug 2004			
			MSC				O/C				
			[End Of Month Item]								
345038 (345038A) Airframe	No. 1 Integrated Nav Unit 7510100-731		HRS		5262.9			798			0
	01055436		AFL								0
			MOS		242.8			04 Aug 2004			
			MSC				O/C				
			[End Of Month Item]								
345038 (345038B) Airframe	No. 2 Integrated Nav Unit 7510100-733		HRS		1896.4			4164.5			0
	02056538		AFL		1519			2646			0
			MOS		160.7			07 Jun 2011			
			MSC				O/C				
			[End Of Month Item]								
345077 Airframe	Data Transfer Unit 1408-00-1		HRS		1300			4760.9			0
	3921		AFL		947			3218			0
			MOS		82.9			03 Dec 2017			
			MSC				O/C				
			[End Of Month Item]								
345079 (345079B) Airframe	No. 2 GPS Flt Mgmt Computer 3019-41-201		HRS		1300			4760.9			0
	1008		AFL		947			3218			0
			MOS		82.9			03 Dec 2017			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
345079 (345079A) Airframe	No. 1 GPS Flt Mgmt Computer 3019-41-201		1005	HRS	1300			4760.9			0
				AFL	947			3218			0
				MOS	82.9			03 Dec 2017			
				MSC			O/C				
[End Of Month Item]											
345088 (345088B) Airframe	No. 2 Radio Management Unit 7013270-983		17099706	HRS	1300			4760.9			0
				AFL	947			3218			0
				MOS	82.9			03 Dec 2017			
				MSC			O/C				
[End Of Month Item]											
345088 (345088A) Airframe	No. 1 Radio Management Unit 7013270-983		17099707	HRS	1300			4760.9			0
				AFL	947			3218			0
				MOS	82.9			03 Dec 2017			
				MSC			O/C				
[End Of Month Item]											
345093 (345093B) Airframe	No.2 GPS Antenna 10708		9860	HRS	1300			4760.9			0
				AFL	947			3218			0
				MOS	82.9			03 Dec 2017			
				MSC			O/C				
[End Of Month Item]											
345093 (345093A) Airframe	No.1 GPS Antenna 10708		9861	HRS	1300			4760.9			0
				AFL	947			3218			0
				MOS	82.9			03 Dec 2017			
				MSC			O/C				
[End Of Month Item]											
345201 (345201R) Airframe	Right Nav Antenna CI120-1-L		5045734	HRS	4636.9			1424			0
				AFL							0
				MOS	229.5			16 Sep 2005			
				MSC			O/C				
[End Of Month Item]											
345201 (345201L) Airframe	Left Nav Antenna CI120-1-L		5045735	HRS	4636.9			1424			0
				AFL							0
				MOS	229.5			16 Sep 2005			
				MSC			O/C				
[End Of Month Item]											
345301 (345301R) Airframe	Right DME Indicator 7513006-911		02052465	HRS	6060.9			0			0
				AFL	4165			0			0
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
345301 (345301L) Airframe	Left DME Indicator		HRS		2328.9			3732			0	
	7513006-911	01102339	AFL								0	
			MOS		183.3			21 Jul 2009				
			MSC				O/C					
				[End Of Month Item]								
346001 (346001A) Airframe	TCAS Processor		HRS		411.8			5649.1			0	
	066-01146-0101	40125	AFL		273			3892			0	
			MOS		20.7			07 Feb 2023				
			MSC				O/C					
				[End Of Month Item]								
346002 (346002B) Airframe	Bottom TCAS Antenna		HRS		1451.7			4609.2			0	
	071-01548-0100	583-15736	AFL		1130			3035			0	
			MOS		111.3			21 Jul 2015				
			MSC				O/C					
				[End Of Month Item]								
346002 (346002T) Airframe	Top TCAS Antenna		HRS		6060.9			0			0	
	071-01548-0200	9084	AFL		4165			0			0	
			MOS		265.3			20 Sep 2002				
			MSC				O/C					
				[End Of Month Item]								
346012 (346006) Airframe	TCAS li Module		HRS		6060.9			0			0	
	071-00097-1000	3442	AFL		4165			0			0	
			MOS		265.3			20 Sep 2002				
			MSC				O/C					
				[End Of Month Item]								
34-90-10-7200 (B341100) Airframe	No.1 (Pilot) Pitot-Static System Functional Check (Airplanes -5001 Thru -6000)		HRS		34			6026.9			0	
	7014700-914	02056263	AFL		20			4145			0	
			MOS		.4		24	17 Oct 2024	31 Oct 2026			
				[End Of Month Item]								
				CALIBRATION								
34-90-10-7200 (B341100) Airframe	No. 2 (CO-Pilot) Pitot-Static System Functional Check (Airplanes -5001 Thru -6000)		HRS		34			6026.9			0	
	7014700-914	02056265	AFL		20			4145			0	
			MOS		.4		24	17 Oct 2024	31 Oct 2026			
				[End Of Month Item]								
				CALIBRATION								
34FO-33XL Airframe	Gmx 200		HRS		224.1			5836.8			0	
	011-01271-10	38350319	AFL		146			4019			0	
			MOS		12.6			11 Oct 2023				
			MSC				-					
				[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
35 - Oxygen											
35-10-00-2200	Crew Masks and Stowage Boxes Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								
35-10-00-9600	MC10-16-150, MC10-16-100, or MLD20-505 Copilot Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration		HRS		980			5080.9			0
			AFL		689			3476			0
			MOS		56.1	-132	72	26 Feb 2020	31 Oct 2025*		
(351004)	MC10-16-100	74874	[End Of Month Item]								
Airframe											
35-10-00-9600	MC10-16-150, MC10-16-100, or MLD20-505 Pilot Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration		HRS		980			5080.9			0
			AFL		689			3476			0
			MOS		56.1	-132	72	26 Feb 2020	31 Oct 2025*		
(351004)	MC10-16-100	89073	[End Of Month Item]								
Airframe											
351001	Oxygen Pressure (EI002) Gage		HRS		6060.9			0			0
	C668512-0101	D22684	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
351007	Oxygen Regulator		HRS		5912.9			148			0
	804881-01	955	AFL								0
			MOS		259.1			27 Mar 2003			
Airframe			MSC				O/C				
			[End Of Month Item]								
351008	Passenger Oxygen Control Valve		HRS		6060.9			0			0
	P21006	1671	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
			[End Of Month Item]								
35-20-00-2200	Passenger Drop Boxes and Mask Assembly Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
35-20-00-7100	Passenger Oxygen System Operational Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
	Airframe		[MOS: +1m/-1m]								
		5-12-03									
35-20-00-7200	Passenger Oxygen System Functional Check		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
		5-12-06									
352001	Passenger Oxygen Altitude Pressure Switch		HRS		6060.9			0			0
	P24032	0553	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
		[End Of Month Item]									
35-30-00-2200	Optional Protective Breathing Equipment Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
		5-12-01									
35-90-00-7800	Oxygen Bottle Assembly (Hydrostatic Test) Restoration (DOT-SP 8162)		HRS		34			6026.9			0
			AFL		20			4145			0
	804882-14	C14120302	MOS		.4		60	17 Oct 2024	31 Oct 2029		
	(350000)	[End Of Month Item]									
Airframe		HYDRO CHECK									
35-90-00-9600	Oxygen Bottle Assembly (Discard)		HRS		34			6026.9			0
	804882-14	C14120302	AFL		20			4145			0
	(351006)		MOS	TSN:119	.4		180	17 Oct 2024	30 Nov 2029		
	Airframe		[End Of Month Item]								
		MANUFACTURE									
36 - Pneumatic											
361010	Door Solenoid Valve		HRS		6060.9			0			0
	5035-00-1	0552	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361011 (361011L) Airframe	Left Heat Exchanger Actuator 1E50-2										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
361103 (361103R) Airframe	Right Heat B/A Exchanger 8230-2		HRS		1836.4			4224.5			0
	S4883T2147		AFL		1471			2694			0
			MOS		156.4			17 Oct 2011			
			MSC				O/C				
			[End Of Month Item]								
361103 (361103L) Airframe	Left Heat B/A Exchanger 8230-2		HRS		1301.3			4759.6			0
	S4883T3271		AFL		948			3217			0
			MOS		83.6			10 Nov 2017			
			MSC				O/C				
			[End Of Month Item]								
36-11-03-2100 Airframe	Precooler Heat Exchanger General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024 31 Oct 2025* 30 Nov 2025			
	5-12-01		[MOS: +1m/-1m]								
361104 (361104L) Airframe	Left Precooler VD003 Valve 1407-10		HRS		6060.9			0			0
	0573A		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
361104 (361104R) Airframe	Right Precooler VD003 Valve 1407-10		HRS		6060.9			0			0
	0571A		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
36-12-00-2200 Airframe	Auxiliary Power Unit Bleed AIR Check Valve Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021 31 Oct 2025* 30 Nov 2025			
	5-12-06		[MOS: +1m/-1m]								
361208 Airframe	APU-Check Valve 8C210		HRS		6060.9			0			0
	3358		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
361208 (361205B) Airframe	Rudder Bias Check Valve 8C210		HRS		6060.9			0			0
	3361		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom		Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
		Part Number	Serial Number									Approx Price
Logbook Position	HW		SW									Manufacturer
	MM Ref											Date Type
	Ops Number(s)											
361500 (361500B) Airframe	No. 2 B/A Check Valve 8C210		3349	HRS		6060.9			0			0
				AFL		4165			0			0
				MOS		265.3			20 Sep 2002			
				MSC				O/C				
				[End Of Month Item]								
361500 (361500A) Airframe	No. 1 B/A Check Valve 8C210		3363	HRS		6060.9			0			0
				AFL		4165			0			0
				MOS		265.3			20 Sep 2002			
				MSC				O/C				
				[End Of Month Item]								
36-15-00-1700 Airframe	Particulate Trap (Cleaning) Restoration			HRS		632			5428.9			0
				AFL		628			3537			0
				MOS		35.4	-19	48	19 Nov 2021 31 Oct 2025*	30 Nov 2025		
				[MOS: +1m/-1m]								
		5-12-06										
361534 Airframe	Service AIR Regulator 1H75-18		4AV57	HRS		6060.9			0			0
				AFL		4165			0			0
				MOS		265.3			20 Sep 2002			
				MSC				O/C				
				[End Of Month Item]								
38 - Water/Waste												
38-30-02-2200 Airframe	Externally Serviceable Toilet System Detailed Inspection			HRS		34			6026.9			0
				AFL		20			4145			0
				MOS		.4	14	24	17 Oct 2024 31 Oct 2026*	30 Nov 2026		
				[MOS: +1m/-1m]								
		5-12-03										
49 - Airborne Auxiliary Power												
49-00-00-2100 Airframe	Auxiliary Power Unit General Visual Inspection and Operational Check			HRS		632			5428.9			0
				AFL		628			3537			0
				MOS		35.4	-19	48	19 Nov 2021 31 Oct 2025*	30 Nov 2025		
				[MOS: +1m/-1m]								
		5-12-06										
49-00-00-2103 Airframe	Auxiliary Power Unit Containment Box Assembly General Visual Inspection			HRS		34			6026.9			0
				AFL		20			4145			0
				MOS		.4	5	72	17 Oct 2024 22 Oct 2030*	22 Nov 2030		
				[MOS: +1m/-1m]								
		5-12-13										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49-00-00-9600	APU - Compressor Rotor (Life Limit)		HRS		1959.3			0			0
	3822523-003	010350102303	APUS		3272		12000	0	12000		0
			MOS		265.3			20 Sep 2002			
	APU		[End Of Month Item]								
49-00-00-9601	APU - Turbine Rotor (Life Limit)		HRS		1959.3			0			0
	3842340-2	020134502766	APUS		3272		4000	0	4000		0
			MOS		265.3			20 Sep 2002			
	APU		[End Of Month Item]								
490001	APU - APU Electronic Control		HRS		1959.3			0			0
	2119552-2	42H0147	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
490003	APU - Bleed AIR Shutoff Valve		HRS		1749.3			210			0
	50230-8	0043D	APUS								0
			MOS		241.9			03 Sep 2004			
	APU		MSC				O/C				
			[End Of Month Item]								
490004	APU - Dc Ammeter		HRS		1959.3			0			0
	MD144-3	D221264	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
490005	APU - Overheat Detector		HRS		1959.3			0			0
	3001-212-1004/455-9	204178	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
490006	APU - Hourmeter		HRS		1959.3			0			0
	C664503-0104	SN-UNKNOWN	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
491010	APU - Generator Seal		HRS		158.4			1800.9			0
	3863504-1	SN-UNKNOWN	APUS								0
			MOS		16.1			26 Jun 2023			
	APU		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
492030	APU - Rotor Seal		HRS		158.4			1800.9			0
	3861042-2	SN-UNKNOWN	APUS								0
			MOS		16.1			26 Jun 2023			
	APU		MSC				O/C				
			[End Of Month Item]								
493000	APU - Fuel Control Assembly		HRS		1959.3			0			0
	3883900-1	0200383	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
49-30-00-9600	APU - Fuel Filter Element		HRS		117.9		900	1841.4	2741.4	2786.4	0
	3882440-1	NSN	APUS								0
			MOS	TSN:1	11.8		24	05 Nov 2023	31 Oct 2025	30 Nov 2025	
	APU		[End Of Month Item] [MOS: +1m] [HRS: +45]								
493001	APU - Tee-Flow Divider Valve		HRS		1959.3			0			0
	3883921-2	SN-UNKNOWN	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
493002	APU - Fuel Shut-Off Valve		HRS		1959.3			0			0
	PN	SN-UNKNOWN	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
494000	APU - Electrical Igniter Lead		HRS		1959.3			0			0
	3888302-20	SN-UNKNOWN	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
49-40-00-2200	APU - Remove Igniter Plug , Clean, Examine, and Install		HRS		117.9		900	1841.4	2741.4	2786.4	0
	304634-2	SN-UNKNOWN	APUS								0
			MOS		11.8		24	05 Nov 2023	30 Nov 2025	31 Dec 2025	
	APU		[End Of Month Item] [MOS: +1m] [HRS: +45]								
494001	APU - Igniter Plug		HRS		117.9			1841.4			0
	304634-2	SN-UNKNOWN	APUS								0
			MOS		11.8			05 Nov 2023			
	APU		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494002	APU - Ignition Unit		HRS		1959.3			0			0
	3888000-7	020218031058	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
49-70-01-2200	APU - Remove Chip Detector , Clean, Examine and Install		HRS		8.2		450	1951.1	2401.1	2446.1	0
			APUS		-37			3309			0
			MOS		.4		12	17 Oct 2024	31 Oct 2025	30 Nov 2025	
	APU		[End Of Month Item] [MOS: +1m] [HRS: +45]								
499000	APU - Low Oil Pressure Switch		HRS		1959.3			0			0
	3876351-1	010922700473	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
49-90-00-9600	APU - Remove and Replace Oil Filter Element		HRS		8.2		500	1951.1	2451.1	2551.1	0
			APUS		-37			3309			0
			MOS		.4			17 Oct 2024			
	APU		[End Of Month Item] [HRS: +20%/-20%]								
49-90-00-9600	APU - Change Oil		HRS		8.2			1951.1			0
			APUS		-37			3309			0
			MOS		.4			17 Oct 2024			
	APU		MSC				O/C				
			[End Of Month Item]								
499001	APU - Lube Pump Assembly		HRS		1959.3			0			0
	3881825-1	P459	APUS		3272			0			0
			MOS		265.3			20 Sep 2002			
	APU		MSC				O/C				
			[End Of Month Item]								
499002	APU - Oil Level Switch		HRS		1825.3			134			0
	3876318-1	00014	APUS								0
			MOS		250.4			17 Dec 2003			
	APU		MSC				O/C				
			[End Of Month Item]								
499110	APU - Soap Check Oil		HRS		8.2			1951.1			0
			APUS		-37			3309			0
			MOS		.4			17 Oct 2024			
	APU		MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
49APU1	APU		HRS								0
	3800722-1	P-326	AFL								0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				E/C				
[End Of Month Item]											
52 - Doors											
52-10-00-2100	Cabin Door Seals General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
5-12-01											
52-10-00-2200	Cabin Door Assembly Internal Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
5-12-06											
52-10-00-2200- ME	Cabin Door Assembly Detailed Inspection		HRS		6060.9		15000	0	15000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
4-12-ME											
521003	Acoustic Lower Fwd Seal		HRS		6060.9			0			0
	9522-13	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
521004	Acoustic Upper Seal		HRS		6060.9			0			0
	9522-11	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		MSC				O/C				
[End Of Month Item]											
521005	Acoustic Lower Aft Seal		HRS		188.2			5872.7			0
	9522-13	1420	AFL		121			4044			0
			MOS		9.5			13 Jan 2024			
	Airframe		MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
52-20-00-2200	Emergency Exit Door Assembly Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
Airframe	5-12-03		[MOS: +1m/-1m]								
52-20-00-2200- ME	Emergency Exit Door Assembly Detailed Inspection		HRS		6060.9		15000	0	15000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe	4-12-ME		[End Of Month Item]								
52-20-00-2201	Emergency Exit Door Internal Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
Airframe	5-12-16		[MOS: +1m/-1m]								
52-30-00-2200	Baggage Door Assembly Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								
527000	Emergency Exit Switch		HRS		6060.9			0			0
	8-405-04	B53641	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe			MSC				O/C				
[End Of Month Item]											
53 - Fuselage											
53-00-00-2100	Fuselage Fairing Internal Zonal General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								
53-00-00-2101	Fuselage and Fairing External Zonal General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe	5-12-06		[MOS: +1m/-1m]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-00-00-2102	Communication and Navigation Antenna Mounting		HRS								0
	Corrosion General Visual Inspection		AFL								0
			MOS				48		31 Oct 2025	30 Nov 2025	
	[End Of Month Item] [MOS: +1m/-1m]										
Airframe			5-12-06								
53-00-00-2201	Forward and Aft Lower Fairing External L/Hirf Detailed		HRS		632			5428.9			0
	Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	[MOS: +1m/-1m]										
Airframe			5-12-06								
53-00-00-9600	Right Nose Landing Gear Trunnion Support Assembly		HRS		6060.9			0			0
	Discard		AFL		4165		25500	0	25500		0
	6613020-56	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(531001) [End Of Month Item]										
Airframe											
53-00-00-9600	Left Nose Landing Gear Trunnion Support Assembly		HRS		6060.9			0			0
	Discard		AFL		4165		25500	0	25500		0
	6613020-55	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(531001) [End Of Month Item]										
Airframe											
53-00-00-9601	Nose Landing Gear Actuator Fitting Assembly Discard		HRS		6060.9			0			0
	6211190-42 SN-UNKNOWN		AFL		4165		25500	0	25500		0
			MOS		265.3			20 Sep 2002			
	(531001) [End Of Month Item]										
Airframe											
53-10-00-2100	Nose Landing Gear Wheel Well and Door Internal Zonal		HRS		632			5428.9			0
	General Visual Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	[MOS: +1m/-1m]										
Airframe			5-12-06								
53-10-00-2101	Nose Section Internal Zonal General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
	[MOS: +1m/-1m]										
Airframe			5-12-13								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-10-00-2102	Nose Avionics Components Wiring and Bulkhead		HRS		34			6026.9			0
	Connectors Standalone EzapGeneral Visual Inspection		AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe	5-12-13										
53-10-00-2103	Nose Avionics L/Hirf Standalone General Visual		HRS		34			6026.9			0
	Inspection (Airplanes -5001Thru -6000)		AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe	5-12-13										
53-10-00-2200	Nose Landing Gear and Wheel Well Structure and		HRS		34			6026.9			0
	Corrosion General Visual and Detailed Inspection		AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-01										
53-10-00-2201	Nose Structure Internal Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-16										
53-10-00-2202	Nose Non-Metallic Structure (Radome, Door Drip Caps)		HRS		632			5428.9			0
	Internal DetailedInspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-10-00-2203	Radome Diverter Strips L/Hirf Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-10-11-2200	Lower Aft Cabin Internal (Below Externally Serviced Toilet)		HRS		34			6026.9			0
	Structural and Corrosion (Borescope) Special Detailed		AFL		20			4145			0
	Inspection		MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-03										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-10-11-2201	Aft Cabin Lower Skin (Below Drop Aisle) Internal		HRS		632			5428.9			0
	Structural and CorrosionDetailed Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-10-11-2202	Lower Aft Cabin Internal (Below Carry-Out Toilet)		HRS		34			6026.9			0
	Structural and Corrosion Detailed Inspection		AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-03										
53-10-11-2501	Inspect Forward Pressure Bulkhead (Eddy Current)		HRS		446.1		2400	5614.8	8014.8		0
	Special Detailed Inspection		AFL		297			3868			0
			MOS		25	-1	120	29 Sep 2022	30 Sep 2032*		
			[End Of Month Item]								
Airframe	4-12-MD										
53-10-11-2502	Aft Pressure Bulkhead General Visual Inspection		HRS		6060.9		15000	0	15000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe	4-12-ME										
53-10-12-2100	Baggage Door and Forward Tailcone Internal Zonal		HRS		632			5428.9			0
	General Visual Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-10-12-2101	Tailcone External Zonal General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-10-12-2102	Auxiliary Power Unit Enclosure and Stinger Internal Zonal		HRS		632			5428.9			0
	General VisualInspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-10-12-2103	Forward Tailcone Avionics Components, Wire Bundles and Connectors Standalone Ezap General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-06									
53-10-12-2104	Auxiliary Power Unit Generator Power Feeder Cables Standalone EzapGeneral Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-06									
53-10-12-2200	Auxiliary Power Unit Generator, Auxiliary Power Unit Generator Control Unit, and Left / Right EngineGenerator Control Unit L/Hirf Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-06									
53-20-00-2100	Cockpit Internal (Below Floorline) Zonal General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe		5-12-13									
53-20-00-2101	Cockpit Internal (Above Floorline) Zonal General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-16									
53-20-00-2102	Cockpit Wire Bundles Standalone Ezap General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe		5-12-13									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-20-00-2103	Cockpit Avionics Components and Wire Bundles		HRS		6060.9			0			0
	Standalone Ezap General/Visual Inspection		AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-16										
53-20-00-2104	Cockpit Avionics Control Head L/Hirf Standalone General		HRS		6060.9			0			0
	Visual Inspection		AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-16										
53-30-00-2100	Cabin Internal Zonal General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-16										
53-30-00-2101	Forward Cabin (Below Floorline) Internal General Visual		HRS		6060.9			0			0
	Inspection		AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe	5-12-16										
53-30-00-2200	Elevator and Elevator Trim Control System Support		HRS		632			5428.9			0
	Structural Detailed Inspection		AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe	5-12-06										
53-30-01-2100	Upper Fuselage Skin from Right Stringer 13 to Left		HRS		6060.9		13000	0	13000		0
	Stringer 13 General Visual Inspection		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe	4-12-MJ										
53-30-01-2101	Lower Fuselage Skin from Right Stringer 13 to Left		HRS		6060.9		15000	0	15000		0
	Stringer 13 General Visual Inspection		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe	4-12-ME										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
53-30-01-2500	Fuselage External Surface (Eddy Current) Special Detailed Inspection		HRS		6060.9		7200	0	11972.4	11997.4	0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
Airframe		5-12-25									
53-30-01-2501	Upper Fuselage Skin Splice AT BI 0.00 (Eddy Current) Special Detailed Inspection		HRS		6060.9		15000	0	15000		0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe		4-12-ME									
53-30-01-2502	Lower Fuselage Skin Splices AT Stringers 13R and 13L (Eddy Current) Special Detailed Inspection		HRS		6060.9		15000	0	15000		0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe		4-12-ME									
53-31-00-2200	Composite Ventral Strake (Coin Tap) Special Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-16									
54 - Nacelles/Pylons											
54-50-01-2100	Engines Cowlings and Pylons Internal and External Zonal General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145		0	
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-03									
54-50-01-2101	Engine Cowling, Engine Pylon Firewall General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537		0	
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-06									
55 - Stabilizers											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
55-00-00-2200	Empennage Cove Structure and Corrosion Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-01									
55-10-00-2100	Empennage External Zonal General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe		5-12-13									
55-10-00-2101	Horizontal Stabilizer Surfaces Internal Zonal General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-16									
55-10-00-2200	Horizontal Stabilizer Position Switches L/Hirf Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe		5-12-13									
55-10-00-2201	Flux Detectors L/Hirf Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	5	72	17 Oct 2024	22 Oct 2030*	22 Nov 2030	
			[MOS: +1m/-1m]								
Airframe		5-12-13									
55-10-00-2900	Internal Horizontal Stabilizer (Borescope) Special Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-16									
551001	Horizontal Stabilizer Assembly PN SN-UNKNOWN		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
55-20-00-2200	Elevator Assembly Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe			[MOS: +1m/-1m]								
		5-12-06									
55-30-00-2102	Vertical Stabilizer Internal Zonal General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
Airframe			[MOS: +1m/-1m]								
		5-12-16									
55-30-00-2200	Rudder and Rudder Trim Control System Structural Support Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe			[MOS: +1m/-1m]								
		5-12-06									
55-30-00-2201	Vertical Stabilizer Pivot Fitting Detailed Inspection		HRS		216.6		1600	5844.3	7444.3	7469.3	0
			AFL		140			4025			0
			MOS		11.8			05 Nov 2023			
Airframe			[HRS: +25/-25]								
		5-12-17									
55-30-00-2900	Vertical (Stabilizer Areas With Limited Access) (Borescope) Internal SpecialDetailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
Airframe			[MOS: +1m/-1m]								
		5-12-16									
55-40-00-2200	Rudder and Rudder Trim Tab Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
Airframe			[MOS: +1m/-1m]								
		5-12-06									
56 - Windows											
561001 (561001R) Airframe	Right Main Windshield Assembly, (Rh)		HRS		2185.9			3875			0
	NP139731-209210H6923		AFL								0
			MOS		178.7			08 Dec 2009			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
561001 (561001L) Airframe	Left Main Windshield Assy, (Lh)		HRS		1961.5			4099.4			0
	9914380-13	10292H4907	AFL		1576			2589			0
			MOS		165.2			25 Jan 2011			
			MSC				O/C				
	[End Of Month Item]										
561004 (561004R) Airframe	Right Electrically Heated Cockpit Forward Side Window		HRS		6060.9			0			0
	NP139722-6	02053H9265	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
561004 (561004L) Airframe	Left Electrically Heated Cockpit Forward Side Window		HRS		6060.9			0			0
	NP139722-5	02212H2685	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
561005 (561005L) Airframe	Left Openable Cockpit Aft Side Window		HRS		6060.9			0			0
	NP139703-3	0929	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
561005 (561005R) Airframe	Right Openable Cockpit Aft Side Window		HRS		6060.9			0			0
	NP139703-4	0722	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	[End Of Month Item]										
56-11-00-2200 Airframe	Heated Windshield Assembly Hump Seal Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	[MOS: +1m/-1m]										
	5-12-01										
56-11-00-2201 Airframe	Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	[HRS: +25/-25]										
	5-12-07										
56-11-00-2202 Airframe	Windshield Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
	[MOS: +1m/-1m]										
	5-12-03										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
56-11-00-2203	Windshield Retainer Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
	Airframe		[MOS: +1m/-1m]								
		5-12-16									
56-11-00-2204	Cockpit and Openable Side Window Internal Structure Detailed Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
	Airframe		[MOS: +1m/-1m]								
		5-12-16									
56-11-00-2207	Openable Side Cockpit Windows (Transparency) Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
		5-12-06									
56-11-00-7200	Heated Windshield Assembly Fastener Torque Functional Check		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe		[HRS: +25/-25]								
		5-12-08									
56-11-00-7201	Windshield Surface Seal (Mist Spray) Functional Check		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
	Airframe		[MOS: +1m/-1m]								
		5-12-01									
562001 (562001K)	Right No. 5 Cabin Window		HRS		6060.9			0			0
	167400-03	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe						O/C				
		[End Of Month Item]									
562001 (562001J)	Right No. 4 Cabin Window		HRS		6060.9			0			0
	167400-03	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
	Airframe						O/C				
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562001 (562001B) Airframe	Left No. 3 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001F) Airframe	Left No. 7 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001A) Airframe	Left No. 2 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001C) Airframe	Left No. 4 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001D) Airframe	Left No. 5 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001L) Airframe	Right No. 6 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001E) Airframe	Left No. 6 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001G) Airframe	Right No. 1 Emergency Door Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
	SN-UNKNOWN		MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
562001 (562001H) Airframe	Right No. 2 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001M) Airframe	Right No. 7 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
562001 (562001I) Airframe	Right No. 3 Cabin Window		HRS		6060.9			0			0
	167400-03		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
57 - Wings											
57-00-00-2100 Airframe	Wing External Zonal General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	5-12-06										
57-00-00-2101 Airframe	Wing Internal Zonal General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	5-12-06										
57-00-00-2102 Airframe	Wing Fuel Probe Wiring Harness Standalone Ezap General Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	5-12-06										
57-00-00-2200 Airframe	Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
	5-12-01										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
57-10-00-2100	Left and Right Main Landing Gear Wheel Well and Door Internal Zonal General/Visual Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-06									
57-10-00-2101	Left and Right Wing Forward Spar (Forward Side) and Wing Tip InternalStandalone General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe		5-12-16									
57-10-00-2200	Main Landing Gear and Wheel Well Structure and Corrosion Detailed General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	12	17 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe		5-12-01									
57-10-00-2500	Lower Wing Main Spar Lower Skin Splice AT Ws 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection		HRS		6060.9		7500**	0	7500		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe		4-12-MF									
57-10-00-2501	Lower Wing Main Spar Skin Splice Flange AT Ws 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection		HRS		6060.9		11500**	0	11500		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
Airframe		4-12-ML									
57-10-00-2502	Lower Wing Main Spar AT Ws 114.57 (Eddy Current) Special Detailed Inspection		HRS		6060.9		11000**	0	11000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe		4-12-MM									
57-10-00-2503	Lower Wing Main Spar AT Ws 131.07 (Eddy Current) Special Detailed Inspection		HRS		6060.9		9000**	0	9000		0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe		4-12-MN									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
57-10-00-2504	Lower Wing Main Spar AT Ws 149.57 (Eddy Current)		HRS		6060.9		12500**	0	12500		0
	Special Detailed Inspection		AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
Airframe	4-12-MO										
57-10-00-9600	Right Main Landing Gear Forward Trunnion Fitting		HRS		6060.9			0			0
	Discard		AFL		4165		23800	0	23800		0
	6622123-2	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(571001)		[End Of Month Item]								
Airframe											
57-10-00-9600	Left Main Landing Gear Forward Trunnion Fitting Discard		HRS		6060.9			0			0
	6622123-1	SN-UNKNOWN	AFL		4165		23800	0	23800		0
	(571001)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
57-10-00-9601	Left Main Landing Gear Aft Trunnion Fitting Discard		HRS		6060.9			0			0
	6622124-1	SN-UNKNOWN	AFL		4165		23800	0	23800		0
	(571002)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
57-10-00-9601	Right Main Landing Gear Aft Trunnion Fitting Discard		HRS		6060.9			0			0
	6622124-2	SN-UNKNOWN	AFL		4165		23800	0	23800		0
	(571002)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
57-10-00-9602	Left Main Landing Gear Actuator Fitting Discard		HRS		6060.9			0			0
	6621125-5	SN-UNKNOWN	AFL		4165		23800	0	23800		0
	(571003)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
57-10-00-9602	Right Main Landing Gear Actuator Fitting Discard		HRS		6060.9			0			0
	6621125-6	SN-UNKNOWN	AFL		4165		23800	0	23800		0
	(571003)		MOS		265.3			20 Sep 2002			
	Airframe		[End Of Month Item]								
57-30-01-2100	Wing Tip Internal Zonal General Visual Inspection		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3		96	20 Sep 2002	31 Oct 2026	30 Nov 2026	
	Airframe		[MOS: +1m/-1m]								
		5-12-16									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
57-50-00-2200	Speed Brake Panels and Attachment Fittings Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe			5-12-06								
57-50-03-2200	Aileron, Aileron Trim Tab and Hinge Brackets Detailed Inspect		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe			5-12-06								
57-50-04-2900	Inboard and Outboard Flaps (Coin Tap) Special Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe			5-12-06								
57-50-04-9600	Left Wing Right Outboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
(275004)											
Airframe											
57-50-04-9600	Left Wing Left Outboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
(275004)											
Airframe											
57-50-04-9600	Left Wing Right Inboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
(275004)											
Airframe											
57-50-04-9600	Right Wing Left Inboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
			MOS		265.3			20 Sep 2002			
			[End Of Month Item]								
(275004)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
57-50-04-9600 (275004) Airframe	Right Wing Right Inboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600 (275004) Airframe	Right Wing Left Outboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600 (275004) Airframe	Left Wing Left Inboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600 (275004) Airframe	Right Wing Right Outboard Aft Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600.1 (275005) Airframe	Right Wing Right Inboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600.1 (275005) Airframe	Left Wing Right Inboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										
57-50-04-9600.1 (275005) Airframe	Right Wing Right Outboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
57-50-04-9600.1	Left Wing Left Outboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(275005)		[End Of Month Item]								
Airframe											
57-50-04-9600.1	Left Wing Right Outboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(275005)		[End Of Month Item]								
Airframe											
57-50-04-9600.1	Right Wing Left Inboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(275005E)		[End Of Month Item]								
Airframe											
57-50-04-9600.1	Right Wing Left Outboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(275005)		[End Of Month Item]								
Airframe											
57-50-04-9600.1	Left Wing Left Inboard Forward Flap Roller Discard (S3049-5F8)		HRS		6060.9			0			0
			AFL		4165		5000	0	5000		0
	S3049-5F8	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
	(275005)		[End Of Month Item]								
Airframe											
57-60-00-2200	Aileron, Aileron Wing Sectors and Aileron Trim Components Structure Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe											
5-12-06											
71 - Power Plant											
71-00-00	No. 1 Engine - Engine Condition Trend Monitoring		HRS		19.3			6041.6			0
			ENC		9		40	4131	4171		0
			MOS		.4		1	17 Oct 2024	17 Nov 2024	27 Nov 2024	
	Engine		[+10d]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
71-00-00	No. 2 Engine - Engine Condition Trend Monitoring		HRS		19.3			6041.6			0
			ENC		9		40	4131	4171		0
			MOS		.4		1	17 Oct 2024	17 Nov 2024	27 Nov 2024	
			[+10d]								
Engine											
71-00-00-2100	Engine FIRE Detection Element Standalone Ezap General Visual Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
	5-12-03										
71-00-00-2200	Engine Starter Generator, Alternator, Alternator Pcu, Full Authority Digital Electronic Control L/Hirf Detailed Inspection		HRS		34			6026.9			0
			AFL		20			4145			0
			MOS		.4	14	24	17 Oct 2024	31 Oct 2026*	30 Nov 2026	
			[MOS: +1m/-1m]								
Airframe											
	5-12-03										
71-00-00-2201	Engine Cowling L/Hirf Detailed Inspection		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4	-19	48	19 Nov 2021	31 Oct 2025*	30 Nov 2025	
			[MOS: +1m/-1m]								
Airframe											
	5-12-06										
710010	No. 1 Engine - Compressor Desalination Wash		HRS		1288.5			4772.4			0
			ENC		924			3216			0
			MOS		75.7			09 Jul 2018			
			MSC				A/R				
Engine	[End Of Month Item]										
710010	No. 2 Engine - Compressor Desalination Wash		HRS		1288.5			4772.4			0
			ENC		924			3216			0
			MOS		75.7			09 Jul 2018			
			MSC				A/R				
Engine	[End Of Month Item]										
710020	No. 1 Engine - Performance Recovery Wash		HRS		6060.9			0			0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				A/R				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
710020	No. 2 Engine - Performance Recovery Wash		HRS		6060.9			0			0
			ENC		4140			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			A/R					
Engine											
712005	Eng Vibration Monitor- 2789		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe											
			[End Of Month Item]								
71-22-00-9600	Right Bottom Forward Engine IsolatorMount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing BushingFunctional Check) Restoration		HRS		6060.9	15	10000	0	10015*		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			[End Of Month Item]								
(712002)											
Airframe											
71-22-00-9600	Left Aft Engine Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration		HRS		6060.9	15	10000	0	10015*		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			[End Of Month Item]								
(712001)											
Airframe											
71-22-00-9600	Left Bottom Forward Engine IsolatorMount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing BushingFunctional Check) Restoration		HRS		6060.9	15	10000	0	10015*		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			[End Of Month Item]								
(712002)											
Airframe											
71-22-00-9600	Right Aft Engine Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration		HRS		6060.9	15	10000	0	10015*		0
			AFL		4165			0		0	
			MOS		265.3		20 Sep 2002				
			[End Of Month Item]								
(712001)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
71-22-00-9600	Left Upper Forward Engine IsolatorMount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing BushingFunctional Check) Restoration 9912480-1 LK1652		HRS		980		10000	5080.9	15080.9		0
			AFL								0
			MOS		56.1			26 Feb 2020			
			[End Of Month Item]								
(712002)											
Airframe											
71-22-00-9600	Right Upper Forward Engine IsolatorMount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing BushingFunctional Check) Restoration 9912480-1 LK1833		HRS		980		10000	5080.9	15080.9		0
			AFL								0
			MOS		56.1			26 Feb 2020			
			[End Of Month Item]								
(712002)											
Airframe											
71-71-00-2100	Engine Drains General Visual Inspection 5-12-08		HRS		6060.9		2400	0	7005.3	7030.3	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
Airframe											
71EN1	No. 1 Engine 31J1900-01 PCE-DB0569		HRS		6060.9			0			0
			AFL								0
			MOS		265.3			20 Sep 2002			
			MSC				E/C				
Airframe	[End Of Month Item]										
71EN2	No. 2 Engine 31J1900-01 PCE-DB0582		HRS		6060.9			0			0
			AFL								0
			MOS		265.3			20 Sep 2002			
			MSC				E/C				
Airframe	[End Of Month Item]										
72 - Engine											
720002	No. 1 Engine - Borescope Inspection Engine		HRS		975.6			5085.3			0
			ENC								0
			MOS		56.7			08 Feb 2020			
			MSC				N/A				
Engine	[End Of Month Item]										
720002	No. 2 Engine - Borescope Inspection Engine		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[End Of Month Item] [HRS: +25/-25]								
Engine											
057159											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
720075	No. 1 Engine - Lp Compressor Shaft - Discard AT		HRS		6060.9			0			0
	Scheduled Overhaul		ENC		4140			0			0
	PN	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
			MSC				A/R				
	Engine		[End Of Month Item]								
720075	No. 2 Engine - Lp Compressor Shaft - Discard AT		HRS		6060.9			0			0
	Scheduled Overhaul		ENC		4140			0			0
	PN	SN-UNKNOWN	MOS		265.3			20 Sep 2002			
			MSC				A/R				
	Engine		[End Of Month Item]								
720080	No. 1 Engine - Discard Hp Turbine Nut and Keywasher		HRS		6060.9		5000	0	10085.3	10110.3	0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
	Engine										
720080	No. 2 Engine - Discard Hp Turbine Nut and Keywasher		HRS		6060.9		5000	0	10085.3	10110.3	0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
	Engine										
721010	No. 1 Engine - Access Gearbox Shaft		HRS		6060.9			0			0
	30J2201-01	A0015C0K	ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Engine		[End Of Month Item]								
721010	No. 2 Engine - Access Gearbox Shaft		HRS		6060.9			0			0
	30J2201-01	A0016456	ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
	Engine		[End Of Month Item]								
722001	No. 1 Engine - Oil Pump Assembly		HRS		975.6			5085.3			0
	01R30J3365-01	701386	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
	Engine		[End Of Month Item]								
722001	No. 2 Engine - Oil Pump Assembly		HRS		975.6			5085.3			0
	01R30J3365-01	45A501	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				O/C				
	Engine		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723010	No. 1 Engine - Lp Compressor Fan Rotor (Life Limit)		HRS		6060.9			0			0
	30J2091-01	A0015RHW	ENC		4140			0	15000		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				15000	0			
		[End Of Month Item]									
723010	No. 2 Engine - Lp Compressor Fan Rotor (Life Limit)		HRS		6060.9			0			0
	30J2091-01	A0016062	ENC		4140			0	15000		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				15000	0			
		[End Of Month Item]									
723020	No. 1 Engine - Lp Compressor Boost Rotor (Life Limit)		HRS		6060.9			0			0
	30J2210-01	TX1A2121	ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
		[End Of Month Item]									
723020	No. 2 Engine - Lp Compressor Boost Rotor (Life Limit)		HRS		6060.9			0			0
	30J2210-01	TX1A2199	ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
		[End Of Month Item]									
723025	No. 1 Engine - Lp Compressor Shaft		HRS		6060.9			0			0
	PN	SN-UNKNOWN	ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
	Engine		MSC				H/T				
		[End Of Month Item]									
723025	No. 2 Engine - Lp Compressor Shaft		HRS		6060.9			0			0
	PN	SN-UNKNOWN	ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
	Engine		MSC				H/T				
		[End Of Month Item]									
723030	No. 1 Engine - 1ST Stage Hp Compressor Rotor (Life Limit)		HRS	TSN:5085.3	975.6			5085.3			0
			ENC	TSN:3458	682			3458	13500		0
	30J2821-01	A0015221	MOS		56.7			08 Feb 2020			
			ACCC	TSN:3458			13500	0			
	Engine	[End Of Month Item]									
723030	No. 2 Engine - 1ST Stage Hp Compressor Rotor (Life Limit)		HRS	TSN:5085.3	975.6			5085.3			0
			ENC	TSN:3458	682			3458	13500		0
	30J2821-01	A0015RL4	MOS		56.6			10 Feb 2020			
			ACCC	TSN:3458			13500	0			
	Engine	[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723040	No. 1 Engine - 2ND Stage Hp Compressor Rotor (Life Limit)		HRS		6060.9			0			0
			ENC		4140			0	13500		0
	30J2122-01	A0014YC8	MOS		265.3			20 Sep 2002			
			ACCC				13500	0			
Engine	[End Of Month Item]										
723040	No. 2 Engine - 2ND Stage Hp Compressor Rotor (Life Limit)		HRS		6060.9			0			0
			ENC		4140			0	13500		0
	30J2122-01	A0015LDY	MOS		265.3			20 Sep 2002			
			ACCC				13500	0			
Engine	[End Of Month Item]										
723060	No. 1 Engine - Centrifugal Impeller (Life Limit)		HRS		6060.9			0			0
	30J1450-01A00158XB		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
			ACCC				13500	0			
Engine	[End Of Month Item]										
723060	No. 2 Engine - Centrifugal Impeller (Life Limit)		HRS		6060.9			0			0
	30J1450-01A0015P73		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
			ACCC				13500	0			
Engine	[End Of Month Item]										
72-31-00-201	No. 1 Engine - Lp Compressor Section - Engine Mount		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security and Condition of the Engine Mount		ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(723110)											
Engine	057159										
72-31-00-201	No. 2 Engine - Lp Compressor Section - Engine Mount		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security and Condition of the Engine Mount		ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(723110)											
Engine	057159										
72-31-00-202	No. 1 Engine - Lp Compressor Section - External Engine		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do an Inspection for Fuel and Oil Leaks, Corrosion, Cracks and Signs of Damage		ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(723100)											
Engine	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-31-00-202	No. 2 Engine - Lp Compressor Section - External Engine		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do an Inspection for Fuel and		ENC		140			4000	0		0
	Oil Leaks, Corrosion, Cracks and Signs of Damage		MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(723100)											
Engine	057159										
72-31-00-203	No. 1 Engine - Lp Compressor Section - Compressor Inlet		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do an Inspection of the		ENC		140			4000	0		0
	Compressor Inlet Fan, Fan Exit Stator Vanes, Abradable		MOS		11.8			05 Nov 2023			
	Fan Seal for Cleanliness, Damage, Corrosion, Erosion and FOD		[HRS: +25/-25]								
(723120)											
Engine	057159										
72-31-00-203	No. 1 Engine - Lp Compressor Section - Examine the		HRS		6060.9			0			0
	Bottom Center AREA of the Fan Case for Ice. Make Sure		ENC		4140			0			0
	the Fan Rotates Freely		MOS		265.3			20 Sep 2002			
			MSC				A/R				
(723130)											
Engine											
72-31-00-203	No. 2 Engine - Lp Compressor Section - Compressor Inlet		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do an Inspection of the		ENC		140			4000	0		0
	Compressor Inlet Fan, Fan Exit Stator Vanes, Abradable		MOS		11.8			05 Nov 2023			
	Fan Seal for Cleanliness, Damage, Corrosion, Erosion and FOD		[HRS: +25/-25]								
(723120)											
Engine	057159										
72-31-00-203	No. 2 Engine - Lp Compressor Section - Examine the		HRS		6060.9			0			0
	Bottom Center AREA of the Fan Case for Ice. Make Sure		ENC		4140			0			0
	the Fan Rotates Freely		MOS		265.3			20 Sep 2002			
			MSC				A/R				
(723130)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-31-00-901	No. 1 Engine - Lp Compressor Section - Low Pressure Compressor Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(723140)											
Engine											
72-31-00-901	No. 2 Engine - Lp Compressor Section - Low Pressure Compressor Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(723140)											
Engine											
72-32-00-201	No. 1 Engine - Hp Compressor Section - Compressor Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(723200)											
Engine											
72-32-00-201	No. 2 Engine - Hp Compressor Section - Compressor Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(723200)											
Engine											
72-32-00-901	No. 1 Engine - Hp Compressor Section - High Pressure Compressor Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(723210)											
Engine											
72-32-00-901	No. 2 Engine - Hp Compressor Section - High Pressure Compressor Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(723210)											
Engine											
72-40-00-201	No. 1 Engine - Combustion Section - Combustion Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(724000)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-40-00-201 (724000) Engine	No. 2 Engine - Combustion Section - Combustion Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +25/-25]								
72-40-00-901 (724010) Engine	No. 1 Engine - Combustion Section -Combustion Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +25/-25]								
72-40-00-901 (724010) Engine	No. 2 Engine - Combustion Section -Combustion Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +25/-25]								
724001 Engine	No. 1 Engine - Inner Combustion Chamber Liner 30J2546-01 A0015HHE		HRS		6060.9			0			0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
724001 Engine	No. 2 Engine - Inner Combustion Chamber Liner 30J2546-01 A00160T6		HRS		6060.9			0			0
			ENC		4140			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
72-50-00-201 (725050) Engine	No. 1 Engine - Turbine Section - Turbine Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +25/-25]								
72-50-00-201 (725050) Engine	No. 2 Engine - Turbine Section - Turbine Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +25/-25]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-50-00-701	No. 1 Engine - Do A Five Point Performance Uncapped Calibration Run		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0	0		
			MOS		11.8		05 Nov 2023				
	(71-00-00.6)	[End Of Month Item] [HRS: +25/-25]									
Engine	057159										
72-50-00-701	No. 2 Engine - Do A Five Point Performance Uncapped Calibration Run		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0	0		
			MOS		11.8		05 Nov 2023				
	(71-00-00.6)	[End Of Month Item] [HRS: +25/-25]									
Engine	057159										
72-50-00-702	No. 1 Engine - Turbine Section - Acceleration/Deceleration Functional Check		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0	0		
			MOS		11.8		05 Nov 2023				
	(725000)	[HRS: +25/-25]									
Engine	057159										
72-50-00-702	No. 2 Engine - Turbine Section - Acceleration/Deceleration Functional Check		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0	0		
			MOS		11.8		05 Nov 2023				
	(725000)	[HRS: +25/-25]									
Engine	057159										
72-50-00-901	No. 1 Engine - Turbine Section - Turbine Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
	(725060)	[HRS: +25/-25]									
Engine											
72-50-00-901	No. 2 Engine - Turbine Section - Turbine Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
	(725060)	[HRS: +25/-25]									
Engine											
725010	No. 1 Engine - 1ST-Stage Turbine Disk (Life Limit) 30J1551-01 A00168AH		HRS		6060.9			0			0
			ENC		4140		0	13500		0	
			MOS		265.3		20 Sep 2002				
	Engine			ACCC			13500	0			
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725010	No. 2 Engine - 1ST-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30J1551-01 A0016NLW		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725020	No. 1 Engine - 2ND-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3152 75B229		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725020	No. 2 Engine - 2ND-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3152 75B243		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725030	No. 1 Engine - 3RD-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3153 75B700		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725030	No. 2 Engine - 3RD-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3153 75B717		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725040	No. 1 Engine - 4TH-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3154 76B212		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								
725040	No. 2 Engine - 4TH-Stage Turbine Disk (Life Limit)		HRS		6060.9			0			0
	30H3154 76B190		ENC		4140			0	13500		0
			MOS		265.3			20 Sep 2002			
	Engine		ACCC				13500	0			
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-60-00-201	No. 1 Engine - Accessory Gearbox - Engine Accessory		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security of		ENC		140			4000	0		0
	Installation and General Condition of Accessories and Gearbox		MOS		11.8			05 Nov 2023			
	[HRS: +25/-25]										
(726000)											
Engine	057159										
72-60-00-201	No. 2 Engine - Accessory Gearbox - Engine Accessory		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security of		ENC		140			4000	0		0
	Installation and General Condition of Accessories and Gearbox		MOS		11.8			05 Nov 2023			
	[HRS: +25/-25]										
(726000)											
Engine	057159										
72-60-00-901	No. 1 Engine - Accessory Gearbox - Accessory Gearbox		HRS		975.6		5000	5085.3	10085.3	10110.3	0
	(Engine TBO) Restoration		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	[HRS: +25/-25]										
(726010)											
Engine											
72-60-00-901	No. 2 Engine - Accessory Gearbox - Accessory Gearbox		HRS		975.6		5000	5085.3	10085.3	10110.3	0
	(Engine TBO) Restoration		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	[HRS: +25/-25]										
(726010)											
Engine											
72-70-00-201	No. 1 Engine - Bypass Section - Bypass Ducts and		HRS		216.6		800	5844.3	0		0
	Fairings General Visual Inspection: Do A Check for		ENC		140			4000	0		0
	Cleanliness and FOD. Do an Inspection for Cracks In the		MOS		11.8			05 Nov 2023			
	Outer Bypass Duct, Rear Bypass Duct, Struts and Fairing		[HRS: +25/-25]								
(727010)											
Engine	057159										
72-70-00-201	No. 2 Engine - Bypass Section - Bypass Ducts and		HRS		216.6		800	5844.3	0		0
	Fairings General Visual Inspection: Do A Check for		ENC		140			4000	0		0
	Cleanliness and FOD. Do an Inspection for Cracks In the		MOS		11.8			05 Nov 2023			
	Outer Bypass Duct, Rear Bypass Duct, Struts and Fairing		[HRS: +25/-25]								
(727010)											
Engine	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
72-70-00-202	No. 1 Engine - Bypass Section - Bypass Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(727000)			MOS		56.7			08 Feb 2020			
Engine			[HRS: +25/-25]								
72-70-00-202	No. 2 Engine - Bypass Section - Bypass Section (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(727000)			MOS		56.6			10 Feb 2020			
Engine			[HRS: +25/-25]								
72-70-00-901	No. 1 Engine - Bypass Section - Bypass Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
(727030)			MOS		56.7			08 Feb 2020			
Engine			[HRS: +25/-25]								
72-70-00-901	No. 2 Engine - Bypass Section - Bypass Section (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
(727030)			MOS		56.6			10 Feb 2020			
Engine			[HRS: +25/-25]								
73 - Engine Fuel and Control											
73-10-00-201	No. 1 Engine - Hot Section Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(720060)			MOS		56.7			08 Feb 2020			
Engine			[End Of Month Item] [HRS: +25/-25]								
73-10-00-201	No. 2 Engine - Hot Section Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(720060)			MOS		56.6			10 Feb 2020			
Engine			[End Of Month Item] [HRS: +25/-25]								
73-10-00-202	No. 1 Engine - Fuel Distribution - External Tubing General Visual Inspection: Examine for Signs of Wear, Chafing, Cracks, Leaks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
(731000)			MOS		11.8			05 Nov 2023			
Engine			[HRS: +25/-25]								
057159											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
73-10-00-202	No. 2 Engine - Fuel Distribution - External Tubing General Visual Inspection: Examine for Signs of Wear, Chafing, Cracks, Leaks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731000)	[HRS: +25/-25]										
Engine	057159										
73-10-00-204	No. 1 Engine - Fuel Distribution - Fuel Metering and Control Components General Visual Inspection: Do A Check for Security, Leakage (No Leakage Permitted) and General Condition		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731040)	[HRS: +25/-25]										
Engine	057159										
73-10-00-204	No. 2 Engine - Fuel Distribution - Fuel Metering and Control Components General Visual Inspection: Do A Check for Security, Leakage (No Leakage Permitted) and General Condition		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731040)	[HRS: +25/-25]										
Engine	057159										
73-10-00-205	No. 1 Engine - Fuel Distribution - Fuel Oil Heat Exchanger General Visual Inspection: Do an Inspection for Security, Leakage and General Condition		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731050)	[HRS: +25/-25]										
Engine	057159										
73-10-00-205	No. 2 Engine - Fuel Distribution - Fuel Oil Heat Exchanger General Visual Inspection: Do an Inspection for Security, Leakage and General Condition		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731050)	[HRS: +25/-25]										
Engine	057159										
73-10-00-206	No. 1 Engine - Fuel Distribution - Fuel Filter Element Detailed Inspection: Do an Inspection for Foreign Material and Damage		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731020)	[HRS: +25/-25]										
Engine	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
73-10-00-206	No. 2 Engine - Fuel Distribution - Fuel Filter Element		HRS		216.6		800	5844.3	0		0
	Detailed Inspection: Do an Inspection for Foreign Material and Damage		ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(731020)	[HRS: +25/-25]										
Engine	057159										
73-10-00-207	No. 1 Engine - Fuel Distribution - Emergency Fuel Shutoff		HRS		216.6		800	5844.3	0		0
	System Detailed Inspection: Do an Inspection Through		ENC		140			4000	0		0
	Hole In the Exhaust Cone and Check for Security of		MOS		11.8			05 Nov 2023			
(731100)	[End Of Month Item] [HRS: +25/-25]										
Engine	057159										
73-10-00-207	No. 1 Engine - Dimensional Check Emergency Fuel		HRS		975.6			5085.3			0
	Shutoff Pin		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
(731110)	MSC A/R										
Engine	[End Of Month Item]										
73-10-00-207	No. 2 Engine - Dimensional Check Emergency Fuel		HRS		975.6			5085.3			0
	Shutoff Pin		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
(731110)	MSC A/R										
Engine	[End Of Month Item]										
73-10-00-207	No. 2 Engine - Fuel Distribution - Emergency Fuel Shutoff		HRS		216.6		800	5844.3	0		0
	System Detailed Inspection: Do an Inspection Through		ENC		140			4000	0		0
	Hole In the Exhaust Cone and Check for Security of		MOS		11.8			05 Nov 2023			
(731100)	[End Of Month Item] [HRS: +25/-25]										
Engine	057159										
73-10-00-701	No. 1 Engine - Fuel Distribution - Emergency Fuel Shutoff		HRS		975.6		2500	5085.3	7585.3	7610.3	0
	System Operational Check: Do A Check for the Rigging		ENC								0
	and Operation of the Emergency Fuel Shutoff System		MOS		56.7			08 Feb 2020			
(731070)	[HRS: +25/-25]										
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
73-10-00-701	No. 2 Engine - Fuel Distribution - Emergency Fuel Shutoff System Operational Check: Do A Check for the Rigging and Operation of the Emergency Fuel Shutoff System		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC							0	
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(731070)											
Engine											
73-10-00-901	No. 1 Engine - Install New Fuel Filter Element		HRS		975.6		1200	5085.3	6285.3	6310.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
			[End Of Month Item] [HRS: +25/-25]								
(731030)											
Engine											
73-10-00-901	No. 2 Engine - Install New Fuel Filter Element		HRS		975.6		1200	5085.3	6285.3	6310.3	0
			ENC		682		3458			0	
			MOS		56.6		10 Feb 2020				
			[End Of Month Item] [HRS: +25/-25]								
(731030)											
Engine											
73-10-00-902	No. 1 Engine - Fuel Distribution - Fuel Distribution (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(731080)											
Engine											
73-10-00-902	No. 2 Engine - Fuel Distribution - Fuel Distribution (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458			0	
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(731080)											
Engine											
731002	No. 1 Engine - Flow Divider Valve 819710-2 F55228		HRS		975.6			5085.3			0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
			MSC				O/C				
Engine	[End Of Month Item]										
731002	No. 2 Engine - Flow Divider Valve 819710-2 F55439		HRS	TSN:5085.3	975.6			5085.3			0
			ENC	TSN:3458	682		3458			0	
			MOS		56.6		10 Feb 2020				
			MSC				O/C				
Engine	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731004	No. 1 Engine - Inspect Fuel Manifold		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
731004	No. 2 Engine - Inspect Fuel Manifold		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
731015	No. 1 Engine - Inspect and Functional Test Fuel Filter Differential Pressure Switch		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
731015	No. 2 Engine - Inspect and Functional Test Fuel Filter Differential Pressure Switch		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
731025	No. 1 Engine - Overhaul or Refurbish Flow Divider		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
731025	No. 2 Engine - Overhaul or Refurbish Flow Divider		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
731090	No. 1 Engine - Fuel System - Fuel Flow Divider Valve: Security, Leakage and General Condition		HRS		1288.5			4772.4			0
			ENC						0		
			MOS		75.7		09 Jul 2018				
			MSC			A/R					
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731090	No. 2 Engine - Fuel System - Fuel Flow Divider Valve: Security, Leakage and General Condition		HRS		1288.5			4772.4			0
			ENC							0	
			MOS		75.7		09 Jul 2018				
			MSC				A/R				
Engine											
731105	No. 1 Engine - Fuel Shut-Off Cable - Do an Inspection		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +100]								
Engine											
731105	No. 2 Engine - Fuel Shut-Off Cable - Do an Inspection		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +100]								
Engine											
731125	No. 1 Engine - Inspect Fuel Shut-Off Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +100]								
Engine											
731125	No. 2 Engine - Inspect Fuel Shut-Off Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +100]								
Engine											
731150	No. 1 Engine - Overhaul/Refurbish Fuel Nozzles		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +100]								
Engine											
731150	No. 2 Engine - Overhaul/Refurbish Fuel Nozzles		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +100]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
73-20-00-201	No. 1 Engine - Fuel Controlling - Engine Wiring Harness		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security of All		ENC		140			4000	0		0
	Clamps and Brackets. Examine the Cables for Sign of		MOS		11.8			05 Nov 2023			
	Wear, Fraying, Chafing and Cracks.Do A Check for		[HRS: +25/-25]								
Security of All Wiring Harness Connectors. Examine the											
Outer Surfaces for Cracks and Corrosion. Examine the											
Control Linkage and ROD End Bearings for Freedom of											
Movement.											
(732030)											
Engine											
057159											
73-20-00-201	No. 2 Engine - Fuel Controlling - Engine Wiring Harness		HRS		216.6		800	5844.3	0		0
	General Visual Inspection: Do A Check for Security of All		ENC		140			4000	0		0
	Clamps and Brackets. Examine the Cables for Sign of		MOS		11.8			05 Nov 2023			
	Wear, Fraying, Chafing and Cracks.Do A Check for		[HRS: +25/-25]								
Security of All Wiring Harness Connectors. Examine the											
Outer Surfaces for Cracks and Corrosion. Examine the											
Control Linkage and ROD End Bearings for Freedom of											
Movement.											
(732030)											
Engine											
057159											
73-20-00-901	No. 1 Engine - Fuel Controlling - Engine Wiring Harness		HRS		216.6		800	5844.3	0		0
	(Cleaning) Restoration: Disconnect Each Wiring Harness		ENC		140			4000	0		0
	Connector, Clean, Inspect and Connect Again. Do the		MOS		11.8			05 Nov 2023			
	Necessary Engine Checks after Wiring Harness		[End Of Month Item] [HRS: +25/-25]								
Replacement											
(710060)											
Engine											
057159											
73-20-00-901	No. 2 Engine - Fuel Controlling - Engine Wiring Harness		HRS		216.6		800	5844.3	0		0
	(Cleaning) Restoration: Disconnect Each Wiring Harness		ENC		140			4000	0		0
	Connector, Clean, Inspect and Connect Again. Do the		MOS		11.8			05 Nov 2023			
	Necessary Engine Checks after Wiring Harness		[End Of Month Item] [HRS: +25/-25]								
Replacement											
(710060)											
Engine											
057159											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
73-20-00-902	No. 1 Engine - Fuel Controlling - Fuel Controlling (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
(732040)			[HRS: +25/-25]								
Engine											
73-20-00-902	No. 2 Engine - Fuel Controlling - Fuel Controlling (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
(732040)			[HRS: +25/-25]								
Engine											
732001	No. 1 Engine - Hydromechanical Fuel Control		HRS		975.6			5085.3			0
	1012635-13	F52831	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
Engine			MSC				O/C				
			[End Of Month Item]								
732001	No. 2 Engine - Hydromechanical Fuel Control		HRS		975.6			5085.3			0
	1012635-13	F56232	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
Engine			MSC				O/C				
			[End Of Month Item]								
732003	No. 1 Engine - Inspect Eec		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
Engine			[HRS: +100]								
732003	No. 2 Engine - Inspect Eec		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
Engine			[HRS: +100]								
732005	No. 1 Engine - Overhaul Fuel Control Unit and Pump		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	1012635-13	F52831	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
Engine			[HRS: +100]								
732005	No. 2 Engine - Overhaul Fuel Control Unit and Pump		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	1012635-13	F56232	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
Engine			[HRS: +100]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
732010	No. 1 Engine - Inspect T0 Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
732010	No. 2 Engine - Inspect T0 Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
732015	No. 1 Engine - Inspect T1 Fcu Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
732015	No. 2 Engine - Inspect T1 Fcu Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
733001 (733001L) Airframe	Left Fuel Flow Transmitter 9-231-28		L8523	HRS	6060.9			0			0
				AFL	4165			0			0
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
733001 (733001R) Airframe	Right Fuel Flow Transmitter 9-231-28		L8480	HRS	6060.9			0			0
				AFL	4165			0			0
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
733004 (733004R) Airframe	Right Fuel Pressure Switch 6057-3		1653	HRS	6060.9			0			0
				AFL	4165			0			0
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
733004 (733004L) Airframe	Left Fuel Pressure Switch 6057-3		1722	HRS	6060.9			0			0
				AFL	4165			0			0
				MOS	265.3			20 Sep 2002			
				MSC			O/C				
				[End Of Month Item]							
74 - Ignition											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
741000	No. 1 Engine - Clean and Inspect Ignition Exciter Box		HRS		975.6		5000	5085.3	10085.3	10185.3	0	
			ENC		682			3458			0	
			MOS		56.7			08 Feb 2020				
			[HRS: +100]									
741000	No. 2 Engine - Clean and Inspect Ignition Exciter Box		HRS		975.6		5000	5085.3	10085.3	10185.3	0	
			ENC		682			3458			0	
			MOS		56.6			10 Feb 2020				
			[HRS: +100]									
741001	No. 1 Engine - Ignition Exciter 500335-1	NN02266369	HRS		975.6			5085.3			0	
			ENC		682			3458			0	
			MOS		56.7			08 Feb 2020				
			MSC				O/C					
741001	No. 2 Engine - Ignition Exciter 500335-1	NNA04516347	[End Of Month Item]									
			HRS		216.6			5844.3			0	
			ENC		140			4000			0	
			MOS		11.8			05 Nov 2023				
741015	No. 1 Engine - Clean and Inspect Ignition Plugs		MSC				O/C					
			[End Of Month Item]									
			HRS		975.6		5000	5085.3	10085.3	10185.3	0	
			ENC		682			3458			0	
741015	No. 2 Engine - Clean and Inspect Ignition Plugs		MOS		56.7			08 Feb 2020				
			[HRS: +100]									
			HRS		975.6		5000	5085.3	10085.3	10185.3	0	
			ENC		682			3458			0	
741015			MOS		56.6			10 Feb 2020				
			[HRS: +100]									
			HRS		216.6		800	5844.3	0		0	
			ENC		140			4000	0		0	
74-20-00-201	No. 1 Engine - Ignition - Ignition Exciter General Visual Inspection: Do A Check for Security and General Condition		MOS		11.8			05 Nov 2023				
			[HRS: +25/-25]									
			(742030)									
			Engine									
057159												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
74-20-00-201	No. 2 Engine - Ignition - Ignition Exciter General Visual Inspection: Do A Check for Security and General Condition		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(742030)											
Engine	057159										
74-20-00-202	No. 1 Engine - Ignition - Igniters (Tip Measurement) Functional Check (Pre-SB30340): Do A Check for Cleanliness and Measure Erosion		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				N/A				
(740010)	[End Of Month Item]										
Engine											
74-20-00-202	No. 2 Engine - Ignition - Igniters (Tip Measurement) Functional Check (Pre-SB30340): Do A Check for Cleanliness and Measure Erosion		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				N/A				
(740010)	[End Of Month Item]										
Engine											
74-20-00-203	No. 1 Engine - Ignition - Igniters (Tip Measurement) Functional Check (Post-SB30340): Do A Check for Cleanliness and Measure Erosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(740010)											
Engine	057159										
74-20-00-203	No. 2 Engine - Ignition - Igniters (Tip Measurement) Functional Check (Post-SB30340): Do A Check for Cleanliness and Measure Erosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(740010)											
Engine	057159										
74-20-00-205	No. 1 Engine - Ignition - Ignition Cables General Visual Inspection: Do A Check for Chafing, Wear and Security		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(742020)											
Engine	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
74-20-00-205	No. 2 Engine - Ignition - Ignition Cables General Visual Inspection: Do A Check for Chafing, Wear and Security		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
	(742020)			[HRS: +25/-25]							
Engine	057159										
74-20-00-206	No. 1 Engine - Ignition - Ignition (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
	(742050)			[HRS: +25/-25]							
Engine											
74-20-00-206	No. 2 Engine - Ignition - Ignition (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458			0	
			MOS		56.6		10 Feb 2020				
	(742050)			[HRS: +25/-25]							
Engine											
74-20-00-701	No. 1 Engine - Ignition - Igniters Operational Check: Do an Operational Test		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
	(742040)			[HRS: +25/-25]							
Engine	057159										
74-20-00-701	No. 2 Engine - Ignition - Igniters Operational Check: Do an Operational Test		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
	(742040)			[HRS: +25/-25]							
Engine	057159										
74-20-00-901	No. 1 Engine - Ignition - Ignition (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
	(742060)			[HRS: +25/-25]							
Engine											
74-20-00-901	No. 2 Engine - Ignition - Ignition (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458			0	
			MOS		56.6		10 Feb 2020				
	(742060)			[HRS: +25/-25]							
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
742001 (742001OTBD) Engine	No. 1 Engine - Outboard Igniter		HRS		216.6			5844.3			0
	30J2825-01 NNA23270062		ENC		140			4000			0
			MOS		11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								
742001 (742001INBD) Engine	No. 1 Engine - Inboard Igniter		HRS		216.6			5844.3			0
	30J2825-01 NNA23270098		ENC		140			4000			0
			MOS	TSN:1	11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								
742001 (742001OTBD) Engine	No. 2 Engine - Outboard Igniter		HRS		216.6			5844.3			0
	30J2825-01 NNA23270085		ENC		140			4000			0
			MOS	TSN:1	11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								
742001 (742001INBD) Engine	No. 2 Engine - Inboard Igniter		HRS		216.6			5844.3			0
	30J2825-01 NNA23270071		ENC		140			4000			0
			MOS		11.8			05 Nov 2023			
			MSC				O/C				
			[End Of Month Item]								
742002 Engine	No. 1 Engine - Short Igniter Lead		HRS		1706.1			4354.8			0
	30J3125-01 NNA12030021		ENC		1345			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				O/C				
			[End Of Month Item]								
742002 Engine	No. 2 Engine - Short Igniter Lead		HRS		1706.1			4354.8			0
	30J3125-01 NNA12030019		ENC		1345			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				O/C				
			[End Of Month Item]								
742003 Engine	No. 1 Engine - Long Igniter Lead		HRS		1706.1			4354.8			0
	30J3125-02 NNA12100041		ENC		1345			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				O/C				
			[End Of Month Item]								
742003 Engine	No. 2 Engine - Long Igniter Lead		HRS		1706.1			4354.8			0
	30J3125-02 NNA12100036		ENC		1345			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				O/C				
			[End Of Month Item]								
75 - AIR											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
750100	No. 1 Engine - Overhaul or Refurbish Anti-Icing Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			[HRS: +100]								
Engine											
750100	No. 2 Engine - Overhaul or Refurbish Anti-Icing Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			[HRS: +100]								
Engine											
75-10-00-201	No. 1 Engine - AIR System - Anti-Ice Valve and P3 Anti-Ice Tube (Leak Check) General Visual Inspection: Do A Check for Leakage AT P3 AIR Supply to Bleed Valve, Anti-Ice Valve, Anti-Ice AIR Tube and Fcu.		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(751010)											
Engine											
	057159										
75-10-00-201	No. 2 Engine - AIR System - Anti-Ice Valve and P3 Anti-Ice Tube (Leak Check) General Visual Inspection: Do A Check for Leakage AT P3 AIR Supply to Bleed Valve, Anti-Ice Valve, Anti-Ice AIR Tube and Fcu.		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(751010)											
Engine											
	057159										
75-10-00-203	No. 1 Engine - Replace Intercompressor Bleed Valve Servo Valve		HRS		1644.3			4416.6			0
			ENC		1264			2876			0
			MOS		132.4			17 Oct 2013			
			MSC				-				
(751030)											
Engine											
	[End Of Month Item]										
75-10-00-203	No. 1 Engine - AIR System - Do A Borescope Inspection of the Combustion Liner and Hp Turbine Vane Ring		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(751080)											
Engine											
	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
75-10-00-203	No. 1 Engine - AIR System - Bleed Off Valve General Visual Inspection: Examine the Torque Motor Electrical Connection for Security, Fraying and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(751070)			[HRS: +25/-25]								
Engine			057159								
75-10-00-203	No. 2 Engine - AIR System - Bleed Off Valve General Visual Inspection: Examine the Torque Motor Electrical Connection for Security, Fraying and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(751070)			[HRS: +25/-25]								
Engine			057159								
75-10-00-203	No. 2 Engine - Replace Intercompressor Bleed Valve Servo Valve		HRS		1644.3			4416.6			0
			ENC		1264			2876			0
			MOS		132.4			17 Oct 2013			
(751030)			MSC								
Engine			[End Of Month Item]								
75-10-00-203	No. 2 Engine - AIR System - Do A Borescope Inspection of the Combustion Liner and Hp Turbine Vane Ring		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
(751080)			[HRS: +25/-25]								
Engine			057159								
75-10-00-204	No. 1 Engine - AIR System - AIR System (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
(751040)			[HRS: +25/-25]								
Engine											
75-10-00-204	No. 2 Engine - AIR System - AIR System (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
(751040)			[HRS: +25/-25]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
75-10-00-901	No. 1 Engine - AIR System - AIR System (Engine TBO)		HRS		975.6		5000	5085.3	10085.3	10110.3	0
	Restoration		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			[HRS: +25/-25]								
(751060)											
Engine											
75-10-00-901	No. 2 Engine - AIR System - AIR System (Engine TBO)		HRS		975.6		5000	5085.3	10085.3	10110.3	0
	Restoration		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			[HRS: +25/-25]								
(751060)											
Engine											
751003	No. 1 Engine - Compressor Bleed Valve Assy		HRS		975.6			5085.3			0
	30J2207-01	41A437	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
Engine	[End Of Month Item]										
751003	No. 2 Engine - Compressor Bleed Valve Assy		HRS		975.6			5085.3			0
	30J2207-01	47A535	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				O/C				
Engine	[End Of Month Item]										
751004	No. 1 Engine - Intercompressor Bleed Valve Servo Valve		HRS		1644.3			4416.6			0
	30J3490-01	TR6722	ENC		1264			2876			0
			MOS		132.4			17 Oct 2013			
			MSC				O/C				
Engine	[End Of Month Item]										
751004	No. 2 Engine - Intercompressor Bleed Valve Servo Valve		HRS		1644.3			4416.6			0
	30J3490-01	TR6759	ENC		1264			2876			0
			MOS		132.4			17 Oct 2013			
			MSC				O/C				
Engine	[End Of Month Item]										
751005	No. 1 Engine - Linear Transducer		HRS		975.6			5085.3			0
	GM9424	1651	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
Engine	[End Of Month Item]										
751005	No. 2 Engine - Linear Transducer		HRS		975.6			5085.3			0
	GM9424	1675	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				O/C				
Engine	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
751050	No. 1 Engine - Inspect Linear Variable Differential Transformer		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
Engine											
751050	No. 2 Engine - Inspect Linear Variable Differential Transformer		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
Engine											
753000	No. 1 Engine - Replace Bov Torque Motor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
Engine											
753000	No. 2 Engine - Replace Bov Torque Motor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
Engine											
753001	No. 1 Engine - Inspect P3 AIR Inertial Separator		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
Engine											
753001	No. 2 Engine - Inspect P3 AIR Inertial Separator		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
Engine											
753005	No. 1 Engine - Inspect Compressor AIR Bleed Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			[HRS: +100]								
Engine											
753005	No. 2 Engine - Inspect Compressor AIR Bleed Valve		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			[HRS: +100]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
76 - Engine Controls											
76-10-00-7201	Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 Thru-6000, and Airplanes -5001 Thru - 5196 Incorporating SB560XL-76-03)		HRS		34		300	6026.9	6326.9	6351.9	0
			AFL		20		4145		0		
			MOS		.4		17 Oct 2024				
			[HRS: +25/-25]								
Airframe	5-12-19										
761001	No. 1 Engine - Electronic Engine Control 817962-8-012 02031093		HRS		975.6			5085.3			0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			MSC			O/C					
Engine	[End Of Month Item]										
761001	No. 2 Engine - Electronic Engine Control 817962-8-012 02025343		HRS		975.6			5085.3			0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			MSC			O/C					
Engine	[End Of Month Item]										
761001 (761001L)	Left Throttle Detent Valve 5303-2A 2139		HRS		6060.9			0			0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe	[End Of Month Item]										
761001 (761001R)	Right Throttle Detent Valve 5303-2A 2250		HRS		6060.9			0			0
			AFL		4165		0		0		
			MOS		265.3		20 Sep 2002				
			MSC			O/C					
Airframe	[End Of Month Item]										
77 - Engine Indicating											
77-10-00-201	No. 1 Engine - Engine Indicating (N1, N2, and Itt) - Engine Wiring Harness General Visual Inspection: Do A Check for Security of All Clamps and Brackets, Cables for Signs of Wear, Fraying, Chafing and Cracks Do A Check for Security of All Wiring Harness Connectors. Examine the Outer Surfaces for Cracks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
(771020)											
Engine	057159										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
77-10-00-201	No. 2 Engine - Engine Indicating (N1, N2, and Itt) - Engine Wiring Harness General Visual Inspection: Do A Check for Security of All Clamps and Brackets, Cables for Signs of Wear, Fraying, Chafing and Cracks Do A Check for Security of All Wiring Harness Connectors. Examine the Outer Surfaces for Cracks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
(771020)											
Engine			057159								
77-10-00-202	No. 1 Engine - Engine Indicating (N1, N2, and Itt) - Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
			[HRS: +25/-25]								
(771000)											
Engine											
77-10-00-202	No. 2 Engine - Engine Indicating (N1, N2, and Itt) - Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682		3458			0	
			MOS		56.6		10 Feb 2020				
			[HRS: +25/-25]								
(771000)											
Engine											
77-10-00-901	No. 1 Engine - Engine Indicating (N1, N2, and Itt) - Engine Wiring Harness (Cleaning) Restoration: Disconnect Each Wiring Harness Connector, Clean, Inspect and Connect Again. Do the Necessary Engine Checks after the Replacement of WiringHarness		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
Engine											
			057159								
77-10-00-901	No. 2 Engine - Engine Indicating (N1, N2, and Itt) - Engine Wiring Harness (Cleaning) Restoration: Disconnect Each Wiring Harness Connector, Clean, Inspect and Connect Again. Do the Necessary Engine Checks after the Replacement of WiringHarness		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
Engine											
			057159								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
77-10-00-902	No. 1 Engine - Engine Indicating (N1, N2, and Itt) - Engine Indicating Speed Sensor System (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
	(771010)			[HRS: +25/-25]							
Engine											
77-10-00-902	No. 2 Engine - Engine Indicating (N1, N2, and Itt) - Engine Indicating Speed Sensor System (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
	(771010)			[HRS: +25/-25]							
Engine											
771004	No. 1 Engine - Speed N1 Sensor 31J2072-01CH881		HRS		975.6			5085.3			0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
	Engine			MSC				O/C			
			[End Of Month Item]								
771004	No. 2 Engine - Speed N1 Sensor 31J2072-01CH907		HRS		6060.9			0			0
			ENC		4140		0		0		
			MOS		265.3		20 Sep 2002				
	Engine			MSC				O/C			
			[End Of Month Item]								
771005	No. 1 Engine - Speed N2 Sensor 31J2073-01CH1776		HRS		6060.9			0			0
			ENC		4140		0		0		
			MOS		265.3		20 Sep 2002				
	Engine			MSC				O/C			
			[End Of Month Item]								
771005	No. 2 Engine - Speed N2 Sensor 31J2073-01CH1766		HRS		6060.9			0			0
			ENC		4140		0		0		
			MOS		265.3		20 Sep 2002				
	Engine			MSC				O/C			
			[End Of Month Item]								
771006	Engine (Amlcd) Indicator 10644D02M0503010285AB		HRS		119.2			5941.7			0
			AFL		77		4088		0		
			MOS		5.9		03 May 2024				
	Airframe			MSC				O/C			
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
771014	No. 1 Engine - Inspect N1 Speed Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	31J2072-01 CH881		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
771014	No. 2 Engine - Inspect N1 Speed Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	31J2072-01 CH907		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
771015	No. 1 Engine - Inspect N2 Speed Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	31J2073-01 CH1776		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
771015	No. 2 Engine - Inspect N2 Speed Sensor		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	31J2073-01 CH1766		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
772001	No. 1 Engine - Temperature Sensor		HRS		975.6			5085.3			0
	31J2113-03 RTK9855		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		MSC				O/C				
		[End Of Month Item]									
772001	No. 2 Engine - Temperature Sensor		HRS		975.6			5085.3			0
	31J2113-03 RTJ2139		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		MSC				O/C				
		[End Of Month Item]									
77-20-02	No. 1 Engine - Inspect and Functional Check T6 Harness		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	and Thermocouples		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	(772002)		[HRS: +100]								
Engine											
77-20-02	No. 2 Engine - Inspect and Functional Check T6 Harness		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	and Thermocouples		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	(772002)		[HRS: +100]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
772010	No. 1 Engine - Inspect and Functional Check T1 Harness		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			Engine	[HRS: +100]							
772010	No. 2 Engine - Inspect and Functional Check T1 Harness		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			Engine	[HRS: +100]							
774001	No. 1 Engine - Data Collection Unit 32205-01DP02-1939		HRS		975.6			5085.3			0
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			MSC			O/C					
			Engine	[End Of Month Item]							
774001	No. 2 Engine - Data Collection Unit 32205-01DP02-1955		HRS		975.6			5085.3			0
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			MSC			O/C					
			Engine	[End Of Month Item]							
774040	No. 1 Engine - Data Collection Unit - Download Data 32205-01DP02-1939		HRS		196.9		5000	5864	10864	10964	0
			ENC		136		4004		0		
			MOS		10.3		20 Dec 2023				
			Engine	[HRS: +100]							
774040	No. 2 Engine - Data Collection Unit - Download Data 32205-01DP02-1955		HRS		196.9		5000	5864	10864	10964	0
			ENC		136		4004		0		
			MOS		10.3		20 Dec 2023				
			Engine	[HRS: +100]							
78 - Exhaust											
78-10-00-201	No. 1 Engine - Engine Exhaust - Exhaust and Mixer: Gvi Obvious Signs of Damage or Loose Debris		HRS		6060.9			0			0
			ENC		4140		0		0		
			MOS		265.3		20 Sep 2002				
			(781000)			MSC			BF/F		
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
78-10-00-201	No. 1 Engine - Engine Exhaust - Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(781010)			MOS		56.7			08 Feb 2020			
Engine			[HRS: +25/-25]								
78-10-00-201	No. 2 Engine - Engine Exhaust - Exhaust and Mixer: Gvi Obvious Signs of Damage or Loose Debris		HRS		6060.9			0			0
			ENC		4140			0			0
(781000)			MOS		265.3			20 Sep 2002			
Engine			MSC				BF/F				
78-10-00-201	No. 2 Engine - Engine Exhaust - Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection		HRS		975.6		2500	5085.3	7585.3	7610.3	0
			ENC		682			3458			0
(781010)			MOS		56.6			10 Feb 2020			
Engine			[HRS: +25/-25]								
78-10-00-202	No. 1 Engine - Engine Exhaust - Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an Inspection Through Hole In the Exhaust Cone for Security of Control Lever, Signs of Oil Leaks or Carbon AT No.5 Bearing AREA, Examine the Cable and Linkages		HRS		975.6		1600	5085.3	6685.3	6710.3	0
			ENC								0
(781030)			MOS		56.7			08 Feb 2020			
Engine			[HRS: +25/-25]								
78-10-00-202	No. 2 Engine - Engine Exhaust - Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an Inspection Through Hole In the Exhaust Cone for Security of Control Lever, Signs of Oil Leaks or Carbon AT No.5 Bearing AREA, Examine the Cable and Linkages		HRS		975.6		1600	5085.3	6685.3	6710.3	0
			ENC								0
(781030)			MOS		56.6			10 Feb 2020			
Engine			[HRS: +25/-25]								
78-10-00-901	No. 1 Engine - Engine Exhaust - Turbine Exhaust Case and Mixer (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
(781020)			MOS		56.7			08 Feb 2020			
Engine			[HRS: +25/-25]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
78-10-00-901	No. 2 Engine - Engine Exhaust - Turbine Exhaust Case and Mixer (Engine TBO) Restoration		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			[HRS: +25/-25]								
(781020)											
Engine											
783001	Right Engine Thrust Reverser Assembly 64ND-78002-4		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783001R)	[End Of Month Item]										
783001	Left Engine Thrust Reverser Assembly 64ND-78002-3		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783001L)	[End Of Month Item]										
783002	Right Thrust Reverser Valve 65680		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783002R)	[End Of Month Item]										
783002	Left Thrust Reverser Valve 65680		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783002L)	[End Of Month Item]										
783010	Right Outboard Thrust Reverser Actuator 2564000-7		HRS		2580.9			3480			0
			AFL		2001			2164		0	
			MOS		190.5			14 Dec 2008			
			MSC				O/C				
(783010RO)	[End Of Month Item]										
783010	Left Outboard Thrust Reverser Actuator 64ND-78204-5		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783010LO)	[End Of Month Item]										
783010	Left Inboard Thrust Reverser Actuator 64ND-78204-5		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
(783010LI)	[End Of Month Item]										
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783010 (783010RI) Airframe	Right Inboard Thrust Reverser Actuator		HRS		6060.9			0			0
	64ND-78204-5	SN-UNKNOWN	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
78-31-00-2200 Airframe	Thrust Reverser Assembly Detailed Inspection		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
5-12-07											
78-31-00-7200 Airframe	Thrust Reverser Assembly Functional Check		HRS		6060.9		1600	0	6349.5	6374.5	0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			[HRS: +25/-25]								
5-12-07											
783101 (783101L) Airframe	Left ARM Pressure Switch		HRS		6060.9			0			0
	6607A7-45	B042589	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783101 (783101R) Airframe	Right ARM Pressure Switch		HRS		6060.9			0			0
	6607A7-45	B042526	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783102 (783102L) Airframe	Left Thrust Reverser Isolation Valve		HRS		6060.9			0			0
	13027-4	4582	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783102 (783102R) Airframe	Right Thrust Reverser Isolation Valve		HRS		6060.9			0			0
	13027-4	4679	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783103 (783103RI) Airframe	Right Inboard Stow Limit Switch		HRS		5985.9			75			0
	53ND78304-1	SN-UNKNOWN	AFL		4116			49			0
			MOS		263.1			27 Nov 2002			
			MSC				O/C				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
783103 (783103RO) Airframe	Right Outboard Stow Limit Switch 53ND78304-1		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783103 (783103LO) Airframe	Left Outboard Stow Limit Switch 53ND78304-1		HRS		6060.9			0			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
			[End Of Month Item]								
783103 (783103LI) Airframe	Left Inboard Stow Limit Switch 53ND78304-1		HRS		5985.9			75			0
			AFL		4116			49			0
			MOS		263.1			27 Nov 2002			
			MSC				O/C				
			[End Of Month Item]								
783104 (783104R) Airframe	Right Deploy Limit Switch 53ND78304-5		HRS		5985.9			75			0
			AFL		4116			49			0
			MOS		263.1			27 Nov 2002			
			MSC				O/C				
			[End Of Month Item]								
783104 (783104L) Airframe	Left Deploy Limit Switch 53ND78304-5		HRS		5985.9			75			0
			AFL		4116			49			0
			MOS		263.1			27 Nov 2002			
			MSC				O/C				
			[End Of Month Item]								
79 - Oil											
790010 Engine	No. 1 Engine - Oil Filter Element 31J1700-01		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
			[End Of Month Item]								
790010 Engine	No. 2 Engine - Oil Filter Element 31J1700-01		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				O/C				
			[End Of Month Item]								
790020 Engine	No. 1 Engine - Change Oil		HRS		1896.4			4164.5			0
			ENC		1494			2646			0
			MOS		160.7			07 Jun 2011			
			MSC				A/R				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
790020	No. 2 Engine - Change Oil		HRS		1896.4			4164.5			0
			ENC		1494			2646		0	
			MOS		160.7			07 Jun 2011			
			MSC			A/R					
Engine		[End Of Month Item]									
79-10-00-201	No. 1 Engine - Oil System - External Oil Tube General Visual Inspection: Examine for Signs of Wear, Chafing, Cracks, Leaks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(791050)											
Engine		057159									
79-10-00-201	No. 2 Engine - Oil System - External Oil Tube General Visual Inspection: Examine for Signs of Wear, Chafing, Cracks, Leaks and Corrosion		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(791050)											
Engine		057159									
79-10-00-202	No. 1 Engine - Oil System - Fuel Oil Heat Exchanger General Visual Inspection: Do an Inspection for Security, Leakage and General Condition. No Leakage Permitted		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(791080)											
Engine		057159									
79-10-00-202	No. 2 Engine - Oil System - Fuel Oil Heat Exchanger General Visual Inspection: Do an Inspection for Security, Leakage and General Condition. No Leakage Permitted		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(791080)											
Engine		057159									
79-10-00-203	No. 1 Engine - Oil System - Accessory Gear Box PAD Seal General Visual Inspection: Examine the PAD Seals for Oil Leaks		HRS		216.6		800	5844.3	0		0
			ENC		140			4000	0		0
			MOS		11.8			05 Nov 2023			
			[HRS: +25/-25]								
(791040)											
Engine		057159									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
79-10-00-203	No. 2 Engine - Oil System - Accessory Gear Box PAD		HRS		216.6		800	5844.3	0		0
	Seal General Visual Inspection: Examine the PAD Seals		ENC		140			4000	0		0
	for Oil Leaks		MOS		11.8			05 Nov 2023			
(791040)	[HRS: +25/-25]										
Engine	057159										
79-10-00-204	No. 1 Engine - Oil System - External Engine General		HRS		216.6		800	5844.3	0		0
	Visual Inspection: Examine for Fuel and Oil Leaks,		ENC		140			4000	0		0
	Corrosion, Cracks and Signs of Damage		MOS		11.8			05 Nov 2023			
(791060)	[HRS: +25/-25]										
Engine	057159										
79-10-00-204	No. 2 Engine - Oil System - External Engine General		HRS		216.6		800	5844.3	0		0
	Visual Inspection: Examine for Fuel and Oil Leaks,		ENC		140			4000	0		0
	Corrosion, Cracks and Signs of Damage		MOS		11.8			05 Nov 2023			
(791060)	[HRS: +25/-25]										
Engine	057159										
79-10-00-205	No. 1 Engine - Oil System - Oil Filter Detailed Inspection:		HRS		216.6		800	5844.3	0		0
	Remove and Do A Check for Foreign Material and		ENC		140			4000	0		0
	Damage		MOS		11.8			05 Nov 2023			
(791010)	[HRS: +25/-25]										
Engine	057159										
79-10-00-205	No. 2 Engine - Oil System - Oil Filter Detailed Inspection:		HRS		216.6		800	5844.3	0		0
	Remove and Do A Check for Foreign Material and		ENC		140			4000	0		0
	Damage		MOS		11.8			05 Nov 2023			
(791010)	[HRS: +25/-25]										
Engine	057159										
79-10-00-206	No. 1 Engine - Oil System - Oil Special Detailed		HRS		6060.9			0			0
	Inspection: Do A Check for Oil Level With the Outboard		ENC		4140			0			0
	Sight Glass		MOS		265.3			20 Sep 2002			
(791000)			MSC				BF/F				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
79-10-00-206	No. 1 Engine - Oil System - Oil Special Detailed		HRS		216.6		800	5844.3	0		0
	Inspection: Do A Check for Oil Level With the Outboard		ENC		140			4000	0		0
	Sight Glass. Monitor the Oil Quality on Condition and Do		MOS		11.8			05 Nov 2023			
	Analysis Periodically as Observations Warrant.		[HRS: +25/-25]								
(790030)											
Engine											
057159											
79-10-00-206	No. 2 Engine - Oil System - Oil Special Detailed		HRS		216.6		800	5844.3	0		0
	Inspection: Do A Check for Oil Level With the Outboard		ENC		140			4000	0		0
	Sight Glass. Monitor the Oil Quality on Condition and Do		MOS		11.8			05 Nov 2023			
	Analysis Periodically as Observations Warrant.		[HRS: +25/-25]								
(790030)											
Engine											
057159											
79-10-00-206	No. 2 Engine - Oil System - Oil Special Detailed		HRS		6060.9			0			0
	Inspection: Do A Check for Oil Level With the Outboard		ENC		4140			0			0
	Sight Glass		MOS		265.3			20 Sep 2002			
			MSC				BF/F				
(791000)											
Engine											
79-10-00-207	No. 1 Engine - Oil System - Oil Filter Bypass Valve		HRS				2500		7585.3	7610.3	0
	Functional Check		ENC								0
			DATE								
			[End Of Month Item] [HRS: +25/-25]								
Engine											
79-10-00-207	No. 1 Engine - Oil System - Impending Bypass Valve		HRS		975.6			5085.3			0
	Indicator General Visual Inspection: Do A Check of Aircraft		ENC								0
	Cockpit Indicator Lamp		MOS		56.7			08 Feb 2020			
			MSC				N/A				
(791020)											
Engine											
79-10-00-207	No. 2 Engine - Oil System - Oil Filter Bypass Valve		HRS				2500		7585.3	7610.3	0
	Functional Check		ENC								0
			DATE								
			[End Of Month Item] [HRS: +25/-25]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
79-10-00-207 (791020) Engine	No. 2 Engine - Oil System - Impending Bypass Valve Indicator General Visual Inspection: Do A Check of Aircraft Cockpit Indicator Lamp		HRS		975.6			5085.3			0
			ENC						0		
			MOS		56.6		10 Feb 2020				
			MSC			N/A					
79-10-00-208 ^U (791030) Engine	No. 1 Engine - Oil System - Magnetic Chip Detector General Visual Inspection: Remove and Do A Check for Metallic Debris		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
79-10-00-208 ^U (791030) Engine	No. 2 Engine - Oil System - Magnetic Chip Detector General Visual Inspection: Remove and Do A Check for Metallic Debris		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
79-10-00-208/209 (793001) Engine	No. 1 Engine - Oil System - Magnetic Chip Detector/Collector General Visual Inspection: Remove and Do A Check for Metallic Debris		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
79-10-00-208/209 (793001) Engine	No. 2 Engine - Oil System - Magnetic Chip Detector/Collector General Visual Inspection: Remove and Do A Check for Metallic Debris		HRS		216.6		800	5844.3	0		0
			ENC		140		4000	0		0	
			MOS		11.8		05 Nov 2023				
			[HRS: +25/-25]								
79-10-00-901 (720010) Engine	No. 1 Engine - Engine Overhaul		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682		3458			0	
			MOS		56.7		08 Feb 2020				
			[End Of Month Item] [HRS: +25/-25]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
79-10-00-901 (720010) Engine	No. 2 Engine - Engine Overhaul		HRS		975.6		5000	5085.3	10085.3	10110.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	[End Of Month Item] [HRS: +25/-25]										
79-10-00-902 (790040) Engine	No. 1 Engine - Install New Oil Filter Element		HRS		975.6		1200	5085.3	6285.3	6310.3	0
	31J1700-01	SN-UNKNOWN	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	[End Of Month Item] [HRS: +25/-25]										
79-10-00-902 (790040) Engine	No. 2 Engine - Install New Oil Filter Element		HRS		975.6		1200	5085.3	6285.3	6310.3	0
	31J1700-01	SN-UNKNOWN	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	[End Of Month Item] [HRS: +25/-25]										
792010 Engine	No. 1 Engine - Inspect and Functional Test Oil Filter		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	Differential Pressure Switch		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	[HRS: +100]										
792010 Engine	No. 2 Engine - Inspect and Functional Test Oil Filter		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	Differential Pressure Switch		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	[HRS: +100]										
793002 (793002R) Airframe	Right Oil Temp Xmtr Sensor		HRS		6060.9			0			0
	102-00083	3757	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
793002 (793002L) Airframe	Left Oil Temp Xmtr Sensor		HRS		6060.9			0			0
	102-00083	3806	AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				O/C				
[End Of Month Item]											
793003 Engine	No. 1 Engine - Fuel Oil Heat Exchanger		HRS		975.6			5085.3			0
	D2552-600B	08287537	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				O/C				
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793003	No. 2 Engine - Fuel Oil Heat Exchanger		HRS		975.6			5085.3			0
	D2552-600B	M49535	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		MSC				O/C				
			[End Of Month Item]								
793005	No. 1 Engine - Overhaul or Refurbish Oil Tank Filler CAP		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
793005	No. 2 Engine - Overhaul or Refurbish Oil Tank Filler CAP		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
793010	No. 1 Engine - Overhaul/Refurbish Fuel to Oil Heat Exchanger		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	D2552-600B	08287537	ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
793010	No. 2 Engine - Overhaul/Refurbish Fuel to Oil Heat Exchanger		HRS		975.6		5000	5085.3	10085.3	10185.3	0
	D2552-600B	M49535	ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
793021	No. 1 Engine - Inspect Oil Level Indicator (Sight Glass)		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
	Engine		[HRS: +100]								
793021	No. 2 Engine - Inspect Oil Level Indicator (Sight Glass)		HRS		975.6		5000	5085.3	10085.3	10185.3	0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
	Engine		[HRS: +100]								
793102 (793102R)	Right Engine Oil Transmitter		HRS		1614.7			4446.2			0
	APTE-237C-1000-250D	8021-8-754	AFL		1271			2894			0
			MOS		131.3			20 Nov 2013			
	Airframe		MSC				O/C				
		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793102 (793102L) Airframe	Left Engine Oil Transmitter		HRS		2185.9			3875			0
	APTE-237C-1000-250D		AFL								0
	66719370		MOS		178.7			08 Dec 2009			
			MSC				O/C				
				[End Of Month Item]							
793117 (793117R) Airframe	Right Oil Pressure Switch		HRS		6060.9			0			0
	1153P0098-01		AFL		4165			0			0
	583		MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
793117 (793117L) Airframe	Left Oil Pressure Switch		HRS		6060.9			0			0
	1153P0098-01		AFL		4165			0			0
	805		MOS		265.3			20 Sep 2002			
			MSC				O/C				
				[End Of Month Item]							
80 - Starting											
80-10-00-9600 (801000) Airframe	Right Engine Starter - Generator (Section Ii Overhaul)		HRS		69.6		1000	5991.3	6991.3		0
	Restoration		AFL		42			4123			0
	300SGL138Q-4		MOS		3.6			10 Jul 2024			
			[End Of Month Item]								
	Notes: AMM Allows +25 grace										
80-10-00-9600 (801000) Airframe	Left Engine Starter - Generator (Section Ii Overhaul)		HRS		69.6		1000	5991.3	6991.3		0
	Restoration		AFL		42			4123			0
	300SGL138Q-4		MOS		3.6			10 Jul 2024			
			[End Of Month Item]								
	Notes: AMM Allows +25 grace										
80-11-00-2200 (A801103) Airframe	Auxiliary Power Unit Starter - Generator Detailed		HRS		304.8			5756.1			0
	Inspection		AFL		193			3972			0
	300SGL138Q-6		MOS		16.1			26 Jun 2023			
	5319XL		APH		158.4		500	1800.9	2300.9	2325.9	
				[End Of Month Item] [APH: +25/-25]							

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
80-11-00-9600	Auxiliary Power Unit Starter -Generator (Section II Overhaul) Restoration		HRS		304.8			5756.1			0
			AFL		193			3972		0	
		300SGL138Q-6	5319XL	MOS		16.1			26 Jun 2023		
	(801100)			APH	TSN:237.3	158.4		1000	1800.9	2563.6	2588.6
Airframe			[End Of Month Item] [APH: +25/-25]								
AD - Airworthiness Directives											
FAA 1974-08-09 R02	Lavatory Paper or Linen Waste Receptacle FIRE Prevention (Mandatory)		HRS		2074.9			3986			0
			AFL		1680			2485		0	
	(FAA 1974-08-09 R2)			MOS		175.8			05 Mar 2010		
				MSC				-			
Airframe			[End Of Month Item]								
FAA 1974-08-09 R03	Lavatory Paper or Linen Waste Receptacle FIRE Prevention (Mandatory)		HRS		216.6		1000	5844.3	6844.3		0
			AFL		140			4025		0	
	(1974-08-09 R03)			MOS		11.8			05 Nov 2023		
	Airframe			[End Of Month Item]							
FAA 1995-22-01	Appliance AD - Aerospace Lighting Power Unit (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0		0	
	(95-22-01)			MOS		265.3			20 Sep 2002		
				MSC				A/R			
Airframe			[End Of Month Item]								
FAA 1997-05-03 R01	Appliance AD - Gnx-XIs and Gns-XI GPS (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0		0	
	(FAA 1997-05-03 R1)			MOS		265.3			20 Sep 2002		
				MSC				A/R			
Airframe			[End Of Month Item]								
FAA 1998-25-10	Appliance AD - Aircraft Belt Inspection (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0		0	
	(98-25-10)			MOS		265.3			20 Sep 2002		
				MSC				A/R			
Airframe			[End Of Month Item]								
FAA 1999-23-22	Appliance AD - Transport Category MODE C Xpd (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0		0	
	(1999-23-22)			MOS		265.3			20 Sep 2002		
				MSC				A/R			
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 1999-23-22 R01 (1999-23-22 R01) Airframe	Appliance AD - Transport Category MODE C Xpd (Mandatory)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
FAA 1999-23-22 R02 (1999-23-22 R02) Airframe	Appliance AD - Transport Category MODE C Xpd (Mandatory)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
FAA 2000-15-51 (2000-15-51) Airframe	Aileron Cable Fairlead Tube and Aileron Cable Sector (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				-				
			[End Of Month Item]								
FAA 2001-23-17 (2001-23-17) Airframe	Garmin International Gns 430 (Mandatory)		HRS		6045.9			15			0
			AFL		4165			0			0
			MOS		265.3			20 Sep 2002			
			MSC				A/R				
			[End Of Month Item]								
FAA 2003-03-21 (2003-03-21) Engine	No. 1 Engine - Engine Fuel and Control - One-Time Visual Inspection and RE-Marking, or In Lieu of Inspection, Replacement of Certain Part Numbers (P/N'S) of the Flexible Fuel Tube Located Between the Fuel/Oil Heat Exchanger and the Integral Fuel Control Unit-Fuel Pump		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
FAA 2003-03-21 (2003-03-21) Engine	No. 2 Engine - Engine Fuel and Control - One-Time Visual Inspection and RE-Marking, or In Lieu of Inspection, Replacement of Certain Part Numbers (P/N'S) of the Flexible Fuel Tube Located Between the Fuel/Oil Heat Exchanger and the Integral Fuel Control Unit-Fuel Pump		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
FAA 2003-04-06	Appliance AD - Honeywell Primus Rnz-850/851 NM (Superseded)		HRS		5447.9			613			0	
			AFL								0	
			MOS		247.2			25 Mar 2004				
			MSC				A/R					
(2003-04-06)			[End Of Month Item]									
Airframe												
FAA 2006-04-10	Installing Identification Sleeves on the Wires for the Positive and Negative Studs of the Engine and/ or (APU) FIRE Extinguishing Bottles, as Applicable, and Reconnecting the Wires to the Correct Terminal Studs. (Mandatory)		HRS		3482.9			2578			0	
			AFL									0
			MOS		206.9			02 Aug 2007				
			MSC				A/R					
(2006-04-10)			[End Of Month Item]									
Airframe												
FAA 2006-16-18	Appliance AD - Sandel Avi MOD ST3400 TAWS/RM (Mandatory)		HRS		3962.9			2098			0	
			AFL									0
			MOS		216.5			15 Oct 2006				
			MSC				A/R					
(2006-16-18)			[End Of Month Item]									
Airframe												
FAA 2006-19-04	Appliance AD - Honeywell Rcz Comm & Xpdrs (Mandatory)		HRS		3962.9			2098			0	
			AFL									0
			MOS		216.5			15 Oct 2006				
			MSC				A/R					
(2006-19-04)			[End Of Month Item]									
Airframe												
FAA 2006-22-05	Appliance AD - Honeywell Primus Rnz-850/851 NM (Mandatory)		HRS		3266.9			2794			0	
			AFL									0
			MOS		202.8			04 Dec 2007				
			MSC				A/R					
(2006-22-05)			[End Of Month Item]									
Airframe												
FAA 2007-11-17	FIRE Protection - Installation of Identification Sleeves on the Wires for the Positive and Negative Terminal Studs of the Applicable FIRE Extinguishing Bottles (Mandatory)		HRS		3482.9			2578			0	
			AFL									0
			MOS		206.9			02 Aug 2007				
			MSC				A/R					
(2007-11-17)			[End Of Month Item]									
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2010-07-02	Perform A One-Time General Visual Inspection of the Modification Plate for the Honeywell Primus II Nv-850 Navigation Receiver Module (Nrm) (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			MOS		136.8			05 Jun 2013			
			MSC				A/R				
(2010-07-02)			[End Of Month Item]								
Airframe											
FAA 2010-18-09	No. 1 Engine - Intercompressor Bleed Valve/Servo Valve (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(2010-18-09)			[End Of Month Item]								
Engine											
FAA 2010-18-09	No. 2 Engine - Intercompressor Bleed Valve/Servo Valve (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(2010-18-09)			[End Of Month Item]								
Engine											
FAA 2010-18-09 PARA (E)(2)	No. 1 Engine - Accomplish Intercompressor Bleed Valve/Servo Valve Remove (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(2010-18-09 PARA (E) (2))			[End Of Month Item]								
Engine											
FAA 2010-18-09 PARA (E)(2)	No. 2 Engine - Accomplish Intercompressor Bleed Valve/Servo Valve Remove (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(2010-18-09 PARA (E) (2))			[End Of Month Item]								
Engine											
FAA 2010-18-09 PARA (E)(3)	No. 1 Engine - Accomplish Intercompressor Bleed Valve/Servo Valve Engine Testing (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(2010-18-09 PARA (E) (3))			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2010-18-09 PARA (E)(3) (2010-18-09 PARA (E) (3)) Engine	No. 2 Engine - Accomplish Intercompressor Bleed		HRS		975.6			5085.3			0
	Valve/Servo Valve Engine Testing (Mandatory)		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
FAA 2012-02-08 (2012-02-08) Airframe	Appliance AD - Aviation Communication and Surveillance		HRS		1644.3			4416.6			0
	Systems (Acss) TrafficAlert and Collision Avoidance		AFL		1289			2876			0
	System (TCAS) Units (Mandatory)		MOS		132.5			16 Oct 2013			
			MSC				-				
			[End Of Month Item]								
FAA 2012-06-01 (2012-06-01) Airframe	Modify the Drain Installation of the Tailcone Stinger on the		HRS		1706.1			4354.8			0
	Aft Canted Bulkhead (Mandatory)		AFL		1370			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				-				
			[End Of Month Item]								
FAA 2012-09-01 (2012-09-01) Airframe	Landing Gear - Torque Lug - Inspection (Mandatory)		HRS		1706.1			4354.8			0
			AFL		1370			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				-				
			[End Of Month Item]								
FAA 2012-26-15 (2012-26-15) Airframe	Appliance AD - Identify Out of Spec AIR Data Computers		HRS		1672.9			4388			0
	(ADC), Airdata Modules (ADM), AIR Data Attitude		AFL		1347			2818			0
	Heading Reference Systems (Adahrs) and Digital AIR		MOS		141.2			24 Jan 2013			
	Data Computers (Dadc) (Rescinded By FAA 2012-26-15		MSC				-				
	R01) (Mandatory)		[End Of Month Item]								
FAA 2012-26-15 PARA (G)(1) (FAA 2012-26-15 PARA (G)(1)) Airframe	Remove Identify Out of Spec AIR Data Computers (ADC),		HRS		1672.9			4388			0
	Airdata Modules (ADM), AIR Data Attitude Heading		AFL		1347			2818			0
	Reference Systems (Adahrs) and Digital AIR Data		DATE		4297 d			24 Jan 2013			
	Computers (Dadc) (Rescinded By FAA 2012-26-15 R01)		MSC				-				
	Affected ADC, ADM, Adahrs, or Dadc (Mandatory)		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2012-26-15 PARA (G)(2)	Perform Identify Out of Spec AIR Data Computers (ADC), Airdata Modules (ADM), AIR Data Attitude Heading Reference Systems (Adahrs) and Digital AIR Data Computers (Dadc) (Rescinded By FAA 2012-26-15 R01) Pitot-Static Certification Test		HRS		1672.9			4388		0	
			AFL		1347			2818		0	
			DATE		4297 d			24 Jan 2013			
			MSC				-				
			[End Of Month Item]								
(FAA 2012-26-15 PARA (G)(2))											
Airframe											
FAA 2012-26-15 R01	Appliance AD - AIR Data Pressure Transducers, as Installed In AIR Data Computers (ADC), AIR Data Modules (ADM), AIR Data Attitude Heading Reference Systems (Adahrs), and Digital AIR Data Computers (Dadc) (Mandatory)		HRS							0	
			AFL							0	
			MOS								
			MSC				-				
			[End Of Month Item]								
(2012-26-15 R01)											
Airframe											
FAA 2013-09-11	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System (Mandatory)		HRS		1661.3			4399.6		0	
			AFL		1326			2839		0	
			MOS		136.8			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11)											
Airframe											
FAA 2013-09-11 PARA (G)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Inspection for Part Number (P/N) (Mandatory)		HRS		1661.3			4399.6		0	
			AFL		1326			2839		0	
			DATE		4165 d			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11 PARA (G))											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2013-09-11 PARA (H)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Inspection A/C Compressor Hour Meter and Maintenance Records (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			DATE		4165 d			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11 PARA (H)) Airframe											
FAA 2013-09-11 PARA (I) & (J)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Replacement of A/C Compressor Motor Brushes and Related Maintenance Manual Information (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			MOS		136.8			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11 PARA (I) & (J)) Airframe											
FAA 2013-09-11 PARA (K)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Deactivation of A/C System (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			MOS		136.8			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11 PARA (K)) Airframe											
FAA 2013-09-11 PARA (L)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Reactivation of A/C System (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			MOS		136.8			05 Jun 2013			
			MSC				-				
			[End Of Month Item]								
(2013-09-11 PARA (L)) Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2013-09-11 PARA (M)	AIR Conditioning - Replacement of the Brushes on A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, or Deactivation of the A/C System Parts Return and Reporting Requirements (Mandatory)		HRS		1661.3			4399.6			0
			AFL		1326			2839			0
			MOS		136.8			05 Jun 2013			
			MSC				-				
(2013-09-11 PARA (M))			[End Of Month Item]								
Airframe											
FAA 2014-17-02	Appliance AD - Emergency Locator Transmitter - Battery Wiring Discrepancies - Honeywell Asca Inc (Mandatory)		HRS		1509			4551.9			0
			AFL		1164			3001			0
			MOS		120.5			14 Oct 2014			
			MSC				-				
(2014-17-02)			[End Of Month Item]								
Airframe											
FAA 2014-18-01	Navigation - Rockwell Collins, Inc. MODE S Transponders - Inspection / Modification (Mandatory)		HRS		1509			4551.9			0
			AFL		1164			3001			0
			MOS		120.5			14 Oct 2014			
			MSC				-				
(2014-18-01)			[End Of Month Item]								
Airframe											
FAA 2015-08-07	Appliance AD - Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flightcrew Oxygen Mask Regulators - Inspection / Replacement of Inflatable Harnesses (Mandatory)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(2015-08-07)			[End Of Month Item]								
Airframe											
FAA 2015-08-07 PARA (G)	Inspect the Inflatable Harness Fitted to Each Flightcrew Oxygen Mask Regulator to Determine IF the Inflatable Harness Is Installed With A Part Number and A Batch Number Identified In Appendix I of Zodiac Aerospace Service Bulletin Mxh-35-240, Revision 7, Dated September 1, 2011 (Mandatory)		HRS		1311.4			4749.5			0
			AFL		961			3204			0
			MOS		88			30 Jun 2017			
			MSC				-				
(2015-08-07 PARA (G))			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2015-08-07 PARA (H) (2015-08-07 PARA (H)) Airframe	Replace the Inflatable Harness Identified In Paprgraph G With A New or RE-Identified Harnesses (Mandatory)		HRS		1311.4			4749.5		0	
			AFL		961		3204		0		
			MOS		88		30 Jun 2017				
			MSC			-					
			[End Of Month Item]								
FAA 2015-10-02 (2015-10-02) Airframe	Appliance AD - Equipment/Furnishings - Zodiac Seats France - Inspection/Replacement (Mandatory)		HRS							0	
			AFL						0		
			MOS								
			MSC			-					
			[End Of Month Item]								
FAA 2015-10-02 PARA (G) (2015-10-02 PARA (G)) Airframe	General Visual Inspection for Cracking of Seat Backrest Links Having Part Number (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 and P/N 90- 000202-104-2 (Mandatory)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
FAA 2015-10-02 PARA (H) (2015-10-02 PARA (H)) Airframe	Corrective Actions - Cracking Is Found on the Link (Mandatory)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
FAA 2015-10-02 PARA (I) (2015-10-02 PARA (I)) Airframe	Replace All Seat Backrest Links, Having P/N 90-000200- 104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 and P/N 90-000202-104-2, With New Links (Mandatory)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
FAA 2015-10-51 (2015-10-51) Airframe	Appliance AD - Avidyne Integrated Flight Display (Ifd)- Incorporate Operational Limitations Into Limitations Section of the Afm or AFMS (Mandatory)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2015-10-51-E	Appliance AD - Avidyne Integrated Flight Display (Ifd)- Incorporate Operational Limitations Into Limitations Section of the Afm or AFMS. (Mandatory)		HRS		1455.6			4605.3		0	
			AFL		1115		3050		0		
			MOS		112.1		26 Jun 2015				
			MSC				-				
(2015-10-51-E)			[End Of Month Item]								
Airframe											
FAA 2015-23-09	Appliance AD - Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flight Crew Oxygen Mask Regulators - Inspection / Replacement of Oxygen Mask Regulators (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS		103.9		02 Mar 2016				
			MSC				-				
(2015-23-09)			[End Of Month Item]								
Airframe											
FAA 2015-23-09 PARA (G)	Inspect Each Flightcrew Oxygen Mask Regulator to Identify the Part Number and Serial Number (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS								
			DATE		3164 d		02 Mar 2016				
(2015-23-09 PARA (G))			MSC				-				
Airframe			[End Of Month Item]								
FAA 2015-23-09 PARA (H)(1)	Replace Each Affected Flightcrew Oxygen Mask With A Part Identified In Paragraph (H)(1)(I) or (H)(1)(Ii). (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS								
			DATE		3164 d		02 Mar 2016				
(FAA 2015-23-09 PARA (H)(1))			MSC				-				
Airframe			[End Of Month Item]								
FAA 2015-23-09 PARA (H)(2)(I)	Revise the Emergency Procedures Section of the Airplane Flight Manual (Afm) By Inserting the Statement provided In Figure 1 (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS								
			DATE		3164 d		02 Mar 2016				
(FAA 2015-23-09 PARA (H)(2)(I))			MSC				-				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2015-23-09 PARA (H)(2)(II)	Fabricate and Install A Placard on the Flightcrew Oxygen Mask Container that States: "Use Selector on 100% or Emergency Only." (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS								
			DATE		3164 d		02 Mar 2016				
			MSC				-				
(FAA 2015-23-09 PARA (H)(2)(II))			[End Of Month Item]								
Airframe											
FAA 2015-23-09 PARA (I)	Regulator Replacement (Mandatory)		HRS		1422.9			4638		0	
			AFL		1074		3091		0		
			MOS		103.9		02 Mar 2016				
			MSC				-				
			[End Of Month Item]								
Airframe											
FAA 2016-11-20	Appliance AD - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 that Are Installed on Airplanes. Superseded By FAA AD 2017-18-12 (Mandatory)		HRS		1301.3			4759.6		0	
			AFL		948		3217		0		
			MOS		83.6		10 Nov 2017				
			MSC				-				
			[End Of Month Item]								
(2016-11-20)											
Airframe											
FAA 2016-11-20 PARA (G)	Physically Inspect the Pbe Pouch to Determine IF IT Has an Intact Vacuum Seal In Accordance With B/E Aerospace Service Bulletin No. 119003-35-011, Rev .000, Dated February 4, 2015, Para Iii.A..1 Superseded By FAA AD 2017-18-12 (Mandatory)		HRS		1301.3			4759.6		0	
			AFL		948		3217		0		
			MOS		83.6		10 Nov 2017				
			MSC				-				
			[End Of Month Item]								
(2016-11-20 PARA (G))											
Airframe											
FAA 2016-11-20 PARA (H)(1)	Replacement of A Pbe Pouch, Found During the Inspection In Paragraph (G) of This AD, that Does Not Have an Intact Vacuum Seal. Superseded By FAA AD 2017-18-12 (Mandatory)		HRS		1301.3			4759.6		0	
			AFL		948		3217		0		
			MOS		83.6		10 Nov 2017				
			MSC				-				
			[End Of Month Item]								
(FAA 2016-11-20 PARA (H)(1))											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2016-11-20 PARA (H)(2)	Replacement of A Pbe Pouch, Found During the Inspection In Paragraph (G) of This AD, Where the Vacuum Seal Is Intact. Superseded By FAA AD 2017-18-12 (Mandatory)		HRS		1301.3			4759.6			0
			AFL		948			3217			0
			MOS		83.6			10 Nov 2017			
			MSC				-				
			[End Of Month Item]								
(FAA 2016-11-20 PARA (H)(2))											
Airframe											
FAA 2017-04-14	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires (Mandatory)		HRS		1335.4			4725.5			0
			AFL		978			3187			0
			MOS		91.5			14 Mar 2017			
			MSC				-				
			[End Of Month Item]								
(2017-04-14)											
Airframe											
FAA 2017-04-14 PARA (G)	Accomplish General Visual Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires for Evidence of Damage, All Applicable Adjustments, and All Applicable Corrective Actions (Mandatory)		HRS		1335.4			4725.5			0
			AFL		978			3187			0
			DATE		2787 d			14 Mar 2017			
			MSC				-				
			[End Of Month Item]								
(2017-04-14 PARA (G))											
Airframe											
FAA 2017-04-14 PARA (H)	Submit A Report of the Findings (Both Positive and Negative) of the Inspections Required By Paragraph (G) of This AD to Textron Aviation (Mandatory)		HRS		1335.4			4725.5			0
			AFL		978			3187			0
			DATE		2319 d			25 Jun 2018			
			MSC				-				
			[End Of Month Item]								
(2017-04-14 PARA (H))											
Airframe											
FAA 2017-16-01	Appliance AD - Equipment / Furnishings - Ameri-King Corporation Model Ak-450() and Ak-451() Series Emergency Locator Transmitters - Repetative Inspections, Checks, Tests and Verifications (Mandatory)		HRS		1300			4760.9			0
			AFL		947			3218			0
			MOS		82.8			04 Dec 2017			
			MSC				-				
			[End Of Month Item]								
(2017-16-01)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2017-16-01 PARA (G)	Perform General Visual Inspections of the ELT for Discrepancies; Checks , Tests and Verifications as Applicable, to Ensure the ELT Is Functioning, and All Applicable Corrective Actions		HRS		1300			4760.9			0
			AFL		947			3218			0
			MOS		82.8			04 Dec 2017			
			MSC				-				
(2017-16-01 PARA (G))			[End Of Month Item]								
Airframe											
FAA 2017-16-01 PARA (J)	Optional Terminating Action: Replace ELT With A Serviceable FAA-Approved ELT (Mandatory)		HRS		1300			4760.9			0
			AFL		947			3218			0
			MOS		82.8			04 Dec 2017			
			MSC				-				
(2017-16-01 PARA (J))			[End Of Month Item]								
Airframe											
FAA 2017-18-12	Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 and 119003-21 that Are Installed on Airplanes (Mandatory)		HRS		1301.3			4759.6			0
			AFL		948			3217			0
			MOS		83.6			10 Nov 2017			
			MSC				-				
(2017-18-12)			[End Of Month Item]								
Airframe											
FAA 2017-18-12 PARA (G)	Inspection Retained from AD 2016-11-20 for Airplanes With Pbe, P/N 119003-11, Installed (Mandatory)		HRS		1301.3			4759.6			0
			AFL		948			3217			0
			MOS		83.6			10 Nov 2017			
			MSC				-				
(2017-18-12 PARA (G))			[End Of Month Item]								
Airframe											
FAA 2017-18-12 PARA (H)	Replacement Retained from AD 2016-11-20 for Airplanes With Pbe, P/N 119003-11, Installed (Mandatory)		HRS		1301.3			4759.6			0
			AFL		948			3217			0
			MOS		83.6			10 Nov 2017			
			MSC				-				
(2017-18-12 PARA (H))			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
FAA 2017-18-12 PARA (I) & (J)	Inspect to Determine IF the S/N of the Installed Pbe, P/N 119003-21, Is Within the Range of 004-14768M Through 004-21093M or 004-02393M Through 004-03033M and IF Found Within the S/N Range Replace IT. (Mandatory)		HRS		1301.3			4759.6			0	
			AFL		948			3217			0	
			MOS		83.6			10 Nov 2017				
			MSC					-				
			[End Of Month Item]									
(2017-18-12 PARA (I) & (J))												
Airframe												
FAA 2018-21-14	Appliance AD - Oxygen - Oxygen Mask Regulator Harness Inflation Hoses - Inspection / Replacement (Mandatory)		HRS								0	
			AFL								0	
			DATE									
			MSC					-				
			(2018-21-14)									
Airframe												
FAA 2018-21-14 PARA (G)	Required Actions (Mandatory)		HRS		553.1			5507.8			0	
			AFL		367			3798			0	
			MOS		31.3			22 Mar 2022				
			MSC					-				
			(2018-21-14 PARA (G))									
Airframe												
FAA 2018-21-14 PARA (H)	Do Not Install on Any Airplane A Flight Crew Oxygen Mask Regulator With A P/N Listed In Planning Information, Paragraph 1.A.(1), of Zodiac Sb MC10-35-274 R02, Dated June 25, 2014, unless IT Meets the Definition of A Part Eligible for Installation In Para (I) of This AD (Mandatory)		HRS								0	
			AFL									0
			DATE									
			MSC						-			
			(2018-21-14 PARA (H))									
Airframe												
FAA 2019-07-10	Navigation - Litef Attitude Heading and Reference System (Ahrs) - Removal (Mandatory)		HRS		1068.4			4992.5			0	
			AFL		758			3407			0	
			MOS		63.6			10 Jul 2019				
			MSC					-				
			(2019-07-10)									
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2019-07-10 PARA (F)(1) (2019-07-10 PARA (F) (1)) Airframe	Remove the Ahrs Unit from Service (Mandatory)		HRS		1068.4			4992.5			0
			AFL		758			3407			0
			MOS		63.6			10 Jul 2019			
			MSC				-				
FAA 2019-07-10 PARA (F)(3) (2019-07-10 PARA (F) (3)) Airframe	Do Not Install an Ahrs Unit P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, or 145130-7100 on Any Aircraft (Mandatory)		HRS		1068.4			4992.5			0
			AFL		758			3407			0
			MOS		63.6			10 Jul 2019			
			MSC				-				
FAA 2020-26-05 (2020-26-05) Airframe	Engine Controls - Left and Right Throttle Quadrant Assembly Sensor Link and Sensor Drive ARM Pivot Rivets - Inspection/Corrective Action (Mandatory)		HRS								0
			AFL								0
			DATE								
			MSC				-				
FAA 2021-07-13 (FAA 990714) Airframe	Appliance AD - Equipment and Furnishing - Seat Restraint System Plastic Rotary Buckle Handle - Inspection/Replacement (Mandatory)		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				-				
FAA 2021-07-13 PARA (E)(1) (FAA 990715) Airframe	Inspect the Buckle Handle for A Crack and IF Cracked, before Further Flight, Replace IT With an Airworthy Buckle (Mandatory)		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				-				
FAA 2021-07-13 PARA (E)(2) (FAA 990716) Airframe	Measure the Thichness of the Buckle Handle Vane; IF Thickness Is 0.125 Inch or Greater, before Further Flight, Remove the Buckle from Service and Replace IT With an Airworthy Buckle (Mandatory)		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA 2021-07-13 PARA (E)(3)	Do Not Install A Buckle or Restraint System With A Buckle P/N 1111430 or 1111475, All Dash Numbers, With A Handle Vane Thickness of 0.125 Inch or Greater (Mandatory)		HRS		632			5428.9			0
			AFL		628			3537			0
			MOS		35.4			19 Nov 2021			
			MSC				-				
(FAA 990717)											
Airframe											
FAA 2021-23-12	Appliance AD - Indicating / Recording / Navigation - Radio (Radar) Altimeter - Afm Revision to Incorporate Limitations (Mandatory)		HRS								0
			AFL								0
			MOS		33.9			03 Jan 2022			
			MSC				DUE**				
(FAA 992199)											
Airframe											
FAA 2023-10-02	Indicating/Recording System/Navigation - Radio Altimeter - Afm Revision (Mandatory)		HRS		293.8			5767.1			0
			AFL		193			3972			0
			MOS		16			29 Jun 2023			
			MSC				-				
(2023-10-02)											
Airframe											
FAA 2023-10-02 PARA (H)	Revise the Limitations Section of the Existing Afm (until 30 -June-2023 - Satisfied By FAA 2021-23-12) (Mandatory)		HRS		293.8			5767.1			0
			AFL		193			3972			0
			MOS		16			29 Jun 2023			
			MSC				-				
(2023-10-02 PARA (H))											
Airframe											
FAA 2023-10-02 PARA (I)	Revise the Limitations Section and Remove the Afm Revision Required By Para (H) (after 30 Jun 2023) (Mandatory)		HRS		293.8			5767.1			0
			AFL		193			3972			0
			MOS		16			29 Jun 2023			
			MSC				-				
(2023-10-02 PARA (I))											
Airframe											
TCCA CF-2002- 42	No. 1 Engine - Pratt & Whitney Canada (P&WC) PW530A, PW535A, and PW545A Engines - Inspection of Flexible Fuel Tubes (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(CF-2002-42)											
Engine											
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
TCCA CF-2002-42 (CF-2002-42) Engine	No. 2 Engine - Pratt & Whitney Canada (P&WC)		HRS		975.6			5085.3			0
	PW530A, PW535A, and PW545A Engines - Inspection of		ENC		682			3458			0
	Flexible Fuel Tubes (Mandatory)		MOS		56.6			10 Feb 2020			
			MSC					-			
			[End Of Month Item]								
TCCA CF-2010-19 (CF-2010-19) Engine	No. 1 Engine - Intercompressor Bleed Valve/Servo Valve		HRS		975.6			5085.3			0
	Malfunction (Mandatory)		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
TCCA CF-2010-19 (CF-2010-19) Engine	No. 2 Engine - Intercompressor Bleed Valve/Servo Valve		HRS		975.6			5085.3			0
	Malfunction (Mandatory)		ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
TCCA CF-2010-19 STEP A,B,C,D,E,F,G (CF-2010-19 STEP A,B,C,D,E,F,G) Engine	No. 1 Engine - Incorporation Intercompressor Bleed		HRS		975.6			5085.3			0
	Valve/Servo Valve Malfunction of Asb A30421		ENC		682			3458			0
	(Mandatory)		MOS		56.7			08 Feb 2020			
			MSC				A/R				
TCCA CF-2010-19 STEP A,B,C,D,E,F,G (CF-2010-19 STEP A,B,C,D,E,F,G) Engine	No. 2 Engine - Incorporation Intercompressor Bleed		HRS		975.6			5085.3			0
	Valve/Servo Valve Malfunction of Asb A30421		ENC		682			3458			0
	(Mandatory)		MOS		56.6			10 Feb 2020			
			MSC				A/R				
TCCA CF-2010-19 STEP H. (CF-2010-19 STEP H.) Engine	No. 1 Engine - Test Intercompressor Bleed Valve/Servo		HRS		975.6			5085.3			0
	Valve Malfunction Procedure Part A (Mandatory)		ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
TCCA CF-2010-19 STEP H. (CF-2010-19 STEP H.) Engine	No. 2 Engine - Test Intercompressor Bleed Valve/Servo Valve Malfunction Procedure Part A (Mandatory)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
SIAC - Service Information/Bulletins											
3-1571-32-8^U Airframe	Goodrich Service Bulletin 3-1571-32-8, Service Bulletin		HRS		1587.1			4473.8			0
			AFL		1250			2915			0
			MOS		129.4			17 Jan 2014			
			MSC				-				
			[End Of Month Item]								
560XL-05-01 Airframe	Time Limits/Maintenance Checks - Conversion from Calendar Schedule Maintenance Program to Msg-3 Schedule Maintenance Program (Cancelled and Superseded By SL560XL-05-03),, Service Bulletin (Optional)		HRS		2000.7			4060.2			0
			AFL		1616			2549			0
			MOS		168.6			12 Oct 2010			
			MSC				A/R				
			[End Of Month Item]								
560XL-05-01 R01 (560XL-05-01 R1) Airframe	Time Limits/Maintenance Checks - Conversion from Calendar Schedule Maintenance Program to Msg-3 Schedule Maintenance Program (Cancelled and Superseded By SL560XL-05-03), Service Bulletin (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
560XL-21-15 Airframe	AIR Conditioning - Cockpit Temperature Sensor Improvement, Service Bulletin (Discretionary)		HRS		5772.9			288			0
			AFL								0
			MOS		255			29 Jul 2003			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-21-18	AIR Conditioning - Temperature Controller Upgrade (Superseded By 560XL-21-18 R01), Service Bulletin (Recommended)		HRS		3266.9			2794			0
			AFL								0
			MOS		202.8			04 Dec 2007			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-21-19	AIR Conditioning - Emergency Pressurization Operation Improvement (Superseded By 560XL-21-19 R01), Service Bulletin (Recommended)		HRS		4281.9			1779			0
			AFL								0
			MOS		222.2			24 Apr 2006			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-21-24 R01	AIR Conditioning - Aft Evaporator Installation and Wiring Modification, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(560XL-21-24 R1)											
Airframe											
560XL-23-05 R01	Communications - Rnz-850 Navigation Radio Upgrade, Service Bulletin (Mandatory)		HRS		5447.9			613			0
			AFL								0
			MOS		247.2			25 Mar 2004			
			MSC				-				
			[End Of Month Item]								
(560XL-23-05 R1)											
Airframe											
560XL-23-07 R03	Communications - Radio Management Unit (RM855) Installation, Service Bulletin (Optional)		HRS		1300			4760.9			0
			AFL		947			3218			0
			MOS		82.8			04 Dec 2017			
			MSC				-				
			[End Of Month Item]								
(560XL-23-07 R3)											
Airframe											
560XL-23-11	Communications - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(560XL-23-11 R1)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-24-02 R01 (560XL-24-02 R1) Airframe	Electrical Power - Concorde Battery Installation, Service Bulletin (Optional)		HRS		6060.9			0			0
			AFL		4165			0		0	
			MOS		265.9			02 Sep 2002			
			MSC				-				
			[End Of Month Item]								
560XL-24-11 R01 (560XL-24-11 R1) Airframe	Electrical Power - Emergency Lighting Battery Pack Circuit Breaker Modification, Service Bulletin (Discretionary)		HRS		2000.7			4060.2			0
			AFL		1616			2549		0	
			MOS		168.6			11 Oct 2010			
			MSC				A/R				
			[End Of Month Item]								
560XL-24-20 (24-20) Airframe	Electrical Power - AC J-Box Wire Bundle Anchor Installation, Service Bulletin (Mandatory)		HRS		980			5080.9			0
			AFL		689			3476		0	
			MOS		56.1			26 Feb 2020			
			MSC				-				
			[End Of Month Item]								
560XL-25-08 Airframe	Equipment/Furnishings - Aft Divider Improvement, Service Bulletin (Optional)		HRS		5772.9			288			0
			AFL							0	
			MOS		255			29 Jul 2003			
			MSC				-				
			[End Of Month Item]								
560XL-25-09 Airframe	Equipment/Furnishings - Galley Storage Door Hinge Improvement, Service Bulletin (Recommended)		HRS		5015.9			1045			0
			AFL							0	
			MOS		238.5			16 Dec 2004			
			MSC				-				
			[End Of Month Item]								
560XL-25-11 R03 (560XL-25-11 R3) Airframe	Equipment/Furnishings - Artex C406-2 Three-Frequency Emergency Locator Transmitter (ELT), Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-25-19	Equipment/Furnishings - Replacement of the 4569508-1 Water Barrier Assembly, Service Bulletin (Recommended)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
560XL-25-22	Equipment/Furnishings - Inspection of the SWI610-31 Entry Door Switch Indicator Light Emitting Diode (Led) Lights for Proper Indication, Service Letter (Recommended)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
560XL-26-01	FIRE Protection - Transmittal of Pacific Scientific Service Bulletin 26-03-35071497, Inspection and Replacement of Temperature Compensated Pressure Switch (Superseded By 560XL-26-01 R01), Service Bulletin (Mandatory)		HRS		5874.9			186			0
			AFL							0	
			MOS		257.6			10 May 2003			
			MSC				A/R				
[End Of Month Item]											
Airframe											
560XL-26-02	FIRE Protection - FIRE Bottle Wire Identification Sleeve Installation (Superseded By 560XL-26-02 R01), Service Bulletin (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156		0	
			MOS		.4			17 Oct 2024			
			MSC				A/R				
[End Of Month Item]											
Airframe											
560XL-26-04	FIRE Protection - Replacement of the Halon Type 1211 Portable FIRE Extinguishers, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
560XL-27-13 R01	Flight Controls - Aft Aileron Sector Tube Finish Improvement (Superseded By 560XL-27-13 R02), Service Bulletin (Recommended)		HRS		5698.9			362			0
			AFL							0	
			MOS		252.9			03 Oct 2003			
			MSC				A/R				
(560XL-27-13 R1)											
Airframe											
[End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-27-13 R02	Flight Controls - Aft Aileron Sector Tube Finish Improvement, Service Bulletin (Recommended)		HRS		5156.9			904			0
			AFL								0
			MOS		241.3			20 Sep 2004			
	(560XL-27-13 R2)		MSC				-				
Airframe		[End Of Month Item]									
560XL-27-17 R02	Flight Controls - Elevator Trim Tab Inspection/Repair, Service Bulletin (Recommended)		HRS		5874.9			186			0
			AFL								0
			MOS		257.6			10 May 2003			
	(560XL-27-17 R2)		MSC				-				
Airframe		[End Of Month Item]									
560XL-27-19 R03	Flight Controls - Steep Approach Certification, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-27-19 R04	Flight Controls - Steep Approach Certification, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-27-22 R01	Flight Controls - Aileron Wing Cable Pulley Bracket Replacement, Service Bulletin (Mandatory)		HRS		4300.9			1760			0
			AFL								0
			MOS		223.1			26 Mar 2006			
	(560XL-27-22 R1)		MSC				A/R				
Airframe		[End Of Month Item]									
560XL-27-28	Flight Controls - Rudder Pedal Position Adjustment Modification, Service Bulletin (Discretionary)		HRS		2242.9			3818			0
			AFL								0
			MOS		180.5			15 Oct 2009			
			MSC				A/R				
Airframe		[End Of Month Item]									
560XL-27-29 R01	Flight Controls - Speed Brake Electrical Connector Replacement, Service Bulletin (Recommended)		HRS		2242.9			3818			0
			AFL								0
			MOS		180.5			15 Oct 2009			
	(560XL-27-29 R1)		MSC				A/R				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-27-32	Flight Controls - Rudder Pedal Position Modification (Superseded By 560XL-27-32 R01), Service Bulletin (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-27-35	Flight Controls - Stainless Steel Hydraulic Tube Replacement (Superseded By 560XL-27-35 R01), Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
560XL-27-35 R01	Flight Controls - Stainless Steel Hydraulic Tube Replacement, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			(560XL-27-35 R1)								
Airframe	[End Of Month Item]										
560XL-28-02	Fuel - Wing Fuel Boost Pump Fairing Insulation Installation (Superseded By 560XL-28-02 R01), Service Bulletin (Recommended)		HRS		4775.9			1285			0
			AFL								0
			MOS		232.7			08 Jun 2005			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-28-03	Fuel - Wing Fuel Boost Pump Fairing Insulation Installaton, Service Bulletin (Mandatory)		HRS		4775.9			1285			0
			AFL								0
			MOS		232.7			08 Jun 2005			
			MSC				-				
			[End Of Month Item]								
Airframe											
560XL-29-04	Hydraulic Power - Wheel Well Hydraulic Line Support Improvement, Service Bulletin (Mandatory)		HRS		4946.9			1114			0
			AFL								0
			MOS		237.6			10 Jan 2005			
			MSC				-				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-31-02	Indicating/Recording Systems - Stab Miscompare Annunciation Improvement (Superseded By 560XL-31-02 R01), Service Bulletin (Mandatory)		HRS		5447.9			613		0	
			AFL						0		
			MOS		247.2		25 Mar 2004				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-32-20 R01	Landing Gear - Nose Gear Torque-Link Quick Disconnect (Superseded By 560XL-32-20 R02), Service Bulletin (Optional)		HRS		4767.9			1293		0	
			AFL						0		
			MOS		232.4		19 Jun 2005				
			MSC			-					
			[End Of Month Item]								
(560XL-32-20 R1)											
Airframe											
560XL-32-20 R02	Landing Gear - Nose Gear Torque-Link Quick Disconnect, Service Bulletin (Optional)		HRS		4027.9			2033		0	
			AFL						0		
			MOS		217.7		08 Sep 2006				
			MSC			A/R					
			[End Of Month Item]								
(560XL-32-20 R2)											
Airframe											
560XL-32-24	Landing Gear - Emergency Gear Extension Bottle Actuator Handle Pivot Screw Replacement (Superseded By 560XL-32-24 R01), Service Bulletin (Mandatory)		HRS		5274.9			786		0	
			AFL						0		
			MOS		243.1		27 Jul 2004				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-32-26 R02	Landing Gear - Nose Landing Gear Door Mechanism Improvement, Service Bulletin (Mandatory)		HRS		4281.9			1779		0	
			AFL						0		
			MOS		222.2		24 Apr 2006				
			MSC			A/R					
			[End Of Month Item]								
(560XL-32-26 R2)											
Airframe											
560XL-32-27	Landing Gear - Main Landing Gear Trailing Link Pivot Pin Retention Improvement, Service Bulletin (Recommended)		HRS		3745.9			2315		0	
			AFL						0		
			MOS		212.6		12 Feb 2007				
			MSC			A/R					
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-32-32	Landing Gear - Brake Hydraulic Pack Filter Bowl Replacement, Service Bulletin (Recommended)		HRS		2978.9			3082			0
			AFL						0		
			MOS		197.2		23 May 2008				
			MSC			A/R					
Airframe	[End Of Month Item]										
560XL-32-37	Landing Gear - Nose Landing Gear Steering Hardware Replacement, Service Bulletin (Discretionary)		HRS		2000.7			4060.2			0
			AFL		1616		2549		0		
			MOS		168.6		11 Oct 2010				
			MSC			A/R					
Airframe	[End Of Month Item]										
560XL-32-38 R02	Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link, Service Bulletin (Optional)		HRS								0
			AFL						0		
			DATE								
			MSC			-					
Airframe											
560XL-32-40	Landing Gear Annunciation Wiring Modification, Service Bulletin (Recommended)		HRS		2978.9			3082			0
			AFL						0		
			MOS		197.2		23 May 2008				
			MSC			A/R					
Airframe	[End Of Month Item]										
560XL-32-41 R01	Landing Gear - Transmittal of Goodrich Service Bulletin 3-1571-32-7, Service Bulletin (Mandatory)		HRS		1706.1			4354.8			0
			AFL		1370		2795		0		
			MOS		145.1		28 Sep 2012				
			MSC			A/R					
(560XL-32-41 R1)											
Airframe	[End Of Month Item]										
560XL-32-42 R02	Landing Gear - Stainless Steel Hydraulic Tube Replacement, Service Bulletin (Optional)		HRS								0
			AFL						0		
			DATE								
			MSC			-					
(560XL-32-42 R2)											
Airframe	[End Of Month Item]										
560XL-32-43	Landing Gear - Copilot Left Brake Cylinder Hose Replacement, Service Bulletin (Optional)		HRS								0
			AFL						0		
			DATE								
			MSC			-					
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-32-44	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation (Superseded By 560XL-32-44 R01), Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(32-44)			[End Of Month Item]								
Airframe											
560XL-32-44 R01	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-32-44 R02	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-32-45	Landing Gear - Landing Gear Warning Horn Replacement, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-32-47	Landing Gear - Main Landing Gear Brake Hydraulic Line Fitting Replacement, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
560XL-33-05	Lights - Led Tail Position Light Installation (Superseded By 560XL-33-05 R01), Service Bulletin (Optional)		HRS		5935.9			125			0
			AFL								0
			MOS		260.9			03 Feb 2003			
			MSC				A/R				
Airframe			[End Of Month Item]								
560XL-33-05 R02	Lights - Led Tail Position Light Installation, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(560XL-33-05 R2)			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-33-06 R01	Lights - Cabin Upwash/Downwash Indirect Lighting Improvement, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(560XL-33-06 R1)		[End Of Month Item]									
Airframe											
560XL-33-08 R02	Lights - Chart Light Modification, Service Bulletin (Recommended)		HRS		2978.9			3082			0
			AFL							0	
			MOS		197.2			23 May 2008			
			MSC				A/R				
(560XL-33-08 R2)		[End Of Month Item]									
Airframe											
560XL-33-09	Lights - Light Emitting Diode (Led) Emergency Overwing Lighting Installation, Service Bulletin (Optional)		HRS		4636.9			1424			0
			AFL							0	
			MOS		229.5			16 Sep 2005			
			MSC				-				
Airframe		[End Of Month Item]									
560XL-33-15	Lights - Wing Tip Navigation and Anti-Collision Led Light Installation, Service Bulletin (Optional)		HRS		2317.9			3743			0
			AFL							0	
			MOS		183			29 Jul 2009			
			MSC				A/R				
Airframe		[End Of Month Item]									
560XL-34-29	Navigation - Honeywell Primus 1000 Phase 3.0 Software Upgrade, Service Bulletin (Recommended)		HRS		5912.9			148			0
			AFL							0	
			MOS		259.1			27 Mar 2003			
			MSC				-				
Airframe		[End Of Month Item]									
560XL-34-30	Navigation - Honeywell Primus 1000 Phase 3.0 Software Upgrade, Service Bulletin (Recommended)		HRS		5698.9			362			0
			AFL							0	
			MOS		252.9			03 Oct 2003			
			MSC				-				
Airframe		[End Of Month Item]									
560XL-34-32 R02	Navigation - Category II Operations, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
(560XL-34-32 R2)		[End Of Month Item]									
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-34-38 R01 (560XL-34-38 R1) Airframe	Navigation - UNS1-Csp to UNS1-Csp+ and UNS1-ESP Upgrade to Software Control Number (Scn) 802.2 (Superseded By 560XL-34-38 R02), Service Bulletin (Optional)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
			[End Of Month Item]								
560XL-34-38 R02 (560XL-34-38 R2) Airframe	Navigation - UNS1-Csp to UNS1-Csp+ and UNS1-ESP Upgrade to Software Control Number (Scn) 802.2, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
560XL-34-44 R03 (560XL-34-44 R3) Airframe	Navigation - Honeywell MODE S Transponder Upgrade for Enhanced Surveillance, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
560XL-34-46 Airframe	Navigation - Honeywell CD-820 Flight Management System (FMS) Wiring Modification, Service Bulletin (Recommended)		HRS		4471.9			1589			0
			AFL								0
			MOS		226.4			19 Dec 2005			
			MSC				-				
			[End Of Month Item]								
560XL-34-47 Airframe	Navigation - Universal Performance Database Disablement, Service Bulletin (Mandatory)		HRS		4636.9			1424			0
			AFL								0
			MOS		229.5			16 Sep 2005			
			MSC				A/R				
			[End Of Month Item]								
560XL-34-50 Airframe	Navigation - IC-615 Vertical Glide Path and Flight Director Improvements (Superseded By 560XL-34-50 R01), Service Bulletin (Recommended)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
560XL-34-52	Navigation - Universal Performance Database Installation (Superseded By 560XL-34-52 R01), Service Bulletin (Optional)		HRS		3566.9			2494			0	
			AFL								0	
			MOS		208.4			19 Jun 2007				
			MSC				A/R					
			[End Of Month Item]									
Airframe												
560XL-34-54 R03	Navigation - Meggitt Mark I Secondary Flight Display Indicator and AIR Data Unit Replacement or Mark Ii Secondary Flight Display Indicator Replacement, Service Bulletin (Optional)		HRS								0	
			AFL									0
			DATE									
			MSC				-					
			[End Of Month Item]									
(560XL-34-54 R3)												
Airframe												
560XL-34-57	Navigation - IC-600 Flight Director Improvements, Service Bulletin (Discretionary)		HRS		3566.9			2494			0	
			AFL									0
			MOS		208.4			19 Jun 2007				
			MSC				A/R					
			[End Of Month Item]									
Airframe												
560XL-34-58	Navigation - IC-615 Flight Director Improvements (Superseded By 560XL-34-58 R01), Service Bulletin (Discretionary)		HRS		2185.9			3875			0	
			AFL									0
			MOS		178.7			08 Dec 2009				
			MSC				A/R					
			[End Of Month Item]									
Airframe												
560XL-34-60	Navigation - Universal Uns-1ESPW FMS Wide AREA Augmentation System (WAAS) Upgrade, Service Bulletin (Optional)		HRS		1300			4760.9			0	
			AFL		947			3218				0
			MOS		82.8			04 Dec 2017				
			MSC				-					
			[End Of Month Item]									
Airframe												
560XL-34-66 R01	Navigation - Installation of Scn 802.8 for Uns-1 FMS, Service Bulletin (Recommended)		HRS		1644.3			4416.6			0	
			AFL		1289			2876				0
			MOS		132.5			16 Oct 2013				
			MSC				-					
			[End Of Month Item]									
(560XL-34-66 R1)												
Airframe												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-34-70	Navigation - Universal Solid State Data Transfer Unit (Ssdtu) Upgrade, Service Bulletin (Optional)		HRS		1300			4760.9			0
			AFL		947			3218			0
			MOS		82.8			04 Dec 2017			
			MSC				A/R				
Airframe			[End Of Month Item]								
560XL-34-71	Navigation - TCAS 2000 Interference Limiting Functionality Upgrade for Software Version 7.0 (Superseded By 560XL-34-71 R01), Service Bulletin (Mandatory)		HRS		1644.3			4416.6			0
			AFL		1289			2876			0
			MOS		132.5			16 Oct 2013			
			MSC				-				
Airframe			[End Of Month Item]								
560XL-34-71 R01	Navigation - TCAS 2000 Interference Limiting Functionality Upgrade for Software Version 7.0, Service Bulletin (Mandatory)		HRS		1644.3			4416.6			0
			AFL		1289			2876			0
			MOS		132.5			16 Oct 2013			
			MSC				-				
(560XL-34-71 R1)			[End Of Month Item]								
Airframe											
560XL-34-72	Navigation - TCAS 2000 Update Software to Version 7.1 (Superseded By 560XL-34-72 R01), Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
560XL-34-72 R01	Navigation - TCAS 2000 Update Software to Version 7.1, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(560XL-34-72 R1)			[End Of Month Item]								
Airframe											
560XL-34-75 R01	Navigation - Honeywell Traffic Alert and Collision Avoidance System Ii (TCAS Ii) Version 7.1 Software Update, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(560XL-34-75 R1)			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-34-77 R03	Navigation - Automatic Dependent Surveillance Broadcast (ADS-B) Out Transponder Installation (Superseded By 560XL-34-77 R04), Service Bulletin (Optional)		HRS		1300			4760.9			0
			AFL		947			3218		0	
			MOS		82.8			04 Dec 2017			
			MSC				-				
(560XL-34-77 R3)		[End Of Month Item]									
Airframe											
560XL-34-77 R04	Navigation - Automatic Dependent Surveillance Broadcast (ADS-B) Out Transponder Installation, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
560XL-34-78	Navigation - Universal Uns-1ESPW FMS Software Upgrade 1000.8, Service Bulletin (Optional)		HRS		1300			4760.9			0
			AFL		947			3218		0	
			MOS		82.8			04 Dec 2017			
			MSC				-				
Airframe		[End Of Month Item]									
560XL-34-80	Navigation - Litef Lcr-93 Ahrs Obsolescence, Service Bulletin (Optional) 145130-60001093		HRS		968.3			5092.6			0
			AFL		672			3493		0	
			MOS		55.6			12 Mar 2020			
			MSC				-				
(34-80)		[End Of Month Item]									
Airframe											
560XL-34-82	Navigation - Standby Flight Display (SFD) Weight on Wheels (Wow) Electrical Wiring Improvement, Service Bulletin (Recommended)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
560XL-38-03	Water/Waste - Toilet Override Relay Installation, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-49-10	Auxiliary Power - APU to Engine Start Improvement (Superseded By 560XL-49-10 R01), Service Bulletin (Recommended)		HRS		5772.9			288		0	
			AFL						0		
			MOS		255		29 Jul 2003				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-49-11	Auxiliary Power Unit Generator Control Unit Wiring Improvement (Superseded By 560XL-49-11 R01), Service Bulletin (Recommended)		HRS		5912.9			148		0	
			AFL						0		
			MOS		259.1		27 Mar 2003				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-49-16	Auxiliary Power - APU Starter Generator Cooling Kit Installation, Service Bulletin (Discretionary)		HRS		3442.9			2618		0	
			AFL						0		
			MOS		206.1		28 Aug 2007				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-49-17	Auxiliary Power - Auxiliary Power Unit Mount Bolt Change, Service Bulletin (Optional)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
Airframe											
560XL-52-14	Doors - Cabin Door Reinforcement Modification (Superseded By 560XL-52-14 R01), Service Bulletin (Discretionary)		HRS		2352.9			3708		0	
			AFL						0		
			MOS		183.5		14 Jul 2009				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
560XL-52-14 R01	Doors - Cabin Door Reinforcement Modification, Service Bulletin (Discretionary)		HRS							0	
			AFL						0		
			DATE								
			MSC			A/R					
			[End Of Month Item]								
(560XL-52-14 R1)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-52-15 R01 (560XL-52-15 R1) Airframe	Doors - Cabin Entry Door Counterbalance Spring Replacement, Service Bulletin (Discretionary)		HRS		2352.9			3708		0	
			AFL					0			
			MOS		183.5		14 Jul 2009				
			MSC			A/R					
			[End Of Month Item]								
560XL-52-17 R01 (560XL-52-17 R1) Airframe	Doors - Cabin Entry Door Operation Improvement, Service Bulletin (Recommended)		HRS		2750.9			3310		0	
			AFL					0			
			MOS		193.7		09 Sep 2008				
			MSC			A/R					
			[End Of Month Item]								
560XL-52-18 Airframe	Doors - Aft Baggage Door Hinge Monel Rivet Replacement (Superseded By 560XL-52-18 R01), Service Bulletin (Recommended)		HRS		3115.9			2945		0	
			AFL					0			
			MOS		200.2		23 Feb 2008				
			MSC			A/R					
			[End Of Month Item]								
560XL-53-13 Airframe	Fuselage - Nose Drip CAP Bond Inspection (Superseded By 560XL-53-13 R01), Service Bulletin (Mandatory)		HRS		1706.1			4354.8		0	
			AFL		1370		2795		0		
			MOS		145.1		28 Sep 2012				
			MSC			A/R					
			[End Of Month Item]								
560XL-53-13 R01 (560XL-53-13 R1) Airframe	Fuselage - Nose Drip CAP Bond Inspection, Service Bulletin (Mandatory)		HRS		1706.1			4354.8		0	
			AFL		1370		2795		0		
			MOS		145.1		28 Sep 2012				
			MSC			A/R					
			[End Of Month Item]								
560XL-53-14 Airframe	Fuselage - Carbon Fiber Strake Modification, Service Bulletin (Optional)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
560XL-53-16 Airframe	Fuselage - Stinger Drain Installation, Service Bulletin (Mandatory)		HRS		1706.1			4354.8		0	
			AFL		1370		2795		0		
			MOS		145.1		28 Sep 2012				
			MSC			A/R					
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-57-03	Wings - Wing Wire Bundle Anchor Improvement (Superseded By 560XL-57-03 R01), Service Bulletin (Recommended)		HRS		5772.9			288			0
			AFL							0	
			MOS		255			29 Jul 2003			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-57-04 R02	Wings - Vortex Generator Adhesive Improvement, Service Bulletin (Recommended)		HRS		4775.9			1285			0
			AFL							0	
			MOS		232.7			08 Jun 2005			
			MSC				-				
			[End Of Month Item]								
(560XL-57-04 R2)											
Airframe											
560XL-71-07	Power Plant - Motive Flow Fuel Line/Oil Line Clearance Improvement (Superseded By 560XL-71-07 R01), Service Bulletin (Recommended)		HRS		4775.9			1285			0
			AFL							0	
			MOS		232.7			08 Jun 2005			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-71-09	Power Plant - Engine Oil Door Doubler Installation, Service Bulletin (Recommended)		HRS		3266.9			2794			0
			AFL							0	
			MOS		202.8			04 Dec 2007			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-71-11	Power Plant - Engine Fuel Manifold Drain Line Installation (Superseded By 560XL-71-11 R01), Service Bulletin (Optional)		HRS		980			5080.9			0
			AFL		689			3476			0
			MOS		56.1			26 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
560XL-71-11 R01	Power Plant - Engine Fuel Manifold Drain Line Installation, Service Bulletin (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
(560XL-71-11 R1)											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
560XL-71-12	Power Plant - Engine Fuel Manifold Drain Line Removal, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
560XL-73-01	Engine Fuel and Control - Engine Fuel Line Fitting Inspection, Service Bulletin (Mandatory)		HRS		5997.9			63			0
			AFL								0
			MOS		263.4			19 Nov 2002			
			MSC				-				
Airframe			[End Of Month Item]								
560XL-80-03	Starting - APU Generator Control Unit (Gcu) Current Limiting, Service Bulletin (Recommended)		HRS		4775.9			1285			0
			AFL								0
			MOS		232.7			08 Jun 2005			
			MSC				-				
Airframe			[End Of Month Item]								
ASL560XL-26-01	FIRE Protection - Transmittal of Meggitt Safety Systems Service Bulletin 26-36-Thermistors Detectors (Superseded By ASL560XL-26-01 R01), Alert Service Letter (Mandatory)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
Airframe			[End Of Month Item]								
ASL560XL-27-10	Flight Controls - Transmittal of FAA Approved Airplane Flight Manual Temporary Change 56XFM Tc-09-04, Alert Service Letter (Mandatory)		HRS		5912.9			148			0
			AFL								0
			MOS		259.1			27 Mar 2003			
			MSC				-				
Airframe			[End Of Month Item]								
ASL560XL-27-12	Flight Controls - Aileron Wing Cable Inspection (Superseded By ASL560XL-27-12 R01), Alert Service Letter (Mandatory)		HRS		5598.9			462			0
			AFL								0
			MOS		250.8			05 Dec 2003			
			MSC				A/R				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASL560XL-32-13	Landing Gear - Emergency Brake,Flaps,Emergency Gear and Speed Brake Hydraulic/Pneumatic Line Clamp Inspection, Alert Service Letter (Mandatory)		HRS		5698.9			362		0	
			AFL						0		
			MOS		252.9		03 Oct 2003				
			MSC			-					
			[End Of Month Item]								
Airframe											
ASL560XL-32-14	Landing Gear - Nose Landing Gear Oleo Pressure Inspection, Alert Service Letter (Mandatory)		HRS		4946.9			1114		0	
			AFL						0		
			MOS		237.6		10 Jan 2005				
			MSC			A/R					
			[End Of Month Item]								
(560XL-32-14)											
Airframe											
ASL560XL-34-08	Navigation - Transmittal of Honeywell Technical Newsletter A23-3850-001, Alert Service Letter (Mandatory)		HRS		5912.9			148		0	
			AFL						0		
			MOS		259.1		27 Mar 2003				
			MSC			-					
			[End Of Month Item]								
Airframe											
ASL560XL-53-08	Fuselage - Aft Canted Bulkhead Drain Installation (Superseded By ASL560XL-53-08 R01), Alert Service Letter (Mandatory)		HRS		1961.5			4099.4		0	
			AFL		1576		2589		0		
			DATE		5027 d		25 Jan 2011				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
ASL560XL-53-08 R01	Fuselage - Aft Canted Bulkhead Drain Installation, Alert Service Letter (Mandatory)		HRS		19.3			6041.6		0	
			AFL		9		4156		0		
			DATE		13 d		17 Oct 2024				
			MSC			A/R					
			[End Of Month Item]								
(ASL560XL-53-08 R1)											
Airframe											
ASL560XL-72-19	Right Engine Transmittal of P&WC Service Documents - Intercompressor Bleed Valve/Servo-Valve-Inspection/Replacement of, Alert Service Letter (Mandatory)		HRS		1985.6			4075.3		0	
			AFL		1609		2556		0		
			MOS		167.8		04 Nov 2010				
			MSC			A/R					
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
ASL560XL-72-19	Left Engine Transmittal of P&WC Service Documents -		HRS		1985.6			4075.3			0
	Intercompressor Bleed Valve/Servo - Valve -		AFL		1609			2556			0
	Inspection/Replacement of, Alert Service Letter		MOS		167.8			04 Nov 2010			
	(Mandatory)		MSC				A/R				
			[End Of Month Item]								
Airframe											
ASL560XL-73-11	Left Engine Transmittal of Pratt & Whitney Canada		HRS		3424.9			2636			0
	(P&WC) Service Bulletin A30319 Turbofan Engine New		AFL								0
	Fuel Manifold-Introduction of, Alert Service Letter		MOS		205.7			08 Sep 2007			
	(Mandatory)		MSC				A/R				
			[End Of Month Item]								
Airframe											
ASL560XL-73-11	Right Engine Transmittal of Pratt & Whitney Canada		HRS		3424.9			2636			0
	(P&WC) Service Bulletin A30319 Turbofan Engine New		AFL								0
	Fuel Manifold-Introduction of, Alert Service Letter		MOS		205.7			08 Sep 2007			
	(Mandatory)		MSC				A/R				
			[End Of Month Item]								
Airframe											
CIL-03-01	Certification Requirements - Supplemental Type		HRS								0
	Certificate (STC), Service Letter (Informational)		AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
CIL-20-01 R02	Standard Practices - Cessna Certification of		HRS								0
	Nondestructive Testing Facilities/Personnel, Service Letter		AFL								0
	(Informational)		DATE								
			MSC				-				
			[End Of Month Item]								
(CIL-20-01 R2)											
Airframe											
CIL-20-01 R03-CN	Standard Practices - Cessna Certification of		HRS								0
	Nondestructive Testing Facilities/Personnel, Service Letter		AFL								0
	(Cancelled)		DATE								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
CIL-21-01	Compressor Motor Brush Life Limit, Service Letter (Informational)		HRS								0	
			AFL								0	
			DATE									
			MSC				-					
Airframe			[End Of Month Item]									
CIL-21-03	AIR Conditioning - Transmittal of Honeywell Sb 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, Pn 2341316-2 and -3, for Corrosion, Service Letter (Informational)		HRS								0	
			AFL									0
			DATE									
			MSC				-					
Airframe			[End Of Month Item]									
CIL-21-03 R01	AIR Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, Pn 2341316-2 and -3, for Corrosion, Service Letter (Informational)		HRS								0	
			AFL									0
			DATE									
			MSC				-					
Airframe												
CIL-26-01 R01	FIRE Protection - FIRE Extinguisher Bottle Cartridge Ground Stud Torquing, Service Letter (Mandatory)		HRS		1108.2			4952.7			0	
			AFL		788			3377			0	
			MOS		64.8			04 Jun 2019				
			MSC				-					
(CIL-26-01 R1)												
Airframe			[End Of Month Item]									
CIL-28-01	Fuel - Microbiological Contamination In Aircraft Fuel Tanks and Fuel Systems, Service Letter (Informational)		HRS								0	
			AFL									0
			DATE									
			MSC				-					
Airframe												
CIL-30-01 R01	Ice and Rain Protection - Approved Deicing Program Updates, Service Letter (Informational)		HRS								0	
			AFL									0
			DATE									
			MSC				-					
(CIL-30-01 R1)												
Airframe			[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CIL-31-01	Indicating/Recording Systems - Cvr, FDR, and Cvdr 90-Day Battery Underwater Locator Beacon (UIb) Installation, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
CIL-32-01	Landing Gear - Improved Nose Wheel Grease Seal, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
CIL-32-04	Wireless Tire Pressure Monitoring System Installation, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
CIL-32-06	Landing Gear - Wireless Tire Pressure Sensor Fill Valve Torque Verification, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-32-07	Landing Gear - Modification of the Accomplishment Instructions for Preparing the Aircraft for Maintenance Operations, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-34-01	Navigation - Transmit Universal Avionics Alert Service Bulletin 3XXX.()-34-3508, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CIL-34-02	Navigation - Transmittal of Honeywell Sil		HRS		1661.3			4399.6			0
	D201301000032, Primus li Integrated Radio System,		AFL		1326			2839			0
	Service Letter (Mandatory)		MOS		136.8			05 Jun 2013			
			MSC				-				
Airframe		[End Of Month Item]									
CIL-34-03 R02	Transmittal of Honeywell Service Bulletin 7014300-22-16,		HRS								0
	Modification (MOD) R to Du-870 Display Unit Pn 7014300		AFL								0
	-901 and -902; Decrease Failure Rate of High Voltage		DATE								
	Power Supply (Hvps) because of High Humidity, Service		MSC				-				
(CIL-34-03 R2)		[End Of Month Item]									
Airframe											
CIL-34-06 R01	Navigation - Transmittal of Honeywell Sil		HRS								0
	D201206000008R002, Primus Epic and Primus li MODE		AFL								0
	S Transponder; (1) TCAS, Change 7.1, Reports an Earlier		DATE								
	TCAS li Version Number to ATC Ground Stations, (2)		MSC				-				
(CIL-34-06 R1)		[End Of Month Item]									
Airframe											
CIL-34-09	Navigation - Transmittal of Honeywell Service Bulletin		HRS								0
	Fmz-2000/2010 - Flight Management System (FMS)		AFL								0
	Software Version 6.1 (FMS 6.1) Upgrade and		DATE								
	Consolidation, Service Letter (Informational)		MSC				-				
Airframe											
CIL-34-09 R01	Navigation - Transmittal of Honeywell Service Information		HRS								0
	Letter Fmz-2000/2010 - Flight Management System		AFL								0
	(FMS) Software Version 6.1 (FMS 6.1) Upgrade and		DATE								
	Consolidation, Service Letter (Informational)		MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CIL-34-11	Navigation - Transmittal of Collins Aerospace Service Bulletin Alt-4000-34-14, Navigation - Alt 4000 Power Supply Robustness Improvement, Service Bulletin (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-35-05	Oxygen - Transmittal of Zodiac Aerospace Sb Mcf-Sbu-35 -001, Service Letter (Mandatory)		HRS		1422.9			4638			0
			AFL		1074			3091			0
			MOS								
			DATE		3164 d			02 Mar 2016			
Airframe											
[End Of Month Item]											
CIL-71-01	Transmittal of Pratt & Whitney Canada Service Bulletin 30463, Service Letter (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
[End Of Month Item]											
CIL-99-01 R02	Miscellaneous - Use of Corrosion Inhibiting Compounds, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(CIL-99-01 R2)											
Airframe											
[End Of Month Item]											
CIL-99-01 R03	Miscellaneous - Use of Corrosion Inhibiting Compounds, Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-99-02	Miscellaneous - Avoid Operations on Runways Treated With Runway De-Ice (Rdi) Fluids. Aircraft Washing Recommended after Exposure to Rdi Fluids, Service Letter (Recommended)		HRS								0
			AFL								0
			MOS								
			MSC				-				
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
CIL-99-02 R01	Miscellaneous - Avoid Operations on Runways Treated With Runway De-Ice (Rdi) Fluids. Aircraft Washing Recommended after Exposure to Rdi Fluids, Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-99-03 R01	Miscellaneous - Corrosion Prevention and Control Program (Cpcp), Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(CIL-99-03 R1)			[End Of Month Item]								
Airframe											
CIL-99-03 R02	Miscellaneous - Corrosion Prevention and Control Program (Cpcp), Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
CIL-99-04	Miscellaneous - Incremental Library Updates for Cesview, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
CIL-99-04 R01	Miscellaneous - Incremental Library Updates for Cesview, Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
MC 680-004	New Flexible Coupling P/N: 99040-6-6, Communique (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-03-01 R01	Certification Requirements - Supplemental Type Certificate (Superseded By Cil-03-01), Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(SL560XL-03-01 R1)		[End Of Month Item]									
Airframe											
SL560XL-05-03	Time Limits/Maintenance Checks - Conversion from Calendar Schedule Maintenance Program to Msg-3 Schedule Maintenance Program, Service Letter (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(560XL-05-03)		[End Of Month Item]									
Airframe											
SL560XL-05-04	Time Limits/Maintenance Checks - Removal of Phase Inspection Program from the Maintenance Manual Chapter 5, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(560XL-05-04)		[End Of Month Item]									
Airframe											
SL560XL-05-05	Time Limits/Maintenance Checks - Msg-3 Scheduled Maintenance Program Change Bridging Document, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-05-05 R01	Time Limits/Maintenance Checks - Msg-3 Scheduled Maintenance Program Change Bridging Document, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-05-05 R02	Time Limits/Maintenance Checks - Msg-3 Scheduled Maintenance Program Change Bridging Document, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-05-06	Time Limits/Maintenance Checks - New AE13083-5		HRS								0
	Engine and Auxiliary Power Unit FIRE Extinguisher		AFL								0
	Cartridge Squib Interval Grace Period Implementation,		DATE								
	Service Letter (Informational)		MSC				-				
Airframe											
SL560XL-20-01 R10	Standard Practices - Cessna Certification of		HRS								0
	Nondestructive Testing Facilities/Personnel (Superseded		AFL								0
	By SL560XL-20-01 R11), Service Letter (Informational)		DATE								
			MSC				A/R				
[End Of Month Item]											
Airframe											
SL560XL-20-04	Standard Practices - Cessna Standard Practices Manual,		HRS								0
	Service Letter (Informational)		AFL								0
	(560XL-20-04)		DATE								
			MSC				-				
[End Of Month Item]											
Airframe											
SL560XL-21-07	AIR Conditioning - Transmittal of Honeywell Service		HRS		5912.9			148			0
	Bulletin 2215460-21-2762, Environmental Control Unit		AFL								0
	(Ecu) - Inspect and Replace the Over Temperature Switch		MOS		259.1			27 Mar 2003			
	(Superseded By SL560XL-21-07 R01), Service Letter		MSC				A/R				
(Recommended)											
[End Of Month Item]											
Airframe											
SL560XL-23-05	Communications - Transmittal of Honeywell Service		HRS		5698.9			362			0
	Bulletin A21-3851-001, Rcz Integrated Communication		AFL								0
	Unit, Service Letter (Recommended)		MOS		252.9			03 Oct 2003			
			MSC				-				
[End Of Month Item]											
Airframe											
SL560XL-23-10	Communications - Atg 4000 Software Update, Service		HRS								0
	Letter (Optional)		AFL								0
	(560XL-23-10)		DATE								
			MSC				-				
[End Of Month Item]											
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-23-11 (560XL-23-11) Airframe	Communications - Atg 4000 Software Update to Version 2.8, Service Letter (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
SL560XL-24-02 Airframe	Electrical Power - Main Engine and APU Ground Installation Inspection and Bond Check, Service Letter (Discretionary)		HRS		5368.9			692			0
			AFL							0	
			MOS		244.5			14 Jun 2004			
			MSC				-				
			[End Of Month Item]								
SL560XL-24-07 Airframe	Electrical Power - Right AC Generator Wire Routing Verification, Service Letter (Mandatory)		HRS		1335.4			4725.5			0
			AFL		978			3187		0	
			DATE		2787 d			14 Mar 2017			
			MSC				-				
			[End Of Month Item]								
SL560XL-24-09 (560XL-24-09) Airframe	Electrical Power - Battery Temperature Indicator Gage Blanking Plate Installation, Service Letter (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
SL560XL-25-02 Airframe	Equipment/Furnishings - Toilet Shroud Assembly Inspection, Service Letter (Recommended)		HRS		5368.9			692			0
			AFL							0	
			MOS		244.5			14 Jun 2004			
			MSC				-				
			[End Of Month Item]								
SL560XL-25-10 Airframe	Equipment/Furnishings - Transmittal of Pacific Scientific Aerospace Service Bulletin Sb 25-1111432, Information Regarding the Potential Failure of the Guarded RotaryBuckle Plastic Handle, Service Letter (Mandatory)		HRS		2978.9			3082			0
			AFL							0	
			MOS		197.2			23 May 2008			
			MSC				A/R				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-25-17	Equipment/Furnishings - Transmittal of Goodrich Service Bulletin 1423-25-003 Revision C Lumbar Assembly Cable Wear, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-25-20	Equipment/Furnishings - Inspection of the Inertial Reel and Restraint System, Service Letter (Mandatory)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			Airframe								
SL560XL-25-21	Equipment/Furnishings - Transmittal of Millennium Service Bulletin SB2050-25-20-09 Model 2050 Seating System Cross Tube Cover Installation, Service Letter (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			Airframe								
SL560XL-25-23	Equipment/Furnishings - Passenger Seat Swivel Plate Swing ARM Assembly Fastener Inspection for Proper Adhesive Application, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			Airframe								
SL560XL-26-02 R01	FIRE Protection - FIRE Bottle Wire Verification and Test, Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156			0
			DATE		13 d			17 Oct 2024			
			MSC				-				
			Airframe								
SL560XL-27-13	Flight Controls - Elevator Trim Cable Inspection, Service Letter (Recommended)		HRS		4775.9			1285			0
			AFL								0
			MOS		232.7			08 Jun 2005			
			MSC				-				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-27-17	Flight Controls - Elevator Trim Wheel Inspection, Service Letter (Recommended)		HRS		2352.9			3708			0
			AFL							0	
			MOS		183.5			14 Jul 2009			
			MSC				A/R				
Airframe			[End Of Month Item]								
SL560XL-27-18	Flight Controls - Elevator Trim Cable Replacement Intervals, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-27-20	Flight Controls - Rudder Torque Tube/Sector Assembly Gap Inspection (Superseded By SL560XL-27-20 R01), Service Letter (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-27-20 R01	Flight Controls - Rudder Torque Tube/Sector Assembly Gap Inspection (Superseded By SL560XL-27-20 R02), Service Letter (Mandatory)		HRS		1644.3			4416.6			0
			AFL		1289			2876			0
			MOS		132.4			17 Oct 2013			
			MSC				-				
(SL560XL-27-20 R1)			[End Of Month Item]								
Airframe											
SL560XL-27-20 R02	Flight Controls - Rudder Torque Tube/Sector Assembly Gap Inspection, Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156			0
			MOS		.4			17 Oct 2024			
			MSC				-				
(SL560XL-27-20 R2)			[End Of Month Item]								
Airframe											
SL560XL-27-21	Flight Controls - Rudder Torque Tube/Sector Assembly Inspection, Service Letter (Mandatory)		HRS		1561.5			4499.4			0
			AFL		1224			2941			0
			MOS		126.7			09 Apr 2014			
			MSC				-				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-27-33	Flight Controls - Elevator Cable Inspection AT the Aft Canted Bulkhead, Service Letter (Mandatory)		HRS		1474.4			4586.5		0	
			AFL		1136			3029		0	
			MOS		117			30 Jan 2015			
			MSC				-				
Airframe		[End Of Month Item]									
SL560XL-27-34 R01	Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection, Service Letter (Mandatory)		HRS		1239.2			4821.7		0	
			AFL		889			3276		0	
			MOS		72.3			22 Oct 2018			
			MSC				-				
(SL560XL-27-34 R1)		[End Of Month Item]									
Airframe											
SL560XL-27-34 R02	Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection, Service Letter (Mandatory)		HRS		19.3			6041.6		0	
			AFL		9			4156		0	
			MOS		.4			17 Oct 2024			
			MSC				-				
Airframe											
SL560XL-27-35	Flight Controls - Aft Aileron Sector Assembly Inspection, Service Letter (Mandatory)		HRS		1410.4			4650.5		0	
			AFL		1058			3107		0	
			MOS								
			DATE		3078 d			27 May 2016			
(560XL-27-35)		MSC				-					
Airframe		[End Of Month Item]									
SL560XL-27-38	Flight Controls - Inspection of the Horizontal Stabilizer Upper Scissor Link Fitting, Service Bulletin (Recommended)		HRS							0	
			AFL							0	
			DATE								
			MSC				-				
Airframe											
SL560XL-27-39	Flight Controls - Control Lock Cable Assembly Swivel Seal Inspection, Service Letter (Recommended)		HRS							0	
			AFL							0	
			DATE								
			MSC				-				
Airframe											
SL560XL-28-05	Fuel - Fuel Boost Pump Inspection (Superseded By SL560XL-28-05 R01), Service Letter (Mandatory)		HRS		1644.3			4416.6		0	
			AFL		1289			2876		0	
			MOS		132.4			17 Oct 2013			
			MSC				-				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-28-05 R01 (SL560XL-28-05 R1) Airframe	Fuel - Fuel Boost Pump Inspection, Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156			0
			MOS		.4			17 Oct 2024			
			MSC				-				
			[End Of Month Item]								
SL560XL-28-07 Airframe	Fuel - 6621102-1 Left Web Corrosion Protection, Service Letter (Recommended)		HRS								0
			AFL								0
			MOS								
			MSC				-				
SL560XL-29-03 Airframe	Hydraulic Power - Engine Hydraulic Hose Inspection, Service Letter (Recommended)		HRS		2185.9			3875			0
			AFL								0
			MOS		178.7			08 Dec 2009			
			MSC				A/R				
			[End Of Month Item]								
SL560XL-29-03 R01 Airframe	Hydraulic Power - Engine Hydraulic Hose Inspection, Service Letter (Recommended)		HRS		864			5196.9			0
			AFL								0
			MOS		47.4			19 Nov 2020			
			MSC				-				
SL560XL-29-05 (560XL-29-05) Airframe	Hydraulic Power - Engine Driven Pump Hydraulic Verification, Service Letter (Recommended)		HRS		980			5080.9			0
			AFL		689			3476			0
			MOS		56.1			26 Feb 2020			
			MSC				-				
			[End Of Month Item]								
SL560XL-31-03 Airframe	Indicating/Recording Systems - Instrument Panel Installation Modification (Superseded By SL560XL-31-03 R01), Service Letter (Discretionary)		HRS		4471.9			1589			0
			AFL								0
			MOS		226.4			19 Dec 2005			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-31-05	Indicating/Recording Systems - Transmittal of L-3 Communications Alert Bulletin No. Cessna Sb 001, Service Letter (Mandatory)		HRS		1706.1			4354.8			0
			AFL		1370			2795			0
			MOS		145.1			28 Sep 2012			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-31-08	Indicating/Recording Systems - Collins Environmental Controller (Iec) and Power Supply (Pwr) Iaps Modules Inspection/Replacement, Service Letter (Recommended)		HRS								0
			AFL								0
			MOS								
			MSC				-				
Airframe											
SL560XL-32-16	Landing Gear - Transmittal of Goodrich Service Bulletin 2-1601-32-4, Landing Gear - Brake Assembly - P/N 2-1601-1, Introduction of New O-Ring, Service Letter (Discretionary)		HRS		2978.9			3082			0
			AFL								0
			MOS		197.2			23 May 2008			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-32-18	Landing Gear - Transmittal of Goodrich Service Bulletins 3-1571-32-2 and 3-1571-32-3, Service Letter (Recommended)		HRS		1765.4			4295.5			0
			AFL		1429			2736			0
			MOS		150.6			11 Apr 2012			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-32-20	Landing Gear - Transmittal of Goodrich Service Letter 2056, Service Letter (Recommended)		HRS		2978.9			3082			0
			AFL		2243			1922			0
			MOS		197.2			23 May 2008			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-32-22 R01	Landing Gear - Landing Gear Component Placard Installation, Service Letter (Optional)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-32-23	Landing Gear - Emergency Gear Release Inspection, Service Letter (Recommended)		HRS		2185.9			3875			0
			AFL							0	
			MOS		178.7			08 Dec 2009			
			MSC				A/R				
Airframe		[End Of Month Item]									
SL560XL-32-24 R01	Landing Gear - Transmittal of Curtiss Wright Sb 049801- 32-01, Landing Gear Control Alternate Led Lighting Bulb (Cancelled), Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
(SL560XL-32-24 R1)		[End Of Month Item]									
Airframe											
SL560XL-32-26	Landing Gear - Replacement of the Cotter Pin for the Emergency Gear-Release, Service Letter (Mandatory)		HRS		1896.4			4164.5			0
			AFL		1519			2646			0
			MOS		160.7			07 Jun 2011			
			MSC				A/R				
Airframe		[End Of Month Item]									
SL560XL-32-30	Landing Gear - Brake Hydraulic Reservoir Sight Glass Fastener Torque Inspection, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-32-32	Landing Gear - Main Landing Gear Components Repair, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-33-08	Lights - Wing Tip Navigation Light Improvements, Service Letter (Informational)		HRS		3745.9			2315			0
			AFL								0
			MOS		212.6			12 Feb 2007			
			MSC				A/R				
Airframe		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-33-10	Lights - Aft Sideledge Divider Light		HRS		1836.4			4224.5			0
	Inspection/Replacement, Service Letter (Recommended)		AFL		1471			2694			0
			MOS		156.4			17 Oct 2011			
			MSC				A/R				
Airframe			[End Of Month Item]								
SL560XL-34-02	Navigation - Reduced Vertical Separation Minimum (RVSM) (Superseded By SL560XL-34-02 R01), Service Letter (Informational)		HRS		5717.9			343			0
			AFL								0
			MOS		253.8			05 Sep 2003			
			MSC				A/R				
Airframe			[End Of Month Item]								
SL560XL-34-07	Navigation - Transmittal of Honeywell Publication Number A21-3440-001, Primus 1000/2000 Integrated Avionics System- AZ840/850 Micro AIR Data Computer (Madc) - Inspect for Presence of Vendor Specific Components and Replace as Required, Service Letter (Recommended)		HRS		5447.9			613			0
			AFL								0
			MOS		247.2			25 Mar 2004			
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-34-11	Navigation - Transmittal of Honeywell Service Bulletin 7014700-34-0040, Service Letter (Recommended)		HRS		5698.9			362			0
			AFL								0
			MOS		252.9			03 Oct 2003			
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-34-13	Navigation - Transmittal of Honeywell Service Bulletin 965 -0976-Xxx-34-70, Enhanced Ground Proximity Warning System (Egpws) (Superseded By SL560XL-34-13 R01), Service Letter (Discretionary)		HRS		5598.9			462			0
			AFL								0
			MOS		250.8			05 Dec 2003			
			MSC				A/R				
Airframe			[End Of Month Item]								
SL560XL-34-18	Navigation - Elementary Surveillance Transponder Product Improvement, Service Letter (Mandatory)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				-				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-34-24	Navigation - Service Information from Honeywell (Superseded By SL560XL-34-24 R01), Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				A/R				
Airframe			[End Of Month Item]								
SL560XL-34-24 R01	Navigation - Service Information from Honeywell, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-34-30	Navigation - Transmittal of Collins Aerospace Service Bulletin Fgc-3XXX-22-Aa - Pitch Trim Failure and/or Chatter AT Start-Up, Service Letter (Optional)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe											
SL560XL-35-04	Oxygen - Transmittal of Intertechnique Service Bulletin Mxh-35-240 (Superseded By SL560XL-35-04 R01), Service Letter (Mandatory)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-35-04 R01	Oxygen - Transmittal of Intertechnique Service Bulletin Mxh-35-240 (Superseded By SL560XL-35-04 R02), Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156		0	
			MOS		.4			17 Oct 2024			
			MSC				-				
Airframe			[End Of Month Item]								
SL560XL-35-04 R02	Oxygen - Transmittal of Intertechnique Service Bulletin Mxh-35-240, Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156		0	
			MOS		.4			17 Oct 2024			
			MSC				-				
Airframe			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-36-01	Pneumatic - Particulate Trap Drain Hole Addition (Superseded By SL560XL-36-01 R01), Service Letter (Recommended)		HRS		6045.9			15		0	
			AFL						0		
			MOS		265.3		21 Sep 2002				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
SL560XL-36-01 R01 (SL560XL-36-01 R1)	Pneumatic - Particulate Trap Drain Hole Addition, Service Letter (Recommended)		HRS		6045.9			15		0	
			AFL						0		
			MOS		265.3		21 Sep 2002				
			MSC			-					
			[End Of Month Item]								
Airframe											
SL560XL-36-03	Pneumatic - APU Bleed AIR Orifice Replacement, Service Letter (Optional)		HRS		4636.9			1424		0	
			AFL						0		
			MOS		229.5		16 Sep 2005				
			MSC			-					
			[End Of Month Item]								
Airframe											
SL560XL-38-01	Water/Waste - Transmittal of Monogram Systems Service Information Letter SIL15900-023, Service Letter (Recommended)		HRS		1644.3			4416.6		0	
			AFL		1289		2876		0		
			MOS		132.4		17 Oct 2013				
			MSC			A/R					
			[End Of Month Item]								
Airframe											
SL560XL-49-13	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8250 Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, Pn 3881825-1 With Pn 3881825-2, for the RE100[Cs] and RE100[XI] Auxiliary Power Unit (APU), Service Letter (Informational)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
			[End Of Month Item]								
(560XL-49-13)											
Airframe											
SL560XL-49-14	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8364 Auxiliary Airborne - Gas Turbine Engine - Replace Wiring Harness Pn 3888395-2 With Pn 3888395-3 on the RE100[XI] Auxiliary Power Unit (APU), Service Letter (Optional)		HRS							0	
			AFL						0		
			DATE								
			MSC			-					
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-52-03	Doors - Cabin Door Annunciation Improvement (Superseded By SL560XL-52-03 R01), Service Letter (Recommended)		HRS		4636.9			1424			0
			AFL								0
			MOS		229.5			16 Sep 2005			
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-52-07	Doors - Exterior Door Switch Improvement, Service Letter (Informational)		HRS								0
			AFL								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-52-08	Doors - Cabin Door Lintel Fastener Verification, Service Letter (Recommended)		HRS		864			5196.9			0
			AFL								0
			MOS		47.4			19 Nov 2020			
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-52-11	Doors - Installation of Protective Sleeve on the Cabin Entry Door Step Light Wire Harness Assembly, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-53-05	Fuselage Stinger Drain Hole Installation, Service Letter (Mandatory)		HRS		4775.9			1285			0
			AFL								0
			MOS		232.7			08 Jun 2005			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-53-06	Fuselage FS 528.50 Frame Drain Hole Installation, Service Letter (Recommended)		HRS		4471.9			1589			0
			AFL								0
			MOS		226.4			19 Dec 2005			
			MSC				-				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-53-17	Fuselage - Dorsal Duct Inspection, Service Letter (Recommended)		HRS		1644.3			4416.6			0
			AFL		1289			2876			0
			MOS		132.4			17 Oct 2013			
			MSC				-				
Airframe	[End Of Month Item]										
SL560XL-53-19	Fuselage - Empennage Fastener Verification, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-53-21	Fuselage - Inspection of the Tailcone Stinger Attach Nutplates for Damage, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-55-01	Stabilizers - Pivot Fitting Inspection (Superseded By SL560XL-55-01 R01), Service Letter (Mandatory)		HRS		19.3			6041.6			0
			AFL		9			4156			0
			MOS		.4			17 Oct 2024			
			MSC				-				
Airframe	[End Of Month Item]										
SL560XL-55-01 R03 (SL560XL-55-01 R3)	Stabilizers - Pivot Fitting Inspection, Service Letter (Cancelled)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe	[End Of Month Item]										
SL560XL-55-03	Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-56-01	Windows - Openable Cockpit Window Hinge and Latch Inspection, Service Letter (Mandatory)		HRS		3770.9			2290			0
			AFL								0
			MOS		213.4			17 Jan 2007			
			MSC				A/R				
Airframe	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-56-03	Windows - Openable Cockpit Window Hinge and Latch Inspection, Service Letter (Mandatory)		HRS								0
			AFL								0
			MOS								
			MSC				A/R				
Airframe	[End Of Month Item]										
SL560XL-71-02 R01 (SL560XL-71-02R1)	Power Plant - Engine Electrical Ground Inspection for Rtv, Service Letter (Recommended)		HRS		5912.9			148			0
			AFL								0
			MOS		259.1			27 Mar 2003			
			MSC				-				
Airframe	[End Of Month Item]										
SL560XL-71-06	Power Plant - Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30248 Turbofan Engine Front Fan Case Assembly Vibration Damper Ring-Installation, Service Letter (Recommended)		HRS		4471.9			1589			0
			AFL								0
			MOS		226.4			19 Dec 2005			
			MSC				A/R				
Airframe	[End Of Month Item]										
SL560XL-71-07	Power Plant - Transmittal of Pratt and Whitney Canada (P&WC) Special Instruction Number 17-2005, PW500 Auto Shut - Off Mechanism Inspection., Service Letter (Mandatory)		HRS		4300.9			1760			0
			AFL								0
			MOS		223.1			26 Mar 2006			
			MSC				A/R				
Airframe	[End Of Month Item]										
SL560XL-71-08	Power Plant - Bleed AIR Tube Sleeving Installation Improvement, Service Letter (Recommended)		HRS		4253.9			1807			0
			AFL								0
			MOS		221.7			07 May 2006			
			MSC				-				
Airframe	[End Of Month Item]										
SL560XL-71-11	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes, Service Letter		HRS								0
			AFL								0
			MOS								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-71-11 R01	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes, Service Letter (Recommended)		HRS								0
			AFL								0
			DATE								
			MSC				-				
Airframe											
SL560XL-71-11 R02	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes, Service Letter (Recommended)		HRS								0
			AFL								0
			MOS								
			MSC				-				
Airframe											
SL560XL-72-11	Right Engine Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement of (Superseded By SL560XL-72-11 R01), Service Letter (Recommended)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-72-11	Left Engine Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement of (Superseded By SL560XL-72-11 R01), Service Letter (Recommended)		HRS		3566.9			2494			0
			AFL								0
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-72-12	Engine - Transmittal of Pratt and Whitney Canada Service Bulletin PW500-72-30331 Modification of Fuel Pressure Hose and Tube Routing, Service Letter (Optional)		HRS		2000.7			4060.2			0
			AFL		1616			2549			0
			MOS		168.6			11 Oct 2010			
			MSC				A/R				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-72-13	Left Engine Transmittal of Pratt and Whitney Canada		HRS		2940.9			3120			0
	Service Bulletin PW500-72-30335 Turbofan Engine Gas-		AFL								0
	Generator-Case to Intermediate-Case Retaining-Bolts		MOS		197.2			23 May 2008			
	BorescopeInspection of, Service Letter (Recommended)		MSC				A/R				
(SL560XL-72-13L)			[End Of Month Item]								
Airframe											
SL560XL-72-13	Right Engine Transmittal of Pratt and Whitney Canada		HRS		2940.9			3120			0
	Service Bulletin PW500-72-30335 Turbofan Engine Gas-		AFL								0
	Generator-Case to Intermediate-Case Retaining-Bolts		MOS		197.2			23 May 2008			
	BorescopeInspection of, Service Letter (Recommended)		MSC				A/R				
(SL560XL-72-13R)			[End Of Month Item]								
Airframe											
SL560XL-72-14	Right Engine Transmittal of Pratt & Whitney Canada		HRS		2978.9			3082			0
	Service Bulletin PW500-72-30306 Turbofan Engine New		AFL								0
	Transfer Tubes With Heat Shield, Service Letter		MOS		197.2			23 May 2008			
	(Recommended)		MSC				A/R				
(SL560XL-72-14R)			[End Of Month Item]								
Airframe											
SL560XL-72-14	Left Engine Transmittal of Pratt & Whitney Canada		HRS		2978.9			3082			0
	Service Bulletin PW500-72-30306 Turbofan Engine New		AFL								0
	Transfer Tubes With Heat Shield, Service Letter		MOS		197.2			23 May 2008			
	(Recommended)		MSC				A/R				
(SL560XL-72-14L)			[End Of Month Item]								
Airframe											
SL560XL-73-03	Engine Fuel and Control - Transmittal of P&WC Service		HRS		5368.9			692			0
	Bulletin 30249 Turbofan Engine Fuel Manifold -		AFL								0
	Inspection/Replacement of and Commercial Support		MOS		244.5			14 Jun 2004			
	Program Notification (Cspn) A03008, Service Letter		MSC				-				
(Recommended)			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-73-04	Engine Fuel and Control - Transmittal of Pratt & Whitney		HRS		5598.9			462			0
	Canada Service Bulletin 30253: Turbofan Engine Fuel		AFL								0
	Pressure Tube Replacement and Attenuator Introduction		MOS		250.9			03 Dec 2003			
	of Model Application PW545A and Commercial Support		MSC				A/R				
	Program Notification (Cspn) A03012 (Superseded By		[End Of Month Item]								
SL560XL-73-04 R01), Service Letter (Recommended)											
Airframe											
SL560XL-73-08	Engine Fuel and Control - Transmittal of Pratt & Whitney		HRS		4152.9			1908			0
	Canada Service Bulletin Number 30296R1, Turbofan		AFL								0
	Engine Hfc Ratio Unit Setscrew Adjustment - Inspection		MOS		220			29 Jun 2006			
	of, Service Letter (Mandatory)		MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-73-12	Engine Fuel and Control - Transmittal of Pratt and		HRS		2000.7			4060.2	0		0
	Whitney Canada Service Bulletin PW500-72-30381R2,		AFL		1616			2549	0		0
	Fuel Manifold and Fuel Shut-Off Cable Grommets and		MOS		168.6			11 Oct 2010			
	CoverPlate/Fairing/Replacement of (Superseded By		MSC				A/R				
	SL560XL-73-12 R01), Service Letter (Recommended)		[End Of Month Item]								
Airframe											
SL560XL-73-12 R01	Engine Fuel and Control - Transmittal of Pratt and		HRS								0
	Whitney Canada Service BulletinPW500-72-30381R2,		AFL								0
	Fuel Manifold and Fuel Shut-Off Cable Grommets and		DATE								
	Cover Plate/Fairing/Replacement of, Service Letter		MSC				A/R				
	(Recommended)		[End Of Month Item]								
(SL560XL-73-12 R1)											
Airframe											
SL560XL-76-05	Engine Controls - Inspection of the Right Engine Throttle		HRS								0
	Quadrant Rotary Variable Differential Transformer (Rvdt)		AFL								0
	Electrical Wiring, Service Letter (Mandatory)		DATE								
			MSC				-				
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-78-04	Exhaust - Thrust Reverser Stow Limit Switch Test (Superseded By SL560XL-78-04 R01), Service Letter (Informational)		HRS		3566.9			2494			0
			AFL							0	
			MOS		208.4			19 Jun 2007			
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-99-01 R04 (SL560XL-99-01 R4)	Cescom Prices, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-99-03 R01 (SL560XL-99-03 R1)	Miscellaneous - Transmittal of Cessna'S Certification Requirements for Portable Electronic Device Usage, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											
SL560XL-99-04	Miscellaneous - Cessna Part Number Suffixes for Remanufactured Parts, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-99-05	Miscellaneous - Cessna Service Document Change Notification, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Airframe											
SL560XL-99-07 (99-07)	Miscellaneous - Transmittal of Rockwell Collins Operators Bulletin (Opsb) 0166-17 - the FMS May Turn In the Wrong Direction after Sequencing A "Climb to" Altitude that Was Manually Edited or Temperature Compensated, Service Letter (Informational)		HRS								0
			AFL							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Airframe											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
SL560XL-99-08	Miscellaneous - Transmittal of Textron Aviation'S		HRS								0
	Certification Requirements for Portable Electronic Device		AFL								0
	Usage for the Model 560XL (Citation Excel and Xls) With		DATE								
	the Garmin G5000 STC Installed By Textron Aviation, Service Letter (Informational)		MSC				-				

Airframe

SIAE - APU/Engine Service Information/Bulletins											
3615880-49-8149 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, Pn 3615880-1, Pn 3615880-002, Pn 3615880-3, and Pn 3615880-4, on Multiple Apus, Service Bulletin (Recommended)		HRS								0
			APUS							0	
			DATE								
			MSC				-				
(8149 R2)			[End Of Month Item]								
APU											
3822101-49-8148 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, Pn 3822101-1, on Multiple Apus, Service Bulletin (Recommended)		HRS								0
			APUS							0	
			DATE								
			MSC				-				
(8148 R2)			[End Of Month Item]								
APU											
3881800-49-7523 R04	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch, Pn 3876255-2 With Pn 3876351-1 and Reidentify Lube Pump from Pn 3881800-1 to Pn 3881825-1, on RE100[XI] and RE100[Lj] Apus, Service Bulletin (Recommended)		HRS								0
			APUS							0	
			DATE								
			MSC				-				
(D200002000032 R4)			[End Of Month Item]								
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
3883900-49-7976 R02	APU - Airborne Auxiliary Power - Main Fuel Control Unit (Fcu) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, Pn 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required AT Next Auxiliary Power Unit (APU) Shop Visit, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				ESV**				
(D200902000078 R02)											
APU											
3883900-49-8297	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Seal, Pn 3883905-1, With Pn 70722907-1 on the Fuel Control Unit (Fcu), Pn 3883900-1 for the RE100 APU, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201812000015)											
APU											
49-7933 R08	APU - Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils, Service Bulletin		HRS								0
			APUS								0
			DATE								
			MSC				-				
(7933 R8)											
APU	[End Of Month Item]										
49-7997 R05	APU - Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines, Service Bulletin		HRS								0
			APUS								0
			DATE								
			MSC				-				
(7997 R05)	[End Of Month Item]										
APU											
70721598-49-8168 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, Pn 70721598-1, on Multiple Apus, Service Bulletin (Recommended)		HRS								0
			APUS								0
			MOS								
			MSC				-				
(D201506000010 R01)	[End Of Month Item]										
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
70721598-49-8168 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, Pn 70721598-1, on Multiple Apus, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(8168 R2)			[End Of Month Item]								
APU											
70721725-49-8152 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, Pn 70721725-2 and Pn 70721725-5, on Multiple Apus, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(8152 R2)			[End Of Month Item]								
APU											
APU-49 R10	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D199912000065 R10)			[End Of Month Item]								
APU											
APU-49 R11	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
APU											
APU-49 R12	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
APU-49 R13	APU - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
APU											
GEN-153 R06	No. 1 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R06	No. 2 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R07	No. 1 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R07	No. 2 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R08	No. 1 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
GEN-153 R08	No. 2 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R09	No. 1 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R09	No. 2 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R10	No. 1 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
GEN-153 R10	No. 2 Engine - P&WC'S Oil Analysis Technology Service Logistics Information, Service Information Letter (Informational)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30060	No. 1 Engine - Vibration Damper/Insulation Blanket- Removal of-Compressor Stator Assembly-Replacement of (Superseded By PW500-72-30060 R01), Service Bulletin (Superseded)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30073 R01 (72-30073 R1) Engine	No. 1 Engine - Replacement of T1/Fcu Temperature Sensor, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30073 R01 (72-30073 R1) Engine	No. 2 Engine - Replacement of T1/Fcu Temperature Sensor, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30075 R01 (72-30075 R1) Engine	No. 1 Engine - Replacement of Mounting Hardware, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30075 R01 (72-30075 R1) Engine	No. 2 Engine - Replacement of Mounting Hardware, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30084 R02 Engine	No. 1 Engine - Replacement of Fan Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30084 R02 Engine	No. 2 Engine - Replacement of Fan Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30097 R03 Engine	No. 1 Engine - Replacement of Turbine Case and Turbine Vane Ring Assemblies, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30097 R03	No. 2 Engine - Replacement of Turbine Case and Turbine Vane Ring Assemblies, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30115	No. 1 Engine - Inspection of Intercompressor Bleed Valve Servo to P10 Connector, Service Bulletin (Category 4)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30115	No. 2 Engine - Inspection of Intercompressor Bleed Valve Servo to P10 Connector, Service Bulletin (Category 4)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30126 R02 (72-30126 R2)	No. 1 Engine - Replacement of Intermediate Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30126 R02 (72-30126 R2)	No. 2 Engine - Replacement of Intermediate Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30131 R02	No. 1 Engine - Replacement of Cold Start Valve Assembly, Service Bulletin (Category 3)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine [End Of Month Item]											
PW500-72-30131 R02	No. 2 Engine - Replacement of Cold Start Valve Assembly, Service Bulletin (Category 3)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine [End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30141 R01	No. 1 Engine - Replacement/Modification of Compressor Stator Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30141 R01	No. 2 Engine - Replacement/Modification of Compressor Stator Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30151 R02	No. 1 Engine - Replacement/Modification of Gas Generator Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30151 R02	No. 2 Engine - Replacement/Modification of Gas Generator Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30151 R03	No. 1 Engine - Replacement/Modification of Gas Generator Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30151 R03	No. 2 Engine - Replacement/Modification of Gas Generator Case, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30156 R01 (72-30156 R1)	No. 1 Engine - Replacement of Anti-Icing Valve, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30156 R01 (72-30156 R1) Engine	No. 2 Engine - Replacement of Anti-Icing Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30157 R01 Engine	No. 1 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30157 R01 Engine	No. 2 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30157 R02 Engine	No. 1 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30157 R02 Engine	No. 2 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30158 R01 (72-30158 R1) Engine	No. 1 Engine - Replacement of High Pressure Compressor Shaft, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30158 R01 (72-30158 R1) Engine	No. 2 Engine - Replacement of High Pressure Compressor Shaft, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30169 R02 (72-30169 R2) Engine	No. 1 Engine - Replacement of Fuel Nozzle, Service Bulletin (Category 7)		HRS		975.6			5085.3		0	
			ENC		682		3458		0		
			MOS		56.7		08 Feb 2020				
			MSC			-					
			[End Of Month Item]								
PW500-72-30169 R02 (72-30169 R2) Engine	No. 2 Engine - Replacement of Fuel Nozzle, Service Bulletin (Category 7)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					
			[End Of Month Item]								
PW500-72-30176 R02 (72-30176 R2) Engine	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					
			[End Of Month Item]								
PW500-72-30176 R02 (72-30176 R2) Engine	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					
			[End Of Month Item]								
PW500-72-30182 R02 (PW500-72-30182 R2) Engine	No. 1 Engine - Replacement/Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					
			[End Of Month Item]								
PW500-72-30182 R02 (PW500-72-30182 R2) Engine	No. 2 Engine - Replacement/Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					
			[End Of Month Item]								
PW500-72-30190 R01 Engine	No. 1 Engine - Replacement/Modification of Turbofan Engine - Lp Turbine Second-Stage Vane Assembly, Service Bulletin (Category 6)		HRS							0	
			ENC							0	
			DATE								
			MSC			-					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30190 R01	No. 2 Engine - Replacement/Modification of Turbofan Engine - Lp Turbine Second-Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30202 R02 (72-30202 R2)	No. 1 Engine - Introduction of RE-Profiled Grafoil Gaskets, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30202 R02 (72-30202 R2)	No. 2 Engine - Introduction of RE-Profiled Grafoil Gaskets, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30203 R01 (72-30203 R1)	No. 1 Engine - Replacement of Alternator Shaft Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30203 R01 (72-30203 R1)	No. 2 Engine - Replacement of Alternator Shaft Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30205 R01 (PW500-72-30205 R1)	No. 1 Engine - Replacement of Lpt Second-Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30205 R01 (PW500-72-30205 R1)	No. 2 Engine - Replacement of Lpt Second-Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30215 R02 (PW500-72-30215 R2) Engine	No. 1 Engine - Modification/Rework of Turbine Exhaust Case, Service Bulletin (Category 6)		HRS ENC DATE MSC								0 0
							-				
PW500-72-30215 R02 (PW500-72-30215 R2) Engine	No. 2 Engine - Modification/Rework of Turbine Exhaust Case, Service Bulletin (Category 6)		HRS ENC DATE MSC								0 0
							-				
PW500-72-30221 R02 Engine	No. 1 Engine - Replacement of T1/Fcu Temperature Sensor, Service Bulletin (Category 8)		HRS ENC MOS MSC [End Of Month Item]		975.6 707 56.6			5085.3 3433 10 Feb 2020			0 0
							-				
PW500-72-30221 R02 Engine	No. 2 Engine - Replacement of T1/Fcu Temperature Sensor, Service Bulletin (Category 8)		HRS ENC MOS MSC [End Of Month Item]		975.6 682 56.6			5085.3 3458 10 Feb 2020			0 0
							-				
PW500-72-30226 R02 Engine	No. 1 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS ENC MOS MSC		975.6 682 56.7			5085.3 3458 08 Feb 2020			0 0
							-				
PW500-72-30226 R02 Engine	No. 2 Engine - Replacement of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS ENC MOS MSC		975.6 682 56.6			5085.3 3458 10 Feb 2020			0 0
							-				
PW500-72-30238 Engine	No. 1 Engine - Replacement of 2ND and 3RD Stage Low Pressure Turbine Rotor Blade-Retaiing-Rivets, Service Bulletin (Category 6)		HRS ENC MOS MSC [End Of Month Item]		975.6 682 56.7			5085.3 3458 08 Feb 2020			0 0
							-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30238	No. 2 Engine - Replacement of 2ND and 3RD Stage Low Pressure Turbine Rotor Blade-Retaiing-Rivets, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30240 R04 (72-30240 R4)	No. 1 Engine - Replacement of Alternator Shaft Plain Seal, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30240 R04 (72-30240 R4)	No. 2 Engine - Replacement of Alternator Shaft Plain Seal, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30242 R04	No. 1 Engine - Replacement/Field Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30242 R04	No. 2 Engine - Replacement/Field Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30245 R05 (72-30245 R5)	No. 1 Engine - Replacement of Starter-Generator-Drive Gearshaft and Plain Seal, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30245 R05 (72-30245 R5) Engine	No. 2 Engine - Replacement of Starter-Generator-Drive Gearshaft and Plain Seal, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30262 R01 (PW500-72-30262 R1) Engine	No. 1 Engine - Modification of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30262 R01 (PW500-72-30262 R1) Engine	No. 2 Engine - Modification of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30266 R01 Engine	No. 1 Engine - Replacement/Modification of Ignition Exciter, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
PW500-72-30266 R01 Engine	No. 2 Engine - Replacement/Modification of Ignition Exciter, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
			[End Of Month Item]								
PW500-72-30267 R04 Engine	No. 1 Engine - Replacement of Inlet Compressor Vane Rings, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30267 R04 Engine	No. 2 Engine - Replacement of Inlet Compressor Vane Rings, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30267 R05	No. 1 Engine - Replacement of Inlet Compressor Vane Rings, Service Bulletin (Category 5)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30267 R05	No. 2 Engine - Replacement of Inlet Compressor Vane Rings, Service Bulletin (Category 5)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30270 R01 (72-30270 R1)	No. 1 Engine - Replacement of Turbine Exhaust Case Assy, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30270 R01 (72-30270 R1)	No. 2 Engine - Replacement of Turbine Exhaust Case Assy, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30271	No. 1 Engine - Modification/Replacement of Fan Rotor Balancing Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30271	No. 2 Engine - Modification/Replacement of Fan Rotor Balancing Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30271 R01	No. 1 Engine - Modification/Replacement of Fan Rotor Balancing Assy, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30271 R01	No. 2 Engine - Modification/Replacement of Fan Rotor Balancing Assy, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30280	No. 1 Engine - Replacement/Inspection of Oil Pump Gearshaft Spur, Service Bulletin (Category 8)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30280	No. 2 Engine - Replacement/Inspection of Oil Pump Gearshaft Spur, Service Bulletin (Category 8)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine [End Of Month Item]											
PW500-72-30281 R02	No. 1 Engine - Replacement of Fuel Nozzle Gasket, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30281 R2) Engine [End Of Month Item]											
PW500-72-30281 R02	No. 2 Engine - Replacement of Fuel Nozzle Gasket, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30281 R2) Engine [End Of Month Item]											
PW500-72-30288 R02	No. 1 Engine - Modification of Turbine Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
Engine [End Of Month Item]											
PW500-72-30288 R02	No. 2 Engine - Modification of Turbine Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
Engine [End Of Month Item]											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30288 R03	No. 1 Engine - Modification of Turbine Case Assembly (This Sb Is Superseded By P&WC S.B. No. 30284), Service Bulletin (Superseded)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30288 R03	No. 2 Engine - Modification of Turbine Case Assembly (This Sb Is Superseded By P&WC S.B. No. 30284), Service Bulletin (Superseded)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30291 R01	No. 1 Engine - Replacement of First Stage High Compressor Rotor, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30291 R01	No. 2 Engine - Replacement of First Stage High Compressor Rotor, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30294 R02	No. 1 Engine - Inspection of Oil Tank Filler CAP, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30294 R02	No. 2 Engine - Inspection of Oil Tank Filler CAP, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30294 R02 PART (A)	No. 1 Engine - Inspect Inspection of Oil Tank Filler CAP, Service Bulletin Using Finger (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30294 R02 PART (A)	No. 2 Engine - Inspect Inspection of Oil Tank Filler CAP, Service Bulletin Using Finger (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30294 R02 PART (B)	No. 1 Engine - Inspect Inspection of Oil Tank Filler CAP, Service Bulletin Using Torque Wrench (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30294 R02 PART (B)	No. 2 Engine - Inspect Inspection of Oil Tank Filler CAP, Service Bulletin Using Torque Wrench (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30296 R03	No. 1 Engine - Inspection of Hfc Ratio Unit Setscrew Adjustment, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30296 R03	No. 2 Engine - Inspection of Hfc Ratio Unit Setscrew Adjustment, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30300 R03	No. 1 Engine - Replacement of Oil Pump Plain Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30300 R03	No. 2 Engine - Replacement of Oil Pump Plain Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine	[End Of Month Item]										
PW500-72-30306 R05	No. 1 Engine - New Transfer Tubes With Heat Shield, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(PW500-72-30306 R5)	[End Of Month Item]										
Engine											
PW500-72-30306 R05	No. 2 Engine - New Transfer Tubes With Heat Shield, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(PW500-72-30306 R5)	[End Of Month Item]										
Engine											
PW500-72-30308	No. 1 Engine - Replacement Compressor Retaining Nut, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine	[End Of Month Item]										
PW500-72-30308	No. 2 Engine - Replacement Compressor Retaining Nut, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine	[End Of Month Item]										
PW500-72-30309 R04	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine	[End Of Month Item]										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30309 R04	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30323	No. 1 Engine - Fan Case With Additional Drain Holes - on-Wing Modification, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30323	No. 2 Engine - Fan Case With Additional Drain Holes - on-Wing Modification, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30325 R03	No. 1 Engine - Replacement of Oil-Pump Plain Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
(PW500-72-30325 R3) Engine			[End Of Month Item]								
PW500-72-30325 R03	No. 2 Engine - Replacement of Oil-Pump Plain Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30325 R3) Engine			[End Of Month Item]								
PW500-72-30326	No. 1 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30326	No. 2 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30327	No. 1 Engine - Replacement of No. 4 Bearing Carbon Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			Engine	[End Of Month Item]							
PW500-72-30327	No. 2 Engine - Replacement of No. 4 Bearing Carbon Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			Engine	[End Of Month Item]							
PW500-72-30331	No. 2 Engine - Modification of Fuel Pressure Hose & Tube Routing, Service Bulletin (Category 5)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			Engine	[End Of Month Item]							
PW500-72-30332 R02	No. 1 Engine - Replacement of Accessory Gearbox Drive Shaft Annular Ball Bearing, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
			Engine	[End Of Month Item]							
PW500-72-30332 R02	No. 2 Engine - Replacement of Accessory Gearbox Drive Shaft Annular Ball Bearing, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
			Engine	[End Of Month Item]							
PW500-72-30332 R03	No. 1 Engine - Replacement of Accessory Gearbox Drive Shaft Annular Ball Bearing, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			Engine								
PW500-72-30332 R03	No. 2 Engine - Replacement of Accessory Gearbox Drive Shaft Annular Ball Bearing, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			Engine								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30332 R04	No. 1 Engine - Replacement of Accessory Gearbox Drive- Shaft Annular Ball-Bearing, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30332 R04	No. 2 Engine - Replacement of Accessory Gearbox Drive- Shaft Annular Ball-Bearing, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30334 R03	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30334 R03	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30336 R01	No. 1 Engine - Replacement / Modification of Hydromechanical Fuel Control, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30336 R1)			[End Of Month Item]								
Engine											
PW500-72-30336 R01	No. 2 Engine - Replacement / Modification of Hydromechanical Fuel Control, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30336 R1)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30339 R02	No. 1 Engine - Replacement/Modification of Front Fan Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30339 R02	No. 2 Engine - Replacement/Modification of Front Fan Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30340 R02	No. 1 Engine - Replacement of Igniters and Ignition Cables, Service Bulletin (Category 7)		HRS		1706.1			4354.8			0
			ENC		1345			2795		0	
			MOS		145.1			28 Sep 2012			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30340 R02	No. 2 Engine - Replacement of Igniters and Ignition Cables, Service Bulletin (Category 7)		HRS		1706.1			4354.8			0
			ENC		1345			2795		0	
			MOS		145.1			28 Sep 2012			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30343 R05	No. 1 Engine - Replacement of Servo Valve for the Intercompressor-Bleed-Valve (Superseded By PW500-72-30343 R06), Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30343 R05	No. 2 Engine - Replacement of Servo Valve for the Intercompressor-Bleed-Valve (Superseded By PW500-72-30343 R06), Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30343 R06 (72-30343 R6) Engine	No. 1 Engine - Replacement of Servo Valve for the Intercompressor-Bleed-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30343 R06 (72-30343 R6) Engine	No. 2 Engine - Replacement of Servo Valve for the Intercompressor-Bleed-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30344 R01 (72-30344 R1) Engine	No. 1 Engine - Replacement of Various Cadmium Plated Parts, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30344 R01 (72-30344 R1) Engine	No. 2 Engine - Replacement of Various Cadmium Plated Parts, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30353 R01 Engine	No. 1 Engine - Replacement of Intershaft Carbon Seals, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30353 R01 Engine	No. 2 Engine - Replacement of Intershaft Carbon Seals, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30356 R02	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control With Additional Protective Screens, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30356 R2)			[End Of Month Item]								
Engine											
PW500-72-30356 R02	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control With Additional Protective Screens, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30356 R2)			[End Of Month Item]								
Engine											
PW500-72-30362	No. 1 Engine - Replacement Hp Turbine Disk Balancing Assembly With Thicker Feather Seals , Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30362	No. 2 Engine - Replacement Hp Turbine Disk Balancing Assembly With Thicker Feather Seals , Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30364 R01	No. 1 Engine - Replacement Accessory Gearbox Plain Seals, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30364 R01	No. 2 Engine - Replacement Accessory Gearbox Plain Seals, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30364 R02	No. 1 Engine - Accessory Gearbox Plain Seals - Replacement, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30364 R02	No. 2 Engine - Accessory Gearbox Plain Seals - Replacement, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30364 R03	No. 1 Engine - Replacement of Accessory Gearbox Plain Seals, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30364 R03	No. 2 Engine - Replacement of Accessory Gearbox Plain Seals, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30369 R01	No. 1 Engine - Replacement/Modification Oil Pump Assembly With A New Rear Oil Pump Housing, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30369 R01	No. 2 Engine - Replacement/Modification Oil Pump Assembly With A New Rear Oil Pump Housing, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30371 R02	No. 1 Engine - Introduction Accessory Gearbox Fcu- Starter Gearshaft Oil Baffle, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30371 R2)		[End Of Month Item]									
Engine											
PW500-72-30371 R02	No. 2 Engine - Introduction Accessory Gearbox Fcu- Starter Gearshaft Oil Baffle, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30371 R2)		[End Of Month Item]									
Engine											
PW500-72-30376 R02	No. 1 Engine - Replacement/Modification of Oil Pump Assembly and Oil-Pump-Drive Spur Gear, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30376 R2)		[End Of Month Item]									
Engine											
PW500-72-30376 R02	No. 2 Engine - Replacement/Modification of Oil Pump Assembly and Oil-Pump-Drive Spur Gear, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30376 R2)		[End Of Month Item]									
Engine											
PW500-72-30384 R01	No. 1 Engine - Replacement of AIR/Oil Separator, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
Engine		[End Of Month Item]									
PW500-72-30384 R01	No. 2 Engine - Replacement of AIR/Oil Separator, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
Engine		[End Of Month Item]									

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (* =Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30387 R06 (PW500-72-30387 R6) Engine	No. 1 Engine - Replacement / Modification Rear By-PASS Duct Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30387 R06 (PW500-72-30387 R6) Engine	No. 2 Engine - Replacement / Modification Rear By-PASS Duct Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30389 Engine	No. 1 Engine - Replacement of Carbon Seal, No. 4 Bearing, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30389 Engine	No. 2 Engine - Replacement of Carbon Seal, No. 4 Bearing, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30390 R05 (30390 R5) Engine	No. 1 Engine - Cavitation Repair Hydromechanical Fuel Control Unit (Superseded By PW500-72-30409 R08), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30390 R05 (30390 R5) Engine	No. 2 Engine - Cavitation Repair Hydromechanical Fuel Control Unit (Superseded By PW500-72-30409 R08), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30398	No. 1 Engine - Replacement of Bolts, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30398	No. 2 Engine - Replacement of Bolts, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30400 R04	No. 1 Engine - Replacement of Intermediate Case Assembly and Intershaft Seal Carrier, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
(72-30400 R4)											
Engine											
PW500-72-30400 R04	No. 2 Engine - Replacement of Intermediate Case Assembly and Intershaft Seal Carrier, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
(72-30400 R4)											
Engine											
PW500-72-30403 R03	No. 1 Engine - Replacement of Tee Head Bolt/1ST- 2ND Stage Hp Compressor Assemblies, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(PW500-72-30403 R3)											
Engine											
PW500-72-30403 R03	No. 2 Engine - Replacement of Tee Head Bolt/1ST- 2ND Stage Hp Compressor Assemblies, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(PW500-72-30403 R3)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30403 R04	No. 1 Engine - Replacement of Tee Head Bolt/1ST.- 2ND. Stage Hp Compressor Assemblies, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30403 R04	No. 2 Engine - Replacement of Tee Head Bolt/1ST.- 2ND. Stage Hp Compressor Assemblies, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30404 R03	No. 1 Engine - Replacement of Servo Valve for the Intercompressor Bleed-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30404 R03	No. 2 Engine - Replacement of Servo Valve for the Intercompressor Bleed-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30405 R04	No. 1 Engine - Replacement of Fuel Nozzle Manifold, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(PW500-72-30405 R4)			[End Of Month Item]								
Engine											
PW500-72-30405 R04	No. 2 Engine - Replacement of Fuel Nozzle Manifold, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30405 R4)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30408	No. 1 Engine - Replacement of Engine Gasket, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30408	No. 2 Engine - Replacement of Engine Gasket, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30409	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit (Superseded By PW500-72-30409 R01), Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
(30409)											
Engine											
PW500-72-30409 R10	No. 1 Engine - Replacement / Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
			[End Of Month Item]								
(72-30409 R10)											
Engine											
PW500-72-30409 R10	No. 2 Engine - Replacement / Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
			[End Of Month Item]								
(72-30409 R10)											
Engine											
PW500-72-30413	No. 1 Engine - Introduction of Deeper Sump (Superseded By PW500-72-30413 R01), Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				A/R				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30413 R10 (72-30413 R10) Engine	No. 1 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30413 R10 (72-30413 R10) Engine	No. 2 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30413 R11 Engine	No. 1 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
PW500-72-30413 R11 Engine	No. 2 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
PW500-72-30413 R12 Engine	No. 1 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30413 R12 Engine	No. 2 Engine - Introduction of Deeper Sump, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30414 Engine	No. 1 Engine - Replacement of Servo Valve for the Intercompressor Bleed-Valve, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30414	No. 2 Engine - Replacement of Servo Valve for the Intercompressor Bleed-Valve, Service Bulletin (Category 10)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
			[End Of Month Item]								
Engine											
PW500-72-30415 R03 (72-30415 R3)	No. 1 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30415 R03 (72-30415 R3)	No. 2 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30415 R04	No. 1 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30415 R04	No. 2 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30416 R01 (72-30416 R1)	No. 1 Engine - Replacement of No.4 Bearing Carbon Seal, Service Bulletin (Category 10)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30416 R01 (72-30416 R1)	No. 2 Engine - Replacement of No.4 Bearing Carbon Seal, Service Bulletin (Category 10)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30417 R08	No. 1 Engine - Replacement of Front Seal Runner, No. 4 Bearing, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30417 R08	No. 2 Engine - Replacement of Front Seal Runner, No. 4 Bearing, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30419 R01 (72-30419 R1)	No. 1 Engine - Replacement of Combustion Chamber Liner, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30419 R01 (72-30419 R1)	No. 2 Engine - Replacement of Combustion Chamber Liner, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30420	No. 1 Engine - Replacement/Modification of Intercompressor Bleed Valve/ Servo-Valve (Superseded By PW500-72-30420 R01), Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30420 R05 (PW500-72-30420 R5)	No. 1 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								
PW500-72-30420 R05 (PW500-72-30420 R5)	No. 2 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
	Engine		[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30420 R06	No. 1 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30420 R06	No. 2 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30423	No. 1 Engine - Replacement/Modification Intermediate Case Assembly (Superseded By PW500-72-30423 R01), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
[End Of Month Item]											
Engine											
PW500-72-30423	No. 2 Engine - Replacement/Modification Intermediate Case Assembly (Superseded By PW500-72-30423 R01), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				A/R				
[End Of Month Item]											
Engine											
PW500-72-30423 R01	No. 1 Engine - Replacement/Modification Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
[End Of Month Item]											
Engine											
PW500-72-30423 R01	No. 2 Engine - Replacement/Modification Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
[End Of Month Item]											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30425 R03 (72-30425 R3) Engine	No. 1 Engine - Replacement of No. 4 Bearing Carbon Seal, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30425 R03 (72-30425 R3) Engine	No. 2 Engine - Replacement of No. 4 Bearing Carbon Seal, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30427 R01 Engine	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly (Superseded By PW500-72-30427 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30427 R01 Engine	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly (Superseded By PW500-72-30427 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30427 R02 Engine	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly (Superseded By PW500-72-30427 R03), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30427 R02 Engine	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly (Superseded By PW500-72-30427 R03), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30427 R03	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30427 R03	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30427 R04	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30427 R04	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30428 R05	No. 1 Engine - Replacement of Fuel Manifold System Interface, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(PW500-72-30428 R5)			[End Of Month Item]								
Engine											
PW500-72-30428 R05	No. 2 Engine - Replacement of Fuel Manifold System Interface, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(PW500-72-30428 R5)			[End Of Month Item]								
Engine											
PW500-72-30428 R06	No. 1 Engine - Replacement of Fuel Manifold System Interface, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30428 R06	No. 2 Engine - Replacement of Fuel Manifold System Interface, Service Bulletin (Category 6)		HRS		975.6			5085.3		0	
			ENC		682		3458		0		
			MOS		56.6		10 Feb 2020				
			MSC			-					
Engine											
PW500-72-30429 R06	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS							0	
			ENC						0		
			DATE								
			MSC			-					
(PW500-72-30429 R6)											
Engine [End Of Month Item]											
PW500-72-30429 R06	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS							0	
			ENC						0		
			DATE								
			MSC			-					
(PW500-72-30429 R6)											
Engine [End Of Month Item]											
PW500-72-30432	No. 1 Engine - Plain Seal Accessory Gearbox - Replacement of (Superseded By PW500-72-30432 R01), Service Bulletin (Category 7)		HRS							0	
			ENC						0		
			DATE								
			MSC			A/R					
[End Of Month Item]											
Engine											
PW500-72-30432	No. 2 Engine - Plain Seal Accessory Gearbox - Replacement of (Superseded By PW500-72-30432 R01), Service Bulletin (Category 7)		HRS							0	
			ENC						0		
			DATE								
			MSC			A/R					
[End Of Month Item]											
Engine											
PW500-72-30432 R01	No. 1 Engine - Plain Seal Accessory Gearbox - Replacement of, Service Bulletin (Category 7)		HRS							0	
			ENC						0		
			DATE								
			MSC			A/R					
[End Of Month Item]											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30432 R01	No. 2 Engine - Plain Seal Accessory Gearbox - Replacement of, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				A/R				
Engine			[End Of Month Item]								
PW500-72-30436 R04	No. 1 Engine - Replacement/Modification of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(PW500-72-30436 R4)			[End Of Month Item]								
Engine											
PW500-72-30436 R04	No. 2 Engine - Replacement/Modification of Lpt 2ND Stage Vane Assembly, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30436 R4)			[End Of Month Item]								
Engine											
PW500-72-30440 R05	No. 1 Engine - Replacement of New or Modified Oil Tank Vent Tube Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30440 R5)			[End Of Month Item]								
Engine											
PW500-72-30440 R05	No. 2 Engine - Replacement of New or Modified Oil Tank Vent Tube Assembly, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30440 R5)			[End Of Month Item]								
Engine											
PW500-72-30440 R06	No. 1 Engine - Replacement of New or Modified Oil Tank Vent Tube Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30440 R06	No. 2 Engine - Replacement of New or Modified Oil Tank Vent Tube Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30442 R03	No. 1 Engine - Replacement / Modification of Hydromechanical Fuel Control Unit (Superseded By PW500-72-30442 R04), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30442 R3)			[End Of Month Item]								
Engine											
PW500-72-30442 R03	No. 2 Engine - Replacement / Modification of Hydromechanical Fuel Control Unit (Superseded By PW500-72-30442 R04), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30442 R3)			[End Of Month Item]								
Engine											
PW500-72-30442 R04	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
(PW500-72-30442 R4)											
Engine											
PW500-72-30442 R04	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
(PW500-72-30442 R4)											
Engine											
PW500-72-30443	No. 1 Engine - Inspection Fuel Manifold, Service Bulletin (Category 3)		HRS		1644.3			4416.6			0
			ENC		1264			2876		0	
			MOS		132.4			17 Oct 2013			
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30443	No. 2 Engine - Inspection Fuel Manifold, Service Bulletin (Category 3)		HRS		1644.3			4416.6			0
			ENC		1264			2876		0	
			MOS		132.4			17 Oct 2013			
			MSC				-				
Engine			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30446 R02 (72-30446 R2) Engine	No. 1 Engine - Replacement of Low Pressure Compressor Shaft Balancing Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30446 R02 (72-30446 R2) Engine	No. 2 Engine - Replacement of Low Pressure Compressor Shaft Balancing Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30447 Engine	No. 1 Engine - New Coating Modification of Gas Generator Case (Superseded By PW500-72-30447 R01), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30447 Engine	No. 2 Engine - New Coating Modification of Gas Generator Case (Superseded By PW500-72-30447 R01), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30447 R01 Engine	No. 1 Engine - New Coating Modification of Gas Generator Case, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30447 R01 Engine	No. 2 Engine - New Coating Modification of Gas Generator Case, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30449 R02 (72-30449 R2) Engine	No. 1 Engine - Replacement of Hp Turbine Disk Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30449 R02 (72-30449 R2) Engine	No. 2 Engine - Replacement of Hp Turbine Disk Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30453 R03 (PW500-72-30453 R3) Engine	No. 1 Engine - Replacement of No. 4 Carbon Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30453 R03 (PW500-72-30453 R3) Engine	No. 2 Engine - Replacement of No. 4 Carbon Seal, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30455 R04 (72-30455 R4) Engine	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30455 R04 (72-30455 R4) Engine	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30455 R05	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30455 R05	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30462 R02	No. 1 Engine - Conversion of PW545A Build Specification 1156 to 884 Conversion of PW545B Build Specification 1194 to 1161, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(PW500-72-30462 R2)			[End Of Month Item]								
Engine											
PW500-72-30462 R02	No. 2 Engine - Conversion of PW545A Build Specification 1156 to 884 Conversion of PW545B Build Specification 1194 to 1161, Service Bulletin (Category 8)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(PW500-72-30462 R2)			[End Of Month Item]								
Engine											
PW500-72-30463	No. 1 Engine - Replacement of Accessory Drive Lip Seal (Superseded By PW500-72-30463 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30463)			[End Of Month Item]								
Engine											
PW500-72-30463	No. 2 Engine - Replacement of Accessory Drive Lip Seal (Superseded By PW500-72-30463 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30463)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30463 R01	No. 1 Engine - Replacement of Accessory Drive Lip Seal (Superseded By PW500-72-30463 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30463 R01	No. 2 Engine - Replacement of Accessory Drive Lip Seal (Superseded By PW500-72-30463 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30463 R02 (72-30463 R2)	No. 1 Engine - Replacement of Accessory Drive Lip Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30463 R02 (72-30463 R2)	No. 2 Engine - Replacement of Accessory Drive Lip Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30464 (72-30464)	No. 1 Engine - Replacement of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-30464 (72-30464)	No. 2 Engine - Replacement of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30465 (72-30465) Engine	No. 1 Engine - Replacement of Fuel Manifold Tubes (Superseded By PW500-72-30465 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30465 (72-30465) Engine	No. 2 Engine - Replacement of Fuel Manifold Tubes (Superseded By PW500-72-30465 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30465 R01 (72-30465 R1) Engine	No. 1 Engine - Replacement of Fuel Manifold Tubes (Superseded By PW500-72-30465 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30465 R01 (72-30465 R1) Engine	No. 2 Engine - Replacement of Fuel Manifold Tubes (Superseded By PW500-72-30465 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30465 R02 (72-30465 R2) Engine	No. 1 Engine - Replacement of Fuel Manifold Tubes, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30465 R02 (72-30465 R2) Engine	No. 2 Engine - Replacement of Fuel Manifold Tubes, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30466 R02 (PW500-72-30466 R2) Engine	No. 1 Engine - Replacement / Modification of 2ND Stage Turbine Vane Assy, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
PW500-72-30466 R02 (PW500-72-30466 R2) Engine	No. 2 Engine - Replacement / Modification of 2ND Stage Turbine Vane Assy, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
PW500-72-30470 Engine	No. 1 Engine - Replacement of Data Collection Unit (Superseded By PW500-72-30470 R01), Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30470 Engine	No. 2 Engine - Replacement of Data Collection Unit (Superseded By PW500-72-30470 R01), Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30470 R01 (72-30470 R1) Engine	No. 1 Engine - Replacement of Data Collection Unit, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30470 R01 (72-30470 R1) Engine	No. 2 Engine - Replacement of Data Collection Unit, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30472 R01	No. 1 Engine - Replacement of - N1 and N2 Speed		HRS								0
	Sensors (Superseded By PW500-72-30472 R02), Service		ENC								0
	Bulletin (Category 7)		DATE								
			MSC				-				
(72-30472 R1)			[End Of Month Item]								
Engine											
PW500-72-30472 R01	No. 2 Engine - Replacement of - N1 and N2 Speed		HRS								0
	Sensors (Superseded By PW500-72-30472 R02), Service		ENC								0
	Bulletin (Category 7)		DATE								
			MSC				-				
(72-30472 R1)			[End Of Month Item]								
Engine											
PW500-72-30472 R02	No. 1 Engine - Replacement of N1 and N2 Speed		HRS								0
	Sensors, Service Bulletin (Category 7)		ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30472 R02	No. 2 Engine - Replacement of N1 and N2 Speed		HRS								0
	Sensors, Service Bulletin (Category 7)		ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30475 R03	No. 1 Engine - Replacement of Accessory Drive Gearshaft		HRS								0
	Assembly and Fuel Control Drive Spur Gearshaft		ENC								0
	Assembly, Service Bulletin (Category 7)		DATE								
			MSC				-				
(72-30475 R3)			[End Of Month Item]								
Engine											
PW500-72-30475 R03	No. 2 Engine - Replacement of Accessory Drive Gearshaft		HRS								0
	Assembly and Fuel Control Drive Spur Gearshaft		ENC								0
	Assembly, Service Bulletin (Category 7)		DATE								
			MSC				-				
(72-30475 R3)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30475 R03 PART A	No. 1 Engine - Accomplish Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly, Service Bulletin Remove and Install Fuel Control Drive Gearshaft (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC					-			
	(72-30475 R3)		[End Of Month Item]								
Engine											
PW500-72-30475 R03 PART A	No. 2 Engine - Accomplish Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly, Service Bulletin Remove and Install Fuel Control Drive Gearshaft (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC					-			
	(72-30475 R3)		[End Of Month Item]								
Engine											
PW500-72-30475 R03 PART B	No. 1 Engine - Accomplish Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly, Service Bulletin Remove and Install the Accessory Drive Gearshaft (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC					-			
	(72-30475 R3)		[End Of Month Item]								
Engine											
PW500-72-30475 R03 PART B	No. 2 Engine - Accomplish Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly, Service Bulletin Remove and Install the Accessory Drive Gearshaft (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC					-			
	(72-30475 R3)		[End Of Month Item]								
Engine											
PW500-72-30479 R06	No. 1 Engine - Replacement of No. 4 Bearing Front Cover, Hpt Rotor Seal, Cold Start Valve Assembly and the Oil Transfer Tube, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC					-			
	(30479 R6)		[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30479 R06	No. 2 Engine - Replacement of No. 4 Bearing Front Cover, Hpt Rotor Seal, Cold Start Valve Assembly and the Oil Transfer Tube, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(30479 R6)			[End Of Month Item]								
Engine											
PW500-72-30482 R03	No. 1 Engine - Inspection of Combustion Chamber Liner Cooling Ring Segments SELF-Locking Nut (Superseded By Sb PW500-72-30492 R02), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30482 R3)			[End Of Month Item]								
Engine											
PW500-72-30482 R03	No. 2 Engine - Inspection of Combustion Chamber Liner Cooling Ring Segments SELF-Locking Nut (Superseded By Sb PW500-72-30492 R02), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30482 R3)			[End Of Month Item]								
Engine											
PW500-72-30483	No. 1 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483)			[End Of Month Item]								
Engine											
PW500-72-30483	No. 2 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483)			[End Of Month Item]								
Engine											
PW500-72-30483 R01	No. 1 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R1)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30483 R01	No. 2 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R1)			[End Of Month Item]								
Engine											
PW500-72-30483 R02	No. 1 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R03), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R2)			[End Of Month Item]								
Engine											
PW500-72-30483 R02	No. 2 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30483 R03), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R2)			[End Of Month Item]								
Engine											
PW500-72-30483 R03	No. 1 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30492 R02), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R3)			[End Of Month Item]								
Engine											
PW500-72-30483 R03	No. 2 Engine - Replacement/Modification of Combustion Chamber Liner Assembly (Superseded By PW500-72-30492 R02), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30483 R3)			[End Of Month Item]								
Engine											
PW500-72-30485 R02	No. 1 Engine - Replacement of Rear Outer By-PASS Duct Hardware, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(PW500-72-30485 R2)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30485 R02 (PW500-72-30485 R2) Engine	No. 2 Engine - Replacement of Rear Outer By-PASS Duct Hardware, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30486 R02 (72-30486 R2) Engine	No. 1 Engine - Replacement of Breather Adapter Preformed Packing, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30486 R02 (72-30486 R2) Engine	No. 2 Engine - Replacement of Breather Adapter Preformed Packing, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30487 R03 (72-30487 R3) Engine	No. 1 Engine - Replacement of Fuel Control Drive and Accessory Drive Lip Seal (Superseded By Sb PW500-72-30502), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30487 R03 (72-30487 R3) Engine	No. 2 Engine - Replacement of Fuel Control Drive and Accessory Drive Lip Seal (Superseded By Sb PW500-72-30502), Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30491 R02 (72-30491 R2) Engine	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30491 R02 (72-30491 R2) Engine	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner Assembly, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30492 (72-30492) Engine	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R01, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30492 (72-30492) Engine	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R01, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30492 R01 (72-30492 R1) Engine	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30492 R01 (72-30492 R1) Engine	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R02), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30492 R02 (72-30492 R2) Engine	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R03), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
PW500-72-30492 R02	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R03), Service Bulletin (Category 7)		HRS								0	
			ENC								0	
			DATE									
			MSC				-					
(72-30492 R2)			[End Of Month Item]									
Engine												
PW500-72-30492 R03	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R04), Service Bulletin (Category 6)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
(72-30492 R3)			[End Of Month Item]									
Engine												
PW500-72-30492 R03	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner (Superseded By PW500-72-30492 R04), Service Bulletin (Category 6)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
(72-30492 R3)			[End Of Month Item]									
Engine												
PW500-72-30492 R04	No. 1 Engine - Replacement / Modification of Combustion Chamber Liner, Service Bulletin (Category 6)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
(72-30492 R4)			[End Of Month Item]									
Engine												
PW500-72-30492 R04	No. 2 Engine - Replacement / Modification of Combustion Chamber Liner, Service Bulletin (Category 6)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
(72-30492 R4)			[End Of Month Item]									
Engine												
PW500-72-30495 R01	No. 1 Engine - Modification of Accessory Gearbox Cover Bolt Torquing Procedure, Service Bulletin (Category 10)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
(72-30495 R1)			[End Of Month Item]									
Engine												

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30495 R01 (72-30495 R1) Engine	No. 2 Engine - Modification of Accessory Gearbox Cover Bolt Torquing Procedure, Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30496 (72-30496) Engine	No. 1 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30496 (72-30496) Engine	No. 2 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30496 R01 Engine	No. 1 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30496 R01 Engine	No. 2 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30498 R03 (PW500-72-30498 R3) Engine	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30498 R03 (PW500-72-30498 R3) Engine	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30500 (72-30500) Engine	No. 1 Engine - Replacement of Preformed Packing, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30500 (72-30500) Engine	No. 2 Engine - Replacement of Preformed Packing, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30501 (72-30501) Engine	No. 1 Engine - Replacement of Shipping Caps for Shipping Containers, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30501 (72-30501) Engine	No. 2 Engine - Replacement of Shipping Caps for Shipping Containers, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30502 R04 (72-30502 R4) Engine	No. 1 Engine - Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30502 R04 (72-30502 R4) Engine	No. 2 Engine - Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30502 R04 PART A	No. 1 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Fuel Control Gearshaft Seal (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30502 R4 PART A)			[End Of Month Item]								
Engine											
PW500-72-30502 R04 PART A	No. 2 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Fuel Control Gearshaft Seal (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30502 R4 PART A)			[End Of Month Item]								
Engine											
PW500-72-30502 R04 PART B	No. 1 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Accessory Gearshaft Seal (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30502 R4 PART B)			[End Of Month Item]								
Engine											
PW500-72-30502 R04 PART B	No. 2 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Accessory Gearshaft Seal (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30502 R4 PART B)			[End Of Month Item]								
Engine											
PW500-72-30504 R02	No. 1 Engine - Replacement of Fuel/Oil Heat Exchanger, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30504 R2)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30504 R02 (72-30504 R2) Engine	No. 2 Engine - Replacement of Fuel/Oil Heat Exchanger, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30504 R03 Engine	No. 1 Engine - Replacement of Fuel/Oil Heat Exchanger, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30504 R03 Engine	No. 2 Engine - Replacement of Fuel/Oil Heat Exchanger, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30505 R02 (72-30505 R2) Engine	No. 1 Engine - Replacement of Bleed Off Valve (Bov) Gaskets, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30505 R02 (72-30505 R2) Engine	No. 2 Engine - Replacement of Bleed Off Valve (Bov) Gaskets, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30505 R03 Engine	No. 1 Engine - Replacement of Bleed Off Valve (Bov) Gaskets, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30505 R03 Engine	No. 2 Engine - Replacement of Bleed Off Valve (Bov) Gaskets, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30505 R04	No. 1 Engine - Replacement of Bleed Off Valve (Bov)		HRS								0
	Gaskets, Service Bulletin (Category 3)		ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30505 R04	No. 2 Engine - Replacement of Bleed Off Valve (Bov)		HRS								0
	Gaskets, Service Bulletin (Category 3)		ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30506	No. 1 Engine - Replacement of Fuel Manifold Adapters		HRS								0
	(Superseded By PW500-72-30506 R01), Service Bulletin		ENC								0
	(Category 7)		DATE								
			MSC				-				
(72-30506)		[End Of Month Item]									
Engine											
PW500-72-30506	No. 2 Engine - Replacement of Fuel Manifold Adapters		HRS								0
	(Superseded By PW500-72-30506 R01), Service Bulletin		ENC								0
	(Category 7)		DATE								
			MSC				-				
(72-30506)		[End Of Month Item]									
Engine											
PW500-72-30506 R01	No. 1 Engine - Replacement of Fuel Manifold Adapters		HRS								0
	(Superseded By PW500-72-30506 R02), Service Bulletin		ENC								0
	(Category 7)		DATE								
			MSC				-				
(72-30506 R1)		[End Of Month Item]									
Engine											
PW500-72-30506 R01	No. 2 Engine - Replacement of Fuel Manifold Adapters		HRS								0
	(Superseded By PW500-72-30506 R02), Service Bulletin		ENC								0
	(Category 7)		DATE								
			MSC				-				
(72-30506 R1)		[End Of Month Item]									
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs	
	Part Number	Serial Number									Approx Price	
Logbook Position	HW	SW									Manufacturer	
	MM Ref										Date Type	
	Ops Number(s)											
PW500-72-30506 R02 (72-30506 R2) Engine	No. 1 Engine - Replacement of Fuel Manifold Adapters, Service Bulletin (Category 7)		HRS		975.6			5085.3			0	
			ENC		682			3458			0	
			MOS		56.7			08 Feb 2020				
			MSC				-					
			[End Of Month Item]									
PW500-72-30506 R02 (72-30506 R2) Engine	No. 2 Engine - Replacement of Fuel Manifold Adapters, Service Bulletin (Category 7)		HRS		975.6			5085.3			0	
			ENC		682			3458			0	
			MOS		56.6			10 Feb 2020				
			MSC				-					
			[End Of Month Item]									
PW500-72-30508 R02 (72-30508 R2) Engine	No. 1 Engine - Replacement / Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
			[End Of Month Item]									
PW500-72-30508 R02 (72-30508 R2) Engine	No. 2 Engine - Replacement / Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0	
			ENC									0
			DATE									
			MSC				-					
			[End Of Month Item]									
PW500-72-30508 R03 Engine	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS		975.6			5085.3			0	
			ENC		682			3458			0	
			MOS		56.7			08 Feb 2020				
			MSC				-					
PW500-72-30508 R03 Engine	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS		975.6			5085.3			0	
			ENC		682			3458			0	
			MOS		56.6			10 Feb 2020				
			MSC				-					

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30508 R04	No. 1 Engine - Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30508 R04	No. 2 Engine - Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30511 R01 (72-30511 R1)	No. 1 Engine - RE-Torqueing of Agb Cover Bolts or Nuts, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30511 R01 (72-30511 R1)	No. 2 Engine - RE-Torqueing of Agb Cover Bolts or Nuts, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine			[End Of Month Item]								
PW500-72-30511 R02	No. 1 Engine - RE-Torqueing of Agb Cover Bolts or Nuts, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30511 R02	No. 2 Engine - RE-Torqueing of Agb Cover Bolts or Nuts, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30512 R03	No. 1 Engine - Inspection/Replacement of Hydromechanical Fuel Control, Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
(72-30512 R3)		[End Of Month Item]									
Engine											
PW500-72-30512 R03	No. 2 Engine - Inspection/Replacement of Hydromechanical Fuel Control, Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
(72-30512 R3)		[End Of Month Item]									
Engine											
PW500-72-30516 R02	No. 1 Engine - Replacement of Hp Turbine Seal Rings, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30516 R2)		[End Of Month Item]									
Engine											
PW500-72-30516 R02	No. 2 Engine - Replacement of Hp Turbine Seal Rings, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30516 R2)		[End Of Month Item]									
Engine											
PW500-72-30517 R01	No. 1 Engine - Deletion of Igniter Flange Gaskets, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
(72-30517 R1)		[End Of Month Item]									
Engine											
PW500-72-30517 R01	No. 2 Engine - Deletion of Igniter Flange Gaskets, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
(72-30517 R1)		[End Of Month Item]									
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30518	No. 1 Engine - Saleability Change - Turbine Exhaust Case End Cone, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30518)			[End Of Month Item]								
Engine											
PW500-72-30518	No. 2 Engine - Saleability Change - Turbine Exhaust Case End Cone, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30518)			[End Of Month Item]								
Engine											
PW500-72-30521 R01	No. 1 Engine - Replacement of Combustion Chamber Liner, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30521 R1)			[End Of Month Item]								
Engine											
PW500-72-30521 R01	No. 2 Engine - Replacement of Combustion Chamber Liner, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30521 R1)			[End Of Month Item]								
Engine											
PW500-72-30523 R01	No. 1 Engine - Replacement of Accessory Gearbox Cover Gasket, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30523 R1)			[End Of Month Item]								
Engine											
PW500-72-30523 R01	No. 2 Engine - Replacement of Accessory Gearbox Cover Gasket, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
(72-30523 R1)			[End Of Month Item]								
Engine											
PW500-72-30526	No. 1 Engine - Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
(72-30526)			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30526 (72-30526) Engine	No. 2 Engine - Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
			[End Of Month Item]								
PW500-72-30526 R01 Engine	No. 1 Engine - Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
PW500-72-30526 R01 Engine	No. 2 Engine - Modification of Intermediate Case Assembly, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
PW500-72-30527 (72-30527) Engine	No. 1 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30527 (72-30527) Engine	No. 2 Engine - Replacement of No. 4 Roller Bearing, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30532 (72-30532) Engine	No. 1 Engine - Replacement of Retaining Rings, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30532 (72-30532) Engine	No. 2 Engine - Replacement of Retaining Rings, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30534 R04 (PW500-72-30534 R4) Engine	No. 1 Engine - Replacement of Data Collection Unit, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30534 R04 (PW500-72-30534 R4) Engine	No. 2 Engine - Replacement of Data Collection Unit, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30535 R01 (PW500-72-30535 R1) Engine	No. 1 Engine - Replacement of Engine Shipping Container, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30535 R01 (PW500-72-30535 R1) Engine	No. 2 Engine - Replacement of Engine Shipping Container, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30535 R02 Engine	No. 1 Engine - Replacement of Engine Shipping Container, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30535 R02 Engine	No. 2 Engine - Replacement of Engine Shipping Container, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 (72-30540) Engine	No. 1 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30540 (72-30540) Engine	No. 2 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30540 R01 Engine	No. 1 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 R01 Engine	No. 2 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 R02 Engine	No. 1 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 R02 Engine	No. 2 Engine - Replacement of High Pressure Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 R03 Engine	No. 1 Engine - Replacement of High-Pressure-Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
PW500-72-30540 R03 Engine	No. 2 Engine - Replacement of High-Pressure-Turbine AIR Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30541 R01 (PW500-72-30541 R1) Engine	No. 1 Engine - Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30541 R01 (PW500-72-30541 R1) Engine	No. 2 Engine - Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30541 R01 PART A Engine	No. 1 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Fuel Control Gearshaft Seal (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30541 R01 PART A Engine	No. 2 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Fuel Control Gearshaft Seal (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30541 R01 PART B Engine	No. 1 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Accessory Gearshaft Seal (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
PW500-72-30541 R01 PART B Engine	No. 2 Engine - Accomplish Replacement of Fuel Control Drive and Accessory Drive Plain Seal, Service Bulletin Accessory Gearshaft Seal (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30542	No. 1 Engine - Replacement of Igniter Cables, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30542)			[End Of Month Item]								
Engine											
PW500-72-30542	No. 2 Engine - Replacement of Igniter Cables, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30542)			[End Of Month Item]								
Engine											
PW500-72-30543	No. 1 Engine - Replacement of T1 Thermocouple Harness, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30543)			[End Of Month Item]								
Engine											
PW500-72-30543	No. 2 Engine - Replacement of T1 Thermocouple Harness, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30543)			[End Of Month Item]								
Engine											
PW500-72-30543 R01	No. 1 Engine - Replacement of T1 Thermocouple Harness, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30543 R01	No. 2 Engine - Replacement of T1 Thermocouple Harness, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30545	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R01	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R01	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R02	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R02	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R03	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30545 R03	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30545 R04	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30545 R04	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 3)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30546	No. 1 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30546	No. 2 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30546 R01	No. 1 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30546 R01	No. 2 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS		975.6			5085.3			0
			ENC		682			3458			0
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30546 R02	No. 1 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30546 R02	No. 2 Engine - Replacement of Hpt AIR Seal, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30548	No. 1 Engine - Replacement/Modification of Anti-Icing Valve (Superseded By PW500-72-30548 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30548)											
Engine											
PW500-72-30548	No. 2 Engine - Replacement/Modification of Anti-Icing Valve (Superseded By PW500-72-30548 R01), Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
(72-30548)											
Engine											
PW500-72-30548 R01	No. 1 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30548 R01	No. 2 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30548 R02	No. 1 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.7			08 Feb 2020			
			MSC				-				
Engine											
PW500-72-30548 R02	No. 2 Engine - Replacement/Modification of Anti-Icing Valve, Service Bulletin (Category 7)		HRS		975.6			5085.3			0
			ENC		682			3458		0	
			MOS		56.6			10 Feb 2020			
			MSC				-				
Engine											
PW500-72-30550	No. 1 Engine - Replacement of No. 4 Bearing Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30550	No. 2 Engine - Replacement of No. 4 Bearing Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30550 PART A	No. 1 Engine - Accomplish Replacement of No. 4 Bearing Seal Runners, Service Bulletin Replace the Front No. 4 Bearing Seal Runner With A New One (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30550 PART A	No. 2 Engine - Accomplish Replacement of No. 4 Bearing Seal Runners, Service Bulletin Replace the Front No. 4 Bearing Seal Runner With A New One (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30550 PART B	No. 1 Engine - Accomplish Replacement of No. 4 Bearing Seal Runners, Service Bulletin Replace the Rear No. 4 Bearing Seal Runner With A New One (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30550 PART B	No. 2 Engine - Accomplish Replacement of No. 4 Bearing Seal Runners, Service Bulletin Replace the Rear No. 4 Bearing Seal Runner With A New One (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30554 R01	No. 1 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30554 R01	No. 2 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30554 R02	No. 1 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30554 R02	No. 2 Engine - Replacement of Intercompressor Bleed Valve/ Servo-Valve, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562	No. 1 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562	No. 2 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562 R01	No. 1 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562 R01	No. 2 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562 R02	No. 1 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30562 R02	No. 2 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30562 R03	No. 1 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30562 R03	No. 2 Engine - Replacement of Mixer Assembly, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564	No. 1 Engine - Replacement of Lockbolt Collar, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564	No. 2 Engine - Replacement of Lockbolt Collar, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564 R01	No. 1 Engine - Replacement of Lockbolt Collar, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564 R01	No. 2 Engine - Replacement of Lockbolt Collar, Service Bulletin (Category 9)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564 R02	No. 1 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30564 R02	No. 2 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564 R03	No. 1 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30564 R03	No. 2 Engine - Replacement/Modification of Second Stage Turbine Vane, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30565	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30565	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 7)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											
PW500-72-30565 R01	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 6)		HRS								0
			ENC							0	
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30565 R01	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30565 R02	No. 1 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30565 R02	No. 2 Engine - Replacement/Modification of Hydromechanical Fuel Control Unit, Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30567	No. 1 Engine - Inspection of Turbofan Engine Engine Electronic Control (Eec), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30567	No. 2 Engine - Inspection of Turbofan Engine Engine Electronic Control (Eec), Service Bulletin (Category 6)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30568	No. 1 Engine - Replacement of No. 4 Bearing Front and Rear Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-30568	No. 2 Engine - Replacement of No. 4 Bearing Front and Rear Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30568 R01	No. 1 Engine - Replacement of No. 4 Bearing Front and Rear Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30568 R01	No. 2 Engine - Replacement of No. 4 Bearing Front and Rear Seal Runners, Service Bulletin (Category 7)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30572	No. 1 Engine - Inspection of Hp Turbine Disk, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-30572	No. 2 Engine - Inspection of Hp Turbine Disk, Service Bulletin (Category 5)		HRS								0
			ENC								0
			DATE								
			MSC				-				
Engine											
PW500-72-A30421	No. 1 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve (Superseded By PW500-72-A30421 R01), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
[End Of Month Item]											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-A30421	No. 2 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve (Superseded By PW500-72-A30421 R01), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30421 R01	No. 1 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve (Superseded By PW500-72-A30421 R02), Alert Service Bulletin (Category 3)		HRS		1985.6			4075.3			0
			ENC		1584			2556			0
			MOS		167.8			04 Nov 2010			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30421 R01	No. 2 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve (Superseded By PW500-72-A30421 R02), Alert Service Bulletin (Category 3)		HRS		1985.6			4075.3			0
			ENC		1584			2556			0
			MOS		167.8			04 Nov 2010			
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30421 R02	No. 1 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve, Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(A30421 R2)											
Engine											
PW500-72-A30421 R02	No. 2 Engine - Inspection/Replacement of Intercompressor Bleed Valve/Servo-Valve, Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
(A30421 R2)											
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW500-72-A30452	No. 1 Engine - Turbofan Engine Oil System - Special Inspection of Mop (Superseded By PW500-72-A30452 R01), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30452	No. 2 Engine - Turbofan Engine Oil System - Special Inspection of Mop (Superseded By PW500-72-A30452 R01), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30452 R01	No. 1 Engine - Turbofan Engine - Oil System - Special Inspection of Mop (Superseded By PW500-72-A30452 R02), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30452 R01	No. 2 Engine - Turbofan Engine - Oil System - Special Inspection of Mop (Superseded By PW500-72-A30452 R02), Alert Service Bulletin (Category 3)		HRS								0
			ENC								0
			MOS								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30452 R02 (A30452 R2)	No. 1 Engine - Special Inspection of Mop Oil System (Cancelled), Alert Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											
PW500-72-A30452 R02 (A30452 R2)	No. 2 Engine - Special Inspection of Mop Oil System (Cancelled), Alert Service Bulletin (Category 10)		HRS								0
			ENC								0
			DATE								
			MSC				-				
			[End Of Month Item]								
Engine											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
RE100-49-7896 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck and (Dipstick) CAP, Pn 361-530- 9354, With Oil Filler Neck CAP, Pn 361-530-9355, on the RE100 APU, Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(7896 R1)			[End Of Month Item]								
APU											
RE100-49-7992	APU - Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, Pn 2119552 -2 or Pn 2119552-3, With Electronic Control Unit, Pn 2119552-4, Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(1)			[End Of Month Item]								
APU											
RE100-49-7992 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, Pn 2119552 -2 or Pn 2119552-3, With Electronic Control Unit, Pn 2119552-4, Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(1)			[End Of Month Item]								
APU											
RE100-49-8139	APU - Airborne Auxiliary Power - Gas Turbine Engine - Increase the Installation Torque and Add the Use of Locking Compound During Carbon Seal Assembly on the RE100 APU, Service Bulletin (Recommended)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201407000063)			[End Of Month Item]								
APU											
RE100-49-8250 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, Pn 3881825-1 With Pn3881825-2, for the RE100[Cs] and RE100[XI] Auxiliary Power Unit (APU), Service Bulletin (Attrition)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(RE100-49-8250 R1)											
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
RE100-49-8250 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, Pn 3881825-1 With Pn 3881825-2, for the RE100[Cs] and RE100[XI] Auxiliary Power Unit (APU), Service Bulletin (Attrition)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201706000033 R02)											
APU											
RE100-49-8303	APU - Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU), Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201903000011)											
APU											
RE100-49-8303 R03	APU - Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU), Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201903000011 R03)											
APU											
RE100-49-8303 R04	APU - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU), Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D201903000011 R04)											
APU											
RE100-49-8360	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Pn 627-504-9209 on Engines RE100[Cs], RE100[LJ], and RE100[XI] Models, Service Bulletin (Category 2)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D202108001909)											
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
RE100-49-8360 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Pn 627-504-9209 on Engines RE100[Cs], RE100[Lj], and RE100[XI] Models, Service Bulletin (Category 2)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D202108001909 R01)											
APU											
RE100-49-8360 R02	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Pn 627-504-9209 on RE100 Engine Models, Service Bulletin (Category 2)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D202108001909 R02)											
APU											
RE100-49-8363 R01	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing Pn 3810880-1/-2 With Pn 70724596-1 or Pn 70724596-2, Gearbox Housing Pn 3863409-6 With Pn 70724597-1, Gearbox Housing Pn 3863409-5 With Pn 70724597-2 and Gearbox Housing Pn 3863409-4 With Pn 70724597-3 on the RE100 Auxiliary Power Unit (APU), Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D202109001986 R01)											
APU											
RE100-49-8364	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Wiring Harness Pn 3888395-2 With Pn 3888395-3 on the RE100[XI] Auxiliary Power Unit (APU), Service Bulletin (Optional)		HRS								0
			APUS								0
			DATE								
			MSC				-				
(D202109001987)											
APU											

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
RE100-49-8366	APU - Airborne Auxiliary Power - Gas Turbine Engine - Replace Spline Adapter Pn 3861055-1 With Pn 3861055-2 on the RE100[XI] Auxiliary Power Unit (APU), Service Bulletin (Category 2)		HRS								0
			APUS							0	
			DATE								
			MSC				-				
(D202109001996)											
APU											