



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
4-12-MD <i>0592MD</i>	INSPECTION DOCUMENT MD	KFXE		MTH 18-Aug-2017 HRS 4839.9 LDG 3814 APUH 1875.1 APUS 3476		120 2400		31-Aug-2027 7239.9	30 m 28 d 818.3
4-12-ME <i>0592ME</i>	INSPECTION DOCUMENT ME	*CF		MTH 16-Sep-2007 HRS 0		15000		15000	8578.4
4-12-MF <i>0592MF</i>	INSPECTION DOCUMENT MF	*CF		MTH 16-Sep-2007 HRS 0		7500		7500	1078.4
4-12-MH	INSPECTION DOCUMENT MH			MTH		N/A			
4-12-MJ <i>0592MJ</i>	INSPECTION DOCUMENT MJ	*CF		MTH 16-Sep-2007 HRS 0		13000		13000	6578.4
4-12-MK	INSPECTION DOCUMENT MK			MTH		N/A			
4-12-ML <i>0592ML</i>	INSPECTION DOCUMENT ML	*CF		MTH 16-Sep-2007 HRS 0		11500		11500	5078.4
4-12-MM <i>0592MM</i>	INSPECTION DOCUMENT MM	*CF		MTH 16-Sep-2007 HRS 0		11000		11000	4578.4
4-12-MN <i>0592MN</i>	INSPECTION DOCUMENT MN	*CF		MTH 16-Sep-2007 HRS 0		9000		9000	2578.4
4-12-MO <i>0592MO</i>	INSPECTION DOCUMENT MO	*CF		MTH 16-Sep-2007 HRS 0		12500		12500	6078.4
4-12-MU	INSPECTION DOCUMENT MU			MTH 16-Sep-2007 HRS 0		12000		12000	5578.4
4-12-MV <i>0592MV</i>	INSPECTION DOCUMENT MV	KJVL		MTH 21-Aug-2024 HRS 6355.7 LDG 4596		24		31-Aug-2026	18 m 28 d
050000	FAA REGISTRATION RENEWAL	KJVL		MTH 05-Feb-2024 HRS 6262.9 LDG 4538		DUE DUE DUE DUE		24-Jan-2025	-10 d
Over Due									
5-12-01	INSPECTION DOCUMENT 1	KJVL		MTH 21-Aug-2024 HRS 6355.7 LDG 4596	-21	12		31-Jul-2025	5 m 28 d
5-12-03	INSPECTION DOCUMENT 3	KJVL		MTH 27-Jul-2023 HRS 6170.3 LDG 4480	-23	24		04-Jul-2025	5 m 1 d
5-12-06	INSPECTION DOCUMENT 6	KJVL		MTH 26-Oct-2023 HRS 6186.8 LDG 4490	26	48		21-Nov-2027	33 m 18 d
5-12-07	INSPECTION DOCUMENT 7	KJVL		MTH 11-Dec-2024 HRS 6416.4 LDG 4639	23.5	1600		8039.9	1618.3
5-12-08	INSPECTION DOCUMENT 8			MTH HRS		2400		6701.8	280.2
5-12-11	INSPECTION DOCUMENT 11	KJVL		MTH 27-Jul-2023 HRS 6170.3 LDG 4480	-23	24		04-Jul-2025	5 m 1 d
5-12-12	INSPECTION DOCUMENT 12	KJVL		MTH 27-Jul-2023 HRS 6170.3 LDG 4480	-21	60		06-Jul-2028	41 m 3 d
5-12-13	INSPECTION DOCUMENT 13	KSAT		MTH 04-Jul-2021 HRS 5613.7 LDG 4146		72		04-Jul-2027	29 m 1 d
5-12-16	INSPECTION DOCUMENT 16	KJVL		MTH 27-Jul-2023 HRS 6170.3 LDG 4480		96		31-Jul-2031	77 m 28 d



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-17	INSPECTION DOCUMENT 17			MTH HRS LDG	12-Aug-2022 5959.7 4366		1600		7559.7	1138.1
5-12-18	INSPECTION DOCUMENT 18			MTH			N/A			
5-12-19	INSPECTION DOCUMENT 19 KDLL			MTH HRS LDG	18-Jun-2024 6323.5 4576	3.8	300		6627.3	205.7
5-12-20	INSPECTION DOCUMENT 20			MTH			N/A			
5-12-21	INSPECTION DOCUMENT 21 KSAT			MTH HRS LDG	04-Jul-2021 5613.7 4146		6			
5-12-22	INSPECTION DOCUMENT 22			MTH HRS			6600		9519.9	3098.3
5-12-25	INSPECTION DOCUMENT 25			MTH HRS			7200		11995.2	5573.6
055000 E1	FOD			MTH	16-Sep-2007		A/R			
055000 E2	FOD			MTH	16-Sep-2007		A/R			
055005 E1	BIRD STRIKE			MTH	16-Sep-2007		A/R			
055005 E2	BIRD STRIKE			MTH	16-Sep-2007		A/R			
055010 E1	ENGINE WINDMILLING IN FLIGHT			MTH	16-Sep-2007		A/R			
055010 E2	ENGINE WINDMILLING IN FLIGHT			MTH	16-Sep-2007		A/R			
055015 E1	LIGHTNING STRIKE			MTH	16-Sep-2007		A/R			
055015 E2	LIGHTNING STRIKE			MTH	16-Sep-2007		A/R			
055020 E1	FUEL FILTER IMPENDING BYPASS			MTH	16-Sep-2007		A/R			
055020 E2	FUEL FILTER IMPENDING BYPASS			MTH	16-Sep-2007		A/R			
055025 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT			MTH	16-Sep-2007		A/R			
055025 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT			MTH	16-Sep-2007		A/R			
055030 E1	INCORRECT ENGINE SHUTDOWN ON THE GROUND			MTH	16-Sep-2007		A/R			
055030 E2	INCORRECT ENGINE SHUTDOWN ON THE GROUND			MTH	16-Sep-2007		A/R			
055035 E1	HEAVY LANDING			MTH	16-Sep-2007		A/R			
055035 E2	HEAVY LANDING			MTH	16-Sep-2007		A/R			
055040 E1	SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS			MTH	16-Sep-2007		A/R			
055040 E2	SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS			MTH	16-Sep-2007		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
055045 E1	ITT SPIKE ON ENGINE START DUE TO A FROZEN FAN			MTH 16-Sep-2007		A/R			
055045 E2	ITT SPIKE ON ENGINE START DUE TO A FROZEN FAN			MTH 16-Sep-2007		A/R			
055050 E1	LOOSE HIGH PRESSURE COMPRESSOR CASE BOLTS			MTH 16-Sep-2007		A/R			
055050 E2	LOOSE HIGH PRESSURE COMPRESSOR CASE BOLTS			MTH 16-Sep-2007		A/R			
055055 E1	DATA COLLECTION UNIT (DCU) INOPERATIVE			MTH 16-Sep-2007		A/R			
055055 E2	DATA COLLECTION UNIT (DCU) INOPERATIVE			MTH 16-Sep-2007		A/R			
055060 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 16-Sep-2007		A/R			
055060 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 16-Sep-2007		A/R			
055065 E1	STARTER GENERATOR FAIL INDICATION			MTH 16-Sep-2007		A/R			
055065 E2	STARTER GENERATOR FAIL INDICATION			MTH 16-Sep-2007		A/R			
055070 E1	HYDRAULIC PUMP UNSCHEDULED REMOVAL			MTH 16-Sep-2007		A/R			
055070 E2	HYDRAULIC PUMP UNSCHEDULED REMOVAL			MTH 16-Sep-2007		A/R			
055075 E1	FUEL CONTAMINATION			MTH 16-Sep-2007		A/R			
055075 E2	FUEL CONTAMINATION			MTH 16-Sep-2007		A/R			
057120 E1	INSPECTION LOW UTILIZATION UNK			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		120		30-Apr-2028	38 m 27 d
057120 E2	INSPECTION LOW UTILIZATION UNK			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		120		30-Apr-2028	38 m 27 d
12-26-00-6001	15 DAY HIGH EXPOSURE AREA WASH					A/R			
12-26-00-6002	45 DAY MEDIUM EXPOSURE AREA WASH					A/R			
12-26-00-6003	90 DAY LOW EXPOSURE AREA WASH					A/R			
21-22-00-9600	COCKPIT SIDE WINDOW DEFOG FILTER DISCARD			MTH 16-Sep-2007		A/R			
21-52-00-9600	VAPOR CYCLE COOLING SYSTEM 500 COMPRESSOR HOUR DRIVE MOTOR BRUSH DISCARD (AIRPLANES INCORPORATING VAPOR CYCLE COOLING WITH 1134104-1 AND -5 COMPRESSOR MOTORS)			MTH		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
23-90-20-7200 NO. 1 059245 : <i>XPDR1</i> Calibration Date: 05-Jul-2023	NO. 1 TRANSPONDER FUNCTIONAL CHECK (AIRPLANES -5001 THRU -6000)	KJVL		7517400-922 0608B727	MTH 05-Jul-2023		24		31-Jul-2025	5 m 28 d
23-90-20-7200 NO. 2 059245 : <i>XPDR2</i> Calibration Date: 05-Jul-2023	NO. 2 TRANSPONDER FUNCTIONAL CHECK (AIRPLANES -5001 THRU -6000)	KJVL		7517400-922 0605B010	MTH 05-Jul-2023		24		31-Jul-2025	5 m 28 d
24-32-00-7202	42 AMP-HOUR CONCORDE LEAD ACID MAIN BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK	KJVL		S3597-8 41181955	MTH 11-Dec-2024 HRS 6416.4 LDG 4639		6 300		30-Jun-2025 6716.4	4 m 27 d 294.8
24-32-00-9600	NO. 1 SECURAPLANE BATTERY DISCARD	KJVL		100-2410-04 1193494	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		48		31-Aug-2028	42 m 28 d
25-60-10-7200	ARTEX 110-4 EMERGENCY LOCATOR TRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL CHECK (AIRPLANES -5001 THRU -5500 NOT INCORPORATING SB560XL-25-11)	KMCO		453-5060 252-00486	MTH		N/A			
25-60-10-7201	ARTEX 110-406 EMERGENCY LOCATOR TRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL CHECK (AIRPLANES -5501 THRU -5564 AND AIRPLANES -5002 THRU -5372 NOT INCORPORATING SB560XL-25-11)			453-5060 252-00486	MTH		N/A			
25-60-10-7202	ARTEX C406-2 EMERGENCY LOCATOR TRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL TEST (AIRPLANES -5501 THRU -5564 AND AIRPLANES -5002 THRU -5372 INCORPORATING SB560XL-25-11)	KMCO		453-5060 252-00486	MTH		N/A			
25-60-10-7203	ARTEX C406-N EMERGENCY LOCATOR TRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL CHECK (AIRPLANES -5565 AND ON)	KJVL		453-5060 252-00486	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		12		31-Aug-2025	6 m 28 d
26-20-00-2200	ENGINE FIRE DEPLOYMENT CHECK TEESPECIAL DETAILED INSPECTION				MTH 16-Sep-2007		O/C			
26-21-01-7100 AFT	AFT ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK			30400037-1 84377B1	MTH 01-Aug-2021		60		01-Aug-2026	17 m 29 d
26-21-01-7100 FORWARD	FWD ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK			30400037-1 84380B1	MTH 01-Aug-2021		60		01-Aug-2026	17 m 29 d
26-21-01-7200	OPTIONAL AFT VANITY FIRE EXTINGUISHER BOTTLE (WEIGHT CHECK) FUNCTIONAL CHECK (AIRPLANES -6224 AND ON)	KDLL			MTH 31-Jan-2023 HRS 6101.2 LDG 4440		60		31-Jan-2028	35 m 28 d
26-21-01-7800 AFT 059238 : <i>A</i>	AFT ENGINE FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION			30400037-1 84377B1	MTH 01-Aug-2021		60		01-Aug-2026	17 m 29 d
26-21-01-7800 FORWARD 059238 : <i>F</i>	FORWARD ENGINE FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION			30400037-1 84380B1	MTH 01-Aug-2021		60		01-Aug-2026	17 m 29 d
26-21-01-9600.1 AFT/FWD	13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB CARTRIDGE - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		72		01-Aug-2027	29 m 29 d
26-21-01-9600.1 AFT REAR	13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		72		01-Aug-2027	29 m 29 d



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
26-21-01-9600.1 FORWARD/FORW ARD	13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		72		01-Aug-2027	29 m 29 d
26-21-01-9600.1 FWD REAR	13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		72		01-May-2027	26 m 28 d
26-21-01-9600 AFT/FWD	13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH 01-Aug-2021		108		31-Aug-2030	66 m 28 d
Manufacture Date: 01-Aug-2021										
26-21-01-9600 AFT REAR	13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH 01-Aug-2021		108		31-Aug-2030	66 m 28 d
Manufacture Date: 01-Aug-2021										
26-21-01-9600 FORWARD/FORW ARD	13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH 01-Aug-2021		108		31-Aug-2030	66 m 28 d
Manufacture Date: 01-Aug-2021										
26-21-01-9600 FWD REAR	13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH 01-May-2021		108		31-May-2030	63 m 28 d
Manufacture Date: 01-May-2021										
26-21-01-9601.1	13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - SERVICE LIFE	KDLL		13083-5 9399	MTH 31-Jan-2023 HRS 6101.2 LDG 4440		72		31-Jan-2029	47 m 28 d
26-21-01-9601	13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - TOTAL LIFE	KDLL		13083-5 9399	MTH 01-Jun-2022		108		01-Jun-2031	75 m 29 d
Manufacture Date: 01-Jun-2022										
26-21-01-9602.1 AFT/FWD	AE13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602.1 AFT REAR	AE13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602.1 FORWARD/FORW ARD	AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602.1 FWD REAR	AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602 AFT/FWD	AE13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602 AFT REAR	AE13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602 FORWARD/FORW ARD	AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9602 FWD REAR	AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - TOTAL LIFE			13083-5 SN-UNKNOWN	MTH		N/A			
26-21-01-9603.1	AE13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 9399	MTH		N/A			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
26-21-01-9603	AE13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - TOTAL LIFE									
				13083-5 9399	MTH		N/A			
26-22-00-2200	CABIN PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK									
CABIN		KJVL		C352TS F49186190	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		12		31-Aug-2025	6 m 28 d
26-22-00-2200	COCKPIT PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK									
COCKPIT		KJVL		C352TS F49186237	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		12		31-Aug-2025	6 m 28 d
26-22-00-2201	CABIN PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION)									
CABIN		KJVL		C352TS F49186190	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		72		21-Aug-2030	66 m 18 d
26-22-00-2201	COCKPIT PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION)									
COCKPIT		KJVL		C352TS F49186237	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		72		21-Aug-2030	66 m 18 d
26-22-00-7800	CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK									
CABIN		KFXE		C352TS F49186190	MTH 31-Dec-2018		144		31-Dec-2030	70 m 28 d
059241 : CABIN Hydro Check Date: 31-Dec-2018										
26-22-00-7800	COCKPIT PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK									
COCKPIT		KFXE		C352TS F49186237	MTH 31-Dec-2018		144		31-Dec-2030	70 m 28 d
059241 : CKPT Hydro Check Date: 31-Dec-2018										
26-23-00-7101	AUXILIARY POWER UNIT FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK									
APU				30100033-7 38140A1	MTH 22-Jan-2022		60		31-Jan-2027	23 m 28 d
26-23-00-7800	APU FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION									
APU				30100033-7 38140A1	MTH 22-Jan-2022		60		31-Jan-2027	23 m 28 d
059238 : APU Hydro Check Date: 22-Jan-2022										
28-00-02-2200	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 23-Aug-2022 HRS 5972 LDG 4375		A/R			
28-00-02-2201	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
		KJVL			MTH 26-Oct-2023 HRS 6186.8 LDG 4490	12	12		31-Oct-2025	8 m 28 d
32-10-00-2201	MAIN LANDING GEAR ACTUATOR ROD END DETAILED INSPECTION (AIRPLANES OPERATING IN SEVERE CORROSION ENVIRONMENTS)									
					MTH		48		31-Jul-2028	41 m 28 d
32-30-09-7800	EMERGENCY GEAR EXTENSION/BRAKE PNEUMATIC STORAGE BOTTLE(HYDROSTATIC TEST) RESTORATION									
059237 : N2		KJVL		40005347-3 4385	MTH 11-Dec-2024 HRS 6416.4 LDG 4639		36		31-Dec-2027	34 m 28 d
Hydro Check Date: 10-Dec-2024										
32-40-00-2200	LEFT LANDING GEAR BRAKES DETAILED INSPECTION, MAIN LANDING GEAR AXLE GENERAL VISUAL INSPECTION, AND FUNCTIONAL (WEAR PIN) CHECK									
LEFT				3-1571-6 2125	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			
32-40-00-2200	RIGHT LANDING GEAR BRAKES DETAILED INSPECTION, MAIN LANDING GEAR AXLE GENERAL VISUAL INSPECTION, AND FUNCTIONAL (WEAR PIN) CHECK									
RIGHT				3-1571-6 2128	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-40-00-2203 NOSE	NOSE LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		WHL/C WHL/C WHL/C WHL/C			
32-40-00-7200 LEFT	LEFT BRAKE ASSEMBLY (WEAR PIN) FUNCTIONAL CHECK			3-1571-6 2125	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			
32-40-00-7200 RIGHT	RIGHT BRAKE ASSEMBLY (WEAR PIN) FUNCTIONAL CHECK			3-1571-6 2128	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			
32-41-00-2100 LEFT	LEFT LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1571-6 2125	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			
32-41-00-2100 NOSE	NOSE LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		WHL/C WHL/C WHL/C WHL/C			
32-41-00-2100 RIGHT	RIGHT LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1571-6 2128	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		WHL/C WHL/C WHL/C WHL/C			
32-41-00-2101 NOSE	OPTIONAL NOSE WHEEL SPIN UP GENERAL INSPECTION			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		WHL/C WHL/C WHL/C WHL/C			
32-41-00-2200 LEFT	LEFT MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	KDLL		3-1571-6 2125	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		24 WHL/C WHL/C WHL/C		30-Jun-2026	16 m 27 d
32-41-00-2200 RIGHT	RIGHT MAIN LANDING GEAR WHEEL AND TIRE DETAILED INSPECTION	KDLL		3-1571-6 2128	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		24 WHL/C WHL/C WHL/C		30-Jun-2026	16 m 27 d
32-41-00-2800 NOSE <i>059243 : N</i>	NOSE LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		T/C			
32-41-00-2801 LEFT <i>059243 : L</i>	LEFT MAIN LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION			3-1571-6 2125	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		T/C			
32-41-00-2801 RIGHT <i>059243 : R</i>	RIGHT MAIN LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION			3-1571-6 2128	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		T/C			
32-41-00-7200 NOSE	OPTIONAL NOSE WHEEL SPIN UP FUNCTIONAL CHECK			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		WHL/C WHL/C WHL/C WHL/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ICA-560XL-32-00001	NOSE LANDING GEAR STEERING BEARING				MTH 16-Sep-2007		-			
33-50-00-9600 AFT	AFT EMERGENCY LIGHTING BATTERY PACK RESTORATION	KJVL		9913-1 1373	MTH 27-Jul-2023 HRS 6170.3 LDG 4480		48		27-Jul-2027	29 m 24 d
33-50-00-9600 FORWARD	FORWARD EMERGENCY LIGHTING BATTERY PACK RESTORATION	KJVL		9913-1 1165	MTH 27-Jul-2023 HRS 6170.3 LDG 4480		48		27-Jul-2027	29 m 24 d
34-90-10-7200 NO. 1 059245 : ADC#1 Calibration Date: 05-Jul-2023	NO.1 (PILOT) PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000)	KJVL		7030700-71703 07051444	MTH 05-Jul-2023		24		31-Jul-2025	5 m 28 d
34-90-10-7200 NO. 2 059245 : ADC#2 Calibration Date: 05-Jul-2023	NO. 2 (CO-PILOT) PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000)	KJVL		7030700-71703 07051450	MTH 05-Jul-2023		24		31-Jul-2025	5 m 28 d
35-90-00-7800 059237 : O2	OXYGEN BOTTLE ASSEMBLY (HYDROSTATIC TEST) RESTORATION(DOT-SP 8162)			804882-14 ALT281-52599	MTH 01-Dec-2021		60		31-Dec-2026	22 m 28 d
Hydro Check Date: 01-Dec-2021										
49-10-00-1-B-1	OPERATE APU AT NO-LOAD GOVERNED SPEED FOR 5 MINUTES MINIMUM				16-Sep-2007		A/R			
49-10-00-1-B-2	PRESERVATION PROCEDURE FOR STORAGE MORE THAN 180 DAYS				16-Sep-2007		A/R			
49-10-00-1-B-3	MOTORING FOR TOTAL OF 15 SECONDS				16-Sep-2007		A/R			
49-10-00-3-A-1	PRESERVATION PROCEDURE FOR APU OUT OF SERVICE EXCEEDING 120 DAYS AND UPTO 240 DAYS				16-Sep-2007		A/R			
49-10-00-3-D-4	PERFORM OPERATIONAL TEST OF APU BEFORE IT IS PUT IN SERVICE				16-Sep-2007		A/R			
49-10-00-3-E	PREPARE APU FOR SERVICE AFTER PRESERVATION AND STORAGE				16-Sep-2007		A/R			
49-40-00-2200	AUXILIARY POWER UNIT IGNITER PLUG DETAILED INSPECTION	KDLL		304634-2 NSN	APUH 10-Apr-2024 APUS 2489.5 4054		24 900		30-Apr-2026 3389.5	14 m 27 d 838.6
49-70-01-2200	REMOVE CHIP DETECTOR , CLEAN, EXAMINE AND INSTALL	KJVL		PN SN-UNKNOWN	APUH 21-Aug-2024 APUS 2522.9 4078		12 450		31-Aug-2025 2972.9	6 m 28 d 422
49-90-00-9600 A	CHANGE OIL	KSAT			04-Jul-2021		O/C			
49-90-00-9600 B	REMOVE AND REPLACE OIL FILTER ELEMENT	KSAT			APUH 04-Jul-2021 2158.9		500		2658.9	108
531030	INSPECT DRAIN HOLE IN LOWER FORWARD EDGE OF TAILCONE STINGER FOR PROPER SIZE				MTH 16-Sep-2007		A/R			
70-00-CA-201 E1	EXTERNALS - CHECK FOR SECURITY OF CONNECTIONS, CLAMPS AND BRACKETS				MTH 16-Sep-2007		N/A			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
70-00-CA-201 E2	EXTERNALS - CHECK FOR SECURITY OF CONNECTIONS, CLAMPS AND BRACKETS			MTH 16-Sep-2007		N/A			
70-00-CA-202 E1	CABLES - CHECK FOR EVIDENCE OF FRAYING OR BROKEN STRANDS ON CONTROL CABLE			MTH 16-Sep-2007		N/A			
70-00-CA-202 E2	CABLES - CHECK FOR EVIDENCE OF FRAYING OR BROKEN STRANDS ON CONTROL CABLE			MTH 16-Sep-2007		N/A			
71-00-00 E1 10.	BLEED VALVE OPERATION ADJUSTMENT - TEST			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
71-00-00 E1 8	COMPRESSOR WASH			MTH 11-Aug-2020 HRS 5431.7 LDG 4067		A/R			
71-00-00 E2 10.	BLEED VALVE OPERATION ADJUSTMENT - TEST			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
71-00-00 E2 8	COMPRESSOR WASH			MTH 11-Aug-2020 HRS 5431.7 LDG 4067		A/R			
710020 E1	PERFORMANCE RECOVERY WASH			MTH 16-Sep-2007		A/R			
710020 E2	PERFORMANCE RECOVERY WASH			MTH 16-Sep-2007		A/R			
72-00-00 E1 720060	HOT SECTION INSPECTION (HSI) UNK			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		2500		(7482.6)7532.2	1110.6
72-00-00 E2 720060	HOT SECTION INSPECTION (HSI) UNK			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		2500		(7482.6)7532.2	1110.6
72-00-01 E1	ENGINE PRESERVATION FOR INACTIVE ENGINE - 1 TO 7 DAYS			MTH 16-Sep-2007		A/R			
72-00-01 E2	ENGINE PRESERVATION FOR INACTIVE ENGINE - 1 TO 7 DAYS			MTH 16-Sep-2007		A/R			
72-00-02 E1	ENGINE PRESERVATION FOR INACTIVE ENGINE - 8 TO 28 DAYS			MTH 16-Sep-2007		A/R			
72-00-02 E2	ENGINE PRESERVATION FOR INACTIVE ENGINE - 8 TO 28 DAYS			MTH 16-Sep-2007		A/R			
72-00-03 E1	ENGINE PRESERVATION FOR INACTIVE ENGINE - 29 TO 90 DAYS			MTH 16-Sep-2007		A/R			
72-00-03 E2	ENGINE PRESERVATION FOR INACTIVE ENGINE - 29 TO 90 DAYS			MTH 16-Sep-2007		A/R			
72-00-04 E1	ENGINE PRESERVATION FOR INACTIVE ENGINE - 91 DAYS AND OVER			MTH 16-Sep-2007		A/R			
72-00-04 E2	ENGINE PRESERVATION FOR INACTIVE ENGINE - 91 DAYS AND OVER			MTH 16-Sep-2007		A/R			
72-00-05 E1	ENGINE DE-PRESERVATION FOR INACTIVE ENGINE			MTH 16-Sep-2007		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-05 E2	ENGINE DE-PRESERVATION FOR INACTIVE ENGINE		MTH	16-Sep-2007		A/R			
72-31-00-201 E1	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-201 E2	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-202 E1	LP COMPRESSOR SECTION - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-202 E2	LP COMPRESSOR SECTION - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-203 E1 NO. 1	LP COMPRESSOR SECTION - COMPRESSOR INLET GENERAL VISUAL INSPECTION: DO AN INSPECTION OF THE COMPRESSOR INLET FAN, FAN EXIT STATOR VANES, ABRADABLE FAN SEAL FOR CLEANLINESS, DAMAGE, CORROSION, EROSION AND FOD		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-203 E1 NO. 2	LP COMPRESSOR SECTION - EXAMINE THE BOTTOM CENTER AREA OF THE FAN CASE FOR ICE. MAKE SURE THAT THE FAN TURNS FREELY		MTH	16-Sep-2007		A/R			
72-31-00-203 E1 NO. 3	INSPECT FOR CORROSION THE BLEED VALVE SEAT ON THE INTERMEDIATE CASE AND MAIN INTERMEDIATE CASE FLANGES - USE BORESCOPE WHERE REQUIRED	KDLL	MTH	31-Jan-2023					
			HRS	6101.2	7.4	800		(6859.1)6908.6	487
			LDG	4440					
72-31-00-203 E2 NO. 1	LP COMPRESSOR SECTION - COMPRESSOR INLET GENERAL VISUAL INSPECTION: DO AN INSPECTION OF THE COMPRESSOR INLET FAN, FAN EXIT STATOR VANES, ABRADABLE FAN SEAL FOR CLEANLINESS, DAMAGE, CORROSION, EROSION AND FOD		MTH	18-Feb-2022					
			HRS	5819.3	12.8	800		(6582.6)6632.1	210.5
			LDG	4279					
72-31-00-203 E2 NO. 2	LP COMPRESSOR SECTION - EXAMINE THE BOTTOM CENTER AREA OF THE FAN CASE FOR ICE. MAKE SURE THAT THE FAN TURNS FREELY		MTH	16-Sep-2007		A/R			
72-31-00-203 E2 NO. 3	INSPECT FOR CORROSION THE BLEED VALVE SEAT ON THE INTERMEDIATE CASE AND MAIN INTERMEDIATE CASE FLANGES - USE BORESCOPE WHERE REQUIRED	KDLL	MTH	31-Jan-2023					
			HRS	6101.2	7.4	800		(6859.1)6908.6	487
			LDG	4440					
72-31-00-901 E1	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION		MTH	16-Sep-2007					
			HRS	49.5		5000		(9982.6)10032.1	3610.5
72-31-00-901 E2	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION		MTH	16-Sep-2007					
			HRS	49.5		5000		(9982.6)10032.1	3610.5
72-32-00-201 E1	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH	03-Apr-2018					
			HRS	5032.1		2500		(7482.6)7532.1	1110.5
			LDG	3896					
72-32-00-201 E2	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH	05-Apr-2018					
			HRS	5032.1		2500		(7482.6)7532.1	1110.5
			LDG	3896					
72-32-00-901 E1	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION		MTH	16-Sep-2007					
			HRS	49.5		5000		(9982.6)10032.1	3610.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-32-00-901 E2	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-40-00-201 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-40-00-201 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-40-00-901 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-40-00-901 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-50-00-201 E1	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-50-00-201 E2	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-50-00-701 E1	PERFORM A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
72-50-00-701 E2	PERFORM A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
72-50-00-702 E1	TURBINE SECTION - ACCELERATION/DECELERATION FUNCTIONAL CHECK			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-50-00-702 E2	TURBINE SECTION - ACCELERATION/DECELERATION FUNCTIONAL CHECK			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-50-00-901 E1	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-50-00-901 E2	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-60-00-201 E1	ACCESSORY GEARBOX - ENGINE ACCESSORY GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF INSTALLATION AND GENERAL CONDITION OF ACCESSORIES AND GEARBOX			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-60-00-201 E2	ACCESSORY GEARBOX - ENGINE ACCESSORY GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF INSTALLATION AND GENERAL CONDITION OF ACCESSORIES AND GEARBOX			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-60-00-901 E1	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-60-00-901 E2	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-70-00-201 E1	BYPASS SECTION - BYPASS DUCTS AND FAIRINGS GENERAL VISUAL INSPECTION: DO A CHECK FOR CLEANLINESS AND FOD. DO AN INSPECTION FOR CRACKS IN THE OUTER BYPASS DUCT, REAR BYPASS DUCT, STRUTS AND FAIRING			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-70-00-201 E2	BYPASS SECTION - BYPASS DUCTS AND FAIRINGS GENERAL VISUAL INSPECTION: DO A CHECK FOR CLEANLINESS AND FOD. DO AN INSPECTION FOR CRACKS IN THE OUTER BYPASS DUCT, REAR BYPASS DUCT, STRUTS AND FAIRING			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
72-70-00-202 E1	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-70-00-202 E2	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
72-70-00-901 E1	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-70-00-901 E2	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
72-70-CA-201 E1	BYPASS DUCTS AND FAIRINGS - CHECK FOR LOOSE AIRFRAME CABIN BLEED ADAPTER WHERE IT MATES TO THE ENGINE. BE SURE THERE ARE NO AIR LEAKS			MTH 16-Sep-2007		N/A			
72-70-CA-201 E2	BYPASS DUCTS AND FAIRINGS - CHECK FOR LOOSE AIRFRAME CABIN BLEED ADAPTER WHERE IT MATES TO THE ENGINE. BE SURE THERE ARE NO AIR LEAKS			MTH 16-Sep-2007		N/A			
720075 E1	LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL			MTH 16-Sep-2007		A/R			
720075 E2	LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL			MTH 16-Sep-2007		A/R			
79-10-00-902 E1 1 720010	OVERHAUL ENGINE UNK			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
79-10-00-902 E2 1 720010	OVERHAUL ENGINE UNK			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
73-10-00-202 E1	FUEL DISTRIBUTION - EXTERNAL TUBING GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-202 E2	FUEL DISTRIBUTION - EXTERNAL TUBING GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-204 E1	FUEL DISTRIBUTION - FUEL METERING AND CONTROL COMPONENTS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY, LEAKAGE (NO LEAKAGE PERMITTED) AND GENERAL CONDITION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
73-10-00-204 E2	FUEL DISTRIBUTION - FUEL METERING AND CONTROL COMPONENTS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY, LEAKAGE (NO LEAKAGE PERMITTED) AND GENERAL CONDITION				MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-205 E1	FUEL DISTRIBUTION - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION				MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-205 E2	FUEL DISTRIBUTION - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION				MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-206 E1	FUEL DISTRIBUTION - FUEL FILTER ELEMENT DETAILED INSPECTION: DO AN INSPECTION FOR FOREIGN MATERIAL AND DAMAGE				MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-206 E2	FUEL DISTRIBUTION - FUEL FILTER ELEMENT DETAILED INSPECTION: DO AN INSPECTION FOR FOREIGN MATERIAL AND DAMAGE				MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-10-00-207 E1 NO. 1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE AND CHECK FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA				MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
73-10-00-207 E1 NO. 2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION OF CABLE AND LINKAGES	KDLL			MTH 31-Jan-2023 HRS 6101.2 LDG 4440		800		(6851.7)6901.2	479.6
73-10-00-207 E1 NO. 3	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	UNK			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			
73-10-00-207 E2 NO. 1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE AND CHECK FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA				MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
73-10-00-207 E2 NO. 2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION OF CABLE AND LINKAGES	KDLL			MTH 31-Jan-2023 HRS 6101.2 LDG 4440		800		(6851.7)6901.2	479.6
73-10-00-207 E2 NO. 3	DIMENSIONAL CHECK EMERGENCY FUEL SHUTOFF PIN	UNK			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			
73-10-00-701 E1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: REMOVAL/ADJUSTMENT & INSTALLATION				MTH 16-Sep-2007 HRS 49.5		2500		(7482.6)7532.1	1110.5
73-10-00-701 E2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: REMOVAL/ADJUSTMENT & INSTALLATION				MTH 16-Sep-2007 HRS 49.5		2500		(7482.6)7532.1	1110.5
73-10-00-901 E1	INSTALL FILTER NEW FUEL FILTER ELEMENT	KJVL	PN SN-UNKNOWN		MTH 27-Jul-2023 HRS 6170.3 LDG 4480		1200		(7320.8)7370.3	948.7
73-10-00-901 E2	INSTALL FILTER NEW FUEL FILTER ELEMENT	KJVL	PN SN-UNKNOWN		MTH 27-Jul-2023 HRS 6170.3 LDG 4480		1200		(7320.8)7370.3	948.7



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
73-10-00-902 E1	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
73-10-00-902 E2	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
73-10-CA-201 E1	FUEL SYSTEM - FUEL FLOW DIVIDER VALVE: SECURITY, LEAKAGE AND GENERAL CONDITION		MTH 16-Sep-2007		A/R			
73-10-CA-201 E2	FUEL SYSTEM - FUEL FLOW DIVIDER VALVE: SECURITY, LEAKAGE AND GENERAL CONDITION		MTH 16-Sep-2007		A/R			
73-20-00-201 E1 NO. 1	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS. EXAMINE THE CABLES FOR SIGN OF WEAR, FRAYING, CHAFING AND CRACKS.DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-20-00-201 E1 NO. 2	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: EXAMINE THE CONTROL LINKAGE AND ROD END BEARINGS FOR FREEDOM OF MOVEMENT	KDLL	MTH 31-Jan-2023 HRS 6101.2 LDG 4440		800		(6851.7)6901.2	479.6
73-20-00-201 E2 NO. 1	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS. EXAMINE THE CABLES FOR SIGN OF WEAR, FRAYING, CHAFING AND CRACKS.DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
73-20-00-201 E2 NO. 2	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: EXAMINE THE CONTROL LINKAGE AND ROD END BEARINGS FOR FREEDOM OF MOVEMENT	KDLL	MTH 31-Jan-2023 HRS 6101.2 LDG 4440		800		(6851.7)6901.2	479.6
73-20-00-901 E1	FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN.DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESSREPLACEMENT		MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
73-20-00-901 E2	FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN.DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESSREPLACEMENT		MTH 18-Feb-2022 HRS 5819.3 LDG 4279		800		(6569.8)6619.3	197.7
73-20-00-902 E1	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
73-20-00-902 E2	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
731004 E1	INSPECT FUEL MANIFOLD		MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731004 E2	INSPECT FUEL MANIFOLD		MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731005 E1	FLOW DIVIDER - OVERHAUL OR REFURBISH UNK		MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731005 E2	FLOW DIVIDER - OVERHAUL OR REFURBISH UNK		MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731015 E1	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731015 E2	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731105 E1	DO AN INSPECTION - FUEL SHUT-OFF CABLE			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731105 E2	DO AN INSPECTION - FUEL SHUT-OFF CABLE			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731125 E1	INSPECT FUEL SHUT-OFF VALVE		31J2944-01 WV021918	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731125 E2	INSPECT FUEL SHUT-OFF VALVE		31J2944-01 WV022118	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731151 E1	FUEL NOZZLE ASSEMBLY - OVERHAUL/REFURBISH UNK			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
731151 E2	FUEL NOZZLE ASSEMBLY - OVERHAUL/REFURBISH UNK			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732003 E1	INSPECT EEC			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732003 E2	INSPECT EEC			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732005 E1	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012636-25 F64323	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		5000		(10910.2)10959.7	4538.1
732005 E2	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012636-25 F67029	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		5000		(10910.2)10959.7	4538.1
732010 E1	INSPECT T0 SENSOR			MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732010 E2	INSPECT T0 SENSOR			MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732015 E1	INSPECT T1 FCU SENSOR		818487-4 KC072687	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
732015 E2	INSPECT T1 FCU SENSOR		818487-4 KC072200	MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
74-20-00-201 E1	IGNITION - IGNITION EXCITER GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND GENERAL CONDITION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
74-20-00-201 E2	IGNITION - IGNITION EXCITER GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND GENERAL CONDITION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
74-20-00-202 E1	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK (PRE-SB30340): DO A CHECK FOR CLEANLINESS AND MEASURE EROSION	KJVL		MTH 21-Aug-2024 HRS 6355.7 LDG 4596			300		(6606.2)6655.7	234.1
74-20-00-202 E2	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK (PRE-SB30340): DO A CHECK FOR CLEANLINESS AND MEASURE EROSION	KJVL		MTH 21-Aug-2024 HRS 6355.7 LDG 4596			300		(6606.2)6655.7	234.1
74-20-00-203 E1	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK (POST-SB30340): DO A CHECK FOR CLEANLINESS AND MEASURE EROSION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279			800		(6569.8)6619.3	197.7
74-20-00-203 E2	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK (POST-SB30340): DO A CHECK FOR CLEANLINESS AND MEASURE EROSION			MTH 18-Feb-2022 HRS 5819.3 LDG 4279			800		(6569.8)6619.3	197.7
74-20-00-205 E1	IGNITION - IGNITION CABLES GENERAL VISUAL INSPECTION: DO A CHECK FOR CHAFING, WEAR AND SECURITY			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		12.8	800		(6582.6)6632.1	210.5
74-20-00-205 E2	IGNITION - IGNITION CABLES GENERAL VISUAL INSPECTION: DO A CHECK FOR CHAFING, WEAR AND SECURITY			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		12.8	800		(6582.6)6632.1	210.5
74-20-00-206 E1	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 03-Apr-2018 HRS 5032.1 LDG 3896			2500		(7482.6)7532.1	1110.5
74-20-00-206 E2	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 05-Apr-2018 HRS 5032.1 LDG 3896			2500		(7482.6)7532.1	1110.5
74-20-00-701 E1	IGNITION - IGNITERS OPERATIONAL CHECK: DO AN OPERATIONAL TEST			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		12.8	800		(6582.6)6632.1	210.5
74-20-00-701 E2	IGNITION - IGNITERS OPERATIONAL CHECK: DO AN OPERATIONAL TEST			MTH 18-Feb-2022 HRS 5819.3 LDG 4279		12.8	800		(6582.6)6632.1	210.5
74-20-00-901 E1	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
74-20-00-901 E2	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
741000 E1	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 03-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
741000 E2	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 03-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
741015 E1	CLEAN AND INSPECT IGNITION PLUGS			MTH 03-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
741015 E2	CLEAN AND INSPECT IGNITION PLUGS			MTH 05-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
75-10-00-201 E1	AIR SYSTEM - ANTI-ICE VALVE AND P3 ANTI-ICE TUBE (LEAK CHECK) GENERAL VISUAL INSPECTION: DO A CHECK FOR LEAKAGE AT P3 AIR SUPPLY TO BLEED VALVE, ANTI-ICE VALVE, ANTI-ICE AIR TUBE AND FCU		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-201 E2	AIR SYSTEM - ANTI-ICE VALVE AND P3 ANTI-ICE TUBE (LEAK CHECK) GENERAL VISUAL INSPECTION: DO A CHECK FOR LEAKAGE AT P3 AIR SUPPLY TO BLEED VALVE, ANTI-ICE VALVE, ANTI-ICE AIR TUBE AND FCU		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-202 E1	AIR SYSTEM - P3 BELLOWS SEAL AND BLEED AIR TRANSFER TUBE GENERAL VISUAL INSPECTION: DO A VISUAL INSPECTION FOR AIR LEAK		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-202 E2	AIR SYSTEM - P3 BELLOWS SEAL AND BLEED AIR TRANSFER TUBE GENERAL VISUAL INSPECTION: DO A VISUAL INSPECTION FOR AIR LEAK		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-203 E1 NO. 1	AIR SYSTEM - BLEED OFF VALVE GENERAL VISUAL INSPECTION: EXAMINE THE TORQUE MOTOR ELECTRICAL CONNECTION FOR SECURITY, FRAYING AND CORROSION		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-203 E1 NO. 2	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE		MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			
75-10-00-203 E2 NO. 1	AIR SYSTEM - BLEED OFF VALVE GENERAL VISUAL INSPECTION: EXAMINE THE TORQUE MOTOR ELECTRICAL CONNECTION FOR SECURITY, FRAYING AND CORROSION		MTH 18-Feb-2022 HRS 5819.3 LDG 4279	12.8	800		(6582.6)6632.1	210.5
75-10-00-203 E2 NO. 2	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE		MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			
75-10-00-204 E1	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH 03-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
75-10-00-204 E2	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH 03-Apr-2018 HRS 5032.1 LDG 3896		2500		(7482.6)7532.1	1110.5
75-10-00-901 E1	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
75-10-00-901 E2	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
751006 E1	ANTI ICING VALVE - OVERHAUL/REFURBISH UNK 540-0406-4 4144		MTH 03-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
751006 E2	ANTI ICING VALVE - OVERHAUL/REFURBISH UNK 540-0406-5 4129		MTH 05-Apr-2018 HRS 5032.1 LDG 3896		5000		(9982.6)10032.1	3610.5
751050 E1	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER		MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
751050 E2	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
753000 E1	REPLACE BOV TORQUE MOTOR	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
753000 E2	REPLACE BOV TORQUE MOTOR	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
753001 E1	INSPECT P3 AIR INERTIAL SEPARATOR	MTH 03-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
753001 E2	INSPECT P3 AIR INERTIAL SEPARATOR	MTH 05-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
77-10-00-201 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS, CABLES FOR SIGNS OF WEAR, FRAYING, CHAFING AND CRACKS DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
77-10-00-201 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS, CABLES FOR SIGNS OF WEAR, FRAYING, CHAFING AND CRACKS DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
77-10-00-202 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			2500		(7482.6)7532.2	1110.6
77-10-00-202 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION	MTH 05-Apr-2018 HRS 5032.2 LDG 3896			2500		(7482.6)7532.2	1110.6
77-10-00-901 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	MTH 18-Feb-2022 HRS 5819.4 LDG 4279			800		(6569.8)6619.4	197.8
77-10-00-901 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	MTH 18-Feb-2022 HRS 5819.4 LDG 4279			800		(6569.8)6619.4	197.8
77-10-00-902 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
77-10-00-902 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
77-10-01 E1 5.	SPEED SENSORS - MAINTENANCE PRACTICES - N2 SPEED SENSOR REMOVAL & INSTALLATION	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			A/R			
77-10-01 E1 6.	SPEED SENSORS - MAINTENANCE PRACTICES - N1 SPEED SENSOR REMOVAL & INSTALLATION	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			A/R			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
77-10-01 E1 7.	SPEED SENSORS - MAINTENANCE PRACTICES - SENSOR CLEANING AND INSPECTION			MTH 16-Sep-2007		A/R			
77-10-01 E2 5.	SPEED SENSORS - MAINTENANCE PRACTICES - N2 SPEED SENSOR REMOVAL & INSTALLATION			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			
77-10-01 E2 6.	SPEED SENSORS - MAINTENANCE PRACTICES - N1 SPEED SENSOR REMOVAL & INSTALLATION			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			
77-10-01 E2 7.	SPEED SENSORS - MAINTENANCE PRACTICES - SENSOR CLEANING AND INSPECTION			MTH 16-Sep-2007		A/R			
77-20-01 E1	T1 SYSTEM - MAINTENANCE PRACTICES			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
77-20-01 E2	T1 SYSTEM - MAINTENANCE PRACTICES			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
77-20-02 E1	T6 SYSTEM - MAINTENANCE PRACTICES			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
77-20-02 E2	T6 SYSTEM - MAINTENANCE PRACTICES			MTH 05-Apr-2018 HRS 5032.2 LDG 3896		5000		(9982.6)10032.2	3610.6
77-40-01 E1	DATA COLLECTION UNIT (DCU) - MAINTENANCE PRACTICES			MTH 16-Sep-2007		A/R			
77-40-01 E2	DATA COLLECTION UNIT (DCU) - MAINTENANCE PRACTICES			MTH 16-Sep-2007		A/R			
771014 E1	INSPECT N1 SPEED SENSOR		31J2072-01 CH1623	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
771014 E2	INSPECT N1 SPEED SENSOR		31J2072-01 CH1622	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
771015 E1	INSPECT N2 SPEED SENSOR		31J2073-01 CH2488	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
771015 E2	INSPECT N2 SPEED SENSOR		31J2073-01 CH2503	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
774040 E1	DATA COLLECTION UNIT - DOWNLOAD DATA		32205-03 DP074606	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
774040 E2	DATA COLLECTION UNIT - DOWNLOAD DATA		62118-05 17050983	MTH 16-Sep-2007 HRS 49.5		5000		(9982.6)10032.1	3610.5
78-10-00-201 E1 NO. 1	ENGINE EXHAUST - EXHAUST AND MIXER: GVI OBVIOUS SIGNS OF DAMAGE OR LOOSE DEBRIS			MTH 16-Sep-2007		BF/F BF/F			
78-10-00-201 E1 NO. 2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 03-Apr-2018 HRS 5032.2 LDG 3896		2500		(7482.6)7532.2	1110.6
78-10-00-201 E2 NO. 1	ENGINE EXHAUST - EXHAUST AND MIXER: GVI OBVIOUS SIGNS OF DAMAGE OR LOOSE DEBRIS			MTH 16-Sep-2007		BF/F BF/F			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
78-10-00-201 E2 NO. 2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION	MTH 05-Apr-2018 HRS 5032.2 LDG 3896			2500		(7482.6)7532.2	1110.6
78-10-00-202 E1	ENGINE EXHAUST - EMERGENCY FUEL SHUT OFF LEVER AND CABLE DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA, EXAMINE THE CABLE AND LINKAGES	MTH 03-Apr-2018 HRS 5032.1 LDG 3896			1600		(6582.6)6632.1	210.5
78-10-00-202 E2	ENGINE EXHAUST - EMERGENCY FUEL SHUT OFF LEVER AND CABLE DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA, EXAMINE THE CABLE AND LINKAGES	MTH 05-Apr-2018 HRS 5032.1 LDG 3896			1600		(6582.6)6632.1	210.5
78-10-00-901 E1	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
78-10-00-901 E2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION	MTH 16-Sep-2007 HRS 49.5			5000		(9982.6)10032.1	3610.5
79-10-00-201 E1	OIL SYSTEM - EXTERNAL OIL TUBE GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-201 E2	OIL SYSTEM - EXTERNAL OIL TUBE GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-202 E1	OIL SYSTEM - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION. NO LEAKAGE PERMITTED	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-202 E2	OIL SYSTEM - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION. NO LEAKAGE PERMITTED	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-203 E1	OIL SYSTEM - ACCESSORY GEAR BOX PAD SEAL GENERAL VISUAL INSPECTION: EXAMINE THE PAD SEALS FOR OIL LEAKS	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-203 E2	OIL SYSTEM - ACCESSORY GEAR BOX PAD SEAL GENERAL VISUAL INSPECTION: EXAMINE THE PAD SEALS FOR OIL LEAKS	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-204 E1	OIL SYSTEM - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: EXAMINE FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-204 E2	OIL SYSTEM - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: EXAMINE FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-205 E1	OIL SYSTEM - OIL FILTER DETAILED INSPECTION: REMOVE AND DO A CHECK FOR FOREIGN MATERIAL AND DAMAGE	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6
79-10-00-205 E2	OIL SYSTEM - OIL FILTER DETAILED INSPECTION: REMOVE AND DO A CHECK FOR FOREIGN MATERIAL AND DAMAGE	MTH 18-Feb-2022 HRS 5819.4 LDG 4279		12.8	800		(6582.6)6632.2	210.6



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
79-10-00-206/601 E1 NO. 1	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS		MTH	16-Sep-2007		BF/F BF/F			
79-10-00-206/601 E1 NO. 2	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS. MONITOR THE OIL QUALITY ON CONDITION AND DO ANALYSIS PERIODICALLY AS OBSERVATIONS WARRANT		MTH	18-Feb-2022					
			HRS	5819.4	12.8	800		(6582.6)6632.2	210.6
			LDG	4279					
79-10-00-206/601 E2 NO. 1	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS		MTH	16-Sep-2007		BF/F BF/F			
79-10-00-206/601 E2 NO. 2	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS. MONITOR THE OIL QUALITY ON CONDITION AND DO ANALYSIS PERIODICALLY AS OBSERVATIONS WARRANT		MTH	18-Feb-2022					
			HRS	5819.4	12.8	800		(6582.6)6632.2	210.6
			LDG	4279					
79-10-00-207 E1 1	OIL SYSTEM - IMPENDING BYPASS VALVE INDICATOR : DO A CHECK OF AIRCRAFT COCKPIT INDICATOR LAMP		MTH	03-Apr-2018		A/R			
			HRS	5032.1					
			LDG	3896					
79-10-00-207 E1 2	OIL SYSTEM - OIL FILTER BYPASS VALVE FUNCTIONAL CHECK		MTH	18-Feb-2022					
			HRS	5819.4		2500		(8269.8)8319.4	1897.8
			LDG	4279					
79-10-00-207 E2 1	OIL SYSTEM - IMPENDING BYPASS VALVE INDICATOR : DO A CHECK OF AIRCRAFT COCKPIT INDICATOR LAMP		MTH	05-Apr-2018		A/R			
			HRS	5032.1					
			LDG	3896					
79-10-00-207 E2 2	OIL SYSTEM - OIL FILTER BYPASS VALVE FUNCTIONAL CHECK		MTH	18-Feb-2022					
			HRS	5819.4		2500		(8269.8)8319.4	1897.8
			LDG	4279					
79-10-00-208/209 E1	OIL SYSTEM - MAGNETIC CHIP DETECTOR/COLLECTOR GENERAL VISUAL INSPECTION: REMOVE AND DO A CHECK FOR METALLIC DEBRIS		MTH	18-Feb-2022					
			HRS	5819.4	12.8	800		(6582.6)6632.2	210.6
			LDG	4279					
79-10-00-208/209 E2	OIL SYSTEM - MAGNETIC CHIP DETECTOR/COLLECTOR GENERAL VISUAL INSPECTION: REMOVE AND DO A CHECK FOR METALLIC DEBRIS		MTH	18-Feb-2022					
			HRS	5819.4	12.8	800		(6582.6)6632.2	210.6
			LDG	4279					
79-10-00-901 E1	INSTALL FILTER NEW OIL FILTER ELEMENT	KJVL	PN	MTH	27-Jul-2023				
			SN-UNKNOWN	HRS	6170.3	1200		(7320.8)7370.3	948.7
				LDG	4480				
79-10-00-901 E2	INSTALL FILTER NEW OIL FILTER ELEMENT	KJVL	PN	MTH	27-Jul-2023				
			SN-UNKNOWN	HRS	6170.3	1200		(7320.8)7370.3	948.7
				LDG	4480				
790020 E1	CHANGE OIL	KICT		MTH	22-Oct-2012	A/R			
				HRS	2584.8				
				LDG	2110				
790020 E2	CHANGE OIL	KICT		MTH	22-Oct-2012	A/R			
				HRS	2584.8				
				LDG	2110				
792010 E1	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH	03-Apr-2018				
				HRS	5032.2	5000		(9982.6)10032.2	3610.6
				LDG	3896				



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
792010 E2	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNK	MTH 05-Apr-2018 HRS 5032.2 LDG 3896			5000		(9982.6)10032.2	3610.6
793005 E1	FUEL TO OIL HEAT EXCHANGER - OVERHAUL/REFURBISH UNK	MTH 03-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
793005 E2	FUEL TO OIL HEAT EXCHANGER - OVERHAUL/REFURBISH UNK	MTH 05-Apr-2018 HRS 5032.1 LDG 3896			5000		(9982.6)10032.1	3610.5
793006 E1	OVERHAUL OR REFURBISH OIL TANK FILLER CAP	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			5000		(9982.6)10032.2	3610.6
793006 E2	OVERHAUL OR REFURBISH OIL TANK FILLER CAP	MTH 05-Apr-2018 HRS 5032.2 LDG 3896			5000		(9982.6)10032.2	3610.6
793021 E1	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			5000		(9982.6)10032.2	3610.6
793021 E2	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)	MTH 05-Apr-2018 HRS 5032.2 LDG 3896			5000		(9982.6)10032.2	3610.6
80-11-00-2200 APU	AUXILIARY POWER UNIT STARTER - GENERATOR DETAILED INSPECTION	300SGL138Q-6 8408XL MTH 24-May-2022 HRS 5912.7 LDG 4335 APUH 2351		24.1	500		2875.1	324.2



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE *CF			4713-19 0888	MTH 16-Sep-2007		O/C	0		
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2621	MTH 16-Sep-2007		O/C	0		
211120 RIGHT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2624	MTH 16-Sep-2007		O/C	0		
212100 LOWER LEFT	WARM AIR CHECK VALVE *CF			4001-20 2839A	MTH 16-Sep-2007		O/C	0		
212100 LOWER RIGHT	WARM AIR CHECK VALVE *CF			4001-20 2680A	MTH 16-Sep-2007		O/C	0		
212100 UPPER RIGHT	COOL AIR CHECK VALVE *CF			4001-20 3285A	MTH 16-Sep-2007		O/C	0		
212100 UPPER LEFT	COOL AIR CHECK VALVE *CF			4001-20 3304A	MTH 16-Sep-2007		O/C	0		
212200	MOTOR AND BLOWER ASSEMBLY *CF			7003-400 0733	MTH 16-Sep-2007		O/C	0		
213005	MANUAL TOGGLE VALVE 9912409-12	*CF		52773-114 1488	MTH 16-Sep-2007		O/C	0		
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-13	SMF		52770-116 962	MTH 13-Aug-2008 HRS 462		O/C	0 0		
213007 PRIMARY	OUTFLOW VALVE 9912409-19	*CF		52771-314 1120B	MTH 16-Sep-2007		O/C	0		
213007 SECONDARY	OUTFLOW VALVE 9912409-11	*CF		52772-114 1335B	MTH 16-Sep-2007		O/C	0		
213101	ALT PRESSURE SWITCH 9910095-6	KMCO		GB300NA161 1503222	MTH 20-Aug-2015 HRS 4301.8 LDG 3582 APUH 1676 APUS 3198		O/C	0 0		
215001	ENVIRONMENTAL CONTROL UNIT 9912493-8	*CF		2215460-3 870	MTH 16-Sep-2007		O/C	0		
215004	PAC OVERHEAT SWITCH 1173T0570	*CF		927223-2-2 0421	MTH 16-Sep-2007		O/C	0		
215005	ACM COOLING TURBINE *CF			2206610-1 864	MTH 16-Sep-2007		O/C	0		
215006	HEAT EXCHANGER *CF			2340594-6 925	MTH 16-Sep-2007		O/C	0		
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF		2215605-1 NSN	MTH 16-Sep-2007		O/C	0		
215101	WATER SEPARATOR TEMP 1 SENSOR KFEX			9914130-20 9B795	MTH 04-Oct-2019 HRS 5324.2 LDG 4020		O/C	0 0		
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-5	*CF		1E64-2 10BB253	MTH 16-Sep-2007		O/C	0		
216003 NO. 1	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 5BC135	MTH 16-Sep-2007		O/C	0		
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 5BC125	MTH 16-Sep-2007		O/C	0		
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF		1E46-1 11BB366	MTH 16-Sep-2007		O/C	0		
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	*CF		1E46-1 4BC118	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
216015	CABIN TEMPERATURE DISPLAY 25-22-03 06A-36	101016-10 2510721	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C	0 0 0		
216099 216100	ECU TEMP CONTROL VALVE 9912518-2 KFXE	27241287-14 11AT228F	MTH 04-Oct-2019 HRS 5324.2 LDG 4020		O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2 *CF	27241287-14 3BC74A	MTH 16-Sep-2007		O/C	0		
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE KFXE	27241287-14 / 9912518-2 7BJ102F	MTH 10-Feb-2016 HRS 4431.4 LDG 3636		O/C	0 0		
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH *CF	1173T42 3333	MTH 16-Sep-2007		O/C	0		
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH *CF	1173T42 3332	MTH 16-Sep-2007		O/C	0		
217001	WATER SEPARATOR 9912493-7 *CF	2341316-2 921	MTH 16-Sep-2007		O/C	0		
217101 LEFT	OZONE CONVERTER 9914523-2 *CF	31A437-1 12282191	MTH 16-Sep-2007		O/C	0		
217101 RIGHT	OZONE CONVERTER 9914523-2 *CF	31A437-1 12212184	MTH 16-Sep-2007		O/C	0		
221009	AUTOPILOT (PC400) CONTROLLER PC-400 *CF	7003897-923 07043659	MTH 16-Sep-2007		O/C	0		
221010 AILERON	DRIVE SERVO SM-200 *CF	4006719-906 0703H685	MTH 16-Sep-2007		O/C	0		
221010 AUTOPILOT	ELEVATOR TRIM SERVO	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
221010 ELEVATOR	DRIVE SERVO *CF	4006719-921 0703H682	MTH 16-Sep-2007		O/C	0		
221010 RUDDER	DRIVE SERVO *CF	4006719-922 0703H625	MTH 16-Sep-2007		O/C	0		
23-70-00-9600 237006A	DK120 OR DK120/90 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD 266-E0305-00 KFXE	810-2008/K NSN	MTH 19-Aug-2019 HRS 5308.7 LDG 4014		DUE DUE DUE DUE	0 0 0 0	31-May-2025	3 m 28 d
Expiration Date: 31-May-2025								
230003	AMPLIFIER	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
230004	BLUE TOOTH MODULE	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
230005	XM RECEIVER	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231003	HIGH FREQUENCY RECEIVER/EXCITER HONEYWELL KHF-1050 RX 1053	064-01073-0102 3185	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			
231004	HF POWER AMP FXE HONEYWELL KHF-1050 KPA 1052	064-01072-0101 KPA1052-7123	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
231006	H.F. ANTENNA COUPLER			064-01074-0101 KAC1052-4837	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			
231011	KHF950 HIGH FREQUENCY (KFS594) CONTROLLER PS440	FXE		G7511-01 1396	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			
231030 AFT	AFT L5 AVANCE ANTENNA			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231030 FWD	FWD L5 AVANCE ANTENNA			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231030	L5 AVANCE			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231050	AIRCELL CONFIGURATION MODULE KCOU			P14126 1412630801	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C			
231051	AIRCELL SWIFT BROADBAND UNIT (SBU) MODEM UNIT PN SN-UNKNOWN				MTH 16-Sep-2007		O/C	0		
231105	KHF950 HF POWER AMPLIFIER/ANTENNA (KAC952) COUPLER FXE			064-01074-0101 KAC1052-4837	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			
231501	FLITEPHONE VI ASSEMBLY ANTENNA IRIDIUM	*CF		S67-1575-109 6318	MTH 16-Sep-2007		O/C	0		
231524	ST-4300 RACK			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231525	ST-4300 SATELLITE TRANCEIVER			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231526	INMARSAT LNA - HI-POWER UT506			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231527	INMARSAT FILTER UT512			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
231528	IRIDIUM FILTER UT504			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
232003 NO. 1	COMM ANTENNA	*CF		S65-8282-1 2123	MTH 16-Sep-2007		O/C			
232003 NO. 2	COMM ANTENNA	*CF		21-38-1RF/36 10966	MTH 16-Sep-2007		O/C	0		
232003	GLOBAL VHF AFIS ANTENNA			S65-8282-1 2123	MTH 16-Sep-2007		O/C	0		
232004	FLITEPHONE 800 RADIOTELEPHONE (RT800) TRANCEIVER ST3100	*CF		400-10680-001 1068012330	MTH 16-Sep-2007		O/C	0		
232006	AIRCELL ROUTER	KDLL		P12083-001 1208373186	MTH 30-Nov-2023 HRS 6223.8 LDG 4514		O/C			
232006A AFT	AIRCELL ANTENNA	SMF		P12949 345667	MTH 03-May-2011 HRS 1723 LDG 1443		O/C	0 0 0		
232006A FWD	AIRCELL ANTENNA	SMF		P12949 345644	MTH 03-May-2011 HRS 1723 LDG 1443		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
232008 NO. 1	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT	KSFB	AV	7510733-666 0605A577	MTH 20-Feb-2018 HRS 4982.6 LDG 3875		O/C			
232008 NO. 2	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT			7510733-666 1303D066	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C			
232010 NO. 1	COMM TRANSCEIVER TR-833	*CF		7510763-901 0608A967	MTH 16-Sep-2007		O/C	0		
232010 NO. 2	COMM TRANSCEIVER TR-833	SMF		7510763-901 0605A616	MTH 08-May-2009 HRS 741		O/C	0 0		
232011	SELCAL DECODER CSD-714	FXE		1200008-000 142	MTH 22-Apr-2016 HRS 4502 LDG 3665		O/C			
232012	ATG4000 BROADBAND RLU AIRCELL			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
232013 NO. 1	CLUSTER COMM MODULE XC-833	*CF		7510784-835 0608B042	MTH 16-Sep-2007		O/C	0		
232013 NO. 2	CLUSTER COMM MODULE XC-833	SMF		7510784-835 0901C903	MTH 08-May-2009 HRS 741		O/C	0 0		
232015 #6	SEAT AIRCELL HANDSET			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
232015 #7	SEAT AIRCELL HANDSET			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
232023 #1	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124929	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232023 #2	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124926	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232023 #3	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124918	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232023 #4	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124903	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232023 #5	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124886	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232023 #6	GOGO INTERNAL WIFI ANTENNA --			P16917-001 1691700124859	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232024 #1	GOGO INTERNAL TM (TERRESTRIAL MODEM) ANTENNA --			P18350-001 P1835014543	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232024 #2	GOGO INTERNAL TM (TERRESTRIAL MODEM) ANTENNA --			P18350-001 P1835014535	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
232026 AFT	AIRCELL ANTENNA			P12949 345667	MTH 03-May-2011 HRS 1723 LDG 1443		O/C	0 0 0		
232026 FWD	AIRCELL ANTENNA			P12949 345644	MTH 03-May-2011 HRS 1723 LDG 1443		O/C	0 0 0		
232030	KRX-1053 HF RECEIVER/EXCITER FXE			064-01073-0102 3185	MTH 15-Apr-2016 HRS 4483.8 LDG 3658		O/C			
232050	AIRCELL AIR-GROUND TRANSCEIVER KDLL			P15864-001 1586412719	MTH 30-Nov-2023 HRS 6223.8 LDG 4514		O/C			
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER AV-850A *CF			7511001-915 0703B947	MTH 16-Sep-2007		O/C	0		
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER AV-850A *CF			7511001-915 0703B948	MTH 16-Sep-2007		O/C	0		
235006	INT PC DATA PANEL			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
236002R	ROSEN COCKPIT CONTROLLER			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
237001	COCKPIT VOICE RECORDER FA2100 *CF			2100-1020-02 451891	MTH 16-Sep-2007		O/C	0		
237002	CVR GRAVITY SWITCH *CF			6895D1-X-5-5 6636	MTH 16-Sep-2007		O/C	0		
237004	CVR CONTROL UNIT *CF			S251-1120-00 000442272	MTH 16-Sep-2007		O/C	0		
237005 NO. 1	GOGO 4G BELLY ANTENNA --			P34110-002 SN-UNKNOWN	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
237005 NO. 2	GOGO 4G BELLY ANTENNA --			P34110-002 SN-UNKNOWN	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
237005	AIRCELL CONFIGURATION MODULE (GOGO) --			P14126 1412630801	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
237006	CVR UNDERWATER LOCATOR BEACON 03-TM-0037 SMF			DK120 SD17689	MTH 15-Sep-2013 HRS 3128.3 LDG 2538		O/C	0 0 0		
238001	STDBY CONTROL UNIT CD-850 KFXE	G		7513000-835 07043493	MTH 19-Sep-2019 HRS 5324.2 LDG 4020		O/C			
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6 *CF			91479-1 1588	MTH 16-Sep-2007		O/C	0		
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6 *CF			91479-1 1624	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains	
240002 GALLEY	GALLEY GROUND FAULT INTERRUPTER (GFI) OUTLET PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0			
240003	ABC 2000 INVERTER PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0			
240004	ENTRY SWITCH PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0			
242001	30 VA STATIC INVERTER SS50 6406	MTH 30-Sep-2015 HRS 4353.7 LDG 3603		O/C	7			
242002 TAILCONE	500 VA STATIC (UT043) INVERTER KFXE SS50 6406	MTH 30-Sep-2015 HRS 4353.7 LDG 3603		O/C	7 0 0			
242050 LEFT	AC (UD017) GENERATOR 9914435-8 *CF	91372-3 1286	MTH 16-Sep-2007		O/C	0		
242050 RIGHT	AC (UE018) GENERATOR 9914435-8 KJVL	91372-3 735	MTH 11-Dec-2024 HRS 6416.4 LDG 4639		O/C	0 0		
243003 APU	GENERATOR (UT032) CONTROL UNIT MHR 51525-001F 96051	MTH 13-Jul-2012 HRS 2421.2 LDG 1989		O/C				
243003 LEFT	GENERATOR (UT007) CONTROL UNIT UNK 51525-001F 96051	MTH 06-Jun-2024 HRS 6317.8 LDG 4572		O/C				
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT UNK 51525-001F 99728	MTH 06-Jun-2024 HRS 6317.8 LDG 4572		O/C				
243004 LEFT	DC (EI011) AMMETER S3439-1 *CF	MD144-1 K0611521	MTH 16-Sep-2007		O/C	0		
243004 RIGHT	DC (EI010) AMMETER S3439-1 *CF	MD144-1 B0710827	MTH 16-Sep-2007		O/C	0		
243005	DC (EI009) VOLTMETER MD129-1 *CF	C662502-0101 B0711272	MTH 16-Sep-2007		O/C	0		
243007	MAIN SHIP (UY006) BATTERY RG-380E/44LA5 KCOU	S3597-8 41181955	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	30 589 349		
243008	OVERHEAT MONITOR- SMF 1529-1 2877	MTH 17-Jun-2015 HRS 4225.1 LDG 3517		O/C	0 0 0			
243009	BATTERY TEMP INDICATOR *CF 1229-1 3519	MTH 16-Sep-2007		O/C	0			
243010	BATTERY TEMP SENSOR S3597-9 KFXE	TS-C1A3 40006583	MTH 31-Oct-2017 HRS 4901.8 LDG 3843 APUH 1903.8 APUS 3511		O/C	0 0		
243015	BATTERY DISCONNECT (KY001) RELAY *CF A876K CP26903	MTH 16-Sep-2007		O/C	0			
243016	OVERVOLTAGE (UZ003) MONITOR- *CF 1645-1-3 4204	MTH 16-Sep-2007		O/C	0			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245002 LEFT	START NZ013 PCB	6318324-5 NSN	MTH 02-Sep-2014 HRS 3723.8 LDG 3068		O/C	0 0 0		
245079 LEFT	START CNTL NZ013 PCB SJC	6318324-5 NSN	MTH 02-Sep-2014 HRS 3723.8 LDG 3068		O/C	0 0		
245079 RIGHT	START CNTL NZ012 PCB SMF	6318324-5 NSN	MTH 13-Aug-2008 HRS 462		O/C	0 0		
245080	TRIM NZ001 PCB *CF	6518351-7 1008	MTH 16-Sep-2007		O/C	0		
245081	PRESS NZ002 PCB *CF	6518352-5 NSN	MTH 16-Sep-2007		O/C	0		
245082	DIMMING NZ023 PCB *CF	6518366-3 0458	MTH 16-Sep-2007		O/C	0		
245083 LEFT	EEC INTERFACE NZ021 PCB KFXE	6618002-4 1549	MTH 21-Oct-2017 HRS 4896.3 LDG 3839 APUH 1896.9 APUS 3504		O/C	0 0		
245083 RIGHT	EEC INTERFACE NZ020 PCB *CF	6618002-4 0486	MTH 16-Sep-2007		O/C	0		
245083	PCB AUDIO CONTROL	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
245084	LANDING GEAR NZ004 PCB *CF	6618704-6 0795	MTH 16-Sep-2007		O/C	0		
245086	SQUAT SW NZ006 PCB *CF	6618706-1 0730	MTH 16-Sep-2007		O/C	0		
245087	CABIN DOOR NZ007 PCB KFXE	6618707-26 0597	MTH 02-Apr-2018 HRS 5023.8 LDG 3892		O/C	0 0		
245088	LANDING GEAR CONT NZ009 PCB *CF	6618735-1 0333	MTH 16-Sep-2007		O/C	0		
245091	NO TAKE-OFF NZ008 PCB FDR OPTION *CF	6618708-6 0295	MTH 16-Sep-2007		O/C	0		
245092 LEFT	FUEL NZ015 PCB *CF	6618714-11 1364	MTH 16-Sep-2007		O/C	0		
245092 RIGHT	FUEL NZ014 PCB *CF	6618714-11 1362	MTH 16-Sep-2007		O/C	0		
245094	HYD NZ016 PCB *CF	6618723-5 0340	MTH 16-Sep-2007		O/C	0		
245095	POS TAIL NZ017 PCB *CF	6618721-1 0734	MTH 16-Sep-2007		O/C	0		
245096 LEFT	ANTI ICE NZ019 PCB *CF	6618718-1 1323	MTH 16-Sep-2007		O/C	0		
245096 RIGHT	ANTI-ICE NZ018 PCB *CF	6618718-1 1321	MTH 16-Sep-2007		O/C	0		
245098	RUDDER BIAS NZ029 PCB *CF	6618812-1 0731	MTH 16-Sep-2007		O/C	0		
245099	PCB-APU CURRENT LIMITER	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
245103	APU NZ025 PCB *CF	6618808-26 0434	MTH 16-Sep-2007		O/C	0		
245104	APU NZ026 PCB *CF	6618809-1 0694	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245105	TAIL DEICE CONT NZ031 PCB *CF	6618730-1 0332	MTH 16-Sep-2007		O/C	0		
245106	TAIL DEICE MON NZ033 PCB *CF	6618731-1 0336	MTH 16-Sep-2007		O/C	0		
245107	MISCELLANEOUS NZ035 PCB *CF	6618732-1 0339	MTH 16-Sep-2007		O/C	0		
25-60-00-9601 NO. 10	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 10	P01074-101 220602000007	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 11	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 11	P01074-101 22060981312	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 1	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 1	P01074-101 22060981191	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 2	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 2	P01074-101 22060981425	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 3	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 3	P01074-101 22060980453	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 4	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 4	P01074-101 22062000722	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 5	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 5	P01074-101 22060981176	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 6	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 6	P01074-101 22062000729	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 7	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 7	P01074-101 22060980190	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-00-9601 NO. 8	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 8	P01074-101 22062000275	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
25-60-00-9601 NO. 9	P01074-103, P0723E105PA, GA12 LIFE VEST (ACCOMPLISH SUPPLIER 60 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 9	P01074-101 22062000552	MTH 23-Aug-2022 HRS 5972 LDG 4375		60	0 0	30-Sep-2026	19 m 27 d
Manufacture Date: 30-Sep-2021								
25-60-10-9600 256003	EMERGENCY LOCATOR TRANSMITTER BATTERY DISCARD	452-0133 391747-012	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		DUE DUE DUE DUE	0 0 0 0	30-Sep-2026	19 m 27 d
Expiration Date: 30-Sep-2026								
250002	AV VISOR PLUS PROCESSOR *CF	90008-0031 43B00010	MTH 16-Sep-2007		O/C	0		
250003	AV VISOR DISPLAY *CF	15004-00300 143431	MTH 16-Sep-2007		O/C	0		
250017 RIGHT HAND FORWARD	RIGHT HAND FORWARD MONITOR	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
250018 RIGHT HAND FORWARD	RIGHT HAND FORWARD ARMREST SWITCH	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
250121 CO-PILOT	CO-PILOT 110 VAC-USB OUTLET	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
250121 PILOT	PILOT 110 VAC-USB OUTLET	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
251005	FIRST AID KIT -- KJVL	FL220-FAKFAA 0819-1342	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		12	0	31-Aug-2025	6 m 28 d
252003	TEMPERATURE PROBE *CF	102DB1AG A71869	MTH 16-Sep-2007		O/C	0		
252320 GALLEY	GALLEY SWITCH PANEL	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
252321	INTERIOR GALLEY SWITCH	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
252525	EXTERNALLY SERVICABLE TOILET MHR	15900-023 0044	MTH 09-Aug-2013 HRS 3069 LDG 2485		O/C	0 0 0		
253003	MICROWAVE	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
256002	EMERGENCY LOCATOR TRANSMITTER C406N KFXE	453-5060 252-00486	MTH 07-Jul-2016 HRS 4537.8 LDG 3683 APUH 1768.9 APUS 3328		O/C	0 0		
256004	ELT ANTENNA *CF	DMQ18-3 180346	MTH 16-Sep-2007		O/C	0		
256011	LIFE RAFT KFXE	RAF1210-103T 2373LBA/2356LBA	MTH 20-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0		
256061	ROSEVIEW MONITOR --	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
256062	CKPT CONTROLLER-ROSEN --	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
256063	FIRST AID KIT	PN SN-UNKNOWN	MTH 16-Sep-2007		H/T H/T	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT 9912036-12	*CF		377-02838 0718463	MTH 16-Sep-2007		O/C	0		
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT 9912036-12	*CF		377-02838 0718462	MTH 16-Sep-2007		O/C	0		
262001 AFT	ENGINE FIRE BOTTLE			30400037-1 84377B1	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0 0		
262001 APU	FIRE BOTTLE 9914513-7			30100033-7 38140A1	MTH 22-Mar-2022 HRS 5854.7 LDG 4295		O/C	0 0 0		
262001 FORWARD	ENGINE FIRE BOTTLE			30400037-1 84380B1	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0 0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER			C352TS F49186190	MTH 27-Sep-2021 HRS 5618 LDG 4148		O/C			
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER			C352TS F49186237	MTH 27-Sep-2021 HRS 5618 LDG 4148		O/C			
263004 262003 : APU	AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB KDLL			13083-5 9399	MTH 31-Jan-2023 HRS 6101.2 LDG 4440		O/C			
Manufacture Date: 01-Jun-2022										
263006 FORWARD/FORW ARD 262003 : FL	FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0		
Manufacture Date: 01-Aug-2021										
263008 FWD REAR 262003 : FR	FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0		
Manufacture Date: 01-May-2021										
263010 AFT/FWD 262003 : AL	AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0		
Manufacture Date: 01-Aug-2021										
263012 AFT REAR 262003 : AR	AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB			13083-5 SN-UNKNOWN	MTH 14-Jan-2022 HRS 5790.4 LDG 4258		O/C	0 0		
Manufacture Date: 01-Aug-2021										
272001	RUDDER BIAS SHUTOFF VALVE *CF			5307-1 1039C	MTH 16-Sep-2007		O/C	0		
272002 LEFT	STICK SHAKER (MC001) UNIT *CF			201 6942	MTH 16-Sep-2007		O/C	0		
272002 RIGHT	STICK SHAKER (MF004) UNIT *CF			201 7267	MTH 16-Sep-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
272003	RUDDER BIAS ACTUATOR *CF	6660613-12 NSN	MTH 16-Sep-2007		O/C	0		
273004	SERVO ACTUATOR KJVL	44430-3739 T700	MTH 11-Dec-2024 HRS 6416.4 LDG 4639		O/C	0 0		
273005 LEFT	ELEVATOR TRIM ACTUATOR	6660161-20 NSN	MTH 15-Oct-2021 HRS 5635.8 LDG 4158		O/C	0 0 0		
273006 RIGHT	ELEVATOR TRIM ACTUATOR	6660161-14 NSN	MTH 15-Oct-2021 HRS 5635.8 LDG 4158		O/C			
273020	AFT ELEVATOR TRIM CABLE ASSEMBLY KFXE	6660003-1 NSN	MTH 16-Jun-2017 HRS 4795.2 LDG 3796 APUH 1859.7 APUS 3456		O/C	0		
273201	ELEV TRIM SWITCH *CF	8-405-04 B62823	MTH 16-Sep-2007		O/C	0		
274000	HORIZONTAL STABILIZER ACTUATOR 9912548-7 ICT	41011680-108 0450	MTH 01-Aug-2009 HRS 840		O/C	104		
274001	HYDRAULIC MANIFOLD ASSEMBLY 9912625-19 *CF	8244-2 0257	MTH 16-Sep-2007		O/C	0		
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE 9912625-13 *CF	4220-1 0267	MTH 16-Sep-2007		O/C	0		
274044	HORIZONTAL STAB VALVE ASSY 9912625-12 *CF	4218-1 0124	MTH 16-Sep-2007		O/C	0		
275001	FLAP CONTROL (UY024) VALVE 9912625-5 *CF	4216-3 0251	MTH 16-Sep-2007		O/C	0		
275003 LEFT	FLAP ACTUATOR 9912007-1	1535000-1 2567	MTH 16-Sep-2007		O/C	0		
275003 RIGHT	FLAP ACTUATOR 9912007-1	1535000-1 2571	MTH 16-Sep-2007		O/C	0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1 *CF	1535500-1 3217	MTH 16-Sep-2007		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1 *CF	1535500-1 3241	MTH 16-Sep-2007		O/C	0		
276002	SPEED BRAKE CONTROL VALVE 9912625-6 *CF	4216-2 0256	MTH 16-Sep-2007		O/C	0		
276003	SPEED BRAKE SAFETY VALVE 9912625-7 *CF	4217-1 0264	MTH 16-Sep-2007		O/C	0		
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2 *CF	840203-105 4746XPR	MTH 16-Sep-2007		O/C	0		
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2 *CF	840203-105 4636XPR	MTH 16-Sep-2007		O/C	0		
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1 *CF	61087 4679	MTH 16-Sep-2007		O/C	0		
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1 *CF	61087 4675	MTH 16-Sep-2007		O/C	0		
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5 *CF	60221-4 1527	MTH 16-Sep-2007		O/C	0		
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5 *CF	60221-4 1669	MTH 16-Sep-2007		O/C	0		
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2 *CF	2950024-101 3833	MTH 16-Sep-2007		O/C	0		

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3831	MTH 16-Sep-2007		O/C	0		
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3829	MTH 16-Sep-2007		O/C	0		
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3828	MTH 16-Sep-2007		O/C	0		
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3824	MTH 16-Sep-2007		O/C	0		
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3823	MTH 16-Sep-2007		O/C	0		
282012 LEFT 282012A : L	FUEL BOOST CARTRIDGE SJC			LR55505-2 C-833	MTH 02-Sep-2014 HRS 3723.8 LDG 3068		O/C			
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1355	MTH 16-Sep-2007		O/C	0		
282012 RIGHT 282012A : R	FUEL BOOST CARTRIDGE *CF			LR55505-2 D1387	MTH 16-Sep-2007		O/C	0		
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1309	MTH 16-Sep-2007		O/C	0		
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1309	MTH 16-Sep-2007		O/C	0		
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1311	MTH 16-Sep-2007		O/C	0		
282014	FUEL CROSSFEED ACTUATOR 9914423-2	*CF		MA20A1029-1 AA109720	MTH 16-Sep-2007		O/C	0		
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE *CF			80002-101 1952	MTH 16-Sep-2007		O/C	0		
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE *CF			80002-101 1991	MTH 16-Sep-2007		O/C	0		
282106	FUEL CROSSFEED VALVE 9914423-4	*CF		125838AW AA108872	MTH 16-Sep-2007		O/C	0		
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE *CF			4151 1255	MTH 16-Sep-2007		O/C	0		
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE *CF			4151 1238	MTH 16-Sep-2007		O/C	0		
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 AA91219	MTH 16-Sep-2007		O/C	0		
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 AA108321	MTH 16-Sep-2007		O/C	0		
282200 LEFT	LOW LEVEL VALVE ASSY *CF			726400-1 1233	MTH 16-Sep-2007		O/C	0		
282200 RIGHT	LOW LEVEL VALVE ASSY *CF			726400-1 1179	MTH 16-Sep-2007		O/C	0		
282201	VALVE-REFUEL/DEFUEL *CF			9036-351-2 1383	MTH 16-Sep-2007		O/C	0		
282202 LEFT	FUEL VALVE ASSY *CF			750800-2 1336	MTH 16-Sep-2007		O/C	0		
282202 RIGHT	FUEL VALVE ASSY *CF			750800-2 1321	MTH 16-Sep-2007		O/C	0		
284012 LEFT	LOW FUEL LEVEL SENSOR 9914427-2	*CF		GIF5400-43 2579	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5728**
 Unit: **5728** Reg No: **N608BT**
 Airworthiness: **16-Sep-2007**
 Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284012 RIGHT	LOW FUEL LEVEL SENSOR KFXE			L16H-15 1356	MTH 21-Nov-2019 HRS 5334.6 LDG 4025		O/C	0 0		
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 MN08765	MTH 16-Sep-2007		O/C	0		
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 MN08762	MTH 16-Sep-2007		O/C	0		
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 MN08740	MTH 16-Sep-2007		O/C	0		
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 MN08709	MTH 16-Sep-2007		O/C	0		
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN08884	MTH 16-Sep-2007		O/C	0		
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN08706	MTH 16-Sep-2007		O/C	0		
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN09347	MTH 16-Sep-2007		O/C	0		
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN09184	MTH 16-Sep-2007		O/C	0		
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4	ICT		10634T05Y00 MN04899	MTH 24-Sep-2007 HRS 11		O/C	0 0		
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 MN06132	MTH 16-Sep-2007		O/C	0		
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN09446	MTH 16-Sep-2007		O/C	0		
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN08861	MTH 16-Sep-2007		O/C	0		
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6	KFXE		10634T06Y00 1426	MTH 19-Aug-2019 HRS 5308.7 LDG 4014		O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 MN09049	MTH 16-Sep-2007		O/C	0		
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-7	KFXE		10635B01Y01 B514	MTH 19-Aug-2019 HRS 5308.7 LDG 4014		O/C	0 0		
284268 RIGHT WING	FUEL LOW LEVEL FLOAT SWITCH			L16H-15 1356	MTH 21-Nov-2019 HRS 5334.6 LDG 4025		O/C	0 0 0		
28FO905B	BPTURBO OIL SERIAL KIT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
291001	HYDRAULIC RESERVOIR 9912542-1	*CF		7470 851	MTH 16-Sep-2007		O/C	0		
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5028	MTH 16-Sep-2007		O/C	0		
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5003	MTH 16-Sep-2007		O/C	0		
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	SMF		3520020100-4 07711	MTH 06-Jul-2015 HRS 4257.2 LDG 3544		O/C	0 0		
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 06987	MTH 16-Sep-2007		O/C	0		
291008	SPEED BRAKE THERMAL RELIEF VALVE 9912625-8	*CF		2664 0256	MTH 16-Sep-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
291010	HYD PRESS SWITCH 9912625-3	80637 0757	MTH 16-Sep-2007		O/C	0		
291013	FIREWALL HYD SHUTOFF VALVE	AV24B1325C5	MTH 16-Sep-2007		O/C	0		
LEFT	*CF	AA102197						
291013	FIREWALL HYD SHUTOFF VALVE	AV24B1325C5	MTH 16-Sep-2007		O/C	0		
RIGHT	*CF	AA74952						
301001	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH		MTH 16-Sep-2007		O/C	0		
LEFT WING	*CF	1173T42-4 3554						
301001	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH		MTH 16-Sep-2007		O/C	0		
RIGHT WING	*CF	1173T42-4 3410						
301002	ISOLATION VALVE	2602-36	MTH 16-Sep-2007		O/C	0		
	9912403-2	1681						
301008	DEICE TAIL VALVE	3D2353-06	MTH 16-Sep-2007		O/C	0		
LEFT	*CF	N071536						
301008	DEICE TAIL VALVE	3D2353-06	MTH 16-Sep-2007		O/C	0		
RIGHT	*CF	N071527						
301020	WINDSHIELD RAIN REMOVAL MN001 FAN		MTH 16-Sep-2007		O/C	0		
	*CF	011598-501 C07160077						
301137	INLET ANTI-ICE PRESSURE REG SHUTOFF VD001 VALVE		MTH 31-Jan-2023		O/C	9		
LEFT WING	9912495-1	1962-00-7 2234	HRS 6101.2 LDG 4440					
301137	INLET ANTI-ICE PRESSURE REG SHUTOFF VE002 VALVE		MTH 16-Sep-2007		O/C	0		
RIGHT WING	9912495-1	1962-00-7 3641						
301201	TAIL DEICE PRESSURE SV005 SWITCH	1106P55-1	MTH 16-Sep-2007		O/C	0		
LEFT	*CF	4816A						
301201	TAIL DEICE PRESSURE SV004 SWITCH	1106P55-1	MTH 16-Sep-2007		O/C	0		
RIGHT	*CF	4803A						
301202	HORIZ STAB DEICE BOOT	P29S4D5280-11	MTH 27-Feb-2019		O/C	0		
LEFT	KFXE	NEQ7570	HRS 5203.1 LDG 3967			0		
301202	HORIZ STAB DEICE BOOT	P29S4D5280-12	MTH 04-Mar-2022		O/C	0		
RIGHT		NFZ7480	HRS 5831.1 LDG 4286			0 0 0		
302101	PRESSURE REG VALVE	1946-00-19	MTH 20-Feb-2018		O/C			
LEFT	9912495-4	3709	HRS 4982.6 LDG 3875					
302101	PRESSURE REG VALVE	1946-00-19	MTH 20-Feb-2018		O/C			
RIGHT	9912495-4	2159	HRS 4982.6 LDG 3875					
302104	NACELLE INLET SWITCH	1173T0759	MTH 16-Sep-2007		O/C	0		
LEFT	*CF	4042						
302104	NACELLE INLET SWITCH	1173T0759	MTH 16-Sep-2007		O/C	0		
RIGHT	*CF	4192						
303001	PITOT TUBE	PH1100-1-VCW	MTH 16-Sep-2007		O/C	0		
LEFT	*CF	727704						
303001	PITOT TUBE	PH1100-1-VCW	MTH 16-Sep-2007		O/C	0		
RIGHT	*CF	727702						
303001	PITOT TUBE	PH1100-1-RCDW	MTH 16-Sep-2007		O/C	0		
STANDBY	*CF	744004						
304100	WINDSHIELD CONTROLLER	856-1-3	MTH 16-Sep-2007		O/C	0		
LEFT	9914411-2	206500312						

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-2	856-1-3 206490532	MTH 16-Sep-2007		O/C	0		
302005 E1	ANTI-ICING VALVE 31J2879-04	540-0406-4 4144	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0 0		
302005 E2	ANTI-ICING VALVE 31J2879-05	540-0406-5 4129	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 4982.6 3825		
31-30-04-9600 313007A	DK120 OR DK120/90 FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD							
		810-2008/K NSN	MTH 19-Aug-2019 HRS 5308.7 LDG 4014		DUE DUE DUE	0 0 0	31-Aug-2025	6 m 28 d
Expiration Date: 31-Aug-2025								
312001 LEFT HAND	DIGITAL CLOCK	M877A5V 24857	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C	36 651		
312002I	INCLINOMETER	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
313001	FDR ACCELEROMETER *CF	3001-01-111-3 030711004	MTH 16-Sep-2007		O/C	0		
313003 LEFT	ENGINE ACCELEROMETER *CF	6222SM15 20893	MTH 16-Sep-2007		O/C	0		
313003 RIGHT	ENGINE ACCELEROMETER *CF	6222SM15 20546	MTH 16-Sep-2007		O/C	0		
313007	FDR UNDERWATER LOCATOR BEACON	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
313008	FDR IMPACT SWITCH *CF	6895-D-1-X-5-5 6646	MTH 16-Sep-2007		O/C	0		
313010	FLIGHT DATA AQUISITION (FDAU) UNIT	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
313011 INBOARD	FLIGHT DATA RECORDER (PCB) PRINTED CIRCUIT BOARD	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
313011 OUTBOARD	FLIGHT DATA RECORDER (PCB) PRINTED CIRCUIT BOARD	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
315001	FDR FAIL ANNUNCIATOR 9912504-16	1304-1-16 207080009	MTH 16-Sep-2007		O/C	0		
315101 LEFT	WARNING GEN/MIXER UNIT *CF	1287-1-2 207170217	MTH 16-Sep-2007		O/C	0		
315101 RIGHT	WARNING GEN/MIXER UNIT *CF	1287-1-2 207170218	MTH 16-Sep-2007		O/C	0		
316001	TILT INDICATOR	3001J72 23949	MTH 16-Sep-2007		O/C	0		
316016	ROSEVIEW LX PROCESSOR --	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
32-10-00-9601 LEFT MAIN LANDING GEAR 321003 : L	LEFT MAIN LANDING GEAR TRUNNION SUBASSEMBLY DISCARD *CF	6641630-27 NSN	MTH 16-Sep-2007 LDG 0			0 0	33300	28658
32-10-00-9601 RIGHT MAIN LANDING GEAR 321003 : R	RIGHT MAIN LANDING GEAR TRUNNION SUBASSEMBLY DISCARD *CF	6641630-28 NSN	MTH 16-Sep-2007 LDG 0			0 0	33300	28658



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-10-00-9602 LEFT MAIN LANDING GEAR 321004 : L	LEFT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD			6641530-4 30170108	MTH 09-Sep-2021 HRS 5613.7 LDG 4146			0 0 0	37446	32804
32-10-00-9602 RIGHT MAIN LANDING GEAR 321004 : R	RIGHT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD			6641530-3 29659105	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		33300	0 0 0	37446	32804
32-10-00-9603 LEFT MAIN LANDING GEAR 321011 : L	LEFT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD	*CF		6641533-1 NSN	MTH 16-Sep-2007 LDG 0		33300	0 0	33300	28658
32-10-00-9603 RIGHT MAIN LANDING GEAR 321011 : R	RIGHT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD			6641533-2 30010421T	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		33300	0 0 0	37446	32804
32-10-00-9604.1 LEFT MAIN LANDING GEAR 323011 : L	LEFT UPPER CAP MAIN LANDING GEAR OLEO ASSEMBLY DISCARD	*CF		6641616-4 NSN	MTH 16-Sep-2007 LDG 0		14900	0 0	14900	10258
32-10-00-9604.1 RIGHT MAIN LANDING GEAR 323011 : R	RIGHT UPPER CAP MAIN LANDING GEAR OLEO ASSEMBLY DISCARD	*CF		6641616-4 NSN	MTH 16-Sep-2007 LDG 0		14900	0 0	14900	10258
32-10-00-9604 LEFT MAIN LANDING GEAR 323010 : L	LEFT (EXCEPT UPPER CAP) MAIN LANDING GEAR OLEO ASSEMBLY DISCARD			6641615-7 30236582	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		38000	0 0 0	42366	37724
32-10-00-9604 RIGHT MAIN LANDING GEAR 323010 : R	RIGHT (EXCEPT UPPER CAP) MAIN LANDING GEAR OLEO ASSEMBLY DISCARD			6641615-7 30389208	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		38000	0 0 0	42366	37724
32-10-00-9605 LEFT MAIN LANDING GEAR 323001 : L	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			1550000-4 1283	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		70200	4146	70200	65558
32-10-00-9605 RIGHT MAIN LANDING GEAR 323002 : R	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD			9912537-3 1255B	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		70200	4146	70200	65558
32-20-00-9600 NOSE 322001	NOSE LANDING GEAR ASSEMBLY DISCARD	*CF		6642625-6-1 1	MTH 16-Sep-2007 LDG 0		33300	0	33300	28658
32-20-00-9601 NOSE LANDING GEAR 323003	NOSE LANDING GEAR ACTUATOR DISCARD	SMF		1549300-9 0466	MTH 17-Jun-2015 HRS 4225.1 LDG 3517		33300	2037	34780	30138
32-30-09-9600 323006	EMERGENCY GEAR EXTENSION / BRAKE PNEUMATIC STORAGE BOTTLE ASSEMBLY DISCARD	KJVL		40005347-3 4385	MTH 11-Dec-2024 HRS 6416.4 LDG 4639		288		28-Feb-2029	48 m 25 d
321020 LEFT MAIN LANDING GEAR	BREATHER VENT	KDLL		QSB-5-SS N/A	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		12 600	0 0	30-Jun-2025 6923.5	4 m 27 d 501.9
321020 RIGHT MAIN LANDING GEAR	BREATHER VENT	KDLL		QSB-5-SS N/A	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		12 600	0 0	30-Jun-2025 6923.5	4 m 27 d 501.9
322002 NOSE GEAR	SHIMMY DAMPER			5543001-12 11-12X	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
322007 NOSE GEAR	TRUNNION	*CF		6642611-9 NSN	MTH 16-Sep-2007		O/C	0		
323004 LEFT	UPLOCK ACTUATOR	*CF		5527504-3 3876	MTH 16-Sep-2007		O/C	0		
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-3 3893	MTH 16-Sep-2007		O/C	0		
323004 RIGHT	UPLOCK ACTUATOR	*CF		5527504-3 3877	MTH 16-Sep-2007		O/C	0		
323005	PRESSURE EMER GEAR GAUGE	*CF		19940929-1 020631	MTH 16-Sep-2007		O/C	0		
323007	LANDING GEAR CONTROL (VY047) VALVE	*CF		9912625-9 4219-1 0254	MTH 16-Sep-2007		O/C	0		
323008	DUMP VALVE	*CF		9912625-11 9615 0271	MTH 16-Sep-2007		O/C	0		
323009	LANDING GEAR CONTROL			049801-001 9912550-1 0139	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C	0 0 0		
323014 323010A	LOADING VALVE	*CF		4215-2 9912625-18 0131	MTH 16-Sep-2007		O/C	0		
324001 LEFT	MAIN WHEEL ASSEMBLY			3-1571-6 9912487-11 2125	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY			3-1571-6 9912487-11 2128	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
324002 NOSE	WHEEL ASSEMBLY			3-1418OPT4 9407	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C	0 0 0		
324003 LEFT	MAIN BRAKE ASSEMBLY	SMF		2-1601-1 9912487-7 1663	MTH 17-Jun-2015 HRS 4225.1 LDG 3517		O/C	0 0 0		
324004 RIGHT	MAIN BRAKE ASSEMBLY	KFXE		2-1601-1 9912487-7 1445	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		O/C	0 0		
324005 LEFT	MAIN TIRE	KDLL		M13702 9912488-3 2248T194	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		O/C	0 0 0		
324005 RIGHT	MAIN TIRE	KDLL		M13702 9912488-3 2243T204	MTH 18-Jun-2024 HRS 6323.5 LDG 4576		O/C	0 0 0		
324006	NOSE TIRE			031-613-8 9914070-1 2038T00344	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C	0 0 0		
324009	POWER BRAKE VALVE	*CF		32-105-3 9912627-6 346	MTH 16-Sep-2007		O/C	0		
324010 LEFT	EXTEND/RETRACT VALVE	*CF		98120 3811	MTH 16-Sep-2007		O/C	0		
324010 NOSE	EXTEND/RETRACT VALVE	*CF		98120 3998	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324010 RIGHT	EXTEND/RETRACT VALVE *CF			98120 3562	MTH 16-Sep-2007		O/C	0		
324014	EMERGENCY AIR BRAKE CONTROL VALVE *CF			65830-4 0991	MTH 16-Sep-2007		O/C	0		
324015 LEFT	BRAKE SHUTTLE VALVE *CF			211-114 1487	MTH 16-Sep-2007		O/C	0		
324015 RIGHT	BRAKE SHUTTLE VALVE *CF			211-114 1567	MTH 16-Sep-2007		O/C	0		
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3	SMF		640931 7250	MTH 19-Jun-2015 HRS 4227.7 LDG 3520		O/C	0 0 0		
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4	*CF		39-837 938	MTH 16-Sep-2007		O/C	0		
324022	ANTISKID DIGITAL CONTROL 9912489-9	*CF		42-985-2 735	MTH 16-Sep-2007		O/C	0		
324023	POWER BRAKE ACCUMULATOR 9912644-1	*CF		7551-1 0077	MTH 16-Sep-2007		O/C	0		
324024 LEFT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 16-Sep-2007		O/C	0		
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 NSN	MTH 16-Sep-2007		O/C	0		
324025	PRESSURE (SN011) SWITCH *CF			GPP1250-52 0718918	MTH 16-Sep-2007		O/C	0		
324026	POWER PACK MOTOR MHR			MP50B1 4921	MTH 28-May-2015 HRS 4193.3 LDG 3484		O/C	0 0		
324027	ANTISKID FAULT DISPLAY 9912305-9	*CF		42-92750 2062A	MTH 16-Sep-2007		O/C	0		
324101	PARKING BRAKE VALVE 9912388-11	*CF		98433-2 0182	MTH 16-Sep-2007		O/C	0		
324153 3242153	PRESS ANTISKID BRK SWITCH *CF			GPP1250-73 0637604	MTH 16-Sep-2007		O/C	0		
324200 324201	ANTISKID PRESSURE GAUGE *CF			19940929-1 023407	MTH 16-Sep-2007		O/C	0		
324206	ANTISKID HYD RELIEF VALVE *CF			1785-2 875	MTH 16-Sep-2007		O/C	0		
324217	ANTI-SKID BRAKE HYDRAULIC PACK ASSEMBLY PN SN-UNKNOWN				MTH 16-Sep-2007		O/C	0		
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 16-Sep-2007		O/C	0		
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 16-Sep-2007		O/C	0		
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF			65-430087 NSN	MTH 16-Sep-2007		O/C	0		
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY *CF			273-1 207190031	MTH 16-Sep-2007		O/C	0		
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF			273-1 207190025	MTH 16-Sep-2007		O/C	0		
331001 RIGHT	5 VDC UN006 DIMMER POWER SUPPLY *CF			273-1 207190033	MTH 16-Sep-2007		O/C	0		
331011	EL PANEL INVERTER *CF			EM2044-1 5597A	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
331099	EL PANEL	KFXE	9912525-26	MTH	18-Aug-2017	O/C		
			0378	HRS	4839.9			
				LDG	3814			
332002	GLARESHIELD INVERTER	6900173	MTH	16-Sep-2007	O/C	0		
	*CF	4242						
334001	PULSE LITE CONTROL	2401C	MTH	16-Sep-2007	O/C	0		
	*CF	TR01033						
334002	EMPENNAGE LIGHT ASSY	01-0790044-37	MTH	16-Sep-2007	O/C	0		
	*CF	NSN						
334003	TAIL LIGHT ASSY	SMF	01-0770966-00	MTH	06-Apr-2009	O/C	0	
			03512A	HRS	701	0		
334006	STROBE POWER SUPPLY	01-0790101-05	MTH	16-Sep-2007	O/C	0		
LEFT	*CF	01497						
334006	STROBE POWER SUPPLY	01-0790101-05	MTH	16-Sep-2007	O/C	0		
RIGHT	*CF	SN-UNKNOWN						
335001	EMERGENCY LIGHTING UC020 BATTERY PACK		MTH	27-Jul-2023	O/C	0		
AFT	KJVL	9913-1	HRS	6170.3		0		
		1373	LDG	4480				
335001	EMERGENCY LIGHTING UC019 BATTERY PACK		MTH	27-Jul-2023	O/C	0		
FORWARD	KJVL	9913-1	HRS	6170.3		0		
		1165	LDG	4480				
335007	AFT OVERWING EMERGENCY LIGHT ASSEMBLY		MTH	16-Sep-2007	O/C	0		
AFT		PN						
		SN-UNKNOWN						
335007	RIGHT EXIT EMERGENCY FORWARD LED LIGHT ASSEMBLY		MTH	16-Sep-2007	O/C	0		
FORWARD RIGHT		PN						
		SN-UNKNOWN						
335007	MID OVERWING EMERGENCY LIGHT ASSEMBLY		MTH	16-Sep-2007	O/C	0		
MID		PN						
		SN-UNKNOWN						
335007	RIGHT EXIT EMERGENCY LED LIGHT ASSEMBLY		MTH	16-Sep-2007	O/C	0		
R/H		PN						
		SN-UNKNOWN						
335007	RIGHT OVERWING ESCAPE LED LIGHT ASSEMBLY		MTH	16-Sep-2007	O/C	0		
RIGHTHAND		PN						
		SN-UNKNOWN						
336015	AVANCE L5 TRANSRECEIVER (GOGO) --		MTH	03-May-2024	O/C	0		
		P34110-002	HRS	6284.6		0		
		341100024658E	LDG	4550		0		
340037	MAGNETOMETER	*CF	501-1826-03	MTH	16-Sep-2007	O/C	0	
	MAG-3000A		2077					
341009	SAFE FLIGHT AOA UF004 SENSOR	C-12717-1	MTH	16-Sep-2007	O/C	0		
	*CF	1923						
341011	SAFE FLIGHT AOA UC009 COMPUTER	C13006-3	MTH	16-Sep-2007	O/C	0		
	*CF	1284						
341014	SAFE FLIGHT AOA FI003 INDEXER	C12763-1	MTH	16-Sep-2007	O/C	0		
	*CF	1232						
341016	ADU	KFXE	501-1890-02	MTH	18-Aug-2017	O/C		
SECONDARY	UF-031		2163A	HRS	4839.9			
				LDG	3814			
				APUH	1875.1			
				APUS	3476			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY GH-3000	KFXE	18	501-1741-2103 1323B	MTH 18-Aug-2017 HRS 4839.9 LDG 3814 APUH 1875.1 APUS 3476		O/C			
341101	DIFFERENTIAL PRESSURE SWITCH SMF			D45C-24 1424	MTH 26-Sep-2011 HRS 1968.8 LDG 1635		O/C	0 0 0		
341107 NO. 1	(PILOT) AIR DATA COMPUTER *CF			7030700-71703 07051444	MTH 16-Sep-2007		O/C	0		
341107 NO. 2	(COPILOT) AIR DATA COMPUTER *CF			7030700-71703 07051450	MTH 16-Sep-2007		O/C	0		
342005 1	FLIGHT GUIDANCE COMPUTER			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
342005 2	FLIGHT GUIDANCE COMPUTER			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
342023	RADAR CONTROLLER WC-880	*CF		7008471-407 01076015	MTH 16-Sep-2007		O/C	0		
342050 LEFT	FLUX DETECTOR FX-220	*CF		2594484 0702H745	MTH 16-Sep-2007		O/C	0		
342050 RIGHT	FLUX DETECTOR FX-220	*CF		2594484 0707H738	MTH 16-Sep-2007		O/C	0		
342053	AERONETICS HSI-15 STANDBY HORIZONTAL SITUATION INDICATOR HSI-315B	*CF		520-3151-003 24890	MTH 16-Sep-2007		O/C	0		
342054	ELEC HORIZ SIT INDICATOR			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
342064	NO. 1 STANDBY BATTERY PACK SECURAPLANE	KJVL		100-2410-04 1193494	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		O/C			
342065 NO. 2	NO. 2 STANDBY BATTERY PACK	9		PS-855B 1477	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
342069	HONEYWELL PRIMUS 1000 EFIS MC800 MULTIFUNCTION DISPLAY CONTROLLER	KFXE	C	7007062-987 00042266	MTH 27-Feb-2019 HRS 5203.1 LDG 3967		O/C			
342070	GARMIN MULTI FUNCTION DISPLAY	KFXE	1	011-01271-10 38350354	MTH 31-Jul-2018 HRS 5096.7 LDG 3925		O/C	8		
342074	DATA TRANSFER AFIS UNIT *CF			15655-0101 4550	MTH 16-Sep-2007		O/C	0		
342082 LEFT	LITEF LCR-93 AHRS TRAY *CF			140691 4334	MTH 16-Sep-2007		O/C	0		
342082 RIGHT	LITEF LCR-93 AHRS TRAY *CF			140691 4340	MTH 16-Sep-2007		O/C	0		
342083 LEFT	AHRS COMPUTER			142185-1100 2054	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
342083 RIGHT	AHRS COMPUTER	KFXE	8	142185-1100 1137	MTH 26-Mar-2021 HRS 5558.7 LDG 4121		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
342104 LEFT	MSU CALIBRATION PROM UNIT *CF			124282 9819	MTH 16-Sep-2007		O/C	0		
342104 RIGHT	MSU CALIBRATION PROM UNIT *CF			124282 9938	MTH 16-Sep-2007		O/C	0		
342200	DATA CONFIGURATION MODULE			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
342500	HONEYWELL PRIMUS 1000 EFIS RI553 REMOTE INSTRUMENT CONTROLLER RI-553	*CF		7016954-971 07052800	MTH 16-Sep-2007		O/C	0		
342504 COPILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER *CF			7016986-759 07056880	MTH 16-Sep-2007		O/C	0		
342504 PILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER *CF			7016986-759 07056868	MTH 16-Sep-2007		O/C	0		
342505 NO.1	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-615	*CF		7017000-96814 07057970	MTH 16-Sep-2007		O/C	0		
342505 NO.2	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-615	*CF		7017000-97814 07088139	MTH 16-Sep-2007		O/C	0		
342506 LEFT	AP/FD MODE SELECTOR MS-560	KFXE		7018341-803 04022404	MTH 13-May-2021 HRS 5590.1 LDG 4135		O/C			
342506 RIGHT	AP/FD MODE SELECTOR MS-560	MHR		7018341-803 98010979	MTH 01-Nov-2011 HRS 2031.9 LDG 1677		O/C			
342507 LEFT	FMS DISPLAY CONTROLLER CD-810			7007549-901 07047436	MTH 16-Sep-2007		O/C	0		
342507 RIGHT	FMS DISPLAY CONTROLLER CD-810	*CF	P	7007549-901 07047436	MTH 16-Sep-2007		O/C			
342509 COPILOT 342501 : R	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080	MHR		7037625-15001 07080294	MTH 10-Apr-2015 HRS 4114.9 LDG 3417		O/C			
342509 PILOT 342501 : L	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080	MCO		7037625-15001 07050234	MTH 12-Mar-2010 HRS 1092 LDG 934		O/C			
342510 CENTER 342501 : CNTR	ELECTRONIC DISPLAY UNIT DU-1080			7037625-15001 07050236	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C			
342613 342501	HONEYWELL PRIMUS 1000 EFIS RI552 REVERSION CONTROLLER RI-552			7016954-981 06042413	MTH 09-Nov-2021 HRS 5701.8 LDG 4206		O/C			
343001 NAVIGATION 343001A	ANTENNA COUPLER *CF			CI-120-5 184145	MTH 16-Sep-2007		O/C	0		
343001	GLIDESLOPE ANTENNA COUPLER *CF			CI503 189062	MTH 16-Sep-2007		O/C	0		
343002 343001 : B	MARKER BEACON ANTENNA COUPLER *CF			CI509 188898	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344005	RADAR TRANSCEIVER WU-880		P	7021450-801 98080968	MTH 28-Oct-2021 HRS 5669.1 LDG 4183		O/C			
344022	RADIO ALTIMETER ALT-55B TRANSCEIVER RT-300		FXE	7001840-936 98117248	MTH 25-Feb-2016 HRS 4439.9 LDG 3640		O/C			
344023 AFT	RADIO ALT RECEIVER ANTENNA *CF			S67-2002 54338717	MTH 16-Sep-2007		O/C	0		
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA *CF			S67-2002 54338729	MTH 16-Sep-2007		O/C	0		
344024	EGPWS COMPUTER S2800-702	KFXE	9	965-0976-040-219-219 21157	MTH 15-Oct-2015 HRS 4369.9 LDG 3610 APUH 1704.3 APUS 3238		O/C			
344030C	RECEIVER/ANT/ WEATHER RADAR TRANSCEIVER PN SN-UNKNOWN				MTH 16-Sep-2007		O/C	0		
345004 LEFT NO. 1	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 112629	MTH 16-Sep-2007		O/C	0		
345004 RIGHT NO. 2	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 112631	MTH 16-Sep-2007		O/C	0		
345005 LEFT NO. 1	TOP TRANSPONDER DIVERSITY ANTENNA 85226 *CF			DMNI50-2-2 112632	MTH 16-Sep-2007		O/C	0		
345005 RIGHT NO. 2	TOP TRANSPONDER DIVERSITY ANTENNA 85226 *CF			DMNI50-2-2 112516	MTH 16-Sep-2007		O/C	0		
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226 *CF			DMNI50-2-2 112615	MTH 16-Sep-2007		O/C	0		
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226 SMF			DMNI50-2-2 113793	MTH 04-Sep-2014 HRS 3728.5 LDG 3074		O/C	0 0		
345011 NO. 1	ADF RECEIVER MODULE DF-850 *CF			7510114-901 0704B796	MTH 16-Sep-2007		O/C	0		
345011 NO. 2	ADF RECEIVER MODULE *CF			7510112-901 0705A545	MTH 16-Sep-2007		O/C	0		
345014 NO. 1	ADF ANTENNA AT-860 *CF			7510300-901 0704C481	MTH 16-Sep-2007		O/C	0		
345014 NO. 2	ADF ANTENNA PN SN-UNKNOWN				MTH 16-Sep-2007		O/C	0		
345017	MARKER BEACON ANTENNA *CF			MB10-754 0706	MTH 16-Sep-2007		O/C	0		
345029 NO. 1	NAV CLUSTER MODULE XN-850 *CF			7510164-921 0704B162	MTH 16-Sep-2007		O/C	0		
345029 NO. 2	NAV CLUSTER MODULE XN-850 *CF			7510164-921 0708B334	MTH 16-Sep-2007		O/C	0		
345032 NO. 1	VHF NAV RECEIVER NV-850 *CF			7510134-731 0704B235	MTH 16-Sep-2007		O/C	0		
345032 NO. 2	VHF NAV RECEIVER NV-850 *CF			7510134-731 0708B383	MTH 16-Sep-2007		O/C	0		
345034 NO. 1	ATC TRANSPONDER *CF			7517400-922 0608B727	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345034 NO. 2	ATC TRANSPONDER	SMF		7517400-922 0605B010	MTH 08-May-2009 HRS 741		O/C	0 0		
345036 NO. 1	DME INTERROGATOR DM-850	*CF		7510184-902 0704C122	MTH 16-Sep-2007		O/C	0		
345036 NO. 2	DME INTERROGATOR DM-850	*CF		7510184-902 0708C895	MTH 16-Sep-2007		O/C	0		
345038 NO. 1	INTEGRATED NAV UNIT RNZ-850	KFXE	AS	7510100-731 97032160	MTH 27-May-2021 HRS 5604.3 LDG 4141		O/C			
345038 NO. 2	INTEGRATED NAV UNIT RNZ-850B	*CF		7510100-733 0708B323	MTH 16-Sep-2007		O/C	0		
345065 NO. 3	EXTERNAL COMPENSATION UNIT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
345069	XM WEATHER RECEIVER UNIT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
345070F 1	EXT COMPENSATION FSU UNIT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
345077	DATA TRANSFER UNIT	MHR	2	1408-00-1 1718	MTH 23-Mar-2012 HRS 2261.8 LDG 1855		O/C	0 0		
345078 NO. 2	GPS W/SBAS RECEIVER			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
345079 NO. 1	GPS FLT MGMT COMPUTER UNS-1ESP	SMF		2019-41-201 749	MTH 19-Mar-2008 HRS 287		O/C	0 0		
345079 NO. 2	GPS FLT MGMT COMPUTER UNS-1ESP	KFXE	6	2019-41-201 666	MTH 23-Aug-2016 HRS 4576.3 LDG 3700 APUH 1784.3 APUS 3357		O/C			
345088 NO. 1	RADIO MANAGEMENT UNIT KSFB		S	7013270-973 07035698	MTH 20-Feb-2018 HRS 4982.6 LDG 3875		O/C			
345088 NO. 2	RADIO MANAGEMENT UNIT KSFB		S	7013270-973 07045772	MTH 20-Feb-2018 HRS 4982.6 LDG 3875		O/C			
345093 NO.1	GPS ANTENNA ANTENNA			10708 12744	MTH 09-Sep-2021 HRS 5613.7 LDG 4146		O/C	0 0 0		
345093 NO.2	GPS ANTENNA ANTENNA	*CF		10706 11973	MTH 16-Sep-2007		O/C	0		
345093 NO. 3	GPS ANTENNA	*CF		011-01032-00 44000418	MTH 16-Sep-2007		O/C	0		
345201 LEFT	NAV ANTENNA CI120-200G/S-L	KJVL		CI120-1-L 724190	MTH 26-Oct-2023 HRS 6186.8 LDG 4490		O/C	0 0		
345201 RIGHT	NAV ANTENNA CI120-200G/S-L	KJVL		CI120-1-L 724191	MTH 26-Oct-2023 HRS 6186.8 LDG 4490		O/C	0 0		
346001	TCAS PROCESSOR RT-951 (S3100-196)	*CF		7517900-55003 20009040	MTH 16-Sep-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
346002 BOTTOM	TCAS ANTENNA AT-910	KCOU 7514081-910 ANE65194	MTH 03-May-2024 HRS 6284.6 LDG 4550		O/C	0 0 0		
346002 TOP	TCAS ANTENNA AT-910	*CF 7514081-910 ANE26899	MTH 16-Sep-2007		O/C	0		
35-10-00-9600 COPILOT 351004 : CP	MC10-16-150, MC10-16-100, OR MLD20-505 KFXE	COPILOT CREW MASK (ACCOMPLISH SUPPLIER TESTING AND FAULT ISOLATION TASK) RESTORATION MC10-16-150 120253	MTH 12-Apr-2019 HRS 5235.1 LDG 3983		72	0	30-Apr-2025	2 m 27 d
35-10-00-9600 PILOT 351004 : P	MC10-16-150, MC10-16-100, OR MLD20-505 KFXE	PILOT CREW MASK (ACCOMPLISH SUPPLIER TESTING AND FAULT ISOLATION TASK) RESTORATION MC10-16-150 SE78096	MTH 12-Apr-2019 HRS 5235.1 LDG 3983		72	0	30-Apr-2025	2 m 27 d
35-90-00-9600 351006	OXYGEN BOTTLE ASSEMBLY (DISCARD)	804882-14 ALT281-52599	MTH 18-Feb-2022 HRS 5819.3 LDG 4279		180		31-Dec-2036	142 m 28 d
Manufacture Date: 01-Dec-2021								
350002 LH	OXYGEN BOX	MXP326-3 15856	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C	0 0 0		
350002 RH	OXYGEN BOX	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
351001	OXYGEN PRESSURE (EI002) GAGE MD-97 *CF	C668512-0101 K0610039	MTH 16-Sep-2007		O/C	0		
351002	OXYGEN PRESSURE GAUGE	PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
351007	OXYGEN REGULATOR KFXE	804881-01 C16080366	MTH 28-Mar-2017 HRS 4728.3 LDG 3770 APUH 1840.5 APUS 3430		O/C	0 0		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19 *CF	P21006 2530	MTH 16-Sep-2007		O/C	0		
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH *CF	P24032 1273	MTH 16-Sep-2007		O/C	0		
361010	DOOR SOLENOID VALVE KJVL	6711335-1 N/A	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		O/C	0 0		
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4 *CF	1E50-2 5BC86	MTH 16-Sep-2007		O/C	0		
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4 *CF	1E50-2 5BC89	MTH 16-Sep-2007		O/C	0		
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2 *CF	1173T181-2 5178	MTH 16-Sep-2007		O/C	0		
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2 *CF	1173T181-2 5193	MTH 16-Sep-2007		O/C	0		
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	1E51-1 5BW359	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2			MTH 12-Aug-2022 1E51-1 5BW357	HRS 5959.7 LDG 4366		O/C	0 0 0		
361103 LEFT	HEAT B/A EXCHANGER 9912486-2			8230-2 S4883T4073	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C	0 0 0		
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2			8230-2 S4883T4072	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C	0 0 0		
361104 LEFT	PRECOOLER VD003 VALVE *CF			1406-7 0618	MTH 16-Sep-2007		O/C	0		
361104 RIGHT	PRECOOLER VD003 VALVE *CF			1406-8 0588	MTH 16-Sep-2007		O/C	0		
361208 APU	APU-CHECK VALVE 9914171-1	*CF		8C210 6424	MTH 16-Sep-2007		O/C	0		
361208	RUDDER BIAS CHECK VALVE 9914171-1	*CF		8C210 6359	MTH 16-Sep-2007		O/C	0		
361500 NO. 1	B/A CHECK VALVE 9914171-1	*CF		8C210 6416	MTH 16-Sep-2007		O/C	0		
361500 NO. 2	B/A CHECK VALVE 9914171-1	*CF		8C210 6356	MTH 16-Sep-2007		O/C	0		
361534	SERVICE AIR REGULATOR 9912510-1	*CF		1H75-18 5BC22	MTH 16-Sep-2007		O/C	0		
380003	VANITY SWITCH			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
380004	ABC SWITCH			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
383005	FLUSH SWITCH			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
49APU1 490000	APU 9912484-1	*CF		3800722-1 P-661	MTH 16-Sep-2007		E/C			
49-00-00-9600 492003	COMPRESSOR ROTOR *CF			3822523-003 060350105452	APUS 16-Sep-2007 0			0 12000		7888
49-00-00-9601 492004	TURBINE ROTOR			70722360-1 21-156101-07286	APUH 18-Feb-2022 APUS 2259.4 3964			0 0 4000		3852
49-30-00-9600	FUEL FILTER ELEMENT KDLL			3882440-1 NA	APUH 10-Apr-2024 APUS 2489.5 4054		24 900	0 0	30-Apr-2026 3389.5	14 m 27 d 838.6
490001	APU ELECTRONIC CONTROL *CF			2119552-3 66K0116	16-Sep-2007		O/C	0		
490003	BLEED AIR SHUTOFF VALVE SMF			1413-7 0603	APUH 06-Apr-2009 230		O/C	0 0		
490004	DC AMMETER S3439-3	*CF		MD144-3 C0711642	16-Sep-2007		O/C	0		
490005	OVERHEAT DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207978	16-Sep-2007		O/C	0		
490006	HOURLY METER *CF			C664503-0104 NSN	16-Sep-2007		O/C	0		
491011	GENERATOR MATCHED SEAL SET			PN SN-UNKNOWN	16-Sep-2007		O/C	0		
492031	COMPRESSOR MATCHED SEAL SET			PN SN-UNKNOWN	16-Sep-2007		O/C	0		
493000	FUEL CONTROL ASSEMBLY *CF			3883900-1 0601041	16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
493001	TEE-FLOW DIVIDER VALVE *CF			3883921-2 NSN	16-Sep-2007		O/C	0		
494000	ELECTRICAL IGNITER LEAD *CF			3888302-20 NSN	16-Sep-2007		O/C	0		
494001	IGNITER PLUG			304634-2 NSN	APUH 18-Feb-2022 APUS 2259.4 3964		O/C	0 0 0		
494002	IGNITION UNIT *CF			3888000-7 060218072848	16-Sep-2007		O/C	0		
499000	LOW OIL PRESSURE SWITCH			3876351-1 21-150241-03106	APUH 15-Oct-2021 APUS 2171.3 3849		O/C	0 0 0		
499001	LUBE PUMP ASSEMBLY *CF			3881825-1 P1064	16-Sep-2007		O/C	0		
499002	OIL LEVEL SWITCH *CF			3876318-3 060147000369	16-Sep-2007		O/C	0		
521003	ACOUSTIC LOWER FWD SEAL *CF			9522-15 NSN	MTH 16-Sep-2007		O/C	0		
521004	ACOUSTIC UPPER SEAL *CF			9522-11 NSN	MTH 16-Sep-2007		O/C	0		
521005	ACOUSTIC LOWER AFT SEAL *CF			9522-13 NSN	MTH 16-Sep-2007		O/C	0		
527000	EMERGENCY EXIT SWITCH *CF			8-405-04 B62589	MTH 16-Sep-2007		O/C	0		
527007	CABIN ENTRANCE DOOR WARNING (SC046) SWITCH KJVL			8-405-04 B87470	MTH 21-Aug-2024 HRS 6355.7 LDG 4596		O/C	0 0		
53-00-00-9600 LEFT NOSE LANDING GEAR 531001 : L	LEFT NOSE LANDING GEAR TRUNNION SUPPORT ASSEMBLY DISCARD *CF			6613020-55 NSN	MTH 16-Sep-2007 LDG 0			0 0	25500	20858
53-00-00-9600 RIGHT NOSE LANDING GEAR 531001 : R	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT ASSEMBLY DISCARD *CF			6613020-56 NSN	MTH 16-Sep-2007 LDG 0			0 0	25500	20858
53-00-00-9601 NOSE GEAR 531002	NOSE LANDING GEAR ACTUATOR FITTING ASSEMBLY DISCARD *CF			6611591-9 NSN	MTH 16-Sep-2007 LDG 0			0 0	25500	20858
531201	RADOME ASSEMBLY KICT			6613101-833 437	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		O/C			
551001	HORIZONTAL STABILIZER ASSEMBLY			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
561001 LEFT	MAIN WINDSHIELD ASSY, (LH) 9914380-13 SMF			NP139731-1 08142H6576	MTH 31-May-2009 HRS 775		O/C	0 0		
561001 RIGHT	RIGHT MAIN WINDSHIELD ASSEMBLY, (RH) 9914380-12 PHX			NP139721-12 08282H4809	MTH 16-Dec-2009 HRS 971		O/C	0 0		
561004 LEFT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-7 *CF			NP139722-7 07109H3270	MTH 16-Sep-2007		O/C	0		
561004 RIGHT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-8 *CF			NP139722-8 07059H7291	MTH 16-Sep-2007		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561005 LEFT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-33	*CF		NP139703-3 2115	MTH 16-Sep-2007		O/C	0		
561005 RIGHT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-34	*CF		NP139703-4 2020	MTH 16-Sep-2007		O/C	0		
562001 LEFT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 9734	MTH 16-Sep-2007		O/C	0		
562001 LEFT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 9846	MTH 16-Sep-2007		O/C	0		
562001 LEFT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 5501	MTH 16-Sep-2007		O/C	0		
562001 LEFT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 0142	MTH 16-Sep-2007		O/C	0		
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 9705	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 9831	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 0143	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 9813	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 9830	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 9837	MTH 16-Sep-2007		O/C	0		
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 0250	MTH 16-Sep-2007		O/C	0		
57-10-00-9600 LEFT MAIN LANDING GEAR <i>571001 : L</i>	LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD *CF			6622123-1 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-10-00-9600 RIGHT MAIN LANDING GEAR <i>571001 : R</i>	RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD *CF			6622123-2 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-10-00-9601 LEFT MAIN LANDING GEAR <i>571002 : L</i>	LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD *CF			6622124-1 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-10-00-9601 RIGHT MAIN LANDING GEAR <i>571002 : R</i>	RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD *CF			6622124-2 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-10-00-9602 LEFT MAIN LANDING GEAR <i>571003 : L</i>	LEFT MAIN LANDING GEAR ACTUATOR FITTING DISCARD *CF			6621125-5 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-10-00-9602 RIGHT MAIN LANDING GEAR <i>571003 : R</i>	RIGHT MAIN LANDING GEAR ACTUATOR FITTING DISCARD *CF			6621125-6 NSN	MTH 16-Sep-2007 LDG 0			0 0		23800 19158
57-50-04-9600.1 LEFT WING LEFT INBOARD <i>275005 : LWLI</i>	LEFT WING LEFT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 16-Sep-2007 LDG 0			0 0		5000 358
57-50-04-9600.1 LEFT WING LEFT OUTBOARD <i>275005 : LWLO</i>	LEFT WING LEFT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 16-Sep-2007 LDG 0			0 0		5000 358



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
57-50-04-9600.1	LEFT WING RIGHT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING RIGHT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : LWRI										
57-50-04-9600.1	LEFT WING RIGHT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING RIGHT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : LWRO										
57-50-04-9600.1	RIGHT WING LEFT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING LEFT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : RWLI										
57-50-04-9600.1	RIGHT WING LEFT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING LEFT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : RWLO										
57-50-04-9600.1	RIGHT WING RIGHT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING RIGHT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : RWRI										
57-50-04-9600.1	RIGHT WING RIGHT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING RIGHT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275005 : RWRO										
57-50-04-9600	LEFT WING LEFT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING LEFT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : LWLI										
57-50-04-9600	LEFT WING LEFT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING LEFT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : LWLO										
57-50-04-9600	LEFT WING RIGHT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING RIGHT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : LWRI										
57-50-04-9600	LEFT WING RIGHT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
LEFT WING RIGHT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : LWRO										
57-50-04-9600	RIGHT WING LEFT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING LEFT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : RWLI										
57-50-04-9600	RIGHT WING LEFT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING LEFT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : RWLO										
57-50-04-9600	RIGHT WING RIGHT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING RIGHT INBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : RWRI										
57-50-04-9600	RIGHT WING RIGHT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8)									
RIGHT WING RIGHT OUTBOARD	CF-2920	*CF		S3049-5F8	MTH 16-Sep-2007			0		
				NSN	LDG 0		5000	0	5000	358
275004 : RWRO										
71-22-00-9600	LEFT AFT ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION									
LEFT					MTH 16-Sep-2007			0		
712001 : L	9912480-2	*CF		LM451-SA2	HRS 0		10000	0	10000	3578.4
				LK1273						



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
71-22-00-9600 LEFT BOTTOM 712002 : LB	LEFT BOTTOM FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	*CF		LM451-SA4 LK2846	MTH 16-Sep-2007 HRS 0			0 0		3578.4
71-22-00-9600 LEFT UPPER 712002 : LT	LEFT UPPER FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	KSFB		LM451-SA4 LK1636	MTH 20-Feb-2018 HRS 4982.6 LDG 3875		10000	0	14982.6	8561
71-22-00-9600 RIGHT 712001 : R	RIGHT AFT ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-2	*CF		LM451-SA2 LK1267	MTH 16-Sep-2007 HRS 0		10000	0	10000	3578.4
71-22-00-9600 RIGHT BOTTOM 712002 : RB	RIGHT BOTTOM FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	*CF		LM451-SA4 LK2853	MTH 16-Sep-2007 HRS 0		10000	0	10000	3578.4
71-22-00-9600 RIGHT UPPER 712002 : RT	RIGHT UPPER FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	*CF		LM451-SA4 LK2847	MTH 16-Sep-2007 HRS 0		10000	0	10000	3578.4
712005	ENG VIBRATION MONITOR- 9912519-2	*CF		2789 090655	MTH 16-Sep-2007		O/C	0		
71EN1 NO. 1 710001 : E1**L	ENGINE			30J2622-01 PCE-DD0469	MTH 20-Apr-2018 HRS 5032.2 LDG 3896		E/C			
71EN2 NO. 2 710001 : E2**R	ENGINE			30J2622-01 PCE-DD0470	MTH 20-Apr-2018 HRS 5032.2 LDG 3896		E/C			
72-30-05-900-801-03 E1	HP TURBINE AIR SEAL			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
72-30-05-900-801-03 E2	HP TURBINE AIR SEAL			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
721010 E1	ACCESS GEARBOX SHAFT *CF			30J2201-01 RWA66A188	MTH 16-Sep-2007		O/C	0		
721010 E2	ACCESS GEARBOX SHAFT *CF			30J2201-01 RWA64A372	MTH 16-Sep-2007		O/C	0		
722001 E1	OIL PUMP ASSEMBLY UNK			30J3365-01 EC01A001A012	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0 0		
722001 E2	OIL PUMP ASSEMBLY UNK			01R30J3365-01 EC01A001A017	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0 0		
723010 E1	LP COMPRESSOR FAN ROTOR *CF			30J2681-01 A0026DAC	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	15000	0 0	(15000)15071	10429 10429
723010 E2	LP COMPRESSOR FAN ROTOR *CF			30J2681-01 A0026LDE	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	15000	0 0	(15000)15071	10429 10429
723020 E1	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 TXA1B2745	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	13500	0 0	(14062)14133	9491 9111

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723020 E2	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 TXA1B2458	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	13500	0 0	(14062)14133	9491 9111
723030 E1	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2821-01 A00262H8	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	13500	0 0	(13500)13571	8929 8929
723030 E2	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2821-01 A001XDAT	MTH 16-Sep-2007 LDG 71 ACCC YC	-24	13500	0 0	(13500)13571	8929 8929
723040 E1	2ND STAGE HP COMPRESSOR ROTOR UNK			30J2429-01 EAAE00K606	MTH 03-Apr-2018 HRS 5032.2 LDG 3896 ACCC YC		13500	0 0 0	(17325)17396	12754 12754
723040 E2	2ND STAGE HP COMPRESSOR ROTOR UNK			30J2429-01 EAAE000K605	MTH 05-Apr-2018 HRS 5032.2 LDG 3896 ACCC YC		13500	0 0 0	(17325)17396	12754 12754
723060 E1	CENTRIFUGAL IMPELLER *CF			30J1450-01 A00263W8	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(14062)14133	9491 9111
723060 E2	CENTRIFUGAL IMPELLER *CF			30J1450-01 A00263W9	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
724001 E1 INNER	COMBUSTION CHAMBER LINER *CF			30J2342-01 A00267MC	MTH 16-Sep-2007		O/C	0		
724001 E1 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A0025PT9	MTH 16-Sep-2007		O/C	0		
724001 E2 INNER	COMBUSTION CHAMBER LINER *CF			30J2342-01 A0026AAM	MTH 16-Sep-2007		O/C	0		
724001 E2 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A0025DPP	MTH 16-Sep-2007		O/C	0		
725010 E1	1ST-STAGE TURBINE DISK *CF			30J1551-01 A00264NH	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725010 E2	1ST-STAGE TURBINE DISK *CF			30J1551-01 A00264NL	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725020 E1	2ND-STAGE TURBINE DISK *CF			30H3152 MAA31949	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725020 E2	2ND-STAGE TURBINE DISK *CF			30H3152 MAA31993	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725030 E1	3RD-STAGE TURBINE DISK *CF			30H3153 MAA32253	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725030 E2	3RD-STAGE TURBINE DISK *CF			30H3153 MAA32151	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725040 E1	4TH-STAGE TURBINE DISK *CF			30H3154 MAA32584	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
725040 E2	4TH-STAGE TURBINE DISK *CF			30H3154 MAA32595	MTH 16-Sep-2007 LDG 71 ACCC YC		13500	0 0	(13500)13571	8929 8929
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1 *CF			9-231-28 L9562	MTH 16-Sep-2007		O/C	0		
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1 *CF			9-231-28 L9561	MTH 16-Sep-2007		O/C	0		
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3 *CF			6057-3 2434	MTH 16-Sep-2007		O/C	0		
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3 *CF			6057-3 2460	MTH 16-Sep-2007		O/C	0		
731002 E1	FLOW DIVIDER VALVE 30J2887-01 UNK			1006479-1 F66927	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 4982.6 3825		
731002 E2	FLOW DIVIDER VALVE 30J2887-01 UNK			1006479-1 F66930	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 4982.6 3825		
731035 E1	FUEL FILTER ELEMENT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
731035 E2	FUEL FILTER ELEMENT			PN SN-UNKNOWN	MTH 16-Sep-2007		O/C	0		
731120 E1	EMERGENCY FUEL SHUTOFF VALVE UNK			31J2944-01 WV021918	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0 0		
731120 E2	EMERGENCY FUEL SHUTOFF VALVE UNK			31J2944-01 WV022118	MTH 05-Apr-2018		O/C	0		
732001 E1	HYDROMECHANICAL FUEL CONTROL			1012636-25 F64323	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
732001 E2	HYDROMECHANICAL FUEL CONTROL			1012636-25 F67029	MTH 12-Aug-2022 HRS 5959.7 LDG 4366		O/C			
732011 E1	T1/FCU TEMP SENSOR 30J1580-04			818487-4 KC072687	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		O/C	4982.6 3825		
732011 E2	T1/FCU TEMP SENSOR 30J1580-04			818487-4 KC072200	MTH 05-Apr-2018 HRS 5032.1 LDG 3896		O/C	4982.6 3825		
741001 E1	IGNITION EXCITER 31J2807-07			500335-1 NNA15320001	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		O/C			
741001 E2	IGNITION EXCITER 31J2807-07	KFXE		500335-1 NN02307082	MTH 18-May-2021 HRS 5590.1 LDG 4135		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
742001 E1 INBOARD	UPPER IGNITOR 30J2825-01	KMCO		502600-1 NNA15230263	MTH 20-Aug-2015 HRS 4351.3 LDG 3603		O/C	0 0		
742001 E1 OUTBOARD	LOWER IGNITOR 30J2825-01	KMCO		502600-1 NNA15180189	MTH 20-Aug-2015 HRS 4351.3 LDG 3603		O/C	0 0		
742001 E2 INBOARD	UPPER IGNITOR 30J2825-01	KMCO		502600-1 NNA15180193	MTH 20-Aug-2015 HRS 4351.3 LDG 3603		O/C	0 0		
742001 E2 OUTBOARD	LOWER IGNITOR 30J2825-01	KFXE		502600-1 NNA17350212	MTH 21-Oct-2017 HRS 4945.8 LDG 3860		O/C	0 0		
742002 E1	SHORT IGNITOR LEAD 30J3125-01	SMF		508122-1 NNA08198221	MTH 11-Sep-2009 HRS 934.5		O/C	0 0		
742002 E2	SHORT IGNITOR LEAD 30J3125-01	SMF		508122-1 NNA08218979	MTH 11-Sep-2009 HRS 934.5		O/C	0 0		
742003 E1	LONG IGNITOR LEAD 30J3125-02	SMF		508122-2 NNA08374551	MTH 11-Sep-2009 HRS 934.5		O/C	0 0		
742003 E2	LONG IGNITOR LEAD 30J3125-02	SMF		508122-2 NNA08187739	MTH 11-Sep-2009 HRS 934.5		O/C	0 0		
751003 E1	COMPRESSOR BLEED VALVE ASSY UNK			30J2954-01 AHX004893	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 0 0		
751003 E2	COMPRESSOR BLEED VALVE ASSY UNK			30J2954-01 AHX008476	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C	0 4982.6 3825		
751004 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE UNK			30J3491-01 TR5720	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		O/C	0 0 0		
751004 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE UNK			30J3491-01 TR5682	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		O/C	0 0 0		
751005 E1	LINEAR TRANSDUCER UNK			GM9424 2415	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		O/C			
751005 E2	LINEAR TRANSDUCER *CF			31J2071-01 2409	MTH 16-Sep-2007		O/C	0		
761001 LEFT	THROTTLE DETENT VALVE *CF			5303-2A 4062A	MTH 16-Sep-2007		O/C	0		
761001 RIGHT	THROTTLE DETENT VALVE *CF			5303-2A 4064A	MTH 16-Sep-2007		O/C	0		
761001 E1	ELECTRONIC ENGINE CONTROL 30J2659-03 *CF			1004855-2-002 07046670	MTH 16-Sep-2007		O/C	0		
761001 E2	ELECTRONIC ENGINE CONTROL 30J2659-03 UNK			1004855-2-002 07054760	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
771006	ENGINE (AMLCD) INDICATOR 9912574-5	RNO		10644D02M05 07080737A	MTH 06-Mar-2011 HRS 1662.7 LDG 1393		O/C			
771004 E1	SPEED N1 SENSOR	*CF		31J2072-01 CH1623	MTH 16-Sep-2007		O/C	0		
771004 E2	SPEED N1 SENSOR	*CF		31J2072-01 CH1622	MTH 16-Sep-2007		O/C	0		
771005 E1	SPEED N2 SENSOR	*CF		31J2073-01 CH2488	MTH 16-Sep-2007		O/C	0		
771005 E2	SPEED N2 SENSOR	*CF		31J2073-01 CH2503	MTH 16-Sep-2007		O/C	0		
772001 E1	TEMPERATURE SENSOR			31J2113-03 RTK9838	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		O/C	4982.6 3825		
772001 E2	TEMPERATURE SENSOR	UNK		31J2113-03 RTK9851	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C			
774001 E1	DATA COLLECTION UNIT 30J2673-02	*CF		32205-03 DP074606	MTH 16-Sep-2007		O/C	0		
774001 E2	DATA COLLECTION UNIT	UNK		62118-05 17050983	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		O/C	0		
783001 LEFT ENGINE 783001X : E1**L	THRUST REVERSER ASSEMBLY 9912609-13	*CF		64ND-78002-5 1215	MTH 16-Sep-2007		O/C	0		
783001 RIGHT ENGINE 783001X : E2**R	THRUST REVERSER ASSEMBLY 9912609-14	*CF		64ND-78002-6 1216	MTH 16-Sep-2007		O/C	0		
783002 LEFT	THRUST REVERSER VALVE	*CF		4221 0471	MTH 16-Sep-2007		O/C	0		
783002 RIGHT	THRUST REVERSER VALVE	*CF		4221 0500	MTH 16-Sep-2007		O/C	0		
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2691	MTH 16-Sep-2007		O/C	0		
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR	KJVL		2564000-7 0871	MTH 26-Oct-2023 HRS 6186.8 LDG 4490		O/C	0 0		
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2703	MTH 16-Sep-2007		O/C	0		
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2706	MTH 16-Sep-2007		O/C	0		
783100 LEFT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0468	MTH 16-Sep-2007		O/C	0		
783100 RIGHT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0495	MTH 16-Sep-2007		O/C	0		
783101 LEFT	ARM PRESSURE SWITCH	*CF		80637-1 0777	MTH 16-Sep-2007		O/C	0		
783101 RIGHT	ARM PRESSURE SWITCH	*CF		80637-1 0792	MTH 16-Sep-2007		O/C	0		
783102 LEFT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0473M	MTH 16-Sep-2007		O/C	0		
783102 RIGHT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0469M	MTH 16-Sep-2007		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
783103	STOW LIMIT SWITCH			53ND78304-1	MTH 16-Sep-2007		O/C	0		
LEFT INBOARD		*CF		NSN						
783103	STOW LIMIT SWITCH			53ND78304-1	MTH 16-Sep-2007		O/C	0		
LEFT OUTBOARD		*CF		NSN						
783103	STOW LIMIT SWITCH			53ND78304-1	MTH 16-Sep-2007		O/C	0		
RIGHT INBOARD		*CF		NSN						
783103	STOW LIMIT SWITCH			53ND78304-1	MTH 16-Sep-2007		O/C	0		
RIGHT OUTBOARD		*CF		NSN						
783104	DEPLOY LIMIT SWITCH			53ND78304-5	MTH 16-Sep-2007		O/C	0		
LEFT		*CF		NSN						
783104	DEPLOY LIMIT SWITCH			53ND78304-5	MTH 16-Sep-2007		O/C	0		
RIGHT		*CF		NSN						
793002	OIL TEMP XMTR SENSOR			102-00083	MTH 16-Sep-2007		O/C	0		
LEFT		*CF		05658						
793002	OIL TEMP XMTR SENSOR			102-00083	MTH 16-Sep-2007		O/C	0		
RIGHT		*CF		05664						
793102	ENGINE OIL TRANSMITTER			APTE-237E-1000-	MTH 16-Sep-2007		O/C	0		
LEFT	9912464-1	*CF		250D 73078327						
793102	ENGINE OIL TRANSMITTER			APTE-237E-1000-	MTH 16-Sep-2007		O/C	0		
RIGHT	9912464-1	*CF		250D 739011212						
793117	OIL PRESSURE SWITCH			1153P0098-01	MTH 16-Sep-2007		O/C	0		
LEFT	9912466-2	*CF		1875						
793117	OIL PRESSURE SWITCH			1153P0098-01	MTH 16-Sep-2007		O/C	0		
RIGHT	9912466-2	*CF		1831						
790010	OIL FILTER ELEMENT			PN	MTH 16-Sep-2007		O/C	0		
E1				SN-UNKNOWN						
790010	OIL FILTER ELEMENT			PN	MTH 16-Sep-2007		O/C	0		
E2				SN-UNKNOWN						
793003	FUEL OIL HEAT EXCHANGER			D2552-800B	MTH 03-Apr-2018		O/C	0		
E1		UNK		0018731774	HRS 5032.2 LDG 3896			0 0 0		
793003	FUEL OIL HEAT EXCHANGER			31J2955-02	MTH 05-Apr-2018		O/C	0		
E2	D2552-600B	UNK		03646145	HRS 5032.2 LDG 3896			0 0 0		
80-10-00-9600	LEFT ENGINE STARTER - GENERATOR (BEARINGS DISCARD AND ARMATURE FUNCTIONAL CHECK) RESTORATION									
LEFT ENGINE	9912499-6	KDLL		300SGL138Q-4	MTH 10-Apr-2024					
801000 : L				7598XL	HRS 6283.8 LDG 4550		1000	0	7283.8	862.2
80-10-00-9600	RIGHT ENGINE STARTER - GENERATOR (BEARINGS DISCARD AND ARMATURE FUNCTIONAL CHECK) RESTORATION									
RIGHT ENGINE	9912499-6			300SGL138Q-4	MTH 25-Aug-2022			0		
801000 : R				3954XL	HRS 5972 LDG 4375		1000	0 0 0	6972	550.4
80-11-00-9600	AUXILIARY POWER UNIT STARTER - GENERATOR (BEARINGS DISCARD AND ARMATURE FUNCTIONAL CHECK) RESTORATION									
APU		KFXE		300SGL138Q-6	MTH 18-Aug-2017					
801100 : APU	9912499-31			8408XL	HRS 4839.9 LDG 3814 APUH 1875.1 APUS 3476		1000	0	2875.1	324.2



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560XL-03-01 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SB 560XL-05-01	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM (CANCELLED AND SUPERSEDED BY SL560XL-05-03),						-			
	MOC :									
SL CIL-99-01 R02	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			CANCELLED			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL 560XL-20-01 R04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R05)			SUPERSEDED			-			
	MOC :									
SL 560XL-20-01 R06	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R07)			SUPERSEDED			-			
	MOC :									
SL 560XL-20-01 R07	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R08)			SUPERSEDED			-			
	MOC :									
SL 560XL-20-01 R08	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R09)			SUPERSEDED			-			
	MOC :									
SL 560XL-20-01 R09	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R10)			SUPERSEDED			-			
	MOC :									
SL 560XL-20-01 R10	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R11)			SUPERSEDED MTH			-			
	MOC :									
SL 560XL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R01)			SUPERSEDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-21-18	AIR CONDITIONING - TEMPERATURE CONTROLLER UPGRADE (SUPERSEDED BY 560XL-21-18 R01) SUPERSEDED				-			
	MOC :							
SB 560XL-21-22	AIR CONDITIONING - CABIN TEMPERATURE SENSOR RELOCATION (SUPERSEDED BY 560XL-21-22 R01) SUPERSEDED				-			
	MOC :							
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT INFORMATIONAL				-			
	MOC :							
SL CIL-21-03 R01	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION INFORMATIONAL				-			
	MOC :							
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION INFORMATIONAL				-			
	MOC :							
SL 560XL-21-07	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2215460-21-2762, ENVIRONMENTAL CONTROL UNIT (ECU) - INSPECT AND REPLACE THE OVER TEMPERATURE SWITCH (SUPERSEDED BY SL560XL-21-07 R01) SUPERSEDED				-			
	MOC :							
SL 560XL-21-09	AIR CONDITIONING - AIR CYCLE MACHINE INLET DUCT VANE REMOVAL (SUPERSEDED BY SL560XL-21-09 R01) SUPERSEDED				-			
	MOC :							
SL 560XL-21-12	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2215460-21-2814, AIR CONDITIONING - ENVIRONMENTAL CONTROL UNIT - MODIFICATION OF ENVIRONMENTAL CONTROL UNIT (ECU), PN 2215460-2 SERIES 2, OR PN 2215460-3 SERIES 1, BY REPLACEMENT OF COMPRESSOR OUTLET OVER TEMPERATURE SWITCH, PN 927223-2-2 INFORMATIONAL				A/R			
	MOC :							
SB 560XL-23-10	COMMUNICATIONS - AVIATOR 300 SATCOM INTERMEDIATE GAIN ANTENNA (IGA) REPLACEMENT OPTIONAL				-			
	MOC :							
SB 560XL-23-11	COMMUNICATIONS - ATN-B1 CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION OPTIONAL				-			
	MOC :							
SL 560XL-23-08	COMMUNICATIONS - TRANSMITTAL OF HONEYWELL SIL D201005000001 INFORMATIONAL				A/R			
	MOC :							
SL 560XL-23-12	COMMUNICATIONS - INSTALLATION OF THE SATCOM ANTENNA DOUBLERS OPTIONAL				-			
	MOC :							
SL 560XL-23-13	COMMUNICATIONS - COCKPIT VOICE RECORDER (CVR) CONTROL PANEL REPLACEMENT RECOMMENDED				-			
	MOC :							
SB 560XL-24-02 R01 24SB-02 : XLR1	ELECTRICAL POWER - CONCORDE BATTERY INSTALLATION OPTIONAL		MTH 24-Feb-2009 HRS 678		-			Complete
	MOC : COMPLIED WITH							
SB 560XL-24-02	ELECTRICAL POWER - CONCORDE BATTERY INSTALLATION (SUPERSEDED BY 560XL-24-02 R01) SUPERSEDED				-			
	MOC :							
SB 560XL-24-14 R01	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT (SUPERSEDED BY 560XL-24-14 R02) SUPERSEDED				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-24-14 R02 <i>24SB-14 : XLR2</i>	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT	SMF		RECOMMENDED	MTH 26-Feb-2010 HRS 1073		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-24-14	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT (SUPERSEDED BY 560XL-24-14 R01)			SUPERSEDED			-			
MOC :										
SB 560XL-24-16	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT			RECOMMENDED			A/R			
MOC :										
SB 560XL-24-18	ELECTRICAL POWER - STANDBY POWER WIRING MODIFICATION			RECOMMENDED			A/R			
MOC :										
SB 560XL-24-21 R01	ELECTRICAL POWER - INSTALL NEW RIGHT ALTERNATOR POWER CONTROL UNIT (PCU) (UE016) MOUNTING BRACKET			RECOMMENDED			-			
MOC :										
SL 560XL-24-07	ELECTRICAL POWER - RIGHT AC GENERATOR WIRE ROUTING VERIFICATION	KFXE		MANDATORY	DAYS 28-Mar-2017 HRS 4728.3 LDG 3770		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2017-04-14. INSPECTED AREA AS REFERENCED IN TEXTRON AVIATION SL560XL-24-07. NOTICED SLIGHT CHAFFING ON FUEL TUBE ASSEMBLY P/N 66166110-30 WELL WITHIN LIMITS 0.002" AS PER PARA. 3A(1) OF SERVICE LETTER. INSPECTED GENERATOR WIRING AND FOUND SLIGHT CHAFFING ON WIRE IDENTIFICATION TAG. REPAIRED AS REQUIRED IAW PARA. 3B(1) OF SERVICE LETTER. ROUTED WIRE BUNDLES AS PER PARA. 3(C) VIEW A-A OF SERVICE LETTER. NO FURTHER ACTION REQUIRED.										
SB 560XL-25-05 R02	EQUIPMENT/FURNISHINGS - INTERIOR CABINETRY ATTACHING FLOOR PLATES INSTALLATION			MANDATORY			-			
MOC :										
SB 560XL-25-12	EQUIPMENT/FURNISHINGS - GLARESHIELD LEATHER STRIP INSTALLATION (SUPERSEDED BY 560XL-25-12 R01)			SUPERSEDED			-			
MOC :										
SB 560XL-25-15 R01	EQUIPMENT/FURNISHINGS - IMPROVEMENT TO THE AFT DIVIDER			OPTIONAL	MTH 16-Sep-2007		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W ON SERIALNUMBERS 560XL-5353 AND ON										
SL CIL-25-02	EQUIPMENT/FURNISHINGS - MEDAIRE AIRCRAFT FIRST AID KITS WITH MEDICATION SUBJECT TO RECALL NOTICE			INFORMATIONAL			-			
MOC :										
SL CIL-25-03 R01	EQUIPMENT/FURNISHINGS - SEAT PAN TILT BLOCKING TAB INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 560XL-25-14	EQUIPMENT/FURNISHINGS - PASSENGER SEAT INSPECTION			MANDATORY	MTH		A/R			
MOC :										
SL 560XL-25-15 R01	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF AIRCRAFT BELTS INC. SB-BUC062-A001 INSPECTION OF BUCKLES FOR PROPER OPERATION			MANDATORY	MTH		A/R			
MOC :										
SL 560XL-25-16	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF IPECO SERVICE BULLETINS 428-25-01, AND 429-25-01, ADDITION OF CABLE CLIP			RECOMMENDED	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-25-17	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR	SMF		RECOMMENDED	MTH 15-Sep-2013 HRS 3128.3 LDG 2538		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL-25-17, BY CHANGING THE LUMBAR ASSEMBLY										
SL 560XL-25-18	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE CABINET SPRING ASSEMBLY PINS			RECOMMENDED			-			
MOC :										
SL 560XL-25-19 R01	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE SEAT PAN TILT SNAP RINGS (MILLENNIUM SERVICE BULLETIN SB2050-25-20-02B)			RECOMMENDED			-			
MOC :										
SB 560XL-26-02 R01	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			Complete
MOC : COMPLIED WITH										
SB 560XL-26-02	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION (SUPERSEDED BY 560XL-26-02 R01)			SUPERSEDED			-			
MOC :										
SB 560XL-26-04	FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS			OPTIONAL			-			
MOC :										
ASL 560XL-26-01 R01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 THERMISTORS DETECTORS (SUPERSEDED BY ASL560XL-26-01 R02)						-			
MOC :										
ASL 560XL-26-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36-THERMISTORS DETECTORS (SUPERSEDED BY ASL560XL-26-01 R01)						-			
MOC :										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KFXE		MANDATORY	MTH 12-Apr-2019 HRS 5235.1 LDG 3983		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER CIL-26-01R1 FIRE EXTINGUISHER STUD TORQUING. NO DISCREPANCIES NOTED.										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)			MANDATORY	MTH		-			
MOC :										
SL 560XL-26-02 R01	FIRE PROTECTION - FIRE BOTTLE WIRE VERIFICATION AND TEST	KJVL		MANDATORY	DAYS 21-Aug-2024 HRS 6355.7 LDG 4596		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL-26-02 R01 IN ACCORDANCE WITH CESSNA 560XL MAINTENANCE MANUAL AND SL560XL-26-02 R01. NO FURTHER ACTION REQUIRED.										
SL 560XL-26-02	FIRE PROTECTION - FIRE BOTTLE WIRE VERIFICATION AND TEST			MANDATORY	MTH 17-Sep-2021 HRS 5613.7 LDG 4146		-			Complete
MOC : COMPLIED WITH										
SB 560XL-27-11 REV A	HORIZONTAL STABILIZER ACTUATOR REPLACEMENT			RECOMMENDED			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-27-19	FLIGHT CONTROLS - STEEP APPROACH CERTIFICATION (SUPERSEDED BY 560XL-27-19 R01)			SUPERSEDED			-			
	MOC :									
SB 560XL-27-24	FLIGHT CONTROLS - AILERON WING CABLE PULLEY REPLACEMENT			RECOMMENDED			-			
	MOC :									
SB 560XL-27-32 R01	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION (SUPERSEDED BY 560XL-27-32 R02)	SMF		SUPERSEDED	MTH 03-May-2011 HRS 1723 LDG 1443		-			Complete
	MOC : COMPLIED WITH									
SB 560XL-27-33	FLIGHT CONTROLS - PILOT ERGONOMICS INSTALLATION			OPTIONAL			A/R			
	MOC :									
SL 560XL-27-20 R02	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION	MHR		MANDATORY	MTH 24-Jan-2014 HRS 3361.9 LDG 2730		-			Complete
	MOC : COMPLIED WITH - PERFORMED SL560XL-27-21 BY COMPLIANCE OF SL560XL-27-20 AT THIS TIME. NO DEFECTS NOTED AT THIS TIME.									
SL 560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION	MHR		MANDATORY	MTH 24-Jan-2014 HRS 3361.9 LDG 2730		-			Complete
	MOC : COMPLIED WITH - PERFORMED SL560XL-27-20R2 PER SL INSTRUCTIONS. NO DEFECTS NOTED AT THIS TIME.									
SL 560XL-27-33	FLIGHT CONTROLS - ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD	KMCO		MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH BY OBTAINING POPPER CLEARANCE OF ELEVATOR CABLE DAMPERS PER SL INSTRUCTIONS.									
SL 560XL-27-34 R01	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION	KMCO		MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH BY VERIFYING FOR CORRECT RIGHT AILERON CABLE INSTALLATION PER SL INSTRUCTIONS.									
SL 560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION	KFXE		MANDATORY	MTH 07-Jul-2016 DAYS 4537.8 HRS 3683 LDG 1768.9 APUH 3328 APUS		-			Complete
	MOC : COMPLIED WITH - PERFORMED THE INSPECTION REQUIREMENTS OF SL 560XL-27-35 FLIGHT CONTROLS-AFT AILERON SECTOR ASSEMBLY INSPECTION. ACCOMPLISHED REFERENCING PARAGRAPH 1 THROUGH 3 B. NO DRAIN HOLES OR CORROSION NOTED. CONTINUED WITH STEP 4A. NO CORROSION NOTED. COMPLIED STEP 6 THROUGH 8 ABC. OK FOR CONTINUED SERVICE.									
SB SL560XL-27-38	FLIGHT CONTROLS - INSPECTION OF THE HORIZONTAL STABILIZER UPPER SCISSOR LINK FITTING			RECOMMENDED	MTH		-			
	MOC :									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-28-03	FUEL - MOTIVE FLOW SHUTOFF VALVE O-RING REPLACEMENT	SMF		RECOMMENDED	MTH 03-May-2011 HRS 1723 LDG 1443		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-28-07	FUEL - 6621102-1 LEFT WEB CORROSION PROTECTION			RECOMMENDED			-			
MOC :										
SL 560XL-29-03 29SL-03 : XL	HYDRAULIC POWER - ENGINE HYDRAULIC HOSE INSPECTION	SMF		RECOMMENDED	MTH 11-Sep-2009 HRS 885		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-30-01 R01	ICE AND RAIN - RAIN REMOVAL FAN CHECK VALVE INSTALLAION			RECOMMENDED			-			
MOC :										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 560XL-30-01 R15	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY CIL-30-01)			SUPERSEDED			-			
MOC :										
SB 560XL-31-06	INDICATING/RECORDING SYSTEMS - OPTION TO REPLACE THE AVIONICA SECONDARY QUICK ACCESS RECORDER (QAR) WITH AN L-3 SECONDARY QUICK ACCESS RECORDER			OPTIONAL			-			
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 560XL-31-06	INDICATING/RECORDING SYSTEMS - INSPECTION OF THE POSITION-SENSOR POTENTIOMETER FOR THE ELEVATOR TRIM TAB			RECOMMENDED			-			
MOC :										
SB 560XL-32-38 R02	LANDING GEAR - REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK			OPTIONAL	MTH 17-Sep-2021 HRS 5613.7 LDG 4146		-			Complete
MOC : COMPLIED WITH										
SB 560XL-32-40 32SB-40 : XL	LANDING GEAR ANNUNCIATION WIRING MODIFICATION	SMF		RECOMMENDED	MTH 09-Apr-2008 HRS 310		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-32-41 R01	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7	MHR		MANDATORY	MTH 14-Mar-2012 HRS 2244 LDG 1841		A/R			Complete
MOC : COMPLIED WITH - PERFORMED SB 560XL-32-41 PER INSTRUCTIONS AND INSTALLATION OF INSERTS P/N 170-664 ON RIGHT WHEEL ONLY.										
SB 560XL-32-45	LANDING GEAR - LANDING GEAR WARNING HORN REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-32-47	LANDING GEAR - MAIN LANDING GEAR BRAKE HYDRAULIC LINE FITTING REPLACEMENT			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
	MOC :									
SL CIL-32-07	LANDING GEAR - MODIFICATION OF THE ACCOMPLISHMENT INSTRUCTIONS FOR PREPARING THE AIRCRAFT FOR MAINTENANCE OPERATIONS			INFORMATIONAL			-			
	MOC :									
SL 560XL-32-21 32SL-21 : XL	LANDING GEAR - MS20819-4 SLEEVE INSPECTION	SMF		MANDATORY	MTH 09-Apr-2008 HRS 310		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-32-23 32SL-23 : XL	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	SMF		RECOMMENDED	MTH 07-Jan-2010 HRS 996		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-32-25	LANDING GEAR - MAIN WHEEL ASSEMBLY, P/N 3-1571 SERIES-MODEL 560XL/XLS SERIES AIRCRAFT - IMPROVED INSPECTION PROCEDURE			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-32-27	LANDING GEAR - HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION (SUPERSEDED BY SL560XL-32-27 R01)	SMF		MANDATORY	DAYS 30-Sep-2014 HRS 3765.5 LDG 3115		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL 560XL-32-27 BY INSPECTION OF AND THE INSTALLATION OF PROTECTIVE SLEEVING ON THE HYDRAULIC LOADING VALVE WIRING ASSEMBLY. NO DEFECTS NOTED. OPERATIONAL CHECK NORMAL.									
SL 560XL-32-32	LANDING GEAR - MAIN LANDING GEAR COMPONENTS REPAIR			INFORMATIONAL			-			
	MOC :									
SB 560XL-33-13	LIGHTS - AFT EMERGENCY BATTERY INSTALLATION IMPROVEMENT (SUPERSEDED BY 560XL-33-13 R01)			SUPERSEDED			-			
	MOC :									
SB 560XL-33-14 33SB-14 : XL	LIGHTS - BAGGAGE COMPARTMENT LIGHT ASSEMBLY REPLACEMENT	SMF		MANDATORY	MTH 13-Sep-2008 HRS 485		A/R			Complete
	MOC : COMPLIED WITH									
ASL 560XL-33-07	LIGHTS - TRANSMITTAL OF BIRK SERVICE BULLETIN SB25-01, INTERIOR LIGHT LAMP SOCKET REPLACEMENT (SUPERSEDED BY ASL560XL-33-07 R01)			SUPERSEDED			-			
	MOC :									
SAIB CE-10-29 R01	AFT SIDE LEDGE DIVIDER LIGHT			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-33-10	LIGHTS - AFT SIDELEDGE DIVIDER LIGHT INSPECTION/REPLACEMENT			RECOMMENDED			A/R			
	MOC :									
SB 560XL-34-38 R02	NAVIGATION - UNS1-CSP TO UNS1-CSP+ AND UNS1-ESP UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2			OPTIONAL			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-34-43 R01 <i>34SB-43 : XLR1</i>	NAVIGATION - UNIVERSAL AVIONICS PERFORMANCE DATABASE UPGRADE OPTIONAL	MTH HRS	24-Feb-2009 678		A/R			Complete
MOC : COMPLIED WITH								
SB 560XL-34-60	NAVIGATION - UNIVERSAL UNS-1ESPW FMS WIDE AREA AUGMENTATION SYSTEM (WAAS) UPGRADE KSFB OPTIONAL	MTH HRS LDG	20-Feb-2018 4982.6 3875		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB SEE MODIFIED FMS FMS-1 UNS-1ESP (P/N: 2019-41-201 S/N: 649) AND FMS-2 UNS-1ESP (P/N: 2019-41-201 S/N: 666) MODIFIED TO FMS-1 UNS-1ESPW (P/N: 3019-41-201 S/N: 1064) AND FMS-2 UNS-1ESPW (P/N: 3019-41-201 S/N: 1065).								
SB 560XL-34-62 <i>34SB-62 : XL</i>	NAVIGATION - STANDBY GYRO BATTERY WIRING MODIFICATION SMF RECOMMENDED	MTH HRS	09-Apr-2008 310		A/R			Complete
MOC : COMPLIED WITH								
SB 560XL-34-68 R01	NAVIGATION - AFD AOA CONFIGURATION WIRING INSTALLATION RECOMMENDED				A/R			
MOC :								
SB 560XL-34-70	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE MHR OPTIONAL	MTH HRS LDG	23-Mar-2012 2261.8 1855		A/R			Complete
MOC : COMPLIED WITH								
SB 560XL-34-71	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0 (SUPERSEDED BY 560XL-34-71 R01) KICT MANDATORY	MTH HRS LDG	22-Oct-2012 2535.3 2080		-			Complete
MOC : COMPLIED WITH								
SB 560XL-34-72 R01	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1 KSFB OPTIONAL	MTH HRS LDG	20-Feb-2018 4982.6 3875		-			Complete
MOC : COMPLIED WITH - TCAS 2000 (S/W VER. 7.0) (P/N: 7517900-55012 S/N: 20009040) UPGRADED TO TCAS 2000 (S/W VER. 7.1) (P/N: 7517900-55020 S/N: 2009040) IAW CESSNA SB560XL-34-72 REV.1.								
SB 560XL-34-72	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1 (SUPERSEDED BY 560XL-34-72 R01) KSFB OPTIONAL	MTH HRS LDG	20-Feb-2018 4982.6 3875		-			Complete
MOC : COMPLIED WITH - TCAS 2000 (S/W VER. 7.0) (P/N: 7517900-55012 S/N: 20009040) UPGRADED TO TCAS 2000 (S/W VER. 7.1) (P/N: 7517900-55020 S/N: 2009040) IAW CESSNA SB560XL-34-72.								
SB 560XL-34-73	NAVIGATION - TRAFFIC SURVEILLANCE SYSTEM (TTR-4000) TCAS II SOFTWARE 7.1 UPGRADE OPTIONAL				-			
MOC :								
SL CIL-34-01	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.()-34-3508 INFORMATIONAL				-			
MOC :								
SL CIL-34-02	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM MHR MANDATORY	MTH HRS LDG	26-Mar-2013 2808.5 2284		-			Complete
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-34-06 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE	INFORMATIONAL			-			
	MOC :							
SL CIL-34-06	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE (SUPERSEDED BY CIL-34-06 R01)	INFORMATIONAL			-			
	MOC :							
SL CIL-34-08	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ATL-4000-34-D, NAVIGATION - ALT-4000 - EVALUATION OF SURFACE MOUNT FERRITE BEAD USED ON THE POWER SUPPLY	RECOMMENDED			-			
	MOC :							
SL CIL-34-09 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE INFORMATION LETTER FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION	INFORMATIONAL			-			
	MOC :							
SL CIL-34-09	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION	INFORMATIONAL			-			
	MOC :							
SB CIL-34-11	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT	OPTIONAL			-			
	MOC :							
SL 560XL-34-23	NAVIGATION - HONEYWELL SERVICE INFORMATION LETTER DU-870 DRY OUT PROCEDURES	INFORMATIONAL			A/R			
	MOC :							
SL 560XL-34-26	NAVIGATION - 822-2189-100 GPS-4000S SB15 UPDATE	RECOMMENDED			-			
	MOC :							
SL 560XL-34-27 R02	NAVIGATION - GPS-4000S GLOBAL POSITIONING SYSTEM SOFTWARE UPDATE	MANDATORY			DUE			
	MOC :							
SL 560XL-34-29	NAVIGATION - IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES	MANDATORY			-			
	MOC :							
SL 560XL-34-30	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN FGC-3XXX-22-AA - PITCH TRIM FAILURE AND/OR CHATTER AT START-UP	OPTIONAL			-			
	MOC :							
SB 560XL-35-04	OXYGEN - OXYGEN SYSTEM PRESSURE SWITCH REPLACEMENT FOR CHINESE REGISTERED AIRPLANES	OPTIONAL			-			
	MOC :							
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	MANDATORY	MTH 16-Jan-2016 DAYS 4421.1 HRS 3632 LDG		-			N/A
	MOC : NOT APPLICABLE - THE PREVIOUS COMPLIANCE OF AD2015-23-09 ZODIAC AEROTECHNIC - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR INSPECTION / REPAIR REFERENCING ZODIAC AEROSPACE SB MCF-SBU-35-001 ON 16-JAN-16 @ 4421.1 HOURS / 3632 LANDINGS MEETS THE REQUIREMENTS OF THIS CIL. NO FURTHER ACTION REQUIRED.							
SL 560XL-35-04	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R01)	MANDATORY	MTH 26-Sep-2011 HRS 1968.8 LDG 1635		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL560XL-35-04, MASK ASSEMBLIES DO NOT FALL INTO THE EFFECTIVE RANGE.							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-38-02 R01	WATER/WASTE - EXTERNALLY SERVICEABLE TOILET IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SL 560XL-38-01	WATER/WASTE - TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023	SMF		RECOMMENDED	MTH 03-May-2011 HRS 1723 LDG 1443		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-49-14	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8364 AUXILIARY AIRBORNE - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888395-2 WITH PN 3888395-3 ON THE RE100[XL] AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
	MOC :									
SB 3615880-49-8149 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 3615880-49-8149 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 3822101-49-8148 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 3822101-49-8148 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 3881800-49-7523 R01	GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PART NO. 3876255-2 WITH PART NO. 3876351-1 AND RE-IDENTIFY LUBE PUMP FROM PART NO. 3881800-1 TO PART NO. 3881825-1			RECOMMENDED			-			
	MOC :									
SB 3881800-49-7523 R02	GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PART NO. 3876255-2 WITH PART NO. 3876351-1 AND RE-IDENTIFY LUBE PUMP FROM PART NO. 3881800-1 TO PART NO. 3881825-1			RECOMMENDED			-			
	MOC :									
SB 3881800-49-7523 R03	GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PART NO. 3876255-2 WITH PART NO. 3876351-1 AND RE-IDENTIFY LUBE PUMP FROM PART NO. 3881800-1 TO PART NO. 3881825-1			RECOMMENDED			-			
	MOC :									
SB 3881800-49-7523 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PN 3876255-2 WITH PN 3876351-1 AND REIDENTIFY LUBE PUMP FROM PN 3881800-1 TO PN 3881825-1, ON RE100[XL] AND RE100[LJ] APUS			RECOMMENDED			-			
	MOC :									
SB 3881800-49-7523	GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PART NO. 3876255-2 WITH PART NO. 3876351-1 AND RE-IDENTIFY LUBE PUMP FROM PART NO. 3881800-1 TO PART NO. 3881825-1			RECOMMENDED			-			
	MOC :									
SB 3883900-49-7976 R02	AIRBORNE AUXILIARY POWER - MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1, ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT AUXILIARY POWER UNIT (APU) SHOP VISIT			RECOMMENDED			ESV			
	MOC :									
SB 3883900-49-8297	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL SEAL, PN 3883905-1, WITH PN 70722907-1 ON THE FUEL CONTROL UNIT (FCU), PN 3883900-1 FOR THE RE100 APU			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 49-7933 R02	APPROVED OILS			RECOMMENDED			-			
	MOC :									
SB 49-7933 R03	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS			RECOMMENDED			-			
	MOC :									
SB 49-7933 R05	OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R6)						-			
	MOC :									
SB 49-7933 R06	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R7)						-			
	MOC :									
SB 49-7933 R07	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R08)						-			
	MOC :									
SB 49-7933 R08	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						-			
	MOC :									
SB 49-7997 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						-			
	MOC :									
SB 49-7997 R05	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						-			
	MOC :									
SB 70721598-49-8168 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 70721598-49-8168 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 70721725-49-8152 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 70721725-49-8152 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED			-			
	MOC :									
SB 70722360-49-8306	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF TURBINE ROTOR PN 70722360-1 ON RE100 AUXILIARY POWER UNITS (APU)				APUH 18-Feb-2022 APUS 2259.4 3964		-			Complete
	MOC : COMPLIED WITH									
SIL APU-49 R10	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			-			
	MOC :									
SIL APU-49 R11	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			-			
	MOC :									
SIL APU-49 R12	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SIL APU-49 R13	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED			-			
MOC :										
SB RE100-49-7530 R01	GAS TURBINE ENGINE - REPLACE LUBE PUMP, PART NO. 3881800-1 WITH PART NO. 3881825-1			RECOMMENDED			-			
MOC :										
SB RE100-49-7530	GAS TURBINE ENGINE - REPLACE LUBE PUMP, PART NO. 3881800-1 WITH PART NO. 3881825-1			RECOMMENDED			-			
MOC :										
SB RE100-49-7563	GAS TURBINE ENGINE - REPLACE GENERATOR SEAL, PART NO. 3863387-1 WITH PART NO. 3863504-1			RECOMMENDED			-			
MOC :										
SB RE100-49-7896 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK CAP, PN 361-530-9355, ON THE RE100 APU			OPTIONAL			-			
MOC :										
SB RE100-49-7992 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
MOC :										
SB RE100-49-8139	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU			RECOMMENDED	APUH 18-Feb-2022 APUS 2259.4 3964		-			Complete
MOC : COMPLIED WITH										
SB RE100-49-8250 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN3881825-2, FOR THE RE100[CS] AND RE100 [XL] AUXILIARY POWER UNIT (APU)			ATTRITION			-			
MOC :										
SB RE100-49-8250 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100 [XL] AUXILIARY POWER UNIT (APU)			ATTRITION			-			
MOC :										
SB RE100-49-8303 R03	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
MOC :										
SB RE100-49-8303 R04	GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
MOC :										
SB RE100-49-8303	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU)			OPTIONAL			-			
MOC :										
SB RE100-49-8360 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS			CATEGORY 2			-			
MOC :										
SB RE100-49-8360 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON RE100 ENGINE MODELS			CATEGORY 2			-			
MOC :										
SB RE100-49-8360	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS			CATEGORY 2			-			
MOC :										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB RE100-49-8363 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE INLET HOUSING PN 3810880-1/-2 WITH PN 70724596-1 OR PN 70724596-2, GEARBOX HOUSING PN 3863409-6 WITH PN 70724597-1, GEARBOX HOUSING PN 3863409-5 WITH PN 70724597-2 AND GEARBOX HOUSING PN 3863409-4 WITH PN 70724597-3 ON THE RE100 AUXILIARY POWER UNIT (APU)									
			OPTIONAL			-				
MOC :										
SB RE100-49-8364	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888395-2 WITH PN 3888395-3 ON THE RE100[XL] AUXILIARY POWER UNIT (APU)									
			OPTIONAL			-				
MOC :										
SB RE100-49-8366	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE SPLINE ADAPTER PN 3861055-1 WITH PN 3861055-2 ON THE RE100[XL] AUXILIARY POWER UNIT (APU)									
			CATEGORY 2			-				
MOC :										
SB 560XL-52-13 R01	DOORS - BAGGAGE DOOR HINGE CHANNEL IMPROVEMENT (SUPERSEDED BY 560XL-52-13 R02)									
			SUPERSEDED			-				
MOC :										
SB 560XL-52-13	DOORS - BAGGAGE DOOR HINGE CHANNEL IMPROVEMENT (SUPERSEDED BY 560XL-52-13 R01)									
			SUPERSEDED			-				
MOC :										
SB 560XL-52-14	DOORS - CABIN DOOR REINFORCEMENT MODIFICATION (SUPERSEDED BY 560XL-52-14 R01)									
			SUPERSEDED			-				
MOC :										
SB 560XL-52-15	DOORS - CABIN ENTRY DOOR COUNTERBALANCE SPRING REPLACEMENT (SUPERSEDED BY 560XL-52-15 R01)									
			SUPERSEDED			-				
MOC :										
SB 560XL-52-17 52SB-17 : XL	DOORS - CABIN ENTRY DOOR OPERATION IMPROVEMENT (SUPERSEDED BY 560XL-52-17 R01)									
	SMF		SUPERSEDED	MTH 13-Sep-2008 HRS 485		-				Complete
MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
SB 560XL-52-18	DOORS - AFT BAGGAGE DOOR HINGE MONEL RIVET REPLACEMENT (SUPERSEDED BY 560XL-52-18 R01)									
			SUPERSEDED			-				
MOC :										
SL 560XL-52-10	DOORS - REPLACEMENT OF THE CABIN DOOR PRECATCH HOUSING ASSEMBLY									
			RECOMMENDED				DUE			
MOC :										
SB 560XL-53-13 R01	FUSELAGE - NOSE DRIP CAP BOND INSPECTION									
	KICT		MANDATORY	MTH 22-Oct-2012 HRS 2535.3 LDG 2080			A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION (SUPERSEDED BY 560XL-53-13 R01)									
			MANDATORY	MTH		-				
MOC :										
SB 560XL-53-15	FUSELAGE - FASTENER INSTALLATION F.S. 115.20									
			MANDATORY	MTH			A/R			
MOC :										
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION									
	KICT		MANDATORY	MTH 22-Oct-2012 HRS 2535.3 LDG 2080			A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 560XL-53-08 R01	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION	SMF		MANDATORY	DAYS 14-May-2011 HRS 1750.3 LDG 1460		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-53-01 R01	FUSELAGE - NOSE RADOME GUIDE PIN REPLACEMENT			RECOMMENDED			-			
MOC :										
SL 560XL-53-07 53SL-07 : XL	FUSELAGE - LOWER SKIN ASSEMBLY FASTENER INSPECTION	SMF		MANDATORY	MTH 11-Sep-2009 HRS 885		-			Complete
MOC : COMPLIED WITH										
SL 560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION	KICT		RECOMMENDED	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		-			Complete
MOC : COMPLIED WITH										
SL 560XL-53-20	FUSELAGE - INSTRUMENT PANEL SUPPORT FASTENER VERIFICATION			RECOMMENDED			-			
MOC :										
SL 560XL-55-02	STABILIZERS - REPLACEMENT OF THE RUDDER STOP BLOCK			RECOMMENDED			-			
MOC :										
SL 560XL-55-03 R01	STABILIZERS - INSPECTION OF THE HORIZONTAL STABILIZER UPPER AND LOWER SPLICE PLATE HUCK BOLT FASTENERS			RECOMMENDED			-			
MOC :										
COM MC 560XL- 001	WINDOWS; SURFACE SEAL COATING REFORMULATION			INFORMATIONAL			-			
MOC :										
SL 560XL-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION	SMF		MANDATORY	MTH 26-Sep-2011 HRS 1968.8 LDG 1635		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL-56-03 BY INSPECTING COCKPIT OPENABLE WINDOW HINGE AND LATCHES										
SB 560XL-71-07	POWER PLANT - MOTIVE FLOW FUEL LINE/OIL LINE CLEARANCE IMPROVEMENT (SUPERSEDED BY 560XL-71-07 R01)			SUPERSEDED			-			
MOC :										
SB 560XL-71-11 R01	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION	KICT		OPTIONAL	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		-			Complete
MOC : COMPLIED WITH										
SB 560XL-71-11	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560XL-71-11 R01)			OPTIONAL			-			
MOC :										
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463			OPTIONAL			-			
MOC :										
ASL 560XL-72-19 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	SMF		MANDATORY	MTH 26-Sep-2011 HRS 1968.8 LDG 1635		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL560XL-72-19 TRANSMITTAL OF P&W A30421 R1 BY PERFORMING PART "A" OF BULLETINS ACCOMPLISHMENT INSTRUCTIONS. NO DEFECTS NOTED										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 560XL-72-19 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	SMF		MANDATORY	MTH 26-Sep-2011 HRS 1968.8 LDG 1635		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL560XL-72-19 TRANSMITTAL OF P&W A30421 R1 BY PERFORMING PART "A" OF BULLETINS ACCOMPLISHMENT INSTRUCTIONS. NO DEFECTS NOTED										
SL 560XL-72-13 LEFT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPEINSPECTION OF	KICT		RECOMMENDED	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-13 RIGHT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPEINSPECTION OF	KICT		RECOMMENDED	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-16 72SL-16 : XL	ENGINE - TRANSMITTAL OF PRATT AND WHITNEY CANADA TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30368, TURBOFAN ENGINE INTERCOMPRESSOR BLEEDVALVE SERVO VALVE - INSPECTION	SMF		RECOMMENDED	MTH 11-Sep-2009 HRS 885		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-17 LEFT ENGINE 72SL-17 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	SMF		MANDATORY	MTH 03-May-2011 HRS 1723 LDG 1443		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-17 RIGHT ENGINE 72SL-17 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	SMF		MANDATORY	MTH 03-May-2011 HRS 1723 LDG 1443		A/R			Complete
MOC : COMPLIED WITH										
SB PW300-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW300-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW500-72-30215 R02 E1	MODIFICATION/REWORK OF TURBINE EXHAUST CASE CATEGORY 6						-			
MOC :										
SB PW500-72-30215 R02 E2	MODIFICATION/REWORK OF TURBINE EXHAUST CASE CATEGORY 6						-			
MOC :										
SB PW500-72-30269 R01 E1	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30269 R01 E2	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30270 R01 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30270 R01 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30281 R02 E1	REPLACEMENT OF FUEL NOZZLE GASKET			CATEGORY 6			-			
	MOC :									
SB PW500-72-30281 R02 E2	REPLACEMENT OF FUEL NOZZLE GASKET			CATEGORY 6			-			
	MOC :									
SB PW500-72-30288 R02 E1	MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30288 R02 E2	MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30288 R03 E1	MODIFICATION OF TURBINE CASE ASSEMBLY (THIS SB IS SUPERSEDED BY P&WC S.B. NO. 30284)			SUPERSEDED			-			
	MOC :									
SB PW500-72-30288 R03 E2	MODIFICATION OF TURBINE CASE ASSEMBLY (THIS SB IS SUPERSEDED BY P&WC S.B. NO. 30284)			SUPERSEDED			-			
	MOC :									
SB PW500-72-30294 R02 E1	INSPECTION OF OIL TANK FILLER CAP	UNK		CATEGORY 3	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30296 R03 E1	INSPECTION OF HFC RATIO UNIT SETSCREW ADJUSTMENT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30296 R03 E2	INSPECTION OF HFC RATIO UNIT SETSCREW ADJUSTMENT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30306 R05 E1	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30306 R05 E2	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30309 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30309 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
MOC :										
SB PW500-72-30311 R03 E1	REPLACEMENT OF COMPRESSOR BLEED VALVE ASSEMBLY AND SERVO VALVE			CATEGORY 8			-			
MOC :										
SB PW500-72-30311 R03 E2	REPLACEMENT OF COMPRESSOR BLEED VALVE ASSEMBLY AND SERVO VALVE			CATEGORY 8			-			
MOC :										
SB PW500-72-30323 E1	FAN CASE WITH ADDITIONAL DRAIN HOLES - ON-WING MODIFICATION	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30323 E2	FAN CASE WITH ADDITIONAL DRAIN HOLES - ON-WING MODIFICATION	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R02 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R02 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30331 E1	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING	UNK		CATEGORY 5	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30331 E2	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING	UNK		CATEGORY 5	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30332 R02 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30332 R02 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30332 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30334 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30334 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30335 R01 E1	BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS	UNK		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30335 R01 E2	BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS	UNK		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30336 R01 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30336 R01 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30339 R02 E1	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30339 R02 E2	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30343 R06 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30343 R06 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R01 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30344 R01 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30353 R01 E1	REPLACEMENT OF INTERSHAFT CARBON SEALS	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30353 R01 E2	REPLACEMENT OF INTERSHAFT CARBON SEALS	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30356 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30356 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30362 E1	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30362 E2	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30364 R01 E1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS						-			
	MOC :									
SB PW500-72-30364 R01 E2	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30364 R02 E1	ACCESSORY GEARBOX PLAIN SEALS - REPLACEMENT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R02 E2	ACCESSORY GEARBOX PLAIN SEALS - REPLACEMENT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30369 R01 E1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30369 R01 E2	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30371 R02 E1	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE			CATEGORY 10			-			
	MOC :									
SB PW500-72-30371 R02 E2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE	UNK		CATEGORY 10	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30376 R01 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30376 R01 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30376 R02 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30376 R02 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30384 R01 E1	REPLACEMENT OF AIR/OIL SEPARATOR	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30384 R01 E2	REPLACEMENT OF AIR/OIL SEPARATOR	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30387 R02 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R03)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30387 R02 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R03)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30387 R06 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R06 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30389 E1	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING	UNK		CATEGORY 7	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30389 E2	REPLACEMENT OF CARBON SEAL, NO. 4 BEARING	UNK		CATEGORY 7	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30390 R05 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R08)			CATEGORY 10			-			
MOC :										
SB PW500-72-30390 R05 E2	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R08)			CATEGORY 10			-			
MOC :										
SB PW500-72-30399 E1	REPLACEMENT OF BOLTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30399 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30400 R03 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30400 R03 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30400 R04 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30400 R04 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R03 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R03 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R04 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R04 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R03 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R04)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30405 R03 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R04)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30405 R04 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R04 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET UNK	CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH								
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30409 R09 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)	CATEGORY 7			-			
MOC :								
SB PW500-72-30409 R09 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)	CATEGORY 7			-			
MOC :								
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT UNK	CATEGORY 3	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	CATEGORY 3	MTH		-			
MOC :								
SB PW500-72-30413 R01 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R02)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R01 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R02)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R02 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R03)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R02 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R03)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R03 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R04)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R03 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R04)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R04 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R05)	CATEGORY 6			A/R			
MOC :								
SB PW500-72-30413 R04 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R05)	CATEGORY 6			A/R			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30413 R05 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R06)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R05 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R06)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R06 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R07)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R06 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R07)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R07 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R08)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R07 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R08)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R08 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R09)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R08 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R09)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R09 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R10)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R09 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R10)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R10 E1	INTRODUCTION OF DEEPER SUMP UNK			CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30413 R10 E2	INTRODUCTION OF DEEPER SUMP UNK			CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30413 R11 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R11 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30413 R12 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 R12 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30413 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30415 R01 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R01 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R02 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R02 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R03 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30415 R03 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30415 R04 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R04 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30415 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30416 R01 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30416 R01 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30417 R01 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R02)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R01 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R02)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R02 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R03)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R02 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R03)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R03 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R04)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R03 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R04)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R04 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R05)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R04 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R05)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R05 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R06)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R05 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R06)			CATEGORY 5			A/R			
	MOC :									
SB PW500-72-30417 R06 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R07)			CATEGORY 5			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30417 R06 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R07)	CATEGORY 5			A/R			
MOC :								
SB PW500-72-30417 R07 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R08)	CATEGORY 7			A/R			
MOC :								
SB PW500-72-30417 R07 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R08)	CATEGORY 7			A/R			
MOC :								
SB PW500-72-30417 R08 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING	CATEGORY 10			-			
MOC :								
SB PW500-72-30417 R08 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING	CATEGORY 10			-			
MOC :								
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R01)	CATEGORY 5			A/R			
MOC :								
SB PW500-72-30417 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R01)	CATEGORY 5			A/R			
MOC :								
SB PW500-72-30419 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
MOC :								
SB PW500-72-30419 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
MOC :								
SB PW500-72-30419 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30419 R01)	CATEGORY 7	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30419 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30419 R01)	CATEGORY 7	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30420 R01 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)	CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								
SB PW500-72-30420 R01 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)	CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 2								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30420 R02 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	UNK		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R02 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	UNK		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R03 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R03 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R04 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30420 R04 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30420 R05 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R05 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R06 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R06 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)			CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW500-72-30420 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)			CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW500-72-30423 R01 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30423 R01 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30425 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R02)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R02)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 R02 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30425 R02 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30425 R03 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30425 R03 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30425 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R01)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R01)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30427 R01 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30427 R01 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30427 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R03)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30427 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R04 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30427 R04 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30428 R01 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30428 R01 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30428 R02 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R02 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R03 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30428 R03 E2	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)	UNK		CATEGORY 6	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30428 R04 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R04 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R06 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R06 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R01 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30429 R01 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30429 R02 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30429 R02 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30429 R03 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R03 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R04 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R04 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R05 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R05 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R06 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30429 R06 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30429 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30429 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30432 R01 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 R01 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF (SUPERSEDED BY PW500-72-30432 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF (SUPERSEDED BY PW500-72-30432 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30436 R01 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 R01 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 R02 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R03)	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30436 R02 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R03)	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30436 R03 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R04)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 R03 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R04)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 R04 E1	REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 R04 E2	REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30436 E1	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30436 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30436 E2	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30436 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30440 R01 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30440 R01 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30440 R02 E1	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30440 R02 E2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30440 R03 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 R03 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 R04 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 R04 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 R05 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30440 R05 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30440 R06 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30440 R06 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30440 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R01 E1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R01 E2	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30442 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30442 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 E2	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30446 R01 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30446 R01 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30446 R02 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30446 R02 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30447 R01 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30447 R01 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30449 R01 E1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF (SUPERSEDED BY PW500-72-30449 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R01 E2	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF (SUPERSEDED BY PW500-72-30449 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R02 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R02 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY (SUPERSEDED BY PW500-72-30449 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30449 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY (SUPERSEDED BY PW500-72-30449 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30453 R01 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R01 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30453 R02 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R02 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30455 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30455 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30455 R05 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 R05 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30455 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30457 R01 E1	INSPECTION/REPLACEMENT OF FUEL MANIFOLDS			CATEGORY 10			-			
	MOC :									
SB PW500-72-30457 R01 E2	INSPECTION/REPLACEMENT OF FUEL MANIFOLDS			CATEGORY 10			-			
	MOC :									
SB PW500-72-30457 E1	INSPECTION/REPLACEMENT FUEL MANIFOLDS (SUPERSEDED BY PW500-72-30457 R01)	ICT		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
	MOC :									
SB PW500-72-30457 E2	INSPECTION/REPLACEMENT FUEL MANIFOLDS (SUPERSEDED BY PW500-72-30457 R01)	ICT		CATEGORY 3	MTH 09-Oct-2012 HRS 2584.8 LDG 2110		-			Complete
	MOC :									
SB PW500-72-30462 R01 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R02)			CATEGORY 8			-			
	MOC :									
SB PW500-72-30462 R01 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R02)			CATEGORY 8			-			
	MOC :									
SB PW500-72-30462 R02 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161			CATEGORY 8			-			
	MOC :									
SB PW500-72-30462 R02 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161			CATEGORY 8			-			
	MOC :									
SB PW500-72-30462 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R01)			CATEGORY 8			-			
	MOC :									
SB PW500-72-30462 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R01)			CATEGORY 8			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30463 R01 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R02) CATEGORY 7				-			
	MOC :							
SB PW500-72-30463 R01 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R02) CATEGORY 7				-			
	MOC :							
SB PW500-72-30463 R02 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30463 R02 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R01) CATEGORY 7				-			
	MOC :							
SB PW500-72-30463 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R01) CATEGORY 7				-			
	MOC :							
SB PW500-72-30464 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS CATEGORY 7				-			
	MOC :							
SB PW500-72-30464 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 R01 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02) CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 R01 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02) CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 R02 E1	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 R02 E2	REPLACEMENT OF FUEL MANIFOLD TUBES CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01) CATEGORY 7				-			
	MOC :							
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01) CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30466 R01 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R02)	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30466 R01 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R02)	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30466 R02 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 R02 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 E1	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 E2	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 R01 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 R01 E2	REPLACEMENT OF DATA COLLECTION UNIT	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30470 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R01 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R01 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R02 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R02 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART A E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART A E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART B E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART B E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30479 R01 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R02)			CATEGORY 5			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30479 R01 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R02)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R02 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R03)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R02 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R03)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R03 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R04)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R03 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R04)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R04 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R05)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R04 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R05)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R05 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R06)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R05 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R06)			CATEGORY 5			-			
MOC :										
SB PW500-72-30479 R06 E1	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE	UNK		CATEGORY 3	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30479 R06 E2	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE	UNK		CATEGORY 3	MTH 05-Apr-2018 HRS 5032.1 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30479 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30479 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30482 R01 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R02)			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30482 R01 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R02)	CATEGORY 3			-			
MOC :								
SB PW500-72-30482 R02 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R03) SMF	CATEGORY 3	MTH 04-Sep-2014 HRS 3778 LDG 3095		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PWC SB # 30482R2 BY COMPLETING BORESCOPE INSPECTION OF THE SELF LOCKING NUTS ON THE COMBUSTION LINER COOLING RING SEGMENTS, FOUND ALL NUTS SECURE (CONDITION A). POSTMAINTENANCE OPERATIONAL AND LEAK CHECKS NORMAL.								
SB PW500-72-30482 R02 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R03) SMF	CATEGORY 3	MTH 04-Sep-2014 HRS 3778 LDG 3095		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PWC SB # 30482R2 BY COMPLETING BORESCOPE INSPECTION OF THE SELF LOCKING NUTS ON THE COMBUSTION LINER COOLING RING SEGMENTS, FOUND ALL NUTS SECURE (CONDITION A). POSTMAINTENANCE OPERATIONAL AND LEAK CHECKS NORMAL.								
SB PW500-72-30482 R03 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R02)	CATEGORY 10			-			
MOC :								
SB PW500-72-30482 R03 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R02)	CATEGORY 10			-			
MOC :								
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R01)	CATEGORY 3			-			
MOC :								
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R01)	CATEGORY 3			-			
MOC :								
SB PW500-72-30483 R01 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30483 R01 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30483 R02 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R03)	CATEGORY 7			-			
MOC :								
SB PW500-72-30483 R02 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R03)	CATEGORY 7			-			
MOC :								
SB PW500-72-30483 R03 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02)	CATEGORY 10			-			
MOC :								
SB PW500-72-30483 R03 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02)	CATEGORY 10			-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R01) MOC :	CATEGORY 7			-			
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R01) MOC :	CATEGORY 7			-			
SB PW500-72-30485 R01 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-3048 R02) MOC :	CATEGORY 7			-			
SB PW500-72-30485 R01 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-3048 R02) MOC :	CATEGORY 7			-			
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE MOC :	CATEGORY 7			-			
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE MOC :	CATEGORY 7			-			
SB PW500-72-30486 R01 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R02) MOC :	CATEGORY 7			-			
SB PW500-72-30486 R01 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R02) MOC :	CATEGORY 7			-			
SB PW500-72-30486 R02 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING. MOC :	CATEGORY 7			-			
SB PW500-72-30486 R02 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING. MOC :	CATEGORY 7			-			
SB PW500-72-30486 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R01) MOC :	CATEGORY 7			-			
SB PW500-72-30486 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R01) MOC :	CATEGORY 7			-			
SB PW500-72-30487 R03 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502) MOC :	CATEGORY 10			-			
SB PW500-72-30487 R03 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502) MOC :	CATEGORY 10			-			
SB PW500-72-30487 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30487 R01) MOC :				-			



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30487 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30487 R01)				-			
MOC :								
SB PW500-72-30491 R01 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30491 R01 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30491 R02 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY	UNK CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30491 R02 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY	UNK CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30491 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R01)	CATEGORY 7			-			
MOC :								
SB PW500-72-30491 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R01)	CATEGORY 7			-			
MOC :								
SB PW500-72-30492 R01 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30492 R01 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)	CATEGORY 7			-			
MOC :								
SB PW500-72-30492 R02 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)	CATEGORY 7			-			
MOC :								
SB PW500-72-30492 R02 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)	CATEGORY 7			-			
MOC :								
SB PW500-72-30492 R03 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)	CATEGORY 6			-			
MOC :								
SB PW500-72-30492 R03 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)	CATEGORY 6			-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30492 R04 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30492 R04 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30495 R01 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 R01 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30496 R01 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6			-			
MOC :										
SB PW500-72-30496 R01 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6			-			
MOC :										
SB PW500-72-30496 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE (SUPERSEDED BY PW500-72-30496 R01)	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30496 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE (SUPERSEDED BY PW500-72-30496 R01)	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30498 R01 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30498 R01 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30498 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R02 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R02 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R02 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R02 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30502 R02 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30502 R02 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R03 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 R04 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)	CATEGORY 7			-			
MOC :								
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)	CATEGORY 7			-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30504 R01 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02) CATEGORY 7				-			
MOC :								
SB PW500-72-30504 R01 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02) CATEGORY 7				-			
MOC :								
SB PW500-72-30504 R02 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER UNK CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896			-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30504 R02 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7				-			
MOC :								
SB PW500-72-30504 R03 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7				-			
MOC :								
SB PW500-72-30504 R03 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER CATEGORY 7				-			
MOC :								
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01) CATEGORY 7				-			
MOC :								
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01) CATEGORY 7				-			
MOC :								
SB PW500-72-30505 R01 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02) CATEGORY 3				-			
MOC :								
SB PW500-72-30505 R01 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02) CATEGORY 3				-			
MOC :								
SB PW500-72-30505 R02 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS UNK CATEGORY 3	MTH 03-Apr-2018 HRS 5032.1 LDG 3896			-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30505 R02 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS UNK CATEGORY 3	MTH 05-Apr-2018 HRS 5032.1 LDG 3896			-			Complete
MOC : COMPLIED WITH								
SB PW500-72-30505 R03 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3				-			
MOC :								
SB PW500-72-30505 R03 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30505 R04 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
	MOC :									
SB PW500-72-30505 R04 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS CATEGORY 3						-			
	MOC :									
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01) CATEGORY 3						-			
	MOC :									
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01) CATEGORY 3						-			
	MOC :									
SB PW500-72-30506 R01 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02) CATEGORY 7						-			
	MOC :									
SB PW500-72-30506 R01 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02) CATEGORY 7						-			
	MOC :									
SB PW500-72-30506 R02 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30506 R02 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01) CATEGORY 7						-			
	MOC :									
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01) CATEGORY 7						-			
	MOC :									
SB PW500-72-30507 E1	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY UNK CATEGORY 8				MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30507 E2	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 8						-			
	MOC :									
SB PW500-72-30508 R01 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R02) CATEGORY 7						-			
	MOC :									
SB PW500-72-30508 R01 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R02) CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30508 R02 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30508 R02 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30508 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R04 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R04 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30511 R01 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R01 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R02 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R02 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30512 R01 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)	MHR		CATEGORY 3	MTH 28-Mar-2015 HRS 4153.7 LDG 3429		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30512 IS NOT APPLICABLE DUE TO HFC NOT POST SB30442 AND P/N INSTALLED: 1012636-5. NO ACTION REQUIRED.										
SB PW500-72-30512 R01 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)	MHR		CATEGORY 3	MTH 28-Mar-2015 HRS 4153.7 LDG 3429		-			N/A
MOC : NOT APPLICABLE - SB PW500-72-30512 IS NOT APPLICABLE DUE TO HFC NOT POST SB30442 AND P/N INSTALLED: 1012636-5. NO ACTION REQUIRED.										
SB PW500-72-30512 R02 E1	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 R02 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 R03 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)	UNK		CATEGORY 3	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30512 R03 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)	UNK		CATEGORY 3	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30512 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3			-			
MOC :										
SB PW500-72-30516 R01 E1	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R01 E2	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E1	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E2	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30517 R01 E1	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30517 R01 E2	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30518 E1	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
MOC :										
SB PW500-72-30518 E2	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
MOC :										
SB PW500-72-30521 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30521 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30523 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
MOC :										
SB PW500-72-30523 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
MOC :										
SB PW500-72-30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30526 R01 E1	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30526 R01 E2	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30526 E1	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30526 E2	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30534 R01 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R01 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R02 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R02 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R03 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R04)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R03 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R04)	UNK		CATEGORY 7	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30534 R04 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 R04 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30534 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R01)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER CATEGORY 7				-			
	MOC :							
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER CATEGORY 7				-			
	MOC :							
SB PW500-72-30535 R02 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER CATEGORY 7				-			
	MOC :							
SB PW500-72-30535 R02 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER CATEGORY 7				-			
	MOC :							
SB PW500-72-30535 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01) CATEGORY 7				-			
	MOC :							
SB PW500-72-30535 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01) CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R01 E1	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R01 E2	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R02 E1	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R02 E2	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R03 E1	REPLACEMENT OF HIGH-PRESSURE-TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 R03 E2	REPLACEMENT OF HIGH-PRESSURE-TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 E1	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30540 E2	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL CATEGORY 7				-			
	MOC :							
SB PW500-72-30541 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) FUEL CONTROL GEARSHAFT SEAL CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30541 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30541 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30542 E1	REPLACEMENT OF IGNITER CABLES	CATEGORY 7			-			
	MOC :							
SB PW500-72-30542 E2	REPLACEMENT OF IGNITER CABLES	CATEGORY 7			-			
	MOC :							
SB PW500-72-30543 R01 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS	CATEGORY 7			-			
	MOC :							
SB PW500-72-30543 R01 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS	CATEGORY 7			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30543 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS (SUPERSEDED BY PW500-72-30543 R01) CATEGORY 7						-			
	MOC :									
SB PW500-72-30543 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS (SUPERSEDED BY PW500-72-30543 R01) CATEGORY 7						-			
	MOC :									
SB PW500-72-30545 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									
SB PW500-72-30545 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									
SB PW500-72-30545 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									
SB PW500-72-30545 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									
SB PW500-72-30545 R03 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3						-			
	MOC :									
SB PW500-72-30545 R03 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3						-			
	MOC :									
SB PW500-72-30545 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3				MTH 12-Aug-2022 HRS 5959.6 LDG 4366		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30545 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 3				MTH 12-Aug-2022 HRS 5959.6 LDG 4366		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30546 R01 E1	REPLACEMENT OF HPT AIR SEAL CATEGORY 9						-			
	MOC :									
SB PW500-72-30546 R01 E2	REPLACEMENT OF HPT AIR SEAL CATEGORY 9						-			
	MOC :									
SB PW500-72-30546 R02 E1	REPLACEMENT OF HPT AIR SEAL CATEGORY 9						-			
	MOC :									
SB PW500-72-30546 R02 E2	REPLACEMENT OF HPT AIR SEAL CATEGORY 9						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30546 E1	REPLACEMENT OF HPT AIR SEAL	CATEGORY 9			-			
	MOC :							
SB PW500-72-30546 E2	REPLACEMENT OF HPT AIR SEAL	CATEGORY 9			-			
	MOC :							
SB PW500-72-30548 R01 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30548 R01 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30548 R02 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30548 R02 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30548 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30548 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 PART A E1	ACCOMPLISH REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS REPLACE THE FRONT NO. 4 BEARING SEAL RUNNER WITH A NEW ONE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 PART A E2	ACCOMPLISH REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS REPLACE THE FRONT NO. 4 BEARING SEAL RUNNER WITH A NEW ONE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 PART B E1	ACCOMPLISH REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS REPLACE THE REAR NO. 4 BEARING SEAL RUNNER WITH A NEW ONE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 PART B E2	ACCOMPLISH REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS REPLACE THE REAR NO. 4 BEARING SEAL RUNNER WITH A NEW ONE	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 E1	REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS	CATEGORY 7			-			
	MOC :							
SB PW500-72-30550 E2	REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS	CATEGORY 7			-			
	MOC :							
SB PW500-72-30554 R01 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	CATEGORY 7			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30554 R01 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30554 R02 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30554 R02 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30562 R01 E1	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 R01 E2	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 R02 E1	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 R02 E2	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 R03 E1	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 R03 E2	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 E1	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30562 E2	REPLACEMENT OF MIXER ASSEMBLY			CATEGORY 9			-			
	MOC :									
SB PW500-72-30564 R01 E1	REPLACEMENT OF LOCKBOLT COLLAR			CATEGORY 9			-			
	MOC :									
SB PW500-72-30564 R01 E2	REPLACEMENT OF LOCKBOLT COLLAR			CATEGORY 9			-			
	MOC :									
SB PW500-72-30564 R02 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30564 R02 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30564 R03 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE CATEGORY 7						-			
	MOC :									
SB PW500-72-30564 R03 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE CATEGORY 7						-			
	MOC :									
SB PW500-72-30564 E1	REPLACEMENT OF LOCKBOLT COLLAR CATEGORY 9						-			
	MOC :									
SB PW500-72-30564 E2	REPLACEMENT OF LOCKBOLT COLLAR CATEGORY 9						-			
	MOC :									
SB PW500-72-30565 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 6						-			
	MOC :									
SB PW500-72-30565 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 6						-			
	MOC :									
SB PW500-72-30565 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30565 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30567 E1	INSPECTION OF TURBOFAN ENGINE ENGINE ELECTRONIC CONTROL (EEC) CATEGORY 6						-			
	MOC :									
SB PW500-72-30567 E2	INSPECTION OF TURBOFAN ENGINE ENGINE ELECTRONIC CONTROL (EEC) CATEGORY 6						-			
	MOC :									
SB PW500-72-30568 R01 E1	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30568 R01 E2	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30568 E1	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30568 E2	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7						-			
	MOC :									
SB PW500-72-30572 R01 E1	INSPECTION/MODIFICATION OF HP TURBINE DISK CATEGORY 3						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30572 R01 E2	INSPECTION/MODIFICATION OF HP TURBINE DISK			CATEGORY 3			-			
	MOC :									
SB PW500-72-30572 E1	INSPECTION OF HP TURBINE DISK			CATEGORY 5			-			
	MOC :									
SB PW500-72-30572 E2	INSPECTION OF HP TURBINE DISK			CATEGORY 5			-			
	MOC :									
ASB PW500-72-A30421 R02 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
	MOC :									
ASB PW500-72-A30421 R02 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
	MOC :									
ASB PW500-72-A30452 R01 E1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R02)			CATEGORY 3	MTH		-			
	MOC :									
ASB PW500-72-A30452 R01 E2	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R02)			CATEGORY 3	MTH		-			
	MOC :									
ASB PW500-72-A30452 R02 E1	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30452 R02 E2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30452 E1	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R01)			CATEGORY 3			-			
	MOC :									
ASB PW500-72-A30452 E2	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R01)			CATEGORY 3			-			
	MOC :									
SL 560XL-73-12 73SL-12 : XL	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVERPLATE/FAIRING/REPLACEMENT OF (SUPERSEDED BY SL560XL-73-12 R01)			RECOMMENDED	MTH 07-Jan-2010 HRS 996		A/R			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30409 R06 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)	SMF		CATEGORY 3	MTH 03-May-2011 HRS 1772.5 LDG 1480		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30409 R06 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)	SMF		CATEGORY 3	MTH 03-May-2011 HRS 1772.5 LDG 1480		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30565 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
MOC :										
SB PW500-72-30565 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
MOC :										
SB PW500-72-30343 R05 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30343 R05 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R03 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R03 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
SB PW500-72-30414 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
ASB PW500-72-A30421 R01 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	KMHR		CATEGORY 3	MTH 01-Dec-2010 HRS 1547 LDG 1310		-			N/A
MOC : NOT APPLICABLE - DETERMINED LEFT AND RI9HT ENGINES NOT APPLICABLE BY PWC S8 PW500-72-A30421 EMBODIMENT AND TIME IN SERVICE. NO FURTHER ACTION REQUIRED.										
ASB PW500-72-A30421 R01 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	KMHR		CATEGORY 3	MTH 01-Dec-2010 HRS 1547 LDG 1310		-			N/A
MOC : NOT APPLICABLE - DETERMINED LEFT AND RI9HT ENGINES NOT APPLICABLE BY PWC S8 PW500-72-A30421 EMBODIMENT AND TIME IN SERVICE. NO FURTHER ACTION REQUIRED.										
ASB PW500-72-A30421 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)	KMHR		CATEGORY 3	MTH 24-Aug-2010 HRS 1372.2 LDG 1168		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AIRWORTHINESS DIRECTIVE BY RECORDS REVIEW AND DETERMINED SUBJECT PART NUMBER BOV NOT INSTALLED. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW500-72-A30421 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)									
		KMHR		CATEGORY 3	MTH 24-Aug-2010 HRS 1372.2 LDG 1168		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AIRWORTHINESS DIRECTIVE BY RECORDS REVIEW AND DETERMINED SUBJECT PART NUMBER BOV NOT INSTALLED. NO FURTHER ACTION REQUIRED										
SB 560XL-76-04	ENGINE CONTROLS - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN30434 TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL/REPLACEMENT-MODIFICATION ANDP&WC SERVICE BULLETIN 30438 TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT/MODIFICATIONS OF									
				RECOMMENDED			A/R			
MOC :										
SL 560XL-76-04 R01	ENGINE CONTROLS - THROTTLE QUADRANT RVDLT LINKAGE INSPECTION									
		KSAT		MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE										
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION									
				INFORMATIONAL			-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS									
				CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
				CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
				CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
				CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2008-06-28 R01	APPLIANCE AD - TIME LIMITATIONS - CHECK OF THE MAINTENANCE RECORDS AND INSPECTION OF THE PFD (IF NECESSARY) TO DETERMINE IF AN AFFECTED SERIAL NUMBER PFD IS INSTALLED (SUPERSEDED BY FAA AD 2009-05-05)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (G) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (H) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (I) AND (J) DO NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (K) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (L) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2013-09-11 PARA (M) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	KSAT MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2013-09-11 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2008-02-06 PARA (E)(1)	CHECK THE SERIAL TAG OF THE INSTALLED GSM 85 SERVO GEARBOX UNIT TO DETERMINE THE MOD LEVEL	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
FAA 2008-02-06 PARA (E)(2)	INSPECT THE SERVO GEARBOX FOR FOREIGN OBJECT DEBRIS (IF THE SERIAL TAG ON THE GSM 85 SERVO GEARBOX FOR P/NS SPECIFIED IN PARA (E)(1) IS NOT MARKED AT MOD LEVEL 1 OR MOD LEVEL 3)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
FAA 2008-02-06 PARA (E)(3)	REMOVE AND RETURN THE GSM 85 SERVO GEARBOX TO THE MANUFACTURER FOR REPLACEMENT (IF FOREIGN OBJECT DEBRIS IS FOUND DURING THE INSPECTION REQUIRED IN PARA (E)(2))	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
FAA 2008-02-06	APPLIANCE AD - AUTO FLIGHT - INSPECT THE GSM 85 SERVO GEARBOX FOR FOREIGN OBJECT DEBRIS AND RETURN THE UNIT TO THE MANUFACTURER FOR REPLACEMENT IF YOU FIND DEBRIS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED								
FAA 2006-19-04 34AD-14 : XL	APPLIANCE AD - HONEYWELL RCZ COMM & XPDRS ICT	MANDATORY	MTH 16-Sep-2007 HRS 9		A/R			N/A
MOC : NOT APPLICABLE								
FAA 2013-18-09	APPLIANCE/EMERGENCY AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC (SUPERSEDED BY FAA AD 2014-17-02)	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS	MANDATORY	DAYS 28-Mar-2017 HRS 4728.3 LDG 3770		-			Complete
MOC : COMPLIED WITH								
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION	MANDATORY	DAYS 28-Mar-2017 HRS 4728.3 LDG 3770		-			Complete
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES	KFXE		MANDATORY	MTH 28-Mar-2017 HRS 4728.3 LDG 3770 APUH 1840.5 APUS 3430		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2017-04-14. INSPECTED AREA AS REFERENCED IN TEXTRON AVIATION SL560XL-24-07. NOTICED SLIGHT CHAFFING ON FUEL TUBE ASSEMBLY P/N 66166110-30 WELL WITHIN LIMITS 0.002" AS PER PARA. 3A(1) OF SERVICE LETTER. INSPECTED GENERATOR WIRING AND FOUND SLIGHT CHAFFING ON WIRE IDENTIFICATION TAG. REPAIRED AS REQUIRED IAW PARA. 3B(1) OF SERVICE LETTER. ROUTED WIRE BUNDLE AS PER PARA. 3(C) VIEW A-A OF SERVICE LETTER. NO FURTHER ACTION REQUIRED.										
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION			MANDATORY	MTH 27-Sep-2021 HRS 5618 LDG 4146		1000		6618	Complete 196.4
MOC : COMPLIED WITH										
FAA 2007-19-12	APPLIANCE AD - SICMA AERO SEATS - 50XXX			AIRWORTHINESS	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2007-19-13	APPLIANCE AD - B/E AEROSPACE SKYLUXE SEATS			AIRWORTHINESS	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2010-02-06	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECTIONS / REPLACEMENT OF CENTRAL SPREADERS, ALL APPLICABLE CORRECTIVE ACTIONS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2011-12-01 PARA (G)(1)	DETERMINE IF THE SEATS ARE COMPLIANT WITH 14 CFR 25.561(B)(3)(II) AND 14 CFR 25.561(B)(3)(III) FOR KOITO INDUSTRIES, LTD., SEATS APPROVED UNDER TSO-C39B OR TSO-C39C IF NOT REMOVE THE NON-COMPLIANT SEATS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2011-12-01 PARA (G)(2)	DETERMINE IF THE SEATING SYSTEMS ARE COMPLIANT FOR KOITO INDUSTRIES, LTD., SEATING SYSTEMS APPROVED UNDER TSO-C127A IF NOT REMOVE THE NON-COMPLIANT SEATING SYSTEMS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2011-12-01 PARA (G)(3)	DETERMINE IF THE SEATING SYSTEMS ARE COMPLIANT WITH 14 CFR 25.561(B)(3)(II) AND 14 CFR 25.561(B)(3)(III) FOR KOITO INDUSTRIES, LTD., SEATING SYSTEMS APPROVED UNDER TSO-C127A IF NOT REMOVE THE NON-COMPLIANT SEATING SYSTEMS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2011-12-01 PARA (G)(4)	DETERMINE IF THE SEAT BOTTOM CUSHION ASSEMBLY AND SEAT BACK CUSHION ASSEMBLY ARE SHOWN TO BE COMPLIANT WITH 14 CFR 25.853(C) FOR KOITO INDUSTRIES, LTD., SEATS APPROVED UNDER TSO-C39B OR TSO-C39C AND COMPONENTS OF SEATING SYSTEMS APPROVED UNDER TSO -C127A REMOVE AS NEEDED			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2011-12-01 PARA (H)(1)	REMOVE THE NON-COMPLIANT SEATING SYSTEMS FOR SEATING SYSTEMS THAT ARE SHOWN TO BE COMPLIANT WITH 14 CFR 25.562(B)(2), AND 14 CFR 25.562(C)(7)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-12-01 PARA (H)(2)	REMOVE ANY SEATING SYSTEMS ARE NOT SHOWN TO BE COMPLIANT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-12-01	APPLIANCE AD - EQUIPMENT/FURNISHINGS - DETERMINING IF AFFECTED SEATS AND SEATING SYSTEMS AND THEIR COMPONENTS ARE COMPLIANT WITH CERTAIN FAA REGULATIONS, AND REMOVING THOSE SEATS, SEATING SYSTEMS, AND THEIR COMPONENTS THAT ARE SHOWN TO BE UNSAFE FROM THE AFFECTED FLEET	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-21-08 PARA (F)(1)	GENERAL VISUAL INSPECTION OF THE BACKREST LINKS HAVING P/NS 90-000200-104-1 AND 90-000200-104-2	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-21-08 PARA (F)(2)	REPLACE BOTH BACKREST LINKS OF THE AFFECTED SEAT WITH NEW, IMPROVED BACKREST LINKS HAVING P/NS 90-100200-104-1 AND 90-100200-104-2 (IF, DURING THE INSPECTION REQUIRED BY PARA (F)(1), CRACKING IS FOUND BETWEEN THE SIDE OF THE BACKREST LINK AND THE LOCK-OUT PIN HOLE BUT THE CRACKING DOES NOT PASS THIS LOCK-OUT PIN HOLE)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-21-08 PARA (F)(3)	REPLACE BOTH BACKREST LINKS OF THE AFFECTED SEAT WITH NEW, IMPROVED BACKREST LINKS HAVING P/NS 90-100200-104-1 AND 90-100200-104-2 (IF, DURING THE INSPECTION REQUIRED BY PARA (F)(1), CRACKING IS FOUND THAT PASSES BEYOND THE LOCK-OUT PIN HOLE)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-21-08 PARA (F)(5)	REPLACE THE LINKS, P/NS 90-000200-104-1 AND 90-000200-104-2, WITH NEW IMPROVED LINKS, P/NS 90-100200-104-1 AND 90-100200-104-2 (IF NO CRACKING IS FOUND DURING THE INSPECTION REQUIRED BY PARA (F)(1))	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2011-21-08	APPLIANCE AD - EQUIPMENT/FURNISHINGS - TO IDENTIFY AND CORRECT AN UNSAFE CONDITION FOR SICMA AERO SEAT 88XX, 89XX, 90XX, 91XX, 92XX, 93XX, 95XX, AND 96XX SERIES PASSENGER SEAT ASSEMBLIES	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2011-23-06 PARA (G)	PERFORM A DETAILED INSPECTION FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS / REPAIR THE AFFECTED SPREADER (IF ALL CRACKS FOUND ON ANY CENTRAL SPREADER ARE SHORTER THAN 8 MM (0.315 INCH)) / REPLACE (IF ONE OR MORE CRACKS ARE FOUND THAT ARE 8 MM (0.315 INCH) OR LONGER ON ANY LATERAL OR CENTRAL SPREADER)							
		MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2011-23-06 PARA (H)	TERMINATING ACTION REPLACING ALL CENTRAL AND LATERAL SPREADERS ON AN AFFECTED SEAT ASSEMBLY (MODIFY TO "AMENDMENT B" STANDARD), IN ACCORDANCE WITH PARAGRAPHS 2/A THROUGH D2. OF THE ACCOMPLISHMENT INSTRUCTIONS OF SICMA AERO SEAT SERVICE BULLETIN 94-25-012, REVISION 1, DATED JUNE 26, 2008, TERMINATES THE INSPECTIONS REQUIRED BY THIS AD FOR THAT SEAT ASSEMBLY							
		MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2011-23-06	APPLIANCE AD - REPETITIVE [DETAILED] INSPECTIONS OF THE AFFECTED SEATS AND DEPENDING ON FINDINGS, THE REPAIR OR REPLACEMENT OF DAMAGED SPREADERS WITH AN IMPROVED DESIGN							
		MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2012-08-07	APPLIANCE AD - EQUIPMENT/FURNISHINGS - REPETITIVE DETAILED INSPECTIONS FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS, AND REPAIR OR REPLACEMENT OF THE SPREADER IF NECESSARY							
		MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2014-20-11	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT (SUPERSEDED BY 2015-10-02)							
		MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2							
	KMCO	MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 DATED JUNE, 12,2015 IS N/A DUE TO ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK							
	KMCO	MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 DATED JUNE, 12,2015 IS N/A DUE TO ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS							
	KMCO	MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 DATED JUNE, 12,2015 IS N/A DUE TO ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KMCO		MANDATORY	MTH 20-Aug-2015 HRS 4301.8 LDG 3582		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-02 DATED JUNE, 12,2015 IS N/A DUE TO ZODIAC SEATS ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD NA AFFECTED EQUIPMENT NOTINSTALLED										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KFXE			MTH 16-Oct-2018 HRS 5143.1 LDG 3943		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KFXE		MANDATORY	MTH 16-Oct-2018 HRS 5143.1 LDG 3943		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KFXE		MANDATORY	MTH 16-Oct-2018 HRS 5143.1 LDG 3943		-			N/A
MOC : NOT APPLICABLE - VERIFIED AD NOT APPLICABLE BY AIRCRAFT NOT EQUIPPED WITH AMERI-KING ELT. NO FURTHER ACTION REQUIRED.										
FAA 2017-16-04 (1)(II)	REPLACE THE BUCKLE ASSEMBLY WITH A BUCKLE ASSEMBLY NOT IDENTIFIED IN PARAGRAPH (A) OF THIS AD AND PLACARD THE SEAT AS PARA (E)(1)(I) & (E) INOPERATIVE IF THE STRAPS DO NOT RELEASE FROM BUCKLE ASSEMBLY			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY AD 2020 ₀₉ 02										
FAA 2017-16-04 PARA (E)(1)	INSPECT EACH RESTRAINT SYSTEM FOR CORRECT OPERATION			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY AD 2020 ₀₉ 02										
FAA 2017-16-04 PARA (E)(2)	DO NOT INSTALL A RESTRAINT SYSTEM WITH A BUCKLE ASSEMBLY IDENTIFIED IN PARAGRAPH (A) OF THIS AD ON ANY HELICOPTER			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY AD 2020 ₀₉ 02										
FAA 2017-16-04	APPLIANCE AD - ROMTEX ANJOU AERONAUTIQUE (ROMTEX) TORSO RESTRAINT SYSTEMS ROTARY BUCKLE ASSEMBLY INSPECTION AND REPLACEMENT			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY AD 2020 ₀₉ 02										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-22-02 PARA (F)	MODIFY AND RE-IDENTIFY AFFECTED EACH PILOT AND CO-PILOT SEAT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2017-22-02 PARA (G)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE SEAT IS MODIFIED AND REIDENTIFIED AS SPECIFIED IN PARAGRAPH (F)(2) OF THIS AD	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2017-22-02	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2018-16-01 PARA (G)	REVIEW EACH AFFECTED ATTENDANT SEAT NG AND PILOT SEAT 120/335, REMOVE AND REPLACE THE EA ASSEMBLIES ON EACH AFFECTED PILOT SEAT, AND REMOVE EACH AFFECTED ATTENDANT SEAT AND REPLACE WITH A REWORKED SEAT IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-16-01 PARA (H)	DO NOT INSTALL AN AFFECTED SEAT ON AN AIRCRAFT UNLESS, PRIOR TO INSTALLATION, THE EAASSEMBLIES ON THE SEAT HAVE BEEN REPLACED IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-09-02 PARA (G)(1)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY (FOR THE RESTRAINT SYSTEMS LISTED IN THE EFFECTIVITY OF ANJOU AERO SB 358SB-14-101 R01, EXCEPT FOR S/NS 1038-1048 (INCLUSIVE), 1050-1055 (INCLUSIVE), AND 1062-1073 (INCLUSIVE))	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-09-02 PARA (G)(2)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE RESTRAINT SYSTEM FROM SERVICE (FOR RESTRAINT SYSTEMS, P/N 358XX-XXX-YY-ZZZ (WHERE 358XX-XXX-YY-ZZZ CAN BE ANY COMBINATION OF NUMBERS AND/OR LETTERS), HAVING S/NS 738-1619 (INCLUSIVE))	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2020-09-02 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN ANJOU AERONAUTIQUE RESTRAINT SYSTEM, P/N 358XX-XXX-YY-ZZZ, HAVING S/NS 738-1619 (INCLUSIVE), EVEN IF THE RESTRAINT SYSTEM IS LABELED IN COMPLIANCE WITH ANJOU AERO SB 358SB-14-101 R01, DATED DECEMBER 12, 2014		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-09-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REPLACEMENT		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KSAT	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
MOC : NOT APPLICABLE - AD2021-07-13 PARA (E)(1) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KSAT	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
MOC : NOT APPLICABLE - AD2021-07-13 PARA (E)(2) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	KSAT	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
MOC : NOT APPLICABLE - AD2021-07-13 PARA (E)(3) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT		MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
		MANDATORY						
	KSAT							
MOC : NOT APPLICABLE - AD2021-07-13 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2006-04-10	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
		MANDATORY						
MOC : NOT APPLICABLE - SUPERSEDED BY AD 2007-11-17								
FAA 2007-11-17	FIRE PROTECTION - INSTALLATION OF IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE TERMINAL STUDS OF THE APPLICABLE FIRE EXTINGUISHING BOTTLES		MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			Complete
		MANDATORY						
MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER			MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-19-05 PARA (F)(1)	INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED			MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-19-05 PARA (F)(2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-19-05 PARA (F)(2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-19-05 PARA (F)(3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-19-05 PARA (G)	DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2017-19-05	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-21-02 PARA (H) & (I)	DO AN INSPECTION TO DETERMINE THE PART NUMBER AND SERIAL NUMBER OF THE CARGO FIRE EXTINGUISHER HALON BOTTLES INSTALLED IN THE CARGO COMPARTMENT AND REPLACE WITH A SERVICEABLE PART AS REQUIRED	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-21-02 PARA (J)	NO PERSON MAY INSTALL ON ANY AIRPLANE AN AFFECTED PART AS IDENTIFIED IN PARAGRAPH (G)(3) OF THIS AD UNLESS THAT PART HAS A CIRCLED LETTER "G" STAMPED AT A DISTANCE 8 OF APPROXIMATELY ONE INCH FROM THE LEFT EDGE OF THE PLACARD, INDICATING THAT THE CARGO FIRE EXTINGUISHER HALON BOTTLE HAS BEEN TESTED AND REFILLED	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOTINSTALLED.								
FAA 2021-22-07	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT	MANDATORY	DAYS 18-Nov-2021 HRS 5717.7 LDG 4217		-			N/A
MOC : NOT APPLICABLE - FOUND TO BE NOTAPPLICABLE DUE TO AFFECTED PARTS NOTINSTALLED. NO FURTHER ACTION REQUIRED								
FAA 2000-15-51	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - TO AIRCRAFT SERIAL NUMBER								
FAA 2009-05-05	APPLIANCE AD - INDICATING AND RECORDING - CHECK OF THE MAINTENANCE RECORDS AND INSPECTION OF THE PFD (IF NECESSARY) TO DETERMINE IF AN AFFECTED SERIAL NUMBER PFD IS INSTALLED AND INCORPORATE (IF NECESSARY) OPERATIONAL LIMITATIONS.	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	MANDATORY	MTH 21-Dec-2021 HRS 5778.9 LDG 4253		-			Complete
MOC : COMPLIED WITH - NO FURTHER ACTION REQUIRED								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)	KJVL		MANDATORY	MTH 27-Jul-2023 HRS 6170.3 LDG 4480		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA 2023-10-02 IN ACCORDANCE WITH FAA 2023-10-02 PARAGRAPH (I). NO FURTHER ACTION REQUIRED.										
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	KJVL		MANDATORY	MTH 27-Jul-2023 HRS 6170.3 LDG 4480		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA 2023-10-02 IN ACCORDANCE WITH FAA 2023-10-02 PARAGRAPH (I). NO FURTHER ACTION REQUIRED.										
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	KJVL		MANDATORY	MTH 27-Jul-2023 HRS 6170.3 LDG 4480		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH FAA 2023-10-02 IN ACCORDANCE WITH FAA 2023-10-02 PARAGRAPH (I). NO FURTHER ACTION REQUIRED.										
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION	KICT		MANDATORY	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		-			Complete
MOC : COMPLIED WITH										
FAA 2012-17-01	APPLIANCE AD - INSPECT THE MAIN LANDING GEAR TIRES				MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2013-10-01 PARA (E)(1)	INSERT A COPY OF NIGHTSUN XP SEARCHLIGHT SAFETY AND SERVICE BULLETIN NO. SL 0810-01, AMENDMENT NO. 2 INTO THE NORMAL PROCEDURES SECTION OF THE ROTORCRAFT FLIGHT MANUAL			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2013-10-01 PARA (E)(2)	VISUALLY CHECK THE SEARCHLIGHT INSTALLATION FOR A GAP BETWEEN THE TOP SHROUD RUBBER EDGING, P/N 033381, AND THE SIDE COVERS, P/N 033286			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2013-10-01 PARA (E)(4)	MODIFY AND RE-IDENTIFY THE GIMBAL ASSEMBLY IF THE EDGING DOES NOT REMAIN IN PHYSICAL CONTACT WITH THE SIDE COVER WHEN SLIGHT PRESSURE IS APPLIED TO THE SEARCHLIGHT			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										
FAA 2013-10-01 PARA (E)(5)	MODIFY AND RE-IDENTIFY THE GIMBAL ASSEMBLY			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-10-01	APPLIANCE AD - EXTERIOR LIGHTING - INSERT INFORMATION INTO THE NORMAL PROCEDURES SECTION OF THE ROTORCRAFT FLIGHT MANUAL (RFM), A DAILY CHECK OF THE SEARCHLIGHT, AND AT A SPECIFIED TIME INTERVAL OR IF CERTAIN CONDITIONS ARE FOUND, MODIFY ANY AFFECTED SEARCHLIGHT GIMBAL ASSEMBLY	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
EASA 2006-0265-CN	APPLIANCE AD - CANCELLED: NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK	CANCELLED			-			
MOC :								
EASA 2006-0265	APPLIANCE AD - NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK	MANDATORY			-			
MOC :								
FAA 1999-23-22 R01	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD KSAT	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD1999-23-22R1 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 1999-23-22 R02	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD KSAT	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD1999-23-22R2 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2001-23-17 34AD-09 : XL	GARMIN INTERNATIONAL GNS 430 ICT	MANDATORY	MTH 16-Sep-2007 HRS 9		A/R			N/A
MOC : NOT APPLICABLE								
FAA 2002-06-05 PARA (A)	TEST (PULSE WIDTH)				-			
MOC :								
FAA 2002-06-05 PARA (D)	REPORT	MANDATORY			-			
MOC :								
FAA 2006-16-18 34AD-13 : XL	APPLIANCE AD - SANDEL AVI MOD ST3400 TAWS/RM ICT	MANDATORY	MTH 16-Sep-2007 HRS 9		A/R			N/A
MOC : NOT APPLICABLE								
FAA 2006-22-05 34AD-15 : XL	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM ICT	SUPERSEDED	MTH 16-Sep-2007 HRS 9		A/R			N/A
MOC : NOT APPLICABLE								
FAA 2007-07-12	APPLIANCE AD - NAVIGATION - IDENTIFY AFFECTED COMPUTERS BY PART NUMBER AND SOFTWARE MODIFICATION LEVEL AND REVISE THE LIMITATIONS SECTION OF APPLICABLE AIRPLANE FLIGHT MANUALS (SUPERSEDED BY FAA AD 2009-08-01)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2009-05-08	APPLIANCE AD - NAVIGATION - UPGRADE THE SYSTEM SOFTWARE OF ANY TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GPS NAVIGATION SYSTEM, PART NUMBER (P/N) 81440-XX-241E, 81440-XX-241F, OR 81440-XX-241G	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2009-08-01	APPLIANCE AD - NAVIGATION - IDENTIFY AFFECTED COMPUTERS BY PART NUMBER AND SOFTWARE MODIFICATION LEVEL AND REVISE THE LIMITATIONS SECTION OF APPLICABLE AIRPLANE FLIGHT MANUALS & UPGRADING NEW SOFTWARE	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	KMHR MANDATORY	MTH 29-Mar-2010 HRS 1117.2 LDG 954		A/R			N/A
MOC : NOT APPLICABLE - BY PART NUMBER #2 RNZ 850 FOUND NOT APPLICABLE BY PART NUMBER INSTALLED.								
FAA 2010-09-04	APPLIANCE AD - NAVIGATION - REVISE THE LIMITATIONS SECTION OF THE APPLICABLE AFM	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KICT MANDATORY	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		-			Complete
MOC : COMPLIED WITH								
FAA 2012-14-15 PARA (G)	INCORPORATE LANGUAGE INTO THE LIMITATIONS SECTION OF THE AIRCRAFT FLIGHT MANUAL	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2012-14-15 PARA (H)	FABRICATE AND INSTALL A PLACARD	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2012-14-15	APPLIANCE AD - HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² WIDE AREA AUGMENTATION SYSTEM (WAAS) GLOBAL NAVIGATION SATELLITE SENSOR UNITS (GNSSU)	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.								
FAA 2012-26-15 PARA (G)(1)	REMOVE IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) AFFECTED ADC, ADM, ADAHRS, OR DADC	MHR MANDATORY	DAYS 05-Mar-2013 HRS 2768.6 LDG 2259		-			N/A
MOC : NOT APPLICABLE								
FAA 2012-26-15 PARA (G)(2)	PERFORM IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) PITOT-STATIC CERTIFICATION TEST	MHR	DAYS 05-Mar-2013 HRS 2768.6 LDG 2259		-			N/A
MOC : NOT APPLICABLE								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)									
			MANDATORY	MTH	13-Aug-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01)									
		MHR	MANDATORY	MTH	05-Mar-2013		-			N/A
				HRS	2768.6					
				LDG	2259					
MOC : NOT APPLICABLE										
FAA 2014-05-27	APPLIANCE AD - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION									
			MANDATORY	MTH	13-Aug-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION									
		MHR	MANDATORY	MTH	17-Oct-2014		-			N/A
				HRS	3797.1					
				LDG	3138					
MOC : NOT APPLICABLE - AD 2014-18-01 NOT APPLICABLE AS HONEYWELL TRANSPONDERS ARE INSTALLED. NO ACTION REQUIRED.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.									
		KSAT	MANDATORY	MTH	04-Jul-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AD2015-10-51-E DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS									
		KSAT	MANDATORY	MTH	04-Jul-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AD2015-10-51 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC. AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0									
			MANDATORY	MTH	13-Aug-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS									
			MANDATORY	MTH	13-Aug-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC									
			MANDATORY	MTH	13-Aug-2021		-			N/A
				HRS	5613.7					
				LDG	4146					
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-01-02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE KSAT		MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2019-07-10 PARA (F)(1) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT								
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT KSAT	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2019-07-10 PARA (F)(3) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT								
FAA 2019-07-10	NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL KSAT	MANDATORY	MTH 04-Jul-2021		-			N/A
MOC : NOT APPLICABLE								
FAA 2019-12-09	NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)		DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2020-08-02	APPLIANCE AD - NAVIGATION - THALES AVS FRANCE SAS - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2021-05-17 PARA (G)(1) & (G) (2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)	MANDATORY	MTH 18-Nov-2021 HRS 5717.7 LDG 4217		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE	MANDATORY	MTH 18-Nov-2021 HRS 5717.7 LDG 4217		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2021-05-17	NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE	MANDATORY	MTH 18-Nov-2021 HRS 5717.7 LDG 4217		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2007-26-11	APPLIANCE AD - HIGH-PRESSURE OXYGEN CYLINDER TEARING WITH SUDDEN EMPTYING	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2009-21-10	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2010-11-05	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		A/R			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2011-01-09	APPLIANCE AD - OXYGEN - TO DETERMINE THE SERIAL NUMBER OF THE PBE UNITS INSTALLED IN THE AIRCRAFT, REPLACE THE PBE WITH A SERVICEABLE PBE FOR ANY PBE THAT HAS A SERIAL NUMBER FROM 003-50730M TO 003-51329M INCLUSIVE	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2011-04-09	APPLIANCE AD - OXYGEN GENERATORS PRESENTS AHAZARD THAT COULD JEOPARDIZE FLIGHT SAFETY (SUPERSEDED BY FAA AD 2012-11-09).	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED								
FAA 2011-14-08	APPLIANCE AD - CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY	MANDATORY	MTH 27-Sep-2021 HRS 5618 LDG 4148		A/R			N/A
MOC : NOT APPLICABLE								
FAA 2012-11-09 PARA (G)	DISCHARGE ALL CHEMICAL OXYGEN GENERATORS	MANDATORY	DAYS 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2012-11-09 PARA (L)	INSTALL A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2012-11-09 R01 PARA (G)	ACTIVATE ALL CHEMICAL OXYGEN GENERATORS IN THE LAVATORIES UNTIL THE GENERATOR OXYGEN SUPPLY IS EXPENDED OR REMOVE THE OXYGEN GENERATOR (S) AND REMOVE OR RE-STOW THE OXYGEN MASKS AND CLOSE THE MASK DISPENSER DOOR (FOR EACH CHEMICAL OXYGEN GENERATOR, AFTER THE GENERATOR IS EXPENDED (OR REMOVED))	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2012-11-09 R01 PARA (L)	INSTALL A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2012-11-09 R01	OXYGEN - INSTALLING A SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2012-11-09	ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES	MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED								
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KFXE MANDATORY	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE PART NUMBER OF THE INSTALLED MASKS ARE LISTED IN ZODIAC AEROSPACE SB MXH-35-240 PARAGRAPH 1 (4).								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KFXE		MANDATORY	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE PART NUMBER OF THE INSTALLED MASKS ARE LISTED IN ZODIAC AEROSPACE SB MXH-35-240 PARAGRAPH 1 (4).										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KFXE		MANDATORY	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE PART NUMBER OF THE INSTALLED MASKS ARE LISTED IN ZODIAC AEROSPACE SB MXH-35-240 PARAGRAPH 1 (4).										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KFXE		MANDATORY	MTH 16-Jan-2016 DAYS 4421.1 HRS 3632 LDG		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KFXE		MANDATORY	MTH 16-Jan-2016 DAYS 4421.1 HRS 3632 LDG		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KFXE		MANDATORY	MTH 16-Jan-2016 DAYS 4421.1 HRS 3632 LDG		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KFXE		MANDATORY	MTH 16-Jan-2016 DAYS 4421.1 HRS 3632 LDG		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KFXE		MANDATORY	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KFXE		MANDATORY	MTH 16-Jan-2016 HRS 4421.1 LDG 3632		-			N/A
MOC : NOT APPLICABLE - VERIFIED THIS AD IS NOT APPLICABLE BY THE AFFECTED PART NUMBER / SERIAL NUMBER MASKS LISTED IN ZODIAC AEROSPACE SB MCF-SBU-35-001, APPENDIX 1 ARE NOT INSTALLED IN THIS AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 12-Jul-2016		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH ANY PBE DEVICES								
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 12-Jul-2016		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH ANY PBE DEVICES								
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 12-Jul-2016		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH ANY PBE DEVICES								
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 12-Jul-2016		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH ANY PBE DEVICES								
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2017-18-12 PARA (G) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2017-18-12 PARA (H) DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	MANDATORY	MTH 04-Jul-2021		-			N/A
MOC : NOT APPLICABLE								
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2017-18-12 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2018-21-14 PARA (G) DOES NOT APPLY DUE TO THE INTENT OF ZODIAC SB MC10-35-274 R2 HAS BEEN PREVIOUSLY COMPLIED WITH.								
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD	MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2018-21-14 PARA (H) DOES NOT APPLY DUE TO THE INTENT OF ZODIAC SB MC10-35-274 R2 HAS BEEN PREVIOUSLY COMPLIED WITH.								



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT	KSAT		MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2018-21-14 DOES NOT APPLY DUE TO THE INTENT OF ZODIAC SB MC10-35-274 R2 HAS BEEN PREVIOUSLY COMPLIED WITH.										
FAA 2022-04-09 PARA (H) & (I)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF AN EFFECTED PART INSTALLED; IF INSTALLED, BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY AND PERFORM CORRECTIVE ACTIONS			MANDATORY	DAYS 24-May-2022 HRS 5912.7 LDG 4335		-			N/A
MOC : NOT APPLICABLE - FOUND THAT AD EFFECTED EQUIPMENT NOTINSTALLED. NO FURTHER ACTION REQUIRED										
FAA 2022-04-09 PARA (J)	REPORT THE RESULTS OF THE INSPECTION			MANDATORY	DAYS 24-May-2022 HRS 5912.7 LDG 4335		-			N/A
MOC : NOT APPLICABLE - FOUND THAT AD EFFECTED EQUIPMENT NOTINSTALLED. NO FURTHER ACTION REQUIRED										
FAA 2022-04-09	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECT / REPLACE			MANDATORY	MTH 24-May-2022 HRS 5912.7 LDG 4335		-			N/A
MOC : NOT APPLICABLE - FOUND THAT AD EFFECTED EQUIPMENT NOTINSTALLED. NO FURTHER ACTION REQUIRED										
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016			MANDATORY	MTH 13-Aug-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD	KICT		MANDATORY	MTH 22-Oct-2012 HRS 2535.3 LDG 2080		-			Complete
MOC : COMPLIED WITH										
FAA 2010-18-09 PARA (E)(2) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
FAA 2010-18-09 PARA (E)(2) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
FAA 2010-18-09 PARA (E)(3) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2010-18-09 PARA (E)(3) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		-			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E1	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E2	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.1 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP H. E1	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.1 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP H. E2	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.1 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	UNK		MANDATORY	MTH 03-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	UNK		MANDATORY	MTH 05-Apr-2018 HRS 5032.2 LDG 3896		A/R			Complete
MOC : COMPLIED WITH										
FAA 2020-26-05	ENGINE CONTROLS - LEFT AND RIGHT THROTTLE QUADRANT ASSEMBLY SENSOR LINK AND SENSOR DRIVE ARM PIVOT RIVETS - INSPECTION/CORRECTIVE ACTION	KSAT		MANDATORY	MTH 04-Jul-2021 HRS 5613.7 LDG 4146		-			N/A
MOC : NOT APPLICABLE - AD2020-26-05 DOES NOT APPLY DUE TO THE SERIAL NUMBER OF THIS AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **BTT CITATION, LLC**
Aircraft Model: **560XLS - CITATION XLS (MSG)**
Aircraft Serial: **560XL-5728**
Unit: **5728** Reg No: **N608BT**
Airworthiness: **16-Sep-2007**
Print Date: **03-Feb-2025 7:49AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6421.6	4642	01-Jan-2025	.5
ENG 1	6372.1	4571	01-Jan-2025	.5
ENG 2	6372.1	4571	01-Jan-2025	.5
APU	2550.9	4112	01-Jan-2025	.17

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
23FO-01XL <i>23FO-01 : XL</i>	ST-3100 TELEPHONE SYS AIRCELL FACTORY OPTION	*CF		807D FO	MTH 16-Sep-2007		-	0		
23FO-05XL/V <i>23FO-05 : XL/V</i>	RECORDER: FDR PROVISION HWELL/ TELEDYNE FACTORY OPTION	*CF		634V FO	MTH 16-Sep-2007		-	0		
24FO-01XL/N <i>24FO-01 : XL/N</i>	BATTERY: SEALED LEAD ACID FACTORY OPTION	*CF		186N FO	MTH 16-Sep-2007		-			
27FO-01XL <i>27FO-01 : XL</i>	U.S. STREEP APPROACH OPTION FACTORY OPTION	*CF		16C FO	MTH 16-Sep-2007		-			
34FO-01XL <i>34FO-01 : XL</i>	COCKPIT SPEAKER MUTE SWITCH FACTORY OPTION	*CF		674B FO	MTH 16-Sep-2007		-	0		
34FO-22XL <i>34FO-22 : XL</i>	UNS-1ESP (SECOND) UNIVERSAL FACTORY OPTION	*CF		697Q FO	MTH 16-Sep-2007		-	0		
34FO-23XL <i>34FO-23 : XL</i>	PERFORMANCE DATABASE- UNIVERSA FACTORY OPTION	*CF		698F FO	MTH 16-Sep-2007		-			
34FO-26XL <i>34FO-26 : XL</i>	DUAL MODE S DIV XPDR W EN SURV FACTORY OPTION	*CF		624F FO	MTH 16-Sep-2007		-	0		