



DueList Report

TBM 900

S/N 1085 N330EA

OWNER: SKYWARE LLC
ADDRESS: 17002 MARCY ST
OMAHA NE 68118

OPERATOR: SKYWARE LLC
ADDRESS: 17002 MARCY ST
OMAHA NE 68118

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: JOSHUA MCNAMEE
EMAIL: JMCNAMEE@CAMPSYSTEMS.COM

0870 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PROJECTED: 12 MOS. to 05-FEB-26

AIRCRAFT	SERIAL / REGNO: 1085/N330EA	MODEL: TBM 900	MANUFACTURER: DAHER
CERTIFICATION DATE: 04-SEP-2015		LAST ACTUALS:	PROJECTED:
		1470.1 A/C HRS as of 18-DEC-2024	1770.10
		978 AFL as of 26-NOV-2024	1158
		0 FLTS as of 04-SEP-2015	180
ENGINE NO. 1	SERIAL / PART: PCE-RV0433/3071016-01	MODEL: PT6A-66D2	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 06-JUN-2021		LAST ACTUALS:	PROJECTED:
862.5 ENG. HRS 862.5 A/C HRS		1470.1 ENG. HRS as of 18-DEC-2024	1770.10
571 ENC		978 ENC as of 26-NOV-2024	1158
PROPELLER NO. 1	SERIAL / PART: RJ134/HC-E5N-3C/NC8834K	MODEL: HC-E5N-3C	MANUFACTURER: HARTZELL PROPELLER LLC
INSTALLED ON: 06-JUN-2021		LAST ACTUALS:	PROJECTED:
862.5 PROP HRS 862.5 A/C HRS		1470.1 PROP HRS as of 18-DEC-2024	1770.10
0 PRC			



New Requirement/Flagged Items

Operator Review and Action Required

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB 70-333-53		WINDSHIELD LOWER COVER STRIP WATER ACCUMULATION, SERVICE BULLETIN					Bulletin ATA:53
	01-Nov-24	MOS	T:DUE	01-Nov-24	_____	31-Jan-25 * (M)	RECOMMENDED
		HRS			_____		
		AFL			_____		

NEW REQUIREMENT ADDED ON 20-DEC-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES. REF: BULLETINS

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
SB 70-335-34 R01									
GARMIN G1000 NXI GDU SOFTWARE VERSION V20.98 (P/N 006-B4560-00), SERVICE BULLETIN									
	MOS	T:DUE			31-Jan-25 (M)		OVD		Bulletin ATA:34
	HRS								
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									
SB 70-337-76									
PEDESTAL CONTROL SET IMPROVEMENT, SERVICE BULLETIN									
	MOS	T:DUE			31-Jan-25 (M)		OVD		Bulletin ATA:76
	HRS								
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									
28-20-04-730-801									
MECHANICAL PUMP - OVERHAUL									
PN:1127-02	MOS	120 (+10%/-10%)	04-Sep-15	TSN:0	04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:852	HRS	3500 (+10%/-10%)	0	TSN:0	3500	3850	2029.9 (+350)		1470.1
	AFL		0	TSN:0					978
Disposition: OVERHAUL REF: AMM 28-20-04									
32-10-01-220-801									
LEFT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER									
PN:D23767001-2	MOS	60 (+10%/-10%)	02-Dec-20	Adj:-89d	04-Sep-25	04-Mar-26	211 d (+181)	04-Sep-2025	50.1
SN:15AR1214	HRS		780.7						689.4
	AFL								
REF: AMM 32-10-01, AMM 12-13-03									
32-10-01-220-801									
RIGHT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER.									
PN:D23768001-2	MOS	60 (+10%/-10%)	02-Dec-20	Adj:-89d	04-Sep-25	04-Mar-26	211 d (+181)	04-Sep-2025	50.1
SN:15AR1214	HRS		780.7						689.4
	AFL								
REF: AMM 32-10-01, AMM 12-13-03									
32-10-01-220-802									
LEFT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.									
PN:D23767001-2	MOS	120 (+10%/-10%)	04-Sep-15		04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:15AR1214	HRS		0						1470.1
	AFL		0						978
REF: AMM 32-10-01									
32-10-01-220-802									
RIGHT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.									
PN:D23768001-2	MOS	120 (+10%/-10%)	04-Sep-15		04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:15AR1214	HRS		0						1470.1
	AFL		0						978

REF: AMM 32-10-01



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
32-20-01-220-801		NOSE LANDING GEAR - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS.							Service ATA:32
PN:D23766000-2	MOS	60 (+10%/-10%)	02-Dec-20	Adj:-89d	04-Sep-25	04-Mar-26	211 d (+181)	04-Sep-2025	50.1
SN:15AR1214	HRS		780.7						689.4
	AFL								
REF: AMM 12-13-04, AMM 32-20-01									
32-20-01-220-802		NOSE LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.							Service ATA:32
PN:D23766000-2	MOS	120 (+10%/-10%)	04-Sep-15		04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:15AR1214	HRS		0						1470.1
	AFL		0						978
REF: AMM 32-20-01									
32-20-01-680-801		NOSE LANDING GEAR - DO AN OIL CHANGE FOR THE SHOCK ABSORBER							Service ATA:32
	MOS	60 (+10%/-10%)	02-Dec-20	Adj:-89d	04-Sep-25	04-Mar-26	211 d (+181)	04-Sep-2025	50.1
	HRS		780.7						689.4
	AFL								
REF: AMM 12-13-04									
32-30-01-730-801		LEFT MAIN LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	120 (+10%/-10%)	04-Sep-15	TSN:0	04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:3390	HRS		0	TSN:0					1470.1
	AFL	5000 (+10%/-10%)	0	TSN:0	5000	5500	4022 (+500)		978
Disposition: OVERHAUL		REF: AMM 32-30-01							
32-30-01-730-801		RIGHT MAIN LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	120 (+10%/-10%)	04-Sep-15	TSN:0	04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:3391	HRS		0	TSN:0					1470.1
	AFL	5000 (+10%/-10%)	0	TSN:0	5000	5500	4022 (+500)		978
Disposition: OVERHAUL		REF: AMM 32-30-01							
32-30-02-730-801		NOSE LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	120 (+10%/-10%)	04-Sep-15	TSN:0	04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:3394	HRS		0	TSN:0					1470.1
	AFL	5000 (+10%/-10%)	0	TSN:0	5000	5500	4022 (+500)		978
Disposition: OVERHAUL		REF: AMM 32-30-01, AMM 32-30-02							
32-35-01-730-801		ELECTRO-HYDRAULIC GENERATOR - OVERHAUL							Component ATA:32
PN:1118-04	MOS	120 (+10%/-10%)	04-Sep-15	TSN:0	04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
SN:835	HRS		0	TSN:0					1470.1
	AFL	10000 (+10%/-10%)	0	TSN:0	10000	11000	9022 (+1000)		978
Disposition: OVERHAUL		REF: AMM 32-35-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement)(EFF) - Effective C/W M-Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
55-00-00-280-802 VERTICAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION									
	MOS	T:120 (+12m/-12m)	04-Sep-15		04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
	HRS	T:6000 (+600/-600)	0		6000	6600	4529.9 (+600)		1470.1
	AFL		0						978
REF: AMM 55-30-00									
71-00-00-200-804 FIREWALL - CHECK THE FIREWALL AND THE FRONT CARGO COMPARTMENT UPHOLSTERY PANELS									
	MOS	120 (+10%/-10%)	04-Sep-15		04-Sep-25	04-Sep-26	211 d (+365)	04-Sep-2025	113
	HRS		0						1470.1
	AFL		0						978
REF: AMM 25-50-03									
05-20-02 STANDARD PROGRAM - A INSPECTION									
	MOS	12 (+1m/-1m)	18-Dec-24		18-Dec-25	18-Jan-26	316 d (+31)	06-Oct-2025	1.6
	HRS	200 (+10/-10)	1470.1		1670.1	1680.1	200 (+10)		0
	AFL								
REF: TLMC 05-20-02									
05-70-CA-890-801 NO. 1 ENGINE - MINOR INSPECTION									
	MOS	12 (+1m)	18-Dec-24		18-Dec-25	18-Jan-26	316 d (+31)	06-Oct-2025	1.6
	HRS	200 (+10)	1470.1		(1670.1)1670.1	1680.1	200 (+10)		0
	ENC								
REF: EMM 72-00-00									
24-30-04-760-802 LEAD-ACID BATTERY IF INSTALLED - CHECK CAPACITY									
PN:RG-380E/44	MOS	12 (+1m/-1m)	18-Dec-24	Adj:15d	02-Jan-26	02-Feb-26	331 d (+31)	06-Oct-2025	1.6
SN:70017654	HRS	200 (+10%/-10%)	1470.1		1670.1	1690.1	200 (+20)		0
	AFL								
REF: AMM 24-30-04									
73-30-CA-100-801 NO. 1 ENGINE - CLEAN PNEUMATIC P3 FILTER									
PN:3059788-01	MOS	12 (+1m)	18-Dec-24	Adj:-33d	15-Nov-25	15-Dec-25	283 d (+30)	06-Oct-2025	1.6
SN:UNKNOWN	HRS	200 (+10)	1470.1		(1670.1)1670.1	1680.1	200 (+10)		0
	ENC								
REF: EMM 73-10-07									
05-20-03 STANDARD PROGRAM - B INSPECTION									
	MOS	24 (+1m/-1m)	02-Jan-24		02-Jan-26		331 d	09-Nov-2025	13.1
	HRS	400 (+10/-10)	1298.1		1698.1		228		172
	AFL		838						140
REF: TLMC 05-20-03									



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
74-00-CA-200-801 NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION									
	MOS		02-Jan-24					09-Nov-2025	13.1
	HRS	400 (+10%)	1298.1		(1698.1)1698.1	1738.1	228 (+40)		172
	ENC		838						140
REF: EMM 74-10-00									
74-10-00-200-801 IGNITION EXCITER - CHECK FOR CONDITION AND ATTACHMENT.									
	MOS		02-Jan-24					09-Nov-2025	13.1
	HRS	400 (+10/-10)	1298.1		1698.1	1708.1	228 (+10)		172
	AFL		838						140
REF: EMM 74-10-00, AMM 74-00-00									
74-20-00-200-801 IGNITION CABLES - CHECK FOR ROUTING, ATTACHMENT AND WEAR DUE TO CHAFING.									
	MOS		02-Jan-24					09-Nov-2025	13.1
	HRS	400 (+10/-10)	1298.1		1698.1	1708.1	228 (+10)		172
	AFL		838						140
REF: AMM 74-00-00									
74-20-00-200-802 SPARK IGNITERS - CHECK FOR CLEANLINESS AND EROSION.									
	MOS		02-Jan-24					09-Nov-2025	13.1
	HRS	400 (+10/-10)	1298.1		1698.1	1708.1	228 (+10)		172
	AFL		838						140
REF: AMM 74-20-00									
61-10-00-220-801 BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK.									
	MOS	12 (+10%/-10%)	18-Dec-24	Adj:-33d	15-Nov-25	21-Dec-25	283 d (+36)	15-Nov-2025	1.6
	HRS	600 (+10%/-10%)	1470.1		2070.1	2130.1	600 (+60)		0
	AFL								
REF: GENERIC NO REF									
79-20-02-710-801 NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST									
	MOS	12 (+1m)	18-Dec-24	Adj:-33d	15-Nov-25	15-Dec-25	283 d (+30)	15-Nov-2025	1.6
	HRS	600 (+10%)	1470.1		(2070.1)2070.1	2130.1	600 (+60)		0
	ENC								
REF: EMM 79-20-02, AMM 72-00-00									
25-61-00-710-806 EMERGENCY LOCATOR TRANSMITTER - DO AN OPERATIONAL TEST AND RECORD OPERATING TIME									
PN:8201	MOS	12 (+1m/-1m)	18-Dec-24		18-Dec-25	18-Jan-26	316 d (+31)	18-Dec-2025	1.6
SN:251-08010	HRS		1470.1						0
	AFL								
REF: AMM 25-61-00, AMM 25-61-01									



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
30-60-00-760-801									
PERFORM A DE-ICE CIRCUIT RESISTANCE CHECK (REFER TO HARTZELL CMM 180)									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS		1470.1						0
	AFL								
REF: GENERIC NO REF, CMM 30-61-80									
34-11-00-760-801									
STANDBY INDICATOR - DO A BATTERY CAPACITY METER CALIBRATION									
PN:9200-32500-0021	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
SN:2621	HRS		1470.1						0
	AFL								
REF: GENERIC NO REF									
61-00-00-200-802									
NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS	600	1470.1		(2070.1)2070.1		600		0
REF: POM 61-00-47									
61-10-00-200-801									
NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS	400	1470.1		(1870.1)1870.1		400		0
REF: POM 61-00-47									
61-10-01-640-801									
NO. 1 PROPELLER - PROPELLER - LUBRICATE									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS	400	1470.1		(1870.1)1870.1		400		0
REF: POM 61-00-47, AMM 61-10-01									
61-10-01-640-802									
NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS	400	1470.1		(1870.1)1870.1		400		0
REF: POM 61-00-47									
Disposition: CPCP									
SB 70-118-27 R03 PARA C									
ACCOMPLISH INBOARD FLAP ACTUATOR, SERVICE BULLETIN CLEAN AND LUBRICATE THE ACTUATOR SCREW									
	MOS	12	18-Dec-24		18-Dec-25		316 d	18-Dec-2025	1.6
	HRS	400	1470.1		1870.1		400		0
	AFL								
REF: BULLETINS									
Disposition: MANDATORY									
24-30-05-900-801									
STANDBY GENERATOR BELT - REPLACE									
PN:7133280007	MOS		15-Nov-22					26-Dec-2025	26.7
SN:UNKNOWN	HRS	600	1136.8		1736.8		266.7		333.3
	AFL		750						228
Disposition: LIFE LIMIT									
REF: AMM 24-30-05									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-20-05		ANNUAL INSPECTION							Package ATA:05
	MOS	12	18-Dec-24		31-Dec-25		329 d	31-Dec-2025	1.6
	HRS		1470.1						0
	AFL								
REF: TLMC 05-20-05									
21-30-02-100-801		OUTFLOW VALVE - CLEAN VALVE SEATS							Service ATA:21
	MOS	24 (+10%/-10%)	02-Jan-24		02-Jan-26	14-Mar-26	331 d (+71)	02-Jan-2026	13.1
	HRS		1298.1						172
	AFL		838						140
REF: AMM 21-30-03, AMM 21-30-02									
21-30-03-100-802		SAFETY VALVE - CLEAN VALVE SEATS							Service ATA:21
	MOS	24 (+10%/-10%)	02-Jan-24		02-Jan-26	14-Mar-26	331 d (+71)	02-Jan-2026	13.1
	HRS		1298.1						172
	AFL		838						140
REF: AMM 21-30-03									
34-11-00-820-801		NO. 1 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION							Service ATA:34
PN:011-01110-01	MOS	24	02-Jan-24		02-Jan-26		331 d	02-Jan-2026	13.1
SN:1SW006585	HRS								
	AFL								
Disposition: MANDATORY REF: CFR FAR PART 91.411, AMM 34-11-00									
34-11-00-820-801		NO. 2 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION							Service ATA:34
PN:011-01110-01	MOS	24	02-Jan-24		02-Jan-26		331 d	02-Jan-2026	13.1
SN:1SW006589	HRS								
	AFL								
Disposition: MANDATORY REF: CFR FAR PART 91.411, AMM 34-11-00									
34-11-00-820-803		STANDBY INDICATOR - 
CHECK CALIBRATION (14 CFR PART 91.411)							Service ATA:34
PN:9200-32500-0021	MOS	24	02-Jan-24		02-Jan-26		331 d	02-Jan-2026	13.1
SN:2621	HRS		1298.1						172
	AFL		838						140
Disposition: MANDATORY REF: AMM 34-11-00									
34-53-00-710-801		NO. 1 (A56) TRANSPONDER - DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-03303-00	MOS	24	02-Jan-24		02-Jan-26		331 d	02-Jan-2026	13.1
SN:3EH021721	HRS								
	AFL								
Disposition: MANDATORY REF: CFR FAR PART 91.413, AMM 34-53-00									



Due List Report

Model: TBM 900 Serial: 1085 RegNo: N330EA HRS: 1470.1 AFL: 978 As Of: 18-Dec-2024 Operator: SKYWARE LLC

Report Date: 05-Feb-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
34-53-00-710-801		NO. 2 (A57) TRANSPONDER- DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-00779-30	MOS	24	02-Jan-24		02-Jan-26		331 d	02-Jan-2026	13.1
SN:89129217	HRS								
	AFL								
Disposition: MANDATORY		REF: CFR FAR PART 91.413, AMM 34-53-00							
72-00-00-730-801		NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION (HSI)							Service ATA:72
PN:PN	MOS		04-Sep-15					11-Jan-2026	113
SN:UNKNOWN	HRS	1750 (+250)	0		(1750)1750	2000	279.9 (+250)		1470.1
	ENC		0						978
		REF: EMM 72-00-00							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time