



DueList Report

TBM 910

S/N 1242 N910ZV

OWNER: CENTREX CONSTRUCTION INC. OPERATOR: CENTREX CONSTRUCTION INC.
ADDRESS: 8250 SW HUNZIKER STREET ADDRESS: 8250 SW HUNZIKER STREET
TIGARD OR 97223 TIGARD OR 97223
OFFICE: 805-223-1324 OFFICE: 805-223-1324
FAX: FAX:

ANALYST: JOSHUA MCNAMEE 0870 (DIRECT) 800-787-9749 (EFAX-CARDS)
EMAIL: JMCNAMEE@CAMPSYSTEMS.COM +1-631-588-3200 (MAIN) 631-980-4222 (FAX)
WWW.CAMPSYSTEMS.COM

PROJECTED: 6 MOS. to 05-DEC-2025

AIRCRAFT	SERIAL/REGNO: 1242/N910ZV	MODEL: TBM 910	MANUFACTURER: DAHER
CERTIFICATION DATE: 03-JUL-2018		LAST ACTUALS:	PROJECTED:
		889.6 A/C HRS as of 04-JUN-2025	979.85
		632 AFL as of 04-JUN-2025	692
		0 FLTS as of 03-JUL-2018	60
ENGINE NO. 1	SERIAL/PART: PCE-RV0589/3071016-01	MODEL: PT6A-66D	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 03-JUL-2018		LAST ACTUALS:	PROJECTED:
0 ENG. HRS 0 A/C HRS		889.6 ENG. HRS as of 04-JUN-2025	949.77
0 ENC		632 ENC as of 04-JUN-2025	692
PROPELLER NO. 1	SERIAL/PART: RJ376/HC-E5N-3C/NC8834K	MODEL: HC-E5N-3C	MANUFACTURER: HARTZELL PROPELLER LLC
INSTALLED ON: 03-JUL-2018		LAST ACTUALS:	PROJECTED:
0 PROP HRS 0 A/C HRS		889.6 PROP HRS as of 04-JUN-2025	949.77
0 PRC			



Due List Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025 Operator: CENTREX CONSTRUCTION INC.

Report Date: 06-Jun-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
34-23-01-820-801		STANDBY COMPASS - DO A COMPENSATION						Service ATA:34
PN:C2350L4M23	MOS	36 (+10%/-10%)		22-Jul-21	22-Jul-24	09-Nov-24	OVD	
SN:EA-908	HRS			488.9				
	AFL							
REF: AMM 34-23-01								
35-21-02-730-801		ALTIMETRIC VALVE - OVERHAUL						Component ATA:35
PN:DVE90-06	MOS	72 (+10%/-10%)	TSN:0	03-Jul-18	03-Jul-24	08-Feb-25	OVD	
SN:9589	HRS		TSN:0	0				
	AFL		TSN:0	0				
Disposition: OVERHAUL REF: AMM 35-21-02								
ASB PT6A-72-A14575 R02		NO. 1 ENGINE - INSPECTION/REPLACEMENT OF SINGLE-ENGINE APPLICATION FIRST-STAGE PT BLADES, ALERT SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:6		EFF	13-Dec-24 * (M)		OVD	
	HRS	T:100		EFF	(907.52)907.52 * (M)		17.9	
	ENC							
Disposition: CATEGORY 3 REF: BULLETINS								
FAA 2025-02-08		REVISE THE EXISTING PILOT'S OPERATING HANDBOOK BY INCORPORATING TEMPORARY REVISION 30, DATED JULY 2023						AD ATA:26
	DAYS	T:30		EFF	18-Apr-25 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY REF: AD								
32-20-01-900-801		NOSE LANDING GEAR - REPLACE NOSE GEAR ACTUATOR HINGE PIN SECURING BOLT						Service ATA:32
	MOS	84		03-Jul-18	03-Jul-25		28 d	03-Jul-2025
	HRS			0				
	AFL	5000		0	5000		4368	
REF: AMM 32-20-01								
05-20-02		STANDARD PROGRAM - A INSPECTION						Package ATA:05
	MOS	12 (+1m/-1m)	Adj:-73d	15-Oct-24	03-Aug-25	03-Sep-25	59 d (+31)	03-Aug-2025
	HRS	200 (+10/-10)		834	1034	1044	144.4 (+10)	
	AFL			612				
REF: TLMC 05-20-02								
61-10-00-220-801		BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK.						Service ATA:61
	MOS	12 (+10%/-10%)	Adj:-73d	15-Oct-24	03-Aug-25	09-Sep-25	59 d (+37)	03-Aug-2025
	HRS	600 (+10%/-10%)		834	1434	1494	544.4 (+60)	
	AFL							
REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025 Operator: CENTREX CONSTRUCTION INC.

Report Date: 06-Jun-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
79-00-CA-610-801		NO. 1 ENGINE - SERVICING OIL SYSTEM						Service ATA:79
	MOS	12 (+1m)	Adj:-73d	15-Oct-24	03-Aug-25	03-Sep-25	59 d (+31)	03-Aug-2025
	HRS			834				
	ENC							
		REF: EMM 72-00-00						
79-20-02-710-801		NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST						Service ATA:79
	MOS	12 (+1m)	Adj:-73d	15-Oct-24	03-Aug-25	03-Sep-25	59 d (+31)	03-Aug-2025
	HRS	600 (+10%)		834	(1434)1434	1494	544.4 (+60)	
	ENC			612				
		REF: AMM 72-00-00, EMM 79-20-02						
SB 70-310-24 R01		REMOVAL, UPGRADING AND RE-INSTALLATION OF THE STARTER-GENERATOR, SERVICE BULLETIN						Bulletin ATA:24
	MOS	T:DUE		EFF	03-Aug-25 * (M)		59 d	03-Aug-2025
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
05-70-CA-890-801		NO. 1 ENGINE - MINOR INSPECTION						Package ATA:05
	MOS	12 (+1m)	Adj:-40d	15-Oct-24	05-Sep-25	05-Oct-25	92 d (+30)	05-Sep-2025
	HRS	200 (+10)		834	(1034)1034	1044	144.4 (+10)	
	ENC			612				
		REF: EMM 72-00-00						
SB 70-335-34 R01		GARMIN G1000 NXI GDU SOFTWARE VERSION V20.98 (P/N 006-B4560-00), SERVICE BULLETIN						Bulletin ATA:34
	MOS	T:DUE			30-Sep-25 (M)		117 d	30-Sep-2025
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
SL SL70-068-32		MAIN WHEEL ASSEMBLY P/N 40-489- RUPTURE DISC TORQUE, SERVICE LETTER						Bulletin ATA:32
	MOS	T:12		EFF	01-Oct-25 *		118 d	01-Oct-2025
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
24-30-04-760-802		LEAD-ACID BATTERY IF INSTALLED - CHECK CAPACITY						Service ATA:24
PN:RG-380E/44	MOS	12 (+1m/-1m)		15-Oct-24	15-Oct-25	15-Nov-25	132 d (+31)	15-Oct-2025
SN:41405768	HRS	200 (+10%/-10%)		834	1034	1054	144.4 (+20)	
	AFL			612				
		REF: AMM 24-30-04						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025 Operator: CENTREX CONSTRUCTION INC.

Report Date: 06-Jun-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
25-61-00-710-806		EMERGENCY LOCATOR TRANSMITTER - DO AN OPERATIONAL TEST AND RECORD OPERATING TIME						Service ATA:25
PN:8201	MOS	12 (+1m/-1m)		15-Oct-24	15-Oct-25	15-Nov-25	132 d (+31)	15-Oct-2025
SN:251-10603	HRS			834				
	AFL			612				
REF: AMM 25-61-00, AMM 25-61-01								
30-60-00-760-801		PERFORM A DE-ICE CIRCUIT RESISTANCE CHECK (REFER TO HARTZELL CMM 180)						Service ATA:30
	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
	HRS			834				
	AFL							
REF: GENERIC NO REF, CMM 30-61-80								
34-11-00-760-801		STANDBY INDICATOR - DO A BATTERY CAPACITY METER CALIBRATION						Service ATA:34
PN:6420302-1	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
SN:C18-10053	HRS			834				
	AFL							
REF: GENERIC NO REF								
61-00-00-200-802		NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP						Service ATA:61
	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
	HRS	600		834	(1434)1434		544.4	
REF: POM 61-00-47								
61-10-00-200-801		NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION						Service ATA:61
	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
	HRS	400		834	(1234)1234		344.4	
REF: POM 61-00-47								
61-10-01-640-801		NO. 1 PROPELLER - PROPELLER - LUBRICATE						Service ATA:61
	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
	HRS	400		834	(1234)1234		344.4	
REF: POM 61-00-47, AMM 61-10-01								
FAA 2025-01-04 PARA (G)(1) LH		CLEAN AND LUBRICATE THE LEFT-HAND (LH) INTERNAL ACTUATOR RODS						AD ATA:27
	MOS	12		EFF	15-Oct-25 * (M)		132 d	15-Oct-2025
	HRS	400		EFF	1234 * (M)		344.4	
	AFL							
Disposition: MANDATORY REF: AD								
FAA 2025-01-04 PARA (G)(1) RH		CLEAN AND LUBRICATE THE RIGHT-HAND (RH) INTERNAL ACTUATOR RODS						AD ATA:27
	MOS	12		EFF	15-Oct-25 * (M)		132 d	15-Oct-2025
	HRS	400		EFF	1234 * (M)		344.4	
	AFL							
Disposition: MANDATORY REF: AD								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025 Operator: CENTREX CONSTRUCTION INC.

Report Date: 06-Jun-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB 70-118-27 R03 PARA C								
ACCOMPLISH INBOARD FLAP ACTUATOR, SERVICE BULLETIN CLEAN AND LUBRICATE THE ACTUATOR SCREW								
Bulletin ATA:27								
	MOS	12		15-Oct-24	15-Oct-25		132 d	15-Oct-2025
	HRS	400		834	1234		344.4	
	AFL			612				
Disposition: MANDATORY								
REF: BULLETINS								
05-20-05								
ANNUAL INSPECTION								
Package ATA:05								
	MOS	12		15-Oct-24	31-Oct-25		148 d	31-Oct-2025
	HRS			834				
	AFL			612				
REF: TLMC 05-20-05								
SB 70-337-76								
PEDESTAL CONTROL SET IMPROVEMENT, SERVICE BULLETIN								
Bulletin ATA:76								
	MOS	T:DUE			31-Oct-25 (M)		148 d	31-Oct-2025
	HRS							
	AFL							
Disposition: RECOMMENDED								
REF: BULLETINS								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time