



Status Report

TBM 910

S/N 1242 N910ZV

OWNER: CENTREX CONSTRUCTION INC. OPERATOR: CENTREX CONSTRUCTION INC.
ADDRESS: 8250 SW HUNZIKER STREET ADDRESS: 8250 SW HUNZIKER STREET
TIGARD OR 97223 TIGARD OR 97223
OFFICE: 805-223-1324 OFFICE: 805-223-1324
FAX: FAX:

ANALYST: JOSHUA MCNAMEE 0870 (DIRECT) 800-787-9749 (EFAX-CARDS) PLEASE REACH OUT TO YOUR ANALYST TO
EMAIL: JMCNAMEE@CAMPSYSTEMS.COM +1-631-588-3200 (MAIN) 631-980-4222 (FAX) RECORD CHANGES TO ADDRESS, LAST ACTUALS
WWW.CAMPSYSTEMS.COM (IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 1242/N910ZV	MODEL: TBM 910	MANUFACTURER: DAHER
CERTIFICATION DATE: 03-JUL-2018		LAST ACTUALS:	
		889.6 A/C HRS	as of 04-JUN-2025
		632 AFL	as of 04-JUN-2025
		0 FLTS	as of 03-JUL-2018
ENGINE NO. 1	SERIAL / PART: PCE-RV0589/3071016-01	MODEL: PT6A-66D	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 03-JUL-2018		LAST ACTUALS:	
0	ENG. HRS	0 A/C HRS	889.6 ENG. HRS as of 04-JUN-2025
0	ENC		632 ENC as of 04-JUN-2025
PROPELLER NO. 1	SERIAL / PART: RJ376/HC-E5N-3C/NC8834K	MODEL: HC-E5N-3C	MANUFACTURER: HARTZELL PROPELLER LLC
INSTALLED ON: 03-JUL-2018		LAST ACTUALS:	
0	PROP HRS	0 A/C HRS	889.6 PROP HRS as of 04-JUN-2025
0	PRC		



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
05-21-30	PRESSURIZATION VALVES SEAT CLEANING							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-23-15	HF COMMUNICATION EQUIPMENT CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-25-12	COCKPIT SEAT AIRBAG SYSTEM CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-28-10	FLAPPER VALVES AND STRAINERS CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-32-00	HYDRAULIC FLUID REPLACEMENT							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								
05-32-01	5-YEAR LANDING GEAR LONG LIFE PROGRAM							Service ATA:00
	MOS/MSC	05-Sep-23	-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
05-34-00	OPERATIONAL TEST AND CALIBRATION OF COMMUNICATION AND NAVIGATION EQUIPMENT							Service ATA:00
	MOS/MSC	21-Aug-23	-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-72-00	HOT SECTION & FUEL NOZZLE CHECKS							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-72-01	ENGINE INITIAL 100 HOURS INSPECTION							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-73-10	FUEL PUMP FILTERS CLEANING & REPLACEMENT							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E66D-170707	NO. 1 ENGINE - REVIEW SB PT6A-72-14603 REV 27							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E66DPROC. REF: RCF E66D								
E66D-230410	NO. 1 ENGINE - REVIEW PT6A-66D EMM REV 24.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E66DPROC. REF: RCF E66D								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P900-170701	NO. 1 PROPELLER - REVIEW POM 147 REV 13							Service ATA:00
	MOS/MSC	03-Jul-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
PROC. REF: RCF P900PROC. REF: RCF P900								
P900-200301	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL (MANUAL 180) REVISION 32							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF P900PROC. REF: RCF P900								
P900-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
PROC. REF: RCF P900PROC. REF: RCF P900								
S850-180522	REVIEW TBM 850 AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	03-Jul-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, RCF S850PROC. REF: GENERIC NO REF, RCF S850								
S850-190101	REVIEW TBM 850/900/910 MAINTENANCE MANUAL CHAPTER 5 REV.18							Service ATA:00
	MOS/MSC	03-Jul-18	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, RCF S850PROC. REF: GENERIC NO REF, RCF S850								
S850-190701	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.19							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF S850, GENERIC NO REFPROC. REF: RCF S850, GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
S850-200201	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.20							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF S850, GENERIC NO REFPROC. REF: RCF S850, GENERIC NO REF								
S850-201201	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.21							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF S850, GENERIC NO REFPROC. REF: RCF S850, GENERIC NO REF								
S850-230701	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.22							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: GENERIC NO REF, RCF S850PROC. REF: GENERIC NO REF, RCF S850								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-100-801 ^S	IF REQUIRED, CLEAN THE AIRCRAFT EXTERIOR SURFACE.							Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-22-01PROC. REF: AMM 12-22-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-801 ^S	SHUTDOWN ENGINE - CHECK FOR FUEL OR OIL LEAKS AT POWER PLANT. CHECK COMPONENTS REMOVED OR REPLACED DURING INSPECTION FOR CONDITION.							Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-200-802	^S	CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-12-01PROC. REF: AMM 12-12-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-803	^S	CHECK THAT ENGINE COWLINGS, ACCESS DOORS, FLOOR PANELS, KARMANS AND FAIRINGS ARE CORRECTLY INSTALLED.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-804	^S	SHUTDOWN ENGINE - CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-12-01PROC. REF: AMM 12-12-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-805	^S	DO A GENERAL VISUAL INSPECTION OF UNCOVERED AREA UNDER FLOOR, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 06-30-01, AMM 06-30-01, AMM 53-60-00PROC. REF: AMM 06-30-01, AMM 06-30-01, AMM 53-60-00								PKG:1,6,11
05-10-01-210-801	^S	DO A GENERAL VISUAL INSPECTION OF AREA 100, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 06-20-00, AMM 71-10-00, AMM 71-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 71-10-00, AMM 71-10-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-210-802	^S	DO A GENERAL VISUAL INSPECTION OF AREA 200, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-210-803	^S	DO A GENERAL VISUAL INSPECTION OF AREA 210, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-210-804	^S	DO A GENERAL VISUAL INSPECTION OF AREA 300, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 55-10-00, AMM 55-20-00, AMM 55-30-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 55-10-00, AMM 55-20-00, AMM 55-30-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-210-805	^S	DO A GENERAL VISUAL INSPECTION OF AREA 500, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-210-806	^S	DO A GENERAL VISUAL INSPECTION OF AREA 600, INCLUDING VISIBLE HOSES.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-210-807	^S	DO A GENERAL VISUAL INSPECTION OF AREA 700, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 06-20-00, AMM 32-00-00, AMM 32-10-00PROC. REF: AMM 06-20-00, AMM 32-00-00, AMM 32-10-00								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-860-801	^S	DISCONNECT THE GROUND POWER UNIT.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-40-00, AMM 24-40-00PROC. REF: AMM 24-40-00, AMM 24-40-00								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-860-802	^S	CONNECT A GROUND POWER UNIT AND ENERGIZE						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-40-00, AMM 24-40-00PROC. REF: AMM 24-40-00, AMM 24-40-00								PKG:1,5,6,7,8,9 ,10 ,11
05-12-01-710-801	^S	START ENGINE WITH GROUND POWER UNIT THEN MAKE GROUND POWER UNIT DISCONNECT - DO A MAINTENANCE RUN-UP. FILL ALL FILES OF MAINTENANCE RUN-UP.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02), AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02), AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00								PKG:1,5,6,7,8,9 ,10 ,11
05-12-01-710-802	^S	DO A MAINTENANCE RUN-UP - FILL ALL FILES OF MAINTENANCE RUN-UP.						Service ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02), AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02), AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-12-01-715-801	PERFORM MAINTENANCE RUN-UP							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
WC#: 05.020	AFL	0						
PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02)PROC. REF: TLMC 05-12-01 (01), TLMC 05-12-01 (02)								
05-12-02-710-801 ^S	PERFORM A POST INSPECTION FLIGHT. FILL ALL FILES OF POST INSPECTION FLIGHT							Service ATA:05
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	AFL	612						
PROC. REF: TLMC 05-12-02 (01), TLMC 05-12-02 (02)PROC. REF: TLMC 05-12-02 (01), TLMC 05-12-02 (02)								PKG:11,12
05-12-02-715-802	PERFORM TEST FLIGHT							Service ATA:05
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
WC#: 05.030	AFL	612						
PROC. REF: TLMC 05-12-02 (01), TLMC 05-12-02 (02)PROC. REF: TLMC 05-12-02 (01), TLMC 05-12-02 (02)								
05-20-01	STANDARD PROGRAM - FIRST INSPECTION							Package ATA:05
	MOS/MSC	21-Jan-19	-					
	HRS	103.1		Adj -3.1				
WC#: 05.040	AFL	68						
PROC. REF: TLMC 05-20-01PROC. REF: TLMC 05-20-01								PKG:1
05-20-02	STANDARD PROGRAM - A INSPECTION							Package ATA:05
	MOS	15-Oct-24	12 (+1m/-1m)	Adj -73d	03-Aug-25	03-Sep-25	59 d (+31)	
	HRS	834	200 (+10/-10)		1034	1044	144.4 (+10)	
	AFL	612						
PROC. REF: TLMC 05-20-02PROC. REF: TLMC 05-20-02								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-20-03	STANDARD PROGRAM - B INSPECTION							Package ATA:05
	MOS	15-Oct-24	24 (+1m/-1m)	Adj -73d	03-Aug-26	03-Sep-26	424 d (+31)	
	HRS	834	400 (+10/-10)		1234	1244	344.4 (+10)	
	AFL	612						
PROC. REF: TLMC 05-20-03PROC. REF: TLMC 05-20-03								PKG:10
05-20-04	STANDARD PROGRAM - C INSPECTION							Package ATA:05
	MOS	03-Aug-22	48 (+1m/-1m)		03-Aug-26		424 d	
	HRS	607.6	800 (+10/-10)	Adj -118.8	1288.8		399.2	
	AFL							
PROC. REF: TLMC 05-20-04PROC. REF: TLMC 05-20-04								PKG:11
05-20-05	ANNUAL INSPECTION							Package ATA:05
	MOS	15-Oct-24	12		31-Oct-25		148 d	
	HRS	834						
	AFL	612						
PROC. REF: TLMC 05-20-05PROC. REF: TLMC 05-20-05								PKG:12
05-50-01-601-801	INSPECTION - CHECK AFTER A HARD LANDING							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: TLMC 05-50-01PROC. REF: TLMC 05-50-01								
05-50-02-601-801	INSPECTION - CHECK AFTER FLIGHT IN SEVERE AIR TURBULENCE OR WITH SEVERE MANEUVERS							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: TLMC 05-50-02PROC. REF: TLMC 05-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-03-601-801	INSPECTION - CHECK AFTER LIMITATION OVERSHOOTS							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: TLMC 05-50-03PROC. REF: TLMC 05-50-03								
05-50-04-601-801	INSPECTION - CHECK AFTER A LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: TLMC 05-50-04PROC. REF: TLMC 05-50-04								
05-50-05-601-801	INSPECTION - CHECK AFTER PROPELLER TOUCH-DOWN							Service ATA:05
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: TLMC 05-50-05PROC. REF: TLMC 05-50-05								
05-70-CA-890-801	NO. 1 ENGINE - MINOR INSPECTION							Package ATA:05
	MOS	15-Oct-24	12 (+1m)	Adj -40d	05-Sep-25	05-Oct-25	92 d (+30)	
	HRS	834	200 (+10)		(1034) 1034	1044	144.4 (+10)	
	ENC	612						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 07 - LIFTING AND SHORING								
07-10-00-580-801	^S	JACK-UP THE AIRCRAFT						Service ATA:07
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 07-10-00PROC. REF: AMM 07-10-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 07 - LIFTING AND SHORING								
07-10-00-580-802	^S	LOWER THE AIRCRAFT TO GROUND AND REMOVE THE JACKS.						Service ATA:07
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 07-10-00PROC. REF: AMM 07-10-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 08 - LEVELING AND WEIGHING								
08-10-00-970-801		PERFORM A WEIGHT AND BALANCE						Service ATA:08
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
WC#: 08.010	AFL	0						
PROC. REF: AMM 08-10-00PROC. REF: AMM 08-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-100-801	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED UP TO A MONTH							Service ATA:10
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
10-10-00-100-802	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED FROM 1 TO 6 MONTHS							Service ATA:10
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
10-10-00-100-803	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED MORE THAN 6 MONTHS							Service ATA:10
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
ATA 11 - PLACARDS AND MARKINGS								
11-00-00-701-801	PAINT AIRCRAFT							Service ATA:11
	MOS/MSC	03-Jul-18	-					MANDATORY
	HRS	0						
WC#: 11.010	AFL	0						
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM								
11-21-00-210-801 ^S	PLACARDS AND MARKINGS, AREA 100 - ENSURE PRESENCE AND READABILITY.							Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-21-00PROC. REF: AMM 11-21-00								
PKG:12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
11-22-00-210-801	^S	EXTERIOR PLACARDS AND MARKINGS, AREA 200 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-22-00PROC. REF: AMM 11-22-00								PKG:12
11-22-01-210-801	^S	PLACARDS AND MARKINGS, AREA 210 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
11-23-00-210-801	^S	PLACARDS AND MARKINGS, AREA 300 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-23-00PROC. REF: AMM 11-23-00								PKG:12
11-24-00-210-801	^S	PLACARDS AND MARKINGS, AREA 500 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-24-00PROC. REF: AMM 11-24-00								PKG:12
11-24-00-210-802	^S	PLACARDS AND MARKINGS, AREA 600 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-24-00PROC. REF: AMM 11-24-00								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
11-25-00-210-801	^S	PLACARDS AND MARKINGS, AREA 700 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: AMM 11-25-00PROC. REF: AMM 11-25-00								PKG:12
ATA 12 - SERVICING								
11-30-00-210-801	^S	INTERIOR PLACARDS AND MARKINGS, AREA 200 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
ATA 12 - SERVICING								
12-21-00-640-801	^S	LUBRICATION OF EXTERNAL ACCESS AND INSPECTION DOORS. LUBRICATE EXTERNAL DOOR HINGES						Service ATA:12
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
WC#: 12.010	AFL	612						
PROC. REF: AMM 12-21-03, AMM 12-21-02, AMM 12-21-02PROC. REF: AMM 12-21-03, AMM 12-21-02, AMM 12-21-02								PKG:8,10 ,11
12-21-00-640-802		PROTECTION OF EXTERNAL FITTINGS						Service ATA:12
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 12.020	AFL	0						
PROC. REF: AMM 12-21-04, AMM 12-21-03PROC. REF: AMM 12-21-04, AMM 12-21-03								
12-21-01-640-801	^S	LUBRICATE AREA 100						Service ATA:12
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-01, AMM 12-21-01PROC. REF: AMM 12-21-01, AMM 12-21-01								PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
12-21-02-640-801	^S	LUBRICATE AREA 200						Service ATA:12
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-02, AMM 12-21-02PROC. REF: AMM 12-21-02, AMM 12-21-02								PKG:6,9 ,10 ,11
12-21-03-640-801	^S	LUBRICATE AREA 300						Service ATA:12
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6,9 ,10 ,11
12-21-04-640-802	^S	LUBRICATE AREA 500						Service ATA:12
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:5,6,7,8,9 ,10 ,11
12-21-04-640-803	^S	LUBRICATE AREA 600						Service ATA:12
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:5,6,7,8,9 ,10 ,11
12-21-05-640-801	^S	LUBRICATE AREA 700						Service ATA:12
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								PKG:8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-00-00-200-801	^S	POWER PLANT COMPARTMENT - CHECK CLAMPS FOR CONDITION AND ATTACHMENT ON HOSES AND RIGID PIPES. CHECK FOR DAMAGE. CHECK THE HEAT EXCHANGER, VALVES, SENSORS AND SWITCHES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE					Service	ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,5,11
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								
21-00-00-200-802	^S	PRESSURIZED FUSELAGE SECTION - CHECK VENTILATION HOSES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE. CHECK EVAPORATORS ASSY, SENSORS AND SWITCHES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE					Service	ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								
21-00-00-200-803	^S	NON PRESSURIZED FUSELAGE SECTION - CHECK CLAMPS FOR CONDITION AND ATTACHMENT ON HOSES AND RIGID PIPES. CHECK FOR DAMAGE. CHECK THE CONDENSER ASSY, SENSOR AND DRIER FILTER FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE					Service	ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								
21-00-00-710-801	^S	AIR CONDITIONING - DO AN OPERATIONAL TEST					Service	ATA:21
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00								
21-00-01-210-801	^S	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR ATTACHMENT					Service	ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:5,6,7,8,11
PROC. REF: AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-01, AMM 21-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-00-01-710-801	^S	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR CORRECT MECHANICAL OPERATION						Service ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-01, AMM 21-00-01								PKG:5,6,7,8,11
21-20-00-200-802	^S	WINDSHIELD AND SIDE WINDOWS DEFOGGING OUTLETS - CHECK FOR CLOGGING						Service ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00, AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00, AMM 21-00-01, AMM 21-00-01								PKG:5,6,7,8,11
21-20-02-710-801	^S	EMERGENCY AIR CONTROL - CHECK CONTROL MECHANICAL OPERATION						Service ATA:21
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								PKG:1,5,6,7,8,11
21-30-00-900-801		PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 1						Component ATA:21
PN:T700A2130025004	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801		PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 2						Component ATA:21
PN:T700A2130025009	MOS	01-Oct-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801		PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 1						Component ATA:21
PN:T700A213002501300	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30-00-900-801	PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 2							Component ATA:21
PN:T700A213002501200	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801	PRESSURIZATION SAFETY HOSE							Component ATA:21
PN:T700A2130025006	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM								
21-30-02-100-801	OUTFLOW VALVE - CLEAN VALVE SEATS							Service ATA:21
	MOS	15-Oct-24	24 (+10%/-10%)		15-Oct-26	27-Dec-26	497 d (+73)	
	HRS	834						
WC#: 21.030	AFL	612						
PROC. REF: AMM 21-30-03, AMM 21-30-02PROC. REF: AMM 21-30-03, AMM 21-30-02								
21-30-02-900-801	OUTFLOW VALVE							Component ATA:21
PN:81144A010101	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:81144-00262	HRS	0		TSN 0				
WC#: 21.030	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								
21-30-03-100-802	SAFETY VALVE - CLEAN VALVE SEATS							Service ATA:21
	MOS	15-Oct-24	24 (+10%/-10%)		15-Oct-26	27-Dec-26	497 d (+73)	
	HRS	834						
WC#: 21.040	AFL	612						
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
21-30-03-900-801	SAFETY VALVE							Component ATA:21
PN:81145A010101	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:81145-00258	HRS	0		TSN 0				
WC#: 21.040	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
21-30-03-960-801	SAFETY VALVE - REPLACE THE FILTER							Service ATA:21
	MOS	03-Jul-18						
	HRS	0	2400		2400		1510.4	
WC#: 21.040	AFL	0						
PROC. REF: AMM 21-30-03, AMM 21-30-03PROC. REF: AMM 21-30-03, AMM 21-30-03								
21-30-05-900-801	CABIN ALT ALARM SWITCH							Component ATA:21
PN:214C40.3.261	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:11038662A	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: AMM 21-30-05, AMM 21-30-05PROC. REF: AMM 21-30-05, AMM 21-30-05								
21-30-08-900-801	CABIN ALT SENSOR							Component ATA:21
PN:CP0304	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:581	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: AMM 21-30-08PROC. REF: AMM 21-30-08								
21-41-01-900-801	NO. 1 LIEBHERR KIT							Component ATA:21
PN:20286-102	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:258	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-41-02-900-801	NO. 2 LIEBHERR KIT							Component ATA:21
PN:20286-201	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:520	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-41-03-900-801	NO. 3 LIEBHERR KIT							Component ATA:21
PN:20286-304	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:201	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-50-01-900-801 PRESSURE REGULATING AND SHUT OFF VALVE								Component ATA:21
PN:6784A010001	MOS/MSC	12-Oct-22	O/C	TSR 24				
SN:6784-00636	HRS	617		TSR 0				
WC#: 21.260	AFL	407		TSR 0				
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01								
21-50-03-900-801 HEAT EXCHANGER								Component ATA:21
PN:81249A010001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:81249-00605	HRS	0		TSN 0				
WC#: 21.070	AFL	0		TSN 0				
PROC. REF: AMM 21-50-03, AMM 21-50-03PROC. REF: AMM 21-50-03, AMM 21-50-03								
21-50-71-900-801 CABIN DELTA P WARN SWITCH								Component ATA:21
PN:17-600-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B0775	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-55-01-200-801 ^S COMPRESSOR BELT- CHECK CONDITION								Service ATA:21
PN:6046297261	MOS	15-Oct-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	834	200 (+1/-10)					
	AFL	612						
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								PKG:1,5,6,7,8,9 ,10 ,11
21-55-01-820-801 ^S COMPRESSOR BELT - CHECK TENSION								Service ATA:21
PN:6046297261	MOS	15-Oct-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-55-01-900-801		COMPRESSOR						Component ATA:21
PN:1377A010001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1377-00650	HRS	0		TSN 0				
WC#: 21.170	AFL	0		TSN 0				
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								
21-55-01-900-802		COMPRESSOR BELT - REPLACE						Service ATA:21
PN:6046297261	MOS	22-Jul-21						SCRAP
SN:UNKNOWN	HRS	488.9	600		1088.9		199.3	
	AFL							
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								
21-55-01-900-803		FREON COMPRESSOR BELT						Component ATA:21
PN:6046297261	MOS/MSC	22-Jul-21	H/T	TSN 0				
SN:UNKNOWN	HRS	488.9		TSN 0				
WC#: 21.110	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-55-02-900-801		CONDENSER						Component ATA:21
PN:81250A010001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:81250-00613	HRS	0		TSN 0				
WC#: 21.180	AFL	0		TSN 0				
PROC. REF: AMM 21-55-02PROC. REF: AMM 21-55-02								
21-60-31-900-801		GENERAL AIR SYSTEM CONTROLLER						Component ATA:21
PN:82024A040801	MOS/MSC	05-Sep-23	O/C	TSN 62, TSR 0				
SN:82024-00630	HRS	688.8		TSN 688.8, TSR 0				
	AFL			TSR 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
219000 ^U		CABIN EVAPORATOR						Component ATA:21
PN:3733A010001	MOS/MSC	23-Feb-23	O/C	TSN 0				
SN:3187R	HRS	661.6		TSN 0				
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-00-200-802	^S	AUTOPILOT - PERFORM A VISUAL INSPECTION						Service ATA:22
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 22-11-00, AMM 22-11-00, AMM 22-11-00, AMM 22-11-00PROC. REF: AMM 22-11-00, AMM 22-11-00, AMM 22-11-00, AMM 22-11-00								PKG:6,11
22-11-00-200-803	^S	B35, B36, B37 AND B38 SERVO-ACTUATORS - CHECK CABLES FOR CONDITION.VERIFY THE PULLEYS TO MAKE SURE OF THE ABSENCE OF SETAND OF DETERIORATION (EXCEPT MARKING IN BOTTOM OFTHROAT)						Service ATA:22
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 22.020	AFL	612						
PROC. REF: AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 20-10-04, AMM 20-10-05								PKG:12
22-11-00-710-801	^S	B35, B36, B37 AND B38 SERVO-ACTUATORS - PERFORM A SLIP CLUTCH MANUAL OVERRIDE.						Service ATA:22
	MOS	15-Oct-24	12					
	HRS	834						
	AFL	612						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								PKG:12
22-11-00-720-803		B35, B36, B37 AND B38 SERVO ACTUATORS - CHECK CLUTCH FRICTION TORQUES.						Service ATA:22
	MOS	03-Jul-18						
	HRS	0	3000 (+10%/-10%)		3000	3300	2110.4 (+300)	
	AFL	0						
PROC. REF: AMM 22-11-00, AMM 22-11-00PROC. REF: AMM 22-11-00, AMM 22-11-00								
22-11-00-820-801	^S	B35,B36 AND B37 SERVO ACTUATORS - CHECK CABLE TENSION						Service ATA:22
	MOS	15-Oct-24	12					
	HRS	834						
	AFL	612						
PROC. REF: AMM 22-11-03, AMM 22-11-04, AMM 22-11-05PROC. REF: AMM 22-11-03, AMM 22-11-04, AMM 22-11-05								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-01-900-801		AUTO PILOT CONTROLLER					Component	ATA:22
PN:011-01020-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:22008579	HRS	0		TSN 0				
WC#: 22.190	AFL	0		TSN 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-03-900-801		ROLL SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1A1020091	HRS	0		TSN 0				
WC#: 22.110	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03								
22-11-03-900-802		ROLL SERVO MOUNT					Component	ATA:22
PN:011-01904-03	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:28K008230	HRS	0		TSN 0				
WC#: 22.170	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03								
22-11-04-900-801		PITCH SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1A1020071	HRS	0		TSN 0				
WC#: 22.030	AFL	0		TSN 0				
PROC. REF: AMM 22-11-04, AMM 22-11-04, AMM 22-11-04, AMM 22-11-04PROC. REF: AMM 22-11-04, AMM 22-11-04, AMM 22-11-04, AMM 22-11-04								
22-11-05-900-801		YAW SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1A1020034	HRS	0		TSN 0				
WC#: 22.040	AFL	0		TSN 0				
PROC. REF: AMM 22-11-05, AMM 22-11-05PROC. REF: AMM 22-11-05, AMM 22-11-05								
22-11-05-900-802		YAW SERVO MOUNT					Component	ATA:22
PN:011-01904-03	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:28K008261	HRS	0		TSN 0				
WC#: 22.160	AFL	0		TSN 0				
PROC. REF: AMM 22-11-05, AMM 22-11-05PROC. REF: AMM 22-11-05, AMM 22-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-06-900-801	PITCH SERVO MOUNT							Component ATA:22
PN:011-01904-03	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:28K008284	HRS	0		TSN 0				
WC#: 22.150	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-06-900-802	PITCH TRIM SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1A1020095	HRS	0		TSN 0				
WC#: 22.100	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-06-900-803	PITCH TRIM SERVO MOUNT							Component ATA:22
PN:011-01904-03	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:28K008266	HRS	0		TSN 0				
WC#: 22.180	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-14-900-801	TRIM ADAPTER							Component ATA:22
PN:011-00960-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:66904787	HRS	0		TSN 0				
WC#: 22.210	AFL	0		TSN 0				
PROC. REF: AMM 22-11-14, AMM 22-11-14PROC. REF: AMM 22-11-14, AMM 22-11-14								
ATA 23 - COMMUNICATIONS								
23-00-00-710-801	COMMUNICATION EQUIPMENT - DO AN OPERATIONAL TEST.							Service ATA:23
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
WC#: 23.010	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
23-10-06-900-801	GSR56 UNIT							Component ATA:23
PN:011-02268-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1NZ007458	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-10-21-900-801		NO. 1 VHF COMMUNICATION/NAV AND GPS UNIT					Component	ATA:23
PN:011-01105-40	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:2DC003951	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-10-21-900-801		NO. 2 VHF COMMUNICATION/NAV AND GPS UNIT					Component	ATA:23
PN:011-01105-40	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:2DC003965	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-11-01-900-801		NO. 1 AUDIO CONTROL PANEL					Component	ATA:23
PN:011-01257-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:17108960	HRS	0		TSN 0				
WC#: 22.220	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01, AMM 23-11-01PROC. REF: AMM 23-11-01, AMM 23-11-01								
23-11-01-900-802		NO. 2 AUDIO CONTROL PANEL					Component	ATA:23
PN:011-01257-20	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:17108966	HRS	0		TSN 0				
WC#: 22.220	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01, AMM 23-11-01PROC. REF: AMM 23-11-01, AMM 23-11-01								
23-12-02-900-801		NO. 1 AERIAL BLADE ANTENNA					Component	ATA:23
PN:16-21B-P3	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:50757	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-12-02-900-801		NO. 2 AERIAL BLADE ANTENNA					Component	ATA:23
PN:16-21B-P3	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:50752	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-21-02-900-801	IRIDIUM ANTENNA							Component ATA:23
PN:CI490-490	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:563539	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-60-00-210-801 ^S	STATIC DISCHARGERS - CHECK FOR CONDITION							Service ATA:23
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:1,5,6,7,8,9 ,10 ,11
23-60-00-760-801 ^S	STATIC DISCHARGERS - CHECK FOR RESISTANCE AND CONTINUITY							Service ATA:23
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 23-60-00, AMM 23-60-00, AMM 23-60-00PROC. REF: AMM 23-60-00, AMM 23-60-00, AMM 23-60-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 24 - ELECTRICAL POWER								
24-00-00-200-801 ^S	ELECTRICAL HARNESSSES, AREA 100 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.							Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,5,11
24-00-00-200-802 ^S	ELECTRICAL HARNESSSES, AREA 200 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.							Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-00-00-200-803	^S	ELECTRICAL HARNESSSES, AREA 210 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,5,11
24-00-00-200-804	^S	ELECTRICAL HARNESSSES, AREA 300 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,6,11
24-00-00-200-805	^S	ELECTRICAL HARNESSSES, AREA 500 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,7,11
24-00-00-200-806	^S	ELECTRICAL HARNESSSES, AREA 600 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,7,11
24-00-00-200-807	^S	ELECTRICAL HARNESSSES, AREA 700 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:1,8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-00-00-200-808	^S	POWER PLANT / FIREWALL GROUND CABLE - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:5,11
24-30-02-200-802	^S	ELECTRICAL POWER SYSTEM - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE OR LOOSE CONNECTIONS						Service ATA:24
	MOS	15-Oct-24	24 (+1d/-1d)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-30-02, AMM 24-30-02PROC. REF: AMM 24-30-02, AMM 24-30-02								PKG:1,5,10 ,11
24-30-02-900-804		ELECTRICAL POWER SYSTEM BOX						Component ATA:24
PN:1408-1-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:274	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-02, AMM 24-30-02PROC. REF: AMM 24-30-02, AMM 24-30-02								
24-30-03-200-803	^S	STARTER GENERATOR - CHECK FOR ATTACHMENT, CLEANLINESS OF CONNECTION TERMINAL BLOCK AND ELECTRICAL CONNECTIONS AND EVIDENCE OF OVERHEAT, ARCING AND DAMAGE. CHECK COVER FOR CONDITION. ENSURE GOOD CONDITION OF CLAMP AND SECTOR. CHECK FOR CRACKS. CHECK R701 SHUNT FOR CONDITION.						Service ATA:24
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								PKG:5,10 ,11
24-30-03-200-804	^S	STARTER GENERATOR DRIVE PAD - CHECK DRAIN LINE FOR CONDITION AND CHECK FOR LEAKS AT MOUNTING INTERFACE.						Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								PKG:1,5,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-03-730-803	STARTER/GENERATOR - OVERHAUL							Component ATA:24
PN:MG94K-1	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:265	HRS	0	1500 (+10%/-10%)	TSN 0	1500	1650	610.4 (+150)	
WC#: 24.030	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								
24-30-04-200-801 ^S	BATTERY CABLES - CHECK CABLES AND CONNECTORS FOR CORROSION AND EVIDENCE OF DAMAGE. CHECK FOR CLEANLINESS, EVIDENCE OF CORROSION AND CRACKS ON FIREWALL ATTACHMENTS. CHECK CONNECTIONS AND F100 FUSE FOR CONDITION							Service ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:5,11
PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04								
24-30-04-760-802	LEAD-ACID BATTERY IF INSTALLED - CHECK CAPACITY							Service ATA:24
PN:RG-380E/44	MOS	15-Oct-24	12 (+1m/-1m)		15-Oct-25	15-Nov-25	132 d (+31)	
SN:41405768	HRS	834	200 (+10%/-10%)		1034	1054	144.4 (+20)	
WC#: 24.010	AFL	612						
PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04								
24-30-04-900-801	MAIN BATTERY							Component ATA:24
PN:RG-380E/44	MOS/MSC	15-Oct-24	O/C	TSN 0				
SN:41405768	HRS	834		TSN 0				
WC#: 24.010	AFL	612		TSN 0				
PROC. REF: AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04								
24-30-05-200-802 ^S	STAND-BY GENERATOR BELT - CHECK FOR CONDITION							Service ATA:24
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,7,9 ,10 ,11
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-05-200-803	^S	STAND-BY GENERATOR - CHECK FOR CONDITION AND CONNECTIONS-INSPECT AREA AROUND THE BRUSH HOLDER FOR SOOT.						Service ATA:24
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								PKG:1,5,6,7,8,9 ,10 ,11
24-30-05-730-802		ALTERNATOR - OVERHAUL						Component ATA:24
PN:ES-10024B-5	MOS/MSC	03-Jul-18	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED
SN:H-S023196	HRS	0		TSN 0				
WC#: 24.020	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-06, AMM 24-30-06, AMM 24-30-06PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-06, AMM 24-30-06, AMM 24-30-06								
24-30-05-730-803		ALTERNATOR - OVERHAUL						Service ATA:24
	MOS	03-Jul-18						OVERHAUL
	HRS	0	2000 (+10%/-10%)		2000	2200	1110.4 (+200)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-30-05-820-801	^S	STAND-BY GENERATOR BELT - CHECK TENSION						Service ATA:24
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05								PKG:1,5,7,9 ,10 ,11
24-30-05-900-801		STANDBY GENERATOR BELT - REPLACE						Service ATA:24
PN:PN	MOS	15-Oct-24						LIFE LIMIT
SN:UNKNOWN	HRS	834	600		1434		544.4	
	AFL	612						
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05								
24-30-05-900-803		STANDBY GENERATOR BELT						Component ATA:24
PN:PN	MOS/MSC	15-Oct-24	H/T	TSN 0				
SN:UNKNOWN	HRS	834		TSN 0				
	AFL	612		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-30-06-200-802	^S	STANDBY BY GENERATOR DRIVE - CHECK DRAIN LINES FOR ATTACHMENT AND CONDITION, CHECK FOR LEAKS AT MOUNTING INTERFACE AND MANUALLY CHECK THAT THE SHEAR SHAFT OR THE PULLEY ARE NOT DAMAGED BY MANUALLY ROTATING THE STAND-BY GENERATOR DRIVE PULLEY.					Service	ATA:24
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:5,10 ,11
PROC. REF: AMM 24-30-06PROC. REF: AMM 24-30-06								
24-40-00-200-802	^S	EXTERNAL POWER SUPPLY - CHECK GPU RECEPTACLE FOR ATTACHMENT AND EVIDENCE OF DAMAGE AND CHECK CABLES FOR CONDITION AND CONNECTIONS					Service	ATA:24
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:5,10 ,11
PROC. REF: AMM 24-40-00PROC. REF: AMM 24-40-00								
24-60-01-210-801	^S	PL1 CIRCUIT BREAKER PANEL - CHECK PANEL FOR ATTACHMENT AND CLEANLINESS AND ELECTRICAL COMPONENTS FOR CONDITION.					Service	ATA:24
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,6,11
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-00-210-803	^S	SUN VISOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 25-11-00, AMM 25-11-00PROC. REF: AMM 25-11-00, AMM 25-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-12-00-210-801	^S	COCKPIT SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:1,5,6,7,8,9 ,10 ,11
25-12-00-210-802	^S	COCKPIT BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS.						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:1,5,6,7,8,9 ,10 ,11
25-12-00-710-803	^S	COCKPIT BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION.						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:1,5,6,7,8,9 ,10 ,11
25-12-01-900-801		PILOT SEAT						Component ATA:25
PN:421000-501	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-12-01PROC. REF: AMM 25-12-01								
25-12-02-900-801		COPILOT SEAT						Component ATA:25
PN:421000-502	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-12-01, AMM 25-12-02PROC. REF: AMM 25-12-01, AMM 25-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-00-210-801	^S	STORAGE CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-802	^S	FOLDING TABLE, IF INSTALLED - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-803	^S	AUDIO CABINET, IF INSTALLED - CHECK ELECTRICAL COMPONENTS FOR ATTACHMENT AND CONDITION.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-804	^S	REFRESHMENT CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-805	^S	UPHOLSTERING PANELS - CHECK ATTACHMENT AND CONDITION.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-00-210-806	^S	CABIN WINDOW CURTAINS - CHECK CONDITION AND OPERATION.						Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-05-710-801	^S	TOILETS, REAR BAGGAGE COMPARTMENT, IF INSTALLED - DO AN OPERATIONAL TEST.						Service ATA:25
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								PKG:6,10 ,11
25-22-00-210-801	^S	PASSENGERS SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION. CHECK THAT PASSENGERS SEATS ARE INSTALLED IN CORRECT PAINT MARKS LOCATIONS.						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00								PKG:1,5,6,7,8,9 ,10 ,11
25-22-00-210-802	^S	PASSENGERS BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS.						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00								PKG:1,5,6,7,8,9 ,10 ,11
25-22-00-710-803	^S	PASSENGERS BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION.						Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-22-01-900-801	LEFT PASSENGER SEAT							Component ATA:25
PN:424000-501	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.050	AFL	0		TSN 0				
PROC. REF: AMM 25-22-01, AMM 25-22-01PROC. REF: AMM 25-22-01, AMM 25-22-01								
25-22-01-900-801	RIGHT PASSENGER SEAT							Component ATA:25
PN:424000-502	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.050	AFL	0		TSN 0				
PROC. REF: AMM 25-22-01, AMM 25-22-01PROC. REF: AMM 25-22-01, AMM 25-22-01								
25-22-02-900-802	LEFT REAR BENCH							Component ATA:25
PN:422000-505	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
PROC. REF: AMM 25-22-02PROC. REF: AMM 25-22-02								
25-22-02-900-802	RIGHT REAR BENCH							Component ATA:25
PN:422000-506	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
PROC. REF: AMM 25-22-02PROC. REF: AMM 25-22-02								
25-50-00-610-801 ^S	FUSE AND BULB BOX - COMPLETE IF NECESSARY.							Service ATA:25
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:5,11
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
25-61-00-200-801 ^S	EMERGENCY LOCATOR TRANSMITTER - CHECK FOR ATTACHMENT AND POSITION OF FUNCTION SWITCH. MAKE SURE THERE ARE NO LEAKS AND NO CORROSION AT BATTERY. CHECK ANTENNA FOR ATTACHMENT AND CONNECTION.							Service ATA:25
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-61-00, AMM 25-61-00PROC. REF: AMM 25-61-00, AMM 25-61-00								
25-61-00-200-804 ^S EMERGENCY LOCATOR TRANSMITTER - CHECK BATTERY REPLACEMENT DATE Service ATA:25								
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PKG:1,5,6,7,8,9 ,10 ,11								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-61-00-710-806 EMERGENCY LOCATOR TRANSMITTER - DO AN OPERATIONAL TEST AND RECORD OPERATING TIME Service ATA:25								
PN:8201	MOS	15-Oct-24	12 (+1m/-1m)		15-Oct-25	15-Nov-25	132 d (+31)	
SN:251-10603	HRS	834						
WC#: 25.020	AFL	612						
PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-01PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-01								
25-61-00-900-803 EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE Service ATA:25								
PN:452-6504-1	MOS/MSC	15-Oct-24	DUE		01-Aug-28 (M)		1153 d	LIFE LIMIT
SN:1003611-005	HRS	834						
WC#: 25.030	AFL							
Expiry Date: : 01-Aug-28								
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01								
25-61-01-900-811 EMERGENCY LOCATOR TRANSMITTER Component ATA:25								
PN:8201	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:251-10603	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01								
25-61-01-900-821 EMERGENCY LOCATOR TRANSMITTER BATTERY Component ATA:25								
PN:452-6504-1	MOS/MSC	15-Oct-24	O/C	TSN 0				
SN:1003611-005	HRS	834		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-02-900-801	EMERGENCY LOCATOR TRANSMITTER ANTENNA							Component ATA:25
PN:110-338	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:560608	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 26 - FIRE PROTECTION								
26-10-00-200-801 ^S	FIRE DETECTION, IF INSTALLED - CHECK DETECTORS AND WIRINGS FOR CONDITION AND ATTACHMENT.							Service ATA:26
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20-01-200-802	AIR TOTAL FIRE EXTINGUISHER, IF INSTALLED - CHECK FOR WEIGHT AND PRESSURE							Service ATA:26
PN:74-00	MOS	15-Oct-24	24 (+10%/-10%)	15-Oct-26	27-Dec-26	497 d (+73)		
SN:A030522	HRS	834						
	AFL							
WeightCheck Date : : 15-Oct-24								
PROC. REF: AMM 26-20-01PROC. REF: AMM 26-20-01								
26-20-01-730-801	AIR-TOTAL FIRE EXTINGUISHER PORTABLE - OVERHAUL							Service ATA:26
PN:74-00	MOS	01-Mar-18	120 (+10%/-10%)	01-Mar-28	01-Mar-29	1000 d (+365)	OVERHAUL	
SN:A030522	HRS							
	AFL							
Manufacture Date:: 01-Mar-18								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20-01-900-803	AIR-TOTAL FIRE EXTINGUISHER PORTABLE							Component ATA:26
PN:74-00	MOS/MSC	01-Mar-18	H/T	TSN 0				
SN:A030522	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 26-20-01PROC. REF: AMM 26-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-801	^S	AILERON TRIM TAB ACTUATOR RODS - VISUALLY CHECK THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11
27-10-00-200-802	^S	AILERON CONTROL INBOARD AND OUTBOARD L.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								PKG:7,10 ,11
27-10-00-200-803	^S	AILERON CONTROL INBOARD AND OUTBOARD R.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								PKG:7,10 ,11
27-10-00-200-804	^S	L.H. AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:1,7,11
27-10-00-200-805	^S	R.H. AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:1,7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-806	^S	L.H. AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:1,7,11
27-10-00-200-807	^S	R.H. AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:1,7,11
27-10-00-200-808	^S	SPOILER CABLE ASSEMBLY IN FUSELAGE - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:1,6,11
27-10-00-200-809	^S	SPOILER AND AILERON CABLE ASSEMBLY ON L.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:1,7,11
27-10-00-200-810	^S	SPOILER AND AILERON CABLE ASSEMBLY ON R.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:1,7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-811	^S	AILERON CONTROL INBOARD AND OUTBOARD L.H. BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:7,11
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								
27-10-00-200-812	^S	AILERON CONTROL INBOARD AND OUTBOARD R.H. BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:7,11
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								
27-10-00-200-813	^S	L.H. WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,7,11
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								
27-10-00-200-814	^S	R.H. WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,7,11
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								
27-10-00-720-801	^S	AILERON TRIM TAB - CHECK TRAVEL					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.030	AFL							
								PKG:8,11
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-720-802	^S	AILERONS AND SPOILERS - CHECK TRAVEL					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.010	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:8,11
27-10-00-720-803	^S	CONTROL WHEEL ASSEMBLY - CHECK FOR SLACK AND FRICTION POINTS IN AILERON CONTROL.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:6,11
27-10-00-820-801	^S	SPOILER AND AILERON CABLE ASSEMBLY ON WING - CHECK CABLE TENSION AND SAFETYING OF TURNBUCKLES					Service	ATA:27
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 27.020	AFL	612						
PROC. REF: AMM 27-10-00, AMM 27-10-00PROC. REF: AMM 27-10-00, AMM 27-10-00								PKG:12
27-10-02-210-801	^S	L.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,7,10 ,11
27-10-02-210-802	^S	R.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:1,7,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-02-210-803	^S	L.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								PKG:7,10 ,11
27-10-02-210-804	^S	R.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								PKG:7,10 ,11
27-10-04-900-801		LEFT AILERON TRIM TAB ACTUATOR					Component	ATA:27
PN:145700.02	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:F03358	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								
27-20-00-200-801	^S	RUDDER LEVER AND ROD ASSEMBLY - CHECK ATTACHMENT, CONDITION OF LEVER BALL JOINT AND SAFETYING OF ROD HINGES. CHECK THAT THE TWO STOP SCREWS CANNOT BE SCREWED OR UNSCREWED MANUALLY.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:1,6,11
27-20-00-200-802	^S	RUDDER CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 20-10-04, AMM 20-10-05, AMM 27-20-00PROC. REF: AMM 20-10-04, AMM 20-10-05, AMM 27-20-00								PKG:1,6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20-00-720-801	^S	RUDDER TRIM TAB - CHECK TRAVEL						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.060	AFL							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:8,11
27-20-00-720-802	^S	RUDDER - CHECK TRAVEL						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.040	AFL							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:8,11
27-20-00-820-801	^S	RUDDER CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES						Service ATA:27
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 27.050	AFL	612						
PROC. REF: AMM 27-20-00, AMM 27-20-00PROC. REF: AMM 27-20-00, AMM 27-20-00								PKG:12
27-20-01-710-801	^S	RUDDER PEDALS - CHECK FREE MOVEMENT OF RUDDER PEDALS AND CORRECT OPERATION OF RUDDER PEDAL POSITION ADJUSTING CONTROLS FOR THE PILOT AND RIGHT STATIONS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:5,6,7,8,11
27-20-04-200-801	^S	RUDDER TRIM TAB ACTUATOR - VISUALLY CHECK FOR CONDITION AND ATTACHMENT. VISUALLY ENSURE THAT THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20-04-900-801	B32 RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:T700A2720018000	MOS/MSC	27-Aug-20	O/C	TSN 0				
SN:F14799	HRS	393.8		TSN 0				
WC#: 27.120	AFL			TSN 0				
PROC. REF: AMM 27-20-04PROC. REF: AMM 27-20-04								
27-30-00-200-801	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK FOR CONDITION, ATTACHMENT AND BALL JOINTS ON BELLCRANKS AND LEVERS. CHECK THAT STOP SCREWS ON HINGE BEARING CANNOT BE SCREWED OR UNSCREWED MANUALLY. CHECK SAFETYING OF ROD HINGES.							Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,6,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								
27-30-00-200-802	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK CONDITION AND ATTACHMENT OF ROD, SLEEVE AND FOR CRACKS ON PRESSURE BULKHEAD C17.							Service ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:6,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								
27-30-00-710-801	ELEVATOR TRIM TABS EMERGENCY MANUAL CONTROL - TURN TRIM WHEEL AND CHECK FREE MOVEMENT AND OPERATION OF INDICATOR.							Service ATA:27
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								
27-30-00-720-801	ELEVATORS - CHECK TRAVEL							Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.070	AFL							
								PKG:8,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30-00-720-802	^S	ELEVATOR TRIM TABS - CHECK TRAVEL						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.080	AFL							
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:8,11
27-30-00-820-801	^S	ELEVATOR TRIM TAB CONTROL CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES						Service ATA:27
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 27.080	AFL	612						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:12
27-30-01-900-801		PILOT CONTROL WHEEL						Component ATA:27
PN:83912112	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:218	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01, AMM 27-30-01PROC. REF: AMM 27-30-01, AMM 27-30-01								
27-30-01-900-802		COPILOT CONTROL WHEEL						Component ATA:27
PN:83912113	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:218	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01, AMM 27-30-01PROC. REF: AMM 27-30-01, AMM 27-30-01								
27-30-03-200-801	^S	ELEVATOR TRIM TAB CONTROL CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05								PKG:1,6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30-03-200-802	^S	ELEVATOR TRIM TAB CONTROL CABLES - CHECK CONDITION OF SCREW JACK CHAINS. CHECK ATTACHMENT AND SAFETYING OF LINKS THAT CONNECT CABLES TO CHAINS. EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:1,6,11
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05								
27-30-04-200-801	^S	ELEVATOR TRIM TAB ACTUATORS - CHECK RODS FOR CONDITION AND NO SLACK. VISUALLY CHECK ATTACHMENTS ON REAR SPAR OF FIXED HORIZONTAL STABILIZER.						Service ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:6,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								
27-30-04-900-801		LEFT ELEVATOR TRIM TAB ACTUATOR						Component ATA:27
PN:145400.02	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:F04347	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
PROC. REF: AMM 27-30-04, AMM 27-30-04PROC. REF: AMM 27-30-04, AMM 27-30-04								
27-30-04-900-801		RIGHT ELEVATOR TRIM TAB ACTUATOR						Component ATA:27
PN:145400.02	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:F04346	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
PROC. REF: AMM 27-30-04, AMM 27-30-04PROC. REF: AMM 27-30-04, AMM 27-30-04								
27-50-00-200-801	^S	FLAP CONTROL, L.H. BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS						Service ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:7,10 ,11
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-00-200-802	^S	FLAP CONTROL, R.H. BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-200-803	^S	GEARED MOTOR - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:6,11	
27-50-00-200-804	^S	FLAP CONTROLS, INBOARD AND OUTBOARD L.H. ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-200-805	^S	FLAP CONTROLS, INBOARD AND OUTBOARD R.H. ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-720-801	^S	FLAPS - CHECK TRAVELS					Service	ATA:27
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
WC#: 27.090	AFL							
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:8,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-01-900-801		FLAP MOTOR					Component	ATA:27
PN:6157-1	MOS/MSC	10-Apr-23	O/C	TSR 36				
SN:868V	HRS	664.7		TSR 0				
WC#: 27.100	AFL	530		TSR 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-50-02-900-801		LEFT INNER FLAP ACTUATOR					Component	ATA:27
PN:1-5295	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:13197	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50-02-900-802		RIGHT INNER FLAP ACTUATOR					Component	ATA:27
PN:2-5295	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1400	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-02-900-803		LEFT OUTER FLAP ACTUATOR					Component	ATA:27
PN:1-5297	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1421	HRS	0		TSN 0				
WC#: 27.150	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-02-900-804		RIGHT OUTER FLAP ACTUATOR					Component	ATA:27
PN:2-5297	MOS/MSC	25-Apr-23	O/C	TSN 0				
SN:1643	HRS	672		TSN 0				
WC#: 27.150	AFL			TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-03-900-801		LEFT WING CENTER CONTROL LINKAGE BEARING					Component	ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6572	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-03-900-801	LEFT WING INBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6569	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	LEFT WING OUTBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6563	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING CENTER CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6557	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING INBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6558	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING OUTBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:6570	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 28 - FUEL								
28-10-00-200-801 ^S	FILLER CAP AND LINES, L.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION.							Service ATA:28
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							

PKG:7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-802	^S	FILLER CAP AND LINES, R.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION.						Service ATA:28
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:7,11
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-803		FLAPPER VALVES - CHECK RUBBER CONDITION						Service ATA:28
	MOS	03-Aug-22	48 (+10%/-10%)		03-Aug-26	27-Dec-26	424 d (+146)	
	HRS	607.6	1500 (+10%/-10%)		2107.6	2257.6	1218 (+150)	
WC#: 28.030	AFL							
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-804	^S	L.H. VENT VALVES - CHECK FOR CLEANLINESS.						Service ATA:28
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:7,10 ,11
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-805	^S	R.H. VENT VALVES - CHECK FOR CLEANLINESS.						Service ATA:28
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:7,10 ,11
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-806	^S	L.H. FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS.						Service ATA:28
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,6,9 ,10 ,11
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-10-00-200-807	^S	R.H. FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS.						Service ATA:28
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:1,6,9 ,10 ,11
28-10-06-200-801		STRAINERS - CHECK FOR CLEANLINESS AND CONDITION						Service ATA:28
	MOS	03-Aug-22	48 (+10%/-10%)		03-Aug-26	27-Dec-26	424 d (+146)	
	HRS	607.6	1500 (+10%/-10%)		2107.6	2257.6	1218 (+150)	
WC#: 28.030	AFL							
PROC. REF: AMM 28-10-06, AMM 28-10-06, AMM 28-10-06, AMM 28-10-06PROC. REF: AMM 28-10-06, AMM 28-10-06, AMM 28-10-06, AMM 28-10-06								
28-20-00-200-801	^S	DISTRIBUTION SYSTEM - CHECK.						Service ATA:28
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 28-20-00, AMM 28-20-00PROC. REF: AMM 28-20-00, AMM 28-20-00								PKG:5,6,11
28-20-01-900-801		FUEL UNIT - REPLACE FILTER ELEMENT						Service ATA:28
PN:L88A15-651	MOS	22-Jul-21						LIFE LIMIT
SN:K19240	HRS	488.9	600		1088.9		199.3	
WC#: 28.020	AFL							
PROC. REF: AMM 28-20-01, AMM 28-20-01PROC. REF: AMM 28-20-01, AMM 28-20-01								
28-20-01-900-802		FUEL UNIT						Component ATA:28
PN:L88A15-651	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:K19240	HRS	0		TSN 0				
WC#: 28.020	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01, AMM 28-20-01PROC. REF: AMM 28-20-01, AMM 28-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20-03-710-801	^S	FUEL SEQUENCER - DO A GROUND OPERATIONAL TEST.						Service ATA:28
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 28-20-00, AMM 28-20-00PROC. REF: AMM 28-20-00, AMM 28-20-00								
28-20-03-900-801		FUEL SEQUENCER						Component ATA:28
PN:SE9203.A.01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:995	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
28-20-04-730-801		MECHANICAL PUMP - OVERHAUL						Component ATA:28
PN:1127-02	MOS	03-Jul-18	120 (+10%/-10%)	TSN 0	03-Jul-28	03-Jul-29	1124 d (+365)	OVERHAUL
SN:1055	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	2610.4 (+350)	
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04, AMM 28-20-04, AMM 28-20-04, AMM 28-20-04PROC. REF: AMM 28-20-04, AMM 28-20-04, AMM 28-20-04, AMM 28-20-04								
28-20-05-730-801		ELECTRIC PUMP - CHECK BRUSHES FOR WEAR						Service ATA:28
PN:2022-B	MOS	03-Jul-18						
SN:202231	HRS	0	6000 (+10%/-10%)		6000	6600	5110.4 (+600)	
WC#: 28.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-20-05-900-801		ELECTRIC FUEL BOOST PUMP						Component ATA:28
PN:2022-B	MOS/MSC	03-Jul-18	H/T	TSN 0				
SN:202231	HRS	0		TSN 0				
WC#: 28.010	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
28-20-06-900-801		U20 PRINTED CIRCUIT BOARD						Component ATA:28
PN:FAP03-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:180304	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-40-00-710-801	^S	LOW LEVEL SENSORS - DO A LOW LEVEL TEST						Service ATA:28
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
WC#: 28.030	AFL	612						
PROC. REF: AMM 28-40-00, AMM 28-40-00PROC. REF: AMM 28-40-00, AMM 28-40-00								PKG:10 ,11
28-40-01-900-801		LEFT INNER MT21 PROBE						Component ATA:28
PN:762438-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:906	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-801		RIGHT INNER MT22 PROBE						Component ATA:28
PN:762439-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:912	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-802		LEFT MEDIAN GAGE						Component ATA:28
PN:762440-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1523	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-802		RIGHT MEDIAN GAGE						Component ATA:28
PN:762440-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1519	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-803		LEFT OUTER MT25 PROBE						Component ATA:28
PN:762441-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1459	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-40-01-900-803	RIGHT OUTER MT26 PROBE							Component ATA:28
PN:762441-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1458	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-02-900-801	LEFT WING MT27 LOW LEVEL SENSOR							Component ATA:28
PN:747971-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:849	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
28-40-02-900-801	RIGHT WING MT28 LOW LEVEL SENSOR							Component ATA:28
PN:747971-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:848	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
28-40-05-900-801	FUEL AMPLIFIER							Component ATA:28
PN:738574-1-0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:738574IN00647	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05, AMM 28-40-05PROC. REF: AMM 28-40-05, AMM 28-40-05								
ATA 30 - ICE AND RAIN PROTECTION								
30-10-00-101	AIRFOIL DE ICING TROUBLESHOOTING							Service ATA:30
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-10-00, AMM 30-10-00PROC. REF: AMM 30-10-00, AMM 30-10-00								
30-10-00-210-801 ^S	PNEUMATIC DE-ICERS - CHECK FOR ATTACHMENT AND EVIDENCE OF ABRASION, CUTS OR NICKS.							Service ATA:30
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PKG:1,5,6,7,8,9 ,10 ,11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								
30-10-00-870-801	^S	DEICING SYSTEM - DEICING SYSTEM DRAINING						Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								PKG:7,11
30-10-03-200-801	^S	A43 PNEUMATIC DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								PKG:6,11
30-10-03-900-801		TIMER						Component ATA:30
PN:42E25-2A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:U1432	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
30-10-04-200-801	^S	WATER SEPARATOR FILTER - CHECK FOR CONDITION AND ATTACHMENT						Service ATA:30
PN:44E21-2A	MOS	15-Oct-24	12					
SN:180109	HRS	834						
WC#: 30.010	AFL	612						
PROC. REF: AMM 30-10-04, AMM 30-10-04PROC. REF: AMM 30-10-04, AMM 30-10-04								PKG:12
30-10-04-900-801		AIRFOIL DE-ICE WATER SEPARATOR						Component ATA:30
PN:44E21-2A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:180109	HRS	0		TSN 0				
WC#: 30.010	AFL	0		TSN 0				
PROC. REF: AMM 30-10-04PROC. REF: AMM 30-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10-05-200-801	^S	L21 DE-ICING VALVE - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								PKG:5,11
30-30-00-710-801	^S	HEATING OF PITOT TUBES AND STALL WARNING INDICATOR - DO AN OPERATIONAL TEST.						Service ATA:30
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 30-30-00, AMM 30-30-00, AMM 30-30-00PROC. REF: AMM 30-30-00, AMM 30-30-00, AMM 30-30-00								PKG:1,5,6,7,8,9 ,10 ,11
30-40-00-200-803	^S	A41/A42 LH/RH WINDSHIELDS DE-ICING CONTROLLERS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-40-00, AMM 30-40-00PROC. REF: AMM 30-40-00, AMM 30-40-00								PKG:5,6,7,11
30-40-00-710-802	^S	A41/A42 LH/RH WINDSHIELD DE-ICING CONTROLLERS - DO AN OPERATIONAL TEST						Service ATA:30
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 30-40-00, AMM 30-40-00PROC. REF: AMM 30-40-00, AMM 30-40-00								PKG:1,5,6,7,8,9 ,10 ,11
30-40-00-720-803	^S	A41/A42 LH/RH WINDSHIELD DE-ICING CONTROLLERS - DO A FUNCTIONAL TEST OF THE SYSTEM						Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								PKG:5,6,7,8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-40-00-900-801	LEFT WINDSHIELD DEICING UNIT							Component ATA:30
PN:TWH93-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1783	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								
30-40-00-900-802	RIGHT WINDSHIELD DEICING UNIT							Component ATA:30
PN:TWH93-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1784	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								
30-60-00-200-801 ^S	PROPELLER DE-ICING SYSTEM - CHECK BRUSH BLOCK AND SLIP RING FOR EVIDENCE OF OIL LEAKS. CHECK DE-ICERS AND WIRINGS FOR CONDITION AND ATTACHMENT. CHECK FOR SLIP RING WEAR, OVERHEATING AND CLEANLINESS. CHECK BRUSHES FOR WEAR, EVIDENCE OF DAMAGE, ATTACHMENT AND CLEANLINESS. CHECK WIRES FOR CONDITION AND ATTACHMENT.							Service ATA:30
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								PKG:1,5,6,7,8,9 ,10 ,11
30-60-00-710-801 ^S	PROPELLER DE-ICING SYSTEM - PERFORM A GROUND OPERATIONAL TEST							Service ATA:30
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 30-60-00, AMM 30-60-01PROC. REF: AMM 30-60-00, AMM 30-60-01								PKG:1,5,6,7,8,9 ,10 ,11
30-60-00-760-801	PERFORM A DE-ICE CIRCUIT RESISTANCE CHECK (REFER TO HARTZELL CMM 180)							Service ATA:30
	MOS	15-Oct-24	12		15-Oct-25		132 d	
	HRS	834						
	AFL							
PROC. REF: MM 30-61-80, MM 30-61-80, MM 30-61-80, MM 30-61-80, GENERIC NO REF, CMM 30-61-80PROC. REF: MM 30-61-80, MM 30-61-80, MM 30-61-80, MM 30-61-80, GENERIC NO REF, CMM 30-61-80								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-60-01-900-801	A40 TIMER							Component ATA:30
PN:3E2311-4	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:UD0381	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-60-02PROC. REF: AMM 30-60-02								
30-60-02-200-801	A40 PROPELLER DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:30
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 30-60-02PROC. REF: AMM 30-60-02								PKG:6,11
30-70-01-900-801	PL13 DE-ICING PANEL							Component ATA:30
PN:T700H925130200000	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:137	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-20-01-710-802 ^S	CHRONOMETER - CHECK OPERATION.							Service ATA:31
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM							PKG:1,5,6,7,8,9 ,10 ,11	
31-20-01-900-801	NO. 1 AIRFRAME/ENGINE INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:46725150	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
31-20-01-900-801	NO. 2 AIRFRAME/ENGINE INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:46725219	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
31-31-00-710-801	LIGHTWEIGHT DATA RECORDER - CHECK OPERATIONS							Service ATA:31
	MOS	15-Oct-24	24 (+10%/-10%)		15-Oct-26	27-Dec-26	497 d (+73)	
	HRS	834						
	AFL	612						
PROC. REF: AMM 31-31-00PROC. REF: AMM 31-31-00								
31-31-01-900-801	LIGHTWEIGHT DATA RECORDER							Component ATA:31
PN:1000-1210-11	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1262362	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-01PROC. REF: AMM 31-31-01								
319000 ^U	FASTBOX							Component ATA:31
PN:FAST-A-010-3	MOS/MSC	05-Apr-22	O/C	TSR 0				
SN:401484	HRS	572.9		TSR 0				
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-00-00-100-801	S	IF NECESSARY, CLEAN THE EXTERNAL SECTIONS OF LANDING GEARS.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-22-01PROC. REF: AMM 12-22-01								PKG:1,5,6,7,8,9 ,10 ,11
32-00-00-210-801	S	LEFT MAIN LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS						Service ATA:32
PN:D23767001-2	MOS	15-Oct-24	12 (+1m/-1m)					
SN:18AR19806	HRS	834						
WC#: 32.190	AFL	612						
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								PKG:12
32-00-00-210-801	S	NOSE LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS						Service ATA:32
PN:D23766000-2	MOS	15-Oct-24	12					
SN:18AR19805	HRS	834						
WC#: 32.220	AFL	612						
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								PKG:12
32-00-00-210-801	S	RIGHT MAIN LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS						Service ATA:32
PN:D23767001-2	MOS	15-Oct-24	12					
SN:18AR19807	HRS	834						
WC#: 32.190	AFL	612						
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								PKG:12
32-00-00-640-801	S	LH, RH, AND NOSE LANDING GEAR - LUBRICATION OF LANDING GEAR AXELS						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834						
	AFL	612						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-00-00-710-801	^S	DO AN OPERATIONAL TEST IN NORMAL/EMERGENCY CONDITIONS AND CHECK FOR SEALING OF NORMAL/EMERGENCY HYDRAULIC VALVE.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-00-00, AMM 32-00-00, AMM 32-00-00PROC. REF: AMM 32-00-00, AMM 32-00-00, AMM 32-00-00								
32-10-00-730-801	LEFT MAIN LANDING GEAR - OVERHAUL							Component ATA:32
PN:D23767001-2	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:18AR19806	HRS	0		TSN 0				
WC#: 32.010	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-10-01, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 32-10-01								
32-10-00-730-801	RIGHT MAIN LANDING GEAR - OVERHAUL							Component ATA:32
PN:D23767001-2	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:18AR19807	HRS	0		TSN 0				
WC#: 32.010	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-10-01, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 32-10-01								
32-10-01-220-801	LEFT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER							Service ATA:32
PN:D23767001-2	MOS	05-Sep-23	60 (+10%/-10%)		05-Sep-28	05-Mar-29	1188 d (+181)	
SN:18AR19806	HRS	688.8						
WC#: 32.200	AFL							
PROC. REF: AMM 32-10-01, AMM 12-13-03, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 12-13-03, AMM 32-10-01								
32-10-01-220-801	RIGHT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER.							Service ATA:32
PN:D23767001-2	MOS	05-Sep-23	60 (+10%/-10%)		05-Sep-28	05-Mar-29	1188 d (+181)	
SN:18AR19807	HRS	688.8						
WC#: 32.200	AFL							
PROC. REF: AMM 32-10-01, AMM 12-13-03, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 12-13-03, AMM 32-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10-01-220-802		LEFT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.						Service ATA:32
PN:D23767001-2	MOS	03-Jul-18	120 (+10%/-10%)		03-Jul-28	03-Jul-29	1124 d (+365)	
SN:18AR19806	HRS	0						
WC#: 32.210	AFL	0						
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
32-10-01-220-802		RIGHT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.						Service ATA:32
PN:D23767001-2	MOS	03-Jul-18	120 (+10%/-10%)		03-Jul-28	03-Jul-29	1124 d (+365)	
SN:18AR19807	HRS	0						
WC#: 32.210	AFL	0						
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
32-10-01-780-801 ^S		LEFT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 32.120	AFL	612						
PKG:12								
PROC. REF: AMM 12-14-01PROC. REF: AMM 12-14-01								
32-10-01-780-801 ^S		RIGHT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 32.120	AFL	612						
PKG:12								
PROC. REF: AMM 12-14-01PROC. REF: AMM 12-14-01								
32-20-00-200-801 ^S		NOSE LANDING GEAR MOUNT - VISUALLY CHECK FOR CRACKS. CHECK AXIAL PLAY OF HINGE BALL JOINTS. PENDULATE THE NOSE LANDING GEAR TO CHECK HINGE BALL JOINTS FOR CONDITION.						Service ATA:32
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PKG:8,11								
PROC. REF: AMM 32-20-00PROC. REF: AMM 32-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-20-00-730-801		NOSE LANDING GEAR - OVERHAUL						Component ATA:32
PN:D23766000-2	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:18AR19805	HRS	0		TSN 0				
WC#: 32.020	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-01-220-801		NOSE LANDING GEAR - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS.						Service ATA:32
PN:D23766000-2	MOS	05-Sep-23	60 (+10%/-10%)		05-Sep-28	05-Mar-29	1188 d (+181)	
SN:18AR19805	HRS	688.8						
WC#: 32.230	AFL							
PROC. REF: AMM 12-13-04, AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 12-13-04, AMM 32-20-01, AMM 32-20-01								
32-20-01-220-802		NOSE LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.						Service ATA:32
PN:D23766000-2	MOS	03-Jul-18	120 (+10%/-10%)		03-Jul-28	03-Jul-29	1124 d (+365)	
SN:18AR19805	HRS	0						
WC#: 32.240	AFL	0						
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-01-680-801		NOSE LANDING GEAR - DO AN OIL CHANGE FOR THE SHOCK ABSORBER						Service ATA:32
	MOS	05-Sep-23	60 (+10%/-10%)		05-Sep-28	05-Mar-29	1188 d (+181)	
	HRS	688.8						
	AFL							
PROC. REF: AMM 12-13-04PROC. REF: AMM 12-13-04								
32-20-01-780-801 ^S		NOSE LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 32.130	AFL	612						
PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02								
32-20-01-900-801		NOSE LANDING GEAR - REPLACE NOSE GEAR ACTUATOR HINGE PIN SECURING BOLT						Service ATA:32
	MOS	03-Jul-18	84		03-Jul-25		28 d	
	HRS	0						
	AFL	0	5000		5000		4368	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-03-200-801 ^S	SHIMMY DAMPER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
WC#: 32.030	AFL	612						
								PKG:1,6,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20-03-680-801	SHIMMY DAMPER - REPLACE HYDRAULIC FLUID.							Service ATA:32
	MOS	15-Oct-24	36 (+10%/-10%)		15-Oct-27	02-Feb-28	862 d (+110)	
	HRS	834						
WC#: 32.030	AFL	612						
PROC. REF: AMM 12-13-01PROC. REF: AMM 12-13-01								
32-20-04-900-801	LEFT HAND NOSE GEAR MOUNT ASSEMBLY							Component ATA:32
PN:T700A3220002002	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:940	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-20-04PROC. REF: AMM 32-20-04								
32-20-04-900-801	RIGHT HAND NOSE GEAR MOUNT ASSEMBLY							Component ATA:32
PN:T700A3220002003	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:944	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-20-04PROC. REF: AMM 32-20-04								
32-30-00-200-801 ^S	HYDRAULIC LINES (IN NOSE GEAR WELL) - CHECK FOR SEALING, CONDITION AND ATTACHMENT.							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,6,8,9 ,10 ,11
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30-00-200-802	^S	HYDRAULIC AND BRAKE LINES (IN MAIN GEAR WELL) - CHECK FOR SEALING, CONDITION, ATTACHMENT AND ROUTING.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								PKG:1,6,8,9 ,10 ,11
32-30-00-210-801	^S	MAIN LANDING GEARS ACTUATORS - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								PKG:1,5,6,7,8,9 ,10 ,11
32-30-00-210-802	^S	NOSE LANDING GEAR ACTUATOR - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								PKG:1,5,6,7,8,9 ,10 ,11
32-30-01-730-801		LEFT MAIN LANDING GEAR ACTUATOR - OVERHAUL						Component ATA:32
PN:7897340001	MOS	03-Jul-18	120 (+10%/-10%)	TSN 0	03-Jul-28	03-Jul-29	1124 d (+365)	OVERHAUL
SN:3833	HRS	0		TSN 0				
WC#: 32.040	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01								
32-30-01-730-801		RIGHT MAIN LANDING GEAR ACTUATOR - OVERHAUL						Component ATA:32
PN:7897340001	MOS	03-Jul-18	120 (+10%/-10%)	TSN 0	03-Jul-28	03-Jul-29	1124 d (+365)	OVERHAUL
SN:3892	HRS	0		TSN 0				
WC#: 32.040	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30-02-730-801	NOSE LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	03-Jul-18	120 (+10%/-10%)	TSN 0	03-Jul-28	03-Jul-29	1124 d (+365)	OVERHAUL
SN:3834	HRS	0		TSN 0				
WC#: 32.050	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4368 (+500)	
PROC. REF: AMM 32-30-01, AMM 32-30-02PROC. REF: AMM 32-30-01, AMM 32-30-02								
32-35-00-680-801	HYDRAULIC SYSTEM - REPLACE HYDRAULIC FLUID							Service ATA:32
	MOS	15-Oct-24	36 (+10%/-10%)		15-Oct-27	02-Feb-28	862 d (+110)	
	HRS	834						
WC#: 32.070	AFL	612						
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								
32-35-01-200-801 ^S	ELECTRO-HYDRAULIC GENERATOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-35-01PROC. REF: AMM 32-35-01								
32-35-01-200-802 ^S	ELECTRO-HYDRAULIC GENERATOR - CHECK FILTER CLEANLINESS.							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,9 ,10 ,11
PROC. REF: AMM 32-35-01PROC. REF: AMM 32-35-01								
32-35-01-730-801	ELECTRO-HYDRAULIC GENERATOR - OVERHAUL							Component ATA:32
PN:1118-04	MOS	03-Jul-18	120 (+10%/-10%)	TSN 0	03-Jul-28	03-Jul-29	1124 d (+365)	OVERHAUL
SN:991	HRS	0		TSN 0				
WC#: 32.060	AFL	0	10000 (+10%/-10%)	TSN 0	10000	11000	9368 (+1000)	
PROC. REF: AMM 32-35-01, AMM 32-35-01PROC. REF: AMM 32-35-01, AMM 32-35-01								
32-35-04-900-801	NORMAL/EMERGENCY SELECTOR VALVE							Component ATA:32
PN:978D6-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:K15251	HRS	0		TSN 0				
WC#: 32.080	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-35-04PROC. REF: AMM 32-35-04								
32-40-01-100-801	^S	LEFT MAIN LANDING GEAR - CLEAN WHEEL BEARINGS OF THE MAIN LANDING GEAR						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01								
32-40-01-100-801	^S	RIGHT MAIN LANDING GEAR - CLEAN WHEEL BEARINGS OF THE MAIN LANDING GEAR						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01								
32-40-01-200-803	^S	LEFT MAIN LANDING GEAR WHEELS - CHECK BEARINGS FOR CONDITION AND CORROSION						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
WC#: 32.280	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-200-803	^S	RIGHT MAIN LANDING GEAR WHEELS - CHECK BEARINGS FOR CONDITION AND CORROSION						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
WC#: 32.280	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-210-801	^S	MAIN LANDING GEAR TIRES - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-01-640-801 ^S	LEFT MAIN LANDING GEAR - LUBRICATE WHEEL BEARINGS OF THE MAIN LANDING GEAR							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								PKG:5,6,7,8,9 ,10 ,11
32-40-01-640-801 ^S	RIGHT MAIN LANDING GEAR - LUBRICATE WHEEL BEARINGS OF THE MAIN LANDING GEAR							Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								PKG:5,6,7,8,9 ,10 ,11
32-40-01-730-801	LEFT MAIN LANDING GEAR WHEEL - OVERHAUL							Component ATA:32
PN:40-434	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:2920	HRS	0		TSN 0				
WC#: 32.090	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	368 (+100)	
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-730-801	RIGHT MAIN LANDING GEAR WHEEL - OVERHAUL							Component ATA:32
PN:40-434	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:2921	HRS	0		TSN 0				
WC#: 32.100	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	368 (+100)	
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-900-801	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:185F03-5	MOS/MSC	05-Sep-23	O/C	TSN 0				
SN:32210316	HRS	688.8		TSN 0				
WC#: 32.090	AFL			TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-900-801	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:185F03-5	MOS/MSC	05-Sep-23	O/C	TSN 0				
SN:32210280	HRS	688.8		TSN 0				
WC#: 32.100	AFL			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-02-100-801	^S	NOSE LANDING GEAR WHEEL - CLEAN BEARINGS OF THE NOSE LANDING GEAR						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834	200					
WC#: 32.285	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-02PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-02								
32-40-02-200-802	^S	NOSE LANDING GEAR WHEEL - CHECK BEARINGS FOR CONDITION AND CORROSION						Service ATA:32
	MOS	15-Oct-24	12					
	HRS	834	200					
WC#: 32.285	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
32-40-02-210-801	^S	NOSE LANDING GEAR TIRE - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE.						Service ATA:32
	MOS	15-Oct-24	12 (-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03								
32-40-02-640-801	^S	NOSE LANDING GEAR WHEEL - LUBRICATE WHEEL BEARINGS OF NOSE LANDING GEAR						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								
32-40-02-730-801		NOSE LANDING GEAR WHEEL - OVERHAUL						Component ATA:32
PN:040-262AA	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:2315	HRS	0		TSN 0				
WC#: 32.110	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	368 (+100)	
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-02-900-801		NOSE LANDING GEAR TIRE					Component	ATA:32
PN:071-311-0	MOS/MSC	15-Oct-24	O/C	TSN 0				
SN:4058T00116	HRS	834		TSN 0				
WC#: 32.110	AFL	612		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
32-40-03-200-801 ^S		BRAKE ASSEMBLY - CHECK FOR WEAR, CRACKS ON LININGS AND DISC, AND REPLACE IF NECESSARY.					Service	ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								
32-40-03-900-801		LEFT MAIN LANDING GEAR BRAKE ASSEMBLY					Component	ATA:32
PN:030-19100	MOS/MSC	11-Feb-21	O/C					
SN:3405	HRS	460.6		TSN 460.6				
WC#: 32.140	AFL	189		TSN 189				
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								
32-40-03-900-801		RIGHT MAIN LANDING GEAR BRAKE ASSEMBLY					Component	ATA:32
PN:030-19100	MOS/MSC	11-Feb-21	O/C	TSR 0				
SN:3404	HRS	460.6		TSN 460.6, TSR 0				
WC#: 32.140	AFL	189		TSN 189, TSR 0				
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								
32-40-04-200-801 ^S		HYDRAULIC AND BRAKE LINES (IN FUSELAGE) - CHECK FOR SEALING, CONDITION AND ATTACHMENT.					Service	ATA:32
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 32-40-04PROC. REF: AMM 32-40-04								
32-40-04-200-802 ^S		BRAKE MASTER CYLINDER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.					Service	ATA:32
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-04PROC. REF: AMM 32-40-04								
32-40-04-710-801	^S	BRAKE MASTER CYLINDER - DO AN OPERATIONAL TEST.						Service ATA:32
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:10 ,11
PROC. REF: AMM 32-40-00, AMM 32-40-00PROC. REF: AMM 32-40-00, AMM 32-40-00								
32-40-05-710-801	^S	PARKING BRAKE VALVE AND CONTROL - CHECK CORRECT OPERATION OF INDICATION AND BRAKING.						Service ATA:32
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,10 ,11
PROC. REF: AMM 32-40-00, AMM 32-40-00PROC. REF: AMM 32-40-00, AMM 32-40-00								
32-40-07-200-801	^S	BRAKE RESERVOIR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS. CHECK HYDRAULIC FLUID LEVEL.						Service ATA:32
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-04, AMM 12-13-01PROC. REF: AMM 32-40-04, AMM 12-13-01								
32-40-07-680-801		BRAKE RESERVOIR - REPLACE HYDRAULIC FLUID						Service ATA:32
	MOS	15-Oct-24	36 (+10%/-10%)		15-Oct-27	02-Feb-28	862 d (+110)	
	HRS	834						
WC#: 32.150	AFL	612						
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								
32-50-00-200-801	^S	STEERING CONTROL - CHECK CONDITION OF RODS, BELLCRANK, CAM AND ROLLERS. MAKE SURE THAT THERE ARE NO FRICTION POINTS IN THE CONTROL.						Service ATA:32
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:1,8,10 ,11
PROC. REF: AMM 32-50-00PROC. REF: AMM 32-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-60-01-900-801	A14 LANDING GEAR CONTROL BOX							Component ATA:32
PN:LGCP-14-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:276	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 33 - LIGHTS								
33-10-00-710-801 ^S	INSTRUMENT PANEL AND PL1 LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 33-10-00, AMM 33-10-00PROC. REF: AMM 33-10-00, AMM 33-10-00								
33-20-00-710-801 ^S	CABIN LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 33-20-00PROC. REF: AMM 33-20-00								
33-20-00-710-802 ^S	REAR BAGGAGE COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 33-20-00PROC. REF: AMM 33-20-00								
33-30-01-710-802 ^S	FRONT CARGO COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 33-30-00, AMM 33-30-00, AMM 33-30-00PROC. REF: AMM 33-30-00, AMM 33-30-00, AMM 33-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-30-02-710-802	^S	FUEL UNIT CLOGGING INDICATOR LIGHTING - CHECK FOR CONDITION AND OPERATION.						Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 33-30-00, AMM 33-30-02PROC. REF: AMM 33-30-00, AMM 33-30-02								PKG:1,5,6,7,8,9 ,10 ,11
33-40-00-710-801	^S	EXTERIOR LIGHTS - CHECK FOR CONDITION, ATTACHMENTS AND OPERATION						Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00, AMM 33-40-00PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00, AMM 33-40-00								PKG:1,5,6,7,8,9 ,10 ,11
33-40-04-900-801		LEFT WING STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:01-0771234-07	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:896	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-04, AMM 33-40-04PROC. REF: AMM 33-40-04, AMM 33-40-04								
33-40-04-900-801		RIGHT WING STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:01-0771234-07	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:897	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-04, AMM 33-40-04PROC. REF: AMM 33-40-04, AMM 33-40-04								
33-40-04-900-801		TAILCONE STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:01-0771234-07	MOS/MSC	24-Jul-19	O/C	TSR 0				
SN:00373	HRS	196.2		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 33-40-04, AMM 33-40-04PROC. REF: AMM 33-40-04, AMM 33-40-04								
33-50-00-710-801	^S	INSTRUMENT PANEL EMERGENCY LIGHTING - CHECK FOR CONDITION AND OPERATION.						Service ATA:33
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00								
ATA 34 - NAVIGATION								
34-00-00-200-802	^S	ANTENNAS - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF CORROSION.						Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 34-30-00, AMM 34-40-00, AMM 34-50-00PROC. REF: AMM 34-30-00, AMM 34-40-00, AMM 34-50-00								
34-00-00-200-803	^S	CONTROLS AND COMPONENTS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 34-20-00, AMM 34-30-00, AMM 34-40-00, AMM 34-50-00PROC. REF: AMM 34-20-00, AMM 34-30-00, AMM 34-40-00, AMM 34-50-00								
34-00-00-710-801		VFR EQUIPMENT - DO AN OPERATIONAL TEST.						Service ATA:34
	MOS/MS	03-Jul-18	A/R					
	HRS	0						
WC#: 34.040	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
34-00-00-710-802		IFR EQUIPMENT - DO AN OPERATIONAL TEST.						Service ATA:34
	MOS/MS	03-Jul-18	A/R					
	HRS	0						
WC#: 34.050	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
34-11-00-200-801	^S	STATIC PRESSURE PORTS - CHECK FOR CONDITION AND CLEANLINESS.						Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-200-802	^S	AIR DATA SYSTEM LINES - CHECK FOR CONDITION, ATTACHMENT AND WEAR DUE TO CHAFING AT HOSE CONNECTIONS.						Service ATA:34
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								PKG:6,11
34-11-00-210-801	^S	PITOT TUBES - CHECK FOR CONDITION, ATTACHMENT, CLEANLINESS AND EVIDENCE OF OVERHEATING.						Service ATA:34
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								PKG:5,6,7,8,10 ,11
34-11-00-710-801	^S	VMO WARNING - DO A GROUND OPERATIONAL TEST.						Service ATA:34
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								PKG:7,10 ,11
34-11-00-760-801		STANDBY INDICATOR - DO A BATTERY CAPACITY METER CALIBRATION						Service ATA:34
PN:6420302-1	MOS	15-Oct-24	12		15-Oct-25		132 d	
SN:C18-10053	HRS	834						
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-790-801	^S	AIR DATA SYSTEM - DO A LEAKAGE TEST OF STATIC AND DYNAMIC SYSTEMS AND A CHECK OF ASSOCIATED INSTRUMENTS AND EQUIPMENTS.						Service ATA:34
	MOS	15-Oct-24	24					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								PKG:6,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-820-801	ALTIMETRY - CHECK CALIBRATION							Service ATA:34
	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
	HRS	834						
WC#: 34.020	AFL	612						
Calibration Date: : 15-Oct-24								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-820-801	NO. 1 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION							Service ATA:34
PN:011-03734-00	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
SN:4E5000424	HRS	834						
	AFL	612						
Calibration Date: : 15-Oct-24								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-820-801	NO. 2 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION							Service ATA:34
PN:011-03734-00	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
SN:4E5000425	HRS	834						
	AFL	612						
Calibration Date: : 15-Oct-24								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-820-803	STANDBY INDICATOR - CHECK CALIBRATION (14 CFR PART 91.411)							Service ATA:34
PN:6420302-1	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
SN:C18-10053	HRS	834						
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-870-801 ^S	STATIC SYSTEMS - BLEED SYSTEM							Service ATA:34
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PKG:6,10 ,11								
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-870-802	^S	STATIC SYSTEMS - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED.						Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00							PKG:5,6,7,8,9 ,10 ,11	
34-11-00-870-803	^S	DYNAMIC SYSTEM - BLEED SYSTEM.						Service ATA:34
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00							PKG:7,10 ,11	
34-11-00-870-804	^S	DYNAMIC SYSTEM - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED.						Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00							PKG:5,6,7,8,9 ,10 ,11	
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 1						Component ATA:34
PN:PN	MOS	03-Jul-18	168	TSN 0	03-Jul-32		2585 d	LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 2						Component ATA:34
PN:T700A341503500800	MOS	01-Oct-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 3						Component ATA:34
PN:T700A3415035003	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 1						Component ATA:34
PN:T700A341503500001	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 2						Component ATA:34
PN:T700A341503501400	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 3						Component ATA:34
PN:T700A341503500601	MOS	01-Oct-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 1						Component ATA:34
PN:T700A341503500201	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 2						Component ATA:34
PN:T700A341503501200	MOS	01-Oct-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 3						Component ATA:34
PN:T700A341503500501	MOS	01-Apr-17	168	TSN 0	01-May-32 (M)		2522 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-803		ELECTRONIC STANDBY INDICATOR						Component ATA:34
PN:6420302-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:C18-10053	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-03PROC. REF: AMM 34-24-03								
34-11-08-900-801		LEFT PITOT TUBE						Component ATA:34
PN:5812-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AS11176348	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
PROC. REF: AMM 34-11-08PROC. REF: AMM 34-11-08								
34-11-08-900-801		RIGHT PITOT TUBE						Component ATA:34
PN:5812-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AS11175760	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
PROC. REF: AMM 34-11-08PROC. REF: AMM 34-11-08								
34-11-10-900-801		NO. 1 DIGITAL AIR DATA COMPUTER						Component ATA:34
PN:011-03734-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:4E5000424	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10								
34-11-10-900-801		NO. 2 DIGITAL AIR DATA COMPUTER						Component ATA:34
PN:011-03734-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:4E5000425	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-61-900-801	GDL69A DATALINK							Component ATA:34
PN:011-03177-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:3NV002586	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-13-00-210-801 ^S	OUTSIDE AIR TEMPERATURE PROBE - CHECK FOR ATTACHMENT AND CONDITION.							Service ATA:34
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00								PKG:5,6,7,8,11
34-13-01-900-801	OUTSIDE TEMPERATURE SENSOR							Component ATA:34
PN:100723-2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1130757	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-13-01, AMM 34-13-01PROC. REF: AMM 34-13-01, AMM 34-13-01								
34-15-00-710-801 ^S	ANGLE OF ATTACK - DO A GROUND OPERATIONAL TEST							Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00								PKG:1,5,6,7,8,9 ,10 ,11
34-15-01-900-801	A590 STALL WARNING / AOA COMPUTER							Component ATA:34
PN:C-101706-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:174787-05	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01								
34-15-02-900-801	S590 LIFT TRANSDUCER							Component ATA:34
PN:C-101707-2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:174790A-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-02PROC. REF: AMM 34-15-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-20-00-210-801	^S	STANDBY COMPASS - CHECK FOR ATTACHMENT, CONDITION AND FLUID LEVEL.						Service ATA:34
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PKG:6,11								
PROC. REF: AMM 34-20-00PROC. REF: AMM 34-20-00								
34-21-05-900-801		NO. 1 ATTITUDE AND HEADING REFERENCE SYSTEM						Component ATA:34
PN:011-03732-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:45T000949	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								
34-21-05-900-801		NO. 2 ATTITUDE AND HEADING REFERENCE SYSTEM						Component ATA:34
PN:011-03732-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:45T001008	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								
34-21-05-900-801		STORMSCOPE PROCESSOR						Component ATA:34
PN:805-11500-001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:103885	HRS	0		TSN 0				
WC#: 34.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: GENERIC NO REF, AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								
34-21-05-900-802		STORMSCOPE ANTENNA						Component ATA:34
PN:805-10930-001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:102867	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-23-01-820-801		STANDBY COMPASS - DO A COMPENSATION						Service ATA:34
PN:C2350L4M23	MOS	22-Jul-21	36 (+10%/-10%)		22-Jul-24	09-Nov-24	OVD	
SN:EA-908	HRS	488.9						
WC#: 34.030	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-23-01, AMM 34-23-01PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-23-01-900-801 STANDBY COMPASS								Component ATA:34
PN:C2350L4M23	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:EA-908	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01, AMM 34-23-01PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-24-03-900-801 STANDBY HORIZON								Component ATA:34
PN:6420302-1	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:C18-10053	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: AMM 34-24-03, AMM 34-24-03, AMM 34-24-03, AMM 34-24-03PROC. REF: AMM 34-24-03, AMM 34-24-03, AMM 34-24-03, AMM 34-24-03								
34-28-00-070-801 ^S ELECTRONIC FLIGHT INSTRMENT SYSTEM - REMOVE DATA FOM SD CARDS								Service ATA:34
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:6,8,9 ,10 ,11
PROC. REF: AMM 34-28-00, AMM 34-28-00PROC. REF: AMM 34-28-00, AMM 34-28-00								
34-28-10-900-801 NO. 1 PRIMARY FLIGHT DISPLAY								Component ATA:34
PN:011-03470-10	MOS/MSC	30-Mar-21	O/C	TSO 1				
SN:494101370	HRS	468.7		TSO 0				
WC#: 34.190	AFL	196		TSO 0				
PROC. REF: AMM 34-28-10, AMM 34-28-10PROC. REF: AMM 34-28-10, AMM 34-28-10								
34-28-10-900-801 NO. 2 PRIMARY FLIGHT DISPLAY								Component ATA:34
PN:11-03470-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:494101423	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: AMM 34-28-10, AMM 34-28-10PROC. REF: AMM 34-28-10, AMM 34-28-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-28-11-900-801		MULTIFUNCTION DISPLAY					Component	ATA:34
PN:011-03472-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:496001028	HRS	0		TSN 0				
WC#: 34.120	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-28-14-900-801		NO. 1 TRIAXIAL MAGNETOMETER					Component	ATA:34
PN:011-00870-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1CM020860	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-28-14-900-801		NO. 2 TRIAXIAL MAGNETOMETER					Component	ATA:34
PN:011-00870-10	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1CM023120	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-40-01-900-801		REMOTE FMS PEDESTAL MOUNTED CONTROLLER					Component	ATA:34
PN:011-04475-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:48V000167	HRS	0		TSN 0				
WC#: 34.230	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-42-01-900-801		WEATHER RADAR UNIT					Component	ATA:34
PN:011-01768-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1DP008227	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-43-01-900-801		RADAR ALTIMETER RECEIVER/TRANSMITTER					Component	ATA:34
PN:011-02537-05	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:3RC006404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01, AMM 34-43-01, AMM 34-43-01PROC. REF: AMM 34-43-01, AMM 34-43-01, AMM 34-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-43-03-900-801	NO. 1 RADAR ALTIMETER ANTENNA							Component ATA:34
PN:013-00378-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:543-87389	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-03, AMM 34-43-03PROC. REF: AMM 34-43-03, AMM 34-43-03								
34-43-03-900-801	NO. 2 RADAR ALTIMETER ANTENNA							Component ATA:34
PN:013-00378-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:543-87381	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-03, AMM 34-43-03PROC. REF: AMM 34-43-03, AMM 34-43-03								
34-44-01-900-802	TAS COMPUTER							Component ATA:34
PN:011-01446-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1EA005971	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-44-01-900-803	TAS AMPLIFIER							Component ATA:34
PN:011-01347-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:140051372	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-44-02-900-801	NO. 1 TAS ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:124014510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-44-02-900-801	NO. 2 TAS ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:124014511	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-53-00-710-801	NO. 1 (A56) TRANSPONDER - DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-03303-00	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
SN:3EH002910	HRS	834						
WC#: 34.060	AFL	612						
Calibration Date: : 15-Oct-24								
PROC. REF: CFR FAR PART 91.413, AMM 34-53-00PROC. REF: CFR FAR PART 91.413, AMM 34-53-00								
34-53-00-710-801	NO. 2 (A57) TRANSPONDER- DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-03303-00	MOS	15-Oct-24	24		15-Oct-26		497 d	MANDATORY
SN:3EH003723	HRS	834						
WC#: 34.060	AFL	612						
Calibration Date: : 15-Oct-24								
PROC. REF: CFR FAR PART 91.413, AMM 34-53-00PROC. REF: CFR FAR PART 91.413, AMM 34-53-00								
34-53-01-900-801	NO. 1 (A56) TRANSPONDER							Component ATA:34
PN:011-03303-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:3EH002910	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01								
34-53-01-900-801	NO. 2 (A57) TRANSPONDER							Component ATA:34
PN:011-03303-00	MOS/MSC	24-Jul-19	O/C					
SN:3EH003723	HRS	196.2						
WC#: 34.060	AFL							
PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01								
34-55-01-900-801	DME UNIT							Component ATA:34
PN:066-01070-0001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:42125	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01, AMM 34-55-01PROC. REF: AMM 34-55-01, AMM 34-55-01								
34-57-02-900-801	GA36 WAAS ARINC ANTENNA							Component ATA:34
PN:013-00244-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:17588	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-57-02-900-802	GA37 WAAS/XM ARINC ANTENNA							Component ATA:34
PN:013-00245-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:17477	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 35 - OXYGEN								
35-00-00-710-801 ^S	GASEOUS OXYGEN SYSTEM - CHECK COMPONENTS AND LINES FOR LEAKS,CONDITION AND ATTACHMENT. DO AN OPERATIONAL TEST							Service ATA:35
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 35.010	AFL	612						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								
35-11-01-200-801 ^S	GASEOUS OXYGEN CYLINDER - CHECK FOR TIGHTNESS. CHECK FOR CORROSION AND DISTORTION (BULGE, DENT). CHECK FOR ATTACHMENT. CHECK HYDROSTATIC TEST DATE.							Service ATA:35
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
	AFL	612						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
35-11-01-730-801	GASEOUS OXYGEN CYLINDER - DO A HYDROSTATIC TEST							Service ATA:35
PN:2213-6519	MOS	15-Oct-24	60 (+10%/-10%)	01-Oct-29 (M)	01-Apr-30	1579 d (+182)	OVERHAUL	
SN:991	HRS	834						
WC#: 35.040	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-11-01-900-801	GASEOUS OXYGEN CYLINDER - REPLACE							Component ATA:35
PN:2213-6519	MOS	15-Oct-24	180	TSN 100, TSR 0	01-Jun-31	2187 d	LIFE LIMIT	
SN:991	HRS	834		TSR 0				
WC#: 35.040	AFL	612		TSR 0				
Manufacture Date:: 01-Jun-16								
PROC. REF: AMM 35-11-01PROC. REF: AMM 35-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-02-730-801	COPILOT OXYGEN MASK							Component ATA:35
PN:MC10-02-122	MOS	15-Oct-24	72 (+10%/-10%)	TSO 0	15-Oct-30	21-May-31	1958 d (+218)	OVERHAUL
SN:B134095	HRS	834		TSO 0				
WC#: 35.020	AFL	612		TSO 0				
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-02-730-801	PILOT OXYGEN MASK							Component ATA:35
PN:MC10-02-122	MOS	15-Oct-24	72 (+10%/-10%)	TSO 0	15-Oct-30	21-May-31	1958 d (+218)	OVERHAUL
SN:B134096	HRS	834		TSO 0				
WC#: 35.020	AFL	612		TSO 0				
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-03-900-801	PRESSURE TRANSMITER							Component ATA:35
PN:452065	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:Z170309315	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
35-11-04-900-801	BP VALVE							Component ATA:35
PN:P21030-2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1168	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
35-21-01-110-801 ^S	NO. 1 PASSENGER MASK - INSPECT AND DISINFECT							Service ATA:35
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 35.050	AFL	612						
								PKG:12
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-110-801 ^S	NO. 2 PASSENGER MASK - INSPECT AND DISINFECT							Service ATA:35
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
WC#: 35.050	AFL	612						
								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-110-801	^S	NO. 3 PASSENGER MASK - INSPECT AND DISINFECT						Service ATA:35
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834						
WC#: 35.060	AFL	612						
								PKG:12
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-110-801	^S	NO. 4 PASSENGER MASK - INSPECT AND DISINFECT						Service ATA:35
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 35.060	AFL	612						
								PKG:12
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-900-801		FORWARD PASSENGER OXYGEN MASK BOX						Component ATA:35
PN:833-610-09	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:D18010905	HRS	0		TSN 0				
WC#: 35.090	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-900-804		AFT PASSENGER OXYGEN MASK BOX						Component ATA:35
PN:833-610-09	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:D18010908	HRS	0		TSN 0				
WC#: 35.090	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-02-730-801		ALTIMETRIC VALVE - OVERHAUL						Component ATA:35
PN:DVE90-06	MOS	03-Jul-18	72 (+10%/-10%)	TSN 0	03-Jul-24	08-Feb-25	OVD	OVERHAUL
SN:9589	HRS	0		TSN 0				
WC#: 35.080	AFL	0		TSN 0				
PROC. REF: AMM 35-21-02PROC. REF: AMM 35-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-03-900-801	BAROMETRIC ALTITUDE SWITCH							Component ATA:35
PN:P24031	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:3880	HRS	0		TSN 0				
WC#: 35.110	AFL	0		TSN 0				
PROC. REF: AMM 35-21-03PROC. REF: AMM 35-21-03								
ATA 37 - VACUUM								
30-10-05-900-801	DISTRIBUTING VALVE							Component ATA:37
PN:1532-10C	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:N180091	HRS	0		TSN 0				
WC#: 37.050	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
37-10-00-200-801 ^S	AIR EJECTOR - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)							Service ATA:37
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,11
37-10-00-200-802 ^S	HOSES - CHECK FOR CONDITION AND ATTACHMENTS. (REFER TO 37-10-00-601)							Service ATA:37
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,6,11
37-10-00-200-803 ^S	SUCTION RELIEF VALVE - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)							Service ATA:37
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 37 - VACUUM								
37-10-00-200-804	^S	REGULATING AND RELIEF VALVE - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)						Service ATA:37
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,11
37-10-00-200-805	^S	S67 PRESSURE SWITCH - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)						Service ATA:37
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:6,11
37-10-01-900-801		REGULATOR AND RELIEF VALVE						Component ATA:37
PN:38E-96.2D	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:N180170	HRS	0		TSN 0				
WC#: 37.020	AFL	0		TSN 0				
PROC. REF: AMM 37-10-01, AMM 37-10-01, AMM 37-10-01PROC. REF: AMM 37-10-01, AMM 37-10-01, AMM 37-10-01								
37-10-02-900-801		AIR EJECTOR VALVE						Component ATA:37
PN:19E17-5A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:N180340	HRS	0		TSN 0				
WC#: 37.030	AFL	0		TSN 0				
PROC. REF: AMM 37-10-02, AMM 37-10-02, AMM 37-10-02PROC. REF: AMM 37-10-02, AMM 37-10-02, AMM 37-10-02								
37-10-03-900-801		SUCTION RELIEF VALVE						Component ATA:37
PN:691-21A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:N180258	HRS	0		TSN 0				
WC#: 37.040	AFL	0		TSN 0				
PROC. REF: AMM 37-10-03, AMM 37-10-03PROC. REF: AMM 37-10-03, AMM 37-10-03								
37-10-04-900-801		AIR CHECK VALVE						Component ATA:37
PN:557-18E	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:N180088	HRS	0		TSN 0				
WC#: 37.060	AFL	0		TSN 0				
PROC. REF: AMM 37-10-04, AMM 37-10-04, AMM 37-10-04PROC. REF: AMM 37-10-04, AMM 37-10-04, AMM 37-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 37 - VACUUM								
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
51-25-00-370-801	WITH MOD 70-135-11 - AIRCRAFT WITHOUT FINISH PAINT. AIRCRAFT MUST MANDATORILY BE PAINTED, AS PER DRAWING T700B-1110056, LAST ISSUE, WITHIN FIVE WEEKS AFTER AIRCRAFT INITIAL ACCEPTANCE (DELIVERY OF EXPORT CERTIFICATE OF AIRWORTHINESS BY FRENCH AUTHORITIES).						Service	ATA:51
	MOS/MSC	03-Jul-18	-					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 52 - DOORS								
52-10-00-900-801	PILOT DOOR						Component	ATA:52
PN:T700B5210426000	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB265	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								
52-11-00-200-803 ^S	LATCH CATCH AND FITTING ASSEMBLIES (LARGE DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR.						Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11
52-11-00-200-804 ^S	LARGE DOOR SEAL - CHECK FOR CONDITION.						Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:5,6,7,8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-00-200-805	^S	LARGE DOOR CLOSING MECHANISM - EXAMINE CABLE FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. CHECK GEARED MOTOR ASSEMBLY FOR SECURITY AND CONDITION.					Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11
52-11-00-220-801	^S	LARGE DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES.					Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11
52-11-00-710-801	^S	LARGE DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK AND GAS STRUTS FOR OPERATION. CHECK CENTERING ROLLER FOR WEAR AND OPERATION.					Service	ATA:52
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,10 ,11
52-11-01-900-801	DOOR						Component	ATA:52
PN:T700B5200000000196	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB780	HRS	0		TSN 0				
WC#: 52.020	AFL	0		TSN 0				
PROC. REF: AMM 52-11-01PROC. REF: AMM 52-11-01								
52-11-02-900-801	CABIN DOOR GEARED MOTOR ASSEMBLY						Component	ATA:52
PN:T700B521000101300	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB0282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-02PROC. REF: AMM 52-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-12-00-200-802	^S	PILOT DOOR - CHECK WINDOW FRAMING AND CARRY-THRU LONGERON ATTACHMENTS TO DOOR STRUCTURE FOR CRACKS AND LOOSE RIVETS.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:6,11
52-12-00-200-804	^S	LATCH CATCH ASSEMBLIES AND PIN (PILOT DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,11
52-12-00-200-805	^S	PILOT DOOR SEAL - CHECK FOR CONDITION.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,11
52-12-00-220-801	^S	PILOT DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,11
52-12-00-710-801	^S	PILOT DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK FOR OPERATION.						Service ATA:52
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-00-710-801	^S	EMERGENCY EXIT - CHECK FOR CONDITION, ATTACHMENT AND OPERATION (INSIDE AND OUTSIDE).						Service ATA:52
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								PKG:6,10 ,11
52-20-00-900-801		EMERGENCY EXIT						Component ATA:52
PN:T700A522000000110	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB907	HRS	0		TSN 0				
WC#: 52.030	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								
52-30-01-010-801	^S	OPEN ACCESS DOOR 211.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-30-01-410-801	^S	CLOSE ACCESS DOOR 211.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-30-01-710-801	^S	ACCESS DOOR 211 - CHECK FOR CONDITION, ATTACHMENT AND LOCKING. CHECK OPERATION OF LOCK AND COMPENSATION ROD.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-30-01PROC. REF: AMM 52-30-01								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-40-01-210-801	^S	L.H. WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 28-10-00, AMM 52-40-01PROC. REF: AMM 28-10-00, AMM 52-40-01								PKG:7,11
52-40-01-210-802	^S	R.H. WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 28-10-00, AMM 52-40-01PROC. REF: AMM 28-10-00, AMM 52-40-01								PKG:7,11
52-40-03-010-802	^S	REMOVE ACCESS PANELS 213 AND 214.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-40-03-010-804	^S	REMOVE ACCESS PANEL 212.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-40-03-010-805	^S	REMOVE ACCESS DOOR 311						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-40-03-210-801	^S	ACCESS DOOR 311 - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-40-03, AMM 52-40-03PROC. REF: AMM 52-40-03, AMM 52-40-03								PKG:6,11
52-40-03-210-802	^S	CLOGGING INDICATOR ACCESS DOOR - CHECK FOR CONDITION, ATTACHMENT AND LOCKING.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 52-40-03, AMM 52-40-03PROC. REF: AMM 52-40-03, AMM 52-40-03								PKG:5,11
52-40-03-410-802	^S	INSTALL ACCESS PANELS 213 AND 214.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-40-03-410-804	^S	INSTALL ACCESS PANEL 212.						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
52-40-03-410-805	^S	INSTALL ACCESS DOOR 311						Service ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-60-00-210-801	^S	LARGE DOOR STAIRWAY AND HANDRAIL - CHECK FOR CONDITION, SECURITY AND OPERATION. EXAMINE HANDRAIL AND STAIRWAY CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.					Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 52-11-00, AMM 52-11-00, AMM 52-60-00PROC. REF: AMM 52-11-00, AMM 52-11-00, AMM 52-60-00								
52-60-01-900-801	STAIRWAY						Component	ATA:52
PN:T700B526010100412	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB788	HRS	0		TSN 0				
WC#: 52.010	AFL	0		TSN 0				
PROC. REF: AMM 52-60-01PROC. REF: AMM 52-60-01								
52-71-00-710-801	^S	LARGE DOOR INDICATION - CHECK FOR OPERATION.					Service	ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 52-71-00, AMM 52-71-00PROC. REF: AMM 52-71-00, AMM 52-71-00								
52-71-00-710-802	^S	PILOT DOOR INDICATION - CHECK FOR OPERATION.					Service	ATA:52
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 52-71-00, AMM 52-71-00PROC. REF: AMM 52-71-00, AMM 52-71-00								
52-80-01-200-801	^S	MAIN LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF FITTINGS, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS.					Service	ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:8,11
PROC. REF: AMM 32-10-00, AMM 52-80-01, AMM 52-80-01PROC. REF: AMM 32-10-00, AMM 52-80-01, AMM 52-80-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-80-02-200-801	^S	NOSE LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF HINGES, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS.						Service ATA:52
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:8,11
PROC. REF: AMM 32-20-00, AMM 52-80-02, AMM 52-80-02PROC. REF: AMM 32-20-00, AMM 52-80-02, AMM 52-80-02								
ATA 53 - FUSELAGE								
53-00-00-200-801	^S	LARGE DOOR FRAMING - CHECK DOOR FRAMING VISIBLE AREA AND STRUCTURE JUNCTION UNDER FLOOR FOR CRACKS AND LOOSE RIVETS.						Service ATA:53
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-200-802	^S	PILOT DOOR FRAMING - CHECK FOR CRACKS AND LOOSE RIVETS						Service ATA:53
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-210-802	^S	EXTERNAL SURFACES - CHECK (REFER TO 53-00-00-61, PARAGRAPH 1)						Service ATA:53
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-210-803	^S	EXTERNAL SURFACES - CHECK (REFER TO PARAGRAPH 2)						Service ATA:53
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:6,11
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00-00-280-801	UPPER FUSELAGE STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION							Service ATA:53
	MOS	03-Jul-18	T:168 (+16m/-16m)		03-Jul-32	03-Nov-33	2585 d (+488)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5110.4 (+600)	
WC#: 53.020	AFL	0						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-280-802	LARGE DOOR FRAMING - CHECK DOOR FRAMING AND STRUCTURE JUNCTIONS FORCRACKS AND LOOSE RIVETS.							Service ATA:53
	MOS	03-Jul-18						
	HRS	0	3000 (+300/-300)		3000	3300	2110.4 (+300)	
WC#: 53.040	AFL	0						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-900-801	FUSELAGE							Component ATA:53
PN:PN	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	16200	TSN 0	16200		15310.4	
WC#: 53.080	AFL	0	12000	TSN 0	12000		11368	
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
53-20-00-200-801 ^S	DRAIN UNDER FLOOR - CHECK THAT DRAIN HOLES ARE NOT CLOGGED. CHECK GOOD CONDITION OF STRAINER SEAL OR SHUTTER. CHECK CLEANLINESS AND CORRECT ATTACHMENT OF STRAINER OR SEAT AND SHUTTER.CHECK THAT EMERGENCY EXIT DRAIN IS NOT CLOGGED							Service ATA:53
	MOS	15-Oct-24	12					
	HRS	834						
WC#: 53.050	AFL	612						
PROC. REF: AMM 53-20-00PROC. REF: AMM 53-20-00								PKG:12
53-20-00-900-801	FRONT FUSELAGE							Component ATA:53
PN:T850K1002	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB925	HRS	0		TSN 0				
WC#: 53.060	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-900-801	REAR FUSELAGE							Component ATA:53
PN:T850K6001	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB925	HRS	0		TSN 0				
WC#: 53.070	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
53-60-00-010-801 ^S	REMOVE FLOOR PANELS 222L, 222C, 222R, 231R, 232C, 232R, 241L, 241C, 241R, 251L, 251C, 261L, 261C AND 261R.							Service ATA:53
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								PKG:1,6,10 ,11
53-60-00-010-802 ^S	REMOVE FLOOR PANELS 231L AND 232L.							Service ATA:53
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								PKG:1,5,6,7,8,9 ,10 ,11
53-60-00-200-801 ^S	FLOOR PANELS - CHECK FOR CONDITION AND DENTS.							Service ATA:53
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								PKG:6,11
53-60-00-410-801 ^S	INSTALL FLOOR PANELS 222L, 222C, 222R, 231R, 232C, 232R, 241L, 241C, 241R, 251L, 251C, 261L, 261C AND 261R.							Service ATA:53
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								PKG:1,6,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-60-00-410-802	^S	INSTALL FLOOR PANELS 231L AND 232L.						Service ATA:53
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 53 - FUSELAGE								
53-70-00-200-801	^S	PEDESTAL - CHECK FOR CRACKS AND EVIDENCE OF DAMAGE						Service ATA:53
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 53-70-00PROC. REF: AMM 53-70-00								PKG:6,11
ATA 55 - STABILIZERS								
55-00-00-280-802		VERTICAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION						Service ATA:55
	MOS	03-Jul-18	T:120 (+12m/-12m)		03-Jul-28	03-Jul-29	1124 d (+365)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5110.4 (+600)	
WC#: 55.020	AFL	0						
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								
ATA 55 - STABILIZERS								
55-00-00-280-803		HORIZONTAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION						Service ATA:55
	MOS	03-Jul-18	T:168 (+16m/-16m)		03-Jul-32	03-Nov-33	2585 d (+488)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5110.4 (+600)	
	AFL	0						
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								
ATA 55 - STABILIZERS								
55-10-00-200-802	^S	FIXED HORIZONTAL STABILIZER - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION.						Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-280-801	FIXED HORIZONTAL STABILIZER - DO THE FOLLOWING INSPECTIONS : - ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:55
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 55.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03								
55-10-00-900-801	LEFT HORIZONTAL STABILIZER							Component ATA:55
PN:T700A551016000000	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1257	HRS	0		TSN 0				
WC#: 55.110	AFL	0		TSN 0				
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								
55-10-00-900-801	RIGHT HORIZONTAL STABILIZER							Component ATA:55
PN:T700A551016000100	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1260	HRS	0		TSN 0				
WC#: 55.110	AFL	0		TSN 0				
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								
55-20-00-200-801 ^S	ELEVATORS - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK BONDING STRAPS FOR CONDITION. CHECK FITTINGS, BEARINGS AND HINGE PINS FOR CRACKS, EVIDENCE OF DAMAGE AND SLACK. CHECK ATTACHING BOLT SAFETYING. CHECK SLACK INTO THE ELEVATOR CONTROL.							Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 55-20-00PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 55-20-00								
55-20-00-200-803 ^S	ELEVATOR TRIM TABS - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF BEARINGS AND HINGE PINS AS WELL AS TRIM TABS FOR SLACK .							Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-00-280-801	ELEVATORS - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:55
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 55.060	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02PROC. REF: AMM 51-20-00, AMM 51-20-02								
55-20-00-900-801	LEFT ELEVATOR							Component ATA:55
PN:T700A552000100400	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1259	HRS	0		TSN 0				
WC#: 55.070	AFL	0		TSN 0				
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								
55-20-00-900-801	RIGHT ELEVATOR							Component ATA:55
PN:T700A552000100500	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1263	HRS	0		TSN 0				
WC#: 55.070	AFL	0		TSN 0				
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								
55-30-00-200-803 ^S	FIN - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION.							Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								
55-30-00-280-801	FIN - DO THE FOLLOWING INSPECTIONS : - ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS							Service ATA:55
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 55.040	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-00-900-801	VERTICAL STABILIZER							Component ATA:55
PN:T700A553000100400	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1269	HRS	0		TSN 0				
WC#: 55.100	AFL	0		TSN 0				
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								
55-40-00-200-801	RUDDER - VISUALLY CHECK RUDDER AND HORN SKIN FOR CRACKS AND DENTS. CHECK CONDITION OF BONDING STRAP AND MAKE SURE THAT RUDDER DRAIN HOLES ARE NOT CLOGGED. CHECK FOR CONDITION, ATTACHMENT, CRACKS AND SLACK ON FITTINGS AND BEARINGS. VISUALLY CHECK THAT BOLTS ON UPPER AND CENTRAL BEARINGS AS WELL AS BEARING RIB NUT ARE SAFETIED.							Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
55-40-00-200-803	RUDDER TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF HINGE FITTINGS AND TRIM TAB FOR SLACK.							Service ATA:55
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
55-40-00-280-801	RUDDER - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:55
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 55.050	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 55-40-00PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 55-40-00								
55-40-00-640-801	RUDDER - SPRAY SICCATIVE OIL INSIDE THE TORQUE SHAFT.							Service ATA:55
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
	AFL	0						
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-00-900-801	RUDDER							Component ATA:55
PN:T700A554000100710	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1248	HRS	0		TSN 0				
WC#: 55.050	AFL	0		TSN 0				
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
ATA 56 - WINDOWS								
56-10-00-210-801 ^S	WINDSHIELD AND SIDE WINDOWS - CHECK FOR CONDITION.							Service ATA:56
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								
56-10-01-900-801	LEFT WINDSHIELD ASSY, (LH)							Component ATA:56
PN:TBM700 1.5.2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:2935	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
56-10-01-900-801	RIGHT WINDSHIELD ASSY, (LH)							Component ATA:56
PN:TBM700 2.5.2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:2978	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
56-10-02-900-801	LEFT SIDE WINDOW							Component ATA:56
PN:TBM-8-2-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1995	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
56-10-02-900-801	RIGHT SIDE WINDOW							Component ATA:56
PN:TBM700 4.2.0	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:2032	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
56-20-00-210-801	^S	CABIN WINDOWS - CHECK FOR CONDITION.						Service ATA:56
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 56-20-00PROC. REF: AMM 56-20-00								
ATA 57 - WINGS								
57-00-00-280-801		LEFT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION						Service ATA:57
	MOS	03-Jul-18	T:168 (+16m/-16m)	03-Jul-32	03-Nov-33	2585 d (+488)		
	HRS	0	T:6000 (+600/-600)	6000	6600	5110.4 (+600)		
WC#: 57.010	AFL	0						
PROC. REF: AMM 57-00-00PROC. REF: AMM 57-00-00								
57-00-00-280-802		RIGHT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION						Service ATA:57
	MOS	03-Jul-18	T:168 (+16m/-16m)	03-Jul-32	03-Nov-33	2585 d (+488)		
	HRS	0	T:6000 (+600/-600)	6000	6600	5110.4 (+600)		
WC#: 57.010	AFL	0						
PROC. REF: AMM 57-00-00PROC. REF: AMM 57-00-00								
57-10-00-210-801	^S	L.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:7,11
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								
57-10-00-210-802	^S	R.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:7,11
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-200-801	^S	L.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-802	^S	R.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-803	^S	L.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-804	^S	R.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-805	^S	L.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-200-806	^S	R.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								
57-20-00-900-801		LEFT WING						Component ATA:57
PN:T850K5700000021011	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:LT928	HRS	0	41600	TSN 0	41600		40710.4	
WC#: 57.010	AFL	0		TSN 0				
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								
57-20-00-900-801		RIGHT WING						Component ATA:57
PN:T850K5700000021021	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:LT928	HRS	0	41600	TSN 0	41600		40710.4	
WC#: 57.010	AFL	0		TSN 0				
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								
57-30-00-200-803	^S	L.H. WINGLET -CHECK FOR CONDITION, ATTACHMENT, SCRATCHES AND DENTS						Service ATA:57
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
							PKG:1,7,10 ,11	
PROC. REF: AMM 57-30-00, AMM 57-30-00PROC. REF: AMM 57-30-00, AMM 57-30-00								
57-30-00-200-804	^S	R.H. WINGLET - CHECK FOR CONDITION, ATTACHMENT, SCRATCHES AND DENTS						Service ATA:57
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
							PKG:1,7,10 ,11	
PROC. REF: AMM 57-30-00, AMM 57-30-00PROC. REF: AMM 57-30-00, AMM 57-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-200-801	^S	L.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:7,11
57-50-00-200-802	^S	R.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:7,11
57-50-00-200-803	^S	L.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,5,7,9 ,10 ,11
57-50-00-200-804	^S	R.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,5,7,9 ,10 ,11
57-50-00-200-805	^S	L.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,7,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-200-806	^S	R.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,7,9 ,10 ,11
57-50-00-200-809	^S	R.H. FLAP CARRIAGES - CHECK FOR CRACKS						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,7,9 ,10 ,11
57-50-00-200-815	^S	L.H. FLAP CARRIAGES - CHECK FOR CRACKS.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,7,9 ,10 ,11
57-50-00-280-801		L.H. FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.						Service ATA:57
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 57.020	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-50-00-280-802		R.H. FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.						Service ATA:57
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 57.020	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-640-801	^S	L.H. FLAP - LUBRICATE LH FLAP ROLLERS						Service ATA:57
	MOS	15-Oct-24	12					
	HRS	834						
	AFL	612						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:12
57-50-00-640-802	^S	R.H. FLAP - LUBRICATE RH FLAP ROLLERS						Service ATA:57
	MOS	15-Oct-24	12					
	HRS	834						
	AFL	612						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:12
57-50-00-900-802		LEFT FLAP						Component ATA:57
PN:T700A575500100800	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1289	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								
57-50-00-900-802		RIGHT FLAP						Component ATA:57
PN:T700A575500100900	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1267	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								
57-60-00-200-803	^S	AILERON TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK HINGES FOR CONDITION AND TRIM TAB FOR SLACK. CHECK BONDING STRAP FOR CONDITION.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-210-801	^S	L.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								PKG:1,5,6,7,8,9 ,10 ,11
57-60-00-210-802	^S	R.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS.						Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								PKG:1,5,6,7,8,9 ,10 ,11
57-60-00-280-801		L.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.						Service ATA:57
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 57.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-60-00-280-802		R.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.						Service ATA:57
	MOS	03-Jul-18						
	HRS	0	1200 (+10%/-10%)		1200	1320	310.4 (+120)	
WC#: 57.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-60-00-900-801		LEFT AILERON						Component ATA:57
PN:T700A576003501000	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1254	HRS	0		TSN 0				
WC#: 57.030	AFL	0		TSN 0				
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-900-801	RIGHT AILERON							Component ATA:57
PN:T700A576010100300	MOS/MSC	20-May-19	O/C					
SN:SC1263	HRS							
WC#: 57.030	AFL							
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-70-00-210-801 ^S	L.H. SPOILER - CHECK FOR CONDITION.							Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00							PKG:1,5,6,7,8,9 ,10 ,11	
57-70-00-210-802 ^S	R.H. SPOILER - CHECK FOR CONDITION.							Service ATA:57
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00							PKG:1,5,6,7,8,9 ,10 ,11	
57-70-00-900-801	LEFT SPOILER							Component ATA:57
PN:T700A576500400400	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1254	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
57-70-00-900-801	RIGHT SPOILER							Component ATA:57
PN:T700A576500400500	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:SC1258	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
ATA 61 - PROPELLERS/PROPULSORS								
61-00-00-200-802	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP							Service ATA:61
	MOS	15-Oct-24	12		15-Oct-25		132 d	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
	HRS	834	600		(1434) 1434		544.4	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-804 NO. 1 PROPELLER - PRE-FLIGHT CHECKS Service ATA:61								
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-805 NO. 1 PROPELLER - OPERATIONAL CHECKS Service ATA:61								
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-806 NO. 1 PROPELLER - INSPECT EXPOSED SECTION USING COIN-TAP Service ATA:61								
	MOS	03-Jul-18						
	HRS	0	1200		(1200) 1200		310.4	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-808 NO. 1 PROPELLER - DE-ICE COMPONENT OVERHAUL Service ATA:61								
	MOS	15-Oct-24	72		15-Oct-30		1958 d	OVERHAUL
	HRS	834	4000		(4834) 4834		3944.4	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-10-00-200-801 NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION Service ATA:61								
	MOS	15-Oct-24	12		15-Oct-25		132 d	
	HRS	834	400		(1234) 1234		344.4	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-802 NO. 1 PROPELLER - OVERSPEED/OVERTORQUE Service ATA:61								
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-10-00-200-803	NO. 1 PROPELLER - LIGHTNING STRIKE							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								
61-10-00-200-804	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								
61-10-00-200-805	NO. 1 PROPELLER - FIRE/HEAT DAMAGE							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								
61-10-00-200-806	NO. 1 PROPELLER - SUDDEN STOPPAGE							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-807	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-808	NO. 1 PROPELLER - LONG TERM STORAGE							Service ATA:61
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-10-00-220-801	BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK.							Service ATA:61
	MOS	15-Oct-24	12 (+10%/-10%)	Adj -73d	03-Aug-25	09-Sep-25	59 d (+37)	
	HRS	834	600 (+10%/-10%)		1434	1494	544.4 (+60)	
WC#: 61.020	AFL							
PROC. REF: GENERIC NO REF, POM 61-00-49, POM 61-00-47, POM 61-00-47, POM 61-00-47PROC. REF: GENERIC NO REF, POM 61-00-49, POM 61-00-47, POM 61-00-47, POM 61-00-47								
61-10-01-640-801	NO. 1 PROPELLER - PROPELLER - LUBRICATE							Service ATA:61
	MOS	15-Oct-24	12		15-Oct-25		132 d	
	HRS	834	400		(1234) 1234		344.4	
PROC. REF: POM 61-00-47, AMM 61-10-01-301, AMM 61-10-01 (A1), AMM 61-10-01, AMM 61-10-01PROC. REF: POM 61-00-47, AMM 61-10-01-301, AMM 61-10-01 (A1), AMM 61-10-01, AMM 61-10-01								
61-10-01-640-802	NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service ATA:61
	MOS/MSC		A/R					CPCP
	HRS							
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-01-730-801	NO. 1 PROPELLER - PROPELLER - OVERHAUL							Service ATA:61
	MOS	15-Oct-24	72		15-Oct-30		1958 d	OVERHAUL
	HRS	834	4000		(4834) 4834		3944.4	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-15-00-900-801	NO. 1 PROPELLER - NO. 1 BLADE							Component ATA:61
PN:NC8834K	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B8404	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-802	NO. 1 PROPELLER - NO. 2 BLADE							Component ATA:61
PN:NC8834K	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B8360	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-803	NO. 1 PROPELLER - NO. 3 BLADE							Component ATA:61
PN:NC8834K	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B8358	HRS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-804	NO. 1 PROPELLER - NO. 4 BLADE							Component ATA:61
PN:NC8834K	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B8359	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-805	NO. 1 PROPELLER - NO. 5 BLADE							Component ATA:61
PN:NC8834K	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:B8406	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-20-00-200-801 ^S	PROPELLER GOVERNOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.							Service ATA:61
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-20-00-730-801	NO. 1 ENGINE - PROPELLER GOVERNOR - OVERHAUL							Component ATA:61
PN:8210-007-01	MOS	15-Oct-24		TSO 0				OVERHAUL
SN:21127905	HRS	834	3500 (+500)	TSO 0	(4334) 4334	4834	3444.4 (+500)	
	ENC	612		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-20-01-200-802 ^S	L3 FEATHER SOLENOID/OVERSPEED GOVERNOR - CHECK FOR ATTACHMENT, LEAKS AND FOR ROUTING AND CONDITION OF WIRING							Service ATA:61
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 61-20-00, AMM 61-20-00PROC. REF: AMM 61-20-00, AMM 61-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-20-01-710-802	^S	L3 FEATHER SOLENOID/OVERSPEED GOVERNOR - DO A GROUND OPERATIONAL TEST, ENGINE RUNNING						Service ATA:61
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 61-20-01PROC. REF: AMM 61-20-01								PKG:1,5,9 ,10 ,11
61-20-01-730-802		L3 FEATHER SOLENOID / OVERSPEED GOVERNOR - OVERHAUL (POST-MOD70-0324-00)						Service ATA:61
PN:1439292	MOS	03-Jul-18						OVERHAUL
SN:181009	HRS	0	3500 (+10%/-10%)		3500	3850	2610.4 (+350)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-20-01-900-802		L3 FEATHER SOLENOID / OVERSPEED GOVENOR						Component ATA:61
PN:1439292	MOS/MSC	03-Jul-18	H/T	TSN 0				
SN:181009	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 61-20-01PROC. REF: AMM 61-20-01								
61-30-00-900-801		SPINNER DOME						Component ATA:61
PN:105044P	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1801569	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 61-10-02, AMM 61-10-02PROC. REF: AMM 61-10-02, AMM 61-10-02								
61PR1		NO. 1 PROPELLER						Component ATA:61
PN:HC-E5N-3C/NC8834K	MOS/MSC	03-Jul-18	PP/C					
SN:RJ376	HRS	0						
WC#: 61.PR1	AFL	0						
PROC. REF: AMM 61-10-01, AMM 61-10-01PROC. REF: AMM 61-10-01, AMM 61-10-01								
ATA 71 - POWER PLANT								
71-00-00-100-801	^S	IF NECESSARY, CLEAN ENGINE AND COWLINGS.						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71-00-00, AMM 12-22-05PROC. REF: AMM 71-00-00, AMM 12-22-05								PKG:1,5,6,7,8,9 ,10 ,11
71-00-00-200-801	S	POWERPLANT - CHECK						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-00-00PROC. REF: AMM 71-00-00								PKG:1,5,6,7,8,9 ,10 ,11
71-00-00-200-802	S	FIREWALL - CHECK FOR CONDITION AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								PKG:5,11
71-00-00-200-804		FIREWALL - CHECK THE FIREWALL AND THE FRONT CARGO COMPARTMENT UPHOLSTERY PANELS						Service ATA:71
	MOS	03-Jul-18	120 (+10%/-10%)	03-Jul-28	03-Jul-29	1124 d (+365)		
	HRS	0						
WC#: 25.010	AFL	0						
PROC. REF: AMM 25-50-03, AMM 25-50-03, AMM 25-50-03PROC. REF: AMM 25-50-03, AMM 25-50-03, AMM 25-50-03								
71-00-00-6.A		NO. 1 ENGINE - COMPRESSOR DESALINATION WASH						Service ATA:71
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	ENC	612						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-00-6.C		NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH						Service ATA:71
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	ENC	612						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00.10	NO. 1 ENGINE - FCU CHECKS							Service ATA:71
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-00.13	NO. 1 ENGINE - TORQUEMETER FUNCTION CHECK							Service ATA:71
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-CA-820-801 ^S	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION							Service ATA:71
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								PKG:1
71-00-CA-970-801	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:71
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: SIL GEN-055PROC. REF: SIL GEN-055								
71-10-00-010-801 ^S	OPEN ENGINE COWLINGS 131 AND 132.							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								PKG:1,5,6,7,8,9 ,10 ,11
71-10-00-010-802 ^S	REMOVE ENGINE COWLINGS 121, 122, 133 AND 134							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								
71-10-00-210-802 ^S	POWER PLANT COWLING ASSEMBLY - CHECK FOR CONDITION, ATTACHMENT,SCRATCHES AND DENTS. CHECK FOR EROSION AT ENGINE COWLING 122 AIR INTAKE.							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00								
71-10-00-410-801 ^S	CLOSE ENGINE COWLINGS 131 AND 132.							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								
71-10-00-410-802 ^S	INSTALL ENGINE COWLINGS 121, 122, 133 AND 134.							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								
71-20-00-200-801 ^S	ENGINE MOUNT - CHECK FOR ATTACHMENT, CRACKS AND EVIDENCE OF DAMAGE. CHECK ELASTOMER VIBRATION ISOLATORS FOR CONDITION AND ATTACHMENT.							Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,9 ,10 ,11
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-20-00-900-801	LEFT LOWER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	03-Jul-18						LIFE LIMIT
	HRS	0	3500		3500		2610.4	
WC#: 71.010	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-900-801	LEFT UPPER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	03-Jul-18						LIFE LIMIT
	HRS	0	3500		3500		2610.4	
WC#: 71.010	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-801	RIGHT LOWER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	03-Jul-18						LIFE LIMIT
	HRS	0	3500		3500		2610.4	
WC#: 71.020	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-801	RIGHT UPPER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	03-Jul-18						LIFE LIMIT
	HRS	0	3500		3500		2610.4	
WC#: 71.020	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-802	ENGINE MOUNT							Component ATA:71
PN:T700F712000500000	MOS/MSC	03-Jul-18	E/C	TSN 0				
SN:F55	HRS	0		TSN 0				
WC#: 71.040	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-821	PYLON STRUCTURE							Component ATA:71
PN:T700H537002000121	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB244	HRS	0		TSN 0				
WC#: 71.050	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
71-60-01-200-803 ^S	INERTIAL SEPARATOR - CHECK FOR CONDITION, ATTACHMENT, DENTS AND SCRATCHES							Service ATA:71
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-60-01-200-804	^S	INERTIAL SEPERATOR - CHECK BELLOW FOR CONDITION						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:1,5,9 ,10 ,11
71-60-01-200-805	^S	INERTIAL SEPERATOR - CHECK THAT DRAIN HOLE IS NOT CLOGGED						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:1,5,6,7,8,9 ,10 ,11
71-60-01-900-801		INERTIAL SEPARATOR ACTUATOR						Component ATA:71
PN:JA23372-1000-2	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:317	HRS	0		TSN 0				
WC#: 71.030	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01, AMM 71-60-01								
71-60-02-010-802	^S	REMOVE ENGINE PLENUM CHAMBER ACCESS PANEL 135						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-02PROC. REF: AMM 71-60-02								PKG:5,6,7,8,9 ,10 ,11
71-60-02-200-801	^S	ENGINE PLENUM CHAMBER - CHECK.						Service ATA:71
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 71-60-02, AMM 71-60-02PROC. REF: AMM 71-60-02, AMM 71-60-02								PKG:5,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-60-02-200-802	^S	ENGINE PLENUM CHAMBER - CHECK TEST SEAL AND SEALS FOR CONDITION						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-02, AMM 71-60-02, AMM 71-60-02PROC. REF: AMM 71-60-02, AMM 71-60-02, AMM 71-60-02								PKG:1,5,9 ,10 ,11
71-60-02-410-802	^S	INSTALL ENGINE PLENUM CHAMBER ACCESS PANEL 135						Service ATA:71
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 71-60-02PROC. REF: AMM 71-60-02								PKG:1,5,6,7,8,9 ,10 ,11
71-70-00-200-801	^S	ECOLOGICAL TANK AND ENGINE DRAINS - CHECK HOSES AND RIGID PIPES FOR ATTACHMENT, ROUTING AND CONDITION.						Service ATA:71
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 71-70-00PROC. REF: AMM 71-70-00								PKG:5,11
71EN1		NO. 1 ENGINE						Component ATA:71
PN:3071016-01	MOS/MSC	03-Jul-18	O/C					
SN:PCE-RV0589	HRS	0						
WC#: 71.EN1	AFL	0						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								
ATA 72 - ENGINE								
72-00-00-100-801		NO. 1 ENGINE - COMPRESSOR DESALINATION WASH						Service ATA:72
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	ENC	612						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-100-801	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:72
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	ENC	612						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-801	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH							Service ATA:72
	MOS/MSC	15-Oct-24	A/R					
	HRS	834						
	ENC	612						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-801	NO. 1 ENGINE - EXTERNAL ENGINE WASH							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-805	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE				0 - 7 DAYS			Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-806	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE 8 - 28 DAYS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-807	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE 29-90 DAYS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-100-808	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE FOR PERIODS EXCEEDING 90 DAYS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-809	NO. 1 ENGINE - ENGINE DEPRESERVATION							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-200-801 ^S	ENGINE - CHECK FOR GENERAL CONDITION, ATTACHMENT, LINKAGE AND EVIDENCE OF DAMAGE.							Service ATA:72
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-00-00-290-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION WITH BOROSCOPE							Service ATA:72
	MOS	05-Sep-23						
	HRS	688.8	400 (+10%)		(1088.8) 1088.8	1128.8	199.2 (+40)	
	ENC							
PROC. REF: EMM 72-00-00, EMM 72-00-00PROC. REF: EMM 72-00-00, EMM 72-00-00								
72-00-00-710-801 ^S	ENGINE - PERFORM A TORQUE LIMITER FUNCTION CHECK							Service ATA:72
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-730-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION (HSI)							Service ATA:72
PN:PN	MOS	03-Jul-18						
SN:UNKNOWN	HRS	0	1750 (+250)		(1750) 1750	2000	860.4 (+250)	
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-730-802	NO. 1 ENGINE - ENGINE - OVERHAUL							Service ATA:72
	MOS	03-Jul-18						OVERHAUL
	HRS	0	3500		(3500) 3500		2610.4	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-00-00-9.F	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER LINER							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.G	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT STATOR ASSEMBLY							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.H	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT BLADES AND SHROUD SEGMENTS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.I	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT DISK FACE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00.5	NO. 1 ENGINE - ENGINE CONDITION TREND MONITORING SYSTEM							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00.6	NO. 1 ENGINE - FAULT ISOLATION							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-801	NO. 1 ENGINE - PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-802	NO. 1 ENGINE - OVERSPEED							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-803	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-804	NO. 1 ENGINE - OVER TEMPERATURE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-805	NO. 1 ENGINE - OVER TORQUE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-806	NO. 1 ENGINE - IMMERSION IN WATER							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-807	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-808	NO. 1 ENGINE - MATERIAL INGESTION (E.G., ICE, STONES, ETC.)							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-809	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION (E.G. RAGS, PLASTIC BAGS, ETC.							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-810	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-811	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-812	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-813	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-814	NO. 1 ENGINE - HEAVY/HARD LANDING							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-815	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-816	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-817	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-818	NO. 1 ENGINE - HIGH OIL PRESSURE							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-819	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-820	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING, SCRAPING							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-821	NO. 1 ENGINE - PROPELLER WIND MILLING AFTER IN-FLIGHT SHUTDOWN							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-822	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-823	NO. 1 ENGINE - CONTAMINATION OF OIL WITH CARBON DEBRIS							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-824	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN (COARSE HAT-TYPE SCREEN ATTACHED TO THE INNER END OF THE FILTER)							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-825	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-826	NO. 1 ENGINE - HIGH TORQUE INDICATION AT LOW POWER							Service ATA:72
	MOS/MSC	03-Jul-18	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-CA-200-801 ^S	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FORATTACHMENT							Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-CA-200-802	^S	NO. 1 ENGINE - CHECK CLAMPS,BRACKETS,TUBES/LINES,LINKAGES FOR CHAFING, CRACKS AND CORROSION						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-803	^S	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-804	^S	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-805	^S	NO. 1 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-290-801	^S	NO. 1 ENGINE - VISUAL INSPECT FIRST-STAGECOMPRESSORROTOR WITH A MIRROR OR A BORESCOPE						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-CA-610-801	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE							Service ATA:72
	MOS/MSC	30-Mar-21	A/R					
	HRS	468.7						
	ENC	196						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-10-00-200-801 ^S	PROPELLER DRIVE SHAFT SEAL - CHECK FOR LEAKS AND ATTACHMENT.							Service ATA:72
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: EMM 72-10-00PROC. REF: EMM 72-10-00								
72-10-CA-900-801	NO. 1 ENGINE - NO.1 SECOND STAGE REDUCTION PLANET GEAR							Component ATA:72
PN:3008012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766030	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-801	NO. 1 ENGINE - NO.2 SECOND STAGE REDUCTION PLANET GEAR							Component ATA:72
PN:3008012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766033	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-801	NO. 1 ENGINE - NO.3 SECOND STAGE REDUCTION PLANET GEAR							Component ATA:72
PN:3008012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766035	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-801	NO. 1 ENGINE - NO.4 SECOND STAGE REDUCTION PLANET GEAR							Component ATA:72
PN:3008012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766046	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-10-CA-900-801	NO. 1 ENGINE - NO.5 SECOND STAGE REDUCTION PLANET GEAR							Component ATA:72
PN:3008012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766050	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-802	NO. 1 ENGINE - 2ND-STAGE REDUCTION COUPLING FLEX SHAFT							Component ATA:72
PN:3012286	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA762872	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-803	NO. 1 ENGINE - 2ND-STAGE REDUCTION 46 TEETH SUN GEAR							Component ATA:72
PN:3023250	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA763896	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-804	NO. 1 ENGINE - 1ST-STAGE ADAPTER-SPLINED CARRIER							Component ATA:72
PN:3023252	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA761407	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-805	NO. 1 ENGINE - 2ND-STAGE REDUCTION CARRIER							Component ATA:72
PN:3027977	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA766575	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-806	NO. 1 ENGINE - BALL BEARING							Component ATA:72
PN:3072721-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:BB0281590	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-10-CA-900-807	NO. 1 ENGINE - ROLLER FLANGED BEARING							Component ATA:72
PN:3028007	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:BB0285005	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-808	NO. 1 ENGINE - 2ND-STAGE REDUCTION RING GEAR							Component ATA:72
PN:3028683	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA763876	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-809	NO. 1 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY							Component ATA:72
PN:3029022	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA39F991	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-810	NO. 1 ENGINE - PROPELLER SHAFT							Component ATA:72
PN:3048695-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:EAAE000F980	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-11-CA-900-801	NO. 1 ENGINE - 1ST-STAGE REDUCTION GEAR RING							Component ATA:72
PN:3059927-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA764120	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-11-CA-900-802	NO. 1 ENGINE - 1ST-STAGE REDUCTION CARRIER							Component ATA:72
PN:3101419-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA756419	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-20-00-200-801	^S	ENGINE AIR INTAKE SCREEN - CHECK FOR CLEANLINESS AND ATTACHMENT.						Service ATA:72
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
72-20-00.8		NO. 1 ENGINE - COMPRESSOR AIR INLET APPROVED REPAIRS						Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								
72-20-CA-200-801	^S	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								PKG:1
72-20-CA-200-802	^S	NO. 1 ENGINE - INSPECT WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE THE COMPRESSOR INLET CASE OVERALL SURFACE AREAS ANDSTRUTS FOR CORROSION						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								PKG:1
72-30-00-200-801	^S	GENERATOR TURBINE CASE - CHECK FOR CRACKS, DISTORTIONS AND CORROSION.						Service ATA:72
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-01-200-801	^S	FIRESEAL MOUNT RINGS - CHECK FOR GENERAL CONDITION AND ATTACHMENT.						Service ATA:72
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,10 ,11
72-30-05.6		NO. 1 ENGINE - COMPRESSOR ROTOR APPROVED REPAIRS FIRST STAGE COMPRESSOR ROTOR						Service ATA:72
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-30-05PROC. REF: EMM 72-30-05								
72-30-CA-200-801	^S	NO. 1 ENGINE - INSPECT/CHECK GASGENERATORCASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FORCRACKS, DISTORTION, AND CORROSION						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								PKG:1
72-30-CA-200-802	^S	NO. 1 ENGINE - CHECK FIRESEALMOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								PKG:1
72-30-CA-900-801		NO. 1 ENGINE - SHAFT,STUB, COMPRESSOR ROTOR, FLANGED ROLLER BEARING						Component ATA:72
PN:3073900-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0282996	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-20-00, EMM 72-30-01PROC. REF: EMM 72-20-00, EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-CA-900-802	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3042701	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:FRAEPWMB35	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: EMM 72-30-05PROC. REF: EMM 72-30-05								
72-30-CA-900-803	NO. 1 ENGINE - COUPLING, POWER TUBINE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073900-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0283566	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-804	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT							Component ATA:72
PN:3043063	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:PKAAA749681	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-805	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040942	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:FRAEPWMH49	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-806	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040933	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:FRAEPWMB60	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-CA-900-807	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040944	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:EAAE000K027	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-808	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3036898	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:FRAEPWNB74	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23368	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-809	NO. 1 ENGINE - REAR HUB COMPRESSOR COUPLING							Component ATA:72
PN:3112612-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA745098	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-810	NO. 1 ENGINE - NO.1 BALL BEARING							Component ATA:72
PN:3113589-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:FAA1800751	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-811	NO. 1 ENGINE - COMPRESSOR ROTOR STUB SHAFT							Component ATA:72
PN:3120663-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA41F088	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-31-CA-900-801	NO. 1 ENGINE - GAS GENERATOR CASE							Component ATA:72
PN:3123229-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA40F206	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								
72-40-CA-900-801	NO. 1 ENGINE - OUTER LINER COMBUSTION CHAMBER							Component ATA:72
PN:3127192-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA41F969	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
72-40-CA-900-802	NO. 1 ENGINE - INNER LINER COMBUSTION CHAMBER							Component ATA:72
PN:3116790-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA40F491	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
72-50-CA-200-801 ^S	NO. 1 ENGINE - INSPECT/CHECK EXHAUSTDUCT FOR CRACKS AND DISTORTION							Service ATA:72
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 72-50-05PROC. REF: EMM 72-50-05								PKG:1
72-50-CA-900-801	NO. 1 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY							Component ATA:72
PN:3070673-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:LPA000022725	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-802	NO. 1 ENGINE - BALL, FLANGED BEARING							Component ATA:72
PN:3112696-03	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:FCN482828	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-CA-900-803	NO. 1 ENGINE - COMPRESSOR TURBINE DISK							Component ATA:72
PN:3053740-01	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:YUAB001K732	HRS	0		TSN 0				
	ENC	0		TSN 0	(8000) 8000 (M)		7368	
	ACCCYC	0	8000	TSN 0				
PROC. REF: EMM 72-50-02PROC. REF: EMM 72-50-02								
72-50-CA-900-804	NO. 1 ENGINE - REPLACE GAS GENERATOR MODULE COMPRESSOR TURBINE BLADES							Service ATA:72
PN:PN	MOS/MSC	03-Jul-18	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-805	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037312	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:A0047RR1	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		14368	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-806	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037313	MOS	03-Jul-18		TSN 0				LIFE LIMIT
SN:YUAB001H601	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		14368	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-809	NO. 1 ENGINE - FIRST STAGE SUN GEAR							Component ATA:72
PN:3059928-01	MOS/MSC	03-Jul-18	A/R	TSN 0				
SN:PKAAA761135	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-CA-900-810	NO. 1 ENGINE - NO. 1 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	03-Jul-18	A/R	TSN 0				
SN:PKAAA760892	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-810	NO. 1 ENGINE - NO. 2 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	03-Jul-18	A/R	TSN 0				
SN:PKAAA760895	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-810	NO. 1 ENGINE - NO. 3 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	03-Jul-18	A/R	TSN 0				
SN:PKAAA760902	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-811	NO. 1 ENGINE - TURBINE 3RD STAGE VANE-RING							Component ATA:72
PN:3078643CL01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PDAMAXLR01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-812	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR ASSEMBLY							Component ATA:72
PN:3040931CL07	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PDAMAR7X01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
72-50-CA-900-813	NO. 1 ENGINE - POWER TURBINE VANE-RING							Component ATA:72
PN:3040982CL01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:BHALTNCK01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-801	NO. 1 ENGINE - HOUSING POWER TURBINE STATOR ASSEMBLY							Component ATA:72
PN:3043705-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:EDA1726H	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
72-51-CA-900-802	NO. 1 ENGINE - TURBINE EXHAUST DUCT							Component ATA:72
PN:3043919-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA39F503	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-803	NO. 1 ENGINE - POWER TURBINE COUPLING							Component ATA:72
PN:3107525-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA764005	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-804	NO. 1 ENGINE - POWER TURBINE SHAFT							Component ATA:72
PN:3109251-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:RWA00F536	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-805	NO. 1 ENGINE - POWER TURBINE COUPLING SHAFT							Component ATA:72
PN:3113744-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:PKAAA757160	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-807	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG72A698	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-808	NO. 1 ENGINE - NO. 2 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG72A717	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-809	NO. 1 ENGINE - NO. 3 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG72A724	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-810	NO. 1 ENGINE - NO. 4 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG72A732	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-811	NO. 1 ENGINE - NO. 5 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG73A446	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-812	NO. 1 ENGINE - NO. 6 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG73A453	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-813	NO. 1 ENGINE - NO. 7 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG73A457	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-814	NO. 1 ENGINE - NO. 8 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG73A468	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-815	NO. 1 ENGINE - NO. 9 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG79A886	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-816	NO. 1 ENGINE - NO. 10 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG79A896	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-817	NO. 1 ENGINE - NO. 11 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A862	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-818	NO. 1 ENGINE - NO. 12 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A863	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-819	NO. 1 ENGINE - NO. 13 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A868	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-820	NO. 1 ENGINE - NO. 14 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A897	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-821	NO. 1 ENGINE - NO. 15 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A901	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-822	NO. 1 ENGINE - NO. 16 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG85A904	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-823	NO. 1 ENGINE - NO. 17 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A062	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-824	NO. 1 ENGINE - NO. 18 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A073	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-825	NO. 1 ENGINE - NO. 19 2ND-STAGE POWER TURBINE(3RD STAGE TURBIBE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A094	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-826	NO. 1 ENGINE - NO. 20 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A565	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-827	NO. 1 ENGINE - NO. 21 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A586	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-828	NO. 1 ENGINE - NO. 22 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A588	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-829	NO. 1 ENGINE - NO. 23 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A589	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-830	NO. 1 ENGINE - NO. 24 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A743	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-831	NO. 1 ENGINE - NO. 25 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A760	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-832	NO. 1 ENGINE - NO. 26 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A973	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-833	NO. 1 ENGINE - NO. 27 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A975	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-834	NO. 1 ENGINE - NO. 28 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A976	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-835	NO. 1 ENGINE - NO. 29 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG86A982	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-836	NO. 1 ENGINE - NO. 30 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG87A010	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-837	NO. 1 ENGINE - NO. 31 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG87A111	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-838	NO. 1 ENGINE - NO. 32 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG87A117	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-839	NO. 1 ENGINE - NO. 33 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG87A126	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-840	NO. 1 ENGINE - NO. 34 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG87A142	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-841	NO. 1 ENGINE - NO. 35 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG88A007	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-842	NO. 1 ENGINE - NO. 36 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG88A029	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-843	NO. 1 ENGINE - NO. 37 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG88A039	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-844	NO. 1 ENGINE - NO. 38 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG91A055	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-845	NO. 1 ENGINE - NO. 39 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG91A056	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-846	NO. 1 ENGINE - NO. 40 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG91A059	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-847	NO. 1 ENGINE - NO. 41 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG92A252	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-848	NO. 1 ENGINE - NO. 42 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG92A262	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-849	NO. 1 ENGINE - NO. 43 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	03-Jul-18		TSN 0				REPLACE
SN:CG92A268	HRS	0	5000	TSN 0	(5000) 5000		4110.4	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-851	NO. 1 ENGINE - NO. 1 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM07K99	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-852	NO. 1 ENGINE - NO. 2 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K14	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-853	NO. 1 ENGINE - NO. 3 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K17	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-854	NO. 1 ENGINE - NO. 4 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K31	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-855	NO. 1 ENGINE - NO. 5 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K33	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-856	NO. 1 ENGINE - NO. 6 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K34	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-857	NO. 1 ENGINE - NO. 7 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K53	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-858	NO. 1 ENGINE - NO. 8 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K54	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-859	NO. 1 ENGINE - NO. 9 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K59	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-860	NO. 1 ENGINE - NO. 10 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K74	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-861	NO. 1 ENGINE - NO. 11 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K75	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-862	NO. 1 ENGINE - NO. 12 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K86	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-863	NO. 1 ENGINE - NO. 13 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K94	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-864	NO. 1 ENGINE - NO. 14 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM08K97	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-865	NO. 1 ENGINE - NO. 15 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM09K09	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-866	NO. 1 ENGINE - NO. 16 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM09K10	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-867	NO. 1 ENGINE - NO. 17 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM09K18	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-868	NO. 1 ENGINE - NO. 18 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM12N58	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-869	NO. 1 ENGINE - NO. 19 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM12N60	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-870	NO. 1 ENGINE - NO. 20 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM12N61	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-871	NO. 1 ENGINE - NO. 21 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM12N62	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-872	NO. 1 ENGINE - NO. 22 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM12N73	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-873	NO. 1 ENGINE - NO. 23 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N13	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-874	NO. 1 ENGINE - NO. 24 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N14	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-875	NO. 1 ENGINE - NO. 25 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N17	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-876	NO. 1 ENGINE - NO. 26 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N38	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-877	NO. 1 ENGINE - NO. 27 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N42	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-878	NO. 1 ENGINE - NO. 28 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM16N50	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-879	NO. 1 ENGINE - NO. 29 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM17N71	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-880	NO. 1 ENGINE - NO. 30 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM17N72	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-881	NO. 1 ENGINE - NO. 31 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM17N75	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-882	NO. 1 ENGINE - NO. 32 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM17N89	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-883	NO. 1 ENGINE - NO. 33 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N03	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-884	NO. 1 ENGINE - NO. 34 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N11	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-885	NO. 1 ENGINE - NO. 35 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N17	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-886	NO. 1 ENGINE - NO. 36 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N23	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-887	NO. 1 ENGINE - NO. 37 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N40	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-888	NO. 1 ENGINE - NO. 38 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N44	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-889	NO. 1 ENGINE - NO. 39 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N58	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-890	NO. 1 ENGINE - NO. 40 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM18N99	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-891	NO. 1 ENGINE - NO. 41 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM19N17	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-892	NO. 1 ENGINE - NO. 42 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM30L77	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-893	NO. 1 ENGINE - NO. 43 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	03-Jul-18	O/C	TSN 0				REPLACE
SN:PM97L67	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-00-200-801 ^S	ACCESSORY GEARBOX BREATHER LINE - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:72
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,10 ,11
72-60-00-200-802 ^S	ENGINE ACCESSORIES - CHECK FOR GENERAL CONDITION, ATTACHMENTS AND LINKAGE.							Service ATA:72
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-CA-900-802	NO. 1 ENGINE - FORWARD TOP GEARSHAFT,SPUR, ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281205	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-802	NO. 1 ENGINE - REAR TOP GEARSHAFT, SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281206	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-803	NO. 1 ENGINE - FORWARD BOTTOM GEARSHAFT,SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281210	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-803	NO. 1 ENGINE - REAR BOTTOM GEARSHAFT,SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281225	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-804	NO. 1 ENGINE - FORWARD GEARSHAFT, STARTER, GENERATOR DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281235	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-804	NO. 1 ENGINE - REAR GEARSHAFT,STARTER, GENERATOR DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281236	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-CA-900-805		NO. 1 ENGINE - FORWARD GEARSHAFT, DRIVE, ACCESSORY GEARBOX, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281237	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-805		NO. 1 ENGINE - REAR GEARSHAFT, DRIVE, ACCESSORY GEARBOX, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281247	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-806		NO. 1 ENGINE - FORWARD GEARSHAFT ASSEMBLY, SPUR, FUEL CONROL DRIVE, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281248	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-806		NO. 1 ENGINE - REAR GEARSHAFT ASSEMBLY, SPUR, FUEL CONTROL DRIVE, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281249	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-807		NO. 1 ENGINE - FORWARD GEARSHAFT, SCAVENGE PUMP, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281258	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-807		NO. 1 ENGINE - REAR GEARSHAFT, SCAVENGE PUMP, FLANGED ROLLER BEARING					Component	ATA:72
PN:3073908-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:AEB0281264	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-02-200-801	NO. 1 ENGINE - FUEL PUMP INLET SCREEN - CHECK AND CLEAN							Service ATA:73
PN:3040760	MOS	03-Aug-22						
SN:016018	HRS	607.6	600 (+10%)	Adj -7.6	(1200) 1200	1260	310.4 (+60)	
	ENC							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-02-200-802 ^S	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - CHECK FOR FOREIGN MATTER OR DISTORTION							Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
								PKG:1
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-02-960-801	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - REPLACE							Service ATA:73
PN:3040760	MOS	05-Sep-23						REPLACE
SN:016018	HRS	688.8	600 (+10%)		(1288.8) 1288.8	1348.8	399.2 (+60)	
	ENC							
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
73-10-05-790-801	NO. 1 ENGINE - FUEL MANIFOLD ADAPTERS - PERFORM LEAK TEST AND FUNCTION TEST							Service ATA:73
	MOS	05-Sep-23						
	HRS	688.8	400 (+10%)		(1088.8) 1088.8	1128.8	199.2 (+40)	
	ENC							
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-10-06-200-801 ^S	GENERATOR CASE DRAIN - CHECK FOR ATTACHMENT AND LEAKS.							Service ATA:73
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
								PKG:5,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-07-130-801 ^S	P3 FILTER - ULTRASONIC CLEANING. CHECK FOR CONDITON AND ATTACHMENT.							Service ATA:73
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: EMM 73-10-07, EMM 73-10-07PROC. REF: EMM 73-10-07, EMM 73-10-07								PKG:1,5,6,7,8,9 ,10 ,11
73-10-07-960-801	NO. 1 ENGINE - P3 FILTER - REPLACE							Service ATA:73
PN:PN	MOS	03-Jul-18						REPLACE
SN:UNKNOWN	HRS	0	1000 (+100)		(1000) 1000	1100	110.4 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-07.10	NO. 1 ENGINE - COMPRESSOR DELIVERY AIR LINES ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								
73-10-07.9	NO. 1 ENGINE - COMPRESSOR DELIVERY AIR LINES APPROVED REPAIRS							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								
73-10-08.7	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES INSPECTION CHECK							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								
73-10-08.8	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES APPROVED REPAIRS.							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-08.9	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								
73-10-09.7	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE INSPECTION CHECK							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-10-09.8	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE APPROVED REPAIRS							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-10-09.9	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-10-CA-200-801 ^S	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS							Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-CA-200-802	^S	NO. 1 ENGINE - CHECK FLOW DIVIDER FOR INSTALLATION AND LEAKS						Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								PKG:1
73-10-CA-200-803	^S	NO. 1 ENGINE - CHECK OIL-TO-FUEL HEATER INSTALLATION						Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								PKG:1
73-10-CA-200-804	^S	NO. 1 ENGINE - CHECK P3 FILTER FOR INSTALLATION						Service ATA:73
PN:PN	MOS	15-Oct-24	12 (+1m)					
SN:UNKNOWN	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								PKG:1
73-10-CA-200-805	^S	NO. 1 ENGINE - CHECK DRAIN VALVE(S) FOR INSTALLATION AND LEAKS						Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-06PROC. REF: EMM 73-10-06								PKG:1
73-10-CA-200-806	^S	NO. 1 ENGINE - CHECK FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE						Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-CA-210-804 ^S	NO. 1 ENGINE - EXAMINE PNEUMATICSYSTEM FILTER BOWL							Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								PKG:1
73-10-CA-900-801	NO. 1 ENGINE - REPLACE FUEL CONTOL UNIT BELLOWS							Service ATA:73
PN:3120023-10	MOS/MSC	03-Jul-18	O/C					
SN:21179246	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-CA-900-802	NO. 1 ENGINE - ENGINE DRIVEN FUEL PUMP							Component ATA:73
PN:3040760	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:016018	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
73-10-CA-900-803	NO. 1 ENGINE - FUEL HEATER							Component ATA:73
PN:3057249-01	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:WA57135	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								
73-10-CA-900-804	NO. 1 ENGINE - FLOW DIVIDER/START CONTROL VALVE							Component ATA:73
PN:3023670	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:M0972	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-CA-900-805	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3120023-10	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:21179246	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-11-05.7	NO. 1 ENGINE - DUPLEX FUEL MANIFOLD INSPECTION CHECK							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-11-05.8	NO. 1 ENGINE - FUEL MANIFOLD APPROVED REPAIRS							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-11-05.9	NO. 1 ENGINE - DUPLEX FUEL MANIFOLD ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-11-CA-900-801	NO. 1 ENGINE - OVERTORQUE LIMITER							Component ATA:73
PN:3055726-01	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:F14505	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-20-00.7	NO. 1 ENGINE - FUEL CONTROL UNIT INSPECTION CHECK							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-00.8	NO. 1 ENGINE - FUEL CONTROL UNIT APPROVED REPAIRS							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-00.9	NO. 1 ENGINE - FUEL CONTROL UNIT ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-CA-200-801 ^S	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES							Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								PKG:1
73-30-CA-100-801 ^S	NO. 1 ENGINE - CLEAN PNEUMATIC P3 FILTER							Service ATA:73
PN:PN	MOS	15-Oct-24	12 (+1m)					
SN:UNKNOWN	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								PKG:1
73-30-CA-100-802 ^S	NO. 1 ENGINE - CLEAN/INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY							Service ATA:73
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 73-10-07, EMM 73-10-07PROC. REF: EMM 73-10-07, EMM 73-10-07								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-CA-900-801	NO. 1 ENGINE - P3 FILTER							Component ATA:73
PN:PN	MOS/MSC	03-Jul-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 74 - IGNITION								
74-00-CA-200-801	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION							Service ATA:74
	MOS	05-Sep-23						
	HRS	688.8	400 (+10%)		(1088.8) 1088.8	1128.8	199.2 (+40)	
	ENC							
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								
74-00-CA-900-801	NO. 1 ENGINE - IGNITION EXCITER							Component ATA:74
PN:3035889	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:NNA18090041	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								
74-10-00-200-801	IGNITION EXCITER - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:74
	MOS	05-Sep-23						
	HRS	688.8	400 (+10/-10)		1088.8	1098.8	199.2 (+10)	
	AFL							
PROC. REF: AMM 74-00-00, EMM 74-10-00PROC. REF: AMM 74-00-00, EMM 74-10-00								
74-20-00-200-801	IGNITION CABLES - CHECK FOR ROUTING, ATTACHMENT AND WEAR DUE TO CHAFING.							Service ATA:74
	MOS	05-Sep-23						
	HRS	688.8	400 (+10/-10)		1088.8	1098.8	199.2 (+10)	
	AFL							
PROC. REF: AMM 74-00-00PROC. REF: AMM 74-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-20-00-200-802	SPARK IGNITERS - CHECK FOR CLEANLINESS AND EROSION.							Service ATA:74
	MOS	05-Sep-23						
	HRS	688.8	400 (+10/-10)		1088.8	1098.8	199.2 (+10)	
	AFL							
PROC. REF: AMM 74-20-00PROC. REF: AMM 74-20-00								
74-20-00-710-801 ^S	SPARK IGNITERS - DO AN OPERATIONAL TEST.							Service ATA:74
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 74-20-00, AMM 74-20-00, EMM 74-00-00PROC. REF: AMM 74-20-00, AMM 74-20-00, EMM 74-00-00								
74-20-CA-200-802	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECKFUNCTION							Service ATA:74
	MOS	05-Sep-23						
	HRS	688.8	400 (+10%)		(1088.8) 1088.8	1128.8	199.2 (+40)	
	ENC							
PROC. REF: EMM 74-20-00PROC. REF: EMM 74-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-00-00-900-801	AIR INTAKE ASSEMBLY							Component ATA:75
PN:T700H716010500012	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:TB241	HRS	0		TSN 0				
WC#: 75.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
75-30-00.7	NO. 1 ENGINE - COMPRESSOR BLEED VALVE INSPECTION CHECK							Service ATA:75
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-00PROC. REF: EMM 75-30-00								
75-30-CA-900-801	NO. 1 ENGINE - BLEED VALVE COMPRESSOR							Component ATA:75
PN:3059835-01	MOS	03-Jul-18		TSN 0				OVERHAUL
SN:AHX1001352	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2610.4 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-00PROC. REF: EMM 75-30-00								
ATA 76 - ENGINE CONTROLS								
76-10-00-200-801 ^S	ENGINE CONTROLS - CHECK FOR TRAVEL, ATTACHMENT, ROUTING AND EVIDENCE OF DAMAGE.							Service ATA:76
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 76-10-00, AMM 76-10-00PROC. REF: AMM 76-10-00, AMM 76-10-00								
76-10-CA-200-801 ^S	NO. 1 ENGINE - INSPECT CONTROL LINKAGES							Service ATA:76
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
								PKG:1
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
ATA 77 - ENGINE INDICATING								
77-00-00-601	NO. 1 ENGINE - ENGINE INDICATING INSPECTION CHECK ALL							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								
77-10-CA-900-801	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS							Component ATA:77
PN:3043825-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:NRA102805	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-11-00-200-801 ^S	MT12 NG TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE.							Service ATA:77
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,11
77-11-00-900-801	NO. 1 RPM TRANSMITTER							Component ATA:77
PN:MIL.G.26611CGEU7/A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:319228	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
77-11-00-900-801	NO. 2 RPM TRANSMITTER							Component ATA:77
PN:MIL.G.26611CGEU7/A	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:319227	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
77-11-02-900-801	SIGNAL CONDITIONER							Component ATA:77
PN:305662-00	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:1389	HRS	0		TSN 0				
WC#: 77.080	AFL	0		TSN 0				
PROC. REF: AMM 77-11-02, AMM 77-11-02PROC. REF: AMM 77-11-02, AMM 77-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-12-00-200-801 ^S	MT41 FUEL FLOW TRANSMITTER - CHECK FOR ATTACHMENT, LEAKS AND EVIDENCE OF DAMAGE.							Service ATA:77
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00							PKG:1,5,6,7,8,9 ,10 ,11	
77-13-00-101.01	NO. 1 ENGINE - PROPELLER SPEED (NP) INDICATING TROUBLE SHOOTING UP TO SN 1269							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-13-00PROC. REF: AMM 77-13-00								
77-13-00-101.02	NO. 1 ENGINE - PROPELLER SPEED (NP) INDICATING TROUBLE SHOOTING FROM SN 1270							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-13-00PROC. REF: AMM 77-13-00								
77-13-00-200-801 ^S	MT11 NP TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE.							Service ATA:77
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00							PKG:5,11	
77-14-00-101	NO. 1 ENGINE - ENGINE TORQUE INDICATING TROUBLE SHOOTING ALL							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-200-801 ^S	MT10 TORQUE TRANSMITTER - CHECK FOR ATTACHMENT AND LEAKS.							Service ATA:77
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
							PKG:1,5,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								
77-14-00-501 KULITE	NO. 1 ENGINE - ENGINE TORQUE INDICATING ADJUSTMENT TEST KULITE							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-501 SAGEM	NO. 1 ENGINE - ENGINE TORQUE ADJUSTMENT TEST SAGEM							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-501 THALES	NO. 1 ENGINE - ENGINE TORQUE INDICATING ADJUSTMENT TEST THALES							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-900-801	TORQUE TRANSDUCER							Component ATA:77
PN:660526AS	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:5829	HRS	0		TSN 0				
WC#: 77.070	AFL	0		TSN 0				
PROC. REF: AMM 77-12-00, AMM 77-12-00PROC. REF: AMM 77-12-00, AMM 77-12-00								
77-14-00-900-802	TORQUE DETECTOR							Component ATA:77
PN:APTE-438-1000-75D	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:8458-6-45	HRS	0		TSN 0				
WC#: 77.040	AFL	0		TSN 0				
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-00-200-802	^S	MT13 THERMOCOUPLE HARNESS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:77
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,11
77-20-00-501 POST		NO. 1 ENGINE - ENGINE TEMPERATURE INDICATING ADJUSMENT TEST POST MOD70-0323-71						Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-20-00PROC. REF: AMM 77-20-00								
77-20-00-501 PRE		NO. 1 ENGINE - ENGINE TEMPERATURE INDICATING ADJUSTMET TEST PRE MOD70-033-71						Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-20-00PROC. REF: AMM 77-20-00								
77-20-01.7		NO. 1 ENGINE - SENSING SYSTEM INSPECTION CHECK						Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-01.8		NO. 1 ENGINE - T5 SENSING SYSTEM APPROVED REPAIRS						Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-01.9		NO. 1 ENGINE - T5 SENSING SYSTEM ADJUSTMENT TEST						Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-CA-900-801	NO. 1 ENGINE - T5 BUS BAR POSITIVE TERMINAL ASSEMBLY							Component ATA:77
PN:3109240-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:NR14868	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-CA-900-802	NO. 1 ENGINE - T5 BUS BAR NEGATIVE TERMINAL ASSEMBLY							Component ATA:77
PN:3109239-01	MOS/MSC	03-Jul-18	O/C	TSN 0				
SN:NR14556	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-21-00-101	NO. 1 ENGINE - INTERTUBINE TEMPERATURE (ITT) INDICATING TROUBLE SHOOTING ALL							Service ATA:77
	MOS/MSC	03-Jul-18	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-21-00PROC. REF: AMM 77-21-00								
ATA 78 - EXHAUST								
78-10-00-200-801 ^S	EXHAUST STUBS - CHECK FOR ATTACHMENT, CRACKS, DISTORTIONS AND EVIDENCE OF DAMAGE.							Service ATA:78
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 78-10-00PROC. REF: AMM 78-10-00								
ATA 79 - OIL								
79-00-00-680-801	NO. 1 ENGINE - ENGINE OIL - CHANGE OIL							Service ATA:79
	MOS/MSC	22-Jul-21	O/C					
	HRS	488.9						
	ENC							
PROC. REF: AMM 12-12-02-301, AMM 12-12-02 (A1), AMM 12-12-02PROC. REF: AMM 12-12-02-301, AMM 12-12-02 (A1), AMM 12-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-00-CA-200-801	^S	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR(S) FOR CONTINUITY						Service ATA:79
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								PKG:1
79-00-CA-200-802	^S	NO. 1 ENGINE - EXAMINE THE OIL FILTER ELEMENT AND SECONDARY SCREEN						Service ATA:79
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								PKG:1
79-00-CA-200-803	^S	NO. 1 ENGINE - CHECK SCAVANGE OIL PUMP HOUSING FOR LEAKS						Service ATA:79
	MOS	15-Oct-24	12 (+1m)					
	HRS	834	200 (+10)					
	ENC	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
79-00-CA-610-801		NO. 1 ENGINE - SERVICING OIL SYSTEM						Service ATA:79
	MOS	15-Oct-24	12 (+1m)	Adj -73d	03-Aug-25	03-Sep-25	59 d (+31)	
	HRS	834						
	ENC							
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
79-00-CA-900-802		NO. 1 ENGINE - OIL FILTER ELEMENT						Component ATA:79
PN:PN	MOS/MSC	03-Jul-18	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-10-00-200-801	^S	OIL FILLER CAP - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:79
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1,5,6,7,8,9 ,10 ,11
79-20-00-200-801	^S	OIL FILTER - INSPECT AND CLEAN IF NECESSARY.						Service ATA:79
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
PROC. REF: AMM 79-20-02, EMM 79-20-02PROC. REF: AMM 79-20-02, EMM 79-20-02								PKG:1,5,6,7,8,9 ,10 ,11
79-20-00-200-802		NO. 1 ENGINE - ACCESSORY GEARBOX - CHECK INTERNAL SCAVENGE PUMP INLET SCREEN						Service ATA:79
	MOS	03-Jul-18						
	HRS	0	1000 (+100)		(1000) 1000	1100	110.4 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-20-00-200-803	^S	OIL COOLER - CHECK FOR CONDITION, ATTACHMENT, EVIDENCE OF DAMAGE AND LEAKS. CHECK CORE CLEANLINESS.						Service ATA:79
	MOS	03-Aug-22	48 (+1m/-1m)					
	HRS	607.6	800 (+10/-10)					
	AFL							
PROC. REF: AMM 79-20-00PROC. REF: AMM 79-20-00								PKG:5,11
79-20-00-730-801		OIL COOLER - OVERHAUL						Component ATA:79
PN:L8538233	MOS	24-Jul-19		TSO 0				OVERHAUL
SN:08C-015	HRS	196.2	2100 (+10%/-10%)	TSO 0	2296.2	2506.2	1406.6 (+210)	
WC#: 79.020	AFL			TSO 0				
PROC. REF: AMM 79-20-01, AMM 79-20-01PROC. REF: AMM 79-20-01, AMM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20-00-960-801	NO. 1 ENGINE - OIL FILTER - REPLACE							Service ATA:79
PN:PN	MOS	03-Aug-22						REPLACE
SN:UNKNOWN	HRS	607.6	1000 (+100)	Adj -607.6	(1000) 1000	1100	110.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-20-02-710-801	NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST							Service ATA:79
	MOS	15-Oct-24	12 (+1m)	Adj -73d	03-Aug-25	03-Sep-25	59 d (+31)	
	HRS	834	600 (+10%)		(1434) 1434	1494	544.4 (+60)	
	ENC	612						
PROC. REF: AMM 72-00-00 (A1), AMM 72-00-00, EMM 79-20-02PROC. REF: AMM 72-00-00 (A1), AMM 72-00-00, EMM 79-20-02								
79-20-02-760-801 ^S	CHIP DETECTOR - CHECK CONTINUITY WITH AN OHMMETER.							Service ATA:79
	MOS	15-Oct-24	12 (+1m/-1m)					
	HRS	834	200 (+10/-10)					
	AFL	612						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: EMM 79-20-02, EMM 79-20-02PROC. REF: EMM 79-20-02, EMM 79-20-02								
79-30-00-200-801 ^S	S42 PRESSURE SWITCH AND MT15 OIL TEMPERATURE PROBE - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.							Service ATA:79
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:5,10 ,11
PROC. REF: AMM 79-30-00PROC. REF: AMM 79-30-00								
79-30-00-200-802 ^S	MT14 OIL PRESSURE TRANSMITTER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.							Service ATA:79
	MOS	15-Oct-24	24 (+1m/-1m)					
	HRS	834	400 (+10/-10)					
	AFL	612						
								PKG:5,10 ,11
PROC. REF: AMM 79-30-00PROC. REF: AMM 79-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1242 RegNo: N910ZV HRS: 889.6 AFL: 632 As Of: 04-Jun-2025

05-Jun-2025 11:28 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-03-900-801		OIL PRESSURE SENDER UNIT						Component ATA:79
PN:APT-369A-1000-150G		MOS/MSC	03-Jul-18	O/C	TSN 0			
SN:8279-93-73		HRS	0	TSN 0				
WC#: 79.030		AFL	0	TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task