

|                                  |  |                              |  |                                                                                       |  |
|----------------------------------|--|------------------------------|--|---------------------------------------------------------------------------------------|--|
| OWNER: FORTUNE AVIATION, LLC     |  | OPERATOR: JETPROS, LLC       |  | OPERATOR: FW AVIATION MANAGEMENT, LLC                                                 |  |
| ADDRESS: 1522 COLONY CIR         |  | ADDRESS: 231 TERMINAL CIRCLE |  | ADDRESS: 4301 NORTH MAIN STREET                                                       |  |
| LONGVIEW TX 75604                |  | LONGVIEW TX 75603            |  | FORT WORTH TX 76106-2746                                                              |  |
| OFFICE: (903) 753-3050           |  | OFFICE: 903-300-5533         |  | OFFICE: 8176240030                                                                    |  |
| FAX:                             |  | FAX:                         |  | FAX: 8176240031                                                                       |  |
| ANALYST: OBUM ONWUDIWE           |  | (514)448-1163 (DIRECT)       |  | 800-787-9749 (EFAX-CARDS)                                                             |  |
| EMAIL: OONWUDIWE@CAMPSYSTEMS.COM |  | +1-631-588-3200 (MAIN)       |  | 631-980-4222 (EFAX-CARDS)                                                             |  |
|                                  |  | WWW.CAMPSYSTEMS.COM          |  | PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY). |  |

|                                 |                                 |               |            |                       |
|---------------------------------|---------------------------------|---------------|------------|-----------------------|
| AIRCRAFT                        | SERIAL / REGNO: 50500281/N419PJ | MODEL:        | PHENOM 300 | MANUFACTURER: EMBRAER |
| CERTIFICATION DATE: 29-APR-2015 |                                 | LAST ACTUALS: |            |                       |
|                                 |                                 | 2100          | A/C HRS    | as of 16-JUN-2025     |
|                                 |                                 | 1252          | AFL        | as of 16-JUN-2025     |
|                                 |                                 | 612.4         | CDMHRS     | as of 29-APR-2024     |

|                           |                                       |           |               |                                            |                   |
|---------------------------|---------------------------------------|-----------|---------------|--------------------------------------------|-------------------|
| ENGINE NO. 1              | SERIAL / PART: PCE-DG0533/A3072913-01 | MODEL:    | PW535E        | MANUFACTURER: PRATT & WHITNEY CANADA CORP. |                   |
| INSTALLED ON: 17-DEC-2014 |                                       |           | LAST ACTUALS: |                                            |                   |
| 0                         | ENG. HRS                              | 0 A/C HRS | 2100          | ENG. HRS                                   | as of 16-JUN-2025 |
| 0                         | ENC                                   |           | 1252          | ENC                                        | as of 16-JUN-2025 |

|                           |                                       |           |               |                                            |
|---------------------------|---------------------------------------|-----------|---------------|--------------------------------------------|
| ENGINE NO. 2              | SERIAL / PART: PCE-DG0534/A3072913-01 | MODEL:    | PW535E        | MANUFACTURER: PRATT & WHITNEY CANADA CORP. |
| INSTALLED ON: 17-DEC-2014 |                                       |           | LAST ACTUALS: |                                            |
| 0                         | ENG. HRS                              | 0 A/C HRS | 2100          | ENG. HRS as of 16-JUN-2025                 |
| 0                         | ENC                                   |           | 1252          | ENC as of 16-JUN-2025                      |

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                                        | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|----------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA GENERAL                                    |              |                                                                            |               |          |                        |           |           |             |                |
| Z210-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION    |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                                  | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                     |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                       |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                        |           |           |             | PKG:87         |
| Z210-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION    |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                                  | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                     |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                       |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                        |           |           |             | PKG:87         |
| Z220-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                                  | 60 (+1m/-1m)  |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                     |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                       |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                        |           |           |             | PKG:84         |
| Z220-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                                  | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                     |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                       |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                        |           |           |             | PKG:87         |
| Z230-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION    |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                                  | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                     |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                       |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                            |               |          |                        |           |           |             | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                                     | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|-------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA GENERAL                                    |              |                                                                         |               |          |                        |           |           |             |                |
| Z230-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                               | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                  |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                    |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                        |           |           |             | PKG:87         |
| Z240-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION  |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                               | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                  |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                    |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                        |           |           |             | PKG:87         |
| Z240-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION  |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                               | 60 (+1m/-1m)  |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                  |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                    |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                        |           |           |             | PKG:84         |
| Z310-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION    |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                               | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                  |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                    |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                         |               |          |                        |           |           |             | PKG:87         |
| Z310-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION    |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                               | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                                  |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                    |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                         |               |          |                        |           |           |             | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                                 | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|---------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA GENERAL                                    |              |                                                                     |               |          |                        |           |           |             |                |
| Z320-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                           | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                              |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                     |               |          |                        |           |           |             | PKG:87         |
| Z320-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                           | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                              |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                     |               |          |                        |           |           |             | PKG:87         |
| Z330-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER       |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                           | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                              |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                        |           |           |             | PKG:87         |
| Z330-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER       |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                           | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                              |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                        |           |           |             | PKG:87         |
| Z340-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER     |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                           | 60 (+1m/-1m)  |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                              |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                                |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                        |           |           |             | PKG:84         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                             | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|-----------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA GENERAL                                    |              |                                                                 |               |          |                        |           |           |             |                |
| Z340-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                       | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                          |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                            |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                 |               |          |                        |           |           |             | PKG:87         |
| Z410-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON                 |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                       | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                          |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                            |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                        |           |           |             | PKG:87         |
| Z410-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON                 |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                       | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                          |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                            |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                        |           |           |             | PKG:87         |
| Z430-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE               |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                       | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                          |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                            |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                        |           |           |             | PKG:87         |
| Z430-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE               |               |          |                        |           |           |             | Service ATA:-- |
|                                                | MOS          | 14-May-25                                                       | 120 (+1m/-1m) |          |                        |           |           |             |                |
|                                                | HRS          | 2086.2                                                          |               |          |                        |           |           |             |                |
|                                                | AFL          | 1243                                                            |               |          |                        |           |           |             |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                        |           |           |             | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                     | C/W                                                             | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                 | Warranty       |
|------------------------------------------------|------------------------------------------|-----------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-----------------------------|----------------|
| ATA GENERAL                                    |                                          |                                                                 |              |          |                        |           |           |                             |                |
| Z500-001                                       | <sup>S</sup>                             | EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS                 |              |          |                        |           |           |                             | Service ATA:-- |
|                                                | MOS                                      | 14-May-25                                                       | 60 (+1m/-1m) |          |                        |           |           |                             |                |
|                                                | HRS                                      | 2086.2                                                          |              |          |                        |           |           |                             |                |
|                                                | AFL                                      | 1243                                                            |              |          |                        |           |           |                             |                |
| PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00 |                                          |                                                                 |              |          |                        |           |           |                             | PKG:84         |
| Z500-002                                       | <sup>S</sup>                             | INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS                 |              |          |                        |           |           |                             | Service ATA:-- |
|                                                | MOS                                      | 14-May-25                                                       | 60 (+1m/-1m) |          |                        |           |           |                             |                |
|                                                | HRS                                      | 2086.2                                                          |              |          |                        |           |           |                             |                |
|                                                | AFL                                      | 1243                                                            |              |          |                        |           |           |                             |                |
| PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00 |                                          |                                                                 |              |          |                        |           |           |                             | PKG:84         |
| Z700-001                                       | <sup>S</sup>                             | EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY |              |          |                        |           |           |                             | Service ATA:-- |
|                                                | MOS                                      | 14-May-25                                                       | 60 (+1m/-1m) |          |                        |           |           |                             |                |
|                                                | HRS                                      | 2086.2                                                          |              |          |                        |           |           |                             |                |
|                                                | AFL                                      | 1243                                                            |              |          |                        |           |           |                             |                |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00 |                                          |                                                                 |              |          |                        |           |           |                             | PKG:84         |
| ATA 00 - INFORMATION                           |                                          |                                                                 |              |          |                        |           |           |                             |                |
| E53E-160530                                    | NO. 1 ENGINE - REVIEW PW535E MM REV 11.0 |                                                                 |              |          |                        |           |           | Service                     | ATA:00         |
|                                                | MOS/MSC                                  | EFF                                                             | -            |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                      |                                                                 |              |          |                        |           |           |                             |                |
|                                                | ENC                                      |                                                                 |              |          |                        |           |           |                             |                |
| PROC. REF: RCF E53EPROC. REF: RCF E53E         |                                          |                                                                 |              |          |                        |           |           |                             |                |
| E53E-160530                                    | NO. 2 ENGINE - REVIEW PW535E MM REV 11.0 |                                                                 |              |          |                        |           |           | Service                     | ATA:00         |
|                                                | MOS/MSC                                  | EFF                                                             | -            |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                      |                                                                 |              |          |                        |           |           |                             |                |
|                                                | ENC                                      |                                                                 |              |          |                        |           |           |                             |                |
| PROC. REF: RCF E53EPROC. REF: RCF E53E         |                                          |                                                                 |              |          |                        |           |           |                             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                  | Unit                                                                                                                                               | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                 | Warranty |
|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|-----|----------|----------|------------------------|-----------|-----------|-----------------------------|----------|
| ATA 00 - INFORMATION                                     |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |
| EM55-160520                                              | REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16                                   |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                            |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-160520PROC. REF: RCF EM55-160520     |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |
| EM55-160705                                              | REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY<br>CHANGE FORM                      |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                            | EFF | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-160705PROC. REF: RCF EM55-160705     |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |
| EM55-160705-1                                            | REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16<br>REQUIREMENT CHANGE FORM           |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                            | EFF | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-160705-1PROC. REF: RCF EM55-160705-1 |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |
| EM55-160822                                              | REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016<br>REQUIREMENT SUMMARY CHANGE FORM         |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                            |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-160822PROC. REF: RCF EM55-160822     |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |
| EM55-161022                                              | REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016<br>REQUIREMENT SUMMARY CHANGE FORM |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                            |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-161022PROC. REF: RCF EM55-161022     |                                                                                                                                                    |     |          |          |                        |           |           |                             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                  | Unit                                                                                                                                                          | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                 | Warranty |
|----------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|----------|----------|------------------------|-----------|-----------|-----------------------------|----------|
| ATA 00 - INFORMATION                                     |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |
| EM55-161122                                              | REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016                                                    |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                                       | EFF | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-161122PROC. REF: RCF EM55-161122     |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |
| EM55-161122-1                                            | REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016                                               |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                                       |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-161122-1PROC. REF: RCF EM55-161122-1 |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |
| EM55-161202                                              | REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED<br>DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                                       |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55-161202PROC. REF: RCF EM55-161202     |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |
| EM55-180219                                              | REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED<br>FEB 19/18                                 |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                                       | EFF | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55PROC. REF: RCF EM55                   |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |
| EM55-190218A                                             | REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019                                                           |     |          |          |                        |           |           | Service                     | ATA:00   |
|                                                          | MOS/MSC                                                                                                                                                       |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |          |
|                                                          | HRS                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
|                                                          | AFL                                                                                                                                                           |     |          |          |                        |           |           |                             |          |
| PROC. REF: RCF EM55PROC. REF: RCF EM55                   |                                                                                                                                                               |     |          |          |                        |           |           |                             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                            | Unit                                                                         | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                 | Warranty       |
|------------------------------------|------------------------------------------------------------------------------|-----|----------|----------|------------------------|-----------|-----------|-----------------------------|----------------|
| ATA 00 - INFORMATION               |                                                                              |     |          |          |                        |           |           |                             |                |
| EM55-210514-ALS                    | REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021  |     |          |          |                        |           |           |                             | Service ATA:00 |
|                                    | MOS/MSC                                                                      |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                    | HRS                                                                          |     |          |          |                        |           |           |                             |                |
|                                    | AFL                                                                          |     |          |          |                        |           |           |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                        |           |           |                             |                |
| EM55-211103-SMR                    | REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021         |     |          |          |                        |           |           |                             | Service ATA:00 |
|                                    | MOS/MSC                                                                      |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                    | HRS                                                                          |     |          |          |                        |           |           |                             |                |
|                                    | AFL                                                                          |     |          |          |                        |           |           |                             |                |
| EM55-220505-CAMP<br>ADJUSTMENT     | REVIEW CAMP ADJUSTMENT FORM DATED MAY 05/2022 FOR EMBRAER PHENOM 300         |     |          |          |                        |           |           |                             | Service ATA:00 |
|                                    | MOS/MSC                                                                      |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                    | HRS                                                                          |     |          |          |                        |           |           |                             |                |
|                                    | AFL                                                                          |     |          |          |                        |           |           |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                        |           |           |                             |                |
| EM55-220630-CAMP<br>ADJUSTMENT     | REVIEW EMBRAER EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED JUN 30, 2022      |     |          |          |                        |           |           |                             | Service ATA:00 |
|                                    | MOS/MSC                                                                      |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                    | HRS                                                                          |     |          |          |                        |           |           |                             |                |
|                                    | AFL                                                                          |     |          |          |                        |           |           |                             |                |
| PROC. REF: RCF -PROC. REF: RCF -   |                                                                              |     |          |          |                        |           |           |                             |                |
| EM55-220812-CAMP<br>ADJUSTMENT     | REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-505 - PHENOM 300 |     |          |          |                        |           |           |                             | Service ATA:00 |
|                                    | MOS/MSC                                                                      |     | -        |          |                        |           |           | REQUIREMENT<br>CHANGE FORMS |                |
|                                    | HRS                                                                          |     |          |          |                        |           |           |                             |                |
|                                    | AFL                                                                          |     |          |          |                        |           |           |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                        |           |           |                             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                                                                                         | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition                 | Warranty       |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-------------|-----------------------------|----------------|
| ATA 00 - INFORMATION                           |                                                                                                              |           |               |          |                        |           |             |                             |                |
| EM55-221017-AWL                                | REVIEW EMB-505 - PHENOM 300 AMM - PART IV - AIRWORTHINESS LIMITATIONS (AWL) REV 1 DATED OCT 17/2022          |           |               |          |                        |           |             |                             | Service ATA:00 |
|                                                | MOS/MSC                                                                                                      |           | -             |          |                        |           |             | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                                                                                          |           |               |          |                        |           |             |                             |                |
|                                                | AFL                                                                                                          |           |               |          |                        |           |             |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |          |                        |           |             |                             |                |
| EM55-221103-SMR                                | REVIEW EMB-505 - PHENOM 300 AMM - PART III - SCHEDULE MAINTENANCE REQUIREMENTS (SMR) REV 5 DATED NOV 03/2022 |           |               |          |                        |           |             |                             | Service ATA:00 |
|                                                | MOS/MSC                                                                                                      |           | -             |          |                        |           |             | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                                                                                          |           |               |          |                        |           |             |                             |                |
|                                                | AFL                                                                                                          |           |               |          |                        |           |             |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |          |                        |           |             |                             |                |
| EM55-230201-CAMP<br>ADJUSTMENT                 | REVIEW EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED FEB 01, 2023                                              |           |               |          |                        |           |             |                             | Service ATA:00 |
|                                                | MOS/MSC                                                                                                      |           | -             |          |                        |           |             | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                                                                                          |           |               |          |                        |           |             |                             |                |
|                                                | AFL                                                                                                          |           |               |          |                        |           |             |                             |                |
| EM55-230216-CAMP<br>ADJUSTMENT                 | REVIEW CAMP ADJUSTMENT FORM DATED FEB 16/2023 FOR EMB-505 - PHENOM 300                                       |           |               |          |                        |           |             |                             | Service ATA:00 |
|                                                | MOS/MSC                                                                                                      |           | -             |          |                        |           |             | REQUIREMENT<br>CHANGE FORMS |                |
|                                                | HRS                                                                                                          |           |               |          |                        |           |             |                             |                |
|                                                | AFL                                                                                                          |           |               |          |                        |           |             |                             |                |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |          |                        |           |             |                             |                |
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                                              |           |               |          |                        |           |             |                             |                |
| 05-30-01                                       | 800 FH MAINTENANCE PACKAGE                                                                                   |           |               |          |                        |           |             |                             | Package ATA:05 |
|                                                | MOS                                                                                                          | 29-Apr-24 |               |          |                        |           |             |                             |                |
|                                                | HRS                                                                                                          | 1952.5    | 800 (+30/-30) |          | 2752.5                 | 2782.5    | 652.5 (+30) |                             |                |
|                                                | AFL                                                                                                          | 1160      |               |          |                        |           |             |                             |                |
| PROC. REF: SMR 05-30-01PROC. REF: SMR 05-30-01 |                                                                                                              |           |               |          |                        |           |             |                             |                |
|                                                |                                                                                                              |           |               |          |                        |           |             |                             | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                           | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|------------------------------------------------|------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                |           |                |          |                        |           |             |             |                |
| 051254                                         | NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION |           |                |          |                        |           |             |             | Package ATA:05 |
|                                                | MOS                                            | 14-May-25 | 12 (+30d)      |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |             |                |
|                                                | HRS                                            | 2086.2    | 800 (+10%)     |          | (2886.2)<br>2886.2     | 2966.2    | 786.2 (+80) |             |                |
|                                                | ENC                                            | 1243      |                |          |                        |           |             |             |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00   |                                                |           |                |          |                        |           |             |             | PKG:1          |
| 051254                                         | NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION |           |                |          |                        |           |             |             | Package ATA:05 |
|                                                | MOS                                            | 14-May-25 | 12 (+30d)      |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |             |                |
|                                                | HRS                                            | 2086.2    | 800 (+10%)     |          | (2886.2)<br>2886.2     | 2966.2    | 786.2 (+80) |             |                |
|                                                | ENC                                            | 1243      |                |          |                        |           |             |             |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00   |                                                |           |                |          |                        |           |             |             | PKG:1          |
| 05-30-10                                       | 1600 FH MAINTENANCE PACKAGE                    |           |                |          |                        |           |             |             | Package ATA:05 |
|                                                | MOS                                            | 28-Dec-18 |                |          |                        |           |             |             |                |
|                                                | HRS                                            | 1178.1    | 1600 (+30/-30) | Adj 21.9 | 2800                   | 2830      | 700 (+30)   |             |                |
|                                                | AFL                                            | 679       |                |          |                        |           |             |             |                |
| PROC. REF: SMR 05-30-10PROC. REF: SMR 05-30-10 |                                                |           |                |          |                        |           |             |             | PKG:10         |
| 05-30-20                                       | 2400 FH MAINTENANCE PACKAGE                    |           |                |          |                        |           |             |             | Package ATA:05 |
|                                                | MOS                                            | 29-Apr-15 |                |          |                        |           |             |             |                |
|                                                | HRS                                            | 0         | 2400 (+30/-30) |          | 2400                   | 2430      | 300 (+30)   |             |                |
|                                                | AFL                                            | 0         |                |          |                        |           |             |             |                |
| PROC. REF: SMR 05-30-20PROC. REF: SMR 05-30-20 |                                                |           |                |          |                        |           |             |             | PKG:20         |
| 05-30-40                                       | 3200 FH MAINTENANCE PACKAGE                    |           |                |          |                        |           |             |             | Package ATA:05 |
|                                                | MOS                                            | 29-Apr-15 |                |          |                        |           |             |             |                |
|                                                | HRS                                            | 0         | 3200 (+30/-30) |          | 3200                   | 3230      | 1100 (+30)  |             |                |
|                                                | AFL                                            | 0         |                |          |                        |           |             |             |                |
| PROC. REF: SMR 05-30-40PROC. REF: SMR 05-30-40 |                                                |           |                |          |                        |           |             |             | PKG:40         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                              | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty       |
|------------------------------------------------|-----------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                   |           |                |          |                        |           |              |             |                |
| 05-30-42                                       | 3200 FH/60 MO MAINTENANCE PACKAGE |           |                |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                               | 14-May-25 | 60 (+1m/-1m)   |          | 14-May-30              | 14-Jun-30 | 1793 d (+31) |             |                |
|                                                | HRS                               | 2086.2    | 3200 (+30/-30) |          | 5286.2                 | 5316.2    | 3186.2 (+30) |             |                |
|                                                | AFL                               | 1243      |                |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-42PROC. REF: SMR 05-30-42 |                                   |           |                |          |                        |           |              |             | PKG:42         |
| 05-30-50                                       | 5600 FH MAINTENANCE PACKAGE       |           |                |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                               | 29-Apr-15 |                |          |                        |           |              |             |                |
|                                                | HRS                               | 0         | 5600 (+30/-30) |          | 5600                   | 5630      | 3500 (+30)   |             |                |
|                                                | AFL                               | 0         |                |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-50PROC. REF: SMR 05-30-50 |                                   |           |                |          |                        |           |              |             | PKG:50         |
| 05-30-60                                       | 6400 FH MAINTENANCE PACKAGE       |           |                |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                               | 29-Apr-15 |                |          |                        |           |              |             |                |
|                                                | HRS                               | 0         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30)   |             |                |
|                                                | AFL                               | 0         |                |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-60PROC. REF: SMR 05-30-60 |                                   |           |                |          |                        |           |              |             | PKG:60         |
| 05-30-80                                       | 12 MO MAINTENANCE PACKAGE         |           |                |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                               | 14-May-25 | 12 (+1m/-1m)   |          | 14-May-26              | 14-Jun-26 | 332 d (+31)  |             |                |
|                                                | HRS                               | 2086.2    |                |          |                        |           |              |             |                |
|                                                | AFL                               | 1243      |                |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-80PROC. REF: SMR 05-30-80 |                                   |           |                |          |                        |           |              |             | PKG:80         |
| 05-30-81                                       | 24 MO MAINTENANCE PACKAGE         |           |                |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                               | 14-May-25 | 24 (+1m/-1m)   |          | 14-May-27              | 14-Jun-27 | 697 d (+31)  |             |                |
|                                                | HRS                               | 2086.2    |                |          |                        |           |              |             |                |
|                                                | AFL                               | 1243      |                |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-81PROC. REF: SMR 05-30-81 |                                   |           |                |          |                        |           |              |             | PKG:81         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                        | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty       |
|------------------------------------------------|---------------------------------------------|-----------|---------------|----------|------------------------|-----------|--------------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                             |           |               |          |                        |           |              |             |                |
| 05-30-82                                       | 36 MO MAINTENANCE PACKAGE                   |           |               |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                                         | 29-Apr-24 | 36 (+1m/-1m)  |          | 29-Apr-27              | 29-May-27 | 682 d (+30)  |             |                |
|                                                | HRS                                         | 1952.5    |               |          |                        |           |              |             |                |
|                                                | AFL                                         | 1160      |               |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-82PROC. REF: SMR 05-30-82 |                                             |           |               |          |                        |           |              |             | PKG:82         |
| 05-30-83                                       | 48 MO MAINTENANCE PACKAGE                   |           |               |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                                         | 24-Apr-23 | 48 (+1m/-1m)  | Adj 5d   | 29-Apr-27              | 29-May-27 | 682 d (+30)  |             |                |
|                                                | HRS                                         | 1825.5    |               |          |                        |           |              |             |                |
|                                                | AFL                                         | 1042      |               |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-83PROC. REF: SMR 05-30-83 |                                             |           |               |          |                        |           |              |             | PKG:83         |
| 05-30-84                                       | 60 MO MAINTENANCE PACKAGE                   |           |               |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                                         | 14-May-25 | 60 (+1m/-1m)  |          | 14-May-30              | 14-Jun-30 | 1793 d (+31) |             |                |
|                                                | HRS                                         | 2086.2    |               |          |                        |           |              |             |                |
|                                                | AFL                                         | 1243      |               |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-84PROC. REF: SMR 05-30-84 |                                             |           |               |          |                        |           |              |             | PKG:84         |
| 05-30-87                                       | 120 MO MAINTENANCE PACKAGE                  |           |               |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                                         | 14-May-25 | 120 (+1m/-1m) |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) |             |                |
|                                                | HRS                                         | 2086.2    |               |          |                        |           |              |             |                |
|                                                | AFL                                         | 1243      |               |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-87PROC. REF: SMR 05-30-87 |                                             |           |               |          |                        |           |              |             | PKG:87         |
| 05-30-90                                       | 120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE |           |               |          |                        |           |              |             | Package ATA:05 |
|                                                | MOS                                         | 14-May-25 | 60 (+1m/-1m)  |          | 14-May-30              | 14-Jun-30 | 1793 d (+31) |             |                |
|                                                | HRS                                         | 2086.2    |               |          |                        |           |              |             |                |
|                                                | AFL                                         | 1243      |               |          |                        |           |              |             |                |
| PROC. REF: SMR 05-30-90PROC. REF: SMR 05-30-90 |                                             |           |               |          |                        |           |              |             | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|-------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-802                             | NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-802                             | NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-803                             | NO. 1 ENGINE - ENGINE OVERTEMPERATURE                 |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-803                             | NO. 2 ENGINE - ENGINE OVERTEMPERATURE                 |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-804                             | NO. 1 ENGINE - ENGINE OVERSPEED                       |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |
| 05-50-00-210-804                             | NO. 2 ENGINE - ENGINE OVERSPEED                       |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                               | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                   | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                   | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                   | Warranty       |
|----------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-805                             | NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD) |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-805                             | NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD) |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-806                             | NO. 1 ENGINE - LIGHTNING STRIKE            |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-806                             | NO. 2 ENGINE - LIGHTNING STRIKE            |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-807                             | NO. 1 ENGINE - DROPPED ENGINE              |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-807                             | NO. 2 ENGINE - DROPPED ENGINE              |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |                               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|---------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                             |           |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-808                             | NO. 1 ENGINE - HEAVY LANDING                |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-808                             | NO. 2 ENGINE - HEAVY LANDING                |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-809                             | NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-809                             | NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-810                             | NO. 1 ENGINE - ENGINE IMMERSION IN WATER    |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |
|                                              |                                             |           |          |          |                        |           |           |             |                |
| 05-50-00-210-810                             | NO. 2 ENGINE - ENGINE IMMERSION IN WATER    |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                     | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                         | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                         | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|---------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-811                             | NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT     |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-811                             | NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT     |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-812                             | NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-812                             | NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-813                             | NO. 1 ENGINE - LOSS OF OIL                                    |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |
| 05-50-00-210-813                             | NO. 2 ENGINE - LOSS OF OIL                                    |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                                       | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                           | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                           | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-815                             | NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS      |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-815                             | NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS      |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-816                             | NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-816                             | NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-817                             | NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE            |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |
| 05-50-00-210-817                             | NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE            |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                            | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                    |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-818                             | NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-818                             | NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-819                             | NO. 1 ENGINE - FUEL FILTER CONTAMINATION   |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-819                             | NO. 2 ENGINE - FUEL FILTER CONTAMINATION   |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-820                             | NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN  |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |
| 05-50-00-210-820                             | NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN  |           |          |          |                        |           |           |             | Service ATA:05 |
|                                              | MOS/MSC                                    | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                        | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                        | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                   | Warranty       |
|----------------------------------------------|------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-821                             | NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 26-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-821                             | NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 27-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-822                             | NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL    |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 26-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-822                             | NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL    |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 27-Nov-14 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-823                             | NO. 1 ENGINE - FUEL CONTAMINATION                    |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 26-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                        |           |           |                               |                |
| 05-50-00-210-823                             | NO. 2 ENGINE - FUEL CONTAMINATION                    |           |          |          |                        |           |           |                               | Service ATA:05 |
|                                              | MOS/MSC                                              | 27-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                  | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                  | 0         |          |          |                        |           |           |                               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                                                                   | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                         | Warranty |
|------------------------------------------------|----------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|-------------------------------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                        |           |               |          |                        |           |           |                                     |          |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |
| 05-50-00-210-824                               | NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE                                          |           |               |          |                        |           |           | Service                             | ATA:05   |
|                                                | MOS/MSC                                                                                | 26-Nov-14 | A/R           |          |                        |           |           | UNSCHEDULED<br>MAINTENANCE<br>CHECK |          |
|                                                | HRS                                                                                    | 0         |               |          |                        |           |           |                                     |          |
|                                                | ENC                                                                                    | 0         |               |          |                        |           |           |                                     |          |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |
| 05-50-00-210-824                               | NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE                                          |           |               |          |                        |           |           | Service                             | ATA:05   |
|                                                | MOS/MSC                                                                                | 27-Nov-14 | A/R           |          |                        |           |           | UNSCHEDULED<br>MAINTENANCE<br>CHECK |          |
|                                                | HRS                                                                                    | 0         |               |          |                        |           |           |                                     |          |
|                                                | ENC                                                                                    | 0         |               |          |                        |           |           |                                     |          |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |
| H140-001 <sup>S</sup>                          | EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE |           |               |          |                        |           |           | Service                             | ATA:05   |
|                                                | MOS                                                                                    | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |                                     |          |
|                                                | HRS                                                                                    | 2086.2    |               |          |                        |           |           |                                     |          |
|                                                | AFL                                                                                    | 1243      |               |          |                        |           |           |                                     |          |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |
| H242-001 <sup>S</sup>                          | INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE |           |               |          |                        |           |           | Service                             | ATA:05   |
|                                                | MOS                                                                                    | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |                                     |          |
|                                                | HRS                                                                                    | 2086.2    |               |          |                        |           |           |                                     |          |
|                                                | AFL                                                                                    | 1243      |               |          |                        |           |           |                                     |          |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |
| H430-001 <sup>S</sup>                          | INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS  |           |               |          |                        |           |           | Service                             | ATA:05   |
|                                                | MOS                                                                                    | 14-May-25 | 60 (+1m/-1m)  |          |                        |           |           |                                     |          |
|                                                | HRS                                                                                    | 2086.2    |               |          |                        |           |           |                                     |          |
|                                                | AFL                                                                                    | 1243      |               |          |                        |           |           |                                     |          |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |                                                                                        |           |               |          |                        |           |           |                                     |          |
|                                                |                                                                                        |           |               |          |                        |           |           |                                     |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                             | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                                                                                                                  |           |              |          |                        |           |           |             |          |
| H700-001 <sup>S</sup>                                                      | EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS |           |              |          |                        |           |           | Service     | ATA:05   |
|                                                                            | MOS                                                                                                              | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                                                                                              | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                              | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                        |           |           |             | PKG:84   |
| H700-002 <sup>S</sup>                                                      | EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS |           |              |          |                        |           |           | Service     | ATA:05   |
|                                                                            | MOS                                                                                                              | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                                                                                              | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                              | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                        |           |           |             | PKG:84   |
| H700-003 <sup>S</sup>                                                      | EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING                                            |           |              |          |                        |           |           | Service     | ATA:05   |
|                                                                            | MOS                                                                                                              | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                                                                                              | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                              | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                        |           |           |             | PKG:84   |
| ATA 21 - AIR CONDITIONING                                                  |                                                                                                                  |           |              |          |                        |           |           |             |          |
| 21-01-01                                                                   | RH INSC ILLUM PANEL                                                                                              |           |              |          |                        |           |           | Component   | ATA:21   |
| PN:441-42629-002                                                           | MOS/MSC                                                                                                          | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:1191                                                                    | HRS                                                                                                              | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                                                                              | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-01-01, AMM 21-01-01PROC. REF: AMM 21-01-01, AMM 21-01-01 |                                                                                                                  |           |              |          |                        |           |           |             |          |
| 21-20-01                                                                   | AVIONICS BLOWER                                                                                                  |           |              |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                                                      | MOS/MSC                                                                                                          | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS                                                                                                              | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                                                                              | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-41-07, AMM 31-41-07PROC. REF: AMM 31-41-07, AMM 31-41-07 |                                                                                                                  |           |              |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 21 - AIR CONDITIONING                                                  |                                                 |           |                |          |                        |           |           |             |          |
| 21-20-02                                                                   | AVIONICS/DISPLAY COOLING FAN                    |           |                |          |                        |           |           | Component   | ATA:21   |
| PN:PN                                                                      | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-61-02, AMM 31-61-02PROC. REF: AMM 31-61-02, AMM 31-61-02 |                                                 |           |                |          |                        |           |           |             |          |
| 21-20-03                                                                   | NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY |           |                |          |                        |           |           | Component   | ATA:21   |
| PN:1300250-9                                                               | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:814                                                                     | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01 |                                                 |           |                |          |                        |           |           |             |          |
| 21-20-03                                                                   | NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY |           |                |          |                        |           |           | Component   | ATA:21   |
| PN:1300250-9                                                               | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:818                                                                     | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01 |                                                 |           |                |          |                        |           |           |             |          |
| 21-20-05                                                                   | GROUND COOLING FAN                              |           |                |          |                        |           |           | Component   | ATA:21   |
| PN:1133660-3                                                               | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:396                                                                     | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 21-23-05, AMM 21-23-05PROC. REF: AMM 21-23-05, AMM 21-23-05 |                                                 |           |                |          |                        |           |           |             |          |
| 21-21-02-001 <sup>S</sup>                                                  | OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE   |           |                |          |                        |           |           | Service     | ATA:21   |
|                                                                            | MOS                                             | 29-Apr-15 |                |          |                        |           |           |             |          |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02                             |                                                 |           |                |          |                        |           |           |             |          |
| 21-21-02-001 <sup>S</sup>                                                  | OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE   |           |                |          |                        |           |           | Service     | ATA:21   |
|                                                                            | MOS                                             | 29-Apr-15 |                |          |                        |           |           |             |          |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL                                             | 0         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02                             |                                                 |           |                |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-01                                                                   | ELECTROMECHANICAL LINEAR ACTUATOR               |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:100000-77                                                               | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:28816                                                                   | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03 |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-03                                                                   | RAM AIR VALVE                                   |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:505-18030-405                                                           | MOS/MSC                                         | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0000834333                                                              | HRS                                             | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03 |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-03-002 <sup>S</sup>                                                  | OPERATIONAL CHECK OF RAM AIR VALVE              |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                             | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03                             |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-03-003 <sup>S</sup>                                                  | OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION    |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                             | 29-Apr-24 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                             | 1952.5    | 800 (+30/-30)  |          |                        |           |           |             |                  |
|                                                                            | AFL                                             | 1160      |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03                             |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-04-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF RAM AIR CHECK VALVES       |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                             | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-23-04PROC. REF: AMM 21-23-04                             |                                                 |           |                |          |                        |           |           |             |                  |
| 21-23-05-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF GROUND COOLING FAN |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                             | 28-Dec-18 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                             | 1178.1    | 1600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                             | 679       |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                                | Interval | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------|--------------------------------------------------------------------|----------|-----------|------------------------|-----------|-----------|-------------|----------|
| ATA 21 - AIR CONDITIONING                      |              |                                                                    |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-23-05PROC. REF: AMM 21-23-05 |              |                                                                    |          |           |                        |           |           |             |          |
| 21-24-01-001                                   | <sup>S</sup> | OPERATIONAL CHECK OF IFE COOLING FAN                               |          |           |                        |           |           | Service     | ATA:21   |
|                                                | MOS          | 29-Apr-15                                                          |          |           |                        |           |           |             |          |
|                                                | HRS          | 0                                                                  | 6400     | (+30/-30) |                        |           |           |             |          |
|                                                | AFL          | 0                                                                  |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-24-01PROC. REF: AMM 21-24-01 |              |                                                                    |          |           |                        |           |           |             | PKG:60   |
| 21-31-00-002                                   | <sup>S</sup> | OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE            |          |           |                        |           |           | Service     | ATA:21   |
|                                                | MOS          | 29-Apr-24                                                          |          |           |                        |           |           |             |          |
|                                                | HRS          | 1952.5                                                             | 800      | (+30/-30) |                        |           |           |             |          |
|                                                | AFL          | 1160                                                               |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00 |              |                                                                    |          |           |                        |           |           |             | PKG:1    |
| 21-31-00-003                                   | <sup>S</sup> | OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)     |          |           |                        |           |           | Service     | ATA:21   |
|                                                | MOS          | 29-Apr-24                                                          |          |           |                        |           |           |             |          |
|                                                | HRS          | 1952.5                                                             | 800      | (+30/-30) |                        |           |           |             |          |
|                                                | AFL          | 1160                                                               |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00 |              |                                                                    |          |           |                        |           |           |             | PKG:1    |
| 21-31-00-004                                   | <sup>S</sup> | OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS |          |           |                        |           |           | Service     | ATA:21   |
|                                                | MOS          | 29-Apr-15                                                          |          |           |                        |           |           |             |          |
|                                                | HRS          | 0                                                                  | 5600     | (+30/-30) |                        |           |           |             |          |
|                                                | AFL          | 0                                                                  |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00 |              |                                                                    |          |           |                        |           |           |             | PKG:50   |
| 21-31-00-005                                   | <sup>S</sup> | OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL                |          |           |                        |           |           | Service     | ATA:21   |
|                                                | MOS          | 29-Apr-15                                                          |          |           |                        |           |           |             |          |
|                                                | HRS          | 0                                                                  | 5600     | (+30/-30) |                        |           |           |             |          |
|                                                | AFL          | 0                                                                  |          |           |                        |           |           |             |          |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00 |              |                                                                    |          |           |                        |           |           |             | PKG:50   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                  | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-01                                                                   | (ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT                       |           |                |          |                        |           |              |             | Component ATA:21 |
| PN:2119286-10                                                              | MOS/MSC                                                               | 05-Sep-24 | O/C            | TSN 1    |                        |           |              |             |                  |
| SN:2119286-01540                                                           | HRS                                                                   | 2037.3    |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                                   | 1207      |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-01, AMM 21-31-01PROC. REF: AMM 21-31-01, AMM 21-31-01 |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-01-001                                                               | RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) |           |                |          |                        |           |              |             | Service ATA:21   |
| PN:2119286-10                                                              | MOS                                                                   | 05-Sep-24 |                |          |                        |           |              |             |                  |
| SN:2119286-01540                                                           | HRS                                                                   | 2037.3    | 5600 (+30/-30) |          | 7637.3                 | 7667.3    | 5537.3 (+30) |             |                  |
|                                                                            | AFL                                                                   | 1207      |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01                             |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-02                                                                   | OUTFLOW VALVE                                                         |           |                |          |                        |           |              |             | Component ATA:21 |
| PN:103922-1                                                                | MOS/MSC                                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:103922-00284                                                            | HRS                                                                   | 0         |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                                   | 0         |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-02, AMM 21-31-02PROC. REF: AMM 21-31-02, AMM 21-31-02 |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-02-001                                                               | RESTORATION (REPAIR) OF OUTFLOW VALVE                                 |           |                |          |                        |           |              |             | Service ATA:21   |
| PN:103922-1                                                                | MOS                                                                   | 29-Apr-15 |                |          |                        |           |              |             |                  |
| SN:103922-00284                                                            | HRS                                                                   | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30)   |             |                  |
|                                                                            | AFL                                                                   | 0         |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02                             |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-03                                                                   | NEGATIVE PRESSURE RELIEF (NPR) VALVE                                  |           |                |          |                        |           |              |             | Component ATA:21 |
| PN:130664-2                                                                | MOS/MSC                                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:34163-0640                                                              | HRS                                                                   | 0         |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                                   | 0         |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-03, AMM 21-31-03PROC. REF: AMM 21-31-03, AMM 21-31-03 |                                                                       |           |                |          |                        |           |              |             |                  |
| 21-31-03-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE                   |           |                |          |                        |           |              |             | Service ATA:21   |
|                                                                            | MOS                                                                   | 29-Apr-15 |                |          |                        |           |              |             |                  |
|                                                                            | HRS                                                                   | 0         | 5600 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL                                                                   | 0         |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03                             |                                                                       |           |                |          |                        |           |              |             |                  |

PKG:50

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit    | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------------|----------|------------------------|--------------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                                         |           |                |          |                        |              |           |             |                  |
| 21-31-04                                                                   | PRESSURE RELIEF (PRV) VALVE                             |           |                |          |                        |              |           |             | Component ATA:21 |
| PN:103918-2                                                                | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |              |           |             |                  |
| SN:103918-00368                                                            | HRS                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
| PROC. REF: AMM 21-31-04, AMM 21-31-04PROC. REF: AMM 21-31-04, AMM 21-31-04 |                                                         |           |                |          |                        |              |           |             |                  |
| 21-31-04-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE               |           |                |          |                        |              |           |             | Service ATA:21   |
|                                                                            | MOS                                                     | 29-Apr-15 |                |          |                        |              |           |             |                  |
|                                                                            | HRS                                                     | 0         | 5600 (+30/-30) |          |                        |              |           |             |                  |
|                                                                            | AFL                                                     | 0         |                |          |                        |              |           |             |                  |
| PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04                             |                                                         |           |                |          |                        |              |           |             |                  |
| 21-41-01                                                                   | BHS SHUT-OFF VALVE                                      |           |                |          |                        |              |           |             | Component ATA:21 |
| PN:PN                                                                      | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |              |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
| PROC. REF: AMM 21-41-01, AMM 21-41-01PROC. REF: AMM 21-41-01, AMM 21-41-01 |                                                         |           |                |          |                        |              |           |             |                  |
| 21-41-04                                                                   | RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS |           |                |          |                        |              |           |             | Component ATA:21 |
| PN:PN                                                                      | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |              |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |              |           |             |                  |
| PROC. REF: AMM 21-41-04, AMM 21-41-04PROC. REF: AMM 21-41-04, AMM 21-41-04 |                                                         |           |                |          |                        |              |           |             |                  |
| 21-52-01                                                                   | VCS COMPRESSOR DRIVE MODULE                             |           |                |          |                        |              |           |             | Component ATA:21 |
| PN:1133640-10                                                              | MOS/MSC                                                 | 20-Oct-24 | O/C            |          |                        |              |           |             |                  |
| SN:1178                                                                    | HRS                                                     | 2045      |                |          |                        |              |           |             |                  |
|                                                                            | AFL                                                     | 1212      |                |          |                        |              |           |             |                  |
| PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01 |                                                         |           |                |          |                        |              |           |             |                  |
| 21-52-01-002                                                               | DISCARD OF COMPRESSOR DRIVE MODULE BELT                 |           |                |          |                        |              |           |             | Service ATA:21   |
|                                                                            | MOS                                                     | 28-Dec-18 |                |          |                        |              |           |             |                  |
|                                                                            | HRS                                                     | 1178.1    | 2000 (+30/-30) | 3178.1   | 3208.1                 | 1078.1 (+30) |           |             |                  |
|                                                                            | AFL                                                     | 679       |                |          |                        |              |           |             |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                             |                                                         |           |                |          |                        |              |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit         | C/W                                                | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|--------------|----------------------------------------------------|----------------|----------|------------------------|-----------|------------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                                                                          |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-01-003                                                                                                                       | <sup>S</sup> | FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION        |                |          |                        |           |            |             | Service ATA:21   |
|                                                                                                                                    | MOS          | 29-Apr-24                                          |                |          |                        |           |            |             |                  |
|                                                                                                                                    | HRS          | 1952.5                                             | 800 (+30/-30)  |          |                        |           |            |             |                  |
|                                                                                                                                    | AFL          | 1160                                               |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                                                                                     |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-01-004                                                                                                                       |              | RESTORATION (OVERHAUL) COMPRESSOR                  |                |          |                        |           |            |             | Service ATA:21   |
| PN:1133640-10                                                                                                                      | MOS          | 20-Oct-24                                          |                |          |                        |           |            |             |                  |
| SN:1178                                                                                                                            | HRS          | 2045                                               | 2000 (+30/-30) |          | 4045                   | 4075      | 1945 (+30) |             |                  |
|                                                                                                                                    | AFL          | 1212                                               |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                                                                                     |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-02                                                                                                                           |              | CDM COMPRESSOR MODULE                              |                |          |                        |           |            |             | Component ATA:21 |
| PN:PN                                                                                                                              | MOS/MSC      | 29-Apr-15                                          | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01                                                         |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-03                                                                                                                           |              | SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE       |                |          |                        |           |            |             | Component ATA:21 |
| PN:1133860-4                                                                                                                       | MOS/MSC      | 29-Apr-15                                          | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:439                                                                                                                             | HRS          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-03, AMM 21-52-03PROC. REF: AMM 21-52-03, AMM 21-52-03                                                         |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-03-001                                                                                                                       | <sup>S</sup> | GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES    |                |          |                        |           |            |             | Service ATA:21   |
|                                                                                                                                    | MOS          | 29-Apr-24                                          |                |          |                        |           |            |             |                  |
|                                                                                                                                    | HRS          | 1952.5                                             | 800 (+30/-30)  |          |                        |           |            |             |                  |
|                                                                                                                                    | AFL          | 1160                                               |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-03PROC. REF: AMM 21-52-03                                                                                     |              |                                                    |                |          |                        |           |            |             |                  |
| 21-52-04                                                                                                                           |              | FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER |                |          |                        |           |            |             | Component ATA:21 |
| PN:1133850-104                                                                                                                     | MOS/MSC      | 29-Apr-15                                          | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:121                                                                                                                             | HRS          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL          | 0                                                  |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04 |              |                                                    |                |          |                        |           |            |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-05                                                                   | COMPRESSOR DRIVE MODULE BELT               |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:PN                                                                      | MOS/MSC                                    | 29-Apr-15 | H/T            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-06-001 <sup>S</sup>                                                  | SERVICING OF VCS REFRIGERANT FLUID         |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                        | 14-May-25 | 12 (+1m/-1m)   |          |                        |           |           |             |                  |
|                                                                            | HRS                                        | 2086.2    |                |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 1243      |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 12-17-00PROC. REF: AMM 12-17-00                             |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-08                                                                   | AIR CONDITION CONDENSER ASSEMBLY           |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:1133760-2                                                               | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:379                                                                     | HRS                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-52-08, AMM 21-52-08PROC. REF: AMM 21-52-08, AMM 21-52-08 |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-08-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF VCS CONDENSER |           |                |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS                                        | 28-Dec-18 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                        | 1178.1    | 1600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 679       |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-52-08PROC. REF: AMM 21-52-08                             |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-09                                                                   | AIR CONDITION MIX FLOW CONDENSER FAN       |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:1133720-4                                                               | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:404                                                                     | HRS                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-52-09, AMM 21-52-09PROC. REF: AMM 21-52-09, AMM 21-52-09 |                                            |           |                |          |                        |           |           |             |                  |
| 21-52-10                                                                   | AIR CONDITION BLEED AIR HEAT EXCHANGER     |           |                |          |                        |           |           |             | Component ATA:21 |
| PN:1320260-2                                                               | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:376                                                                     | HRS                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-52-10, AMM 21-52-10PROC. REF: AMM 21-52-10, AMM 21-52-10 |                                            |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                    | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|--------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM |               |          |                        |           |           |             | Service ATA:21   |
|                                                                            | MOS          | 29-Apr-24                                              |               |          |                        |           |           |             |                  |
|                                                                            | HRS          | 1952.5                                                 | 800 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1160                                                   |               |          |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-00PROC. REF: AMM 21-61-00                             |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-01                                                                   |              | ECS TEMPERATURE CONTROLLER                             |               |          |                        |           |           |             | Component ATA:21 |
| PN:1300670-8                                                               | MOS/MSC      | 20-Oct-24                                              | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:01110                                                                   | HRS          | 2045                                                   |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 1212                                                   |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-01, AMM 21-61-01PROC. REF: AMM 21-61-01, AMM 21-61-01 |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-03                                                                   |              | LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH               |               |          |                        |           |           |             | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC      | 29-Apr-15                                              | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:2800                                                                    | HRS          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03 |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-03                                                                   |              | RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH              |               |          |                        |           |           |             | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC      | 29-Apr-15                                              | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:2807                                                                    | HRS          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03 |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-04                                                                   |              | COCKPIT DUCT TEMPERATURE SENSOR/SWITCH                 |               |          |                        |           |           |             | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC      | 29-Apr-15                                              | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:2885                                                                    | HRS          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                      |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-04, AMM 21-61-04PROC. REF: AMM 21-61-04, AMM 21-61-04 |              |                                                        |               |          |                        |           |           |             |                  |
| 21-61-05                                                                   |              | CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH         |               |          |                        |           |           |             | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC      | 29-Apr-24                                              | O/C           | TSN 20   |                        |           |           |             |                  |
| SN:5392                                                                    | HRS          | 1952.5                                                 |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 1160                                                   |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 21-61-05, AMM 21-61-05PROC. REF: AMM 21-61-05, AMM 21-61-05 |              |                                                        |               |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                                                       | Interval       | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit   | Remaining     | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------|----------------|-----------|------------------------|-------------|---------------|-------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 21-61-06-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR                                                         |                |           |                        |             |               |             | Service ATA:21   |
|                                                                            | MOS          | 29-Apr-15                                                                                                 |                |           |                        |             |               |             |                  |
|                                                                            | HRS          | 0                                                                                                         | 6400 (+30/-30) |           |                        |             |               |             |                  |
|                                                                            | AFL          | 0                                                                                                         |                |           |                        |             |               |             |                  |
| PROC. REF: AMM 21-61-06PROC. REF: AMM 21-61-06                             |              |                                                                                                           |                |           |                        |             |               |             |                  |
| ATA 22 - AUTO FLIGHT                                                       |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 22-11-00                                                                   |              | GMC 715 GUIDANCE PANEL                                                                                    |                |           |                        |             |               |             | Component ATA:22 |
| PN:011-01430-00                                                            | MOS/MSC      | 30-Apr-22                                                                                                 | O/C            | TSR 0     |                        |             |               |             |                  |
| SN:15900714                                                                | HRS          | 1728.6                                                                                                    |                | TSR 0     |                        |             |               |             |                  |
|                                                                            | AFL          | 989                                                                                                       |                | TSR 0     |                        |             |               |             |                  |
| PROC. REF: AMM 22-11-01, AMM 22-11-01PROC. REF: AMM 22-11-01, AMM 22-11-01 |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 22-11-00-001                                                               |              | FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                   |                |           |                        |             |               |             | Service ATA:22   |
| PN:011-01904-00                                                            | MOS          | 14-May-25                                                                                                 | 12 (+30d/-30d) | 14-May-26 | 13-Jun-26              | 332 d (+30) | AIRWORTHINESS |             |                  |
| SN:1GK012553                                                               | HRS          | 2086.2                                                                                                    |                |           |                        |             |               |             |                  |
|                                                                            | AFL          | 1243                                                                                                      |                |           |                        |             |               |             |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 22-11-00-001                                                               |              | FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                  |                |           |                        |             |               |             | Service ATA:22   |
| PN:011-01904-00                                                            | MOS          | 14-May-25                                                                                                 | 12 (+30d/-30d) | 14-May-26 | 13-Jun-26              | 332 d (+30) | AIRWORTHINESS |             |                  |
| SN:1GK012390                                                               | HRS          | 2086.2                                                                                                    |                |           |                        |             |               |             |                  |
|                                                                            | AFL          | 1243                                                                                                      |                |           |                        |             |               |             |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 22-11-00-001                                                               |              | FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                    |                |           |                        |             |               |             | Service ATA:22   |
| PN:011-01904-00                                                            | MOS          | 14-May-25                                                                                                 | 12 (+30d/-30d) | 14-May-26 | 13-Jun-26              | 332 d (+30) | AIRWORTHINESS |             |                  |
| SN:1GK012513                                                               | HRS          | 2086.2                                                                                                    |                |           |                        |             |               |             |                  |
|                                                                            | AFL          | 1243                                                                                                      |                |           |                        |             |               |             |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |              |                                                                                                           |                |           |                        |             |               |             |                  |
| 22-11-00-001                                                               |              | FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO |                |           |                        |             |               |             | Service ATA:22   |
| PN:011-01904-00                                                            | MOS          | 14-May-25                                                                                                 | 12 (+30d/-30d) | 14-May-26 | 13-Jun-26              | 332 d (+30) | AIRWORTHINESS |             |                  |
| SN:1GK012534                                                               | HRS          | 2086.2                                                                                                    |                |           |                        |             |               |             |                  |
|                                                                            | AFL          | 1243                                                                                                      |                |           |                        |             |               |             |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |              |                                                                                                           |                |           |                        |             |               |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                          | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|----------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 22 - AUTO FLIGHT                                                       |         |                                              |                |          |                        |           |           |             |          |
| 22-11-00-002 <sup>S</sup>                                                  |         | LUBRICATION OF SERVO ACTUATORS               |                |          |                        |           |           | Service     | ATA:22   |
|                                                                            | MOS     | 14-May-25                                    | 12 (+1m/-1m)   |          |                        |           |           |             |          |
|                                                                            | HRS     | 2086.2                                       |                |          |                        |           |           |             |          |
|                                                                            | AFL     | 1243                                         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |         |                                              |                |          |                        |           |           |             |          |
| 22-11-00-003 <sup>S</sup>                                                  |         | DETAILED INSPECTION OF AUTOPILOT SERVO CABLE |                |          |                        |           |           | Service     | ATA:22   |
|                                                                            | MOS     | 14-May-25                                    | 60 (+1m/-1m)   |          |                        |           |           |             |          |
|                                                                            | HRS     | 2086.2                                       | 3200 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL     | 1243                                         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |         |                                              |                |          |                        |           |           |             |          |
| 22-11-01                                                                   |         | TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO  |                |          |                        |           |           | Component   | ATA:22   |
| PN:011-00877-21                                                            | MOS/MSC | 29-Apr-15                                    | O/C            | TSN 0    |                        |           |           |             |          |
| SN:1A0006378                                                               | HRS     | 0                                            |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                            |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |          |                        |           |           |             |          |
| 22-11-02                                                                   |         | AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO    |                |          |                        |           |           | Component   | ATA:22   |
| PN:011-00878-20                                                            | MOS/MSC | 29-Apr-15                                    | O/C            | TSN 0    |                        |           |           |             |          |
| SN:1A1011984                                                               | HRS     | 0                                            |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                            |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |          |                        |           |           |             |          |
| 22-11-02                                                                   |         | ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO   |                |          |                        |           |           | Component   | ATA:22   |
| PN:011-00878-20                                                            | MOS/MSC | 29-Apr-15                                    | O/C            | TSN 0    |                        |           |           |             |          |
| SN:1A1011933                                                               | HRS     | 0                                            |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                            |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |          |                        |           |           |             |          |
| 22-11-02                                                                   |         | RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO     |                |          |                        |           |           | Component   | ATA:22   |
| PN:011-00878-20                                                            | MOS/MSC | 29-Apr-15                                    | O/C            | TSN 0    |                        |           |           |             |          |
| SN:1A1011926                                                               | HRS     | 0                                            |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                            |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                   | C/W       | Interval     | TSX/Adj.      | Next Due (ENG/APU) A/C | Max Limit   | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------------|-----------|--------------|---------------|------------------------|-------------|-----------|-------------|------------------|
| ATA 22 - AUTO FLIGHT                                                       |                                                        |           |              |               |                        |             |           |             |                  |
| 22-11-03                                                                   | AILERON GSM 86 AUTOPILOT SERVO MOUNT                   |           |              |               |                        |             |           |             | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 29-Apr-15 | O/C          | TSN 0         |                        |             |           |             |                  |
| SN:1GK012553                                                               | HRS                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
| PROC. REF: AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03 |                                                        |           |              |               |                        |             |           |             |                  |
| 22-11-03-001 <sup>S</sup>                                                  | DISCARD OF AILERON CLUTCH RETAINING BOLT AND WASHER    |           |              |               |                        |             |           |             | Service ATA:22   |
|                                                                            | MOS                                                    | 29-Apr-15 | 36 (+1m/-1m) | 29-Apr-27 (M) | 29-May-27              | 682 d (+30) |           |             |                  |
|                                                                            | HRS                                                    | 0         |              |               |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              |               |                        |             |           |             |                  |
| PROC. REF: AMM 22-11-03PROC. REF: AMM 22-11-03                             |                                                        |           |              |               |                        |             |           |             |                  |
| 22-11-06                                                                   | ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT                  |           |              |               |                        |             |           |             | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 29-Apr-15 | O/C          | TSN 0         |                        |             |           |             |                  |
| SN:1GK012390                                                               | HRS                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
| PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06 |                                                        |           |              |               |                        |             |           |             |                  |
| 22-11-09                                                                   | RUDDER GSM 86 AUTOPILOT SERVO MOUNT                    |           |              |               |                        |             |           |             | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 29-Apr-15 | O/C          | TSN 0         |                        |             |           |             |                  |
| SN:1GK012513                                                               | HRS                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
| PROC. REF: AMM 22-11-09, AMM 22-11-09PROC. REF: AMM 22-11-09, AMM 22-11-09 |                                                        |           |              |               |                        |             |           |             |                  |
| 22-11-12                                                                   | TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT |           |              |               |                        |             |           |             | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 29-Apr-15 | O/C          | TSN 0         |                        |             |           |             |                  |
| SN:1GK012534                                                               | HRS                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
| PROC. REF: AMM 22-11-12, AMM 22-11-12PROC. REF: AMM 22-11-12, AMM 22-11-12 |                                                        |           |              |               |                        |             |           |             |                  |
| ATA 23 - COMMUNICATIONS                                                    |                                                        |           |              |               |                        |             |           |             |                  |
| 23-11-01                                                                   | PS440 HF CONTROL DISPLAY UNIT                          |           |              |               |                        |             |           |             | Component ATA:23 |
| PN:PN                                                                      | MOS/MSC                                                | 29-Apr-15 | O/C          | TSN 0         |                        |             |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
|                                                                            | AFL                                                    | 0         |              | TSN 0         |                        |             |           |             |                  |
| PROC. REF: AMM 23-11-01, AMM 23-11-01PROC. REF: AMM 23-11-01, AMM 23-11-01 |                                                        |           |              |               |                        |             |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                   | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 23 - COMMUNICATIONS                                                    |         |                                                       |          |          |                        |           |           |             |          |
| 23-11-02                                                                   |         | REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-11-02, AMM 23-11-02PROC. REF: AMM 23-11-02, AMM 23-11-02 |         |                                                       |          |          |                        |           |           |             |          |
| 23-11-03                                                                   |         | KPA 1052 POWER AMPLIFIER                              |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-11-03, AMM 23-11-03PROC. REF: AMM 23-11-03, AMM 23-11-03 |         |                                                       |          |          |                        |           |           |             |          |
| 23-11-04                                                                   |         | HF ANTENNA COUPLER                                    |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-11-04, AMM 23-11-04PROC. REF: AMM 23-11-04, AMM 23-11-04 |         |                                                       |          |          |                        |           |           |             |          |
| 23-12-01                                                                   |         | VHF 1 (UPPER FUSELAGE) ANTENNA                        |          |          |                        |           |           | Component   | ATA:23   |
| PN:S65-8280-41                                                             | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:322-4047                                                                | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02 |         |                                                       |          |          |                        |           |           |             |          |
| 23-12-02                                                                   |         | VHF 2 (LOWER FORWARD FUSELAGE) ANTENNA                |          |          |                        |           |           | Component   | ATA:23   |
| PN:S65-8280-41                                                             | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:322-4055                                                                | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02 |         |                                                       |          |          |                        |           |           |             |          |
| 23-21-01                                                                   |         | SELCAL CSD DECODER                                    |          |          |                        |           |           | Component   | ATA:23   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                             | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                     |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-21-01, AMM 23-21-01PROC. REF: AMM 23-21-01, AMM 23-21-01 |         |                                                       |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                                                    |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-01                                                                   | LEFT GMA 1347D AUDIO PANEL         |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:011-01257-20                                                            | MOS/MSC                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:17108020                                                                | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-01, AMM 23-51-01PROC. REF: AMM 23-51-01, AMM 23-51-01 |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-02                                                                   | COPILOT HEADSET                    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:026-55-999-0131                                                         | MOS/MSC                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00202911                                                                | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-13-07, AMM 44-13-07PROC. REF: AMM 44-13-07, AMM 44-13-07 |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-02                                                                   | PILOT HEADSET                      |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:026-55-999-0131                                                         | MOS/MSC                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00202914                                                                | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-13-07, AMM 44-13-07PROC. REF: AMM 44-13-07, AMM 44-13-07 |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-03                                                                   | LH CONSOLE COCKPIT HAND MICROPHONE |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:85-03-12369-04                                                          | MOS/MSC                            | 28-Mar-19 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:524881                                                                  | HRS                                | 1216.8    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 700       |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-04                                                                   | COCKPIT SPEAKER                    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                                                      | MOS/MSC                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-02, AMM 23-51-02PROC. REF: AMM 23-51-02, AMM 23-51-02 |                                    |           |          |          |                        |           |           |             |                  |
| 23-50-05                                                                   | CDVR MICROPHONE                    |           |          |          |                        |           |           |             | Component ATA:23 |
| PN:PN                                                                      | MOS/MSC                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-31-07, AMM 31-31-07PROC. REF: AMM 31-31-07, AMM 31-31-07 |                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 23 - COMMUNICATIONS                                                    |              |                                                           |                |          |                        |           |           |             |                  |
| 23-51-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE |                |          |                        |           |           |             | Service ATA:23   |
|                                                                            | MOS          | 29-Apr-15                                                 |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                         | 3200 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-00PROC. REF: AMM 23-51-00                             |              |                                                           |                |          |                        |           |           |             |                  |
| 23-51-01                                                                   |              | RIGHT GMA 1347D AUDIO PANEL                               |                |          |                        |           |           |             | Component ATA:23 |
| PN:011-01257-20                                                            | MOS/MSC      | 29-Apr-15                                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:17105022                                                                | HRS          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-01, AMM 23-51-01PROC. REF: AMM 23-51-01, AMM 23-51-01 |              |                                                           |                |          |                        |           |           |             |                  |
| 23-51-05                                                                   |              | LEFT CONTROL PANEL                                        |                |          |                        |           |           |             | Component ATA:23 |
| PN:441-40943-002                                                           | MOS/MSC      | 29-Apr-15                                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0507                                                                    | HRS          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05 |              |                                                           |                |          |                        |           |           |             |                  |
| 23-51-05                                                                   |              | RIGHT CONTROL PANEL                                       |                |          |                        |           |           |             | Component ATA:23 |
| PN:441-40943-002                                                           | MOS/MSC      | 29-Apr-15                                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0508                                                                    | HRS          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05 |              |                                                           |                |          |                        |           |           |             |                  |
| 23-61-00-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF STATIC DISCHARGERS                    |                |          |                        |           |           |             | Service ATA:23   |
|                                                                            | MOS          | 24-Apr-23                                                 | 48 (+1m/-1m)   |          |                        |           |           |             |                  |
|                                                                            | HRS          | 1825.5                                                    |                |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1042                                                      |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 23-61-00PROC. REF: AMM 23-61-00                             |              |                                                           |                |          |                        |           |           |             |                  |
| ATA 24 - ELECTRICAL POWER                                                  |              |                                                           |                |          |                        |           |           |             |                  |
| 24-01-01                                                                   |              | LEFT CONSOLE CONTROL PANEL                                |                |          |                        |           |           |             | Component ATA:24 |
| PN:441-40929-002                                                           | MOS/MSC      | 29-Apr-15                                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0635                                                                    | HRS          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                         |                | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                                                                                                  | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 24 - ELECTRICAL POWER                                                  |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-01-01, AMM 24-01-01PROC. REF: AMM 24-01-01, AMM 24-01-01 |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| 24-31-01                                                                   | NO. 1 ENGINE STARTER/GENERATOR                                                                                                                                                        |           |               |          |                        |           |             |             | Component ATA:24 |
| PN:400SG180Q                                                               | MOS/MSC                                                                                                                                                                               | 21-Nov-19 | O/C           | TSO 0    |                        |           |             |             |                  |
| SN:S00662XL                                                                | HRS                                                                                                                                                                                   | 1463.8    |               | TSO 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                                                                                                                   | 842       |               | TSO 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01 |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| 24-31-01                                                                   | NO. 2 ENGINE STARTER/GENERATOR                                                                                                                                                        |           |               |          |                        |           |             |             | Component ATA:24 |
| PN:400SG180Q                                                               | MOS/MSC                                                                                                                                                                               | 21-Nov-19 | O/C           | TSO 0    |                        |           |             |             |                  |
| SN:S01027XL                                                                | HRS                                                                                                                                                                                   | 1463.8    |               | TSO 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                                                                                                                   | 842       |               | TSO 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01 |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| 24-31-01-001                                                               | NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 |           |               |          |                        |           |             |             | Service ATA:24   |
| PN:400SG180Q                                                               | MOS                                                                                                                                                                                   | 21-Nov-19 |               |          |                        |           |             |             |                  |
| SN:S00662XL                                                                | HRS                                                                                                                                                                                   | 1463.8    | 800 (+30/-30) |          | 2663.8 (M)             | 2693.8    | 563.8 (+30) |             |                  |
|                                                                            | AFL                                                                                                                                                                                   | 842       |               |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| 24-31-01-001                                                               | NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 |           |               |          |                        |           |             |             | Service ATA:24   |
| PN:400SG180Q                                                               | MOS                                                                                                                                                                                   | 21-Nov-19 |               |          |                        |           |             |             |                  |
| SN:S01027XL                                                                | HRS                                                                                                                                                                                   | 1463.8    | 800 (+30/-30) |          | 2663.8 (M)             | 2693.8    | 563.8 (+30) |             |                  |
|                                                                            | AFL                                                                                                                                                                                   | 842       |               |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |
| 24-31-01-003                                                               | RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)                                                                           |           |               |          |                        |           |             |             | Service ATA:24   |
| PN:400SG180Q                                                               | MOS/MSC                                                                                                                                                                               |           | N/A           |          |                        |           |             |             |                  |
| SN:S00662XL                                                                | HRS                                                                                                                                                                                   |           |               |          |                        |           |             |             |                  |
|                                                                            | AFL                                                                                                                                                                                   |           |               |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                        | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                                                  |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-31-01-003                                                               | RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) |           |              |          |                        |           |           | Service     | ATA:24   |
| PN:400SG180Q                                                               | MOS/MSC                                                                                                     |           | N/A          |          |                        |           |           |             |          |
| SN:S01027XL                                                                | HRS                                                                                                         |           |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         |           |              |          |                        |           |           |             |          |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-31-02                                                                   | LEFT 28V DC GENERATOR CONTROL UNIT                                                                          |           |              |          |                        |           |           | Component   | ATA:24   |
| PN:GCSG550-12A                                                             | MOS/MSC                                                                                                     | 04-Feb-16 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:55031                                                                   | HRS                                                                                                         | 268.5     |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         | 158       |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02 |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-31-02                                                                   | RIGHT 28V DC GENERATOR CONTROL UNIT                                                                         |           |              |          |                        |           |           | Component   | ATA:24   |
| PN:GCSG550-12A                                                             | MOS/MSC                                                                                                     | 04-Feb-16 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:55030                                                                   | HRS                                                                                                         | 268.5     |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         | 158       |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02 |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-31-07-001 <sup>S</sup>                                                  | RESTORATION (CLEANING) OF LH SHUNT GENERATOR                                                                |           |              |          |                        |           |           | Service     | ATA:24   |
|                                                                            | MOS                                                                                                         | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                                                                                         | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07                             |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-31-07-001 <sup>S</sup>                                                  | RESTORATION (CLEANING) OF RH SHUNT GENERATOR                                                                |           |              |          |                        |           |           | Service     | ATA:24   |
|                                                                            | MOS                                                                                                         | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                                                                                         | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07                             |                                                                                                             |           |              |          |                        |           |           |             |          |
| 24-36-01                                                                   | AFT MAIN BATTERY                                                                                            |           |              |          |                        |           |           | Component   | ATA:24   |
| PN:7638-48P                                                                | MOS/MSC                                                                                                     | 14-May-25 | H/T          | TSN 0    |                        |           |           |             |          |
| SN:G03303437                                                               | HRS                                                                                                         | 2086.2    |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                                                                         | 1243      |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01 |                                                                                                             |           |              |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                              | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|------------------------------------------------------------------|----------------|----------|------------------------|-----------|-------------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                                                  |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01                                                                   |         | FORWARD MAIN BATTERY                                             |                |          |                        |           |             | Component   | ATA:24   |
| PN:7639-34                                                                 | MOS/MSC | 14-May-25                                                        | H/T            | TSN 0    |                        |           |             |             |          |
| SN:G03253554                                                               | HRS     | 2086.2                                                           |                | TSN 0    |                        |           |             |             |          |
|                                                                            | AFL     | 1243                                                             |                | TSN 0    |                        |           |             |             |          |
| PROC. REF: AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01 |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01-003                                                               |         | DISCARD AFT MAIN BATTERY                                         |                |          |                        |           |             | Service     | ATA:24   |
| PN:7638-48P                                                                | MOS     | 14-May-25                                                        | 24 (+1m/-1m)   |          | 14-May-27              | 14-Jun-27 | 697 d (+31) | LIFE LIMIT  |          |
| SN:G03303437                                                               | HRS     | 2086.2                                                           |                |          |                        |           |             |             |          |
|                                                                            | AFL     | 1243                                                             | 600 (+30/-30)  |          | 1843                   | 1873      | 591 (+30)   |             |          |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01-003                                                               |         | DISCARD FORWARD MAIN BATTERY                                     |                |          |                        |           |             | Service     | ATA:24   |
| PN:7639-34                                                                 | MOS     | 14-May-25                                                        | 24 (+1m/-1m)   |          | 14-May-27              | 14-Jun-27 | 697 d (+31) | LIFE LIMIT  |          |
| SN:G03253554                                                               | HRS     | 2086.2                                                           |                |          |                        |           |             |             |          |
|                                                                            | AFL     | 1243                                                             | 600 (+30/-30)  |          | 1843                   | 1873      | 591 (+30)   |             |          |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01-004                                                               |         | FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015)     |                |          |                        |           |             | Service     | ATA:24   |
| PN:7638-48P                                                                | MOS/MSC |                                                                  | N/A            |          |                        |           |             |             |          |
| SN:G03303437                                                               | HRS     |                                                                  |                |          |                        |           |             |             |          |
|                                                                            | AFL     |                                                                  |                |          |                        |           |             |             |          |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01-004                                                               |         | FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) |                |          |                        |           |             | Service     | ATA:24   |
| PN:7639-34                                                                 | MOS/MSC |                                                                  | N/A            |          |                        |           |             |             |          |
| SN:G03253554                                                               | HRS     |                                                                  |                |          |                        |           |             |             |          |
|                                                                            | AFL     |                                                                  |                |          |                        |           |             |             |          |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |         |                                                                  |                |          |                        |           |             |             |          |
| 24-36-01-005                                                               |         | FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)    |                |          |                        |           |             | Service     | ATA:24   |
| PN:7638-48P                                                                | MOS     | 14-May-25                                                        | T:12 (+1m/-1m) |          | 14-May-26              | 14-Jun-26 | 332 d (+31) |             |          |
| SN:G03303437                                                               | HRS     | 2086.2                                                           |                |          |                        |           |             |             |          |
|                                                                            | AFL     | 1243                                                             |                |          |                        |           |             |             |          |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |         |                                                                  |                |          |                        |           |             |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                         | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 24 - ELECTRICAL POWER                                                  |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-36-01-005                                                               | FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)                            |           |                |          |                        |           |             |             | Service ATA:24   |
| PN:7639-34                                                                 | MOS                                                                                          | 14-May-25 | T:12 (+1m/-1m) |          | 14-May-26              | 14-Jun-26 | 332 d (+31) |             |                  |
| SN:G03253554                                                               | HRS                                                                                          | 2086.2    |                |          |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 1243      |                |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-36-02-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)                                            |           |                |          |                        |           |             |             | Service ATA:24   |
|                                                                            | MOS                                                                                          | 29-Apr-15 |                |          |                        |           |             |             |                  |
|                                                                            | HRS                                                                                          | 0         | 6400 (+30/-30) |          |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 0         |                |          |                        |           |             |             |                  |
| PROC. REF: AMM 24-36-02PROC. REF: AMM 24-36-02                             |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-54-05                                                                   | 28 VDC / 115 VAC STATIC INVERTER                                                             |           |                |          |                        |           |             |             | Component ATA:24 |
| PN:AS-24-0026-001                                                          | MOS/MSC                                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |             |                  |
| SN:0678                                                                    | HRS                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-54-05, AMM 24-54-05PROC. REF: AMM 24-54-05, AMM 24-54-05 |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-65-00                                                                   | W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE |           |                |          |                        |           |             |             | Component ATA:24 |
| PN:PN                                                                      | MOS/MSC                                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-65-02, AMM 24-65-02PROC. REF: AMM 24-65-02, AMM 24-65-02 |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-65-01                                                                   | LEFT POWER DISTRIBUTION BOX                                                                  |           |                |          |                        |           |             |             | Component ATA:24 |
| PN: SX7EG20-3                                                              | MOS/MSC                                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |             |                  |
| SN:0327                                                                    | HRS                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-65-01, AMM 24-65-01PROC. REF: AMM 24-65-01, AMM 24-65-01 |                                                                                              |           |                |          |                        |           |             |             |                  |
| 24-65-02                                                                   | RIGHT POWER DISTRIBUTION BOX                                                                 |           |                |          |                        |           |             |             | Component ATA:24 |
| PN: SX7EG21-3                                                              | MOS/MSC                                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |             |                  |
| SN:0328                                                                    | HRS                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                          | 0         |                | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 24-65-02, AMM 24-65-02PROC. REF: AMM 24-65-02, AMM 24-65-02 |                                                                                              |           |                |          |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                             | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|----------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 24 - ELECTRICAL POWER                                                  |                                  |           |                |          |                        |           |           |             |          |
| 24-65-04                                                                   | NOSE POWER DISTRIBUTION BOX      |           |                |          |                        |           |           | Component   | ATA:24   |
| PN: SX7EG22-3                                                              | MOS/MSC                          | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN: 0314                                                                   | HRS                              | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                              | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 24-65-04, AMM 24-65-04PROC. REF: AMM 24-65-04, AMM 24-65-04 |                                  |           |                |          |                        |           |           |             |          |
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                  |           |                |          |                        |           |           |             |          |
| 25-11-01                                                                   | COPILOT SEAT                     |           |                |          |                        |           |           | Component   | ATA:25   |
| PN: 1419-04HE                                                              | MOS/MSC                          | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN: 763-1419                                                               | HRS                              | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                              | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01 |                                  |           |                |          |                        |           |           |             |          |
| 25-11-01                                                                   | PILOT SEAT                       |           |                |          |                        |           |           | Component   | ATA:25   |
| PN: 1419-03HE                                                              | MOS/MSC                          | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN: 762-1419                                                               | HRS                              | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                              | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01 |                                  |           |                |          |                        |           |           |             |          |
| 25-11-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION COPILOT SEAT |           |                |          |                        |           |           | Service     | ATA:25   |
|                                                                            | MOS                              | 29-Apr-15 |                |          |                        |           |           |             |          |
|                                                                            | HRS                              | 0         | 2400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL                              | 0         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |                                  |           |                |          |                        |           |           |             |          |
| 25-11-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION PILOT SEAT   |           |                |          |                        |           |           | Service     | ATA:25   |
|                                                                            | MOS                              | 29-Apr-15 |                |          |                        |           |           |             |          |
|                                                                            | HRS                              | 0         | 2400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL                              | 0         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |                                  |           |                |          |                        |           |           |             |          |

PKG:20

PKG:20

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |              |                                           |                |          |                        |           |           |             |                  |
| 25-11-01-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF COCKPIT SEAT BELTS |                |          |                        |           |           |             | Service ATA:25   |
|                                                                            | MOS          | 29-Apr-15                                 |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                         | 2400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |              |                                           |                |          |                        |           |           |             |                  |
| 25-21-01                                                                   |              | PAX 1 - RH AFT FACE SEAT                  |                |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                           |                |          |                        |           |           |             |                  |
| 25-21-01                                                                   |              | PAX 2 - LH AFT FACE SEAT                  |                |          |                        |           |           |             | Component ATA:25 |
| PN:403174-25CDDGEH                                                         | MOS/MSC      | 29-Apr-15                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:57861                                                                   | HRS          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                           |                |          |                        |           |           |             |                  |
| 25-21-01                                                                   |              | PAX 3 - RH AFT FACE SEAT                  |                |          |                        |           |           |             | Component ATA:25 |
| PN:403174-26CDDGEH                                                         | MOS/MSC      | 29-Apr-15                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:57863                                                                   | HRS          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                           |                |          |                        |           |           |             |                  |
| 25-21-01                                                                   |              | PAX 6 - LH FWD FACE SEAT                  |                |          |                        |           |           |             | Component ATA:25 |
| PN:403174-27CDDGEH                                                         | MOS/MSC      | 29-Apr-15                                 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:57864                                                                   | HRS          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                        | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                             |           |                |          |                        |           |           |             |                  |
| 25-21-01                                                                   | PAX 7 - RH FWD FACE SEAT                    |           |                |          |                        |           |           |             | Component ATA:25 |
| PN:403174-28CDDGEH                                                         | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:57865                                                                   | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |                                             |           |                |          |                        |           |           |             |                  |
| 25-21-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION OF PASSENGER SEATS      |           |                |          |                        |           |           |             | Service ATA:25   |
|                                                                            | MOS                                         | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                         | 0         | 2400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01                             |                                             |           |                |          |                        |           |           |             |                  |
| 25-21-01-002 <sup>S</sup>                                                  | DETAILED INSPECTION OF PASSENGER SEAT BELTS |           |                |          |                        |           |           |             | Service ATA:25   |
|                                                                            | MOS                                         | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                         | 0         | 2400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01                             |                                             |           |                |          |                        |           |           |             |                  |
| 25-21-02                                                                   | DIVAN                                       |           |                |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-02, AMM 25-21-02PROC. REF: AMM 25-21-02, AMM 25-21-02 |                                             |           |                |          |                        |           |           |             |                  |
| 25-21-02-001 <sup>S</sup>                                                  | DETAILED INSPECTION DIVAN                   |           |                |          |                        |           |           |             | Service ATA:25   |
|                                                                            | MOS                                         | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                         | 0         | 3200 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-02PROC. REF: AMM 25-21-02                             |                                             |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                                                                                             | Interval       | TSX/Adj.      | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------|----------------|---------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |
| 25-21-02-002                                                               | <sup>S</sup> | DETAILED INSPECTION DIVAN SEAT BELTS                                                                                                            |                |               |                        |           |           |             | Service ATA:25   |
|                                                                            | MOS          | 29-Apr-15                                                                                                                                       |                |               |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                                                                                                               | 3200 (+30/-30) |               |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                                                                               |                |               |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-02PROC. REF: AMM 25-21-02                             |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |
| 25-21-03                                                                   |              | PAX 4 - LH FWD FACE SEAT                                                                                                                        |                |               |                        |           |           |             | Component ATA:25 |
| PN:403174-25CDDGEH                                                         | MOS/MSC      | 29-Apr-15                                                                                                                                       | O/C            | TSN 0         |                        |           |           |             |                  |
| SN:57860                                                                   | HRS          | 0                                                                                                                                               |                | TSN 0         |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                                                                               |                | TSN 0         |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |
| 25-21-03                                                                   |              | PAX 5 - RH FWD FACE SEAT                                                                                                                        |                |               |                        |           |           |             | Component ATA:25 |
| PN:403174-26CDDGEH                                                         | MOS/MSC      | 29-Apr-15                                                                                                                                       | O/C            | TSN 0         |                        |           |           |             |                  |
| SN:57862                                                                   | HRS          | 0                                                                                                                                               |                | TSN 0         |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                                                                               |                | TSN 0         |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-01, AMM 25-21-01 |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |
| 25-21-04                                                                   |              | (DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY                                                                                                     |                |               |                        |           |           |             | Component ATA:25 |
| PN:508358-415                                                              | MOS/MSC      | 26-Aug-21                                                                                                                                       | O/C            | TSN 0         |                        |           |           |             |                  |
| SN:A08OCT20-67                                                             | HRS          | 1658.4                                                                                                                                          |                | TSN 0         |                        |           |           |             |                  |
|                                                                            | AFL          | 953                                                                                                                                             |                | TSN 0         |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-04, AMM 25-21-04PROC. REF: AMM 25-21-04, AMM 25-21-04 |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |
| 25-21-04-001                                                               |              | RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY |                |               |                        |           |           |             | Service ATA:25   |
| PN:508358-415                                                              | MOS          | 26-Aug-21                                                                                                                                       | 84             | 08-Oct-27 (M) |                        | 844 d     |           |             |                  |
| SN:A08OCT20-67                                                             | HRS          | 1658.4                                                                                                                                          |                |               |                        |           |           |             |                  |
|                                                                            | AFL          | 953                                                                                                                                             |                |               |                        |           |           |             |                  |
| PROC. REF: AMM 25-21-04, AMM 25-21-04PROC. REF: AMM 25-21-04, AMM 25-21-04 |              |                                                                                                                                                 |                |               |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                         |           |                |          |                        |           |              |             |                  |
| 25-21-04-002                                                               | DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER       |           |                |          |                        |           |              |             | Service ATA:25   |
| PN:510184-401                                                              | MOS                                                     | 14-May-25 | 120            |          | 01-Mar-35              |           | 3545 d       | LIFE LIMIT  |                  |
| SN:AS2F1LEYALF                                                             | HRS                                                     | 2086.2    |                |          |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 1243      |                |          |                        |           |              |             |                  |
| Manufacture Date:: 01-Mar-25                                               |                                                         |           |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                         |           |                |          |                        |           |              |             |                  |
| 25-21-04-003                                                               | DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG ASSEMBLY |           |                |          |                        |           |              |             | Service ATA:25   |
| PN:PN                                                                      | MOS                                                     | 14-May-25 | 48 (+1m/-1m)   | Adj 12d  | 26-May-29              | 26-Jun-29 | 1440 d (+31) |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 2086.2    |                |          |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 1243      |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                         |           |                |          |                        |           |              |             |                  |
| 25-21-04-004                                                               | OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY          |           |                |          |                        |           |              |             | Service ATA:25   |
| PN:PN                                                                      | MOS                                                     | 14-May-25 | 48 (+1m/-1m)   | Adj 12d  | 26-May-29              | 26-Jun-29 | 1440 d (+31) |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 2086.2    |                |          |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 1243      |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                         |           |                |          |                        |           |              |             |                  |
| 25-21-10                                                                   | AIRBAG CYLINDER INFLATOR, ACH COLD                      |           |                |          |                        |           |              |             | Component ATA:25 |
| PN:510184-401                                                              | MOS/MSC                                                 | 14-May-25 | H/T            | TSN 2    |                        |           |              |             |                  |
| SN:AS2F1LEYALF                                                             | HRS                                                     | 2086.2    |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 1243      |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                         |           |                |          |                        |           |              |             |                  |
| 25-21-11                                                                   | DIVAN SEAT BELT AIRBAG ASSEMBLY                         |           |                |          |                        |           |              |             | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 25-21-04, AMM 25-21-04PROC. REF: AMM 25-21-04, AMM 25-21-04 |                                                         |           |                |          |                        |           |              |             |                  |
| 25-43-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION BELTED TOILET UNIT           |           |                |          |                        |           |              |             | Service ATA:25   |
|                                                                            | MOS                                                     | 29-Apr-15 |                |          |                        |           |              |             |                  |
|                                                                            | HRS                                                     | 0         | 3200 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL                                                     | 0         |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02                             |                                                         |           |                |          |                        |           |              |             |                  |
| PKG:40                                                                     |                                                         |           |                |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                           | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |              |                                                               |                |          |                        |           |           |             |          |
| 25-43-01-002                                                               | <sup>S</sup> | DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT            |                |          |                        |           |           | Service     | ATA:25   |
|                                                                            | MOS          | 29-Apr-15                                                     |                |          |                        |           |           |             |          |
|                                                                            | HRS          | 0                                                             | 3200 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                             |                |          |                        |           |           |             |          |
| PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02                             |              |                                                               |                |          |                        |           |           |             |          |
| 25-60-01                                                                   |              | EMERGENCY LOCATOR TRANSMITTER                                 |                |          |                        |           |           | Component   | ATA:25   |
| PN:S1821502-02                                                             | MOS/MSC      | 29-Apr-15                                                     | O/C            | TSN 0    |                        |           |           |             |          |
| SN:LX1100115090                                                            | HRS          | 0                                                             |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                             |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01 |              |                                                               |                |          |                        |           |           |             |          |
| 25-60-03                                                                   |              | ELT ANTENNA                                                   |                |          |                        |           |           | Component   | ATA:25   |
| PN:S65-8282-406                                                            | MOS/MSC      | 29-Apr-15                                                     | O/C            | TSN 0    |                        |           |           |             |          |
| SN:401-2550                                                                | HRS          | 0                                                             |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                             |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-61-03, AMM 25-61-03PROC. REF: AMM 25-61-03, AMM 25-61-03 |              |                                                               |                |          |                        |           |           |             |          |
| 25-60-11                                                                   |              | EMERGENCY LOCATOR TRANSMITTER BATTERY                         |                |          |                        |           |           | Component   | ATA:25   |
| PN:S1820506-01                                                             | MOS/MSC      | 20-Oct-20                                                     | H/T            | TSN 0    |                        |           |           |             |          |
| SN:20230195                                                                | HRS          | 1531.4                                                        |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 894                                                           |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01 |              |                                                               |                |          |                        |           |           |             |          |
| 25-61-00-001                                                               |              | OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM |                |          |                        |           |           | Service     | ATA:25   |
| PN:S1821502-02                                                             | MOS          | 14-May-25                                                     | 12             |          | 14-May-26              |           | 332 d     |             |          |
| SN:LX1100115090                                                            | HRS          | 2086.2                                                        |                |          |                        |           |           |             |          |
|                                                                            | AFL          | 1243                                                          |                |          |                        |           |           |             |          |
| PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00                             |              |                                                               |                |          |                        |           |           |             |          |
| 25-61-00-002                                                               |              | GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER    |                |          |                        |           |           | Service     | ATA:25   |
| PN:S1821502-02                                                             | MOS          | 14-May-25                                                     | 12             |          | 14-May-26              |           | 332 d     |             |          |
| SN:LX1100115090                                                            | HRS          | 2086.2                                                        |                |          |                        |           |           |             |          |
|                                                                            | AFL          | 1243                                                          |                |          |                        |           |           |             |          |
| PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00                             |              |                                                               |                |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                               |           |          |          |                        |           |           |             |                  |
| 25-61-04-001                                                               | DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY |           |          |          |                        |           |           |             | Service ATA:25   |
| PN:S1820506-01                                                             | MOS/MSC                                       | 20-Oct-20 | DUE      |          | 01-May-27 (M)          |           | 684 d     | LIFE LIMIT  |                  |
| SN:20230195                                                                | HRS                                           | 1531.4    |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                           | 894       |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-61-04PROC. REF: AMM 25-61-04                             |                                               |           |          |          |                        |           |           |             |                  |
| 25-61-05                                                                   | CS144-A ELT/NAV INTERFACE MODULE              |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-61-05, AMM 25-61-05PROC. REF: AMM 25-61-05, AMM 25-61-05 |                                               |           |          |          |                        |           |           |             |                  |
| 25-62-01                                                                   | #1 FIRST AID KIT                              |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:39N814                                                                  | MOS/MSC                                       | 14-May-25 | H/T      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 2086.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 1243      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                               |           |          |          |                        |           |           |             |                  |
| 25-62-01-001                                                               | VISUAL CHECK #1 FIRST AID KIT                 |           |          |          |                        |           |           |             | Service ATA:25   |
| PN:39N814                                                                  | MOS/MSC                                       | 14-May-25 | DUE      |          | 28-Feb-26 (M)          |           | 257 d     |             |                  |
| SN:UNKNOWN                                                                 | HRS                                           | 2086.2    |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                           | 1243      |          |          |                        |           |           |             |                  |
| Expiry Date: : 28-Feb-26                                                   |                                               |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01                             |                                               |           |          |          |                        |           |           |             |                  |
| 25-62-02                                                                   | COPILOT LIFE VEST                             |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:66601-505                                                               | MOS/MSC                                       | 14-May-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:L6520964                                                                | HRS                                           | 2086.2    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 1243      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                               |           |          |          |                        |           |           |             |                  |
| 25-62-02                                                                   | DIVAN NO. 1 LIFE VEST                         |           |          |          |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                                       | 14-May-25 | O/C      |          |                        |           |           |             |                  |
| SN:L2680227                                                                | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                      | C/W       | Interval | TSX/Adj.          | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------|-----------|----------|-------------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | DIVAN NO. 2 LIFE VEST     |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 0             |                        |           |           |             |                  |
| SN:L2680226                                                                | HRS                       | 0         |          | TSN 0             |                        |           |           |             |                  |
|                                                                            | AFL                       | 0         |          | TSN 0             |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | NO. 1 PASSENGER LIFE VEST |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 121, TSO 0    |                        |           |           |             |                  |
| SN:L2680228                                                                | HRS                       | 2086.2    |          | TSN 2086.2, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                       | 1243      |          | TSN 1243, TSO 0   |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | NO. 2 PASSENGER LIFE VEST |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 121, TSO 0    |                        |           |           |             |                  |
| SN:L2680231                                                                | HRS                       | 2086.2    |          | TSN 2086.2, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                       | 1243      |          | TSN 1243, TSO 0   |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | NO. 3 PASSENGER LIFE VEST |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 121, TSO 0    |                        |           |           |             |                  |
| SN:L2680241                                                                | HRS                       | 2086.2    |          | TSN 2086.2, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                       | 1243      |          | TSN 1243, TSO 0   |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | NO. 4 PASSENGER LIFE VEST |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 121, TSO 0    |                        |           |           |             |                  |
| SN:L2680229                                                                | HRS                       | 2086.2    |          | TSN 2086.2, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                       | 1243      |          | TSN 1243, TSO 0   |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |
| 25-62-02                                                                   | NO. 5 PASSENGER LIFE VEST |           |          |                   |                        |           |           |             | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 14-May-25 | O/C      | TSN 121, TSO 0    |                        |           |           |             |                  |
| SN:L2680239                                                                | HRS                       | 2086.2    |          | TSN 2086.2, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                       | 1243      |          | TSN 1243, TSO 0   |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |                   |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                             | Interval                  | TSX/Adj.          | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty  |        |
|----------------------------------------------------------------------------|---------|-------------------------------------------------|---------------------------|-------------------|------------------------|-----------|-----------|-------------|-----------|--------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02                                                                   |         | NO. 6 PASSENGER LIFE VEST                       |                           |                   |                        |           |           |             | Component | ATA:25 |
| PN:66601-105                                                               | MOS/MSC | 14-May-25                                       | O/C                       | TSN 121, TSO 0    |                        |           |           |             |           |        |
| SN:L2680240                                                                | HRS     | 2086.2                                          |                           | TSN 2086.2, TSO 0 |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           | TSN 1243, TSO 0   |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02                                                                   |         | PILOT LIFE VEST                                 |                           |                   |                        |           |           |             | Component | ATA:25 |
| PN:66601-505                                                               | MOS/MSC | 14-May-25                                       | O/C                       | TSN 0             |                        |           |           |             |           |        |
| SN:L6468242                                                                | HRS     | 2086.2                                          |                           | TSN 0             |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           | TSN 0             |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02                                                                   |         | TOILET PAX LIFE VEST                            |                           |                   |                        |           |           |             | Component | ATA:25 |
| PN:66601-105                                                               | MOS/MSC | 14-May-25                                       | O/C                       | TSN 121, TSO 0    |                        |           |           |             |           |        |
| SN:L2680242                                                                | HRS     | 2086.2                                          |                           | TSN 2086.2, TSO 0 |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           | TSN 1243, TSO 0   |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02-001                                                               |         | RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST    |                           |                   |                        |           |           |             | Service   | ATA:25 |
| PN:66601-505                                                               | MOS     | 14-May-25                                       | 120                       | 14-May-35         |                        |           | 3619 d    | OVERHAUL    |           |        |
| SN:L6520964                                                                | HRS     | 2086.2                                          |                           |                   |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           |                   |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02                             |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02-001                                                               |         | RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST |                           |                   |                        |           |           |             | Service   | ATA:25 |
| PN:66601-105                                                               | MOS     | 14-May-25                                       | 120                       | 08-May-35         |                        |           | 3613 d    | OVERHAUL    |           |        |
| SN:L2680227                                                                | HRS     | 2086.2                                          |                           |                   |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           |                   |                        |           |           |             |           |        |
|                                                                            |         |                                                 | OverHaul Date:: 08-May-25 |                   |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02                             |         |                                                 |                           |                   |                        |           |           |             |           |        |
| 25-62-02-001                                                               |         | RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST |                           |                   |                        |           |           |             | Service   | ATA:25 |
| PN:66601-105                                                               | MOS     | 14-May-25                                       | 120                       | 08-May-35         |                        |           | 3613 d    | OVERHAUL    |           |        |
| SN:L2680226                                                                | HRS     | 2086.2                                          |                           |                   |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                            |                           |                   |                        |           |           |             |           |        |
|                                                                            |         |                                                 | OverHaul Date:: 08-May-25 |                   |                        |           |           |             |           |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02                             |         |                                                 |                           |                   |                        |           |           |             |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit | C/W                                       | Interval                  | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |        |
|------------------------------------------------|------|-------------------------------------------|---------------------------|----------|------------------------|-----------|-----------|-------------|----------|--------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |      |                                           |                           |          |                        |           |           |             |          |        |
| 25-62-02-001                                   |      | RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST |                           |          |                        |           |           |             | Service  | ATA:25 |
| PN:66601-105                                   | MOS  | 14-May-25                                 | 120                       |          | 08-May-35              |           | 3613 d    | OVERHAUL    |          |        |
| SN:L2680228                                    | HRS  | 2086.2                                    |                           |          |                        |           |           |             |          |        |
|                                                | AFL  | 1243                                      |                           |          |                        |           |           |             |          |        |
|                                                |      |                                           | OverHaul Date:: 08-May-25 |          |                        |           |           |             |          |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |      |                                           |                           |          |                        |           |           |             |          |        |
| 25-62-02-001                                   |      | RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST |                           |          |                        |           |           |             | Service  | ATA:25 |
| PN:66601-105                                   | MOS  | 14-May-25                                 | 120                       |          | 08-May-35              |           | 3613 d    | OVERHAUL    |          |        |
| SN:L2680231                                    | HRS  | 2086.2                                    |                           |          |                        |           |           |             |          |        |
|                                                | AFL  | 1243                                      |                           |          |                        |           |           |             |          |        |
|                                                |      |                                           | OverHaul Date:: 08-May-25 |          |                        |           |           |             |          |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |      |                                           |                           |          |                        |           |           |             |          |        |
| 25-62-02-001                                   |      | RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST |                           |          |                        |           |           |             | Service  | ATA:25 |
| PN:66601-105                                   | MOS  | 14-May-25                                 | 120                       |          | 08-May-35              |           | 3613 d    | OVERHAUL    |          |        |
| SN:L2680241                                    | HRS  | 2086.2                                    |                           |          |                        |           |           |             |          |        |
|                                                | AFL  | 1243                                      |                           |          |                        |           |           |             |          |        |
|                                                |      |                                           | OverHaul Date:: 08-May-25 |          |                        |           |           |             |          |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |      |                                           |                           |          |                        |           |           |             |          |        |
| 25-62-02-001                                   |      | RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST |                           |          |                        |           |           |             | Service  | ATA:25 |
| PN:66601-105                                   | MOS  | 14-May-25                                 | 120                       |          | 08-May-35              |           | 3613 d    | OVERHAUL    |          |        |
| SN:L2680229                                    | HRS  | 2086.2                                    |                           |          |                        |           |           |             |          |        |
|                                                | AFL  | 1243                                      |                           |          |                        |           |           |             |          |        |
|                                                |      |                                           | OverHaul Date:: 08-May-25 |          |                        |           |           |             |          |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |      |                                           |                           |          |                        |           |           |             |          |        |
| 25-62-02-001                                   |      | RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST |                           |          |                        |           |           |             | Service  | ATA:25 |
| PN:66601-105                                   | MOS  | 14-May-25                                 | 120                       |          | 08-May-35              |           | 3613 d    | OVERHAUL    |          |        |
| SN:L2680239                                    | HRS  | 2086.2                                    |                           |          |                        |           |           |             |          |        |
|                                                | AFL  | 1243                                      |                           |          |                        |           |           |             |          |        |
|                                                |      |                                           | OverHaul Date:: 08-May-25 |          |                        |           |           |             |          |        |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |      |                                           |                           |          |                        |           |           |             |          |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                             | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                     |                                                  |           |              |          |                        |           |           |             |                  |
| 25-62-02-001                                       | RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST        |           |              |          |                        |           |           |             | Service ATA:25   |
| PN:66601-105                                       | MOS                                              | 14-May-25 | 120          |          | 08-May-35              |           | 3613 d    | OVERHAUL    |                  |
| SN:L2680240                                        | HRS                                              | 2086.2    |              |          |                        |           |           |             |                  |
|                                                    | AFL                                              | 1243      |              |          |                        |           |           |             |                  |
| OverHaul Date:: 08-May-25                          |                                                  |           |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02     |                                                  |           |              |          |                        |           |           |             |                  |
| 25-62-02-001                                       | RESTORATION (OVERHAUL) OF PILOT LIFE VEST        |           |              |          |                        |           |           |             | Service ATA:25   |
| PN:66601-505                                       | MOS                                              | 14-May-25 | 120          |          | 14-May-35              |           | 3619 d    | OVERHAUL    |                  |
| SN:L6468242                                        | HRS                                              | 2086.2    |              |          |                        |           |           |             |                  |
|                                                    | AFL                                              | 1243      |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02     |                                                  |           |              |          |                        |           |           |             |                  |
| 25-62-02-001                                       | RESTORATION (OVERHAUL) OF TOILET LIFE VEST       |           |              |          |                        |           |           |             | Service ATA:25   |
| PN:66601-105                                       | MOS                                              | 14-May-25 | 120          |          | 08-May-35              |           | 3613 d    | OVERHAUL    |                  |
| SN:L2680242                                        | HRS                                              | 2086.2    |              |          |                        |           |           |             |                  |
|                                                    | AFL                                              | 1243      |              |          |                        |           |           |             |                  |
| OverHaul Date:: 08-May-25                          |                                                  |           |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02     |                                                  |           |              |          |                        |           |           |             |                  |
| 25-62-04-001 <sup>S</sup>                          | DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER |           |              |          |                        |           |           |             | Service ATA:25   |
|                                                    | MOS                                              | 14-May-25 | 24 (+1m/-1m) |          |                        |           |           |             |                  |
|                                                    | HRS                                              | 2086.2    |              |          |                        |           |           |             |                  |
|                                                    | AFL                                              | 1243      |              |          |                        |           |           |             |                  |
| OverHaul Date:: 08-May-25                          |                                                  |           |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04     |                                                  |           |              |          |                        |           |           |             |                  |
| 25-66-01                                           | LIFE RAFT                                        |           |              |          |                        |           |           |             | Component ATA:25 |
| PN:1015FASA-331-1-101                              | MOS/MSC                                          | 09-Nov-22 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:10SA-00247                                      | HRS                                              |           |              | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                                              |           |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |              |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                       |           |                |          |                        |           |           |             |                  |
| 25-66-01-001                                                               | RESTORATION LIFE RAFT (OVERHAUL)                      |           |                |          |                        |           |           |             | Service ATA:25   |
| PN:1015FASA-331-1-101                                                      | MOS/MSC                                               | 09-Nov-22 | N/A            |          |                        |           |           |             |                  |
| SN:10SA-00247                                                              | HRS                                                   |           |                |          |                        |           |           |             |                  |
|                                                                            | AFL                                                   |           |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 25-66-01PROC. REF: AMM 25-66-01                             |                                                       |           |                |          |                        |           |           |             |                  |
| ATA 26 - FIRE PROTECTION                                                   |                                                       |           |                |          |                        |           |           |             |                  |
| 26-11-01                                                                   | LEFT ENGINE FIRE DETECTOR                             |           |                |          |                        |           |           |             | Component ATA:26 |
| PN:3951-51-565/215C-5.1M                                                   | MOS/MSC                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:49751                                                                   | HRS                                                   | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01 |                                                       |           |                |          |                        |           |           |             |                  |
| 26-11-01                                                                   | RIGHT ENGINE FIRE DETECTOR                            |           |                |          |                        |           |           |             | Component ATA:26 |
| PN:3951-51-565/215C-5.1M                                                   | MOS/MSC                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:49755                                                                   | HRS                                                   | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01 |                                                       |           |                |          |                        |           |           |             |                  |
| 26-11-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR  |           |                |          |                        |           |           |             | Service ATA:26   |
|                                                                            | MOS                                                   | 28-Dec-18 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                   | 1178.1    | 1600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 679       |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |                                                       |           |                |          |                        |           |           |             |                  |
| 26-11-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR |           |                |          |                        |           |           |             | Service ATA:26   |
|                                                                            | MOS                                                   | 28-Dec-18 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                   | 1178.1    | 1600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 679       |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |                                                       |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                 | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------|----------------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 26 - FIRE PROTECTION                                                   |              |                                                     |                |          |                        |           |           |               |                  |
| 26-11-01-002                                                               | <sup>S</sup> | OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR         |                |          |                        |           |           |               | Service ATA:26   |
|                                                                            | MOS          | 29-Apr-24                                           |                |          |                        |           |           |               |                  |
|                                                                            | HRS          | 1952.5                                              | 800 (+30/-30)  |          |                        |           |           |               |                  |
|                                                                            | AFL          | 1160                                                |                |          |                        |           |           |               |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |              |                                                     |                |          |                        |           |           |               |                  |
| 26-11-01-002                                                               | <sup>S</sup> | OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR        |                |          |                        |           |           |               | Service ATA:26   |
|                                                                            | MOS          | 29-Apr-24                                           |                |          |                        |           |           |               |                  |
|                                                                            | HRS          | 1952.5                                              | 800 (+30/-30)  |          |                        |           |           |               |                  |
|                                                                            | AFL          | 1160                                                |                |          |                        |           |           |               |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |              |                                                     |                |          |                        |           |           |               |                  |
| 26-15-01                                                                   |              | MODEL 602 SMOKE DETECTOR                            |                |          |                        |           |           |               | Component ATA:26 |
| PN:8930-223B60L014                                                         | MOS/MSC      | 29-Apr-15                                           | O/C            | TSN 0    |                        |           |           |               |                  |
| SN:23981                                                                   | HRS          | 0                                                   |                | TSN 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 0                                                   |                | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 26-15-01, AMM 26-15-01PROC. REF: AMM 26-15-01, AMM 26-15-01 |              |                                                     |                |          |                        |           |           |               |                  |
| 26-21-01                                                                   |              | ENGINE FIRE EXTINGUISHER BOTTLE                     |                |          |                        |           |           |               | Component ATA:26 |
| PN:33000073-1                                                              | MOS/MSC      | 14-May-25                                           | O/C            | TSO 8    |                        |           |           |               |                  |
| SN:72069A1                                                                 | HRS          | 2086.2                                              |                | TSO 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 1243                                                |                | TSO 0    |                        |           |           |               |                  |
| PROC. REF: AMM 26-21-03, AMM 26-21-03PROC. REF: AMM 26-21-03, AMM 26-21-03 |              |                                                     |                |          |                        |           |           |               |                  |
| 26-21-01-001                                                               |              | FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL |                |          |                        |           |           |               | Service ATA:26   |
|                                                                            | MOS          | 29-Apr-15                                           |                |          |                        |           |           | AIRWORTHINESS |                  |
|                                                                            | HRS          | 0                                                   | 2400 (+30/-30) |          | 2400                   | 2430      | 300 (+30) |               |                  |
|                                                                            | AFL          | 0                                                   |                |          |                        |           |           |               |                  |
| PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00                             |              |                                                     |                |          |                        |           |           |               |                  |
| 26-21-01A                                                                  |              | FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL             |                |          |                        |           |           |               | Component ATA:26 |
| PN:441-42702-002                                                           | MOS/MSC      | 29-Apr-15                                           | O/C            | TSN 0    |                        |           |           |               |                  |
| SN:0584                                                                    | HRS          | 0                                                   |                | TSN 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 0                                                   |                | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 26-21-01, AMM 26-21-01PROC. REF: AMM 26-21-01, AMM 26-21-01 |              |                                                     |                |          |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                 | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 26 - FIRE PROTECTION                                                   |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-03-001                                                               |         | FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE                 |                |          |                        |           |           | Service       | ATA:26   |
| PN:33000073-1                                                              | MOS     | 04-Sep-24                                                           | 120            |          | 04-Sep-34              |           | 3367 d    | AIRWORTHINESS |          |
| SN:72069A1                                                                 | HRS     |                                                                     |                |          |                        |           |           |               |          |
|                                                                            | AFL     |                                                                     |                |          |                        |           |           |               |          |
| PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03                             |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-05-001 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) |                |          |                        |           |           | Service       | ATA:26   |
|                                                                            | MOS     | 29-Apr-15                                                           |                |          |                        |           |           |               |          |
|                                                                            | HRS     | 0                                                                   | 2400 (+30/-30) |          |                        |           |           |               |          |
|                                                                            | AFL     | 0                                                                   |                |          |                        |           |           |               |          |
| PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05                             |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-07                                                                   |         | NO. 1 CARTRIDGE                                                     |                |          |                        |           |           | Component     | ATA:26   |
| PN:30903962-1                                                              | MOS/MSC | 14-May-25                                                           | H/T            | TSN 0    |                        |           |           |               |          |
| SN:0171EL                                                                  | HRS     | 2086.2                                                              |                | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL     | 1243                                                                |                | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07 |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-07                                                                   |         | NO. 2 CARTRIDGE                                                     |                |          |                        |           |           | Component     | ATA:26   |
| PN:30903963-1                                                              | MOS/MSC | 14-May-25                                                           | H/T            | TSN 0    |                        |           |           |               |          |
| SN:00993                                                                   | HRS     | 2086.2                                                              |                | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL     | 1243                                                                |                | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07 |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-07-001                                                               |         | DISCARD NO. 1 CARTRIDGE                                             |                |          |                        |           |           | Service       | ATA:26   |
| PN:30903962-1                                                              | MOS     | 14-May-25                                                           | 120            |          | 14-May-35              |           | 3619 d    | LIFE LIMIT    |          |
| SN:0171EL                                                                  | HRS     | 2086.2                                                              |                |          |                        |           |           |               |          |
|                                                                            | AFL     | 1243                                                                |                |          |                        |           |           |               |          |
| PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07                             |         |                                                                     |                |          |                        |           |           |               |          |
| 26-21-07-001                                                               |         | DISCARD NO. 2 CARTRIDGE                                             |                |          |                        |           |           | Service       | ATA:26   |
| PN:30903963-1                                                              | MOS     | 14-May-25                                                           | 120            |          | 14-May-35              |           | 3619 d    | LIFE LIMIT    |          |
| SN:00993                                                                   | HRS     | 2086.2                                                              |                |          |                        |           |           |               |          |
|                                                                            | AFL     | 1243                                                                |                |          |                        |           |           |               |          |
| PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07                             |         |                                                                     |                |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 26 - FIRE PROTECTION

|                                                |              |                                                                          |                |  |  |  |  |         |        |
|------------------------------------------------|--------------|--------------------------------------------------------------------------|----------------|--|--|--|--|---------|--------|
| 26-21-09-001                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING |                |  |  |  |  | Service | ATA:26 |
|                                                | MOS          | 29-Apr-15                                                                |                |  |  |  |  |         |        |
|                                                | HRS          | 0                                                                        | 2400 (+30/-30) |  |  |  |  |         |        |
|                                                | AFL          | 0                                                                        |                |  |  |  |  |         |        |
| PROC. REF: AMM 26-21-09PROC. REF: AMM 26-21-09 |              |                                                                          |                |  |  |  |  |         | PKG:20 |

|                                                                            |         |                                  |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------|----------------------------------|-----|-------|--|--|--|-----------|--------|
| 26-24-01                                                                   |         | CABIN PORTABLE FIRE EXTINGUISHER |     |       |  |  |  | Component | ATA:26 |
| PN:RT-A1200                                                                | MOS/MSC | 27-Apr-18                        | H/T | TSN 0 |  |  |  |           |        |
| SN:Y-501331                                                                | HRS     | 1013.5                           |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL     | 579                              |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-24-01, AMM 26-24-01PROC. REF: AMM 26-24-01, AMM 26-24-01 |         |                                  |     |       |  |  |  |           |        |

|                                                                            |         |                                    |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------|------------------------------------|-----|-------|--|--|--|-----------|--------|
| 26-24-01                                                                   |         | COCKPIT PORTABLE FIRE EXTINGUISHER |     |       |  |  |  | Component | ATA:26 |
| PN:RT-A1200                                                                | MOS/MSC | 24-Apr-23                          | H/T | TSN 5 |  |  |  |           |        |
| SN:D58318324                                                               | HRS     | 1825.5                             |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL     | 1042                               |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 26-24-01, AMM 26-24-01PROC. REF: AMM 26-24-01, AMM 26-24-01 |         |                                    |     |       |  |  |  |           |        |

|                                                |     |                                               |    |           |  |       |  |         |                                |
|------------------------------------------------|-----|-----------------------------------------------|----|-----------|--|-------|--|---------|--------------------------------|
| 26-24-01-001                                   |     | WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER |    |           |  |       |  | Service | ATA:26                         |
| PN:RT-A1200                                    | MOS | 14-May-25                                     | 12 | 14-May-26 |  | 332 d |  |         |                                |
| SN:Y-501331                                    | HRS | 2086.2                                        |    |           |  |       |  |         |                                |
|                                                | AFL | 1243                                          |    |           |  |       |  |         |                                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |     |                                               |    |           |  |       |  |         | WeightCheck Date : : 14-May-25 |

|                                                |     |                                                    |    |           |  |       |  |         |                                |
|------------------------------------------------|-----|----------------------------------------------------|----|-----------|--|-------|--|---------|--------------------------------|
| 26-24-01-001                                   |     | WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER |    |           |  |       |  | Service | ATA:26                         |
| PN:RT-A1200                                    | MOS | 14-May-25                                          | 12 | 14-May-26 |  | 332 d |  |         |                                |
| SN:D58318324                                   | HRS | 2086.2                                             |    |           |  |       |  |         |                                |
|                                                | AFL | 1243                                               |    |           |  |       |  |         |                                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |     |                                                    |    |           |  |       |  |         | WeightCheck Date : : 14-May-25 |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |        |
|----------------------------------------------------------------------------|---------|----------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|--------|
| ATA 26 - FIRE PROTECTION                                                   |         |                                                    |          |          |                        |           |           |             |          |        |
| 26-24-01-002                                                               |         | DISCARD CABIN PORTABLE FIRE EXTINGUISHER           |          |          |                        |           |           |             | Service  | ATA:26 |
| PN:RT-A1200                                                                | MOS     | 01-Jan-17                                          | 144      |          | 01-Jan-29              |           | 1295 d    | LIFE LIMIT  |          |        |
| SN:Y-501331                                                                | HRS     |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     |                                                    |          |          |                        |           |           |             |          |        |
| Manufacture Date:: 01-Jan-17                                               |         |                                                    |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |         |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            |         |                                                    |          |          |                        |           |           |             |          |        |
| 26-24-01-002                                                               |         | DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER      |          |          |                        |           |           |             | Service  | ATA:26 |
| PN:RT-A1200                                                                | MOS     |                                                    | 144      |          | 01-Jul-34 (M)          |           | 3302 d    | LIFE LIMIT  |          |        |
| SN:D58318324                                                               | HRS     |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     |                                                    |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |         |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            |         |                                                    |          |          |                        |           |           |             |          |        |
| 26-24-01-004                                                               |         | WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER   |          |          |                        |           |           |             | Service  | ATA:26 |
|                                                                            | MOS/MSC |                                                    | N/A      |          |                        |           |           |             |          |        |
|                                                                            | HRS     |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     |                                                    |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |         |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            |         |                                                    |          |          |                        |           |           |             |          |        |
| 26-24-01-004                                                               |         | WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER |          |          |                        |           |           |             | Service  | ATA:26 |
| PN:RT-A1200                                                                | MOS/MSC |                                                    | N/A      |          |                        |           |           |             |          |        |
| SN:D58318324                                                               | HRS     |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     |                                                    |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |         |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            |         |                                                    |          |          |                        |           |           |             |          |        |
| ATA 27 - FLIGHT CONTROLS                                                   |         |                                                    |          |          |                        |           |           |             |          |        |
| 27-001                                                                     |         | DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR          |          |          |                        |           |           |             | Service  | ATA:27 |
| PN:475100-1013                                                             | MOS/MSC | 29-Apr-15                                          | N/A      |          |                        |           |           |             |          |        |
| SN:0599                                                                    | HRS     | 0                                                  |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     | 0                                                  |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |         |                                                    |          |          |                        |           |           |             |          |        |
|                                                                            |         |                                                    |          |          |                        |           |           |             |          |        |
| 27-001                                                                     |         | DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR         |          |          |                        |           |           |             | Service  | ATA:27 |
| PN:475100-1013                                                             | MOS/MSC | 29-Apr-15                                          | N/A      |          |                        |           |           |             |          |        |
| SN:0024                                                                    | HRS     | 0                                                  |          |          |                        |           |           |             |          |        |
|                                                                            | AFL     | 0                                                  |          |          |                        |           |           |             |          |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |         |                                                    |          |          |                        |           |           |             |          |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                            |           |          |          |                        |           |           |             |                  |
| 27-002                                                                     | DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR  |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-2013                                                             | MOS/MSC                                    | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:1173                                                                    | HRS                                        | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-002                                                                     | DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-2013                                                             | MOS/MSC                                    | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:1182                                                                    | HRS                                        | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-003                                                                     | DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR   |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-1013                                                             | MOS/MSC                                    | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:1178                                                                    | HRS                                        | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-003                                                                     | DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR  |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-1013                                                             | MOS/MSC                                    | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:1186                                                                    | HRS                                        | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-004                                                                     | ROLL TRIM ACTUATOR                         |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:470500-1005                                                             | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0300                                                                    | HRS                                        | 0         | 12000    | TSN 0    | 12000                  |           | 9900      |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-14-02, AMM 27-14-02PROC. REF: AMM 27-14-02, AMM 27-14-02 |                                            |           |          |          |                        |           |           |             |                  |
| 27-005                                                                     | YAW TRIM ACTUATOR                          |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:470600-1005                                                             | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0299                                                                    | HRS                                        | 0         | 12000    | TSN 0    | 12000                  |           | 9900      |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-24-02, AMM 27-24-02PROC. REF: AMM 27-24-02, AMM 27-24-02 |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                                                                           |                                     |           |          |          |                        |           |           |             |                  |
| 27-006                                                                                                                             | PITCH TRIM ACTUATOR                 |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:467500-1003                                                                                                                     | MOS                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0306                                                                                                                            | HRS                                 | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-41-01, AMM 27-41-01PROC. REF: AMM 27-41-01, AMM 27-41-01                                                         |                                     |           |          |          |                        |           |           |             |                  |
| 27-007                                                                                                                             | LEFT SPOILER ACTUATOR               |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:456800-1003                                                                                                                     | MOS                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0580                                                                                                                            | HRS                                 | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02 |                                     |           |          |          |                        |           |           |             |                  |
| 27-007                                                                                                                             | RIGHT SPOILER ACTUATOR              |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:456800-1003                                                                                                                     | MOS                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0581                                                                                                                            | HRS                                 | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02 |                                     |           |          |          |                        |           |           |             |                  |
| 27-008                                                                                                                             | ELECTRO - RUDDER GUST LOCK ACTUATOR |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                                                                                                              | MOS/MSC                             | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-70-01, AMM 27-70-01PROC. REF: AMM 27-70-01, AMM 27-70-01                                                         |                                     |           |          |          |                        |           |           |             |                  |
| 27-009                                                                                                                             | RUDDER BOOSTER ACTUATOR             |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:9125-3                                                                                                                          | MOS                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0242T                                                                                                                           | HRS                                 | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-23-02, AMM 27-23-02PROC. REF: AMM 27-23-02, AMM 27-23-02                                                         |                                     |           |          |          |                        |           |           |             |                  |
| 27-01-01                                                                                                                           | LEFT CONTROL WHEEL                  |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:83912139                                                                                                                        | MOS/MSC                             | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00864                                                                                                                           | HRS                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01                                                         |                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                              | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                   |           |              |          |                        |           |           |             |                  |
| 27-01-01                                                                   | RIGHT CONTROL WHEEL               |           |              |          |                        |           |           |             | Component ATA:27 |
| PN:83912141                                                                | MOS/MSC                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:00824                                                                   | HRS                               | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                               | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01 |                                   |           |              |          |                        |           |           |             |                  |
| 27-01-02                                                                   | LH PEDAL ASSEMBLY                 |           |              |          |                        |           |           |             | Component ATA:27 |
| PN:505-15420-427                                                           | MOS/MSC                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:0000833145                                                              | HRS                               | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                               | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-01-02, AMM 27-01-02PROC. REF: AMM 27-01-02, AMM 27-01-02 |                                   |           |              |          |                        |           |           |             |                  |
| 27-01-02                                                                   | RH PEDAL ASSEMBLY                 |           |              |          |                        |           |           |             | Component ATA:27 |
| PN:PN                                                                      | MOS/MSC                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                               | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                               | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-01-02, AMM 27-01-02PROC. REF: AMM 27-01-02, AMM 27-01-02 |                                   |           |              |          |                        |           |           |             |                  |
| 27-01-03-001 <sup>S</sup>                                                  | LUBRICATION OF ROTARY BALL SPLINE |           |              |          |                        |           |           |             | Service ATA:27   |
|                                                                            | MOS                               | 14-May-25 | 24 (+1m/-1m) |          |                        |           |           |             |                  |
|                                                                            | HRS                               | 2086.2    |              |          |                        |           |           |             |                  |
|                                                                            | AFL                               | 1243      |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |                                   |           |              |          |                        |           |           |             |                  |
| 27-010                                                                     | LEFT TOGGLE LINK                  |           |              |          |                        |           |           |             | Component ATA:27 |
| PN:456870-1001                                                             | MOS                               | 29-Apr-15 |              | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0654                                                                    | HRS                               | 0         | 35000        | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                               | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-65-02, AMM 27-65-02PROC. REF: AMM 27-65-02, AMM 27-65-02 |                                   |           |              |          |                        |           |           |             |                  |
| 27-010                                                                     | RIGHT TOGGLE LINK                 |           |              |          |                        |           |           |             | Component ATA:27 |
| PN:456870-1001                                                             | MOS                               | 29-Apr-15 |              | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0666                                                                    | HRS                               | 0         | 35000        | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                               | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-65-02, AMM 27-65-02PROC. REF: AMM 27-65-02, AMM 27-65-02 |                                   |           |              |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                            |           |          |          |                        |           |           |             |                  |
| 27-011                                                                     | STICK PUSHER ACTUATOR                      |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:9124-1                                                                  | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0309T                                                                   | HRS                                        | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-36-02, AMM 27-36-02PROC. REF: AMM 27-36-02, AMM 27-36-02 |                                            |           |          |          |                        |           |           |             |                  |
| 27-012                                                                     | POWER DRIVE UNIT                           |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:467700-1003                                                             | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0330                                                                    | HRS                                        | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-07, AMM 27-51-07PROC. REF: AMM 27-51-07, AMM 27-51-07 |                                            |           |          |          |                        |           |           |             |                  |
| 27-013                                                                     | LEFT FLAP POSITION SENSOR UNIT             |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:457310-1001                                                             | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0646                                                                    | HRS                                        | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03 |                                            |           |          |          |                        |           |           |             |                  |
| 27-013                                                                     | RIGHT FLAP POSITION SENSOR UNIT            |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:457310-1001                                                             | MOS                                        | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:0572                                                                    | HRS                                        | 0         | 35000    | TSN 0    | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03 |                                            |           |          |          |                        |           |           |             |                  |
| 27-014                                                                     | DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT  |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:457360-1007                                                             | MOS/MSC                                    | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:SSW0570                                                                 | HRS                                        | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                            |           |          |          |                        |           |           |             |                  |
| 27-014                                                                     | DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:457360-1005                                                             | MOS                                        | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:SSW1151                                                                 | HRS                                        | 0         | 35000    |          | 35000                  |           | 32900     |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                              |           |          |          |                        |           |           |             |                |
| 27-014                                                                     | DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:SSW1156                                                                 | HRS                                          | 0         | 35000    |          | 35000                  |           | 32900     |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-014                                                                     | DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT   |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1007                                                             | MOS/MSC                                      | 29-Apr-15 | N/A      |          |                        |           |           |             |                |
| SN:SSW0581                                                                 | HRS                                          | 0         |          |          |                        |           |           |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-014                                                                     | DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:SSW1157                                                                 | HRS                                          | 0         | 35000    |          | 35000                  |           | 32900     |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-014                                                                     | DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:SSW1165                                                                 | HRS                                          | 0         | 35000    |          | 35000                  |           | 32900     |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT    |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1007                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:SSW0570                                                                 | HRS                                          | 0         | 35000    |          | 35000                  |           | 32900     |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT   |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 29-Apr-15 | N/A      |          |                        |           |           |             |                |
| SN:SSW1151                                                                 | HRS                                          | 0         |          |          |                        |           |           |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 29-Apr-15 | N/A      |          |                        |           |           |             |                |
| SN:SSW1156                                                                 | HRS                                          | 0         |          |          |                        |           |           |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT   |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1007                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:SSW0581                                                                 | HRS                                          | 0         | 35000    |          | 35000                  |           | 32900     |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 29-Apr-15 | N/A      |          |                        |           |           |             |                |
| SN:SSW1157                                                                 | HRS                                          | 0         |          |          |                        |           |           |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-015                                                                     | DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 29-Apr-15 | N/A      |          |                        |           |           |             |                |
| SN:SSW1165                                                                 | HRS                                          | 0         |          |          |                        |           |           |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                        |           |           |             |                |
| 27-016                                                                     | DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR    |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:475100-1013                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:0599                                                                    | HRS                                          | 0         | 7200     |          | 7200                   |           | 5100      |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                              |           |          |          |                        |           |           |             |                |
| 27-016                                                                     | DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR   |           |          |          |                        |           |           |             | Service ATA:27 |
| PN:475100-1013                                                             | MOS                                          | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                |
| SN:0024                                                                    | HRS                                          | 0         | 7200     |          | 7200                   |           | 5100      |             |                |
|                                                                            | AFL                                          | 0         |          |          |                        |           |           |             |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                              |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                            |           |          |          |                        |           |           |             |                  |
| 27-017                                                                     | DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR  |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-2013                                                             | MOS                                        | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:1173                                                                    | HRS                                        | 0         | 7200     |          | 7200                   |           | 5100      |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-017                                                                     | DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-2013                                                             | MOS                                        | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:1182                                                                    | HRS                                        | 0         | 7200     |          | 7200                   |           | 5100      |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-018                                                                     | DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR   |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-1013                                                             | MOS                                        | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:1178                                                                    | HRS                                        | 0         | 7200     |          | 7200                   |           | 5100      |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-018                                                                     | DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR  |           |          |          |                        |           |           |             | Service ATA:27   |
| PN:475000-1013                                                             | MOS                                        | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:1186                                                                    | HRS                                        | 0         | 7200     |          | 7200                   |           | 5100      |             |                  |
|                                                                            | AFL                                        | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-03-01                                                                   | NO. 1 ELECTRONICS FLIGHT CONTROL           |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:462900-1017                                                             | MOS/MSC                                    | 01-Jun-23 | O/C      | TSR 3    |                        |           |           |             |                  |
| SN:0766                                                                    | HRS                                        | 1842.7    |          | TSR 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 1053      |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-03-01, AMM 27-03-01PROC. REF: AMM 27-03-01, AMM 27-03-01 |                                            |           |          |          |                        |           |           |             |                  |
| 27-03-01                                                                   | NO. 2 ELECTRONICS FLIGHT CONTROL           |           |          |          |                        |           |           |             | Component ATA:27 |
| PN:462900-1017                                                             | MOS/MSC                                    | 07-Jun-23 | O/C      | TSR 9    |                        |           |           |             |                  |
| SN:1230                                                                    | HRS                                        | 1842.7    |          | TSR 0    |                        |           |           |             |                  |
|                                                                            | AFL                                        | 1053      |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 27-03-01, AMM 27-03-01PROC. REF: AMM 27-03-01, AMM 27-03-01 |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |              |                                                           |                |          |                        |           |            |               |                  |
| 27-03-01-002                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP            |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS          | 29-Apr-15                                                 |                |          |                        |           |            |               |                  |
|                                                                            | HRS          | 0                                                         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL          | 0                                                         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |              |                                                           |                |          |                        |           |            |               | PKG:50           |
| 27-03-01-003                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER     |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS          | 29-Apr-15                                                 |                |          |                        |           |            |               |                  |
|                                                                            | HRS          | 0                                                         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL          | 0                                                         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |              |                                                           |                |          |                        |           |            |               | PKG:50           |
| 27-03-01-004                                                               |              | OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR     |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS          | 29-Apr-15                                                 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS          | 0                                                         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |                  |
|                                                                            | AFL          | 0                                                         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |              |                                                           |                |          |                        |           |            |               |                  |
| 27-04-01                                                                   |              | TRIM ACTUATOR CONTROLLER                                  |                |          |                        |           |            |               | Component ATA:27 |
| PN:475200-1009                                                             | MOS/MSC      | 29-Apr-15                                                 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:0342                                                                    | HRS          | 0                                                         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL          | 0                                                         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-04-01, AMM 27-04-01PROC. REF: AMM 27-04-01, AMM 27-04-01 |              |                                                           |                |          |                        |           |            |               |                  |
| 27-04-01-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS          | 29-Apr-15                                                 |                |          |                        |           |            |               |                  |
|                                                                            | HRS          | 0                                                         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL          | 0                                                         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01                             |              |                                                           |                |          |                        |           |            |               | PKG:50           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                         | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------|----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-04-01-002                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP                     |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 29-Apr-15                                                                   |                |          |                        |           |              |             |                  |
|                                                                            | HRS          | 0                                                                           | 5600 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                           |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01                             |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-11-00                                                                   |              | AILERON CABLES ASSY.                                                        |                |          |                        |           |              |             | Component ATA:27 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                   | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 27-11-02, AMM 27-11-02PROC. REF: AMM 27-11-02, AMM 27-11-02 |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-11-00-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 14-May-25                                                                   | 60 (+1m/-1m)   |          |                        |           |              |             |                  |
|                                                                            | HRS          | 2086.2                                                                      | 3200 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL          | 1243                                                                        |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00                             |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-11-01                                                                   |              | LEFT AILERON                                                                |                |          |                        |           |              |             | Component ATA:27 |
| PN:505-14717-401                                                           | MOS/MSC      | 29-Apr-15                                                                   | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:0000841196                                                              | HRS          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01 |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-11-01                                                                   |              | RIGHT AILERON                                                               |                |          |                        |           |              |             | Component ATA:27 |
| PN:505-14718-401                                                           | MOS/MSC      | 29-Apr-15                                                                   | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:0000841197                                                              | HRS          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                           |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01 |              |                                                                             |                |          |                        |           |              |             |                  |
| 27-11-02-001                                                               |              | FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION                          |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 26-May-21                                                                   | 60 (+1m/-1m)   |          | 26-May-26              | 26-Jun-26 | 344 d (+31)  |             |                  |
|                                                                            | HRS          | 1601.5                                                                      | 3200 (+30/-30) |          | 4801.5                 | 4831.5    | 2701.5 (+30) |             |                  |
|                                                                            | AFL          | 928                                                                         |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |              |                                                                             |                |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                     | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------------------------------------|----------------|----------|------------------------|-----------|------------|---------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |         |                                                                         |                |          |                        |           |            |               |          |
| 27-11-02-001(INITIAL)                                                      |         | FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK |                |          |                        |           |            | Service       | ATA:27   |
|                                                                            | MOS/MSC | 29-Apr-15                                                               | -              |          |                        |           |            |               |          |
|                                                                            | HRS     | 0                                                                       |                |          |                        |           |            |               |          |
|                                                                            | AFL     | 0                                                                       |                |          |                        |           |            |               |          |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |         |                                                                         |                |          |                        |           |            |               |          |
| 27-11-02-002 <sup>S</sup>                                                  |         | DETAILED INSPECTION OF AILERON CONTROL CABLES                           |                |          |                        |           |            | Service       | ATA:27   |
|                                                                            | MOS     | 14-May-25                                                               | 60 (+1m/-1m)   |          |                        |           |            |               |          |
|                                                                            | HRS     | 2086.2                                                                  | 3200 (+30/-30) |          |                        |           |            |               |          |
|                                                                            | AFL     | 1243                                                                    |                |          |                        |           |            |               |          |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |         |                                                                         |                |          |                        |           |            |               |          |
| 27-14-02-001                                                               |         | FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY                    |                |          |                        |           |            | Service       | ATA:27   |
|                                                                            | MOS     | 29-Apr-15                                                               |                |          |                        |           |            | AIRWORTHINESS |          |
|                                                                            | HRS     | 0                                                                       | 6000 (+30/-30) |          | 6000                   | 6030      | 3900 (+30) |               |          |
|                                                                            | AFL     | 0                                                                       |                |          |                        |           |            |               |          |
| PROC. REF: AMM 27-14-03PROC. REF: AMM 27-14-03                             |         |                                                                         |                |          |                        |           |            |               |          |
| 27-14-02-002                                                               |         | DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM                    |                |          |                        |           |            | Service       | ATA:27   |
|                                                                            | MOS     | 29-Apr-15                                                               |                |          |                        |           |            | AIRWORTHINESS |          |
|                                                                            | HRS     | 0                                                                       | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |          |
|                                                                            | AFL     | 0                                                                       |                |          |                        |           |            |               |          |
| PROC. REF: AMM 27-14-02PROC. REF: AMM 27-14-02                             |         |                                                                         |                |          |                        |           |            |               |          |
| 27-14-03                                                                   |         | LEFT AILERON TAB                                                        |                |          |                        |           |            | Component     | ATA:27   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                                               | O/C            | TSN 0    |                        |           |            |               |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                       |                | TSN 0    |                        |           |            |               |          |
|                                                                            | AFL     | 0                                                                       |                | TSN 0    |                        |           |            |               |          |
| PROC. REF: AMM 27-14-03, AMM 27-14-03PROC. REF: AMM 27-14-03, AMM 27-14-03 |         |                                                                         |                |          |                        |           |            |               |          |
| 27-21-00                                                                   |         | RUDDER CABLES ASSY.                                                     |                |          |                        |           |            | Component     | ATA:27   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                                               | O/C            | TSN 0    |                        |           |            |               |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                       |                | TSN 0    |                        |           |            |               |          |
|                                                                            | AFL     | 0                                                                       |                | TSN 0    |                        |           |            |               |          |
| PROC. REF: AMM 27-21-02, AMM 27-21-02PROC. REF: AMM 27-21-02, AMM 27-21-02 |         |                                                                         |                |          |                        |           |            |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                        | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------------------------------|----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-21-00-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 14-May-25                                                                  | 60 (+1m/-1m)   |          |                        |           |              |             |                  |
|                                                                            | HRS          | 2086.2                                                                     | 3200 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL          | 1243                                                                       |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-21-00PROC. REF: AMM 27-21-00                             |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-21-01                                                                   |              | RUDDER ASSEMBLY                                                            |                |          |                        |           |              |             | Component ATA:27 |
| PN:505-39084-413                                                           | MOS/MSC      | 29-Apr-15                                                                  | O/C            | TSN 0    |                        |           |              |             |                  |
| SN:0000841194                                                              | HRS          | 0                                                                          |                | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                          |                | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 27-21-01, AMM 27-21-01PROC. REF: AMM 27-21-01, AMM 27-21-01 |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-21-02-001                                                               |              | FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION                          |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 26-May-21                                                                  | 60 (+1m/-1m)   |          | 26-May-26              | 26-Jun-26 | 344 d (+31)  |             |                  |
|                                                                            | HRS          | 1601.5                                                                     | 3200 (+30/-30) |          | 4801.5                 | 4831.5    | 2701.5 (+30) |             |                  |
|                                                                            | AFL          | 928                                                                        |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02                             |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-21-02-001(INITIAL)                                                      |              | FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK   |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS/MSC      | 29-Apr-15                                                                  | -              |          |                        |           |              |             |                  |
|                                                                            | HRS          | 0                                                                          |                |          |                        |           |              |             |                  |
|                                                                            | AFL          | 0                                                                          |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02                             |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-21-02-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF RUDDER CONTROL CABLES                               |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 14-May-25                                                                  | 60 (+1m/-1m)   |          |                        |           |              |             |                  |
|                                                                            | HRS          | 2086.2                                                                     | 3200 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL          | 1243                                                                       |                |          |                        |           |              |             |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02                             |              |                                                                            |                |          |                        |           |              |             |                  |
| 27-23-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM                     |                |          |                        |           |              |             | Service ATA:27   |
|                                                                            | MOS          | 28-Dec-18                                                                  |                |          |                        |           |              |             |                  |
|                                                                            | HRS          | 1178.1                                                                     | 1600 (+30/-30) |          |                        |           |              |             |                  |
|                                                                            | AFL          | 679                                                                        |                |          |                        |           |              |             |                  |

PKG:42

PKG:42

PKG:10

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                         | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                              |           |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-23-00PROC. REF: AMM 27-23-00                             |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-24-02-001                                                               | FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH                                     |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                                          | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                                          | 0         | 6000 (+30/-30) |          | 6000                   | 6030      | 3900 (+30) |               |                  |
|                                                                            | AFL                                                                          | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-24-03PROC. REF: AMM 27-24-03                             |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-24-02-002                                                               | DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM                          |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                                          | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                                          | 0         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |                  |
|                                                                            | AFL                                                                          | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-24-02PROC. REF: AMM 27-24-02                             |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-24-03                                                                   | RUDDER TRIM TAB                                                              |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:505-10450-409                                                           | MOS/MSC                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:0000839621                                                              | HRS                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-24-03, AMM 27-24-03PROC. REF: AMM 27-24-03, AMM 27-24-03 |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-26-01                                                                   | VENTRAL RUDDER                                                               |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:505-07540-417                                                           | MOS/MSC                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:0000838744                                                              | HRS                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-26-01, AMM 27-26-01PROC. REF: AMM 27-26-01, AMM 27-26-01 |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-31-00                                                                   | ELEVATOR CABLES ASSY                                                         |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:PN                                                                      | MOS/MSC                                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:UNKNOWN                                                                 | HRS                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                                                          | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-31-02, AMM 27-31-02PROC. REF: AMM 27-31-02, AMM 27-31-02 |                                                                              |           |                |          |                        |           |            |               |                  |
| 27-31-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                                          | 14-May-25 | 60 (+1m/-1m)   |          |                        |           |            |               |                  |
|                                                                            | HRS                                                                          | 2086.2    | 3200 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL                                                                          | 1243      |                |          |                        |           |            |               |                  |

PKG:42

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 27 - FLIGHT CONTROLS

PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00

| 27-31-01                                                                   | LEFT ELEVATOR |           |     |       |  |  |  | Component | ATA:27 |
|----------------------------------------------------------------------------|---------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:505-11082-401                                                           | MOS/MSC       | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000841185                                                              | HRS           | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL           | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-31-01, AMM 27-31-01PROC. REF: AMM 27-31-01, AMM 27-31-01 |               |           |     |       |  |  |  |           |        |

| 27-31-01                                                                   | RIGHT ELEVATOR |           |     |       |  |  |  | Component | ATA:27 |
|----------------------------------------------------------------------------|----------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:505-11082-402                                                           | MOS/MSC        | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000841187                                                              | HRS            | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL            | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-31-01, AMM 27-31-01PROC. REF: AMM 27-31-01, AMM 27-31-01 |                |           |     |       |  |  |  |           |        |

| 27-31-02-001                                   | FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION |           |                |           |           |              | Service | ATA:27 |
|------------------------------------------------|-----------------------------------------------------|-----------|----------------|-----------|-----------|--------------|---------|--------|
|                                                | MOS                                                 | 26-May-21 | 60 (+1m/-1m)   | 26-May-26 | 26-Jun-26 | 344 d (+31)  |         |        |
|                                                | HRS                                                 | 1601.5    | 3200 (+30/-30) | 4801.5    | 4831.5    | 2701.5 (+30) |         |        |
|                                                | AFL                                                 | 928       |                |           |           |              |         |        |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02 |                                                     |           |                |           |           |              |         |        |

| 27-31-02-001(INITIAL)                          | FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK |           |   | Service | ATA:27 |
|------------------------------------------------|----------------------------------------------------------------------------|-----------|---|---------|--------|
|                                                | MOS/MSC                                                                    | 29-Apr-15 | - |         |        |
|                                                | HRS                                                                        | 0         |   |         |        |
|                                                | AFL                                                                        | 0         |   |         |        |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02 |                                                                            |           |   |         |        |

| 27-31-02-002 <sup>S</sup>                      | DETAILED INSPECTION OF ELEVATOR CONTROL CABLES |           |                |  |  |  | Service | ATA:27 |
|------------------------------------------------|------------------------------------------------|-----------|----------------|--|--|--|---------|--------|
|                                                | MOS                                            | 14-May-25 | 60 (+1m/-1m)   |  |  |  |         |        |
|                                                | HRS                                            | 2086.2    | 3200 (+30/-30) |  |  |  |         |        |
|                                                | AFL                                            | 1243      |                |  |  |  |         |        |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02 |                                                |           |                |  |  |  |         |        |

PKG:42

| 27-31-03         | LEFT ELEVATOR TAB |           |     |       |  |  |  | Component | ATA:27 |
|------------------|-------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:505-11084-401 | MOS/MSC           | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000840878    | HRS               | 0         |     | TSN 0 |  |  |  |           |        |
|                  | AFL               | 0         |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                               | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                    |           |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-31-03, AMM 27-31-03PROC. REF: AMM 27-31-03, AMM 27-31-03 |                                                    |           |                |          |                        |           |            |               |                  |
|                                                                            |                                                    |           |                |          |                        |           |            |               |                  |
| 27-31-03                                                                   | RIGHT ELEVATOR TAB                                 |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:505-11084-402                                                           | MOS/MSC                                            | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:0000839351                                                              | HRS                                                | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                                | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-31-03, AMM 27-31-03PROC. REF: AMM 27-31-03, AMM 27-31-03 |                                                    |           |                |          |                        |           |            |               |                  |
|                                                                            |                                                    |           |                |          |                        |           |            |               |                  |
| 27-31-03-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH    |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                | 29-Apr-15 |                |          |                        |           |            |               |                  |
|                                                                            | HRS                                                | 0         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL                                                | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03                             |                                                    |           |                |          |                        |           |            |               |                  |
|                                                                            |                                                    |           |                |          |                        |           |            |               |                  |
| 27-31-03-002 <sup>S</sup>                                                  | DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                | 29-Apr-15 |                |          |                        |           |            |               |                  |
|                                                                            | HRS                                                | 0         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL                                                | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03                             |                                                    |           |                |          |                        |           |            |               |                  |
|                                                                            |                                                    |           |                |          |                        |           |            |               |                  |
| 27-36-03-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH          |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                | 01-May-19 |                |          |                        |           |            |               |                  |
|                                                                            | HRS                                                | 1230      | 1600 (+30/-30) |          |                        |           |            |               |                  |
|                                                                            | AFL                                                | 711       |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-36-03PROC. REF: AMM 27-36-03                             |                                                    |           |                |          |                        |           |            |               |                  |
|                                                                            |                                                    |           |                |          |                        |           |            |               |                  |
| 27-41-01-001                                                               | DETAILED INSPECTION OF PITCH TRIM ACTUATOR         |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                | 0         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |                  |
|                                                                            | AFL                                                | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01                             |                                                    |           |                |          |                        |           |            |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                                    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|------------------------------------------------|---------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |                                                         |           |                |          |                        |           |            |               |                  |
| 27-41-01-002                                   | FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH        |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                | MOS                                                     | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                | HRS                                                     | 0         | 6000 (+30/-30) |          | 6000                   | 6030      | 3900 (+30) |               |                  |
|                                                | AFL                                                     | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00 |                                                         |           |                |          |                        |           |            |               |                  |
| 27-41-01-003 <sup>S</sup>                      | LUBRICATION OF PITCH TRIM ACTUATOR                      |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                | MOS                                                     | 24-Apr-23 | 48 (+1m/-1m)   |          |                        |           |            |               |                  |
|                                                | HRS                                                     | 1825.5    |                |          |                        |           |            |               |                  |
|                                                | AFL                                                     | 1042      |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |                                                         |           |                |          |                        |           |            |               |                  |
| 27-41-01-004                                   | OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK       |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                | MOS                                                     | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                | HRS                                                     | 0         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |                  |
|                                                | AFL                                                     | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01 |                                                         |           |                |          |                        |           |            |               |                  |
| 27-41-01-005 <sup>S</sup>                      | SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES             |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                | MOS                                                     | 24-Apr-23 | 48 (+1m/-1m)   |          |                        |           |            |               |                  |
|                                                | HRS                                                     | 1825.5    |                |          |                        |           |            |               |                  |
|                                                | AFL                                                     | 1042      |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 12-18-00PROC. REF: AMM 12-18-00 |                                                         |           |                |          |                        |           |            |               |                  |
| 27-41-01-006 <sup>S</sup>                      | FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                | MOS                                                     | 29-Apr-15 |                |          |                        |           |            |               |                  |
|                                                | HRS                                                     | 0         | 5600 (+30/-30) |          |                        |           |            |               |                  |
|                                                | AFL                                                     | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01 |                                                         |           |                |          |                        |           |            |               |                  |
| 27-43-02                                       | COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL               |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:PN                                          | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:UNKNOWN                                     | HRS                                                     | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                | AFL                                                     | 0         |                | TSN 0    |                        |           |            |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                       | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty       |
|--------------------------------------------------------------|----------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|----------------|
| ATA 27 - FLIGHT CONTROLS                                     |                                                                            |           |                |          |                        |           |            |               |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                            |           |                |          |                        |           |            |               |                |
| 27-50-01-01-901                                              | DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL |           |                |          |                        |           |            |               | Service ATA:27 |
|                                                              | MOS                                                                        | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                |
|                                                              | HRS                                                                        | 0         | T:17500        |          | 17500                  |           | 15400      |               |                |
|                                                              | AFL                                                                        | 0         | T:14000        |          | 14000                  |           | 12748      |               |                |
| PROC. REF: NDT PART 5 27-51-00PROC. REF: NDT PART 5 27-51-00 |                                                                            |           |                |          |                        |           |            |               |                |
| 27-51-01-001 <sup>S</sup>                                    | LUBRICATION OF FLAP ACTUATORS BALL SCREWS                                  |           |                |          |                        |           |            |               | Service ATA:27 |
|                                                              | MOS                                                                        | 24-Apr-23 | 48 (+1m/-1m)   |          |                        |           |            |               |                |
|                                                              | HRS                                                                        | 1825.5    |                |          |                        |           |            |               |                |
|                                                              | AFL                                                                        | 1042      |                |          |                        |           |            |               |                |
|                                                              |                                                                            |           |                |          |                        |           |            |               | PKG:83         |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00               |                                                                            |           |                |          |                        |           |            |               |                |
| 27-51-01-002                                                 | DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR                       |           |                |          |                        |           |            |               | Service ATA:27 |
|                                                              | MOS                                                                        | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                |
|                                                              | HRS                                                                        | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                |
|                                                              | AFL                                                                        | 0         |                |          |                        |           |            |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01               |                                                                            |           |                |          |                        |           |            |               |                |
| 27-51-01-002                                                 | DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR                      |           |                |          |                        |           |            |               | Service ATA:27 |
|                                                              | MOS                                                                        | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                |
|                                                              | HRS                                                                        | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                |
|                                                              | AFL                                                                        | 0         |                |          |                        |           |            |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01               |                                                                            |           |                |          |                        |           |            |               |                |
| 27-51-01-002                                                 | DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR                      |           |                |          |                        |           |            |               | Service ATA:27 |
|                                                              | MOS                                                                        | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                |
|                                                              | HRS                                                                        | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                |
|                                                              | AFL                                                                        | 0         |                |          |                        |           |            |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01               |                                                                            |           |                |          |                        |           |            |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                   | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-002                                                               | DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR  |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                    | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                  |
|                                                                            | AFL                                                    | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01                             |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-002                                                               | DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                    | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                  |
|                                                                            | AFL                                                    | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01                             |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-002                                                               | DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                    | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                  |
|                                                                            | AFL                                                    | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01                             |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-004                                                               | FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER       |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                    | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                   | 7230      | 5100 (+30) |               |                  |
|                                                                            | AFL                                                    | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01                             |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-005 <sup>S</sup>                                                  | SERVICING OF FLAP ACTUATOR GEAR BOXES                  |           |                |          |                        |           |            |               | Service ATA:27   |
|                                                                            | MOS                                                    | 24-Apr-23 | 48 (+1m/-1m)   |          |                        |           |            |               |                  |
|                                                                            | HRS                                                    | 1825.5    |                |          |                        |           |            |               |                  |
|                                                                            | AFL                                                    | 1042      |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 12-18-00PROC. REF: AMM 12-18-00                             |                                                        |           |                |          |                        |           |            |               |                  |
| 27-51-01-900-801-01                                                        | LEFT NO. 3 OUTBOARD FLAP ACTUATOR                      |           |                |          |                        |           |            |               | Component ATA:27 |
| PN:475100-1013                                                             | MOS/MSC                                                | 29-Apr-15 | H/T            | TSN 0    |                        |           |            |               |                  |
| SN:0599                                                                    | HRS                                                    | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                                    | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                                        |           |                |          |                        |           |            |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit    | C/W                                | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|---------|------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                                                                           |         |                                    |          |          |                        |           |           |             |          |
| 27-51-01-900-801-02                                                                                                                |         | RIGHT NO. 3 OUTBOARD FLAP ACTUATOR |          |          |                        |           |           | Component   | ATA:27   |
| PN:475100-1013                                                                                                                     | MOS/MSC | 29-Apr-15                          | H/T      | TSN 0    |                        |           |           |             |          |
| SN:0024                                                                                                                            | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                    |          |          |                        |           |           |             |          |
| 27-51-01-900-801-03                                                                                                                |         | LEFT NO. 2 OUTBOARD FLAP ACTUATOR  |          |          |                        |           |           | Component   | ATA:27   |
| PN:475000-2013                                                                                                                     | MOS/MSC | 29-Apr-15                          | H/T      | TSN 0    |                        |           |           |             |          |
| SN:1173                                                                                                                            | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                    |          |          |                        |           |           |             |          |
| 27-51-01-900-801-04                                                                                                                |         | RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |          |          |                        |           |           | Component   | ATA:27   |
| PN:475000-2013                                                                                                                     | MOS/MSC | 29-Apr-15                          | H/T      | TSN 0    |                        |           |           |             |          |
| SN:1182                                                                                                                            | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                    |          |          |                        |           |           |             |          |
| 27-51-01-900-801-05                                                                                                                |         | LEFT NO. 1 INBOARD FLAP ACTUATOR   |          |          |                        |           |           | Component   | ATA:27   |
| PN:475000-1013                                                                                                                     | MOS/MSC | 29-Apr-15                          | H/T      | TSN 0    |                        |           |           |             |          |
| SN:1178                                                                                                                            | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                    |          |          |                        |           |           |             |          |
| 27-51-01-900-801-06                                                                                                                |         | RIGHT NO. 1 INBOARD FLAP ACTUATOR  |          |          |                        |           |           | Component   | ATA:27   |
| PN:475000-1013                                                                                                                     | MOS/MSC | 29-Apr-15                          | H/T      | TSN 0    |                        |           |           |             |          |
| SN:1186                                                                                                                            | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                    |          |          |                        |           |           |             |          |
| 27-51-05                                                                                                                           |         | LEFT INBOARD FLAP                  |          |          |                        |           |           | Component   | ATA:27   |
| PN:505-14358-401                                                                                                                   | MOS/MSC | 29-Apr-15                          | O/C      | TSN 0    |                        |           |           |             |          |
| SN:0000842001                                                                                                                      | HRS     | 0                                  |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0                                  |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |         |                                    |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 27 - FLIGHT CONTROLS

|                                                                                                                                    |                    |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 27-51-05                                                                                                                           | LEFT OUTBOARD FLAP |           |     |       |  |  |  | Component | ATA:27 |
| PN:505-14359-401                                                                                                                   | MOS/MSC            | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000841952                                                                                                                      | HRS                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                                                                                    | AFL                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |                    |           |     |       |  |  |  |           |        |

|                                                                                                                                    |                    |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 27-51-05                                                                                                                           | RIGHT INBOARD FLAP |           |     |       |  |  |  | Component | ATA:27 |
| PN:505-14358-402                                                                                                                   | MOS/MSC            | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000841954                                                                                                                      | HRS                | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                                                                                    | AFL                | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |                    |           |     |       |  |  |  |           |        |

|                                                                                                                                    |                     |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 27-51-05                                                                                                                           | RIGHT OUTBOARD FLAP |           |     |       |  |  |  | Component | ATA:27 |
| PN:505-14359-402                                                                                                                   | MOS/MSC             | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:0000841468                                                                                                                      | HRS                 | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                                                                                    | AFL                 | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |                     |           |     |       |  |  |  |           |        |

|                                                |                                             |           |              |  |  |  |  |         |        |
|------------------------------------------------|---------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 27-51-06-001 <sup>S</sup>                      | LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT |           |              |  |  |  |  | Service | ATA:27 |
|                                                | MOS                                         | 24-Apr-23 | 48 (+1m/-1m) |  |  |  |  |         |        |
|                                                | HRS                                         | 1825.5    |              |  |  |  |  |         |        |
|                                                | AFL                                         | 1042      |              |  |  |  |  |         |        |
|                                                |                                             |           |              |  |  |  |  |         | PKG:83 |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |                                             |           |              |  |  |  |  |         |        |

|                                                |                                               |           |              |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 27-51-06-001 <sup>S</sup>                      | LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT |           |              |  |  |  |  | Service | ATA:27 |
|                                                | MOS                                           | 24-Apr-23 | 48 (+1m/-1m) |  |  |  |  |         |        |
|                                                | HRS                                           | 1825.5    |              |  |  |  |  |         |        |
|                                                | AFL                                           | 1042      |              |  |  |  |  |         |        |
|                                                |                                               |           |              |  |  |  |  |         | PKG:83 |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |                                               |           |              |  |  |  |  |         |        |

|                                                |                                            |           |              |  |  |  |  |         |        |
|------------------------------------------------|--------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 27-51-06-001 <sup>S</sup>                      | LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT |           |              |  |  |  |  | Service | ATA:27 |
|                                                | MOS                                        | 24-Apr-23 | 48 (+1m/-1m) |  |  |  |  |         |        |
|                                                | HRS                                        | 1825.5    |              |  |  |  |  |         |        |
|                                                | AFL                                        | 1042      |              |  |  |  |  |         |        |
|                                                |                                            |           |              |  |  |  |  |         | PKG:83 |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |                                            |           |              |  |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                          | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------|--------------|--------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                       |              |                                                              |              |          |                        |           |           |             |          |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT                   |              |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS          | 24-Apr-23                                                    | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                | HRS          | 1825.5                                                       |              |          |                        |           |           |             |          |
|                                                | AFL          | 1042                                                         |              |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                                              |              |          |                        |           |           |             | PKG:83   |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT                 |              |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS          | 24-Apr-23                                                    | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                | HRS          | 1825.5                                                       |              |          |                        |           |           |             |          |
|                                                | AFL          | 1042                                                         |              |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                                              |              |          |                        |           |           |             | PKG:83   |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT               |              |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS          | 24-Apr-23                                                    | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                | HRS          | 1825.5                                                       |              |          |                        |           |           |             |          |
|                                                | AFL          | 1042                                                         |              |          |                        |           |           |             |          |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                                              |              |          |                        |           |           |             | PKG:83   |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT   |              |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS          | 24-Apr-23                                                    | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                | HRS          | 1825.5                                                       |              |          |                        |           |           |             |          |
|                                                | AFL          | 1042                                                         |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                        |           |           |             | PKG:83   |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT |              |          |                        |           |           | Service     | ATA:27   |
|                                                | MOS          | 24-Apr-23                                                    | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                | HRS          | 1825.5                                                       |              |          |                        |           |           |             |          |
|                                                | AFL          | 1042                                                         |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                        |           |           |             | PKG:83   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                           | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT     |              |          |                        |           |           | Service     | ATA:27   |
|                                                                            | MOS     | 24-Apr-23                                                     | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS     | 1825.5                                                        |              |          |                        |           |           |             |          |
|                                                                            | AFL     | 1042                                                          |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                        |           |           |             | PKG:83   |
|                                                                            |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT     |              |          |                        |           |           | Service     | ATA:27   |
|                                                                            | MOS     | 24-Apr-23                                                     | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS     | 1825.5                                                        |              |          |                        |           |           |             |          |
|                                                                            | AFL     | 1042                                                          |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                        |           |           |             | PKG:83   |
|                                                                            |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT   |              |          |                        |           |           | Service     | ATA:27   |
|                                                                            | MOS     | 24-Apr-23                                                     | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS     | 1825.5                                                        |              |          |                        |           |           |             |          |
|                                                                            | AFL     | 1042                                                          |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                        |           |           |             | PKG:83   |
|                                                                            |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT |              |          |                        |           |           | Service     | ATA:27   |
|                                                                            | MOS     | 24-Apr-23                                                     | 48 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS     | 1825.5                                                        |              |          |                        |           |           |             |          |
|                                                                            | AFL     | 1042                                                          |              |          |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                        |           |           |             | PKG:83   |
|                                                                            |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-900-801-01                                                        |         | RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT                          |              |          |                        |           |           | Component   | ATA:27   |
| PN:457360-1005                                                             | MOS/MSC | 29-Apr-15                                                     | H/T          | TSN 0    |                        |           |           |             |          |
| SN:SSW1165                                                                 | HRS     | 0                                                             |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                             |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |         |                                                               |              |          |                        |           |           |             |          |
|                                                                            |         |                                                               |              |          |                        |           |           |             |          |
| 27-51-06-900-801-02                                                        |         | RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT                           |              |          |                        |           |           | Component   | ATA:27   |
| PN:457360-1005                                                             | MOS/MSC | 29-Apr-15                                                     | H/T          | TSN 0    |                        |           |           |             |          |
| SN:SSW1157                                                                 | HRS     | 0                                                             |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                             |              | TSN 0    |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                               | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|---------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                                                                              |         |           |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06                                                            |         |           |          |          |                        |           |           |               |          |
| 27-51-06-900-801-03 LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT                                                                               |         |           |          |          |                        |           |           | Component     | ATA:27   |
| PN:457360-1005                                                                                                                        | MOS/MSC | 29-Apr-15 | H/T      | TSN 0    |                        |           |           |               |          |
| SN:SSW1156                                                                                                                            | HRS     | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                                                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06                                                            |         |           |          |          |                        |           |           |               |          |
| 27-51-06-900-801-04 LEFT INBOARD FLAP FLEXIBLE 1 SHAFT                                                                                |         |           |          |          |                        |           |           | Component     | ATA:27   |
| PN:457360-1005                                                                                                                        | MOS/MSC | 29-Apr-15 | H/T      | TSN 0    |                        |           |           |               |          |
| SN:SSW1151                                                                                                                            | HRS     | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                                                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06                                                            |         |           |          |          |                        |           |           |               |          |
| 27-51-06-900-801-05 LEFT CENTER FLAP FLEXIBLE 2 SHAFT                                                                                 |         |           |          |          |                        |           |           | Component     | ATA:27   |
| PN:457360-1007                                                                                                                        | MOS/MSC | 29-Apr-15 | H/T      | TSN 0    |                        |           |           |               |          |
| SN:SSW0570                                                                                                                            | HRS     | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                                                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06                                                            |         |           |          |          |                        |           |           |               |          |
| 27-51-06-900-801-06 RIGHT CENTER FLAP FLEXIBLE 2 SHAFT                                                                                |         |           |          |          |                        |           |           | Component     | ATA:27   |
| PN:457360-1007                                                                                                                        | MOS/MSC | 29-Apr-15 | H/T      | TSN 0    |                        |           |           |               |          |
| SN:SSW0581                                                                                                                            | HRS     | 0         |          | TSN 0    |                        |           |           |               |          |
|                                                                                                                                       | AFL     | 0         |          | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06                                                            |         |           |          |          |                        |           |           |               |          |
| 27-53-01 FLAP SELECTOR, PRODUCTION, LEVER                                                                                             |         |           |          |          |                        |           |           | Component     | ATA:27   |
| PN:780501-9                                                                                                                           | MOS/MSC | 29-Apr-24 | O/C      |          |                        |           |           |               |          |
| SN:3065                                                                                                                               | HRS     | 1952.5    |          |          |                        |           |           |               |          |
|                                                                                                                                       | AFL     | 1160      |          |          |                        |           |           |               |          |
| PROC. REF: AMM 27-53-01, AMM 27-53-01PROC. REF: AMM 27-53-01, AMM 27-53-01                                                            |         |           |          |          |                        |           |           |               |          |
| 27-64-01-01-901 SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS-INTERNAL |         |           |          |          |                        |           |           | Service       | ATA:27   |
|                                                                                                                                       | MOS     | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                                                       | HRS     | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                                                                                                       | AFL     | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                                           | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                                                                                |           |                |          |                        |           |           |               |          |
| PROC. REF: NDT PART 6 27-64-00PROC. REF: NDT PART 6 27-64-00               |                                                                                                                                |           |                |          |                        |           |           |               |          |
| 27-64-01-01-902                                                            | DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL                        |           |                |          |                        |           |           | Service       | ATA:27   |
|                                                                            | MOS                                                                                                                            | 29-Apr-15 |                |          |                        |           |           | AIRWORTHINESS |          |
|                                                                            | HRS                                                                                                                            | 0         | T:17500        |          | 17500                  |           | 15400     |               |          |
|                                                                            | AFL                                                                                                                            | 0         | T:14000        |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 27-64-00PROC. REF: NDT PART 5 27-64-00               |                                                                                                                                |           |                |          |                        |           |           |               |          |
| 27-64-01-02-901                                                            | SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL |           |                |          |                        |           |           | Service       | ATA:27   |
|                                                                            | MOS                                                                                                                            | 29-Apr-15 |                |          |                        |           |           | AIRWORTHINESS |          |
|                                                                            | HRS                                                                                                                            | 0         | T:17500        |          | 17500                  |           | 15400     |               |          |
|                                                                            | AFL                                                                                                                            | 0         | T:14000        |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 7 27-64-00PROC. REF: NDT PART 7 27-64-00               |                                                                                                                                |           |                |          |                        |           |           |               |          |
| 27-65-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM                                                                               |           |                |          |                        |           |           | Service       | ATA:27   |
|                                                                            | MOS                                                                                                                            | 29-Apr-15 |                |          |                        |           |           |               |          |
|                                                                            | HRS                                                                                                                            | 0         | 6400 (+30/-30) |          |                        |           |           |               |          |
|                                                                            | AFL                                                                                                                            | 0         |                |          |                        |           |           |               |          |
|                                                                            |                                                                                                                                |           |                |          |                        |           |           |               | PKG:60   |
| PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00                             |                                                                                                                                |           |                |          |                        |           |           |               |          |
| 27-65-01-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)                                                    |           |                |          |                        |           |           | Service       | ATA:27   |
|                                                                            | MOS                                                                                                                            | 29-Apr-15 |                |          |                        |           |           |               |          |
|                                                                            | HRS                                                                                                                            | 0         | 6400 (+30/-30) |          |                        |           |           |               |          |
|                                                                            | AFL                                                                                                                            | 0         |                |          |                        |           |           |               |          |
|                                                                            |                                                                                                                                |           |                |          |                        |           |           |               | PKG:60   |
| PROC. REF: AMM 27-65-00PROC. REF: AMM 27-65-00                             |                                                                                                                                |           |                |          |                        |           |           |               |          |
| 27-66-01                                                                   | NO. 1 CONTROL WHEEL POSITION SENSOR                                                                                            |           |                |          |                        |           |           | Component     | ATA:27   |
| PN:456896-1001                                                             | MOS/MSC                                                                                                                        | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |               |          |
| SN:134359                                                                  | HRS                                                                                                                            | 0         |                | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                                                            | 0         |                | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 27-66-01, AMM 27-66-01PROC. REF: AMM 27-66-01, AMM 27-66-01 |                                                                                                                                |           |                |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                   |           |              |          |                        |           |           |             |          |
| 27-66-01                                                                   | NO. 2 CONTROL WHEEL POSITION SENSOR               |           |              |          |                        |           |           | Component   | ATA:27   |
| PN:456896-1001                                                             | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:134360                                                                  | HRS                                               | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-66-01, AMM 27-66-01PROC. REF: AMM 27-66-01, AMM 27-66-01 |                                                   |           |              |          |                        |           |           |             |          |
| 27-66-02                                                                   | LEFT SPOILER SURFACE POSITION SENSOR              |           |              |          |                        |           |           | Component   | ATA:27   |
| PN:456897-1001                                                             | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:136638                                                                  | HRS                                               | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-66-02, AMM 27-66-02PROC. REF: AMM 27-66-02, AMM 27-66-02 |                                                   |           |              |          |                        |           |           |             |          |
| 27-66-02                                                                   | RIGHT SPOILER SURFACE POSITION SENSOR             |           |              |          |                        |           |           | Component   | ATA:27   |
| PN:456897-1001                                                             | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:136640                                                                  | HRS                                               | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 27-66-02, AMM 27-66-02PROC. REF: AMM 27-66-02, AMM 27-66-02 |                                                   |           |              |          |                        |           |           |             |          |
| ATA 28 - FUEL                                                              |                                                   |           |              |          |                        |           |           |             |          |
| 28-11-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS |           |              |          |                        |           |           | Service     | ATA:28   |
|                                                                            | MOS                                               | 14-May-25 | 12 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                            | HRS                                               | 2086.2    |              |          |                        |           |           |             |          |
|                                                                            | AFL                                               | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00                             |                                                   |           |              |          |                        |           |           |             |          |
| 28-11-05                                                                   | LEFT WING WATER DRAIN VALVE                       |           |              |          |                        |           |           | Component   | ATA:28   |
| PN:L83A13-628                                                              | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:J00290                                                                  | HRS                                               | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05 |                                                   |           |              |          |                        |           |           |             |          |
| 28-11-05                                                                   | RIGHT WING WATER DRAIN VALVE                      |           |              |          |                        |           |           | Component   | ATA:28   |
| PN:L83A13-628                                                              | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:J00280                                                                  | HRS                                               | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05 |                                                   |           |              |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                                              |                                               |           |                |          |                        |           |           |             |                  |
| 28-11-07                                                                   | LEFT WING DUMP VALVE                          |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:V98A32-001                                                              | MOS/MSC                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J12614                                                                  | HRS                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07 |                                               |           |                |          |                        |           |           |             |                  |
| 28-11-07                                                                   | RIGHT WING DUMP VALVE                         |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:V98A32-001                                                              | MOS/MSC                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J12620                                                                  | HRS                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07 |                                               |           |                |          |                        |           |           |             |                  |
| 28-12-01-001 <sup>S</sup>                                                  | SPECIAL DETAILED INSPECTION OF FUEL VENT NACA |           |                |          |                        |           |           |             | Service ATA:28   |
|                                                                            | MOS                                           | 29-Apr-24 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                           | 1952.5    | 800 (+30/-30)  |          |                        |           |           |             |                  |
|                                                                            | AFL                                           | 1160      |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01                             |                                               |           |                |          |                        |           |           |             |                  |
| 28-12-03                                                                   | LEFT FUEL TANK FLOAT VENT VALVE               |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:L87-19-001P2                                                            | MOS/MSC                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J02378                                                                  | HRS                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03, AMM 28-12-03PROC. REF: AMM 28-12-03, AMM 28-12-03 |                                               |           |                |          |                        |           |           |             |                  |
| 28-12-03                                                                   | RIGHT FUEL TANK FLOAT VENT VALVE              |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:L87-19-001P2                                                            | MOS/MSC                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J16043                                                                  | HRS                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03, AMM 28-12-03PROC. REF: AMM 28-12-03, AMM 28-12-03 |                                               |           |                |          |                        |           |           |             |                  |
| 28-12-03-001 <sup>S</sup>                                                  | OPERATIONAL CHECK LEFT FLOAT VENT VALVE       |           |                |          |                        |           |           |             | Service ATA:28   |
|                                                                            | MOS                                           | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                           | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03                             |                                               |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                     | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                                              |              |                                                         |                |          |                        |           |           |             |                  |
| 28-12-03-001                                                               | <sup>S</sup> | OPERATIONAL CHECK RIGHT FLOAT VENT VALVE                |                |          |                        |           |           |             | Service ATA:28   |
|                                                                            | MOS          | 29-Apr-15                                               |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                       | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                       |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03                             |              |                                                         |                |          |                        |           |           |             |                  |
| PKG:60                                                                     |              |                                                         |                |          |                        |           |           |             |                  |
| 28-21-01                                                                   |              | LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE  |                |          |                        |           |           |             | Component ATA:28 |
| PN:L96-19-007P4                                                            | MOS/MSC      | 29-Apr-24                                               | O/C            | TSN 15   |                        |           |           |             |                  |
| SN:N40011                                                                  | HRS          | 1952.5                                                  |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 1160                                                    |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01 |              |                                                         |                |          |                        |           |           |             |                  |
| 28-21-01                                                                   |              | RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE |                |          |                        |           |           |             | Component ATA:28 |
| PN:L96-19-007P4                                                            | MOS/MSC      | 29-Apr-24                                               | O/C            | TSN 15   |                        |           |           |             |                  |
| SN:N39992                                                                  | HRS          | 1952.5                                                  |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 1160                                                    |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01 |              |                                                         |                |          |                        |           |           |             |                  |
| 28-21-02                                                                   |              | LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE             |                |          |                        |           |           |             | Component ATA:28 |
| PN:P99C25-606P2                                                            | MOS/MSC      | 29-Apr-15                                               | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:G35760                                                                  | HRS          | 0                                                       |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |              |                                                         |                |          |                        |           |           |             |                  |
| 28-21-02                                                                   |              | RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE            |                |          |                        |           |           |             | Component ATA:28 |
| PN:P99C25-606P2                                                            | MOS/MSC      | 19-Jan-24                                               | O/C            |          |                        |           |           |             |                  |
| SN:F08779                                                                  | HRS          | 1914.3                                                  |                |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1114                                                    |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |              |                                                         |                |          |                        |           |           |             |                  |
| 28-21-03                                                                   |              | LEFT WING DC AUXILIARY BOOST PUMP CANISTER              |                |          |                        |           |           |             | Component ATA:28 |
| PN:C93R25-606P2                                                            | MOS/MSC      | 29-Apr-15                                               | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:G36260                                                                  | HRS          | 0                                                       |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |              |                                                         |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition   | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|---------------|----------|------------------------|-----------|-------------|---------------|------------------|
| ATA 28 - FUEL                                                              |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-03                                                                   | RIGHT WING DC AUXILIARY BOOST PUMP CANISTER   |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:C93R25-606P2                                                            | MOS/MSC                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:G36263                                                                  | HRS                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-05                                                                   | LEFT WING JET PUMP FEED LINE                  |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:T99A19-602                                                              | MOS/MSC                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:G29996                                                                  | HRS                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05 |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-05                                                                   | RIGHT WING JET PUMP FEED LINE                 |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:T99A19-602                                                              | MOS/MSC                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:G29998                                                                  | HRS                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05 |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-07                                                                   | LEFT 0.75 SHUTOFF VALVE                       |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:B97-15-601                                                              | MOS/MSC                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:J08766                                                                  | HRS                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-07                                                                   | RIGHT 0.75 SHUTOFF VALVE                      |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:B97-15-601                                                              | MOS/MSC                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:J08769                                                                  | HRS                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                           | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                               |           |               |          |                        |           |             |               |                  |
| 28-21-07-001                                                               | OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM |           |               |          |                        |           |             |               | Service ATA:28   |
|                                                                            | MOS                                           | 29-Apr-22 |               |          |                        |           |             | AIRWORTHINESS |                  |
|                                                                            | HRS                                           | 1728.6    | 800 (+30/-30) |          | 2528.6                 | 2558.6    | 428.6 (+30) |               |                  |
|                                                                            | AFL                                           | 989       |               |          |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07                             |                                               |           |               |          |                        |           |             |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition   | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-------------|---------------|------------------|
| ATA 28 - FUEL                                                              |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-07-001                                                               | OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM |           |               |          |                        |           |             |               | Service ATA:28   |
|                                                                            | MOS                                            | 29-Apr-22 |               |          |                        |           |             | AIRWORTHINESS |                  |
|                                                                            | HRS                                            | 1728.6    | 800 (+30/-30) |          | 2528.6                 | 2558.6    | 428.6 (+30) |               |                  |
|                                                                            | AFL                                            | 989       |               |          |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07                             |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-08                                                                   | FORWARD LEFT 28 VDC SOV ACTUATOR               |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC                                        | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:C701943                                                                 | HRS                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-08                                                                   | LEFT WING 28 VDC SOV ACTUATOR                  |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC                                        | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:C701945                                                                 | HRS                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-08                                                                   | REAR RIGHT 28 VDC SOV ACTUATOR                 |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC                                        | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:C701956                                                                 | HRS                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-09                                                                   | LEFT WING SCAVENGER JET PUMP                   |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:T99A19-603                                                              | MOS/MSC                                        | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:G27415                                                                  | HRS                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-09, AMM 28-21-09PROC. REF: AMM 28-21-09, AMM 28-21-09 |                                                |           |               |          |                        |           |             |               |                  |
| 28-21-09                                                                   | RIGHT WING SCAVENGER JET PUMP                  |           |               |          |                        |           |             |               | Component ATA:28 |
| PN:T99A19-603                                                              | MOS/MSC                                        | 29-Apr-15 | O/C           | TSN 0    |                        |           |             |               |                  |
| SN:G29726                                                                  | HRS                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                            | 0         |               | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 28-21-09, AMM 28-21-09PROC. REF: AMM 28-21-09, AMM 28-21-09 |                                                |           |               |          |                        |           |             |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                  | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------|-----------|-----------------|----------|------------------------|-----------|------------|-------------|------------------|
| ATA 28 - FUEL                                                              |                                       |           |                 |          |                        |           |            |             |                  |
| 28-21-10                                                                   | 3/4" (CROSSFEED) SHUT OFF VALVE       |           |                 |          |                        |           |            |             | Component ATA:28 |
| PN:B97H19-608P2                                                            | MOS/MSC                               | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:H63066                                                                  | HRS                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 28-21-10, AMM 28-21-10PROC. REF: AMM 28-21-10, AMM 28-21-10 |                                       |           |                 |          |                        |           |            |             |                  |
| 28-21-10-001                                                               | OPERATIONAL CHECK OF FUEL XFEED VALVE |           |                 |          |                        |           |            |             | Service ATA:28   |
|                                                                            | MOS                                   | 29-Apr-15 |                 |          |                        |           |            |             |                  |
|                                                                            | HRS                                   | 0         | 12000 (+30/-30) |          | 12000                  | 12030     | 9900 (+30) |             |                  |
|                                                                            | AFL                                   | 0         |                 |          |                        |           |            |             |                  |
| PROC. REF: AMM 28-21-10PROC. REF: AMM 28-21-10                             |                                       |           |                 |          |                        |           |            |             |                  |
| 28-21-11                                                                   | LEFT WING 1/2 INCH CHECK VALVE VALVE  |           |                 |          |                        |           |            |             | Component ATA:28 |
| PN:L96-13-001                                                              | MOS/MSC                               | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:J12563                                                                  | HRS                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11 |                                       |           |                 |          |                        |           |            |             |                  |
| 28-21-11                                                                   | RIGHT WING 1/2 INCH CHECK VALVE VALVE |           |                 |          |                        |           |            |             | Component ATA:28 |
| PN:L96-13-001                                                              | MOS/MSC                               | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:J12573                                                                  | HRS                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11 |                                       |           |                 |          |                        |           |            |             |                  |
| 28-21-13                                                                   | INSC ILLUM PANEL                      |           |                 |          |                        |           |            |             | Component ATA:28 |
| PN:441-42621-002                                                           | MOS/MSC                               | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:1282                                                                    | HRS                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 28-21-13, AMM 28-21-13PROC. REF: AMM 28-21-13, AMM 28-21-13 |                                       |           |                 |          |                        |           |            |             |                  |
| 28-23-01                                                                   | REFUEL CONTROL PANEL                  |           |                 |          |                        |           |            |             | Component ATA:28 |
| PN:742388-1-2                                                              | MOS/MSC                               | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:742388IN00390                                                           | HRS                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 28-23-01, AMM 28-23-01PROC. REF: AMM 28-23-01, AMM 28-23-01 |                                       |           |                 |          |                        |           |            |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                                              |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-03                                                                   | LEFT WING PRESSURE REFUELING SOLENOID VALVE             |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:L94E31-653P3                                                            | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J17600                                                                  | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-03, AMM 28-23-03PROC. REF: AMM 28-23-03, AMM 28-23-03 |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-03                                                                   | RIGHT WING PRESSURE REFUELING SOLENOID VALVE            |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:L94E31-653P3                                                            | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:J17610                                                                  | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-03, AMM 28-23-03PROC. REF: AMM 28-23-03, AMM 28-23-03 |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-04-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER |           |                |          |                        |           |           |             | Service ATA:28   |
|                                                                            | MOS                                                     | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                     | 0         | 3200 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05                             |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-07                                                                   | LEFT HIGH LEVEL SENSOR                                  |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:722860-2-0                                                              | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0822                                                                    | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-07, AMM 28-23-07PROC. REF: AMM 28-23-07, AMM 28-23-07 |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-07                                                                   | RIGHT HIGH LEVEL SENSOR                                 |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:722860-2-0                                                              | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0821                                                                    | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-07, AMM 28-23-07PROC. REF: AMM 28-23-07, AMM 28-23-07 |                                                         |           |                |          |                        |           |           |             |                  |
| 28-23-09                                                                   | FUEL PORT AND CAP                                       |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:K97-63-613                                                              | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:G09638                                                                  | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-23-09, AMM 28-23-09PROC. REF: AMM 28-23-09, AMM 28-23-09 |                                                         |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                                              |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 1 LEFT PROBE  |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765896-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765896IN000663                                                          | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 1 RIGHT PROBE |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765896-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765896IN000665                                                          | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 2 LEFT PROBE  |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765873-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765873IN00717                                                           | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 2 RIGHT PROBE |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765873-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765873IN00719                                                           | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 3 LEFT PROBE  |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765874-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765874IN00704                                                           | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 3 RIGHT PROBE |           |          |          |                        |           |           |             | Component ATA:28 |
| PN:765874-1-0                                                              | MOS/MSC           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:765874IN00705                                                           | HRS               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                        | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 28 - FUEL                                                              |                                             |           |                |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 4 LEFT PROBE                            |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:765875-1-0                                                              | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:765875IN00686                                                           | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                                             |           |                |          |                        |           |           |             |                  |
| 28-41-01                                                                   | NO. 4 RIGHT PROBE                           |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:765875-1-0                                                              | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:765875IN00684                                                           | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                                             |           |                |          |                        |           |           |             |                  |
| 28-41-05                                                                   | EFCU ELECTRICAL FUEL CONTROL UNIT           |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:738742-1-4                                                              | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:738790IN00814                                                           | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-41-05, AMM 28-41-05PROC. REF: AMM 28-41-05, AMM 28-41-05 |                                             |           |                |          |                        |           |           |             |                  |
| 28-43-01                                                                   | TEMPERATURE SENSOR                          |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:798840-1-0                                                              | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:04117                                                                   | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-43-01, AMM 28-43-01PROC. REF: AMM 28-43-01, AMM 28-43-01 |                                             |           |                |          |                        |           |           |             |                  |
| 28-43-01-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR |           |                |          |                        |           |           |             | Service ATA:28   |
|                                                                            | MOS                                         | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                         | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 28-43-01PROC. REF: AMM 28-43-01                             |                                             |           |                |          |                        |           |           |             |                  |
| 28-45-01                                                                   | LEFT PRESSURE SWITCH                        |           |                |          |                        |           |           |             | Component ATA:28 |
| PN:D98C07-611                                                              | MOS/MSC                                     | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:1267                                                                    | HRS                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01 |                                             |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                                       | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 28 - FUEL                                                                                                                      |                                                            |           |                |          |                        |           |           |             |          |
| 28-45-01                                                                                                                           | RIGHT PRESSURE SWITCH                                      |           |                |          |                        |           |           | Component   | ATA:28   |
| PN:D98C07-611                                                                                                                      | MOS/MSC                                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:1272                                                                                                                            | HRS                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01                                                         |                                                            |           |                |          |                        |           |           |             |          |
| ATA 29 - HYDRAULIC POWER                                                                                                           |                                                            |           |                |          |                        |           |           |             |          |
| 29-12-02                                                                                                                           | CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR |           |                |          |                        |           |           | Component   | ATA:29   |
| PN:3032763-003                                                                                                                     | MOS/MSC                                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:MX780887                                                                                                                        | HRS                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                                            |           |                |          |                        |           |           |             |          |
| 29-12-02                                                                                                                           | LEFT ENGINE DRIVEN HYDRAULIC PUMP                          |           |                |          |                        |           |           | Component   | ATA:29   |
| PN:3032249-002                                                                                                                     | MOS/MSC                                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:MX782684                                                                                                                        | HRS                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                                            |           |                |          |                        |           |           |             |          |
| 29-12-02                                                                                                                           | RIGHT ENGINE DRIVEN HYDRAULIC PUMP                         |           |                |          |                        |           |           | Component   | ATA:29   |
| PN:3032249-002                                                                                                                     | MOS/MSC                                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |          |
| SN:MX782791                                                                                                                        | HRS                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                                            |           |                |          |                        |           |           |             |          |
| 29-12-02-001 <sup>S</sup>                                                                                                          | VISUAL CHECK OF MANIFOLD/ RESERVOIR                        |           |                |          |                        |           |           | Service     | ATA:29   |
|                                                                                                                                    | MOS                                                        | 14-May-25 | 12 (+1m/-1m)   |          |                        |           |           |             |          |
|                                                                                                                                    | HRS                                                        | 2086.2    |                |          |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 1243      |                |          |                        |           |           |             |          |
| PROC. REF: AMM 29-12-02PROC. REF: AMM 29-12-02                                                                                     |                                                            |           |                |          |                        |           |           |             |          |
| 29-12-02-002 <sup>S</sup>                                                                                                          | OPERATIONAL CHECK LEFT EDP CHECK VALVE                     |           |                |          |                        |           |           | Service     | ATA:29   |
|                                                                                                                                    | MOS                                                        | 29-Apr-15 |                |          |                        |           |           |             |          |
|                                                                                                                                    | HRS                                                        | 0         | 5600 (+30/-30) |          |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 29-12-02PROC. REF: AMM 29-12-02                                                                                     |                                                            |           |                |          |                        |           |           |             |          |

PKG:80

PKG:50

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                     | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 29 - HYDRAULIC POWER                                                   |              |                                         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00                             |              |                                         |                |          |                        |           |           |             |                  |
|                                                                            |              |                                         |                |          |                        |           |           |             |                  |
| 29-12-02-002                                                               | <sup>S</sup> | OPERATIONAL CHECK RIGHT EDP CHECK VALVE |                |          |                        |           |           |             | Service ATA:29   |
|                                                                            | MOS          | 29-Apr-15                               |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                       | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                       |                |          |                        |           |           |             |                  |
| PKG:50                                                                     |              |                                         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00                             |              |                                         |                |          |                        |           |           |             |                  |
|                                                                            |              |                                         |                |          |                        |           |           |             |                  |
| 29-15-03                                                                   |              | HYDRAULIC ACCUMULATOR                   |                |          |                        |           |           |             | Component ATA:29 |
| PN:11172-2                                                                 | MOS/MSC      | 29-Apr-15                               | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:11172-0054                                                              | HRS          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-15-03, AMM 29-15-03PROC. REF: AMM 29-15-03, AMM 29-15-03 |              |                                         |                |          |                        |           |           |             |                  |
|                                                                            |              |                                         |                |          |                        |           |           |             |                  |
| 29-15-03-001                                                               | <sup>S</sup> | SERVICING OF HYDRAULIC ACCUMULATOR      |                |          |                        |           |           |             | Service ATA:29   |
| PN:11172-2                                                                 | MOS          | 14-May-25                               | 12 (+1m/-1m)   |          |                        |           |           |             |                  |
| SN:11172-0054                                                              | HRS          | 2086.2                                  |                |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1243                                    |                |          |                        |           |           |             |                  |
| PKG:80                                                                     |              |                                         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 12-13-00PROC. REF: AMM 12-13-00                             |              |                                         |                |          |                        |           |           |             |                  |
|                                                                            |              |                                         |                |          |                        |           |           |             |                  |
| 29-15-04                                                                   |              | NO. 1 FSOV FIRE SHUT OFF VALVE          |                |          |                        |           |           |             | Component ATA:29 |
| PN:3032428-001                                                             | MOS/MSC      | 29-Apr-15                               | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:AA492485                                                                | HRS          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-15-04, AMM 29-15-04PROC. REF: AMM 29-15-04, AMM 29-15-04 |              |                                         |                |          |                        |           |           |             |                  |
|                                                                            |              |                                         |                |          |                        |           |           |             |                  |
| 29-15-04                                                                   |              | NO. 2 FSOV FIRE SHUT OFF VALVE          |                |          |                        |           |           |             | Component ATA:29 |
| PN:3032428-001                                                             | MOS/MSC      | 29-Apr-15                               | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:AA492486                                                                | HRS          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                       |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-15-04, AMM 29-15-04PROC. REF: AMM 29-15-04, AMM 29-15-04 |              |                                         |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition   | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|---------------|------------------|
| ATA 29 - HYDRAULIC POWER                                                   |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 29-15-04-001                                                               | OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE                    |           |                |          |                        |           |              |               | Service ATA:29   |
| PN:3032428-001                                                             | MOS                                                                                                 | 24-Apr-23 | 48 (+30d/-30d) |          | 24-Apr-27              | 24-May-27 | 677 d (+30)  | AIRWORTHINESS |                  |
| SN:AA492485                                                                | HRS                                                                                                 | 1825.5    | 3200 (+30/-30) |          | 5025.5                 | 5055.5    | 2925.5 (+30) |               |                  |
|                                                                            | AFL                                                                                                 | 1042      |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 29-15-04PROC. REF: AMM 29-15-04                             |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 29-15-04-001                                                               | OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE                    |           |                |          |                        |           |              |               | Service ATA:29   |
| PN:3032428-001                                                             | MOS                                                                                                 | 24-Apr-23 | 48 (+30d/-30d) |          | 24-Apr-27              | 24-May-27 | 677 d (+30)  | AIRWORTHINESS |                  |
| SN:AA492486                                                                | HRS                                                                                                 | 1825.5    | 3200 (+30/-30) |          | 5025.5                 | 5055.5    | 2925.5 (+30) |               |                  |
|                                                                            | AFL                                                                                                 | 1042      |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 29-15-04PROC. REF: AMM 29-15-04                             |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 29-15-05                                                                   | PRIORITY VALVE                                                                                      |           |                |          |                        |           |              |               | Component ATA:29 |
| PN:2217-0001-401                                                           | MOS/MSC                                                                                             | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:00289                                                                   | HRS                                                                                                 | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                                                                 | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 29-15-05, AMM 29-15-05PROC. REF: AMM 29-15-05, AMM 29-15-05 |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 29-31-02-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE |           |                |          |                        |           |              |               | Service ATA:29   |
|                                                                            | MOS                                                                                                 | 29-Apr-15 |                |          |                        |           |              |               |                  |
|                                                                            | HRS                                                                                                 | 0         | 5600 (+30/-30) |          |                        |           |              |               |                  |
|                                                                            | AFL                                                                                                 | 0         |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 29-31-02PROC. REF: AMM 29-31-02                             |                                                                                                     |           |                |          |                        |           |              |               |                  |
| PKG:50                                                                     |                                                                                                     |           |                |          |                        |           |              |               |                  |
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 30-01-01                                                                   | MD INSC ILLUM PANEL                                                                                 |           |                |          |                        |           |              |               | Component ATA:30 |
| PN:441-43234-002                                                           | MOS/MSC                                                                                             | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:1169                                                                    | HRS                                                                                                 | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                                                                 | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 30-01-01, AMM 30-01-01PROC. REF: AMM 30-01-01, AMM 30-01-01 |                                                                                                     |           |                |          |                        |           |              |               |                  |
| 30-12-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM                                                  |           |                |          |                        |           |              |               | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 29-Apr-15 |                |          |                        |           |              |               |                  |
|                                                                            | HRS                                                                                                 | 0         | 6400 (+30/-30) |          |                        |           |              |               |                  |
|                                                                            | AFL                                                                                                 | 0         |                |          |                        |           |              |               |                  |
| PKG:60                                                                     |                                                                                                     |           |                |          |                        |           |              |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit         | C/W                                                                   | Interval | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------|----------|-----------|------------------------|-----------|-----------|-------------|----------|
| ATA 30 - ICE AND RAIN PROTECTION                                                                                                   |              |                                                                       |          |           |                        |           |           |             |          |
| PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00                                                                                     |              |                                                                       |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| 30-12-01-001                                                                                                                       | <sup>S</sup> | FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS |          |           |                        |           |           | Service     | ATA:30   |
|                                                                                                                                    | MOS          | 29-Apr-15                                                             |          |           |                        |           |           |             |          |
|                                                                                                                                    | HRS          | 0                                                                     | 6400     | (+30/-30) |                        |           |           |             |          |
|                                                                                                                                    | AFL          | 0                                                                     |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| PROC. REF: AMM 30-12-01PROC. REF: AMM 30-12-01                                                                                     |              |                                                                       |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| 30-12-02                                                                                                                           |              | LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE                    |          |           |                        |           |           | Component   | ATA:30   |
| PN:RYLB-53534-3                                                                                                                    | MOS/MSC      | 29-Apr-15                                                             | O/C      | TSN 0     |                        |           |           |             |          |
| SN:0282                                                                                                                            | HRS          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
|                                                                                                                                    | AFL          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 30-12-02, AMM 30-12-02PROC. REF: AMM 30-12-02, AMM 30-12-02                                                         |              |                                                                       |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| 30-12-02                                                                                                                           |              | RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE                   |          |           |                        |           |           | Component   | ATA:30   |
| PN:RYLB-53534-4                                                                                                                    | MOS/MSC      | 29-Apr-15                                                             | O/C      | TSN 0     |                        |           |           |             |          |
| SN:0287                                                                                                                            | HRS          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
|                                                                                                                                    | AFL          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 30-12-02, AMM 30-12-02PROC. REF: AMM 30-12-02, AMM 30-12-02                                                         |              |                                                                       |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| 30-12-05                                                                                                                           |              | LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER               |          |           |                        |           |           | Component   | ATA:30   |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC      | 29-Apr-15                                                             | O/C      | TSN 0     |                        |           |           |             |          |
| SN:8145-6-310                                                                                                                      | HRS          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
|                                                                                                                                    | AFL          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |              |                                                                       |          |           |                        |           |           |             |          |
|                                                                                                                                    |              |                                                                       |          |           |                        |           |           |             |          |
| 30-12-05                                                                                                                           |              | LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER                               |          |           |                        |           |           | Component   | ATA:30   |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC      | 29-Apr-15                                                             | O/C      | TSN 0     |                        |           |           |             |          |
| SN:8145-6-327                                                                                                                      | HRS          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
|                                                                                                                                    | AFL          | 0                                                                     |          | TSN 0     |                        |           |           |             |          |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |              |                                                                       |          |           |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                                          | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                                                                                   |                                                               |           |                |          |                        |           |           |             |                  |
| 30-12-05                                                                                                                           | LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER                    |           |                |          |                        |           |           |             | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8145-6-297                                                                                                                      | HRS                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                               |           |                |          |                        |           |           |             |                  |
| 30-12-05                                                                                                                           | RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER      |           |                |          |                        |           |           |             | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8172-1-221                                                                                                                      | HRS                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                               |           |                |          |                        |           |           |             |                  |
| 30-12-05                                                                                                                           | RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER                      |           |                |          |                        |           |           |             | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8145-6-320                                                                                                                      | HRS                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                               |           |                |          |                        |           |           |             |                  |
| 30-12-05                                                                                                                           | RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER                   |           |                |          |                        |           |           |             | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8145-6-284                                                                                                                      | HRS                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                               |           |                |          |                        |           |           |             |                  |
| 30-12-05-001 <sup>S</sup>                                                                                                          | FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER |           |                |          |                        |           |           |             | Service ATA:30   |
|                                                                                                                                    | MOS                                                           | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                                                                                    | HRS                                                           | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                                                                                     |                                                               |           |                |          |                        |           |           |             |                  |

PKG:60

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                         | Interval | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------|----------|-----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |              |                                                                             |          |           |                        |           |           |             |                  |
| 30-12-05-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER              |          |           |                        |           |           |             | Service ATA:30   |
|                                                                            | MOS          | 29-Apr-15                                                                   |          |           |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                                           | 6400     | (+30/-30) |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                           |          |           |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                             |              |                                                                             |          |           |                        |           |           |             | PKG:60           |
| 30-12-05-002                                                               | <sup>S</sup> | FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER  |          |           |                        |           |           |             | Service ATA:30   |
|                                                                            | MOS          | 29-Apr-15                                                                   |          |           |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                                           | 6400     | (+30/-30) |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                           |          |           |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                             |              |                                                                             |          |           |                        |           |           |             | PKG:60           |
| 30-12-05-002                                                               | <sup>S</sup> | FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER |          |           |                        |           |           |             | Service ATA:30   |
|                                                                            | MOS          | 29-Apr-15                                                                   |          |           |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                                           | 6400     | (+30/-30) |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                           |          |           |                        |           |           |             |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                             |              |                                                                             |          |           |                        |           |           |             | PKG:60           |
| 30-21-01                                                                   |              | LEFT ENGINE ANTI-ICE PRESUURE VALVE                                         |          |           |                        |           |           |             | Component ATA:30 |
| PN:10030295                                                                | MOS/MSC      | 04-Feb-16                                                                   | O/C      | TSN 0     |                        |           |           |             |                  |
| SN:0001128                                                                 | HRS          | 268.5                                                                       |          | TSN 0     |                        |           |           |             |                  |
|                                                                            | AFL          | 158                                                                         |          | TSN 0     |                        |           |           |             |                  |
| PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01 |              |                                                                             |          |           |                        |           |           |             |                  |
| 30-21-01                                                                   |              | RIGHT ENGINE ANTI-ICE PRESUURE VALVE                                        |          |           |                        |           |           |             | Component ATA:30 |
| PN:10030295                                                                | MOS/MSC      | 29-Apr-15                                                                   | O/C      | TSN 0     |                        |           |           |             |                  |
| SN:0000578                                                                 | HRS          | 0                                                                           |          | TSN 0     |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                           |          | TSN 0     |                        |           |           |             |                  |
| PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01 |              |                                                                             |          |           |                        |           |           |             |                  |
| 30-21-02                                                                   |              | LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER                                    |          |           |                        |           |           |             | Component ATA:30 |
| PN:APTE-477F-1000-100G                                                     | MOS/MSC      | 29-Apr-15                                                                   | O/C      | TSN 0     |                        |           |           |             |                  |
| SN:8172-5-127                                                              | HRS          | 0                                                                           |          | TSN 0     |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                           |          | TSN 0     |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit  | Remaining | Disposition                   | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|-----------------|----------|------------------------|------------|-----------|-------------------------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02 |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| 30-21-02                                                                   | RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER                                                           |           |                 |          |                        |            |           |                               | Component ATA:30 |
| PN:APTE-477F-1000-100G                                                     | MOS/MSC                                                                                             | 29-Apr-15 | O/C             | TSN 0    |                        |            |           |                               |                  |
| SN:8178-8-588                                                              | HRS                                                                                                 | 0         |                 | TSN 0    |                        |            |           |                               |                  |
|                                                                            | AFL                                                                                                 | 0         |                 | TSN 0    |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02 |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| 30-21-02-001                                                               | FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER                                      |           |                 |          |                        |            |           |                               | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 29-Apr-15 |                 |          |                        |            |           |                               |                  |
|                                                                            | HRS                                                                                                 | 0         | 12000 (+30/-30) | 12000    | 12030                  | 9900 (+30) |           |                               |                  |
|                                                                            | AFL                                                                                                 | 0         |                 |          |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02                             |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| 30-21-02-001                                                               | FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER                                     |           |                 |          |                        |            |           |                               | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 29-Apr-15 |                 |          |                        |            |           |                               |                  |
|                                                                            | HRS                                                                                                 | 0         | 12000 (+30/-30) | 12000    | 12030                  | 9900 (+30) |           |                               |                  |
|                                                                            | AFL                                                                                                 | 0         |                 |          |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02                             |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| 30-21-02-720-801-A                                                         | TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK |           |                 |          |                        |            |           |                               | Service ATA:30   |
|                                                                            | MOS/MSC                                                                                             | 29-Apr-15 | A/R             |          |                        |            |           | UNSCHEDULED MAINTENANCE CHECK |                  |
|                                                                            | HRS                                                                                                 | 0         |                 |          |                        |            |           |                               |                  |
|                                                                            | AFL                                                                                                 | 0         |                 |          |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02                             |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| 30-21-03-001 <sup>S</sup>                                                  | BORESCOPE INSPECTION OF PICCOLO TUBE                                                                |           |                 |          |                        |            |           |                               | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 29-Apr-15 |                 |          |                        |            |           |                               |                  |
|                                                                            | HRS                                                                                                 | 0         | 5600 (+30/-30)  |          |                        |            |           |                               |                  |
|                                                                            | AFL                                                                                                 | 0         |                 |          |                        |            |           |                               |                  |
| PROC. REF: AMM 30-21-03PROC. REF: AMM 30-21-03                             |                                                                                                     |           |                 |          |                        |            |           |                               |                  |
| PKG:50                                                                     |                                                                                                     |           |                 |          |                        |            |           |                               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit         | C/W                                                                          | Interval       | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit   | Remaining | Disposition | Warranty       |
|------------------------------------------------|--------------|------------------------------------------------------------------------------|----------------|-----------|------------------------|-------------|-----------|-------------|----------------|
| ATA 30 - ICE AND RAIN PROTECTION               |              |                                                                              |                |           |                        |             |           |             |                |
| 30-21-04-001                                   | <sup>S</sup> | DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS                                 |                |           |                        |             |           |             | Service ATA:30 |
|                                                | MOS          | 29-Apr-15                                                                    |                |           |                        |             |           |             |                |
|                                                | HRS          | 0                                                                            | 2400 (+30/-30) |           |                        |             |           |             |                |
|                                                | AFL          | 0                                                                            |                |           |                        |             |           |             |                |
| PROC. REF: AMM 30-21-00PROC. REF: AMM 30-21-00 |              |                                                                              |                |           |                        |             |           |             |                |
| PKG:20                                         |              |                                                                              |                |           |                        |             |           |             |                |
| 30-31-00-002                                   |              | OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING                        |                |           |                        |             |           |             | Service ATA:30 |
|                                                | MOS          | 14-May-25                                                                    | 24 (+1m/-1m)   | 14-May-27 | 14-Jun-27              | 697 d (+31) |           |             |                |
|                                                | HRS          | 2086.2                                                                       |                |           |                        |             |           |             |                |
|                                                | AFL          | 1243                                                                         |                |           |                        |             |           |             |                |
| PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00 |              |                                                                              |                |           |                        |             |           |             |                |
| PKG:81                                         |              |                                                                              |                |           |                        |             |           |             |                |
| 30-41-01-002                                   | <sup>S</sup> | DISCARD OF WINDSHIELD RAIN REPELLENT COATING                                 |                |           |                        |             |           |             | Service ATA:30 |
|                                                | MOS          | 14-May-25                                                                    | 12 (+1m/-1m)   |           |                        |             |           |             |                |
|                                                | HRS          | 2086.2                                                                       |                |           |                        |             |           |             |                |
|                                                | AFL          | 1243                                                                         |                |           |                        |             |           |             |                |
| PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01 |              |                                                                              |                |           |                        |             |           |             |                |
| PKG:80                                         |              |                                                                              |                |           |                        |             |           |             |                |
| 30-41-01-003                                   | <sup>S</sup> | FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE |                |           |                        |             |           |             | Service ATA:30 |
|                                                | MOS          | 14-May-25                                                                    | 12 (+1m/-1m)   |           |                        |             |           |             |                |
|                                                | HRS          | 2086.2                                                                       |                |           |                        |             |           |             |                |
|                                                | AFL          | 1243                                                                         |                |           |                        |             |           |             |                |
| PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01 |              |                                                                              |                |           |                        |             |           |             |                |
| PKG:80                                         |              |                                                                              |                |           |                        |             |           |             |                |
| 30-42-00-001                                   | <sup>S</sup> | OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM                               |                |           |                        |             |           |             | Service ATA:30 |
|                                                | MOS          | 29-Apr-24                                                                    |                |           |                        |             |           |             |                |
|                                                | HRS          | 1952.5                                                                       | 800 (+30/-30)  |           |                        |             |           |             |                |
|                                                | AFL          | 1160                                                                         |                |           |                        |             |           |             |                |
| PROC. REF: AMM 30-42-00PROC. REF: AMM 30-42-00 |              |                                                                              |                |           |                        |             |           |             |                |
| PKG:1                                          |              |                                                                              |                |           |                        |             |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval     | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit   | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|--------------|-----------|------------------------|-------------|-----------|-------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                   |           |              |           |                        |             |           |             |                  |
| 30-42-01                                                                   | LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL   |           |              |           |                        |             |           |             | Component ATA:30 |
| PN:EPM-112-4                                                               | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0     |                        |             |           |             |                  |
| SN:02729                                                                   | HRS                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
| PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01 |                                                   |           |              |           |                        |             |           |             |                  |
| 30-42-01                                                                   | RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL   |           |              |           |                        |             |           |             | Component ATA:30 |
| PN:EPM-112-4                                                               | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0     |                        |             |           |             |                  |
| SN:02775                                                                   | HRS                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
| PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01 |                                                   |           |              |           |                        |             |           |             |                  |
| 30-81-02                                                                   | LEFT NOSE ICE DETECTOR                            |           |              |           |                        |             |           |             | Component ATA:30 |
| PN:0871LM3-1                                                               | MOS/MSC                                           | 27-Apr-18 | O/C          | TSR 1     |                        |             |           |             |                  |
| SN:0787                                                                    | HRS                                               | 1013.5    |              | TSR 0     |                        |             |           |             |                  |
|                                                                            | AFL                                               | 579       |              | TSR 0     |                        |             |           |             |                  |
| PROC. REF: AMM 30-81-02, AMM 30-81-02PROC. REF: AMM 30-81-02, AMM 30-81-02 |                                                   |           |              |           |                        |             |           |             |                  |
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                   |           |              |           |                        |             |           |             |                  |
| 31-30-02                                                                   | CVDR ACCELEROMETER                                |           |              |           |                        |             |           |             | Component ATA:31 |
| PN:3001-01-111                                                             | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0     |                        |             |           |             |                  |
| SN:0914-DTU4249                                                            | HRS                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
| PROC. REF: AMM 31-31-05, AMM 31-31-05PROC. REF: AMM 31-31-05, AMM 31-31-05 |                                                   |           |              |           |                        |             |           |             |                  |
| 31-30-03                                                                   | REAR CVDR IMPACT SWITCH                           |           |              |           |                        |             |           |             | Component ATA:31 |
| PN:5930-4-000                                                              | MOS/MSC                                           | 29-Apr-15 | O/C          | TSN 0     |                        |             |           |             |                  |
| SN:6763                                                                    | HRS                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0     |                        |             |           |             |                  |
| PROC. REF: AMM 31-31-04, AMM 31-31-04PROC. REF: AMM 31-31-04, AMM 31-31-04 |                                                   |           |              |           |                        |             |           |             |                  |
| 31-31-00-002                                                               | OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) |           |              |           |                        |             |           |             | Service ATA:31   |
|                                                                            | MOS                                               | 14-May-25 | 12 (+1m/-1m) | 14-May-26 | 14-Jun-26              | 332 d (+31) |           |             |                  |
|                                                                            | HRS                                               | 2086.2    |              |           |                        |             |           |             |                  |
|                                                                            | AFL                                               | 1243      |              |           |                        |             |           |             |                  |
| PROC. REF: AMM 31-31-00PROC. REF: AMM 31-31-00                             |                                                   |           |              |           |                        |             |           |             |                  |
| PKG:80                                                                     |                                                   |           |              |           |                        |             |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                  | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                                    |         |           |          |          |                        |           |           |             |          |
| 31-31-01 (CVR / CVDR) COCKPIT VOICE RECORDER                                             |         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:2100-3083-50                                                                          | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:001017510                                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                          | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-31-01, AMM 31-31-01PROC. REF: AMM 31-31-01, AMM 31-31-01               |         |           |          |          |                        |           |           |             |          |
| 31-31-03 CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON                     |         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:266-E0305-00                                                                          | MOS/MSC | 29-Apr-15 | H/T      | TSN 0    |                        |           |           |             |          |
| SN:SD44403                                                                               | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                          | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-31-03, AMM 31-31-03PROC. REF: AMM 31-31-03, AMM 31-31-03               |         |           |          |          |                        |           |           |             |          |
| 31-31-03-001 DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY |         |           |          |          |                        |           |           | Service     | ATA:31   |
| PN:266-E0305-00                                                                          | MOS/MSC | 05-Aug-20 | DUE      |          | 15-Apr-27 (M)          |           | 668 d     | LIFE LIMIT  |          |
| SN:SD44403                                                                               | HRS     | 1517.87   |          |          |                        |           |           |             |          |
|                                                                                          | AFL     | 884       |          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-31-03PROC. REF: AMM 31-31-03                                           |         |           |          |          |                        |           |           |             |          |
| 31-31-09 CVDR CONTROL PANEL                                                              |         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:441-42635-003                                                                         | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:0586                                                                                  | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                          | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-31-09, AMM 31-31-09PROC. REF: AMM 31-31-09, AMM 31-31-09               |         |           |          |          |                        |           |           |             |          |
| 31-33-01 FDR - FLIGHT DATA RECORDER                                                      |         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:2100-2044-00                                                                          | MOS/MSC | 27-Apr-18 | O/C      | TSR 6    |                        |           |           |             |          |
| SN:000830204                                                                             | HRS     | 1013.5    |          | TSR 0    |                        |           |           |             |          |
|                                                                                          | AFL     | 579       |          | TSR 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-33-01, AMM 31-33-01PROC. REF: AMM 31-33-01, AMM 31-33-01               |         |           |          |          |                        |           |           |             |          |
| 31-33-03 FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON                        |         |           |          |          |                        |           |           | Component   | ATA:31   |
| PN:DK120/90                                                                              | MOS/MSC | 14-May-25 | H/T      | TSN 0    |                        |           |           |             |          |
| SN:AT219062                                                                              | HRS     | 2086.2    |          | TSN 0    |                        |           |           |             |          |
|                                                                                          | AFL     | 1243      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-33-03, AMM 31-33-03PROC. REF: AMM 31-33-03, AMM 31-33-03               |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                                                              | Interval                 | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------------------------------------|--------------------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-03-001                                                               |         | DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED) |                          |          |                        |           |           | Service     | ATA:31   |
| PN:DK120/90                                                                | MOS/MSC | 14-May-25                                                                                                        | DUE                      |          | 01-Mar-32 (M)          |           | 2450 d    | LIFE LIMIT  |          |
| SN:AT219062                                                                | HRS     | 2086.2                                                                                                           |                          |          |                        |           |           |             |          |
|                                                                            | AFL     | 1243                                                                                                             |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  | Expiry Date: : 01-Mar-32 |          |                        |           |           |             |          |
| PROC. REF: AMM 31-33-03PROC. REF: AMM 31-33-03                             |         |                                                                                                                  |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-04                                                                   |         | FORWARD CVDR IMPACT SWITCH                                                                                       |                          |          |                        |           |           | Component   | ATA:31   |
| PN:5930-4-000                                                              | MOS/MSC | 29-Apr-15                                                                                                        | O/C                      | TSN 0    |                        |           |           |             |          |
| SN:6631                                                                    | HRS     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-33-04, AMM 31-33-04PROC. REF: AMM 31-33-04, AMM 31-33-04 |         |                                                                                                                  |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-05                                                                   |         | ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER                                                    |                          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                                                                                        | O/C                      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-33-05, AMM 31-33-05PROC. REF: AMM 31-33-05, AMM 31-33-05 |         |                                                                                                                  |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-05                                                                   |         | RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER                                                      |                          |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                                                                                        | O/C                      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                |                          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-33-05, AMM 31-33-05PROC. REF: AMM 31-33-05, AMM 31-33-05 |         |                                                                                                                  |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-05-001                                                               |         | FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER                                  |                          |          |                        |           |           | Service     | ATA:31   |
|                                                                            | MOS/MSC | 29-Apr-15                                                                                                        | N/A                      |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                                                                                                |                          |          |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                |                          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-33-05PROC. REF: AMM 31-33-05                             |         |                                                                                                                  |                          |          |                        |           |           |             |          |
|                                                                            |         |                                                                                                                  |                          |          |                        |           |           |             |          |
| 31-33-05-002                                                               |         | FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER                                |                          |          |                        |           |           | Service     | ATA:31   |
|                                                                            | MOS/MSC | 29-Apr-15                                                                                                        | N/A                      |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                                                                                                |                          |          |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                                                                                |                          |          |                        |           |           |             |          |
| PROC. REF: AMM 31-33-05PROC. REF: AMM 31-33-05                             |         |                                                                                                                  |                          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                                                  |                                                         |           |                |          |                        |           |           |             |                  |
| 31-40-01                                                                                               | LH DCU UNIT                                             |           |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01457-00                                                                                        | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:16906190                                                                                            | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-41-01, AMM 31-41-01PROC. REF: AMM 31-41-01, AMM 31-41-01                             |                                                         |           |                |          |                        |           |           |             |                  |
| 31-40-01                                                                                               | RH DCU UNIT                                             |           |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01457-00                                                                                        | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:16906193                                                                                            | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-41-01, AMM 31-41-01PROC. REF: AMM 31-41-01, AMM 31-41-01                             |                                                         |           |                |          |                        |           |           |             |                  |
| 31-40-02                                                                                               | LEFT GIA 63W INTEGRATED AVIONICS UNIT                   |           |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01105-20                                                                                        | MOS/MSC                                                 | 29-Apr-24 | O/C            | TSR 17   |                        |           |           |             |                  |
| SN:1HQ006492                                                                                           | HRS                                                     | 1952.5    |                | TSR 0    |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 1160      |                | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05 |                                                         |           |                |          |                        |           |           |             |                  |
| 31-40-02                                                                                               | RIGHT GIA 63W INTEGRATED AVIONICS UNIT                  |           |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01105-20                                                                                        | MOS/MSC                                                 | 05-Dec-23 | O/C            | TSN 104  |                        |           |           |             |                  |
| SN:1HQ011904                                                                                           | HRS                                                     | 1910      |                | TSN 1910 |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 1101      |                | TSN 1101 |                        |           |           |             |                  |
| PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05 |                                                         |           |                |          |                        |           |           |             |                  |
| 31-41-01                                                                                               | LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL |           |                |          |                        |           |           |             | Component ATA:31 |
| PN:441-42627-001                                                                                       | MOS/MSC                                                 | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:1277                                                                                                | HRS                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                         |           |                |          |                        |           |           |             |                  |
| 31-42-00-001 <sup>S</sup>                                                                              | OPERATIONAL CHECK OF HSDB SWITCH REVERSION              |           |                |          |                        |           |           |             | Service ATA:31   |
|                                                                                                        | MOS                                                     | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                                                        | HRS                                                     | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                                                        | AFL                                                     | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 31-42-00PROC. REF: AMM 31-42-00                                                         |                                                         |           |                |          |                        |           |           |             |                  |
| PKG:60                                                                                                 |                                                         |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                | C/W       | Interval       | TSX/Adj.   | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------|----------------|------------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-50-01                                                                   | (GEA 71) ENGINE AIRFRAME INTERFACE UNIT                                             |           |                |            |                        |           |           | Component   | ATA:31   |
| PN:PN                                                                      | MOS/MSC                                                                             | 29-Apr-15 | O/C            | TSN 0      |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS                                                                                 | 0         |                | TSN 0      |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 0         |                | TSN 0      |                        |           |           |             |          |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-50-01                                                                   | 1 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                              |           |                |            |                        |           |           | Component   | ATA:31   |
| PN:011-00831-00                                                            | MOS/MSC                                                                             | 14-May-25 | O/C            | TSN 121    |                        |           |           |             |          |
| SN:46719166                                                                | HRS                                                                                 | 2086.2    |                | TSN 2086.2 |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 1243      |                | TSN 1243   |                        |           |           |             |          |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-50-01                                                                   | 2 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                              |           |                |            |                        |           |           | Component   | ATA:31   |
| PN:011-00831-00                                                            | MOS/MSC                                                                             | 14-May-25 | O/C            | TSN 121    |                        |           |           |             |          |
| SN:46719328                                                                | HRS                                                                                 | 2086.2    |                | TSN 2086.2 |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 1243      |                | TSN 1243   |                        |           |           |             |          |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-50-01                                                                   | 3 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                              |           |                |            |                        |           |           | Component   | ATA:31   |
| PN:011-00831-00                                                            | MOS/MSC                                                                             | 29-Apr-15 | O/C            | TSN 0      |                        |           |           |             |          |
| SN:46719119                                                                | HRS                                                                                 | 0         |                | TSN 0      |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 0         |                | TSN 0      |                        |           |           |             |          |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-61-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)   |           |                |            |                        |           |           | Service     | ATA:31   |
| PN:011-01440-10                                                            | MOS                                                                                 | 29-Apr-15 |                |            |                        |           |           |             |          |
| SN:18T006402                                                               | HRS                                                                                 | 0         | 3200 (+30/-30) |            |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 0         |                |            |                        |           |           |             |          |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |                                                                                     |           |                |            |                        |           |           |             |          |
| 31-61-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) |           |                |            |                        |           |           | Service     | ATA:31   |
| PN:011-01440-10                                                            | MOS                                                                                 | 29-Apr-15 |                |            |                        |           |           |             |          |
| SN:18T006473                                                               | HRS                                                                                 | 0         | 3200 (+30/-30) |            |                        |           |           |             |          |
|                                                                            | AFL                                                                                 | 0         |                |            |                        |           |           |             |          |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |                                                                                     |           |                |            |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                                 | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) |                |          |                        |           |           |             | Service ATA:31   |
| PN:011-01440-10                                                            | MOS          | 29-Apr-15                                                                           |                |          |                        |           |           |             |                  |
| SN:18T006479                                                               | HRS          | 0                                                                                   | 3200 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-01                                                                   |              | MFD (MULTI-FUNCTION FLIGHT DISPLAY)                                                 |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01440-10                                                            | MOS/MSC      | 29-Apr-15                                                                           | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:18T006402                                                               | HRS          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-01                                                                   |              | PFD 1 (PRIMARY FLIGHT DISPLAY)                                                      |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01440-10                                                            | MOS/MSC      | 29-Apr-15                                                                           | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:18T006473                                                               | HRS          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-01                                                                   |              | PFD 2 (PRIMARY FLIGHT DISPLAY)                                                      |                |          |                        |           |           |             | Component ATA:31 |
| PN:011-01440-10                                                            | MOS/MSC      | 29-Apr-15                                                                           | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:18T006479                                                               | HRS          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-05                                                                   |              | TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY                                         |                |          |                        |           |           |             | Component ATA:31 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                           | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-05, AMM 31-61-05PROC. REF: AMM 31-61-05, AMM 31-61-05 |              |                                                                                     |                |          |                        |           |           |             |                  |
| 31-61-06                                                                   |              | NO. 1 BARO INSC ILLUMINATED PANEL                                                   |                |          |                        |           |           |             | Component ATA:31 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                           | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 31-61-06, AMM 31-61-06PROC. REF: AMM 31-61-06, AMM 31-61-06 |              |                                                                                     |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                                   |           |               |          |                        |           |           |             |          |
| 31-61-06                                                                   | NO. 2 BARO INSC ILLUMINATED PANEL                                 |           |               |          |                        |           |           | Component   | ATA:31   |
| PN:PN                                                                      | MOS/MSC                                                           | 29-Apr-15 | O/C           | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 31-61-06, AMM 31-61-06PROC. REF: AMM 31-61-06, AMM 31-61-06 |                                                                   |           |               |          |                        |           |           |             |          |
| ATA 32 - LANDING GEAR                                                      |                                                                   |           |               |          |                        |           |           |             |          |
| 32-00-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS |           |               |          |                        |           |           | Service     | ATA:32   |
|                                                                            | MOS                                                               | 29-Apr-24 |               |          |                        |           |           |             |          |
|                                                                            | HRS                                                               | 1952.5    | 800 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL                                                               | 1160      |               |          |                        |           |           |             |          |
| PROC. REF: AMM 32-00-20PROC. REF: AMM 32-00-20                             |                                                                   |           |               |          |                        |           |           |             |          |
| 32-001                                                                     | LEFT MLG SHOCK STRUT LEFT MAIN FITTING                            |           |               |          |                        |           |           | Component   | ATA:32   |
| PN:2317-1201-503                                                           | MOS                                                               | 29-Apr-15 |               | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1540677/001                                                             | HRS                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                               | 0         | 16800         | TSN 0    | 16800                  |           | 15548     |             |          |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                                   |           |               |          |                        |           |           |             |          |
| 32-002                                                                     | RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING                          |           |               |          |                        |           |           | Component   | ATA:32   |
| PN:2317-1201-504                                                           | MOS                                                               | 29-Apr-15 |               | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1546167/001                                                             | HRS                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                               | 0         | 16800         | TSN 0    | 16800                  |           | 15548     |             |          |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                                   |           |               |          |                        |           |           |             |          |
| 32-003                                                                     | LEFT PINTLE PIN                                                   |           |               |          |                        |           |           | Component   | ATA:32   |
| PN:2317-1101-003                                                           | MOS                                                               | 29-Apr-15 |               | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1540349/001                                                             | HRS                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                               | 0         | 16800         | TSN 0    | 16800                  |           | 15548     |             |          |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                                   |           |               |          |                        |           |           |             |          |
| 32-003                                                                     | RIGHT PINTLE PIN                                                  |           |               |          |                        |           |           | Component   | ATA:32   |
| PN:2317-1101-003                                                           | MOS                                                               | 29-Apr-15 |               | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1540349/006                                                             | HRS                                                               | 0         |               | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                               | 0         | 16800         | TSN 0    | 16800                  |           | 15548     |             |          |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                                   |           |               |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                      |           |          |          |                        |           |           |             |                  |
| 32-004                                                                     | LEFT PINTLE PIN                      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1102-001                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1542544/008                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |
| 32-004                                                                     | RIGHT PINTLE PIN                     |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1102-001                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1542544/011                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |
| 32-005                                                                     | LEFT MLG SHOCK STRUT (MF - AS) AXLE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1103-003                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541520/001                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |
| 32-005                                                                     | RIGHT MLG SHOCK STRUT (MF - AS) AXLE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1103-003                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541520/002                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |
| 32-006                                                                     | LEFT MLG SHOCK STRUT (TR - AS) AXLE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1107-005                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1518508/001                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 15300    | TSN 0    | 15300                  |           | 14048     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |
| 32-006                                                                     | RIGHT MLG SHOCK STRUT (TR - AS) AXLE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1107-005                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1518508/008                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 15300    | TSN 0    | 15300                  |           | 14048     |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                       |           |          |          |                        |           |           |             |                  |
| 32-007                                                                     | LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1109-003                                                           | MOS                                                   | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541525/013                                                             | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                       |           |          |          |                        |           |           |             |                  |
| 32-007                                                                     | RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1109-003                                                           | MOS                                                   | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541527/002                                                             | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                       |           |          |          |                        |           |           |             |                  |
| 32-008                                                                     | LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1126-003                                                           | MOS                                                   | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1540545/017                                                             | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                       |           |          |          |                        |           |           |             |                  |
| 32-008                                                                     | RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1126-003                                                           | MOS                                                   | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1540545/018                                                             | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                       |           |          |          |                        |           |           |             |                  |
| 32-10-00                                                                   | LEFT MAIN LANDING GEAR                                |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                       |           |          |          |                        |           |           |             |                  |
| 32-10-00                                                                   | RIGHT MAIN LANDING GEAR                               |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                 |           |          |          |                        |           |           |             |                  |
| 32-10-01                                                                   | LEFT MAIN LANDING GEAR LEG STRUT ASSY           |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1100-405                                                           | MOS/MSC                                         | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |                  |
| SN:00207                                                                   | HRS                                             | 2086.2    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 1243      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-10-01                                                                   | RIGHT MAIN LANDING GEAR LEG STRUT ASSY          |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1100-406                                                           | MOS/MSC                                         | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |                  |
| SN:00207                                                                   | HRS                                             | 2086.2    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 1243      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-100                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM ASSY        |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1500-405                                                           | MOS/MSC                                         | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |                  |
| SN:00212                                                                   | HRS                                             | 2086.2    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 1243      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-100                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM ASSY       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1500-406                                                           | MOS/MSC                                         | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |                  |
| SN:00215                                                                   | HRS                                             | 2086.2    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 1243      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-101                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1502-003                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1543288/001                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 15300    | TSN 0    | 15300                  |           | 14048     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-101                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1502-003                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1543288/002                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 15300    | TSN 0    | 15300                  |           | 14048     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                           |           |          |          |                        |           |           |             |                  |
| 32-102                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM AXLE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1503-005                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1538228/003                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |
| 32-102                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM AXLE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1503-005                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1538228/006                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |
| 32-103                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM BOLT  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1509-001                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1519879/001                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |
| 32-103                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM BOLT |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1509-001                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1519879/004                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |
| 32-104                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1513-501                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1544102/001                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |
| 32-105                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-1513-502                                                           | MOS                                       | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541749/001                                                             | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                       | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                          | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------------|-----------|-----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-106                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN               |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2317-1505-001                                                           | MOS                                                           | 29-Apr-15 |                 | TSN 0    |                        |           |              | LIFE LIMIT  |                  |
| SN:1540468/008                                                             | HRS                                                           | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 0         | 16800           | TSN 0    | 16800                  |           | 15548        |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-106                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN              |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2317-1505-001                                                           | MOS                                                           | 29-Apr-15 |                 | TSN 0    |                        |           |              | LIFE LIMIT  |                  |
| SN:1540468/015                                                             | HRS                                                           | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 0         | 16800           | TSN 0    | 16800                  |           | 15548        |             |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-11-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR                |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                           | 14-May-25 | 12 (+1m/-1m)    |          |                        |           |              |             |                  |
|                                                                            | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      |                 |          |                        |           |              |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                               |           |                 |          |                        |           |              |             |                  |
| PKG:80                                                                     |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-11-00-003                                                               | LUBRICATION OF MAIN LANDING GEAR                              |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                           | 14-May-25 | 12 (+1m/-1m)    |          | 14-May-26              | 14-Jun-26 | 332 d (+31)  |             |                  |
|                                                                            | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 650 (+30/-30)   |          | 1893                   | 1923      | 641 (+30)    |             |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-11-01-001                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH) |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-1100-405                                                           | MOS                                                           | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00207                                                                   | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-11-01-002                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH) |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-1100-406                                                           | MOS                                                           | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00207                                                                   | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                               |           |                 |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                 | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------------|-----------------|----------|------------------------|-----------|--------------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-001                                                               |         | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH) |                 |          |                        |           |              | Service     | ATA:32   |
| PN:2117-3000-601                                                           | MOS     | 14-May-25                                                           | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |          |
| SN:00455                                                                   | HRS     | 2086.2                                                              |                 |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                                | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |          |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-002                                                               |         | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH) |                 |          |                        |           |              | Service     | ATA:32   |
| PN:2117-3000-601                                                           | MOS     | 31-Jan-25                                                           | 120 (+1m/-1m)   |          | 31-Jan-35              | 28-Feb-35 | 3516 d (+28) | OVERHAUL    |          |
| SN:00502                                                                   | HRS     | 2062.9                                                              |                 |          |                        |           |              |             |          |
|                                                                            | AFL     | 1226                                                                | 12000 (+30/-30) |          | 13226                  | 13256     | 11974 (+30)  |             |          |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-900-801-05                                                        |         | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON             |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC | 31-Jan-25                                                           | H/T             | TSN 0    |                        |           |              |             |          |
| SN:1562838/009                                                             | HRS     | 2062.9                                                              |                 | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 1226                                                                |                 | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-900-801-06                                                        |         | LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON              |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC |                                                                     | H/T             | TSN 0    |                        |           |              |             |          |
| SN:1541222/007                                                             | HRS     |                                                                     |                 | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | EFF                                                                 |                 | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-900-801-07                                                        |         | LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER                      |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2117-3027-901                                                           | MOS/MSC |                                                                     | H/T             | TSN 0    |                        |           |              |             |          |
| SN:13049                                                                   | HRS     |                                                                     |                 | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | EFF                                                                 |                 | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |                                                                     |                 |          |                        |           |              |             |          |
| 32-11-02-900-801-08                                                        |         | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER                     |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2117-3010-001                                                           | MOS/MSC | 31-Jan-25                                                           | H/T             | TSN 0    |                        |           |              |             |          |
| SN:17282                                                                   | HRS     | 2062.9                                                              |                 | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 1226                                                                |                 | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |                                                                     |                 |          |                        |           |              |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval        | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit    | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|-----------------|-----------|------------------------|--------------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-02-900-801-13                                                        | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN                      |           |                 |           |                        |              |           |             | Component ATA:32 |
| PN:2117-3019-001                                                           | MOS/MSC                                                           | 31-Jan-25 | H/T             | TSN 0     |                        |              |           |             |                  |
| SN:1467482/021                                                             | HRS                                                               | 2062.9    |                 | TSN 0     |                        |              |           |             |                  |
|                                                                            | AFL                                                               | 1226      |                 | TSN 0     |                        |              |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-02-900-801-14                                                        | LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN                       |           |                 |           |                        |              |           |             | Component ATA:32 |
| PN:2117-3019-003                                                           | MOS/MSC                                                           |           | H/T             | TSN 0     |                        |              |           |             |                  |
| SN:1538133/008                                                             | HRS                                                               |           |                 | TSN 0     |                        |              |           |             |                  |
|                                                                            | AFL                                                               | EFF       |                 | TSN 0     |                        |              |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-02-900-801-15                                                        | LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE            |           |                 |           |                        |              |           |             | Component ATA:32 |
| PN:2117-3007-003                                                           | MOS/MSC                                                           |           | H/T             | TSN 0     |                        |              |           |             |                  |
| SN:1534419/001                                                             | HRS                                                               |           |                 | TSN 0     |                        |              |           |             |                  |
|                                                                            | AFL                                                               | EFF       |                 | TSN 0     |                        |              |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-02-900-801-16                                                        | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE           |           |                 |           |                        |              |           |             | Component ATA:32 |
| PN:2117-3007-003                                                           | MOS/MSC                                                           | 31-Jan-25 | H/T             | TSN 0     |                        |              |           |             |                  |
| SN:1604484/003                                                             | HRS                                                               | 2062.9    |                 | TSN 0     |                        |              |           |             |                  |
|                                                                            | AFL                                                               | 1226      |                 | TSN 0     |                        |              |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-03-001                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH) |           |                 |           |                        |              |           |             | Service ATA:32   |
| PN:2317-3000-403                                                           | MOS                                                               | 14-May-25 | 120 (+1m/-1m)   | 14-May-35 | 14-Jun-35              | 3619 d (+31) | OVERHAUL  |             |                  |
| SN:00457                                                                   | HRS                                                               | 2086.2    |                 |           |                        |              |           |             |                  |
|                                                                            | AFL                                                               | 1243      | 12000 (+30/-30) | 13243     | 13273                  | 11991 (+30)  |           |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                   |           |                 |           |                        |              |           |             |                  |
| 32-11-03-002                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH) |           |                 |           |                        |              |           |             | Service ATA:32   |
| PN:2317-3000-403                                                           | MOS                                                               | 14-May-25 | 120 (+1m/-1m)   | 14-May-35 | 14-Jun-35              | 3619 d (+31) | OVERHAUL  |             |                  |
| SN:00460                                                                   | HRS                                                               | 2086.2    |                 |           |                        |              |           |             |                  |
|                                                                            | AFL                                                               | 1243      | 12000 (+30/-30) | 13243     | 13273                  | 11991 (+30)  |           |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                   |           |                 |           |                        |              |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                             | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------------------------------------------------------------|-----------------|----------|------------------------|-----------|--------------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-11-03-004                                                               |         | SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER                   |                 |          |                        |           |              | Service     | ATA:32   |
|                                                                            | MOS     | 14-May-25                                                       | 12 (+1m/-1m)    |          | 14-May-26              | 14-Jun-26 | 332 d (+31)  |             |          |
|                                                                            | HRS     | 2086.2                                                          |                 |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                            | 650 (+30/-30)   |          | 1893                   | 1923      | 641 (+30)    |             |          |
| PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02                             |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-11-04-001                                                               |         | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH) |                 |          |                        |           |              | Service     | ATA:32   |
| PN:2317-1500-405                                                           | MOS     | 14-May-25                                                       | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |          |
| SN:00212                                                                   | HRS     | 2086.2                                                          |                 |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                            | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |          |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-11-04-002                                                               |         | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH) |                 |          |                        |           |              | Service     | ATA:32   |
| PN:2317-1500-406                                                           | MOS     | 14-May-25                                                       | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |          |
| SN:00215                                                                   | HRS     | 2086.2                                                          |                 |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                            | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |          |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-20-01                                                                   |         | NOSE LANDING GEAR                                               |                 |          |                        |           |              | Component   | ATA:32   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15                                                       | O/C             | TSN 0    |                        |           |              |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0                                                               |                 | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 0                                                               |                 | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-200                                                                     |         | LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER                       |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2317-3000-403                                                           | MOS/MSC | 14-May-25                                                       | O/C             | TSO 1    |                        |           |              |             |          |
| SN:00457                                                                   | HRS     | 2086.2                                                          |                 | TSO 0    |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                            |                 | TSO 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |         |                                                                 |                 |          |                        |           |              |             |          |
| 32-200                                                                     |         | RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER                      |                 |          |                        |           |              | Component   | ATA:32   |
| PN:2317-3000-403                                                           | MOS/MSC | 14-May-25                                                       | O/C             | TSO 1    |                        |           |              |             |          |
| SN:00460                                                                   | HRS     | 2086.2                                                          |                 | TSO 0    |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                            |                 | TSO 0    |                        |           |              |             |          |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |         |                                                                 |                 |          |                        |           |              |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                     |           |          |          |                        |           |           |             |                  |
| 32-201                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3011-001                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1553282/001                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 32-201                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER     |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3011-001                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1545722/001                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 32-202                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3021-001                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541535/001                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 32-202                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3021-001                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1548430/001                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 32-203                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3001-003                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541532/015                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 32-203                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-3001-003                                                           | MOS                                                 | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541532/009                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                  |           | 15548     |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                     | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------------|-----------|-----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-204                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT                |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2317-3004-001                                                           | MOS                                                      | 29-Apr-15 |                 | TSN 0    |                        |           |              | LIFE LIMIT  |                  |
| SN:1548912/009                                                             | HRS                                                      | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 0         | 16800           | TSN 0    | 16800                  |           | 15548        |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-204                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT               |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2317-3004-001                                                           | MOS                                                      | 29-Apr-15 |                 | TSN 0    |                        |           |              | LIFE LIMIT  |                  |
| SN:1548912/005                                                             | HRS                                                      | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 0         | 16800           | TSN 0    | 16800                  |           | 15548        |             |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-21-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR           |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                      | 14-May-25 | 12 (+1m/-1m)    |          |                        |           |              |             |                  |
|                                                                            | HRS                                                      | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 1243      |                 |          |                        |           |              |             |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-21-00-003                                                               | LUBRICATION OF NOSE LANDING GEAR                         |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                      | 14-May-25 | 12 (+1m/-1m)    |          | 14-May-26              | 14-Jun-26 | 332 d (+31)  |             |                  |
|                                                                            | HRS                                                      | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 1243      | 650 (+30/-30)   |          | 1893                   | 1923      | 641 (+30)    |             |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-21-01-001                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-5100-403                                                           | MOS                                                      | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00217                                                                   | HRS                                                      | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                          |           |                 |          |                        |           |              |             |                  |
| 32-21-02                                                                   | NLG RETRACTION ACTUATOR                                  |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2117-1000-401                                                           | MOS/MSC                                                  | 29-Apr-15 | O/C             | TSN 0    |                        |           |              |             |                  |
| SN:00094                                                                   | HRS                                                      | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                      | 0         |                 | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 32-21-02, AMM 32-21-02PROC. REF: AMM 32-21-02, AMM 32-21-02 |                                                          |           |                 |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                          | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------------|-----------|-----------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-03                                                                   | NLG DOWNLOCK ACTUATOR                                         |           |                 |          |                        |           |              |             | Component ATA:32 |
| PN:2117-2000-401                                                           | MOS/MSC                                                       | 29-Apr-15 | O/C             | TSN 0    |                        |           |              |             |                  |
| SN:00295                                                                   | HRS                                                           | 0         |                 | TSN 0    |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 0         |                 | TSN 0    |                        |           |              |             |                  |
| PROC. REF: AMM 32-21-03, AMM 32-21-03PROC. REF: AMM 32-21-03, AMM 32-21-03 |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-04-001                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY    |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-6500-403                                                           | MOS                                                           | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00215                                                                   | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-05-001                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER  |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-5170-403                                                           | MOS                                                           | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00223                                                                   | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-05-004                                                               | SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER                 |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                           | 14-May-25 | 12 (+1m/-1m)    |          | 14-May-26              | 14-Jun-26 | 332 d (+31)  |             |                  |
|                                                                            | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 650 (+30/-30)   |          | 1893                   | 1923      | 641 (+30)    |             |                  |
| PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03                             |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-06-005 <sup>S</sup>                                                  | VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER               |           |                 |          |                        |           |              |             | Service ATA:32   |
|                                                                            | MOS                                                           | 14-May-25 | 12 (+1m/-1m)    |          |                        |           |              |             |                  |
|                                                                            | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      |                 |          |                        |           |              |             |                  |
| PROC. REF: AMM 32-21-06PROC. REF: AMM 32-21-06                             |                                                               |           |                 |          |                        |           |              |             |                  |
| PKG:80                                                                     |                                                               |           |                 |          |                        |           |              |             |                  |
| 32-21-09-001                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY |           |                 |          |                        |           |              |             | Service ATA:32   |
| PN:2317-6000-403                                                           | MOS                                                           | 14-May-25 | 120 (+1m/-1m)   |          | 14-May-35              | 14-Jun-35 | 3619 d (+31) | OVERHAUL    |                  |
| SN:00220                                                                   | HRS                                                           | 2086.2    |                 |          |                        |           |              |             |                  |
|                                                                            | AFL                                                           | 1243      | 12000 (+30/-30) |          | 13243                  | 13273     | 11991 (+30)  |             |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                               |           |                 |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                           | C/W       | Interval | TSX/Adj.        | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------------------|-----------|----------|-----------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-23-03                                                                   | NLG DOOR - TORQUE TUBE ASSEMBLY                                |           |          |                 |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                                        | 29-Apr-15 | O/C      | TSN 0           |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                            | 0         |          | TSN 0           |                        |           |           |             |                  |
|                                                                            | AFL                                                            | 0         |          | TSN 0           |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-300                                                                     | LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR                    |           |          |                 |                        |           |           |             | Component ATA:32 |
| PN:2117-3000-601                                                           | MOS/MSC                                                        | 14-May-25 | O/C      | TSO 1           |                        |           |           |             |                  |
| SN:00455                                                                   | HRS                                                            | 2086.2    |          | TSO 0           |                        |           |           |             |                  |
|                                                                            | AFL                                                            | 1243      |          | TSO 0           |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-300                                                                     | RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR                   |           |          |                 |                        |           |           |             | Component ATA:32 |
| PN:2117-3000-601                                                           | MOS/MSC                                                        | 31-Jan-25 | O/C      | TSO 33          |                        |           |           |             |                  |
| SN:00502                                                                   | HRS                                                            | 2062.9    |          | TSN 25.7, TSO 0 |                        |           |           |             |                  |
|                                                                            | AFL                                                            | 1226      |          | TSN 6, TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-301                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER               |           |          |                 |                        |           |           |             | Component ATA:32 |
| PN:2117-3034-501                                                           | MOS                                                            |           |          | TSN 0           |                        |           |           | LIFE LIMIT  |                  |
| SN:1548220/001                                                             | HRS                                                            |           |          | TSN 0           |                        |           |           |             |                  |
|                                                                            | AFL                                                            | EFF       | 12000    | TSN 0           | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-301                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER              |           |          |                 |                        |           |           |             | Component ATA:32 |
| PN:2117-3034-501                                                           | MOS                                                            |           |          | TSN 0           |                        |           |           | LIFE LIMIT  |                  |
| SN:1515015/001                                                             | HRS                                                            |           |          | TSN 0           |                        |           |           |             |                  |
|                                                                            | AFL                                                            | EFF       | 12000    | TSN 0           | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |                 |                        |           |           |             |                  |
| 32-302                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON |           |          |                 |                        |           |           |             | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC                                                        | 29-Apr-15 | N/A      |                 |                        |           |           |             |                  |
| SN:1541222/007                                                             | HRS                                                            | 0         |          |                 |                        |           |           |             |                  |
|                                                                            | AFL                                                            | 0         |          |                 |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |                 |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-302                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC                                                         |           | N/A      |          |                        |           |           |             |                  |
| SN:1562838/009                                                             | HRS                                                             |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                             |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-303                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER          |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS/MSC                                                         | 29-Apr-15 | N/A      |          |                        |           |           |             |                  |
| SN:13049                                                                   | HRS                                                             | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                             | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-303                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER         |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3010-001                                                           | MOS                                                             | 31-Jan-25 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:17282                                                                   | HRS                                                             | 2062.9    |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                             | 1226      | 12000    |          | 13226                  |           | 11974     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-304                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD                     |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-3008-901                                                           | MOS                                                             |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:76450/0015                                                              | HRS                                                             |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                             | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-304                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD                    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-3008-901                                                           | MOS                                                             |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:75014/0025                                                              | HRS                                                             |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                             | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |
| 32-305                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON          |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-3009-007                                                           | MOS                                                             |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1555334/014                                                             | HRS                                                             |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                             | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |                                                                 |           |          |          |                        |           |           |             |          |
| 32-305                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2117-3009-007                                                           | MOS                                                             |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1497137/010                                                             | HRS                                                             |           |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                             | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |
| 32-306                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN             |           |          |          |                        |           |           | Service     | ATA:32   |
| PN:2117-3019-003                                                           | MOS/MSC                                                         | 29-Apr-15 | N/A      |          |                        |           |           |             |          |
| SN:1538133/008                                                             | HRS                                                             | 0         |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                             | 0         |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |
| 32-306                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN            |           |          |          |                        |           |           | Service     | ATA:32   |
| PN:2117-3019-001                                                           | MOS                                                             | 31-Jan-25 |          |          |                        |           |           | LIFE LIMIT  |          |
| SN:1467482/021                                                             | HRS                                                             | 2062.9    |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                             | 1226      | 12000    |          | 13226                  |           | 11974     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |
| 32-307                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE  |           |          |          |                        |           |           | Service     | ATA:32   |
| PN:2117-3007-003                                                           | MOS/MSC                                                         | 29-Apr-15 | N/A      |          |                        |           |           |             |          |
| SN:1534419/001                                                             | HRS                                                             | 0         |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                             | 0         |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |
| 32-307                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE |           |          |          |                        |           |           | Service     | ATA:32   |
| PN:2117-3007-003                                                           | MOS/MSC                                                         |           | N/A      |          |                        |           |           |             |          |
| SN:1604484/003                                                             | HRS                                                             |           |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                             |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |
| 32-308                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP                    |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2117-3011-001                                                           | MOS                                                             |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1544259/015                                                             | HRS                                                             |           |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                             | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |           |          |          |                        |           |           |             |          |
| 32-308 RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP                       |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2117-3011-001                                                           | MOS     |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1507924/004                                                             | HRS     |           |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-309 LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING                 |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2117-3013-001                                                           | MOS     |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1550531/006                                                             | HRS     |           |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-309 RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING                |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2117-3013-001                                                           | MOS     |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1519831/003                                                             | HRS     |           |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |          |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-31-01 LANDING GEAR CONTROL LEVER                                        |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:827101-7                                                                | MOS/MSC | 28-Jan-25 | O/C      |          |                        |           |           |             |          |
| SN:1143                                                                    | HRS     | 2061.3    |          |          |                        |           |           |             |          |
|                                                                            | AFL     | 1225      |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-31-01, AMM 32-31-01PROC. REF: AMM 32-31-01, AMM 32-31-01 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-31-04 CENTER FUSELAGE LANDING GEAR SELECTOR VALVE                       |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:7342-1                                                                  | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:0299T                                                                   | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-31-04, AMM 32-31-04PROC. REF: AMM 32-31-04, AMM 32-31-04 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-31-05 LH MLG UPLOCK BOX ASSY                                            |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2617-1000-401                                                           | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:00442                                                                   | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                    |           |          |          |                        |           |           |             |                  |
| 32-31-05                                                                   | NLG UPLOCK BOX ASSY                                |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2617-1000-401                                                           | MOS/MSC                                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00439                                                                   | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |                                                    |           |          |          |                        |           |           |             |                  |
| 32-31-05                                                                   | RH MLG UPLOCK BOX ASSY                             |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2617-1000-402                                                           | MOS/MSC                                            | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00282                                                                   | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |                                                    |           |          |          |                        |           |           |             |                  |
| 32-310                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-3015-001                                                           | MOS                                                |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1548330/008                                                             | HRS                                                |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                    |           |          |          |                        |           |           |             |                  |
| 32-310                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-3015-001                                                           | MOS                                                |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1510200/009                                                             | HRS                                                |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | EFF       | 12000    | TSN 0    | 12007 *                |           | 10755     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                    |           |          |          |                        |           |           |             |                  |
| 32-311                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:MTMKS14ALGA1                                                            | MOS                                                |           |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:00464                                                                   | HRS                                                |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | EFF       | 10500    | TSN 0    | 10507 *                |           | 9255      |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                    |           |          |          |                        |           |           |             |                  |
| 32-311                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END   |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:MTMKS14ALGA1                                                            | MOS                                                | 31-Jan-25 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:10028                                                                   | HRS                                                | 2062.9    |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                | 1226      | 10500    | TSN 0    | 11726                  |           | 10474     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                         |           |          |          |                        |           |           |             |                  |
| 32-312                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER  |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS                                                     | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:13049                                                                   | HRS                                                     | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         | 12000    |          | 12000                  |           | 10748     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 32-312                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3010-001                                                           | MOS/MSC                                                 |           | N/A      |          |                        |           |           |             |                  |
| SN:17282                                                                   | HRS                                                     |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                     |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 32-313                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS                                                     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         | 28000    | TSN 0    | 28000                  |           | 26748     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 32-313                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS                                                     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:UNKNOWN                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         | 28000    | TSN 0    | 28000                  |           | 26748     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 32-314                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN     |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3019-003                                                           | MOS                                                     | 29-Apr-15 |          |          |                        |           |           | LIFE LIMIT  |                  |
| SN:1538133/008                                                             | HRS                                                     | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                     | 0         | 12000    |          | 12000                  |           | 10748     |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 32-314                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN    |           |          |          |                        |           |           |             | Service ATA:32   |
| PN:2117-3019-001                                                           | MOS/MSC                                                 |           | N/A      |          |                        |           |           |             |                  |
| SN:1467482/021                                                             | HRS                                                     |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                     |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                             | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition   | Warranty       |
|----------------------------------------------------------------------------|------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|---------------|----------------|
| ATA 32 - LANDING GEAR                                                      |                                                                  |           |                |          |                        |           |              |               |                |
| 32-315                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE   |           |                |          |                        |           |              |               | Service ATA:32 |
| PN:2117-3007-003                                                           | MOS                                                              | 29-Apr-15 |                |          |                        |           |              | LIFE LIMIT    |                |
| SN:1534419/001                                                             | HRS                                                              | 0         |                |          |                        |           |              |               |                |
|                                                                            | AFL                                                              | 0         | 12000          |          | 12000                  |           | 10748        |               |                |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                        |           |              |               |                |
| 32-315                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE  |           |                |          |                        |           |              |               | Service ATA:32 |
| PN:2117-3007-003                                                           | MOS                                                              | 31-Jan-25 |                |          |                        |           |              | LIFE LIMIT    |                |
| SN:1604484/003                                                             | HRS                                                              | 2062.9    |                |          |                        |           |              |               |                |
|                                                                            | AFL                                                              | 1226      | 12000          |          | 13226                  |           | 11974        |               |                |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                        |           |              |               |                |
| 32-316                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON   |           |                |          |                        |           |              |               | Service ATA:32 |
| PN:2117-3001-003                                                           | MOS                                                              | 29-Apr-15 |                |          |                        |           |              | LIFE LIMIT    |                |
| SN:1541222/007                                                             | HRS                                                              | 0         |                |          |                        |           |              |               |                |
|                                                                            | AFL                                                              | 0         | 12000          |          | 12000                  |           | 10748        |               |                |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                        |           |              |               |                |
| 32-316                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON  |           |                |          |                        |           |              |               | Service ATA:32 |
| PN:2117-3001-003                                                           | MOS                                                              | 31-Jan-25 |                |          |                        |           |              | LIFE LIMIT    |                |
| SN:1562838/009                                                             | HRS                                                              | 2062.9    |                |          |                        |           |              |               |                |
|                                                                            | AFL                                                              | 1226      | 12000          |          | 13226                  |           | 11974        |               |                |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                        |           |              |               |                |
| 32-35-00-001                                                               | FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM      |           |                |          |                        |           |              |               | Service ATA:32 |
|                                                                            | MOS                                                              | 14-May-25 | 24 (+30d/-30d) |          | 14-May-27              | 13-Jun-27 | 697 d (+30)  | AIRWORTHINESS |                |
|                                                                            | HRS                                                              | 2086.2    | 1600 (+30/-30) |          | 3686.2                 | 3716.2    | 1586.2 (+30) |               |                |
|                                                                            | AFL                                                              | 1243      |                |          |                        |           |              |               |                |
| PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00                             |                                                                  |           |                |          |                        |           |              |               |                |
| 32-35-00-002                                                               | GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES |           |                |          |                        |           |              |               | Service ATA:32 |
|                                                                            | MOS                                                              | 14-May-25 | 24 (+30d/-30d) |          | 14-May-27              | 13-Jun-27 | 697 d (+30)  | AIRWORTHINESS |                |
|                                                                            | HRS                                                              | 2086.2    | 1600 (+30/-30) |          | 3686.2                 | 3716.2    | 1586.2 (+30) |               |                |
|                                                                            | AFL                                                              | 1243      |                |          |                        |           |              |               |                |
| PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00                             |                                                                  |           |                |          |                        |           |              |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |           |          |          |                        |           |           |             |          |
| 32-35-02 CENTER FUSELAGE FREE FALL VALVE                                   |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:7343-2                                                                  | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:0289T                                                                   | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-35-02, AMM 32-35-02PROC. REF: AMM 32-35-02, AMM 32-35-02 |         |           |          |          |                        |           |           |             |          |
| 32-400 NOSE LANDING GEAR SHOCK STRUT                                       |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5100-403                                                           | MOS/MSC | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |          |
| SN:00217                                                                   | HRS     | 2086.2    |          | TSO 0    |                        |           |           |             |          |
|                                                                            | AFL     | 1243      |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |         |           |          |          |                        |           |           |             |          |
| 32-401 NOSE LANDING GEAR SHOCK STRUT AXLE BOLT                             |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2310-1144-005                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:00249                                                                   | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |         |           |          |          |                        |           |           |             |          |
| 32-402 NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT                    |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2310-1173-001                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1540012/009                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-06, AMM 32-21-06PROC. REF: AMM 32-21-06, AMM 32-21-06 |         |           |          |          |                        |           |           |             |          |
| 32-403 LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN                       |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5105-001                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1541466/001                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |         |           |          |          |                        |           |           |             |          |
| 32-403 RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN                      |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5105-001                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1545466/012                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                 |           |          |          |                        |           |           |             |                  |
| 32-404                                                                     | NOSE LANDING GEAR SHOCK STRUT MAIN FITTING      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-5301-503                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1542992/001                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-405                                                                     | NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER     |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2117-4000-403                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:00300                                                                   | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-06, AMM 32-21-06PROC. REF: AMM 32-21-06, AMM 32-21-06 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-406                                                                     | NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE        |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-5101-001                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1540020/006                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-407                                                                     | LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-5201-001                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1545445/019                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-407                                                                     | UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-5201-001                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1545445/005                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                 |           |          |          |                        |           |           |             |                  |
| 32-408                                                                     | NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN    |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6003-001                                                           | MOS                                             | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1528159/001                                                             | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                |           |                |          |                        |           |           |             |                  |
| 32-409                                                                     | NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:2310-1165-001                                                           | MOS                                            | 29-Apr-15 |                | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1548248/010                                                             | HRS                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         | 11200          | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                |           |                |          |                        |           |           |             |                  |
| 32-41-00                                                                   | BRAKE CONTROL UNIT                             |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00100-10                                                             | MOS/MSC                                        | 19-Apr-17 | O/C            |          |                        |           |           |             |                  |
| SN:343400431                                                               | HRS                                            | 682.6     |                |          |                        |           |           |             |                  |
|                                                                            | AFL                                            | 388       |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-01, AMM 32-41-01PROC. REF: AMM 32-41-01, AMM 32-41-01 |                                                |           |                |          |                        |           |           |             |                  |
| 32-41-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM          |           |                |          |                        |           |           |             | Service ATA:32   |
|                                                                            | MOS                                            | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                            | 0         | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-00PROC. REF: AMM 32-41-00                             |                                                |           |                |          |                        |           |           |             |                  |
| 32-41-01                                                                   | BRAKE CONTROL UNIT TRAY                        |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00134-01                                                             | MOS/MSC                                        | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:1100                                                                    | HRS                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-01, AMM 32-41-01PROC. REF: AMM 32-41-01, AMM 32-41-01 |                                                |           |                |          |                        |           |           |             |                  |
| 32-41-02                                                                   | LH BRAKE PEDAL TRANSDUCER                      |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:Q3008                                                                   | MOS/MSC                                        | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:132517                                                                  | HRS                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02 |                                                |           |                |          |                        |           |           |             |                  |
| 32-41-02                                                                   | RH BRAKE PEDAL TRANSDUCER                      |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:Q3008                                                                   | MOS/MSC                                        | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:132518                                                                  | HRS                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02 |                                                |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                         | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|---------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |                                             |                |          |                        |           |           |             |          |
| 32-41-02-001 <sup>S</sup>                                                  |         | OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER |                |          |                        |           |           | Service     | ATA:32   |
|                                                                            | MOS     | 29-Apr-15                                   |                |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                           | 6400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL     | 0                                           |                |          |                        |           |           |             |          |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |         |                                             |                |          |                        |           |           |             | PKG:60   |
| 32-41-02-001 <sup>S</sup>                                                  |         | OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER |                |          |                        |           |           | Service     | ATA:32   |
|                                                                            | MOS     | 29-Apr-15                                   |                |          |                        |           |           |             |          |
|                                                                            | HRS     | 0                                           | 6400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL     | 0                                           |                |          |                        |           |           |             |          |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |         |                                             |                |          |                        |           |           |             | PKG:60   |
| 32-41-02-002 <sup>S</sup>                                                  |         | FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER  |                |          |                        |           |           | Service     | ATA:32   |
|                                                                            | MOS     | 14-Apr-20                                   |                |          |                        |           |           |             |          |
|                                                                            | HRS     | 1483.9                                      | 1600 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL     | 855                                         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |         |                                             |                |          |                        |           |           |             | PKG:10   |
| 32-41-02-002 <sup>S</sup>                                                  |         | FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER  |                |          |                        |           |           | Service     | ATA:32   |
|                                                                            | MOS     | 14-Apr-20                                   |                |          |                        |           |           |             |          |
|                                                                            | HRS     | 1483.9                                      | 1600 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL     | 855                                         |                |          |                        |           |           |             |          |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |         |                                             |                |          |                        |           |           |             | PKG:10   |
| 32-41-06                                                                   |         | LH MLG WHEEL SPEED TRANSDUCER               |                |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00103-01                                                             | MOS/MSC | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |          |
| SN:019NR                                                                   | HRS     | 0                                           |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                           |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06 |         |                                             |                |          |                        |           |           |             |          |
| 32-41-06                                                                   |         | RH MLG WHEEL SPEED TRANSDUCER               |                |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00103-01                                                             | MOS/MSC | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |          |
| SN:017NR                                                                   | HRS     | 0                                           |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                           |                | TSN 0    |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit    | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                                                                              |         |           |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06                                                         |         |           |                |          |                        |           |           |             |                  |
| 32-41-07 BRAKE CONTROL MODULE                                                                                                      |         |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00101-02                                                                                                                     | MOS/MSC | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:42MK                                                                                                                            | HRS     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL     | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-41-07, AMM 32-41-07PROC. REF: AMM 32-41-07, AMM 32-41-07                                                         |         |           |                |          |                        |           |           |             |                  |
| 32-410 NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN                                                                          |         |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:57675-1                                                                                                                         | MOS     | 29-Apr-15 |                | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:00727                                                                                                                           | HRS     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL     | 0         | 11200          | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07                                                         |         |           |                |          |                        |           |           |             |                  |
| 32-411 NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT                                                                              |         |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:2310-1183-001                                                                                                                   | MOS     | 29-Apr-15 |                | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:00210                                                                                                                           | HRS     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL     | 0         | 11200          | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07                                                         |         |           |                |          |                        |           |           |             |                  |
| 32-412 NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK                                                                            |         |           |                |          |                        |           |           |             | Component ATA:32 |
| PN:2317-5191-001                                                                                                                   | MOS     | 29-Apr-15 |                | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1550786/001                                                                                                                     | HRS     | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL     | 0         | 11200          | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03 |         |           |                |          |                        |           |           |             |                  |
| 32-43-00-001 <sup>S</sup> FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM                                                      |         |           |                |          |                        |           |           |             | Service ATA:32   |
|                                                                                                                                    | MOS     | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                                                                                    | HRS     | 0         | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL     | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00                                                                                     |         |           |                |          |                        |           |           |             |                  |
| PKG:50                                                                                                                             |         |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                         | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-01-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM |                |          |                        |           |           |             | Service ATA:32   |
|                                                                            | MOS          | 29-Apr-15                                                   |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                           | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00                             |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-02                                                                   |              | PRESSURE SWITCH                                             |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00108-01                                                             | MOS/MSC      | 29-Apr-15                                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:010NP                                                                   | HRS          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 29-12-03, AMM 29-12-03PROC. REF: AMM 29-12-03, AMM 29-12-03 |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-04                                                                   |              | EMERGENCY/PARKING BRAKE ACCUMULATOR                         |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00106-01                                                             | MOS/MSC      | 29-Apr-15                                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:289                                                                     | HRS          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-04, AMM 32-43-04PROC. REF: AMM 32-43-04, AMM 32-43-04 |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-05                                                                   |              | EMERGENCY/PARKING BRAKE VALVE                               |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00107-01                                                             | MOS/MSC      | 29-Apr-15                                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:037NQ                                                                   | HRS          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-02PROC. REF: AMM 32-43-02                             |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-06                                                                   |              | PRESSURE TRANSDUCER                                         |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00109-01                                                             | MOS/MSC      | 29-Apr-15                                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8067-12-36                                                              | HRS          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-06, AMM 32-43-06PROC. REF: AMM 32-43-06, AMM 32-43-06 |              |                                                             |                |          |                        |           |           |             |                  |
| 32-43-08                                                                   |              | THERMAL RELIEF VALVE                                        |                |          |                        |           |           |             | Component ATA:32 |
| PN:DAP00110-01                                                             | MOS/MSC      | 29-Apr-15                                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:301                                                                     | HRS          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-43-08, AMM 32-43-08PROC. REF: AMM 32-43-08, AMM 32-43-08 |              |                                                             |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                 | Unit    | C/W       | Interval      | TSX/Adj.       | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition   | Warranty |
|-----------------------------------------------------------------------------------------|---------|-----------|---------------|----------------|------------------------|-----------|-------------|---------------|----------|
| ATA 32 - LANDING GEAR                                                                   |         |           |               |                |                        |           |             |               |          |
| 32-43-10 EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE                                     |         |           |               |                |                        |           |             | Component     | ATA:32   |
| PN:DAP00202-01                                                                          | MOS/MSC | 29-Apr-15 | O/C           | TSN 0          |                        |           |             |               |          |
| SN:365                                                                                  | HRS     | 0         |               | TSN 0          |                        |           |             |               |          |
|                                                                                         | AFL     | 0         |               | TSN 0          |                        |           |             |               |          |
| PROC. REF: AMM 32-43-02, AMM 32-43-02PROC. REF: AMM 32-43-02, AMM 32-43-02              |         |           |               |                |                        |           |             |               |          |
| 32-43-11 FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE                               |         |           |               |                |                        |           |             | Component     | ATA:32   |
| PN:2216-0001-401                                                                        | MOS/MSC | 29-Apr-15 | O/C           | TSN 0          |                        |           |             |               |          |
| SN:00627                                                                                | HRS     | 0         |               | TSN 0          |                        |           |             |               |          |
|                                                                                         | AFL     | 0         |               | TSN 0          |                        |           |             |               |          |
| PROC. REF: AMM 32-43-11, AMM 32-43-11PROC. REF: AMM 32-43-11, AMM 32-43-11              |         |           |               |                |                        |           |             |               |          |
| 32-43-11-001 OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE |         |           |               |                |                        |           |             | Service       | ATA:32   |
|                                                                                         | MOS     | 29-Apr-22 |               |                |                        |           |             | AIRWORTHINESS |          |
|                                                                                         | HRS     | 1728.6    | 800 (+30/-30) |                | 2528.6                 | 2558.6    | 428.6 (+30) |               |          |
|                                                                                         | AFL     | 989       |               |                |                        |           |             |               |          |
| PROC. REF: AMM 32-43-11PROC. REF: AMM 32-43-11                                          |         |           |               |                |                        |           |             |               |          |
| 32-45-00 LH MAIN WHEEL AND TIRE ASSY                                                    |         |           |               |                |                        |           |             | Component     | ATA:32   |
| PN:505-19517-611                                                                        | MOS/MSC | 05-Dec-23 | O/C           | TSO 1          |                        |           |             |               |          |
| SN:5088SJ                                                                               | HRS     | 1910      |               | TSO 0          |                        |           |             |               |          |
|                                                                                         | AFL     | 1101      |               | TSO 0          |                        |           |             |               |          |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02              |         |           |               |                |                        |           |             |               |          |
| 32-45-00 NOSE WHEEL AND TIRE ASSY                                                       |         |           |               |                |                        |           |             | Component     | ATA:32   |
| PN:505-19601-607                                                                        | MOS/MSC | 12-Jun-24 | O/C           | TSO 0          |                        |           |             |               |          |
| SN:5034LQ                                                                               | HRS     | 1976.5    |               | TSO 0          |                        |           |             |               |          |
|                                                                                         | AFL     |           |               | TSO 0          |                        |           |             |               |          |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02              |         |           |               |                |                        |           |             |               |          |
| 32-45-00 RH MAIN WHEEL AND TIRE ASSY                                                    |         |           |               |                |                        |           |             | Component     | ATA:32   |
| PN:505-19517-611                                                                        | MOS/MSC | 05-Dec-23 | O/C           | TSR 1          |                        |           |             |               |          |
| SN:5200TH                                                                               | HRS     | 1910      |               | TSR 0          |                        |           |             |               |          |
|                                                                                         | AFL     | 1101      |               | TSO 759, TSR 0 |                        |           |             |               |          |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02              |         |           |               |                |                        |           |             |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                          | C/W       | Interval | TSX/Adj.       | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------------------|-----------|----------|----------------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-01                                                                   | LEFT MAIN WHEEL                                               |           |          |                |                        |           |           |             | Component ATA:32 |
| PN:PN-UNKNOWN                                                              | MOS/MSC                                                       | 05-Dec-23 | O/C      | TSO 1          |                        |           |           |             |                  |
| SN:5088SJ                                                                  | HRS                                                           | 1910      |          | TSO 0          |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      |          | TSO 0          |                        |           |           |             |                  |
| PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01 |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-01                                                                   | RIGHT MAIN WHEEL                                              |           |          |                |                        |           |           |             | Component ATA:32 |
| PN:PN-UNKNOWN                                                              | MOS/MSC                                                       | 05-Dec-23 | O/C      | TSR 1          |                        |           |           |             |                  |
| SN:5200TH                                                                  | HRS                                                           | 1910      |          | TSR 0          |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      |          | TSO 759, TSR 0 |                        |           |           |             |                  |
| PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01 |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-01-003                                                               | RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY |           |          |                |                        |           |           |             | Service ATA:32   |
| PN:PN-UNKNOWN                                                              | MOS                                                           | 05-Dec-23 |          |                |                        |           |           |             |                  |
| SN:5088SJ                                                                  | HRS                                                           | 1910      |          |                |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      | 1500     |                | 2601                   |           | 1349      |             |                  |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-01-003                                                               | RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY |           |          |                |                        |           |           |             | Service ATA:32   |
| PN:PN-UNKNOWN                                                              | MOS                                                           | 05-Dec-23 |          |                |                        |           |           |             |                  |
| SN:5200TH                                                                  | HRS                                                           | 1910      |          |                |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      | 1500     | TAC 759        | 1842                   |           | 590       |             |                  |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-02                                                                   | LEFT MAIN WHEEL TIRE                                          |           |          |                |                        |           |           |             | Component ATA:32 |
| PN:258K63-2                                                                | MOS/MSC                                                       | 05-Dec-23 | O/C      | TSN 0          |                        |           |           |             |                  |
| SN:23570569                                                                | HRS                                                           | 1910      |          | TSN 0          |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      |          | TSN 0          |                        |           |           |             |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |                                                               |           |          |                |                        |           |           |             |                  |
| 32-45-02                                                                   | RIGHT MAIN WHEEL TIRE                                         |           |          |                |                        |           |           |             | Component ATA:32 |
| PN:258K63-2                                                                | MOS/MSC                                                       | 05-Dec-23 | O/C      | TSN 0          |                        |           |           |             |                  |
| SN:30730589                                                                | HRS                                                           | 1910      |          | TSN 0          |                        |           |           |             |                  |
|                                                                            | AFL                                                           | 1101      |          | TSN 0          |                        |           |           |             |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |                                                               |           |          |                |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-03                                                                   | LH MLG HUB CAP                                             |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00131-02                                                             | MOS/MSC                                                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:62NK                                                                    | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-45-03, AMM 32-45-03PROC. REF: AMM 32-45-03, AMM 32-45-03 |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-03                                                                   | RH MLG HUB CAP                                             |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00131-02                                                             | MOS/MSC                                                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:58NK                                                                    | HRS                                                        | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL                                                        | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-45-03, AMM 32-45-03PROC. REF: AMM 32-45-03, AMM 32-45-03 |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-11                                                                   | NOSE WHEEL                                                 |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:PN                                                                      | MOS/MSC                                                    | 12-Jun-24 | O/C      | TSO 0    |                        |           |           |             |          |
| SN:5034LQ                                                                  | HRS                                                        | 1976.5    |          | TSO 0    |                        |           |           |             |          |
|                                                                            | AFL                                                        |           |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11 |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-11-003                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY |           |          |          |                        |           |           | Service     | ATA:32   |
| PN:PN                                                                      | MOS/MSC                                                    | 12-Jun-24 | T/C      |          |                        |           |           |             |          |
| SN:5034LQ                                                                  | HRS                                                        | 1976.5    |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                        |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-12                                                                   | NOSE TIRE                                                  |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:156E23-1                                                                | MOS/MSC                                                    | 12-Jun-24 | O/C      |          |                        |           |           |             |          |
| SN:33190653                                                                | HRS                                                        | 1976.5    |          |          |                        |           |           |             |          |
|                                                                            | AFL                                                        |           |          |          |                        |           |           |             |          |
| PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11 |                                                            |           |          |          |                        |           |           |             |          |
| 32-45-21                                                                   | LH MLG CARBON BRAKE ASSY                                   |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00097-04                                                             | MOS/MSC                                                    | 07-Aug-17 | O/C      | TSR 2    |                        |           |           |             |          |
| SN:129KQ                                                                   | HRS                                                        | 773.7     |          | TSR 0    |                        |           |           |             |          |
|                                                                            | AFL                                                        | 444       |          | TSR 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21 |                                                            |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                               | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|---------------------------------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |                                                   |          |          |                        |           |           |             |          |
| 32-45-21                                                                   |         | RH MLG CARBON BRAKE ASSY                          |          |          |                        |           |           | Component   | ATA:32   |
| PN:DAP00097-04                                                             | MOS/MSC | 07-Aug-17                                         | O/C      | TSO 1    |                        |           |           |             |          |
| SN:5068NV                                                                  | HRS     | 773.7                                             |          | TSO 0    |                        |           |           |             |          |
|                                                                            | AFL     | 444                                               |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21 |         |                                                   |          |          |                        |           |           |             |          |
| 32-500                                                                     |         | NOSE LANDING GEAR SHOCK ABSORBER                  |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5170-403                                                           | MOS/MSC | 14-May-25                                         | O/C      | TSO 1    |                        |           |           |             |          |
| SN:00223                                                                   | HRS     | 2086.2                                            |          | TSO 0    |                        |           |           |             |          |
|                                                                            | AFL     | 1243                                              |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                   |          |          |                        |           |           |             |          |
| 32-501                                                                     |         | NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK       |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5227-501                                                           | MOS     | 29-Apr-15                                         |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1547716/001                                                             | HRS     | 0                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                 | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                   |          |          |                        |           |           |             |          |
| 32-502                                                                     |         | NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING    |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5113-005                                                           | MOS     | 29-Apr-15                                         |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1541549/003                                                             | HRS     | 0                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                 | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                   |          |          |                        |           |           |             |          |
| 32-503                                                                     |         | NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-5237-501                                                           | MOS     | 29-Apr-15                                         |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1535213/003                                                             | HRS     | 0                                                 |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0                                                 | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                   |          |          |                        |           |           |             |          |
| 32-600                                                                     |         | NOSE LANDING GEAR DRAG BRACE                      |          |          |                        |           |           | Component   | ATA:32   |
| PN:2317-6000-403                                                           | MOS/MSC | 14-May-25                                         | O/C      | TSO 1    |                        |           |           |             |          |
| SN:00220                                                                   | HRS     | 2086.2                                            |          | TSO 0    |                        |           |           |             |          |
|                                                                            | AFL     | 1243                                              |          | TSO 0    |                        |           |           |             |          |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |         |                                                   |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                               |           |          |          |                        |           |           |             |                  |
| 32-601                                                                     | NOSE LANDING GEAR UPPER DRAG BRACE            |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6114-501                                                           | MOS                                           | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541979/001                                                             | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                        |           |           |             |                  |
| 32-602                                                                     | NOSE LANDING GEAR LOWER DRAG BRACE            |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6201-001                                                           | MOS                                           | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1528387/004                                                             | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                        |           |           |             |                  |
| 32-603                                                                     | LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6001-001                                                           | MOS                                           | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1540751/002                                                             | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                        |           |           |             |                  |
| 32-603                                                                     | RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6001-001                                                           | MOS                                           | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1540749/003                                                             | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                        |           |           |             |                  |
| 32-604                                                                     | NOSE LANDING GEAR DRAG BRACE PIN              |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6003-001                                                           | MOS                                           | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1515572/006                                                             | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                        |           |           |             |                  |
| 32-61-01                                                                   | LH WING PROXIMITY SWITCH                      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:38430                                                                   | HRS                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|----------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                              |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 1 LEFT MLG PROXIMITY SWITCH  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                       | MOS/MSC                          | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:38415                                           | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 1 NLG PROXIMITY SWITCH       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                       | MOS/MSC                          | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:38436                                           | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 1 RIGHT MLG PROXIMITY SWITCH |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                       | MOS/MSC                          | 28-Jan-25 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:63735                                           | HRS                              | 2061.3    |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 1225      |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 2 LEFT MLG PROXIMITY SWITCH  |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                          | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 2 NLG PROXIMITY SWITCH       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                       | MOS/MSC                          | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:38601                                           | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |
| 32-61-01                                           | NO. 2 RIGHT MLG PROXIMITY SWITCH |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                              | MOS/MSC                          | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | AFL                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                      |           |          |          |                        |           |           |             |                  |
| 32-61-01                                                                   | NO. 3 LEFT MLG PROXIMITY SWITCH      |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                              | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                        |           |           |             |                  |
| 32-61-01                                                                   | NO. 3 RIGHT MLG PROXIMITY SWITCH     |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                              | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                        |           |           |             |                  |
| 32-61-01                                                                   | RH WING PROXIMITY SWITCH             |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                              | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:38428                                                                   | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                        |           |           |             |                  |
| 32-700                                                                     | NOSE LANDING GEAR LOCKING STAY       |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6500-403                                                           | MOS/MSC                              | 14-May-25 | O/C      | TSO 1    |                        |           |           |             |                  |
| SN:00215                                                                   | HRS                                  | 2086.2    |          | TSO 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 1243      |          | TSO 0    |                        |           |           |             |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                        |           |           |             |                  |
| 32-701                                                                     | NOSE LANDING GEAR UPPER LOCKING STAY |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6521-003                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1541576/007                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                        |           |           |             |                  |
| 32-702                                                                     | NOSE LANDING GEAR LOWER LOCKING STAY |           |          |          |                        |           |           |             | Component ATA:32 |
| PN:2317-6531-001                                                           | MOS                                  | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:1552520/005                                                             | HRS                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                  | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 32 - LANDING GEAR                                                      |         |           |          |          |                        |           |           |             |          |
| 32-703 LOWER NOSE LANDING GEAR LOCKING STAY BOLT                           |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2310-1734-001                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1543265/016                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 32-703 UPPER NOSE LANDING GEAR LOCKING STAY BOLT                           |         |           |          |          |                        |           |           | Component   | ATA:32   |
| PN:2310-1734-001                                                           | MOS     | 29-Apr-15 |          | TSN 0    |                        |           |           | LIFE LIMIT  |          |
| SN:1543265/015                                                             | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         | 11200    | TSN 0    | 11200                  |           | 9948      |             |          |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| ATA 33 - LIGHTS                                                            |         |           |          |          |                        |           |           |             |          |
| 33-01-01 OVERHEAD LIGHTS CONTROL PANEL                                     |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:441-43246-002                                                           | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:1218                                                                    | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-01-01, AMM 33-01-01PROC. REF: AMM 33-01-01, AMM 33-01-01 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 33-12-01 COCKPIT DIMMER                                                    |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:81-01760-002                                                            | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:0672                                                                    | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-12-01, AMM 33-12-01PROC. REF: AMM 33-12-01, AMM 33-12-01 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 33-12-02 INSC ILLUM - TEST PANEL                                           |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:441-42631-003                                                           | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:1278                                                                    | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 33-12-02, AMM 33-12-02PROC. REF: AMM 33-12-02, AMM 33-12-02 |         |           |          |          |                        |           |           |             |          |
|                                                                            |         |           |          |          |                        |           |           |             |          |
| 33-13-01 LH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY     |         |           |          |          |                        |           |           | Component   | ATA:33   |
| PN:PN                                                                      | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                 | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 33 - LIGHTS                                                                                                                    |                                                               |           |          |          |                        |           |           |             |                  |
| 33-13-01                                                                                                                           | RH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                               |           |          |          |                        |           |           |             |                  |
| 33-31-02                                                                                                                           | NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS               |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:PN                                                                                                                              | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                               |           |          |          |                        |           |           |             |                  |
| 33-42-01                                                                                                                           | LH LWR FWD TAXI LIGHT ASSY                                    |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:81017-3                                                                                                                         | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:000343                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01 |                                                               |           |          |          |                        |           |           |             |                  |
| 33-42-01                                                                                                                           | RH LWR FWD TAXI LIGHT ASSY                                    |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:81017-4                                                                                                                         | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:000455                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01 |                                                               |           |          |          |                        |           |           |             |                  |
| 33-47-01                                                                                                                           | LEFT LANDING LIGHT ASSY                                       |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:81017-5                                                                                                                         | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:000321                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01 |                                                               |           |          |          |                        |           |           |             |                  |
| 33-47-01                                                                                                                           | RIGHT LANDING LIGHT ASSY                                      |           |          |          |                        |           |           |             | Component ATA:33 |
| PN:81017-6                                                                                                                         | MOS/MSC                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:000326                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01 |                                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-----------|-----------------|----------|------------------------|-----------|------------|-------------|------------------|
| ATA 33 - LIGHTS                                                                                                                    |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00                                                                                                                           | LEFT NO. 1 NAVIGATION LIGHT         |           |                 |          |                        |           |            |             | Component ATA:33 |
| PN:84004-7                                                                                                                         | MOS/MSC                             | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:000691                                                                                                                          | HRS                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00                                                                                                                           | LEFT NO. 2 NAVIGATION LIGHT         |           |                 |          |                        |           |            |             | Component ATA:33 |
| PN:84075-1                                                                                                                         | MOS/MSC                             | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:000141                                                                                                                          | HRS                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00                                                                                                                           | RIGHT NO. 1 NAVIGATION LIGHT        |           |                 |          |                        |           |            |             | Component ATA:33 |
| PN:84004-7                                                                                                                         | MOS/MSC                             | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:000688                                                                                                                          | HRS                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00                                                                                                                           | RIGHT NO. 2 NAVIGATION LIGHT        |           |                 |          |                        |           |            |             | Component ATA:33 |
| PN:84075-2                                                                                                                         | MOS/MSC                             | 29-Apr-15 | O/C             | TSN 0    |                        |           |            |             |                  |
| SN:000174                                                                                                                          | HRS                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00-001                                                                                                                       | DISCARD LEFT NO. 1 NAVIGATION LIGHT |           |                 |          |                        |           |            |             | Service ATA:33   |
| PN:84004-7                                                                                                                         | MOS                                 | 29-Apr-15 |                 |          |                        |           |            |             |                  |
| SN:000691                                                                                                                          | HRS                                 | 0         | 12000 (+30/-30) |          | 12000                  | 12030     | 9900 (+30) |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 |          |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                     |                                     |           |                 |          |                        |           |            |             |                  |
| 33-48-00-001                                                                                                                       | DISCARD LEFT NO. 2 NAVIGATION LIGHT |           |                 |          |                        |           |            |             | Service ATA:33   |
| PN:84075-1                                                                                                                         | MOS                                 | 29-Apr-15 |                 |          |                        |           |            |             |                  |
| SN:000141                                                                                                                          | HRS                                 | 0         | 12000 (+30/-30) |          | 12000                  | 12030     | 9900 (+30) |             |                  |
|                                                                                                                                    | AFL                                 | 0         |                 |          |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                     |                                     |           |                 |          |                        |           |            |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                                   | C/W       | Interval        | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty       |
|------------------------------------------------|--------------------------------------------------------|-----------|-----------------|----------|------------------------|-----------|------------|-------------|----------------|
| ATA 33 - LIGHTS                                |                                                        |           |                 |          |                        |           |            |             |                |
| 33-48-00-001                                   | DISCARD RIGHT NO. 1 NAVIGATION LIGHT                   |           |                 |          |                        |           |            |             | Service ATA:33 |
| PN:84004-7                                     | MOS                                                    | 29-Apr-15 |                 |          |                        |           |            |             |                |
| SN:000688                                      | HRS                                                    | 0         | 12000 (+30/-30) |          | 12000                  | 12030     | 9900 (+30) |             |                |
|                                                | AFL                                                    | 0         |                 |          |                        |           |            |             |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                        |           |                 |          |                        |           |            |             |                |
| 33-48-00-001                                   | DISCARD RIGHT NO. 2 NAVIGATION LIGHT                   |           |                 |          |                        |           |            |             | Service ATA:33 |
| PN:84075-2                                     | MOS                                                    | 29-Apr-15 |                 |          |                        |           |            |             |                |
| SN:000174                                      | HRS                                                    | 0         | 12000 (+30/-30) |          | 12000                  | 12030     | 9900 (+30) |             |                |
|                                                | AFL                                                    | 0         |                 |          |                        |           |            |             |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                        |           |                 |          |                        |           |            |             |                |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT  |           |                 |          |                        |           |            |             | Service ATA:33 |
|                                                | MOS                                                    | 29-Apr-15 |                 |          |                        |           |            |             |                |
|                                                | HRS                                                    | 0         | 2400 (+30/-30)  |          |                        |           |            |             |                |
|                                                | AFL                                                    | 0         |                 |          |                        |           |            |             |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                        |           |                 |          |                        |           |            |             | PKG:20         |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT  |           |                 |          |                        |           |            |             | Service ATA:33 |
|                                                | MOS                                                    | 29-Apr-15 |                 |          |                        |           |            |             |                |
|                                                | HRS                                                    | 0         | 2400 (+30/-30)  |          |                        |           |            |             |                |
|                                                | AFL                                                    | 0         |                 |          |                        |           |            |             |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                        |           |                 |          |                        |           |            |             | PKG:20         |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT |           |                 |          |                        |           |            |             | Service ATA:33 |
|                                                | MOS                                                    | 29-Apr-15 |                 |          |                        |           |            |             |                |
|                                                | HRS                                                    | 0         | 2400 (+30/-30)  |          |                        |           |            |             |                |
|                                                | AFL                                                    | 0         |                 |          |                        |           |            |             |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                        |           |                 |          |                        |           |            |             | PKG:20         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                                                                                                                                            | Unit    | C/W                                                    | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty         |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--------------------------------------------------------|----------------|----------|------------------------|-----------|------------|-------------|------------------|
| ATA 33 - LIGHTS                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-48-00-002 <sup>S</sup>                                                                                                                                                                                                                          |         | GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT |                |          |                        |           |            |             | Service ATA:33   |
|                                                                                                                                                                                                                                                    | MOS     | 29-Apr-15                                              |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | HRS     | 0                                                      | 2400 (+30/-30) |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                                                                                                                                     |         |                                                        |                |          |                        |           |            |             | PKG:20           |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-49-00                                                                                                                                                                                                                                           |         | NO. 1 STROBE LIGHT                                     |                |          |                        |           |            |             | Component ATA:33 |
| PN:84036-3                                                                                                                                                                                                                                         | MOS/MSC | 29-Apr-15                                              | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:000355                                                                                                                                                                                                                                          | HRS     | 0                                                      |                | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02 |         |                                                        |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-49-00                                                                                                                                                                                                                                           |         | NO. 2 STROBE LIGHT                                     |                |          |                        |           |            |             | Component ATA:33 |
| PN:84036-4                                                                                                                                                                                                                                         | MOS/MSC | 29-Apr-15                                              | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:000358                                                                                                                                                                                                                                          | HRS     | 0                                                      |                | TSN 0    |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02 |         |                                                        |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-49-00-001                                                                                                                                                                                                                                       |         | DISCARD NO. 1 STROBE LIGHT                             |                |          |                        |           |            |             | Service ATA:33   |
| PN:84036-3                                                                                                                                                                                                                                         | MOS     | 29-Apr-15                                              |                |          |                        |           |            |             |                  |
| SN:000355                                                                                                                                                                                                                                          | HRS     | 0                                                      | 8000 (+30/-30) |          | 8000                   | 8030      | 5900 (+30) |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                                                                                                                                                                                                     |         |                                                        |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-49-00-001                                                                                                                                                                                                                                       |         | DISCARD NO. 2 STROBE LIGHT                             |                |          |                        |           |            |             | Service ATA:33   |
| PN:84036-4                                                                                                                                                                                                                                         | MOS     | 29-Apr-15                                              |                |          |                        |           |            |             |                  |
| SN:000358                                                                                                                                                                                                                                          | HRS     | 0                                                      | 8000 (+30/-30) |          | 8000                   | 8030      | 5900 (+30) |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                                                                                                                                                                                                     |         |                                                        |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             |                  |
| 33-49-00-002 <sup>S</sup>                                                                                                                                                                                                                          |         | GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT           |                |          |                        |           |            |             | Service ATA:33   |
|                                                                                                                                                                                                                                                    | MOS     | 29-Apr-15                                              |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | HRS     | 0                                                      | 2400 (+30/-30) |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    | AFL     | 0                                                      |                |          |                        |           |            |             |                  |
|                                                                                                                                                                                                                                                    |         |                                                        |                |          |                        |           |            |             | PKG:20           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                                                     | Interval       | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty  |        |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------------------------------------------------|----------------|-----------|------------------------|-----------|-----------|-------------|-----------|--------|
| ATA 33 - LIGHTS                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                             |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-49-00-002 <sup>S</sup>                                                  |         | GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT                                                            |                |           |                        |           |           |             | Service   | ATA:33 |
|                                                                            | MOS     | 29-Apr-15                                                                                               |                |           |                        |           |           |             |           |        |
|                                                                            | HRS     | 0                                                                                                       | 2400 (+30/-30) |           |                        |           |           |             |           |        |
|                                                                            | AFL     | 0                                                                                                       |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| PKG:20                                                                     |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                             |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-52-01                                                                   |         | EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR)                                                          |                |           |                        |           |           |             | Component | ATA:33 |
| PN:7450LS-00                                                               | MOS/MSC | 29-Apr-24                                                                                               | O/C            | TSR 0     |                        |           |           |             |           |        |
| SN:005001                                                                  | HRS     | 1952.5                                                                                                  | TSR 0          |           |                        |           |           |             |           |        |
|                                                                            | AFL     | 1160                                                                                                    | TSR 0          |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-52-01, AMM 33-52-01PROC. REF: AMM 33-52-01, AMM 33-52-01 |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-52-01                                                                   |         | EMERGENCY LIGHT BATTERY 2 (CENTER COMPT)                                                                |                |           |                        |           |           |             | Component | ATA:33 |
| PN:7450LS-00                                                               | MOS/MSC | 29-Apr-24                                                                                               | O/C            | TSR 0     |                        |           |           |             |           |        |
| SN:005387                                                                  | HRS     | 1952.5                                                                                                  | TSR 0          |           |                        |           |           |             |           |        |
|                                                                            | AFL     | 1160                                                                                                    | TSR 0          |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-52-01, AMM 33-52-01PROC. REF: AMM 33-52-01, AMM 33-52-01 |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-52-01-001                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY) |                |           |                        |           |           |             | Service   | ATA:33 |
| PN:7450LS-00                                                               | MOS     | 14-May-25                                                                                               | 12             | 14-May-26 |                        |           | 332 d     |             |           |        |
| SN:005001                                                                  | HRS     | 2086.2                                                                                                  |                |           |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                                                                                    |                |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01                             |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-52-01-001                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)       |                |           |                        |           |           |             | Service   | ATA:33 |
| PN:7450LS-00                                                               | MOS     | 14-May-25                                                                                               | 12             | 14-May-26 |                        |           | 332 d     |             |           |        |
| SN:005387                                                                  | HRS     | 2086.2                                                                                                  |                |           |                        |           |           |             |           |        |
|                                                                            | AFL     | 1243                                                                                                    |                |           |                        |           |           |             |           |        |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01                             |         |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            |         |                                                                                                         |                |           |                        |           |           |             |           |        |
| 33-52-01-002                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH DLE BATTERY)          |                |           |                        |           |           |             | Service   | ATA:33 |
| PN:7450LS-00                                                               | MOS/MSC | N/A                                                                                                     |                |           |                        |           |           |             |           |        |
| SN:005001                                                                  | HRS     |                                                                                                         |                |           |                        |           |           |             |           |        |
|                                                                            | AFL     |                                                                                                         |                |           |                        |           |           |             |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 33 - LIGHTS

PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01

|                                                |                                                                                          |  |     |  |  |  |  |         |        |
|------------------------------------------------|------------------------------------------------------------------------------------------|--|-----|--|--|--|--|---------|--------|
| 33-52-01-002                                   | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH DLE BATTERY) |  |     |  |  |  |  | Service | ATA:33 |
| PN:7450LS-00                                   | MOS/MSC                                                                                  |  | N/A |  |  |  |  |         |        |
| SN:005387                                      | HRS                                                                                      |  |     |  |  |  |  |         |        |
|                                                | AFL                                                                                      |  |     |  |  |  |  |         |        |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01 |                                                                                          |  |     |  |  |  |  |         |        |

|                                                |                                                           |  |     |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------------------|--|-----|--|--|--|--|---------|--------|
| 33-52-01-003                                   | DISCARD OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) |  |     |  |  |  |  | Service | ATA:33 |
| PN:7450LS-00                                   | MOS/MSC                                                   |  | N/A |  |  |  |  |         |        |
| SN:005001                                      | HRS                                                       |  |     |  |  |  |  |         |        |
|                                                | AFL                                                       |  |     |  |  |  |  |         |        |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01 |                                                           |  |     |  |  |  |  |         |        |

|                                                |                                                     |  |     |  |  |  |  |         |        |
|------------------------------------------------|-----------------------------------------------------|--|-----|--|--|--|--|---------|--------|
| 33-52-01-003                                   | DISCARD OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) |  |     |  |  |  |  | Service | ATA:33 |
| PN:7450LS-00                                   | MOS/MSC                                             |  | N/A |  |  |  |  |         |        |
| SN:005387                                      | HRS                                                 |  |     |  |  |  |  |         |        |
|                                                | AFL                                                 |  |     |  |  |  |  |         |        |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01 |                                                     |  |     |  |  |  |  |         |        |

|                                                                            |                       |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|-----------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 33-52-05                                                                   | SELF-ILLUMINATED UNIT |           |     |       |  |  |  | Component | ATA:33 |
| PN:PN                                                                      | MOS/MSC               | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                                                 | HRS                   | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                   | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 33-52-05, AMM 33-52-05PROC. REF: AMM 33-52-05, AMM 33-52-05 |                       |           |     |       |  |  |  |           |        |

|                                                |                                                                                |           |                |  |  |  |  |         |        |
|------------------------------------------------|--------------------------------------------------------------------------------|-----------|----------------|--|--|--|--|---------|--------|
| 33-52-17-001 <sup>S</sup>                      | OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED) |           |                |  |  |  |  | Service | ATA:33 |
|                                                | MOS                                                                            | 01-May-19 |                |  |  |  |  |         |        |
|                                                | HRS                                                                            | 1230      | 1600 (+30/-30) |  |  |  |  |         |        |
|                                                | AFL                                                                            | 711       |                |  |  |  |  |         |        |
| PROC. REF: AMM 33-52-17PROC. REF: AMM 33-52-17 |                                                                                |           |                |  |  |  |  |         |        |

PKG:10

### ATA 34 - NAVIGATION

|            |                      |           |     |       |  |  |  |           |        |
|------------|----------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 34-00-02   | TRANSPONDER RF RELAY |           |     |       |  |  |  | Component | ATA:34 |
| PN:PN      | MOS/MSC              | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN | HRS                  | 0         |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                                                                                |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-00-03                                                                                                                           | NO.1 IASP SMART PROBE                 |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:2015L-4B                                                                                                                        | MOS/MSC                               | 14-May-25 | O/C      |          |                        |           |           |             |                  |
| SN:17233                                                                                                                           | HRS                                   | 2086.2    |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 1243      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-15-07, AMM 34-15-07PROC. REF: AMM 34-15-07, AMM 34-15-07                                                         |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-00-03                                                                                                                           | NO.2 IASP SMART PROBE                 |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:2015L-4B                                                                                                                        | MOS/MSC                               | 14-May-25 | O/C      |          |                        |           |           |             |                  |
| SN:17306                                                                                                                           | HRS                                   | 2086.2    |          |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 1243      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 34-15-07, AMM 34-15-07PROC. REF: AMM 34-15-07, AMM 34-15-07                                                         |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-00-04                                                                                                                           | SD CARD DATABASE                      |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                                                                                                              | MOS/MSC                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-10-01                                                                                                                           | RADIO ALTIMETER                       |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:066-01153-0101                                                                                                                  | MOS/MSC                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:KRA405B-15881                                                                                                                   | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-31-01, AMM 34-31-01, AMM 34-31-01, AMM 34-31-01PROC. REF: AMM 34-31-01, AMM 34-31-01, AMM 34-31-01, AMM 34-31-01 |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-10-02                                                                                                                           | LEFT RADIO ALTIMETER TRANSMIT ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S67-2002-45                                                                                                                     | MOS/MSC                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:553-6648                                                                                                                        | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-31-02, AMM 34-31-02PROC. REF: AMM 34-31-02, AMM 34-31-02                                                         |                                       |           |          |          |                        |           |           |             |                  |
|                                                                                                                                    |                                       |           |          |          |                        |           |           |             |                  |
| 34-10-02                                                                                                                           | RIGHT RADIO ALTIMETER RECEIVE ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S67-2002-45                                                                                                                     | MOS/MSC                               | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:553-6649                                                                                                                        | HRS                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                                   | 0         |          | TSN 0    |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                                                          | C/W       | Interval     | TSX/Adj.  | Next Due (ENG/APU) A/C | Max Limit   | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|-----------|------------------------|-------------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| PROC. REF: AMM 34-31-02, AMM 34-31-02PROC. REF: AMM 34-31-02, AMM 34-31-02 |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| 34-11-00                                                                   | IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT                                                                                               |           |              |           |                        |             |           |             | Component ATA:34 |
| PN:C16786DA01                                                              | MOS/MSC                                                                                                                                       | 29-Apr-15 | O/C          | TSN 0     |                        |             |           |             |                  |
| SN:C16786012259                                                            | HRS                                                                                                                                           | 0         |              | TSN 0     |                        |             |           |             |                  |
|                                                                            | AFL                                                                                                                                           | 0         |              | TSN 0     |                        |             |           |             |                  |
| PROC. REF: AMM 34-11-01, AMM 34-11-01PROC. REF: AMM 34-11-01, AMM 34-11-01 |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| 34-11-00-001                                                               | FUNCTIONAL CHECK OF (IESI) INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) |           |              |           |                        |             |           |             | Service ATA:34   |
| PN:C16786DA01                                                              | MOS                                                                                                                                           | 14-May-25 | 24 (+1m/-1m) | 14-May-27 | 14-Jun-27              | 697 d (+31) |           |             |                  |
| SN:C16786012259                                                            | HRS                                                                                                                                           | 2086.2    |              |           |                        |             |           |             |                  |
|                                                                            | AFL                                                                                                                                           | 1243      |              |           |                        |             |           |             |                  |
| PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00                             |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| 34-11-02                                                                   | PITOT/STATIC PROBE                                                                                                                            |           |              |           |                        |             |           |             | Component ATA:34 |
| PN:0856UT4                                                                 | MOS/MSC                                                                                                                                       | 01-May-19 | O/C          | TSN 49    |                        |             |           |             |                  |
| SN:289336                                                                  | HRS                                                                                                                                           | 1230      |              | TSN 1230  |                        |             |           |             |                  |
|                                                                            | AFL                                                                                                                                           | 711       |              | TSN 711   |                        |             |           |             |                  |
| PROC. REF: AMM 34-11-02, AMM 34-11-02PROC. REF: AMM 34-11-02, AMM 34-11-02 |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| 34-11-02-001                                                               | RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)                   |           |              |           |                        |             |           |             | Service ATA:34   |
| PN:0856UT4                                                                 | MOS                                                                                                                                           | 14-May-25 | 24 (+1m/-1m) | 14-May-27 | 14-Jun-27              | 697 d (+31) |           |             |                  |
| SN:289336                                                                  | HRS                                                                                                                                           | 2086.2    |              |           |                        |             |           |             |                  |
|                                                                            | AFL                                                                                                                                           | 1243      |              |           |                        |             |           |             |                  |
| PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02                             |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| 34-15-00-001                                                               | FUNCTIONAL CHECK OF AIR DATA SYSTEM                                                                                                           |           |              |           |                        |             |           |             | Service ATA:34   |
|                                                                            | MOS                                                                                                                                           | 14-May-25 | 24 (+1m/-1m) | 14-May-27 | 14-Jun-27              | 697 d (+31) |           |             |                  |
|                                                                            | HRS                                                                                                                                           | 2086.2    |              |           |                        |             |           |             |                  |
|                                                                            | AFL                                                                                                                                           | 1243      |              |           |                        |             |           |             |                  |
| PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00                             |                                                                                                                                               |           |              |           |                        |             |           |             |                  |
| PKG:81                                                                     |                                                                                                                                               |           |              |           |                        |             |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                     | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty |
|----------------------------------------------------------------------------|---------|-------------------------------------------------------------------------|--------------|----------|------------------------|-----------|--------------|-------------|----------|
| ATA 34 - NAVIGATION                                                        |         |                                                                         |              |          |                        |           |              |             |          |
| 34-15-00-002                                                               |         | SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS |              |          |                        |           |              | Service     | ATA:34   |
|                                                                            | MOS     | 14-May-25                                                               | 60 (+1m/-1m) |          | 14-May-30              | 14-Jun-30 | 1793 d (+31) |             |          |
|                                                                            | HRS     | 2086.2                                                                  |              |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                                    |              |          |                        |           |              |             |          |
| PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00                             |         |                                                                         |              |          |                        |           |              |             |          |
| 34-15-00-003                                                               |         | DETAILED INSPECTION OF IASP                                             |              |          |                        |           |              | Service     | ATA:34   |
|                                                                            | MOS     | 14-May-25                                                               | 24 (+1m/-1m) |          | 14-May-27              | 14-Jun-27 | 697 d (+31)  |             |          |
|                                                                            | HRS     | 2086.2                                                                  |              |          |                        |           |              |             |          |
|                                                                            | AFL     | 1243                                                                    |              |          |                        |           |              |             |          |
| PROC. REF: AMM 34-15-07PROC. REF: AMM 34-15-07                             |         |                                                                         |              |          |                        |           |              |             |          |
| 34-20-01                                                                   |         | LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM                         |              |          |                        |           |              | Component   | ATA:34   |
| PN:011-00868-10                                                            | MOS/MSC | 29-Apr-15                                                               | O/C          | TSN 0    |                        |           |              |             |          |
| SN:42026753                                                                | HRS     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01 |         |                                                                         |              |          |                        |           |              |             |          |
| 34-20-01                                                                   |         | RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM                         |              |          |                        |           |              | Component   | ATA:34   |
| PN:011-00868-10                                                            | MOS/MSC | 29-Apr-15                                                               | O/C          | TSN 0    |                        |           |              |             |          |
| SN:42026761                                                                | HRS     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01 |         |                                                                         |              |          |                        |           |              |             |          |
| 34-20-02                                                                   |         | LEFT MAGNETOMETER                                                       |              |          |                        |           |              | Component   | ATA:34   |
| PN:011-00870-10                                                            | MOS/MSC | 29-Apr-15                                                               | O/C          | TSN 0    |                        |           |              |             |          |
| SN:1CM013580                                                               | HRS     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02 |         |                                                                         |              |          |                        |           |              |             |          |
| 34-20-02                                                                   |         | RIGHT MAGNETOMETER                                                      |              |          |                        |           |              | Component   | ATA:34   |
| PN:011-00870-10                                                            | MOS/MSC | 29-Apr-15                                                               | O/C          | TSN 0    |                        |           |              |             |          |
| SN:1CM013575                                                               | HRS     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
|                                                                            | AFL     | 0                                                                       |              | TSN 0    |                        |           |              |             |          |
| PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02 |         |                                                                         |              |          |                        |           |              |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit    | C/W                                                                      | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty  |        |
|----------------------------------------------------------------------------|---------|--------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-------------|-----------|--------|
| ATA 34 - NAVIGATION                                                        |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-21-00-001 <sup>S</sup>                                                  |         | FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER |              |          |                        |           |           |             | Service   | ATA:34 |
| PN:011-00870-10                                                            | MOS     | 29-Apr-24                                                                | 36 (+1m/-1m) |          |                        |           |           |             |           |        |
| SN:1CM013580                                                               | HRS     | 1952.5                                                                   |              |          |                        |           |           |             |           |        |
|                                                                            | AFL     | 1160                                                                     |              |          |                        |           |           |             |           |        |
| PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02                             |         |                                                                          |              |          |                        |           |           |             |           |        |
| PKG:82                                                                     |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-21-00-001 <sup>S</sup>                                                  |         | FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER |              |          |                        |           |           |             | Service   | ATA:34 |
| PN:011-00870-10                                                            | MOS     | 29-Apr-24                                                                | 36 (+1m/-1m) |          |                        |           |           |             |           |        |
| SN:1CM013575                                                               | HRS     | 1952.5                                                                   |              |          |                        |           |           |             |           |        |
|                                                                            | AFL     | 1160                                                                     |              |          |                        |           |           |             |           |        |
| PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02                             |         |                                                                          |              |          |                        |           |           |             |           |        |
| PKG:82                                                                     |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-23-00                                                                   |         | MAGNETIC COMPASS                                                         |              |          |                        |           |           |             | Component | ATA:34 |
| PN:KCA0120W                                                                | MOS/MSC | 29-Apr-15                                                                | O/C          | TSN 0    |                        |           |           |             |           |        |
| SN:BL6630714                                                               | HRS     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
|                                                                            | AFL     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
| PROC. REF: AMM 34-23-01, AMM 34-23-01PROC. REF: AMM 34-23-01, AMM 34-23-01 |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-23-00-001 <sup>S</sup>                                                  |         | FUNCTIONAL CHECK OF STANDBY COMPASS                                      |              |          |                        |           |           |             | Service   | ATA:34 |
| PN:KCA0120W                                                                | MOS     | 29-Apr-24                                                                | 36 (+1m/-1m) |          |                        |           |           |             |           |        |
| SN:BL6630714                                                               | HRS     | 1952.5                                                                   |              |          |                        |           |           |             |           |        |
|                                                                            | AFL     | 1160                                                                     |              |          |                        |           |           |             |           |        |
| PROC. REF: AMM 34-23-00PROC. REF: AMM 34-23-00                             |         |                                                                          |              |          |                        |           |           |             |           |        |
| PKG:82                                                                     |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-30-01                                                                   |         | LEFT VOR/LOC 2 & 3 BLADE ANTENNA                                         |              |          |                        |           |           |             | Component | ATA:34 |
| PN:S65-247170                                                              | MOS/MSC | 29-Apr-15                                                                | O/C          | TSN 0    |                        |           |           |             |           |        |
| SN:173-4301                                                                | HRS     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
|                                                                            | AFL     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
| PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03 |         |                                                                          |              |          |                        |           |           |             |           |        |
| 34-30-01                                                                   |         | RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE                                      |              |          |                        |           |           |             | Component | ATA:34 |
| PN:S65-247170                                                              | MOS/MSC | 29-Apr-15                                                                | O/C          | TSN 0    |                        |           |           |             |           |        |
| SN:173-4294                                                                | HRS     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
|                                                                            | AFL     | 0                                                                        |              | TSN 0    |                        |           |           |             |           |        |
| PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03 |         |                                                                          |              |          |                        |           |           |             |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 34 - NAVIGATION

| 34-40-01                                                                   | GDL-69A SATELLITE WEATHER AND RADIO RECEIVER |           |     |       |  |  |  | Component | ATA:34 |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:011-00987-00                                                            | MOS/MSC                                      | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:47768191                                                                | HRS                                          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                                          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 34-57-01, AMM 34-57-01PROC. REF: AMM 34-57-01, AMM 34-57-01 |                                              |           |     |       |  |  |  |           |        |

| 34-40-02                                                                                               | AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA |           |     |       |  |  |  | Component | ATA:34 |
|--------------------------------------------------------------------------------------------------------|----------------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:013-00245-00                                                                                        | MOS/MSC                                                  | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:12210                                                                                               | HRS                                                      | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                                                        | AFL                                                      | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02 |                                                          |           |     |       |  |  |  |           |        |

| 34-40-02                                                                                               | FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA |           |     |       |  |  |  | Component | ATA:34 |
|--------------------------------------------------------------------------------------------------------|----------------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:013-00245-00                                                                                        | MOS/MSC                                                  | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:12209                                                                                               | HRS                                                      | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                                                        | AFL                                                      | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02 |                                                          |           |     |       |  |  |  |           |        |

| 34-40-03                                                                   | WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA |           |     |       |  |  |  | Component | ATA:34 |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:011-00883-20                                                            | MOS/MSC                                    | 28-Oct-15 | O/C | TSO 1 |  |  |  |           |        |
| SN:47204512                                                                | HRS                                        | 180.5     |     | TSO 0 |  |  |  |           |        |
|                                                                            | AFL                                        | 103       |     | TSO 0 |  |  |  |           |        |
| PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01 |                                            |           |     |       |  |  |  |           |        |

| 34-40-04                                                                   | TCAS II UNIT |           |     |       |  |  |  | Component | ATA:34 |
|----------------------------------------------------------------------------|--------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:9003500-55905                                                           | MOS/MSC      | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:TSE02785                                                                | HRS          | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL          | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 34-43-01, AMM 34-43-01PROC. REF: AMM 34-43-01, AMM 34-43-01 |              |           |     |       |  |  |  |           |        |

| 34-40-05                                                                   | TCAS II TOP ANTENNA |           |     |       |  |  |  | Component | ATA:34 |
|----------------------------------------------------------------------------|---------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:7514060-902                                                             | MOS/MSC             | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:ANE44617                                                                | HRS                 | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                 | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 34-43-05, AMM 34-43-05PROC. REF: AMM 34-43-05, AMM 34-43-05 |                     |           |     |       |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                              |           |          |          |                        |           |           |             |                  |
| 34-43-02                                                                   | LOWER TCAS L BAND ANTENNA                    |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S65-5366-7L                                                             | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:261-105861                                                              | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-43-02, AMM 34-43-02PROC. REF: AMM 34-43-02, AMM 34-43-02 |                                              |           |          |          |                        |           |           |             |                  |
| 34-50-02                                                                   | BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S65-5366-7L                                                             | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:261-117253                                                              | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02 |                                              |           |          |          |                        |           |           |             |                  |
| 34-50-02                                                                   | TOP XPDR L BAND ANTENNA                      |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S65-5366-7L                                                             | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:261-116985                                                              | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02 |                                              |           |          |          |                        |           |           |             |                  |
| 34-50-03                                                                   | KN 63 DISTANCE MEASURING UNIT                |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:066-01070-0001                                                          | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:37737                                                                   | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-51-01, AMM 34-51-01PROC. REF: AMM 34-51-01, AMM 34-51-01 |                                              |           |          |          |                        |           |           |             |                  |
| 34-50-05                                                                   | PHASING COUPLER                              |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:SSPD-113-10                                                             | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:7948                                                                    | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-32-01, AMM 34-32-01PROC. REF: AMM 34-32-01, AMM 34-32-01 |                                              |           |          |          |                        |           |           |             |                  |
| 34-50-06                                                                   | MARKER BEACON ANTENNA                        |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S35-1000-2                                                              | MOS/MSC                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:102-10978                                                               | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-32-04, AMM 34-32-04PROC. REF: AMM 34-32-04, AMM 34-32-04 |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-07                                                                   | MARKER BEACON ANTENNA SPLITTER  |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                                                      | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-32-05, AMM 34-32-05PROC. REF: AMM 34-32-05, AMM 34-32-05 |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-08                                                                   | VOR/LOC/GS ANTENNA SPLITTER     |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                                                      | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-32-02, AMM 34-32-02PROC. REF: AMM 34-32-02, AMM 34-32-02 |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-09                                                                   | VOR/LOC/GS ANTENNA RF CABLE     |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:PN                                                                      | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 34-32-02, AMM 34-32-02PROC. REF: AMM 34-32-02, AMM 34-32-02 |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-10                                                                   | GSR 56 IRIDIUM UNIT             |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:011-02268-00                                                            | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:1NZ006124                                                               | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-15-01, AMM 23-15-01PROC. REF: AMM 23-15-01, AMM 23-15-01 |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-11                                                                   | IRIDIUM SATCOM ANTENNA          |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:S67-1575-109                                                            | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:430-13996                                                               | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-15-03, AMM 23-15-03PROC. REF: AMM 23-15-03, AMM 23-15-03 |                                 |           |          |          |                        |           |           |             |                  |
| 34-50-12                                                                   | GDL 59 DATALINK MANAGEMENT UNIT |           |          |          |                        |           |           |             | Component ATA:34 |
| PN:011-01746-00                                                            | MOS/MSC                         | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:1EJ005572                                                               | HRS                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 23-23-01, AMM 23-23-01PROC. REF: AMM 23-23-01, AMM 23-23-01 |                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                                                                                    | Unit    | C/W                      | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--------------------------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 34 - NAVIGATION                                                                                                                                                                        |         |                          |          |          |                        |           |           |             |          |
| 34-50-13                                                                                                                                                                                   |         | WI-FI - DATALINK ANTENNA |          |          |                        |           |           | Component   | ATA:34   |
| PN:S65-5366-71S                                                                                                                                                                            | MOS/MSC | 29-Apr-15                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:258-3688                                                                                                                                                                                | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11 |         |                          |          |          |                        |           |           |             |          |
| 34-50-14                                                                                                                                                                                   |         | ADF ANTENNA              |          |          |                        |           |           | Component   | ATA:34   |
| PN:622-7383-001                                                                                                                                                                            | MOS/MSC | 29-Apr-15                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:43P47G                                                                                                                                                                                  | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-53-02, AMM 34-53-02PROC. REF: AMM 34-53-02, AMM 34-53-02                                                                                                                 |         |                          |          |          |                        |           |           |             |          |
| 34-50-15                                                                                                                                                                                   |         | ADF UNIT                 |          |          |                        |           |           | Component   | ATA:34   |
| PN:622-7382-101                                                                                                                                                                            | MOS/MSC | 29-Apr-15                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:4KGLC                                                                                                                                                                                   | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01                                                                                                                 |         |                          |          |          |                        |           |           |             |          |
| 34-51-02                                                                                                                                                                                   |         | NO. 1 DME L BAND ANTENNA |          |          |                        |           |           | Component   | ATA:34   |
| PN:S65-5366-7L                                                                                                                                                                             | MOS/MSC | 29-Apr-15                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:261-117289                                                                                                                                                                              | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-51-02, AMM 34-51-02PROC. REF: AMM 34-51-02, AMM 34-51-02                                                                                                                 |         |                          |          |          |                        |           |           |             |          |
| 34-52-00                                                                                                                                                                                   |         | NO. 1 TRANSPONDER        |          |          |                        |           |           | Component   | ATA:34   |
| PN:NXT-600                                                                                                                                                                                 | MOS/MSC | 01-May-19                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:NXE05298                                                                                                                                                                                | HRS     | 1230                     |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 711                      |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01                                                                                                                 |         |                          |          |          |                        |           |           |             |          |
| 34-52-00                                                                                                                                                                                   |         | NO. 2 TRANSPONDER        |          |          |                        |           |           | Component   | ATA:34   |
| PN:PN                                                                                                                                                                                      | MOS/MSC | 29-Apr-15                | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                                                                                 | HRS     | 0                        |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                                                                            | AFL     | 0                        |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01                                                                                                                 |         |                          |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                         | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|---------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                              |           |                |          |                        |           |              |               |                  |
| 34-52-00-001                                                               | FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM                 |           |                |          |                        |           |              |               | Service ATA:34   |
| PN:NXT-600                                                                 | MOS                                                          | 14-May-25 | 24             |          | 14-May-27              |           | 697 d        |               |                  |
| SN:NXE05298                                                                | HRS                                                          | 2086.2    |                |          |                        |           |              |               |                  |
|                                                                            | AFL                                                          | 1243      |                |          |                        |           |              |               |                  |
| Calibration Date: : 14-May-25                                              |                                                              |           |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 34-52-00PROC. REF: AMM 34-52-00                             |                                                              |           |                |          |                        |           |              |               |                  |
| 34-52-04                                                                   | LOWER COAXIAL UNIT                                           |           |                |          |                        |           |              |               | Component ATA:34 |
| PN:PN                                                                      | MOS/MSC                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 34-52-04, AMM 34-52-04PROC. REF: AMM 34-52-04, AMM 34-52-04 |                                                              |           |                |          |                        |           |              |               |                  |
| 34-52-04                                                                   | UPPER COAXIAL UNIT                                           |           |                |          |                        |           |              |               | Component ATA:34 |
| PN:PN                                                                      | MOS/MSC                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:UNKNOWN                                                                 | HRS                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 34-52-04, AMM 34-52-04PROC. REF: AMM 34-52-04, AMM 34-52-04 |                                                              |           |                |          |                        |           |              |               |                  |
| 34-53-01                                                                   | ADF MOUNTING TRAY                                            |           |                |          |                        |           |              |               | Component ATA:34 |
| PN:622-5212-001                                                            | MOS/MSC                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:44068T                                                                  | HRS                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01 |                                                              |           |                |          |                        |           |              |               |                  |
| 34-60-03                                                                   | FLIGHT MANAGEMENT SYSTEM PANEL                               |           |                |          |                        |           |              |               | Component ATA:34 |
| PN:011-01428-00                                                            | MOS/MSC                                                      | 29-Apr-15 | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:194005836                                                               | HRS                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 34-61-03, AMM 34-61-03PROC. REF: AMM 34-61-03, AMM 34-61-03 |                                                              |           |                |          |                        |           |              |               |                  |
| ATA 35 - OXYGEN                                                            |                                                              |           |                |          |                        |           |              |               |                  |
| 35-00-00-001                                                               | FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE |           |                |          |                        |           |              |               | Service ATA:35   |
|                                                                            | MOS                                                          | 29-Apr-24 | 36 (+30d/-30d) | Adj 27d  | 26-May-27              | 25-Jun-27 | 709 d (+30)  | AIRWORTHINESS |                  |
|                                                                            | HRS                                                          | 1952.5    | 2400 (+30/-30) |          | 4352.5                 | 4382.5    | 2252.5 (+30) |               |                  |
|                                                                            | AFL                                                          | 1160      |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00                             |                                                              |           |                |          |                        |           |              |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                 | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                                            |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-00-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION |              |          |                        |           |           |             | Service ATA:35   |
|                                                                            | MOS          | 14-May-25                                           | 60 (+1m/-1m) |          |                        |           |           |             |                  |
|                                                                            | HRS          | 2086.2                                              |              |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1243                                                |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-02PROC. REF: AMM 35-01-02                             |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-02                                                                   |              | OXYGEN CYLINDER TRANSDUCER                          |              |          |                        |           |           |             | Component ATA:35 |
| PN:4441125-000                                                             | MOS/MSC      | 29-Apr-15                                           | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:8114-9-327                                                              | HRS          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-02, AMM 35-01-02PROC. REF: AMM 35-01-02, AMM 35-01-02 |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-05                                                                   |              | CREW OXYGEN SYSTEM LOW PRESSURE SWITCH              |              |          |                        |           |           |             | Component ATA:35 |
| PN:P24151                                                                  | MOS/MSC      | 29-Apr-15                                           | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:0377                                                                    | HRS          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-05, AMM 35-01-05PROC. REF: AMM 35-01-05, AMM 35-01-05 |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-06                                                                   |              | OXYGEN SYSTEM CONTROL PANEL                         |              |          |                        |           |           |             | Component ATA:35 |
| PN:441-40945-002                                                           | MOS/MSC      | 29-Apr-15                                           | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:0650                                                                    | HRS          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-06, AMM 35-01-06PROC. REF: AMM 35-01-06, AMM 35-01-06 |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-07                                                                   |              | COCKPIT SENSOR                                      |              |          |                        |           |           |             | Component ATA:35 |
| PN:P24099                                                                  | MOS/MSC      | 29-Apr-15                                           | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:0677                                                                    | HRS          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-07, AMM 35-01-07PROC. REF: AMM 35-01-07, AMM 35-01-07 |              |                                                     |              |          |                        |           |           |             |                  |
| 35-01-08                                                                   |              | PAX LOW PRESSURE OXYGEN SYSTEM SWITCH               |              |          |                        |           |           |             | Component ATA:35 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                           | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                   |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |              |                                                     |              |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                                            |                                                   |           |          |          |                        |           |           |             |                  |
| 35-01-09                                                                   | ALTITUDE COMPENSATING REGULATOR                   |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:4421135-001                                                             | MOS/MSC                                           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00550                                                                   | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-09, AMM 35-01-09PROC. REF: AMM 35-01-09, AMM 35-01-09 |                                                   |           |          |          |                        |           |           |             |                  |
| 35-01-10                                                                   | LOW PRESSURE OXYGEN VALVE                         |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:4421132-109                                                             | MOS/MSC                                           | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:00662                                                                   | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-01-10, AMM 35-01-10PROC. REF: AMM 35-01-10, AMM 35-01-10 |                                                   |           |          |          |                        |           |           |             |                  |
| 35-02-01                                                                   | OXYGEN CYLINDER                                   |           |          |          |                        |           |           |             | Component ATA:35 |
| PN:4441122-050                                                             | MOS/MSC                                           | 24-Apr-23 | H/T      | TSR 3    |                        |           |           |             |                  |
| SN:908760701                                                               | HRS                                               | 1825.5    |          | TSR 0    |                        |           |           |             |                  |
|                                                                            | AFL                                               | 1042      |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-02-01, AMM 35-02-01PROC. REF: AMM 35-02-01, AMM 35-02-01 |                                                   |           |          |          |                        |           |           |             |                  |
| 35-02-01-001                                                               | FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR     |           |          |          |                        |           |           |             | Service ATA:35   |
| PN:4441122-050                                                             | MOS                                               | 24-Apr-23 | 60       |          | 01-Dec-27 (M)          |           | 898 d     |             |                  |
| SN:908760701                                                               | HRS                                               |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                               |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |          |                        |           |           |             |                  |
| 35-02-01-003                                                               | DISCARD OF OXYGEN CYLINDER                        |           |          |          |                        |           |           |             | Service ATA:35   |
| PN:4441122-050                                                             | MOS                                               |           | 180      |          | 01-Jul-32 (M)          |           | 2572 d    | LIFE LIMIT  |                  |
| SN:908760701                                                               | HRS                                               |           |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                               |           |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |          |                        |           |           |             |                  |
| 35-02-01-004                                                               | RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER |           |          |          |                        |           |           |             | Service ATA:35   |
| PN:4441122-050                                                             | MOS                                               | 24-Apr-23 | 60       |          | 01-Dec-27 (M)          |           | 898 d     |             |                  |
| SN:908760701                                                               | HRS                                               | 1825.5    |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                               | 1042      |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition   | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-------------|---------------|------------------|
| ATA 35 - OXYGEN                                                            |                                                       |           |                |          |                        |           |             |               |                  |
| 35-02-05                                                                   | OXYGEN PRESSURE REGULATOR                             |           |                |          |                        |           |             |               | Component ATA:35 |
| PN:172421-14                                                               | MOS/MSC                                               | 24-Apr-23 | O/C            | TSR 3    |                        |           |             |               |                  |
| SN:1057                                                                    | HRS                                                   | 1825.5    |                | TSR 0    |                        |           |             |               |                  |
|                                                                            | AFL                                                   | 1042      |                | TSR 0    |                        |           |             |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |                |          |                        |           |             |               |                  |
| 35-11-00-001                                                               | OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX |           |                |          |                        |           |             |               | Service ATA:35   |
|                                                                            | MOS                                                   | 14-May-25 | 12 (+30d/-30d) |          | 14-May-26              | 13-Jun-26 | 332 d (+30) | AIRWORTHINESS |                  |
|                                                                            | HRS                                                   | 2086.2    | 800 (+30/-30)  |          | 2886.2                 |           | 786.2 (+30) |               |                  |
|                                                                            | AFL                                                   | 1243      |                |          |                        |           |             |               |                  |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02                             |                                                       |           |                |          |                        |           |             |               |                  |
| 35-11-01                                                                   | COPILOT OXYGEN MASK STOWAGE BOX                       |           |                |          |                        |           |             |               | Component ATA:35 |
| PN:1186F6-23                                                               | MOS/MSC                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |               |                  |
| SN:01280                                                                   | HRS                                                   | 0         |                | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01 |                                                       |           |                |          |                        |           |             |               |                  |
| 35-11-01                                                                   | PILOT OXYGEN MASK STOWAGE BOX                         |           |                |          |                        |           |             |               | Component ATA:35 |
| PN:1186F6-23                                                               | MOS/MSC                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |             |               |                  |
| SN:01281                                                                   | HRS                                                   | 0         |                | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01 |                                                       |           |                |          |                        |           |             |               |                  |
| 35-11-02                                                                   | LEFT CREW OXYGEN MASK                                 |           |                |          |                        |           |             |               | Component ATA:35 |
| PN:174232-93                                                               | MOS/MSC                                               | 01-Oct-20 | O/C            | TSN 12   |                        |           |             |               |                  |
| SN:46933                                                                   | HRS                                                   | 1531.4    |                | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                                   | 894       |                | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02 |                                                       |           |                |          |                        |           |             |               |                  |
| 35-11-02                                                                   | RIGHT CREW OXYGEN MASK                                |           |                |          |                        |           |             |               | Component ATA:35 |
| PN:174232-93                                                               | MOS/MSC                                               | 01-Oct-20 | O/C            | TSN 12   |                        |           |             |               |                  |
| SN:46934                                                                   | HRS                                                   | 1531.4    |                | TSN 0    |                        |           |             |               |                  |
|                                                                            | AFL                                                   | 894       |                | TSN 0    |                        |           |             |               |                  |
| PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02 |                                                       |           |                |          |                        |           |             |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                        | Unit                                                 | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty       |
|------------------------------------------------|------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|--------------|-------------|----------------|
| ATA 35 - OXYGEN                                |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-001                                   | DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK  |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS                                                  | 14-May-25 | 24 (+1m/-1m)   |          | 14-May-27              | 14-Jun-27 | 697 d (+31)  |             |                |
| SN:46933                                       | HRS                                                  | 2086.2    |                |          |                        |           |              |             |                |
|                                                | AFL                                                  | 1243      |                |          |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-001                                   | DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS                                                  | 14-May-25 | 24 (+1m/-1m)   |          | 14-May-27              | 14-Jun-27 | 697 d (+31)  |             |                |
| SN:46934                                       | HRS                                                  | 2086.2    |                |          |                        |           |              |             |                |
|                                                | AFL                                                  | 1243      |                |          |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-002                                   | RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK      |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS                                                  | 01-Oct-20 | 72 (+1m/-1m)   | TAC 12   | 01-Oct-25              | 01-Nov-25 | 107 d (+31)  |             |                |
| SN:46933                                       | HRS                                                  | 1531.4    | 3600 (+30/-30) | TAC 0    | 5131.4                 | 5161.4    | 3031.4 (+30) |             |                |
|                                                | AFL                                                  | 894       |                | TAC 0    |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-002                                   | RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK     |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS                                                  | 01-Oct-20 | 72 (+1m/-1m)   | TAC 12   | 01-Oct-25              | 01-Nov-25 | 107 d (+31)  |             |                |
| SN:46934                                       | HRS                                                  | 1531.4    | 3600 (+30/-30) | TAC 0    | 5131.4                 | 5161.4    | 3031.4 (+30) |             |                |
|                                                | AFL                                                  | 894       |                | TAC 0    |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-003                                   | DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK  |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS/MSC                                              |           | N/A            |          |                        |           |              |             |                |
| SN:46933                                       | HRS                                                  |           |                |          |                        |           |              |             |                |
|                                                | AFL                                                  |           |                |          |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |
| 35-11-02-003                                   | DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK |           |                |          |                        |           |              |             | Service ATA:35 |
| PN:174232-93                                   | MOS/MSC                                              |           | N/A            |          |                        |           |              |             |                |
| SN:46934                                       | HRS                                                  |           |                |          |                        |           |              |             |                |
|                                                | AFL                                                  |           |                |          |                        |           |              |             |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                        |           |              |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                           | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------|----------------|----------|------------------------|-----------|--------------|---------------|------------------|
| ATA 35 - OXYGEN                                                            |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-11-04-001                                                               | <sup>S</sup> | DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) |                |          |                        |           |              |               | Service ATA:35   |
|                                                                            | MOS          | 29-Apr-24                                                                     | 36 (+1m/-1m)   |          |                        |           |              |               |                  |
|                                                                            | HRS          | 1952.5                                                                        |                |          |                        |           |              |               |                  |
|                                                                            | AFL          | 1160                                                                          |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 35-11-04PROC. REF: AMM 35-11-04                             |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-21-00-001                                                               |              | FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE                      |                |          |                        |           |              |               | Service ATA:35   |
|                                                                            | MOS          | 29-Apr-24                                                                     | 36 (+30d/-30d) | Adj 27d  | 26-May-27              | 25-Jun-27 | 709 d (+30)  | AIRWORTHINESS |                  |
|                                                                            | HRS          | 1952.5                                                                        | 2400 (+30/-30) |          | 4352.5                 | 4382.5    | 2252.5 (+30) |               |                  |
|                                                                            | AFL          | 1160                                                                          |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00                             |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-21-00-002                                                               |              | OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTM IN MANUAL MODE                    |                |          |                        |           |              |               | Service ATA:35   |
|                                                                            | MOS          | 29-Apr-24                                                                     | 36 (+30d/-30d) | Adj 27d  | 26-May-27              | 25-Jun-27 | 709 d (+30)  | AIRWORTHINESS |                  |
|                                                                            | HRS          | 1952.5                                                                        | 2400 (+30/-30) |          | 4352.5                 | 4382.5    | 2252.5 (+30) |               |                  |
|                                                                            | AFL          | 1160                                                                          |                |          |                        |           |              |               |                  |
| PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00                             |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-21-01                                                                   |              | AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER                                      |                |          |                        |           |              |               | Component ATA:35 |
| PN:4411071-112                                                             | MOS/MSC      | 29-Apr-15                                                                     | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:4411071-012-00383                                                       | HRS          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-21-01                                                                   |              | FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER                                      |                |          |                        |           |              |               | Component ATA:35 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                     | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |              |                                                                               |                |          |                        |           |              |               |                  |
| 35-21-01                                                                   |              | NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER                                    |                |          |                        |           |              |               | Component ATA:35 |
| PN:4411072-112                                                             | MOS/MSC      | 29-Apr-15                                                                     | O/C            | TSN 0    |                        |           |              |               |                  |
| SN:4411072-012-00874                                                       | HRS          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |
|                                                                            | AFL          | 0                                                                             |                | TSN 0    |                        |           |              |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                                            |                                               |           |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                               |           |              |          |                        |           |           |             |                  |
| 35-21-01                                                                   | NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER    |           |              |          |                        |           |           |             | Component ATA:35 |
| PN:4411072-112                                                             | MOS/MSC                                       | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:4411072-012-00879                                                       | HRS                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                               |           |              |          |                        |           |           |             |                  |
| 35-21-01                                                                   | NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER    |           |              |          |                        |           |           |             | Component ATA:35 |
| PN:4411072-112                                                             | MOS/MSC                                       | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:4411072-012-00880                                                       | HRS                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                               |           |              |          |                        |           |           |             |                  |
| 35-21-01                                                                   | NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER    |           |              |          |                        |           |           |             | Component ATA:35 |
| PN:4411072-112                                                             | MOS/MSC                                       | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:4411072-012-00881                                                       | HRS                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                               |           |              |          |                        |           |           |             |                  |
| 35-21-01                                                                   | NO. 5 OXYGEN TWO MASK DEPLOYMENT CONTAINER    |           |              |          |                        |           |           |             | Component ATA:35 |
| PN:4411072-112                                                             | MOS/MSC                                       | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |                  |
| SN:4411072-012-00883                                                       | HRS                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                           | 0         |              | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                               |           |              |          |                        |           |           |             |                  |
| 35-21-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION OF PASSENGER OXYGEN MASKS |           |              |          |                        |           |           |             | Service ATA:35   |
|                                                                            | MOS                                           | 14-May-25 | 36 (+1m/-1m) |          |                        |           |           |             |                  |
|                                                                            | HRS                                           | 2086.2    |              |          |                        |           |           |             |                  |
|                                                                            | AFL                                           | 1243      |              |          |                        |           |           |             |                  |
| PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01                             |                                               |           |              |          |                        |           |           |             |                  |
|                                                                            |                                               |           |              |          |                        |           |           |             | PKG:82           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|--------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 35 - OXYGEN                                                                                        |                                                                              |           |          |          |                        |           |           |               |                  |
| 35-31-01                                                                                               | PBE - PROTECTIVE BREATHING EQUIPMENT                                         |           |          |          |                        |           |           |               | Component ATA:35 |
| PN:MR-10022NEMB                                                                                        | MOS/MSC                                                                      | 14-May-25 | N/A      | TSN 0    |                        |           |           | NOT INSTALLED |                  |
| SN:E1405347                                                                                            | HRS                                                                          |           |          | TSN 0    |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          |           |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01 |                                                                              |           |          |          |                        |           |           |               |                  |
| 35-31-01-001                                                                                           | DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)                              |           |          |          |                        |           |           |               | Service ATA:35   |
| PN:MR-10022NEMB                                                                                        | MOS/MSC                                                                      | 01-Sep-14 | N/A      |          |                        |           |           |               |                  |
| SN:E1405347                                                                                            | HRS                                                                          |           |          |          |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          |           |          |          |                        |           |           |               |                  |
| PROC. REF: AMM 35-31-01PROC. REF: AMM 35-31-01                                                         |                                                                              |           |          |          |                        |           |           |               |                  |
| ATA 36 - PNEUMATIC                                                                                     |                                                                              |           |          |          |                        |           |           |               |                  |
| 36-00-00-710-801-A                                                                                     | TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK |           |          |          |                        |           |           |               | Service ATA:36   |
|                                                                                                        | MOS/MSC                                                                      | 29-Apr-15 | A/R      |          |                        |           |           |               |                  |
|                                                                                                        | HRS                                                                          | 0         |          |          |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          | 0         |          |          |                        |           |           |               |                  |
| PROC. REF: AMM 36-00-00PROC. REF: AMM 36-00-00                                                         |                                                                              |           |          |          |                        |           |           |               |                  |
| 36-01-01                                                                                               | PNEUMATIC INSC ILLUM PANEL                                                   |           |          |          |                        |           |           |               | Component ATA:36 |
| PN:441-42633-002                                                                                       | MOS/MSC                                                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |               |                  |
| SN:1278                                                                                                | HRS                                                                          | 0         |          | TSN 0    |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          | 0         |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 36-01-01, AMM 36-01-01PROC. REF: AMM 36-01-01, AMM 36-01-01                             |                                                                              |           |          |          |                        |           |           |               |                  |
| 36-11-01                                                                                               | LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE                           |           |          |          |                        |           |           |               | Component ATA:36 |
| PN:RYLB-53505-5                                                                                        | MOS/MSC                                                                      | 28-Feb-19 | O/C      |          |                        |           |           |               |                  |
| SN:0053                                                                                                | HRS                                                                          | 1197.7    |          |          |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          | 691       |          |          |                        |           |           |               |                  |
| PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01                             |                                                                              |           |          |          |                        |           |           |               |                  |
| 36-11-01                                                                                               | RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE                          |           |          |          |                        |           |           |               | Component ATA:36 |
| PN:RYLB-53505-4                                                                                        | MOS/MSC                                                                      | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |               |                  |
| SN:0290                                                                                                | HRS                                                                          | 0         |          | TSN 0    |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                          | 0         |          | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01                             |                                                                              |           |          |          |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                              | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 36 - PNEUMATIC                                                         |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-01-001                                                               | <sup>S</sup> | RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER |                |          |                        |           |           | Service     | ATA:36   |
|                                                                            | MOS          | 29-Apr-15                                                                        |                |          |                        |           |           |             |          |
|                                                                            | HRS          | 0                                                                                | 2400 (+30/-30) |          |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                                                |                |          |                        |           |           |             |          |
| PKG:20                                                                     |              |                                                                                  |                |          |                        |           |           |             |          |
| PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01                             |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-01-002                                                               | <sup>S</sup> | OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION                              |                |          |                        |           |           | Service     | ATA:36   |
|                                                                            | MOS          | 29-Apr-24                                                                        |                |          |                        |           |           |             |          |
|                                                                            | HRS          | 1952.5                                                                           | 800 (+30/-30)  |          |                        |           |           |             |          |
|                                                                            | AFL          | 1160                                                                             |                |          |                        |           |           |             |          |
| PKG:1                                                                      |              |                                                                                  |                |          |                        |           |           |             |          |
| PROC. REF: AMM 36-11-00PROC. REF: AMM 36-11-00                             |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-02-001                                                               | <sup>S</sup> | DETAILED INSPECTION OF BLEED LINE WATER DRAINS                                   |                |          |                        |           |           | Service     | ATA:36   |
|                                                                            | MOS          | 14-May-25                                                                        | 24 (+1m/-1m)   |          |                        |           |           |             |          |
|                                                                            | HRS          | 2086.2                                                                           |                |          |                        |           |           |             |          |
|                                                                            | AFL          | 1243                                                                             |                |          |                        |           |           |             |          |
| PKG:81                                                                     |              |                                                                                  |                |          |                        |           |           |             |          |
| PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02                             |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-03                                                                   |              | AMS CONTROLLER                                                                   |                |          |                        |           |           | Component   | ATA:36   |
| PN:SYLZ-53632-205                                                          | MOS/MSC      | 29-Apr-15                                                                        | O/C            | TSN 0    |                        |           |           |             |          |
| SN:0347A                                                                   | HRS          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 36-11-03, AMM 36-11-03PROC. REF: AMM 36-11-03, AMM 36-11-03 |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-04                                                                   |              | NO. 1 ENGINE FAN AIR VALVE                                                       |                |          |                        |           |           | Component   | ATA:36   |
| PN:RYLB-53527-1                                                            | MOS/MSC      | 29-Apr-15                                                                        | O/C            | TSN 0    |                        |           |           |             |          |
| SN:0579                                                                    | HRS          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 36-11-04, AMM 36-11-04PROC. REF: AMM 36-11-04, AMM 36-11-04 |              |                                                                                  |                |          |                        |           |           |             |          |
| 36-11-04                                                                   |              | NO. 2 ENGINE FAN AIR VALVE                                                       |                |          |                        |           |           | Component   | ATA:36   |
| PN:RYLB-53527-1                                                            | MOS/MSC      | 29-Apr-15                                                                        | O/C            | TSN 0    |                        |           |           |             |          |
| SN:0572                                                                    | HRS          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
|                                                                            | AFL          | 0                                                                                |                | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 36-11-04, AMM 36-11-04PROC. REF: AMM 36-11-04, AMM 36-11-04 |              |                                                                                  |                |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                      | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                                           |           |                |          |                        |           |           |             |                  |
| 36-11-04-001 <sup>S</sup>                                                  | RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER      |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                       | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                       | 0         | 2400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-04PROC. REF: AMM 36-11-04                             |                                                           |           |                |          |                        |           |           |             |                  |
| 36-11-05                                                                   | LH INCONEL 625 BLEED PRE-COOLER                           |           |                |          |                        |           |           |             | Component ATA:36 |
| PN:10965000-105                                                            | MOS/MSC                                                   | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:T0272                                                                   | HRS                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-05, AMM 36-11-05PROC. REF: AMM 36-11-05, AMM 36-11-05 |                                                           |           |                |          |                        |           |           |             |                  |
| 36-11-05                                                                   | RH INCONEL 625 BLEED PRE-COOLER                           |           |                |          |                        |           |           |             | Component ATA:36 |
| PN:10964000-105                                                            | MOS/MSC                                                   | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:T0271                                                                   | HRS                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-05, AMM 36-11-05PROC. REF: AMM 36-11-05, AMM 36-11-05 |                                                           |           |                |          |                        |           |           |             |                  |
| 36-11-06                                                                   | CROSS BLEED VALVE                                         |           |                |          |                        |           |           |             | Component ATA:36 |
| PN:RYLB-53506-1                                                            | MOS/MSC                                                   | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:0285                                                                    | HRS                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-06, AMM 36-11-06PROC. REF: AMM 36-11-06, AMM 36-11-06 |                                                           |           |                |          |                        |           |           |             |                  |
| 36-11-06-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                       | 29-Apr-24 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                       | 1952.5    | 800 (+30/-30)  |          |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 1160      |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-06PROC. REF: AMM 36-11-06                             |                                                           |           |                |          |                        |           |           |             |                  |

PKG:20

PKG:1

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                      | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                                                         |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-06-002                                                               | <sup>S</sup> | RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS          | 29-Apr-15                                                |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                                        | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-06PROC. REF: AMM 36-11-06                             |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-07                                                                   |              | NO. 1 BLEED PRESSURE TRANSDUCER                          |                |          |                        |           |           |             | Component ATA:36 |
| PN:APTE-479F-1000-200G                                                     | MOS/MSC      | 29-Apr-15                                                | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8134-8-696                                                              | HRS          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-07, AMM 36-11-07PROC. REF: AMM 36-11-07, AMM 36-11-07 |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-07                                                                   |              | NO. 2 BLEED PRESSURE TRANSDUCER                          |                |          |                        |           |           |             | Component ATA:36 |
| PN:APTE-479F-1000-200G                                                     | MOS/MSC      | 29-Apr-15                                                | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:8134-8-702                                                              | HRS          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-07, AMM 36-11-07PROC. REF: AMM 36-11-07, AMM 36-11-07 |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-08                                                                   |              | NO. 1 BLEED TEMPERATURE SENSOR                           |                |          |                        |           |           |             | Component ATA:36 |
| PN:8TJ107DAJ1                                                              | MOS/MSC      | 29-Apr-15                                                | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:DTS9478                                                                 | HRS          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-08                                                                   |              | NO. 2 BLEED TEMPERATURE SENSOR                           |                |          |                        |           |           |             | Component ATA:36 |
| PN:8TJ107DAJ1                                                              | MOS/MSC      | 29-Apr-15                                                | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:DTS9479                                                                 | HRS          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |              |                                                          |                |          |                        |           |           |             |                  |
| 36-11-08                                                                   |              | NO. 3 BLEED TEMPERATURE SENSOR                           |                |          |                        |           |           |             | Component ATA:36 |
| PN:8TJ107DAJ1                                                              | MOS/MSC      | 29-Apr-15                                                | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:DTS9498                                                                 | HRS          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                        |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |              |                                                          |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                                     |           |                |          |                        |           |           |             |                  |
| 36-11-08                                                                   | NO. 4 BLEED TEMPERATURE SENSOR                      |           |                |          |                        |           |           |             | Component ATA:36 |
| PN:8TJ107DAJ1                                                              | MOS/MSC                                             | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:DTS9500                                                                 | HRS                                                 | 0         |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |                                                     |           |                |          |                        |           |           |             |                  |
| 36-11-08-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                 | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                 | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08                             |                                                     |           |                |          |                        |           |           |             |                  |
| 36-11-08-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                 | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                 | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08                             |                                                     |           |                |          |                        |           |           |             |                  |
| 36-11-08-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                 | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                 | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08                             |                                                     |           |                |          |                        |           |           |             |                  |
| 36-11-08-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR |           |                |          |                        |           |           |             | Service ATA:36   |
|                                                                            | MOS                                                 | 29-Apr-15 |                |          |                        |           |           |             |                  |
|                                                                            | HRS                                                 | 0         | 6400 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL                                                 | 0         |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08                             |                                                     |           |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|---------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                            |           |                |          |                        |           |            |               |                  |
| 36-21-01-001                                                               | OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS |           |                |          |                        |           |            |               | Service ATA:36   |
|                                                                            | MOS                                        | 29-Apr-15 |                |          |                        |           |            | AIRWORTHINESS |                  |
|                                                                            | HRS                                        | 0         | 6400 (+30/-30) |          | 6400                   | 6430      | 4300 (+30) |               |                  |
|                                                                            | AFL                                        | 0         |                |          |                        |           |            |               |                  |
| PROC. REF: AMM 36-21-01PROC. REF: AMM 36-21-01                             |                                            |           |                |          |                        |           |            |               |                  |
| ATA 38 - WATER/WASTE                                                       |                                            |           |                |          |                        |           |            |               |                  |
| 38-33-00                                                                   | TOILET ASSY                                |           |                |          |                        |           |            |               | Component ATA:38 |
| PN:PN                                                                      | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:UNKNOWN                                                                 | HRS                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                            |           |                |          |                        |           |            |               |                  |
| 38-33-07                                                                   | WASTE DRAIN VALVE                          |           |                |          |                        |           |            |               | Component ATA:38 |
| PN:0218-0032-1                                                             | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:223066                                                                  | HRS                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 38-33-07, AMM 38-33-07PROC. REF: AMM 38-33-07, AMM 38-33-07 |                                            |           |                |          |                        |           |            |               |                  |
| ATA 44 - CABIN SYSTEMS                                                     |                                            |           |                |          |                        |           |            |               |                  |
| 44-12-07                                                                   | 3-CHANNEL AUDIO AMPLIFER                   |           |                |          |                        |           |            |               | Component ATA:44 |
| PN:0700-005                                                                | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:14070259                                                                | HRS                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 44-12-07, AMM 44-12-07PROC. REF: AMM 44-12-07, AMM 44-12-07 |                                            |           |                |          |                        |           |            |               |                  |
| 44-21-03                                                                   | DC-DC CONVERTER                            |           |                |          |                        |           |            |               | Component ATA:44 |
| PN:PN                                                                      | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:UNKNOWN                                                                 | HRS                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 44-21-03, AMM 44-21-03PROC. REF: AMM 44-21-03, AMM 44-21-03 |                                            |           |                |          |                        |           |            |               |                  |
| 44-21-09                                                                   | IFE INSC ILLUM PANEL                       |           |                |          |                        |           |            |               | Component ATA:44 |
| PN:441-42725-001                                                           | MOS/MSC                                    | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |               |                  |
| SN:0261                                                                    | HRS                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
|                                                                            | AFL                                        | 0         |                | TSN 0    |                        |           |            |               |                  |
| PROC. REF: AMM 44-21-09, AMM 44-21-09PROC. REF: AMM 44-21-09, AMM 44-21-09 |                                            |           |                |          |                        |           |            |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 44 - CABIN SYSTEMS                                                                                                             |                            |           |          |          |                        |           |           |             |                  |
| 44-21-11                                                                                                                           | XM RECEIVER                |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-200                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14090078                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-23-21, AMM 44-23-21, AMM 44-21-11, AMM 44-21-11PROC. REF: AMM 44-23-21, AMM 44-23-21, AMM 44-21-11, AMM 44-21-11 |                            |           |          |          |                        |           |           |             |                  |
| 44-21-13                                                                                                                           | XM HEAD CONTROL            |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-300                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14120248                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-13, AMM 44-21-13PROC. REF: AMM 44-21-13, AMM 44-21-13                                                         |                            |           |          |          |                        |           |           |             |                  |
| 44-21-15                                                                                                                           | AUDIO VOLUME CONTROLLER    |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0700-008                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14060296                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-15, AMM 44-21-15PROC. REF: AMM 44-21-15, AMM 44-21-15                                                         |                            |           |          |          |                        |           |           |             |                  |
| 44-21-17                                                                                                                           | IR RECEIVER WITH CONNECTOR |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-018                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14070269                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-17, AMM 44-21-17PROC. REF: AMM 44-21-17, AMM 44-21-17                                                         |                            |           |          |          |                        |           |           |             |                  |
| 44-21-19                                                                                                                           | IR REMOTE CONTOLLER        |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-028                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14090090                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-17, AMM 44-21-17PROC. REF: AMM 44-21-17, AMM 44-21-17                                                         |                            |           |          |          |                        |           |           |             |                  |
| 44-21-21                                                                                                                           | WIRELESS AUDIO TRANSMITTER |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0700-009                                                                                                                        | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14060388                                                                                                                        | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-21, AMM 44-21-21PROC. REF: AMM 44-21-21, AMM 44-21-21                                                         |                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 44 - CABIN SYSTEMS                                                     |                                                |           |          |          |                        |           |           |             |                  |
| 44-21-23                                                                   | NO. 1 WIRELESS HEADPHONE                       |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-100                                                                | MOS/MSC                                        | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14020148                                                                | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                |           |          |          |                        |           |           |             |                  |
| 44-21-23                                                                   | NO. 2 WIRELESS HEADPHONE                       |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0500-100                                                                | MOS/MSC                                        | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14070162                                                                | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                |           |          |          |                        |           |           |             |                  |
| 44-21-25                                                                   | HEADPHONE DISTRIBUTION AMPLIFIER               |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:PN                                                                      | MOS/MSC                                        | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-21-25, AMM 44-21-25PROC. REF: AMM 44-21-25, AMM 44-21-25 |                                                |           |          |          |                        |           |           |             |                  |
| 44-22-01                                                                   | CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:0604-003                                                                | MOS/MSC                                        | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:14070370                                                                | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-22-01, AMM 44-22-01PROC. REF: AMM 44-22-01, AMM 44-22-01 |                                                |           |          |          |                        |           |           |             |                  |
| 44-22-03                                                                   | NO. 1 10.4 INCH FOLD DOWN MONITOR-             |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:1043-308                                                                | MOS/MSC                                        | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:15010148                                                                | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-22-03, AMM 44-22-03PROC. REF: AMM 44-22-03, AMM 44-22-03 |                                                |           |          |          |                        |           |           |             |                  |
| 44-32-01                                                                   | ATG5000 TRANSCEIVER                            |           |          |          |                        |           |           |             | Component ATA:44 |
| PN:P15864-002                                                              | MOS/MSC                                        | 19-May-17 | O/C      | TSR 0    |                        |           |           |             |                  |
| SN:1586400215797                                                           | HRS                                            | 714.9     |          | TSR 0    |                        |           |           |             |                  |
|                                                                            | AFL                                            | 406       |          | TSR 0    |                        |           |           |             |                  |
| PROC. REF: AMM 44-32-01, AMM 44-32-01PROC. REF: AMM 44-32-01, AMM 44-32-01 |                                                |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 44 - CABIN SYSTEMS                                                                                                             |         |           |          |          |                        |           |           |             |          |
| 44-32-03 AIRCELL CONFIGURATION MODULE                                                                                              |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-32-03, AMM 44-32-03PROC. REF: AMM 44-32-03, AMM 44-32-03                                                         |         |           |          |          |                        |           |           |             |          |
| 44-32-05 AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER                                                                      |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-32-05, AMM 44-32-05PROC. REF: AMM 44-32-05, AMM 44-32-05                                                         |         |           |          |          |                        |           |           |             |          |
| 442127-0101 LH NO. 1 AUDIO CONTROL JACK                                                                                            |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |         |           |          |          |                        |           |           |             |          |
| 442127-0102 RH NO. 2 AUDIO CONTROL JACK                                                                                            |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |         |           |          |          |                        |           |           |             |          |
| 442127-0103 LH NO. 3 AUDIO CONTROL JACK                                                                                            |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |         |           |          |          |                        |           |           |             |          |
| 442127-0104 RH NO. 4 AUDIO CONTROL JACK                                                                                            |         |           |          |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS     | 0         |          | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL     | 0         |          | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |         |           |          |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit                                                       | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 44 - CABIN SYSTEMS                                                                                                             |                                                            |           |              |          |                        |           |           |             |          |
| 442127-0105                                                                                                                        | LH NO. 5 AUDIO CONTROL JACK                                |           |              |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC                                                    | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |                                                            |           |              |          |                        |           |           |             |          |
| 442127-0106                                                                                                                        | RH NO. 6 AUDIO CONTROL JACK                                |           |              |          |                        |           |           | Component   | ATA:44   |
| PN:PN                                                                                                                              | MOS/MSC                                                    | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:UNKNOWN                                                                                                                         | HRS                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11 |                                                            |           |              |          |                        |           |           |             |          |
| ATA 52 - DOORS                                                                                                                     |                                                            |           |              |          |                        |           |           |             |          |
| 52-00-00                                                                                                                           | KEY LOCK KIT                                               |           |              |          |                        |           |           | Component   | ATA:52   |
| PN:505-09736-901                                                                                                                   | MOS/MSC                                                    | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:8MA001027CL                                                                                                                     | HRS                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                            |           |              |          |                        |           |           |             |          |
| 52-10-00-001 <sup>S</sup>                                                                                                          | INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE |           |              |          |                        |           |           | Service     | ATA:52   |
|                                                                                                                                    | MOS                                                        | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                                                                                    | HRS                                                        | 2086.2    |              |          |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 1243      |              |          |                        |           |           |             |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00                                                                       |                                                            |           |              |          |                        |           |           |             |          |
| 52-10-00-01A                                                                                                                       | PAX DOOR EQUIPPED MAIN DOOR ASSY                           |           |              |          |                        |           |           | Component   | ATA:52   |
| PN:505-09910-461                                                                                                                   | MOS/MSC                                                    | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |             |          |
| SN:0000837153                                                                                                                      | HRS                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 0         |              | TSN 0    |                        |           |           |             |          |
| PROC. REF: AMM 52-10-00, AMM 52-10-00PROC. REF: AMM 52-10-00, AMM 52-10-00                                                         |                                                            |           |              |          |                        |           |           |             |          |
| 52-10-01-001 <sup>S</sup>                                                                                                          | EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE |           |              |          |                        |           |           | Service     | ATA:52   |
|                                                                                                                                    | MOS                                                        | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                                                                                                    | HRS                                                        | 2086.2    |              |          |                        |           |           |             |          |
|                                                                                                                                    | AFL                                                        | 1243      |              |          |                        |           |           |             |          |
| PKG:84                                                                                                                             |                                                            |           |              |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 52 - DOORS                                               |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| 52-10-01-01-901                                              | GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL                                    |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS                                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| 52-10-01-02-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL                                         |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS                                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| 52-10-01-02-902                                              | DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS                                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| 52-10-02-01-901                                              | GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL                                         |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS                                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| 52-10-20-001 <sup>S</sup>                                    | GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL                                                                                  |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                              | MOS                                                                                                                                 | 14-May-25 | 12 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                 | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                 | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: AMM 52-10-20PROC. REF: AMM 52-10-20               |                                                                                                                                     |           |              |          |                        |           |           |               |          |
| PKG:80                                                       |                                                                                                                                     |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                            | Unit         | C/W                                                                               | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 52 - DOORS                                                                                                                     |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-11-00-001                                                                                                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM   |                |          |                        |           |           |             | Service ATA:52   |
|                                                                                                                                    | MOS          | 24-Apr-23                                                                         | 48 (+1m/-1m)   |          |                        |           |           |             |                  |
|                                                                                                                                    | HRS          | 1825.5                                                                            |                |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 1042                                                                              |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00                                                                                     |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-11-00-003                                                                                                                       | <sup>S</sup> | FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH                            |                |          |                        |           |           |             | Service ATA:52   |
|                                                                                                                                    | MOS          | 29-Apr-24                                                                         |                |          |                        |           |           |             |                  |
|                                                                                                                                    | HRS          | 1952.5                                                                            | 800 (+30/-30)  |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 1160                                                                              |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 52-11-23PROC. REF: AMM 52-11-23                                                                                     |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-13-00                                                                                                                           |              | MAIN DOOR BALANCE ASSY. GEAR SECTOR                                               |                |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                                                                                                              | MOS/MSC      | 29-Apr-15                                                                         | H/T            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-13-01                                                                                                                           |              | MAIN DOOR BALANCE ASSY. PINION SHAFT                                              |                |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                                                                                                              | MOS/MSC      | 29-Apr-15                                                                         | H/T            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-13-21-001                                                                                                                       | <sup>S</sup> | DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED) |                |          |                        |           |           |             | Service ATA:52   |
|                                                                                                                                    | MOS          | 29-Apr-15                                                                         |                |          |                        |           |           |             |                  |
|                                                                                                                                    | HRS          | 0                                                                                 | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 0                                                                                 |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 52-13-21PROC. REF: AMM 52-13-21                                                                                     |              |                                                                                   |                |          |                        |           |           |             |                  |
| 52-13-22                                                                                                                           |              | MAIN DOOR BALANCING MECHANISM                                                     |                |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                                                                                                              | MOS/MSC      | 29-Apr-15                                                                         | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                         | HRS          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
|                                                                                                                                    | AFL          | 0                                                                                 |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22 |              |                                                                                   |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                               | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining  | Disposition | Warranty         |
|--------------------------------------------------------------|------------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|------------|-------------|------------------|
| ATA 52 - DOORS                                               |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-13-22-001                                                 | DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE                                     |           |                |          |                        |           |            |             | Service ATA:52   |
| PN:PN                                                        | MOS/MSC                                                                            | 28-Dec-18 | O/C            |          |                        |           |            |             |                  |
| SN:UNKNOWN                                                   | HRS                                                                                | 1178.1    |                |          |                        |           |            |             |                  |
|                                                              | AFL                                                                                | 679       |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22               |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-13-22-004                                                 | DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES                                    |           |                |          |                        |           |            |             | Service ATA:52   |
|                                                              | MOS                                                                                | 29-Apr-15 |                |          |                        |           |            |             |                  |
|                                                              | HRS                                                                                | 0         | 3200 (+30/-30) |          | 3200                   | 3230      | 1100 (+30) |             |                  |
|                                                              | AFL                                                                                | 0         |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22               |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-13-23-001 <sup>S</sup>                                    | DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED) |           |                |          |                        |           |            |             | Service ATA:52   |
|                                                              | MOS                                                                                | 29-Apr-15 |                |          |                        |           |            |             |                  |
|                                                              | HRS                                                                                | 0         | 5600 (+30/-30) |          |                        |           |            |             |                  |
|                                                              | AFL                                                                                | 0         |                |          |                        |           |            |             |                  |
| PROC. REF: AMM 52-13-23PKG:50                                |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-20-00                                                     | EMERGENCY DOOR                                                                     |           |                |          |                        |           |            |             | Component ATA:52 |
| PN:500-09700-439                                             | MOS/MSC                                                                            | 29-Apr-15 | O/C            | TSN 0    |                        |           |            |             |                  |
| SN:0000837746                                                | HRS                                                                                | 0         |                | TSN 0    |                        |           |            |             |                  |
|                                                              | AFL                                                                                | 0         |                | TSN 0    |                        |           |            |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-20-01-001                                                 | EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE                     |           |                |          |                        |           |            |             | Service ATA:52   |
|                                                              | MOS/MSC                                                                            | 29-Apr-15 | O/C            |          |                        |           |            |             |                  |
|                                                              | HRS                                                                                | 0         |                |          |                        |           |            |             |                  |
|                                                              | AFL                                                                                | 0         |                |          |                        |           |            |             |                  |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00 |                                                                                    |           |                |          |                        |           |            |             |                  |
| 52-20-01-002 <sup>S</sup>                                    | INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE                     |           |                |          |                        |           |            |             | Service ATA:52   |
|                                                              | MOS                                                                                | 14-May-25 | 60 (+1m/-1m)   |          |                        |           |            |             |                  |
|                                                              | HRS                                                                                | 2086.2    |                |          |                        |           |            |             |                  |
|                                                              | AFL                                                                                | 1243      |                |          |                        |           |            |             |                  |
| PKG:90                                                       |                                                                                    |           |                |          |                        |           |            |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                                                 | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 52 - DOORS                                                                                         |                                                                                      |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00 |                                                                                      |           |              |          |                        |           |           |               |          |
| 52-20-01-01-901                                                                                        | GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL    |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                                                                        | MOS                                                                                  | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                  | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                  | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00                                           |                                                                                      |           |              |          |                        |           |           |               |          |
| 52-20-01-01-902                                                                                        | DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL  |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                                                                        | MOS                                                                                  | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                  | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                  | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00                                           |                                                                                      |           |              |          |                        |           |           |               |          |
| 52-20-20-001 <sup>S</sup>                                                                              | INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                                                                        | MOS                                                                                  | 24-Apr-23 | 48 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                  | 1825.5    |              |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                  | 1042      |              |          |                        |           |           |               |          |
| PROC. REF: AMM 52-20-20PROC. REF: AMM 52-20-20                                                         |                                                                                      |           |              |          |                        |           |           |               | PKG:83   |
| 52-20-21-001 <sup>S</sup>                                                                              | EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL                     |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                                                                        | MOS                                                                                  | 14-May-25 | 24 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                  | 2086.2    |              |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                  | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: AMM 52-20-21PROC. REF: AMM 52-20-21                                                         |                                                                                      |           |              |          |                        |           |           |               | PKG:81   |
| 52-31-20-001 <sup>S</sup>                                                                              | GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM    |           |              |          |                        |           |           | Service       | ATA:52   |
|                                                                                                        | MOS                                                                                  | 24-Apr-23 | 48 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                  | 1825.5    |              |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                  | 1042      |              |          |                        |           |           |               |          |
| PROC. REF: AMM 52-31-20PROC. REF: AMM 52-31-20                                                         |                                                                                      |           |              |          |                        |           |           |               | PKG:83   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 52 - DOORS                                                             |              |                                                                           |               |          |                        |           |           |             |                  |
| 52-32-20-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM |               |          |                        |           |           |             | Service ATA:52   |
|                                                                            | MOS          | 24-Apr-23                                                                 | 48 (+1m/-1m)  |          |                        |           |           |             |                  |
|                                                                            | HRS          | 1825.5                                                                    |               |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1042                                                                      |               |          |                        |           |           |             |                  |
| PROC. REF: AMM 52-32-20PROC. REF: AMM 52-32-20                             |              |                                                                           |               |          |                        |           |           |             |                  |
| 52-71-20                                                                   |              | LOWER PAX DOOR MICRO SWITCH ASSEMBLY                                      |               |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                 | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                         |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                         |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-71-20, AMM 52-71-20PROC. REF: AMM 52-71-20, AMM 52-71-20 |              |                                                                           |               |          |                        |           |           |             |                  |
| 52-71-20                                                                   |              | UPPER PAX DOOR MICRO SWITCH ASSEMBLY                                      |               |          |                        |           |           |             | Component ATA:52 |
| PN:PN                                                                      | MOS/MSC      | 29-Apr-15                                                                 | O/C           | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                                                         |               | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                                                         |               | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 52-71-20, AMM 52-71-20PROC. REF: AMM 52-71-20, AMM 52-71-20 |              |                                                                           |               |          |                        |           |           |             |                  |
| ATA 53 - FUSELAGE                                                          |              |                                                                           |               |          |                        |           |           |             |                  |
| 53-00-00-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS                  |               |          |                        |           |           |             | Service ATA:53   |
|                                                                            | MOS          | 29-Apr-24                                                                 |               |          |                        |           |           |             |                  |
|                                                                            | HRS          | 1952.5                                                                    | 800 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1160                                                                      |               |          |                        |           |           |             |                  |
| PROC. REF: AMM 53-00-20PROC. REF: AMM 53-00-20                             |              |                                                                           |               |          |                        |           |           |             |                  |
| 53-05-00-001                                                               | <sup>S</sup> | DETAILED INSPECTION OF FUSELAGE DRAINS                                    |               |          |                        |           |           |             | Service ATA:53   |
|                                                                            | MOS          | 14-May-25                                                                 | 60 (+1m/-1m)  |          |                        |           |           |             |                  |
|                                                                            | HRS          | 2086.2                                                                    |               |          |                        |           |           |             |                  |
|                                                                            | AFL          | 1243                                                                      |               |          |                        |           |           |             |                  |
| PROC. REF: AMM 53-05-00PROC. REF: AMM 53-05-00                             |              |                                                                           |               |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                               | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 53-10-00-001                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES                                                                |               |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 60 (+1m/-1m)  |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 53-10-00-002                                                 |              | EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES                                               |               |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS/MSC      | 29-Apr-15                                                                                                                         | O/C           |          |                        |           |           |               |                |
|                                                              | HRS          | 0                                                                                                                                 |               |          |                        |           |           |               |                |
|                                                              | AFL          | 0                                                                                                                                 |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 53-10-00-003                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE                                                      |               |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 53-10-01-01-901                                              |              | DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL |               |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 53-10-01-01-902                                              |              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL                     |               |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-02-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-02-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL                |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-03-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL                     |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL                                      |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-04-01-901                                              | DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL        |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                              |           |          |          |                        |           |           |               |          |
| 53-10-04-01-902                                              | DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL        |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                               | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| 53-10-05-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD                                                                                  |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 14-May-25                                                                                                                                         | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                                                                            |              |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                                                                              |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| PKG:90                                                       |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| 53-10-05-01-901                                              |              | DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL                                                    |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                         |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                                 | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                                                                 | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| 53-10-07-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE                                                                       |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 14-May-25                                                                                                                                         | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                                                                            |              |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                                                                              |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| PKG:84                                                       |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| 53-10-07-01-901                                              |              | SPECIAL DETAILED INSPECTION (BOREScope) OF TRUNNIONS,DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                         |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                                 | T:15000      |          | 15000                  |           | 12900     |               |          |
|                                                              | AFL          | 0                                                                                                                                                 | T:12000      |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
|                                                              |              |                                                                                                                                                   |              |          |                        |           |           |               |          |
| 53-10-07-02-901                                              |              | DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - EXTERNAL                                           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                         |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                                 | T:15000      |          | 15000                  |           | 12900     |               |          |
|                                                              | AFL          | 0                                                                                                                                                 | T:12000      |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                   |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                                       | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                                          |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-10-07-02-902                                                            | DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WEEL STRUCTURE.    |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                                            | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                                            | HRS                                                                                                        | 0         | T:15000      |          | 15000                  |           | 12900     |               |          |
|                                                                            | AFL                                                                                                        | 0         | T:12000      |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00               |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-14-00                                                                   | NOSE RADOME                                                                                                |           |              |          |                        |           |           | Component     | ATA:53   |
| PN:5190-102-1                                                              | MOS/MSC                                                                                                    | 29-Apr-15 | O/C          | TSN 0    |                        |           |           |               |          |
| SN:634                                                                     | HRS                                                                                                        | 0         |              | TSN 0    |                        |           |           |               |          |
|                                                                            | AFL                                                                                                        | 0         |              | TSN 0    |                        |           |           |               |          |
| PROC. REF: AMM 53-14-00, AMM 53-14-00PROC. REF: AMM 53-14-00, AMM 53-14-00 |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-20-00-001 <sup>S</sup>                                                  | EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES                                          |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                                            | MOS                                                                                                        | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                            | HRS                                                                                                        | 2086.2    |              |          |                        |           |           |               |          |
|                                                                            | AFL                                                                                                        | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00               |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-20-00-002 <sup>S</sup>                                                  | INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES                                          |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                                            | MOS                                                                                                        | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                            | HRS                                                                                                        | 2086.2    |              |          |                        |           |           |               |          |
|                                                                            | AFL                                                                                                        | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00               |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-20-01-01-901                                                            | DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                                            | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                                            | HRS                                                                                                        | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                                            | AFL                                                                                                        | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00               |                                                                                                            |           |              |          |                        |           |           |               |          |
| 53-20-01-01-902                                                            | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL                     |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                                            | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                                            | HRS                                                                                                        | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                                            | AFL                                                                                                        | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00               |                                                                                                            |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                        |           |          |          |                        |           |           |               |          |
| 53-20-02-01-901                                              | DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL                                 |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                    | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                        |           |           |               |          |
| 53-20-02-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL                                                                  |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                    | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                        |           |           |               |          |
| 53-20-03-01-901                                              | DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL                                |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                    | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                        |           |           |               |          |
| 53-20-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL                                                                 |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                    | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                        |           |           |               |          |
| 53-20-04-01-901                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                    | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                                          | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-20-04-01-902                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL                                    |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-20-04-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 53-20-00PROC. REF: NDT PART 6 53-20-00 |                                                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-20-04-02-902                                              | GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL                                                        |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-20-05-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE                                               |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                           | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                           | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                                           | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |              |          |                        |           |           |               | PKG:90   |
| 53-20-05-003 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE                                                |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                           | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                           | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                                           | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |              |          |                        |           |           |               | PKG:90   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 53-20-05-01-901                                              | GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 53-20-05-02-901                                              | DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL              |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 53-20-05-03-901                                              | DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL          |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 53-20-05-04-901                                              | DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL                    |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 53-20-05-05-901                                              | GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL                     |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                          | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                                              |              |          |                        |           |           |               |                |
| 53-20-06-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE                                                                             |              |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 14-May-25                                                                                                                                    | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                                       |              |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                                         |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |              |          |                        |           |           |               |                |
| 53-20-06-002                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE                                                                            |              |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 14-May-25                                                                                                                                    | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                                       |              |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                                         |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |              |          |                        |           |           |               |                |
| 53-20-06-01-901                                              |              | DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL                                               |              |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 29-Apr-15                                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |              |          |                        |           |           |               |                |
| 53-20-06-01-902                                              |              | DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL |              |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 29-Apr-15                                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                            | T:8750       |          | 8750                   |           | 6650      |               |                |
|                                                              | AFL          | 0                                                                                                                                            | T:7000       |          | 7000                   |           | 5748      |               |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |              |          |                        |           |           |               |                |
| 53-20-07-01-901                                              |              | DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL             |              |          |                        |           |           |               | Service ATA:53 |
|                                                              | MOS          | 29-Apr-15                                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |              |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                         | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                              |           |              |          |                        |           |           |               |          |
| 53-20-07-01-902                                              | DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |              |          |                        |           |           |               |          |
| 53-20-08-002 <sup>S</sup>                                    | INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE                                                      |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                          | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                          | 1243      |              |          |                        |           |           |               |          |
| PKG:90                                                       |                                                                                                                              |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |              |          |                        |           |           |               |          |
| 53-20-08-01-901                                              | GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL                      |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |              |          |                        |           |           |               |          |
| 53-20-08-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL                       |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |              |          |                        |           |           |               |          |
| 53-20-10-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS                                                    |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                          | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                          | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                          | 1243      |              |          |                        |           |           |               |          |
| PKG:90                                                       |                                                                                                                              |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                     | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                          |           |              |          |                        |           |           |               |          |
| 53-20-10-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |              |          |                        |           |           |               |          |
| 53-20-10-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL                                |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |              |          |                        |           |           |               |          |
| 53-20-10-02-901                                              | GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL                    |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |              |          |                        |           |           |               |          |
| 53-30-00-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE                               |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                      | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                      | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                      | 1243      |              |          |                        |           |           |               |          |
|                                                              |                                                                                                                          |           |              |          |                        |           |           |               | PKG:90   |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                          |           |              |          |                        |           |           |               |          |
| 53-30-00-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES                                                           |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                      | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                      | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                      | 1243      |              |          |                        |           |           |               |          |
|                                                              |                                                                                                                          |           |              |          |                        |           |           |               | PKG:90   |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                          |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                        | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-01-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                         | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                         | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                         | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-01-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL                                         |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                         | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                         | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                         | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-02-002                                                 | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL                                                         |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS/MS                                                                                                                      | 29-Apr-15 | O/C      |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                         | 0         |          |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                         | 0         |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-02-01-901                                              | DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL                       |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                         | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                         | 0         | T:12500  |          | 12500                  |           | 10400     |               |          |
|                                                              | AFL                                                                                                                         | 0         | T:10000  |          | 10000                  |           | 8748      |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-02-01-902                                              | GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL                   |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                         | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                         | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                         | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |
| 53-30-02-01-903                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL                                          |           |          |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                         | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                         | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                         | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                             |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                          | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-03-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL                              |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL                                                           |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-04-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES                                                                              |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                           | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                           | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| PKG:90                                                       |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-04-01-901                                              | DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-04-01-902                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL        |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 53-30-05-02-901                                              | DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL                                   |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:10000      |          | 10000                  |           | 7900      |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:8000       |          | 8000                   |           | 6748      |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                 | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                      |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |
| 53-30-06-01-901                                              | DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL    |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                  | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                  | 0         | T:12500      |          | 12500                  |           | 10400     |               |          |
|                                                              | AFL                                                                                                                  | 0         | T:10000      |          | 10000                  |           | 8748      |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |
| 53-30-06-01-902                                              | GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                  | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                  | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                  | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |
| 53-30-06-01-903                                              | DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL          |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                  | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                  | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                  | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |
| 53-30-07-001 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION                                  |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                  | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                  | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                  | 1243      |              |          |                        |           |           |               |          |
|                                                              |                                                                                                                      |           |              |          |                        |           |           |               | PKG:90   |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |
| 53-30-07-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION                                  |           |              |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                  | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                  | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                  | 1243      |              |          |                        |           |           |               |          |
|                                                              |                                                                                                                      |           |              |          |                        |           |           |               | PKG:90   |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                      |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                    | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 53 - FUSELAGE                                            |                                                                                                                         |           |               |          |                        |           |           |               |          |
| 53-30-07-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL |           |               |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                     | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                     | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                     | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                         |           |               |          |                        |           |           |               |          |
| 53-30-07-01-902                                              | DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL         |           |               |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                     | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                     | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                     | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                         |           |               |          |                        |           |           |               |          |
| 53-30-08-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46                                                                         |           |               |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                     | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                     | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                     | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                         |           |               |          |                        |           |           |               |          |
| 53-30-08-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46                                                                         |           |               |          |                        |           |           | Service       | ATA:53   |
|                                                              | MOS                                                                                                                     | 14-May-25 | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                     | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                     | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                         |           |               |          |                        |           |           |               |          |
| ATA 54 - NACELLES/PYLONS                                     |                                                                                                                         |           |               |          |                        |           |           |               |          |
| 54-00-00-001 <sup>S</sup>                                    | GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS                                                                   |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                                                     | 29-Apr-24 |               |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                     | 1952.5    | 800 (+30/-30) |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                     | 1160      |               |          |                        |           |           |               |          |
| PROC. REF: AMM 54-51-20PROC. REF: AMM 54-51-20               |                                                                                                                         |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit         | C/W                                                                                                 | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 54 - NACELLES/PYLONS                                                                               |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-00-001                                                                                           | <sup>S</sup> | INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE                                  |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 14-May-25                                                                                           | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                                                                        | HRS          | 2086.2                                                                                              |              |          |                        |           |           |               |                |
|                                                                                                        | AFL          | 1243                                                                                                |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00                                           |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-00-002                                                                                           | <sup>S</sup> | INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX                                                      |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 14-May-25                                                                                           | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                                                                        | HRS          | 2086.2                                                                                              |              |          |                        |           |           |               |                |
|                                                                                                        | AFL          | 1243                                                                                                |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00 |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-01-01-901                                                                                        |              | GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 29-Apr-15                                                                                           |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                   | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                                                                        | AFL          | 0                                                                                                   | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00                                           |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-02-01-901                                                                                        |              | GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL            |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 29-Apr-15                                                                                           |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                   | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                                                                        | AFL          | 0                                                                                                   | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00                                           |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-03-001                                                                                           | <sup>S</sup> | EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.                                  |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 14-May-25                                                                                           | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                                                                        | HRS          | 2086.2                                                                                              |              |          |                        |           |           |               |                |
|                                                                                                        | AFL          | 1243                                                                                                |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00                                           |              |                                                                                                     |              |          |                        |           |           |               |                |
| 54-50-03-01-901                                                                                        |              | GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL |              |          |                        |           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 29-Apr-15                                                                                           |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                   | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                                                                        | AFL          | 0                                                                                                   | T:14000      |          | 14000                  |           | 12748     |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                             | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 54 - NACELLES/PYLONS                                     |                                                                                                  |           |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                  |           |               |          |                        |           |           |               |          |
| 54-50-03-01-902                                              | DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL                         |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                  |           |               |          |                        |           |           |               |          |
| 54-50-04-01-901                                              | GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                  |           |               |          |                        |           |           |               |          |
| 54-50-05-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES                                               |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                              | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                              | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                              | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                                  |           |               |          |                        |           |           |               | PKG:87   |
| 54-50-05-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL                  |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                              | 0         | T:15000       |          | 15000                  |           | 12900     |               |          |
|                                                              | AFL                                                                                              | 0         | T:12000       |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 6 54-55-00PROC. REF: NDT PART 6 54-55-00 |                                                                                                  |           |               |          |                        |           |           |               |          |
| 54-50-05-02-901                                              | DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL      |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                                  |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                   | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 54 - NACELLES/PYLONS                                     |                                                                                        |           |               |          |                        |           |           |               |          |
| 54-50-06-01-901                                              | DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL                |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                    | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                    | 0         | T:15000       |          | 15000                  |           | 12900     |               |          |
|                                                              | AFL                                                                                    | 0         | T:12000       |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                        |           |               |          |                        |           |           |               |          |
| 54-50-06-01-902                                              | DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL                |           |               |          |                        |           |           | Service       | ATA:54   |
|                                                              | MOS                                                                                    | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                    | 0         | T:15000       |          | 15000                  |           | 12900     |               |          |
|                                                              | AFL                                                                                    | 0         | T:12000       |          | 12000                  |           | 10748     |               |          |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                        |           |               |          |                        |           |           |               |          |
| ATA 55 - STABILIZERS                                         |                                                                                        |           |               |          |                        |           |           |               |          |
| 55-00-00-001 <sup>S</sup>                                    | GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS                             |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                    | 29-Apr-24 |               |          |                        |           |           |               |          |
|                                                              | HRS                                                                                    | 1952.5    | 800 (+30/-30) |          |                        |           |           |               |          |
|                                                              | AFL                                                                                    | 1160      |               |          |                        |           |           |               |          |
| PKG:1                                                        |                                                                                        |           |               |          |                        |           |           |               |          |
| PROC. REF: AMM 55-00-20PROC. REF: AMM 55-00-20               |                                                                                        |           |               |          |                        |           |           |               |          |
| 55-10-00                                                     | HORIZONTAL STABILIZER (COMPLETION)                                                     |           |               |          |                        |           |           | Component     | ATA:55   |
| PN:505-10700-413                                             | MOS/MSC                                                                                | 29-Apr-15 | O/C           | TSN 0    |                        |           |           |               |          |
| SN:0000837459                                                | HRS                                                                                    | 0         |               | TSN 0    |                        |           |           |               |          |
|                                                              | AFL                                                                                    | 0         |               | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                        |           |               |          |                        |           |           |               |          |
| 55-10-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                    | 14-May-25 | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                              | HRS                                                                                    | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                    | 1243      |               |          |                        |           |           |               |          |
| PKG:84                                                       |                                                                                        |           |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                        |           |               |          |                        |           |           |               |          |

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                               | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-10-00-002                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING                                            |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 60 (+1m/-1m)  |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-10-01-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILZER-TO-HORIZONTAL STABILIZER ATTACHMENTS                                     |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-10-01-01-901                                              |              | DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-10-02-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-10-02-01-902                                              |              | DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL                      |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                   | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                                       |               |          |                        |           |           |               |                |
| 55-10-03-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN                                                     |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                             | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                                |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                                  |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                       |               |          |                        |           |           |               |                |
| 55-10-03-002                                                 | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN                                          |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                             | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                                |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                                  |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                       |               |          |                        |           |           |               |                |
| 55-10-03-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                             |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                     | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                     | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                       |               |          |                        |           |           |               |                |
| 55-10-03-01-902                                              |              | DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL                           |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                             |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                     | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                     | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                       |               |          |                        |           |           |               |                |
| 55-10-04-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL                      |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                             |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                     | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                     | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                       |               |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                          | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-001                                                 | <sup>S</sup> | INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS                                                          |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                    | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                       |              |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                         |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL            |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-02-901                                              |              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 6 55-10-00PROC. REF: NDT PART 6 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-02-902                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                 |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-03-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                           |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |
| 55-10-05-04-901                                              |              | DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                      |              |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                              |              |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                            | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                                 |           |               |          |                        |           |           |               |          |
| 55-10-05-05-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                                 |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                             | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                             | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                             | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 55-10-00PROC. REF: NDT PART 6 55-10-00 |                                                                                                                                                 |           |               |          |                        |           |           |               |          |
| 55-10-07-01-901                                              | GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL                                                    |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                             | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                             | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                             | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                                 |           |               |          |                        |           |           |               |          |
| 55-10-08-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS                                                      |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                             | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                             | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                             | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                                 |           |               |          |                        |           |           |               |          |
| 55-10-08-01-901                                              | DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                             | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                             | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                             | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                                 |           |               |          |                        |           |           |               |          |
| 55-10-09-001                                                 | EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT                                                     |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS/MS                                                                                                                                          | 29-Apr-15 | O/C           |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                             | 0         |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                             | 0         |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                                 |           |               |          |                        |           |           |               |          |

PKG:87

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                                                                             | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                                                                   |                                                                                                                  |           |               |          |                        |           |           |               |          |
| 55-10-09-01-901                                                                                        | DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00                                           |                                                                                                                  |           |               |          |                        |           |           |               |          |
| 55-10-09-01-902                                                                                        | DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00                                           |                                                                                                                  |           |               |          |                        |           |           |               |          |
| 55-10-10-001 <sup>S</sup>                                                                              | EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS                                                 |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                              | 14-May-25 | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                                              | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                              | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-10-00PKG:90                                                                   |                                                                                                                  |           |               |          |                        |           |           |               |          |
| 55-10-10-01-901                                                                                        | DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL   |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                              | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                                              | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                                              | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00                                           |                                                                                                                  |           |               |          |                        |           |           |               |          |
| 55-20-01-002 <sup>S</sup>                                                                              | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX                                              |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                              | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                                              | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                              | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00PKG:87                                              |                                                                                                                  |           |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00 |                                                                                                                  |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                     | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |                                                                                                                          |           |               |          |                        |           |           |               |          |
| 55-20-01-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL                 |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               |          |
| 55-20-01-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               |          |
| 55-20-02-01-901                                              | DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL                                           |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               |          |
| 55-20-02-02-901                                              | GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL                                         |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               |          |
| 55-20-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY                                                     |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                      | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                      | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               | PKG:87   |
| 55-20-03-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL          |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                      | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                      | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                      | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 55-20-00PROC. REF: NDT PART 6 55-20-00 |                                                                                                                          |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                                                                          | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                                                                   |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-20-03-02-901                                                                                        | SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL     |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                           | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                                                                        | HRS                                                                                                           | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                                                                        | AFL                                                                                                           | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 8 55-20-00PROC. REF: NDT PART 8 55-20-00                                           |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-20-04-001                                                                                           | INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS                            |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                           | 14-May-25 | 60            |          | 14-May-30              |           | 1793 d    | ALI           |          |
|                                                                                                        | HRS                                                                                                           | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                           | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00 |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-20-04-002                                                                                           | SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS                             |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                           | 14-May-25 | 60            |          | 14-May-30              |           | 1793 d    | ALI           |          |
|                                                                                                        | HRS                                                                                                           | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                           | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-22-00-001 <sup>S</sup>                                                                              | EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB                                                      |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                           | 14-May-25 | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                                           | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                           | 1243      |               |          |                        |           |           |               |          |
| PKG:90                                                                                                 |                                                                                                               |           |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-22-00PROC. REF: NDT PART 5 55-22-00                                           |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-30-00                                                                                               | VERTICAL STABILIZER                                                                                           |           |               |          |                        |           |           | Component     | ATA:55   |
| PN:505-10100-415                                                                                       | MOS/MSC                                                                                                       | 29-Apr-15 | O/C           | TSN 0    |                        |           |           |               |          |
| SN:0000840891                                                                                          | HRS                                                                                                           | 0         |               | TSN 0    |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                           | 0         |               | TSN 0    |                        |           |           |               |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                     |                                                                                                               |           |               |          |                        |           |           |               |          |
| 55-30-01-001 <sup>S</sup>                                                                              | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                                                                        | MOS                                                                                                           | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                                                                        | HRS                                                                                                           | 2086.2    |               |          |                        |           |           |               |          |
|                                                                                                        | AFL                                                                                                           | 1243      |               |          |                        |           |           |               |          |
| PKG:87                                                                                                 |                                                                                                               |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit | C/W                                                                                                                                                           | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| 55-30-01-002                                                 | S    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER                                                     |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS  | 14-May-25                                                                                                                                                     | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS  | 2086.2                                                                                                                                                        |              |          |                        |           |           |               |          |
|                                                              | AFL  | 1243                                                                                                                                                          |              |          |                        |           |           |               |          |
| PKG:90                                                       |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| 55-30-01-01-901                                              |      | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS  | 29-Apr-15                                                                                                                                                     |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS  | 0                                                                                                                                                             | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL  | 0                                                                                                                                                             | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| 55-30-01-02-901                                              |      | DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                          |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS  | 29-Apr-15                                                                                                                                                     |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS  | 0                                                                                                                                                             | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL  | 0                                                                                                                                                             | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| 55-30-01-03-901                                              |      | DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                                                    |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS  | 29-Apr-15                                                                                                                                                     |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS  | 0                                                                                                                                                             | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL  | 0                                                                                                                                                             | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |
| 55-30-01-04-901                                              |      | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL        |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS  | 29-Apr-15                                                                                                                                                     |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS  | 0                                                                                                                                                             | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL  | 0                                                                                                                                                             | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |      |                                                                                                                                                               |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                             | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                                                 |               |          |                        |           |           |               |          |
| 55-30-02-002                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER                          |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS          | 14-May-25                                                                                                                                       | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                                                                          |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                                                                            |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                                 |               |          |                        |           |           |               | PKG:87   |
| 55-30-02-01-901                                              |              | DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                       |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                                 |               |          |                        |           |           |               |          |
| 55-30-02-03-901                                              |              | DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                       |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                                 |               |          |                        |           |           |               |          |
| 55-30-02-04-901                                              |              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                       |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |              |                                                                                                                                                 |               |          |                        |           |           |               |          |
| 55-30-02-05-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL    |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS          | 29-Apr-15                                                                                                                                       |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                                 |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                                  | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |
| 55-30-02-06-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |
| 55-30-02-07-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |
| 55-30-03-001 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS                                                                                    |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                   | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                   | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                                   | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PKG:87                         |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |
| 55-30-03-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX                                                                                                   |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                   | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                                   | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                                   | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00PKG:87    |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |
| 55-30-03-01-901                                              | DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL                                                                            |           |               |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                              | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| 55-30-03-01-902                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL |           |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                               | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                               | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                               | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| 55-30-04-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING                                                |           |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                               | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                               | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                               | 1243      |              |          |                        |           |           |               |          |
| PKG:84                                                       |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| 55-30-04-01-901                                              | GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL                                         |           |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                               | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                               | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                               | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| 55-30-05-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER                      |           |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                               | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                               | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                               | 1243      |              |          |                        |           |           |               |          |
| PKG:84                                                       |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |              |          |                        |           |           |               |          |
| 55-30-05-01-901                                              | DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL  |           |              |          |                        |           |           | Service       | ATA:55   |
|                                                              | MOS                                                                                                                               | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                               | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                               | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                               | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-30-06-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING                                                           |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 60 (+1m/-1m)  |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-30-06-01-901                                              |              | DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-40-01-002                                                 | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX                                                                 |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                         | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                            |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                              |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-40-01-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL                            |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |
| 55-40-01-01-902                                              |              | DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL            |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                         |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                                   |               |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                          | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-02-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS                                                                 |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                    | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                       |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                         |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-02-01-901                                              |              | DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL                                               |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-02-02-901                                              |              | GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL                                        |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-03-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY                                                           |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                    | 120 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                                       |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                         |               |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-03-01-901                                              |              | GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 29-Apr-15                                                                                                                    |               |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                            | T:17500       |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                                            | T:14000       |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                              |               |          |                        |           |           |               |                |
| 55-40-04-002                                                 |              | INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS                                  |               |          |                        |           |           |               | Service ATA:55 |
|                                                              | MOS          | 14-May-25                                                                                                                    | 60            |          | 14-May-30              |           | 1793 d    | ALI           |                |
|                                                              | HRS          | 2086.2                                                                                                                       |               |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                                         |               |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 55 - STABILIZERS

PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00

|              |                                                                                                    |           |    |  |           |  |        |         |        |
|--------------|----------------------------------------------------------------------------------------------------|-----------|----|--|-----------|--|--------|---------|--------|
| 55-40-04-003 | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS |           |    |  |           |  |        | Service | ATA:55 |
|              | MOS                                                                                                | 14-May-25 | 60 |  | 14-May-30 |  | 1793 d | ALI     |        |
|              | HRS                                                                                                | 2086.2    |    |  |           |  |        |         |        |
|              | AFL                                                                                                | 1243      |    |  |           |  |        |         |        |

PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00

|                           |                                                        |           |              |  |  |  |  |         |        |
|---------------------------|--------------------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 55-42-00-001 <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB |           |              |  |  |  |  | Service | ATA:55 |
|                           | MOS                                                    | 14-May-25 | 60 (+1m/-1m) |  |  |  |  |         |        |
|                           | HRS                                                    | 2086.2    |              |  |  |  |  |         |        |
|                           | AFL                                                    | 1243      |              |  |  |  |  |         |        |

PKG:90

PROC. REF: NDT PART 5 55-42-00PROC. REF: NDT PART 5 55-42-00

## ATA 56 - WINDOWS

|                |                                      |           |     |       |  |  |  |           |        |
|----------------|--------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-10-00       | COPILOT HEATED GLASS WINDSHIELD ASSY |           |     |       |  |  |  | Component | ATA:56 |
| PN:NP-195301-4 | MOS/MSC                              | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:14084H0032  | HRS                                  | 0         |     | TSN 0 |  |  |  |           |        |
|                | AFL                                  | 0         |     | TSN 0 |  |  |  |           |        |

PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00

|                |                                    |           |     |       |  |  |  |           |        |
|----------------|------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-10-00       | PILOT HEATED GLASS WINDSHIELD ASSY |           |     |       |  |  |  | Component | ATA:56 |
| PN:NP-195301-3 | MOS/MSC                            | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:14070H8441  | HRS                                | 0         |     | TSN 0 |  |  |  |           |        |
|                | AFL                                | 0         |     | TSN 0 |  |  |  |           |        |

PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00

|                           |                                                                      |           |              |  |  |  |  |         |        |
|---------------------------|----------------------------------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 56-10-01-001 <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOWS PANE (BOTH SIDES) |           |              |  |  |  |  | Service | ATA:56 |
|                           | MOS                                                                  | 14-May-25 | 60 (+1m/-1m) |  |  |  |  |         |        |
|                           | HRS                                                                  | 2086.2    |              |  |  |  |  |         |        |
|                           | AFL                                                                  | 1243      |              |  |  |  |  |         |        |

PKG:84

PROC. REF: NDT PART 5 56-12-00PROC. REF: NDT PART 5 56-12-00

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                  | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|--------------------------------------------------------------|-----------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 56 - WINDOWS                                             |                                                                       |           |                |          |                        |           |             |             |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS      |           |                |          |                        |           |             |             | Service ATA:56 |
| PN:NP-195302-4                                               | MOS                                                                   | 10-Jan-17 |                |          |                        |           |             |             |                |
| SN:14165H8955                                                | HRS                                                                   | 606.7     | 1600 (+30/-30) |          | 2206.7                 | 2236.7    | 106.7 (+30) |             |                |
|                                                              | AFL                                                                   | 345       |                |          |                        |           |             |             |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                |          |                        |           |             |             |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS       |           |                |          |                        |           |             |             | Service ATA:56 |
| PN:NP-195301-4                                               | MOS                                                                   | 10-Jan-17 |                |          |                        |           |             |             |                |
| SN:14084H0032                                                | HRS                                                                   | 606.7     | 1600 (+30/-30) |          | 2206.7                 | 2236.7    | 106.7 (+30) |             |                |
|                                                              | AFL                                                                   | 345       |                |          |                        |           |             |             |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                |          |                        |           |             |             |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW ATTACHING BOLTS        |           |                |          |                        |           |             |             | Service ATA:56 |
| PN:NP-195302-3                                               | MOS                                                                   | 10-Jan-17 |                |          |                        |           |             |             |                |
| SN:14202H2731                                                | HRS                                                                   | 606.7     | 1600 (+30/-30) |          | 2206.7                 | 2236.7    | 106.7 (+30) |             |                |
|                                                              | AFL                                                                   | 345       |                |          |                        |           |             |             |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                |          |                        |           |             |             |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS         |           |                |          |                        |           |             |             | Service ATA:56 |
| PN:NP-195301-3                                               | MOS                                                                   | 10-Jan-17 |                |          |                        |           |             |             |                |
| SN:14070H8441                                                | HRS                                                                   | 606.7     | 1600 (+30/-30) |          | 2206.7                 | 2236.7    | 106.7 (+30) |             |                |
|                                                              | AFL                                                                   | 345       |                |          |                        |           |             |             |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                |          |                        |           |             |             |                |
| 56-10-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE |           |                |          |                        |           |             |             | Service ATA:56 |
|                                                              | MOS                                                                   | 14-May-25 | 60 (+1m/-1m)   |          |                        |           |             |             |                |
|                                                              | HRS                                                                   | 2086.2    |                |          |                        |           |             |             |                |
|                                                              | AFL                                                                   | 1243      |                |          |                        |           |             |             |                |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00 |                                                                       |           |                |          |                        |           |             |             | PKG:90         |
| 56-10-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE |           |                |          |                        |           |             |             | Service ATA:56 |
|                                                              | MOS                                                                   | 14-May-25 | 60 (+1m/-1m)   |          |                        |           |             |             |                |
|                                                              | HRS                                                                   | 2086.2    |                |          |                        |           |             |             |                |
|                                                              | AFL                                                                   | 1243      |                |          |                        |           |             |             |                |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00 |                                                                       |           |                |          |                        |           |             |             | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                                                                                           | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 56 - WINDOWS                                                           |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-10-03-001                                                               | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE                                                 |              |          |                        |           |           |               | Service ATA:56   |
|                                                                            | MOS          | 14-May-25                                                                                                     | 60 (+1m/-1m) |          |                        |           |           |               |                  |
|                                                                            | HRS          | 2086.2                                                                                                        |              |          |                        |           |           |               |                  |
|                                                                            | AFL          | 1243                                                                                                          |              |          |                        |           |           |               |                  |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00               |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-10-03-001                                                               | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE                                                |              |          |                        |           |           |               | Service ATA:56   |
|                                                                            | MOS          | 14-May-25                                                                                                     | 60 (+1m/-1m) |          |                        |           |           |               |                  |
|                                                                            | HRS          | 2086.2                                                                                                        |              |          |                        |           |           |               |                  |
|                                                                            | AFL          | 1243                                                                                                          |              |          |                        |           |           |               |                  |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00               |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-10-03-01-901                                                            |              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL |              |          |                        |           |           |               | Service ATA:56   |
|                                                                            | MOS          | 29-Apr-15                                                                                                     |              |          |                        |           |           | AIRWORTHINESS |                  |
|                                                                            | HRS          | 0                                                                                                             | T:17500      |          | 17500                  |           | 15400     |               |                  |
|                                                                            | AFL          | 0                                                                                                             | T:14000      |          | 14000                  |           | 12748     |               |                  |
| PROC. REF: NDT PART 6 56-10-00PROC. REF: NDT PART 6 56-10-00               |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-12-00                                                                   |              | COPILOT ACRYLIC SIDE WINDOW                                                                                   |              |          |                        |           |           |               | Component ATA:56 |
| PN:NP-195302-4                                                             | MOS/MSC      | 29-Apr-15                                                                                                     | O/C          | TSN 0    |                        |           |           |               |                  |
| SN:14165H8955                                                              | HRS          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00 |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-12-00                                                                   |              | PILOT ACRYLIC SIDE WINDOW                                                                                     |              |          |                        |           |           |               | Component ATA:56 |
| PN:NP-195302-3                                                             | MOS/MSC      | 29-Apr-15                                                                                                     | O/C          | TSN 0    |                        |           |           |               |                  |
| SN:14202H2731                                                              | HRS          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00 |              |                                                                                                               |              |          |                        |           |           |               |                  |
| 56-20-00                                                                   |              | NO. 1 WINDOW TRANSPARENCY                                                                                     |              |          |                        |           |           |               | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC      | 29-Apr-15                                                                                                     | O/C          | TSN 0    |                        |           |           |               |                  |
| SN:2202016                                                                 | HRS          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |              | TSN 0    |                        |           |           |               |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |              |                                                                                                               |              |          |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|----------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 56 - WINDOWS                                                           |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 10 WINDOW TRANSPARENCY |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2323922                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 11 WINDOW TRANSPARENCY |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2323955                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 2 WINDOW TRANSPARENCY  |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2267118                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 3 WINDOW TRANSPARENCY  |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2313438                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 4 WINDOW TRANSPARENCY  |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2313442                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |
| 56-20-00                                                                   | NO. 5 WINDOW TRANSPARENCY  |           |          |          |                        |           |           |             | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2313445                                                                 | HRS                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 56 - WINDOWS

|                                                                            |                           |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 6 WINDOW TRANSPARENCY |           |     |       |  |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:2313454                                                                 | HRS                       | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 7 WINDOW TRANSPARENCY |           |     |       |  |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:2313467                                                                 | HRS                       | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 8 WINDOW TRANSPARENCY |           |     |       |  |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:2318726                                                                 | HRS                       | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 9 WINDOW TRANSPARENCY |           |     |       |  |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:2318728                                                                 | HRS                       | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |  |           |        |

|                                                              |                                                                   |           |              |  |  |  |  |         |        |
|--------------------------------------------------------------|-------------------------------------------------------------------|-----------|--------------|--|--|--|--|---------|--------|
| 56-20-01-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS |           |              |  |  |  |  | Service | ATA:56 |
|                                                              | MOS                                                               | 14-May-25 | 60 (+1m/-1m) |  |  |  |  |         |        |
|                                                              | HRS                                                               | 2086.2    |              |  |  |  |  |         |        |
|                                                              | AFL                                                               | 1243      |              |  |  |  |  |         |        |
| PROC. REF: NDT PART 5 56-20-00PROC. REF: NDT PART 5 56-20-00 |                                                                   |           |              |  |  |  |  |         |        |

PKG:84

### ATA 57 - WINGS

|                           |                                                         |           |               |  |  |  |  |         |        |
|---------------------------|---------------------------------------------------------|-----------|---------------|--|--|--|--|---------|--------|
| 57-00-00-001 <sup>S</sup> | GENERAL VISUAL INSPECTION OF WINGLET POLYURETHANE FILMS |           |               |  |  |  |  | Service | ATA:57 |
|                           | MOS                                                     | 29-Apr-24 |               |  |  |  |  |         |        |
|                           | HRS                                                     | 1952.5    | 800 (+30/-30) |  |  |  |  |         |        |
|                           | AFL                                                     | 1160      |               |  |  |  |  |         |        |

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                           | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |              |                                                                                               |               |          |                        |           |           |               |          |
| PROC. REF: AMM 57-35-21PROC. REF: AMM 57-35-21               |              |                                                                                               |               |          |                        |           |           |               |          |
| 57-10-00-001                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX                                          |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                     | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                        |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                          |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                               |               |          |                        |           |           |               | PKG:90   |
| 57-10-00-002                                                 | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN                      |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                     | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                        |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                          |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                               |               |          |                        |           |           |               | PKG:87   |
| 57-10-01-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS                    |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                     | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                        |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                          |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-00-00PROC. REF: NDT PART 5 57-00-00 |              |                                                                                               |               |          |                        |           |           |               | PKG:87   |
| 57-10-01-01-901                                              |              | DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 29-Apr-15                                                                                     |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                             | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                             | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                               |               |          |                        |           |           |               |          |
| 57-10-02-002                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR                                        |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                     | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                        |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                          |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                               |               |          |                        |           |           |               | PKG:90   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                           | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-02-01-901                                              | DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL          |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                            | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                            | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-03-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR                                                          |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                            | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                            | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-03-01-901                                              | DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                            | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                            | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-04-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR                                                          |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                            | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                            | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-20-00PROC. REF: NDT PART 5 57-20-00 |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-04-01-901                                              | DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL                                               |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                            | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                            | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |              |          |                        |           |           |               |          |
| 57-10-05-01-901                                              | GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL                 |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                            | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                            | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                            | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |              |                                                                                                    |               |          |                        |           |           |               |          |
| 57-10-06-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL                                            |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                          | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                             |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                               |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |               |          |                        |           |           |               | PKG:87   |
| 57-10-07-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL                                            |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 14-May-25                                                                                          | 60 (+1m/-1m)  |          |                        |           |           |               |          |
|                                                              | HRS          | 2086.2                                                                                             |               |          |                        |           |           |               |          |
|                                                              | AFL          | 1243                                                                                               |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |               |          |                        |           |           |               | PKG:84   |
| 57-10-07-01-901                                              |              | GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 29-Apr-15                                                                                          |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                  | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                  | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |               |          |                        |           |           |               |          |
| 57-10-07-01-902                                              |              | DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL                                 |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 29-Apr-15                                                                                          |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                  | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                  | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |               |          |                        |           |           |               |          |
| 57-10-08-01-901                                              |              | DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL                                         |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS          | 29-Apr-15                                                                                          |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS          | 0                                                                                                  | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL          | 0                                                                                                  | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |               |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-10-08-02-901                                              | DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL                                                 |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-10-11-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE                                                           |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                                 | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                 | 2086.2    |              |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                 | 1243      |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-10-11-01-901                                              | DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL       |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-10-11-01-902                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                                 | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                 | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                                 | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-10-12-01-901                                              | DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL                         |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS/MS                                                                                                              | 29-Apr-15 | N/A          |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                 | 0         |              |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                 | 0         |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |
| 57-50-01-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS                  |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                                 | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                                 | 2086.2    |              |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                                 | 1243      |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                     |           |              |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 57-50-01-01-901                                              | DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL                  |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 57-50-01-01-902                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL                 |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                        | 0         | T:11250  |          | 11250                  |           | 9150      |               |          |
|                                                              | AFL                                                                                                                                                        | 0         | T:9000   |          | 9000                   |           | 7748      |               |          |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 57-50-01-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 57-50-01-03-901                                              | DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL                   |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                            |           |          |          |                        |           |           |               |          |
| 57-50-01-04-901                                              | DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL                    |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                        | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                        | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                        | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                            |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                         | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                              |           |              |          |                        |           |           |               |          |
| 57-50-01-05-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL      |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                              |           |              |          |                        |           |           |               |          |
| 57-50-01-05-902                                              | DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL                             |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                              |           |              |          |                        |           |           |               |          |
| 57-50-02-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK                                                         |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                          | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                                          | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                          | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-20-00PROC. REF: NDT PART 5 57-20-00 |                                                                                                                                                              |           |              |          |                        |           |           |               |          |
| 57-50-02-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                              |           |              |          |                        |           |           |               |          |
| 57-50-02-01-902                                              | DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL                        |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                          | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                              |           |              |          |                        |           |           |               |          |

PKG:84

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                          | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 57-50-02-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 57-50-02-02-902                                              | DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL                        |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 57-52-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP                                                                            |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                           | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                           | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                           | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 57-52-00-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP                                                                                       |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                           | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                                           | 2086.2    |              |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                           | 1243      |              |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |
| 57-52-01-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL                                     |           |              |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                           | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                           | 0         | T:17500      |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                           | 0         | T:14000      |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |              |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                  | C/W       | Interval      | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-52-01-01-902                                              | DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL                                 |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-52-02-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL                                    |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-52-03-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL                             |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                   | 0         | T:11250       |          | 11250                  |           | 9150      |               |          |
|                                                              | AFL                                                                                                                   | 0         | T:9000        |          | 9000                   |           | 7748      |               |          |
| PROC. REF: NDT PART 6 57-52-00PROC. REF: NDT PART 6 57-52-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-52-04-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL    |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-52-04-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 29-Apr-15 |               |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-52-00PROC. REF: NDT PART 6 57-52-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |
| 57-53-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE OUTBOARD FLAP                                                   |           |               |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                   | 14-May-25 | 120 (+1m/-1m) |          |                        |           |           |               |          |
|                                                              | HRS                                                                                                                   | 2086.2    |               |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                   | 1243      |               |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                       |           |               |          |                        |           |           |               |          |

PKG:87

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                       | C/W       | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 57 - WINGS                                               |                                                                                                            |           |              |          |                        |           |           |               |                |
| 57-53-00-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP                                                   |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                        | 14-May-25 | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS                                                                                                        | 2086.2    |              |          |                        |           |           |               |                |
|                                                              | AFL                                                                                                        | 1243      |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                            |           |              |          |                        |           |           |               | PKG:84         |
| 57-53-01-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                        | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                        | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                            |           |              |          |                        |           |           |               |                |
| 57-53-01-01-902                                              | DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL                     |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                        | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                        | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                            |           |              |          |                        |           |           |               |                |
| 57-53-02-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL                        |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                        | 0         | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL                                                                                                        | 0         | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                            |           |              |          |                        |           |           |               |                |
| 57-53-03-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL                 |           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS                                                                                                        | 29-Apr-15 |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                        | 0         | T:11250      |          | 11250                  |           | 9150      |               |                |
|                                                              | AFL                                                                                                        | 0         | T:9000       |          | 9000                   |           | 7748      |               |                |
| PROC. REF: NDT PART 6 57-53-00PROC. REF: NDT PART 6 57-53-00 |                                                                                                            |           |              |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit                                                                                                                                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|---------------|----------|
| ATA 57 - WINGS                                               |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |
| 57-53-04-01-901                                              | DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL                         |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                              | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |
| 57-53-04-02-901                                              | DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL                         |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                              | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |
| 57-53-04-03-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                              | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |
| 57-53-04-04-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                              | 29-Apr-15 |          |          |                        |           |           | AIRWORTHINESS |          |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                  |           | 15400     |               |          |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                  |           | 12748     |               |          |
| PROC. REF: NDT PART 6 57-53-00PROC. REF: NDT PART 6 57-53-00 |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |
| 57-60-00-001                                                 | EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON                                                                                                               |           |          |          |                        |           |           | Service       | ATA:57   |
|                                                              | MOS                                                                                                                                                              | 14-May-25 | 60       |          | 14-May-30              |           | 1793 d    | ALI           |          |
|                                                              | HRS                                                                                                                                                              | 2086.2    |          |          |                        |           |           |               |          |
|                                                              | AFL                                                                                                                                                              | 1243      |          |          |                        |           |           |               |          |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                                                                                                  |           |          |          |                        |           |           |               |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit         | C/W                                                                                                     | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty       |
|--------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|---------------|----------------|
| ATA 57 - WINGS                                               |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-00-002                                                 | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON AND TAB                                       |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 14-May-25                                                                                               | 60 (+1m/-1m) |          |                        |           |           |               |                |
|                                                              | HRS          | 2086.2                                                                                                  |              |          |                        |           |           |               |                |
|                                                              | AFL          | 1243                                                                                                    |              |          |                        |           |           |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-01-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 29-Apr-15                                                                                               |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                       | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                       | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-01-01-902                                              |              | DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL                     |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 29-Apr-15                                                                                               |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                       | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                       | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-01-02-901                                              |              | DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL                                   |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 29-Apr-15                                                                                               |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                       | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                       | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-02-01-901                                              |              | DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL                           |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 29-Apr-15                                                                                               |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                       | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                       | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |
| 57-60-02-02-901                                              |              | DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL                       |              |          |                        |           |           |               | Service ATA:57 |
|                                                              | MOS          | 29-Apr-15                                                                                               |              |          |                        |           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                       | T:17500      |          | 17500                  |           | 15400     |               |                |
|                                                              | AFL          | 0                                                                                                       | T:14000      |          | 14000                  |           | 12748     |               |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |              |                                                                                                         |              |          |                        |           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                      | Unit     | C/W                                                             | Interval     | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|--------------------------------------------------------------|----------|-----------------------------------------------------------------|--------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 57 - WINGS                                               |          |                                                                 |              |          |                        |           |           |             |          |
| 57-70-02-001                                                 | S        | EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS   |              |          |                        |           |           | Service     | ATA:57   |
|                                                              | MOS      | 14-May-25                                                       | 60 (+1m/-1m) |          |                        |           |           |             |          |
|                                                              | HRS      | 2086.2                                                          |              |          |                        |           |           |             |          |
|                                                              | AFL      | 1243                                                            |              |          |                        |           |           |             |          |
| PROC. REF: NDT PART 5 57-70-00PROC. REF: NDT PART 5 57-70-00 |          |                                                                 |              |          |                        |           |           |             |          |
| ATA 70 - STANDARD PRACTICES - ENGINES                        |          |                                                                 |              |          |                        |           |           |             |          |
| 700010                                                       |          | NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION                    |              |          |                        |           |           | Service     | ATA:70   |
|                                                              | MOS/MSC  | 26-Nov-14                                                       | A/R          |          |                        |           |           |             |          |
|                                                              | HRS      | 0                                                               |              |          |                        |           |           |             |          |
|                                                              | ENC      | 0                                                               |              |          |                        |           |           |             |          |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00                 |          |                                                                 |              |          |                        |           |           |             |          |
| 700010                                                       |          | NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION                    |              |          |                        |           |           | Service     | ATA:70   |
|                                                              | MOS/MSC  | 27-Nov-14                                                       | A/R          |          |                        |           |           |             |          |
|                                                              | HRS      | 0                                                               |              |          |                        |           |           |             |          |
|                                                              | ENC      | 0                                                               |              |          |                        |           |           |             |          |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00                 |          |                                                                 |              |          |                        |           |           |             |          |
| ATA 71 - POWER PLANT                                         |          |                                                                 |              |          |                        |           |           |             |          |
| 70-00-00-200-801                                             |          | NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS |              |          |                        |           |           | Service     | ATA:71   |
|                                                              | MOS/MSC  | 26-Nov-14                                                       | A/R          |          |                        |           |           |             |          |
|                                                              | HRS      | 0                                                               |              |          |                        |           |           |             |          |
|                                                              | ENC      | 0                                                               |              |          |                        |           |           |             |          |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00                 |          |                                                                 |              |          |                        |           |           |             |          |
| 70-00-00-200-801                                             |          | NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS |              |          |                        |           |           | Service     | ATA:71   |
|                                                              | MOS/MSC  | 27-Nov-14                                                       | A/R          |          |                        |           |           |             |          |
|                                                              | HRS      | 0                                                               |              |          |                        |           |           |             |          |
|                                                              | ENC      | 0                                                               |              |          |                        |           |           |             |          |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00                 |          |                                                                 |              |          |                        |           |           |             |          |
| 71-00-00-160-805                                             |          | NO. 1 ENGINE - COMPRESSOR WASH                                  |              |          |                        |           |           | Service     | ATA:71   |
|                                                              | DAYS/MSC | 24-Apr-23                                                       | A/R          |          |                        |           |           |             |          |
|                                                              | HRS      | 1825.5                                                          |              |          |                        |           |           |             |          |
|                                                              | ENC      | 1042                                                            |              |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                                                   | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------|----------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 71 - POWER PLANT                         |                                                                                        |           |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-160-805                             | NO. 2 ENGINE - COMPRESSOR WASH                                                         |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | DAYS/MS                                                                                | 24-Apr-23 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 1825.5    |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 1042      |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-160-806                             | NO. 1 ENGINE - PERFORMANCE RECOVERY WASH                                               |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | MOS/MS                                                                                 | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-160-806                             | NO. 2 ENGINE - PERFORMANCE RECOVERY WASH                                               |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | MOS/MS                                                                                 | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-760-810                             | NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN                                   |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | MOS/MS                                                                                 | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-760-810                             | NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN                                   |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | MOS/MS                                                                                 | 27-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |
|                                              |                                                                                        |           |          |          |                        |           |           |             |                |
| 71-00-00-760-814                             | NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK |           |          |          |                        |           |           |             | Service ATA:71 |
|                                              | MOS/MS                                                                                 | 26-Nov-14 | A/R      |          |                        |           |           |             |                |
|                                              | HRS                                                                                    | 0         |          |          |                        |           |           |             |                |
|                                              | ENC                                                                                    | 0         |          |          |                        |           |           |             |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                        |           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                                                   | C/W       | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition                   | Warranty       |
|----------------------------------------------|----------------------------------------------------------------------------------------|-----------|------------|----------|------------------------|-----------|-------------|-------------------------------|----------------|
| ATA 71 - POWER PLANT                         |                                                                                        |           |            |          |                        |           |             |                               |                |
| 71-00-00-760-814                             | NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK |           |            |          |                        |           |             |                               | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 27-Nov-14 | A/R        |          |                        |           |             |                               |                |
|                                              | HRS                                                                                    | 0         |            |          |                        |           |             |                               |                |
|                                              | ENC                                                                                    | 0         |            |          |                        |           |             |                               |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |            |          |                        |           |             |                               |                |
| 71-00-00-760-817                             | NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA                                                |           |            |          |                        |           |             |                               | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 26-Nov-14 | A/R        |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                                                    | 0         |            |          |                        |           |             |                               |                |
|                                              | ENC                                                                                    | 0         |            |          |                        |           |             |                               |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |            |          |                        |           |             |                               |                |
| 71-00-00-760-817                             | NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA                                                |           |            |          |                        |           |             |                               | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 27-Nov-14 | A/R        |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                                                    | 0         |            |          |                        |           |             |                               |                |
|                                              | ENC                                                                                    | 0         |            |          |                        |           |             |                               |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |            |          |                        |           |             |                               |                |
| 71-00-00-760-823                             | NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)                                    |           |            |          |                        |           |             |                               | Service ATA:71 |
|                                              | MOS                                                                                    | 14-May-25 | 12 (+30d)  |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |                               |                |
|                                              | HRS                                                                                    | 2086.2    | 630 (+10%) |          | (2716.2)<br>2716.2     | 2779.2    | 616.2 (+63) |                               |                |
|                                              | ENC                                                                                    | 1243      |            |          |                        |           |             |                               |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |            |          |                        |           |             |                               |                |
| 71-00-00-760-823                             | NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)                                    |           |            |          |                        |           |             |                               | Service ATA:71 |
|                                              | MOS                                                                                    | 14-May-25 | 12 (+30d)  |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |                               |                |
|                                              | HRS                                                                                    | 2086.2    | 630 (+10%) |          | (2716.2)<br>2716.2     | 2779.2    | 616.2 (+63) |                               |                |
|                                              | ENC                                                                                    | 1243      |            |          |                        |           |             |                               |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |            |          |                        |           |             |                               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit         | C/W                                         | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------|---------------------------------------------|----------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                                                       |              |                                             |                |          |                        |           |           |             |                  |
| 71-11-00-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF UPPER MID COWL |                |          |                        |           |           |             | Service ATA:71   |
|                                                                            | MOS          | 29-Apr-15                                   |                |          |                        |           |           |             |                  |
|                                                                            | HRS          | 0                                           | 5600 (+30/-30) |          |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-11-00PROC. REF: AMM 71-11-00                             |              |                                             |                |          |                        |           |           |             |                  |
| 71-20-00                                                                   |              | LEFT AFT ENGINE MOUNT ISOLATOR              |                |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA4                                                              | MOS/MSC      | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:LK0815                                                                  | HRS          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00 |              |                                             |                |          |                        |           |           |             |                  |
| 71-20-00                                                                   |              | LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR  |                |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC      | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:LK1691                                                                  | HRS          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |              |                                             |                |          |                        |           |           |             |                  |
| 71-20-00                                                                   |              | LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR |                |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC      | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:LK1675                                                                  | HRS          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |              |                                             |                |          |                        |           |           |             |                  |
| 71-20-00                                                                   |              | RIGHT AFT ENGINE MOUNT ISOLATOR             |                |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA4                                                              | MOS/MSC      | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:LK0832                                                                  | HRS          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00 |              |                                             |                |          |                        |           |           |             |                  |
| 71-20-00                                                                   |              | RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR |                |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC      | 29-Apr-15                                   | O/C            | TSN 0    |                        |           |           |             |                  |
| SN:LK1718                                                                  | HRS          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |              |                                             |                |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 71 - POWER PLANT                                                       |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00                                                                   | RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR                                  |           |          |          |                        |           |           |             | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:LK1715                                                                  | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00-001                                                               | RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS      |           |          |          |                        |           |           |             | Service ATA:71   |
| PN:LM-475-SA4                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      |          |                        |           |           |             |                  |
| SN:LK0815                                                                  | HRS                                                                           | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00-001                                                               | RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS  |           |          |          |                        |           |           |             | Service ATA:71   |
| PN:LM-475-SA3                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      |          |                        |           |           |             |                  |
| SN:LK1691                                                                  | HRS                                                                           | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00-001                                                               | RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS |           |          |          |                        |           |           |             | Service ATA:71   |
| PN:LM-475-SA3                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      |          |                        |           |           |             |                  |
| SN:LK1675                                                                  | HRS                                                                           | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00-001                                                               | RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS     |           |          |          |                        |           |           |             | Service ATA:71   |
| PN:LM-475-SA4                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      |          |                        |           |           |             |                  |
| SN:LK0832                                                                  | HRS                                                                           | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                               |           |          |          |                        |           |           |             |                  |
| 71-20-00-001                                                               | RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS |           |          |          |                        |           |           |             | Service ATA:71   |
| PN:LM-475-SA3                                                              | MOS/MSC                                                                       | 29-Apr-15 | O/C      |          |                        |           |           |             |                  |
| SN:LK1718                                                                  | HRS                                                                           | 0         |          |          |                        |           |           |             |                  |
|                                                                            | AFL                                                                           | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                             |                                                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                  | C/W       | Interval       | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition   | Warranty         |
|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|------------------------|-----------|-----------|---------------|------------------|
| ATA 71 - POWER PLANT                                                                                   |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-20-00-001                                                                                           | RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS                                                                                                                                        |           |                |          |                        |           |           |               | Service ATA:71   |
| PN:LM-475-SA3                                                                                          | MOS/MSC                                                                                                                                                                                                               | 29-Apr-15 | O/C            |          |                        |           |           |               |                  |
| SN:LK1715                                                                                              | HRS                                                                                                                                                                                                                   | 0         |                |          |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         |                |          |                        |           |           |               |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                         |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-21-01-01-901                                                                                        | RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY |           |                |          |                        |           |           |               | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 29-Apr-15 |                |          |                        |           |           | AIRWORTHINESS |                  |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:7500         |          | 7500                   |           | 5400      |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:6000         |          | 6000                   |           | 4748      |               |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                         |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-22-01-01-901                                                                                        | DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL                                                                                                                                                            |           |                |          |                        |           |           |               | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 29-Apr-15 |                |          |                        |           |           | AIRWORTHINESS |                  |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:4500         |          | 4500                   |           | 2400      |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:3600         |          | 3600                   |           | 2348      |               |                  |
| PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00 |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-22-01-01-902                                                                                        | RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY                                     |           |                |          |                        |           |           |               | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 29-Apr-15 |                |          |                        |           |           | AIRWORTHINESS |                  |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:7500         |          | 7500                   |           | 5400      |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:6000         |          | 6000                   |           | 4748      |               |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                         |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-31-00-001 <sup>S</sup>                                                                              | DETAILED INSPECTION OF PYLON FIREWALL SEAL                                                                                                                                                                            |           |                |          |                        |           |           |               | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 29-Apr-15 |                |          |                        |           |           |               |                  |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | 2400 (+30/-30) |          |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         |                |          |                        |           |           |               |                  |
| PROC. REF: AMM 71-31-00PROC. REF: AMM 71-31-00                                                         |                                                                                                                                                                                                                       |           |                |          |                        |           |           |               |                  |
| 71-60-01                                                                                               | LEFT ENGINE AIR INLET                                                                                                                                                                                                 |           |                |          |                        |           |           |               | Component ATA:71 |
| PN:505-43420-403                                                                                       | MOS/MSC                                                                                                                                                                                                               | 29-Apr-15 | O/C            | TSN 0    |                        |           |           |               |                  |
| SN:CPI081                                                                                              | HRS                                                                                                                                                                                                                   | 0         |                | TSN 0    |                        |           |           |               |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         |                | TSN 0    |                        |           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 71 - POWER PLANT

PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01

| 71-60-01                                                                   | RIGHT ENGINE AIR INLET |           |     |       |  |  |  | Component | ATA:71 |
|----------------------------------------------------------------------------|------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:505-43430-403                                                           | MOS/MSC                | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:CPI081                                                                  | HRS                    | 0         |     | TSN 0 |  |  |  |           |        |
|                                                                            | AFL                    | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01 |                        |           |     |       |  |  |  |           |        |

| 71EN1                                                                      | NO. 1 ENGINE |  |     |  |  |  |  | Component | ATA:71 |
|----------------------------------------------------------------------------|--------------|--|-----|--|--|--|--|-----------|--------|
| PN:A3072913-01                                                             | MOS/MSC      |  | E/C |  |  |  |  |           |        |
| SN:PCE-DG0533                                                              | HRS          |  |     |  |  |  |  |           |        |
| WC#: 71.EN1                                                                | AFL          |  |     |  |  |  |  |           |        |
| PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00 |              |  |     |  |  |  |  |           |        |

| 71EN2                                                                      | NO. 2 ENGINE |  |     |  |  |  |  | Component | ATA:71 |
|----------------------------------------------------------------------------|--------------|--|-----|--|--|--|--|-----------|--------|
| PN:A3072913-01                                                             | MOS/MSC      |  | E/C |  |  |  |  |           |        |
| SN:PCE-DG0534                                                              | HRS          |  |     |  |  |  |  |           |        |
| WC#: 71.EN2                                                                | AFL          |  |     |  |  |  |  |           |        |
| PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00 |              |  |     |  |  |  |  |           |        |

| 72-00-02-810-801                             | NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION |           |     |  |                    |  |       | Service | ATA:71 |
|----------------------------------------------|----------------------------------------------------------------------|-----------|-----|--|--------------------|--|-------|---------|--------|
|                                              | MOS                                                                  | 14-May-25 | 12  |  | 14-May-26          |  | 332 d |         |        |
|                                              | HRS                                                                  | 2086.2    | 630 |  | (2716.2)<br>2716.2 |  | 616.2 |         |        |
|                                              | ENC                                                                  | 1243      |     |  |                    |  |       |         |        |
| PROC. REF: MM 72-00-02PROC. REF: MM 72-00-02 |                                                                      |           |     |  |                    |  |       |         |        |

| 72-00-02-810-801                             | NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION |           |     |  |                    |  |       | Service | ATA:71 |
|----------------------------------------------|----------------------------------------------------------------------|-----------|-----|--|--------------------|--|-------|---------|--------|
|                                              | MOS                                                                  | 14-May-25 | 12  |  | 14-May-26          |  | 332 d |         |        |
|                                              | HRS                                                                  | 2086.2    | 630 |  | (2716.2)<br>2716.2 |  | 616.2 |         |        |
|                                              | ENC                                                                  | 1243      |     |  |                    |  |       |         |        |
| PROC. REF: MM 72-00-02PROC. REF: MM 72-00-02 |                                                                      |           |     |  |                    |  |       |         |        |

## ATA 72 - ENGINE

| 72-00-00-000-802 | NO. 1 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL |           |     |  |  |  |  | Service | ATA:72 |
|------------------|--------------------------------------------------------------------|-----------|-----|--|--|--|--|---------|--------|
| PN:3073356-01    | DAYS/MSC                                                           | 26-Nov-14 | A/R |  |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                      | C/W       | Interval                                            | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty       |
|----------------------------------------------------|---------------------------------------------------------------------------|-----------|-----------------------------------------------------|----------|------------------------|-----------|-----------|-------------|----------------|
| ATA 72 - ENGINE                                    |                                                                           |           |                                                     |          |                        |           |           |             |                |
| SN:PKAAA577204                                     | HRS                                                                       | 0         |                                                     |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 0         |                                                     |          |                        |           |           |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |                                                     |          |                        |           |           |             |                |
| 72-00-00-000-802                                   | NO. 2 ENGINE -                                                            |           | LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL |          |                        |           |           |             | Service ATA:72 |
| PN:3073356-01                                      | MOS/MSC                                                                   | 27-Nov-14 | A/R                                                 |          |                        |           |           |             |                |
| SN:PKAAA577202                                     | HRS                                                                       | 0         |                                                     |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 0         |                                                     |          |                        |           |           |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |                                                     |          |                        |           |           |             |                |
| 72-00-00-212-801 <sup>S</sup>                      | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA         |           |                                                     |          |                        |           |           | Service     | ATA:72         |
|                                                    | MOS                                                                       | 14-May-25 | 12 (+30d)                                           |          |                        |           |           |             |                |
|                                                    | HRS                                                                       | 2086.2    | 800 (+10%)                                          |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 1243      |                                                     |          |                        |           |           |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                        |           |           |             | PKG:1          |
| 72-00-00-212-801 <sup>S</sup>                      | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA         |           |                                                     |          |                        |           |           | Service     | ATA:72         |
|                                                    | MOS                                                                       | 14-May-25 | 12 (+30d)                                           |          |                        |           |           |             |                |
|                                                    | HRS                                                                       | 2086.2    | 800 (+10%)                                          |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 1243      |                                                     |          |                        |           |           |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                        |           |           |             | PKG:1          |
| 72-00-00-212-802 <sup>S</sup>                      | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB |           |                                                     |          |                        |           |           | Service     | ATA:72         |
|                                                    | MOS                                                                       | 14-May-25 | 12 (+30d)                                           |          |                        |           |           |             |                |
|                                                    | HRS                                                                       | 2086.2    | 800 (+10%)                                          |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 1243      |                                                     |          |                        |           |           |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                        |           |           |             | PKG:1          |
| 72-00-00-212-802 <sup>S</sup>                      | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB |           |                                                     |          |                        |           |           | Service     | ATA:72         |
|                                                    | MOS                                                                       | 14-May-25 | 12 (+30d)                                           |          |                        |           |           |             |                |
|                                                    | HRS                                                                       | 2086.2    | 800 (+10%)                                          |          |                        |           |           |             |                |
|                                                    | ENC                                                                       | 1243      |                                                     |          |                        |           |           |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                        |           |           |             | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit         | C/W                                                                      | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------|--------------|--------------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                              |              |                                                                          |            |          |                        |           |           |             |          |
| 72-00-00-212-803                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT              |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                   | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                     |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-803                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT              |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                   | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                     |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-804                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE     |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                   | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                     |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-804                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE     |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                   | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                     |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-805                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                   | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                     |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                        |           |           |             | PKG:1    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit         | C/W                                                                            | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------|--------------|--------------------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                              |              |                                                                                |            |          |                        |           |           |             |          |
| 72-00-00-212-805                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM       |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                      | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                         | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                           |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-806                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM        |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                      | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                         | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                           |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-806                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM        |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                      | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                         | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                           |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-807                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                      | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                         | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                           |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-807                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                      | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                         | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                           |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                        |           |           |             | PKG:1    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit         | C/W                                                                               | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------|--------------|-----------------------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 72 - ENGINE                              |              |                                                                                   |            |          |                        |           |           |             |          |
| 72-00-00-212-808                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM  |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                              |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-808                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM  |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                              |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-809                             | <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                              |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-212-809                             | <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS          | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                                              |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                        |           |           |             | PKG:1    |
| 72-00-00-280-802                             |              | NO. 1 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS            |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS/MSC      | 26-Nov-14                                                                         | A/R        |          |                        |           |           |             |          |
|                                              | HRS          | 0                                                                                 |            |          |                        |           |           |             |          |
|                                              | ENC          | 0                                                                                 |            |          |                        |           |           |             |          |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                        |           |           |             |          |
| 72-00-00-280-802                             |              | NO. 2 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS            |            |          |                        |           |           | Service     | ATA:72   |
|                                              | MOS/MSC      | 27-Nov-14                                                                         | A/R        |          |                        |           |           |             |          |
|                                              | HRS          | 0                                                                                 |            |          |                        |           |           |             |          |
|                                              | ENC          | 0                                                                                 |            |          |                        |           |           |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 72 - ENGINE

PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00

|                  |                                                                          |          |           |           |             |  |  |         |        |
|------------------|--------------------------------------------------------------------------|----------|-----------|-----------|-------------|--|--|---------|--------|
| 72-00-00-280-818 | NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) |          |           |           |             |  |  | Service | ATA:72 |
| MOS              | 14-May-25                                                                | 24 (+1m) | 14-May-27 | 14-Jun-27 | 697 d (+31) |  |  |         |        |
| HRS              | 2086.2                                                                   |          |           |           |             |  |  |         |        |
| ENC              | 1243                                                                     |          |           |           |             |  |  |         |        |

PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00

|                  |                                                                          |          |           |           |             |  |  |         |        |
|------------------|--------------------------------------------------------------------------|----------|-----------|-----------|-------------|--|--|---------|--------|
| 72-00-00-280-818 | NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) |          |           |           |             |  |  | Service | ATA:72 |
| MOS              | 14-May-25                                                                | 24 (+1m) | 14-May-27 | 14-Jun-27 | 697 d (+31) |  |  |         |        |
| HRS              | 2086.2                                                                   |          |           |           |             |  |  |         |        |
| ENC              | 1243                                                                     |          |           |           |             |  |  |         |        |

PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00

|                               |                                                                  |            |  |  |  |  |  |         |        |
|-------------------------------|------------------------------------------------------------------|------------|--|--|--|--|--|---------|--------|
| 72-00-00-280-820 <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES |            |  |  |  |  |  | Service | ATA:72 |
| MOS                           | 14-May-25                                                        | 12 (+30d)  |  |  |  |  |  |         |        |
| HRS                           | 2086.2                                                           | 800 (+10%) |  |  |  |  |  |         |        |
| ENC                           | 1243                                                             |            |  |  |  |  |  |         |        |

PKG:1

PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00

|                               |                                                                  |            |  |  |  |  |  |         |        |
|-------------------------------|------------------------------------------------------------------|------------|--|--|--|--|--|---------|--------|
| 72-00-00-280-820 <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES |            |  |  |  |  |  | Service | ATA:72 |
| MOS                           | 14-May-25                                                        | 12 (+30d)  |  |  |  |  |  |         |        |
| HRS                           | 2086.2                                                           | 800 (+10%) |  |  |  |  |  |         |        |
| ENC                           | 1243                                                             |            |  |  |  |  |  |         |        |

PKG:1

PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00

|                  |                                                                  |      |  |  |  |  |  |         |        |
|------------------|------------------------------------------------------------------|------|--|--|--|--|--|---------|--------|
| 72-00-00-640-802 | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL |      |  |  |  |  |  | Service | ATA:72 |
| MOS/MS           | 27-Apr-18                                                        | BF/F |  |  |  |  |  |         |        |
| HRS              | 1013.5                                                           |      |  |  |  |  |  |         |        |
| ENC              | 579                                                              |      |  |  |  |  |  |         |        |

PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit                                                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                   | Warranty       |
|----------------------------------------------|-----------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------------------------|----------------|
| ATA 72 - ENGINE                              |                                                                                         |           |          |          |                        |           |           |                               |                |
| 72-00-00-640-802                             | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL                        |           |          |          |                        |           |           |                               | Service ATA:72 |
|                                              | MOS/MSC                                                                                 | 27-Apr-18 | BF/F     |          |                        |           |           |                               |                |
|                                              | HRS                                                                                     | 1013.5    |          |          |                        |           |           |                               |                |
|                                              | ENC                                                                                     | 579       |          |          |                        |           |           |                               |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                        |           |           |                               |                |
| 72-00-00-640-806                             | NO. 1 ENGINE - OIL ANALYSIS                                                             |           |          |          |                        |           |           |                               | Service ATA:72 |
|                                              | MOS/MSC                                                                                 | 24-Apr-23 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                                                     | 1825.5    |          |          |                        |           |           |                               |                |
|                                              | ENC                                                                                     | 1042      |          |          |                        |           |           |                               |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                        |           |           |                               |                |
| 72-00-00-640-806                             | NO. 2 ENGINE - OIL ANALYSIS                                                             |           |          |          |                        |           |           |                               | Service ATA:72 |
|                                              | MOS/MSC                                                                                 | 24-Apr-23 | A/R      |          |                        |           |           |                               |                |
|                                              | HRS                                                                                     | 1825.5    |          |          |                        |           |           |                               |                |
|                                              | ENC                                                                                     | 1042      |          |          |                        |           |           |                               |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                        |           |           |                               |                |
| 72-00-01-810-822                             | NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115) |           |          |          |                        |           |           |                               | Service ATA:72 |
|                                              | MOS/MSC                                                                                 | 26-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                                                     | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                                                     | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01 |                                                                                         |           |          |          |                        |           |           |                               |                |
| 72-00-01-810-822                             | NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115) |           |          |          |                        |           |           |                               | Service ATA:72 |
|                                              | MOS/MSC                                                                                 | 27-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED MAINTENANCE CHECK |                |
|                                              | HRS                                                                                     | 0         |          |          |                        |           |           |                               |                |
|                                              | ENC                                                                                     | 0         |          |          |                        |           |           |                               |                |
| PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01 |                                                                                         |           |          |          |                        |           |           |                               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|------------------------------------------------------------------------|-----------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                                     |           |             |          |                        |           |             |             |                  |
| 72-00-34-030-802                                                       | NO. 1 ENGINE - DISCARD GAS GENERATOR CASE           |           |             |          |                        |           |             |             | Service ATA:72   |
| PN:3076150-01                                                          | MOS                                                 |           |             |          |                        |           |             |             |                  |
| SN:RWA60E689                                                           | HRS                                                 |           |             |          |                        |           |             |             |                  |
|                                                                        | ENC                                                 | EFF       | 10000       |          | (10000)<br>10000 *     |           | 8748        |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                        |           |             |             |                  |
| 72-00-34-030-802                                                       | NO. 2 ENGINE - DISCARD GAS GENERATOR CASE           |           |             |          |                        |           |             |             | Service ATA:72   |
| PN:3076150-01                                                          | MOS                                                 |           |             |          |                        |           |             |             |                  |
| SN:RWA60E694                                                           | HRS                                                 |           |             |          |                        |           |             |             |                  |
|                                                                        | ENC                                                 | EFF       | 10000       |          | (10000)<br>10000 *     |           | 8748        |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                        |           |             |             |                  |
| 72-00-51-030-002                                                       | NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER |           |             |          |                        |           |             |             | Service ATA:72   |
|                                                                        | MOS                                                 | EFF       |             |          |                        |           |             | LIFE LIMIT  |                  |
|                                                                        | HRS                                                 | EFF       | 5000 (+100) |          | (5000)<br>5000 *       | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                 |           |             |          |                        |           |             |             |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                                     |           |             |          |                        |           |             |             |                  |
| 72-00-51-030-002                                                       | NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER |           |             |          |                        |           |             |             | Service ATA:72   |
|                                                                        | MOS                                                 | EFF       |             |          |                        |           |             | LIFE LIMIT  |                  |
|                                                                        | HRS                                                 | EFF       | 5000 (+100) |          | (5000)<br>5000 *       | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                 |           |             |          |                        |           |             |             |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                                     |           |             |          |                        |           |             |             |                  |
| 72-34-01-040-801                                                       | NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR        |           |             |          |                        |           |             |             | Component ATA:72 |
| PN:3056210-01                                                          | MOS                                                 | 26-Nov-14 |             | TSN 0    |                        |           |             | LIFE LIMIT  |                  |
| SN:EAAD000M773                                                         | HRS                                                 | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                                        | ENC                                                 | 0         |             | TSN 0    | (13500)<br>13500 (M)   |           | 12248       |             |                  |
|                                                                        | ACCCYC                                              | 0         | 13500       | TSN 0    |                        |           | 12257       |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                            | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining    | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|--------------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                 |           |             |          |                        |           |              |             |                  |
| 72-34-01-040-801                                   | NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR                    |           |             |          |                        |           |              |             | Component ATA:72 |
| PN:3056210-01                                      | MOS                                                             | 27-Nov-14 |             | TSN 0    |                        |           |              | LIFE LIMIT  |                  |
| SN:EAAD000M769                                     | HRS                                                             | 0         |             | TSN 0    |                        |           |              |             |                  |
|                                                    | ENC                                                             | 0         |             | TSN 0    | (13500)<br>13500 (M)   |           | 12248        |             |                  |
|                                                    | ACCCYC                                                          | 0         | 13500       | TSN 0    |                        |           | 12257        |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                 |           |             |          |                        |           |              |             |                  |
| 72-60-01-212-801                                   | NO. 1 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES |           |             |          |                        |           |              |             | Service ATA:72   |
|                                                    | MOS                                                             | 26-Nov-14 |             |          |                        |           |              |             |                  |
|                                                    | HRS                                                             | 0         | 1200 (+100) |          | (2683.9)<br>2683.9 (M) | 2783.9    | 583.9 (+100) |             |                  |
|                                                    | ENC                                                             | 0         |             |          |                        |           |              |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                 |           |             |          |                        |           |              |             |                  |
| 72-60-01-212-801                                   | NO. 2 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES |           |             |          |                        |           |              |             | Service ATA:72   |
|                                                    | MOS                                                             | 27-Nov-14 |             |          |                        |           |              |             |                  |
|                                                    | HRS                                                             | 0         | 1200 (+100) |          | (2683.9)<br>2683.9 (M) | 2783.9    | 583.9 (+100) |             |                  |
|                                                    | ENC                                                             | 0         |             |          |                        |           |              |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                 |           |             |          |                        |           |              |             |                  |
| 720010                                             | NO. 1 ENGINE - OVERHAUL                                         |           |             |          |                        |           |              |             | Service ATA:72   |
|                                                    | MOS                                                             | 26-Nov-14 |             |          |                        |           |              |             |                  |
|                                                    | HRS                                                             | 0         | 5000 (+100) |          | (5000)<br>5000         | 5100      | 2900 (+100)  |             |                  |
|                                                    | ENC                                                             | 0         |             |          |                        |           |              |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                 |           |             |          |                        |           |              |             |                  |
| 720010                                             | NO. 2 ENGINE - OVERHAUL                                         |           |             |          |                        |           |              |             | Service ATA:72   |
|                                                    | MOS                                                             | 27-Nov-14 |             |          |                        |           |              |             |                  |
|                                                    | HRS                                                             | 0         | 5000 (+100) |          | (5000)<br>5000         | 5100      | 2900 (+100)  |             |                  |
|                                                    | ENC                                                             | 0         |             |          |                        |           |              |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                 |           |             |          |                        |           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                  | C/W       | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|---------------------------------------|-----------|------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                       |           |            |          |                        |           |           |             |                  |
| 720060                                                                 | NO. 1 ENGINE - HOT SECTION INSPECTION |           |            |          |                        |           |           |             | Service ATA:72   |
|                                                                        | MOS                                   | 26-Nov-14 |            |          |                        |           |           |             |                  |
|                                                                        | HRS                                   | 0         | 2500 (+50) |          | (2500)<br>2500         | 2550      | 400 (+50) |             |                  |
|                                                                        | ENC                                   | 0         |            |          |                        |           |           |             |                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00                           |                                       |           |            |          |                        |           |           |             |                  |
| 720060                                                                 | NO. 2 ENGINE - HOT SECTION INSPECTION |           |            |          |                        |           |           |             | Service ATA:72   |
|                                                                        | MOS                                   | 27-Nov-14 |            |          |                        |           |           |             |                  |
|                                                                        | HRS                                   | 0         | 2500 (+50) |          | (2500)<br>2500         | 2550      | 400 (+50) |             |                  |
|                                                                        | ENC                                   | 0         |            |          |                        |           |           |             |                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00                           |                                       |           |            |          |                        |           |           |             |                  |
| 721010                                                                 | NO. 1 ENGINE - GEARBOX                |           |            |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                  | MOS/MSC                               | 26-Nov-14 | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                       |           |            |          |                        |           |           |             |                  |
| 721010                                                                 | NO. 2 ENGINE - GEARBOX                |           |            |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                  | MOS/MSC                               | 27-Nov-14 | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                       |           |            |          |                        |           |           |             |                  |
| 722001                                                                 | NO. 1 ENGINE - OIL PUMP               |           |            |          |                        |           |           |             | Component ATA:72 |
| PN:3073477-02                                                          | MOS/MSC                               | 26-Nov-14 | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:EC01A004A641                                                        | HRS                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 79-20-02, MM 79-20-02PROC. REF: MM 79-20-02, MM 79-20-02 |                                       |           |            |          |                        |           |           |             |                  |
| 722001                                                                 | NO. 2 ENGINE - OIL PUMP               |           |            |          |                        |           |           |             | Component ATA:72 |
| PN:3073477-02                                                          | MOS/MSC                               | 27-Nov-14 | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:EC01A004A644                                                        | HRS                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 79-20-02, MM 79-20-02PROC. REF: MM 79-20-02, MM 79-20-02 |                                       |           |            |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                        |           |          |          |                        |           |           |             |                  |
| 723004                                                                 | NO. 1 ENGINE - LP SHAFT ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073356-01                                                          | MOS                                    | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:PKAAA577204                                                         | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                    | 0         |          | TSN 0    | (30000)<br>30000 (M)   |           | 28748     |             |                  |
|                                                                        | ACCCYC                                 | 0         | 30000    | TSN 0    |                        |           | 28757     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                        |           |          |          |                        |           |           |             |                  |
| 723004                                                                 | NO. 2 ENGINE - LP SHAFT ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073356-01                                                          | MOS                                    | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:PKAAA577202                                                         | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                    | 0         |          | TSN 0    | (30000)<br>30000 (M)   |           | 28748     |             |                  |
|                                                                        | ACCCYC                                 | 0         | 30000    | TSN 0    |                        |           | 28757     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                        |           |          |          |                        |           |           |             |                  |
| 723010                                                                 | NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073311-01                                                          | MOS                                    | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KBXN                                                            | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                    | 0         |          | TSN 0    | (15000)<br>15000 (M)   |           | 13748     |             |                  |
|                                                                        | ACCCYC                                 | 0         | 15000    | TSN 0    |                        |           | 13757     |             |                  |
| PROC. REF: MM 72-30-01, MM 72-30-01PROC. REF: MM 72-30-01, MM 72-30-01 |                                        |           |          |          |                        |           |           |             |                  |
| 723010                                                                 | NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073311-01                                                          | MOS                                    | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003K5H7                                                            | HRS                                    | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                    | 0         |          | TSN 0    | (15000)<br>15000 (M)   |           | 13748     |             |                  |
|                                                                        | ACCCYC                                 | 0         | 15000    | TSN 0    |                        |           | 13757     |             |                  |
| PROC. REF: MM 72-30-01, MM 72-30-01PROC. REF: MM 72-30-01, MM 72-30-01 |                                        |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                              |           |          |          |                        |           |           |             |                  |
| 723020                                                                 | NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR     |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073292-01                                                          | MOS                                          | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:TXA1D3922                                                           | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (15000)<br>15000 (M)   |           | 13748     |             |                  |
|                                                                        | ACCCYC                                       | 0         | 15000    | TSN 0    |                        |           | 13757     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 723020                                                                 | NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR     |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073292-01                                                          | MOS                                          | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:TXA1D3924                                                           | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (15000)<br>15000 (M)   |           | 13748     |             |                  |
|                                                                        | ACCCYC                                       | 0         | 15000    | TSN 0    |                        |           | 13757     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 723030                                                                 | NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072981-01                                                          | MOS                                          | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003HEPC                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 723030                                                                 | NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072981-01                                                          | MOS                                          | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003HEPD                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 723050                                                                 | NO. 1 ENGINE - FAN CASE ASSEMBLY             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075221-01                                                          | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:EDA1426F                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723050                                                                 | NO. 2 ENGINE - FAN CASE ASSEMBLY                                                |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075221-01                                                          | MOS/MSC                                                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:EDA1426B                                                            | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723060                                                                 | NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                  | MOS/MSC                                                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723060                                                                 | NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                                                  | MOS/MSC                                                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723070                                                                 | NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY                                       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3079617-01                                                          | MOS/MSC                                                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003KD30                                                            | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723070                                                                 | NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY                                       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3079617-01                                                          | MOS/MSC                                                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003KLPP                                                            | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                        |           |           |             |                  |
| 723080                                                                 | NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY                                      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3076150-01                                                          | MOS/MSC                                                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA60E689                                                           | HRS                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                      |           |          |          |                        |           |           |             |                  |
| 723080                                             | NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3076150-01                                      | MOS/MSC                                              | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA60E694                                       | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |
| 723090                                             | NO. 1 ENGINE - GAS GENERATOR DIFFUSER                |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073236-01                                      | MOS/MSC                                              | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003KLWH                                        | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |
| 723090                                             | NO. 2 ENGINE - GAS GENERATOR DIFFUSER                |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073236-01                                      | MOS/MSC                                              | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003KLWF                                        | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |
| 723095                                             | NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052673-01                                      | MOS/MSC                                              | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA585420                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |
| 723095                                             | NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052673-01                                      | MOS/MSC                                              | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA585428                                     | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |
| 723110                                             | NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052668-01                                      | MOS/MSC                                              | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AFD00P412                                       | HRS                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                |           |          |          |                        |           |           |             |                  |
| 723110                                             | NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052668-01                                      | MOS/MSC                                        | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AFD00P411                                       | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |
| 723120                                             | NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072571-01                                      | MOS/MSC                                        | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UAAE1225                                        | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |
| 723120                                             | NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072571-01                                      | MOS/MSC                                        | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UAAE1240                                        | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |
| 723130                                             | NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072572-01                                      | MOS/MSC                                        | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UAAE1179                                        | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |
| 723130                                             | NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072572-01                                      | MOS/MSC                                        | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UAAE1184                                        | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |
| 723140                                             | NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052737-01                                      | MOS/MSC                                        | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:LPA000016739                                    | HRS                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723140                                             | NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING                                                  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052737-01                                      | MOS/MSC                                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:LPA000016744                                    | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723150                                             | NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR                                           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072574-01                                      | MOS/MSC                                                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:EAAD000M355                                     | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723150                                             | NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR                                           |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072574-01                                      | MOS/MSC                                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:EAAD000M828                                     | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723160                                             | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052670-02                                      | MOS/MSC                                                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN406175                                       | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723160                                             | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052670-02                                      | MOS/MSC                                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN406182                                       | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |
| 723170                                             | NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT                                    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072280-01                                      | MOS/MSC                                                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA583726                                     | HRS                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                         |           |          |          |                        |           |           |             |                  |
| 723170                                             | NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT                    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072280-01                                      | MOS/MSC                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA583723                                     | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |
| 723180                                             | NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052616-01                                      | MOS/MSC                                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN418652                                       | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |
| 723180                                             | NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052616-01                                      | MOS/MSC                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN418647                                       | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |
| 723190                                             | NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052634-01                                      | MOS/MSC                                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN416287                                       | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |
| 723190                                             | NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052634-01                                      | MOS/MSC                                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN416289                                       | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |
| 723705                                             | NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK                      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053812-01                                      | MOS                                                                     | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KKN3                                        | HRS                                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                    | ACCCYC                                                                  | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                                    |           |          |          |                        |           |           |             |                  |
| 723705                                                                 | NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053812-01                                                          | MOS                                                | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KKN2                                                            | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                        |           |           |             |                  |
| 723706                                                                 | NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053743-01                                                          | MOS                                                | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KF5B                                                            | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                        |           |           |             |                  |
| 723706                                                                 | NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053743-01                                                          | MOS                                                | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KF5D                                                            | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                        |           |           |             |                  |
| 724001                                                                 | NO. 1 ENGINE - INNER COMBUSTION LINER              |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075516-01                                                          | MOS/MSC                                            | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003K6L5                                                            | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                                    |           |          |          |                        |           |           |             |                  |
| 724001                                                                 | NO. 2 ENGINE - INNER COMBUSTION LINER              |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075516-01                                                          | MOS/MSC                                            | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003K03P                                                            | HRS                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                              |           |          |          |                        |           |           |             |                  |
| 724002                                                                 | NO. 1 ENGINE - OUTER COMBUSTION LINER        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075522-01                                                          | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003K1NY                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                              |           |          |          |                        |           |           |             |                  |
| 724002                                                                 | NO. 2 ENGINE - OUTER COMBUSTION LINER        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075522-01                                                          | MOS/MSC                                      | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:A003KA96                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                              |           |          |          |                        |           |           |             |                  |
| 724010                                                                 | NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075468-01                                                          | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:ACM221879749                                                        | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 724010                                                                 | NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075468-01                                                          | MOS/MSC                                      | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:ACM221879756                                                        | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 724706                                                                 | NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053331-01                                                          | MOS                                          | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KC8M                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (10000)<br>10000 (M)   |           | 8748      |             |                  |
|                                                                        | ACCCYC                                       | 0         | 10000    | TSN 0    |                        |           | 8757      |             |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                                        |                                                   |           |          |          |                        |           |           |             |                  |
| 724706                                                                 | NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053331-01                                                          | MOS                                               | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003KC8R                                                            | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                               | 0         |          | TSN 0    | (10000)<br>10000 (M)   |           | 8748      |             |                  |
|                                                                        | ACCCYC                                            | 0         | 10000    | TSN 0    |                        |           | 8757      |             |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                                   |           |          |          |                        |           |           |             |                  |
| 724825                                                                 | NO. 1 ENGINE - CENTRIFUGAL IMPELLER               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052661-01                                                          | MOS                                               | 26-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003K50P                                                            | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                               | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                            | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                   |           |          |          |                        |           |           |             |                  |
| 724825                                                                 | NO. 2 ENGINE - CENTRIFUGAL IMPELLER               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052661-01                                                          | MOS                                               | 27-Nov-14 |          | TSN 0    |                        |           |           | LIFE LIMIT  |                  |
| SN:A003K8ET                                                            | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                               | 0         |          | TSN 0    | (13500)<br>13500 (M)   |           | 12248     |             |                  |
|                                                                        | ACCCYC                                            | 0         | 13500    | TSN 0    |                        |           | 12257     |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                                                 | NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                                          | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWMT5791                                                            | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                                                 | NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                                          | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7542                                                            | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7543                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7549                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7560                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7564                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7570                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7572                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7573                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7574                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7578                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWMT5795                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7584                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7595                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7598                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7603                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7604                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7606                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7609                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7612                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7615                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7641                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA0730                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7644                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7647                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7648                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7649                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNC1809                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNC2089                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNC2092                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3873                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3877                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3880                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7534                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3884                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3896                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3897                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3899                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3902                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3904                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3909                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3910                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3923                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3929                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNA7536                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3940                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3959                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3965                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWND3986                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7514                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7515                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7527                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7533                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7534                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7539                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWA7537                                         | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7540                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7538                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7540                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7541                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7541                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7542                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7543                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7552                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7555                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7557                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7564                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7568                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7572                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNH7573                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK2443                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5445                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5458                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5459                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5460                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5476                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5483                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5508                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8925                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8928                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8935                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5391                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8936                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8942                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8945                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8952                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8962                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8969                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8980                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8981                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8990                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8993                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5400                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK8999                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK9006                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK9012                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK9038                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK9042                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1556                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1561                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1562                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1573                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1590                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5401                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1593                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1599                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1603                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1874                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1881                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1882                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1884                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1886                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1889                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1893                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5418                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1900                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1902                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1906                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1911                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1917                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1920                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM1921                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7839                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7843                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7845                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5426                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7846                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5428                                        | HRS                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5436                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNK5438                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7850                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM7851                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9335                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9339                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9342                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9347                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9371                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9378                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9382                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 725010                                             | NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:HWNM9414                                        | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                          | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                               |           |          |          |                        |           |           |             |                  |
| 725015                                             | NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073355-01                                      | MOS/MSC                                                                       | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN414867                                       | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                        |           |           |             |                  |
| 725015                                             | NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073355-01                                      | MOS/MSC                                                                       | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN414866                                       | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                        |           |           |             |                  |
| 725020                                             | NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY                                  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3076552-01                                      | MOS/MSC                                                                       | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA60E698                                       | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-50-03PROC. REF: MM 72-50-03       |                                                                               |           |          |          |                        |           |           |             |                  |
| 725020                                             | NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY                                  |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3076552-01                                      | MOS/MSC                                                                       | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA61E376                                       | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-50-03PROC. REF: MM 72-50-03       |                                                                               |           |          |          |                        |           |           |             |                  |
| 725025                                             | NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER                               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073353-01                                      | MOS/MSC                                                                       | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:MDAA005A525                                     | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                        |           |           |             |                  |
| 725025                                             | NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER                               |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073353-01                                      | MOS/MSC                                                                       | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:MDAA005A519                                     | HRS                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                         |           |          |          |                        |           |           |             |                  |
| 725030                                             | NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053163CL01                                     | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PDAKU9AT01                                      | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 725030                                             | NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3053163CL01                                     | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PDAKU2FC01                                      | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 725035                                             | NO. 1 ENGINE - TURBINE (CASTING) VANE RING              |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052361CL01                                     | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PDAKYCYL01                                      | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 725035                                             | NO. 2 ENGINE - TURBINE (CASTING) VANE RING              |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052361CL01                                     | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PDAKYECR01                                      | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 725040                                             | NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073262CL02                                     | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:BHKKEHL01                                       | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |
| 725040                                             | NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY       |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073262CL02                                     | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:BHKLAYK01                                       | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                    |           |          |          |                        |           |           |             |                  |
| 726010                                             | NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING                          |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                                            | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |
| 726010                                             | NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING                          |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052549-01                                      | MOS/MSC                                                            | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FCN412103                                       | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |
| 726020                                             | NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3112368-01                                      | MOS/MSC                                                            | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1413089                                      | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |
| 726020                                             | NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AEB0208243                                      | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |
| 726030                                             | NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3112368-01                                      | MOS/MSC                                                            | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1413090                                      | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |
| 726030                                             | NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AEB0208375                                      | HRS                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                  | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                       |           |          |          |                        |           |           |             |                  |
| 726040                                             | NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3112368-01                                      | MOS/MSC                                                               | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1413095                                      | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |
| 726040                                             | NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AEB0208381                                      | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |
| 726050                                             | NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3112368-01                                      | MOS/MSC                                                               | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1413099                                      | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |
| 726050                                             | NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING         |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:AEB0208390                                      | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |
| 726060                                             | NO. 1 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3112368-01                                      | MOS/MSC                                                               | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1413100                                      | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |
| 726060                                             | NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                                               | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                   |           |          |          |                        |           |           |             |                  |
| 726070                                             | NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY                 |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726070                                             | NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY                 |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726080                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT                      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072279-01                                      | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA55E422                                       | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726080                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT                      |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072279-01                                      | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:RWA55E423                                       | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726090                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072235-01                                      | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1416223                                      | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726090                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072235-01                                      | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1412822                                      | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                   |           |          |          |                        |           |           |             |                  |
| 726110                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052605-01                                      | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1411178                                      | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726110                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052605-01                                      | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:FAA1411176                                      | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726120                                             | NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052550-01                                      | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:BB0211215                                       | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726120                                             | NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3052550-01                                      | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:BB0208158                                       | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726130                                             | NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072282-01                                      | MOS/MSC                                                           | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA582954                                     | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |
| 726130                                             | NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT             |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3072282-01                                      | MOS/MSC                                                           | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:PKAAA582953                                     | HRS                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                 |           |          |          |                        |           |           |             |                  |
| 727010                                             | NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075013-01                                      | MOS/MSC                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:KYAA014A299                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                 |           |          |          |                        |           |           |             |                  |
| 727010                                             | NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3075013-01                                      | MOS/MSC                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:KYAA014A300                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                 |           |          |          |                        |           |           |             |                  |
| 727020                                             | NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074835-01                                      | MOS/MSC                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:KYAA014A521                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-70-01PROC. REF: MM 72-70-01       |                                                 |           |          |          |                        |           |           |             |                  |
| 727020                                             | NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY        |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:3074835-01                                      | MOS/MSC                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:KYAA014A523                                     | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 72-70-01PROC. REF: MM 72-70-01       |                                                 |           |          |          |                        |           |           |             |                  |
| 793010                                             | NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                         | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                 |           |          |          |                        |           |           |             |                  |
| 793010                                             | NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR    |           |          |          |                        |           |           |             | Component ATA:72 |
| PN:PN                                              | MOS/MSC                                         | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                             | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                 |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit         | C/W                                                                                           | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|----------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |              |                                                                                               |             |          |                        |           |             |             |                |
| 72-00-00-280-819                                   | <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS          | 14-May-25                                                                                     | 12 (+30d)   |          |                        |           |             |             |                |
|                                                    | HRS          | 2086.2                                                                                        | 800 (+10%)  |          |                        |           |             |             |                |
|                                                    | ENC          | 1243                                                                                          |             |          |                        |           |             |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |              |                                                                                               |             |          |                        |           |             |             | PKG:1          |
| 72-00-00-280-819                                   | <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS          | 14-May-25                                                                                     | 12 (+30d)   |          |                        |           |             |             |                |
|                                                    | HRS          | 2086.2                                                                                        | 800 (+10%)  |          |                        |           |             |             |                |
|                                                    | ENC          | 1243                                                                                          |             |          |                        |           |             |             |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |              |                                                                                               |             |          |                        |           |             |             | PKG:1          |
| 73-10-01-212-801                                   |              | NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES                                         |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS          |                                                                                               |             |          |                        |           |             |             |                |
|                                                    | HRS          | EFF                                                                                           | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC          |                                                                                               |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                               |             |          |                        |           |             |             |                |
| 73-10-01-212-801                                   |              | NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES                                         |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS          |                                                                                               |             |          |                        |           |             |             |                |
|                                                    | HRS          | EFF                                                                                           | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC          |                                                                                               |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                               |             |          |                        |           |             |             |                |
| 73-10-04-000-801                                   |              | NO. 1 ENGINE - DISCARD THE FUEL MANIFOLD PAD                                                  |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS          |                                                                                               |             |          |                        |           |             |             |                |
|                                                    | HRS          |                                                                                               |             |          |                        |           |             |             |                |
|                                                    | ENC          | EFF                                                                                           | 9900        |          | (9900)<br>9900 *       |           | 8648        |             |                |
| PROC. REF: MM 73-10-04PROC. REF: MM 73-10-04       |              |                                                                                               |             |          |                        |           |             |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                                      | C/W       | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|------------------------------------------------------------------------|---------------------------------------------------------------------------|-----------|------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                       |                                                                           |           |            |          |                        |           |             |             |                |
| 73-10-04-000-801                                                       | NO. 2 ENGINE - DISCARD THE FUEL MANIFOLD PAD                              |           |            |          |                        |           |             |             | Service ATA:73 |
|                                                                        | MOS                                                                       |           |            |          |                        |           |             |             |                |
|                                                                        | HRS                                                                       |           |            |          |                        |           |             |             |                |
|                                                                        | ENC                                                                       | EFF       | 9900       |          | (9900)<br>9900 *       |           | 8648        |             |                |
| PROC. REF: MM 73-10-04PROC. REF: MM 73-10-04                           |                                                                           |           |            |          |                        |           |             |             |                |
| 73-10-05-212-801                                                       | NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT |           |            |          |                        |           |             |             | Service ATA:73 |
|                                                                        | MOS                                                                       | 14-May-25 | 12 (+30d)  |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |             |                |
|                                                                        | HRS                                                                       | 2086.2    |            |          |                        |           |             |             |                |
|                                                                        | ENC                                                                       | 1243      |            |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                           |                                                                           |           |            |          |                        |           |             |             |                |
| 73-10-05-212-801                                                       | NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT |           |            |          |                        |           |             |             | Service ATA:73 |
|                                                                        | MOS                                                                       | 14-May-25 | 12 (+30d)  |          | 14-May-26              | 13-Jun-26 | 332 d (+30) |             |                |
|                                                                        | HRS                                                                       | 2086.2    |            |          |                        |           |             |             |                |
|                                                                        | ENC                                                                       | 1243      |            |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                           |                                                                           |           |            |          |                        |           |             |             |                |
| 73-10-05-960-801                                                       | NO. 1 ENGINE - DISCARD THE FUEL FILTER                                    |           |            |          |                        |           |             |             | Service ATA:73 |
| PN:PN                                                                  | MOS                                                                       | 24-Apr-23 |            |          |                        |           |             |             |                |
| SN:UNKNOWN                                                             | HRS                                                                       | 1825.5    | 800 (+10%) |          | (2625.5)<br>2625.5     | 2705.5    | 525.5 (+80) |             |                |
|                                                                        | ENC                                                                       | 1042      |            |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-05, MM 73-10-05PROC. REF: MM 73-10-05, MM 73-10-05 |                                                                           |           |            |          |                        |           |             |             |                |
| 73-10-05-960-801                                                       | NO. 2 ENGINE - DISCARD THE FUEL FILTER                                    |           |            |          |                        |           |             |             | Service ATA:73 |
| PN:PN                                                                  | MOS                                                                       | 24-Apr-23 |            |          |                        |           |             |             |                |
| SN:UNKNOWN                                                             | HRS                                                                       | 1825.5    | 800 (+10%) |          | (2625.5)<br>2625.5     | 2705.5    | 525.5 (+80) |             |                |
|                                                                        | ENC                                                                       | 1042      |            |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-05, MM 73-10-05PROC. REF: MM 73-10-05, MM 73-10-05 |                                                                           |           |            |          |                        |           |             |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit         | C/W                                                                                       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|----------------------------------------------|--------------|-------------------------------------------------------------------------------------------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL             |              |                                                                                           |             |          |                        |           |             |             |                |
| 73-10-07-212-801                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE                                |             |          |                        |           |             |             | Service ATA:73 |
|                                              | MOS          | 14-May-25                                                                                 | 12 (+30d)   |          |                        |           |             |             |                |
|                                              | HRS          | 2086.2                                                                                    | 800 (+10%)  |          |                        |           |             |             |                |
|                                              | ENC          | 1243                                                                                      |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-07PROC. REF: MM 73-10-07 |              |                                                                                           |             |          |                        |           |             |             | PKG:1          |
| 73-10-07-212-801                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE                                |             |          |                        |           |             |             | Service ATA:73 |
|                                              | MOS          | 14-May-25                                                                                 | 12 (+30d)   |          |                        |           |             |             |                |
|                                              | HRS          | 2086.2                                                                                    | 800 (+10%)  |          |                        |           |             |             |                |
|                                              | ENC          | 1243                                                                                      |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-10-07PROC. REF: MM 73-10-07 |              |                                                                                           |             |          |                        |           |             |             | PKG:1          |
| 73-20-01-212-801                             |              | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT |             |          |                        |           |             |             | Service ATA:73 |
| PN:3071682-05                                | MOS          |                                                                                           |             |          |                        |           |             |             |                |
| SN:F81513                                    | HRS          | EFF                                                                                       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                              | ENC          |                                                                                           |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-20-01PROC. REF: MM 73-20-01 |              |                                                                                           |             |          |                        |           |             |             |                |
| 73-20-01-212-801                             |              | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT |             |          |                        |           |             |             | Service ATA:73 |
| PN:3071682-05                                | MOS          |                                                                                           |             |          |                        |           |             |             |                |
| SN:F81627                                    | HRS          | EFF                                                                                       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                              | ENC          |                                                                                           |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-20-01PROC. REF: MM 73-20-01 |              |                                                                                           |             |          |                        |           |             |             |                |
| 73-20-02-212-801                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS                     |             |          |                        |           |             |             | Service ATA:73 |
|                                              | MOS          | 14-May-25                                                                                 | 12 (+30d)   |          |                        |           |             |             |                |
|                                              | HRS          | 2086.2                                                                                    | 800 (+10%)  |          |                        |           |             |             |                |
|                                              | ENC          | 1243                                                                                      |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-20-02PROC. REF: MM 73-20-02 |              |                                                                                           |             |          |                        |           |             |             | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit | C/W                                                                     | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|----------------------------------------------------|------|-------------------------------------------------------------------------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |      |                                                                         |             |          |                        |           |             |             |                |
| 73-20-02-212-801                                   | S    | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS   |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS  | 14-May-25                                                               | 12 (+30d)   |          |                        |           |             |             |                |
|                                                    | HRS  | 2086.2                                                                  | 800 (+10%)  |          |                        |           |             |             |                |
|                                                    | ENC  | 1243                                                                    |             |          |                        |           |             |             |                |
| PROC. REF: MM 73-20-02PROC. REF: MM 73-20-02       |      |                                                                         |             |          |                        |           |             |             | PKG:1          |
| 73-20-10-212-801                                   |      | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS |             |          |                        |           |             |             | Service ATA:73 |
| PN:3073237-05                                      | MOS  |                                                                         |             |          |                        |           |             |             |                |
| SN:ADXBA001054                                     | HRS  | EFF                                                                     | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC  |                                                                         |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                         |             |          |                        |           |             |             |                |
| 73-20-10-212-801                                   |      | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS |             |          |                        |           |             |             | Service ATA:73 |
| PN:3073237-05                                      | MOS  |                                                                         |             |          |                        |           |             |             |                |
| SN:ADXBA001069                                     | HRS  | EFF                                                                     | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC  |                                                                         |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                         |             |          |                        |           |             |             |                |
| 73-20-20-212-801                                   |      | NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES                     |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS  |                                                                         |             |          |                        |           |             |             |                |
|                                                    | HRS  | EFF                                                                     | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC  |                                                                         |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                         |             |          |                        |           |             |             |                |
| 73-20-20-212-801                                   |      | NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES                     |             |          |                        |           |             |             | Service ATA:73 |
|                                                    | MOS  |                                                                         |             |          |                        |           |             |             |                |
|                                                    | HRS  | EFF                                                                     | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC  |                                                                         |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |      |                                                                         |             |          |                        |           |             |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                       | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |                                                                                            |           |             |          |                        |           |             |             |                  |
| 73-20-30-212-801                                                           | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                        |           |             |             | Service ATA:73   |
|                                                                            | MOS                                                                                        |           |             |          |                        |           |             |             |                  |
|                                                                            | HRS                                                                                        |           | 5000 (+100) |          | (5000)<br>5000 (M)     | 5100      | 2900 (+100) |             |                  |
|                                                                            | ENC                                                                                        |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                            |           |             |          |                        |           |             |             |                  |
| 73-20-30-212-801                                                           | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                        |           |             |             | Service ATA:73   |
|                                                                            | MOS                                                                                        |           |             |          |                        |           |             |             |                  |
|                                                                            | HRS                                                                                        |           | 5000 (+100) |          | (5000)<br>5000 (M)     | 5100      | 2900 (+100) |             |                  |
|                                                                            | ENC                                                                                        |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                            |           |             |          |                        |           |             |             |                  |
| 73-21-01                                                                   | LEFT FADEC                                                                                 |           |             |          |                        |           |             |             | Component ATA:73 |
| PN:3073593-08                                                              | MOS/MSC                                                                                    | 29-Apr-15 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:2014070034                                                              | HRS                                                                                        | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                        | 0         |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01 |                                                                                            |           |             |          |                        |           |             |             |                  |
| 73-21-01                                                                   | RIGHT FADEC                                                                                |           |             |          |                        |           |             |             | Component ATA:73 |
| PN:3073593-08                                                              | MOS/MSC                                                                                    | 29-Apr-15 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:2014080019                                                              | HRS                                                                                        | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                                                        | 0         |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01 |                                                                                            |           |             |          |                        |           |             |             |                  |
| 73-30-02-212-801 <sup>S</sup>                                              | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR          |           |             |          |                        |           |             |             | Service ATA:73   |
|                                                                            | MOS                                                                                        | 14-May-25 | 12 (+30d)   |          |                        |           |             |             |                  |
|                                                                            | HRS                                                                                        | 2086.2    | 800 (+10%)  |          |                        |           |             |             |                  |
|                                                                            | ENC                                                                                        | 1243      |             |          |                        |           |             |             |                  |
| PROC. REF: MM 73-30-02PROC. REF: MM 73-30-02                               |                                                                                            |           |             |          |                        |           |             |             |                  |
|                                                                            |                                                                                            |           |             |          |                        |           |             |             | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                      | C/W                                                                               | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------|-----------------------------------------------------------|-----------------------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 73-30-02-212-801                                                           | S                                                         | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR |            |          |                        |           |           |             | Service ATA:73   |
|                                                                            | MOS                                                       | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |                  |
|                                                                            | HRS                                                       | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 1243                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 73-30-02PROC. REF: MM 73-30-02                               |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 73-33-01                                                                   | LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER  |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:8TJ300AAB2                                                              | MOS/MSC                                                   | 29-Apr-15                                                                         | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:DTT7743                                                                 | HRS                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01 |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 73-33-01                                                                   | RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:8TJ300AAB2                                                              | MOS/MSC                                                   | 29-Apr-15                                                                         | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:DTT8696                                                                 | HRS                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
|                                                                            | AFL                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01 |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 731002                                                                     | NO. 1 ENGINE - FLOW DIVIDER                               |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 26-Nov-14                                                                         | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 731002                                                                     | NO. 2 ENGINE - FLOW DIVIDER                               |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 27-Nov-14                                                                         | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |                                                                                   |            |          |                        |           |           |             |                  |
| 731005                                                                     | NO. 1 ENGINE - FUEL FILTER                                |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                      | MOS/MSC                                                   | 24-Apr-23                                                                         | O/C        |          |                        |           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                       | 1825.5                                                                            |            |          |                        |           |           |             |                  |
|                                                                            | ENC                                                       | 1042                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                               |                                                           |                                                                                   |            |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                            |           |          |          |                        |           |           |             |                  |
| 731005                                             | NO. 2 ENGINE - FUEL FILTER                 |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                              | MOS/MSC                                    | 24-Apr-23 | O/C      |          |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                        | 1825.5    |          |          |                        |           |           |             |                  |
|                                                    | ENC                                        | 1042      |          |          |                        |           |           |             |                  |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05       |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53571                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54031                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54032                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53572                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53573                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54003                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54006                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54009                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54013                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54014                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54027                                      | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53555                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54020                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54023                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53559                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA53574                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |
| 731010                                             | NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY  |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54004                                      | HRS                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                       |                                                     |           |          |          |                        |           |           |             |                  |
| 731010                                                                 | NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54007                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 731010                                                                 | NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54010                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 731010                                                                 | NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54015                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 731010                                                                 | NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54017                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 731010                                                                 | NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY           |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3057135-01                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:DEAAA54018                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 732001                                                                 | NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3073593-08                                                          | MOS/MSC                                             | 08-Dec-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2014070034                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-03, MM 73-20-03PROC. REF: MM 73-20-03, MM 73-20-03 |                                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                       |                                                     |           |          |          |                        |           |           |             |                  |
| 732001                                                                 | NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3073593-08                                                          | MOS/MSC                                             | 08-Dec-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:2014080019                                                          | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-03, MM 73-20-03PROC. REF: MM 73-20-03, MM 73-20-03 |                                                     |           |          |          |                        |           |           |             |                  |
| 732002                                                                 | NO. 1 ENGINE - FUEL METERING UNIT (FMU)             |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3071682-05                                                          | MOS/MSC                                             | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:F81513                                                              | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-01, MM 73-20-01PROC. REF: MM 73-20-01, MM 73-20-01 |                                                     |           |          |          |                        |           |           |             |                  |
| 732002                                                                 | NO. 2 ENGINE - FUEL METERING UNIT (FMU)             |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3071682-05                                                          | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:F81627                                                              | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-01, MM 73-20-01PROC. REF: MM 73-20-01, MM 73-20-01 |                                                     |           |          |          |                        |           |           |             |                  |
| 732005                                                                 | NO. 1 ENGINE - N2 SPEED SENSOR                      |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                  | MOS/MSC                                             | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 732005                                                                 | NO. 2 ENGINE - N2 SPEED SENSOR                      |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                  | MOS/MSC                                             | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |
| 732006                                                                 | NO. 1 ENGINE - N1 SPEED SENSOR                      |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                  | MOS/MSC                                             | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                                 | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                    | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                                                                           |                                                         |           |          |          |                        |           |           |             |                  |
| 732006                                                                                                                     | NO. 2 ENGINE - N1 SPEED SENSOR                          |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                         |                                                         |           |          |          |                        |           |           |             |                  |
| 732010                                                                                                                     | NO. 1 ENGINE - ELECTRICAL WIRING HARNESS                |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3073237-05                                                                                                              | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:ADXBA001054                                                                                                             | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 732010                                                                                                                     | NO. 2 ENGINE - ELECTRICAL WIRING HARNESS                |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:3073237-05                                                                                                              | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:ADXBA001069                                                                                                             | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02 |                                                         |           |          |          |                        |           |           |             |                  |
| 732030                                                                                                                     | NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                         |                                                         |           |          |          |                        |           |           |             |                  |
| 732030                                                                                                                     | NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                                                 | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                         |                                                         |           |          |          |                        |           |           |             |                  |
| 732040                                                                                                                     | NO. 1 ENGINE - FUEL SHUT-OFF CABLE                      |           |          |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                                                 | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07 |                                                         |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                                                    | Unit                               | C/W                                                                               | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------------------------------------------------------------------------------|------------------------------------|-----------------------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                                                                           |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| 732040                                                                                                                     | NO. 2 ENGINE - FUEL SHUT-OFF CABLE |                                                                                   |            |          |                        |           |           |             | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                            | 27-Nov-14                                                                         | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
|                                                                                                                            | ENC                                | 0                                                                                 |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07 |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| ATA 74 - IGNITION                                                                                                          |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| 74-00-01-750-801                                                                                                           | <sup>S</sup>                       | NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM                            |            |          |                        |           |           |             | Service ATA:74   |
|                                                                                                                            | MOS                                | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |                  |
|                                                                                                                            | HRS                                | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                                                                            | ENC                                | 1243                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-00-01PROC. REF: MM 74-00-01                                                                               |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| 74-00-01-750-801                                                                                                           | <sup>S</sup>                       | NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM                            |            |          |                        |           |           |             | Service ATA:74   |
|                                                                                                                            | MOS                                | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |                  |
|                                                                                                                            | HRS                                | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                                                                            | ENC                                | 1243                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-00-01PROC. REF: MM 74-00-01                                                                               |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| 74-10-01-212-801                                                                                                           | <sup>S</sup>                       | NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER |            |          |                        |           |           |             | Service ATA:74   |
| PN:31J2807-07                                                                                                              | MOS                                | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |                  |
| SN:NNA13430012                                                                                                             | HRS                                | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                                                                            | ENC                                | 1243                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-10-01PROC. REF: MM 74-10-01                                                                               |                                    |                                                                                   |            |          |                        |           |           |             |                  |
| 74-10-01-212-801                                                                                                           | <sup>S</sup>                       | NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER |            |          |                        |           |           |             | Service ATA:74   |
| PN:31J2807-07                                                                                                              | MOS                                | 14-May-25                                                                         | 12 (+30d)  |          |                        |           |           |             |                  |
| SN:NNA14410246                                                                                                             | HRS                                | 2086.2                                                                            | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                                                                            | ENC                                | 1243                                                                              |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-10-01PROC. REF: MM 74-10-01                                                                               |                                    |                                                                                   |            |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                      | Unit         | C/W                                                                | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|----------------------------------------------|--------------|--------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|----------|
| ATA 74 - IGNITION                            |              |                                                                    |            |          |                        |           |           |             |          |
| 74-20-01-212-801                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES    |            |          |                        |           |           | Service     | ATA:74   |
|                                              | MOS          | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                               |            |          |                        |           |           |             |          |
| PROC. REF: MM 74-20-01PROC. REF: MM 74-20-01 |              |                                                                    |            |          |                        |           |           |             | PKG:1    |
| 74-20-01-212-801                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES    |            |          |                        |           |           | Service     | ATA:74   |
|                                              | MOS          | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |          |
|                                              | HRS          | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                               |            |          |                        |           |           |             |          |
| PROC. REF: MM 74-20-01PROC. REF: MM 74-20-01 |              |                                                                    |            |          |                        |           |           |             | PKG:1    |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 1 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR |            |          |                        |           |           | Service     | ATA:74   |
| PN:3070508-01                                | MOS          | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |          |
| SN:NSN                                       | HRS          | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                               |            |          |                        |           |           |             |          |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                        |           |           |             | PKG:1    |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 1 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR |            |          |                        |           |           | Service     | ATA:74   |
| PN:3070508-01                                | MOS          | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |          |
| SN:NSN                                       | HRS          | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                               |            |          |                        |           |           |             |          |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                        |           |           |             | PKG:1    |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 2 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR |            |          |                        |           |           | Service     | ATA:74   |
| PN:3070508-01                                | MOS          | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |          |
| SN:N/A                                       | HRS          | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |          |
|                                              | ENC          | 1243                                                               |            |          |                        |           |           |             |          |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                        |           |           |             | PKG:1    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit    | C/W                                                                | Interval   | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|---------|--------------------------------------------------------------------|------------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 74 - IGNITION                                                      |         |                                                                    |            |          |                        |           |           |             |                  |
| 74-20-02-210-801                                                       | S       | NO. 2 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR |            |          |                        |           |           |             | Service ATA:74   |
| PN:3070508-01                                                          | MOS     | 14-May-25                                                          | 12 (+30d)  |          |                        |           |           |             |                  |
| SN:N/A                                                                 | HRS     | 2086.2                                                             | 800 (+10%) |          |                        |           |           |             |                  |
|                                                                        | ENC     | 1243                                                               |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02                           |         |                                                                    |            |          |                        |           |           |             | PKG:1            |
| 74-20-02-960-801                                                       |         | NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER                           |            |          |                        |           |           |             | Service ATA:74   |
| PN:3070508-01                                                          | MOS/MSC | 27-Apr-18                                                          | O/C        |          |                        |           |           |             |                  |
| SN:NSN                                                                 | HRS     | 1013.5                                                             |            |          |                        |           |           |             |                  |
|                                                                        | ENC     | 579                                                                |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |         |                                                                    |            |          |                        |           |           |             |                  |
| 74-20-02-960-801                                                       |         | NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER                            |            |          |                        |           |           |             | Service ATA:74   |
| PN:3070508-01                                                          | MOS/MSC | 27-Apr-18                                                          | O/C        |          |                        |           |           |             |                  |
| SN:NSN                                                                 | HRS     | 1013.5                                                             |            |          |                        |           |           |             |                  |
|                                                                        | ENC     | 579                                                                |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |         |                                                                    |            |          |                        |           |           |             |                  |
| 74-20-02-960-801                                                       |         | NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER                           |            |          |                        |           |           |             | Service ATA:74   |
| PN:3070508-01                                                          | MOS/MSC | 27-Apr-18                                                          | O/C        |          |                        |           |           |             |                  |
| SN:N/A                                                                 | HRS     | 1013.5                                                             |            |          |                        |           |           |             |                  |
|                                                                        | ENC     | 579                                                                |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |         |                                                                    |            |          |                        |           |           |             |                  |
| 74-20-02-960-801                                                       |         | NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER                            |            |          |                        |           |           |             | Service ATA:74   |
| PN:3070508-01                                                          | MOS/MSC | 27-Apr-18                                                          | O/C        |          |                        |           |           |             |                  |
| SN:N/A                                                                 | HRS     | 1013.5                                                             |            |          |                        |           |           |             |                  |
|                                                                        | ENC     | 579                                                                |            |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |         |                                                                    |            |          |                        |           |           |             |                  |
| 741001                                                                 |         | NO. 1 ENGINE - EXCITER IGNITION                                    |            |          |                        |           |           |             | Component ATA:74 |
| PN:31J2807-07                                                          | MOS/MSC | 26-Nov-14                                                          | O/C        | TSN 0    |                        |           |           |             |                  |
| SN:NNA13430012                                                         | HRS     | 0                                                                  |            | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC     | 0                                                                  |            | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 74-10-01, MM 74-10-01PROC. REF: MM 74-10-01, MM 74-10-01 |         |                                                                    |            |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 74 - IGNITION                                                      |                                           |           |          |          |                        |           |           |             |                  |
| 741001                                                                 | NO. 2 ENGINE - EXCITER IGNITION           |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:31J2807-07                                                          | MOS/MSC                                   | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:NNA14410246                                                         | HRS                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 74-10-01, MM 74-10-01PROC. REF: MM 74-10-01, MM 74-10-01 |                                           |           |          |          |                        |           |           |             |                  |
| 742000                                                                 | NO. 1 ENGINE - 5 O'CLOCK IGNITER          |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:3070508-01                                                          | MOS/MSC                                   | 10-Jan-17 | O/C      |          |                        |           |           |             |                  |
| SN:NSN                                                                 | HRS                                       | 606.7     |          |          |                        |           |           |             |                  |
|                                                                        | ENC                                       | 345       |          |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                        |           |           |             |                  |
| 742000                                                                 | NO. 2 ENGINE - 5 O'CLOCK IGNITER          |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:3070508-01                                                          | MOS/MSC                                   | 10-Jan-17 | O/C      |          |                        |           |           |             |                  |
| SN:N/A                                                                 | HRS                                       | 606.7     |          |          |                        |           |           |             |                  |
|                                                                        | ENC                                       | 345       |          |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                        |           |           |             |                  |
| 742001                                                                 | NO. 1 ENGINE - 7 O'CLOCK IGNITER          |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:3070508-01                                                          | MOS/MSC                                   | 10-Jan-17 | O/C      |          |                        |           |           |             |                  |
| SN:NSN                                                                 | HRS                                       | 606.7     |          |          |                        |           |           |             |                  |
|                                                                        | ENC                                       | 345       |          |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                        |           |           |             |                  |
| 742001                                                                 | NO. 2 ENGINE - 7 O'CLOCK IGNITER          |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:3070508-01                                                          | MOS/MSC                                   | 10-Jan-17 | O/C      |          |                        |           |           |             |                  |
| SN:N/A                                                                 | HRS                                       | 606.7     |          |          |                        |           |           |             |                  |
|                                                                        | ENC                                       | 345       |          |          |                        |           |           |             |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                        |           |           |             |                  |
| 742002                                                                 | NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD |           |          |          |                        |           |           |             | Component ATA:74 |
| PN:3127408-02                                                          | MOS/MSC                                   | 19-Feb-16 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:NNA15510072                                                         | HRS                                       |           |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                       |           |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                           |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

### ATA 74 - IGNITION

|                                                                        |                                           |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------|-------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 742002                                                                 | NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD |           |     |       |  |  |  | Component | ATA:74 |
| PN:3127408-01                                                          | MOS/MSC                                   | 19-Feb-16 | O/C | TSN 0 |  |  |  |           |        |
| SN:NNA15510156                                                         | HRS                                       |           |     | TSN 0 |  |  |  |           |        |
|                                                                        | ENC                                       |           |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                           |           |     |       |  |  |  |           |        |

|                                                                        |                                           |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------|-------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 742003                                                                 | NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD |           |     |       |  |  |  | Component | ATA:74 |
| PN:3127408-01                                                          | MOS/MSC                                   | 19-Feb-16 | O/C | TSN 0 |  |  |  |           |        |
| SN:NNA15500157                                                         | HRS                                       |           |     | TSN 0 |  |  |  |           |        |
|                                                                        | ENC                                       |           |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                           |           |     |       |  |  |  |           |        |

|                                                                        |                                           |           |     |       |  |  |  |           |        |
|------------------------------------------------------------------------|-------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| 742003                                                                 | NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD |           |     |       |  |  |  | Component | ATA:74 |
| PN:3127408-02                                                          | MOS/MSC                                   | 19-Feb-16 | O/C | TSN 0 |  |  |  |           |        |
| SN:NNA15520103                                                         | HRS                                       |           |     | TSN 0 |  |  |  |           |        |
|                                                                        | ENC                                       |           |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                           |           |     |       |  |  |  |           |        |

### ATA 75 - AIR

|                                              |                                                                              |           |            |  |  |  |  |         |        |
|----------------------------------------------|------------------------------------------------------------------------------|-----------|------------|--|--|--|--|---------|--------|
| 75-30-01-212-801 <sup>S</sup>                | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE |           |            |  |  |  |  | Service | ATA:75 |
|                                              | MOS                                                                          | 14-May-25 | 12 (+30d)  |  |  |  |  |         |        |
|                                              | HRS                                                                          | 2086.2    | 800 (+10%) |  |  |  |  |         |        |
|                                              | ENC                                                                          | 1243      |            |  |  |  |  |         |        |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01 |                                                                              |           |            |  |  |  |  |         |        |
|                                              |                                                                              |           |            |  |  |  |  | PKG:1   |        |

|                                              |                                                                              |           |            |  |  |  |  |         |        |
|----------------------------------------------|------------------------------------------------------------------------------|-----------|------------|--|--|--|--|---------|--------|
| 75-30-01-212-801 <sup>S</sup>                | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE |           |            |  |  |  |  | Service | ATA:75 |
|                                              | MOS                                                                          | 14-May-25 | 12 (+30d)  |  |  |  |  |         |        |
|                                              | HRS                                                                          | 2086.2    | 800 (+10%) |  |  |  |  |         |        |
|                                              | ENC                                                                          | 1243      |            |  |  |  |  |         |        |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01 |                                                                              |           |            |  |  |  |  |         |        |
|                                              |                                                                              |           |            |  |  |  |  | PKG:1   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                     | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 75 - AIR                                                           |                                                          |           |             |          |                        |           |             |             |                  |
| 75-30-01-212-802                                                       | NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR       |           |             |          |                        |           |             |             | Service ATA:75   |
|                                                                        | MOS                                                      |           |             |          |                        |           |             |             |                  |
|                                                                        | HRS                                                      | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                      |           |             |          |                        |           |             |             |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                          |           |             |          |                        |           |             |             |                  |
| 75-30-01-212-802                                                       | NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR       |           |             |          |                        |           |             |             | Service ATA:75   |
|                                                                        | MOS                                                      |           |             |          |                        |           |             |             |                  |
|                                                                        | HRS                                                      | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                      |           |             |          |                        |           |             |             |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                          |           |             |          |                        |           |             |             |                  |
| 75-30-01-212-803                                                       | NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE      |           |             |          |                        |           |             |             | Service ATA:75   |
| PN:3053367-01                                                          | MOS                                                      |           |             |          |                        |           |             |             |                  |
| SN:AHX0500397                                                          | HRS                                                      | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                      |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                          |           |             |          |                        |           |             |             |                  |
| 75-30-01-212-803                                                       | NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE      |           |             |          |                        |           |             |             | Service ATA:75   |
| PN:3053367-01                                                          | MOS                                                      |           |             |          |                        |           |             |             |                  |
| SN:AHX0500378                                                          | HRS                                                      | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                                        | ENC                                                      |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                          |           |             |          |                        |           |             |             |                  |
| 75-30-01-900-802                                                       | NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE |           |             |          |                        |           |             |             | Component ATA:75 |
| PN:3075987-01                                                          | MOS/MSC                                                  | 26-Nov-14 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:TR7549                                                              | HRS                                                      | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                                        | ENC                                                      | 0         |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                          |           |             |          |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                                                                     | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition                         | Warranty |
|------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------------------------------|----------|
| ATA 75 - AIR                                                           |                                                                                                          |           |          |          |                        |           |           |                                     |          |
| 75-30-01-900-802                                                       | NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE                                                 |           |          |          |                        |           |           | Component                           | ATA:75   |
| PN:3075987-01                                                          | MOS/MSC                                                                                                  | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |                                     |          |
| SN:TR7575                                                              | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                        |           |           |                                     |          |
| 75-30-01-900-803                                                       | NO. 1 ENGINE - LINEAR TRANSFORMER                                                                        |           |          |          |                        |           |           | Component                           | ATA:75   |
| PN:3071811-01                                                          | MOS/MSC                                                                                                  | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |                                     |          |
| SN:1836                                                                | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                        |           |           |                                     |          |
| 75-30-01-900-803                                                       | NO. 2 ENGINE - LINEAR TRANSFORMER                                                                        |           |          |          |                        |           |           | Component                           | ATA:75   |
| PN:3071811-01                                                          | MOS/MSC                                                                                                  | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |                                     |          |
| SN:1835                                                                | HRS                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                        |           |           |                                     |          |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                        |           |           |                                     |          |
| 75-30-01-960-801                                                       | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES |           |          |          |                        |           |           | Service                             | ATA:75   |
|                                                                        | MOS/MSC                                                                                                  | 26-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED<br>MAINTENANCE<br>CHECK |          |
|                                                                        | HRS                                                                                                      | 0         |          |          |                        |           |           |                                     |          |
|                                                                        | ENC                                                                                                      | 0         |          |          |                        |           |           |                                     |          |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                        |           |           |                                     |          |
| 75-30-01-960-801                                                       | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES |           |          |          |                        |           |           | Service                             | ATA:75   |
|                                                                        | MOS/MSC                                                                                                  | 27-Nov-14 | A/R      |          |                        |           |           | UNSCHEDULED<br>MAINTENANCE<br>CHECK |          |
|                                                                        | HRS                                                                                                      | 0         |          |          |                        |           |           |                                     |          |
|                                                                        | ENC                                                                                                      | 0         |          |          |                        |           |           |                                     |          |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                        |           |           |                                     |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                                          | Unit                                                                                                                           | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition                   | Warranty       |
|--------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------------------------|----------------|
| ATA 75 - AIR                                                                                     |                                                                                                                                |           |             |          |                        |           |             |                               |                |
| 75-30-01-960-802                                                                                 | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE                                 |           |             |          |                        |           |             |                               | Service ATA:75 |
|                                                                                                  | MOS/MSC                                                                                                                        | 26-Nov-14 | A/R         |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
|                                                                                                  | HRS                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01                           |                                                                                                                                |           |             |          |                        |           |             |                               |                |
| 75-30-01-960-802                                                                                 | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE                                 |           |             |          |                        |           |             |                               | Service ATA:75 |
|                                                                                                  | MOS/MSC                                                                                                                        | 27-Nov-14 | A/R         |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
|                                                                                                  | HRS                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01                           |                                                                                                                                |           |             |          |                        |           |             |                               |                |
| 75-30-01-960-803                                                                                 | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER |           |             |          |                        |           |             |                               | Service ATA:75 |
| PN:3071811-01                                                                                    | MOS/MSC                                                                                                                        | 26-Nov-14 | A/R         |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
| SN:1836                                                                                          | HRS                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
| PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01 |                                                                                                                                |           |             |          |                        |           |             |                               |                |
| 75-30-01-960-803                                                                                 | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER |           |             |          |                        |           |             |                               | Service ATA:75 |
| PN:3071811-01                                                                                    | MOS/MSC                                                                                                                        | 27-Nov-14 | A/R         |          |                        |           |             | UNSCHEDULED MAINTENANCE CHECK |                |
| SN:1835                                                                                          | HRS                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                        |           |             |                               |                |
| PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01 |                                                                                                                                |           |             |          |                        |           |             |                               |                |
| 75-30-02-212-801                                                                                 | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER                |           |             |          |                        |           |             |                               | Service ATA:75 |
| PN:3071811-01                                                                                    | MOS                                                                                                                            |           |             |          |                        |           |             |                               |                |
| SN:1836                                                                                          | HRS                                                                                                                            | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |                               |                |
|                                                                                                  | ENC                                                                                                                            |           |             |          |                        |           |             |                               |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                               |                                                                                                                                |           |             |          |                        |           |             |                               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                                                                                            | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 75 - AIR                                       |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 75-30-02-212-801                                   | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER |           |             |          |                        |           |             |             | Service ATA:75   |
| PN:3071811-01                                      | MOS                                                                                                             |           |             |          |                        |           |             |             |                  |
| SN:1835                                            | HRS                                                                                                             | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                    | ENC                                                                                                             |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 75-30-20-212-801                                   | NO. 1 ENGINE - REPLACED WITH NEW - THE BOV TORQUE MOTOR                                                         |           |             |          |                        |           |             |             | Service ATA:75   |
|                                                    | MOS                                                                                                             |           |             |          |                        |           |             |             |                  |
|                                                    | HRS                                                                                                             | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                    | ENC                                                                                                             |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 75-30-20-212-801                                   | NO. 2 ENGINE - REPLACED WITH NEW - THE BOV TORQUE MOTOR                                                         |           |             |          |                        |           |             |             | Service ATA:75   |
|                                                    | MOS                                                                                                             |           |             |          |                        |           |             |             |                  |
|                                                    | HRS                                                                                                             | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                    | ENC                                                                                                             |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 750010                                             | NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR                                                                        |           |             |          |                        |           |             |             | Component ATA:75 |
| PN:PN                                              | MOS/MSC                                                                                                         | 26-Nov-14 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                    | ENC                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: MM 75-00-00PROC. REF: MM 75-00-00       |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 750010                                             | NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR                                                                        |           |             |          |                        |           |             |             | Component ATA:75 |
| PN:PN                                              | MOS/MSC                                                                                                         | 27-Nov-14 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                    | ENC                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: MM 75-00-00PROC. REF: MM 75-00-00       |                                                                                                                 |           |             |          |                        |           |             |             |                  |
| 753002                                             | NO. 1 ENGINE - SERVO COMPUTER                                                                                   |           |             |          |                        |           |             |             | Component ATA:75 |
| PN:PN                                              | MOS/MSC                                                                                                         | 26-Nov-14 | O/C         | TSN 0    |                        |           |             |             |                  |
| SN:UNKNOWN                                         | HRS                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |
|                                                    | ENC                                                                                                             | 0         |             | TSN 0    |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 75 - AIR

PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF

| 753002                                             | NO. 2 ENGINE - SERVO COMPUTER |           |     |       |  |  |  | Component | ATA:75 |
|----------------------------------------------------|-------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:PN                                              | MOS/MSC                       | 27-Nov-14 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                           | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | ENC                           | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                               |           |     |       |  |  |  |           |        |

| 753010                                       | NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY |           |     |       |  |  |  | Component | ATA:75 |
|----------------------------------------------|------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:3053367-01                                | MOS/MSC                                        | 26-Nov-14 | O/C | TSN 0 |  |  |  |           |        |
| SN:AHX0500397                                | HRS                                            | 0         |     | TSN 0 |  |  |  |           |        |
|                                              | ENC                                            | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01 |                                                |           |     |       |  |  |  |           |        |

| 753010                                       | NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY |           |     |       |  |  |  | Component | ATA:75 |
|----------------------------------------------|------------------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:3053367-01                                | MOS/MSC                                        | 27-Nov-14 | O/C | TSN 0 |  |  |  |           |        |
| SN:AHX0500378                                | HRS                                            | 0         |     | TSN 0 |  |  |  |           |        |
|                                              | ENC                                            | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01 |                                                |           |     |       |  |  |  |           |        |

| 753020                                             | NO. 1 ENGINE - BOV TORQUE MOTOR |           |     |       |  |  |  | Component | ATA:75 |
|----------------------------------------------------|---------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:PN                                              | MOS/MSC                         | 26-Nov-14 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                             | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | ENC                             | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |     |       |  |  |  |           |        |

| 753020                                             | NO. 2 ENGINE - BOV TORQUE MOTOR |           |     |       |  |  |  | Component | ATA:75 |
|----------------------------------------------------|---------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:PN                                              | MOS/MSC                         | 27-Nov-14 | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS                             | 0         |     | TSN 0 |  |  |  |           |        |
|                                                    | ENC                             | 0         |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                 |           |     |       |  |  |  |           |        |

## ATA 76 - ENGINE CONTROLS

| 76-11-03      | THROTTLE CONTROL QUADRANT ASSEMBLY |           |     |       |  |  |  | Component | ATA:76 |
|---------------|------------------------------------|-----------|-----|-------|--|--|--|-----------|--------|
| PN:6990010-11 | MOS/MSC                            | 29-Apr-15 | O/C | TSN 0 |  |  |  |           |        |
| SN:1658       | HRS                                | 0         |     | TSN 0 |  |  |  |           |        |
|               | AFL                                | 0         |     | TSN 0 |  |  |  |           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                                                        | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining     | Disposition | Warranty |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|---------------|-------------|----------|
| ATA 76 - ENGINE CONTROLS                                                   |                                                                                             |           |             |          |                        |           |               |             |          |
| PROC. REF: AMM 76-11-01, AMM 76-11-01PROC. REF: AMM 76-11-01, AMM 76-11-01 |                                                                                             |           |             |          |                        |           |               |             |          |
| ATA 77 - ENGINE INDICATING                                                 |                                                                                             |           |             |          |                        |           |               |             |          |
| 77-20-02-750-801                                                           | NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM                           |           |             |          |                        |           |               | Service     | ATA:77   |
|                                                                            | MOS                                                                                         | 29-Apr-24 | 36 (+30d)   |          | 29-Apr-27              | 29-May-27 | 682 d (+30)   |             |          |
|                                                                            | HRS                                                                                         | 1952.5    | 1600 (+100) |          | (3552.5)<br>3552.5     | 3652.5    | 1452.5 (+100) |             |          |
|                                                                            | ENC                                                                                         | 1160      |             |          |                        |           |               |             |          |
| PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02                               |                                                                                             |           |             |          |                        |           |               |             |          |
| 77-20-02-750-801                                                           | NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM                           |           |             |          |                        |           |               | Service     | ATA:77   |
|                                                                            | MOS                                                                                         | 29-Apr-24 | 36 (+30d)   |          | 29-Apr-27              | 29-May-27 | 682 d (+30)   |             |          |
|                                                                            | HRS                                                                                         | 1952.5    | 1600 (+100) |          | (3552.5)<br>3552.5     | 3652.5    | 1452.5 (+100) |             |          |
|                                                                            | ENC                                                                                         | 1160      |             |          |                        |           |               |             |          |
| PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02                               |                                                                                             |           |             |          |                        |           |               |             |          |
| 77-40-01-212-801                                                           | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT |           |             |          |                        |           |               | Service     | ATA:77   |
| PN:3075878-01                                                              | MOS                                                                                         |           |             |          |                        |           |               |             |          |
| SN:14026008                                                                | HRS                                                                                         | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100)   |             |          |
|                                                                            | ENC                                                                                         |           |             |          |                        |           |               |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                             |           |             |          |                        |           |               |             |          |
| 77-40-01-212-801                                                           | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT |           |             |          |                        |           |               | Service     | ATA:77   |
| PN:3075878-01                                                              | MOS                                                                                         |           |             |          |                        |           |               |             |          |
| SN:14025512                                                                | HRS                                                                                         | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100)   |             |          |
|                                                                            | ENC                                                                                         |           |             |          |                        |           |               |             |          |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                             |           |             |          |                        |           |               |             |          |
| 774001                                                                     | NO. 1 ENGINE - DATA COLLECTION UNIT                                                         |           |             |          |                        |           |               | Component   | ATA:77   |
| PN:3075878-01                                                              | MOS/MSC                                                                                     | 26-Nov-14 | O/C         | TSN 0    |                        |           |               |             |          |
| SN:14026008                                                                | HRS                                                                                         | 0         |             | TSN 0    |                        |           |               |             |          |
|                                                                            | ENC                                                                                         | 0         |             | TSN 0    |                        |           |               |             |          |
| PROC. REF: MM 77-40-01, MM 77-40-01PROC. REF: MM 77-40-01, MM 77-40-01     |                                                                                             |           |             |          |                        |           |               |             |          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty |
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|
|---------|------|-----|----------|----------|------------------------|-----------|-----------|-------------|----------|

## ATA 77 - ENGINE INDICATING

|                                                                        |         |                                     |     |       |  |  |  |           |        |
|------------------------------------------------------------------------|---------|-------------------------------------|-----|-------|--|--|--|-----------|--------|
| 774001                                                                 |         | NO. 2 ENGINE - DATA COLLECTION UNIT |     |       |  |  |  | Component | ATA:77 |
| PN:3075878-01                                                          | MOS/MSC | 27-Nov-14                           | O/C | TSN 0 |  |  |  |           |        |
| SN:14025512                                                            | HRS     | 0                                   |     | TSN 0 |  |  |  |           |        |
|                                                                        | ENC     | 0                                   |     | TSN 0 |  |  |  |           |        |
| PROC. REF: MM 77-40-01, MM 77-40-01PROC. REF: MM 77-40-01, MM 77-40-01 |         |                                     |     |       |  |  |  |           |        |

## ATA 78 - EXHAUST

|                                                    |         |                            |     |       |  |  |  |           |        |
|----------------------------------------------------|---------|----------------------------|-----|-------|--|--|--|-----------|--------|
| 78-00-00                                           |         | LH ENGINE EXHAUST ASSEMBLY |     |       |  |  |  | Component | ATA:78 |
| PN:PN                                              | MOS/MSC | 29-Apr-15                  | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS     | 0                          |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL     | 0                          |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                            |     |       |  |  |  |           |        |

|                                                    |         |                            |     |       |  |  |  |           |        |
|----------------------------------------------------|---------|----------------------------|-----|-------|--|--|--|-----------|--------|
| 78-00-00                                           |         | RH ENGINE EXHAUST ASSEMBLY |     |       |  |  |  | Component | ATA:78 |
| PN:PN                                              | MOS/MSC | 29-Apr-15                  | O/C | TSN 0 |  |  |  |           |        |
| SN:UNKNOWN                                         | HRS     | 0                          |     | TSN 0 |  |  |  |           |        |
|                                                    | AFL     | 0                          |     | TSN 0 |  |  |  |           |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |         |                            |     |       |  |  |  |           |        |

## ATA 79 - OIL

|                                                    |     |                                                                          |             |                      |      |             |  |         |        |
|----------------------------------------------------|-----|--------------------------------------------------------------------------|-------------|----------------------|------|-------------|--|---------|--------|
| 79-10-02-212-801                                   |     | NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) |             |                      |      |             |  | Service | ATA:79 |
| PN:3052640-04                                      | MOS |                                                                          |             |                      |      |             |  |         |        |
| SN:09037887                                        | HRS | EFF                                                                      | 5000 (+100) | (5000)<br>5000 * (M) | 5100 | 2900 (+100) |  |         |        |
|                                                    | ENC |                                                                          |             |                      |      |             |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |     |                                                                          |             |                      |      |             |  |         |        |

|                                                    |     |                                                                          |             |                      |      |             |  |         |        |
|----------------------------------------------------|-----|--------------------------------------------------------------------------|-------------|----------------------|------|-------------|--|---------|--------|
| 79-10-02-212-801                                   |     | NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) |             |                      |      |             |  | Service | ATA:79 |
| PN:3052640-04                                      | MOS |                                                                          |             |                      |      |             |  |         |        |
| SN:09037885                                        | HRS | EFF                                                                      | 5000 (+100) | (5000)<br>5000 * (M) | 5100 | 2900 (+100) |  |         |        |
|                                                    | ENC |                                                                          |             |                      |      |             |  |         |        |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |     |                                                                          |             |                      |      |             |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                                                      | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 79 - OIL                                                           |                                                                                           |           |             |          |                        |           |             |             |                |
| 79-20-00-212-801                                                       | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                                                       |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                                                       | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                                                       |           |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                           |           |             |          |                        |           |             |             |                |
| 79-20-00-212-801                                                       | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                                                       |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                                                       | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                                                       |           |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                           |           |             |          |                        |           |             |             |                |
| 79-20-01-210-801                                                       | NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER                                           |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                                                       |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                                                       | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                                                       |           |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-20-01PROC. REF: MM 79-20-01                           |                                                                                           |           |             |          |                        |           |             |             |                |
| 79-20-01-210-801                                                       | NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER                                           |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                                                       |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                                                       | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                                                       |           |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-20-01PROC. REF: MM 79-20-01                           |                                                                                           |           |             |          |                        |           |             |             |                |
| 79-20-01-960-801                                                       | NO. 1 ENGINE - DISCARD THE OIL FILTER                                                     |           |             |          |                        |           |             |             | Service ATA:79 |
| PN:PN                                                                  | MOS                                                                                       | 24-Apr-23 |             |          |                        |           |             | DISCARD     |                |
| SN:UNKNOWN                                                             | HRS                                                                                       | 1825.5    | 800 (+10%)  |          | (2625.5)<br>2625.5     | 2705.5    | 525.5 (+80) |             |                |
|                                                                        | ENC                                                                                       | 1042      |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                                                                           |           |             |          |                        |           |             |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                                  | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|------------------------------------------------------------------------|-------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 79 - OIL                                                           |                                                       |           |             |          |                        |           |             |             |                |
| 79-20-01-960-801                                                       | NO. 2 ENGINE - DISCARD THE OIL FILTER                 |           |             |          |                        |           |             |             | Service ATA:79 |
| PN:PN                                                                  | MOS                                                   | 24-Apr-23 |             |          |                        |           |             | DISCARD     |                |
| SN:UNKNOWN                                                             | HRS                                                   | 1825.5    | 800 (+10%)  |          | (2625.5)<br>2625.5     | 2705.5    | 525.5 (+80) |             |                |
|                                                                        | ENC                                                   | 1042      |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                                       |           |             |          |                        |           |             |             |                |
| 79-30-01-210-801                                                       | NO. 1 ENGINE - EXAMINE - CHIP DETECTOR                |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                   |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                   | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                   |           |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                       |           |             |          |                        |           |             |             |                |
| 79-30-01-210-801                                                       | NO. 2 ENGINE - EXAMINE - CHIP DETECTOR                |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                   |           |             |          |                        |           |             |             |                |
|                                                                        | HRS                                                   | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                                        | ENC                                                   |           |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                       |           |             |          |                        |           |             |             |                |
| 79-30-01-770-801 <sup>S</sup>                                          | NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                   | 14-May-25 | 12 (+30d)   |          |                        |           |             |             |                |
|                                                                        | HRS                                                   | 2086.2    | 800 (+10%)  |          |                        |           |             |             |                |
|                                                                        | ENC                                                   | 1243      |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                       |           |             |          |                        |           |             |             | PKG:1          |
| 79-30-01-770-801 <sup>S</sup>                                          | NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR |           |             |          |                        |           |             |             | Service ATA:79 |
|                                                                        | MOS                                                   | 14-May-25 | 12 (+30d)   |          |                        |           |             |             |                |
|                                                                        | HRS                                                   | 2086.2    | 800 (+10%)  |          |                        |           |             |             |                |
|                                                                        | ENC                                                   | 1243      |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                       |           |             |          |                        |           |             |             | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

## Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit         | C/W                                                                                | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty       |
|----------------------------------------------------|--------------|------------------------------------------------------------------------------------|-------------|----------|------------------------|-----------|-------------|-------------|----------------|
| ATA 79 - OIL                                       |              |                                                                                    |             |          |                        |           |             |             |                |
| 79-30-02-210-801                                   | <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH |             |          |                        |           |             |             | Service ATA:79 |
|                                                    | MOS          | 14-May-25                                                                          | 12 (+30d)   |          |                        |           |             |             |                |
|                                                    | HRS          | 2086.2                                                                             | 800 (+10%)  |          |                        |           |             |             |                |
|                                                    | ENC          | 1243                                                                               |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-02PROC. REF: MM 79-30-02       |              |                                                                                    |             |          |                        |           |             |             | PKG:1          |
| 79-30-02-210-801                                   | <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH |             |          |                        |           |             |             | Service ATA:79 |
|                                                    | MOS          | 14-May-25                                                                          | 12 (+30d)   |          |                        |           |             |             |                |
|                                                    | HRS          | 2086.2                                                                             | 800 (+10%)  |          |                        |           |             |             |                |
|                                                    | ENC          | 1243                                                                               |             |          |                        |           |             |             |                |
| PROC. REF: MM 79-30-02PROC. REF: MM 79-30-02       |              |                                                                                    |             |          |                        |           |             |             | PKG:1          |
| 79-30-03-212-801                                   |              | NO. 1 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP                         |             |          |                        |           |             |             | Service ATA:79 |
|                                                    | MOS          |                                                                                    |             |          |                        |           |             |             |                |
|                                                    | HRS          | EFF                                                                                | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC          |                                                                                    |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                    |             |          |                        |           |             |             |                |
| 79-30-03-212-801                                   |              | NO. 2 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP                         |             |          |                        |           |             |             | Service ATA:79 |
|                                                    | MOS          |                                                                                    |             |          |                        |           |             |             |                |
|                                                    | HRS          | EFF                                                                                | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC          |                                                                                    |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                    |             |          |                        |           |             |             |                |
| 79-30-20-212-801                                   |              | NO. 1 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS)                         |             |          |                        |           |             |             | Service ATA:79 |
|                                                    | MOS          |                                                                                    |             |          |                        |           |             |             |                |
|                                                    | HRS          | EFF                                                                                | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                |
|                                                    | ENC          |                                                                                    |             |          |                        |           |             |             |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                    |             |          |                        |           |             |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval    | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining   | Disposition | Warranty         |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|-------------|----------|------------------------|-----------|-------------|-------------|------------------|
| ATA 79 - OIL                                                               |                                                            |           |             |          |                        |           |             |             |                  |
| 79-30-20-212-801                                                           | NO. 2 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS) |           |             |          |                        |           |             |             | Service ATA:79   |
|                                                                            | MOS                                                        |           |             |          |                        |           |             |             |                  |
|                                                                            | HRS                                                        | EFF       | 5000 (+100) |          | (5000)<br>5000 * (M)   | 5100      | 2900 (+100) |             |                  |
|                                                                            | ENC                                                        |           |             |          |                        |           |             |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |             |          |                        |           |             |             |                  |
| 79-31-05                                                                   | LEFT ENGINE MAIN OIL PRESSURE SENSOR                       |           |             |          |                        |           |             |             | Component ATA:79 |
| PN:APTE-478A-1000-270D                                                     | MOS/MSC                                                    | 05-Sep-24 | O/C         | TSN 9    |                        |           |             |             |                  |
| SN:01676                                                                   | HRS                                                        | 2037.3    |             | TSN 0    |                        |           |             |             |                  |
|                                                                            | AFL                                                        | 1207      |             | TSN 0    |                        |           |             |             |                  |
| PROC. REF: AMM 79-31-05, AMM 79-31-05PROC. REF: AMM 79-31-05, AMM 79-31-05 |                                                            |           |             |          |                        |           |             |             |                  |
| 79-31-05                                                                   | RIGHT ENGINE MAIN OIL PRESSURE SENSOR                      |           |             |          |                        |           |             |             | Component ATA:79 |
| PN:APTE-478A-1000-270D                                                     | MOS/MSC                                                    | 05-Sep-24 | O/C         | TSN 9    |                        |           |             |             |                  |
| SN:01677                                                                   | HRS                                                        | 2037.3    |             | TSN 84.8 |                        |           |             |             |                  |
|                                                                            | AFL                                                        | 1207      |             | TSN 47   |                        |           |             |             |                  |
| PROC. REF: AMM 79-31-05, AMM 79-31-05PROC. REF: AMM 79-31-05, AMM 79-31-05 |                                                            |           |             |          |                        |           |             |             |                  |
| 790000                                                                     | NO. 1 ENGINE - OIL FILTER                                  |           |             |          |                        |           |             |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                                    | 24-Apr-23 | O/C         |          |                        |           |             |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 1825.5    |             |          |                        |           |             |             |                  |
|                                                                            | ENC                                                        | 1042      |             |          |                        |           |             |             |                  |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01     |                                                            |           |             |          |                        |           |             |             |                  |
| 790000                                                                     | NO. 2 ENGINE - OIL FILTER                                  |           |             |          |                        |           |             |             | Component ATA:79 |
| PN:PN                                                                      | MOS/MSC                                                    | 24-Apr-23 | O/C         |          |                        |           |             |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 1825.5    |             |          |                        |           |             |             |                  |
|                                                                            | ENC                                                        | 1042      |             |          |                        |           |             |             |                  |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01     |                                                            |           |             |          |                        |           |             |             |                  |
| 790020                                                                     | NO. 1 ENGINE - CHANGE OIL                                  |           |             |          |                        |           |             |             | Service ATA:79   |
|                                                                            | MOS/MSC                                                    | 26-Nov-14 | A/R         |          |                        |           |             |             |                  |
|                                                                            | HRS                                                        | 0         |             |          |                        |           |             |             |                  |
|                                                                            | ENC                                                        | 0         |             |          |                        |           |             |             |                  |
| PROC. REF: MM 72-00-00, MM 72-00-00PROC. REF: MM 72-00-00, MM 72-00-00     |                                                            |           |             |          |                        |           |             |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                                           |                                              |           |          |          |                        |           |           |             |                  |
| 790020                                                                 | NO. 2 ENGINE - CHANGE OIL                    |           |          |          |                        |           |           |             | Service ATA:79   |
|                                                                        | MOS/MSC                                      | 27-Nov-14 | A/R      |          |                        |           |           |             |                  |
|                                                                        | HRS                                          | 0         |          |          |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          |          |                        |           |           |             |                  |
| PROC. REF: MM 72-00-00, MM 72-00-00PROC. REF: MM 72-00-00, MM 72-00-00 |                                              |           |          |          |                        |           |           |             |                  |
| 792010                                                                 | NO. 1 ENGINE - TEMPERATURE SENSOR            |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:ATS-9-800                                                           | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060214-26                                                           | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 792010                                                                 | NO. 2 ENGINE - TEMPERATURE SENSOR            |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:ATS-9-800                                                           | MOS/MSC                                      | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:060214-29                                                           | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |
| 793003                                                                 | NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER       |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:3052640-04                                                          | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:09037887                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-10-02, MM 73-10-02PROC. REF: MM 73-10-02, MM 73-10-02 |                                              |           |          |          |                        |           |           |             |                  |
| 793003                                                                 | NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER       |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:3052640-04                                                          | MOS/MSC                                      | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:09037885                                                            | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: MM 73-10-02, MM 73-10-02PROC. REF: MM 73-10-02, MM 73-10-02 |                                              |           |          |          |                        |           |           |             |                  |
| 793010                                                                 | NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                                                  | MOS/MSC                                      | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                                             | HRS                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

# Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 2100 AFL: 1252 As Of: 16-Jun-2025

16-Jun-2025 02:33 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due (ENG/APU) A/C | Max Limit | Remaining | Disposition | Warranty         |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|------------------------|-----------|-----------|-------------|------------------|
| ATA 79 - OIL                                       |                                                  |           |          |          |                        |           |           |             |                  |
| 793010                                             | NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR     |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 793020                                             | NO. 1 ENGINE - OIL TANK FILLER CAP               |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 793020                                             | NO. 2 ENGINE - OIL TANK FILLER CAP               |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 793025                                             | NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 26-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |
| 793025                                             | NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) |           |          |          |                        |           |           |             | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 27-Nov-14 | O/C      | TSN 0    |                        |           |           |             |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                        |           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                        |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task