



CESCOM 20 - Projected Maintenance Due

Owner: YUKON AVIATION, LLC
Aircraft Model: CITATION M2
Aircraft Serial: 525-0825
Unit: Reg No: N825MT
Airworthiness: 28-Apr-2014
Print Date: 05-Sep-2025 6:26PM

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 1	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 2	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
AIR COND	1421		22-Aug-2025	.9	9.86	2041.43		207	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-02	INSPECTION DOCUMENT 02 KPWA		MTH 06-Sep-2024 HRS 1964 LDG 1611		12		30-Sep-2025	25 d
5-12-36	INSPECTION DOCUMENT 36 KPWA		MTH 12-Mar-2025 HRS 2005.3 LDG 1639		6		30-Sep-2025	25 d
B262201 CABIN	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 2 KPWA	C352TS Y-650750	MTH 06-Sep-2024 HRS 1964 LDG 1611		12		30-Sep-2025	25 d
A215004	COMPRESSOR DRIVE MOTOR BRUSHES KPWA	1251171 NSN	MTH 23-Jun-2023 HRS 1791.2 LDG 1469 ACH 1264.3	-41	500	0	1723.3	302.3
5-12-37	INSPECTION DOCUMENT 37 KPWA		MTH 23-Jul-2023 HRS 1791.2 LDG 1469 ACH 1264.3		500		1764.3	343.3
052001 E1	FJ44 CHECK 1 KPWA		MTH 30-May-2023 HRS 1787.1 LDG 1464		300		(2087.1)2087.1	49.2
052001 E2	FJ44 CHECK 1 KPWA		MTH 30-May-2023 HRS 1787.1 LDG 1464		300		(2087.1)2087.1	49.2
A215004	COMPRESSOR DRIVE MOTOR BRUSHES KPWA	1251171 NSN	ACH 1264.3	-41	500	0	2223.3	802.3
5-12-37	INSPECTION DOCUMENT 37 KPWA		ACH 1264.3		500		2264.3	843.3
5-12-12	INSPECTION DOCUMENT 12 (14 CFR 91.207) KPWA		MTH 13-Dec-2024 HRS 1989.3 LDG 1628		12		31-Dec-2025	3 m 26 d
5-12-33	INSPECTION DOCUMENT 33 KPWA		MTH 13-Dec-2024 HRS 1989.3 LDG 1628		12 300		31-Dec-2025 2289.3	3 m 26 d 251.4
A256201	DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER ARTEX (ELT): INSPECTION DOCUMENT 12 KPWA	453-5060 14212	MTH 13-Dec-2024 HRS 1989.3 LDG 1628		12		31-Dec-2025	3 m 26 d
B256203	OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR TRANSMITTER: INSPECTION DOCUMENT 12 KPWA		MTH 13-Dec-2024 HRS 1989.3 LDG 1628		12		31-Dec-2025	3 m 26 d
B243601	FUNCTIONAL CHECK MAIN BATTERY NICKEL-CADMIUM BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 17 9914058-6 12400357		MTH 12-Jun-2025 HRS 2018.7 LDG 1650		12 100		30-Jun-2026 2118.7	9 m 25 d 80.8
A215004	COMPRESSOR DRIVE MOTOR BRUSHES KPWA	1251171 NSN	ACH 1264.3	-41	500	0	2723.3	1302.3
5-12-37	INSPECTION DOCUMENT 37 KPWA		ACH 1264.3		500		2764.3	1343.3
26-22-00-961 CABIN	CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK C352TS Y-650750		MTH 01-Jan-2014		144		31-Jan-2026	4 m 26 d
A262201 CABIN	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 06 KPWA	C352TS Y-650750	MTH 30-Jan-2020 HRS 1274.7 LDG 1071		72		31-Jan-2026	4 m 26 d

NOTE: Item codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **YUKON AVIATION, LLC**
Aircraft Model: **CITATION M2**
Aircraft Serial: **525-0825**
Unit: Reg No: **N825MT**
Airworthiness: **28-Apr-2014**
Print Date: **05-Sep-2025 6:26PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 1	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 2	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
AIR COND	1421		22-Aug-2025	.9	9.86	2041.43		207	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
A215004	COMPRESSOR DRIVE MOTOR BRUSHES	KPWA		1251171	ACH 1264.3	-41	500	0	3223.3	1802.3
				NSN						
5-12-37	INSPECTION DOCUMENT 37	KPWA			ACH 1264.3		500		3264.3	1843.3
5-12-03	INSPECTION DOCUMENT 03	KPWA			MTH 26-Mar-2024		24		31-Mar-2026	6 m 26 d
					HRS 1913.1					
					LDG 1568					
5-12-36	INSPECTION DOCUMENT 36	KPWA			MTH 12-Mar-2025		6		31-Mar-2026	6 m 26 d



CESCOM 20 - Projected Maintenance Due

Owner: **YUKON AVIATION, LLC**
Aircraft Model: **CITATION M2**
Aircraft Serial: **525-0825**
Unit: Reg No: **N825MT**
Airworthiness: **28-Apr-2014**
Print Date: **05-Sep-2025 6:26PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 1	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
ENG 2	2037.9	1664	22-Aug-2025	.2	0.66	136.1	101	207	6
AIR COND	1421		22-Aug-2025	.9	9.86	2041.43		207	6

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE	MTH HRS RECOMMENDED MSC			-		(3000)3000	962.1
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE	HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE	HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB FJ44-72-140 R01 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION	MTH HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB FJ44-72-140 R01 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION	MTH HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB WI-73-1009 R05 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE	HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB WI-73-1009 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE	HRS RECOMMENDED MSC			CSI		(5000)5000	2962.1
SB WI-75-1001 R02 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	MTH HRS RECOMMENDED MSC			-		(5000)5000	2962.1
SB WI-75-1001 R02 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE	MTH HRS RECOMMENDED MSC			-		(5000)5000	2962.1
SB 525-27-26	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION	MTH RECOMMENDED MSC			-			
SB 525-34-111	NAVIGATION - TOLD DATABASE UPDATE	MTH RECOMMENDED MSC			-			
SB WI-73-1008 R04 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE	MTH RECOMMENDED MSC			-			
SB WI-73-1008 R04 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE	MTH RECOMMENDED MSC			-			
SL 525-28-06	FUEL - FUEL LOW LEVEL FLOAT SWITCH (SL001, LEFT; SR001, RIGHT) MOUNTING NUT TORQUE INSPECTION	MTH MSC			-			
SL 525-71-08	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL	MTH RECOMMENDED MSC			-			