



Status Report

TBM 910

S/N 1388 N117MV

OWNER: BAYOU DEVELOPMENT CORP

ADDRESS: 333 W. HAMPDEN AVENUE
ENGLEWOOD CO 80110

OFFICE: 504-616-7787

FAX:

OPERATOR: BAYOU DEVELOPMENT CORP

ADDRESS: 333 W. HAMPDEN AVENUE
ENGLEWOOD CO 80110

OFFICE: 504-616-7787

FAX:

ANALYST: JOSHUA MCNAMEE
EMAIL: JMCNAMEE@CAMPSYSTEMS.COM

0870 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT **SERIAL/REGNO:** 1388/N117MV **MODEL:** TBM 910 **MANUFACTURER:** DAHER

CERTIFICATION DATE: 29-SEP-2021

LAST ACTUALS:

701	A/C HRS	as of 01-AUG-2025
483	AFL	as of 01-AUG-2025
0	FLTS	as of 29-SEP-2021

ENGINE NO. 1 **SERIAL/PART:** PCE-RV0737/3071016-01 **MODEL:** PT6A-66D **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 29-SEP-2021

0	ENG. HRS	0 A/C HRS
0	ENC	

LAST ACTUALS:

701	ENG. HRS	as of 01-AUG-2025
483	ENC	as of 01-AUG-2025

PROPELLER NO. 1 **SERIAL/PART:** RJ594/HC-E5N-3C/NC8834K **MODEL:** HC-E5N-3C **MANUFACTURER:** HARTZELL PROPELLER LLC

INSTALLED ON: 29-SEP-2021

0	PROP HRS	0 A/C HRS
0	PRC	

LAST ACTUALS:

701	PROP HRS	as of 01-AUG-2025
-----	----------	-------------------



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
05-21-30	PRESSURIZATION VALVES SEAT CLEANING							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-23-15	HF COMMUNICATION EQUIPMENT CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-25-12	COCKPIT SEAT AIRBAG SYSTEM CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-28-10	FLAPPER VALVES AND STRAINERS CHECK							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-32-00	HYDRAULIC FLUID REPLACEMENT							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								
05-32-01	5-YEAR LANDING GEAR LONG LIFE PROGRAM							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
05-34-00	OPERATIONAL TEST AND CALIBRATION OF COMMUNICATION AND NAVIGATION EQUIPMENT							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-72-00	HOT SECTION & FUEL NOZZLE CHECKS							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-72-01	ENGINE INITIAL 100 HOURS INSPECTION							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-73-10	FUEL PUMP FILTERS CLEANING & REPLACEMENT							Service ATA:00
	MOS/MSC		-					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E66D-230410	NO. 1 ENGINE - REVIEW PT6A-66D EMM REV 24.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E66DPROC. REF: RCF E66D								
P900-170701	NO. 1 PROPELLER - REVIEW POM 147 REV 13							Service ATA:00
	MOS/MSC	29-Sep-21	-					REQUIREMENT CHANGE FORMS
	HRS	0						
PROC. REF: RCF P900PROC. REF: RCF P900								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
S850-201201	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.21							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF S850, GENERIC NO REFPROC. REF: RCF S850, GENERIC NO REF								
S850-230701	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.22							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: GENERIC NO REF, RCF S850PROC. REF: GENERIC NO REF, RCF S850								
S850-230901	REVIEW TBM 850/900/910 TLMC CHAPTER 5 REV.23							Service ATA:00
	MOS/MSC	EBT	-				NEW REQMT	REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF S850PROC. REF: RCF S850								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-20-01	STANDARD PROGRAM - FIRST INSPECTION							Package ATA:05
	MOS/MSC	18-Mar-22	-					
	HRS	105.2		Adj -5.2				
WC#: 05.040	AFL							
								PKG:1
05-70-CA-890-801	NO. 1 ENGINE - MINOR INSPECTION							Package ATA:05
	MOS	01-Aug-25	12 (+1m)	Adj -64d	29-May-26	29-Jun-26	215 d (+31)	
	HRS	701	200 (+10)		(901) 901	911	200 (+10)	
	ENC	483						
								PKG:1
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-20-02	STANDARD PROGRAM - A INSPECTION							Package ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)	Adj -64d	29-May-26	29-Jun-26	215 d (+31)	
	HRS	701	200 (+10/-10)		901	911	200 (+10)	
	AFL	483						
								PKG:9
05-20-03	STANDARD PROGRAM - B INSPECTION							Package ATA:05
	MOS	01-Aug-25	24 (+1m/-1m)	Adj -64d	29-May-27	29-Jun-27	580 d (+31)	
	HRS	701	400 (+10/-10)		1101	1111	400 (+10)	
	AFL	483						
								PKG:10
05-20-04	STANDARD PROGRAM - C INSPECTION							Package ATA:05
	MOS	01-Aug-25	48 (+1m/-1m)	Adj -64d	29-May-29	29-Jun-29	1311 d (+31)	
	HRS	701	800 (+10/-10)		1501	1511	800 (+10)	
	AFL	483						
								PKG:11
05-20-05	ANNUAL INSPECTION							Package ATA:05
	MOS	01-Aug-25	12		01-Aug-26		279 d	
	HRS	701						
	AFL	483						
								PKG:12
05-10-01-100-801 ^S	IF REQUIRED, CLEAN THE AIRCRAFT EXTERIOR SURFACE.							Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-22-01PROC. REF: AMM 12-22-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-200-801	^S	SHUTDOWN ENGINE - CHECK FOR FUEL OR OIL LEAKS AT POWER PLANT. CHECK COMPONENTS REMOVED OR REPLACED DURING INSPECTION FOR CONDITION.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								PKG:5,6,7,8,9 ,10 ,11
05-10-01-200-802	^S	CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-12-01PROC. REF: AMM 12-12-01								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-803	^S	CHECK THAT ENGINE COWLINGS, ACCESS DOORS, FLOOR PANELS, KARMANS AND FAIRINGS ARE CORRECTLY INSTALLED.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-10-00, AMM 71-10-00PROC. REF: AMM 71-10-00, AMM 71-10-00								PKG:1,5,6,7,8,9 ,10 ,11
05-10-01-200-804	^S	SHUTDOWN ENGINE - CHECK ENGINE OIL LEVEL WITHIN 10 MINUTES AFTER SHUTDOWN						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-12-01PROC. REF: AMM 12-12-01								PKG:5,6,7,8,9 ,10 ,11
05-10-01-200-805	^S	DO A GENERAL VISUAL INSPECTION OF UNCOVERED AREA UNDER FLOOR, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 06-30-01, AMM 06-30-01, AMM 53-60-00PROC. REF: AMM 06-30-01, AMM 06-30-01, AMM 53-60-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-210-801	^S	DO A GENERAL VISUAL INSPECTION OF AREA 100, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 06-20-00, AMM 71-10-00, AMM 71-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 71-10-00, AMM 71-10-00, AMM 06-30-01, AMM 06-30-01							PKG:5,6,7,8,9 ,10 ,11	
05-10-01-210-802	^S	DO A GENERAL VISUAL INSPECTION OF AREA 200, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01							PKG:5,6,7,8,9 ,10 ,11	
05-10-01-210-803	^S	DO A GENERAL VISUAL INSPECTION OF AREA 210, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 06-30-01, AMM 06-30-01							PKG:5,6,7,8,9 ,10 ,11	
05-10-01-210-804	^S	DO A GENERAL VISUAL INSPECTION OF AREA 300, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 55-10-00, AMM 55-20-00, AMM 55-30-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 53-00-00, AMM 06-20-00, AMM 55-10-00, AMM 55-20-00, AMM 55-30-00, AMM 06-30-01, AMM 06-30-01							PKG:5,6,7,8,9 ,10 ,11	
05-10-01-210-805	^S	DO A GENERAL VISUAL INSPECTION OF AREA 500, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01							PKG:5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-210-806	^S	DO A GENERAL VISUAL INSPECTION OF AREA 600, INCLUDING VISIBLE HOSES.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01PROC. REF: AMM 06-20-00, AMM 57-10-00, AMM 06-30-01, AMM 06-30-01								PKG:5,6,7,8,9 ,10 ,11
05-10-01-210-807	^S	DO A GENERAL VISUAL INSPECTION OF AREA 700, INCLUDING VISIBLE HOSES						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 06-20-00, AMM 32-00-00, AMM 32-10-00PROC. REF: AMM 06-20-00, AMM 32-00-00, AMM 32-10-00								PKG:5,6,7,8,9 ,10 ,11
05-10-01-860-801	^S	DISCONNECT THE GROUND POWER UNIT.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-40-00, AMM 24-40-00PROC. REF: AMM 24-40-00, AMM 24-40-00								PKG:5,6,7,8,9 ,10 ,11
05-10-01-860-802	^S	CONNECT A GROUND POWER UNIT AND ENERGIZE						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-40-00, AMM 24-40-00PROC. REF: AMM 24-40-00, AMM 24-40-00								PKG:5,6,7,8,9 ,10 ,11
05-12-01-710-801	^S	START ENGINE WITH GROUND POWER UNIT THEN MAKE GROUND POWER UNIT DISCONNECT - DO A MAINTENANCE RUN-UP. FILL ALL FILES OF MAINTENANCE RUN-UP.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-12-01-710-802	^S	DO A MAINTENANCE RUN-UP - FILL ALL FILES OF MAINTENANCE RUN-UP.						Service ATA:05
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00, AMM 71-00-00, AMM 71-00-00								
05-12-01-715-801		PERFORM MAINTENANCE RUN-UP						Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 05.020	AFL	0						
05-12-02-710-801	^S	PERFORM A POST INSPECTION FLIGHT. FILL ALL FILES OF POST INSPECTION FLIGHT						Service ATA:05
	MOS/MSC	01-Aug-25	A/R					
	HRS	701						
	AFL	483						
							PKG:11,12	
05-12-02-715-802		PERFORM TEST FLIGHT						Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 05.030	AFL	0						
05-50-01-601-801		INSPECTION - CHECK AFTER A HARD LANDING						Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
05-50-02-601-801		INSPECTION - CHECK AFTER FLIGHT IN SEVERE AIR TURBULENCE OR WITH SEVERE MANEUVERS						Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-03-601-801	INSPECTION - CHECK AFTER LIMITATION OVERSHOOTS							Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
05-50-04-601-801	INSPECTION - CHECK AFTER A LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
05-50-05-601-801	INSPECTION - CHECK AFTER PROPELLER TOUCH-DOWN							Service ATA:05
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
ATA 07 - LIFTING AND SHORING								
07-10-00-580-801 ^S	JACK-UP THE AIRCRAFT							Service ATA:07
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 07-10-00PROC. REF: AMM 07-10-00								
07-10-00-580-802 ^S	LOWER THE AIRCRAFT TO GROUND AND REMOVE THE JACKS.							Service ATA:07
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 07-10-00PROC. REF: AMM 07-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 08 - LEVELING AND WEIGHING								
08-10-00-970-801	PERFORM A WEIGHT AND BALANCE							Service ATA:08
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 08.010	AFL	0						
PROC. REF: AMM 08-10-00PROC. REF: AMM 08-10-00								
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-100-801	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED UP TO A MONTH							Service ATA:10
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
10-10-00-100-802	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED FROM 1 TO 6 MONTHS							Service ATA:10
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
10-10-00-100-803	STORING - COMPLY WITH COLUMN OF THE TABLE FOR AIRCRAFT BEING STORED MORE THAN 6 MONTHS							Service ATA:10
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00PROC. REF: AMM 10-10-00, AMM 10-10-00, AMM 10-10-00								
ATA 11 - PLACARDS AND MARKINGS								
11-00-00-701-801	PAINT AIRCRAFT							Service ATA:11
	MOS/MSC	29-Sep-21	-					MANDATORY
	HRS	0						
WC#: 11.010	AFL	0						
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
11-21-00-210-801	^S	PLACARDS AND MARKINGS, AREA 100 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-21-00PROC. REF: AMM 11-21-00								PKG:12
11-22-00-210-801	^S	EXTERIOR PLACARDS AND MARKINGS, AREA 200 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-22-00PROC. REF: AMM 11-22-00								PKG:12
11-22-01-210-801	^S	PLACARDS AND MARKINGS, AREA 210 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
11-23-00-210-801	^S	PLACARDS AND MARKINGS, AREA 300 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-23-00PROC. REF: AMM 11-23-00								PKG:12
11-24-00-210-801	^S	PLACARDS AND MARKINGS, AREA 500 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-24-00PROC. REF: AMM 11-24-00								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
11-24-00-210-802	^S	PLACARDS AND MARKINGS, AREA 600 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-24-00PROC. REF: AMM 11-24-00								PKG:12
ATA 11 - PLACARDS AND MARKINGS								
11-25-00-210-801	^S	PLACARDS AND MARKINGS, AREA 700 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: AMM 11-25-00PROC. REF: AMM 11-25-00								PKG:12
ATA 11 - PLACARDS AND MARKINGS								
11-30-00-210-801	^S	INTERIOR PLACARDS AND MARKINGS, AREA 200 - ENSURE PRESENCE AND READABILITY.						Service ATA:11
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
ATA 12 - SERVICING								
12-21-00-640-801	^S	LUBRICATION OF EXTERNAL ACCESS AND INSPECTION DOORS. LUBRICATE EXTERNAL DOOR HINGES						Service ATA:12
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
WC#: 12.010	AFL	483						
PROC. REF: AMM 12-21-03, AMM 12-21-02, AMM 12-21-02PROC. REF: AMM 12-21-03, AMM 12-21-02, AMM 12-21-02								PKG:8,10 ,11
ATA 12 - SERVICING								
12-21-00-640-802		PROTECTION OF EXTERNAL FITTINGS						Service ATA:12
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 12.020	AFL	0						
PROC. REF: AMM 12-21-04, AMM 12-21-03PROC. REF: AMM 12-21-04, AMM 12-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
12-21-01-640-801	^S	LUBRICATE AREA 100						Service ATA:12
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-01, AMM 12-21-01PROC. REF: AMM 12-21-01, AMM 12-21-01								PKG:5,10 ,11
12-21-02-640-801	^S	LUBRICATION OF AREA 200 - LUBRICATE (REFER 12-21-01-301)						Service ATA:12
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-02, AMM 12-21-02PROC. REF: AMM 12-21-02, AMM 12-21-02								PKG:6,9 ,10 ,11
12-21-03-640-801	^S	LUBRICATION OF AREA 300 - LUBRICATE (REFER 12-21-01-301)						Service ATA:12
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6,9 ,10 ,11
12-21-04-640-802	^S	LUBRICATION OF AREA 500 - LUBRICATE (REFER 12-21-01-301)						Service ATA:12
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:5,6,7,8,9 ,10 ,11
12-21-04-640-803	^S	LUBRICATION OF AREA 600 - LUBRICATE (REFER 12-21-01-301)						Service ATA:12
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
12-21-05-640-801	^S	LUBRICATION OF AREA 700 - LUBRICATE (REFER 12-21-01-301)						Service ATA:12
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								PKG:8,9 ,10 ,11
ATA 21 - AIR CONDITIONING								
21-00-00-200-801	^S	POWER PLANT COMPARTMENT - CHECK CLAMPS FOR CONDITION AND ATTACHMENT ON HOSES AND RIGID PIPES. CHECK FOR DAMAGE. CHECK THE HEAT EXCHANGER, VALVES, SENSORS AND SWITCHES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								PKG:5,11
21-00-00-200-802	^S	PRESSURIZED FUSELAGE SECTION - CHECK VENTILATION HOSES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE. CHECK EVAPORATORS ASSY, SENSORS AND SWITCHES FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								PKG:6,11
21-00-00-200-803	^S	NON PRESSURIZED FUSELAGE SECTION - CHECK CLAMPS FOR CONDITION AND ATTACHMENT ON HOSES AND RIGID PIPES. CHECK FOR DAMAGE. CHECK THE CONDENSER ASSY, SENSOR AND DRIER FILTER FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00								PKG:6,11
21-00-00-710-801	^S	AIR CONDITIONING - DO AN OPERATIONAL TEST						Service ATA:21
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-00-00, AMM 21-00-00PROC. REF: AMM 21-00-00, AMM 21-00-00								
21-00-01-210-801	^S	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR ATTACHMENT						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,11
PROC. REF: AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-01, AMM 21-00-01								
21-00-01-710-801	^S	PL23 PANEL - CHECK DEFOGGING AND TEMPERATURE KNOBS FOR CORRECT MECHANICAL OPERATION						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,11
PROC. REF: AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-01, AMM 21-00-01								
21-20-00-200-802	^S	WINDSHIELD AND SIDE WINDOWS DEFOGGING OUTLETS - CHECK FOR CLOGGING						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,11
PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00, AMM 21-00-01, AMM 21-00-01PROC. REF: AMM 21-00-00, AMM 21-00-00, AMM 21-00-00, AMM 21-00-01, AMM 21-00-01								
21-20-02-710-801	^S	EMERGENCY AIR CONTROL - CHECK CONTROL MECHANICAL OPERATION						Service ATA:21
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,11
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
21-30-00-900-801		PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 1						Component ATA:21
PN:T700A2130025004	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30-00-900-801	PRESSURIZATION OUTFLOW VALVE INLET HOSE NO. 2							Component ATA:21
PN:T700A2130025009	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801	PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 1							Component ATA:21
PN:T700A213002501300	MOS	01-Jan-20	168	TSN 0	01-Oct-34 (M)		3262 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801	PRESSURIZATION OUTFLOW VALVE OUTLET HOSE NO. 2							Component ATA:21
PN:T700A213002501200	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
21-30-00-900-801	PRESSURIZATION SAFETY HOSE							Component ATA:21
PN:T700A2130025006	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC CUSTOMPROC. REF: GENERIC CUSTOM								
21-30-02-100-801	OUTFLOW VALVE - CLEAN VALVE SEATS							Service ATA:21
	MOS	01-Aug-25	24 (+10%/-10%)		01-Aug-27	13-Oct-27	644 d (+73)	
	HRS	701						
WC#: 21.030	AFL	483						
PROC. REF: AMM 21-30-03, AMM 21-30-02PROC. REF: AMM 21-30-03, AMM 21-30-02								
21-30-02-900-801	OUTFLOW VALVE							Component ATA:21
PN:81144A010101	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:81144-00430	HRS	0		TSN 0				
WC#: 21.030	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30-03-100-802		SAFETY VALVE - CLEAN VALVE SEATS						Service ATA:21
	MOS	01-Aug-25	24 (+10%/-10%)		01-Aug-27	13-Oct-27	644 d (+73)	
	HRS	701						
WC#: 21.040	AFL	483						
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
21-30-03-900-801		SAFETY VALVE						Component ATA:21
PN:81145A010101	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:81145-00414	HRS	0		TSN 0				
WC#: 21.040	AFL	0		TSN 0				
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
21-30-03-960-801		SAFETY VALVE - REPLACE THE FILTER						Service ATA:21
	MOS	29-Sep-21						
	HRS	0	2400		2400		1699	
WC#: 21.040	AFL	0						
PROC. REF: AMM 21-30-03, AMM 21-30-03PROC. REF: AMM 21-30-03, AMM 21-30-03								
21-30-05-900-801		CABIN ALT ALARM SWITCH						Component ATA:21
PN:214C40.3.261	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AC04271A	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: AMM 21-30-05, AMM 21-30-05PROC. REF: AMM 21-30-05, AMM 21-30-05								
21-30-08-900-801		CABIN ALT SENSOR						Component ATA:21
PN:CP0304	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:760	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: AMM 21-30-08PROC. REF: AMM 21-30-08								
21-41-01-900-801		NO. 1 LIEBHERR KIT						Component ATA:21
PN:20286-111	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:232	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-41-02-900-801		NO. 2 LIEBHERR KIT					Component	ATA:21
PN:20286-201	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:669	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-50-01-900-801		PRESSURE REGULATING AND SHUT OFF VALVE					Component	ATA:21
PN:6784A010001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:6784-00742	HRS	0		TSN 0				
WC#: 21.260	AFL	0		TSN 0				
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01								
21-50-03-900-801		HEAT EXCHANGER					Component	ATA:21
PN:81249A010001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:81249-00762	HRS	0		TSN 0				
WC#: 21.070	AFL	0		TSN 0				
PROC. REF: AMM 21-50-03, AMM 21-50-03PROC. REF: AMM 21-50-03, AMM 21-50-03								
21-50-71-900-801		CABIN DELTA P WARN SWITCH					Component	ATA:21
PN:17-610-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:B2205	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-52-07-900-803		MT50 CABIN INLET TEMPERATURE SENSOR					Component	ATA:21
PN:93276A020001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SER00875	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
21-55-01-200-801 ^S		COMPRESSOR BELT - CHECK TENSION (REFER TO 21-55-01-601)					Service	ATA:21
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-55-01-200-801 ^S		COMPRESSOR BELT- CHECK CONDITION (REFER TO 21-55-01-601)						Service ATA:21
PN:6046297261	MOS	01-Aug-25	12 (+1m/-1m)					
SN:UNKNOWN	HRS	701	200 (+1/-10)					
	AFL	483						
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01							PKG:5,6,7,8,9 ,10 ,11	
21-55-01-900-801		COMPRESSOR						Component ATA:21
PN:1377A010001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1377-00868	HRS	0		TSN 0				
WC#: 21.170	AFL	0		TSN 0				
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								
21-55-01-900-802		COMPRESSOR BELT - REPLACE						Service ATA:21
PN:6046297261	MOS	01-Aug-25						SCRAP
SN:UNKNOWN	HRS	701	600		1301		600	
	AFL	483						
PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01PROC. REF: AMM 21-55-01, AMM 21-55-01, AMM 21-55-01								
21-55-01-900-803		FREON COMPRESSOR BELT						Component ATA:21
PN:6046297261	MOS/MSC	01-Aug-25	H/T	TSN 0				
SN:UNKNOWN	HRS	701		TSN 0				
WC#: 21.110	AFL	483		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-55-02-900-801		CONDENSER						Component ATA:21
PN:81250A010001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:81250-00769	HRS	0		TSN 0				
WC#: 21.180	AFL	0		TSN 0				
PROC. REF: AMM 21-55-02PROC. REF: AMM 21-55-02								
21-55-16-900-801		COCKPIT EVAPORATOR						Component ATA:21
PN:1714A010001	MOS/MSC	17-Dec-24	O/C	TSN 0				
SN:1027R	HRS	570.1		TSN 0				
WC#: 21.140	AFL			TSN 0				
PROC. REF: AMM 21-55-16PROC. REF: AMM 21-55-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-55-17-900-801	CABIN EVAPORATOR							Component ATA:21
PN:3733A040000	MOS/MSC	17-Dec-24	O/C	TSN 0				
SN:3279R	HRS	570.1		TSN 0				
WC#: 21.140	AFL			TSN 0				
PROC. REF: AMM 21-55-17PROC. REF: AMM 21-55-17								
21-60-31-900-801	GENERAL AIR SYSTEM CONTROLLER							Component ATA:21
PN:82024A040801	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:82024-00769	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
21-60-34-900-802	CABIN INLET OVER-TEMPERATURE SWITCH							Component ATA:21
PN:92244B010002	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:93276-20809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
ATA 22 - AUTO FLIGHT								
22-11-00-200-802 ^S	AUTOPILOT - PERFORM A VISUAL INSPECTION							Service ATA:22
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 22-11-00, AMM 22-11-00, AMM 22-11-00, AMM 22-11-00PROC. REF: AMM 22-11-00, AMM 22-11-00, AMM 22-11-00, AMM 22-11-00								PKG:6,11
22-11-00-200-803 ^S	B35, B36, B37 AND B38 SERVO-ACTUATORS - CHECK CABLES FOR CONDITION.VERIFY THE PULLEYS TO MAKE SURE OF THE ABSENCE OF SETAND OF DETERIORATION (EXCEPT MARKING IN BOTTOM OFTHROAT)							Service ATA:22
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 22.020	AFL	483						
PROC. REF: AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 20-10-04, AMM 20-10-05								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-00-710-801	^S	B35, B36, B37 AND B38 SERVO-ACTUATORS - PERFORM A SLIP CLUTCH MANUAL OVERRIDE.						Service ATA:22
	MOS	01-Aug-25	12					
	HRS	701						
	AFL	483						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								PKG:12
22-11-00-720-803		B35, B36, B37 AND B38 SERVO ACTUATORS - CHECK CLUTCH FRICTION TORQUES.						Service ATA:22
	MOS	29-Sep-21						
	HRS	0	3000 (+10%/-10%)		3000	3300	2299 (+300)	
	AFL	0						
PROC. REF: AMM 22-11-00, AMM 22-11-00PROC. REF: AMM 22-11-00, AMM 22-11-00								
22-11-00-820-801	^S	B35,B36 AND B37 SERVO ACTUATORS - CHECK CABLE TENSION						Service ATA:22
	MOS	01-Aug-25	12					
	HRS	701						
	AFL	483						
PROC. REF: AMM 22-11-03, AMM 22-11-04, AMM 22-11-05PROC. REF: AMM 22-11-03, AMM 22-11-04, AMM 22-11-05								PKG:12
22-11-01-900-801		AUTO PILOT CONTROLLER						Component ATA:22
PN:011-01020-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:22009558	HRS	0		TSN 0				
WC#: 22.190	AFL	0		TSN 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-03-900-801		ROLL SERVO						Component ATA:22
PN:011-00878-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1A1030156	HRS	0		TSN 0				
WC#: 22.110	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03								
22-11-03-900-802		ROLL SERVO MOUNT						Component ATA:22
PN:011-01904-03	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:28K010886	HRS	0		TSN 0				
WC#: 22.170	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03, AMM 22-11-03, AMM 22-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-04-900-801	PITCH SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1A1030181	HRS	0		TSN 0				
WC#: 22.030	AFL	0		TSN 0				
PROC. REF: AMM 22-11-04, AMM 22-11-04, AMM 22-11-04, AMM 22-11-04PROC. REF: AMM 22-11-04, AMM 22-11-04, AMM 22-11-04, AMM 22-11-04								
22-11-05-900-801	YAW SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1A1030227	HRS	0		TSN 0				
WC#: 22.040	AFL	0		TSN 0				
PROC. REF: AMM 22-11-05, AMM 22-11-05PROC. REF: AMM 22-11-05, AMM 22-11-05								
22-11-05-900-802	YAW SERVO MOUNT							Component ATA:22
PN:011-01904-03	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:28K010867	HRS	0		TSN 0				
WC#: 22.160	AFL	0		TSN 0				
PROC. REF: AMM 22-11-05, AMM 22-11-05PROC. REF: AMM 22-11-05, AMM 22-11-05								
22-11-06-900-801	PITCH SERVO MOUNT							Component ATA:22
PN:011-01904-03	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:28K010893	HRS	0		TSN 0				
WC#: 22.150	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-06-900-802	PITCH TRIM SERVO							Component ATA:22
PN:011-00878-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1A1030284	HRS	0		TSN 0				
WC#: 22.100	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-06-900-803	PITCH TRIM SERVO MOUNT							Component ATA:22
PN:011-01904-03	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:28K011007	HRS	0		TSN 0				
WC#: 22.180	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-14-900-801	TRIM ADAPTER							Component ATA:22
PN:011-00960-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1A2001672	HRS	0		TSN 0				
WC#: 22.210	AFL	0		TSN 0				
PROC. REF: AMM 22-11-14, AMM 22-11-14PROC. REF: AMM 22-11-14, AMM 22-11-14								
ATA 23 - COMMUNICATIONS								
23-00-00-710-801	COMMUNICATION EQUIPMENT - DO AN OPERATIONAL TEST.							Service ATA:23
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 23.010	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
23-10-06-900-801	GSR56 UNIT							Component ATA:23
PN:011-02268-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1NZ009938	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-10-21-900-801	NO. 1 VHF COMMUNICATION/NAV AND GPS UNIT							Component ATA:23
PN:011-03711-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:5RT006117	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-10-21-900-801	NO. 2 VHF COMMUNICATION/NAV AND GPS UNIT							Component ATA:23
PN:011-03711-01	MOS/MSC	18-Mar-22	O/C	TSO 0				
SN:5RT006698	HRS	105.2		TSO 0				
WC#: 23.030	AFL			TSO 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-11-01-900-801	NO. 1 AUDIO CONTROL PANEL							Component ATA:23
PN:011-03568-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:4QF105438	HRS	0		TSN 0				
WC#: 22.220	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01, AMM 23-11-01PROC. REF: AMM 23-11-01, AMM 23-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-11-01-900-802		NO. 2 AUDIO CONTROL PANEL					Component	ATA:23
PN:011-03568-20	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:4QF105420	HRS	0		TSN 0				
WC#: 22.220	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01, AMM 23-11-01PROC. REF: AMM 23-11-01, AMM 23-11-01								
23-12-02-900-801		NO. 1 AERIAL BLADE ANTENNA					Component	ATA:23
PN:16-21B-P3	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:51089	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-12-02-900-801		NO. 2 AERIAL BLADE ANTENNA					Component	ATA:23
PN:16-21B-P3	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:51088	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
23-21-02-900-801		IRIDIUM ANTENNA					Component	ATA:23
PN:CI 490-490	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:652268	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-60-00-210-801 ^S		STATIC DISCHARGERS - CHECK FOR CONDITION					Service	ATA:23
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								
23-60-00-760-801 ^S		STATIC DISCHARGERS - CHECK FOR RESISTANCE AND CONTINUITY					Service	ATA:23
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 23-60-00, AMM 23-60-00, AMM 23-60-00PROC. REF: AMM 23-60-00, AMM 23-60-00, AMM 23-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
ATA 24 - ELECTRICAL POWER								
24-00-00-200-801	^S	ELECTRICAL HARNESSSES, AREA 100 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00							PKG:5,11	
24-00-00-200-802	^S	ELECTRICAL HARNESSSES, AREA 200 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00							PKG:6,11	
24-00-00-200-803	^S	ELECTRICAL HARNESSSES, AREA 210 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00							PKG:5,11	
24-00-00-200-804	^S	ELECTRICAL HARNESSSES, AREA 300 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00							PKG:6,11	
24-00-00-200-805	^S	ELECTRICAL HARNESSSES, AREA 500 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00							PKG:7,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-00-00-200-806	^S	ELECTRICAL HARNESSSES, AREA 600 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:7,11
24-00-00-200-807	^S	ELECTRICAL HARNESSSES, AREA 700 - CHECK FOR CONDITION, ROUTING AND ATTACHMENT.						Service ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:8,11
24-00-00-200-808	^S	POWER PLANT / FIREWALL GROUND CABLE - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-00-00, AMM 24-00-00PROC. REF: AMM 24-00-00, AMM 24-00-00								PKG:5,11
24-30-02-200-802	^S	ELECTRICAL POWER SYSTEM - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE OR LOOSE CONNECTIONS						Service ATA:24
	MOS	01-Aug-25	24 (+1d/-1d)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-30-02, AMM 24-30-02PROC. REF: AMM 24-30-02, AMM 24-30-02								PKG:5,10 ,11
24-30-02-900-804		ELECTRICAL POWER SYSTEM BOX						Component ATA:24
PN:1408-1-1	MOS/MSC	29-Sep-21	O/C		TSN 0			
SN:409	HRS	0			TSN 0			
	AFL	0			TSN 0			
PROC. REF: AMM 24-30-02, AMM 24-30-02PROC. REF: AMM 24-30-02, AMM 24-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-03-200-803	^S	STARTER GENERATOR - CHECK FOR ATTACHMENT, CLEANLINESS OF CONNECTION TERMINAL BLOCK AND ELECTRICAL CONNECTIONS AND EVIDENCE OF OVERHEAT, ARCING AND DAMAGE. CHECK COVER FOR CONDITION. ENSURE GOOD CONDITION OF CLAMP AND SECTOR. CHECK FOR CRACKS. CHECK R701 SHUNT FOR CONDITION.						Service ATA:24
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								PKG:5,10 ,11
24-30-03-200-804	^S	STARTER GENERATOR DRIVE PAD - CHECK DRAIN LINE FOR CONDITION AND CHECK FOR LEAKS AT MOUNTING INTERFACE.						Service ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								PKG:5,11
24-30-03-730-803		STARTER/GENERATOR - OVERHAUL						Component ATA:24
PN:MG94K-1	MOS	26-Jun-24		TSN 33, TSR 0				OVERHAUL
SN:0434	HRS	523.2	1200 (+10%/-10%)	TSN 523.2, TSR 0	1200	1320	499 (+120)	
WC#: 24.030	AFL			TSR 0				
PROC. REF: AMM 24-30-03, AMM 24-30-03PROC. REF: AMM 24-30-03, AMM 24-30-03								
24-30-04-200-801	^S	BATTERY CABLES - CHECK CABLES AND CONNECTORS FOR CORROSION AND EVIDENCE OF DAMAGE. CHECK FOR CLEANLINESS, EVIDENCE OF CORROSION AND CRACKS ON FIREWALL ATTACHMENTS. CHECK CONNECTIONS AND F100 FUSE FOR CONDITION						Service ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04								PKG:5,11
24-30-04-760-802		LEAD-ACID BATTERY IF INSTALLED - CHECK CAPACITY						Service ATA:24
PN:RG-380E/44	MOS	01-Aug-25	12 (+1m/-1m)		01-Aug-26	01-Sep-26	279 d (+31)	
SN:70035209	HRS	701	200 (+10%/-10%)		901	921	200 (+20)	
WC#: 24.010	AFL	483						
PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04, AMM 24-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-04-900-801	MAIN BATTERY							Component ATA:24
PN:RG-380E/44	MOS/MSC	01-Aug-25	O/C					
SN:70035209	HRS	701						
WC#: 24.010	AFL	483						
PROC. REF: AMM 24-30-04, AMM 24-30-04PROC. REF: AMM 24-30-04, AMM 24-30-04								
24-30-05-200-802 ^S	STAND-BY GENERATOR BELT - CHECK FOR CONDITION							Service ATA:24
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PKG:1,5,7,9 ,10 ,11								
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-05								
24-30-05-200-803 ^S	STAND-BY GENERATOR - CHECK FOR CONDITION AND CONNECTIONS-INSPECT AREA AROUND THE BRUSH HOLDER FOR SOOT.							Service ATA:24
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PKG:5,6,7,8,9 ,10 ,11								
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
24-30-05-220-801 ^S	STAND-BY GENERATOR BELT - CHECK TENSION (REFER TO 24-30-05-601)							Service ATA:24
	MOS	01-Aug-25	12					
	HRS	701	200 (+10%/-10%)					
	AFL	483						
PKG:1,5,7,9 ,10 ,11								
PROC. REF: AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05								
24-30-05-730-802	ALTERNATOR - OVERHAUL							Component ATA:24
PN:ES-10024B-5	MOS/MSC	19-Jun-23	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED
SN:H-X020469	HRS	346.7		TSN 0				
WC#: 24.020	AFL	166		TSN 0				
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-06, AMM 24-30-06, AMM 24-30-06PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05, AMM 24-30-06, AMM 24-30-06, AMM 24-30-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-05-730-803	ALTERNATOR - OVERHAUL							Service ATA:24
	MOS	29-Sep-21						OVERHAUL
	HRS	0	2000 (+10%/-10%)		2000	2200	1299 (+200)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-30-05-900-801	STANDBY GENERATOR BELT - REPLACE							Service ATA:24
PN:7133280007	MOS	01-Aug-25						LIFE LIMIT
SN:UNKNOWN	HRS	701	600		1301		600	
	AFL	483						
PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05PROC. REF: AMM 24-30-05, AMM 24-30-05, AMM 24-30-05								
24-30-05-900-803	STANDBY GENERATOR BELT							Component ATA:24
PN:7133280007	MOS/MSC	01-Aug-25	H/T	TSN 0				
SN:UNKNOWN	HRS	701		TSN 0				
	AFL	483		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-30-06-200-802 ^S	STANDBY BY GENERATOR DRIVE - CHECK DRAIN LINES FOR ATTACHMENT AND CONDITION, CHECK FOR LEAKS AT MOUNTING INTERFACE AND MANUALLY CHECK THAT THE SHEAR SHAFT OR THE PULLEY ARE NOT DAMAGED BY MANUALLY ROTATING THE STAND-BY GENERATOR DRIVE PULLEY.							Service ATA:24
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-30-06PROC. REF: AMM 24-30-06								PKG:5,10 ,11
24-40-00-200-802 ^S	EXTERNAL POWER SUPPLY - CHECK GPU RECEPTACLE FOR ATTACHMENT AND EVIDENCE OF DAMAGE AND CHECK CABLES FOR CONDITION AND CONNECTIONS							Service ATA:24
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-40-00PROC. REF: AMM 24-40-00								PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-60-01-210-801	^S	PL1 CIRCUIT BREAKER PANEL - CHECK PANEL FOR ATTACHMENT AND CLEANLINESS AND ELECTRICAL COMPONENTS FOR CONDITION.					Service	ATA:24
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								PKG:6,11
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-00-210-803	^S	SUN VISOR - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-11-00, AMM 25-11-00PROC. REF: AMM 25-11-00, AMM 25-11-00								PKG:6,11
25-12-00-210-801	^S	COCKPIT SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION					Service	ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:5,6,7,8,9 ,10 ,11
25-12-00-210-802	^S	COCKPIT BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS.					Service	ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:1,5,6,7,8,9 ,10 ,11
25-12-00-710-803	^S	COCKPIT BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION.					Service	ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-12-00PROC. REF: AMM 25-12-00								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-12-01-900-801	PILOT SEAT							Component ATA:25
PN:SOC421000-501	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:848	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-12-01PROC. REF: AMM 25-12-01								
25-12-02-900-801	COPILOT SEAT							Component ATA:25
PN:SOC421000-502	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:848	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-12-02, AMM 25-12-01PROC. REF: AMM 25-12-02, AMM 25-12-01								
25-12-04-900-801	SIEGES CHAUFFANTS HEATED SEATS CONTROL							Component ATA:25
PN:A86-18-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:210602	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-21-00-210-801 ^S	STORAGE CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION.							Service ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-802 ^S	FOLDING TABLE, IF INSTALLED - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.							Service ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								PKG:6,11
25-21-00-210-803 ^S	AUDIO CABINET, IF INSTALLED - CHECK ELECTRICAL COMPONENTS FOR ATTACHMENT AND CONDITION.							Service ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								
25-21-00-210-804	^S	REFRESHMENT CABINET, IF INSTALLED - CHECK ATTACHMENT AND CONDITION.					Service	ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:6,11
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								
25-21-00-210-805	^S	UPHOLSTERING PANELS - CHECK ATTACHMENT AND CONDITION.					Service	ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:6,11
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								
25-21-00-210-806	^S	CABIN WINDOW CURTAINS - CHECK CONDITION AND OPERATION.					Service	ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:6,11
PROC. REF: AMM 25-21-00PROC. REF: AMM 25-21-00								
25-21-05-710-801	^S	TOILETS, REAR BAGGAGE COMPARTMENT, IF INSTALLED - DO AN OPERATIONAL TEST.					Service	ATA:25
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
								PKG:6,10 ,11
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
25-22-00-210-801	^S	PASSENGERS SEATS - CHECK SEAT STRUCTURE FOR CONDITION AND ATTACHMENTS. CHECK CORRECT OPERATION OF CONTROLS. CHECK CUSHIONS FOR CLEANLINESS AND CONDITION. CHECK THAT PASSENGERS SEATS ARE INSTALLED IN CORRECT PAINT MARKS LOCATIONS.					Service	ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-22-00-210-802 ^S		PASSENGERS BELTS - CHECK FOR ATTACHMENT, EVIDENCE OF DAMAGE AND / OR FRAYS.						Service ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00							PKG:1,5,6,7,8,9 ,10 ,11	
25-22-00-710-803 ^S		PASSENGERS BELT REELS - CHECK FOR EVIDENCE OF DAMAGE AND / OR FRAYS. CHECK OPERATION.						Service ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-22-00PROC. REF: AMM 25-22-00							PKG:5,6,7,8,9 ,10 ,11	
25-22-01-900-801		LEFT PASSENGER SEAT						Component ATA:25
PN:SOC424000-501	MOS/MSC	14-Feb-25	O/C	TSN 41				
SN:848	HRS	597.8		TSN 597.8				
WC#: 25.050	AFL							
PROC. REF: AMM 25-22-01, AMM 25-22-01PROC. REF: AMM 25-22-01, AMM 25-22-01								
25-22-01-900-801		RIGHT PASSENGER SEAT						Component ATA:25
PN:SOC424000-502	MOS/MSC	14-Feb-25	O/C	TSN 41				
SN:848	HRS	597.8		TSN 597.8				
WC#: 25.050	AFL							
PROC. REF: AMM 25-22-01, AMM 25-22-01PROC. REF: AMM 25-22-01, AMM 25-22-01								
25-22-02-900-802		LEFT REAR BENCH						Component ATA:25
PN:SOC422000-505	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:848	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
PROC. REF: AMM 25-22-02PROC. REF: AMM 25-22-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-22-02-900-802	RIGHT REAR BENCH							Component ATA:25
PN:SOC422000-506	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:848	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
PROC. REF: AMM 25-22-02PROC. REF: AMM 25-22-02								
25-50-00-610-801 ^S	FUSE AND BULB BOX - COMPLETE IF NECESSARY.							Service ATA:25
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
25-61-00-200-801 ^S	EMERGENCY LOCATOR TRANSMITTER - CHECK FOR ATTACHMENT AND POSITION OF FUNCTION SWITCH. MAKE SURE THERE ARE NO LEAKS AND NO CORROSION AT BATTERY. CHECK ANTENNA FOR ATTACHMENT AND CONNECTION.							Service ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 25-61-00, AMM 25-61-00PROC. REF: AMM 25-61-00, AMM 25-61-00								
25-61-00-200-804 ^S	EMERGENCY LOCATOR TRANSMITTER - CHECK BATTERY REPLACEMENT DATE							Service ATA:25
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-61-00-710-806	EMERGENCY LOCATOR TRANSMITTER - DO AN OPERATIONAL TEST AND RECORD OPERATING TIME							Service ATA:25
PN:A3-06-2749-1	MOS	01-Aug-25	12 (+1m/-1m)		01-Aug-26	01-Sep-26	279 d (+31)	
SN:323-01843	HRS	701						
WC#: 25.020	AFL	483						
PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-01, AMM 25-61-00, AMM 25-61-00PROC. REF: AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-00, AMM 25-61-01, AMM 25-61-00, AMM 25-61-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-00-900-803		EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE					Service	ATA:25
PN:452-6504-1	MOS/MSC	01-Aug-25	DUE		01-Sep-27 (M)		675 d	LIFE LIMIT
SN:390789-019	HRS	701						
WC#: 25.030	AFL	483						
Expiry Date: : 01-Sep-27								
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01								
25-61-01-900-811		EMERGENCY LOCATOR TRANSMITTER					Component	ATA:25
PN:A3-06-2749-1	MOS/MSC	01-Aug-25	O/C	TSN 47				
SN:323-01843	HRS	701		TSN 701				
WC#: 25.020	AFL	483		TSN 483				
PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01								
25-61-01-900-821		EMERGENCY LOCATOR TRANSMITTER BATTERY					Component	ATA:25
PN:452-6504-1	MOS/MSC	01-Aug-25	O/C					
SN:390789-019	HRS	701						
	AFL	483						
PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01, AMM 25-61-01								
25-61-02-900-801		EMERGENCY LOCATOR TRANSMITTER ANTENNA					Component	ATA:25
PN:110-338	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:650716	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-10-00-200-801	^S	FIRE DETECTION, IF INSTALLED - CHECK DETECTORS AND WIRINGS FOR CONDITION AND ATTACHMENT.						Service ATA:26
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							PKG:5,6,7,8,9 ,10 ,11	
26-20-01-200-802		AIR TOTAL FIRE EXTINGUISHER, IF INSTALLED - CHECK FOR WEIGHT AND PRESSURE						Service ATA:26
PN:74-00	MOS	01-Aug-25	24 (+10%/-10%)		01-Aug-27	13-Oct-27	644 d (+73)	
SN:A033517	HRS	701						
	AFL	483						
			WeightCheck Date : : 01-Aug-25					
PROC. REF: AMM 26-20-01PROC. REF: AMM 26-20-01								
26-20-01-730-801		AIR-TOTAL FIRE EXTINGUISHER PORTABLE - OVERHAUL						Service ATA:26
PN:74-00	MOS	01-Dec-20	120 (+10%/-10%)		01-Dec-30	01-Dec-31	1862 d (+365)	OVERHAUL
SN:A033517	HRS							
	AFL							
			Manufacture Date:: 01-Dec-20					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20-01-900-803		AIR-TOTAL FIRE EXTINGUISHER PORTABLE						Component ATA:26
PN:74-00	MOS/MSC	29-Sep-21	H/T	TSN 0				
SN:A033517	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-20-01PROC. REF: AMM 26-20-01								
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-801	^S	AILERON TRIM TAB ACTUATOR RODS - VISUALLY CHECK THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00							PKG:7,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-802	^S	AILERON CONTROL INBOARD AND OUTBOARD L.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00							PKG:7,10 ,11	
27-10-00-200-803	^S	AILERON CONTROL INBOARD AND OUTBOARD R.H. BEARINGS - CHECK CONDITION OF BONDING STRAPS.					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00							PKG:7,10 ,11	
27-10-00-200-804	^S	L.H. AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00							PKG:7,11	
27-10-00-200-805	^S	R.H. AILERON ROD - CHECK CORRECT SAFETYING OF ROD ATTACHMENTS AND STOP SCREWS.					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00							PKG:7,11	
27-10-00-200-806	^S	L.H. AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING.					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00							PKG:7,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-807	^S	R.H. AILERON RODS AND BELLCRANKS - CHECK HINGES FOR EVIDENCE OF DAMAGE, SLACK AND CORRECT SAFETYING.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11
27-10-00-200-808	^S	SPOILER CABLE ASSEMBLY IN FUSELAGE - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:6,11
27-10-00-200-809	^S	SPOILER AND AILERON CABLE ASSEMBLY ON L.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:7,11
27-10-00-200-810	^S	SPOILER AND AILERON CABLE ASSEMBLY ON R.H.WING - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-10-00, AMM 20-10-04, AMM 20-10-05								PKG:7,11
27-10-00-200-811	^S	AILERON CONTROL INBOARD AND OUTBOARD L.H. BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-200-812	^S	AILERON CONTROL INBOARD AND OUTBOARD R.H. BEARINGS - VISUALLY EXAMINE BEARINGS, ROD AND FINGERS FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11
27-10-00-200-813	^S	L.H. WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11
27-10-00-200-814	^S	R.H. WING AILERON LEVER - VISUALLY EXAMINE CONDITION, ATTACHMENT AND SAFETYING.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,11
27-10-00-720-801	^S	AILERON TRIM TAB - CHECK TRAVEL						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.030	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:8,11
27-10-00-720-802	^S	AILERONS AND SPOILERS - CHECK TRAVEL						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.010	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-00-720-803	^S	CONTROL WHEEL ASSEMBLY - CHECK FOR SLACK AND FRICTION POINTS IN AILERON CONTROL.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:6,11
27-10-00-820-801	^S	SPOILER AND AILERON CABLE ASSEMBLY ON WING - CHECK CABLE TENSION AND SAFETYING OF TURNBUCKLES						Service ATA:27
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 27.020	AFL	483						
PROC. REF: AMM 27-10-00, AMM 27-10-00PROC. REF: AMM 27-10-00, AMM 27-10-00								PKG:12
27-10-02-210-801	^S	L.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK.						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:7,10 ,11
27-10-02-210-802	^S	R.H. SPOILER CONTROL - VISUALLY EXAMINE ATTACHMENT FITTINGS AND ACTUATING ROD FOR CONDITION, EVIDENCE OF DAMAGE OR SLACK.						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:7,10 ,11
27-10-02-210-803	^S	L.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION.						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								PKG:7,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10-02-210-804	^S	R.H. SPOILER CONTROL - CHECK BONDING STRAPS FOR CONDITION.						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								PKG:7,10 ,11
27-10-04-900-801		LEFT AILERON TRIM TAB ACTUATOR						Component ATA:27
PN:145700-02	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:F47205	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								
27-20-00-200-801	^S	RUDDER LEVER AND ROD ASSEMBLY - CHECK ATTACHMENT, CONDITION OF LEVER BALL JOINT AND SAFETYING OF ROD HINGES. CHECK THAT THE TWO STOP SCREWS CANNOT BE SCREWED OR UNSCREWED MANUALLY.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:6,11
27-20-00-200-802	^S	RUDDER CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR SLACK OR EVIDENCE OF DAMAGE (EXCEPT MARKINGS AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 20-10-04, AMM 20-10-05, AMM 27-20-00PROC. REF: AMM 20-10-04, AMM 20-10-05, AMM 27-20-00								PKG:6,11
27-20-00-720-801	^S	RUDDER TRIM TAB - CHECK TRAVEL						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.060	AFL	483						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20-00-720-802	^S	RUDDER - CHECK TRAVEL						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.040	AFL	483						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:8,11
27-20-00-820-801	^S	RUDDER CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES						Service ATA:27
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 27.050	AFL	483						
PROC. REF: AMM 27-20-00, AMM 27-20-00PROC. REF: AMM 27-20-00, AMM 27-20-00								PKG:12
27-20-01-710-801	^S	RUDDER PEDALS - CHECK FREE MOVEMENT OF RUDDER PEDALS AND CORRECT OPERATION OF RUDDER PEDAL POSITION ADJUSTING CONTROLS FOR THE PILOT AND RIGHT STATIONS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:5,6,7,8,11
27-20-04-200-801	^S	RUDDER TRIM TAB ACTUATOR - VISUALLY CHECK FOR CONDITION AND ATTACHMENT. VISUALLY ENSURE THAT THERE IS NO SLACK AT RODS. CHECK CORRECT SAFETYING OF ROD NUTS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:6,11
27-20-04-900-801		B32 RUDDER TRIM TAB ACTUATOR						Component ATA:27
PN:145700-02	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:F47210	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: AMM 27-20-04PROC. REF: AMM 27-20-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30-00-200-801	^S	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK FOR CONDITION, ATTACHMENT AND BALL JOINTS ON BELLCRANKS AND LEVERS. CHECK THAT STOP SCREWS ON HINGE BEARING CANNOT BE SCREWED OR UNSCREWED MANUALLY. CHECK SAFETYING OF ROD HINGES.					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:6,11
27-30-00-200-802	^S	ELEVATOR RODS, BELLCRANKS AND LEVERS - CHECK CONDITION AND ATTACHMENT OF ROD, SLEEVE AND FOR CRACKS ON PRESSURE BULKHEAD C17.					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:6,10 ,11
27-30-00-710-801	^S	ELEVATOR TRIM TABS EMERGENCY MANUAL CONTROL - TURN TRIM WHEEL AND CHECK FREE MOVEMENT AND OPERATION OF INDICATOR.					Service	ATA:27
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:1,5,6,7,8,9 ,10 ,11
27-30-00-720-801	^S	ELEVATORS - CHECK TRAVEL					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.070	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:8,11
27-30-00-720-802	^S	ELEVATOR TRIM TABS - CHECK TRAVEL					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.080	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:8,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30-00-820-801 ^S	ELEVATOR TRIM TAB CONTROL CABLES - CHECK TENSION OF CABLES AND SAFETYING OF TURNBUCKLES							Service ATA:27
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 27.080	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								PKG:12
27-30-01-900-801	PILOT CONTROL WHEEL							Component ATA:27
PN:83912112	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:362	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01, AMM 27-30-01PROC. REF: AMM 27-30-01, AMM 27-30-01								
27-30-01-900-802	COPILOT CONTROL WHEEL							Component ATA:27
PN:83912113	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:359	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01, AMM 27-30-01PROC. REF: AMM 27-30-01, AMM 27-30-01								
27-30-02-900-801	STICK SHAKER							Component ATA:27
PN:C-101702-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:187448-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-30-03-200-801 ^S	ELEVATOR TRIM TAB CONTROL CABLES - EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.							Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30-03-200-802	^S	ELEVATOR TRIM TAB CONTROL CABLES - CHECK CONDITION OF SCREW JACK CHAINS. CHECK ATTACHMENT AND SAFETYING OF LINKS THAT CONNECT CABLES TO CHAINS. EXAMINE CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND EVIDENCE OF DAMAGE. CHECK FREE ROTATION OF PULLEYS.						Service ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:6,11
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 20-10-04, AMM 20-10-05								
27-30-04-200-801	^S	ELEVATOR TRIM TAB ACTUATORS - CHECK RODS FOR CONDITION AND NO SLACK. VISUALLY CHECK ATTACHMENTS ON REAR SPAR OF FIXED HORIZONTAL STABILIZER.						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
								PKG:6,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00PROC. REF: AMM 27-30-00, AMM 27-30-00								
27-30-04-900-801		LEFT ELEVATOR TRIM TAB ACTUATOR						Component ATA:27
PN:145400-02	MOS/MSC	29-Sep-21	O/C		TSN 0			
SN:F46701	HRS	0			TSN 0			
WC#: 27.130	AFL	0			TSN 0			
PROC. REF: AMM 27-30-04, AMM 27-30-04PROC. REF: AMM 27-30-04, AMM 27-30-04								
27-30-04-900-801		RIGHT ELEVATOR TRIM TAB ACTUATOR						Component ATA:27
PN:145400-02	MOS/MSC	29-Sep-21	O/C		TSN 0			
SN:F46818	HRS	0			TSN 0			
WC#: 27.130	AFL	0			TSN 0			
PROC. REF: AMM 27-30-04, AMM 27-30-04PROC. REF: AMM 27-30-04, AMM 27-30-04								
27-50-00-200-801	^S	FLAP CONTROL, L.H. BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS						Service ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
								PKG:7,10 ,11
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-00-200-802	^S	FLAP CONTROL, R.H. BULGED SLEEVE - CHECK CONDITION OF BULGED SLEEVE BETWEEN FUSELAGE AND INBOARD SCREW JACKS					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-200-803	^S	GEARED MOTOR - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:6,11	
27-50-00-200-804	^S	FLAP CONTROLS, INBOARD AND OUTBOARD L.H. ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-200-805	^S	FLAP CONTROLS, INBOARD AND OUTBOARD R.H. ACTUATORS - CHECK FOR ATTACHMENT AND EVIDENCE OF DAMAGE.					Service	ATA:27
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:7,10 ,11	
27-50-00-720-801	^S	FLAPS - CHECK TRAVELS					Service	ATA:27
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
WC#: 27.090	AFL	483						
PROC. REF: AMM 27-50-00, AMM 27-50-00PROC. REF: AMM 27-50-00, AMM 27-50-00							PKG:8,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-01-900-801		FLAP MOTOR					Component	ATA:27
PN:6157-1	MOS/MSC	10-Sep-24	O/C	TSR 0				
SN:755	HRS	546.7		TSR 0				
WC#: 27.100	AFL			TSR 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-50-02-900-801		LEFT INNER FLAP ACTUATOR					Component	ATA:27
PN:1-5295	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1552	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-50-02-900-802		RIGHT INNER FLAP ACTUATOR					Component	ATA:27
PN:2-5295	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1602	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-02-900-803		LEFT OUTER FLAP ACTUATOR					Component	ATA:27
PN:1-5297	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1605	HRS	0		TSN 0				
WC#: 27.150	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-02-900-804		RIGHT OUTER FLAP ACTUATOR					Component	ATA:27
PN:2-5297	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1613	HRS	0		TSN 0				
WC#: 27.150	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
27-50-03-900-801		LEFT WING CENTER CONTROL LINKAGE BEARING					Component	ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1460	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-03-900-801	LEFT WING INBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:7459	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	LEFT WING OUTBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:7458	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING CENTER CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:7455	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING INBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:7456	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
27-50-03-900-801	RIGHT WING OUTBOARD CONTROL LINKAGE BEARING							Component ATA:27
PN:5591	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:7457	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 28 - FUEL								
28-10-00-200-801 ^S	FILLER CAP AND LINES, L.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION.							Service ATA:28
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						

PKG:7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-802	^S	FILLER CAP AND LINES, R.H. TANK - CHECK FOR CONDITION, ATTACHMENT AND LEAKS AT LINES. CHECK CAP O-RING FOR CONDITION.						Service ATA:28
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:7,11
28-10-00-200-803		FLAPPER VALVES - CHECK RUBBER CONDITION						Service ATA:28
	MOS	01-Aug-25	48 (+10%/-10%)		01-Aug-29	25-Dec-29	1375 d (+146)	
	HRS	701	1500 (+10%/-10%)		2201	2351	1500 (+150)	
WC#: 28.030	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								
28-10-00-200-804	^S	L.H. VENT VALVES - CHECK FOR CLEANLINESS.						Service ATA:28
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:7,10 ,11
28-10-00-200-805	^S	R.H. VENT VALVES - CHECK FOR CLEANLINESS.						Service ATA:28
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:7,10 ,11
28-10-00-200-806	^S	L.H. FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS.						Service ATA:28
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:1,6,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-10-00-200-807	^S	R.H. FUEL TANK - EXAMINE EXTERNAL AREA AND ACCESS DOORS FOR LEAKS.						Service ATA:28
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00PROC. REF: AMM 28-10-00								PKG:1,6,9 ,10 ,11
28-10-06-200-801		STRAINERS - CHECK FOR CLEANLINESS AND CONDITION						Service ATA:28
	MOS	01-Aug-25	48 (+10%/-10%)		01-Aug-29	25-Dec-29	1375 d (+146)	
	HRS	701	1500 (+10%/-10%)		2201	2351	1500 (+150)	
WC#: 28.030	AFL	483						
PROC. REF: AMM 28-10-06, AMM 28-10-06, AMM 28-10-06, AMM 28-10-06PROC. REF: AMM 28-10-06, AMM 28-10-06, AMM 28-10-06, AMM 28-10-06								
28-20-00-200-801	^S	DISTRIBUTION SYSTEM - CHECK.						Service ATA:28
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-20-00, AMM 28-20-00PROC. REF: AMM 28-20-00, AMM 28-20-00								PKG:5,6,11
28-20-01-900-801		FUEL UNIT - REPLACE FILTER ELEMENT						Service ATA:28
PN:L88A15-651	MOS	01-Aug-25						LIFE LIMIT
SN:K61001	HRS	701	600		1301		600	
WC#: 28.020	AFL	483						
PROC. REF: AMM 28-20-01, AMM 28-20-01PROC. REF: AMM 28-20-01, AMM 28-20-01								
28-20-01-900-802		FUEL UNIT						Component ATA:28
PN:L88A15-651	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:K61001	HRS	0		TSN 0				
WC#: 28.020	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01, AMM 28-20-01PROC. REF: AMM 28-20-01, AMM 28-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20-03-710-801	^S	FUEL SEQUENCER - DO A GROUND OPERATIONAL TEST.						Service ATA:28
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 28-20-00, AMM 28-20-00PROC. REF: AMM 28-20-00, AMM 28-20-00								
28-20-03-900-801		FUEL SEQUENCER						Component ATA:28
PN:SE9203.A.01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1181	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
28-20-04-730-801		MECHANICAL PUMP - OVERHAUL						Component ATA:28
PN:1127-02	MOS	29-Sep-21	120 (+10%/-10%)	TSN 0	29-Sep-31	29-Sep-32	2164 d (+366)	OVERHAUL
SN:1249	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	2799 (+350)	
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04, AMM 28-20-04, AMM 28-20-04, AMM 28-20-04PROC. REF: AMM 28-20-04, AMM 28-20-04, AMM 28-20-04, AMM 28-20-04								
28-20-05-730-801		ELECTRIC PUMP - OVERHAUL						Service ATA:28
PN:2022-B	MOS	29-Sep-21						
SN:225788	HRS	0	6000 (+10%/-10%)		6000	6600	5299 (+600)	
WC#: 28.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-20-05-900-801		ELECTRIC FUEL BOOST PUMP						Component ATA:28
PN:2022-B	MOS/MSC	29-Sep-21	H/T	TSN 0				
SN:225788	HRS	0		TSN 0				
WC#: 28.010	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
28-40-00-710-801	^S	LOW LEVEL SENSORS - DO A LOW LEVEL TEST						Service ATA:28
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
WC#: 28.030	AFL	483						
							PKG:10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-00, AMM 28-40-00PROC. REF: AMM 28-40-00, AMM 28-40-00								
28-40-01-900-801 LEFT INNER MT21 PROBE								Component ATA:28
PN:762438-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1065	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-801 RIGHT INNER MT22 PROBE								Component ATA:28
PN:762439-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1059	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-802 LEFT MEDIAN GAGE								Component ATA:28
PN:762440-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1822	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-802 RIGHT MEDIAN GAGE								Component ATA:28
PN:762440-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1830	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-803 LEFT OUTER MT25 PROBE								Component ATA:28
PN:762441-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1746	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-01-900-803 RIGHT OUTER MT26 PROBE								Component ATA:28
PN:762441-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1750	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
28-40-02-900-801	LEFT WING MT27 LOW LEVEL SENSOR							Component ATA:28
PN:747971-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1203	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
28-40-02-900-801	RIGHT WING MT28 LOW LEVEL SENSOR							Component ATA:28
PN:747971-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1204	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
28-40-05-900-801	FUEL AMPLIFIER							Component ATA:28
PN:73574-1-0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:738574IN00790	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05, AMM 28-40-05PROC. REF: AMM 28-40-05, AMM 28-40-05								
ATA 30 - ICE AND RAIN PROTECTION								
30-00-01-710-801	ICE DETECTION SYSTEM - DO OPERATIONAL TEST							Service ATA:30
	MOS	29-Sep-21						
	HRS	0	800 (+10%/-10%)		800	880	99 (+80)	
	AFL	0						
PROC. REF: AMM 30-00-01PROC. REF: AMM 30-00-01								
30-00-01-900-801	A13 CONTROL AUTO DE-ICING							Component ATA:30
PN:CAIB-20-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:210402	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10-00-101	AIRFOIL DE ICING TROUBLESHOOTING							Service ATA:30
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-10-00, AMM 30-10-00PROC. REF: AMM 30-10-00, AMM 30-10-00								
30-10-00-210-801 ^S	PNEUMATIC DE-ICERS - CHECK FOR ATTACHMENT AND EVIDENCE OF ABRASION, CUTS OR NICKS.							Service ATA:30
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								PKG:1,5,6,7,8,9 ,10 ,11
30-10-00-870-801 ^S	DEICING SYSTEM - DEICING SYSTEM DRAINING							Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								PKG:7,11
30-10-03-200-801 ^S	A43 PNEUMATIC DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								PKG:6,11
30-10-03-900-801	TIMER							Component ATA:30
PN:42E25-2A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:U1741	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10-04-200-801 ^S	WATER SEPARATOR FILTER - CHECK FOR CONDITION AND ATTACHMENT							Service ATA:30
PN:44E21-2A	MOS	01-Aug-25	12					
SN:N210563	HRS	701						
WC#: 30.010	AFL	483						
PROC. REF: AMM 30-10-04, AMM 30-10-04PROC. REF: AMM 30-10-04, AMM 30-10-04								PKG:12
30-10-04-900-801	AIRFOIL DE-ICE WATER SEPARATOR							Component ATA:30
PN:44E21-2A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N210563	HRS	0		TSN 0				
WC#: 30.010	AFL	0		TSN 0				
PROC. REF: AMM 30-10-04PROC. REF: AMM 30-10-04								
30-10-05-200-801 ^S	L21 DE-ICING VALVE - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								PKG:5,11
30-30-00-710-801 ^S	HEATING OF PITOT TUBES AND STALL WARNING INDICATOR - DO AN OPERATIONAL TEST.							Service ATA:30
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-30-00, AMM 30-30-00, AMM 30-30-00PROC. REF: AMM 30-30-00, AMM 30-30-00, AMM 30-30-00								PKG:5,6,7,8,9 ,10 ,11
30-40-00-200-803 ^S	A41/A42 LH/RH WINDSHIELDS DE-ICING CONTROLLERS - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-40-00, AMM 30-40-00PROC. REF: AMM 30-40-00, AMM 30-40-00								PKG:5,6,7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-40-00-710-802 ^S	A41/A42 LH/RH WINDSHIELD DE-ICING CONTROLLERS - DO AN OPERATIONAL TEST							Service ATA:30
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00							PKG:5,6,7,8,9 ,10 ,11	
30-40-00-720-803 ^S	A41/A42 LH/RH WINDSHIELD DE-ICING CONTROLLERS - DO A FUNCTIONAL TEST OF THE SYSTEM							Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00							PKG:5,6,7,8,11	
30-40-00-900-801	LEFT WINDSHIELD DEICING UNIT							Component ATA:30
PN:TWH93-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2084	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								
30-40-00-900-802	RIGHT WINDSHIELD DEICING UNIT							Component ATA:30
PN:TWH93-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2080	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								
30-60-00-200-801 ^S	PROPELLER DE-ICING SYSTEM - PERFORM INSPECTION OF THE PROPELLER DE-ICING SYSTEM (REFER TO 30-60-00-601)							Service ATA:30
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM							PKG:5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-60-00-710-801	^S	PROPELLER DE-ICING SYSTEM - PERFORM A GROUND OPERATIONAL TEST						Service ATA:30
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-60-00, AMM 30-60-01PROC. REF: AMM 30-60-00, AMM 30-60-01								PKG:5,6,7,8,9 ,10 ,11
30-60-00-760-801		PERFORM A DE-ICE CIRCUIT RESISTANCE CHECK (REFER TO HARTZELL CMM 180)						Service ATA:30
	MOS	01-Aug-25	12 (+1m)	Adj -64d	29-May-26	29-Jun-26	215 d (+31)	
	HRS	701						
	AFL	483						
PROC. REF: MM 30-61-80, MM 30-61-80, MM 30-61-80, MM 30-61-80, GENERIC NO REF, CMM 30-61-80PROC. REF: MM 30-61-80, MM 30-61-80, MM 30-61-80, MM 30-61-80, GENERIC NO REF, CMM 30-61-80								
30-60-01-900-801		A40 TIMER						Component ATA:30
PN:3E2311-4	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:UD0561	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-60-02PROC. REF: AMM 30-60-02								
30-60-02-200-801	^S	A40 PROPELLER DE-ICING TIMER - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:30
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 30-60-02PROC. REF: AMM 30-60-02								PKG:6,11
30-80-00-900-801		ICE DETECTOR						Component ATA:30
PN:0871CT2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2490	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-20-01-900-801	NO. 1 AIRFRAME/ENGINE INTERFACE UNIT							Component ATA:31
PN:011-03682-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:497005876	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
31-20-01-900-801	NO. 2 AIRFRAME/ENGINE INTERFACE UNIT							Component ATA:31
PN:011-03682-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:497005946	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
31-31-00-710-801	LIGHTWEIGHT DATA RECORDER - CHECK OPERATIONS							Service ATA:31
	MOS	01-Aug-25	24 (+10%/-10%)		01-Aug-27	13-Oct-27	644 d (+73)	
	HRS	701						
	AFL	483						
PROC. REF: AMM 31-31-00PROC. REF: AMM 31-31-00								
31-31-01-900-801	LIGHTWEIGHT DATA RECORDER							Component ATA:31
PN:1000-1210-11	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2051663	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-01PROC. REF: AMM 31-31-01								
31-31-01-900-802	LIGHTWEIGHT DATA RECORDER MICROPHONE (SURFACE-MOUNT)							Component ATA:31
PN:LDR-MIC-0300	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:100002151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 32 - LANDING GEAR								
32-00-00-100-801 ^S	IF NECESSARY, CLEAN THE EXTERNAL SECTIONS OF LANDING GEARS.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 12-22-01PROC. REF: AMM 12-22-01								
32-00-00-210-801 ^S	LEFT MAIN LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS							Service ATA:32
PN:D23767001-2	MOS	01-Aug-25	12 (+1m/-1m)					
SN:21AR48651	HRS	701						
WC#: 32.190	AFL	483						
PKG:12								
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								
32-00-00-210-801 ^S	NOSE LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS							Service ATA:32
PN:D23766000-2	MOS	01-Aug-25	12					
SN:21AR48091	HRS	701						
WC#: 32.220	AFL	483						
PKG:12								
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								
32-00-00-210-801 ^S	RIGHT MAIN LANDING GEAR - CHECK FOR CONDITION. CHECK FOR LEAKS							Service ATA:32
PN:D23768001-2	MOS	01-Aug-25	12					
SN:21AR48650	HRS	701						
WC#: 32.190	AFL	483						
PKG:12								
PROC. REF: AMM 32-40-01, AMM 32-00-00PROC. REF: AMM 32-40-01, AMM 32-00-00								
32-00-00-640-801 ^S	LH, RH, AND NOSE LANDING GEAR - LUBRICATION OF LANDING GEAR AXELS							Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701						
	AFL	483						
PKG:12								
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								
32-00-00-710-801 ^S	DO AN OPERATIONAL TEST IN NORMAL/EMERGENCY CONDITIONS AND CHECK FOR SEALING OF NORMAL/EMERGENCY HYDRAULIC VALVE.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PKG:5,6,7,8,9 ,10 ,11								
PROC. REF: AMM 32-00-00, AMM 32-00-00, AMM 32-00-00PROC. REF: AMM 32-00-00, AMM 32-00-00, AMM 32-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10-00-730-801	LEFT MAIN LANDING GEAR - OVERHAUL							Component ATA:32
PN:D23767001-2	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:21AR48651	HRS	0		TSN 0				
WC#: 32.010	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-10-01, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 32-10-01								
32-10-00-730-801	RIGHT MAIN LANDING GEAR - OVERHAUL							Component ATA:32
PN:D23768001-2	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:21AR48650	HRS	0		TSN 0				
WC#: 32.010	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-10-01, AMM 32-10-01PROC. REF: AMM 32-10-01, AMM 32-10-01								
32-10-01-220-801	LEFT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER							Service ATA:32
PN:D23767001-2	MOS	29-Sep-21	60 (+10%/-10%)		29-Sep-26	29-Mar-27	338 d (+181)	
SN:21AR48651	HRS	0						
WC#: 32.200	AFL	0						
PROC. REF: AMM 32-10-01, AMM 32-10-01, AMM 12-13-03PROC. REF: AMM 32-10-01, AMM 32-10-01, AMM 12-13-03								
32-10-01-220-801	RIGHT MAIN LANDING - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS. DO AN OIL CHANGE FOR THE SHOCK-ABSORBER.							Service ATA:32
PN:D23768001-2	MOS	29-Sep-21	60 (+10%/-10%)		29-Sep-26	29-Mar-27	338 d (+181)	
SN:21AR48650	HRS	0						
WC#: 32.200	AFL	0						
PROC. REF: AMM 32-10-01, AMM 32-10-01, AMM 12-13-03PROC. REF: AMM 32-10-01, AMM 32-10-01, AMM 12-13-03								
32-10-01-220-802	LEFT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.							Service ATA:32
PN:D23767001-2	MOS	29-Sep-21	120 (+10%/-10%)		29-Sep-31	29-Sep-32	2164 d (+366)	
SN:21AR48651	HRS	0						
WC#: 32.210	AFL	0						
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
32-10-01-220-802	RIGHT MAIN LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.							Service ATA:32
PN:D23768001-2	MOS	29-Sep-21	120 (+10%/-10%)		29-Sep-31	29-Sep-32	2164 d (+366)	
SN:21AR48650	HRS	0						
WC#: 32.210	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
32-10-01-780-801	^S	LEFT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE						Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 32.120	AFL	483						
								PKG:12
PROC. REF: AMM 12-14-01PROC. REF: AMM 12-14-01								
32-10-01-780-801	^S	RIGHT MAIN LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE						Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 32.120	AFL	483						
								PKG:12
PROC. REF: AMM 12-14-01PROC. REF: AMM 12-14-01								
32-20-00-200-801	^S	NOSE LANDING GEAR MOUNT - VISUALLY CHECK FOR CRACKS. CHECK AXIAL PLAY OF HINGE BALL JOINTS. PENDULATE THE NOSE LANDING GEAR TO CHECK HINGE BALL JOINTS FOR CONDITION.						Service ATA:32
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:8,11
PROC. REF: AMM 32-20-00PROC. REF: AMM 32-20-00								
32-20-00-730-801		NOSE LANDING GEAR - OVERHAUL						Component ATA:32
PN:D23766000-2	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:21AR48091	HRS	0		TSN 0				
WC#: 32.020	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-01-220-801		NOSE LANDING GEAR - CHECK FOR PLAY AND EXTERNAL ANTI-CORROSION PROTECTIONS. CHECK FOR INTERNAL ANTI-CORROSION PROTECTIONS. DO A DIMENSIONAL CHECK FOR TORQUE LINKS.						Service ATA:32
PN:D23766000-2	MOS	29-Sep-21	60 (+10%/-10%)		29-Sep-26	29-Mar-27	338 d (+181)	
SN:21AR48091	HRS	0						
WC#: 32.230	AFL	0						
PROC. REF: AMM 12-13-04, AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 12-13-04, AMM 32-20-01, AMM 32-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-20-01-220-802	NOSE LANDING - DO A DIMENSIONAL CHECK FOR ATTACHING BOLTS. DO A CHECK OF PISTON TUBE ASSEMBLY.							Service ATA:32
PN:D23766000-2	MOS	29-Sep-21	120 (+10%/-10%)		29-Sep-31	29-Sep-32	2164 d (+366)	
SN:21AR48091	HRS	0						
WC#: 32.240	AFL	0						
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-01-680-801	NOSE LANDING GEAR - DO AN OIL CHANGE FOR THE SHOCK ABSORBER							Service ATA:32
	MOS	29-Sep-21	60 (+10%/-10%)		29-Sep-26	29-Mar-27	338 d (+181)	
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-13-04PROC. REF: AMM 12-13-04								
32-20-01-780-801 ^S	NOSE LANDING GEAR - CHECK SHOCK-ABSORBER INFLATION PRESSURE							Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 32.130	AFL	483						
PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02								
32-20-01-900-801	NOSE LANDING GEAR - REPLACE NOSE GEAR ACTUATOR HINGE PIN SECURING BOLT							Service ATA:32
	MOS	29-Sep-21	84		29-Sep-28		1069 d	
	HRS	0						
	AFL	0	5000		5000		4517	
PROC. REF: AMM 32-20-01, AMM 32-20-01PROC. REF: AMM 32-20-01, AMM 32-20-01								
32-20-03-200-801 ^S	SHIMMY DAMPER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
WC#: 32.030	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-20-03-680-801	SHIMMY DAMPER - REPLACE HYDRAULIC FLUID.							Service ATA:32
	MOS	01-Aug-25	36 (+10%/-10%)		01-Aug-28	19-Nov-28	1010 d (+110)	
	HRS	701						
WC#: 32.030	AFL	483						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 12-13-01PROC. REF: AMM 12-13-01								
32-20-04-900-801	LEFT HAND NOSE GEAR MOUNT ASSEMBLY							Component ATA:32
PN:T700A322000200400	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1097	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-20-04PROC. REF: AMM 32-20-04								
32-20-04-900-801	RIGHT HAND NOSE GEAR MOUNT ASSEMBLY							Component ATA:32
PN:T700A322000200500	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1116	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-20-04PROC. REF: AMM 32-20-04								
32-30-00-200-801 ^S	HYDRAULIC LINES (IN NOSE GEAR WELL) - CHECK FOR SEALING, CONDITION AND ATTACHMENT.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:6,8,9 ,10 ,11
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								
32-30-00-200-802 ^S	HYDRAULIC AND BRAKE LINES (IN MAIN GEAR WELL) - CHECK FOR SEALING, CONDITION, ATTACHMENT AND ROUTING.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:6,8,9 ,10 ,11
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								
32-30-00-210-801 ^S	MAIN LANDING GEARS ACTUATORS - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30-00-210-802 ^S	NOSE LANDING GEAR ACTUATOR - CHECK FOR CONDITION AND ATTACHMENT. MAKE SURE THAT THERE ARE NO LEAKS AND NO CORROSION.							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								
32-30-01-730-801	LEFT MAIN LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	29-Sep-21	120 (+10%/-10%)	TSN 0	29-Sep-31	29-Sep-32	2164 d (+366)	OVERHAUL
SN:5353	HRS	0		TSN 0				
WC#: 32.040	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01								
32-30-01-730-801	RIGHT MAIN LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	29-Sep-21	120 (+10%/-10%)	TSN 0	29-Sep-31	29-Sep-32	2164 d (+366)	OVERHAUL
SN:5316	HRS	0		TSN 0				
WC#: 32.040	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01								
32-30-02-730-801	NOSE LANDING GEAR ACTUATOR - OVERHAUL							Component ATA:32
PN:7897340001	MOS	29-Sep-21	120 (+10%/-10%)	TSN 0	29-Sep-31	29-Sep-32	2164 d (+366)	OVERHAUL
SN:5343	HRS	0		TSN 0				
WC#: 32.050	AFL	0	5000 (+10%/-10%)	TSN 0	5000	5500	4517 (+500)	
PROC. REF: AMM 32-30-01, AMM 32-30-02PROC. REF: AMM 32-30-01, AMM 32-30-02								
32-35-00-680-801	HYDRAULIC SYSTEM - REPLACE HYDRAULIC FLUID							Service ATA:32
	MOS	01-Aug-25	36 (+10%/-10%)		01-Aug-28	19-Nov-28	1010 d (+110)	
	HRS	701						
WC#: 32.070	AFL	483						
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-35-01-200-801	^S	ELECTRO-HYDRAULIC GENERATOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-35-01PROC. REF: AMM 32-35-01							PKG:1,5,6,7,8,9 ,10 ,11	
32-35-01-200-802	^S	ELECTRO-HYDRAULIC GENERATOR - CHECK FILTER CLEANLINESS.						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-35-01PROC. REF: AMM 32-35-01							PKG:5,9 ,10 ,11	
32-35-01-730-801		ELECTRO-HYDRAULIC GENERATOR - OVERHAUL						Component ATA:32
PN:T700A323500300400	MOS	06-Jun-23	120 (+10%/-10%)	TSO 0	06-Jun-33	06-Jun-34	2780 d (+365)	OVERHAUL
SN:673	HRS	344.9		TSO 0				
WC#: 32.060	AFL	164	10000 (+10%/-10%)	TSO 0	10164	11164	9681 (+1000)	
PROC. REF: AMM 32-35-01, AMM 32-35-01PROC. REF: AMM 32-35-01, AMM 32-35-01								
32-35-04-900-801		NORMAL/EMERGENCY SELECTOR VALVE						Component ATA:32
PN:978D6-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:K59757	HRS	0		TSN 0				
WC#: 32.080	AFL	0		TSN 0				
PROC. REF: AMM 32-35-04PROC. REF: AMM 32-35-04								
32-40-01-100-801	^S	LEFT MAIN LANDING GEAR - CLEAN WHEEL BEARINGS OF THE MAIN LANDING GEAR						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01							PKG:5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-01-100-801	^S	RIGHT MAIN LANDING GEAR - CLEAN WHEEL BEARINGS OF THE MAIN LANDING GEAR						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-01							PKG:5,6,7,8,9 ,10 ,11	
32-40-01-200-803	^S	LEFT MAIN LANDING GEAR WHEELS - CHECK BEARINGS FOR CONDITION AND CORROSION (REFER TO 32-40-01-601)						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
WC#: 32.280	AFL	483						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01							PKG:5,6,7,8,9 ,10 ,11	
32-40-01-200-803	^S	RIGHT MAIN LANDING GEAR WHEELS - CHECK BEARINGS FOR CONDITION AND CORROSION (REFER TO 32-40-01-601)						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
WC#: 32.280	AFL	483						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01							PKG:5,6,7,8,9 ,10 ,11	
32-40-01-210-801	^S	MAIN LANDING GEAR TIRES - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03							PKG:1,5,6,7,8,9 ,10 ,11	
32-40-01-640-801	^S	LEFT MAIN LANDING GEAR - LUBRICATE WHEEL BEARINGS OF THE MAIN LANDING GEAR						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05							PKG:5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-01-640-801 ^S	RIGHT MAIN LANDING GEAR - LUBRICATE WHEEL BEARINGS OF THE MAIN LANDING GEAR							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								
32-40-01-730-801	LEFT MAIN LANDING GEAR WHEEL - OVERHAUL							Component ATA:32
PN:40-489	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:1209	HRS	0		TSN 0				
WC#: 32.090	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	517 (+100)	
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-730-801	RIGHT MAIN LANDING GEAR WHEEL - OVERHAUL							Component ATA:32
PN:40-489	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:1208	HRS	0		TSN 0				
WC#: 32.100	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	517 (+100)	
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-900-801	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:033-631-0	MOS/MSC	01-Aug-25	O/C	TSN 16				
SN:4114T00392	HRS	701		TSN 0				
WC#: 32.090	AFL	483		TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-01-900-801	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:033-631-0	MOS/MSC	01-Aug-25	O/C	TSN 11				
SN:4256T00224	HRS	701		TSN 0				
WC#: 32.100	AFL	483		TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
32-40-02-100-801 ^S	NOSE LANDING GEAR WHEEL - CLEAN BEARINGS OF THE NOSE LANDING GEAR							Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701	200					
WC#: 32.285	AFL	483						
							PKG:5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-02PROC. REF: AMM 12-21-05, AMM 12-21-05, AMM 32-40-02								
32-40-02-200-802 ^S	NOSE LANDING GEAR WHEEL - CHECK BEARINGS FOR CONDITION AND CORROSION							Service ATA:32
	MOS	01-Aug-25	12					
	HRS	701	200					
WC#: 32.285	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
32-40-02-210-801 ^S	NOSE LANDING GEAR TIRE - CHECK FOR EXCESSIVE WEAR AND CUTS. CHECK INFLATION PRESSURE.							Service ATA:32
	MOS	01-Aug-25	12 (-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03								
32-40-02-640-801 ^S	NOSE LANDING GEAR WHEEL - LUBRICATE WHEEL BEARINGS OF NOSE LANDING GEAR							Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 12-21-05, AMM 12-21-05PROC. REF: AMM 12-21-05, AMM 12-21-05								
32-40-02-730-801	NOSE LANDING GEAR WHEEL - OVERHAUL							Component ATA:32
PN:040-262AA	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:2581	HRS	0		TSN 0				
WC#: 32.110	AFL	0	1000 (+10%/-10%)	TSN 0	1000	1100	517 (+100)	
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
32-40-02-900-801	NOSE LANDING GEAR TIRE							Component ATA:32
PN:505T08-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2060128	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-03-200-801	^S	BRAKE ASSEMBLY - CHECK FOR WEAR, CRACKS ON LININGS AND DISC, AND REPLACE IF NECESSARY.						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								PKG:1,5,6,7,8,9 ,10 ,11
32-40-03-900-801		LEFT MAIN LANDING GEAR BRAKE ASSEMBLY						Component ATA:32
PN:030-311	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1213	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								
32-40-03-900-801		RIGHT MAIN LANDING GEAR BRAKE ASSEMBLY						Component ATA:32
PN:030-311	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1212	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
PROC. REF: AMM 32-40-03PROC. REF: AMM 32-40-03								
32-40-04-200-801	^S	HYDRAULIC AND BRAKE LINES (IN FUSELAGE) - CHECK FOR SEALING, CONDITION AND ATTACHMENT.						Service ATA:32
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-04PROC. REF: AMM 32-40-04								PKG:6,11
32-40-04-200-802	^S	BRAKE MASTER CYLINDER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						Service ATA:32
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-04PROC. REF: AMM 32-40-04								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-04-710-801	^S	BRAKE MASTER CYLINDER - DO AN OPERATIONAL TEST.						Service ATA:32
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-00, AMM 32-40-00PROC. REF: AMM 32-40-00, AMM 32-40-00								PKG:10 ,11
32-40-05-710-801	^S	PARKING BRAKE VALVE AND CONTROL - CHECK CORRECT OPERATION OF INDICATION AND BRAKING.						Service ATA:32
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-00, AMM 32-40-00PROC. REF: AMM 32-40-00, AMM 32-40-00								PKG:5,6,7,8,10 ,11
32-40-07-200-801	^S	BRAKE RESERVOIR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS. CHECK HYDRAULIC FLUID LEVEL.						Service ATA:32
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-40-04, AMM 12-13-01PROC. REF: AMM 32-40-04, AMM 12-13-01								PKG:1,5,6,7,8,9 ,10 ,11
32-40-07-680-801		BRAKE RESERVOIR - REPLACE HYDRAULIC FLUID						Service ATA:32
	MOS	01-Aug-25	36 (+10%/-10%)		01-Aug-28	19-Nov-28	1010 d (+110)	
	HRS	701						
WC#: 32.150	AFL	483						
PROC. REF: AMM 12-13-05PROC. REF: AMM 12-13-05								
32-50-00-200-801	^S	STEERING CONTROL - CHECK CONDITION OF RODS, BELLCRANK, CAM AND ROLLERS. MAKE SURE THAT THERE ARE NO FRICTION POINTS IN THE CONTROL.						Service ATA:32
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-50-00PROC. REF: AMM 32-50-00								PKG:8,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-60-01-900-801	A14 LANDING GEAR CONTROL BOX							Component ATA:32
PN:LGCP-14-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:435	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 33 - LIGHTS								
33-10-00-710-801 ^S	INSTRUMENT PANEL AND PL1 LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-10-00, AMM 33-10-00PROC. REF: AMM 33-10-00, AMM 33-10-00								PKG:5,6,7,8,9 ,10 ,11
33-20-00-710-801 ^S	CABIN LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-20-00PROC. REF: AMM 33-20-00								PKG:5,6,7,8,9 ,10 ,11
33-20-00-710-802 ^S	REAR BAGGAGE COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-20-00PROC. REF: AMM 33-20-00								PKG:5,6,7,8,9 ,10 ,11
33-30-01-710-802 ^S	FRONT CARGO COMPARTMENT LIGHTING - CHECK FOR CONDITION AND OPERATION.							Service ATA:33
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-30-00, AMM 33-30-00, AMM 33-30-00PROC. REF: AMM 33-30-00, AMM 33-30-00, AMM 33-30-00								PKG:5,6,7,8,12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-30-02-710-802	^S	FUEL UNIT CLOGGING INDICATOR LIGHTING - CHECK FOR CONDITION AND OPERATION.						Service ATA:33
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-30-02, AMM 33-30-00PROC. REF: AMM 33-30-02, AMM 33-30-00								PKG:5,6,7,8,9 ,10 ,11
33-40-00-710-801 ^S EXTERIOR LIGHTS - CHECK FOR CONDITION, ATTACHMENTS AND OPERATION								
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00, AMM 33-40-00PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00, AMM 33-40-00								PKG:1,5,6,7,8,9 ,10 ,11
33-50-00-710-801 ^S INSTRUMENT PANEL EMERGENCY LIGHTING - CHECK FOR CONDITION AND OPERATION.								
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 34 - NAVIGATION								
34-00-00-200-802	^S	ANTENNAS - CHECK FOR CONDITION, ATTACHMENT AND EVIDENCE OF CORROSION.						Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-30-00, AMM 34-40-00, AMM 34-50-00PROC. REF: AMM 34-30-00, AMM 34-40-00, AMM 34-50-00								PKG:5,6,7,8,9 ,10 ,11
34-00-00-200-803 ^S CONTROLS AND COMPONENTS - CHECK FOR CONDITION AND ATTACHMENT.								
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-20-00, AMM 34-30-00, AMM 34-40-00, AMM 34-50-00PROC. REF: AMM 34-20-00, AMM 34-30-00, AMM 34-40-00, AMM 34-50-00								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-00-00-710-801	VFR EQUIPMENT - DO AN OPERATIONAL TEST.							Service ATA:34
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 34.040	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
34-00-00-710-802	IFR EQUIPMENT - DO AN OPERATIONAL TEST.							Service ATA:34
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
WC#: 34.050	AFL	0						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								
34-11-00-200-801 ^S	STATIC PRESSURE PORTS - CHECK FOR CONDITION AND CLEANLINESS.							Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								PKG:1,5,6,7,8,9 ,10 ,11
34-11-00-200-802 ^S	AIR DATA SYSTEM LINES - CHECK FOR CONDITION, ATTACHMENT AND WEAR DUE TO CHAFING AT HOSE CONNECTIONS.							Service ATA:34
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								PKG:6,11
34-11-00-210-801 ^S	PITOT TUBES - CHECK FOR CONDITION, ATTACHMENT, CLEANLINESS AND EVIDENCE OF OVERHEATING.							Service ATA:34
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								PKG:5,6,7,8,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-710-801	^S	VMO WARNING - DO A GROUND OPERATIONAL TEST.						Service ATA:34
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								PKG:7,10 ,11
34-11-00-790-801	^S	AIR DATA SYSTEM - DO A LEAKAGE TEST OF STATIC AND DYNAMIC SYSTEMS AND A CHECK OF ASSOCIATED INSTRUMENTS AND EQUIPMENTS.						Service ATA:34
	MOS	01-Aug-25	24					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								PKG:6,10 ,11
34-11-00-820-801		ALTIMETRY - CHECK CALIBRATION						Service ATA:34
	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
	HRS	701						
WC#: 34.020	AFL	483						
Calibration Date: : 01-Aug-25								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-820-801		NO. 1 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION						Service ATA:34
PN:011-03734-40	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
SN:4E5000947	HRS	701						
	AFL	483						
Calibration Date: : 01-Aug-25								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-820-801		NO. 2 DIGITAL AIR DATA COMPUTER - CHECK CALIBRATION						Service ATA:34
PN:011-03734-40	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
SN:4E5000949	HRS	701						
	AFL	483						
Calibration Date: : 01-Aug-25								
PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: CFR FAR PART 91.411, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-820-803	STANDBY INDICATOR - CHECK CALIBRATION (14 CFR PART 91.411)							Service ATA:34
PN:6420302-1	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
SN:M20-10783	HRS	701						
	AFL	483						
PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00, AMM 34-11-00								
34-11-00-870-801 ^S	STATIC SYSTEMS - BLEED SYSTEM							Service ATA:34
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PKG:6,10 ,11								
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								
34-11-00-870-802 ^S	STATIC SYSTEMS - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED.							Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PKG:5,6,7,8,9 ,10 ,11								
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								
34-11-00-870-803 ^S	DYNAMIC SYSTEM - BLEED SYSTEM.							Service ATA:34
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PKG:7,10 ,11								
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								
34-11-00-870-804 ^S	DYNAMIC SYSTEM - FOR FREQUENT FLIGHTS IN HIGH HYGROMETRY ATMOSPHERE, PERFORM BLEED.							Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PKG:5,6,7,8,9 ,10 ,11								
PROC. REF: AMM 34-11-00, AMM 34-11-00PROC. REF: AMM 34-11-00, AMM 34-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 1						Component ATA:34
PN:T700A341503501300	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 2						Component ATA:34
PN:T700A341503500800	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM EMERGENCY STATIC HOSE NO. 3						Component ATA:34
PN:T700A34150350003	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 1						Component ATA:34
PN:T700A341503500001	MOS	01-Jan-20	168	TSN 0	01-Oct-34 (M)		3262 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 2						Component ATA:34
PN:T700A341503501400	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 1 HOSE NO. 3						Component ATA:34
PN:T700A341503500601	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 1						Component ATA:34
PN:T700A341503500201	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 2						Component ATA:34
PN:T700A341503501200	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-802		AIR DATA SYSTEM STATIC 2 HOSE NO. 3						Component ATA:34
PN:T700A341503500501	MOS	01-Dec-20	168	TSN 0	01-Aug-35 (M)		3566 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-00-900-803		ELECTRONIC STANDBY INDICATOR						Component ATA:34
PN:6420302-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:M20-10783	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-03PROC. REF: AMM 34-24-03								
34-11-08-900-801		LEFT PITOT TUBE						Component ATA:34
PN:5812-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AS04217998	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
PROC. REF: AMM 34-11-08PROC. REF: AMM 34-11-08								
34-11-08-900-801		RIGHT PITOT TUBE						Component ATA:34
PN:5812-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AS04217850	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
PROC. REF: AMM 34-11-08PROC. REF: AMM 34-11-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-10-900-801	NO. 1 DIGITAL AIR DATA COMPUTER							Component ATA:34
PN:011-03734-40	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:4E5000947	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10								
34-11-10-900-801	NO. 2 DIGITAL AIR DATA COMPUTER							Component ATA:34
PN:011-03734-40	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:4E5000949	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10, AMM 34-11-10								
34-11-61-900-801	GDL69A DATALINK							Component ATA:34
PN:011-03177-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3NV005469	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-13-00-210-801 ^S	OUTSIDE AIR TEMPERATURE PROBE - CHECK FOR ATTACHMENT AND CONDITION.							Service ATA:34
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-13-00PROC. REF: AMM 34-13-00								PKG:5,6,7,8,11
34-13-01-900-801	OUTSIDE TEMPERATURE SENSOR							Component ATA:34
PN:100723-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2122645	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-13-01, AMM 34-13-01PROC. REF: AMM 34-13-01, AMM 34-13-01								
34-15-00-710-801 ^S	ANGLE OF ATTACK - DO A GROUND OPERATIONAL TEST							Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-01-900-801	A590 STALL WARNING / AOA COMPUTER						Component	ATA:34
PN:C:101706-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:188019-02	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01								
34-15-02-900-801	S590 LIFT TRANSDUCER						Component	ATA:34
PN:C:101707-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:188020-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-02PROC. REF: AMM 34-15-02								
34-20-00-210-801 ^S	STANDBY COMPASS - CHECK FOR ATTACHMENT, CONDITION AND FLUID LEVEL.						Service	ATA:34
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-20-00PROC. REF: AMM 34-20-00								
34-20-00-210-802 ^S	STANDBY MAGNETOMETER - CHECK FOR ATTACHMENT AND CONDITION (REFER TO 34-20-00-601). IF INSTALLEED.						Service	ATA:34
	MOS		48					
	HRS		800					
	AFL							
PKG:11								
34-21-05-900-801	NO. 1 ATTITUDE AND HEADING REFERENCE SYSTEM						Component	ATA:34
PN:011-03732-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:45T004881	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-05-900-801	NO. 2 ATTITUDE AND HEADING REFERENCE SYSTEM							Component ATA:34
PN:011-03732-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:45T004743	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								
34-21-05-900-801	STORMSCOPE PROCESSOR							Component ATA:34
PN:805-11500-001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:S00866	HRS	0		TSN 0				
WC#: 34.150	AFL	0		TSN 0				
PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05PROC. REF: AMM 34-21-05, AMM 34-21-05, AMM 34-21-05								
34-21-05-900-802	STORMSCOPE ANTENNA							Component ATA:34
PN:805-10930-001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:S00537	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-24-03-900-801	STANDBY HORIZON							Component ATA:34
PN:6420302-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:M20-10783	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: AMM 34-24-03, AMM 34-24-03, AMM 34-24-03, AMM 34-24-03PROC. REF: AMM 34-24-03, AMM 34-24-03, AMM 34-24-03, AMM 34-24-03								
34-24-04-900-801	STANDBY MAGNETOMETER (MD32)							Component ATA:34
PN:6420032-1	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:E21-11946	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-04PROC. REF: AMM 34-24-04								
34-28-00-070-801 ^S	ELECTRONIC FLIGHT INSTRMENT SYSTEM - REMOVE DATA FOM SD CARDS (REFER TO 34-28-00-301)							Service ATA:34
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 34-28-00, AMM 34-28-00PROC. REF: AMM 34-28-00, AMM 34-28-00								PKG:6,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-28-10-900-801	NO. 1 PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:11-03470-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:494106232	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: AMM 34-28-10, AMM 34-28-10PROC. REF: AMM 34-28-10, AMM 34-28-10								
34-28-10-900-801	NO. 2 PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:11-03470-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:494106140	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: AMM 34-28-10, AMM 34-28-10PROC. REF: AMM 34-28-10, AMM 34-28-10								
34-28-11-900-801	MULTIFUNCTION DISPLAY							Component ATA:34
PN:011-03472-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:496001879	HRS	0		TSN 0				
WC#: 34.120	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-28-14-900-801	NO. 1 TRIAXIAL MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1CM034296	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-28-14-900-801	NO. 2 TRIAXIAL MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1CM034322	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-40-01-900-801	REMOTE FMS PEDESTAL MOUNTED CONTROLLER							Component ATA:34
PN:011-04475-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:48V000428	HRS	0		TSN 0				
WC#: 34.230	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-42-01-900-801		WEATHER RADAR UNIT					Component	ATA:34
PN:011-01768-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1DP009285	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-43-01-900-801		RADAR ALTIMETER RECEIVER/TRANSMITTER					Component	ATA:34
PN:011-02537-05	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3RC007878	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01, AMM 34-43-01, AMM 34-43-01PROC. REF: AMM 34-43-01, AMM 34-43-01, AMM 34-43-01								
34-43-03-900-801		NO. 1 RADAR ALTIMETER ANTENNA					Component	ATA:34
PN:013-00378-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:543-100074	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-03, AMM 34-43-03PROC. REF: AMM 34-43-03, AMM 34-43-03								
34-43-03-900-801		NO. 2 RADAR ALTIMETER ANTENNA					Component	ATA:34
PN:013-00378-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:543-101709	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-03, AMM 34-43-03PROC. REF: AMM 34-43-03, AMM 34-43-03								
34-44-01-900-802		TAS COMPUTER					Component	ATA:34
PN:011-01446-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1EAF07092	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-44-01-900-803		TAS AMPLIFIER					Component	ATA:34
PN:011-01347-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:140051552	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-44-02-900-801	NO. 1 TAS ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:124017704	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-44-02-900-801	NO. 2 TAS ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:124017703	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-53-00-710-801	NO. 1 (A56) TRANSPONDER - DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-03303-00	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
SN:3EH025587	HRS	701						
WC#: 34.060	AFL	483						
Calibration Date: : 01-Aug-25								
PROC. REF: CFR FAR PART 91.413, AMM 34-53-00PROC. REF: CFR FAR PART 91.413, AMM 34-53-00								
34-53-00-710-801	NO. 2 (A57) TRANSPONDER- DO AN OPERATIONAL TEST OF TRANSPONDER(S) AND EACH CONTROL.							Service ATA:34
PN:011-03303-00	MOS	01-Aug-25	24		01-Aug-27		644 d	MANDATORY
SN:3EH025844	HRS	701						
WC#: 34.060	AFL	483						
Calibration Date: : 01-Aug-25								
PROC. REF: CFR FAR PART 91.413, AMM 34-53-00PROC. REF: CFR FAR PART 91.413, AMM 34-53-00								
34-53-01-900-801	NO. 1 (A56) TRANSPONDER							Component ATA:34
PN:011-03303-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3EH025587	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01								
34-53-01-900-801	NO. 2 (A57) TRANSPONDER							Component ATA:34
PN:011-03303-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3EH025844	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01PROC. REF: AMM 34-53-01, AMM 34-53-01, AMM 34-53-01								
34-53-03-900-801	NO. 1 XPDR ANTENNA							Component ATA:34
PN:CI-105-16	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:45106	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-53-03-900-802	NO. 2 XPDR ANTENNA							Component ATA:34
PN:CI-105-16	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:45104	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-55-01-900-801	DME UNIT							Component ATA:34
PN:066-01070-0001	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:44243	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01, AMM 34-55-01PROC. REF: AMM 34-55-01, AMM 34-55-01								
34-57-02-900-801	GA36 WAAS ARINC ANTENNA							Component ATA:34
PN:013-00244-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:23847	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
34-57-02-900-802	GA37 WAAS/XM ARINC ANTENNA							Component ATA:34
PN:00-00245-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:21646	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
ATA 35 - OXYGEN								
35-00-00-710-801 ^S	GASEOUS OXYGEN SYSTEM - CHECK COMPONENTS AND LINES FOR LEAKS,CONDITION AND ATTACHMENT. DO AN OPERATIONAL TEST							Service ATA:35
	MOS	01-Aug-25	12					
	HRS	701						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
WC#: 35.010	AFL	483						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								PKG:12
35-11-01-200-801 ^S	GASEOUS OXYGEN CYLINDER - CHECK FOR TIGHTNESS. CHECK FOR CORROSION AND DISTORTION (BULGE, DENT). CHECK FOR ATTACHMENT. CHECK HYDROSTATIC TEST DATE.						Service	ATA:35
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
	AFL	483						
PROC. REF: GENERIC CMMPROC. REF: GENERIC CMM								PKG:12
35-11-01-730-801	GASEOUS OXYGEN CYLINDER - DO A HYDROSTATIC TEST						Service	ATA:35
PN:2213-6519	MOS	01-May-21	60 (+10%/-10%)		01-May-26	01-Nov-26	187 d (+184)	OVERHAUL
SN:1282	HRS							
WC#: 35.040	AFL							
HydroCheck Date: : 01-May-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-11-01-900-801	GASEOUS OXYGEN CYLINDER - REPLACE						Component	ATA:35
PN:2213-6519	MOS	01-May-21	180	TSN 0	01-May-36		3840 d	LIFE LIMIT
SN:1282	HRS			TSN 0				
WC#: 35.040	AFL			TSN 0				
Manufacture Date:: 01-May-21								
PROC. REF: AMM 35-11-01PROC. REF: AMM 35-11-01								
35-11-02-730-801	COPILOT OXYGEN MASK						Component	ATA:35
PN:MC10-02-123	MOS	29-Sep-21	72 (+10%/-10%)	TSN 0	29-Sep-27	05-May-28	703 d (+219)	OVERHAUL
SN:B169115	HRS	0		TSN 0				
WC#: 35.020	AFL	0		TSN 0				
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-02-730-801	PILOT OXYGEN MASK						Component	ATA:35
PN:MC10-02-123	MOS	29-Sep-21	72 (+10%/-10%)	TSN 0	29-Sep-27	05-May-28	703 d (+219)	OVERHAUL
SN:B168480	HRS	0		TSN 0				
WC#: 35.020	AFL	0		TSN 0				
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-03-900-801	PRESSURE TRANSMITER							Component ATA:35
PN:452065	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1023	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
35-11-04-900-801	BP VALVE							Component ATA:35
PN:P21030-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:R21040164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
35-21-01-110-801 ^S	NO. 1 PASSENGER MASK - INSPECT AND DISINFECT							Service ATA:35
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 35.050	AFL	483						
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-110-801 ^S	NO. 2 PASSENGER MASK - INSPECT AND DISINFECT							Service ATA:35
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
WC#: 35.050	AFL	483						
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-01-110-801 ^S	NO. 3 PASSENGER MASK - INSPECT AND DISINFECT							Service ATA:35
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701						
WC#: 35.060	AFL	483						
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-01-110-801	^S	NO. 4 PASSENGER MASK - INSPECT AND DISINFECT						Service ATA:35
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 35.060	AFL	483						
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								PKG:12
35-21-01-900-801		FORWARD PASSENGER OXYGEN MASK BOX						Component ATA:35
PN:833-610-09	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:D21050910	HRS	0		TSN 0				
WC#: 35.090	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-900-804		AFT PASSENGER OXYGEN MASK BOX						Component ATA:35
PN:833-610-09	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:D21050909	HRS	0		TSN 0				
WC#: 35.090	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-02-730-801		SOLENOID VALVE - OVERHAUL						Component ATA:35
PN:DVE90-08	MOS	29-Sep-21	72 (+10%/-10%)	TSN 0	29-Sep-27	05-May-28	703 d (+219)	OVERHAUL
SN:10059	HRS	0		TSN 0				
WC#: 35.080	AFL	0		TSN 0				
PROC. REF: AMM 35-21-02PROC. REF: AMM 35-21-02								
35-21-03-900-801		BAROMETRIC ALTITUDE SWITCH						Component ATA:35
PN:P24031	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:D20050130	HRS	0		TSN 0				
WC#: 35.110	AFL	0		TSN 0				
PROC. REF: AMM 35-21-03PROC. REF: AMM 35-21-03								
ATA 37 - VACUUM								
30-10-05-900-801		DISTRIBUTING VALVE						Component ATA:37
PN:1532-10C	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N300001	HRS	0		TSN 0				
WC#: 37.050	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 37 - VACUUM								
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
37-10-00-200-801	^S	AIR EJECTOR - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)					Service	ATA:37
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,11
37-10-00-200-802	^S	HOSES - CHECK FOR CONDITION AND ATTACHMENTS. (REFER TO 37-10-00-601)					Service	ATA:37
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,6,11
37-10-00-200-803	^S	SUCTION RELIEF VALVE - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)					Service	ATA:37
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:6,11
37-10-00-200-804	^S	REGULATING AND RELIEF VALVE - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)					Service	ATA:37
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:5,11
37-10-00-200-805	^S	S67 PRESSURE SWITCH - CHECK FOR CONDITION AND ATTACHMENT. (REFER TO 37-10-00-601)					Service	ATA:37
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 37-10-00PROC. REF: AMM 37-10-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 37 - VACUUM								
37-10-01-900-801	REGULATOR AND RELIEF VALVE							Component ATA:37
PN:38E-96.2D	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N210293	HRS	0		TSN 0				
WC#: 37.020	AFL	0		TSN 0				
PROC. REF: AMM 37-10-01, AMM 37-10-01, AMM 37-10-01PROC. REF: AMM 37-10-01, AMM 37-10-01, AMM 37-10-01								
37-10-02-900-801	AIR EJECTOR VALVE							Component ATA:37
PN:19E17-5A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N193798	HRS	0		TSN 0				
WC#: 37.030	AFL	0		TSN 0				
PROC. REF: AMM 37-10-02, AMM 37-10-02, AMM 37-10-02PROC. REF: AMM 37-10-02, AMM 37-10-02, AMM 37-10-02								
37-10-03-900-801	SUCTION RELIEF VALVE							Component ATA:37
PN:691-21A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N210412	HRS	0		TSN 0				
WC#: 37.040	AFL	0		TSN 0				
PROC. REF: AMM 37-10-03, AMM 37-10-03PROC. REF: AMM 37-10-03, AMM 37-10-03								
37-10-04-900-801	AIR CHECK VALVE							Component ATA:37
PN:557-18E	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:N300001	HRS	0		TSN 0				
WC#: 37.060	AFL	0		TSN 0				
PROC. REF: AMM 37-10-04, AMM 37-10-04, AMM 37-10-04PROC. REF: AMM 37-10-04, AMM 37-10-04, AMM 37-10-04								
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
51-25-00-370-801	WITH MOD 70-135-11 - AIRCRAFT WITHOUT FINISH PAINT. AIRCRAFT MUST MANDATORILY BE PAINTED, AS PER DRAWING T700B-1110056, LAST ISSUE, WITHIN FIVE WEEKS AFTER AIRCRAFT INITIAL ACCEPTANCE (DELIVERY OF EXPORT CERTIFICATE OF AIRWORTHINESS BY FRENCH AUTHORITIES).							Service ATA:51
	DAYS/MSC	29-Sep-21	-					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 52 - DOORS								
52-10-00-900-801	PILOT DOOR							Component ATA:52
PN:T700B521042600000	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:411	HRS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
	AFL	0		TSN 0				
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								
52-11-00-200-803	^S	LATCH CATCH AND FITTING ASSEMBLIES (LARGE DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11
52-11-00-200-804	^S	LARGE DOOR SEAL - CHECK FOR CONDITION.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:5,6,7,8,11
52-11-00-200-805	^S	LARGE DOOR CLOSING MECHANISM - EXAMINE CABLE FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS. CHECK GEARED MOTOR ASSEMBLY FOR SECURITY AND CONDITION.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11
52-11-00-220-801	^S	LARGE DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00								PKG:6,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-00-710-801	^S	LARGE DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK AND GAS STRUTS FOR OPERATION. CHECK CENTERING ROLLER FOR WEAR AND OPERATION.					Service	ATA:52
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00PROC. REF: AMM 52-11-00, AMM 52-11-00							PKG:6,10 ,11	
52-11-01-900-801	DOOR						Component	ATA:52
PN:T700B521000510000	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:927	HRS	0		TSN 0				
WC#: 52.020	AFL	0		TSN 0				
PROC. REF: AMM 52-11-01PROC. REF: AMM 52-11-01								
52-11-02-900-801	CABIN DOOR GEARED MOTOR ASSEMBLY						Component	ATA:52
PN:T700B521000101300	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:TB0433	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-02PROC. REF: AMM 52-11-02								
52-12-00-200-802	^S	PILOT DOOR - CHECK WINDOW FRAMING AND CARRY-THRU LONGERON ATTACHMENTS TO DOOR STRUCTURE FOR CRACKS AND LOOSE RIVETS.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00							PKG:6,11	
52-12-00-200-804	^S	LATCH CATCH ASSEMBLIES AND PIN (PILOT DOOR FRAMING) - CHECK FOR DAMAGE, CRACKS AND WEAR.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00							PKG:5,6,7,8,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-12-00-200-805	^S	PILOT DOOR SEAL - CHECK FOR CONDITION.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,11
52-12-00-220-801	^S	PILOT DOOR LATCH LOCKS AND HOOKS - CHECK FOR DAMAGE, CRACKS AND WEAR. CHECK TRAVEL DISTANCES.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,11
52-12-00-710-801	^S	PILOT DOOR - CHECK FOR CONDITION, SECURITY AND OPERATION (INSIDE AND OUTSIDE). CHECK HANDLE LOCK FOR OPERATION.						Service ATA:52
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-12-00PROC. REF: AMM 52-12-00								PKG:5,6,7,8,10 ,11
52-20-00-710-801	^S	EMERGENCY EXIT - CHECK FOR CONDITION, ATTACHMENT AND OPERATION (INSIDE AND OUTSIDE).						Service ATA:52
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								PKG:6,10 ,11
52-20-00-900-801		EMERGENCY EXIT						Component ATA:52
PN:T700A522014000001	MOS/MS	29-Sep-21	O/C	TSN 0				
SN:133	HRS	0		TSN 0				
WC#: 52.030	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-01-710-801	^S	ACCESS DOOR 211 - CHECK FOR CONDITION, ATTACHMENT AND LOCKING. CHECK OPERATION OF LOCK AND COMPENSATION ROD.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-30-01PROC. REF: AMM 52-30-01								PKG:6,11
52-40-01-210-801	^S	L.H. WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00, AMM 52-40-01PROC. REF: AMM 28-10-00, AMM 52-40-01								PKG:7,11
52-40-01-210-802	^S	R.H. WING ACCESS PANELS - CHECK FOR CONDITION AND TIGHTNESS.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 28-10-00, AMM 52-40-01PROC. REF: AMM 28-10-00, AMM 52-40-01								PKG:7,11
52-40-03-210-801	^S	ACCESS DOOR 311 - CHECK FOR CONDITION AND ATTACHMENT.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-40-03, AMM 52-40-03PROC. REF: AMM 52-40-03, AMM 52-40-03								PKG:6,11
52-40-03-210-802	^S	CLOGGING INDICATOR ACCESS DOOR - CHECK FOR CONDITION, ATTACHMENT AND LOCKING.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-40-03, AMM 52-40-03PROC. REF: AMM 52-40-03, AMM 52-40-03								PKG:5,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-40-03-410-802	^S	INSTALL ACCESS PANELS 213 AND 214.						Service ATA:52
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,6,7,8,9 ,10 ,11
52-60-00-210-801	^S	LARGE DOOR STAIRWAY AND HANDRAIL - CHECK FOR CONDITION, SECURITY AND OPERATION. EXAMINE HANDRAIL AND STAIRWAY CABLES FOR BROKEN STRANDS. CHECK PULLEYS FOR CRACKS AND DAMAGE (EXCEPT MARKING AT BOTTOM OF GROOVE). CHECK FREE ROTATION OF PULLEYS.						Service ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-11-00, AMM 52-11-00, AMM 52-60-00PROC. REF: AMM 52-11-00, AMM 52-11-00, AMM 52-60-00								PKG:6,11
52-60-01-900-801		STAIRWAY						Component ATA:52
PN:T700B526010100416	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:TB936	HRS	0		TSN 0				
WC#: 52.010	AFL	0		TSN 0				
PROC. REF: AMM 52-60-01PROC. REF: AMM 52-60-01								
52-71-00-710-801	^S	LARGE DOOR INDICATION - CHECK FOR OPERATION.						Service ATA:52
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-71-00, AMM 52-71-00PROC. REF: AMM 52-71-00, AMM 52-71-00								PKG:5,6,7,8,9 ,10 ,11
52-71-00-710-802	^S	PILOT DOOR INDICATION - CHECK FOR OPERATION.						Service ATA:52
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 52-71-00, AMM 52-71-00PROC. REF: AMM 52-71-00, AMM 52-71-00								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-80-01-200-801	^S	MAIN LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF FITTINGS, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-10-00, AMM 52-80-01, AMM 52-80-01PROC. REF: AMM 32-10-00, AMM 52-80-01, AMM 52-80-01							PKG:8,11	
52-80-02-200-801	^S	NOSE LANDING GEAR DOORS - CHECK FOR CONDITION, ATTACHMENT OF HINGES, EVIDENCE OF DAMAGE, AS WELL AS RIGGING. CHECK FOR SLACK AT ROD END FITTINGS.					Service	ATA:52
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 32-20-00, AMM 52-80-02, AMM 52-80-02PROC. REF: AMM 32-20-00, AMM 52-80-02, AMM 52-80-02							PKG:8,11	
ATA 53 - FUSELAGE								
53-00-00-200-801	^S	LARGE DOOR FRAMING - CHECK DOOR FRAMING VISIBLE AREA AND STRUCTURE JUNCTION UNDER FLOOR FOR CRACKS AND LOOSE RIVETS.					Service	ATA:53
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00							PKG:6,11	
53-00-00-200-802	^S	PILOT DOOR FRAMING - CHECK FOR CRACKS AND LOOSE RIVETS					Service	ATA:53
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00							PKG:6,11	
53-00-00-210-802	^S	EXTERNAL SURFACES - CHECK (REFER TO 53-00-00-61, PARAGRAPH 1)					Service	ATA:53
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00							PKG:1,5,6,7,8,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00-00-210-803	^S	EXTERNAL SURFACES - CHECK (REFER TO PARAGRAPH 2)						Service ATA:53
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								PKG:6,11
53-00-00-280-801		UPPER FUSELAGE STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION						Service ATA:53
	MOS	29-Sep-21	T:168 (+16m/-16m)		29-Sep-35	29-Jan-37	3625 d (+488)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5299 (+600)	
WC#: 53.020	AFL	0						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-280-802		LARGE DOOR FRAMING - CHECK DOOR FRAMING AND STRUCTURE JUNCTIONS FORCRACKS AND LOOSE RIVETS.						Service ATA:53
	MOS	29-Sep-21						
	HRS	0	3000 (+300/-300)		3000	3300	2299 (+300)	
WC#: 53.040	AFL	0						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								
53-00-00-900-801		FUSELAGE						Component ATA:53
PN:PN	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	16200	TSN 0	16200		15499	
WC#: 53.080	AFL	0	12000	TSN 0	12000		11517	
	FLTS	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
53-20-00-200-801	^S	DRAIN UNDER FLOOR - CHECK THAT DRAIN HOLES ARE NOT CLOGGED. CHECK GOOD CONDITION OF STRAINER SEAL OR SHUTTER. CHECK CLEANLINESS AND CORRECT ATTACHMENT OF STRAINER OR SEAT AND SHUTTER.CHECK THAT EMERGENCY EXIT DRAIN IS NOT CLOGGED						Service ATA:53
	MOS	01-Aug-25	12					
	HRS	701						
WC#: 53.050	AFL	483						
PROC. REF: AMM 53-20-00PROC. REF: AMM 53-20-00								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-900-801	FRONT FUSELAGE							Component ATA:53
PN:T850L0005	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1072	HRS	0		TSN 0				
WC#: 53.060	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
53-40-00-900-801	REAR FUSELAGE							Component ATA:53
PN:T850K7002	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:1072	HRS	0		TSN 0				
WC#: 53.070	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
53-60-00-200-801 ^S	FLOOR PANELS - CHECK FOR CONDITION AND DENTS.							Service ATA:53
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-60-00PROC. REF: AMM 53-60-00								
53-70-00-200-801 ^S	PEDESTAL - CHECK FOR CRACKS AND EVIDENCE OF DAMAGE							Service ATA:53
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-70-00PROC. REF: AMM 53-70-00								
ATA 55 - STABILIZERS								
55-00-00-280-802	VERTICAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION							Service ATA:55
	MOS	29-Sep-21	T:120 (+12m/-12m)		29-Sep-31	29-Sep-32	2164 d (+366)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5299 (+600)	
WC#: 55.020	AFL	0						
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-00-00-280-803	HORIZONTAL STABILIZER STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION							Service ATA:55
	MOS	29-Sep-21	T:168 (+16m/-16m)		29-Sep-35	29-Jan-37	3625 d (+488)	
	HRS	0	T:6000 (+600/-600)		6000	6600	5299 (+600)	
	AFL	0						
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								
55-10-00-200-802 ^S	FIXED HORIZONTAL STABILIZER - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION.							Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								PKG:1,5,6,7,8,9 ,10 ,11
55-10-00-280-801	FIXED HORIZONTAL STABILIZER - DO THE FOLLOWING INSPECTIONS : - ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:55
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 55.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03								
55-10-00-900-801	LEFT HORIZONTAL STABILIZER							Component ATA:55
PN:T700A551016000000	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1420	HRS	0		TSN 0				
WC#: 55.110	AFL	0		TSN 0				
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								
55-10-00-900-801	RIGHT HORIZONTAL STABILIZER							Component ATA:55
PN:T700A551016000100	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1423	HRS	0		TSN 0				
WC#: 55.110	AFL	0		TSN 0				
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-00-200-801	^S	ELEVATORS - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK BONDING STRAPS FOR CONDITION. CHECK FITTINGS, BEARINGS AND HINGE PINS FOR CRACKS, EVIDENCE OF DAMAGE AND SLACK. CHECK ATTACHING BOLT SAFETYING. CHECK SLACK INTO THE ELEVATOR CONTROL.						Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 55-20-00PROC. REF: AMM 27-30-00, AMM 27-30-00, AMM 55-20-00								
55-20-00-200-803	^S	ELEVATOR TRIM TABS - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF BEARINGS AND HINGE PINS AS WELL AS TRIM TABS FOR SLACK .						Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								
55-20-00-280-801		ELEVATORS - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.						Service ATA:55
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 55.060	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02PROC. REF: AMM 51-20-00, AMM 51-20-02								
55-20-00-900-801	LEFT ELEVATOR							Component ATA:55
PN:T700A552000100400	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1424	HRS	0		TSN 0				
WC#: 55.070	AFL	0		TSN 0				
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								
55-20-00-900-801	RIGHT ELEVATOR							Component ATA:55
PN:T700A552000100500	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1426	HRS	0		TSN 0				
WC#: 55.070	AFL	0		TSN 0				
PROC. REF: AMM 55-20-00PROC. REF: AMM 55-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-00-200-803	^S	FIN - VISUALLY CHECK SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. CHECK FOR CRACKS AND SLACK AT FASTENERS ON FUSELAGE. CHECK FOR PAINT CONDITION.						Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								
55-30-00-280-801		FIN - DO THE FOLLOWING INSPECTIONS : - ULTRASONICS INSPECTION FOR METAL / METAL BONDINGS, - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS						Service ATA:55
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 55.040	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-03								
55-30-00-900-801		VERTICAL STABILIZER						Component ATA:55
PN:T700A553000100400	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1427	HRS	0		TSN 0				
WC#: 55.100	AFL	0		TSN 0				
PROC. REF: AMM 55-30-00PROC. REF: AMM 55-30-00								
55-40-00-200-801	^S	RUDDER - VISUALLY CHECK RUDDER AND HORN SKIN FOR CRACKS AND DENTS. CHECK CONDITION OF BONDING STRAP AND MAKE SURE THAT RUDDER DRAIN HOLES ARE NOT CLOGGED. CHECK FOR CONDITION, ATTACHMENT, CRACKS AND SLACK ON FITTINGS AND BEARINGS. VISUALLY CHECK THAT BOLTS ON UPPER AND CENTRAL BEARINGS AS WELL AS BEARING RIB NUT ARE SAFETIED.						Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
55-40-00-200-803	^S	RUDDER TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK ATTACHMENT AND CONDITION OF HINGE FITTINGS AND TRIM TAB FOR SLACK.						Service ATA:55
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-00-280-801	RUDDER - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:55
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 55.050	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 55-40-00PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 55-40-00								
55-40-00-640-801	RUDDER - SPRAY SICCATIVE OIL INSIDE THE TORQUE SHAFT.							Service ATA:55
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
	AFL	0						
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
55-40-00-900-801	RUDDER							Component ATA:55
PN:T700A554000100710	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1431	HRS	0		TSN 0				
WC#: 55.050	AFL	0		TSN 0				
PROC. REF: AMM 55-40-00PROC. REF: AMM 55-40-00								
ATA 56 - WINDOWS								
56-10-00-210-801 ^S	WINDSHIELD AND SIDE WINDOWS - CHECK FOR CONDITION.							Service ATA:56
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:1,5,6,7,8,9 ,10 ,11
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								
56-10-01-900-801	LEFT WINDSHIELD ASSY, (LH)							Component ATA:56
PN:SPSTBM700-1-5-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3395	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-01-900-801	RIGHT WINDSHIELD ASSY, (LH)							Component ATA:56
PN:SPSTBM700-2-5-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:3464	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
56-10-02-900-801	LEFT SIDE WINDOW							Component ATA:56
PN:TBM-8-2-00	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2303	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
56-10-02-900-801	RIGHT SIDE WINDOW							Component ATA:56
PN:TBM700 4.2.0	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2372	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
56-20-00-210-801 ^S	CABIN WINDOWS - CHECK FOR CONDITION.							Service ATA:56
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
							PKG:1,5,6,7,8,9 ,10 ,11	
PROC. REF: AMM 56-20-00PROC. REF: AMM 56-20-00								
ATA 57 - WINGS								
57-00-00-280-801	LEFT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION							Service ATA:57
	MOS	29-Sep-21	T:168 (+16m/-16m)	29-Sep-35	29-Jan-37	3625 d (+488)		
	HRS	0	T:6000 (+600/-600)	6000	6600	5299 (+600)		
WC#: 57.010	AFL	0						
PROC. REF: AMM 57-00-00PROC. REF: AMM 57-00-00								
57-00-00-280-802	RIGHT WING STRUCTURE - PERFORM A FATIGUE AND CORROSION INSPECTION							Service ATA:57
	MOS	29-Sep-21	T:168 (+16m/-16m)	29-Sep-35	29-Jan-37	3625 d (+488)		
	HRS	0	T:6000 (+600/-600)	6000	6600	5299 (+600)		
WC#: 57.010	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-00-00PROC. REF: AMM 57-00-00								
57-10-00-210-801	^S	L.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								PKG:7,11
57-10-00-210-802	^S	R.H. KARMANS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								PKG:7,11
57-20-00-200-801	^S	L.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-802	^S	R.H. WING - CHECK FOR LOOSE RIVETS AT UPPER SURFACE SKIN CONNECTION WITH 25 % AND 59 % SPARS.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-803	^S	L.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-200-804	^S	R.H. WING SPAR - CHECK FOR CRACKS OR CORROSION AT FASTENERS ON FUSELAGE AND MAIN LANDING GEARS.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:7,11
57-20-00-200-805	^S	L.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION.						Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:1,5,6,7,8,9 ,10 ,11
57-20-00-200-806	^S	R.H. WING - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK FOR LOOSE RIVETS. CHECK FOR PAINT CONDITION.						Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								PKG:1,5,6,7,8,9 ,10 ,11
57-20-00-900-801	LEFT WING							Component ATA:57
PN:T700F5720000006	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:LT1075	HRS	0	41600	TSN 0	41600		40899	
WC#: 57.010	AFL	0		TSN 0				
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								
57-20-00-900-801	RIGHT WING							Component ATA:57
PN:T700F5720000007	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:LT1075	HRS	0	41600	TSN 0	41600		40899	
WC#: 57.010	AFL	0		TSN 0				
PROC. REF: AMM 57-20-00PROC. REF: AMM 57-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-30-00-200-803	^S	L.H. WINGLET -CHECK FOR CONDITION, ATTACHMENT, SCRATCHES AND DENTS						Service ATA:57
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-30-00, AMM 57-30-00PROC. REF: AMM 57-30-00, AMM 57-30-00								PKG:7,10 ,11
57-30-00-200-804	^S	R.H. WINGLET - CHECK FOR CONDITION, ATTACHMENT, SCRATCHES AND DENTS						Service ATA:57
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-30-00, AMM 57-30-00PROC. REF: AMM 57-30-00, AMM 57-30-00								PKG:7,10 ,11
57-50-00-200-801	^S	L.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:7,11
57-50-00-200-802	^S	R.H. FLAP GUIDE RAIL FAIRINGS - CHECK FOR CONDITION AND ATTACHMENT.						Service ATA:57
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:7,11
57-50-00-200-803	^S	L.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS.						Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								PKG:1,5,7,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-200-804	^S	R.H. FLAP - VISUALLY CHECK SKIN FOR CRACKS AND DENTS. CHECK ALIGNMENT OF RED PAINT MARKS ON CARRIAGES AND BOLT AND SCREW HEADS TO MAKE SURE THERE ARE NOT LOOSE. VISUALLY CHECK GUIDE RAILS AND ROLLERS FOR SLACK, MARKS AND CRACKS.					Service	ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00							PKG:1,5,7,9 ,10 ,11	
57-50-00-200-805	^S	L.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR.					Service	ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00							PKG:7,9 ,10 ,11	
57-50-00-200-806	^S	R.H. FLAP - CHECK FOR CRACKS ON GUIDE RAIL JUNCTION FITTINGS ON SPAR.					Service	ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00							PKG:7,9 ,10 ,11	
57-50-00-200-809	^S	R.H. FLAP CARRIAGES - CHECK FOR CRACKS					Service	ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00							PKG:7,9 ,10 ,11	
57-50-00-200-815	^S	L.H. FLAP CARRIAGES - CHECK FOR CRACKS.					Service	ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00							PKG:7,9 ,10 ,11	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-280-801	L.H. FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:57
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 57.020	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-50-00-280-802	R.H. FLAP - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:57
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 57.020	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-50-00-640-801 ^S	L.H. FLAP - LUBRICATE LH FLAP ROLLERS							Service ATA:57
	MOS	01-Aug-25	12					
	HRS	701						
	AFL	483						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:12
57-50-00-640-802 ^S	R.H. FLAP - LUBRICATE RH FLAP ROLLERS							Service ATA:57
	MOS	01-Aug-25	12					
	HRS	701						
	AFL	483						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:12
57-50-00-900-802	LEFT FLAP							Component ATA:57
PN:T700A575500100800	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1466	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-00-900-802	RIGHT FLAP							Component ATA:57
PN:T700A575500100900	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1448	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 57-50-00PROC. REF: AMM 57-50-00								
57-60-00-200-803 ^S	AILERON TRIM TAB - VISUALLY CHECK TRIM TAB SKIN FOR CRACKS, DENTS AND LOOSE RIVETS. VISUALLY CHECK HINGES FOR CONDITION AND TRIM TAB FOR SLACK. CHECK BONDING STRAP FOR CONDITION.							Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-60-00-210-801 ^S	L.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS.							Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-60-00-210-802 ^S	R.H. AILERON - VISUALLY CHECK AILERON SKIN FOR CRACKS AND DENTS.							Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-60-00-280-801	L.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:57
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 57.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-280-802	R.H. AILERON - DO THE FOLLOWING INSPECTIONS : - FIBROSCOPIC INSPECTION FOR INTERNAL BONDINGS, - TAPING INSPECTION FOR SKIN BONDINGS.							Service ATA:57
	MOS	29-Sep-21						
	HRS	0	1200 (+10%/-10%)		1200	1320	499 (+120)	
WC#: 57.030	AFL	0						
PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01PROC. REF: AMM 51-20-00, AMM 51-20-02, AMM 51-20-01								
57-60-00-900-801	LEFT AILERON							Component ATA:57
PN:T700A576003501301	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1417	HRS	0		TSN 0				
WC#: 57.030	AFL	0		TSN 0				
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-60-00-900-801	RIGHT AILERON							Component ATA:57
PN:T700A576003501401	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1431	HRS	0		TSN 0				
WC#: 57.030	AFL	0		TSN 0				
PROC. REF: AMM 57-60-00, AMM 57-60-00PROC. REF: AMM 57-60-00, AMM 57-60-00								
57-70-00-210-801 ^S	L.H. SPOILER - CHECK FOR CONDITION.							Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
57-70-00-210-802 ^S	R.H. SPOILER - CHECK FOR CONDITION.							Service ATA:57
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
57-70-00-900-801	LEFT SPOILER							Component ATA:57
PN:T700A576500400400	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1397	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
57-70-00-900-801	RIGHT SPOILER							Component ATA:57
PN:T700A576500400500	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SC1404	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
PROC. REF: AMM 57-70-00PROC. REF: AMM 57-70-00								
ATA 61 - PROPELLERS/PROPULSORS								
61-00-00-200-801	NO. 1 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION							Service ATA:61
	MOS	01-Aug-25	12		01-Aug-26		279 d	
	HRS	701	200		(901) 901		200	
PROC. REF: MM 30-61-80PROC. REF: MM 30-61-80								
61-00-00-200-802	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP							Service ATA:61
	MOS	01-Aug-25	12		01-Aug-26		279 d	
	HRS	701	600		(1301) 1301		600	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-804	NO. 1 PROPELLER - PRE-FLIGHT CHECKS							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-805	NO. 1 PROPELLER - OPERATIONAL CHECKS							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-00-00-200-806	NO. 1 PROPELLER - INSPECT EXPOSED SECTION USING COIN-TAP							Service ATA:61
	MOS	29-Sep-21						
	HRS	0	1200		(1200) 1200		499	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-00-00-200-808	NO. 1 PROPELLER - DE-ICE COMPONENT OVERHAUL							Service ATA:61
	MOS	29-Sep-21	72		29-Sep-27		703 d	OVERHAUL
	HRS	0	4000		(4000) 4000		3299	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-10-00-200-801	NO. 1 PROPELLER - PERFORM A PERIODIC INSPECTION							Service ATA:61
	MOS	01-Aug-25	12		01-Aug-26		279 d	
	HRS	701	400		(1101) 1101		400	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-802	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-803	NO. 1 PROPELLER - LIGHTNING STRIKE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								
61-10-00-200-804	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								
61-10-00-200-805	NO. 1 PROPELLER - FIRE/HEAT DAMAGE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47, MM 30-61-80PROC. REF: POM 61-00-47, MM 30-61-80								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-10-00-200-806	NO. 1 PROPELLER - SUDDEN STOPPAGE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-807	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-200-808	NO. 1 PROPELLER - LONG TERM STORAGE							Service ATA:61
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-10-00-220-801	BETA RING AND CARBON BLOCK - DO A DIMENSIONAL CHECK.							Service ATA:61
	MOS	01-Aug-25	12 (+10%/-10%)	Adj -64d	29-May-26	05-Jul-26	215 d (+37)	
	HRS	701	600 (+10%/-10%)		1301	1361	600 (+60)	
WC#: 61.020	AFL	483						
PROC. REF: POM 61-00-47, POM 61-00-49, POM 61-00-47, POM 61-00-47PROC. REF: POM 61-00-47, POM 61-00-49, POM 61-00-47, POM 61-00-47								
61-10-01-640-801	NO. 1 PROPELLER - PROPELLER - LUBRICATE							Service ATA:61
	MOS	01-Aug-25	12		01-Aug-26		279 d	
	HRS	701	400		(1101) 1101		400	
PROC. REF: AMM 61-10-01 (A1), AMM 61-10-01-301, AMM 61-10-01, AMM 61-10-01, POM 61-00-47PROC. REF: AMM 61-10-01 (A1), AMM 61-10-01-301, AMM 61-10-01, AMM 61-10-01, POM 61-00-47								
61-10-01-640-802	NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service ATA:61
	MOS	01-Aug-25	12		01-Aug-26		279 d	CPCP
	HRS	701	400		(1101) 1101		400	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-10-01-730-801		NO. 1 PROPELLER - PROPELLER - OVERHAUL						Service ATA:61
	MOS	29-Sep-21	72		29-Sep-27		703 d	OVERHAUL
	HRS	0	4000		(4000) 4000		3299	
PROC. REF: POM 61-00-47PROC. REF: POM 61-00-47								
61-15-00-900-801		NO. 1 PROPELLER - NO. 1 BLADE						Component ATA:61
PN:NC8834K	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:C8820	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-802		NO. 1 PROPELLER - NO. 2 BLADE						Component ATA:61
PN:NC8834K	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:C8891	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-803		NO. 1 PROPELLER - NO. 3 BLADE						Component ATA:61
PN:NC8834K	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:C8892	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-804		NO. 1 PROPELLER - NO. 4 BLADE						Component ATA:61
PN:NC8834K	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:C8893	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-805		NO. 1 PROPELLER - NO. 5 BLADE						Component ATA:61
PN:NC8834K	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:C8936	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-15-00-900-810		NO. 1 PROPELLER - PROPELLER HUB						Component ATA:61
PN:PN	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-20-00-200-801	^S	PROPELLER GOVERNOR - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						Service ATA:61
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,6,7,8,9 ,10 ,11
61-20-00-730-801		NO. 1 ENGINE - PROPELLER GOVERNOR - OVERHAUL						Component ATA:61
PN:3074158-01	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:22579382	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
61-20-01-200-802	^S	L3 FEATHER SOLENOID/OVERSPEED GOVERNOR - CHECK FOR ATTACHMENT, LEAKS AND FOR ROUTING AND CONDITION OF WIRING						Service ATA:61
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 61-20-00, AMM 61-20-00PROC. REF: AMM 61-20-00, AMM 61-20-00								PKG:5,6,7,8,9 ,10 ,11
61-20-01-710-802	^S	L3 FEATHER SOLENOID/OVERSPEED GOVERNOR - DO A GROUND OPERATIONAL TEST, ENGINE RUNNING						Service ATA:61
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 61-20-01PROC. REF: AMM 61-20-01								PKG:5,9 ,10 ,11
61-20-01-730-802		L3 FEATHER SOLENOID / OVERSPEED GOVERNOR - OVERHAUL (POST-MOD70-0324-00)						Service ATA:61
PN:PN	MOS	29-Sep-21						OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)		3500	3850	2799 (+350)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61-20-01-900-802	L3 FEATHER SOLENOID / OVERSPEED GOVENOR							Component ATA:61
PN:PN	MOS/MSC	29-Sep-21	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 61-20-01PROC. REF: AMM 61-20-01								
61-30-00-900-801	SPINNER DOME							Component ATA:61
PN:105044P	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:2102756	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 61-10-02, AMM 61-10-02PROC. REF: AMM 61-10-02, AMM 61-10-02								
61PR1	NO. 1 PROPELLER							Component ATA:61
PN:HC-E5N-3C/NC8834K	MOS/MSC	29-Sep-21	PP/C	TSN 0				
SN:RJ594	HRS	0		TSN 0				
WC#: 61.PR1	AFL	0		TSN 0				
PROC. REF: AMM 61-10-01, AMM 61-10-01PROC. REF: AMM 61-10-01, AMM 61-10-01								
ATA 71 - POWER PLANT								
71-00-00-100-801 ^S	IF NECESSARY, CLEAN ENGINE AND COWLINGS.							Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 71-00-00, AMM 12-22-05PROC. REF: AMM 71-00-00, AMM 12-22-05								
71-00-00-200-801 ^S	POWERPLANT - CHECK							Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 71-00-00PROC. REF: AMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-200-802	^S	FIREWALL - CHECK FOR CONDITION AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 53-00-00PROC. REF: AMM 53-00-00								PKG:5,11
71-00-00-200-804		FIREWALL - CHECK THE FIREWALL AND THE FRONT CARGO COMPARTMENT UPHOLSTERY PANELS						Service ATA:71
	MOS	29-Sep-21	120 (+10%/-10%)		29-Sep-31	29-Sep-32	2164 d (+366)	
	HRS	0						
WC#: 25.010	AFL	0						
PROC. REF: AMM 25-50-03, AMM 25-50-03, AMM 25-50-03PROC. REF: AMM 25-50-03, AMM 25-50-03, AMM 25-50-03								
71-00-00-6.A		NO. 1 ENGINE - COMPRESSOR DESALINATION WASH						Service ATA:71
	MOS/MSC	01-Aug-25	A/R					
	HRS	701						
	ENC	483						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-00-6.C		NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH						Service ATA:71
	MOS/MSC	01-Aug-25	A/R					
	HRS	701						
	ENC	483						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-00.10		NO. 1 ENGINE - FCU CHECKS						Service ATA:71
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
71-00-00.13		NO. 1 ENGINE - TORQUEMETER FUNCTION CHECK						Service ATA:71
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-CA-820-801	^S	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION						Service ATA:71
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								PKG:1
71-00-CA-970-801		NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)						Service ATA:71
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: SIL GEN-055PROC. REF: SIL GEN-055								
71-10-00-210-802	^S	POWER PLANT COWLING ASSEMBLY - CHECK FOR CONDITION, ATTACHMENT,SCRATCHES AND DENTS. CHECK FOR EROSION AT ENGINE COWLING 122 AIR INTAKE.						Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-10-00PROC. REF: AMM 71-10-00								PKG:5,6,7,8,9 ,10 ,11
71-20-00-200-801	^S	ENGINE MOUNT - CHECK FOR ATTACHMENT, CRACKS AND EVIDENCE OF DAMAGE. CHECK ELASTOMER VIBRATION ISOLATORS FOR CONDITION AND ATTACHMENT.						Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								PKG:5,9 ,10 ,11
71-20-00-900-801		LEFT LOWER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.						Service ATA:71
	MOS	29-Sep-21						LIFE LIMIT
	HRS	0	3500		3500		2799	
WC#: 71.010	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-900-801	LEFT UPPER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	29-Sep-21						LIFE LIMIT
	HRS	0	3500		3500		2799	
WC#: 71.010	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-801	RIGHT LOWER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	29-Sep-21						LIFE LIMIT
	HRS	0	3500		3500		2799	
WC#: 71.020	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-801	RIGHT UPPER VIBRATION ISOLATORS - REPLACE ELASTOMER ONLY.							Service ATA:71
	MOS	29-Sep-21						LIFE LIMIT
	HRS	0	3500		3500		2799	
WC#: 71.020	AFL	0						
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-802	ENGINE MOUNT							Component ATA:71
PN:T700F712000500200	MOS/MSC	29-Sep-21	E/C	TSN 0				
SN:213	HRS	0		TSN 0				
WC#: 71.040	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00, AMM 71-20-00PROC. REF: AMM 71-20-00, AMM 71-20-00								
71-20-00-900-821	PYLON STRUCTURE							Component ATA:71
PN:T700J537010000010	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:TB120	HRS	0		TSN 0				
WC#: 71.050	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
71-60-01-200-803 ^S	INERTIAL SEPARATOR - CHECK FOR CONDITION, ATTACHMENT, DENTS AND SCRATCHES							Service ATA:71
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-60-01-200-804	^S	INERTIAL SEPERATOR - CHECK BELLOW FOR CONDITION						Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:5,9 ,10 ,11
71-60-01-200-805	^S	INERTIAL SEPERATOR - CHECK THAT DRAIN HOLE IS NOT CLOGGED						Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:5,6,7,8,9 ,10 ,11
71-60-01-720-801	^S	INERTIAL SEPERATOR - OPERATIONAL TEST (REFER TO 71-60-01-501)						Service ATA:71
	MOS	29-Sep-21	24					
	HRS	0	400					
	AFL	0						
PROC. REF: AMM 71-60-01PROC. REF: AMM 71-60-01								PKG:10 ,11
71-60-01-900-801		INERTIAL SEPARATOR ACTUATOR						Component ATA:71
PN:JA23372-1000-2	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:482	HRS	0		TSN 0				
WC#: 71.030	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01, AMM 71-60-01								
71-60-02-200-801	^S	ENGINE PLENUM CHAMBER - CHECK.						Service ATA:71
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-60-02, AMM 71-60-02PROC. REF: AMM 71-60-02, AMM 71-60-02								PKG:5,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-60-02-200-802	^S	ENGINE PLENUM CHAMBER - CHECK SEALS FOR CONDITION (REFER TO 71-60-02-601)						Service ATA:71
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-60-02, AMM 71-60-02, AMM 71-60-02PROC. REF: AMM 71-60-02, AMM 71-60-02, AMM 71-60-02								PKG:5,9 ,10 ,11
71-70-00-200-801	^S	ECOLOGICAL TANK AND ENGINE DRAINS - CHECK HOSES AND RIGID PIPES FOR ATTACHMENT, ROUTING AND CONDITION.						Service ATA:71
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 71-70-00PROC. REF: AMM 71-70-00								PKG:5,11
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3071016-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PCE-RV0737	HRS	0		TSN 0				
WC#: 71.EN1	AFL	0		TSN 0				
PROC. REF: SIL F731-88, AMM 71-00-00, AMM 71-00-00PROC. REF: SIL F731-88, AMM 71-00-00, AMM 71-00-00								
ATA 72 - ENGINE								
72-00-00-100-801	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:72
	MOS/MSC	01-Aug-25	A/R					
	HRS	701						
	ENC	483						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-801	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:72
	MOS/MSC	23-Aug-22	A/R					
	HRS	172.3						
	ENC	86						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-100-801	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH							Service ATA:72
	MOS/MSC	01-Aug-25	A/R					
	HRS	701						
	ENC	483						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-801	NO. 1 ENGINE - EXTERNAL ENGINE WASH							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00PROC. REF: AMM 71-00-00 (A1), AMM 71-00-00, EMM 71-00-00								
72-00-00-100-805	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE				0 - 7 DAYS			Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-806	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE 8 - 28 DAYS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-807	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE 29-90 DAYS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-100-808	NO. 1 ENGINE - ENGINE PRESERVATION - IF ENGINE IS INACTIVE FOR PERIODS EXCEEDING 90 DAYS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-100-809	NO. 1 ENGINE - ENGINE DEPRESERVATION							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-200-801 ^S	ENGINE - CHECK FOR GENERAL CONDITION, ATTACHMENT, LINKAGE AND EVIDENCE OF DAMAGE.							Service ATA:72
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,6,7,8,9 ,10 ,11
72-00-00-290-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION WITH BOROSCOPE							Service ATA:72
	MOS	01-Aug-25						
	HRS	701	400 (+10%)		(1101) 1101	1141	400 (+40)	
	ENC	483						
PROC. REF: EMM 72-00-00, EMM 72-00-00PROC. REF: EMM 72-00-00, EMM 72-00-00								
72-00-00-710-801 ^S	ENGINE - PERFORM A TORQUE LIMITER FUNCTION CHECK							Service ATA:72
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								PKG:5,6,7,8,9 ,10 ,11
72-00-00-730-801	NO. 1 ENGINE - ENGINE - INSPECT HOT SECTION (HSI)							Service ATA:72
	MOS	29-Sep-21						
	HRS	0	1750 (+250)		(1750) 1750	2000	1049 (+250)	
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-730-802	NO. 1 ENGINE - ENGINE - OVERHAUL							Service ATA:72
	MOS	29-Sep-21						OVERHAUL
	HRS	0	3500		(3500) 3500		2799	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-00-00-9.F	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER LINER							Service ATA:72
	MOS/MSC	21-Jan-25	A/R					
	HRS	575.9						
	ENC	422						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.G	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT STATOR ASSEMBLY							Service ATA:72
	MOS/MSC	21-Jan-25	A/R					
	HRS	575.9						
	ENC	422						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.H	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT BLADES AND SHROUD SEGMENTS							Service ATA:72
	MOS/MSC	21-Jan-25	A/R					
	HRS	575.9						
	ENC	422						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00-9.I	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE CT DISK FACE							Service ATA:72
	MOS/MSC	10-Sep-24	A/R					
	HRS	546.7						
	ENC							
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-00.5	NO. 1 ENGINE - ENGINE CONDITION TREND MONITORING SYSTEM							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00.6	NO. 1 ENGINE - FAULT ISOLATION							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-801	NO. 1 ENGINE - PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-802	NO. 1 ENGINE - OVERSPEED							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-803	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-804	NO. 1 ENGINE - OVER TEMPERATURE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-805	NO. 1 ENGINE - OVER TORQUE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-05-050-806	NO. 1 ENGINE - IMMERSION IN WATER							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-807	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-808	NO. 1 ENGINE - MATERIAL INGESTION (E.G., ICE, STONES, ETC.)							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-809	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION (E.G. RAGS, PLASTIC BAGS, ETC.							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-810	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-811	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-05-050-812	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-813	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-814	NO. 1 ENGINE - HEAVY/HARD LANDING							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-815	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-816	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-817	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-05-050-818	NO. 1 ENGINE - HIGH OIL PRESSURE							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-819	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-820	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING, SCRAPING							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-821	NO. 1 ENGINE - PROPELLER WIND MILLING AFTER IN-FLIGHT SHUTDOWN							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-822	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-823	NO. 1 ENGINE - CONTAMINATION OF OIL WITH CARBON DEBRIS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-05-050-824	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN (COARSE HAT-TYPE SCREEN ATTACHED TO THE INNER END OF THE FILTER)							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-825	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-05-050-826	NO. 1 ENGINE - HIGH TORQUE INDICATION AT LOW POWER							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
72-00-CA-200-801 ^S	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FORATTACHMENT							Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-802 ^S	NO. 1 ENGINE - CHECK CLAMPS,BRACKETS,TUBES/LINES,LINKAGES FOR CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-CA-200-803	^S	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-804	^S	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-200-805	^S	NO. 1 ENGINE - INSPECT ACCESSORIES FOR OIL AND FUEL LEAKS AS APPLICABLE						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
72-00-CA-290-801	^S	NO. 1 ENGINE - VISUAL INSPECT FIRST-STAGECOMPRESSORROTOR WITH A MIRROR OR A BORESCOPE						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								PKG:1
72-00-CA-610-801		NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE						Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 72 - ENGINE									
72-10-00-200-801	^S	PROPELLER DRIVE SHAFT SEAL - CHECK FOR LEAKS AND ATTACHMENT.						Service	ATA:72
	MOS	01-Aug-25	12 (+1m/-1m)						
	HRS	701	200 (+10/-10)						
	AFL	483							
							PKG:5,6,7,8,9 ,10 ,11		
PROC. REF: EMM 72-10-00PROC. REF: EMM 72-10-00									
72-10-CA-900-801		NO. 1 ENGINE - NO.1 SECOND STAGE REDUCTION PLANET GEAR						Component	ATA:72
	PN:3008012	MOS/MSC	29-Sep-21	O/C	TSN 0				
	SN:PKAA921184	HRS	0		TSN 0				
		ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-10-CA-900-801		NO. 1 ENGINE - NO.2 SECOND STAGE REDUCTION PLANET GEAR						Component	ATA:72
	PN:3008012	MOS/MSC	29-Sep-21	O/C	TSN 0				
	SN:PKAA921185	HRS	0		TSN 0				
		ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-10-CA-900-801		NO. 1 ENGINE - NO.3 SECOND STAGE REDUCTION PLANET GEAR						Component	ATA:72
	PN:3008012	MOS/MSC	29-Sep-21	O/C	TSN 0				
	SN:PKAA921190	HRS	0		TSN 0				
		ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-10-CA-900-801		NO. 1 ENGINE - NO.4 SECOND STAGE REDUCTION PLANET GEAR						Component	ATA:72
	PN:3008012	MOS/MSC	29-Sep-21	O/C	TSN 0				
	SN:PKAA922653	HRS	0		TSN 0				
		ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-10-CA-900-801		NO. 1 ENGINE - NO.5 SECOND STAGE REDUCTION PLANET GEAR						Component	ATA:72
	PN:3008012	MOS/MSC	29-Sep-21	O/C	TSN 0				
	SN:PKAA922663	HRS	0		TSN 0				
		ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-10-CA-900-802	NO. 1 ENGINE - 2ND-STAGE REDUCTION COUPLING FLEX SHAFT							Component ATA:72
PN:3012286	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA920252	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-803	NO. 1 ENGINE - 2ND-STAGE REDUCTION 46 TEETH SUN GEAR							Component ATA:72
PN:3023250	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA919199	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-804	NO. 1 ENGINE - 1ST-STAGE ADAPTER-SPLINED CARRIER							Component ATA:72
PN:3023252	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA919055	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-805	NO. 1 ENGINE - 2ND-STAGE REDUCTION CARRIER							Component ATA:72
PN:3027977	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA917767	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-806	NO. 1 ENGINE - BALL BEARING							Component ATA:72
PN:3072721-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:BB0321675	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-807	NO. 1 ENGINE - ROLLER FLANGED BEARING							Component ATA:72
PN:3028007	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:BB0347324	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-10-CA-900-808	NO. 1 ENGINE - 2ND-STAGE REDUCTION RING GEAR							Component ATA:72
PN:3028683	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA922373	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-809	NO. 1 ENGINE - FRONT PROPELLER REDUCTION GEAR BOX HOUSING ASSEMBLY							Component ATA:72
PN:3029022	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA15H293	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-810	NO. 1 ENGINE - PROPELLER SHAFT							Component ATA:72
PN:3048695-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:EAAF000C763	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-811	NO. 1 ENGINE - PROPELLER SHAFT ASSEMBLY							Component ATA:72
PN:3078250-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:EAAF000C763	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-10-CA-900-812	NO. 1 ENGINE - PROPELLER SHAFT AND SLEEVE SET							Component ATA:72
PN:3078313-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:EAAF000C763	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-11-CA-900-801	NO. 1 ENGINE - 1ST-STAGE REDUCTION GEAR RING							Component ATA:72
PN:3059927-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA921649	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-11-CA-900-802	NO. 1 ENGINE - 1ST-STAGE REDUCTION CARRIER							Component ATA:72
PN:3101419-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA922402	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-20-00-200-801 ^S	ENGINE AIR INTAKE SCREEN - CHECK FOR CLEANLINESS AND ATTACHMENT.							Service ATA:72
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-20-00.8	NO. 1 ENGINE - COMPRESSOR AIR INLET APPROVED REPAIRS							Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								
72-20-CA-200-801 ^S	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS							Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
								PKG:1
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								
72-20-CA-200-802 ^S	NO. 1 ENGINE - INSPECT WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE THE COMPRESSOR INLET CASE OVERALL SURFACE AREAS ANDSTRUTS FOR CORROSION							Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
								PKG:1
PROC. REF: EMM 72-20-00PROC. REF: EMM 72-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-00-200-801	^S	GENERATOR TURBINE CASE - CHECK FOR CRACKS, DISTORTIONS AND CORROSION.						Service ATA:72
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,10 ,11
72-30-01-200-801	^S	FIRESEAL MOUNT RINGS - CHECK FOR GENERAL CONDITION AND ATTACHMENT.						Service ATA:72
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,10 ,11
72-30-05.6		NO. 1 ENGINE - COMPRESSOR ROTOR APPROVED REPAIRS FIRST STAGE COMPRESSOR ROTOR						Service ATA:72
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-30-05PROC. REF: EMM 72-30-05								
72-30-CA-200-801	^S	NO. 1 ENGINE - INSPECT/CHECK GASGENERATORCASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FORCRACKS, DISTORTION, AND CORROSION						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								PKG:1
72-30-CA-200-802	^S	NO. 1 ENGINE - CHECK FIRESEALMOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-CA-900-801	NO. 1 ENGINE - SHAFT,STUB, COMPRESSOR ROTOR, FLANGED ROLLER BEARING							Component ATA:72
PN:3073900-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348403	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-20-00, EMM 72-30-01PROC. REF: EMM 72-20-00, EMM 72-30-01								
72-30-CA-900-802	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3042701	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:MCAKAXXP214	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: EMM 72-30-05PROC. REF: EMM 72-30-05								
72-30-CA-900-803	NO. 1 ENGINE - COUPLING, POWER TUBINE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073900-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348451	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-804	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT							Component ATA:72
PN:3043063	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:PKAAA924393	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-805	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040942	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:FRAEUACA72	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-CA-900-806	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040933	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:FRAEUACA34	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-807	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040944	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:EAAF000C595	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-808	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3036898	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:FRAEUABD98	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		23517	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-809	NO. 1 ENGINE - REAR HUB COMPRESSOR COUPLING							Component ATA:72
PN:3112612-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA919881	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-CA-900-810	NO. 1 ENGINE - NO.1 BALL BEARING							Component ATA:72
PN:3113589-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FAA2104885	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-CA-900-811	NO. 1 ENGINE - COMPRESSOR ROTOR STUB SHAFT							Component ATA:72
PN:3120663-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA16H181	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-31-CA-900-801	NO. 1 ENGINE - GAS GENERATOR CASE							Component ATA:72
PN:3123229-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA17H673	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-04PROC. REF: EMM 72-30-04								
72-40-CA-900-801	NO. 1 ENGINE - OUTER LINER COMBUSTION CHAMBER							Component ATA:72
PN:3127354-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FTA354A0237	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
72-40-CA-900-802	NO. 1 ENGINE - INNER LINER COMBUSTION CHAMBER							Component ATA:72
PN:3116790-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA17H556	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
72-50-CA-200-801 ^S	NO. 1 ENGINE - INSPECT/CHECK EXHAUSTDUCT FOR CRACKS AND DISTORTION							Service ATA:72
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 72-50-05PROC. REF: EMM 72-50-05								PKG:1
72-50-CA-900-801	NO. 1 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY							Component ATA:72
PN:3070673-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:LPA000028926	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-CA-900-802	NO. 1 ENGINE - BALL, FLANGED BEARING							Component ATA:72
PN:3112696-03	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FCN548245	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-803	NO. 1 ENGINE - COMPRESSOR TURBINE DISK							Component ATA:72
PN:3053740-01	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:YUAB001T142	HRS	0		TSN 0				
	ENC	0		TSN 0	(8000) 8000 (M)		7517	
	ACCCYC	0	8000	TSN 0				
PROC. REF: EMM 72-50-02PROC. REF: EMM 72-50-02								
72-50-CA-900-804	NO. 1 ENGINE - REPLACE GAS GENERATOR MODULE COMPRESSOR TURBINE BLADES							Service ATA:72
PN:PN	MOS/MSC	29-Sep-21	O/C					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-805	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037312	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:A004Y86X	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		14517	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-806	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037313	MOS	29-Sep-21		TSN 0				LIFE LIMIT
SN:YUAB001T116	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		14517	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-CA-900-809	NO. 1 ENGINE - FIRST STAGE SUN GEAR							Component ATA:72
PN:3059928-01	MOS/MSC	29-Sep-21	A/R	TSN 0				
SN:PKAAA917462	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-810	NO. 1 ENGINE - NO. 1 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	29-Sep-21	A/R	TSN 0				
SN:PKAAA926661	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-810	NO. 1 ENGINE - NO. 2 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	29-Sep-21	A/R	TSN 0				
SN:PKAAA926662	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-810	NO. 1 ENGINE - NO. 3 FIRST STAGE RGB PLANET GEAR							Component ATA:72
PN:3059924-01	MOS/MSC	29-Sep-21	A/R	TSN 0				
SN:PKAAA926664	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-811	NO. 1 ENGINE - TURBINE 3RD STAGE VANE-RING							Component ATA:72
PN:3078643CL01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PDANH24K01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-CA-900-812	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR ASSEMBLY							Component ATA:72
PN:3040931CL07	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PDANHRRF01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-CA-900-813		NO. 1 ENGINE - POWER TURBINE VANE-RING						Component ATA:72
PN:3040982CL01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:BHAMLDPN01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-801		NO. 1 ENGINE - HOUSING POWER TURBINE STATOR ASSEMBLY						Component ATA:72
PN:3043705-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:SGA0119971	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
72-51-CA-900-802		NO. 1 ENGINE - TURBINE EXHAUST DUCT						Component ATA:72
PN:3043919-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA18H477	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-803		NO. 1 ENGINE - POWER TURBINE COUPLING						Component ATA:72
PN:3107525-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA923366	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-804		NO. 1 ENGINE - POWER TURBINE SHAFT						Component ATA:72
PN:3109251-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:RWA14H896	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-805		NO. 1 ENGINE - POWER TURBINE COUPLING SHAFT						Component ATA:72
PN:3113744-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA921846	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-807	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH23C424	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-808	NO. 1 ENGINE - NO. 2 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH23C425	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-809	NO. 1 ENGINE - NO. 3 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH24C440	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-810	NO. 1 ENGINE - NO. 4 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH24C448	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-811	NO. 1 ENGINE - NO. 5 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH24C451	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-812	NO. 1 ENGINE - NO. 6 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH24C474	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-813	NO. 1 ENGINE - NO. 7 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH27C457	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-814	NO. 1 ENGINE - NO. 8 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH27C467	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-815	NO. 1 ENGINE - NO. 9 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH27C475	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-816	NO. 1 ENGINE - NO. 10 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH27C484	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-817	NO. 1 ENGINE - NO. 11 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH27C492	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-818	NO. 1 ENGINE - NO. 12 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C150	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-819	NO. 1 ENGINE - NO. 13 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C155	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-820	NO. 1 ENGINE - NO. 14 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C175	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-821	NO. 1 ENGINE - NO. 15 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C176	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-822	NO. 1 ENGINE - NO. 16 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C177	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-823	NO. 1 ENGINE - NO. 17 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C180	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-824	NO. 1 ENGINE - NO. 18 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C181	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-825	NO. 1 ENGINE - NO. 19 2ND-STAGE POWER TURBINE(3RD STAGE TURBIBE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C182	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-826	NO. 1 ENGINE - NO. 20 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C185	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-827	NO. 1 ENGINE - NO. 21 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C188	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-828	NO. 1 ENGINE - NO. 22 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C190	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-829	NO. 1 ENGINE - NO. 23 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C194	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-830	NO. 1 ENGINE - NO. 24 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C195	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-831	NO. 1 ENGINE - NO. 25 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C212	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-832		NO. 1 ENGINE - NO. 26 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C218	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-833		NO. 1 ENGINE - NO. 27 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C273	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-834		NO. 1 ENGINE - NO. 28 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C274	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-835		NO. 1 ENGINE - NO. 29 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C281	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-836		NO. 1 ENGINE - NO. 30 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C283	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-837	NO. 1 ENGINE - NO. 31 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C294	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-838	NO. 1 ENGINE - NO. 32 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C297	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-839	NO. 1 ENGINE - NO. 33 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C298	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-840	NO. 1 ENGINE - NO. 34 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C305	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-841	NO. 1 ENGINE - NO. 35 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C306	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-842	NO. 1 ENGINE - NO. 36 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C308	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-843	NO. 1 ENGINE - NO. 37 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C310	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-844	NO. 1 ENGINE - NO. 38 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C314	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-845	NO. 1 ENGINE - NO. 39 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C315	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-846	NO. 1 ENGINE - NO. 40 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C316	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-847		NO. 1 ENGINE - NO. 41 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C324	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-848		NO. 1 ENGINE - NO. 42 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C325	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-849		NO. 1 ENGINE - NO. 43 2ND-STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE						Component ATA:72
PN:3056693-01	MOS	29-Sep-21		TSN 0				REPLACE
SN:TH30C346	HRS	0	5000	TSN 0	(5000) 5000		4299	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-851		NO. 1 ENGINE - NO. 1 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870D0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-852		NO. 1 ENGINE - NO. 2 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870D4	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-853		NO. 1 ENGINE - NO. 3 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870D7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-854		NO. 1 ENGINE - NO. 4 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870E1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-855		NO. 1 ENGINE - NO. 5 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870E7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-856		NO. 1 ENGINE - NO. 6 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870M8	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-857		NO. 1 ENGINE - NO. 7 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870U4	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-858		NO. 1 ENGINE - NO. 8 1ST-STAGE POWER TURBINE BLADE						Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870X9	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-859	NO. 1 ENGINE - NO. 9 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM870Y7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-860	NO. 1 ENGINE - NO. 10 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM871H8	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-861	NO. 1 ENGINE - NO. 11 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM871K5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-862	NO. 1 ENGINE - NO. 12 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM871K9	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-863	NO. 1 ENGINE - NO. 13 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM871L0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-864	NO. 1 ENGINE - NO. 14 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM871U9	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-865	NO. 1 ENGINE - NO. 15 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872A1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-866	NO. 1 ENGINE - NO. 16 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872B6	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-867	NO. 1 ENGINE - NO. 17 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872C5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-868	NO. 1 ENGINE - NO. 18 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872E8	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-869	NO. 1 ENGINE - NO. 19 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872K3	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-870	NO. 1 ENGINE - NO. 20 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872K4	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-871	NO. 1 ENGINE - NO. 21 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872N5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-872	NO. 1 ENGINE - NO. 22 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872P1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-873	NO. 1 ENGINE - NO. 23 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872W3	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-874	NO. 1 ENGINE - NO. 24 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM872Y3	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-875	NO. 1 ENGINE - NO. 25 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873B2	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-876	NO. 1 ENGINE - NO. 26 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873B5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-877	NO. 1 ENGINE - NO. 27 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873D0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-878	NO. 1 ENGINE - NO. 28 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873F2	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-879	NO. 1 ENGINE - NO. 29 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873K2	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-880	NO. 1 ENGINE - NO. 30 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873K5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-881	NO. 1 ENGINE - NO. 31 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873M1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-882	NO. 1 ENGINE - NO. 32 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873M4	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-883	NO. 1 ENGINE - NO. 33 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873N0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-884	NO. 1 ENGINE - NO. 34 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873P3	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-885	NO. 1 ENGINE - NO. 35 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873U3	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-886	NO. 1 ENGINE - NO. 36 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873U7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-887	NO. 1 ENGINE - NO. 37 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873X0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-888	NO. 1 ENGINE - NO. 38 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM873Y1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-CA-900-889	NO. 1 ENGINE - NO. 39 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM874A0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-890	NO. 1 ENGINE - NO. 40 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM874A2	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-891	NO. 1 ENGINE - NO. 41 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM874B7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-892	NO. 1 ENGINE - NO. 42 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM874C7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-CA-900-893	NO. 1 ENGINE - NO. 43 1ST-STAGE POWER TURBINE BLADE							Component ATA:72
PN:3118911-01	MOS/MSC	29-Sep-21	O/C	TSN 0				REPLACE
SN:PM874D6	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-00-200-801 ^S	ACCESSORY GEARBOX BREATHER LINE - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:72
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

PKG:5,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-00-200-802	^S	ENGINE ACCESSORIES - CHECK FOR GENERAL CONDITION, ATTACHMENTS AND LINKAGE.						Service ATA:72
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5,9 ,10 ,11
72-60-CA-900-802	NO. 1 ENGINE - FORWARD TOP GEARSHAFT,SPUR, ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348337	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-802	NO. 1 ENGINE - REAR TOP GEARSHAFT, SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348339	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-803	NO. 1 ENGINE - FORWARD BOTTOM GEARSHAFT,SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348342	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-803	NO. 1 ENGINE - REAR BOTTOM GEARSHAFT,SPUR,ACCESSORY DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348374	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-804	NO. 1 ENGINE - FORWARD GEARSHAFT, STARTER, GENERATOR DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348375	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-CA-900-804	NO. 1 ENGINE - REAR GEARSHAFT,STARTER, GENERATOR DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348376	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-805	NO. 1 ENGINE - FORWARD GEARSHAFT, DRIVE, ACCESSORY GEARBOX, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348378	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-805	NO. 1 ENGINE - REAR GEARSHAFT, DRIVE, ACCESSORY GEARBOX, FLANGED ROLLER BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:AEB0348381	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-806	NO. 1 ENGINE - FORWARD GEARSHAFT ASSEMBLY, SPUR, FUEL CONROL DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FAA2103684	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-806	NO. 1 ENGINE - REAR GEARSHAFT ASSEMBLY, SPUR, FUEL CONTROL DRIVE, FLANGED ROLLER BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FAA2103689	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-807	NO. 1 ENGINE - FORWARD GEARSHAFT, SCAVENGE PUMP, FLANGED ROLLER BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FAA2103693	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-CA-900-807	NO. 1 ENGINE - REAR GEARSHAFT, SCAVENGE PUMP, FLANGED ROLLER BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:FAA2104081	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-60-CA-900-809	NO. 1 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT							Component ATA:72
PN:3070217-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:PKAAA919407	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-02-200-801	NO. 1 ENGINE - FUEL PUMP INLET SCREEN - CHECK AND CLEAN							Service ATA:73
PN:3040760	MOS	01-Aug-25						
SN:018193	HRS	701	600 (+10%)	Adj -101.53	(1199.47) 1199.47	1259.47	498.5 (+60)	
	ENC	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-02-200-802 ^S	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - CHECK FOR FOREIGN MATTER OR DISTORTION							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
73-10-02-960-801	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER - REPLACE							Service ATA:73
PN:3040760	MOS	26-Jun-24					REPLACE	
SN:018193	HRS	523.2	600 (+10%)		(1123.2) 1123.2	1183.2	422.2 (+60)	
	ENC							
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-05-790-801	NO. 1 ENGINE - FUEL MANIFOLD ADAPTERS - PERFORM LEAK TEST AND FUNCTION TEST							Service ATA:73
	MOS	01-Aug-25						
	HRS	701	400 (+10%)		(1101) 1101	1141	400 (+40)	
	ENC	483						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-10-06-200-801 ^S	GENERATOR CASE DRAIN - CHECK FOR ATTACHMENT AND LEAKS.							Service ATA:73
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-07-130-801 ^S	P3 FILTER - ULTRASONIC CLEANING. CHECK FOR CONDITON AND ATTACHMENT.							Service ATA:73
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: EMM 73-10-07, EMM 73-10-07PROC. REF: EMM 73-10-07, EMM 73-10-07								
73-10-07-960-801	NO. 1 ENGINE - P3 FILTER - REPLACE							Service ATA:73
PN:PN	MOS	29-May-23		TAC 20				REPLACE
SN:UNKNOWN	HRS	343.7	1000 (+100)	TAC 343.7	(1000) 1000	1100	299 (+100)	
	ENC	163		TAC 163				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-07.10	NO. 1 ENGINE - COMPRESSOR DELIVERY AIR LINES ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-07.9	NO. 1 ENGINE - COMPRESSOR DELIVERY AIR LINES APPROVED REPAIRS							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								
73-10-08.7	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES INSPECTION CHECK							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								
73-10-08.8	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES APPROVED REPAIRS.							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								
73-10-08.9	NO. 1 ENGINE - GOVERNOR PNEUMATIC TUBES ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-08PROC. REF: EMM 73-10-08								
73-10-09.7	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE INSPECTION CHECK							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-10-09.8	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE APPROVED REPAIRS							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-09.9	NO. 1 ENGINE - TORQUE LIMITER AND SOLENOID VALVE ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-10-CA-200-801 ^S	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-CA-200-802 ^S	NO. 1 ENGINE - CHECK FLOW DIVIDER FOR INSTALLATION AND LEAKS							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
73-10-CA-200-803 ^S	NO. 1 ENGINE - CHECK OIL-TO-FUEL HEATER INSTALLATION							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								
73-10-CA-200-804 ^S	NO. 1 ENGINE - CHECK P3 FILTER FOR INSTALLATION							Service ATA:73
PN:PN	MOS	01-Aug-25	12 (+1m)					
SN:UNKNOWN	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-CA-200-805	^S	NO. 1 ENGINE - CHECK DRAIN VALVE(S) FOR INSTALLATION AND LEAKS						Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-06PROC. REF: EMM 73-10-06								PKG:1
73-10-CA-200-806	^S	NO. 1 ENGINE - CHECK FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE						Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								PKG:1
73-10-CA-210-804	^S	NO. 1 ENGINE - EXAMINE PNEUMATICSYSTEM FILTER BOWL						Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								PKG:1
73-10-CA-900-801		NO. 1 ENGINE - REPLACE FUEL CONTOL UNIT BELLOWS						Service ATA:73
PN:3120023-10	MOS/MSC	29-Sep-21	O/C					
SN:22609815	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-CA-900-802		NO. 1 ENGINE - ENGINE DRIVEN FUEL PUMP						Component ATA:73
PN:3040760	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:018193	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-CA-900-803	NO. 1 ENGINE - FUEL HEATER							Component ATA:73
PN:3124177-01	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:WA62889	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-01PROC. REF: EMM 73-10-01								
73-10-CA-900-804	NO. 1 ENGINE - FLOW DIVIDER/START CONTROL VALVE							Component ATA:73
PN:3023670	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:M1467	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
73-10-CA-900-805	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3120023-10	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:22609815	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-11-05.7	NO. 1 ENGINE - DUPLEX FUEL MANIFOLD INSPECTION CHECK							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-11-05.8	NO. 1 ENGINE - FUEL MANIFOLD APPROVED REPAIRS							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-11-05.9	NO. 1 ENGINE - DUPLEX FUEL MANIFOLD ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-11-05PROC. REF: EMM 73-11-05								
73-11-CA-900-801	NO. 1 ENGINE - OVERTORQUE LIMITER							Component ATA:73
PN:3055726-01	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:F14972	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-09PROC. REF: EMM 73-10-09								
73-20-00.7	NO. 1 ENGINE - FUEL CONTROL UNIT INSPECTION CHECK							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-00.8	NO. 1 ENGINE - FUEL CONTROL UNIT APPROVED REPAIRS							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-00.9	NO. 1 ENGINE - FUEL CONTROL UNIT ADJUSTMENT TEST							Service ATA:73
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								
73-20-CA-200-801 ^S	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-20-00PROC. REF: EMM 73-20-00								

PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-CA-100-801 ^S	NO. 1 ENGINE - CLEAN PNEUMATIC P3 FILTER							Service ATA:73
PN:PN	MOS	01-Aug-25	12 (+1m)					
SN:UNKNOWN	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-07PROC. REF: EMM 73-10-07								PKG:1
73-30-CA-100-802 ^S	NO. 1 ENGINE - CLEAN/INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY							Service ATA:73
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 73-10-07, EMM 73-10-07PROC. REF: EMM 73-10-07, EMM 73-10-07								PKG:1
73-30-CA-900-801	NO. 1 ENGINE - P3 FILTER							Component ATA:73
PN:PN	MOS/MSC	29-May-23	H/T	TSN 20				
SN:UNKNOWN	HRS	343.7		TSN 343.7				
	ENC	163		TSN 163				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 74 - IGNITION								
74-00-CA-200-801	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION							Service ATA:74
	MOS	01-Aug-25						
	HRS	701	400 (+10%)		(1101) 1101	1141	400 (+40)	
	ENC	483						
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								
74-00-CA-900-801	NO. 1 ENGINE - IGNITION EXCITER							Component ATA:74
PN:3035889	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:NNA21160144	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-00PROC. REF: EMM 74-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-10-00-200-801	IGNITION EXCITER - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:74
	MOS	01-Aug-25						
	HRS	701	400 (+10/-10)		1101	1111	400 (+10)	
	AFL	483						
PROC. REF: AMM 74-00-00, EMM 74-10-00PROC. REF: AMM 74-00-00, EMM 74-10-00								
74-20-00-200-801	IGNITION CABLES - CHECK FOR ROUTING, ATTACHMENT AND WEAR DUE TO CHAFING.							Service ATA:74
	MOS	01-Aug-25						
	HRS	701	400 (+10/-10)		1101	1111	400 (+10)	
	AFL	483						
PROC. REF: AMM 74-00-00PROC. REF: AMM 74-00-00								
74-20-00-200-802	SPARK IGNITERS - CHECK FOR CLEANLINESS AND EROSION.							Service ATA:74
	MOS	29-May-23						
	HRS	343.7	400 (+10/-10)		743.7	753.7	42.7 (+10)	
	AFL	163						
PROC. REF: AMM 74-20-00PROC. REF: AMM 74-20-00								
74-20-00-710-801 ^S	SPARK IGNITERS - DO AN OPERATIONAL TEST.							Service ATA:74
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 74-20-00, AMM 74-20-00, EMM 74-00-00PROC. REF: AMM 74-20-00, AMM 74-20-00, EMM 74-00-00								PKG:5,6,7,8,9 ,10 ,11
74-20-CA-200-802	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECKFUNCTION							Service ATA:74
	MOS	29-May-23						
	HRS	343.7	400 (+10%)		(743.7) 743.7	783.7	42.7 (+40)	
	ENC	163						
PROC. REF: EMM 74-20-00PROC. REF: EMM 74-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-00-00-900-801	AIR INTAKE ASSEMBLY							Component ATA:75
PN:T700H716010500110	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:TB392	HRS	0		TSN 0				
WC#: 75.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
75-30-00.7	NO. 1 ENGINE - COMPRESSOR BLEED VALVE INSPECTION CHECK							Service ATA:75
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-00PROC. REF: EMM 75-30-00								
75-30-CA-900-801	NO. 1 ENGINE - BLEED VALVE COMPRESSOR							Component ATA:75
PN:3059835-01	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:AHX1002011	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	2799 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-00PROC. REF: EMM 75-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-00-200-801	^S	ENGINE CONTROLS - CHECK FOR TRAVEL, ATTACHMENT, ROUTING AND EVIDENCE OF DAMAGE.						Service ATA:76
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 76-10-00, AMM 76-10-00PROC. REF: AMM 76-10-00, AMM 76-10-00								PKG:5,6,7,8,9 ,10 ,11
76-10-01-900-801 PEDESTAL CONTROL Component ATA:76								
PN:HA12-1000-5	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:83198	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
76-10-CA-200-801 ^S NO. 1 ENGINE - INSPECT CONTROL LINKAGES Service ATA:76								
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								PKG:1
ATA 77 - ENGINE INDICATING								
77-00-00-601		NO. 1 ENGINE - ENGINE INDICATING INSPECTION CHECK ALL						Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								
77-10-CA-900-801 NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS Component ATA:77								
PN:3043825-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:NRA108985	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-11-00-200-801	^S	MT12 NG TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE.						Service ATA:77
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,11
77-11-00-900-801		NO. 1 RPM TRANSMITTER						Component ATA:77
PN:MIL.G.26611CGEU7/A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:400334	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
77-11-00-900-801		NO. 2 RPM TRANSMITTER						Component ATA:77
PN:MIL.G.26611CGEU7/A	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:400335	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: GENERIC BLANKPROC. REF: GENERIC BLANK								
77-12-00-200-801	^S	MT41 FUEL FLOW TRANSMITTER - CHECK FOR ATTACHMENT, LEAKS AND EVIDENCE OF DAMAGE.						Service ATA:77
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,6,7,8,9 ,10 ,11
77-13-00-101.01		NO. 1 ENGINE - PROPELLER SPEED (NP) INDICATING TROUBLE SHOOTING UP TO SN 1269						Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-13-00PROC. REF: AMM 77-13-00								
77-13-00-101.02		NO. 1 ENGINE - PROPELLER SPEED (NP) INDICATING TROUBLE SHOOTING FROM SN 1270						Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-13-00PROC. REF: AMM 77-13-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-13-00-200-801 ^S	MT11 NP TACHOMETER GENERATOR - CHECK FOR ATTACHMENT AND LEAKS AT MOUNTING INTERFACE.							Service ATA:77
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,11
77-14-00-101	NO. 1 ENGINE - ENGINE TORQUE INDICATING TROUBLE SHOOTING ALL							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-200-801 ^S	MT10 TORQUE TRANSMITTER - CHECK FOR ATTACHMENT AND LEAKS.							Service ATA:77
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								PKG:5,9 ,10 ,11
77-14-00-501 KULITE	NO. 1 ENGINE - ENGINE TORQUE INDICATING ADJUSTMENT TEST KULITE							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-501 SAGEM	NO. 1 ENGINE - ENGINE TORQUE ADJUSTMENT TEST SAGEM							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-14-00-501 THALES	NO. 1 ENGINE - ENGINE TORQUE INDICATING ADJUSTMENT TEST THALES							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-14-00-900-801	TORQUE TRANSDUCER							Component ATA:77
PN:660526AS	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:6585	HRS	0		TSN 0				
WC#: 77.070	AFL	0		TSN 0				
PROC. REF: AMM 77-12-00, AMM 77-12-00PROC. REF: AMM 77-12-00, AMM 77-12-00								
77-14-00-900-802	TORQUE DETECTOR							Component ATA:77
PN:APTE--438-1000-75D	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:8600-9-405	HRS	0		TSN 0				
WC#: 77.040	AFL	0		TSN 0				
PROC. REF: AMM 77-14-00PROC. REF: AMM 77-14-00								
77-20-00-200-802 ^S	MT13 THERMOCOUPLE HARNESS - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:77
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
								PKG:5,11
PROC. REF: AMM 77-00-00PROC. REF: AMM 77-00-00								
77-20-00-501 POST	NO. 1 ENGINE - ENGINE TEMPERATURE INDICATING ADJUSMENT TEST POST MOD70-0323-71							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-20-00PROC. REF: AMM 77-20-00								
77-20-00-501 PRE	NO. 1 ENGINE - ENGINE TEMPERATURE INDICATING ADJUSTMET TEST PRE MOD70-033-71							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-20-00PROC. REF: AMM 77-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-01.7	NO. 1 ENGINE - SENSING SYSTEM INSPECTION CHECK							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-01.8	NO. 1 ENGINE - T5 SENSING SYSTEM APPROVED REPAIRS							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-01.9	NO. 1 ENGINE - T5 SENSING SYSTEM ADJUSTMENT TEST							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-CA-900-801	NO. 1 ENGINE - T5 BUS BAR POSITIVE TERMINAL ASSEMBLY							Component ATA:77
PN:3109240-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:NR16643	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-20-CA-900-802	NO. 1 ENGINE - T5 BUS BAR NEGATIVE TERMINAL ASSEMBLY							Component ATA:77
PN:3109239-01	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:NR16263	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
77-21-00-101	NO. 1 ENGINE - INTERTUBINE TEMPERATURE (ITT) INDICATING TROUBLE SHOOTING ALL							Service ATA:77
	MOS/MSC	29-Sep-21	A/R					
	HRS	0						
	ENC	0						
PROC. REF: AMM 77-21-00PROC. REF: AMM 77-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-10-00-200-801	^S	EXHAUST STUBS - CHECK FOR ATTACHMENT, CRACKS, DISTORTIONS AND EVIDENCE OF DAMAGE.						Service ATA:78
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: AMM 78-10-00PROC. REF: AMM 78-10-00								PKG:1,5,6,7,8,9 ,10 ,11
ATA 79 - OIL								
79-00-00-680-801		NO. 1 ENGINE - ENGINE OIL - CHANGE OIL						Service ATA:79
	MOS/MSC	29-Sep-21	O/C					
	HRS	0						
	ENC	0						
PROC. REF: AMM 12-12-02 (A1), AMM 12-12-02-301, AMM 12-12-02PROC. REF: AMM 12-12-02 (A1), AMM 12-12-02-301, AMM 12-12-02								
79-00-CA-200-801	^S	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR(S) FOR CONTINUITY						Service ATA:79
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								PKG:1
79-00-CA-200-802	^S	NO. 1 ENGINE - EXAMINE THE OIL FILTER ELEMENT AND SECONDARY SCREEN						Service ATA:79
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								PKG:1
79-00-CA-200-803	^S	NO. 1 ENGINE - CHECK SCAVANGE OIL PUMP HOUSING FOR LEAKS						Service ATA:79
	MOS	01-Aug-25	12 (+1m)					
	HRS	701	200 (+10)					
	ENC	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-00-CA-610-801	NO. 1 ENGINE - SERVICING OIL SYSTEM							Service ATA:79
	MOS	01-Aug-25	12 (+1m)	Adj -64d	29-May-26	29-Jun-26	215 d (+31)	
	HRS	701						
	ENC	483						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
79-00-CA-900-802	NO. 1 ENGINE - OIL FILTER ELEMENT							Component ATA:79
PN:PN	MOS/MSC	26-Jun-24	H/T					
SN:UNKNOWN	HRS	523.2						
	ENC							
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
79-10-00-200-801 ^S	OIL FILLER CAP - CHECK FOR CONDITION AND ATTACHMENT.							Service ATA:79
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-20-00-200-801 ^S	OIL FILTER - INSPECT AND CLEAN IF NECESSARY.							Service ATA:79
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
								PKG:5,6,7,8,9 ,10 ,11
PROC. REF: AMM 79-20-02, EMM 79-20-02PROC. REF: AMM 79-20-02, EMM 79-20-02								
79-20-00-200-802	NO. 1 ENGINE - ACCESSORY GEARBOX - CHECK INTERNAL SCAVENGE PUMP INLET SCREEN							Service ATA:79
	MOS	01-Aug-25						
	HRS	701	1000 (+100)		(1701) 1701	1801	1000 (+100)	
	ENC	483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20-00-200-803	^S	OIL COOLER - CHECK FOR CONDITION, ATTACHMENT, EVIDENCE OF DAMAGE AND LEAKS. CHECK CORE CLEANLINESS.						Service ATA:79
	MOS	01-Aug-25	48 (+1m/-1m)					
	HRS	701	800 (+10/-10)					
	AFL	483						
PROC. REF: AMM 79-20-00PROC. REF: AMM 79-20-00								PKG:5,11
79-20-00-730-801 OIL COOLER - OVERHAUL Component ATA:79								
PN:1101532401	MOS	29-Sep-21		TSN 0				OVERHAUL
SN:30	HRS	0	2100 (+10%/-10%)	TSN 0	2100	2310	1399 (+210)	
WC#: 79.020	AFL	0		TSN 0				
PROC. REF: AMM 79-20-01, AMM 79-20-01PROC. REF: AMM 79-20-01, AMM 79-20-01								
79-20-00-960-801 NO. 1 ENGINE - OIL FILTER - REPLACE Service ATA:79								
PN:PN	MOS	26-Jun-24						REPLACE
SN:UNKNOWN	HRS	523.2	1000 (+100)		(1523.2) 1523.2	1623.2	822.2 (+100)	
	ENC							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-20-02-710-801 NO. 1 ENGINE - CHIP DETECTORS - DO AN OPERATIONAL TEST Service ATA:79								
	MOS	01-Aug-25	12 (+1m)		01-Aug-26	01-Sep-26	279 d (+31)	
	HRS	701	600 (+10%)		(1301) 1301	1361	600 (+60)	
	ENC	483						
PROC. REF: AMM 72-00-00 (A1), AMM 72-00-00, EMM 79-20-02PROC. REF: AMM 72-00-00 (A1), AMM 72-00-00, EMM 79-20-02								
79-20-02-760-801 ^S CHIP DETECTOR - CHECK CONTINUITY WITH AN OHMMETER. Service ATA:79								
	MOS	01-Aug-25	12 (+1m/-1m)					
	HRS	701	200 (+10/-10)					
	AFL	483						
PROC. REF: EMM 79-20-02, EMM 79-20-02PROC. REF: EMM 79-20-02, EMM 79-20-02								PKG:5,6,7,8,9 ,10 ,11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: TBM 910 Serial: 1388 RegNo: N117MV HRS: 701 AFL: 483 As Of: 01-Aug-2025

26-Oct-2025 09:52 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-00-200-801	^S	S42 PRESSURE SWITCH AND MT15 OIL TEMPERATURE PROBE - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						Service ATA:79
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 79-30-00PROC. REF: AMM 79-30-00								PKG:5,10 ,11
79-30-00-200-802	^S	MT14 OIL PRESSURE TRANSMITTER - CHECK FOR CONDITION, ATTACHMENT AND LEAKS.						Service ATA:79
	MOS	01-Aug-25	24 (+1m/-1m)					
	HRS	701	400 (+10/-10)					
	AFL	483						
PROC. REF: AMM 79-30-00PROC. REF: AMM 79-30-00								PKG:5,10 ,11
79-30-03-900-801		OIL PRESSURE SENDER UNIT						Component ATA:79
PN:APT-369A-1000-150G	MOS/MSC	29-Sep-21	O/C	TSN 0				
SN:8812-9-442	HRS	0		TSN 0				
WC#: 79.030	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task