



5201 N. Walnut St. Muncie, Indiana 47303  
www.muncieaviation.com  
(800) 289-7141

**WORK ORDER: A-25-6101**

Acct Number: GARYS

Opened: 9/02/2025  
Close Date: 9/25/2025

Sold To: GARY J STRAUSSER HOMEBUILDERS INC  
Gary  
1110 VAN BUREN ROAD  
EASTON, PA 18045 United States

|                                                                                                                                                                                                                                                 |              |                          |          |                                       |                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|--------------------------|----------|---------------------------------------|---------------------|
| <b>Aircraft Number:</b> N917BT                                                                                                                                                                                                                  |              | <b>Type:</b> TBM 700/910 |          | <b>S/N:</b> 1209                      |                     |
| Total Time:                                                                                                                                                                                                                                     |              | Hobbs Time: 528.9        |          | Tach Time: LG Cycles:                 |                     |
| <b>Discrepancy: 1</b>                                                                                                                                                                                                                           |              |                          |          |                                       |                     |
| Discrepancy Status: Approved                                                                                                                                                                                                                    |              |                          |          |                                       |                     |
| <b>Problem:</b><br>Perform preliminary inspection IAW Form 216.                                                                                                                                                                                 |              |                          |          |                                       |                     |
| <b>Action Taken:</b><br>No discrepancies noted.<br>See attached preliminary sheet (Form 216).                                                                                                                                                   |              |                          |          |                                       |                     |
|                                                                                                                                                                                                                                                 |              |                          |          | Total For This Discrepancy: \$ 0.00   |                     |
| <b>Discrepancy: 2</b>                                                                                                                                                                                                                           |              |                          |          |                                       |                     |
| Discrepancy Status: Approved                                                                                                                                                                                                                    |              |                          |          |                                       |                     |
| <b>Problem:</b><br>Comply with SB70-335-34-R1 Garmin G1000 NXi SW V20.98 (P/N 006-B4560-00)                                                                                                                                                     |              |                          |          |                                       |                     |
| <b>Action Taken:</b><br>Complied with SB70-335-34-R1 Garmin G1000 NXi SW V20.98 (P/N 006-B4560-00)                                                                                                                                              |              |                          |          |                                       |                     |
| Charges This Item:                                                                                                                                                                                                                              |              |                          |          | Labor: \$ 930.00                      |                     |
| Part Number                                                                                                                                                                                                                                     | Description  | Credit                   | Quantity | Units                                 | Unit Price Extended |
| 16GB SD CARD CLASS 10                                                                                                                                                                                                                           | 16GB SD CARD |                          | 1.00     | Each                                  | 10.250 \$ 10.25     |
|                                                                                                                                                                                                                                                 |              |                          |          | Parts For This Discrepancy: \$ 10.25  |                     |
|                                                                                                                                                                                                                                                 |              |                          |          | Total For This Discrepancy: \$ 940.25 |                     |
| <b>Discrepancy: 3</b>                                                                                                                                                                                                                           |              |                          |          |                                       |                     |
| Discrepancy Status: Approved                                                                                                                                                                                                                    |              |                          |          |                                       |                     |
| <b>Problem:</b><br>Comply with 1 year autopilot inspection including cable condition and tension check IAW 22-11-03,-04,-05-501; and autopilot clutch manual override check for B35, B36, B37, and B38 servo actuators IAW 22-11-00-601.        |              |                          |          |                                       |                     |
| <b>Action Taken:</b><br>Complied with 1 year autopilot inspection including cable condition and tension check IAW 22-11-03,-04,-05-501; and autopilot clutch manual override check for B35, B36, B37, and B38 servo actuators IAW 22-11-00-601. |              |                          |          |                                       |                     |
| <b>Calibrated Tools Used:</b><br>76 - Cable Tensionmeter S/N: M10523                                                                                                                                                                            |              |                          |          |                                       |                     |
| Charges This Item:                                                                                                                                                                                                                              |              |                          |          | Labor: \$ 155.00                      |                     |
|                                                                                                                                                                                                                                                 |              |                          |          | Total For This Discrepancy: \$ 155.00 |                     |
| <b>Discrepancy: 4</b>                                                                                                                                                                                                                           |              |                          |          |                                       |                     |
| GARY J STRAUSSER HOMEBUILDERS INC N917BT<br>Printed: 9/25/2025 WORK ORDER: A-25-6101 Page: 1 of 3                                                                                                                                               |              |                          |          |                                       |                     |

Discrepancy Status: Approved

**Problem:**

Comply with FAR 91.207d 1, 2, 3, & 4 ELT check.

**Action Taken:**

Complied with Federal Aviation Regulation 91.207d 1, 2, 3, and 4 ELT checks. Removed ELT, inspected battery for condition and leakage. Performed ELT and G switch functional test, and reinstalled ELT. All ELT function checks good. Battery expiration date: August 2028.

**Calibrated Tools Used:**

56 - M. IFR4000 Nav Simulator S/N: 103001159

Charges This Item:

Labor:

\$

116.25

Total For This Discrepancy: \$

116.25

**Discrepancy: 5**

Discrepancy Status: Approved

**Problem:**

Comply with 1 year/200 hour RVSM inspection, Static Port and Dimension check IAW 53-00-00-601.

Comply with 2 year/400 hour RVSM Inspection: Pitot tube condition check IAW 34-11-00-601; and air data system check IAW 34-11-00-501.

Perform IFR certification.

Comply with VMO warning check and Pitot-Static leak check IAW 34-11-00-501.

**Action Taken:**

Complied with 1 year/200 hour RVSM inspection, Static Port and Dimension check IAW 53-00-00-601.

Complied with 2 year/400 hour RVSM Inspection: Pitot tube condition check IAW 34-11-00-601; and air data system check IAW 34-11-00-501.

Complied with VMO warning check and Pitot-Static leak check IAW 34-11-00-501.

Certified that the altimeter/static system, transponder, and encoder have been tested as required by FAR 91.217, 91.411, and 91.413. Units were found to comply with the limits set in FAR 43 appendices E & F to 35,000 feet.

**Calibrated Tools Used:**

65 - 6300 LAVERSAB RVSM S/N: 75315

109 - M. IFR6000 Aeroflex S/N: 1000684955

S39 - Starret Depth Gauge - 643JZ S/N: T-12339

Charges This Item:

Labor:

\$

1,364.00

Total For This Discrepancy: \$

1,364.00

**Discrepancy: 6**

Discrepancy Status: Approved

**Problem:**

#2 GPS needs service.

**Action Taken:**

Could not duplicate discrepancy on several attempts.

Total For This Discrepancy: \$

0.00

**Discrepancy: 7**

Discrepancy Status: Approved

**Problem:**  
attachments

Total For This Discrepancy: \$ 0.00

**Summary:**

|              |    |       |              |    |          |
|--------------|----|-------|--------------|----|----------|
| Total Parts: | \$ | 10.25 | Total Labor: | \$ | 2,565.25 |
|--------------|----|-------|--------------|----|----------|

**Totals:**

|                          |    |                 |
|--------------------------|----|-----------------|
| <b>SubTotal:</b>         | \$ | <b>2,575.50</b> |
| <b>Total Charges:</b>    | \$ | <b>2,575.50</b> |
| <b>Amount Remaining:</b> | \$ | <b>2,575.50</b> |

**CRS # AJVR135C**