

1983 BEECHCRAFT KING AIR F90-1



SERIAL NUMBER: LA-210

N NUMBER: N176LA

AIRFRAME:

Total Time: 6061.5 Hours 461.5 HOBBS

SNEW Landings: 6035

ENGINES: New PT6A-135A Blackhawks

Left Engine Serial Number: PCE-PZ2015

461.0 Total Time SNEW on 12/2021

395 Cycles SNEW

3600 Time Between Overhauls

2500 Hour 5 Year Factory Warranty

Right Engine Serial Number: PCE-PZ2017

461.0 Total Time SNEW on 12/2021

395 Cycles SNEW

3600 Time Between Overhauls

2500 Hour 5 Year Factory Warranty

PROPELLERS: Hartzell HC-BC-B4TN-3A Four Blade Props

Left Prop Serial Number: EAA-1286

461.0 Since New on 12/2021

Right Prop Serial Number: EAA-1288

461.0 Since New on 12/2021

AVIONICS:

- **Autopilot:** Garmin GFC-600
- **Flight Director:** Garmin G-600 TXI
- **HSI:** Garmin G-600 TXI
- **Radar:** Garmin GWX-75
- **XM Weather/Music:** Garmin GDL-69A

- Long Range Navigation: Garmin GTN-750XI
 - Audio: Garmin GMA-350C
 - #1 Comm: Garmin GTN-750XI
 - #2 Comm: Garmin GTN-750XI
 - #1 Nav: Garmin GTN-750XI
 - #2 Nav: Garmin GTN-750XI
 - Transponders: Garmin GTX-345R
 - RMI: Dual Collins RMI-30
 - ADF: Collins ADF-60A w/Single CTL-62 Control
 - DME: Dual Collins DME-40
 - Compass System: Dual Collins MCS-65
 - Radar Altimeter: Collins ALT-80
 - Encoding Altimeters: #1 Collins ALT-80A #2 Collins ALT-80A
 - TWAS: Garmin GNS-
 - Traffic: Garmin GTX-345R
 - ADSB: Garmin GTX-345R
 - ELT: ACK C-406
-

ADDITIONAL EQUIPMENT:

- B-300 Cockpit Seats
 - B-200 Cabin Seats
 - All New De-Ice Boots
 - New Cockpit Side and Storm Windows Left and Right
 - LED Cabin Down Wash Lighting
 - Raisbeck Dual Aft Strakes
 - LED NAV, Recog, Strobe, and Beacon Lights
 - Frakes Exhaust
 - Shadin Fuel Flow Totalizer
 - Standard Landing Gear
 - Dual Door Cables
 - Engine Fire Detection and Extinguishing
 - 77 Cubic Foot Oxygen System
 - Prop Sync
 - Dual KGS SPC-60A Inverters w/Failure Light
 - Flight Hour Meter
 - Lights: Dual Landing, Taxi, Dual Rotating Beacons, Wing Position/Strobe/Recognition, Tail Position/Strobe, Dual Ice, Logo
-

EXTERIOR:

Overall Matterhorn White, Red and Silver Stripes.
 Stainless Steel Screw Kit.
 New Engines Installed after Strip and Paint.

New Strip and Paint on 11/2021.

INTERIOR:

Two B-300 Pilot/Copilot under-seat P.O.H. cases.

Cabin: Four B-200 Cabin Chairs in aft club.

Dual compartment chart cases.

Forward and aft partitions with privacy doors.

Forward LS Pyramid cabinet with heated liquid dispenser, ice chest drawer, three storage drawers, overboard drain and pull-out work surface.

Executive tables with leather table top inserts and over-table reading lights. Aft LS narrow pyramid cabinet with storage. Aft RS magazine rack. Aft front facing belted flushing potty seat.

Interior Materials:

Brown and Black leather upholstery.

IZIT leather Champagne headliner and window panels.

Black leather inset panels, rails, armrests and cockpit sidewalls.

Black Striped Painted Gloss Laminate Cabinetry and working surface.

Grey carpeting.

Black seatbelts and harnesses

LED Cabin Down Wash Lighting

New Interior in Completed on 12/2021.

HISTORY:

- *Logs Complete Since New*
 - *All Logs In English*
-

MAINTENANCE:

- **Left Engine Truss Overhaul/NDT c/w at 5600 HRS ACTT on 12/2021**
- **Right Engine Truss Overhaul/NDT c/w at 5600 HRS ACTT on 12/2021**
- **Left Engine Mount Replacement c/w at 5600 HRS ACTT on 12/2021**
- **Right Engine Mount Replacement c/w at 5600 HRS ACTT on 12/2021**
- **Left Engine Five Year Flammable Fluid Hose Replacement 12/2021**
- **Right Engine Five Year Flammable Fluid Hose Replacement 12/2021**
- **Left Starter-Gen 1000 Hour Overhaul c/w at 5600 HRS ACTT**
- **Right Starter-Gen 1000 Hour Overhaul c/w at 5600 HRS ACTT**
- **Left Overspeed Governor 4100 Hour Overhaul c/w at 5600 HRS ACTT**
- **Right Overspeed Governor 4100 Hour Overhaul c/w at 5600 HRS ACTT**
- **Left Engine TACH GEN/PROP GEN Replacement c/w at 5600 HRS ACTT**
- **Right Engine TACH GEN/PROP GEN Replacement c/w at 5600 HRS ACTT**
- **All New De-Ice Boots c/w on 11/2021**
- **All New Antenna's c/w on 11/2021**
- **All Lighted Edge Panels Overhauled c/w on 12/2021**
- **Six Year Landing Gear Overhaul c/w on 12/2021**
- **Five Year Wing Bolt Replacement NDT c/w 01/2026**
- **Fifteen Year Wing Bolt Replacement c/w 12/2021**
- **Six Year Prop Overhauls/New c/w on 12/2021**
- **Five Year Landing Gear Brake Hoses c/w 12/2021**
- **Five Year O2 Bottle Hydro c/w on 01/2026**
- **Five Year O2 Bottle Regulator Overhaul c/w on 01/2026**
- **91.411 and 91.413 c/w on 01/2026**
- **Phase 1 Thru 4 Inspections c/w on 01/2026**

**Price with 461.0 HR TT SNEW Blackhawk -135As, New Paint, New Interior,
Garmin GFC-600, G-600TXI, GTN-750XI, GMA-345, GXR-75,
and GTX-345R Installed:**

\$2,600,000.00 USD

Ballard Aviation, Inc. makes no representations as to the accuracy of this data. Purchaser needs to verify all specs, maintenance items, times, logbook research, etc. Aircraft times current as of 01/12/2026.

Shane Rives

President

Ballard Aviation, Inc.

316-737-1594 Cell

316-804-4904 Office

316-804-4909 Fax

shane@ballardaircraft.com















