



CESCOM 20 - Projected Maintenance Due

Owner: **JET AMG SERVICES**
Aircraft Model: **525A - CJ2**
Aircraft Serial: **525A-0428**
Unit: **0428** Reg No: **N711RC**
Airworthiness: **05-Nov-2008**
Print Date: **04-Jan-2024 12:01PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2634.9	2008	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 1	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 2	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
AIR COND	790		30-Nov-2023	.1	0.33	129.17		393	12

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
052105D	INSPECT 12 MONTHS ENVIRO SYSTEM CHECK	KCRQ			MTH 10-Feb-2023 HRS 2510.8 LDG 1931		12		29-Feb-2024	1 m 25 d
5-12-02 0512002	INSPECTION DOCUMENT 2	KCRQ			MTH 10-Feb-2023 HRS 2510.8 LDG 1931		12		29-Feb-2024	1 m 25 d
5-12-26	INSPECTION DOCUMENT 26	KCRQ			MTH 06-Sep-2023 HRS 2609.3 LDG 1989	-30	6		29-Feb-2024	1 m 25 d
B262201 CABIN 0512016 : CABIN	CABIN PORTABLE FIRE EXTINGUISHER (WEIGHT) FUNCTIONAL CHECK TASK 26-22-00-720	KCRQ		C352 X-467662	MTH 09-Feb-2023		12		29-Feb-2024	1 m 25 d
B262201 COCKPIT 0512016	COCKPIT PORTABLE FIRE EXTINGUISHER (WEIGHT) FUNCTIONAL CHECK TASK 26-22-00-720	KCRQ		A352TS F-60590241	MTH 09-Feb-2023		12		29-Feb-2024	1 m 25 d
5-12-03 0512003	INSPECTION DOCUMENT 3				MTH 31-Mar-2022 HRS 2355.7 LDG 1836		24		31-Mar-2024	2 m 27 d
A243301	LEAD ACID BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK NOTE: THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED BASED ON OPERATIONS TASK 24-33-00-720	KCRQ		S3597-4 40883382	MTH 06-Sep-2023 HRS 2609.3 LDG 1989		6 500		31-Mar-2024 3109.3	2 m 27 d 474.4
052001 E1	FJ44 CHECK 1	KCRQ			MTH 29-Sep-2022 HRS 2447.5 LDG 1886	-42.5	300		(2631.4)2705	70.1
052001 E2	FJ44 CHECK 1	KCRQ			MTH 29-Sep-2022 HRS 2447.5 LDG 1886	-42.5	300		(2631.4)2705	70.1
052002 E1	FJ44 CHECK 2	UNK			MTH 22-Jun-2021 HRS 2105 LDG 1699		600		(2631.4)2705	70.1
052002 E2	FJ44 CHECK 2	UNK			MTH 17-Jun-2021 HRS 2105 LDG 1699		600		(2631.4)2705	70.1
5-12-26	INSPECTION DOCUMENT 26	KCRQ			MTH 06-Sep-2023	-30	6		31-Aug-2024	7 m 27 d
4-12-MA 05120MA	INSPECTION DOCUMENT MA	KCRQ			MTH 30-Dec-2022 HRS 2492.9 LDG 1916		300		2792.9	158
5-12-08 0512008	INSPECTION DOCUMENT 8	KCRQ			MTH 30-Dec-2022 HRS 2492.9 LDG 1916		24 300		31-Dec-2024 2792.9	11 m 27 d 158
4-12-MG 05120MG	INSPECTION DOCUMENT MG	*CF			MTH 05-Nov-2008 HRS 0		2800		2800	165.1
053301	INSPECTION BOOMBEAM LIGHTING EQUIPMENT AND COMPONENTS	KCRQ			MTH 29-Sep-2023 HRS 2622.7 LDG 1998		12 600		30-Sep-2024 3222.7	8 m 26 d 587.8
4-12-MN	INSPECTION DOCUMENT MN	KCRQ			MTH 29-Sep-2023 HRS 2622.7 LDG 1998		12 330		30-Sep-2024 2952.7	8 m 26 d 317.8
A243301	LEAD ACID BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK NOTE: THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED BASED ON OPERATIONS TASK 24-33-00-720	KCRQ		S3597-4 40883382	MTH 06-Sep-2023		6		30-Sep-2024	8 m 26 d
341060 0512013 : RVSM	FUNCTIONAL CHECK RVSM SKIN WAVINESS (CFR 91.411, 91.413, AND RVSM)	KCRQ			MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **JET AMG SERVICES**
Aircraft Model: **525A - CJ2**
Aircraft Serial: **525A-0428**
Unit: **0428** Reg No: **N711RC**
Airworthiness: **05-Nov-2008**
Print Date: **04-Jan-2024 12:01PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2634.9	2008	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 1	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 2	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
AIR COND	790		30-Nov-2023	.1	0.33	129.17		393	12

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
341066 LEFT 0512013 : L-ADC	CALIBRATION TEST AIR DATA COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)	KCRQ		822-1109-014 357JF	MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
341068 RIGHT 0512013 : R-ADC	CALIBRATION TEST AIR DATA COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)	KCRQ		822-1109-014 357MW	MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
341070 STANDBY 0512013 : STDBY	CALIBRATION TEST ADC COMPUTER FAR 91.411 (CFR 91.411, 91.413, AND RVSM)	KCRQ		501-1890-04 3311	MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
B341001 LEFT 0512013 : L	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (CFR 91.411, 91.413, AND RVSM)	KCRQ			MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
B341001 RIGHT 0512013 : R	FUNCTIONAL CHECK PITOT STATIC SYSTEM (CFR 91.411, 91.413, AND RVSM)	KCRQ			MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
B345001 NO. 1 0512013 : 1	NO. 1 TRANSPONDER SYSTEM 14 CFR PART 91.413 (CALIBRATION) FUNCTIONAL CHECK TASK 34-50-06-720	KCRQ		622-9210-501 4DVHRR	MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
B345001 NO. 2 0512013 : 2	NO. 2 TRANSPONDER SYSTEM 14 CFR PART 91.413 (CALIBRATION) FUNCTIONAL CHECK TASK 34-50-06-720	KCRQ		622-9210-501 290YK	MTH 04-Nov-2022	-22	24		31-Oct-2024	9 m 27 d
5-12-24 0512024	INSPECTION DOCUMENT 24 SMF				MTH 17-Nov-2023 HRS 2633.1 LDG 2005		12 300		30-Nov-2024 2933.1	10 m 26 d 298.2
A256002	EMERGENCY LOCATOR TRANSMITTER DETAILED INSPECTION TASK 25-60-00-210	SMF		453-5060 05843	MTH 17-Nov-2023		12		30-Nov-2024	10 m 26 d
B256003	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR BEACON SYSTEM (14 CFR 91.207)	SMF		453-5060 05843	MTH 17-Nov-2023		12		30-Nov-2024	10 m 26 d
4-12-MD 05120MD	INSPECTION DOCUMENT MD KEUG				MTH 11-May-2018 HRS 1432.2 LDG 1123		1425		2857.2	222.3
5-12-21 0512021	INSPECTION DOCUMENT 21 KCRQ				MTH 01-Dec-2022 HRS 2468 LDG 1902		24 600		31-Dec-2024 3068	11 m 27 d 433.1



CESCOM 20 - Projected Maintenance Due

Owner: **JET AMG SERVICES**
Aircraft Model: **525A - CJ2**
Aircraft Serial: **525A-0428**
Unit: **0428** Reg No: **N711RC**
Airworthiness: **05-Nov-2008**
Print Date: **04-Jan-2024 12:01PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	2634.9	2008	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 1	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
ENG 2	2561.2	1968	30-Nov-2023	.28	0.66	258.4	193	393	12
AIR COND	790		30-Nov-2023	.1	0.33	129.17		393	12

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MTH HRS MANDATORY					(4000)4073.7	1438.8
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MTH HRS MANDATORY			MPI		(4000)4073.7	1438.8
SB FJ44-79-012 R01 E1	OIL - LUBE OIL COOLER - REWORK OR REPLACE			MTH HRS RECOMMENDED			DUE		(4000)4073.7	1438.8
SB FJ44-79-012 R01 E2	OIL - LUBE OIL COOLER - REWORK OR REPLACE			MTH HRS RECOMMENDED			DUE		(4000)4073.7	1438.8
SB WI-73-1009 R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE E2				MTH HRS RECOMMENDED			CSI		(4000)4073.7	1438.8
SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK E1				MTH LDG MANDATORY			8000 ENC		(8000)8040	6032
SB WI-72-1034 R04 HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK E2				MTH LDG MANDATORY			8000 ENC		(8000)8040	6032