



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPONDER 91.413)	KMKE	MTH	01-Nov-2022		24		30-Nov-2024	5 m 13 d
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK					A/R			
055002	ACCOMPLISH OVERSPEED CHECK					A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK					A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK					A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK					A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK					A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK					A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK					A/R			
5-12-01	INSPECTION DOCUMENT 01 KICT		MTH	14-Jun-2024		450		1743.5	450
			HRS	1293.5					
			LDG	1002					
5-12-02	INSPECTION DOCUMENT 02 KMKE		MTH	03-Aug-2015		900		1781.5	488
			HRS	881.5					
			LDG	688					
5-12-03	INSPECTION DOCUMENT 03 KICT		MTH	14-Jun-2024		1350		2643.5	1350
			HRS	1293.5					
			LDG	1002					
5-12-04	INSPECTION DOCUMENT 04		MTH	10-Mar-2010		1800		1800	506.5
			HRS	0					
5-12-05	INSPECTION DOCUMENT 05		MTH	10-Mar-2010		3150		3150	1856.5
			HRS	0					
5-12-06	INSPECTION DOCUMENT 06 KMKE		MTH	10-Nov-2023		12		30-Nov-2024	5 m 13 d
			HRS	1290.9					
			LDG	1000					
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)	KMKE	C352	10-Nov-2023		12		30-Nov-2024	5 m 13 d
			H-01186607	1290.9					
			LDG	1000					
5-12-07	INSPECTION DOCUMENT 07 KMKE		MTH	10-Nov-2023		24		30-Nov-2025	17 m 13 d
			HRS	1290.9					
			LDG	1000					
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE	MTH	23-Oct-2020		60			
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)	KMKE	30401102-2	23-Oct-2020		60		31-Oct-2025	16 m 14 d
			62589B1						
5-12-11	INSPECTION DOCUMENT 11 KMKE		MTH	05-May-2022		72		31-May-2028	47 m 14 d
			HRS	1253					
			LDG	960					



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)	KMKE		C352 H-01186607	MTH 05-May-2022 HRS 1253 LDG 960		72		31-May-2028	47 m 14 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 10-Mar-2010		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)	KMKE		C352 H-01186607	MTH 01-Jan-2021		144		31-Jan-2033	103 m 14 d
5-12-13	INSPECTION DOCUMENT 13	KMKE			MTH 06-Jul-2023 HRS 1288.4 LDG 996		12 450		31-Jul-2024 1738.4	1 m 14 d 444.9
5-12-14	INSPECTION DOCUMENT 14	KMKE			MTH 06-Jul-2023 HRS 1288.4 LDG 996		12 900		31-Jul-2024 2188.4	1 m 14 d 894.9
5-12-15	INSPECTION DOCUMENT 15	KMKE			MTH 10-Nov-2023 HRS 1290.9 LDG 1000		24 1350		30-Nov-2025 2640.9	17 m 13 d 1347.4
5-12-16	INSPECTION DOCUMENT 16	KMKE			MTH 05-May-2022 HRS 1253 LDG 960		36 1350		31-May-2025 2603	11 m 14 d 1309.5
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK			HM50C-3 119B	MTH 29-10-00-720 HRS		36 1350		31-May-2025 2603	11 m 14 d 1309.5
5-12-17	INSPECTION DOCUMENT 17	KMKE			MTH 05-May-2022 HRS 1253 LDG 960		36 1800		31-May-2025 3053	11 m 14 d 1759.5
5-12-18	INSPECTION DOCUMENT 18	KMKE			MTH 05-May-2022 HRS 1253 LDG 960		36 2250		31-May-2025 3503	11 m 14 d 2209.5
5-12-20	INSPECTION DOCUMENT 20	KMKE			MTH 20-Dec-2021 HRS 1237.9 LDG 947		48 2700		31-Dec-2025 3937.9	18 m 14 d 2644.4
5-12-21	INSPECTION DOCUMENT 21	KMKE		453-5060 08952	MTH 10-Nov-2023 HRS 1290.9 LDG 1000		12		30-Nov-2024	5 m 13 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE			MTH 03-Nov-2022 HRS 1266.7 LDG 973		24		30-Nov-2024	5 m 13 d
B341001 AIRSPEED	CALIBRATION TEST INDICATOR 14 CFR PART 91.411	KMKE		261440-1143 294363A	MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d
B341001 NO. 1	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KICT		011-01110-00 43800612	MTH 19-Feb-2024 HRS 1293.5 LDG 1002		24		28-Feb-2026	20 m 11 d
REMOVED GDC P/N: 011-01110-00 S/N: 43805801, DUE TO FAILURE. INSTALLED REPAIRED GDC IAW THE CE-510 M/M CH 34-10-10. OPERATIONAL CHECK GOOD. UNIT WAS REPAIRED ON FEBRUARY 19, 2024 BY GARMININTERNATIONAL FAA CRS# G6XR582Y.										
B341001 NO. 2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KMKE		011-01110-00 43805830	MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d
B341001 STANDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	KMKE		162350-1161 179065C	MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	KMKE			MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d
B345000 LEFT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KMKE		011-00779-21 84810061	MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d
B345000 RIGHT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KMKE		011-00779-21 84805242	MTH 01-Nov-2022		24		30-Nov-2024	5 m 13 d
5-12-23	INSPECTION DOCUMENT 23 (NOT USED)	GRB			MTH 20-Sep-2012 HRS 607.6 LDG 503		N/R			
5-12-28	INSPECTION DOCUMENT 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 10-Mar-2010 HRS 0 LDG 0		A/R			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KMKE		3-1640 0724	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	KICT		3-1642 0395	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KMKE		3-1640 0726	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		A/R			
5-12-30	INSPECTION DOCUMENT 30	KMKE			MTH 20-Dec-2021 HRS 1237.9 LDG 947		48 1800		31-Dec-2025 3037.9	18 m 14 d 1744.4
5-12-31	INSPECTION DOCUMENT 31	KICT			MTH 14-Jun-2024 HRS 1293.5 LDG 1002		450		1743.5	450
5-12-32	INSPECTION DOCUMENT 32	KMKE			MTH 05-May-2022 HRS 1253 LDG 960		72 1800		31-May-2028 2760	47 m 14 d 1758
5-12-35	INSPECTION DOCUMENT 35	KICT			MTH 14-Jun-2024 HRS 1293.5 LDG 1002		6		31-Dec-2024	6 m 14 d
5-12-37	INSPECTION DOCUMENT 37				MTH 10-Mar-2010 HRS 0		7200		8152.1	6858.6
5-12-38	INSPECTION DOCUMENT 38	KGRB			MTH 03-May-2024 HRS 1291.3 LDG 1001		3			
B243000	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK)	KGRB		RG-390E 41060792	MTH 03-May-2024 HRS 1291.3 LDG 1001		3		31-Aug-2024	2 m 14 d
5-12-MA	INSPECTION DOCUMENT MA	ICT			MTH 17-Feb-2016 HRS 934.1 LDG 739		500		1434.1	140.6



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MB	INSPECTION DOCUMENT MB ICT		MTH HRS 934.1 LDG 739	17-Feb-2016		950		1884.1	590.6
5-12-MC	INSPECTION DOCUMENT MC		MTH HRS 0	10-Mar-2010		4000		4000	2706.5
5-12-MD	INSPECTION DOCUMENT MD KMKE		MTH HRS 1290.9 LDG 1000	10-Nov-2023		12		30-Nov-2024	5 m 13 d
5-12-ME	INSPECTION DOCUMENT ME KMKE		MTH HRS 1237.9 LDG 947	20-Dec-2021		36 1400		31-Dec-2024 2637.9	6 m 14 d 1344.4
5-12-MF	INSPECTION DOCUMENT MF		MTH HRS 0	10-Mar-2010		12000		12000	10706.5
5-12-MG	INSPECTION DOCUMENT MG		MTH HRS 0	10-Mar-2010		5000		5000	3706.5
5-12-MH	INSPECTION DOCUMENT MH		MTH HRS 0	10-Mar-2010		8250		8250	6956.5
5-12-MI	INSPECTION DOCUMENT MI		MTH HRS 0	10-Mar-2010		12000		12000	10706.5
5-12-MJ	INSPECTION DOCUMENT MJ		MTH HRS 0	10-Mar-2010		10600		10600	9306.5
5-12-MK	INSPECTION DOCUMENT MK		MTH HRS 0	10-Mar-2010		10400		10400	9106.5
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE		MTH	10-Mar-2010		A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH		DAYS	10-Mar-2010		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH		DAYS	10-Mar-2010		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH		DAYS	10-Mar-2010		A/R			
262003A LEFT	REPLACE FIRE EXT CARTRIDGE ICT		13083-5 21H839-001 MTH HRS 1253 LDG 960	05-May-2022		72	1	30-Apr-2028	46 m 13 d
262003A RIGHT	REPLACE FIRE EXT CARTRIDGE ICT		13083-5 21H839-001 MTH HRS 1253 LDG 960	05-May-2022		72	1	30-Apr-2028	46 m 13 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)		MTH	10-Mar-2010		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)		MTH	10-Mar-2010		A/R			
32-30-40-960	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST) KMKE		40005369-2 5745 MTH	05-Jul-2023		36		31-Jul-2026	25 m 14 d
32-40-00-960	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST) KMKE		40005399-1 6318 MTH	05-Jul-2023		36		31-Jul-2026	25 m 14 d
35-00-00-960	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST KMKE		4441073-040 0775-252 MTH	17-Aug-2022		60		31-Aug-2027	38 m 14 d
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION KMKE		MTH HRS 1288.4 LDG 996	06-Jul-2023		12 450		31-Jul-2024 (1738.4)1738.4	1 m 14 d 444.9

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KMKE		MTH HRS LDG	06-Jul-2023 1288.4 996		12 450		31-Jul-2024 (1738.4)1738.4	1 m 14 d 444.9
710010 E1	COMPRESSOR DESALINATION WASH	ICT		MTH HRS LDG	15-Feb-2011 204.7 174		A/R			
710010 E2	COMPRESSOR DESALINATION WASH	ICT		MTH HRS LDG	15-Feb-2011 204.7 174		A/R			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH	10-Mar-2010		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)			MTH	10-Mar-2010		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH	10-Mar-2010		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)			MTH	10-Mar-2010		A/R			
72-00-00-620-805- 01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-805- 01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-805- 02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-805- 02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-806- 01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-806- 01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-620-806- 02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER			MTH	10-Mar-2010		A/R			
72-00-00-620-806- 02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER			MTH	10-Mar-2010		A/R			
72-00-00-630-804- 01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			
72-00-00-630-804- 01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS			MTH	10-Mar-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	10-Mar-2010		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	10-Mar-2010		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	10-Mar-2010		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	10-Mar-2010		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	10-Mar-2010		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	10-Mar-2010		A/R			
720000 E1	PERFORM ENGINE OVERHAUL		MTH	10-Mar-2010					
			HRS	0		3500		(3500)3500	2206.5
720000 E2	PERFORM ENGINE OVERHAUL		MTH	10-Mar-2010					
			HRS	0		3500		(3500)3500	2206.5
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION		MTH	10-Mar-2010					
			HRS	0		1750		(1750)1750	456.5
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION		MTH	10-Mar-2010					
			HRS	0		1750		(1750)1750	456.5
720003 E1	INSPECT LOW UTILIZATION ENGINE KICT		MTH	14-Jun-2024		24		30-Jun-2026	24 m 13 d
			HRS	1293.5					
			LDG	1002					
720003 E2	INSPECT LOW UTILIZATION ENGINE KICT		MTH	14-Jun-2024		24		30-Jun-2026	24 m 13 d
			HRS	1293.5					
			LDG	1002					
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER		MTH						
			HRS			1750		(1750)1750	456.5
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER		MTH						
			HRS			1750		(1750)1750	456.5
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT KMKE		MTH	06-Jul-2023		12		31-Jul-2024	1 m 14 d
			HRS	1288.4		900		(2188.4)2188.4	894.9
			LDG	996					
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT KMKE		MTH	06-Jul-2023		12		31-Jul-2024	1 m 14 d
			HRS	1288.4		900		(2188.4)2188.4	894.9
			LDG	996					
731055 E1	REPLACE FUEL MANIFOLD		35C4658-01 DE1BFL1008	MTH	10-Mar-2010				
				HRS	0	1750		(1750)1750	456.5
731055 E2	REPLACE FUEL MANIFOLD		35C4658-01 DE1BFM1235	MTH	10-Mar-2010				
				HRS	0	1750		(1750)1750	456.5
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH		PN SN-UNKNOWN	MTH	10-Mar-2010				
				HRS	0	1750		(1750)1750	456.5
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH		PN SN-UNKNOWN	MTH	10-Mar-2010				
				HRS	0	1750		(1750)1750	456.5
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY		PN SN-UNKNOWN	MTH	10-Mar-2010				
				HRS	0	1750		(1750)1750	456.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN	MTH 10-Mar-2010 HRS 0		1750		(1750)1750	456.5
790015 E1	REPLACE OIL FILTER ELEMENT KMKE				MTH 07-Apr-2015 HRS 855.9 LDG 669		900		(1755.9)1755.9	462.4
790015 E2	REPLACE OIL FILTER ELEMENT KMKE				MTH 07-Apr-2015 HRS 855.9 LDG 669		900		(1755.9)1755.9	462.4
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS KICT			PN SN-UNKNOWN	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		6 100		31-Dec-2024 (1393.5)1393.5	6 m 14 d 100
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS KICT			PN SN-UNKNOWN	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		6 100		31-Dec-2024 (1393.5)1393.5	6 m 14 d 100
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH 10-Mar-2010 HRS 0		1750		(1750)1750	456.5
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH 10-Mar-2010 HRS 0		1750		(1750)1750	456.5



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY.			0113-12 1714	MTH 10-Mar-2010		O/C	0		
213001	KAPS II CONTROLLER	KICT		52811-1102 952A	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7			52812-102 1327	MTH 10-Mar-2010		O/C	0		
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7			52812-102 1331	MTH 10-Mar-2010		O/C	0		
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14			1133610-4 360	MTH 10-Mar-2010		O/C	0		
215002	CONDENSOR ASSEMBLY 9912660-3			1134620-5 440	MTH 10-Mar-2010		O/C	0		
215003	RECEIVER DRYER ASSY 9912660-18			1134275-13 2476	MTH 10-Mar-2010		O/C	0		
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7			1133300-1 699	MTH 10-Mar-2010		O/C	0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7			1133300-1 700	MTH 10-Mar-2010		O/C	0		
215005	VANE AXIAL BLOWER ASSY.			PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD	KICT		1251171-6 NSN	MTH 23-Jan-2015 HRS 827.1 LDG 653			0 0 0		
216000 LEFT	THERMAL ACTUATOR	KICT		74S235H6F255 N/A	MTH 25-Jan-2013 HRS 652.4 LDG 529		O/C	0 0 0	1094.1	712.6
221001 AILERON	GSA 80 TORQUE SERVO			011-00877-00 66306542	MTH 10-Mar-2010		O/C	0		
221001 RUDDER	GSA 80 TORQUE SERVO			011-00877-00 66306562	MTH 10-Mar-2010		O/C	0		
221002 ELEVATOR	GSA 81 TORQUE SERVO	KMKE		011-00878-10 71305201	MTH 12-Aug-2011 HRS 338.3 LDG 300		O/C	0 0 0		
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO			011-00878-10 71307359	MTH 10-Mar-2010		O/C	0		
221003 AILERON	GSM 85A SERVO MOUNT			011-01436-A2 10905234	MTH 10-Mar-2010		O/C	0		
221003 ELEVATOR	GSM 85A SERVO MOUNT			011-01436-A0 11205247	MTH 10-Mar-2010		O/C	0		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT			011-01436-A1 11305242	MTH 10-Mar-2010		O/C	0		
221003 RUDDER	GSM 85 SERVO MOUNT	KMKE		11-01436-A3 11000161	MTH 06-Jul-2023 HRS 1288.4 LDG 996		O/C	0 0 0		
221004	GMC 710 AFCS CONTROLLER			011-01020-10 22005502	MTH 10-Mar-2010		O/C	0		
231002 NO. 1	GMA 1347D AUDIO PANEL	KMKE		011-03568-20 4QF105301	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
231002 NO. 2	GMA 1347D AUDIO PANEL	KMKE		011-03568-20 4QF105302	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		
231003 NO. 1	VHF COMM ANTENNA			VHF10-829 662	MTH 10-Mar-2010		O/C	0		
231003 NO. 2	VHF COMM ANTENNA			VHF10-829 0684	MTH 10-Mar-2010		O/C	0		
231011	SAT PHONE ANTENNA			S67-1575-109 NSN	MTH 10-Mar-2010		O/C	0		
231101	HIGH FREQUENCY CONTROLLER S3100-470			071-01605-0201 NSN	MTH 10-Mar-2010		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449			064-01073-0102 NSN	MTH 10-Mar-2010		O/C	0		
231103	HIGH FREQUENCY ANTENNA			16390 NSN	MTH 10-Mar-2010		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFER			064-01072-0101 NSN	MTH 10-Mar-2010		O/C	0		
233001	GRT10 XM REMOTE RECEIVER			PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
233002	GRC10 XM REMOTE CONTROL			PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
233003	ADAPTER MODULE			PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
243001 LEFT	DIGITAL GCU 9912682-3	LBB		GCSG550-5 09118856	MTH 19-May-2010 HRS 62.3 LDG 45		O/C			
243001 RIGHT	DIGITAL GCU 9912682-3	ICT		GCSG550-5 08224154	MTH 17-May-2010 HRS 60 LDG 42		O/C			
243002	EMER INST BATTERY	ICT		CBS24 01108	MTH 29-May-2021 HRS 1220.9 LDG 934		O/C			
243007	MAIN SHIP BATTERY CONCORDE (LEAD ACID)	ICT		RG-390E 41060792	MTH 19-Aug-2022 HRS 1261.2 LDG 967		O/C			
243015	RELAY DISCONNECT BATTERY S3155-1			A-931F CR-55746	MTH 10-Mar-2010		O/C	0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY			7018920-5 0735	MTH 10-Mar-2010		O/C	0		
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY			7018920-5 0736	MTH 10-Mar-2010		O/C	0		
245003	FLAP CONTROL MODULE			7018916-9 0460	MTH 10-Mar-2010		O/C	0		
245005 LEFT	ICE PROTECTION CONTROL			7018917-9 0400	MTH 10-Mar-2010		O/C	0		
245005 RIGHT	ICE PROTECTION CONTROL			7018918-13 0417	MTH 10-Mar-2010		O/C	0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL			7018919-13 0601	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL	7018919-13 0600	MTH 10-Mar-2010		O/C	0		
245008	DOOR MONITOR-	7018921-8 0362	MTH 10-Mar-2010		O/C	0		
245009	LANDING GEAR MONITOR-	7018923-12 0399	MTH 10-Mar-2010		O/C	0		
245010 LEFT	START CONTROL LBB	7018924-5 0650	MTH 19-May-2010 HRS 62.3 LDG 45		O/C	0 0 0		
245010 RIGHT	START CONTROL	7018924-5 0748	MTH 10-Mar-2010		O/C	0		
245011	FLAP MONITOR-	7018925-11 0409	MTH 10-Mar-2010		O/C	0		
245012 LEFT	SPEEDBRAKE ASSY	7018926-1 0797	MTH 10-Mar-2010		O/C	0		
245012 RIGHT	SPEEDBRAKE ASSY	7018926-1 0784	MTH 10-Mar-2010		O/C	0		
245013	DIAGNOSTIC UNIT	7018927-7 0418	MTH 10-Mar-2010		O/C	0		
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3 ICT	85-230-0 0943014M2	MTH 02-Jul-2010 HRS 107.2 LDG 87		O/C	0 0		
245015	MASTER INTERIOR SSR UNIT UZ100	10747P03E25 09076043	MTH 10-Mar-2010		O/C	0		
245016 RIGHT	AVN BUS #1 SENSOR UZ102	10747P03E25 09086143	MTH 10-Mar-2010		O/C	0		
245017 LEFT	AVN SENSOR UZ103	10747P03E25 09096339	MTH 10-Mar-2010		O/C	0		
245018 RIGHT	AVN BUS #2 SENSOR UZ104	10747P03E25 09116494	MTH 10-Mar-2010		O/C	0		
245019 LEFT	IGN #1 SENSOR UZ105	10747P03E10 09096429	MTH 10-Mar-2010		O/C	0		
245019 RIGHT	IGN #1 SENSOR UZ106	10747P03E10 09096428	MTH 10-Mar-2010		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107	10747P03E10 09116457	MTH 10-Mar-2010		O/C	0		
245020 RIGHT	IGN #2 SENSOR UZ108	10747P03E10 09096418	MTH 10-Mar-2010		O/C	0		
245021	COCKPIT FAN SENSOR UZ109	10747P03E25 09116517	MTH 10-Mar-2010		O/C	0		
245022	CABIN FAN SENSOR UZ110	10747P03E25 09086136	MTH 10-Mar-2010		O/C	0		
245023 LEFT	LH BOOST PUMP SENSOR UZ114	10747P03E25 09116495	MTH 10-Mar-2010		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR UZ111	10747P03E25 09116500	MTH 10-Mar-2010		O/C	0		
245024	CONDENSER FAN SENSOR UZ112	10747P03E25 09096361	MTH 10-Mar-2010		O/C	0		
245025	DC-DC CONVERTER UZ116	10747P03E10 09096421	MTH 10-Mar-2010		O/C	0		
245026	AVN EMERG SENSOR UZ200	10747P03E25 09096387	MTH 10-Mar-2010		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE	7018119-1 651	MTH 10-Mar-2010		O/C	0		
245201 RIGHT	CABIN ALTITUDE MODULE	7018119-1 655	MTH 10-Mar-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
251001	GLARESHIELD ASSEMBLY			4319027-17 140833-1	MTH 10-Mar-2010		O/C	0		
252041	CABINET, LEFT, FORWARD ICT			4379002-8 142050-1	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C			
252042	CABINET, RIGHT, FORWARD ICT			4379003-32 142581-2	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C			
256001 NO. 1	LIFE VEST	KMKE		P01074-207 10120850061	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256001 NO. 2	LIFE VEST	KMKE		P01074-207 10120850058	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256001 NO. 3	LIFE VEST	KMKE		P01074-207 10120850060	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256001 NO. 4	LIFE VEST	KMKE		P01074-207 10120850063	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256001 NO. 5	LIFE VEST	KMKE		P01074-207 10120850059	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256001 NO. 6	LIFE VEST	KMKE		P01074-207 10120850062	MTH 27-Oct-2020 HRS 1186.6 LDG 914		60	0 0 0	31-Oct-2025	16 m 14 d
256002	ELT BATTERY	KMKE		452-0133 384161-013	MTH 08-Dec-2019 HRS 1158.6 LDG 888		60	0	28-Feb-2025	8 m 11 d
256004	ELT ANTENNA			110-340 249313	MTH 10-Mar-2010		O/C	0		
256007	ELT PROCESSOR C406N			453-5060 08952	MTH 10-Mar-2010		O/C	0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 210829	MTH 10-Mar-2010		O/C	0		
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 210787	MTH 10-Mar-2010		O/C	0		
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KMKE		30401102-2 62589B1	MTH 27-Oct-2020 HRS 1186.6 LDG 914		O/C	0 0 0		
262003 LEFT	FIRE EXT CARTRIDGE	KMKE		13083-5 21H839-001	MTH 05-May-2022 HRS 1253 LDG 960		72	0 0	30-Apr-2028	46 m 13 d
Manufacture Date: 18-Apr-2022										
262003 RIGHT	FIRE EXT CARTRIDGE	KMKE		13083-5 21H839-001	MTH 05-May-2022 HRS 1253 LDG 960		72	0 0	30-Apr-2028	46 m 13 d
Manufacture Date: 18-Apr-2022										
262004	PORTABLE FIRE EXTINGUISHER KMKE			C352 H-01186607	MTH 05-May-2022 HRS 1253 LDG 960		O/C			
271001 LEFT	CONTROL WHEEL ASSY			4319065-1 1723	MTH 10-Mar-2010		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY			4319065-2 1670	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
273001	RUDDER TRIM ACTUATOR 9912639-2	SYLC-53361-1 462	MTH 10-Mar-2010		O/C	0		
273002	AILERON TRIM ACTUATOR 9912639-2	SYLC-53361-1 0049	MTH 10-Mar-2010		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1	MP50Y-1 320	MTH 10-Mar-2010		O/C	0		
275002 LEFT	FLAP ACTUATOR 9912640-1	41013930-105 0561	MTH 10-Mar-2010		O/C	0		
275002 RIGHT	FLAP ACTUATOR 9912640-2	41013930-106 0737	MTH 10-Mar-2010		O/C	0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-52	140527-5200 0727	MTH 10-Mar-2010		O/C	0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY KMKE	9914344-59 1090	MTH 06-Jul-2023 HRS 1288.4 LDG 996		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-2	41014070-103 0636	MTH 10-Mar-2010		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-2	41014070-103 0632	MTH 10-Mar-2010		O/C	0		
282001 LEFT	PRIMARY EJECTOR 9912190-5	LR45300A C1886	MTH 10-Mar-2010		O/C	0		
282001 RIGHT	PRIMARY EJECTOR 9912190-5	LR45300A C1889	MTH 10-Mar-2010		O/C	0		
282002	TRANSFER VALVE 9914103-6	ZSV57 09-090846	MTH 10-Mar-2010		O/C	0		
282003 LEFT	DC FUEL PUMP 9912553-1	1C7-23 11BE215	MTH 10-Mar-2010		O/C	0		
282003 RIGHT	DC FUEL PUMP 9912553-1	1C7-23 11BE212	MTH 10-Mar-2010		O/C	0		
282004 L1	SCAVENGE EJECTOR 9912190-2	RG45310 C2163	MTH 10-Mar-2010		O/C	0		
282004 L2	SCAVENGE EJECTOR 9912190-2	RG45310 C2164	MTH 10-Mar-2010		O/C	0		
282004 R1	SCAVENGE EJECTOR 9912190-2	RG45310 C2129	MTH 10-Mar-2010		O/C	0		
282004 R2	SCAVENGE EJECTOR 9912190-2	RG45310 C2170	MTH 10-Mar-2010		O/C	0		
282005 LEFT	VALVE-FUEL MOTOR 9912014-3	AV24B1507 211321	MTH 10-Mar-2010		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3	AV24B1507 195525	MTH 10-Mar-2010		O/C	0		
284001 L1	FUEL PROBE 9912664-1	020-251-001 0161	MTH 10-Mar-2010		O/C	0		
284001 L2	FUEL PROBE 9912664-2	020-251-002 0604	MTH 10-Mar-2010		O/C	0		
284001 L3	FUEL PROBE 9912664-3	020-251-003 0819	MTH 10-Mar-2010		O/C	0		
284001 L4	FUEL PROBE 9912664-4	020-251-004 0734	MTH 10-Mar-2010		O/C	0		
284001 L5	FUEL PROBE 9912664-5	020-251-005 0782	MTH 10-Mar-2010		O/C	0		
284001 R1	FUEL PROBE 9912664-1	020-251-001 0249	MTH 10-Mar-2010		O/C	0		
284001 R2	FUEL PROBE 9912664-2	020-251-002 0396	MTH 10-Mar-2010		O/C	0		
284001 R3	FUEL PROBE 9912664-3	020-251-003 0817	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
284001 R4	FUEL PROBE 9912664-4	020-251-004 0785	MTH 10-Mar-2010		O/C	0		
284001 R5	FUEL PROBE 9912664-5	020-251-005 0819	MTH 10-Mar-2010		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6	367-350-001 1254	MTH 10-Mar-2010		O/C	0		
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2	HM50C-3 119B	MTH 10-Mar-2010		O/C	0		
291002	HYDRAULIC CHECK VALVE	4001-20 5493A	MTH 10-Mar-2010		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE	19940933-1 030960	MTH 10-Mar-2010		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	80665 0301	MTH 10-Mar-2010		O/C	0		
291007	HYDRAULIC MANIFOLD 9912657-14	8257-3 0298	MTH 10-Mar-2010		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2	2672 0295	MTH 10-Mar-2010		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3	80664 0333	MTH 10-Mar-2010		O/C	0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	4251 0296	MTH 10-Mar-2010		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	4252 0296	MTH 10-Mar-2010		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15	9625-1 0308	MTH 10-Mar-2010		O/C	0		
291012	HYDRAULIC RESERVOIR ASSEMBLY	7017005-28 21137248	MTH 10-Mar-2010		O/C	0		
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	7550-2 0636	MTH 10-Mar-2010		O/C	0		
301001 LEFT	WING DE-ICE BOOT 9912662-17	P35-4D5317-17 NGZ8080	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		O/C	0 0 0		
301001 RIGHT	WING DE-ICE BOOT 9912662-18	P35-4D5317-18 MBWN200	MTH 10-Mar-2010		O/C	0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3	P29S4D5317-05 MBWA960	MTH 10-Mar-2010		O/C	0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4	P29S4D5317-06 MBWM120	MTH 10-Mar-2010		O/C	0		
301004 L1	DE-ICE PRESSURE SWITCH	1106P55-1 7344A	MTH 10-Mar-2010		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH	1106P55-1 7320A	MTH 10-Mar-2010		O/C	0		
301004 L3	DE-ICE PRESSURE SWITCH	1106P55-1 7373A	MTH 10-Mar-2010		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH	1106P55-1 7227A	MTH 10-Mar-2010		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH	1106P55-1 7225A	MTH 10-Mar-2010		O/C	0		
301004 R3	DE-ICE PRESSURE SWITCH	1106P55-1 7360A	MTH 10-Mar-2010		O/C	0		
301004	VERT DE-ICE BOOT 9912662-13	P29S4D5317-13 MBSB240	MTH 10-Mar-2010		O/C	0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY	5285-00-3 2272	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY 2350	5285-00-3	MTH 10-Mar-2010		O/C	0		
302002 LEFT	TEMP SWITCH 5465	1173T0759	MTH 10-Mar-2010		O/C	0		
302002 RIGHT	TEMP SWITCH 5813	1173T0759	MTH 10-Mar-2010		O/C	0		
304001 L1	DE-ICE VALVE N090917	3D2353-06	MTH 10-Mar-2010		O/C	0		
304001 L2	DE-ICE VALVE N085097	3D2353-06	MTH 10-Mar-2010		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER KMKE	7018108-30 0240	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER KMKE	7018108-30 0248	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY 7041020-5 288	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY 7041020-6 291	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
321001	NOSE LANDING GEAR TRUNNION 7042020-1 300	MTH 10-Mar-2010			O/C	0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY 7041050-4 445	MTH 10-Mar-2010 LDG 0			12000	0	12000	10998
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY 7041050-4 449	MTH 10-Mar-2010 LDG 0			12000	0	12000	10998
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY 7041030-2 293	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY 7041030-1 291	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK 6327504-6 2759	MTH 10-Mar-2010			O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK 6327504-6 2812	MTH 10-Mar-2010			O/C	0		
322002	NOSE GEAR FORK & PISTON ASSEMBLY 7042040-1 298	MTH 10-Mar-2010			O/C	0		
322003 NOSE GEAR	UPLOCK ACTUATOR 6327504-7 1379	MTH 10-Mar-2010			O/C	0		
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1 FA100036-001 FA100036-1-0324	MTH 10-Mar-2010 LDG 0			12000	0	12000	10998
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-5 FA100104-001 FA100104-1-0293	MTH 10-Mar-2010 LDG 0			12000	0	12000	10998
322010 RIGHT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-6 GRB FA100105-001 FA100105-1-0299	MTH 20-Sep-2012 HRS 607.6 LDG 503			12000	430	12073	11071



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
322011	NOSE LANDING GEAR ACTUATOR 9912654-2	FA100087-001 FA100087-1-0224	MTH 10-Mar-2010 LDG 0		12000	0	12000	10998
322202	SHIMMY DAMPER	7042030-2 0038	MTH 10-Mar-2010		O/C	0		
322205	LANDING GEAR STRUT ASSEMBLY NOSE	7042010-4 293	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
322206	LANDING GEAR DRAG BRACE ASSY NOSE	7042120-5 44	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
323001	LANDING GEAR ASSEMBLY LEFT	7041010-5 NSN	MTH 10-Mar-2010		O/C	0		
323001	LANDING GEAR ASSEMBLY RIGHT	7041010-6 NSN	MTH 10-Mar-2010		O/C	0		
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE 9914678-3 KICT	40005369-2 5745	MTH 30-Jan-2014 HRS 752.8 LDG 608		288		30-Nov-2031	89 m 13 d
Manufacture Date: 01-Nov-2007								
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE 9914678-4 KICT	40005399-1 6318	MTH 30-Jan-2014 HRS 752.8 LDG 608		288		31-Jul-2032	97 m 14 d
Manufacture Date: 01-Jul-2008								
323003	EMER BLOW DOWN BTL PRESSURE GAUGE 19940931-1 029739		MTH 10-Mar-2010		O/C	0		
324001	MAIN LANDING GEAR TIRE LEFT	021-523-0 9912646-1 KGRB	MTH 08-Mar-2018 HRS 1051 LDG 818		O/C	2 0 0		
324001	MAIN LANDING GEAR TIRE RIGHT	021-523-0 9912646-1 KMKE	MTH 18-Jan-2018 HRS 1035.6 LDG 808		O/C	0 0 0		
324002	NOSE LANDING GEAR TIRE 9912649-1 KLAS	079-606-0 4267S00248	MTH 24-Apr-2015 HRS 855.9 LDG 669		O/C	0 0 0		
324003	MAIN LANDING GEAR WHEEL LEFT	3-1640 9912645-1 KMKE	MTH 19-May-2017 HRS 1014.2 LDG 798		O/C	86 1014.2 798		
324003	MAIN LANDING GEAR WHEEL RIGHT	3-1640 9912645-1 KMKE	MTH 19-May-2017 HRS 1014.2 LDG 798		O/C	86 1014.2 798		
324004	NOSE LANDING GEAR WHEEL NOSE	3-1642 9912648-1	MTH 10-Mar-2010		O/C	0		
324005	MAIN LANDING GEAR BRAKE ASSY LEFT	2-1706-1 9912645-3 KMKE	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		O/C			
324005	MAIN LANDING GEAR BRAKE ASSY RIGHT	2-1706-1 9912645-3 KMKE	MTH 19-May-2017 HRS 1014.2 LDG 798 ACH 328.8		O/C			
324006	SHUTTLE VALVE LEFT	5145-1 9914689-4	MTH 10-Mar-2010		O/C	0		
324006	SHUTTLE VALVE RIGHT	5145-1 9914689-4	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324007	BRAKE METERING VALVE 9912650-9			84-75 0325	MTH 10-Mar-2010		O/C	0		
324101 LEFT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0587	MTH 10-Mar-2010		O/C	0		
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0636	MTH 10-Mar-2010		O/C	0		
324101	PARKING BRAKE VALVE 9912388-10			98433-1 0262	MTH 10-Mar-2010		O/C	0		
324102	ANTISKID CONTROL UNIT 9912650-1			556-3 302829401	MTH 10-Mar-2010		O/C	0		
324103	ANTISKID CONTROL VALVE 9912650-6			211-134-1 0331	MTH 10-Mar-2010		O/C	0		
324104	EMERGENCY BRAKE VALVE 9912651-1			72298 0305	MTH 10-Mar-2010		O/C	0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE			19940931-1 029733	MTH 10-Mar-2010		O/C	0		
325001	BUNGE ASSEMBLY			7042072-9 NSN	MTH 10-Mar-2010		O/C	0		
334001 LEFT	POWER SUPPLY 9912677-3			82004-1 000635	MTH 10-Mar-2010		O/C	0		
334001 RIGHT	POWER SUPPLY 9912677-3			82004-1 000710	MTH 10-Mar-2010		O/C	0		
334002	GROUND RECOGNITION LIGHT 9912679-3			84003-2 000477	MTH 10-Mar-2010		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1			84005-1 000598	MTH 10-Mar-2010 HRS 0		8000	0	8000	6706.5
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2			84005-2 000539	MTH 10-Mar-2010 HRS 0		8000	0	8000	6706.5
335169 LH	LANDING/TAXI LIGHT LIGHT *CF			9912677-1 000558	MTH 10-Mar-2010		O/C			
335169 R/H	LANDING/TAXI LIGHT LIGHT *CF			9912677-2 000569			O/C			
341001	SWAAT UNIT 9912689-1			0863B2 346	MTH 10-Mar-2010		O/C	0		
341002 NO. 1	GDC 74B AIRDATA SYSTEM KICT			011-01110-00 43800612	MTH 14-Jun-2024 HRS 1293.5 LDG 1002		O/C			
341002 NO. 2	GDC 74B AIRDATA SYSTEM			011-01110-00 43805830	MTH 10-Mar-2010		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM			011-00978-00 47913716	MTH 10-Mar-2010		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM			011-00978-00 47913670	MTH 10-Mar-2010		O/C	0		
341004 LEFT	PITOT PROBE 9912678-1			0851LN 270011	MTH 10-Mar-2010		O/C	0		
341004 RIGHT	PITOT PROBE 9912678-1			0851LN 269727	MTH 10-Mar-2010		O/C	0		
342001 STANDBY	ALTIMETER S3100-465			162350-1161 179065C	MTH 10-Mar-2010		O/C	0		
342002 AIRSPEED	INDICATOR			261440-1143 294363A	MTH 10-Mar-2010		O/C	0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE KMKE			011-00831-00 4671154	MTH 05-May-2022 HRS 1253 LDG 960		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE	KMKE		011-00831-00 4671151	MTH 05-May-2022 HRS 1253 LDG 960		O/C			
342003	MAGNETIC COMPASS			S2800-821 NSN	MTH 10-Mar-2010		O/C	0		
342004 NO. 1	GDU 1040A DISPLAY	KMKE		011-03470-10 494105042	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		
342004 NO. 2	GDU 1040A DISPLAY	KMKE		011-03470-10 494105056	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42013021	MTH 10-Mar-2010		O/C	0		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42013043	MTH 10-Mar-2010		O/C	0		
342006 NO. 1	GMU 44 MAGNETOMETER			011-00870-00 47514542	MTH 10-Mar-2010		O/C	0		
342006 NO. 2	GMU 44 MAGNETOMETER			011-00870-00 47514580	MTH 10-Mar-2010		O/C	0		
342007	GDU 1500 MFD UNIT	KMKE		011-03472-00 496001532	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513			4200-21 M09-10286	MTH 10-Mar-2010		O/C	0		
3420SD	FS510 SD CARD	KMKE		011-03595-00 402008374	MTH 07-Jun-2019 HRS 1136.5 LDG 869		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR ICT			011-00883-20 47203560	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C			
344002	GARMIN GDL-69A DATA LINK			011-00987-00 47762328	MTH 10-Mar-2010		O/C	0		
345001	GPS/WAAS/XM ANTENNA			013-00245-00 6668	MTH 10-Mar-2010		O/C	0		
345002 RIGHT	TRANSPONDER	KMKE		011-00779-21 84805242	MTH 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		O/C			
345003 LEFT	TRANSPONDER	KMKE		011-00779-21 84810061	MTH 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KGRB			011-04475-00 48V000520	MTH 18-Feb-2021 HRS 1196.4 LDG 919		O/C	3 0 0		
345005	ADF RECEIVER			013-00166-00 NSN	MTH 10-Mar-2010		O/C	0		
345006	ADF ANTENNA			013-00165-00 NSN	MTH 10-Mar-2010		O/C	0		
345007	MARKER BEACON ANTENNA			MB10-754-2 319	MTH 10-Mar-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345008	GLIDE SLOPE ANTENNA	RGS10-48 14963	MTH 10-Mar-2010		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA	L10-611-14 2675	MTH 10-Mar-2010		O/C	0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA	L10-611-14 2681	MTH 10-Mar-2010		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA	L10-611-14 2665	MTH 10-Mar-2010		O/C	0		
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA	L10-611-14 2671	MTH 10-Mar-2010		O/C	0		
345010 LEFT	NAV ANTENNA	PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
345010 RIGHT	NAV ANTENNA	PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
345010	VOR/LOC ANTENNA	VT10-767-3 0964	MTH 10-Mar-2010		O/C	0		
345011	KN63 DME TRANSCEIVER	066-01070-0001 33500	MTH 10-Mar-2010		O/C	0		
345013	RMI CONVERTER	013-00167-00 NSN	MTH 10-Mar-2010		O/C	0		
345014	GPS/WAAS/ ANTENNA	013-00244-00 6724	MTH 10-Mar-2010		O/C	0		
345015	DME ANTENNA	L10-611-14 2667	MTH 10-Mar-2010		O/C	0		
346010	TAS PROCESSOR	066-01152-0101 KTA810-2665	MTH 10-Mar-2010		O/C	0		
346011 BOTTOM	TAS ANTENNA	L10-611-14 2825	MTH 10-Mar-2010		O/C	0		
346011 TOP	TAS ANTENNA	071-01599-0100 21635	MTH 10-Mar-2010		O/C	0		
346012	CONFIGURATION MODULE	071-00112-0200 15660	MTH 10-Mar-2010		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT KGRB	011-01105-01 15W009952	MTH 09-Aug-2018 HRS 1074.1 LDG 831		O/C			
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT KGRB	011-01105-01 15W009956	MTH 09-Aug-2018 HRS 1074.1 LDG 831		O/C			
350001	OXYGEN BOTTLE	KMKE 4441073-040 0775-252	MTH 03-Nov-2022 HRS 1266.7 LDG 973		180	0 0 0	30-Nov-2036	149 m 13 d
Manufacture Date: 01-Nov-2021								
350002	OXYGEN PRESSURE GAUGE C668512-0101	MD97-1 L09-11008	MTH 10-Mar-2010		O/C	0		
351001 LEFT	CREW OXYGEN MASK 9914067-41 KMKE	MC10-16-101 81078	MTH 03-Dec-2018 HRS 1099.9 LDG 846		72	1	30-Nov-2024	5 m 13 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41 KMKE	MC10-16-101 81441	MTH 08-Jun-2019 HRS 1136.5 LDG 869		72	1	31-May-2025	11 m 14 d
361001 LEFT	PRECOOLER 9914402-7	8315-2 TO610	MTH 10-Mar-2010		O/C	0		
361001 RIGHT	PRECOOLER 9914402-7	8315-2 TO609	MTH 10-Mar-2010		O/C	0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY	2601-34 0679A	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
361002 RIGHT	VARIABLE VENTURI VALVE ASSY 9912510-2	2601-34 0685A	MTH 10-Mar-2010		O/C	0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2	1H75-23 9BE64	MTH 10-Mar-2010		O/C	0		
361004 LEFT	B/A SHUTOFF VALVE	5253-00-3 2713	MTH 10-Mar-2010		O/C	0		
361004 RIGHT	B/A SHUTOFF VALVE	5253-00-3 2882	MTH 10-Mar-2010		O/C	0		
361101 R1	DE-ICE VALVE	3D2353-06 N092892	MTH 10-Mar-2010		O/C	0		
361101 R2	DE-ICE VALVE	3D2353-06 N093487	MTH 10-Mar-2010		O/C	0		
383001	TOILET CABINET ICT	4379004-32 1741534-2	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C			
522001	CABIN DOOR SEAL 9912674-3	S-22560-3 346	MTH 10-Mar-2010		O/C	0		
522002	ESCAPE HATCH SEAL 9912675-1	S-22561 442	MTH 10-Mar-2010		O/C	0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY 7013022-3 293	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY 7013022-4 293	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY 7013022-11 293	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY 7013022-10 293	MTH 10-Mar-2010 LDG 0			20000	0	20000	18998
534101 FWD SEAT	ENGINE BEAM	7012061-3 295	MTH 10-Mar-2010		O/C	0		
552001 LEFT	ELEVATOR ASSEMBLY	7034001-11 211	MTH 10-Mar-2010		O/C	0		
552001 RIGHT	ELEVATOR ASSEMBLY	7034001-12 216	MTH 10-Mar-2010		O/C	0		
553001	VERTICAL STABILIZER ASSY	7031001-1 260	MTH 10-Mar-2010		O/C	0		
561001 LEFT	WINDSHIELD ASSY, (LH) 9912745-9	NP-188601-1 09310H7726	MTH 10-Mar-2010		O/C	0		
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-10	NP-188601-2 09251H1947	MTH 10-Mar-2010		O/C	0		
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1	93310-1 1677	MTH 10-Mar-2010		O/C	0		
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2	93310-2 1666	MTH 10-Mar-2010		O/C	0		
562003 L1	CABIN WINDOW 9912747-10	93320-10 2940	MTH 10-Mar-2010		O/C	0		
562003 L2	CABIN WINDOW 9912747-10	93320-10 2869	MTH 10-Mar-2010		O/C	0		
562003 L3	CABIN WINDOW 9912747-10	93320-10 2926	MTH 10-Mar-2010		O/C	0		
562003 R1	CABIN WINDOW 9912747-10	93320-10 2938	MTH 10-Mar-2010		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10	93320-10 2765	MTH 10-Mar-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
562003 R3	CABIN WINDOW 9912747-10	93320-10 2915	MTH 10-Mar-2010		O/C	0		
572001 LEFT WING	FWD SPAR	7022022-1 87842	MTH 10-Mar-2010		O/C	0		
572001 RIGHT WING	FWD SPAR	7022022-2 87843	MTH 10-Mar-2010		O/C	0		
572002 LEFT WING	REAR SPAR	7022032-3 87965	MTH 10-Mar-2010		O/C	0		
572002 RIGHT WING	REAR SPAR	7022032-4 87966	MTH 10-Mar-2010		O/C	0		
572003 LEFT WING	MAIN SPAR	7022027-1 87904	MTH 10-Mar-2010		O/C	0		
572003 RIGHT WING	MAIN SPAR	7022027-2 87905	MTH 10-Mar-2010		O/C	0		
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY	7041165-5 278	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY	7041165-6 289	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY	7041155-9 297	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY	7041155-10 278	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY	7041175-5 283	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY	7041175-6 307	MTH 10-Mar-2010 LDG 0		20000	0	20000	18998
712001 LEFT	ENG CHANNEL-FWD MOUNT	7051001-1 230	MTH 10-Mar-2010		O/C	0		
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM	LM-471-SA12 9912647-1 1508	MTH 10-Mar-2010 HRS 0		4000	0	4000	2706.5
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM	LM-471-SA12 9912647-1 1504	MTH 10-Mar-2010 HRS 0		4000	0	4000	2706.5
712001 RIGHT	ENG CHANNEL-FWD MOUNT	7051001-2 306	MTH 10-Mar-2010		O/C	0		
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM	LM-471-SA12 9912647-1 1442	MTH 10-Mar-2010 HRS 0		4000	0	4000	2706.5
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM	LM-471-SA12 9912647-1 1417	MTH 10-Mar-2010 HRS 0		4000	0	4000	2706.5
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY	LM-471-SA4 9912647-3 LK2364	MTH 10-Mar-2010 HRS 0		8000	0	8000	6706.5
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY	LM-471-SA4 9912647-3 LKL2385	MTH 10-Mar-2010 HRS 0		8000	0	8000	6706.5
712003 AFT	ENGINE BEAM	7012066-2 0293	MTH 10-Mar-2010		O/C	0		
712003 LEFT	AFT ENGINE MOUNT CHANNEL	7051001-3 327	MTH 10-Mar-2010		O/C	0		
712003 RIGHT	AFT ENGINE MOUNT CHANNEL	7051001-4 303	MTH 10-Mar-2010		O/C	0		
71EN1 NO. 1	ENGINE	35C0510-01 PCE-LB0609			E/C			
71EN2 NO. 2	ENGINE	35C0510-01 PCE-LB0608			E/C			
72-40-01-900-801 E1	COMBUSTION CHAMBER LINER	35C4281-01 A005C5E1	MTH 03-Jun-2024 HRS 1293.5 LDG 1002		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-40-01-900-801 E2	COMBUSTION CHAMBER LINER	35C4281-01 A005C5CB	MTH 03-Jun-2024 HRS 1293.5 LDG 1002		O/C	0 0 0		
720010 E1	FAN ROTOR	35C1940-01 FRAEPLDE64	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
720010 E2	FAN ROTOR	35C1940-01 FRAEPLDE68	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
721010 E1	HP TURBINE DISK	35C3921-01 CRAZADQC209	MTH 03-Jun-2024 HRS 1293.5 LDG 1002 ACCC YC		5250	0	(6247)6252	5250 5250
721010 E2	HP TURBINE DISK	35C2311-01 CRAZADQC201	MTH 10-Mar-2010 LDG 5 ACCC YC		5250	0 0	(5250)5255	4253 4253
721020 E1	LP TURBINE DISK	35C2372-01 FRAEPKWB30	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
721020 E2	LP TURBINE DISK	35C2372-01 FRAEPKWB9	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
723010 E1	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 AAPPIARV2022	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
723010 E2	IMPELLER AND SHAFT ASSEMBLY	35C4888-01 AAPPIARV2042	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
725010 E1	HP COMPRESSOR ROTOR	35C3661-01 FRAEPKPB125	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
725010 E2	HP COMPRESSOR ROTOR	35C3661-01 FRAEPKPB129	MTH 10-Mar-2010 LDG 5 ACCC YC		10500	0 0	(10500)10505	9503 9503
726010 E1	AGB STARTER MAGNETIC SEAL	PN SN-UNKNOWN	MTH 10-Mar-2010 HRS 0		1750	0	(1750)1750	456.5
726010 E2	AGB STARTER MAGNETIC SEAL	PN SN-UNKNOWN	MTH 10-Mar-2010 HRS 0		1750	0	(1750)1750	456.5
730001 LEFT	ENGINE FUEL PRESSURE SWITCH	1103P0448 9912033-2 9134	MTH 10-Mar-2010		O/C	0		
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH	1103P0448 9912033-2 9063	MTH 10-Mar-2010		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITTER	TFF1573-4 9912417-1 0850-030	MTH 10-Mar-2010		O/C	0		
733001 RIGHT	FUEL FLOW TRANSMITTER	TFF1573-4 9912417-1 0931-014	MTH 10-Mar-2010		O/C	0		
731050 E1	FUEL MANIFOLD	35C4658-01 DE1BFL1008	MTH 10-Mar-2010		O/C	0		
731050 E2	FUEL MANIFOLD	35C4658-01 DE1BFM1235	MTH 10-Mar-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description		Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
732101 E1	FUEL METERING UNIT (F.M.U.)		35C0794-04 16771424	MTH 10-Mar-2010		H/T H/T	0		
732101 E2	FUEL METERING UNIT (F.M.U.)		35C0794-04 16772925	MTH 10-Mar-2010		H/T H/T	0		
741001 E1	IGNITION EXCITER		35C5472-01 WDA110055	MTH 10-Mar-2010		O/C	0		
741001 E2	IGNITION EXCITER		35C5472-01 WDA110047	MTH 10-Mar-2010		O/C	0		
741002 E1 LEFT	IGNITER CABLE		35C0844-01 NSN	MTH 10-Mar-2010		O/C	0		
741002 E2 LEFT	IGNITER CABLE		35C0844-01 NSN	MTH 10-Mar-2010		O/C	0		
741003 E1 RIGHT	IGNITER CABLE		35C0799-01 NSN	MTH 10-Mar-2010		O/C	0		
741003 E2 RIGHT	IGNITER CABLE		35C0799-01 NSN	MTH 10-Mar-2010		O/C	0		
741004 E1 INBOARD	SPARK IGNITER	ICT	35C2353-02 WDA111186	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C	0 0 0		
741004 E2 INBOARD	SPARK IGNITER	ICT	35C2353-02 WDA110028	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C	0 0 0		
741005 E1 OUTBOARD	SPARK IGNITER	ICT	35C2353-02 NSN	MTH 15-Feb-2011 HRS 204.7 LDG 174		O/C	0 0 0		
741005 E2 OUTBOARD	SPARK IGNITER	ICT	35C2353-02 WDA137725	MTH 29-May-2021 HRS 1220.9 LDG 934		O/C			
751003 E1	BLEED VALVE ACTUATOR		35C2851-02 16759917	MTH 10-Mar-2010		H/T H/T	0		
751003 E2	BLEED VALVE ACTUATOR		35C2851-02 16749289	MTH 10-Mar-2010		H/T H/T	0		
761001 E1	FADEC	KICT	01R35C4035-04 09-801	MTH 25-Jan-2013 HRS 652.4 LDG 529		O/C			
761001 E2	FADEC	KICT	01R35C4035-04 09-799	MTH 25-Jan-2013 HRS 652.4 LDG 529		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)		35C3778-04 WA38344	MTH 10-Mar-2010		H/T H/T	0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)		35C3778-04 WA38341	MTH 10-Mar-2010		H/T H/T	0		
793001 E1	OIL TEMP SENSOR		102-00083 07372	MTH 10-Mar-2010		O/C	0		
793001 E2	OIL TEMP SENSOR		102-00083 07498	MTH 10-Mar-2010		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER KNKE		APTE-304A-250G 7723-9-322	MTH 19-May-2017 HRS 1014.2 LDG 798		O/C	86 1014.2 798		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
793002 E2	OIL PRESSURE TRANSMITER KNKE	APTE-304A-250G 7723-5-201	MTH 19-May-2017 HRS 1014.2 LDG 798		O/C	86 1014.2 798		
793010 E1	CHIP COLLECTOR	PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
793010 E2	CHIP COLLECTOR	PN SN-UNKNOWN	MTH 10-Mar-2010		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1 ICT	MG94E-1 974D	MTH 29-May-2021 HRS 1220.9 LDG 934		1500	0	2720.9	1427.4
801000 RIGHT	STARTER GENERATOR 9912676-1 ICT	MG94E-1 953D	MTH 29-May-2021 HRS 1220.9 LDG 934		1500	0	2720.9	1427.4



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 510-99-02 REV 01	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 02)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 510-99-02	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 510-11-03	PLACARDS AND MARKINGS - BRAKE ACCUMULATOR PLACARD INSPECTION	MKE		RECOMMENDED	MTH 03-Mar-2012 HRS 489 LDG 412		A/R			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SL510-11-03 BRAKE ACCUMULATOR PLACARD INSPECTION. DATED JUNE 27, 2011.									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02)									
			INFORMATIONAL				-			
MOC :										
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03)									
			INFORMATIONAL				A/R			
MOC :										
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04)									
			INFORMATIONAL				A/R			
MOC :										
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)									
			INFORMATIONAL				A/R			
MOC :										
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01)									
			INFORMATIONAL				-			
MOC :										
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL									
			INFORMATIONAL				-			
MOC :										
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT									
	ICT	RECOMMENDED	MTH	29-May-2021			-			N/A
			HRS	1220.9						
			LDG	934						
MOC : NOT APPLICABLE - THIS SERVICE LETTER DOES NOT APPLY TO THIS AIRCRAFT, DUE TO P/N: 9912661-6 PRESSURIZATION CONTROLLER BEING INSTALLED.										
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT									
			OPTIONAL				-			
MOC :										
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT									
	GRB	OPTIONAL	MTH	20-Jul-2012			A/R			Complete
			HRS	592						
MOC : COMPLIED WITH - INSTALLED SB 510-23-02 ENABLING XM RADIO IN THE COCKPIT										
SL 510-23-01	LIGHTNING RELATED ANOMALIES OF THE GARMIN GMA 1347[D] AUDIO PANEL									
			INFORMATIONAL				A/R			
MOC :										
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION									
	KICT	MANDATORY	MTH	29-Jan-2014			A/R			N/A
			HRS	752.8						
			LDG	608						
MOC : NOT APPLICABLE - SL510-24-08 R1; STARTER/GENERATOR INSPECTION, DATED MARCH 10, 2010. SL DOES NOT APPLY TO THIS AIRCRAFT DUE TO AIRCRAFT SERIAL NUMBER.										
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION									
			MANDATORY	MTH			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.										
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)									
	ICT	MANDATORY	MTH	08-Sep-2010			A/R			Complete
			HRS	185.1						
			LDG	147						
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-11, RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION	ICT		MANDATORY	MTH 08-Sep-2010 HRS 185.1 LDG 147		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-12, CONTROL COLUMN TIE STRAP INSPECTION										
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION	ICT		MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: ACCOMPLISHED SL510-24-13, THROTTLE QUADRANT WIRE BUNDLE INSPECTION; DATED JUNE 30, 2011.										
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION	KMKE		MANDATORY	DAYS 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRINTED CIRCUIT BOARD VERIFICATION, SL510-24-14 R1 DATED 9/28/2016.										
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)	KMKE		MANDATORY	DAYS 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRINTED CIRCUIT BOARD VERIFICATION, SL510-24-14 DATED 9/13/2016.										
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT			OPTIONAL			A/R			
MOC :										
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER			DISCRETIONARY			A/R			
MOC :										
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS			OPTIONAL			-			
MOC :										
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION			MANDATORY	DAYS		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE -INCORPORATED ON PRODUCTION AIRCRAFT -0278 AND ON										
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION	KMKE		RECOMMENDED	MTH 25-Apr-2013 HRS 676.1 LDG 547		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-27-02 SPEED BRAKE MECHANICAL SWITCH CONVERSION SERVICE BULLETIN DATED 02/27/2013.										
SB 510-28-02	LOCKING FUEL CAP INSTALLATION			OPTIONAL			A/R			
MOC :										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
MOC :										
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT			DISCRETIONARY			-			
MOC :										
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01)			DISCRETIONARY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT	KICT	DISCRETIONARY	MTH 25-Jan-2013 HRS 652.4 LDG 529		A/R				Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-30-03 R1; WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT, DATED OCTOBER 24, 2011.										
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01)		DISCRETIONARY			A/R				
MOC :										
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT		MANDATORY	MTH		A/R				Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.										
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	KICT	MANDATORY	MTH 25-Jan-2013 HRS 652.4 LDG 529		-				Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-30-05; WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION, DATED APRIL 04, 2012.										
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT	KMKE	RECOMMENDED	MTH 19-May-2017 HRS 1014.2 LDG 798		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT, SERVICE BULLETIN DATED 03 AUG 2016.										
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)	ICT	RECOMMENDED	MTH 08-May-2024 HRS 1293.5 LDG 1002		-				Complete
MOC : COMPLIED WITH - SB510-30-06; WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT. IS C/W DUE TO REV. 1 WAS ACCOMPLISHED.										
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-				
MOC :										
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02)		INFORMATIONAL			A/R				
MOC :										
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03)		INFORMATIONAL			A/R				
MOC :										
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)		INFORMATIONAL			A/R				
MOC :										
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01)		INFORMATIONAL			A/R				
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION		INFORMATIONAL			-				
MOC :										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION		INFORMATIONAL			-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL		-			
MOC :									
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	KICT	RECOMMENDED	MTH 25-Jan-2013 HRS 652.4 LDG 529		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-32-05; NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION, DATED APRIL 20, 2012.									
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	KMKE	MANDATORY	DAYS 19-May-2017 HRS 1014.2 LDG 798		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION, SERVICE LETTER DATED 17 FEB 2017.									
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	KGRB	MANDATORY	DAYS 20-Aug-2018 HRS 1074.1 LDG 831		-			Complete
MOC : COMPLIED WITH - ALL LENGTHS WITHIN TOLERANCE.									
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT		OPTIONAL			-			
MOC :									
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	ICT	OPTIONAL	MTH 19-Feb-2011 HRS 205.9 LDG 177		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: SB510-34-10, GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION, WAS FOUND TO BE PREVIOUSLY ACCOMPLISHED. NO ADDITIONAL ACTION REQUIRED.									
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	MKE	MANDATORY	MTH 03-Mar-2012 HRS 489 LDG 412		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-11 R1 GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE. DATED JULY 13, 2011.									
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01)	ICT	MANDATORY	MTH 26-May-2011 HRS 296.6 LDG 256		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-34-11 GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE; ORIGINAL ISSUE DATED APRIL 8, 2011.									
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	MKE	MANDATORY	MTH 03-Mar-2012 HRS 489 LDG 412		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-12 R1 GARMIN DISPLAY IMPROVEMENT. DATED FEB. 13, 2012.									
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB510-34-12; GARMIN DISPLAY IMPROVEMENT. IS C/W DUE TO REV. 1 WAS ACCOMPLISHED.									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	KGRB	MANDATORY	MTH 31-Dec-2012 HRS 648.9 LDG 527		-				Complete
MOC : COMPLIED WITH - C/W G1000 SOFTWARE UPGRADE VERSION 010-00435-24										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE	KMKE	MANDATORY	MTH 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH GARMIN GRS-77 AHRS SOFTWARE UPDATE, SB510-334-16 R1 DATED 9/30/2016.										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)	KMKE	OPTIONAL	MTH 10-Feb-2017 HRS 992.8 LDG 785 ACH 320		-				Complete
MOC : COMPLIED WITH - COMPLIED WITH GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE, SB510-34-17 R1 DATED 9/28/2016.										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)		OPTIONAL			-				
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE		OPTIONAL			-				
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE		OPTIONAL			-				
MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE	ICT	RECOMMENDED	MTH 08-May-2024 HRS 1293.5 LDG 1002		-				N/A
MOC : NOT APPLICABLE - SB510-34-18; GARMIN G1000 ADS-B OUT SOFTWARE UPDATE. DOES NOT APPLY DUE TO G1000 NXI STC WAS ACCOMPLISHED.										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE		INFORMATIONAL			-				
MOC :										
SL 510-34-01	TRANSMITTAL OF GARMIN SERVICE ALERT 070424-00		INFORMATIONAL				A/R			
MOC :										
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING		INFORMATIONAL				A/R			
MOC :										
SL 510-34-05	GARMIN G1000 TRANSPONDER OPERATION CHANGE		INFORMATIONAL				A/R			
MOC :										
SL 510-34-06	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0811, G1000 SERIES FLIGHT PLAN SEQUENCING ISSUE		INFORMATIONAL				A/R			
MOC :										
SL 510-34-07	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 0825 LPV AND LNAV/VNAV APPROACHES WITH THREE-CHARACTER AIRPORT IDENTIFIERS		INFORMATIONAL				A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-08	GPS/WAAS LOSS OF RECEPTION IN ALASKA, NORTHWEST CANADA, AND EASTERN RUSSIA									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-10	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0915 REVISION A, G1000 SERIES NAVIGATION SUSPENDING DURING NON-PRECISION APPROACHES									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-12	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0933 REVISION A, SYSTEM MAY SELECT NAV 2 AS A NAVIGATION SOURCE DURING APPROACH									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-13	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0922 REVISION A, VOR OR LOC/ILS APPROACHES									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	ICT		RECOMMENDED	MTH 15-Feb-2011 HRS 204.7 LDG 174		A/R			Complete
	MOC :			COMPLIED WITH - ACCOMPLISHED SL510-34-15, GARMIN SB 1017 GWX WEATHER RADAR MOD 1.						
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS									
				INFORMATIONAL			A/R			
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION						-			
				INFORMATIONAL						
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL						-			
				INFORMATIONAL						
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	KMKE		RECOMMENDED	MTH 19-May-2017 HRS 1014.2 LDG 798		-			Complete
	MOC :			COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL510-34-23 "NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT".						



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL			-			
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL			-			
	MOC :									
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG			INFORMATIONAL			-			
	MOC :									
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)			INFORMATIONAL			-			
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KMKE		MANDATORY	MTH 01-May-2016 DAYS 952.1 HRS 755 LDG		-			N/A
	MOC : NOT APPLICABLE - CIL-35-05 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO CREW MASK P/N MC10-16-101 BEING INSTALLED (PER SERVICE BULLETIN MCF-SBU-35-001 REVISION 01, DATED 20121203. NO FURTHER ACTION REQUIRED.									
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)	ICT		MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - SL510-35-01 REV. 1; TRANSMITTAL OF INTERTECHNIQUE SB MXH-350-240. IS C/W DUE TO REV. 2 WAS ACCOMPLISHED.									
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KICT		MANDATORY	MTH 25-Jan-2013 HRS 652.4 LDG 529		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL510-35-01 R2; TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, DATED OCTOBER 25, 2012.									
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	ICT		MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		-			Complete
	MOC : COMPLIED WITH - COMMENTS: ACCOMPLISHED SL510-35-01 TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240; DATED SEPTEMBER 2, 2011.									
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY			A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE C/W AT PRODUCTION ON -0095 AND ON.									
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	KMKE		MANDATORY	DAYS 06-Jun-2020 HRS 1170.3 LDG 901		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-52-06, EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT, DATED 01/16/2020.									
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT	KMKE	MANDATORY		DAYS 08-Dec-2019		-			Complete
					HRS 1158.6					
					LDG 888					
MOC : COMPLIED WITH - COMPLIED WITH SL510-052-06, DOORS-INSPECT AND TORQUE THE INNER EMERGENCY EXIT DOOR HANDLE BOLT AND NUT.										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS	KMKE	DISCRETIONARY		MTH 18-Jan-2018		-			Complete
					HRS 1035.6					
					LDG 808					
MOC : COMPLIED WITH - ACCOMPLISHED SB510-54-01 REVISION 1 DATED JUNE 4, 2012; PYLON SKIN IMPROVEMENTS ON RH PYLON.										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)	ICT	MANDATORY		DAYS 26-May-2011		A/R			Complete
					HRS 296.6					
					LDG 256					
MOC : COMPLIED WITH - ACCOMPLISHED SL510-55-02 HORIZONTAL STABILIZER SEALANT INSPECTION; REVISION 1 DATED APRIL 28, 2011.										
SL 510-55-02 REV 02	HORIZONTAL STABILIZER SEALANT INSPECTION	ICT	MANDATORY		DAYS 13-Jan-2012		A/R			Complete
					HRS 460.9					
					LDG 392					
MOC : COMPLIED WITH - ACCOMPLISHED SL510-55-02 REV. 2 HORIZONTAL STABILIZER SEALANT INSPECTION; DATED AUGUST 31, 2011.										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)	ICT	MANDATORY		MTH 19-Feb-2011		A/R			Complete
					HRS 205.9					
					LDG 177					
MOC : COMPLIED WITH - COMMENTS: ACCOMPLISHED SL510-55-02, HORIZONTAL STABILIZER SEALANT INSPECTION										
SB PW600-72-63000 R01 E1	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS		CATEGORY 11				-			
MOC :										
SB PW600-72-63000 R01 E2	FOR INFORMATIONAL RECORD PURPOSES OMNIBUS		CATEGORY 11				-			
MOC :										
SB PW600-72-63001 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER	ICT	CATEGORY 6		MTH 09-May-2024		-			Complete
					HRS 1293.5					
					LDG 1002					
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63001 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER		CATEGORY 6		MTH 09-May-2024		-			Complete
					HRS 1293.5					
					LDG 1002					
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS		CATEGORY 5		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS		CATEGORY 5		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY ICT CATEGORY 7	MTH HRS LDG	09-May-2024 1293.5 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7	MTH HRS LDG	09-May-2024 1293.5 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6	MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6	MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7			MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7			MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY CATEGORY 6			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO REV. 1 WAS ACCOMPLISHED									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)		CATEGORY 9	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)		CATEGORY 9	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63021 E1	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING	ICT	CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
	MOC : NOT APPLICABLE - SB PW600-72-63021; INSPECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.								
SB PW600-72-63021 E2	INSPECTION/CORRECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING	ICT	CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
	MOC : NOT APPLICABLE - SB PW600-72-63021; INSPECTION OF SERIAL NUMBER BAR CODE LABELLING ON BEARING PACKAGING. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.								
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)	ICT	CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - SB PW600-72-63022 REV. 1; REPLACE COMPRESSOR IMPELLER & SHAFT ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)	ICT	CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - SB PW600-72-63022 REV. 1; REPLACE COMPRESSOR IMPELLER & SHAFT ASSEMBLY. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.								
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY	ICT	CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY	ICT	CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)		CATEGORY 7	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)		CATEGORY 7	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING		CATEGORY 7	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING CATEGORY 7		MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER CATEGORY 7		MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER CATEGORY 7		MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9		MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9		MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8				-			
	MOC :							
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8				-			
	MOC :							
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8		MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01) CATEGORY 8		MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY ICT CATEGORY 5		MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED							
SB PW600-72-63028 R01 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY ICT CATEGORY 5		MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED							
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5		MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01) CATEGORY 5		MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01) CATEGORY 7				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63037 R01 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63037 R01 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01) CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72-63043 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) ICT CATEGORY 6		MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63043 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) ICT CATEGORY 6		MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								
SB PW600-72-63043 R02 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER ICT CATEGORY 6		MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED								



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63043 R02 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63043 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)			CATEGORY 6	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01)			CATEGORY 6	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - SB PW600-72-63044; INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.										
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - SB PW600-72-63044; INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY	ICT			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY	ICT			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63051 R01 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63051 R01 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02)	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)			CATEGORY 7	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)			CATEGORY 7	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)			CATEGORY 7	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)			CATEGORY 7	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS	UNK		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY	UNK			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY	ICT			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	UNK			MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	ICT			MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)	UNK		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY	UNK			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY	ICT			MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
	MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED									
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	UNK		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 06-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 14-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - SB PW600-72-63072; REPLACE NO. 3 FLANGED BALL BEARING. WAS ACCOMPLISHED AT PRODUCTION.										
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - SB PW600-72-63072; REPLACE NO. 3 FLANGED BALL BEARING. WAS ACCOMPLISHED AT PRODUCTION.										
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY	ICT		CATEGORY 6	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7	MTH 06-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Jan-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
	MOC :									
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
	MOC :									
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
	MOC :									
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5						A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 5			A/R			
	MOC :									
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5			A/R			
	MOC :									
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5			A/R			
	MOC :									
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KICT		CATEGORY 3	MTH 25-Jan-2013 HRS 652.4 LDG 529		-			Complete
	MOC :									
	COMPLIED WITH - ACCOMPLISHED PRATT & WHITNEY SB PW600-72-63087 REV 2, DATED AUGUST 30, 2012; REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SB510-76-01 REV 2).									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL KICT			CATEGORY 3	MTH 25-Jan-2013 HRS 652.4 LDG 529		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED PRATT & WHITNEY SB PW600-72-63087 REV 2, DATED AUGUST 30, 2012; REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SB510-76-01 REV 2).										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02) CATEGORY 6						A/R			
MOC :										
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02) CATEGORY 6						A/R			
MOC :										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF CATEGORY 6						-			
MOC :										
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF CATEGORY 6						-			
MOC :										
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01) CATEGORY 6						-			
MOC :										
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01) CATEGORY 6						-			
MOC :										
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						A/R			
MOC :										
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7						A/R			
MOC :										
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			
MOC :										
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			
MOC :										
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6				-			
	MOC :							
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6				-			
	MOC :							
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6				-			
	MOC :							
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7				-			
	MOC :							
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7				-			
	MOC :							
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6				A/R			
	MOC :							
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6				A/R			
	MOC :							
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7				-			
	MOC :							
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7				-			
	MOC :							
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7				-			
	MOC :							
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7				-			
	MOC :							
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
MOC :										
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
MOC :										
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
MOC :										
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
MOC :										
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER										
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER										
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - SB PW600-72-63098; INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.										
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - SB PW600-72-63098; INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.										
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
MOC :										
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7			-			
MOC :										
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
MOC :										
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY RECOMMENDED			MTH			-			
	MOC :									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY RECOMMENDED			MTH			-			
	MOC :									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5				-			
	MOC :							
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5				-			
	MOC :							
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5				-			
	MOC :							
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5				-			
	MOC :							
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7				-			
	MOC :							
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE CATEGORY 7				-			
	MOC :							
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
	MOC :							
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
	MOC :							
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
	MOC :							
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7				-			
	MOC :							
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5				-			
	MOC :							
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE CATEGORY 5				-			
	MOC :							
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5				-			
	MOC :							
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KMKE		CATEGORY 3	MTH 08-Dec-2019 HRS 1158.6 LDG 888		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE PER FOHE PART NUMBER.										
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KMKE		CATEGORY 3	MTH 08-Dec-2019 HRS 1158.6 LDG 888		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE PER FOHE PART NUMBER.										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL			CATEGORY 3	MTH HRS		DUE 250 DUE		(1509.72)1509.72	216.22
MOC :										
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL			CATEGORY 3	MTH HRS		DUE 250 DUE		(1509.72)1509.72	216.22
MOC :										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - SB PW600-72-63030 REV. 1; REPLACE ELECTRICAL WIRING HARNESS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - SB PW600-72-63030 REV. 1; REPLACE ELECTRICAL WIRING HARNESS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 510-73-01 LEFT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT	MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			N/A
MOC : NOT APPLICABLE - COMMENTS: ACCOMPLISHED ASL510-73-01. SERVICE LETTER DOES NOT APPLY DUE TO PART NUMBER INSTALLED.									
ASL 510-73-01 RIGHT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT	MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		-			N/A
MOC : NOT APPLICABLE - COMMENTS: ACCOMPLISHED ASL510-73-01. SERVICE LETTER DOES NOT APPLY DUE TO PART NUMBER INSTALLED.									
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT	MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			N/A
MOC : NOT APPLICABLE - COMMENTS: ASL510-73-02 DOES NOT APPLY DUE TO SERIAL NUMBER.									
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	ICT	MANDATORY	MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			N/A
MOC : NOT APPLICABLE - COMMENTS: ASL510-73-02 DOES NOT APPLY DUE TO SERIAL NUMBER.									
SB PW600-1007- 63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-1007- 63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72- 63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72- 63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72- 63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH 06-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72- 63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH 14-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72- 63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7	ICT		MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			N/A
MOC : NOT APPLICABLE - SB PW600-72-63075; REPLACE FUEL OIL/HEAT EXCHANGER. DOES NOT APPLY DUE TO ENGINE SERIAL NUMBER.									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)	ICT		CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			N/A
MOC : NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER										
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6			A/R			
MOC :										
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)	ICT		CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		A/R			Complete
MOC : COMPLIED WITH - DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)			CATEGORY 3	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01) CATEGORY 3		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
ASB PW600-72-A63069 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03) ICT CATEGORY 3		MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			N/A
MOC : NOT APPLICABLE - COMMENTS: SB A63069 R2 DOES NOT APPLY DUE TO PART NUMBER INSTALLED.								
ASB PW600-72-A63069 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R03) ICT CATEGORY 3		MTH 13-Jan-2012 HRS 460.9 LDG 392		A/R			N/A
MOC : NOT APPLICABLE - COMMENTS: SB A63069 R2 DOES NOT APPLY DUE TO PART NUMBER INSTALLED.								
ASB PW600-72-A63071 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01) ICT SUPERSEDED		MTH 13-Jan-2012 HRS 460.9 LDG 392		-			N/A
MOC : NOT APPLICABLE - COMMENTS: SB A63071 DOES NOT APPLY DUE TO SERIAL NUMBER.								
ASB PW600-72-A63071 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01) ICT SUPERSEDED		MTH 13-Jan-2012 HRS 460.9 LDG 392		-			N/A
MOC : NOT APPLICABLE - COMMENTS: SB A63071 DOES NOT APPLY DUE TO SERIAL NUMBER.								
SB PW600-73-63004 E1	REPLACEMENT OF FUEL SHUT-OFF-VALVE PIN CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63004 E2	REPLACEMENT OF FUEL SHUT-OFF-VALVE PIN CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8				-			
MOC :								
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8				-			
MOC :								
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7	MTH	06-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7	MTH	14-Jan-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE							



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63050 E1	LIMITED INCORPORATION OF FUEL MANIFOLD PINS CATEGORY 10						-			
MOC :										
SB PW600-73-63050 E2	LIMITED INCORPORATION OF FUEL MANIFOLD PINS CATEGORY 10						-			
MOC :										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63054 REV. 1; REPLACE BLEED VALVE ACTUATOR. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) ICT			CATEGORY 7	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63054 REV. 1; REPLACE BLEED VALVE ACTUATOR. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) CATEGORY 7			MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) CATEGORY 7			MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087 KICT			MANDATORY	MTH 25-Jan-2013 HRS 652.4 LDG 529		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB510-76-01R2; TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 SERVICE BULLETIN, DATED SEPTEMBER 04, 2012.										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8			MTH	06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8			MTH	14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT OPTIONAL				-			
MOC :								
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION ICT	MANDATORY	DAYS 26-May-2011 HRS 296.6 LDG 256		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-79-02 OIL PRESSURE TRANSMITTER CONNECTION INSPECTION; ORIGINAL ISSUE DATED MARCH 17, 2011.								
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION				-			
MOC :								
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	INFORMATIONAL			-			
MOC :								
SB PW600-72- 63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7		MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72- 63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7		MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								
SB PW600-72- 63068 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)	CATEGORY 6	MTH 06-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE								



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63068 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01)			CATEGORY 6	MTH 14-Jan-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7			A/R			
MOC :										
SB PW600-79-63008 R01 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63008 REV. 1; REPLACE OIL PUMP HOUSING & SOUR GEARS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-79-63008 R01 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R02)	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63008 REV. 1; REPLACE OIL PUMP HOUSING & SOUR GEARS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-79-63008 R02 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63008 REV. 2; REPLACE OIL PUMP HOUSING & SOUR GEARS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB PW600-79-63008 R02 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS	ICT		CATEGORY 5	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63008 REV. 2; REPLACE OIL PUMP HOUSING & SOUR GEARS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7						-			
MOC :										
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63047 R01 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02) ICT			CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63047 REV. 1; REPLACE AIR COOLED PRESSURE OIL TUBE BOLTS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED										
SB PW600-79-63047 R01 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02) ICT			CATEGORY 3	MTH 09-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - SB PW600-72-63047 REV. 1; REPLACE AIR COOLED PRESSURE OIL TUBE BOLTS. IS C/W DUE TO ORIGINAL ISSUE WAS ACCOMPLISHED.										
SB PW600-79-63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)				MTH 06-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)				MTH 14-Jan-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SL 510-80-01	ENGINE STARTING			INFORMATIONAL			-			
MOC :										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM ICT			RECOMMENDED	MTH 29-May-2021 HRS 1220.9 LDG 934		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CITATION SERVICE LETTER SL510-80-02, DATED MARCH 5, 2019.REPLACED L/H STARTER/GENERATOR P/N MG94E-1 (9912676-1), S/N 740B WITH OVERHAULED STARTER/GENERATOR P/N MG94E-1 (9912676-1EX) S/N 974D IAW CE 510 MM 80-10-10. OPERATIONAL CHECK GOOD.REPLACED R/H STARTER/GENERATOR P/N MG94E-1 (9912676-1), S/N 606B WITH OVERHAULED STARTER/GENERATOR P/N MG94E-1 (9912676-1EX) S/N 953D IAW CE 510 MM 80-10-10. OPERATIONAL CHECK GOOD.										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS CANCELLED						-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS CANCELLED						-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) CANCELLED						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Service Bulletins

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
	CANCELLED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KMKE	MANDATORY	MTH 03-Aug-2015 HRS 881.5 LDG 688		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT . SEAT PART NUMBERS AFFECTED BY THIS AD ARE NOT INSTALLED									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KMKE	MANDATORY	MTH 03-Aug-2015 HRS 881.5 LDG 688		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT . SEAT PART NUMBERS AFFECTED BY THIS AD ARE NOT INSTALLED									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KMKE	MANDATORY	MTH 03-Aug-2015 HRS 881.5 LDG 688		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT . SEAT PART NUMBERS AFFECTED BY THIS AD ARE NOT INSTALLED									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KMKE	MANDATORY	MTH 03-Aug-2015 HRS 881.5 LDG 688		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2015-10-02 EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT . SEAT PART NUMBERS AFFECTED BY THIS AD ARE NOT INSTALLED									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KGRB		MTH 06-Nov-2018 HRS 1074.1 LDG 831		-			N/A
MOC : NOT APPLICABLE - INSPECTED INSTALLATION AND FOUND AD NOT APPLICABLE; PART NOT INSTALLED.									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01 PARA (J); AMERI-KING MODEL AK-450 & AK-451 ELT INSPECTION. EFF. DATE IS 10-24-17. DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01; AMERI-KING MODEL AK-450 & AK-451 ELT INSPECTION. EFF. DATE IS 10-24-17. DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2021-07-13 PARA (E)(1); SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE INSPECTION. EFF. DATE IS 5-11-21. DOES NOT APPLY DUE TO PART NUMBER NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2021-07-13 PARA (E)(2); SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE INSPECTION. EFF. DATE IS 5-11-21. DOES NOT APPLY DUE TO PART NUMBER NOT INSTALLED.									
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2021-07-13 PARA (E)(3); SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE INSPECTION. EFF. DATE IS 5-11-21. DOES NOT APPLY DUE TO PART NUMBER NOT INSTALLED.									
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			N/A
MOC : NOT APPLICABLE - AD 2021-07-13; SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE INSPECTION. EFF. DATE IS 5-11-21. DOES NOT APPLY DUE TO PART NUMBER NOT INSTALLED.									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KMKE	MANDATORY	MTH 20-Dec-2021 HRS 1237.9 LDG 947		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2021-23-12 PAR. (G). RADIO ALTIMETER FLIGHT RESTRICTIONS. UPDATED AFM LIMITATIONS SECTION.									
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - AD 2023-10-02; RADIO ALTIMETER AFM REVISION TO INCORPORATE LIMITATIONS. EFF. DATE IS 5-26-23. ACCOMPLISHED PER AD INSTRUCTION.									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - AD 2023-10-02; RADIO ALTIMETER AFM REVISION TO INCORPORATE LIMITATIONS. EFF. DATE IS 5-26-23. ACCOMPLISHED PER AD INSTRUCTION.									
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002		-			Complete
MOC : COMPLIED WITH - AD 2023-10-02; RADIO ALTIMETER AFM REVISION TO INCORPORATE LIMITATIONS. EFF. DATE IS 5-26-23. ACCOMPLISHED PER AD INSTRUCTION.									
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	KGRB	MANDATORY	DAYS 20-Aug-2018 HRS 1074.1 LDG 831		-			Complete
MOC : COMPLIED WITH - VISUALLY INSPECTED INDICATOR LENGTHS. ALL FOUND TO BE WITHIN TOLERANCE.									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KICT	MANDATORY	MTH 23-Jan-2015 HRS 827.1 LDG 653	-					Complete
MOC : COMPLIED WITH - ACCOMPLISHED FAA 2014-18-01, NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION; DATED OCTOBER 14, 2014.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KMKE	MANDATORY	MTH 03-Aug-2015 HRS 881.5 LDG 688	-					N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT. FAA AD2015-10-51E AVIDYNE INTEGRATED FLIGHT DISPLAY AIRWORTHINESS DIRECTIVE DOES NOT APPLY.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002	-					N/A
MOC : NOT APPLICABLE - AD 2015-10-51; AVIDYNE FLIGHT DISPLAY LIMITATION. EFF. DATE IS 7-1-15. DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED.										
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE	ICT	MANDATORY	MTH 08-May-2024 HRS 1293.5 LDG 1002	-					N/A
MOC : NOT APPLICABLE - AD 2021-08-15; GARMIN GMN-00962 GPS PROCESSOR. EFF. DATE IS 5-17-21. DOES NOT APPLY DUE TO PART NUMBER NOT INSTALLED.										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KMKE	MANDATORY	MTH 01-May-2016 HRS 952.1 LDG 755	-					N/A
MOC : NOT APPLICABLE - THIS FAAAD 2015-08-07 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO PILOTS CREW MASK P/N MC10-16-101 S/N 98429 AND CO-PILOT CREW MASK P/N MC10-16-101 S/N 96844 BEING INSTALLED (PER APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011) NO FURTHER ACTION REQUIRED.										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KMKE	MANDATORY	MTH 01-May-2016 HRS 952.1 LDG 755	-					N/A
MOC : NOT APPLICABLE - THIS FAAAD 2015-08-07 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO PILOTS CREW MASK P/N MC10-16-101 S/N 98429 AND CO-PILOT CREW MASK P/N MC10-16-101 S/N 96844 BEING INSTALLED (PER APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011) NO FURTHER ACTION REQUIRED.										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KMKE	MANDATORY	MTH 01-May-2016 HRS 952.1 LDG 755	-					N/A
MOC : NOT APPLICABLE - THIS FAAAD 2015-08-07 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO PILOTS CREW MASK P/N MC10-16-101 S/N 98429 AND CO-PILOT CREW MASK P/N MC10-16-101 S/N 96844 BEING INSTALLED (PER APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011) NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KMKE	MANDATORY	MTH 30-Dec-2015 DAYS 926.5 HRS 730 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD 2015-23-09 OXYGEN - ZODIAC AEROTECHNIQUES (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS. THE PART NUMBER, IDENTIFIED AS REQUIRED BY PARAGRAPH (G) OF THIS AD, ARE NOT LISTED IN APPENDIX 1 OF ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001, REVISION 1, DATED DECEMBER 3, 2012. AD DOES NOT APPLY.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KMKE	MANDATORY	MTH 30-Dec-2015 DAYS 926.5 HRS 730 LDG		-			N/A
MOC : NOT APPLICABLE - OXYGEN MASK REGULATORS HAVING A DATE OF MANUFACTURING (DMF) CODE OF NOVEMBER 2008 (112008 OR 11-08) OR EARLIER, AND THOSE WITH A DMF CODE OF JANUARY 2011 (012011 OR 01-11) OR LATER, AND THOSE HAVING A PART NUMBER LISTED IN PARAGRAPH 1.A.(4), "NOT CONCERNED EQUIPMENT" OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011 IN WHICH THIS AIRCRAFT HAS, ARE EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPHS (G) AND (H) OF THIS AD.									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KMKE	MANDATORY	MTH 30-Dec-2015 DAYS 926.5 HRS 730 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD 2015-23-09 OXYGEN - ZODIAC AEROTECHNIQUES (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS. THE PART NUMBER, IDENTIFIED AS REQUIRED BY PARAGRAPH (G) OF THIS AD, ARE NOT LISTED IN APPENDIX 1 OF ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001, REVISION 1, DATED DECEMBER 3, 2012. AD DOES NOT APPLY.									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KMKE	MANDATORY	MTH 30-Dec-2015 DAYS 926.5 HRS 730 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD 2015-23-09 OXYGEN - ZODIAC AEROTECHNIQUES (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS. THE PART NUMBER, IDENTIFIED AS REQUIRED BY PARAGRAPH (G) OF THIS AD, ARE NOT LISTED IN APPENDIX 1 OF ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001, REVISION 1, DATED DECEMBER 3, 2012. AD DOES NOT APPLY.									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KMKE	MANDATORY	MTH 30-Dec-2015 HRS 926.5 LDG 730		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD 2015-23-09 OXYGEN - ZODIAC AEROTECHNIQUES (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS. THE PART NUMBER, IDENTIFIED AS REQUIRED BY PARAGRAPH (G) OF THIS AD, ARE NOT LISTED IN APPENDIX 1 OF ZODIAC AEROSPACE SERVICE BULLETIN MCF-SBU-35-001, REVISION 1, DATED DECEMBER 3, 2012. AD DOES NOT APPLY.									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNIQUES (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KMKE	MANDATORY	MTH 01-May-2016 HRS 952.1 LDG 755		-			N/A
MOC : NOT APPLICABLE - THIS FAA AD 2015-23-09 IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO CREW MASK P/N MC10-16-101 BEING INSTALLED (PER APPENDIX 1 OF ZODIAC SERVICES SERVICE BULLETIN MCF-SBU-35-001, REVISION 1, DATED DECEMBER 3, 2010) NO FURTHER ACTION REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KMKE	MANDATORY	MTH 15-Oct-2016 HRS 966 LDG 771		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 (G) OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT(PBE) IS NOT APPLICABLE. EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KMKE	MANDATORY	MTH 15-Oct-2016 HRS 966 LDG 771		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 OXYGEN (H)(1) - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT(PBE) IS NOT APPLICABLE. EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KMKE	MANDATORY	MTH 15-Oct-2016 HRS 966 LDG 771		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 OXYGEN (H)(2) - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT(PBE) IS NOT APPLICABLE. EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KMKE	MANDATORY	MTH 15-Oct-2016 HRS 966 LDG 771		-			N/A
MOC : NOT APPLICABLE - AD 2016-11-20 OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT(PBE) IS NOT APPLICABLE. EQUIPMENT NOT INSTALLED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMKE	MANDATORY	MTH 18-Jan-2018 HRS 1035.6 LDG 808		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED AD2017-18-12 DATED OCTOBER 16, 2017; B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBERS (P/N) 119003-11 AND 119003-21, THAT ARE INSTALLED ON AIRPLANES, PARAGRAPHS (I) & (J) BY INSPECTION. B/E AEROSPACE PBE IS NOT ON BOARD, NO FURTHER ACTION IS REQUIRED									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMKE	MANDATORY	MTH 18-Jan-2018 HRS 1035.6 LDG 808		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED AD2017-18-12 DATED OCTOBER 16, 2017; B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBERS (P/N) 119003-11 AND 119003-21, THAT ARE INSTALLED ON AIRPLANES, PARAGRAPHS (I) & (J) BY INSPECTION. B/E AEROSPACE PBE IS NOT ON BOARD, NO FURTHER ACTION IS REQUIRED									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF DATED WITHIN THE S/N RANGE REPLACE IT.	KMKE	MANDATORY	MTH 18-Jan-2018 HRS 1035.6 LDG 808		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED AD2017-18-12 DATED OCTOBER 16, 2017; B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBERS (P/N) 119003-11 AND 119003-21, THAT ARE INSTALLED ON AIRPLANES, PARAGRAPHS (I) & (J) BY INSPECTION. B/E AEROSPACE PBE IS NOT ON BOARD, NO FURTHER ACTION IS REQUIRED									



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION, INC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0293**
Unit: Reg No: **N293MM**
Airworthiness: **10-Mar-2010**
Print Date: **17-Jun-2024 1:45PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1293.5	1002	14-Jun-2024	0
ENG 1	1293.5	997	14-Jun-2024	0
ENG 2	1293.5	997	14-Jun-2024	0
AIR COND	381.5		14-Jun-2024	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
	KMKE	MANDATORY	MTH	18-Jan-2018		-				N/A
			HRS	1035.6						
			LDG	808						
MOC : NOT APPLICABLE - ACCOMPLISHED AD2017-18-12 DATED OCTOBER 16, 2017; B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBERS (P/N) 119003-11 AND 119003-21, THAT ARE INSTALLED ON AIRPLANES, PARAGRAPHS (I) & (J) BY INSPECTION. B/E AEROSPACE PBE IS NOT ON BOARD, NO FURTHER ACTION IS REQUIRED.										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E1	ICT	MANDATORY	MTH	08-Sep-2010		-				Complete
			HRS	185.1						
			LDG	152						
MOC : COMPLIED WITH - PREVIOUSLY ACCOMPLISHED AD2010-17-06, PW615F-A FOHE FUEL FILTER BYPASS VALVE POPPET, EFFECTIVE DATE SEPT/27/2010. ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 01/06/2010 (FOHE P/N 35C3778-04 INSTALLED) . REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E2	ICT	MANDATORY	MTH	08-Sep-2010		-				Complete
			HRS	185.1						
			LDG	152						
MOC : COMPLIED WITH - PREVIOUSLY ACCOMPLISHED AD2010-17-06, PW615F-A FOHE FUEL FILTER BYPASS VALVE POPPET, EFFECTIVE DATE SEPT/27/2010. ASB A63071 WAS PREVIOUSLY ACCOMPLISHED BY P&WC ON 01/14/2010 (FOHE P/N 35C3778-04 INSTALLED) . REV 1 HAS NO EFFECT ON PRIOR ACCOMPLISHMENT OF THIS ASB. NO ADDITIONAL ACTION REQUIRED.										