



DueList Report

PHENOM 300

S/N 50500300 N505BD

OWNER: EMPOWER AIR,LLC
ADDRESS: 101 W RENNER RD
RICHARDSON TX 75082

OPERATOR: DURBIN & COMPANY
ADDRESS: 101 W RENNER RD
RICHARDSON TX 75082

OPERATOR: PBAS JETS
ADDRESS: 70 LA COSTA COURT
VERO BEACH FL 32963

OFFICE:
FAX:

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: ADRIAN SABOU
EMAIL: ASABOU@CAMPSYSTEMS.COM

+1-514-448-1151 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 12 MOS. to 22-JUL-2025

AIRCRAFT	SERIAL/REGNO: 50500300/N505BD	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
CERTIFICATION DATE: 22-DEC-2015		LAST ACTUALS: 1743.5 A/C HRS as of 27-FEB-2024 1148 AFL as of 27-FEB-2024	PROJECTED: 1983.50 1388
ENGINE NO. 1	SERIAL/PART: PCE-DG0613/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 13-JUN-2015 0 ENG. HRS 0 A/C HRS 0 ENC		LAST ACTUALS: 1743.5 ENG. HRS as of 27-FEB-2024 1148 ENC as of 27-FEB-2024	PROJECTED: 1983.50 1388
ENGINE NO. 2	SERIAL/PART: PCE-DG0610/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 09-JUN-2015 0 ENG. HRS 0 A/C HRS 0 ENC		LAST ACTUALS: 1743.5 ENG. HRS as of 27-FEB-2024 1148 ENC as of 27-FEB-2024	PROJECTED: 1983.50 1388



Insufficient Items

Operator Review and Action Required

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

These tasks have insufficient information for calculating next due. Please provide the missing information (marked by ?) so that they can be setup properly. It is important to note that any task that has insufficient information, will not come due correctly unless the necessary information is provided by you.

PN & SN	Unit	Effective Date	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Disposition
24-31-01-001		NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017					Service ATA:24
PN:400SG180Q-4	MOS			14-Feb-24			
SN:S04279	HRS		800 (+30/-30)			?	
	AFL						
ENTER MISSING C/W HRS _____				REF: AMM 24-31-01			
24-31-01-001		NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017					Service ATA:24
PN:400SG180Q-4	MOS			13-Feb-24			
SN:S02074XL	HRS		800 (+30/-30)			?	
	AFL						
ENTER MISSING C/W HRS _____				REF: AMM 24-31-01			
35-02-01-004		RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER					Service ATA:35
	MOS	11-Jan-24	60			?	
	HRS						
	AFL						
ENTER MISSING DATE OF HYDROSTATIC CHECK _____				REF: AMM 35-02-01			

Name: _____ Signature: _____ Cert.#: _____ Date: _____

? - Insufficient Information S - Suppressed Requirement * - Estimated Due (New Requirement) (EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



New Requirement/Flagged Items

Operator Review and Action Required

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition	
				Current	Change To			
SB PW500-72-30579		NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER, SERVICE BULLETIN					Bulletin	ATA:72
	14-Jun-24	MOS	T:ESV	14-Jun-24			CATEGORY 7	
		HRS						
		ENC						
NEW REQUIREMENT ADDED ON 17-JUN-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: BULLETINS			
SB PW500-72-30579		NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER, SERVICE BULLETIN					Bulletin	ATA:72
	14-Jun-24	MOS	T:ESV	14-Jun-24			CATEGORY 7	
		HRS						
		ENC						
NEW REQUIREMENT ADDED ON 17-JUN-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: BULLETINS			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
FAA 2023-21-04		INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5.20						AD ATA:31
	MOS	T:6		EFF	11-Jun-24 *		OVD	
	HRS	T:300		EFF	1988.25 *		244.8	
	AFL							
Disposition: MANDATORY		REF: AD						
FAA 2023-22-11		REPLACEMENT OF THE AILERON AUTOPILOT SERVO MOUNT CLUTCH RETAINING BOLT AND WASHER						AD ATA:22
	MOS	T:3		EFF	26-Mar-24 *		OVD	
	HRS	T:50		EFF	1748.12 *		4.6	
	AFL							
Disposition: MANDATORY		REF: AD						
SB 505-25-0044		EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION, SERVICE BULLETIN						Bulletin ATA:25
	MOS	T:DUE			22-Dec-23 (M)		OVD	
	HRS							
	AFL							
Disposition: RECOMMENDED		REF: BULLETINS						
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY)						Service ATA:33
PN:7450LS-00	MOS	12		26-Aug-23	26-Aug-24		35 d	26-Aug-2024
SN:006453	HRS			1617.9				
	AFL			1071				
		REF: AMM 33-52-01						
33-52-01-001		FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)						Service ATA:33
PN:7450LS-00	MOS	12		26-Aug-23	26-Aug-24		35 d	26-Aug-2024
SN:007037	HRS			1617.9				
	AFL			1071				
		REF: AMM 33-52-01						
31-33-03-001		DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED)						Service ATA:31
PN:266-E5542-00	MOS	DUE		28-Jul-21	31-Aug-24 (M)		40 d	31-Aug-2024
SN:ULB017006	HRS			1134.25				
	AFL			752				
Disposition: LIFE LIMIT		REF: AMM 31-33-03						
35-02-01-001		FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR						Service ATA:35
PN:4441122-077	MOS	60		30-Sep-19	30-Sep-24		70 d	30-Sep-2024
SN:1067859701	HRS							
	AFL							
		REF: AMM 35-02-01						

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
05-30-82	36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	36 (+1m/-1m)	Adj:-35d	11-Jan-22	07-Dec-24	07-Jan-25	138 d (+31)	07-Dec-2024
	HRS			1240.1				
	AFL			832				
REF: SMR 05-30-82								
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	36 (+30d/-30d)	Adj:-35d	11-Jan-22	07-Dec-24	06-Jan-25	138 d (+30)	07-Dec-2024
	HRS	2400 (+30/-30)		1240.1	3640.1	3670.1	1896.6 (+30)	
	AFL			832				
Disposition: AIRWORTHINESS REF: AMM 35-00-00								
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE							Service ATA:35
	MOS	36 (+30d/-30d)	Adj:-35d	11-Jan-22	07-Dec-24	06-Jan-25	138 d (+30)	07-Dec-2024
	HRS	2400 (+30/-30)		1240.1	3640.1	3670.1	1896.6 (+30)	
	AFL			832				
Disposition: AIRWORTHINESS REF: AMM 35-21-00								
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE							Service ATA:35
	MOS	36 (+30d/-30d)	Adj:-35d	11-Jan-22	07-Dec-24	06-Jan-25	138 d (+30)	07-Dec-2024
	HRS	2400 (+30/-30)		1240.1	3640.1	3670.1	1896.6 (+30)	
	AFL			832				
Disposition: AIRWORTHINESS REF: AMM 35-21-00								
05-30-80	12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL			1123				
REF: SMR 05-30-80								
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	12 (+30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
	HRS	800 (+10%)		1711.8	(2511.8)2511.8	2591.8	768.3 (+80)	
	ENC			1123				
REF: MM 05-20-00								
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	12 (+30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
	HRS	800 (+10%)		1711.8	(2511.8)2511.8	2591.8	768.3 (+80)	
	ENC			1123				
REF: MM 05-20-00								

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
22-11-00-001 FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO Service ATA:22								
PN:011-01904-00	MOS	12 (+30d/-30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
SN:1GK013876	HRS			1711.8				
	AFL			1123				
Disposition: AIRWORTHINESS REF: AMM 22-11-00								
22-11-00-001 FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO Service ATA:22								
PN:011-01904-00	MOS	12 (+30d/-30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
SN:1GK013923	HRS			1711.8				
	AFL			1123				
Disposition: AIRWORTHINESS REF: AMM 22-11-00								
22-11-00-001 FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO Service ATA:22								
PN:011-01904-00	MOS	12 (+30d/-30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
SN:1GK013925	HRS			1711.8				
	AFL			1123				
Disposition: AIRWORTHINESS REF: AMM 22-11-00								
22-11-00-001 FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO Service ATA:22								
PN:011-01904-00	MOS	12 (+30d/-30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
SN:1GK014015	HRS			1711.8				
	AFL			1123				
Disposition: AIRWORTHINESS REF: AMM 22-11-00								
25-61-00-002 GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER Service ATA:25								
PN:S1821502-02	MOS	12	Adj:-29d	17-Jan-24	19-Dec-24		150 d	19-Dec-2024
SN:LX1100174046	HRS			1711.8				
	AFL			1123				
REF: AMM 25-61-00								
31-31-00-002 OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) Service ATA:31								
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL			1123				
REF: AMM 31-31-00								
32-11-00-003 LUBRICATION OF MAIN LANDING GEAR Service ATA:32								
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL	650 (+30/-30)		1123	1773	1803	625 (+30)	
REF: AMM 12-21-00								

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-11-03-004 SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER Service ATA:32								
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL	650 (+30/-30)		1123	1773	1803	625 (+30)	
REF: AMM 12-14-02								
32-21-00-003 LUBRICATION OF NOSE LANDING GEAR Service ATA:32								
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL	650 (+30/-30)		1123	1773	1803	625 (+30)	
REF: AMM 12-21-00								
32-21-05-004 SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER Service ATA:32								
	MOS	12 (+1m/-1m)	Adj:-29d	17-Jan-24	19-Dec-24	19-Jan-25	150 d (+31)	19-Dec-2024
	HRS			1711.8				
	AFL	650 (+30/-30)		1123	1773	1803	625 (+30)	
REF: AMM 12-14-03								
35-11-00-001 OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX Service ATA:35								
	MOS	12 (+30d/-30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
	HRS	800 (+30/-30)		1711.8	2511.8	2541.8	768.3 (+30)	
	AFL			1123				
Disposition: AIRWORTHINESS REF: AMM 35-11-02								
73-10-05-212-801 NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT Service ATA:73								
	MOS	12 (+30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
	HRS			1711.8				
	ENC			1123				
REF: MM 73-10-05								
73-10-05-212-801 NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT Service ATA:73								
	MOS	12 (+30d)	Adj:-29d	17-Jan-24	19-Dec-24	18-Jan-25	150 d (+30)	19-Dec-2024
	HRS			1711.8				
	ENC			1123				
REF: MM 73-10-05								
26-21-03-001 FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE Service ATA:26								
PN:33000073-1	MOS	120		01-Jan-15	01-Jan-25		163 d	01-Jan-2025
SN:71216A1	HRS							
	AFL							
Disposition: AIRWORTHINESS REF: AMM 26-21-03								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
24-36-STC-005 ^U		CAPACITY CHECK AFT MAIN BATTERY (CONCORDE BATTERY)						Service ATA:24
PN:RG-380E/53L	MOS	T:12 (+1m/-1m)		17-Jan-24	17-Jan-25	17-Feb-25	179 d (+31)	17-Jan-2025(2)
SN:41296283	HRS			1711.8				
	AFL			1123				
REF:								
24-36-STC-005 ^U		CAPACITY CHECK FORWARD MAIN BATTERY (CONCORDE BATTERY)						Service ATA:24
PN:RG-390E	MOS	T:12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025(2)
SN:41334203	HRS			1711.8				
	AFL			1123				
REF:								
25-61-00-001		OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM						Service ATA:25
PN:S1821502-02	MOS	12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025
SN:LX1100174046	HRS			1711.8				
	AFL			1123				
REF: AMM 25-61-00								
25-62-01-001		VISUAL CHECK #1 FIRST AID KIT						Service ATA:25
PN:S6-01-0005-320	MOS	DUE		17-Jan-24	17-Jan-25 (M)		179 d	17-Jan-2025
SN:001848	HRS			1711.8				
	AFL			1123				
REF: AMM 25-62-01								
26-24-01-001		WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER						Service ATA:26
PN:BA5105-5	MOS	12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025
SN:104451	HRS							
	AFL							
REF: AMM 26-24-01								
26-24-01-001		WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER						Service ATA:26
PN:BA5105-5	MOS	12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025
SN:104450	HRS							
	AFL							
REF: AMM 26-24-01								
71-00-00-760-823		NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)						Service ATA:71
	MOS	12 (+30d)		17-Jan-24	17-Jan-25	16-Feb-25	179 d (+30)	17-Jan-2025
	HRS	630 (+10%)		1711.8	(2341.8)2341.8	2404.8	598.3 (+63)	
	ENC			1123				
REF: MM 71-00-00								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
71-00-00-760-823		NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)						Service ATA:71
	MOS	12 (+30d)		17-Jan-24	17-Jan-25	16-Feb-25	179 d (+30)	17-Jan-2025
	HRS	630 (+10%)		1711.8	(2341.8)2341.8	2404.8	598.3 (+63)	
	ENC			1123				
		REF: MM 71-00-00						
72-00-02-810-801		NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION						Service ATA:71
	MOS	12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025
	HRS	630		1711.8	(2341.8)2341.8		598.3	
	ENC			1123				
		REF: MM 72-00-02						
72-00-02-810-801		NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION						Service ATA:71
	MOS	12		17-Jan-24	17-Jan-25		179 d	17-Jan-2025
	HRS	630		1711.8	(2341.8)2341.8		598.3	
	ENC			1123				
		REF: MM 72-00-02						
26-21-07-001		DISCARD NO. 1 CARTRIDGE						Service ATA:26
PN:30903962-1	MOS	120		01-Feb-15	01-Feb-25		194 d	01-Feb-2025
SN:0066RL	HRS							
	AFL							
Disposition: LIFE LIMIT		REF: AMM 26-21-07						
26-21-07-001		DISCARD NO. 2 CARTRIDGE						Service ATA:26
PN:30903963-1	MOS	120		01-Feb-15	01-Feb-25		194 d	01-Feb-2025
SN:1597RL	HRS							
	AFL							
Disposition: LIFE LIMIT		REF: AMM 26-21-07						
25-62-02-001		RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST						Service ATA:25
	MOS	120		01-Apr-15	01-Apr-25		253 d	01-Apr-2025
	HRS							
	AFL							
Disposition: OVERHAUL		REF: AMM 25-62-02						
25-62-02-001		RESTORATION (OVERHAUL) OF PILOT LIFE VEST						Service ATA:25
	MOS	120		01-Apr-15	01-Apr-25		253 d	01-Apr-2025
	HRS							
	AFL							
Disposition: OVERHAUL		REF: AMM 25-62-02						

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: PHENOM 300 Serial: 50500300 RegNo: N505BD HRS: 1743.5 AFL: 1148 As
Of: 27-Feb-2024 Operator: DURBIN & COMPANY

Report Date: 22-Jul-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
28-21-07-001		OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM						Service ATA:28
	MOS			28-Jul-21				08-May-2025
	HRS	800 (+30/-30)		1134.25	1934.25	1964.25	190.8 (+30)	
	AFL			752				
Disposition: AIRWORTHINESS			REF: AMM 28-21-07					
28-21-07-001		OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM						Service ATA:28
	MOS			28-Jul-21				08-May-2025
	HRS	800 (+30/-30)		1134.25	1934.25	1964.25	190.8 (+30)	
	AFL			752				
Disposition: AIRWORTHINESS			REF: AMM 28-21-07					
32-43-11-001		OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE						Service ATA:32
	MOS			28-Jul-21				08-May-2025
	HRS	800 (+30/-30)		1134.25	1934.25	1964.25	190.8 (+30)	
	AFL			752				
Disposition: AIRWORTHINESS			REF: AMM 32-43-11					