



Status Report

PHENOM 100

S/N 50000129 N43EP

OWNER: BEDFORD JETFLIGHT LLC
ADDRESS: 132 WILLIAMS ROAD
CONCORD MA 01742

OPERATOR: BEDFORD JETFLIGHT LLC
ADDRESS: 132 WILLIAMS ROAD
CONCORD MA 01742

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: STEPHEN CHEN
EMAIL: SCHEN@CAMPSYSTEMS.COM

+1-514-636-2195 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 50000129/N43EP	MODEL: PHENOM 100	MANUFACTURER: EMBRAER
----------	--------------------------------	-------------------	-----------------------

CERTIFICATION DATE: 20-MAR-2010

LAST ACTUALS:

2342.7 A/C HRS as of 25-SEP-2024

2156 AFL as of 25-SEP-2024

ENGINE NO. 1	SERIAL / PART: PCE-LC0277/35C3100-01	MODEL: PW617F-E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	--------------------------------------	-----------------	--

INSTALLED ON: 26-JAN-2010

LAST ACTUALS:

0 ENG. HRS 0 A/C HRS

2342.7 ENG. HRS as of 25-SEP-2024

0 ENC

2074 ENC as of 17-NOV-2023

ENGINE NO. 2	SERIAL / PART: PCE-LC0288/35C3100-01	MODEL: PW617F-E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	--------------------------------------	-----------------	--

INSTALLED ON: 26-JAN-2010

LAST ACTUALS:

0 ENG. HRS 0 A/C HRS

2342.7 ENG. HRS as of 25-SEP-2024

0 ENC

2074 ENC as of 17-NOV-2023



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-160520	REVIEW EMBRAER PHENOM 100 AMM 2432 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 42 DATED MAY 20/16							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-160520								
EM50-160822	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER -5, REVISION 43 DATED 22 AUGUST 2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-160822								
EM50-161022	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161022								
EM50-161122	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 46 DATED NOV 22/2016							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161122								
EM50-161202	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECK (CHAPTER-5) ADVANCE REVISION DATED DEC 02/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161202								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-161216	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/ MAINTENANCE CHECKS/CHAPTER-5 REVISION 47 DATED DEC 16/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161216								
EM50-200626	REVIEW EMBRAER PHENOM 100 - AMM 2432, SMR REV. 03, DATED JUNE 26TH, 2020							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM50-210507-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM FOR PHENOM 100, DATED MAY 07, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM50-211103-SMR	REVIEW EMBRAER PHENOM 100 - AMM 2432, SMR REV. 04, DATED NOV 3, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
EM50-220812-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-500 - PHENOM 100							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM50-221017-AWL	REVIEW EMB-500 - PHENOM 100 AIRWORTHINESS LIMITATIONS REV 01 DATED OCT 17, 2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-221103-SMR	REVIEW EMB-500 - PHENOM 100 SCHEDULED MAINTENANCE REQUIREMENTS REV 05, DATED NOV 03, 2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM50-230103-CAMP ADJUSTMENT	REVIEW EMB-500 - PHENOM 100 - AUDIT OF ITEM CODES 30-11-04 AND 30-11-04-001, DATED JAN 03, 2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM50-230112-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FOR EMB-500 - PHENOM 100 - AUDIT OF TASK CODE 32-43-11-002							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
EM50-230124-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM FOR EMB-500 - PHENOM 100 - AUDIT OF PN TASK 35-31-01							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-01	800 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)	Adj -23	2823.4	2853.4	480.7 (+30)	
	AFL	1866						
PROC. REF: SMR 05-30-01								
								PKG:1
05-30-10	1600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	15-Jan-17						
	HRS	1223.4	1600 (+30/-30)		2823.4	2853.4	480.7 (+30)	
	AFL	1099						
PROC. REF: SMR 05-30-10								
								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-20	2400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)		4578.6	4608.6	2235.9 (+30)	
	AFL	1992						
PROC. REF: SMR 05-30-20							PKG:20	
05-30-40	3200 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	20-Mar-10						
	HRS	0	3200 (+30/-30)		3200	3230	857.3 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-40							PKG:40	
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	07-May-20	60 (+1m/-1m)		07-May-25	07-Jun-25	177 d (+31)	
	HRS	1774.1	3200 (+30/-30)		4974.1	5004.1	2631.4 (+30)	
	AFL	1606						
PROC. REF: SMR 05-30-42							PKG:42	
05-30-50	5600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)		5600	5630	3257.3 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-50							PKG:50	
05-30-60	6400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	EFF						
	HRS	EFF	6400 (+30/-30)		6400 *	6430	4057.3 (+30)	
	AFL							
PROC. REF: SMR 05-30-60							PKG:60	
05-30-80	12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: SMR 05-30-80							PKG:80	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-81	24 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	02-Apr-24	24 (+1m/-1m)		02-Apr-26	02-May-26	507 d (+30)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: SMR 05-30-81							PKG:81	
05-30-82	36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	23-Apr-22	36 (+1m/-1m)	Adj -12d	11-Apr-25	11-May-25	151 d (+30)	
	HRS	2046.4						
	AFL	1866						
PROC. REF: SMR 05-30-82							PKG:82	
05-30-83	48 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	23-Apr-22	48 (+1m/-1m)	Adj -41d	13-Mar-26	13-Apr-26	487 d (+31)	
	HRS	2046.4						
	AFL	1866						
PROC. REF: SMR 05-30-83							PKG:83	
05-30-84	60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	07-May-20	60 (+1m/-1m)		07-May-25	07-Jun-25	177 d (+31)	
	HRS	1774.1						
	AFL	1606						
PROC. REF: SMR 05-30-84							PKG:84	
05-30-87	120 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	07-May-20	120 (+1m/-1m)		07-May-30	07-Jun-30	2003 d (+31)	
	HRS	1774.1						
	AFL	1606						
PROC. REF: SMR 05-30-87							PKG:87	
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	07-May-20	60 (+1m/-1m)		07-May-25	07-Jun-25	177 d (+31)	
	HRS	1774.1						
	AFL	1606						
PROC. REF: SMR 05-30-90							PKG:90	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-805	NO. 1 ENGINE - TROUBLESHOOT - FOREIGN OBJECT DAMAGE							Service ATA:05
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-805	NO. 2 ENGINE - TROUBLESHOOT - FOREIGN OBJECT DAMAGE							Service ATA:05
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
050600	NO. 1 ENGINE - 800 HOURS							Package ATA:05
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 05-20-00								PKG:2
050600	NO. 2 ENGINE - 800 HOURS							Package ATA:05
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 05-20-00								PKG:2
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	02-Apr-24	12 (+30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	
	HRS	2308.3	800 (+10%)		(3108.3) 3108.3	3188.3	765.6 (+80)	
	ENC							
PROC. REF: LMM 05-20-00								PKG:1
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	02-Apr-24	12 (+30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	
	HRS	2308.3	800 (+10%)		(3108.3) 3108.3	3188.3	765.6 (+80)	
	ENC							
PROC. REF: LMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
H242-001 ^S		INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE						Service ATA:05
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-42-00						PKG:87	
H340-001 ^S		INTERNAL GENERAL VISUAL INSPECTION OF PITCH TRIM ACTUATOR ELECTRICAL BONDING						Service ATA:05
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-44-00						PKG:87	
H430-001 ^S		INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS						Service ATA:05
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-46-00						PKG:84	
H700-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						Service ATA:05
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-47-00						PKG:84	
H700-002 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						Service ATA:05
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-47-00						PKG:84	
ATA 21 - AIR CONDITIONING								
21-00-00		ELECTROMECHANICAL LINEAR ACTUATOR						Component ATA:21
PN:100000-77	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0012	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 21-23-03, AMM 21-23-03							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-01-01	PRESSURIZATION AND AIR CONDITIONING CONTROL PANEL							Component ATA:21
PN:441-40931-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0158	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-01-01, AMM 21-01-01								
21-20-02-900-801-01	COCKPIT - CONDITIONED AIR DUCT							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-20-02-900-801-02	PAX CABIN - CONDITIONED AIR DUCT							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-20-02-900-801-03	AFT CABIN - CONDITIONED AIR DUCT							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-21-01	LEFT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY							Component ATA:21
PN:1300230-17	MOS/MSC	25-Jun-12	O/C					
SN:246	HRS	412.8						
	AFL	390						
PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-21-01	RIGHT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY							Component ATA:21
PN:1300230-27	MOS/MSC	17-Aug-18	O/C					
SN:653	HRS	1470.6						
	AFL	1306						
PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-21-02	LH AFT INLET AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-02, AMM 21-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-02	RH AFT INLET AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-02, AMM 21-21-02								
21-21-02-001 ^S	OPERATIONAL CHECK LH AFT INLET AIR CHECK VALVE							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02								
								PKG:60
21-21-02-001 ^S	OPERATIONAL CHECK RH AFT INLET AIR CHECK VALVE							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02								
								PKG:60
21-23-03	RAM AIR VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03-002 ^S	OPERATIONAL CHECK OF RAM AIR VALVE POSITION							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-03								
								PKG:60
21-23-03-003 ^S	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION							Service ATA:21
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-23-03								
								PKG:1
21-23-04	LH AFT FUSELAGE RAM AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-23-04	LH CENTER FUSELAGE RAM AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04								
21-23-04	RH AFT FUSELAGE RAM AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04								
21-23-04-001 ^S	OPERATIONAL CHECK LH AFT FUSELAGE RAM AIR CHECK VALVE							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-04								PKG:50
21-23-04-001 ^S	OPERATIONAL CHECK LH CENTER FUSELAGE RAM AIR CHECK VALVE							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-04								PKG:50
21-23-04-001 ^S	OPERATIONAL CHECK RH AFT FUSELAGE RAM AIR CHECK VALVE							Service ATA:21
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-04								PKG:50
21-23-05	TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY							Component ATA:21
PN:1133710-6	MOS/MSC	06-Dec-18	O/C	TSR 0				
SN:633	HRS	1521.4		TSR 0				
	AFL	1368		TSR 0				
PROC. REF: AMM 21-23-05, AMM 21-23-05								
21-23-05-001 ^S	GENERAL VISUAL INSPECTION TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY							Service ATA:21
PN:1133710-6	MOS	06-Dec-18						
SN:633	HRS	1521.4	1600 (+30/-30)					
	AFL	1368						
PROC. REF: AMM 21-23-05								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-00-002 ^S		OPERATIONAL CHECK AFT BULKHEAD OUTFLOW (OFV) VALVE MANUAL PRESSURIZATION CONTROL MODE						Service ATA:21
PN:103920-1	MOS	23-Apr-22						
SN:103920-00175	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-31-00								PKG:1
21-31-00-003 ^S		OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)						Service ATA:21
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-31-00								PKG:1
21-31-00-004 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS						Service ATA:21
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-00								PKG:50
21-31-00-005 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL						Service ATA:21
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-00								PKG:50
21-31-01		ELECTRONIC CONTROL AND MONITORING UNIT						Component ATA:21
PN:2119286-5	MOS/MSC	06-May-11	O/C	TSN 0				
SN:2119286-00357	HRS	221.6		TSN 0				
	AFL	203		TSN 0				
PROC. REF: AMM 21-31-01, AMM 21-31-01								
21-31-01-001		RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU)						Service ATA:21
PN:2119286-5	MOS	06-May-11						
SN:2119286-00357	HRS	221.6	5600 (+30/-30)		6221.6 (M)	6251.6	3878.9 (+30)	
	AFL	203						
PROC. REF: AMM 21-31-01								
21-31-02		AFT BULKHEAD OUTFLOW (OFV) VALVE						Component ATA:21
PN:103920-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:103920-00175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02, AMM 21-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-02-001	RESTORATION (REPAIR) OF AFT BULKHEAD OUTFLOW VALVE							Service ATA:21
PN:103920-1	MOS	20-Mar-10						
SN:103920-00175	HRS	0	7200 (+30/-30)		7200	7230	4857.3 (+30)	
	AFL	0						
PROC. REF: AMM 21-31-02								
21-31-03	NEGATIVE PRESSURE RELIEF VALVE							Component ATA:21
PN:130664-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:34163-0168	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03, AMM 21-31-03								
21-31-03-001 ^S	OPERATIONAL CHECK NEGATIVE PRESSURE RELIEF VALVE							Service ATA:21
PN:130664-2	MOS	20-Mar-10						
SN:34163-0168	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-03								
PKG:50								
21-31-04	AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE							Component ATA:21
PN:103916-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:103916-00227	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04, AMM 21-31-04								
21-31-04-001 ^S	FUNCTIONAL CHECK AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE							Service ATA:21
PN:103916-2	MOS	20-Mar-10						
SN:103916-00227	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-04								
PKG:50								
21-52-01-001	DETAILED VISUAL INSPECTION VCS COMPRESSOR DRIVE MODULE OF VCS COMPRESSOR MOTOR DRIVE							Service ATA:21
PN:1133630-12	MOS/MSC	13-Mar-18	O/C					
SN:281	HRS	1396.1						
	AFL	1246						
PROC. REF: AMM 21-52-01								
21-52-01-002	DISCARD OF COMPRESSOR DRIVE MODULE BELT							Service ATA:21
	MOS	13-Mar-18						
	HRS	1396.1	2000 (+30/-30)		3396.1	3426.1	1053.4 (+30)	
	AFL	1246						
PROC. REF: AMM 21-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-01-003 ^S	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION							Service ATA:21
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-52-01							PKG:1	
21-52-01-004	RESTORATION (OVERHAUL) VCS COMPRESSOR DRIVE MODULE							Service ATA:21
PN:1133630-12	MOS	13-Mar-18						
SN:281	HRS	1396.1	2000 (+30/-30)		3396.1	3426.1	1053.4 (+30)	
	AFL	1246						
PROC. REF: AMM 21-52-01								
21-52-02	HEAT EXCHANGER PACK							Component ATA:21
PN:1133750-3	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-02, AMM 21-52-02								
21-52-02-001 ^S	GENERAL VISUAL INSPECTION HEAT EXCHANGER PACK							Service ATA:21
PN:1133750-3	MOS	15-Jan-17						
SN:259	HRS	1223.4	1600 (+30/-30)					
	AFL	1099						
PROC. REF: AMM 21-52-02							PKG:10	
21-52-03-001 ^S	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES							Service ATA:21
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-52-03							PKG:1	
21-52-04	FWD FUS VCS SYSTEM FWD EVAPORATOR BLOWER							Component ATA:21
PN:1133850-104	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:302	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-04, AMM 21-52-04								
21-52-06-001 ^S	SERVICING OF VCS REFRIGERANT FLUID							Service ATA:21
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 12-17-00							PKG:80	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-61-00-001 ^S		OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM						Service ATA:21
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 21-61-00								PKG:1
21-61-01		REAR FUS ECS TEMPERATURE CONTROLLER						Component ATA:21
PN:1300650-12	MOS/MSC	23-Mar-12	O/C					
SN:353	HRS	369.7						
	AFL	340						
PROC. REF: AMM 21-61-01, AMM 21-61-01								
21-61-03		COCKPIT DUCT TEMPERATURE SENSOR SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:880	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03		LH REAR DUCT TEMPERATURE SENSOR SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:854	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03		PAX DUCT TEMPERATURE SENSOR SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:837	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03		RH REAR DUCT TEMPERATURE SENSOR SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:852	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-06-001 ^S		OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR						Service ATA:21
	MOS	20-Mar-10						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-61-06								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215201-0101	VCS COMPRESSOR DRIVE MODULE							Component ATA:21
PN:1133630-12	MOS/MSC	13-Mar-18	O/C					
SN:281	HRS	1396.1						
	AFL	1246						
PROC. REF: AMM 21-52-01, AMM 21-52-01, AMM 21-52-01, AMM 21-52-01								
215201-0102	CDM COMPRESSOR MODULE							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
215201-0201	COMPRESSOR DRIVE MODULE BELT							Component ATA:21
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
ATA 22 - AUTO FLIGHT								
22-11-00-001	FUNCTIONAL CHECK OF AILERON SERVO							Service ATA:22
PN:011-01436-01	MOS	02-Apr-24	12 (+30d/-30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	AIRWORTHINESS
SN:22305470	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK OF ELEVATOR SERVO							Service ATA:22
PN:011-01436-01	MOS	02-Apr-24	12 (+30d/-30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	AIRWORTHINESS
SN:22305487	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK OF RUDDER SERVO							Service ATA:22
PN:011-01436-01	MOS	02-Apr-24	12 (+30d/-30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	AIRWORTHINESS
SN:22305253	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 22-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-00-002 ^S		LUBRICATION OF SERVO ACTUATORS						Service ATA:22
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 22-11-00								PKG:80
22-11-00-003 ^S		DETAILED VISUAL INSPECTION OF AUTOPILOT SERVO CABLE						Service ATA:22
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 22-11-00								PKG:42
22-11-01		GMC 715 GUIDANCE PANEL						Component ATA:22
PN:011-01430-00	MOS/MSC	12-Mar-20	O/C	TSR 4				
SN:15900272	HRS	1761.5		TSR 0				
	AFL	1598		TSR 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-02		AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR						Component ATA:22
PN:011-00878-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:71306554	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-03		AILERON GSM 85A MED TORQUE SERVO MOUNT						Component ATA:22
PN:011-01436-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:22305470	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03								
22-11-05		ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR						Component ATA:22
PN:011-00878-20	MOS/MSC	23-Nov-19	O/C	TSR 0				
SN:1A1016295	HRS	1710		TSR 0				
	AFL	1560		TSR 0				
PROC. REF: AMM 22-11-05, AMM 22-11-05								
22-11-06		ELEVATOR GSM 85A MED TORQUE SERVO MOUNT						Component ATA:22
PN:011-01436-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:22305487	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-08	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR							Component ATA:22
PN:011-00878-10	MOS/MSC	18-Nov-16	O/C	TSR 0				
SN:1A1007897	HRS	1209.9		TSR 0				
	AFL	1088		TSR 0				
PROC. REF: AMM 22-11-08, AMM 22-11-08								
22-11-09	RUDDER GSM 85A MED TORQUE SERVO MOUNT							Component ATA:22
PN:011-01436-01	MOS/MSC	23-Mar-12	O/C	TSR 0				
SN:22305253	HRS	369.7		TSR 0				
	AFL	340		TSR 0				
PROC. REF: AMM 22-11-09, AMM 22-11-09								
22-CUS-06 ^U	CO-PILOTS CONTROL WHEEL STEERING SWITCH							Component ATA:22
PN:79550979	MOS/MSC	11-May-22	O/C	TSN 2				
SN:8011382430	HRS	2055		TSN 0				
	AFL	1874		TSN 0				
ATA 23 - COMMUNICATIONS								
23-12-02	BOTTOM VHF ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:322-2170	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-12-02	TOP VHF ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:322-2172	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-15-03	IRIDIUM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-03, AMM 23-15-03								
23-23-03	WIFI - DATALINK ANTENNA							Component ATA:23
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-03, AMM 23-23-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-51-00-001 ^S		OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE						Service ATA:23
	MOS	20-Mar-10						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 23-51-00								PKG:40
23-51-01		COPILOT GMA 1347D AUDIO PANEL						Component ATA:23
PN:011-01257-20	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:17105940	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-51-01		PILOT GMA 1347D AUDIO PANEL						Component ATA:23
PN:011-01257-20	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:17105937	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-51-05		LH AUDIO JACK CONTROL PANEL						Component ATA:23
PN:441-40943-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0341	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-05		RH AUDIO JACK CONTROL PANEL						Component ATA:23
PN:441-40943-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0337	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-09		LH MODEL HME 25-KA-2 HEADSET						Component ATA:23
PN:025-250-015	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:003235	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
23-51-09		RH MODEL HME 25-KA-2 HEADSET						Component ATA:23
PN:025-250-015	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:003246	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-51-11	COCKPIT ELECTRODYNAMIC MICROPHONE							Component ATA:23
PN:85-03-12369-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:210054	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
23-61-00-001 ^S	FUNCTIONAL CHECK OF STATIC DISCHARGERS							Service ATA:23
	MOS	23-Apr-22	48 (+1m/-1m)					
	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 23-61-00								PKG:83
ATA 24 - ELECTRICAL POWER								
24-00-07	RELAY ASSEMBLY							Component ATA:24
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
24-01-01	ELECTRICAL CONTROL PANEL							Component ATA:24
PN:441-40929-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-01-01, AMM 24-01-01								
24-31-01	NO.1 ENGINE STARTER-GENERATOR							Component ATA:24
PN:MG94F-2	MOS/MSC	23-Apr-22	O/C	TSO 3				
SN:0189	HRS	2046.4		TSO 0				
	AFL	1866		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01	NO.2 ENGINE STARTER-GENERATOR							Component ATA:24
PN:MG94F-2	MOS/MSC	23-Apr-22	O/C	TSO 3				
SN:0632	HRS	2046.4		TSO 0				
	AFL	1866		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 500 ACFT WITH STARTER GENERATOR PN MG94F-2 OR PN 400SG180Q SERIES OR POST-MOD SB 500-24-0007							Service ATA:24
PN:MG94F-2	MOS	23-Apr-22						
SN:0189	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 24-31-01								
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 500 ACFT WITH STARTER GENERATOR PN MG94F-2 OR PN 400SG180Q SERIES OR POST-MOD SB 500-24-0007							Service ATA:24
PN:MG94F-2	MOS	23-Apr-22						
SN:0632	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION (OVERHAUL) OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-1)							Service ATA:24
PN:MG94F-2	MOS/MSC		N/A					
SN:0189	HRS							
	AFL							
PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION (OVERHAUL) OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-1)							Service ATA:24
PN:MG94F-2	MOS/MSC		N/A					
SN:0632	HRS							
	AFL							
PROC. REF: AMM 24-31-01								
24-31-02	NO.1 GENERATOR - DC, 28V CONTROL UNIT							Component ATA:24
PN:CG301A-12	MOS/MSC	11-Nov-22	O/C					
SN:226	HRS	2104.6						
	AFL	1929						
PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-02	NO.2 GENERATOR - DC, 28V CONTROL UNIT							Component ATA:24
PN:CG301A-12	MOS/MSC	11-Nov-22	O/C					
SN:202	HRS	2104.6						
	AFL	1929						
PROC. REF: AMM 24-31-02, AMM 24-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-07-001 ^S	RESTORATION (CLEANING) OF LH SHUNT GENERATOR							Service ATA:24
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 24-31-07				PKG:84
24-31-07-001 ^S	RESTORATION (CLEANING) OF RH SHUNT GENERATOR							Service ATA:24
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 24-31-07				PKG:84
24-36-01	NO.1 MAIN BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	02-Apr-24	O/C	TSN 17				
SN:41257455	HRS	2308.3		TSN 197.8				
	AFL	2118		TSN 182				
				PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01				
24-36-01	NO.2 MAIN BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	25-Sep-24	O/C	TSN 22				
SN:41244795	HRS	2342.7		TSN 232.2				
	AFL	2156		TSN 220				
				PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01				
24-36-01-003	DISCARD NO.1 MAIN BATTERY							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41257455	HRS							
	AFL							
				PROC. REF: AMM 24-36-01				
24-36-01-003	DISCARD NO.2 MAIN BATTERY							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41244795	HRS							
	AFL							
				PROC. REF: AMM 24-36-01				
24-36-01-004	FUNCTIONAL CHECK NO.1 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41257455	HRS							
	AFL							
				PROC. REF: AMM 24-36-01				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-01-004	FUNCTIONAL CHECK NO.2 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41244795	HRS							
	AFL							
PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK OF NO.1 MAIN BATTERY - (POST-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41257455	HRS							
	AFL							
PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK OF NO.2 MAIN BATTERY - (POST-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41244795	HRS							
	AFL							
PROC. REF: AMM 24-36-01								
24-36-02	BATTERY CURRENT (HB2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-36-02, AMM 24-36-02								
24-36-02-001 ^S	OPERATIONAL CHECK BATTERY CURRENT (HB2) SENSOR							Service ATA:24
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 24-36-02								
PKG:60								
24-36-STC-003 ^U	DISCARD NO.1 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
PN:RG-390E	MOS	16-Nov-22	48		16-Nov-26		735 d	
SN:41257455	HRS	2110.5						
	AFL	1936						
24-36-STC-003 ^U	DISCARD NO.2 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
PN:RG-390E	MOS	16-Nov-22	48		16-Nov-26		735 d	
SN:41244795	HRS	2110.5						
	AFL	1936						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-STC-005 ^U		CAPACITY CHECK NO.1 MAIN BATTERY (CONCORDE BATTERY)						Service ATA:24
PN:RG-390E	MOS	01-Aug-24	6 (+1m/-1m)		31-Dec-24 (M)	31-Jan-25	50 d (+31)	
SN:41257455	HRS	2330.6						
	AFL	2148						
24-36-STC-005 ^U		CAPACITY CHECK NO.2 MAIN BATTERY (CONCORDE BATTERY)						Service ATA:24
PN:RG-390E	MOS	25-Sep-24	6 (+1m/-1m)		25-Mar-25	25-Apr-25	134 d (+31)	
SN:41244795	HRS	2342.7						
	AFL	2156						
24-54-05		28 VDC / 115 VAC STATIC INVERTER						Component ATA:24
PN:AS-24-0026-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0177	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-65-00		CABLE W109 LPDU/RPDU FEEDER						Component ATA:24
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-01, AMM 24-65-01, AMM 24-65-02, AMM 24-65-02								
24-65-01		LEFT POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG16-1B	MOS/MSC	05-Jul-13	O/C					
SN:0287	HRS	602.8						
	AFL	558						
PROC. REF: AMM 24-65-01, AMM 24-65-01								
24-65-02		RIGHT POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG17-1B	MOS/MSC	05-Jul-13	O/C					
SN:0232	HRS	602.8						
	AFL	558						
PROC. REF: AMM 24-65-02, AMM 24-65-02								
24-65-03		CENTER POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG18-1B	MOS/MSC	05-Jul-13	O/C					
SN:0296	HRS	602.8						
	AFL	558						
PROC. REF: AMM 24-65-03, AMM 24-65-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25 EEI-1 ^U	INSPECT EMERGENCY EQUIPMENT (FAR 91.409 AND FAR 91.513)							Service ATA:25
	MOS	02-Apr-24	12		02-Apr-25		142 d	FAR
	HRS	2308.3						
	AFL	2118						
25-11-01	COPILOT CITRINE FINISH GOODRICH SEAT							Component ATA:25
PN:1429-621AL	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:871-1429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01	PILOT CITRINE FINISH GOODRICH SEAT							Component ATA:25
PN:1429-521AL	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:921-1429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01-001 ^S	DETAILED VISUAL INSPECTION COPILOT CITRINE FINISH GOODRICH SEAT							Service ATA:25
PN:1429-621AL	MOS	28-Mar-23						
SN:871-1429	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-11-01								PKG:20
25-11-01-001 ^S	DETAILED VISUAL INSPECTION PILOT CITRINE FINISH GOODRICH SEAT							Service ATA:25
PN:1429-521AL	MOS	28-Mar-23						
SN:921-1429	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-11-01								PKG:20
25-11-01-002 ^S	DETAILED VISUAL INSPECTION OF COCKPIT SEAT BELTS							Service ATA:25
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-11-01								PKG:20
25-21-01	LH AFT PAX SEAT							Component ATA:25
PN:403176-2ACR	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:47027	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01, AMM 25-21-00, AMM 25-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-01	LH FWD PAX SEAT							Component ATA:25
PN:403176-1ACR	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:47026	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01, AMM 25-21-00, AMM 25-21-00								
25-21-01	RH AFT PAX SEAT							Component ATA:25
PN:403176-4AC	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:46431	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01, AMM 25-21-00, AMM 25-21-00								
25-21-01	RH FWD PAX SEAT							Component ATA:25
PN:403176-3AC	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:46430	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01, AMM 25-21-00, AMM 25-21-00								
25-21-01-001 ^S	DETAILED VISUAL INSPECTION LH AFT PAX SEAT							Service ATA:25
PN:403176-2ACR	MOS	28-Mar-23						
SN:47027	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-21-01								PKG:20
25-21-01-001 ^S	DETAILED VISUAL INSPECTION LH FWD PAX SEAT							Service ATA:25
PN:403176-1ACR	MOS	28-Mar-23						
SN:47026	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-21-01								PKG:20
25-21-01-001 ^S	DETAILED VISUAL INSPECTION RH AFT PAX SEAT							Service ATA:25
PN:403176-4AC	MOS	28-Mar-23						
SN:46431	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-21-01								PKG:20
25-21-01-001 ^S	DETAILED VISUAL INSPECTION RH FWD PAX SEAT							Service ATA:25
PN:403176-3AC	MOS	28-Mar-23						
SN:46430	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 25-21-01								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-01-002 ^S	DETAILED VISUAL INSPECTION OF PASSENGER SEAT BELTS							Service ATA:25
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
	PROC. REF: AMM 25-21-01							PKG:20
25-21-03-001	DETAILED INSPECTION OF FIFTH SEAT							Service ATA:25
	MOS/MSC	20-Mar-10	N/A					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 25-21-03							
25-21-03-002	DETAILED INSPECTION OF THE FIFTH SEAT BELT							Service ATA:25
	MOS/MSC	20-Mar-10	N/A					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 25-21-03							
25-43-01-001 ^S	DETAILED VISUAL INSPECTION OF BELTED TOILET UNIT							Service ATA:25
	MOS	31-Mar-14						
	HRS	722.6	3200 (+30/-30)					
	AFL	663						
	PROC. REF: AMM 25-43-02							PKG:40
25-43-01-002 ^S	DETAILED VISUAL INSPECTION OF BELTED TOILET SEAT BELT							Service ATA:25
	MOS	31-Mar-14						
	HRS	722.6	3200 (+30/-30)					
	AFL	663						
	PROC. REF: AMM 25-43-02							PKG:40
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM							Service ATA:25
PN:S1821502-02	MOS	02-Apr-24	12	Adj -5d	28-Mar-25		137 d	
SN:2621424-0032	HRS	2308.3						
	AFL	2118						
	PROC. REF: AMM 25-61-00							
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:S1821502-02	MOS	02-Apr-24	12	Adj -5d	28-Mar-25		137 d	
SN:2621424-0032	HRS	2308.3						
	AFL	2118						
	PROC. REF: AMM 25-61-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-01	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:S1821502-02	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:2621424-0032	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01								
25-61-02	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:S1820506-01	MOS/MSC	28-Mar-21	H/T	TSN 1				
SN:20120190	HRS	1870		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-61-04								
25-61-03	ELT ANTENNA							Component ATA:25
PN:S65-8282-406	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:401-1611	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-03, AMM 25-61-03								
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY							Service ATA:25
PN:S1820506-01	MOS/MSC	28-Mar-21	DUE		01-Mar-27 (M)		840 d	
SN:20120190	HRS	1870						
	AFL							
PROC. REF: AMM 25-61-04								
25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE							Service ATA:25
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 25-61-07								
25-61-05-01	ELT/NAV INTERFACE - CS144-A MODULE							Component ATA:25
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-05, AMM 25-61-05								
25-62-01	FIRST AID KIT							Component ATA:25
PN:019708-0005L	MOS/MSC	17-Nov-23	H/T	TSN 0				
SN:UNKNOWN	HRS	2251.6		TSN 0				
	AFL	2074		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-01-001	VISUAL CHECK FIRST AID KIT							Service ATA:25
PN:019708-0005L	MOS/MSC	17-Nov-23	DUE		01-Aug-25 (M)		263 d	
SN:UNKNOWN	HRS	2251.6						
	AFL	2074						
PROC. REF: AMM 25-62-01								
25-62-02	COPILOT CREW LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	23-Nov-19	H/T	TSN 6				
SN:L4720467	HRS	1710		TSN 0				
	AFL	1560		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.1 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	11-Apr-19	H/T	TSN 0				
SN:L4475548	HRS	1560.3		TSN 0				
	AFL	1408		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.2 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	11-Apr-19	H/T	TSN 0				
SN:L4475549	HRS	1560.3		TSN 0				
	AFL	1408		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.3 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	11-Apr-19	H/T	TSN 0				
SN:L4475554	HRS	1560.3		TSN 0				
	AFL	1408		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.4 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	11-Apr-19	H/T	TSN 0				
SN:L4475547	HRS	1560.3		TSN 0				
	AFL	1408		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	PILOT CREW LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	23-Nov-19	H/T	TSN 6				
SN:L4720466	HRS	1710		TSN 0				
	AFL	1560		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF COPILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	01-May-19	120		01-May-29		1632 d	OVERHAUL
SN:L4720467	HRS							
	AFL							
	OverHaul Date:: 01-May-19		PROC. REF: AMM 25-62-02					
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST							Service ATA:25
PN:66601-105	MOS	05-Apr-19	120		01-Nov-28 (M)		1451 d	OVERHAUL
SN:L4475548	HRS							
	AFL							
	PROC. REF: AMM 25-62-02							
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST							Service ATA:25
PN:66601-105	MOS	05-Apr-19	120		01-Nov-28 (M)		1451 d	OVERHAUL
SN:L4475549	HRS							
	AFL							
	PROC. REF: AMM 25-62-02							
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST							Service ATA:25
PN:66601-105	MOS	05-Apr-19	120		01-Nov-28 (M)		1451 d	OVERHAUL
SN:L4475554	HRS							
	AFL							
	PROC. REF: AMM 25-62-02							
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST							Service ATA:25
PN:66601-105	MOS	05-Apr-19	120		01-Nov-28 (M)		1451 d	OVERHAUL
SN:L4475547	HRS							
	AFL							
	PROC. REF: AMM 25-62-02							
25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	01-May-19	120		01-May-29		1632 d	OVERHAUL
SN:L4720466	HRS							
	AFL							
	OverHaul Date:: 01-May-19		PROC. REF: AMM 25-62-02					
25-62-03 ^U	LAV LIFE VEST CHECK							Component ATA:25
PN:66601-105	MOS/MSC	22-Nov-21	DUE		01-May-31 (M)		2362 d	
SN:L5234791	HRS	1964.2						
	AFL	1795						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-04	LAV WATER BARRIER							Component ATA:25
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
25-62-04-001 ^S	DETAILED DIMENSIONAL INSPECTION LAV WATER BARRIER							Service ATA:25
PN:PN	MOS	02-Apr-24	24 (+1m/-1m)					
SN:UNKNOWN	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 25-62-04								PKG:81
25-66-00 ^U	LIFE RAFT							Component ATA:25
PN:PN	MOS/MSC	20-Mar-10	A/R	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
25-66-01-001 ^U	RESTORE LIFE RAFT							Service ATA:25
PN:PN	MOS/MSC		N/A					
SN:NOT INSTALLED	HRS							
	AFL							
ATA 26 - FIRE PROTECTION								
26-11-01	LH ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-49-565/211C-3.7M	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:42675	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01	RH ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-49-565/211C-3.7M	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:42676	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-11-01-001 ^S		DETAILED VISUAL INSPECTION LH ENGINE FIRE DETECTOR						Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	15-Jan-17						
SN:42675	HRS	1223.4	1600 (+30/-30)					
	AFL	1099						
				PROC. REF: AMM 26-11-01		PKG:10		
26-11-01-001 ^S		DETAILED VISUAL INSPECTION RH ENGINE FIRE DETECTOR						Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	15-Jan-17						
SN:42676	HRS	1223.4	1600 (+30/-30)					
	AFL	1099						
				PROC. REF: AMM 26-11-01		PKG:10		
26-11-01-002		OPERATIONAL CHECK LH ENGINE FIRE DETECTOR						Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	15-Jan-17						AIRWORTHINESS
SN:42675	HRS	1223.4	1600 (+30/-30)	2823.4	2853.4	480.7 (+30)		
	AFL	1099						
				PROC. REF: AMM 26-11-01				
26-11-01-002		OPERATIONAL CHECK RH ENGINE FIRE DETECTOR						Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	15-Jan-17						AIRWORTHINESS
SN:42676	HRS	1223.4	1600 (+30/-30)	2823.4	2853.4	480.7 (+30)		
	AFL	1099						
				PROC. REF: AMM 26-11-01				
26-21-01		FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL						Component ATA:26
PN:441-42702-002	MOS/MSC	16-Nov-22	O/C	TSR 11				
SN:0545	HRS	2110.5		TSR 0				
	AFL	1936		TSR 0				
				PROC. REF: AMM 26-21-01, AMM 26-21-01, AMM 26-21-02, AMM 26-21-02				
26-21-01-001		FUNCTIONAL CHECK FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL FIREX PANEL/SYSTEM						Service ATA:26
PN:441-42702-002	MOS	28-Mar-23						AIRWORTHINESS
SN:0545	HRS	2178.6	2400 (+30/-30)	4578.6	4608.6	2235.9 (+30)		
	AFL	1992						
				PROC. REF: AMM 26-21-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-03	ENGINE FIRE EXTINGUISHING BOTTLE							Component ATA:26
PN:33000073-4	MOS/MSC	23-Nov-19	O/C	TSN 0				
SN:89012A1	HRS	1710		TSN 0				
	AFL	1560		TSN 0				
PROC. REF: AMM 26-21-03, AMM 26-21-03								
26-21-03-001	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHING BOTTLE							Service ATA:26
PN:33000073-4	MOS	01-May-19	120		01-May-29 (M)		1632 d	AIRWORTHINESS
SN:89012A1	HRS							
	AFL							
PROC. REF: AMM 26-21-03								
26-21-05-001	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)							Service ATA:26
	MOS	28-Mar-23						AIRWORTHINESS
	HRS	2178.6	2400 (+30/-30)		4578.6	4608.6	2235.9 (+30)	
	AFL	1992						
PROC. REF: AMM 26-21-05								
26-21-07	LEFT ENG FIREX CARTRIDGE							Component ATA:26
PN:30903962-1	MOS/MSC	23-Nov-19	O/C	TSN 6				
SN:1483YA	HRS	1710		TSN 0				
	AFL	1560		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07	RIGHT ENG FIREX CARTRIDGE							Component ATA:26
PN:30903962-1	MOS/MSC	23-Nov-19	O/C	TSN 6				
SN:0066WL	HRS	1710		TSN 0				
	AFL	1560		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07-001	DISCARD LEFT ENG FIREX CARTRIDGE							Service ATA:26
PN:30903962-1	MOS	01-May-19	120		01-May-29		1632 d	LIFE LIMIT
SN:1483YA	HRS							
	AFL							
		Manufacture Date:: 01-May-19	PROC. REF: AMM 26-21-07					
26-21-07-001	DISCARD RIGHT ENG FIREX CARTRIDGE							Service ATA:26
PN:30903962-1	MOS	01-May-19	120		01-May-29		1632 d	LIFE LIMIT
SN:0066WL	HRS							
	AFL							
		Manufacture Date:: 01-May-19	PROC. REF: AMM 26-21-07					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-09-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING							Service ATA:26
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
				PROC. REF: AMM 26-21-09				PKG:20
26-24-01	COCKPIT PORTABLE EXTINGUISHER							Component ATA:26
PN:RT-A1200	MOS/MSC	03-Apr-17	H/T	TSN 0				
SN:Y-500626	HRS	1259		TSN 0				
	AFL	1134		TSN 0				
				PROC. REF: AMM 26-24-01, AMM 26-24-01				
26-24-01-001	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	02-Apr-24	12	Adj -5d	28-Mar-25		137 d	
SN:Y-500626	HRS	2308.3						
	AFL							
		WeightCheck Date : 02-Apr-24		PROC. REF: AMM 26-24-01				
26-24-01-002	DISCARD COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS		144		01-Apr-28 (M)		1237 d	
SN:Y-500626	HRS							
	AFL							
				PROC. REF: AMM 26-24-01				
26-24-01-003	DISCARD COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS/MSC		N/A					
SN:Y-500626	HRS							
	AFL							
				PROC. REF: AMM 26-24-01				
26-24-01-004	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER							Service ATA:26
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: AMM 26-24-01				
26-24-01-004	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
	MOS/MSC		N/A					
	HRS							
	AFL							
				PROC. REF: AMM 26-24-01				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-001	LEFT FLAP ACTUATOR							Component ATA:27
PN:6094A0001-05	MOS	13-Dec-12						LIFE LIMIT
SN:0534	HRS	498.2	21000	TSN 549.8	20948.4		18605.7	
	AFL	470		TSN 725				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-001	RIGHT FLAP ACTUATOR							Component ATA:27
PN:6094A0001-05	MOS	13-Dec-12						LIFE LIMIT
SN:0665	HRS	499.1	21000	TSN 67.9	21431.2		19088.5	
	AFL	470		TSN 55				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-002	ROLL TRIM ACTUATOR							Component ATA:27
PN:452900-1007	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:0194	HRS	0	35000	TSN 0	35000		32657.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-02, AMM 27-14-02								
27-003	YAW TRIM ACTUATOR							Component ATA:27
PN:453000-1007	MOS	18-Jan-21		TSR 1				LIFE LIMIT
SN:0267	HRS	1845.7	35000	TSN 1076, TSR 0	35769.7		33427	
	AFL			TSN 864, TSR 0				
PROC. REF: AMM 27-24-02, AMM 27-24-02								
27-004	LEFT PITCH TRIM ACTUATOR							Component ATA:27
PN:453100-1009	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:0179	HRS	0	3200	TSN 0	3200		857.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-02, AMM 27-34-02								
27-004	RIGHT PITCH TRIM ACTUATOR							Component ATA:27
PN:453100-1009	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:0183	HRS	0	3200	TSN 0	3200		857.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-02, AMM 27-34-02								
27-005	LH WING GROUND SPOILER ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	20-Mar-10	N/A	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-62-01, AMM 27-62-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-01-01	LEFT CONTROL YOKE							Component ATA:27
PN:83912039	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00269	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								
27-01-01	RIGHT CONTROL YOKE							Component ATA:27
PN:83912040	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00252	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								
27-01-02	LH PEDAL ASSEMBLY							Component ATA:27
PN:500-15010-417	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00005311886	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-02, AMM 27-01-02								
27-01-03-001 ^S	LUBRICATION OF ROTARY BALL SPLINE							Service ATA:27
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 12-21-00								PKG:81
27-04-01	NO.1 TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:461600-1011	MOS/MSC	22-Nov-21	O/C					
SN:0862	HRS	1964.2						
	AFL	1795						
PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01	NO.2 TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:461600-1011	MOS/MSC	17-Nov-23	O/C					
SN:0889	HRS	2251.6						
	AFL	2074						
PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01-001 ^S	FUNCTIONAL CHECK OF TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-04-01-002 ^S	FUNCTIONAL CHECK OF TRIM TABS ELECTRICAL STOP							Service ATA:27
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 27-04-01							PKG:50
27-04-01-003 ^S	OPERATIONAL CHECK OF TRIM TAB JAM MONITORING FUNCTION							Service ATA:27
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 27-04-01							PKG:50
27-11-00-001 ^S	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
	PROC. REF: AMM 27-11-00							PKG:42
27-11-01	LH AILERON BALANCED ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 27-11-01, AMM 27-11-01							
27-11-01	RH AILERON BALANCED ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 27-11-01, AMM 27-11-01							
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION							Service ATA:27
	MOS	23-Apr-22	60 (+1m/-1m)		23-Apr-27	23-May-27	893 d (+30)	
	HRS	2046.4	3200 (+30/-30)		5246.4	5276.4	2903.7 (+30)	
	AFL	1866						
	PROC. REF: AMM 27-11-02							
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	20-Mar-10	-					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 27-11-02							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-02-002 ^S	DETAILED VISUAL INSPECTION OF AILERON CONTROL CABLES							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-11-02							PKG:42	
27-14-02-001	FUNCTIONAL CHECK ROLL TRIM ACTUATOR AILERON TRIM BACKLASH/ INTEGRITY							Service ATA:27
PN:452900-1007	MOS	20-Mar-10					AIRWORTHINESS	
SN:0194	HRS	0	6000 (+30/-30)		6000	6030	3657.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-03								
27-14-03	LEFT AILERON TRIM TAB							Component ATA:27
PN:500-14630-405	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000527919	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-03, AMM 27-14-03								
27-21-00-001 ^S	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-21-00							PKG:42	
27-21-01	RUDDER BALANCED ASSEMBLY							Component ATA:27
PN:500-10520-411	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000534298	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-01, AMM 27-21-01								
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION							Service ATA:27
	MOS	23-Apr-22	60 (+1m/-1m)		23-Apr-27	23-May-27	893 d (+30)	
	HRS	2046.4	3200 (+30/-30)		5246.4	5276.4	2903.7 (+30)	
	AFL	1866						
PROC. REF: AMM 27-21-02								
27-21-02-001(INITIAL)	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	20-Mar-10	-					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-02-002 ^S	DETAILED VISUAL INSPECTION OF RUDDER CONTROL CABLES							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-21-02								PKG:42
27-24-02-001	FUNCTIONAL CHECK YAW TRIM ACTUATOR RUDDER TRIM BACKLASH INTEGRITY							Service ATA:27
PN:453000-1007	MOS	18-Jan-21						AIRWORTHINESS
SN:0267	HRS	1845.7	6000 (+30/-30)		7845.7	7875.7	5503 (+30)	
	AFL							
PROC. REF: AMM 27-24-03								
27-24-03	TAB RUDDER							Component ATA:27
PN:500-10420-407	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000525147	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-03, AMM 27-24-03								
27-31-00-001 ^S	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-31-00								PKG:42
27-31-01	LEFT ELEVATOR							Component ATA:27
PN:500-11085-4001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000533260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-01	RIGHT ELEVATOR							Component ATA:27
PN:500-11085-4002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000533260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION							Service ATA:27
	MOS	23-Apr-22	60 (+1m/-1m)		23-Apr-27	23-May-27	893 d (+30)	
	HRS	2046.4	3200 (+30/-30)		5246.4	5276.4	2903.7 (+30)	
	AFL	1866						
PROC. REF: AMM 27-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	20-Mar-10	-					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
27-31-02-002 ^S	DETAILED VISUAL INSPECTION OF ELEVATOR CONTROL CABLES							Service ATA:27
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1	3200 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-31-02								
PKG:42								
27-34-02-001	FUNCTIONAL CHECK OF PITCH TRIM BACKLASH/ INTEGRITY							Service ATA:27
	MOS	20-Mar-10						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	3657.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-34-05								
27-34-04	PITCH TRIM INTERCONNECTION ACTUATOR							Component ATA:27
PN:453110-1001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0273	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-04, AMM 27-34-04								
27-34-05	LEFT ELEVATOR TRIM TAB							Component ATA:27
PN:500-11010-4001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000523600	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-05, AMM 27-34-05								
27-34-05	RIGHT ELEVATOR TRIM TAB							Component ATA:27
PN:500-11010-4002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000530437	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-05, AMM 27-34-05								
27-36-01	LEFT ANGLE-OF-ATTACK SENSOR							Component ATA:27
PN:C-100117-4	MOS/MSC	01-Apr-14	O/C					
SN:142880-05	HRS	722.6						
	AFL	663						
PROC. REF: AMM 27-36-01, AMM 27-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-36-01	RIGHT ANGLE-OF-ATTACK SENSOR							Component ATA:27
PN:C-100117-4	MOS/MSC	01-Apr-14	O/C					
SN:143696A-04	HRS	722.6						
	AFL	663						
PROC. REF: AMM 27-36-01, AMM 27-36-01								
27-36-01-001 ^S	OPERATIONAL CHECK OF ANGLE-OF-ATTACK (AOA) SENSOR							Service ATA:27
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 27-36-01								
PKG:1								
27-36-02	STICK PUSHER LINEAR ACTUATOR							Component ATA:27
PN:260926258-0101	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-02, AMM 27-36-02								
27-36-03-001 ^S	OPERATIONAL CHECK OF SPWS CUTOUT SWITCH							Service ATA:27
	MOS	07-May-20						
	HRS	1774.1	1600 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 27-36-03								
PKG:10								
27-36-04	STALL WARNING AND PROTECTION COMPUTER							Component ATA:27
PN:C-100106-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:308	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-04, AMM 27-36-04								
27-51-01-001 ^S	LUBRICATION OF FLAP ACTUATORS BALL SCREWS							Service ATA:27
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 12-21-00								
PKG:80								
27-51-01-002 ^S	DETAILED VISUAL INSPECTION LEFT FLAP ACTUATOR							Service ATA:27
PN:6094A0001-05	MOS	13-Dec-12						
SN:0534	HRS	498.2	6400 (+30/-30)					
	AFL	470						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
PKG:60								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-002 ^S		DETAILED VISUAL INSPECTION RIGHT FLAP ACTUATOR						Service ATA:27
PN:6094A0001-05	MOS	13-Dec-12						
SN:0665	HRS	499.1	6400 (+30/-30)					
	AFL	470						
PROC. REF: AMM 27-51-01, AMM 27-51-01								PKG:60
27-51-01-003		RESTORE (OVERHAUL) LEFT FLAP ACTUATOR						Service ATA:27
PN:6094A0001-05	MOS	13-Dec-12						
SN:0534	HRS	498.2	4000 (+30/-30)	TAC 549.8	3948.4	3978.4	1605.7 (+30)	
	AFL	470		TAC 725				
PROC. REF: AMM 27-51-01								
27-51-01-003		RESTORE (OVERHAUL) RIGHT FLAP ACTUATOR						Service ATA:27
PN:6094A0001-05	MOS	13-Dec-12						
SN:0665	HRS	499.1	4000 (+30/-30)	TAC 67.9	4431.2	4461.2	2088.5 (+30)	
	AFL	470		TAC 55				
PROC. REF: AMM 27-51-01								
27-51-03		LH WING FLAP						Component ATA:27
PN:500-14301-403	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000524918	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-03, AMM 27-51-03								
27-51-03		RH WING FLAP						Component ATA:27
PN:500-14301-404	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000518509	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-03, AMM 27-51-03								
27-53-01		FLAP SELECTOR LEVER						Component ATA:27
PN:780501-9	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:1025	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01, AMM 27-53-01								
27-53-02		FLAP SYSTEM CONTROL UNIT						Component ATA:27
PN:8025A0001-08	MOS/MSC	04-Oct-10	O/C					
SN:0120	HRS	108.9						
	AFL	114						
PROC. REF: AMM 27-53-02, AMM 27-53-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-03	LH WING FLAP POSITION SENSOR UNIT							Component ATA:27
PN:7906A0001-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:KA1523	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-53-03	RH WING FLAP POSITION SENSOR UNIT							Component ATA:27
PN:7906A0001-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:KA1530	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-60-00-001	OPERATIONAL CHECK OF GROUND SPOILER SYSTEM							Service ATA:27
	MOS/MSC	20-Mar-10	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-60-00								
ATA 28 - FUEL								
28-11-00-001 ^S	FUNCTIONAL CHECK OF FUEL TANKS FOR MICRO-ORGANISMS							Service ATA:28
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 28-11-00								PKG:80
28-11-05	LH WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	23-Apr-22	O/C	TSN 0				
SN:UNKNOWN	HRS	2046.4		TSN 0				
	AFL	1866		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-05	RH WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E06626	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-07	LH WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E15601	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-11-07	RH WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E15596	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-12-01-001	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA							Service ATA:28
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 28-12-01								PKG:1
28-12-03	LH WING FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E16340	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07								
28-12-03	RH WING FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E17354	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07								
28-12-03-001 ^S	OPERATIONAL CHECK LH WING FUEL TANK FLOAT VENT VALVE							Service ATA:28
PN:L87-19-001P2	MOS	20-Mar-10						
SN:E16340	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60
28-12-03-001 ^S	OPERATIONAL CHECK RH WING FUEL TANK FLOAT VENT VALVE							Service ATA:28
PN:L87-19-001P2	MOS	20-Mar-10						
SN:E17354	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-12-05	LH WING DRAIN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-12-05	RH WING DRAIN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-21-00	NO.1 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.2 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.3 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.4 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-03	LH WING DC AUXILIARY CANISTER BOOST PUMP							Component ATA:28
PN:C93R19-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E17854	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-03	RH WING DC AUXILIARY CANISTER BOOST PUMP							Component ATA:28
PN:C93R19-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E17887	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-04	LH WING DC AUXILIARY CARTRIDGE BOOST PUMP							Component ATA:28
PN:P99C19-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E24278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-04	RH WING DC AUXILIARY CARTRIDGE BOOST PUMP							Component ATA:28
PN:P99C19-602	MOS/MSC	08-Apr-17	O/C	TSN 0				
SN:G96393	HRS	1260.8		TSN 0				
	AFL	1136		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-05	LH WING MAIN EJECTOR PUMP							Component ATA:28
PN:T99A19-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E17328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-05	RH WING MAIN EJECTOR PUMP							Component ATA:28
PN:T99A19-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E17312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-07-001	OPERATIONAL CHECK LEFT WING 0.75 IN SHUTOFF VALVE							Service ATA:28
PN:B97-15-601	MOS	02-Apr-24						AIRWORTHINESS
SN:D98404	HRS	2308.3	1200 (+30/-30)		3508.3	3538.3	1165.6 (+30)	
	AFL	2118						
PROC. REF: AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK RIGHT WING 0.75 IN SHUTOFF VALVE							Service ATA:28
PN:B97-15-601	MOS	02-Apr-24						AIRWORTHINESS
SN:E06067	HRS	2308.3	1200 (+30/-30)		3508.3	3538.3	1165.6 (+30)	
	AFL	2118						
PROC. REF: AMM 28-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-07-01	LEFT WING 0.75 IN SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:D98404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-01	RIGHT WING 0.75 IN SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E06067	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-02	LH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY							Component ATA:28
PN:D97C00-644P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:C70481	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-02	RH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY							Component ATA:28
PN:D97C00-644P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:C70472	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-08-001 ^S	OPERATIONAL CHECK OF FUEL TRANSFER VALVE							Service ATA:28
PN:B97-38-603P2	MOS	07-May-20						
SN:E19543	HRS	1774.1	1600 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 28-21-08								
PKG:10								
28-21-08-01	1.5 IN FUEL SYSTEM SHUTOFF VALVE							Component ATA:28
PN:B97-38-603P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E19543	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-08, AMM 28-21-08								
28-21-08-02	ENGINE 28-V DC TRANSFER VALVE ACTUATOR ASSEMBLY							Component ATA:28
PN:D97C00-644P2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:C70475	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-08, AMM 28-21-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-11	LH WING MOTIVE FLOW 3/8 IN CHECK VALVE							Component ATA:28
PN:L96-09-001P4	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E22298	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-11	RH WING MOTIVE FLOW 3/8 IN CHECK VALVE							Component ATA:28
PN:L96-09-001P4	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:E22300	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-13	FUEL CONTROL PANEL							Component ATA:28
PN:441-42854-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0126	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-13, AMM 28-21-13								
28-41-01	NO. 1 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765551-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765551IN00257	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 1 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765826-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765826IN00222	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765548-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765548IN00250	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765827-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765827IN00238	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-01	NO. 3 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765549-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765549IN00397	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765549-1-0	MOS/MSC	24-Jul-21	O/C	TSN 0				
SN:765549IN01050	HRS	1908		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765550-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765550IN00415	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765550-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:765550IN00403	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-05	ELECTRONIC FUEL CONTROL UNIT							Component ATA:28
PN:738742-1-4	MOS/MSC	24-Jul-21	O/C					
SN:738790IN00202	HRS	1908						
	AFL							
PROC. REF: AMM 28-41-05, AMM 28-41-05								
28-43-01	FUEL TEMPERATURE SENSOR							Component ATA:28
PN:798840-1-0	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01981	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-43-01, AMM 28-43-01								
28-43-01-001 ^S	FUNCTIONAL CHECK FUEL TEMPERATURE SENSOR							Service ATA:28
PN:798840-1-0	MOS	20-Mar-10						
SN:01981	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-43-01								
								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-45-01	NO.1 FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0273	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								
28-45-01	NO.2 FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								
ATA 29 - HYDRAULIC POWER								
29-00-00-001 ^S	VISUAL CHECK OF HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR (DPI)							Service ATA:29
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 29-31-02								PKG:80
29-11-01	HYDRAULIC POWERPACK							Component ATA:29
PN:3032683-104	MOS/MSC	24-Nov-20	O/C	TSO 0				
SN:MX722391	HRS	1828.5		TSN 1733, TSO 0				
	AFL			TSN 1546, TSO 0				
PROC. REF: AMM 29-11-01, AMM 29-11-01								
29-11-01-001	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK							Service ATA:29
PN:3032683-104	MOS/MSC		N/A					
SN:MX722391	HRS							
	AFL							
PROC. REF: AMM 29-11-01								
29-11-01-002	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK							Service ATA:29
PN:3032683-104	MOS	24-Nov-20						OVERHAUL
SN:MX722391	HRS	1828.5	1600 (+30/-30)	3428.5	3458.5	1085.8 (+30)		
	AFL							
PROC. REF: AMM 29-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-09	HYDRAULIC POWERPACK TEMPERATURE SWITCH							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-09, AMM 29-11-09								
29-11-09-001 ^S	FUNCTIONAL CHECK OF TEMPERATURE SWITCH							Service ATA:29
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-11-09								
							PKG:60	
29-15-01	LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01	LH WING - GROUND SPOILER ACTUATOR RETURN HOSE							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01	RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01	RH WING - GROUND SPOILER ACTUATOR RETURN HOSE							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01-001	DISCARD LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE							Service ATA:29
PN:PN	MOS/MSC	23-Apr-22	N/A					
SN:UNKNOWN	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 29-15-01								
							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-15-01-001	DISCARD LH WING - GROUND SPOILER ACTUATOR RETURN HOSE							Service ATA:29
PN:PN	MOS/MSC	23-Apr-22	N/A					
SN:UNKNOWN	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 29-15-01								PKG:1
29-15-01-001	DISCARD RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE							Service ATA:29
PN:PN	MOS/MSC	23-Apr-22	N/A					
SN:UNKNOWN	HRS	2046.4						
	AFL							
PROC. REF: AMM 29-15-01								PKG:1
29-15-01-001	DISCARD RH WING - GROUND SPOILER ACTUATOR RETURN HOSE							Service ATA:29
PN:PN	MOS/MSC	23-Apr-22	N/A					
SN:UNKNOWN	HRS	2046.4						
	AFL							
PROC. REF: AMM 29-15-01								PKG:1
29-15-03	HYDRAULIC ACCUMULATOR							Component ATA:29
PN:MS28797-3	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:8423-12706	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-03, AMM 29-15-03								
29-15-03-001	DISCARD OF HYDRAULIC ACCUMULATOR							Service ATA:29
	MOS	20-Mar-10						DISCARD
	HRS	0						
	AFL	0	28000		28000		25844	
PROC. REF: AMM 29-15-03								
29-20-01	POWERPACK VENTILATION FAN							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-20-01, AMM 29-20-01								
29-20-01-001 ^S	OPERATIONAL CHECK OF POWERPACK VENTILATION FAN							Service ATA:29
PN:PN	MOS	23-Apr-22						
SN:UNKNOWN	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 29-20-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-31-02	HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR							Component ATA:29
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-02, AMM 29-31-02								
ATA 30 - ICE AND RAIN PROTECTION								
30-01-01	ICE PROTECTION/HEATING SYSTEM CONTROL PANEL							Component ATA:30
PN:441-43199-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0117	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-01-01, AMM 30-01-01								
30-10-00-001 ^S	OPERATIONAL CHECK OF PNEUMATIC DE-ICING SYSTEM							Service ATA:30
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 30-10-00								
PKG:1								
30-11-01	DE-ICING SYSTEM CONTROLLER							Component ATA:30
PN:4D2037-24	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:U0211	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-01, AMM 30-11-01								
30-11-02	NO.1 REAR FUSELAGE CHECK VALVE							Component ATA:30
PN:3D3555-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N091140	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02, AMM 30-11-02								
30-11-02	NO.2 REAR FUSELAGE CHECK VALVE							Component ATA:30
PN:3D3555-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N091142	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02, AMM 30-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-03	REAR FUS PRESSURE REGULATOR/RELIEVER VALVE							Component ATA:30
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03, AMM 30-11-03								
30-11-03-001 ^S	CLEANING REAR FUS PRESSURE REGULATOR/RELIEVER VALVE							Service ATA:30
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-11-03								
								PKG:60
30-11-04	AFT WATER SEPARATOR							Component ATA:30
PN:44E13-1A	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N093515	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-04, AMM 30-11-04								
30-11-04	FORWARD WATER SEPARATOR							Component ATA:30
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-04, AMM 30-11-04								
30-11-04-001 ^S	RESTORATION (CLEANING) OF THE AFT WATER SEPARATOR							Service ATA:30
PN:44E13-1A	MOS	20-Mar-10						
SN:N093515	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-11-04								
								PKG:60
30-11-04-001 ^S	RESTORATION (CLEANING) OF THE FORWARD WATER SEPARATOR							Service ATA:30
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-11-04								
								PKG:60
30-11-05	REAR FUS LOW PRESSURE SWITCH							Component ATA:30
PN:3D3552-02	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:016B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-05, AMM 30-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-05-001 ^S FUNCTIONAL CHECK OF DE-ICING LOW PRESSURESWITCH (REAR FUS)								Service ATA:30
PN:3D3552-02	MOS	20-Mar-10						
SN:016B	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-11-05								PKG:50
30-13-01 INBOARD WING FLOW CONTROL VALVE								Component ATA:30
PN:3D2376-07	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N092439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-01, AMM 30-13-01								
30-13-01 OUTBOARD WING FLOW CONTROL VALVE								Component ATA:30
PN:3D2376-07	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N092460	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-01, AMM 30-13-01								
30-13-02 NO.1 L/H WING DE ICE PRESSURE SWITCH								Component ATA:30
PN:3D3533-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0834	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02 NO.1 R/H WING DE ICE PRESSURE SWITCH								Component ATA:30
PN:3D3533-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0728	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02 NO.2 L/H WING DE ICE PRESSURE SWITCH								Component ATA:30
PN:3D3533-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0844	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02 NO.2 R/H WING DE ICE PRESSURE SWITCH								Component ATA:30
PN:3D3533-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0824	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-13-02-001 ^S FUNCTIONAL CHECK NO.1 L/H WING DE ICE PRESSURE SWITCH								Service ATA:30
PN:3D3533-04	MOS	20-Mar-10						
SN:0834	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02								PKG:50
30-13-02-001 ^S FUNCTIONAL CHECK NO.1 R/H WING DE ICE PRESSURE SWITCH								Service ATA:30
PN:3D3533-04	MOS	20-Mar-10						
SN:0728	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02								PKG:50
30-13-02-001 ^S FUNCTIONAL CHECK NO.2 L/H WING DE ICE PRESSURE SWITCH								Service ATA:30
PN:3D3533-04	MOS	20-Mar-10						
SN:0844	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02								PKG:50
30-13-02-001 ^S FUNCTIONAL CHECK NO.2 R/H WING DE ICE PRESSURE SWITCH								Service ATA:30
PN:3D3533-04	MOS	20-Mar-10						
SN:0824	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02								PKG:50
30-13-03 LH WING DE-ICER BOOT								Component ATA:30
PN:PS29S4D5321-23	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MBLT340	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-03, AMM 30-13-03								
30-13-03 RH WING DE-ICER BOOT								Component ATA:30
PN:PS29S4D5321-24	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MCDB690	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-03, AMM 30-13-03								
30-13-03-001 ^S GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT								Service ATA:30
PN:PS29S4D5321-23	MOS	02-Apr-24	12 (+1m/-1m)					
SN:MBLT340	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-13-03								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-13-03-001 ^S GENERAL VISUAL INSPECTION RH WING DE-ICER BOOT								Service ATA:30
PN:PS29S4D5321-24	MOS	02-Apr-24	12 (+1m/-1m)					
SN:MCDB690	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-13-03								PKG:80
30-15-01 REAR FUS FLOW CONTROL VALVE								Component ATA:30
PN:3D2376-07	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:N092438	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-01, AMM 30-15-01								
30-15-02 REAR FUS DE ICE PRESSURE SWITCH								Component ATA:30
PN:3D3533-04	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0841	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-02, AMM 30-15-02								
30-15-02-001 ^S FUNCTIONAL CHECK OF HORIZONTAL STABILIZER DE-ICER PRESSURE SWITCH (REAR FUS)								Service ATA:30
PN:3D3533-04	MOS	20-Mar-10						
SN:0841	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-15-02								PKG:50
30-15-03 LH TAIL DE-ICER BOOT								Component ATA:30
PN:PS29S4D5321-21	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MBXQ710	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-03, AMM 30-15-03								
30-15-03 RH TAIL DE-ICER BOOT								Component ATA:30
PN:PS29S4D5321-22	MOS/MSC	02-Apr-24	O/C	TSN 0				
SN:NGU5500	HRS	2308.3		TSN 0				
	AFL	2118		TSN 0				
PROC. REF: AMM 30-15-03, AMM 30-15-03								
30-15-03-001 ^S GENERAL VISUAL INSPECTION OF LH TAIL DE-ICER BOOT								Service ATA:30
PN:PS29S4D5321-21	MOS	02-Apr-24	12 (+1m/-1m)					
SN:MBXQ710	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-15-03								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-15-03-001 ^S		GENERAL VISUAL INSPECTION OF RH TAIL DE-ICER BOOT						Service ATA:30
PN:PS29S4D5321-22	MOS	02-Apr-24	12 (+1m/-1m)					
SN:NGU5500	HRS	2308.3						
	AFL	2118						
				PROC. REF: AMM 30-15-03		PKG:80		
30-21-00-900-801-01		LH ENGINE ANTI ICING DUCT						Component ATA:30
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-00, AMM 30-21-00				
30-21-00-900-801-02		RH ENGINE ANTI ICING DUCT						Component ATA:30
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-00, AMM 30-21-00				
30-21-01		LEFT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE						Component ATA:30
PN:5727-00-5	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0304A	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-01, AMM 30-21-01				
30-21-01		RIGHT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE						Component ATA:30
PN:5727-00-5	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0303A	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-01, AMM 30-21-01				
30-21-02		LH ENG ANTI-ICE PRESSURE TRANSDUCER						Component ATA:30
PN:APTE-473A-1000-50G	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:7585-9-135	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-02, AMM 30-21-02				
30-21-02		RH ENG ANTI-ICE PRESSURE TRANSDUCER						Component ATA:30
PN:APTE-473A-1000-50G	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:7651-9-313	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: AMM 30-21-02, AMM 30-21-02				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-21-02-001	FUNCTIONAL CHECK OF LH ENG ANTI-ICE PRESSURE TRANSDUCER							Service ATA:30
PN:APTE-473A-1000-50G	MOS	20-Mar-10						
SN:7585-9-135	HRS	0	12000 (+30/-30)		12000	12030	9657.3 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-02-001	FUNCTIONAL CHECK OF RH ENG ANTI-ICE PRESSURE TRANSDUCER							Service ATA:30
PN:APTE-473A-1000-50G	MOS	20-Mar-10						
SN:7651-9-313	HRS	0	12000 (+30/-30)		12000	12030	9657.3 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-03-001 ^S	BORESCOPE INSPECTION OF PICCOLO TUBE							Service ATA:30
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-21-03								PKG:50
30-21-04-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE ANTI-ICE DUCTS							Service ATA:30
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 30-21-00								PKG:20
30-31-00-001 ^S	OPERATIONAL CHECK OF PITOT, STATIC, AOA AND P-STATIC HEATING							Service ATA:30
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-30-00								PKG:81
30-31-01	AIR DATA PROBES HEATER CURRENT MONITOR-							Component ATA:30
PN:C-100131-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-31-01, AMM 30-31-01								
30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING							Service ATA:30
	MOS/MSC	13-Mar-18	O/C					
	HRS	1396.1						
	AFL	1246						
PROC. REF: AMM 30-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-41-01-002 ^S		DISCARD OF WINDSHIELD RAIN REPELLENT COATING						Service ATA:30
	MOS	02-Apr-24	12 (+1m/-1m)					DISCARD
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-41-01								PKG:80
30-41-01-003		FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE						Service ATA:30
	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 30-41-01								PKG:80
30-42-00-001 ^S		OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM						Service ATA:30
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 30-42-00								PKG:1
30-42-01		LH WINDSHIELD HEATER CONTROL UNIT						Component ATA:30
PN:EPM-112-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00576	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-42-01		RH WINDSHIELD HEATER CONTROL UNIT						Component ATA:30
PN:EPM-112-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00551	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-81-01		CREW CABIN LIGHT ICING INDICATOR						Component ATA:30
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-81-02, AMM 30-81-02								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-00-002 ^S		OPERATIONAL CHECK OF COCKPIT VOICE AND DATA RECORDER SYSTEM						Service ATA:31
PN:2100-3083-50	MOS	02-Apr-24	12 (+1m/-1m)					
SN:000611095	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 31-31-00								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-01	CVDR - COCKPIT VOICE AND DATA RECORDER							Component ATA:31
PN:2100-3083-50	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:000611095	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-01, AMM 31-31-01								
31-31-03	CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY							Component ATA:31
PN:DK120-90	MOS/MSC	05-Nov-21	A/R	TSN 0				
SN:AT170273	HRS	1944		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-31-03-001	DISCARD CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY							Service ATA:31
PN:DK120-90	MOS/MSC	05-Nov-21	DUE		30-Sep-28 (M)		1419 d	DISCARD
SN:AT170273	HRS	1944						
	AFL							
Expiry Date: : 30-Sep-28 PROC. REF: AMM 31-31-03								
31-31-04	IMPACT SWITCH							Component ATA:31
PN:5930-4-000	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:4583	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-04, AMM 31-31-04								
31-31-09	CVDR INSC ILLUM PANEL							Component ATA:31
PN:441-42635-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-09, AMM 31-31-09								
31-31-13	CVDR/UNDERWATER LOCATOR BEACON							Component ATA:31
PN:PN	MOS/MSC	20-Mar-10	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-41-01	GSD 41 DATA CONCENTRATOR UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:16905160	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-41-03	NO.1 ENGINE/AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	07-May-20	O/C					
SN:46710983	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-41-03	NO.2 ENGINE/AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	07-May-20	O/C					
SN:46711019	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-41-03	NO.3 ENGINE/AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:46711039	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-41-05	NO.1 GIA63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-01	MOS/MSC	28-Mar-21	O/C	TSR 4				
SN:15W012178	HRS	1870		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05								
31-41-05	NO.2 GIA63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-01	MOS/MSC	18-Nov-16	O/C	TSR 0				
SN:15W009327	HRS	1209.9		TSR 0				
	AFL	1088		TSR 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05								
31-42-00-001 ^S	OPERATIONAL CHECK OF HSDB SWITCH REVERSION							Service ATA:31
	MOS	20-Mar-10						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-42-00								
PKG:60								
31-42-01	MAINTENANCE CONTROL PANEL							Component ATA:31
PN:441-40947-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0095	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-42-01, AMM 31-42-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-00-001 ^S		OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)						Service ATA:31
	MOS	20-Mar-10						
	HRS	0	3200 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 31-61-00						PKG:40	
31-61-00-001 ^S		OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)						Service ATA:31
	MOS	20-Mar-10						
	HRS	0	3200 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 31-61-00						PKG:40	
31-61-00-001 ^S		OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)						Service ATA:31
	MOS	20-Mar-10						
	HRS	0	3200 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 31-61-00						PKG:40	
31-61-01		MFD (MULTI-FUNCTION FLIGHT DISPLAY)						Component ATA:31
PN:011-03471-00	MOS/MSC	07-Feb-20	O/C	TSN 1				
SN:495001530	HRS	1734.2		TSN 0				
	AFL	1583		TSN 0				
	PROC. REF: AMM 31-61-01, AMM 31-61-01							
31-61-01		PFD 1 (PRIMARY FLIGHT DISPLAY)						Component ATA:31
PN:011-03471-00	MOS/MSC	12-Mar-20	O/C	TSN 0				
SN:495001566	HRS	1761.5		TSN 0				
	AFL	1598		TSN 0				
	PROC. REF: AMM 31-61-01, AMM 31-61-01							
31-61-01		PFD 2 (PRIMARY FLIGHT DISPLAY)						Component ATA:31
PN:011-03471-00	MOS/MSC	07-Feb-20	O/C	TSN 1				
SN:495001533	HRS	1734.2		TSN 0				
	AFL	1583		TSN 0				
	PROC. REF: AMM 31-61-01, AMM 31-61-01							
ATA 32 - LANDING GEAR								
32-00-00-001 ^S		EXTERNAL GENERAL VISUAL INSPECTION OF OF LANDING GEAR POLYURETHANE FILMS						Service ATA:32
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
	PROC. REF: AMM 32-00-20						PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-000	LEFT MAIN GEAR ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-000	RIGHT MAIN GEAR ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-001	LEFT MAIN GEAR SHOCK STRUT - MAIN FITTING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6360	TSN 0	6360		4204	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-002	RIGHT MAIN GEAR SHOCK STRUT - MAIN FITTING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6360	TSN 0	6360		4204	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-005	NO.1 LEFT MAIN GEAR PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-005	NO.1 RIGHT MAIN GEAR PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-005	NO.2 LEFT MAIN GEAR PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-005	NO.2 RIGHT MAIN GEAR PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-006	LEFT MAIN GEAR UPPER AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-006	RIGHT MAIN GEAR UPPER AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-007	LEFT MAIN GEAR LOWER AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-007	RIGHT MAIN GEAR LOWER AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-008	LEFT MAIN GEAR JACKING PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-008	RIGHT MAIN GEAR JACKING PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-009	LEFT MAIN GEAR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-009	RIGHT MAIN GEAR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-010	LEFT MAIN GEAR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-010	RIGHT MAIN GEAR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-100	LEFT MAIN GEAR TRAILING ARM ASSEMBLY							Component ATA:32
PN:2310-3000-401	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00168	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-100	RIGHT MAIN GEAR TRAILING ARM ASSEMBLY							Component ATA:32
PN:2310-3000-402	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00163	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-101	LEFT MAIN GEAR TRAILING ARM AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-101	RIGHT MAIN GEAR TRAILING ARM AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	LEFT MAIN GEAR TRAILING ARM							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-103	RIGHT MAIN GEAR TRAILING ARM							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	LEFT MAIN GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	RIGHT MAIN GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-11-00-001 ^S	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-11-00								PKG:80
32-11-00-001 ^S	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-11-00								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-002	RESTORE (OVERHAUL) LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00								
32-11-00-002	RESTORE (OVERHAUL) RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00								
32-11-00-003	LUBRICATION OF LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:UNKNOWN	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-21-00								
32-11-00-003	LUBRICATION OF RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:UNKNOWN	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-21-00								
32-11-01	LEFT MAIN GEAR SHOCK STRUT							Component ATA:32
PN:2310-2000-601	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00164	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-11-01	RIGHT MAIN GEAR SHOCK STRUT							Component ATA:32
PN:2310-2000-602	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00162	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-11-01-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)							Service ATA:32
PN:2310-2000-601	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00164	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)							Service ATA:32
PN:2310-2000-602	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00162	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)							Service ATA:32
PN:2136-1000-405	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00341	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)							Service ATA:32
PN:2136-1000-405	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00221	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)							Service ATA:32
PN:2310-4000-407	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00490	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)							Service ATA:32
PN:2310-4000-407	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00489	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-004	SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2310-4000-407	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:00490	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-03-004	SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2310-4000-407	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:00489	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-14-02								
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)							Service ATA:32
PN:2310-3000-401	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00168	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)							Service ATA:32
PN:2310-3000-402	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00163	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-11-00								
32-200	LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2310-4000-407	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00490	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-200	RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2310-4000-407	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00489	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-201	LEFT MAIN GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-201	RIGHT MAIN GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-204	LEFT MAIN GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-204	RIGHT MAIN GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-206	LEFT MAIN GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-206	RIGHT MAIN GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-207	LEFT MAIN GEAR SHOCK ABSORBER BEARING CAP							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								
32-207	RIGHT MAIN GEAR SHOCK ABSORBER BEARING CAP							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3500	TSN 0	3500		1344	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-00-001 ^S	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-21-00							PKG:80	
32-21-00-002	RESTORE (OVERHAUL) NOSE LANDING GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	28-Mar-21	O/C					
SN:UNKNOWN	HRS	1870						
	AFL	1703						
PROC. REF: AMM 32-21-00								
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:UNKNOWN	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-21-00								
32-21-01	NOSE LANDING GEAR SHOCK STRUT							Component ATA:32
PN:2310-1000-403	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00151	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-21-01-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY							Service ATA:32
PN:2310-1000-403	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00151	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-21-00								
32-21-02	NOSE LANDING GEAR RETRACT ACTUATOR ASSEMBLY							Component ATA:32
PN:2135-1000-403	MOS/MSC	28-Mar-21	O/C	TSN 132, TSO 0				
SN:00162	HRS	1870		TSN 1870, TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-21-02, AMM 32-21-02								
32-21-03	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR ASSEMBLY							Component ATA:32
PN:2137-1000-401	MOS/MSC	28-Mar-21	O/C	TSN 132, TSO 0				
SN:00157	HRS	1870		TSN 1870, TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-21-03, AMM 32-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-04-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY							Service ATA:32
PN:2310-1700-403	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00060	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-21-00								
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER							Service ATA:32
PN:PN-UNKNOWN	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:UNKNOWN	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-21-00								
32-21-05-004	SERVICING NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER							Service ATA:32
PN:PN-UNKNOWN	MOS	02-Apr-24	12 (+1m/-1m)	Adj -5d	28-Mar-25	28-Apr-25	137 d (+31)	
SN:UNKNOWN	HRS	2308.3						
	AFL	2118	650 (+30/-30)		2768	2798	612 (+30)	
PROC. REF: AMM 12-14-03								
32-21-06-005 ^S	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER							Service ATA:32
PN:2310-1500-405	MOS	02-Apr-24	12 (+1m/-1m)					
SN:00403	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-21-06								PKG:80
32-21-09-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY							Service ATA:32
PN:2310-1400-403	MOS	28-Mar-21	120 (+1m/-1m)		28-Mar-31	28-Apr-31	2328 d (+31)	OVERHAUL
SN:00057	HRS	1870						
	AFL	1703	12000 (+30/-30)		13703	13733	11547 (+30)	
PROC. REF: AMM 32-21-00								
32-300	LEFT MAIN GEAR LOCKING ACTUATOR ASSEMBLY							Component ATA:32
PN:2136-1000-405	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00341	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-300	RIGHT MAIN GEAR LOCKING ACTUATOR ASSEMBLY							Component ATA:32
PN:2136-1000-405	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00221	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-301	LEFT MAIN GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-301	RIGHT MAIN GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-304	LEFT MAIN GEAR LOCKING ACTUATOR PISTON							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-304	RIGHT MAIN GEAR LOCKING ACTUATOR PISTON							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-305	LEFT MAIN GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-305	RIGHT MAIN GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-306	LEFT MAIN GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-306	RIGHT MAIN GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-307	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	19500	TSN 0	19500		17344	
PROC. REF: GENERIC NO REF								
32-307	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	19500	TSN 0	19500		17344	
PROC. REF: GENERIC NO REF								
32-309	LEFT MAIN GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-309	RIGHT MAIN GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-31-01	LANDING GEAR CONTROL LEVER PANEL							Component ATA:32
PN:827101-5	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:1126	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-01, AMM 32-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-02	LANDING GEAR HYDRAULIC SYSTEM (MANIFOLD) ASSEMBLY							Component ATA:32
PN:72375-3	MOS/MSC	07-May-20	O/C	TSO 0				
SN:0346	HRS	1774.1		TSO 0				
	AFL	1606		TSO 0				
PROC. REF: AMM 32-31-02, AMM 32-31-02								
32-310	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-310	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-311	LEFT MAIN GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-311	RIGHT MAIN GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-312	LEFT MAIN GEAR LOCKING ACTUATOR NUT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-312	RIGHT MAIN GEAR LOCKING ACTUATOR NUT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-313	LEFT MAIN GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-313	RIGHT MAIN GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-314	LEFT MAIN GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-314	RIGHT MAIN GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	21000	TSN 0	21000		18844	
PROC. REF: GENERIC NO REF								
32-35-00-001 ^S	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-35-00								PKG:81
32-35-00-002 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES							Service ATA:32
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 32-35-00								PKG:84
32-400	NOSE LANDING GEAR ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-401	LEFT SIDE NLG SIDE PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-401	RIGHT SIDE NLG SIDE PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-402	NOSE LANDING GEAR MAIN FITTING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-404 (1)	NOSE LANDING GEAR TORQUE LINK							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-406	NOSE LANDING GEAR SHOCK STRUT PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-407	NOSE LANDING GEAR AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-408	NOSE LANDING GEAR STEERING BELLCRANK							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-409	NOSE LANDING GEAR SHIMMY DAMPER							Component ATA:32
PN:2310-1500-405	MOS/MSC	02-Apr-14	O/C	TSN 0				
SN:00403	HRS	722.6		TSN 0				
	AFL	663		TSN 0				
PROC. REF: AMM 32-21-06, AMM 32-21-06								
32-41-01	DIGITAL BRAKE CONTROL UNIT							Component ATA:32
PN:90005034-8	MOS/MSC	12-May-23	O/C					
SN:JAN10-1158	HRS	2199						
	AFL	2012						
PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-02	LH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:842660	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02	RH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:843949	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02-001 ^S	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS	13-Mar-18						
SN:842660	HRS	1396.1	6400 (+30/-30)					
	AFL	1246						
PROC. REF: AMM 32-41-02								
							PKG:60	
32-41-02-001 ^S	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS	13-Mar-18						
SN:843949	HRS	1396.1	6400 (+30/-30)					
	AFL	1246						
PROC. REF: AMM 32-41-02								
							PKG:60	
32-41-02-002 ^S	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS	07-May-20						
SN:842660	HRS	1774.1	1600 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 32-41-02								
							PKG:10	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-02-002 ^S FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER								Service ATA:32
PN:Q3008	MOS	07-May-20						
SN:843949	HRS	1774.1	1600 (+30/-30)					
	AFL	1606						
PROC. REF: AMM 32-41-02								PKG:10
32-41-03 MAIN BRAKE SHUT-OFF VALVE								Component ATA:32
PN:90005027	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MAR09-0151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-03								
32-41-04 LH BRAKE CONTROL VALVE								Component ATA:32
PN:90005035-2	MOS/MSC	06-May-11	O/C					
SN:09-10-0423	HRS	221.6						
	AFL	203						
PROC. REF: AMM 32-41-04, AMM 32-41-04								
32-41-04 RH BRAKE CONTROL VALVE								Component ATA:32
PN:90005035-2	MOS/MSC	06-May-11	O/C					
SN:10-06-0532	HRS	221.6						
	AFL	203						
PROC. REF: AMM 32-41-04, AMM 32-41-04								
32-41-05 LH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER								Component ATA:32
PN:90005191-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:OCT08-0123	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05, AMM 32-41-05								
32-41-05 RH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER								Component ATA:32
PN:90005191-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:APR09-0286	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05, AMM 32-41-05								
32-41-06 LEFT MAIN GEAR WHEEL SPEED TRANSDUCER								Component ATA:32
PN:90005036	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MAY09-0344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-06	RIGHT MAIN GEAR WHEEL SPEED TRANSDUCER							Component ATA:32
PN:90005036	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:MAY09-0341	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-11-001 ^S	FUNCTIONAL CHECK OF BRAKE HYDRAULIC ACCUMULATOR							Service ATA:32
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-11								
PKG:50								
32-410	NOSE LANDING GEAR WHEEL AXLE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-411	NOSE LANDING GEAR LOCK PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-412	NOSE LANDING GEAR AXLE BOLT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-413	NOSE LANDING GEAR BOLT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-414	NOSE LANDING GEAR PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-415	NOSE LANDING GEAR BOLT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-43-00-001	FUNCTIONAL CHECK OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 32-43-00								
32-43-01-001	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 32-43-00								
32-43-02	EMERGENCY/PARKING BRAKE VALVE							Component ATA:32
PN:11056-7	MOS/MSC	19-May-22	O/C	TSO 2				
SN:0728	HRS	2055		TSO 0				
	AFL	1874		TSO 0				
PROC. REF: AMM 32-43-02, AMM 32-43-02								
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR							Component ATA:32
PN:0860231003	MOS/MSC	11-May-22	O/C	TSO 8				
SN:60231-2176	HRS	2055		TSN 1198, TSO 0				
	AFL	1874		TSN 1432, TSO 0				
PROC. REF: AMM 32-43-04, AMM 32-43-04								
32-43-05	EMERGENCY/PARKING BRAKE PRESSURE SWITCH							Component ATA:32
PN:15H0126PH	MOS/MSC	23-Apr-22	O/C	TSN 0				
SN:0694	HRS	2046.4		TSN 0				
	AFL	1866		TSN 0				
PROC. REF: AMM 32-43-05, AMM 32-43-05								
32-43-06	EMERGENCY/PARKING BRAKE PRESSURE- TRANSDUCER							Component ATA:32
PN:APT-218A-1000-3000A	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:7539-9-50	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-06, AMM 32-43-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-11	EMERGENCY/PARKING BRAKE SHUT OFF VALVE							Component ATA:32
PN:2216-0001-401	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00165	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-11, AMM 32-43-11								
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE							Service ATA:32
PN:2216-0001-401	MOS	02-Apr-24	12 (+30d/-30d)	Adj -5d	28-Mar-25	27-Apr-25	137 d (+30)	AIRWORTHINESS
SN:00165	HRS	2308.3	800 (+30/-30)		3108.3	3138.3	765.6 (+30)	
	AFL	2118						
PROC. REF: AMM 32-43-11								
32-43-11-002	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE							Service ATA:32
PN:2216-0001-401	MOS/MSC	20-Mar-10	N/A					
SN:00165	HRS	0						
	AFL	0						
PROC. REF: AMM 32-43-11								
32-45-01	LH MLG 21X6.5-10 12PR TIRE							Component ATA:32
PN:215K26-2	MOS/MSC	02-Apr-24	O/C					
SN:22130233	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01	RH MLG 21X6.5-10 12PR TIRE							Component ATA:32
PN:215K26-2	MOS/MSC	02-Apr-24	O/C					
SN:20220222	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01-001	RESTORATION (OVERHAUL) OF LH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	02-Apr-24	T/C					
SN:JUN09-0322	HRS	2308.3						
	AFL	2118	1500 (+30/-30)		3618	3648	1462 (+30)	
PROC. REF: SMR 500-32-0012, AMM 32-45-00								
32-45-01-001	RESTORATION (OVERHAUL) OF RH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	02-Apr-24	T/C					
SN:JUN15-1082	HRS	2308.3						
	AFL	2118	1500 (+30/-30)		3618	3648	1462 (+30)	
PROC. REF: SMR 500-32-0012, AMM 32-45-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC		O/C					
SN:JUN09-0322	HRS							
	AFL							
PROC. REF: AMM 32-45-00								
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	02-Apr-24	O/C					
SN:JUN15-1082	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 32-45-00								
32-45-02	LH MLG 21X6.5-10, AL WHEEL							Component ATA:32
PN:90005024	MOS/MSC	02-Apr-24	O/C	TSR 0				
SN:JUN09-0322	HRS	2308.3		TSR 0				
	AFL	2118		TSO 163, TSR 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-02	RH MLG 21X6.5-10, AL WHEEL							Component ATA:32
PN:90005024	MOS/MSC	02-Apr-24	O/C	TSO 2				
SN:JUN15-1082	HRS	2308.3		TSO 0				
	AFL	2118		TSO 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-03	LH MLG WHEEL ASSEMBLY							Component ATA:32
PN:500-19026-605	MOS/MSC	02-Apr-24	O/C	TSR 0				
SN:JUN09-0322	HRS	2308.3		TSR 0				
	AFL	2118		TSO 163, TSR 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-03	RH MLG WHEEL ASSEMBLY							Component ATA:32
PN:500-19026-605	MOS/MSC	02-Apr-24	O/C	TSO 2				
SN:JUN15-1082	HRS	2308.3		TSO 0				
	AFL	2118		TSO 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-10	NLG 15X6.0-6 10PR TIRE							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	07-May-20	O/C					
SN:UNKNOWN	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 32-45-11, AMM 32-45-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-11	NLG WHEEL ASSEMBLY							Component ATA:32
PN:500-19001-601	MOS/MSC	07-May-20	O/C	TSO 0				
SN:FEB11-0442	HRS	1774.1		TSO 0				
	AFL	1606		TSO 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-11-001	RESTORATION (OVERHAUL) OF NLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19001-601	MOS/MSC	07-May-20	T/C					
SN:FEB11-0442	HRS	1774.1						
	AFL	1606	1500 (+30/-30)		3106	3136	950 (+30)	
PROC. REF: SMR 500-32-0012, AMM 32-45-00								
32-45-11-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19001-601	MOS/MSC	07-May-20	O/C					
SN:FEB11-0442	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 32-45-00								
32-45-12	NLG 15X6.0-6, AL WHEEL							Component ATA:32
PN:90005023-1	MOS/MSC	07-May-20	O/C	TSO 0				
SN:FEB11-0442	HRS	1774.1		TSO 0				
	AFL	1606		TSO 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-21	LH MLG STEEL BRAKE ASSEMBLY							Component ATA:32
PN:90005025-3	MOS/MSC	01-Aug-24	O/C	TSO 1				
SN:APR09-0244	HRS	2330.6		TSO 0				
	AFL	2148		TSO 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21	RH MLG STEEL BRAKE ASSEMBLY							Component ATA:32
PN:90005025-3	MOS/MSC	28-Mar-21	O/C	TSO 2				
SN:S-NOV13-0012	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21-20	LH MLG SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-21-20	RH MLG SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-500	NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	28-Mar-21	O/C					
SN:UNKNOWN	HRS	1870						
	AFL							
PROC. REF: GENERIC NO REF								
32-501	NOSE LANDING GEAR SHOCK ABSORBER PISTON TUBE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-502	NOSE LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-504	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-506	NOSE LANDING GEAR SHOCK ABSORBER FORK							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: GENERIC NO REF								
32-600	NLG DRAG BRACE ASSEMBLY							Component ATA:32
PN:2310-1400-403	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00057	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-21-09, AMM 32-21-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-601	NOSE LANDING GEAR UPPER DRAG BRACE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-603	NOSE LANDING GEAR LOWER DRAG BRACE							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-605	LEFT SIDE NLG DRAG BRACE PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-605	RIGHT SIDE NLG DRAG BRACE PINTLE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-606	NOSE LANDING GEAR DRAG BRACE PIN							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-61-01	LH MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:21418	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:21439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-01	RH MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:21900	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-02	LH MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-02	RH MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-700	NLG LOCKING STAY ASSEMBLY							Component ATA:32
PN:2310-1700-403	MOS/MSC	28-Mar-21	O/C	TSO 0				
SN:00060	HRS	1870		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-701	LOWER NLG LOCKING STAY							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-703	UPPER NLG LOCKING STAY							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-706	LOWER NLG LOCKING STAY BOLT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-04, AMM 32-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-706	UPPER NLG LOCKING STAY BOLT							Component ATA:32
PN:PN	MOS	20-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	35000	TSN 0	35000		32844	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-801	BRAKE SYSTEM ACCUMULATOR							Component ATA:32
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-11, AMM 32-41-11								
Z700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY							Service ATA:32
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-47-00								PKG:84
ATA 33 - LIGHTS								
33-01-01	UPPER COCKPIT LIGHTING SYSTEM CONTROL PANEL							Component ATA:33
PN:441-40941-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0149	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-01-01, AMM 33-01-01								
33-12-01	FORWARD FUSELAGE BOTTOM DIMMER							Component ATA:33
PN:81-01760-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-01, AMM 33-12-01								
33-12-02	MAIN TEST ANUNCIATOR/FIRE PANEL ASSEMBLY							Component ATA:33
PN:441-43213-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0162	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02, AMM 33-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-21-05	PASSENGER-CABIN LED LIGHT DIMMER							Component ATA:33
PN:AS-33-0038-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0190	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-21-05, AMM 33-21-05								
33-31-02	W001 ELECTRICAL NOSE HARNESS							Component ATA:33
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33-41-01	LEFT LANDING/TAXI LIGHT							Component ATA:33
PN:81012-3	MOS/MSC	28-Mar-23	O/C	TSN 0				
SN:001205	HRS	2178.6		TSN 0				
	AFL	1992		TSN 0				
PROC. REF: AMM 33-41-01, AMM 33-41-01								
33-41-01	RIGHT LANDING/TAXI LIGHT							Component ATA:33
PN:81012-4	MOS/MSC	28-Mar-23	O/C	TSN 0				
SN:000582	HRS	2178.6		TSN 0				
	AFL	1992		TSN 0				
PROC. REF: AMM 33-41-01, AMM 33-41-01								
33-43-01	LH WING NAVIGATION/STROBE LIGHTS							Component ATA:33
PN:84016-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:000192	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01, AMM 33-43-01								
33-43-01	RH WING NAVIGATION/STROBE LIGHTS							Component ATA:33
PN:84016-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:000198	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01, AMM 33-43-01								
33-43-01-001	DISCARD LH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-1	MOS	20-Mar-10						
SN:000192	HRS	0	8000 (+30/-30)		8000	8030	5657.3 (+30)	
	AFL	0						
PROC. REF: AMM 33-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-43-01-001	DISCARD RH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-2	MOS	20-Mar-10						
SN:000198	HRS	0	8000 (+30/-30)		8000	8030	5657.3 (+30)	
	AFL	0						
PROC. REF: AMM 33-43-01								
33-43-01-002 ^S	GENERAL VISUAL INSPECTION OF LH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-1	MOS	28-Mar-23						
SN:000192	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 33-43-01								
33-43-01-002 ^S	GENERAL VISUAL INSPECTION OF RH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-2	MOS	28-Mar-23						
SN:000198	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 33-43-01								
ATA 34 - NAVIGATION								
34-11-00-001	FUNCTIONAL CHECK INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT							Service ATA:34
PN:C16786DA01	MOS	02-Apr-24	24 (+1m/-1m)	Adj 21d	23-Apr-26	23-May-26	528 d (+30)	
SN:C16786004856	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-11-00								
34-11-01	INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT							Component ATA:34
PN:C16786DA01	MOS/MSC	06-Dec-18	O/C					
SN:C16786004856	HRS	1521.4						
	AFL	1368						
PROC. REF: AMM 34-11-01, AMM 34-11-01								
34-11-02	PITOT-STATIC PROBE							Component ATA:34
PN:101469-4-003	MOS/MSC	06-May-11	O/C	TSN 0				
SN:865064	HRS	221.6		TSN 0				
	AFL	203		TSN 0				
PROC. REF: AMM 34-11-02, AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-02-001	RESTORATION PITOT-STATIC PROBE (CLEANING)							Service ATA:34
PN:101469-4-003	MOS	02-Apr-24	24 (+1m/-1m)		02-Apr-26	02-May-26	507 d (+30)	
SN:865064	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-11-02								
34-15-00-001	FUNCTIONAL CHECK (CALIBRATION) OF AIR DATA SYSTEM							Service ATA:34
	MOS	02-Apr-24	24 (+1m/-1m)	Adj -32d	01-Mar-26	01-Apr-26	475 d (+31)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-15-00								
34-15-00-002 ^S	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS							Service ATA:34
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 34-15-00								
								PKG:84
34-15-00-003 ^S	SPECIAL DETAILED INSPECTION OF STATIC PORT SURROUNDING PLATE FOR FLUSHNESS							Service ATA:34
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-15-00								
								PKG:81
34-15-01	NO. 1 GDC 74B AIR DATA COMPUTER UNIT							Component ATA:34
PN:011-01110-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:43805786	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-01, AMM 34-15-01								
34-15-01	NO. 2 GDC 74B AIR DATA COMPUTER UNIT							Component ATA:34
PN:011-01110-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:43805821	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-01, AMM 34-15-01								
34-15-03	LH FWD PITOT TUBE							Component ATA:34
PN:0851LW	MOS/MSC	28-Mar-21	O/C	TSN 43				
SN:312746	HRS	1870		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 34-15-03, AMM 34-15-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-03	RH FWD PITOT TUBE							Component ATA:34
PN:0851LW	MOS/MSC	28-Mar-21	O/C	TSN 43				
SN:312745	HRS	1870		TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 34-15-03, AMM 34-15-03								
34-15-03-001 ^S	RESTORATION OF PITOT PROBE (CLEANING)							Service ATA:34
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-15-03								
PKG:81								
34-15-05	LH FWD DUAL STATIC PORT							Component ATA:34
PN:100442-106	MOS/MSC	06-May-11	O/C	TSN 0				
SN:865001	HRS	221.6		TSN 0				
	AFL	203		TSN 0				
PROC. REF: AMM 34-15-05, AMM 34-15-05								
34-15-05	RH FWD DUAL STATIC PORT							Component ATA:34
PN:100442-107	MOS/MSC	06-May-11	O/C	TSN 0				
SN:865001	HRS	221.6		TSN 0				
	AFL	203		TSN 0				
PROC. REF: AMM 34-15-05, AMM 34-15-05								
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER							Service ATA:34
PN:011-00870-00	MOS	23-Apr-22	36 (+1m/-1m)					
SN:47513485	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 34-21-02								
PKG:82								
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER							Service ATA:34
PN:011-00870-00	MOS	23-Apr-22	36 (+1m/-1m)					
SN:47514597	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 34-21-02								
PKG:82								
34-21-01	LH ATTITUDE AND HEADING REFERENCE UNIT							Component ATA:34
PN:011-00868-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:42013189	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-01, AMM 34-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-01	RH ATTITUDE AND HEADING REFERENCE UNIT							Component ATA:34
PN:011-00868-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:42013255	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-01, AMM 34-21-01								
34-21-02	LH WING MAGNETOMETER							Component ATA:34
PN:011-00870-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:47513485	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-02, AMM 34-21-02								
34-21-02	RH WING MAGNETOMETER							Component ATA:34
PN:011-00870-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:47514597	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-02, AMM 34-21-02								
34-23-00-001 ^S	FUNCTIONAL CHECK OF STANDBY COMPASS							Service ATA:34
PN:KCA0120W	MOS	23-Apr-22	36 (+1m/-1m)					
SN:BC9730309	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 34-23-00								PKG:82
34-23-01	MAGNETIC COMPASS							Component ATA:34
PN:KCA0120W	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:BC9730309	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-32-01	TAIL PHASING COUPLER							Component ATA:34
PN:SSPD-113-10	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:6177	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-01, AMM 34-32-01								
34-32-03	LEFT VOR/LOC 2&3 ANTENNA BLADE							Component ATA:34
PN:S65-247170	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:173-2135	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-32-03	RIGHT VOR/LOC 2&3 ANTENNA BLADE							Component ATA:34
PN:S65-247170	MOS/MSC	13-Mar-18	O/C	TSN 0				
SN:173-5322	HRS	1396.1		TSN 0				
	AFL	1246		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-32-04	LW FWR MARKER BEACON ANTENNA							Component ATA:34
PN:S35-1000-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:102-8120	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-04, AMM 34-32-04								
34-42-01	WEATHER RADAR ANTENNA							Component ATA:34
PN:011-00883-20	MOS/MSC	30-Jun-15	O/C					
SN:47203401	HRS	977.8		TSR 0				
	AFL	895		TSR 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-43-00	BAGGAGE COMPARTMENT GTS 850 TRAFFIC PROCESSOR UNIT							Component ATA:34
PN:011-01553-00	MOS/MSC	22-Apr-14	O/C	TSO 0				
SN:1EB005001	HRS	734.1		TSO 0				
	AFL	676		TSO 0				
PROC. REF: GENERIC NO REF								
34-43-02	TRC899 TRANSMITTER RECEIVER COMPUTER							Component ATA:34
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
34-43-05	LOWER DIRECTIONAL ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:124000626	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-05, AMM 34-43-05								
34-43-05	UPPER DIRECTIONAL ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:124000658	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-05, AMM 34-43-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-43-08	LOW NOISE (TCAS) POWER AMPLIFIER							Component ATA:34
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-08, AMM 34-43-08								
34-51-01	NO.1 CENTER DISTANCE MEASURING EQUIP UNIT							Component ATA:34
PN:066-01070-0001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:33401	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-51-01	NO.2 CENTER DISTANCE MEASURING EQUIP UNIT							Component ATA:34
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-51-02	NO. 1 DME L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:261-85366	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02								
34-51-02	NO. 2 DME L BAND ANTENNA							Component ATA:34
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02								
34-52-00-001	FUNCTIONAL CHECK LH TRANSPONDER MODULE TRANSPONDER SYSTEM							Service ATA:34
PN:011-00779-30	MOS	02-Apr-24	24		02-Apr-26		507 d	
SN:89109274	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-52-00								
34-52-00-001	FUNCTIONAL CHECK RH TRANSPONDER MODULE TRANSPONDER SYSTEM							Service ATA:34
PN:011-04224-00	MOS	02-Apr-24	24	Adj -32d	01-Mar-26		475 d	
SN:51Y000542	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 34-52-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-52-01	LH TRANSPONDER MODULE							Component ATA:34
PN:011-00779-30	MOS/MSC	05-Mar-20	O/C					
SN:89109274	HRS	1754.6						
	AFL	1594						
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-01	RH TRANSPONDER MODULE							Component ATA:34
PN:011-04224-00	MOS/MSC	05-Mar-20	O/C	TSN 1				
SN:51Y000542	HRS	1754.6		TSN 0				
	AFL	1594		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-02	BOTTOM TRANSPONDOR 1 L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:261-85375	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-52-02	TOP TRANSPONDOR 2 L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:261-85401	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-52-04	COAXIAL SWITCH							Component ATA:34
PN:D2-729B005	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:555170	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-04, AMM 34-52-04								
34-56-02	LH TOP CENTER GPS WAAS - GA 36 ANTENNA							Component ATA:34
PN:013-00244-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:6252	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02, AMM 34-56-02								
34-56-02	RH TOP CENTER WAAS & SATELLITE WEATHER AND RADAR ANTENNA							Component ATA:34
PN:013-00245-00	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:6834	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02, AMM 34-56-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-57-01	SATELLITE WEATHER AND RADIO RECIEVER							Component ATA:34
PN:011-03177-10	MOS/MSC	07-Feb-20	O/C	TSN 1				
SN:3NV004796	HRS	1734.2		TSN 0				
	AFL	1583		TSN 0				
PROC. REF: AMM 34-57-01, AMM 34-57-01								
34-61-01	FLIGHT MANAGEMENT SYSTEM PANEL							Component ATA:34
PN:011-04475-00	MOS/MSC	07-Feb-20	O/C	TSN 1				
SN:48V000512	HRS	1734.2		TSN 0				
	AFL	1583		TSN 0				
PROC. REF: AMM 34-61-01, AMM 34-61-01								
34FAR02 ^U	FUNCTIONAL CHECK OF AIR DATA SYSTEM (FAR 91.411)							Service ATA:34
	MOS	02-Apr-24	24		02-Apr-26		507 d	FAR
	HRS	2308.3						
	AFL	2118						
34FAR03 ^U	FUNCTIONAL CHECK STATIC PRESSURE (FAR 43 APPENDIX E)							Service ATA:34
	MOS	02-Apr-24	24		02-Apr-26		507 d	FAR
	HRS	2308.3						
	AFL	2118						
34FAR04 ^U	FUNCTIONAL CHECK NO. 1 TRANSPONDER SYSTEM (FAR 91.413)							Service ATA:34
	MOS	02-Apr-24	24		02-Apr-26		507 d	FAR
	HRS	2308.3						
	AFL	2118						
34FAR04 ^U	FUNCTIONAL CHECK NO. 2 TRANSPONDER SYSTEM (FAR 91.413)							Service ATA:34
	MOS	02-Apr-24	24		02-Apr-26		507 d	FAR
	HRS	2308.3						
	AFL	2118						
ATA 35 - OXYGEN								
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	23-Apr-22	36 (+30d/-30d)	Adj -12d	11-Apr-25	11-May-25	151 d (+30)	AIRWORTHINESS
	HRS	2046.4	1800 (+30/-30)		3846.4	3876.4	1503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 35-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-01-00-001 ^S	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION							Service ATA:35
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 35-01-02							PKG:84
35-01-02	OXYGEN CYLINDER PRESSURE AND TEMPERATURE TRANSDUCER							Component ATA:35
PN:4441125-000	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:7528-8-180	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-02, AMM 35-01-02							
35-01-05	OXYGEN SYSTEM LOW PRESSURE SWITCH							Component ATA:35
PN:4421134-000	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0222	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-05, AMM 35-01-05							
35-01-06	LH CSL OXYGEN SYSTEM CONTROL PANEL							Component ATA:35
PN:441-40945-002	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0147	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-06, AMM 35-01-06							
35-01-07	OXYGEN SYSTEM CABIN ALTITUDE SWITCH							Component ATA:35
PN:4421133-000	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0746013	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-07, AMM 35-01-07							
35-01-09	CENTER FUSELAGE ALTITUDE COMPENSATING REGULATOR							Component ATA:35
PN:4421135-000	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00076	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-09, AMM 35-01-09							
35-01-10	OXYGEN LOW PRESSURE 3 POSITION VALVE							Component ATA:35
PN:4421132-109	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00141	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 35-01-10, AMM 35-01-10							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-02-01	50 CU.FT OXYGEN CYLINDER							Component ATA:35
PN:4441122-050	MOS/MSC	12-May-23	O/C	TSN 1				
SN:1153965601	HRS	2199		TSN 0				
	AFL	2012		TSN 0				
PROC. REF: AMM 35-02-01, AMM 35-02-01								
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR							Service ATA:35
PN:4441122-050	MOS	01-Mar-23	60		30-Mar-28 (M)		1235 d	
SN:1153965601	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-01-003	DISCARD 50 CU.FT OXYGEN CYLINDER							Service ATA:35
PN:4441122-050	MOS	12-Apr-23	180		30-Mar-28 (M)		1235 d	
SN:1153965601	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-01-004	RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER							Service ATA:35
	MOS	01-Mar-23	60		30-Mar-28 (M)		1235 d	
	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-05	OXYGEN PRESSURE REGULATOR							Component ATA:35
PN:172421-14	MOS/MSC	12-May-23	O/C	TSN 1				
SN:1153965701	HRS	2199		TSN 0				
	AFL	2012		TSN 0				
PROC. REF: GENERIC NO REF								
35-11-00-001	OPERATIONAL CHECK OF LH CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	02-Apr-24	24 (+1m/-1m)	Adj 21d	23-Apr-26	23-May-26	528 d (+30)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 35-11-02								
35-11-00-001	OPERATIONAL CHECK OF RH CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	02-Apr-24	24 (+1m/-1m)	Adj 21d	23-Apr-26	23-May-26	528 d (+30)	
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-01	LH CREW OXYGEN-MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	30-Oct-20	O/C	TSR 0				
SN:00803	HRS	1824.6		TSR 0				
	AFL	1658		TSR 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-01	RH CREW OXYGEN-MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:00320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-02	LH CREW OXYGEN MASK							Component ATA:35
PN:174232-93	MOS/MSC	02-Apr-24	O/C	TSO 0				
SN:32308	HRS	2308.3		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02								
35-11-02	RH CREW OXYGEN MASK							Component ATA:35
PN:174232-93	MOS/MSC	07-May-20	O/C	TSO 0				
SN:34850	HRS	1774.1		TSO 0				
	AFL	1606		TSO 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF LH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	02-Apr-24	24 (+1m/-1m)		02-Apr-26	02-May-26	507 d (+30)	
SN:32308	HRS	2308.3						
	AFL							
PROC. REF: AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF RH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	02-Apr-24	24 (+1m/-1m)	Adj 21d	23-Apr-26	23-May-26	528 d (+30)	
SN:34850	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 35-11-02								
35-11-02-002	RESTORATION (OVERHAUL) OF LH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	02-Apr-24	72 (+1m/-1m)		02-Apr-30	02-May-30	1968 d (+30)	
SN:32308	HRS	2308.3	3600 (+30/-30)		5908.3	5938.3	3565.6 (+30)	
	AFL							
Restoration Date:: 02-Apr-24			PROC. REF: AMM 35-11-02					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-02-002	RESTORATION (OVERHAUL) OF RH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	01-Aug-19	72 (+1m/-1m)		01-Aug-25	01-Sep-25	263 d (+31)	
SN:34850	HRS	1645	3600 (+30/-30)		5245	5275	2902.3 (+30)	
	AFL							
		Restoration Date:: 01-Aug-19	PROC. REF: AMM 35-11-02					
35-11-04-001 ^S	DETAILED VISUAL INSPECTION OF CREW GOGGLES							Service ATA:35
	MOS	23-Apr-22	36 (+1m/-1m)					
	HRS	2046.4						
	AFL	1866						
			PROC. REF: AMM 35-11-04					
								PKG:82
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE							Service ATA:35
	MOS	23-Apr-22	36 (+30d/-30d)	Adj -12d	11-Apr-25	11-May-25	151 d (+30)	AIRWORTHINESS
	HRS	2046.4	1800 (+30/-30)		3846.4	3876.4	1503.7 (+30)	
	AFL	1866						
			PROC. REF: AMM 35-21-00					
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE							Service ATA:35
	MOS	23-Apr-22	36 (+30d/-30d)	Adj -12d	11-Apr-25	11-May-25	151 d (+30)	AIRWORTHINESS
	HRS	2046.4	1800 (+30/-30)		3846.4	3876.4	1503.7 (+30)	
	AFL	1866						
			PROC. REF: AMM 35-21-00					
35-21-01	PAX 1 OXYGEN MASK							Component ATA:35
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
			PROC. REF: AMM 35-21-01, AMM 35-21-01					
35-21-01	PAX 2 OXYGEN MASK							Component ATA:35
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
			PROC. REF: AMM 35-21-01, AMM 35-21-01					
35-21-01	PAX 3 OXYGEN MASK							Component ATA:35
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
			PROC. REF: AMM 35-21-01, AMM 35-21-01					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-01	PAX 4 OXYGEN MASK							Component ATA:35
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY							Service ATA:35
	MOS	23-Apr-22	36 (+1m/-1m)					
	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 35-21-01								PKG:82
35-21-02	CABIN OXYGEN THREE MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411073-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:4411073-001-00164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-21-02	LH OXYGEN TWO MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411072-001	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:4411072-001-00421	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-21-02	RH OXYGEN TWO MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411072-111	MOS/MSC	11-Apr-19	O/C	TSN 0				
SN:4411072-111-00234	HRS	1560.3		TSN 0				
	AFL	1408		TSN 0				
PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-31-01	PROTECTIVE BREATHING EQUIPMENT (PBE)							Component ATA:35
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-31-01, AMM 35-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-00-001	OPERATIONAL CHECK LH BLEED SHUT-OFF FUNCTION							Service ATA:36
PN:1330310-5	MOS	23-Apr-22						
SN:0169	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 36-11-00								PKG:1
36-11-00-001	OPERATIONAL CHECK RH BLEED SHUT-OFF FUNCTION							Service ATA:36
PN:1330310-5	MOS	23-Apr-22						
SN:0605	HRS	2046.4	800 (+30/-30)		2846.4	2876.4	503.7 (+30)	
	AFL	1866						
PROC. REF: AMM 36-11-00								PKG:1
36-11-01	LH PYLON PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:1330310-5	MOS/MSC	08-Feb-23	O/C					
SN:0169	HRS	2152.6						
	AFL	1973						
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01	RH PYLON PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:1330310-5	MOS/MSC	08-Feb-23	O/C					
SN:0605	HRS	2152.6						
	AFL	1973						
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-02-001	DETAILED INSPECT OF BLEED LINE WATER DRAINS							Service ATA:36
	MOS/MSC	20-Mar-10	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-11-02								
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS							Service ATA:36
	MOS	20-Mar-10						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4057.3 (+30)	
	AFL	0						
PROC. REF: AMM 36-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
24-21-03	DC CONVERTER							Component ATA:44
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-03, AMM 44-21-03								
ATA 52 - DOORS								
52-10-00	OPTIONAL DOOR EQUIPPED STEP ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN PAX DOOR ASSEMBLY STRUCTURE							Service ATA:52
PN:500-09910-445	MOS	07-May-20	60 (+1m/-1m)					
SN:0000533164	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 52-10-00							PKG:84	
52-10-01-002 ^S	INTERNAL GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY STRUCTURE							Service ATA:52
PN:500-09910-445	MOS	07-May-20	60 (+1m/-1m)					
SN:0000533164	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 52-10-00							PKG:90	
52-10-01-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE UPPER EXTERNAL FRAME, UPPER HORIZONTAL STRINGER, EXTERNAL VERTICAL FRAME, AND LOWER HORIZONTAL FRAME.							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 52-10-00								
52-10-01-01-902	EXTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 52-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-02-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR LATCH MECHANISM LATCH PINS.							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 52-10-00								
52-10-20-001 ^S	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY RUBBER SEAL							Service ATA:52
PN:500-09910-445	MOS	02-Apr-24	12 (+1m/-1m)					
SN:0000533164	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 52-10-20								
PKG:80								
52-11-00	MAIN PAX DOOR ASSEMBLY							Component ATA:52
PN:500-09910-445	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000533164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00, AMM 52-10-00								
52-11-00-001 ^S	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY LOCKING AND ACTUATING MECHANISM							Service ATA:52
PN:500-09910-445	MOS	23-Apr-22	48 (+1m/-1m)					
SN:0000533164	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 52-11-00								
PKG:83								
52-11-00-002 ^S	LUBRICATION OF MAIN DOOR LATCH PINS							Service ATA:52
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 52-11-21								
PKG:80								
52-11-01	DOOR KEY LOCK KIT							Component ATA:52
PN:500-38850-901	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:100165-10165	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-13-00	MAIN DOOR BALANCE ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-00, AMM 52-13-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-13-01	MAIN DOOR BALANCE ASSY GEAR SECTOR							Component ATA:52
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-21, AMM 52-13-21								
52-13-02	MAIN DOOR BALANCE ASSY PINION SHAFT							Component ATA:52
PN:PN	MOS/MSC	20-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-23, AMM 52-13-23								
52-13-21-001 ^S	DISCARD GEAR GEAR SECTOR							Service ATA:52
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-21								PKG:60
52-13-22-002 ^S	DISCARD MAIN DOOR BALANCE ASSEMBLY MECHANISM CABLE							Service ATA:52
PN:PN	MOS	23-Apr-22						
SN:UNKNOWN	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 52-13-22								PKG:1
52-13-22-004	DETAILED VISUAL INSPECTION OF MAIN DOOR BALANCING MECHANISM CABLES							Service ATA:52
PN:PN	MOS/MSC	20-Mar-10	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 52-13-22								
52-13-23-001 ^S	DISCARD SHAFT PINION SHAFT							Service ATA:52
PN:PN	MOS	20-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-23								PKG:60
52-20-01-01-901	INTERNAL DETAILED VISUAL INSPECTION EMERGENCY DOOR STRUCTURE SPAR AND FRAMES.							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 52-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-01-01-902	EXTERNAL - DETAILED INSPECTION EMERGENCY DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 52-20-00								
52-20-20-001 ^S	GENERAL VISUAL INSPECTION CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY LOCKING AND ACTUATING MECHANISM							Service ATA:52
PN:500-09700-427	MOS	23-Apr-22	48 (+1m/-1m)					
SN:0000533150	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 52-20-20								PKG:83
52-20-21	CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY							Component ATA:52
PN:500-09700-427	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000533150	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-20-21-001 ^S	GENERAL VISUAL INSPECTION CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY RUBBER SEAL							Service ATA:52
PN:500-09700-427	MOS	02-Apr-24	24 (+1m/-1m)					
SN:0000533150	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 52-20-21								PKG:81
52-31-20-001 ^S	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	23-Apr-22	48 (+1m/-1m)					
	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 52-31-20								PKG:83
52-32-20-001 ^S	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM							Service ATA:52
	MOS	23-Apr-22	48 (+1m/-1m)					
	HRS	2046.4						
	AFL	1866						
PROC. REF: AMM 52-32-20								PKG:83
52-71-20	LOWER DOOR MICRO SWITCH							Component ATA:52
PN:500-38876-401	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000527866	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-71-20	UPPER DOOR MICRO SWITCH							Component ATA:52
PN:500-38876-401	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000527862	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20								
ATA 53 - FUSELAGE								
53-00-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS							Service ATA:53
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
PROC. REF: AMM 53-00-20								PKG:1
53-05-00-001 ^S	DETAILED VISUAL INSPECTION OF FUSELAGE DRAINS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 53-05-00								PKG:84
53-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE LOWER SKIN PANEL AND COCKPIT FLOOR STRUCTURES							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-10-00								PKG:90
53-10-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS, SKIN SPLICES AND WINDSHIELD CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-10-00								PKG:90
53-10-01-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:6300		6300		4144	
PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-01-01-902	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:14000		14000		11844	
PROC. REF: NDT 53-10-00								
53-10-01-01-903	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE SKIN PANEL AND FASTENERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-02-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS FRAMES AND SPLICES.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-02-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-FRAMES AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-02-02-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS STRINGERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-02-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-STRINGERS AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-03-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL FRAMES AND STRINGERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-03-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL SKIN-TO-FRAME/STRINGERS AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-04-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-04-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - SKIN-TO-LONGITUDINAL SPLICE AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-04-02-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-04-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES SKIN-TO-CIRCUMFERENTIAL-SPLICE AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-10-00							PKG:90
53-10-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-10-00							PKG:90
53-10-05-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE PRESSURE BULKHEAD.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-10-00							
53-10-06-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE FORWARD SKIN PANELS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-10-00							PKG:90
53-10-07-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL METALLIC STRUCTURE							Service ATA:53
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
	PROC. REF: NDT 53-10-00							PKG:81
53-10-07-01-901	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE (EDDY CURRENT) TRUNION.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-10-00							
53-10-07-02-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-10-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-07-02-902	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE (EDDY CURRENT) DRAG LOCKING STRUTS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-10-08-002	INTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL COMPOSITE STRUCTURE							Service ATA:53
	MOS/MSC	07-May-20	O/C					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-10-00								
53-10-08-01-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL COMPOSITE STRUCTURE UPPER PANEL AND SIDE SKIN.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-10-00								
53-14-00	NOSE RADOME							Component ATA:53
PN:5190-102-1	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:183	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-14-00, AMM 53-14-00								
53-20-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS AND SKIN SPLICES							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:90
53-20-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS, SKIN SPLICES, AND FLOOR STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-003 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TO-WING LATERAL AND CENTER LINKS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 53-20-00				PKG:90
53-20-01-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) FRAMES.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 53-20-00				
53-20-01-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) SKIN TO FRAMES AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 53-20-00				
53-20-01-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) STRINGERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 53-20-00				
53-20-01-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 53-20-00				
53-20-02-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) FRAMES.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 53-20-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-02-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) SKIN TO FRAMES AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-02-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) STRINGERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-02-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-03-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) CUT-OUT REINFORCEMENT (SKIN DOUBLER).							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-03-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO CUT-OUT AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-03-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) FRAMES AND STRINGERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-03-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO FRAMES AND STRINGERS AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-04-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-04-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-04-02-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE CIRCUNFERENTIAL SKIN SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-04-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICESKIN AT CIRCUMFERENTIAL SKIN SPLICE AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-05-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS SKIN (FROM STRINGER 12L TO 12R).							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-05-01-902	EXTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS (EDDY CURRENT) SPLICE (1ST AND 3RD ROWS) (FROM STRINGER 01R TO 01L, FROM STINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-05-01-903	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS SKIN (FROM STRINGER 01R TO 01L, FROM STRINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-05-01-904	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES END FITTINGS							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-06-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:84
53-20-06-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-06-01-901	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE DOUBLER 1 AT CORNERS OF MAIN DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-20-00							
53-20-06-01-902	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE SKIN AT CORNERS OF THE MAIN DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-20-00							
53-20-06-01-903	EXTERNAL - DETAILED INSPECTION THE MAIN DOOR CUTOUT STRUCTURE SKIN TO DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-20-00							
53-20-06-01-904	INTERNAL GENERAL VISUAL INSPECTION THE MAIN DOOR CUT-OUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-20-00							
53-20-06-01-905	INTERNAL DETAILED INSPECTION MAIN DOOR CUTOUT STRUCTURE MACHINED FRAME AT LATCH PIN BOX AREA .							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-20-00							
53-20-07-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-20-00							PKG:84
53-20-07-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-20-00							PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-07-01-901	INTERNAL GENERAL VISUAL INSPECTION EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-07-01-902	EXTERNAL - DETAILED INSPECTION THE SKIN TO EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-08-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUT-OUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-20-00								PKG:90
53-20-08-01-901	INTERNAL GENERAL VISUAL INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER WINDOW FRAME (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-08-01-902	EXTERNAL - DETAILED INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18) SKIN AT WINDOW AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-10-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-10-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKSMACHINED FRAME (FRAME 14 AND FRAME 18) AND FASTENERS							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-11-01-901	INTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK(EDDY CURRENT) CONNECTION LINK FITTING (LUG AND INNER CAP).							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-11-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK FITTING.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-20-12-01-901	INTERNAL DETAILED INSPECTION AFT PRESSURE BULKHEAD.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-20-00								
53-30-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKINS AND ATTACHMENTS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-30-00								PKG:90
53-30-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER SKIN, JUNCTIONS AND ATTACHMENTS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-30-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN, CUTOUTS AND ATTACHMENTS							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 53-30-00							PKG:90
53-30-01-01-901	INTERNAL DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANELBEDPLATE AND ITS ATTACHMENTS, BEDPLATES TO STRINGER ATTACHMENTS AND SKIN TO BEDPLATE AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-30-00							
53-30-01-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL SKIN TO BEDPLATE AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-30-00							
53-30-02-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL FORWARD MACHINED FRAME (FRAME 22 AND FRAME 23)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-30-00							
53-30-02-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL SKIN TO FRAME AREA							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-30-00							
53-30-02-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL AFT MACHINED FRAME (FRAME 25 AND FR25A)							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 53-30-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-02-02-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL - SKIN TO FRAME AREA							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-04-01-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES AFT FUSELAGE SKIN TO LONGITUDINAL SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-04-01-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES LONGITUDINAL SPLICE							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-04-02-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES TO CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-04-02-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES TO CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-05-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-30-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-05-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-05-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUTSTRUCTUREAFT FUSELAGE THE SKIN TO BAGGAGE DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-06-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE CUTOUT STRUCTURES -INTERNALFRAMES, STRINGER, REINFORCEMENT, AND DOUBLER OF AFT FUSELAGE CUTOUT STRUCTURES.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-07-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER FRAMES 29 TO 32							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-30-00								PKG:84
53-30-07-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) MACHINED FRAMES.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-07-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) SKIN TO FRAME AREA.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-07-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) BEDPLATES AND FASTENERS.							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 53-30-00								
53-30-08-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE MACHINED FRAME 32							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 53-30-00								
ETD-2015-P100-00470698	U	TEMPORARY REPAIR #2 AND #4 CABLE GUARDS ON RH SIDE BENEATH CABIN FLOORBOARD 231ELF						Service ATA:53
	MOS/MSC	03-Apr-17	-					
	HRS	1259						
	AFL	1134						
Z210-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-41-00								
Z210-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-41-00								
Z220-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-41-00								
Z220-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-41-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Z230-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-42-00							PKG:87
Z230-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-42-00							PKG:87
Z240-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-42-00							PKG:87
Z240-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service ATA:53
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-42-00							PKG:84
Z310-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-43-00							PKG:87
Z310-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-43-00							PKG:87
Z320-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION							Service ATA:53
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: AMM 05-43-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
Z320-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION							Service	ATA:53
	MOS	07-May-20	120 (+1m/-1m)						
	HRS	1774.1							
	AFL	1606							
PROC. REF: AMM 05-43-00							PKG:87		
ATA 54 - NACELLES/PYLONS									
54-00-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS							Service	ATA:54
	MOS	23-Apr-22							
	HRS	2046.4	800 (+30/-30)						
	AFL	1866							
PROC. REF: AMM 54-51-20							PKG:1		
54-50-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF PYLON MAIN BOX							Service	ATA:54
	MOS	07-May-20	60 (+1m/-1m)						
	HRS	1774.1							
	AFL	1606							
PROC. REF: NDT 54-50-00							PKG:90		
54-50-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD BEAM							Service	ATA:54
	MOS	07-May-20	60 (+1m/-1m)						
	HRS	1774.1							
	AFL	1606							
PROC. REF: NDT 54-50-00							PKG:90		
54-50-01-01-901	INTERNAL DETAILED INSPECTION PYLON FORWARD BEAM PYLON SPARS 1 AND 2, UPPER AND LOWER SKIN AND FASTENERS.							Service	ATA:54
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T:17500		17500		15344		
PROC. REF: NDT 54-50-00									
54-50-02-01-901	INTERNAL DETAILED INSPECTION PYLON AFT BEAMPYLON SPARS 3 AND 4 AND FASTENERS.							Service	ATA:54
	MOS							AIRWORTHINESS	
	HRS								
	AFL		T:17500		17500		15344		
PROC. REF: NDT 54-50-00									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-03-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF PYLON MAIN BOX							Service ATA:54
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 54-50-00				PKG:90
54-50-03-01-901	EXTERNAL GENERAL VISUAL INSPECTION OF PYLON MAIN BOX MAIN BOX SKIN AND FASTENERS.							Service ATA:54
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 54-50-00				
54-50-04-01-901	INTERNAL DETAILED INSPECTION PYLON-TO-FUSELAGE CONNECTIONS OF BOLTS.							Service ATA:54
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 54-50-00				
54-50-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES							Service ATA:54
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 54-50-00				PKG:84
54-50-05-01-901	INTERNAL DETAILED INSPECTION PYLON YOKESLUG HOLES AT YOKES, YOKES, GUSSETS AND SHIELD.							Service ATA:54
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 54-50-00				
54-50-06-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT MOUNT FITTINGS							Service ATA:54
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 54-50-00				PKG:84
54-50-06-01-901	INTERNAL DETAILED INSPECTION PYLON AFT FITTINGAFT MOUNT FITTING AND FASTENERS.							Service ATA:54
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 54-50-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
Z410-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON							Service ATA:54
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 05-46-00				PKG:87
Z410-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service ATA:54
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 05-46-00				PKG:87
Z430-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE							Service ATA:54
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 05-46-00				PKG:87
Z430-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service ATA:54
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: AMM 05-46-00				PKG:87
ATA 55 - STABILIZERS								
55-00-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF STABILIZER POLYURETHANE FILMS							Service ATA:55
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
				PROC. REF: AMM 55-00-20				PKG:1
55-10-00	HORIZONTAL STABILIZER							Component ATA:55
PN:500-10700-409	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000532454	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-001 ^S	EXTERNAL - DETAILED INSPECTION OF HORIZONTAL-STABILIZER SPARS							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 55-10-00				PKG:87
55-10-00-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER MAIN BOX							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 55-10-00				PKG:84
55-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL-TO-HORIZONTAL STABILIZER ATTACHMENTS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 55-10-00				PKG:84
55-10-01-01-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 55-10-00				
55-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR (BORESCOPIK) FRONT SPAR AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 55-10-00				
55-10-02-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR FRONT SPAR AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 55-10-00				
55-10-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR(BORESCOPIK) REAR SPAR.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 55-10-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-03-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR					REAR SPAR AND FASTENERS.		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN					(BORESCOPIC) STRINGERS.		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-04-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN FASTENERS.					UPPER SKIN AND		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-05-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN - LOWER SKIN.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-05-01-902	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN HORIZONTAL STABILIZER LINK AREA AND STRINGERS, INCLUDING FASTENERS.					LOWER SKIN AT FIN TO		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-06-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER COMPOSITE RIBS AND FASTENERS.					(BORESCOPIC) COMPOSITE RIBS		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-07-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER TIP RIBS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-10-00							PKG:90
55-10-07-01-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER METALLIC RIBS INCLUDING FASTENERS.				ROOT AND TIP METALLIC RIBS,			Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-10-00							
55-10-08-001 ^S	EXTERNAL - DETAILED INSPECTION ON HORIZONTAL STABILIZER ROOT RIBS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-10-00							PKG:90
55-10-08-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE HORIZONTAL STABILIZER LEADING EDGE SKIN AND SPAR.				(BORESCOPIC)			Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-10-00							
55-10-08-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE EDGE SKIN AND FASTENERS.				HORIZONTAL STABILIZER LEADING			Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-10-00							
55-10-09-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL STABILIZER LEADING EDGE							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-10-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-09-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING HINGE FITTINGS, AND FASTENERS.						Service	ATA:55
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-09-02-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING (EDDY CURRENT) LUGS.						Service	ATA:55
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-09-03-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING TORQUE BOX AND FASTENERS.						Service	ATA:55
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-10-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL-STABILIZER HINGE FITTINGS						Service	ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 55-10-00								PKG:90
55-10-10-01-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TAB SUPPORTING FITTING AND FASTENERS.					TRIM	Service	ATA:55
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								
55-10-10-02-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TAB LINK SUPPORT FITTING AND FASTENERS.					TRIM	Service	ATA:55
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-11-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF TRIM-TAB SUPPORT FITTINGS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
			PROC. REF: NDT 55-10-00					PKG:84
55-20-00-001 ^S	EXTERNAL - DETAILED INSPECTION OF ELEVATOR FITTINGS AND TORQUE-TUBE ATTACHMENTS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
			PROC. REF: NDT 55-20-00					PKG:84
55-20-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
			PROC. REF: NDT 55-20-00					PKG:87
55-20-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) SKIN, SPARS, RIBS AND FASTENERS.					(BORESCOPIC)	Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 55-20-00					
55-20-01-01-902	EXTERNAL - DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE AND HORN.					SKIN AND FASTENERS,	Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 55-20-00					
55-20-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS					(DYE PENETRANT) ELEVATOR HINGE PINS.	Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 55-20-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS (EDDY CURRENT) ELEVATOR HINGE FITTINGS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-20-00							
55-20-02-02-902	INTERNAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS ELEVATOR HINGE FITTINGS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-20-00							
55-20-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (EDDY CURRENT) ELEVATOR TORQUE TUBE FLANGE.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-20-00							
55-20-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (DYE PENETRANT) ELEVATOR TORQUE TUBE.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-20-00							
55-22-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TAB PIANO HINGE							Service ATA:55
	MOS/MSC	07-May-20	O/C					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-22-00							
55-22-02-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR TAB BOX							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-22-00							PKG:90
55-30-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER TO AFT FUSELAGE CONNECTIONS AT VERTICAL STABILIZER							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-30-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-REAR FUSELAGE CONNECTIONS AT VERTICAL STABILIZER							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-30-00							PKG:84
55-30-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER FITTING, PINS AND SPARS ATTACHMENTS (UPPER PART OF CONNECTIONS).					(BORESCOPIC)		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-01-01-902	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER SPAR ATTACHMENTS (LOWER PART OF CONNECTIONS), NUT, SEAL AND FASTENERS.					FITTING, PINS AND		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-01-02-901	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER L SHAPE, RIB AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-02-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-30-00							PKG:84
55-30-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) DOUBLER AND TIP RIB.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-02-01-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (EDDY CURRENT) DOUBLER AND TIP RIB AT FRONT AND REAR FITTING AREA.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-30-02-02-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER L SHAPE AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-30-02-02-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) L SHAPE AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-30-02-03-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER FITTINGS AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-30-02-04-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER COMPOSITE PLATES AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-30-03-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL STABILIZER MAIN BOX							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 55-30-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-03-01-901	EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) SKIN AND SPAR.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-03-01-902	INTERNAL SPECIAL DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) (BORESCOPIC) SPAR.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER FITTING							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-30-00							
	PKG:84							
55-30-05-01-901	EXTERNAL - DETAILED INSPECTION RUDDER HINGE FITTINGS HINGE FITTING 1 AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-05-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (EDDY CURRENT) HINGE FITTING 2 FLANGES.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-05-03-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (EDDY CURRENT) RUDDER LUG HINGE FITTINGS 1 AND 2.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-30-00							
55-30-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB ACTUATOR FITTING AND SUPPORT FITTINGS							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-30-00							
	PKG:90							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-06-01-901	EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER TAB ACTUATOR AND SUPPORT FITTINGS FITTINGS, LUGS AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-30-00								
55-33-00	VERTICAL STABILIZER							Component ATA:55
PN:500-10100-417	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0000534274	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
55-40-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF RUDDER ASSEMBLY							Service ATA:55
	MOS/MSC	07-May-20	O/C					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 55-40-00								
55-40-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER ASSEMBLY							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 55-40-00								
PKG:87								
55-40-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER MAIN BOX (BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-40-00								
55-40-01-01-902	EXTERNAL - DETAILED INSPECTION RUDDER MAIN BOX MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS.							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-02-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF RUDDER HINGE FITTINGS							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-40-00							PKG:87
55-40-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS				(DYE PENETRANT) RUDDER HINGE FITTINGS PINS.		Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-40-00							
55-40-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS				(EDDY CURRENT) RUDDER HINGE FITTINGS.		Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-40-00							
55-40-02-02-902	INTERNAL DETAILED INSPECTION RUDDER HINGE FITTINGS				RUDDER HINGE FITTINGS.		Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-40-00							
55-40-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE-TUBE ASSEMBLY							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
	PROC. REF: NDT 55-40-00							PKG:87
55-40-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY				(EDDY CURRENT) RUDDER TORQUE		Service ATA:55	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 55-40-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY TUBE.					(DYE PENETRANT) RUDDER TORQUE		Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 55-40-00								
55-41-00	RUDDER ASSEMBLY							Component ATA:55
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
55-42-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB PIANO HINGE							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 55-42-00								
								PKG:90
Z330-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-44-00								
								PKG:84
Z330-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-44-00								
								PKG:87
Z340-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-44-00								
								PKG:84
Z340-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-44-00								
								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF COCKPIT SIDE-WINDOWS PANE (BOTH SIDES)							Service ATA:56
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 56-10-00								PKG:84
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS							Service ATA:56
PN:NP-195302-4	MOS	15-Jan-17						
SN:09215H7327	HRS	1223.4	1600 (+30/-30)		2823.4	2853.4	480.7 (+30)	
	AFL	1099						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS							Service ATA:56
PN:NP-195301-2	MOS	15-Jan-17						
SN:08305H7779	HRS	1223.4	1600 (+30/-30)		2823.4	2853.4	480.7 (+30)	
	AFL	1099						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW ATTACHING BOLTS							Service ATA:56
PN:NP-195302-3	MOS	15-Jan-17						
SN:09231H8990	HRS	1223.4	1600 (+30/-30)		2823.4	2853.4	480.7 (+30)	
	AFL	1099						
PROC. REF: AMM 56-10-00								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS							Service ATA:56
PN:NP-195301-5	MOS	07-May-20						
SN:19189H8135	HRS	1774.1	T:800 (+30/-30)		2574.1	2604.1	231.4 (+30)	
	AFL	1606						
PROC. REF: AMM 56-10-00								
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WINDSHIELD AND COCKPIT SIDE WINDOW FRAMES AND FASTENERS							Service ATA:56
	MOS	02-Apr-24	24 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: NDT 56-10-00								PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-03-01-901	EXTERNAL SPECIAL DETAILED INSPECTION WINDSHIELD FRAME AND FASTENERS					(EDDY CURRENT) FRAMES AND		Service ATA:56
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 56-10-00								
56-11-00	COPILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP-195301-2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:08305H7779	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-11-00	PILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP-195301-5	MOS/MSC	07-May-20	O/C	TSN 0				
SN:19189H8135	HRS	1774.1		TSN 0				
	AFL	1606		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-12-00	COPILOT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-4	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:09215H7327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-12-00	PILOT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-3	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:09231H8990	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-20-00	LEFT NO.1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01576	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	LEFT NO.2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01580	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-00	LEFT NO.3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01582	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	LEFT NO.4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01586	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01581	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01585	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	09-Mar-16	O/C					
SN:079874	HRS	1086.3						
	AFL	977						
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF PASSENGER CABIN WINDOWS							Service ATA:56
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 56-20-00								
								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF WING POLYURETHANE FILMS							Service ATA:57
	MOS	23-Apr-22						
	HRS	2046.4	800 (+30/-30)					
	AFL	1866						
				PROC. REF: AMM 57-30-20				PKG:1
57-10-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-FUSELAGE LINKS							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 57-10-00				PKG:90
57-10-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 57-10-00				PKG:90
57-10-00-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MIDDLE AND REAR SPARS							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
				PROC. REF: NDT 57-10-00				PKG:84
57-10-01-01-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE SEAL.					FRONT FITTING, BOLT, NUT AND		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 57-10-00				
57-10-01-02-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE SEAL.					REAR FITTING, BOLT, NUT AND		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
				PROC. REF: NDT 57-10-00				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CENTER FITTING AND LUG.					(EDDY CURRENT) WING		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-02-01-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE					WING CENTER FITTING.		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CENTER LINK LUGS.					(EDDY CURRENT)		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-02-02-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE NUT AND SEAL.					CENTER LINK FITTING, BOLT,		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-02-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE HORIZONTAL LINK BOLTS.					(MAGNETIC PARTICLE)		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-03-01-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.				FRONT SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW			Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-03-02-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.			FRONT SPAR LOWER CAP BETWEEN RIB 3 AND 6 AND WINDOW			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-03-03-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR			LOWER SKIN BETWEEN RIB 6 AND 7, INCLUDING FASTENER.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-03-04-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.			FRONT SPAR LOWER CAP BETWEEN RIB 7 AND 10 AND WINDOW			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-03-05-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR			LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-01-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR FASTENERS.			MIDDLE SPAR LOWER CAP BETWEEN RIB 1 AND 3, INCLUDING			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-02-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR FASTENERS .			MIDDLE SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-04-03-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR SPAR-STRINGER-SPLICE AND FASTENERS.		MIDDLE SPAR LOWER CAP BETWEEN RIB 7 AND 9, INCLUDING					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-04-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR AND RADIUS).		(EDDY CURRENT) MLG FRONT TRUNNION (LUG, SURFACE					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-04-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR		MLG FRONT TRUNNION AND FASTENERS.					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-05-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR RADIUS).		(EDDY CURRENT) MLG ACTUATOR FITTING (SURFACE AND					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-04-05-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR		MLG ACTUATOR FITTING AND FASTENERS.					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-05-01-901	INTERNAL DETAILED INSPECTION WING REAR SPAR FRAME.		REAR SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW ACCESS					Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-05-02-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR FASTENERS.			REAR SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING				Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-05-03-901	INTERNAL DETAILED INSPECTION WING REAR SPAR FASTENERS.			REAR SPAR LOWER CAP BETWEEN RIB 7 AND 10, INCLUDING				Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-05-04-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR			LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS.				Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-05-05-901	EXTERNAL SPECIAL DETAILED INSPECTION WING REAR SPAR AND MACHINED RADIUS).			(EDDY CURRENT) MLG REAR TRUNNION (LUG, SURFACE				Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-05-05-902	EXTERNAL - DETAILED INSPECTION WING REAR SPAR			MLG REAR TRUNNION AND FASTENERS.				Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL						Service ATA:57	
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-10-00								
PKG:87								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-07-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
			PROC. REF: NDT 57-10-00					PKG:84
57-10-07-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
			PROC. REF: NDT 57-10-00					PKG:90
57-10-07-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL STRINGER 5 AND SHEAR CLIPS FASTENERS.			STRINGER 2 AND 3 BETWEEN RIB 1 AND 3 AND SHEAR CLIPS OF			Service ATA:57	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-07-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL WINDOW ACCESS PANEL 9 FRAMES.			STRINGER 2 RUN-OUT, STRINGER SHEAR CLIPS AT RIB 8 AND			Service ATA:57	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-07-03-901	EXTERNAL - DETAILED INSPECTION WING LOWER PANEL INCLUDING DOU-BLER AND ITS FASTENERS.			LOWER PANEL AND FASTENERS BETWEEN RIB 2 AND RIB 10,			Service ATA:57	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					
57-10-08-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL 8R).			MACHINED RIBS (RIB 1, RIB 3, RIB 3A, RIB 5R, RIB 6R, RIB 7R, RIB			Service ATA:57	
	MOS						AIRWORTHINESS	
	HRS							
	AFL		T:17500		17500		15344	
			PROC. REF: NDT 57-10-00					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-08-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL 8F, RIB 9, RIB 10, RIB11, RIB 12, RIB 13, RIB 14, RIB 15 AND RIB 16).			WING FORMED RIBS (RIB 2, RIB 4F, RIB 5F, RIB 6F, RIB 7F, RIB			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-08-03-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL			DRY BAY WALLS AND FASTENERS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-10-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE						Service	ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-10-00								
							PKG:90	
57-10-10-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF WING CENTER SPLICE						Service	ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-10-00								
							PKG:90	
57-10-10-003 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTRAL SPLICE						Service	ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-10-00								
							PKG:90	
57-10-10-01-901	EXTERNAL - DETAILED INSPECTION WING CENTRAL SPLICES INCLUDING FASTENERS.			FRONT SPAR SPLICE, LOWER SKIN SPLICES, REAR SPAR SPLICES,			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-10-01-902	INTERNAL DETAILED INSPECTION WING CENTRAL SPLICES WING LOWER SKIN ON SPLICE AREA, BETWEEN RIB1 AND RIB 2, FRONT , REAR AND MIDDLE SPAR ON SPLICE AREA AND MIDDLE SPAR SPLICE, INCLUDING FASTENERS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-10-00								
57-10-11-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON TAB ACTUATOR SUPPORT FITTINGS AND TAB HINGE FITTINGS							Service ATA:57
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-10-00								PKG:87
57-50-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE INBOARD AND OUTBOARD TORQUE BOXES							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-50-00								PKG:84
57-50-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (EDDY CURRENT) WING ROOT TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-01-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS WING ROOT TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-01-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (DYE PENETRANT) WING ROOT ROLLER.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:8875		8875		6719	
PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-01-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (EDDY CURRENT) RIB 1.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-01-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS RIB 1 AND FASTENERS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS WING CENTER TRACK.					(EDDY CURRENT)		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-02-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS					WING CENTER TRACK.		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS WING CENTER TRACK SUPPORT.					(EDDY CURRENT)		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-02-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS SUPPORT.					WING CENTER TRACK		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-02-03-901	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS ATTACHMENTS, PIN AND FASTENERS).					FITTINGS (LUG,		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) WING TIP TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-03-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS WING TIP TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (DYE PENETRANT) WING TIP ROLLER.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:8875		8875		6719	
PROC. REF: NDT 57-50-00								
57-50-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) RIBS 13 AND 13A WEB AND FLANGE.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-03-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS RIBS 13 AND 13A.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-03-04-901	EXTERNAL - DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS TORQUE BOX SKIN AND FASTENERS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE AILERON HINGE FITTING							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-50-00								
								PKG:84
57-50-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 01.					(EDDY		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-04-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 02 .					(EDDY		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-04-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS FITTING 02.					AILERON HINGE		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-50-04-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 03.					(EDDY		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-04-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS					AILERON HINGE		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-50-00								
57-51-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP ASSEMBLY							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-51-00								
PKG:90								
57-51-01-01-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS			FLAP UPPER SKIN FROM RIB 7 TO RIB 9.			Service ATA:57	
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-02-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE FLAP MAIN BOX							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-51-00								
PKG:90								
57-51-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS			(BORESCOPIC) FLAP FRONT SPAR BETWEEN RIB 5A AND RIB			Service ATA:57	
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:7049		7049		4893	
PROC. REF: NDT 57-51-00								
57-51-02-03-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS			FLAP LOWER SKIN FROM RIB 1 TO RIB 5A AND FROM RIB 5B TO			Service ATA:57	
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-02-04-901	EXTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS AND FROM RIB 5B TO RIB 6 AT FRONT SPAR AREA.			(EDDY CURRENT) FLAP LOWER SKIN FROM RIB 4 TO RIB 5A			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-02-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS ROLLERS FITTING TO RIB 5A AND RIB 5B			(BORESCOPIC) AROUND FASTENERS THAT CONNECT CENTER			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-02-06-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS			(EDDY CURRENT) FRONT SPAR FROM RIB 5A TO RIB 5B.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-02-07-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS			(EDDY CURRENT) RIB 1 AND RIB 10.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP TRACK FITTINGS AND ACTUATOR FITTING						Service	ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-51-00								PKG:84
57-51-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP ROOT TRACK.						Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-03-01-902	INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP ROOT TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							
57-51-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP TIP TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							
57-51-03-02-902	INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP TIP TRACK.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							
57-51-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) FLAP ROOT AND TIP ROLLERS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							
57-51-03-04-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) CENTER ROLLERS EXTERNAL PINS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							
57-51-03-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) CENTER ROLLERS FITTING AROUND FASTENERS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
	PROC. REF: NDT 57-51-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-04-01-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING					FLAP ACTUATOR SUPPORT PIN.		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-51-04-02-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING AND FASTENERS.					FLAP ACTUATOR SUPPORT FITTING		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-51-00								
57-60-00	LH AILERON ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
57-60-00	RH AILERON ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
57-60-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON ASSEMBLY AND AILERON TAB BOX							Service ATA:57
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-60-00								
57-60-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON MAIN BOX							Service ATA:57
	MOS	07-May-20	120 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON MAIN BOX			(BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-01-01-902	EXTERNAL - DETAILED INSPECTION AILERON MAIN BOX			SKIN, SPARS, RIBS AND FASTENERS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS			(DYE PENETRANT) AILERON HINGE FITTINGS PINS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS			(EDDY CURRENT) AILERON HINGE FITTINGS (LUGS, STIFFENERS RADIUS).			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-02-02-902	INTERNAL DETAILED INSPECTION AILERON HINGE FITTINGS			AILERON HINGE FITTINGS.			Service	ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-03-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF AILERON ACTUATOR FITTING, HINGE FITTINGS AND PINS						Service	ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-60-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS PINS.					(DYE PENETRANT)		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN ACTUATOR HINGE FITTINGS (LUGS, STIFFEN-ERS RADIUS).					(EDDY CURRENT) AILERON		Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-60-03-02-902	INTERNAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS.							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:17500		17500		15344	
PROC. REF: NDT 57-60-00								
57-63-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF AILERON TAB ASSEMBLY							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: NDT 57-63-00								
								PKG:90
Z500-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-45-00								
								PKG:84
Z500-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:57
	MOS	07-May-20	60 (+1m/-1m)					
	HRS	1774.1						
	AFL	1606						
PROC. REF: AMM 05-45-00								
								PKG:84
ATA 71 - POWER PLANT								
71-00-00-760-812	NO. 1 ENGINE - PERFORM PW617F-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-812	NO. 2 ENGINE - PERFORM PW617F-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-812-A	NO. 1 ENGINE - PERFORM PW617F1-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-812-A	NO. 2 ENGINE - PERFORM PW617F1-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-813	NO. 1 ENGINE - PERFORM PW617F-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	02-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-813	NO. 2 ENGINE - PERFORM PW617F-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	14-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-813-A	NO. 1 ENGINE - PERFORM PW617F1-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	02-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-813-A	NO. 2 ENGINE - PERFORM PW617F1-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	14-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-11-00-001 ^S	GENERAL VISUAL INSPECTION OF UPPER MID COWL							Service ATA:71
	MOS	20-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-11-00								
								PKG:50
71-20-00-001	DISCARD LEFT ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA2	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0475	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0871	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0879	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD RIGHT ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA2	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0448	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-001	DISCARD RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0880	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	20-Mar-10	240 (+1m/-1m)		20-Mar-30	20-Apr-30	1955 d (+31)	
SN:LK0790	HRS	0	4800 (+30/-30)		4800	4830	2457.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00								
71-21-01	LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0871	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0879	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0880	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0790	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.							Service ATA:71
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:5000		5000		2844	
PROC. REF: NDT 71-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-21-01-01-902	INTERNAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY ENGINE BOLT AND SLEEVE BOLT.							Service ATA:71
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:5000		5000		2844	
PROC. REF: NDT 71-21-00								
71-22-01	LEFT ENGINE AFT MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0475	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-22-01	RIGHT ENGINE AFT MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:LK0448	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-22-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.							Service ATA:71
	MOS							AIRWORTHINESS
	HRS							
	AFL		T:5000		5000		2844	
PROC. REF: NDT 71-22-00								
71-22-01-01-902	INTERNAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLYPYLON BOLTS, ENGINE BOLTS AND SLEEVE BOLTS.							Service ATA:71
	MOS	23-Nov-19						AIRWORTHINESS
	HRS	1710						
	AFL	1560	1500		3060		904	
PROC. REF: NDT 71-22-00								
71-31-00-001 ^S	DETAILED VISUAL INSPECTION OF PYLON FIREWALL SEAL							Service ATA:71
	MOS	28-Mar-23						
	HRS	2178.6	2400 (+30/-30)					
	AFL	1992						
PROC. REF: AMM 71-31-00								PKG:20
71-50-00	LH ENG W403 HARNESS							Component ATA:71
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-50-00, AMM 71-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-50-00	RH ENG W404 HARNESS							Component ATA:71
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-50-00, AMM 71-50-00								
71-60-01	LH ENG NACELLE AIR INLET ASSEMBLY							Component ATA:71
PN:500-36000-407	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								
71-60-01	RH ENG NACELLE AIR INLET ASSEMBLY							Component ATA:71
PN:500-36000-407	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:01313	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								
710010	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS/MSC	02-Apr-24	A/R					
	HRS	2308.3						
	ENC							
PROC. REF: LMM 71-00-00, LMM 71-00-00								
710010	NO. 2 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS/MSC	02-Apr-24	A/R					
	HRS	2308.3						
	ENC							
PROC. REF: LMM 71-00-00, LMM 71-00-00								
710011	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	25-Sep-17	A/R					
	HRS	1346.1						
	ENC	1017						
PROC. REF: LMM 71-00-00								
710011	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	25-Sep-17	A/R					
	HRS	1346.1						
	ENC	1017						
PROC. REF: LMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:35C3100-01	MOS/MSC	26-Jan-10	E/C					
SN:PCE-LC0277	HRS	0						
WC#: 71.EN1	AFL	0						
PROC. REF: AMM 71-00-00, AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:35C3100-01	MOS/MSC	26-Jan-10	E/C					
SN:PCE-LC0288	HRS	0						
WC#: 71.EN2	AFL	0						
PROC. REF: AMM 71-00-00, AMM 71-00-00								
ATA 72 - ENGINE								
72-00-00-001 ^S	VISUAL CHECK OF ENGINE MAINTENANCE PAGE FOR ENGINE DISPATCH AND EXCEEDANCE INFORMATION							Service ATA:72
	MOS	02-Apr-24	12 (+1m/-1m)					
	HRS	2308.3						
	AFL	2118						
PROC. REF: AMM 72-00-00								PKG:80
72-00-00-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-802 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-802 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-803 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-804 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-804 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-805 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1
72-00-00-212-805 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 72-00-00				PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-806 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-806 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-801 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-801 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-802	NO. 1 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY							Service ATA:72
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:2
72-00-00-215-802	NO. 2 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY							Service ATA:72
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-215-803	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA							Service ATA:72
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:2
72-00-00-215-803	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA							Service ATA:72
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 72-00-00								PKG:2
72-00-00-280-802	NO. 1 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS							Service ATA:72
	MOS/MSC	02-Apr-24	A/R					
	HRS	2308.3						
	ENC							
PROC. REF: LMM 72-00-00								
72-00-00-280-802	NO. 2 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS							Service ATA:72
	MOS/MSC	02-Apr-24	A/R					
	HRS	2308.3						
	ENC							
PROC. REF: LMM 72-00-00								
72-00-00-290-804	NO. 1 ENGINE - PERFORM BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-290-804	NO. 2 ENGINE - PERFORM BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-290-815	NO. 1 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: LMM 72-00-00								
72-00-00-290-815	NO. 2 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 4 DAYS							Service ATA:72
	MOS/MSC		-					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED IN A HANGAR)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED OUTSIDE)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 4 DAYS							Service ATA:72
	MOS/MSC		-					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED IN A HANGAR)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED OUTSIDE)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-805	NO. 1 ENGINE - ENGINE UNPRESERVED - ENGINE INACTIVE ON-WING 1 - 28 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-805	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-805	NO. 2 ENGINE - ENGINE UNPRESERVED - ENGINE INACTIVE ON-WING 1 - 28 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-805	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-806	NO. 1 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 - 90 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-806	NO. 1 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-806	NO. 2 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 - 90 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-620-806	NO. 2 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
	PROC. REF: LMM 72-00-00							
72-00-00-640-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
	PROC. REF: LMM 72-00-00							PKG:1
72-00-00-640-803 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
	PROC. REF: LMM 72-00-00							PKG:1
72-00-01-810-822	NO. 1 ENGINE - TROUBLESHOOT ENGINE PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 72-00-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-01-810-822	NO. 2 ENGINE - TROUBLESHOOT ENGINE PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-01								
72-00-02-810-801	NO. 1 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM							Service ATA:72
	MOS/MSC	28-Mar-21	O/C					
	HRS	1870						
	ENC							
PROC. REF: LMM 72-00-02								
72-00-02-810-801	NO. 2 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM							Service ATA:72
	MOS/MSC	28-Mar-21	O/C					
	HRS	1870						
	ENC							
PROC. REF: LMM 72-00-02								
72-30-04-000-803	NO. 1 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	23-Dec-19		TSN 0				LIFE LIMIT
SN:RXA418F9	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-30-04-000-803	NO. 2 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	23-Dec-19		TSN 0				LIFE LIMIT
SN:RXA419F1	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-30-04-000-804	NO. 1 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	23-Dec-19		TSN 0				LIFE LIMIT
SN:RXA420F9	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-04-000-804	NO. 2 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	23-Dec-19		TSN 0				LIFE LIMIT
SN:RXA420F4	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-50-02-000-801	NO. 1 ENGINE - DISCARD HP TURBINE RETAINING RING							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 1 ENGINE - DISCARD HP TURBINE RETAINING RING BOLTS							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473 (M)	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 2 ENGINE - DISCARD HP TURBINE RETAINING RING							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 2 ENGINE - DISCARD HP TURBINE RETAINING RING BOLTS							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473 (M)	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-60-01-000-805	NO. 1 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER							Component ATA:72
PN:PN-UNKNOWN	MOS	23-Dec-19		TSN 0				DISCARD
SN:UNKNOWN	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: LMM 72-60-01, LMM 72-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-01-000-805	NO. 2 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER							Component ATA:72
PN:PN-UNKNOWN	MOS	23-Dec-19		TSN 0				DISCARD
SN:UNKNOWN	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: LMM 72-60-01, LMM 72-60-01								
720000	NO. 1 ENGINE - PERFORM ENGINE OVERHAUL							Service ATA:72
	MOS	02-Dec-09						OVERHAUL
	HRS	0	3500 (+100)		(3500) 3500	3600	1157.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720000	NO. 2 ENGINE - PERFORM ENGINE OVERHAUL							Service ATA:72
	MOS	14-Dec-09						OVERHAUL
	HRS	0	3500 (+100)		(3500) 3500	3600	1157.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720001	NO. 1 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-00-00, LMM 72-00-00								
720001	NO. 2 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION							Service ATA:72
	MOS	23-Dec-19						
	HRS	1723	1750 (+50)		(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: MM 72-00-00, LMM 72-00-00								
720003	NO. 1 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	02-Apr-24	24 (+1m)		02-Apr-26	02-May-26	507 d (+30)	
	HRS	2308.3						
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720003	NO. 2 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	02-Apr-24	24 (+1m)		02-Apr-26	02-May-26	507 d (+30)	
	HRS	2308.3						
	ENC							
PROC. REF: GENERIC NO REF								
720010	NO. 1 ENGINE - FAN ROTOR							Component ATA:72
PN:35C3881-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:AATPWACR027	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
720010	NO. 2 ENGINE - FAN ROTOR							Component ATA:72
PN:35C3881-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:AATPWACS022	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
720030 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FOR EVIDENCE OF OIL LEAKS							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: GENERIC NO REF								PKG:1
720030 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FOR EVIDENCE OF OIL LEAKS							Service ATA:72
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: GENERIC NO REF								PKG:1
721010	NO. 1 ENGINE - HP TURBINE DISK							Component ATA:72
PN:35C3091-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:CRAZADQG033	HRS	0		TSN 0				
	ENC	0		TSN 0	(5250) 5332 (M)		3176	
	ACCCYC	0	5250	TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721010	NO. 2 ENGINE - HP TURBINE DISK							Component ATA:72
PN:35C3091-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:CRAZADQG025	HRS	0		TSN 0				
	ENC	0		TSN 0	(5250) 5332 (M)		3176	
	ACCCYC	0	5250	TSN 0				
PROC. REF: GENERIC NO REF								
721015	NO. 1 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
721015	NO. 2 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
721020	NO. 1 ENGINE - LP TURBINE DISK							Component ATA:72
PN:35C5392-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:CRAZADLZ107	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
721020	NO. 2 ENGINE - LP TURBINE DISK							Component ATA:72
PN:35C5392-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:CRAZADOZ329	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
721025	NO. 1 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721025	NO. 2 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723010	NO. 1 ENGINE - IMPELLER AND SHAFT ASSEMBLY							Component ATA:72
PN:35C4716-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:AAPPIAPC2094	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
723010	NO. 2 ENGINE - IMPELLER AND SHAFT ASSEMBLY							Component ATA:72
PN:35C4716-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:AAPPIAPC2092	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
723015	NO. 1 ENGINE - LP COMPRESSOR SHAFT							Component ATA:72
PN:35C4620-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:KWA5195206	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
723015	NO. 2 ENGINE - LP COMPRESSOR SHAFT							Component ATA:72
PN:35C4620-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:KWA5190809	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723020	NO. 1 ENGINE - TOWERSHAFT ANNULAR BALL BEARING							Component ATA:72
PN:35C2168-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN216699	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723020	NO. 2 ENGINE - TOWERSHAFT ANNULAR BALL BEARING							Component ATA:72
PN:35C2168-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN216734	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723025	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:35C4832-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN308112	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723025	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:35C4832-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN308156	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723030	NO. 1 ENGINE - LP SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:35C5051-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN305600	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723030	NO. 2 ENGINE - LP SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:35C5051-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN305581	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723035	NO. 1 ENGINE - LP SHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C4831-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN308381	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723035	NO. 2 ENGINE - LP SHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C4831-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN310383	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723040	NO. 1 ENGINE - TOWERSHAFT ROLLER BEARING							Component ATA:72
PN:3107496-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN308775	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - TOWERSHAFT ROLLER BEARING							Component ATA:72
PN:3107496-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN310080	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723045	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING							Component ATA:72
PN:35C4534-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN308835	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723045	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING							Component ATA:72
PN:35C4534-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN309598	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:35C5325-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:NYAB00005325	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-02, LMM 72-30-02								
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:35C5325-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:NYAB00005378	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-02, LMM 72-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723055	NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY							Component ATA:72
PN:35C4935-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:RWA69C663	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723055	NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY							Component ATA:72
PN:35C4935-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:RWA71C588	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723060	NO. 1 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY							Component ATA:72
PN:35C4860-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:RWA70C981	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723060	NO. 2 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY							Component ATA:72
PN:35C4860-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:RWA70C983	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723065	NO. 1 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C5334-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:PKAAA282400	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723065	NO. 2 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C5334-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:PKAAA282403	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723070	NO. 1 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C3627-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:PKAAA290296	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723070	NO. 2 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C3627-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:PKAAA281751	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723075	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR							Component ATA:72
PN:35C3628-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:PKAAA290279	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723075	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR							Component ATA:72
PN:35C3628-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:PKAAA296385	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723080	NO. 1 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY							Component ATA:72
PN:35C4714-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:AAPPIAPC2094	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723080	NO. 2 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY							Component ATA:72
PN:35C4714-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:AAPPIAPC2092	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723085	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C5326-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:EYA19262	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723085	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C5326-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:EYA19270	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723090	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C4623-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:EYA19634	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723090	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C4623-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:EYA19555	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723095	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component ATA:72
PN:35C5330-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:PKAAA299100	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723095	NO. 2 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component ATA:72
PN:35C5330-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:PKAAA300480	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723110	NO. 1 ENGINE - HOUSING IMPELLER ASSEMBLY							Component ATA:72
PN:35C5211-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:RWA70C231	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723110	NO. 2 ENGINE - HOUSING IMPELLER ASSEMBLY							Component ATA:72
PN:35C5211-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:RWA72C212	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724010	NO. 1 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5050-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:A002N9BY	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724010	NO. 2 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5050-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:A002NB8H	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724015	NO. 1 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5053-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:A002N9C0	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724015	NO. 2 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5053-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:A002NB8M	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - HP COMPRESSOR ROTOR							Component ATA:72
PN:35C4781-01	MOS	02-Dec-09		TSN 0				LIFE LIMIT
SN:AATPWACQ064	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - HP COMPRESSOR ROTOR							Component ATA:72
PN:35C4781-01	MOS	14-Dec-09		TSN 0				LIFE LIMIT
SN:AATPWACQ104	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10582 (M)		8426	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REF								
725015	NO. 1 ENGINE - BALL ROLLER ANNULAR BEARING							Component ATA:72
PN:35C0590-02	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN308930	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725015	NO. 2 ENGINE - BALL ROLLER ANNULAR BEARING							Component ATA:72
PN:35C0590-02	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN308941	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY							Component ATA:72
PN:35C4726-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:RWA71C546	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725020	NO. 2 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY							Component ATA:72
PN:35C4726-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:RWA73C242	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725025	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:35C4755-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:DYA344570	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725025	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:35C5563-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:DYA346052	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - NO. 5 SEAL BEARING RUNNER							Component ATA:72
PN:35C4886-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:EYA19395	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 2 ENGINE - NO. 5 SEAL BEARING RUNNER							Component ATA:72
PN:35C4886-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:EYA19516	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725035	NO. 1 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT							Component ATA:72
PN:35C5798-01	MOS/MSC	23-Dec-19	O/C	TSN 0				
SN:AA22868	HRS	1723		TSN 0				
	ENC	1309		TSN 0				
PROC. REF: GENERIC NO REF								
725035	NO. 2 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT							Component ATA:72
PN:35C5798-01	MOS/MSC	23-Dec-19	O/C	TSN 0				
SN:AA22896	HRS	1723		TSN 0				
	ENC	1309		TSN 0				
PROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4971CL01	MOS/MSC	23-Dec-19	O/C					
SN:PDAHPE5B01	HRS	1723						
	ENC	1309						
PROC. REF: GENERIC NO REF								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4971CL01	MOS/MSC	23-Dec-19	O/C					
SN:PDAH1NPB01	HRS	1723						
	ENC	1309						
PROC. REF: GENERIC NO REF								
725045	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4622CL01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HLA062AA530	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725045	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4622CL01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HLA062AA572	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5655	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7041	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7056	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7058	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7061	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7062	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7064	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7071	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7084	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7086	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7087	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5659	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7089	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7099	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7100	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7101	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7108	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7115	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7117	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7127	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7170	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7176	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5673	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7181	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7197	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7198	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7214	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7218	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7221	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7228	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7234	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7246	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7255	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5682	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7261	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7269	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7271	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0901	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0909	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0911	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0914	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0923	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0935	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0936	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5683	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWDA0938	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5685	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY5691	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7033	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:HWCY7040	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7276	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7319	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7326	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7327	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7331	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7336	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7338	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7346	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7356	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7380	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7384	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7281	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY9596	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY9598	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY9601	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1007	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1008	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1021	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1023	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1025	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1026	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1115	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7282	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1125	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1133	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1141	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA1148	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2807	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2809	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2812	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2818	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2821	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2822	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7286	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2824	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2825	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2827	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2833	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2834	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2836	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA2843	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA3095	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA3107	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA3108	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7294	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWDA3115	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7300	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7307	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7308	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:HWCY7314	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 1 ENGINE - FLANGED ROLLER BEARING							Component ATA:72
PN:3107449-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN291926	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 2 ENGINE - FLANGED ROLLER BEARING							Component ATA:72
PN:3107449-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN291908	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726015	NO. 1 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C3615-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FCN307560	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726015	NO. 2 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C3615-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FCN306929	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726020	NO. 1 ENGINE - ACCESSORY DRIVE GEAR SHAFT							Component ATA:72
PN:35C5333-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:PKAAA279703	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726020	NO. 2 ENGINE - ACCESSORY DRIVE GEAR SHAFT							Component ATA:72
PN:35C5333-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:PKAAA282382	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726025	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY							Component ATA:72
PN:35C5141-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:RWA64C368	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726025	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY							Component ATA:72
PN:35C5141-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:RWA69C406	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 1 ENGINE - BYPASS DUCT ASSEMBLY							Component ATA:72
PN:35C5332-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:FDA6101865	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 2 ENGINE - BYPASS DUCT ASSEMBLY							Component ATA:72
PN:35C5332-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:FDA6189444	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-04-000-801	NO. 1 ENGINE - FUEL MANIFOLD							Component ATA:73
PN:35C6429-01	MOS	23-Dec-19		TSN 0				
SN:DEAAB26287	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC			TSN 0				
PROC. REF: GENERIC NO REF								
73-10-04-000-801	NO. 2 ENGINE - FUEL MANIFOLD							Component ATA:73
PN:35C6429-01	MOS	23-Dec-19		TSN 0				
SN:DEAAB26286	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-05-000-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	02-Apr-24						
	HRS	2308.3	800 (+10%)		(3108.3) 3108.3	3188.3	765.6 (+80)	
	ENC							
PROC. REF: LMM 73-10-05, LMM 73-10-05								PKG:2
73-10-05-000-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	02-Apr-24						
	HRS	2308.3	800 (+10%)		(3108.3) 3108.3	3188.3	765.6 (+80)	
	ENC							
PROC. REF: LMM 73-10-05, LMM 73-10-05								PKG:2
73-10-05-220-801	NO. 1 ENGINE - DETAILED INSPECT THE FUEL FILTER							Service ATA:73
	MOS	02-Apr-24	12 (+30d)		02-Apr-25	02-May-25	142 d (+30)	
	HRS	2308.3						
	ENC							
PROC. REF: LMM 73-10-05								
73-10-05-220-801	NO. 2 ENGINE - DETAILED INSPECT THE FUEL FILTER							Service ATA:73
	MOS	02-Apr-24	12 (+30d)		02-Apr-25	02-May-25	142 d (+30)	
	HRS	2308.3						
	ENC							
PROC. REF: LMM 73-10-05								
73-10-07-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-10-07								PKG:1
73-10-07-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-10-07								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 73-20-02				PKG:1
73-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
				PROC. REF: LMM 73-20-02				PKG:1
73-21-01	LH ENG FULL AUTHORITY DIGITAL FADEC							Component ATA:73
PN:1009211-1-004	MOS/MSC	26-Jul-11	O/C					
SN:2009120013	HRS	260.3						
	AFL	235						
				PROC. REF: AMM 73-21-01, AMM 73-21-01				
73-21-01	RH ENG FULL AUTHORITY DIGITAL FADEC							Component ATA:73
PN:1009211-3-005	MOS/MSC	19-Mar-14	O/C					
SN:2011020015	HRS	722.6						
	AFL	663						
				PROC. REF: AMM 73-21-01, AMM 73-21-01				
73-21-02	NO.1 W205 FADEC CH B FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				
73-21-02	NO.2 W205 FADEC CH B FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				
73-21-03	NO.1 W203 FADEC CH A FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-21-03	NO.2 W203 FADEC CH A FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
73-21-09	NO.1 W307 FADEC CH B HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
73-21-09	NO.2 W307 FADEC CH B HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
73-21-10	NO.1 W305 FADEC CH A HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
73-21-10	NO.2 W305 FADEC CH A HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
73-30-02-212-801 ^S	NO. 1 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-30-02								PKG:1
73-30-02-212-801 ^S	NO. 2 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-30-02								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-02-215-801 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-30-02								PKG:1
73-30-02-215-801 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR							Service ATA:73
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 73-30-02								PKG:1
73-33-01	LH ENG FUEL FLOW METER							Component ATA:73
PN:8TJ300AAF2	MOS/MSC	23-Oct-12	O/C	TSR 0				
SN:21410	HRS	481.9		TSR 0				
	AFL	449		TSR 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								
73-33-01	RH ENG FUEL FLOW METER							Component ATA:73
PN:8TJ300AAF2	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:22849	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								
731002	NO. 1 ENGINE - FUEL TO OIL HEAT EXCHANGER							Component ATA:73
PN:35C4540-02	MOS/MSC	30-Jan-10	O/C					
SN:WA38110	HRS	0						
	ENC	0						
PROC. REF: LMM 73-10-02, LMM 73-10-02								
731002	NO. 2 ENGINE - FUEL TO OIL HEAT EXCHANGER							Component ATA:73
PN:35C4540-03	MOS	14-Dec-09		TSN 0				OVERHAUL
SN:WA38140	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	1157.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 73-10-02, LMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732101	NO. 1 ENGINE - FUEL METERING UNIT							Component ATA:73
PN:1009000-4	MOS	26-Jul-11		TSN 0, TSR 0				OVERHAUL
SN:F69269	HRS	260.3	3500 (+100)	TSN 0, TSR 0	(3760.3) 3760.3	3860.3	1417.6 (+100)	
	ENC	235		TSN 0, TSR 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01								
732101	NO. 2 ENGINE - FUEL METERING UNIT							Component ATA:73
PN:1009000-4	MOS	26-Jul-11		TSN 0, TSR 0				OVERHAUL
SN:F68778	HRS	260.3	3500 (+100)	TSN 0, TSR 0	(3760.3) 3760.3	3860.3	1417.6 (+100)	
	ENC	235		TSN 0, TSR 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01								
732108	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732108	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732110	NO. 1 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILED INSPECTION							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
732110	NO. 2 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILED INSPECTION							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732244	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL							Component ATA:73
PN:1009211-1-004	MOS/MSC	26-Jul-11	O/C					
SN:2009120013	HRS	260.3						
	ENC	235						
PROC. REF: LMM 73-20-03, LMM 73-20-03								
732244	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL							Component ATA:73
PN:1009211-1-004	MOS/MSC	26-Jul-11	O/C					
SN:2008090040	HRS	260.3						
	ENC	235						
PROC. REF: LMM 73-20-03, LMM 73-20-03								
733002	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR							Component ATA:73
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-30-02, LMM 73-30-02								
733002	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR							Component ATA:73
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-30-02, LMM 73-30-02								
733010	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR							Component ATA:73
PN:35C5593-01	MOS/MSC	06-May-11	O/C	TSN 0				
SN:WDA114300	HRS	221.6		TSN 0				
	ENC	203		TSN 0				
PROC. REF: GENERIC NO REF								
733010	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR							Component ATA:73
PN:35C5593-01	MOS/MSC	06-May-11	O/C	TSN 0				
SN:WDA114306	HRS	221.6		TSN 0				
	ENC	203		TSN 0				
PROC. REF: GENERIC NO REF								
733020	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-01, LMM 73-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733020	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-01, LMM 73-30-01								
733030	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-02, LMM 73-30-02								
733030	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-02, LMM 73-30-02								
ATA 74 - IGNITION								
74-00-01-720-801 ^S	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-00-01								PKG:1
74-00-01-720-801 ^S	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-00-01								PKG:1
74-10-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-10-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-10-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-10-01								PKG:1
74-20-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-20-01								PKG:1
74-20-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-20-01								PKG:1
74-20-02-220-801 ^S	NO. 1 ENGINE - INSPECT THE IGNITION IGNITERS							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:1
74-20-02-220-801 ^S	NO. 2 ENGINE - INSPECT THE IGNITION IGNITERS							Service ATA:74
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:1
741001	NO. 1 ENGINE - IGNITION EXCITER							Component ATA:74
PN:35C5472-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:WAD109657	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-10-01, LMM 74-10-01								
741001	NO. 2 ENGINE - IGNITION EXCITER							Component ATA:74
PN:35C5472-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:WDA109858	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-10-01, LMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741002	NO. 1 ENGINE - LEFT IGNITER CABLE							Component ATA:74
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741002	NO. 2 ENGINE - LEFT IGNITER CABLE							Component ATA:74
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741003	NO. 1 ENGINE - RIGHT IGNITER CABLE							Component ATA:74
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741003	NO. 2 ENGINE - RIGHT IGNITER CABLE							Component ATA:74
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741004	NO. 1 ENGINE - INBOARD SPARK IGNITER							Component ATA:74
PN:PN-UNKNOWN	MOS/MSC	15-Jan-17	O/C	TSN 0				
SN:UNKNOWN	HRS	1223.4		TSN 0				
	ENC			TSN 0				
PROC. REF: LMM 74-20-02								
741004	NO. 2 ENGINE - INBOARD SPARK IGNITER							Component ATA:74
PN:PN-UNKNOWN	MOS/MSC	15-Jan-17	O/C	TSN 0				
SN:UNKNOWN	HRS	1223.4		TSN 0				
	ENC	937		TSN 0				
PROC. REF: LMM 74-20-02								
741005	NO. 1 ENGINE - OUTBOARD SPARK IGNITER							Component ATA:74
PN:PN-UNKNOWN	MOS/MSC	15-Jan-17	O/C	TSN 0				
SN:UNKNOWN	HRS	1223.4		TSN 0				
	ENC			TSN 0				
PROC. REF: LMM 74-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741005	NO. 2 ENGINE - OUTBOARD SPARK IGNITER							Component ATA:74
PN:PN-UNKNOWN	MOS/MSC	15-Jan-17	O/C	TSN 0				
SN:UNKNOWN	HRS	1223.4		TSN 0				
	ENC	937		TSN 0				
PROC. REF: LMM 74-20-02								
741010	NO. 1 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-10-01								
741010	NO. 2 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-10-01								
741020	NO. 1 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741020	NO. 2 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01								
741030	NO. 1 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741030	NO. 2 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA							Service ATA:75
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 75-30-01								PKG:1
75-30-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA							Service ATA:75
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 75-30-01								PKG:1
75-30-01-830-801 ^S	NO. 1 ENGINE - RIGGING THE BLEED VALVE ACTUATOR (BVA)							Service ATA:75
PN:35C2851-02	MOS/MSC	02-Dec-09	A/R					
SN:16735207	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01								
75-30-01-830-801 ^S	NO. 2 ENGINE - RIGGING THE BLEED VALVE ACTUATOR (BVA)							Service ATA:75
PN:35C2851-02	MOS/MSC	14-Dec-09	A/R					
SN:16709521	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01								
751003	NO. 1 ENGINE - BLEED VALVE ACTUATOR							Component ATA:75
PN:35C2851-02	MOS	02-Dec-09		TSN 0				OVERHAUL
SN:16735207	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	1157.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 75-30-01, LMM 75-30-01								
751003	NO. 2 ENGINE - BLEED VALVE ACTUATOR							Component ATA:75
PN:35C2851-02	MOS	14-Dec-09		TSN 0				OVERHAUL
SN:16709521	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	1157.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 75-30-01, LMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY							Component ATA:76
PN:6990010-11	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:1167	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
761020 ^U	THROTTLE QUADRANT ACRYLIC LIGHT PANEL							Component ATA:76
PN:441-41343-004	MOS/MSC	20-Jul-23	O/C					
SN:1425	HRS	2219.3						
	AFL	2032						
ATA 77 - ENGINE INDICATING								
77-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 77-20-02								PKG:1
77-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 77-20-02								PKG:1
77-20-02-215-801	NO. 1 ENGINE - ELECTRICAL FUNCTIONAL CHECK OF THE T6 THERMOCOUPLE SYSTEM (ON AIRCRAFT)							Service ATA:77
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02								
77-20-02-215-801	NO. 2 ENGINE - ELECTRICAL FUNCTIONAL CHECK OF THE T6 THERMOCOUPLE SYSTEM (ON AIRCRAFT)							Service ATA:77
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-02-710-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	23-Apr-22	36 (+30d)		23-Apr-25	23-May-25	163 d (+30)	
	HRS	2046.4	1750 (+50)		(3796.4) 3796.4	3846.4	1453.7 (+50)	
	ENC							
PROC. REF: LMM 77-20-02								
77-20-02-710-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	23-Apr-22	36 (+30d)		23-Apr-25	23-May-25	163 d (+30)	
	HRS	2046.4	1750 (+50)		(3796.4) 3796.4	3846.4	1453.7 (+50)	
	ENC							
PROC. REF: LMM 77-20-02								
77-20-02-750-801	NO. 1 ENGINE - FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS ASSEMBLY (REMOVED)							Service ATA:77
	MOS/MSC	02-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02								
77-20-02-750-801	NO. 2 ENGINE - FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS ASSEMBLY (REMOVED)							Service ATA:77
	MOS/MSC	14-Dec-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02								
772002	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY							Component ATA:77
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-20-02, LMM 77-20-02								
772002	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY							Component ATA:77
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-20-02, LMM 77-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772010	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 77-20-02, LMM 77-20-02								
772010	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 77-20-02, LMM 77-20-02								
772103	NO. 1 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:35C5571-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:DP09-1578	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
772103	NO. 2 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:35C5571-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:DP09-1582	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
772110	NO. 1 ENGINE - DO A DCU INTEGRITY VERIFACTION							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 77-40-01, LMM 77-40-01								
772110	NO. 2 ENGINE - DO A DCU INTEGRITY VERIFACTION							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 77-40-01, LMM 77-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-00-00-640-803	NO. 1 ENGINE - OIL CHANGE INTERVAL							Service ATA:79
	MOS/MSC	02-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00								
79-00-00-640-803	NO. 2 ENGINE - OIL CHANGE INTERVAL							Service ATA:79
	MOS/MSC	14-Dec-09	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00								
79-20-01-000-801	NO. 1 ENGINE - DISCARD OIL FILTER							Service ATA:79
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 79-20-01, LMM 79-20-01								PKG:2
79-20-01-000-801	NO. 2 ENGINE - DISCARD OIL FILTER							Service ATA:79
	MOS	28-Mar-21						
	HRS	1870	800 (+10%)		(2670) 2670	2750	327.3 (+80)	
	ENC							
PROC. REF: LMM 79-20-01, LMM 79-20-01								PKG:2
79-20-03-000-805-A	NO. 1 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE							Component ATA:79
PN:PN	MOS	23-Dec-19						LIFE LIMIT
SN:UNKNOWN	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03								
79-20-03-000-805-A	NO. 2 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE							Component ATA:79
PN:PN	MOS	23-Dec-19						LIFE LIMIT
SN:UNKNOWN	HRS	1723	1750 (+50)	TSN 0	(3473) 3473	3523	1130.3 (+50)	
	ENC	1309						
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-01-720-801 ^S	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: GENERIC NO REF								PKG:1
79-30-01-720-801 ^S	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: GENERIC NO REF								PKG:1
79-30-02-210-802 ^S	NO. 1 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 79-30-02								PKG:1
79-30-02-210-802 ^S	NO. 2 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 79-30-02								PKG:1
79-30-02-215-801 ^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 79-30-02								PKG:1
79-30-02-215-801 ^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR							Service ATA:79
	MOS	02-Apr-24	12 (+30d)					
	HRS	2308.3	800 (+10%)					
	ENC							
PROC. REF: LMM 79-30-02								PKG:1
79-31-01	LH ENG OIL TEMPERATURE PRESSURE SENSOR							Component ATA:79
PN:PT9903-275-40012	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0809-2503	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-01, AMM 79-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-31-01	RH ENG OIL TEMPERATURE PRESSURE SENSOR							Component ATA:79
PN:PT9903-275-40012	MOS/MSC	20-Mar-10	O/C	TSN 0				
SN:0809-2511	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-01, AMM 79-31-01								
792007	NO. 1 ENGINE - AIR COOLED OIL COOLER							Component ATA:79
PN:35C2495-05	MOS	02-Dec-09		TSN 0				OVERHAUL
SN:WA37901	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	1157.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07								
792007	NO. 2 ENGINE - AIR COOLED OIL COOLER							Component ATA:79
PN:35C2495-05	MOS	14-Dec-09		TSN 0				OVERHAUL
SN:WA37929	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	1157.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07								
792010	NO. 1 ENGINE - P3 AIR COOLER ASSEMBLY							Component ATA:79
PN:35C5545-01	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:TYAB1706	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - P3 AIR COOLER ASSEMBLY							Component ATA:79
PN:35C5545-01	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:TYAB1722	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793001	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01, LMM 79-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793001	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01, LMM 79-30-01								
793002	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	02-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-02, LMM 79-30-02								
793002	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	14-Dec-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-02, LMM 79-30-02								
793010	NO. 1 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-01, LMM 79-30-01								
793010	NO. 2 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-01, LMM 79-30-01								
793020	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-02, LMM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000129 RegNo: N43EP HRS: 2342.7 AFL: 2156 As Of: 25-Sep-2024

11-Nov-2024 11:03 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793020	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	1157.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-02, LMM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task