



Status Report

PC-12/47E

S/N 1006 N801PB

OWNER: MOUNTAIN LION AVIATION,
LLC

ADDRESS: 11260 DONNER PASS ROAD, SUITE
C1
TRUCKEE CA 96161

OFFICE: 530-655-1100

FAX:

OPERATOR: MOUNTAIN LION AVIATION,
LLC

ADDRESS: 11260 DONNER PASS ROAD, SUITE
C1
TRUCKEE CA 96161

OFFICE: 530-655-1100

FAX:

ANALYST: JOSE BRITO

EMAIL: JBRITO@CAMPSYSTEMS.COM

1-631-619-4578 (DIRECT)

+1-631-588-3200 (MAIN)

WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)

631-980-4222 (FAX)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 1006/N801PB	MODEL: PC-12/47E	MANUFACTURER: PILATUS AIRCRAFT LTDX
-----------------	----------------------------------	-------------------------	--

CERTIFICATION DATE: 31-MAR-2008

LAST ACTUALS:

2910.3 A/C HRS as of 19-NOV-2024

2217 AFL as of 19-NOV-2024

925.2 ACH as of 21-NOV-2023

ENGINE NO. 1	SERIAL/PART: PCE-RY0004/3072955-01	MODEL: PT6A-67P	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	---	------------------------	---

INSTALLED ON: 31-MAR-2008

0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:

2910.3 ENG. HRS as of 19-NOV-2024

2217 ENC as of 19-NOV-2024

PROPELLER NO. 1	SERIAL/PART: KX561/HC-E4A-3D	MODEL: HC-E4A-3	MANUFACTURER: HARTZELL PROPELLER LLC
------------------------	-------------------------------------	------------------------	---

INSTALLED ON: 27-MAY-2014

739.7 PROP HRS 739.7 A/C HRS
0 PRC

LAST ACTUALS:

2960.2 PROP HRS as of 19-NOV-2024



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
00-00/121 ^S	AIRCRAFT - AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED							Service ATA:00
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:15 ,16,17,18,19,20,21
00-00/122 ^S	AIRCRAFT - CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH							Service ATA:00
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:15 ,16,17,18,19,20,21
00-00/481 ^S	AIRCRAFT-CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION							Service ATA:00
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:15 ,16,17,18,19,20,21
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E072							
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E072							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E072							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E072							
E072-230410	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 57.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E072							
P019-210201	NO. 1 PROPELLER - REVIEW PROPELLER ICE PROTECTION SYSTEM MANUAL 180 REV. 35							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P019							
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22							Service ATA:00
	MOS/MSC	31-Mar-08	-					REQUIREMENT CHANGE FORMS
	HRS	0						
	AFL	0						
	PROC. REF: RCF P47E							
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-201125	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 24							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
P47E-210716	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 25							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-220520	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 28							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-220829	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 29							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							
P47E-230116	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 30							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF P47E							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 04 - LIMITATIONS								
040001	AIRCRAFT LIMIT OF VALIDITY							Component ATA:04
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	50000	TSN 0	50000		47089.7	
	AFL	0	60000	TSN 0	60000		57783	
PROC. REF: GENERIC NO REF								
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY							Component ATA:04
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	35000	TSN 0	35000		32089.7	
	AFL	0	43000	TSN 0	43000		40783	
PROC. REF: GENERIC NO REF								
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY							Component ATA:04
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	35000	TSN 0	35000		32089.7	
	AFL	0	43000	TSN 0	43000		40783	
PROC. REF: GENERIC NO REF								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)							Service ATA:05
	MOS	31-Mar-08						
	HRS	0	25000		25000		22089.7	
	AFL	0	30000		30000		27783	
PROC. REF: AMM 12-B-05-10-30-00A-280A-A								
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION							Service ATA:05
	MOS	31-Mar-08						
	HRS	0	25000		25000		22089.7	
	AFL	0	30000		30000		27783	
PROC. REF: AMM 12-B-20-40-00-00A-901A-A, AMM 12-B-20-40-00-00A-040A-A								
05200A	JOB SET UP / CLOSE UP PACKAGE							Package ATA:05
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-05-20-00-00A-913A-A								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05401A	300 HOUR INSPECTION							Package ATA:05
	MOS	15-Nov-24						
	HRS	2910.1	300 (+30/-30)		3210.1	3240.1	299.8 (+30)	
	AFL	2216						
PROC. REF: AMM 12-B-05-40-01-01A-000B-A							PKG:16	
05402A	300 HOUR OR 12 MONTHS INSPECTION							Package ATA:05
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1	300 (+30/-30)		3210.1	3240.1	299.8 (+30)	
	AFL	2216						
PROC. REF: AMM 12-B-05-40-01-02A-000B-A							PKG:17	
05403A	600 HOUR INSPECTION							Package ATA:05
	MOS	21-Nov-23						
	HRS	2764.6	600 (+60/-60)		3364.6	3424.6	454.3 (+60)	
	AFL	2083						
PROC. REF: AMM 12-B-05-40-01-03A-000B-A							PKG:18	
05404A	600 HOUR OR 12 MONTHS INSPECTION							Package ATA:05
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1	600 (+60/-60)		3510.1	3570.1	599.8 (+60)	
	AFL	2216						
PROC. REF: AMM 12-B-05-40-01-04A-000B-A							PKG:19	
05405A	1200 HOUR OR 12 MONTH INSPECTION							Package ATA:05
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1	1200 (+120/-120)		4110.1	4230.1	1199.8 (+120)	
	AFL	2216						
PROC. REF: AMM 12-B-05-40-01-05A-000B-A							PKG:20	
05406A	2400 HOUR OR 24 MONTHS INSPECTION							Package ATA:05
	MOS	21-Nov-23	24 (+1m/-1m)		30-Nov-25	31-Dec-25	374 d (+31)	
	HRS	2764.6	2400 (+60/-60)		5164.6	5224.6	2254.3 (+60)	
	AFL	2083						
PROC. REF: AMM 12-B-05-40-01-06A-000B-A							PKG:21	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057010	NO. 1 ENGINE - MINOR INSPECTION							Package ATA:05
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)		(3210.1) 3210.1	3240.1	299.8 (+30)	
	ENC	2216						
PROC. REF: EMM 72-00-00, EMM 72-00-00								
ATA 06 - DIMENSIONS AND AREAS								
06-00/578 ^S	ACCESS PANEL, WING: 51LB, 51JB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A								PKG:20
06-00/579 ^S	ACCESS PANEL, WING: 51LB, 51JB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A								PKG:20
06-00/582 ^S	ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A								PKG:19
06-00/583 ^S	ACCESS PANEL, ENGINE: 41AT, 42AB, 42AT - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A								PKG:19
06-00/590 ^S	ACCESS PANEL, ENGINE: 11BR, 21QZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/591 ^S	ACCESS PANEL, ENGINE: 11BR,21QZ - INSTALL							Service ATA:06
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:16
06-00/592 ^S	ACCESS PANEL, ENGINE: 42AT - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:16
06-00/593 ^S	ACCESS PANEL, ENGINE: 42AT - INSTALL							Service ATA:06
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:16
06-00/594 ^S	ACCESS PANEL, FUSELAGE: 11BL, 21PZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17
06-00/595 ^S	ACCESS PANEL, FUSELAGE: 11BL, 21PZ - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17
06-00/596 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - OPEN OR REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17
06-00/597 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB, 33ET - CLOSE OR INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/598 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17
06-00/599 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:17
06-00/602 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	21-Nov-23						
	HRS	2764.6	600 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:18
06-00/603 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	21-Nov-23						
	HRS	2764.6	600 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:18
06-00/604 ^S	ACCESS PANEL, FUSELAGE: 11AL,12EL,21QZ - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:19
06-00/605 ^S	ACCESS PANEL, FUSELAGE: 11AL, 12EL,21QZ - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:19
06-00/606 ^S	ACCESS PANEL, WING: 52NB, 52OB, 62NB, 62OB - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/607 ^S	ACCESS PANEL, WING: 52NB, 52OB, 62NB, 62OB - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:19	
06-00/608 ^S	ACCESS PANEL,FUSELAGE: 11AL, 11AR, 11BR, 11BL, 11BZ, 11DZ, 12AL, 12AR, 12AB,12AV, 12BL, 12BR, 12BZ, 12EL, 12HZ, 12JZ, 12MZ, 11BZ, 12AZ, 12BZ, 12DZ, 12GZ,12BL, 12BR, 12EZ, 12ER, 12KZ, 12CZ, 12FZ, 12IZ, 12LZ, 21JZ, 21QZ, 21GZ, 21HZ, 22TZ, 22PZ, 22UZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR							Service ATA:06
	MOS	15-Nov-24	12 (+10m/-10%)					
	HRS	2910.1	1200 (+10/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20	
06-00/609 ^S	ACCESS PANEL,FUSELAGE: 11AL, 11AR, 11BR, 11BL, 11BZ, 11DZ, 12AL, 12AR, 12AB,12AV, 12BL, 12BR, 12BZ, 12EL, 12HZ, 12JZ, 12MZ, 11BZ, 12AZ, 12BZ, 12DZ, 12GZ,12BL, 12BR, 12EZ, 12ER, 12KZ, 12CZ, 12FZ, 12IZ, 12LZ, 21JZ, 21QZ, 21GZ, 21HZ, 22TZ, 22PZ, 22UZ - CLOSE OR INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20	
06-00/610 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - OPEN OR REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20	
06-00/611 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 31AL, 31AR, 32AB, 32BL, 32BR, 32AL, 32CL, 32CT,32DL, 32DR, 32BT, 33DT, 33ET, 34DT - CLOSE OR INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20	
06-00/612 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/613 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:20
06-00/614 ^S	ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, , 12EL, 12ER, 12CZ, 12EZ, 12FZ, 21JZ - OPEN OR REMOVE. EXAMINE AND MAKE SURE THAT ACCESS PANEL DRAIN HOLES ARE CLEAR							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21
06-00/615 ^S	ACCESS PANEL,FUSELAGE: 11AL, 11AZ, 11BL, , 12EL, 12ER, 12CZ, 12EZ, 12FZ, 21JZ - CLOSE AND INSTALL							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21
06-00/616 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - OPEN OR REMOVE AND EXAMINE							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21
06-00/617 ^S	ACCESS PANEL, EMPENNAGE: 31AB, 32AB,32CT, 33ET - INSTALL							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21
06-00/618 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - REMOVE AND EXAMINE							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21
06-00/619 ^S	ACCESS PANEL, ENGINE: 42AT, 42AB - INSTALL							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-06-20-00-00A-040A-A							PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 06 - DIMENSIONS AND AREAS								
06-00/620 ^S	ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - REMOVE AND EXAMINE							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
				PROC. REF: AMM 12-B-06-20-00-00A-040A-A				PKG:21
06-00/621 ^S	ACCESS PANEL, WING: 51AB, 51BB, 61AB, 61BB - INSTALL							Service ATA:06
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
				PROC. REF: AMM 12-B-06-20-00-00A-040A-A				PKG:21
ATA 07 - LIFTING AND SHORING								
07-10/160 ^S	AIRCRAFT - LOWER TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND							Service ATA:07
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
				PROC. REF: AMM 12-B-07-10-00-00A-901A-A				PKG:15 ,16,17,18,19,20,21
07-10/161 ^S	AIRCRAFT - LIFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND							Service ATA:07
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
				PROC. REF: AMM 12-B-07-10-00-00A-901A-A				PKG:15 ,16,17,18,19,20,21
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10/428 ^S	EXTERNAL PROTECTIVE COVERS - EXAMINE. REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.							Service ATA:10
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
				PROC. REF: GENERIC NO REF				PKG:17
ATA 11 - PLACARDS AND MARKINGS								
11-00/220 ^S	PLACARDS AND MARKINGS - EXAMINE AND ATTACH NEW PLACARDS IF NECESSARY							Service ATA:11
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
				PROC. REF: AMM 12-B-11-00-00-00A-040A-A, AMM 12-B-11-00-00-00A-901A-A, AMM 12-B-11-20-00-00A-040A-A, AMM 12-B-11-20-00-00A-901A-A, AMM 12-B-11-30-00-00A-040A-A				PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
12-20/124 ^S	AIRCRAFT - WASH THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS AS REQUIRED TO PERFORM THE INSPECTION							Service ATA:12
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
				PROC. REF: AMM 12-B-12-20-01-00A-902A-A, AMM 12-B-12-20-01-01A-902A-A				PKG:15 ,16,17,18,19,20,21
12-20/125 ^S	WINDSHIELDS AND WINDOWS - CLEAN							Service ATA:12
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
				PROC. REF: AMM 12-B-12-20-02-00A-902A-A				PKG:15 ,16,17,18,19,20,21
12-20/126 ^S	COCKPIT AND CABIN - CLEAN							Service ATA:12
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
				PROC. REF: AMM 12-B-12-20-03-00A-902A-A				PKG:15 ,16,17,18,19,20,21
ATA 20 - STANDARD PRACTICES - AIRFRAME								
00-00/45A	AIRCRAFT - DO THE CORROSION AND CORROSION PROTECTION INSPECTIONS (INTERNAL)							Service ATA:20
	MOS	15-Nov-24	12 (+1m/-1m)		30-Nov-25	31-Dec-25	374 d (+31)	
	HRS	2910.1						
WC#: 20.010	AFL	2216						
				PROC. REF: AMM 12-B-20-40-00-00A-901A-A				
00-00/45B	AIRCRAFT - DO THE CORROSION AND CORROSION PROTECTION INSPECTIONS (EXTERNAL)							Service ATA:20
	MOS	15-Nov-24	12 (+1m/-1m)		30-Nov-25	31-Dec-25	374 d (+31)	
	HRS	2910.1						
WC#: 20.011	AFL	2216						
				PROC. REF: AMM 12-B-20-40-00-00A-901A-A				
ATA 21 - AIR CONDITIONING								
21-20/221 ^S	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE							Service ATA:21
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
				PROC. REF: GENERIC NO REF				PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK							Service ATA:21
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
	HRS	2910.1	3000		5910.1		2999.8	
	AFL	2216						
PROC. REF: GENERIC NO REF								
21-30/314 ^S	CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE - CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT. IF CONTAMINATION IS FOUND REMOVE AND CLEAN							Service ATA:21
PN:PN	MOS	21-Nov-23	24 (+10%/-10%)					
SN:UNKNOWN	HRS	2764.6	2400 (+10%/-10%)					
WC#: 21.030	AFL	2083						
PROC. REF: AMM 12-B-21-30-02-00A-250A-A								PKG:21
21-30/318	PRESSURIZATION DUMP SWITCH MSN 1001-1719 - OPERATIONAL TEST							Service ATA:21
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
	HRS	2910.1	3000		5910.1		2999.8	
WC#: 21.045	AFL	2216						
PROC. REF: AMM 12-B-21-30-00-00A-903A-A								
21-30/46	CABIN POSITIVE PRESSURE RELIEF 1001-1719 - FUNCTIONAL TEST							Service ATA:21
PN:PN	MOS	15-Nov-24	48 (+10%/-10%)		30-Nov-28	24-Apr-29	1470 d (+145)	
SN:UNKNOWN	HRS	2910.1	4800 (+10%/-10%)		7710.1	8190.1	4799.8 (+480)	
WC#: 21.040	AFL	2216						
PROC. REF: AMM 12-B-21-30-00-00A-903A-A								
21-40/128 ^S	FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH - OPERATIONAL TEST							Service ATA:21
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-21-43-00-00A-903A-A								PKG:20
21-40/330 ^S	CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH - OPERATIONAL TEST							Service ATA:21
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
WC#: 21.140	AFL	2216						
PROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-A								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-40/331 ^S		UNDERFLOOR HEATER THERMAL PROTECTION SWITCH - FUNCTIONAL TEST						Service ATA:21
PN:9696781507	MOS	15-Nov-24	12 (+10%/-10%)					
SN:530202	HRS	2910.1	1200 (+10%/-10%)					
WC#: 21.150	AFL	2216						
PROC. REF: AMM 12-B-21-40-01-00A-903A-A, AMM 12-B-21-40-01-00A-903B-A						PKG:20		
21-40/50 ^S		WATER SEPARATOR CONDENSER - CLEAN						Service ATA:21
PN:5214112060	MOS	15-Nov-24	12 (+10%/-10%)					
SN:2557	HRS	2910.1	1200 (+10%/-10%)					
WC#: 21.080	AFL	2216						
PROC. REF: AMM 12-B-21-40-03-00A-250A-A						PKG:20		
21-40/51		OVERTEMPERATURE SWITCH - FUNCTIONAL TEST						Service ATA:21
PN:9738132216	MOS	21-Nov-23	60 (+10%/-10%)		30-Nov-28	31-May-29	1470 d (+182)	
SN:31	HRS	2764.6	4800 (+10%/-10%)		7564.6	8044.6	4654.3 (+480)	
WC#: 21.130	AFL	2083						
PROC. REF: AMM 12-B-21-40-06-00A-903A-A								
21-40/52		DUCT OVERTEMPERATURE SWITCH - FUNCTIONAL TEST						Service ATA:21
PN:9738132214	MOS	21-Nov-23	60 (+10%/-10%)		30-Nov-28	31-May-29	1470 d (+182)	
SN:64	HRS	2764.6	4800 (+10%/-10%)		7564.6	8044.6	4654.3 (+480)	
WC#: 21.120	AFL	2083						
PROC. REF: AMM 12-B-21-60-05-00A-903A-A								
21-40/55 ^S		COLD AIR UNIT - ADD OIL						Service ATA:21
	MOS	21-Nov-23						
	HRS	2764.6	600 (+10%/-10%)					
WC#: 21.060	AFL	2083						
PROC. REF: AMM 12-B-21-40-02-00A-902A-A						PKG:18		
21-40/56 ^S		HEAT EXCHANGER MATRIX - INSPECT/CHECK						Service ATA:21
	MOS	21-Nov-23						
	HRS	2764.6	600 (+10%/-10%)					
WC#: 21.070	AFL	2083						
PROC. REF: AMM 12-B-21-40-02-00A-313A-A						PKG:18		
21-50/223 ^S		VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) - EXAMINE						Service ATA:21
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF						PKG:20		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-50/433	VAPOR CYCLE COMPRESSOR/CONDENSER MODULE (INCLUDIG MOTOR) (IF INSTALLED) - CLEAN							Service ATA:21
PN:9599022102	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	
SN:884	HRS	2910.1	300 (+10%/-10%)		3210.1	3240.1	299.8 (+30)	
	AFL	2216						
PROC. REF: AMM NO REF								
21-50/461	VAPOR CYCLE COMPRESSOR MOTOR (CCM P/N 959.90.22.140) (IF INSTALLED) - INSPECT/CHECK							Service ATA:21
PN:9599022102	MOS/MSC	31-Mar-08	N/A					
SN:884	HRS	0						
	AFL	0						
	ACH							
PROC. REF: AMM 12-B-21-50-03-00A-313A-A								
21-50/462	VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CCM P/N 959.90.22.140) (IF INSTALLED) - CHECK FOR TENSION							Service ATA:21
PN:9599022102	MOS/MSC	31-Mar-08	N/A					
SN:884	HRS	0						
	AFL	0						
	ACH							
PROC. REF: AMM 12-B-21-50-01-00A-903A-A								
21-50/58	VAPOOR CYCLE COMPRESSOR MOTOR (IF INSTALLED) - INSPECTION/CHECK							Service ATA:21
PN:9599022102	MOS	21-Nov-23						
SN:884	HRS	2764.6						
WC#: 21.110	AFL	2083						
	ACH	925.2	500 (+10%/-10%)		1425.2	1475.2	500 (+50)	
PROC. REF: AMM 12-B-21-50-03-00A-313A-A								
21-50/59	VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (IF INSTALLED) - CHECK FOR TENSION							Service ATA:21
PN:9599022102	MOS	21-Nov-23						
SN:884	HRS	2764.6						
WC#: 21.100	AFL	2083						
	ACH	925.2	500 (+10%/-10%)		1425.2	1475.2	500 (+50)	
PROC. REF: AMM 12-B-21-50-01-00A-903A-A								
210005	OVERPRESSURE SWITCH							Component ATA:21
PN:9738115105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:694	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-07-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210010	REFRIGERATION PACK							Component ATA:21
PN:9599020111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1446	HRS	0		TSN 0				
WC#: 21.255	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-02-00A-313A-A								
210015	WATER INJECTOR							Component ATA:21
PN:9599020141	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1450	HRS	0		TSN 0				
WC#: 21.370	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210020	DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1638	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-60-04-00A-920A-A								
210025	PRIM SHUT OFF VALVE							Component ATA:21
PN:2959A000	MOS/MSC	24-Jan-14	O/C					
SN:898929-1	HRS	655						
WC#: 21.290	AFL	400						
PROC. REF: AMM 12-B-21-40-05-00A-920A-A								
210030	HP SHUT OFF VALVE							Component ATA:21
PN:9599020131	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1427	HRS	0		TSN 0				
WC#: 21.280	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-04-00A-920A-A								
210035	WATER SEPARATOR ASSY							Component ATA:21
PN:5214112060	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2557	HRS	0		TSN 0				
WC#: 21.220	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-03-00A-920A-A								
210040	TEMP CONTROL VALVE							Component ATA:21
PN:9599020136	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1410	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-60-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE							Component ATA:21
PN:9599022102	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:884	HRS	0		TSN 0				
WC#: 21.380	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-50-01-00A-920A-A								
210046	VAPOR CYCLE COMPRESSOR MOTOR							Component ATA:21
PN:1134104-6	MOS/MSC	21-Jul-16	O/C	TSN 0				
SN:6016	HRS	1256.6		TSN 0				
	AFL	956		TSN 0				
PROC. REF: AMM 12-B-21-50-01-00A-920A-A								
210050	CENTER EVAPORATOR MODULE ASSY							Component ATA:21
PN:9599022121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:287	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210055	RIGHT SIDE EVAPORATOR MODULE							Component ATA:21
PN:9599022119	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:291	HRS	0		TSN 0				
WC#: 21.210	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210060	CABIN PRESSURE OUTFLOW VALVE							Component ATA:21
PN:103898-3	MOS/MSC	05-Dec-17	O/C					
SN:103898-00599	HRS	1562.9						
WC#: 21.250	AFL							
PROC. REF: AMM 12-B-21-30-03-00A-920A-A								
210065	CABIN PRESSURE RELIEVE VALVE							Component ATA:21
PN:9599091132	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:117/F0014	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER							Component ATA:21
PN:9696781507	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:530202	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210135	LEFT SIDE EVAPORATOR MODULE ASSY							Component ATA:21
PN:9599022118	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:288	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210145	CABIN (REAR) ELECTRIC HEATER							Component ATA:21
PN:969.67.81.507	MOS/MSC	01-Aug-16	O/C					
SN:533077	HRS	1261.2						
WC#: 21.230	AFL	956						
PROC. REF: AMM 12-B-21-40-15-00A-920A-A								
210170	OVERPRESSURE SWITCH							Component ATA:21
PN:9738115106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:700	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-40-07-00A-920A-A								
210175	FLOW CONTROL VALVE ACTUATOR							Component ATA:21
PN:9599020160	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:402	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-60-03-01A-920A-A								
210180	CABIN PRESSURE CONTROL UNIT							Component ATA:21
PN:2119232-4	MOS/MSC	02-Feb-18	O/C	TSR 0				
SN:2119232-00491	HRS	1596.7		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 12-B-21-30-01-00A-920A-A								
210185	INTEG. ECS CONTROL UNIT							Component ATA:21
PN:74A54-01	MOS/MSC	04-Apr-09	O/C	TSO 0				
SN:106	HRS			TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 12-B-21-60-01-00A-920A-A								
210190	FLOOR DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1611	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-21-60-04-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210195	MIDDLE CONSOLE DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1605	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210200	FIREWALL 1415-3 SHUT OFF VALVE							Component ATA:21
PN:963.30.11.006	MOS/MSC	15-Dec-21	O/C	TSN 0				
SN:UNKNOWN	HRS	2266.5		TSN 0				
	AFL	1668		TSN 0				
PROC. REF: AMM 12-B-21-20-01-00A-920A-A								
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH							Component ATA:21
PN:9738132216	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:31	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210210	OVERTEMP. CONDAIR 1173T08 SWITCH							Component ATA:21
PN:9738132214	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:64	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210215	DUAL FLAPPER 1.5 IN. CHECK VALVE							Component ATA:21
PN:9633011105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:0683B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210220	LH DUAL FLAPPER 2.5 IN. CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:0671B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210225	RH DUAL FLAPPER 2.5 IN. CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:0680B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
210230	DUAL FLAPPER 2.5 IN. SPANT 15 CHECK VALVE							Component ATA:21
PN:9633011106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:0638B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
210235	HEAD LINER DUCT TEMP SENSOR							Component ATA:21
PN:9599020121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1659	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
213050 ^U	RUN VAPOR CYCLE COOLING SYSTEM FOR 15 MINUTES							Service ATA:21
	MOS/MSC		A/R					
	HRS	0						
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REF								
ATA 22 - AUTO FLIGHT								
22-10/233 ^S	PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES - EXAMINE							Service ATA:22
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								PKG:21
22-10/60 ^S	SERVO MOUNT - (PITCH, ROLL AND YAW) REMOVE FOR CLUTCH CHECK							Service ATA:22
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
WC#: 22.010	AFL	2216						
PROC. REF: AMM 12-B-22-10-00-00A-313A-A								PKG:20
22-20/129 ^S	ANGLE OF ATTACK (AOA) TRANSMITTERS - EXAMINE							Service ATA:22
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-22-20-02-00A-313A-A								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-20/130 ^S		STICK PUSHER SYSTEM - CHECK						Service ATA:22
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-22-20-00-00A-903A-A								PKG:16
22-20/226 ^S		STICK PUSHER SYSTEM - FUNCTIONAL TEST						Service ATA:22
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-22-20-00-00A-903A-A								PKG:20
220045		STICK PUSHER SERVO						Component ATA:22
PN:501-1684-04	MOS/MSC	25-Jul-17	O/C	TSO 0				
SN:80296	HRS	1497.9		TSO 0				
WC#: 22.220	AFL			TSO 0				
PROC. REF: AMM 12-B-22-20-04-00A-920A-A								
220055		STICK PUSHER CAPSTAN						Component ATA:22
PN:9786111124	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:80302	HRS	0		TSN 0				
WC#: 22.140	AFL	0		TSN 0				
PROC. REF: AMM 12-B-22-20-06-00A-920A-A								
220060		STICK SHAKER						Component ATA:22
PN:9786111143	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:812	HRS	0		TSN 0				
WC#: 22.230	AFL	0		TSN 0				
PROC. REF: AMM 12-B-22-20-03-00A-920A-A								
220070		STICK PUSHER						Component ATA:22
PN:975.44.23.104	MOS/MSC	05-Nov-15	O/C					
SN:132310	HRS	1111.9						
WC#: 22.170	AFL	800						
PROC. REF: AMM 12-B-22-20-04-00A-920A-A								
220075		KMC 9200 FLIGHT CONTROLLER						Component ATA:22
PN:071-01597-0401	MOS/MSC	26-Jul-11	O/C					
SN:KMC9200-1118	HRS	330						
	AFL							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
220085	ELEVATOR KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:KSM375-B1041	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
220090	RUDDER KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:KSM375-B1039	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
220095	AILERON KSM 375 A/P SERVO MOUNT							Component ATA:22
PN:9859912133	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:KSM375-B1051	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
220100	RUDDER KSA 2700 SERVO							Component ATA:22
PN:065-00190-0101	MOS/MSC	11-Jan-16	O/C	TSN 0				
SN:KSA2700-1057	HRS	1146.4		TSN 0				
	AFL	892		TSN 0				
PROC. REF: GENERIC NO REF								
220105	ELEVATOR KSA 2700 SERVO							Component ATA:22
PN:065-00190-0101	MOS/MSC	25-Oct-17	O/C					
SN:KSA2700-1904	HRS	1541.9						
	AFL	1085						
PROC. REF: GENERIC NO REF								
220110	AILERON KSA 2700 SERVO							Component ATA:22
PN:065-00190-0101	MOS/MSC	11-Jan-16	O/C					
SN:KSA2700-1043	HRS	1146.4						
	AFL	892						
PROC. REF: GENERIC NO REF								
ATA 23 - COMMUNICATIONS								
23-10/322 ^S	AUDIO CONTROL PANEL EMERGENCY SWITCH - OPERATIONAL TEST							Service ATA:23
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-23-50-00-00A-903A-A								

PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-10/323 ^S	EMERGENCY FREQUENCY COMM TUNING SWITCH - OPERATIONAL TEST							Service ATA:23
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-23-12-00-00A-903A-A							PKG:21	
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA							Component ATA:23
PN:9848110203	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:310-17321	HRS	0		TSN 0				
WC#: 23.020	AFL	0		TSN 0				
PROC. REF: AMM 12-B-23-12-02-00A-920A-A								
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA							Component ATA:23
PN:9848110203	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:310-17320	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-23-12-03-00A-920A-A								
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO							Component ATA:23
PN:069-01037-0102	MOS/MSC	04-Apr-09	O/C	TSO 0				
SN:1653	HRS			TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 12-B-23-12-01-00A-920A-A								
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO							Component ATA:23
PN:069-01037-0102	MOS/MSC	29-Jan-10	O/C	TSR 0				
SN:2589	HRS	191.3		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 12-B-23-12-01-00A-920A-A								
230055	PILOT KMA 29 AUDIO/MARKER PANEL							Component ATA:23
PN:9859912108	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:D0139	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-23-50-01-00A-920A-A								
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL							Component ATA:23
PN:066-01181-0101	MOS/MSC	06-Aug-10	O/C					
SN:E0364	HRS	252.9						
	AFL							
PROC. REF: AMM 12-B-23-50-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30/309 ^S	GENERATOR 1 (P/N 978.91.23.437) - BRUSH CHECK							Service ATA:24
PN:23085-031 MOD A	MOS/MSC	15-Nov-24	N/A					
SN:P1035	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-24-30-01-00A-313A-A							PKG:16	
24-30/310 ^S	STARTER/GENERATOR 2 (P/N 978.91.23.437) - BRUSH CHECK							Service ATA:24
PN:23085-01 MOD A	MOS	15-Nov-24						
SN:P1020	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-24-30-01-00A-313A-A							PKG:16	
24-30/311	GENERATOR CONTROL UNIT, GCU 1- FUNCTIONAL TEST OF OVER AND UNDER-VOLTAGE TRIP PROTECTION							Service ATA:24
PN:PN	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
SN:UNKNOWN	HRS	2910.1	3000		5910.1		2999.8	
WC#: 24.015	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903D-A								
24-30/311	GENERATOR CONTROL UNIT, GCU 2- FUNCTIONAL TEST OF OVER AND UNDER-VOLTAGE TRIP PROTECTION							Service ATA:24
PN:PN	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
SN:UNKNOWN	HRS	2910.1	3000		5910.1		2999.8	
WC#: 24.025	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903D-A								
24-30/312 ^S	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST							Service ATA:24
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-24-40-00-00A-903A-A							PKG:21	
24-30/313 ^S	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST							Service ATA:24
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903D-A							PKG:20	
24-30/340	NO. 1 LEAD ACID BATTERY - REMOVE AND DO A CAPACITY TEST							Service ATA:24
PN:RG380E/44	MOS	15-Nov-24	6 (+10%/-10%)		31-May-25	18-Jun-25	191 d (+18)	
SN:70027693	HRS	2910.1	600 (+10%/-10%)		3510.1	3570.1	599.8 (+60)	
WC#: 24.010	AFL	2216						
PROC. REF: AMM 12-B-24-30-07-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30/340	NO. 2 LEAD ACID BATTERY - REMOVE AND DO A CAPACITY TEST							Service ATA:24
PN:RG380E/44	MOS	15-Nov-24	T:12 (+1m/-1m)		30-Nov-25	31-Dec-25	374 d (+31)	
SN:70037182	HRS	2910.1	T:1000 (+10%/-10%)		3910.1	4010.1	999.8 (+100)	
WC#: 24.010	AFL	2216						
PROC. REF: AMM 12-B-24-30-07-00A-920A-A								
24-30/473 ^S	GENERATOR 1 (P/N 978.91.23.407) - BRUSH CHECK							Service ATA:24
PN:23085-031 MOD A	MOS	21-Nov-23						
SN:P1035	HRS	2764.6	600 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-24-30-01-00A-313A-A								
								PKG:18
24-30/474 ^S	STARTER/GENERATOR 2 (P/N 978.91.23.407) - BRUSH CHECK							Service ATA:24
PN:23085-01 MOD A	MOS/MSC		N/A					
SN:P1020	HRS							
	AFL							
PROC. REF: AMM 12-B-24-30-01-00A-313A-A								
								PKG:18
24-30/492	GENERATOR 1 (P/N 978.91.23.407) - OVERHAUL							Service ATA:24
PN:23085-031 MOD A	MOS	21-May-21						OVERHAUL
SN:P1035	HRS	2163	1200 (+10%/-10%)		3363	3483	452.7 (+120)	
	AFL	1598						
PROC. REF: AMM 12-B-05-10-10-00A-281A-A								
24-30/493	STARTER/GENERATOR 2 (P/N 978.91.23.407) - OVERHAUL							Service ATA:24
PN:23085-01 MOD A	MOS/MSC		N/A					
SN:P1020	HRS							
	AFL							
PROC. REF: AMM 12-B-24-30-01-00A-313A-A								
24-30/496	GENERATOR 1 (P/N 978.91.23.437) - OVERHAUL							Service ATA:24
PN:23085-031 MOD A	MOS/MSC		N/A					
SN:P1035	HRS							
	AFL							
PROC. REF: AMM 12-B-05-10-10-00A-281A-A								
24-30/497	STARTER/GENERATOR 2 (P/N 978.91.23.437) - OVERHAUL							Service ATA:24
PN:23085-01 MOD A	MOS	22-Nov-22						OVERHAUL
SN:P1020	HRS	2558.5	1000 (+10%/-10%)		3558.5	3658.5	648.2 (+100)	
	AFL	1910						
PROC. REF: AMM 12-B-24-30-01-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-40/229 ^S	EXTERNAL POWER UNIT (EPU) RECEPTACLE - EXAMINE							Service ATA:24
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								PKG:21
24-50/70	EMERGENCY POWER SUPPLY - REMOVE AND CAP TEST							Service ATA:24
PN:501-1712-02	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	
SN:81393	HRS	2910.1						
WC#: 24.050	AFL	2216						
PROC. REF: AMM 12-B-24-52-51-00A-920A-A								
24-60/133 ^S	COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS - EXAMINE							Service ATA:24
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								PKG:21
240005	VOLTAGE REGULATOR 1							Component ATA:24
PN:9882114111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:P1684	HRS	0		TSN 0				
WC#: 24.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-24-30-05-00A-920A-A								
240005-1 ^U	REGULATOR,VOLTAGE,51538-002A							Component ATA:24
PN:9882114111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:P1633	HRS	0		TSN 0				
	AFL	0		TSN 0				
240010	GENERATOR 1 300A CONTACTOR							Component ATA:24
PN:9740338113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N890	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
240015	GENERATOR 2 300A CONTACTOR							Component ATA:24
PN:9740338113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N860	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240120								Component ATA:24
PN:9740338135	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:102	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
240135 NO. 1 LEAD ACID BATTERY								Component ATA:24
PN:RG380E/44	MOS/MSC	15-Nov-24	O/C	TSN 15				
SN:70027693	HRS	2910.1		TSN 194.4				
WC#: 24.010	AFL	2216		TSN 170				
PROC. REF: AMM 12-B-24-30-07-00A-920A-A								
240140 NO. 2 LEAD ACID BATTERY								Component ATA:24
PN:RG380E/44	MOS/MSC	15-Nov-24	O/C	TSN 0				
SN:70037182	HRS	2910.1		TSN 0				
WC#: 24.010	AFL	2216		TSN 0				
PROC. REF: AMM 12-B-24-30-07-00A-920A-A								
241005 NO. 1 CABIN INVERTER OUTLET								Component ATA:24
PN:MT-AC11005-1-HT159	MOS/MSC	03-Jun-08	O/C					
SN:66652-13-1	HRS	25.1						
	AFL	12						
PROC. REF: GENERIC NO REF								
241010 NO. 2 CABIN INVERTER OUTLET								Component ATA:24
PN:MT-AC11005-1-HT159	MOS/MSC	03-Jun-08	O/C					
SN:66652-13-3	HRS	25.1						
	AFL	12						
PROC. REF: GENERIC NO REF								
241015 NO. 3 CABIN INVERTER OUTLET								Component ATA:24
PN:MT-AC11005-1-HT159	MOS/MSC	03-Jun-08	O/C					
SN:66652-13-2	HRS	25.1						
	AFL	12						
PROC. REF: GENERIC NO REF								
243010 NO. 2 STARTER-GENERATOR								Component ATA:24
PN:23085-01 MOD A	MOS/MSC	22-Nov-22	O/C	TSO 0				
SN:P1020	HRS	2558.5		TSO 0				
WC#: 24.215	AFL	1910		TSO 0				
PROC. REF: AMM 12-B-24-30-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT							Component ATA:24
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.015	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT							Component ATA:24
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243080	EMERGENCY POWER SUPPLY							Component ATA:24
PN:501-1712-02	MOS/MSC	15-Nov-24	O/C					
SN:81393	HRS	2910.1						
WC#: 24.050	AFL	2216						
PROC. REF: AMM 12-B-24-52-51-00A-920A-A								
243160	NO. 1 STARTER GENERATOR							Component ATA:24
PN:23085-031 MOD A	MOS/MSC	21-May-21	O/C	TSO 0				
SN:P1035	HRS	2163		TSO 0				
WC#: 24.205	AFL	1598		TSO 0				
PROC. REF: AMM 12-B-24-30-01-00A-920A-A								
243170	110 VOLT STATIC ,SS50 INVERTER							Component ATA:24
PN:9750215107	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3855	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-24-60-01-00A-920A-A								
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER							Component ATA:24
PN:9755085111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N224	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER							Component ATA:24
PN:9755085111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N214	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-10/134 ^S	EXAMINE CREW SEAT BELTS							Service ATA:25
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:17
25-10/135 ^S	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED							Service ATA:25
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:16
25-10/294	CREW SEAT BELTS							Component ATA:25
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
	PROC. REF: GENERIC NO REF							
25-10/296 ^S	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION							Service ATA:25
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
	PROC. REF: AMM 12-B-25-10-01-00A-920A-A							PKG:15 ,16,17,18,19,20,21
25-10/297 ^S	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:25
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
	PROC. REF: AMM 12-B-25-10-01-00A-920A-A							PKG:15 ,16,17,18,19,20,21
25-10/300 ^S	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS.							Service ATA:25
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-25-10-01-00A-920A-A							PKG:20
25-20/136 ^S	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS							Service ATA:25
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-20/137 ^S	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT							Service ATA:25
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
25-20/295	PASSENGER SEAT BELTS							Component ATA:25
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.010	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
25-20/298 ^S	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION							Service ATA:25
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-A							PKG:15 ,16,17,18,19,20,21	
25-20/299 ^S	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:25
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-25-21-01-00A-920A-A, AMM 12-B-25-22-01-00A-920A-A							PKG:15 ,16,17,18,19,20,21	
25-20/302 ^S	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION.							Service ATA:25
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:16	
25-60/231 ^S	OPERATIONAL TEST ELT							Service ATA:25
PN:S1821502-02	MOS	15-Nov-24	12 (+10%/-10%)					
SN:2616951-0005	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-25-63-00-00A-903A-A, AMM 12-B-25-63-00-00A-903B-A							PKG:17	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60/232 ^S		EXAMINE ELT INSTALLATION						Service ATA:25
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
25-60/483		PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED						Service ATA:25
PN:S1821502-02	MOS/MSC	11-Jan-19	A/R					
SN:2616951-0005	HRS	1764						
	AFL							
PROC. REF: GENERIC NO REF								
25-63/23		ELT BATTERY						Component ATA:25
PN:1820506-01	MOS/MSC	23-Dec-20	DUE	TSN 0	01-Aug-27 (M)		983 d	DISCARD
SN:2033-0299	HRS	2096.9		TSN 0				
WC#: 25.020	AFL	1549		TSN 0				
PROC. REF: GENERIC NO REF								
25-63/434		DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED)						Service ATA:25
PN:PN	MOS/MSC	31-Mar-08	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
250005		REMOTE CONTROL PANEL						Component ATA:25
PN:9851380817	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2616275-0081	HRS	0		TSN 0				
WC#: 25.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
250010		EMERGENCY LOCATOR TRANSMITTER						Component ATA:25
PN:S1821502-02	MOS/MSC	11-Jan-19	O/C					
SN:2616951-0005	HRS	1764						
WC#: 25.050	AFL							
PROC. REF: AMM 12-B-25-63-00-00A-920A-A								
250630		KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE						Component ATA:25
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-63-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256020	LH BLACK PILOT SEAT							Component ATA:25
PN:9593001145	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:51237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-10-01-00A-920A-A								
256025	RH BLACK CO-PILOT SEAT							Component ATA:25
PN:9593001146	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:51239	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-25-10-01-00A-920A-A								
258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)							Service ATA:25
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
WC#: 25.110	AFL	2216						
PROC. REF: AMM 12-B-25-63-00-00A-903A-A								
ATA 26 - FIRE PROTECTION								
26-20/2	COCKPIT FIRE EXTINGUISHER							Component ATA:26
PN:959.08.06.219	MOS	16-Jan-18	120	TSN 13	28-Feb-27		829 d	LIFE LIMIT
SN:UNKNOWN	HRS	1583.8		TSN 0				
WC#: 26.010	AFL	1224		TSN 0				
Manufacture Date:: 01-Feb-17 PROC. REF: AMM 12-B-26-20-01-00A-920A-A								
26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)							Service ATA:26
PN:959.08.06.219	MOS	15-Nov-24	12 (+1m/-1m)		30-Nov-25	31-Dec-25	374 d (+31)	
SN:UNKNOWN	HRS	2910.1						
WC#: 26.010	AFL	2216						
PROC. REF: AMM 12-B-26-20-00-01A-289A-A								
260005	FIRE/OVERHEAT DETECTOR							Component ATA:26
PN:975.12.10.012	MOS/MSC	15-Sep-21	O/C	TSN 0				
SN:217538	HRS	2235.9		TSN 0				
WC#: 26.020	AFL	1645		TSN 0				
PROC. REF: AMM 12-B-26-10-01-00A-920A-A								
ATA 27 - FLIGHT CONTROLS								
27-00/138 ^S	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL							Service ATA:27
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:16
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES							Service ATA:27
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 27.255	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: GENERIC NO REF								
27-00/402 ^U	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES							Service ATA:27
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 27.255	AFL	0	T:42000		42000		39783	
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK							Service ATA:27
	MOS	22-Nov-22	60 (+10%/-10%)		30-Nov-27	31-May-28	1104 d (+183)	
	HRS	2558.5	4800 (+10%/-10%)		7358.5	7838.5	4448.2 (+480)	
WC#: 27.010	AFL	1910						
PROC. REF: AMM 12-B-27-00-00-00A-313A-A								
27-10/139 ^S	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIMHINGES WITH MINIMUM QUANTITY OFCPC (MAT. NO. P10-001)							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
27-10/234 ^S	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
27-10/235 ^S	EXAMINE AILERON ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/236 ^S	AILERON CONTROL SYSTEM - INSPECTION/ CHECK							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
				PROC. REF: AMM 12-B-27-10-00-00A-313A-A				PKG:20
27-10/237 ^S	CHECK AILERON CABLE TENSION							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
				PROC. REF: AMM 12-B-27-10-00-00A-903A-A				PKG:20
27-10/238 ^S	FUNCTIONAL TEST AILERONS							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
				PROC. REF: AMM 12-B-27-10-00-00A-903A-A				PKG:21
27-10/394	AILERON CONTROL SYSTEM - EXAMINE							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
				PROC. REF: AMM 12-B-27-10-00-00A-310A-A				
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
				PROC. REF: AMM 12-B-27-10-09-00A-353A-A				
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
				PROC. REF: AMM 12-B-27-00-01-00A-353A-A				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-00-01-00A-352A-A								
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-10-08-00A-352B-A, AMM 12-B-27-10-08-00A-353A-A, AMM 12-B-27-10-08-00A-353B-A								
27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-57-60-06-00A-353A-A								
27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-57-60-06-00A-353A-A								
27-10/444	FLIGHT CONTROL CABLES, AILERON							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-10-01-00A-920A-A								
27-10/445	AUTOPILOT CONTROL CABLE, AILERON							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-10-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-10/470 ^S	LUBRICATE AILERON CONTROL SYSTEM BEARINGS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-10-00-00A-901A-A							PKG:20	
27-15/239 ^S	FUNCTIONAL TEST AILERON TRIM							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-27-15-00-00A-903A-A							PKG:21	
27-20/140 ^S	INSPECTION/CHECK RUDDER							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-55-40-00-00A-313A-A							PKG:17	
27-20/240 ^S	EXAMINE RUDDER STATIC DISCHARGERS							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF							PKG:21	
27-20/241 ^S	RUDDER CONTROL SYSTEM - INSPECTION/ CHECK							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-20-00-00A-313A-A							PKG:20	
27-20/243 ^S	CHECK RUDDER CABLE TENSION							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-20-00-00A-903A-A							PKG:20	
27-20/244 ^S	FUNCTIONAL TEST RUDDER							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-27-20-00-00A-903A-A							PKG:21	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20/245 ^S	FUNCTIONAL TEST RUDDER TRIM							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: AMM 12-B-27-25-00-00A-903A-A							PKG:21
27-20/246 ^S	EXAMINE RUDDER ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:20
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
	PROC. REF: AMM 12-B-27-20-00-00A-310A-A							
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
	PROC. REF: AMM 12-B-27-20-05-00A-310A-A							
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED							Service ATA:27
	MOS/MSC	31-Mar-08	O/C					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 12-B-27-20-00-00A-903A-A							
27-20/431	RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)							Service ATA:27
PN:PN	MOS/MSC	31-Mar-08	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
	PROC. REF: AMM 12-B-27-20-00-00A-903A-A							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-20/446	FLIGHT CONTROL CABLES, RUDDER							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-20-01-00A-920A-A								
27-20/447	AUTOPILOT CONTROL CABLES, RUDDER							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-20-02-00A-920A-A								
27-20/575	REPLACE RUDDER BELLCRANK							Service ATA:27
PN:PN	MOS	31-Mar-08						LIFE LIMIT
SN:UNKNOWN	HRS	0	20000		20000		17089.7	
	AFL	0	27000		27000		24783	
PROC. REF: AMM 12-B-27-20-04-00A-920A-A								
27-30/141 ^S	EXAMINE ELEVATORS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
27-30/247 ^S	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
27-30/248 ^S	EXAMINE ELEVATOR STATIC DISCHARGERS							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								PKG:21
27-30/249 ^S	ELEVATOR CONTROL SYSTEM - INSPECTION/ CHECK							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-30-00-00A-313A-A								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30/250 ^S	CHECK ELEVATOR CABLE TENSION							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-30-00-00A-903A-A							PKG:20	
27-30/251 ^S	FUNCTIONAL TEST ELEVATOR							Service ATA:27
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-27-30-00-00A-903A-A							PKG:21	
27-30/333 ^S	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED							Service ATA:27
	MOS/MSC	03-Apr-09	A/R					
	HRS	100.8						
	AFL	101						
PROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)							Service ATA:27
PN:PN	MOS/MSC	31-Mar-08	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-27-30-00-00A-903A-A								
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE							Service ATA:27
	MOS	31-Mar-08					AIRWORTHINESS	
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-30-00-00A-310A-A								
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS							Service ATA:27
	MOS	31-Mar-08					AIRWORTHINESS	
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-00-01-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-00-01-00A-352A-A								
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-27-30-05-00A-353A-A								
27-30/448	FLIGHT CONTROL CABLES, ELEVATOR							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-30-01-00A-920A-A								
27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-30-02-00A-920A-A								
27-30/450	STICK PUSHER CABLES							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-30/514 ^S	EXAMINE - ELEVATOR STOPS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-55-20-01-00A-904B-A								
PKG:20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (CMR)							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
	HRS	2910.1	3000		5910.1		2999.8	
WC#: 27.021	AFL	2216						
PROC. REF: AMM 12-B-27-40-00-00A-903A-A								
27-40/142 ^S	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-40-00-00A-903A-A								
								PKG:17
27-40/252 ^S	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-40-01-00A-313A-A								
								PKG:20
27-40/26	OVERHAUL PITCH TRIM ACTUATOR							Service ATA:27
PN:978.73.14.203	MOS	01-Sep-20	60		30-Sep-25		313 d	OVERHAUL
SN:2321	HRS	2059.1	5000		7059.1		4148.8	
	AFL	1534						
PROC. REF: GENERIC NO REF								
27-40/291 ^S	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM							Service ATA:27
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-40-00-00A-903A-A								
								PKG:16
27-40/292 ^S	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-40-00-00A-903A-A								
								PKG:20
27-40/3	REPLACE PITCH TRIM ACTUATOR							Service ATA:27
PN:978.73.14.203	MOS	01-Sep-20						LIFE LIMIT
SN:2321	HRS	2059.1	20000		22059.1		19148.8	
	AFL	1534	27000		28534		26317	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7)							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	10000	TSN 0	10000		7089.7	
WC#: 27.036	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-40-02-00A-920A-A								
27-40/574	DISCARD MANUAL PITCH TRIM RELAYS (P/N 974.20.01.221) K161D2 K161E2 ON LH RELAY PANEL A161							Service ATA:27
PN:974.20.01.221	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	DISCARD
SN:UNKNOWN	HRS	2910.1	1200 (+10%/-10%)		4110.1	4230.1	1199.8 (+120)	
	AFL	2216						
PROC. REF: GENERIC NO REF								
27-50/143 ^S	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION							Service ATA:27
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:15 ,16,17,18,19,20,21
27-50/144 ^S	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
27-50/253 ^S	EXAMINE FLAPS ELECTRICAL BONDING STRAPS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
27-50/254 ^S	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
27-50/255 ^S	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-27-50-00-00A-903A-A								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/28	FLAP POWER DRIVE UNIT							Component ATA:27
PN:9787320003	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:683	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7089.7 (+500)	
WC#: 27.030	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	11283 (+500)	
PROC. REF: AMM 12-B-27-50-01-00A-920A-A								
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT							Component ATA:27
PN:9450202205	MOS	31-Mar-08		TSN 0				DISCARD
SN:S6111	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7089.7 (+500)	
WC#: 27.060	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	11283 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT							Component ATA:27
PN:9450202206	MOS	31-Mar-08		TSN 0				DISCARD
SN:S6085	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7089.7 (+500)	
WC#: 27.060	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	11283 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT							Component ATA:27
PN:9450202205	MOS	31-Mar-08		TSN 0				DISCARD
SN:S6112	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7089.7 (+500)	
WC#: 27.070	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	11283 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				DISCARD
SN:UNKNOWN	HRS	0	10000 (+500/-500)	TSN 0	10000	10500	7089.7 (+500)	
WC#: 27.070	AFL	0	13500 (+500/-500)	TSN 0	13500	14000	11283 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-A								
27-50/386	FLAP MECHANISM - EXAMINE							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-27-51-00-00A-353A-A								
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								
27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
	PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A							
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS							Service ATA:27
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
	PROC. REF: AMM 12-B-27-51-01-00A-353A-A, AMM 12-B-27-51-02-00A-353A-A, AMM 12-B-27-51-03-00A-353A-A							
27-50/414	LEFT HAND FLAP							Component ATA:27
PN:5575012003	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:794P	HRS	0	25000	TSN 0	25000	25000	22089.7	
WC#: 57.060	AFL	0	30000	TSN 0	30000	30000	27783	
	PROC. REF: GENERIC NO REF							
27-50/414	RIGHT HAND FLAP							Component ATA:27
PN:5575012004	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:794P	HRS	0	25000	TSN 0	25000	25000	22089.7	
WC#: 57.060	AFL	0	30000	TSN 0	30000	30000	27783	
	PROC. REF: GENERIC NO REF							
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	AIRWORTHINESS
	HRS	2910.1	600 (+10%/-10%)		3510.1	3570.1	599.8 (+60)	
	AFL	2216						
	PROC. REF: AMM 12-B-27-51-00-00A-313A-A							
27-50/443 ^S	SERVICE FLAP UP AND DOWN LIMIT SWITCHES							Service ATA:27
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-12-20-07-00A-902A-A							

PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/451	LEFT INBOARD FLAP TENSION RODS							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-50/451	LEFT MID FLAP TENSION ROD							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-50/451	LEFT OUTBOARD FLAP TENSION ROD							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-50/451	RIGHT INBOARD FLAP TENSION ROD							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-50/451	RIGHT MID FLAP TENSION ROD							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								
27-50/451	RIGHT OUTBOARD FLAP TENSION ROD							Component ATA:27
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/475 ^S		RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						Service ATA:27
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:15 ,16,17,18,19,20,21	
27-50/485		LEFT INBOARD FLAP ACTUATOR						Component ATA:27
PN:9787320309	MOS	31-Mar-08		TSN 0				DISCARD
SN:2907	HRS	0	20000	TSN 0	20000		17089.7	
WC#: 27.040	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485		LEFT OUTBOARD FLAP ACTUATOR						Component ATA:27
PN:9787320309	MOS	31-Mar-08		TSN 0				DISCARD
SN:2872	HRS	0	20000	TSN 0	20000		17089.7	
WC#: 27.041	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485		RIGHT INBOARD FLAP ACTUATOR						Component ATA:27
PN:9787320309	MOS	31-Mar-08		TSN 0				DISCARD
SN:2905	HRS	0	20000	TSN 0	20000		17089.7	
WC#: 27.050	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/485		RIGHT OUTBOARD FLAP ACTUATOR						Component ATA:27
PN:9787320309	MOS	31-Mar-08		TSN 0				DISCARD
SN:2883	HRS	0	20000	TSN 0	20000		17089.7	
WC#: 27.051	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-27-50-03-00A-920A-A								
27-50/495		BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR						Service ATA:27
PN:9787320309	MOS	21-Nov-23	24 (+10%/-10%)		30-Nov-25	12-Feb-26	374 d (+74)	
SN:2907	HRS	2764.6	2400 (+10%/-10%)		5164.6	5404.6	2254.3 (+240)	
WC#: 27.040	AFL	2083	3200 (+10%/-10%)		5283	5603	3066 (+320)	
PROC. REF: AMM 12-B-27-50-03-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/495	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	21-Nov-23	24 (+10%/-10%)		30-Nov-25	12-Feb-26	374 d (+74)	
SN:2872	HRS	2764.6	2400 (+10%/-10%)		5164.6	5404.6	2254.3 (+240)	
WC#: 27.041	AFL	2083	3200 (+10%/-10%)		5283	5603	3066 (+320)	
PROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/495	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	21-Nov-23	24 (+10%/-10%)		30-Nov-25	12-Feb-26	374 d (+74)	
SN:2905	HRS	2764.6	2400 (+10%/-10%)		5164.6	5404.6	2254.3 (+240)	
WC#: 27.050	AFL	2083	3200 (+10%/-10%)		5283	5603	3066 (+320)	
PROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/495	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	21-Nov-23	24 (+10%/-10%)		30-Nov-25	12-Feb-26	374 d (+74)	
SN:2883	HRS	2764.6	2400 (+10%/-10%)		5164.6	5404.6	2254.3 (+240)	
WC#: 27.051	AFL	2083	3200 (+10%/-10%)		5283	5603	3066 (+320)	
PROC. REF: AMM 12-B-27-50-03-00A-313A-A								
27-50/506	OVERHAUL LEFT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	31-Mar-08						OVERHAUL
SN:2907	HRS	0	5000 (+10%/-10%)		5000	5500	2089.7 (+500)	
WC#: 27.040	AFL	0	7000 (+500/-500)		7000	7500	4783 (+500)	
PROC. REF: GENERIC NO REF								
27-50/506	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	31-Mar-08						OVERHAUL
SN:2872	HRS	0	5000 (+10%/-10%)		5000	5500	2089.7 (+500)	
WC#: 27.041	AFL	0	7000 (+500/-500)		7000	7500	4783 (+500)	
PROC. REF: GENERIC NO REF								
27-50/506	OVERHAUL RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	31-Mar-08						OVERHAUL
SN:2905	HRS	0	5000 (+10%/-10%)		5000	5500	2089.7 (+500)	
WC#: 27.050	AFL	0	7000 (+500/-500)		7000	7500	4783 (+500)	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50/506	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	31-Mar-08						OVERHAUL
SN:2883	HRS	0	5000 (+10%/-10%)		5000	5500	2089.7 (+500)	
WC#: 27.051	AFL	0	7000 (+500/-500)		7000	7500	4783 (+500)	
PROC. REF: GENERIC NO REF								
27-50/576 ^S	LUBRICATE LEFT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	15-Nov-24	12 (+10%/-10%)					
SN:2907	HRS	2910.1	300 (+10%/-10%)					
WC#: 27.040	AFL	2216						
PROC. REF: AMM 12-B-27-50-00-00A-902A-A								PKG:17
27-50/576 ^S	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	15-Nov-24	12 (+10%/-10%)					
SN:2872	HRS	2910.1	300 (+10%/-10%)					
WC#: 27.041	AFL	2216						
PROC. REF: AMM 12-B-27-50-00-00A-902A-A								PKG:17
27-50/576 ^S	LUBRICATE RIGHT INBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	15-Nov-24	12 (+1m/-1m)					
SN:2905	HRS	2910.1	300 (+10%/-10%)					
WC#: 27.050	AFL	2216						
PROC. REF: AMM 12-B-27-50-00-00A-902A-A								PKG:17
27-50/576 ^S	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:9787320309	MOS	15-Nov-24	12 (+1m/-1m)					
SN:2883	HRS	2910.1	300 (+10%/-10%)					
WC#: 27.051	AFL	2216						
PROC. REF: AMM 12-B-27-50-00-00A-902A-A								PKG:17
270003	HORIZONTAL TAIL ASSY							Component ATA:27
PN:5551012037	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-55-10-01-00A-920A-A								
270015	ELEVATOR LH ASSY							Component ATA:27
PN:5552012039	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:828	HRS	0		TSN 0				
WC#: 27.015	AFL	0		TSN 0				
PROC. REF: AMM 12-B-55-20-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270023	ELEVATOR RH ASSY							Component ATA:27
PN:5552012040	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:824	HRS	0		TSN 0				
WC#: 27.023	AFL	0		TSN 0				
PROC. REF: AMM 12-B-55-20-01-00A-920A-A								
270025	RUDDER TRIM LINEAR ACTUATOR							Component ATA:27
PN:9787318132	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1690	HRS	0		TSN 0				
WC#: 27.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-25-01-00A-920A-A								
270030	FIN ASSY							Component ATA:27
PN:5553012039	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
WC#: 27.031	AFL	0		TSN 0				
PROC. REF: AMM 12-B-55-30-01-00A-920A-A								
270033	RUDDER ASSY							Component ATA:27
PN:5554012040	MOS/MSC	18-Dec-12	O/C	TSN 0				
SN:6009S	HRS	418.4		TSN 0				
WC#: 27.033	AFL			TSN 0				
PROC. REF: AMM 12-B-55-40-01-00A-920A-A								
270035	FLAP CONTROL AND WARNING UNIT							Component ATA:27
PN:9787320017	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:122346	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-05-00A-920A-A								
270040 ^U	FLEXSHAFT,FLAP,OUTB,B70016707.2A							Component ATA:27
PN:9450202206	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:S6081	HRS	0		TSN 0				
	AFL	0		TSN 0				
270041	RUDDER BELLCRANK							Component ATA:27
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-20-04-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270045	LH INBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:077077DY	HRS	0		TSN 0				
WC#: 27.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270050	LH ROTATION TRANSMITTER							Component ATA:27
PN:9787320602	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1095	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270060	LH OUTBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:077047DZ	HRS	0		TSN 0				
WC#: 27.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270070	RH INBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:077072DW	HRS	0		TSN 0				
WC#: 27.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270075	RH ROTATION,C70016705 TRANSMITTER							Component ATA:27
PN:9787320602	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1096	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
270080	KTA2810,TRIM ADAPTER							Component ATA:27
PN:9859912156	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:KTA2810-1023	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-22-10-07-00A-920A-A, AMM 12-B-22-10-07-00A-920B-A								
270090	AILERON LINEAR ACTUATOR							Component ATA:27
PN:9787318132	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1698	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-15-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270095	RH OUTBOARD TRANSMITTER							Component ATA:27
PN:9787320021	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:077042DZ	HRS	0		TSN 0				
WC#: 27.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-27-50-06-00A-920A-A								
274020	PITCH TRIM ACTUATOR							Component ATA:27
PN:978.73.14.203	MOS/MSC	01-Sep-20	H/T	TSN 0				
SN:2321	HRS	2059.1		TSN 0				
	AFL	1534		TSN 0				
PROC. REF: AMM 12-B-27-40-01-00A-920A-A								
274030	MANUAL PITCH TRIM RELAYS							Component ATA:27
PN:974.20.01.221	MOS/MSC	15-Nov-24	H/T					
SN:UNKNOWN	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								
ATA 28 - FUEL								
28-10/145 ^S	EXAMINE FUEL TANK FILLER CAPS							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
28-10/146 ^S	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-28-10-02-00A-901A-A								PKG:17
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE							Service ATA:28
	MOS	09-Jan-15						
	HRS	902.7	2400 (+10%/-10%)		3302.7	3542.7	392.4 (+240)	
WC#: 28.029	AFL	648						
PROC. REF: AMM 12-B-28-10-01-00A-903A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20/147 ^S	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-28-20-07-00A-903A-A							PKG:17	
28-20/148 ^S	REMOVE/CLEAN FUEL FILTER ELEMENT							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-28-20-01-00A-920A-A, AMM 12-B-28-20-01-00A-250A-A							PKG:17	
28-20/149 ^S	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N)							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:19	
28-20/150 ^S	EXAMINE ENGINE DRIVEN PUMP							Service ATA:28
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:17	
28-20/256 ^S	FUEL SYSTEM COMPONENTS - EXAMINE AS FAR AS POSSIBLE WITH THOSE ACCESS PANELS OPENED / REMOVED IN THIS INSPECTION PACKAGE							Service ATA:28
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF							PKG:21	
28-20/32	OVERHAUL ENGINE DRIVEN PUMP							Service ATA:28
PN:9688451108	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:B5048	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 28.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280005	LOW PRESSURE FUEL PUMP							Component ATA:28
PN:9688451108	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B5048	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-03-00A-920A-A								
280010	FUEL FLOW TRANSMITTER							Component ATA:28
PN:975.35.12.108	MOS/MSC	17-Oct-17	O/C	TSO 0				
SN:0928-028AM	HRS	1541.9		TSO 0				
WC#: 28.130	AFL	1085		TSO 0				
PROC. REF: AMM 12-B-73-30-01-00A-920A-A								
280015	FIREWALL FUEL,SHUT-OFF VALVE							Component ATA:28
PN:9638722301	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2060	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-08-00A-920A-A								
280020	MAINTENANCE FUEL SHUT-OFF VALVE							Component ATA:28
PN:9638722301	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2068	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-12-00A-920A-A								
280025	FUEL FILTER ASSY							Component ATA:28
PN:9683521001	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2007FFT2171	HRS	0		TSN 0				
WC#: 28.025	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-01-00A-920A-A								
280030	FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:9738114102	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1531	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-02-00A-920A-A								
280035	EJECTOR,TRANSFER LH PUMP							Component ATA:28
PN:9688471104	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B3886	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-05-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280040	EJECTOR,DELIVERY LH PUMP							Component ATA:28
PN:9688471105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B4174	HRS	0		TSN 0				
WC#: 28.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-06-00A-920A-A								
280045	FUEL QUANTITY OUTER LH SENSOR							Component ATA:28
PN:9753731220	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:114	HRS	0		TSN 0				
WC#: 28.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280050	FUEL QUANTITY,CENTRAL LH SENSOR							Component ATA:28
PN:9753731219	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:111	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280055	FUEL QUANTITY,INNER LH SENSOR							Component ATA:28
PN:9753731218	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:109	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280060	FUEL QUANTITY,COLLECTOR LH SENSOR							Component ATA:28
PN:9753731217	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280065	FUEL,BOOSTER LH PUMP							Component ATA:28
PN:9688411405	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B6770	HRS	0		TSN 0				
WC#: 28.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-04-00A-920A-A								
280070	EJECTOR,TRANSFER RH PUMP							Component ATA:28
PN:9688471104	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B3879	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-05-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280075	EJECTOR,DELIVERY RH PUMP							Component ATA:28
PN:9688471105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B4171	HRS	0		TSN 0				
WC#: 28.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-20-06-00A-920A-A								
280080	FUEL QUANTITY,COLLECTOR RH SENSOR							Component ATA:28
PN:9753731217	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:114	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280085	FUEL QUANTITY,INNER RH SENSOR							Component ATA:28
PN:9753731218	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:130	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280090	FUEL QUANTITY,CENTRAL RH SENSOR							Component ATA:28
PN:975.37.31.252	MOS/MSC	04-Jan-24	O/C	TSN 0				
SN:3589	HRS	2775.7		TSN 0				
WC#: 28.070	AFL	2096		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280095	FUEL QUANTITY,OUTER RH SENSOR							Component ATA:28
PN:9753731220	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:115	HRS	0		TSN 0				
WC#: 28.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-28-40-01-00A-920A-A								
280100	FUEL,BOOSTER RH PUMP							Component ATA:28
PN:968.84.11.405	MOS/MSC	16-Jun-22	O/C					
SN:B4810	HRS	2437.7						
WC#: 28.050	AFL	1805						
PROC. REF: AMM 12-B-28-20-04-00A-920A-A								
280105	TOP CHECK VALVE							Component ATA:28
PN:9630423105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2002	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280110	BOTTOM CHECK VALVE							Component ATA:28
PN:9630423105	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1994	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
280115	LH FUEL QUANTITY, TANK HARNESS							Component ATA:28
PN:9753731333	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:162	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
280120	RH FUEL QUANTITY, TANK HARNESS							Component ATA:28
PN:9753731333	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:161	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 29 - HYDRAULIC POWER								
29-10/151 ^S	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE							Service ATA:29
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-29-10-04-00A-313A-A								PKG:19
29-10/153 ^S	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY							Service ATA:29
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-29-00-00-00A-902A-A								PKG:17
29-10/257 ^S	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED							Service ATA:29
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-29-00-00-00A-902A-A								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-10/258 ^S		CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)						Service ATA:29
PN:9603001291	MOS	15-Nov-24	12 (+10%/-10%)					
SN:862	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-29-10-02-00A-901A-A								PKG:20
29-10/259 ^S		POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL						Service ATA:29
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
29-10/316 ^S		HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.						Service ATA:29
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-29-00-00-00A-902A-A								PKG:17
29-10/418		NITROGEN ACCUMULATOR (IF INSTALLED)						Component ATA:29
PN:9603001291	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:862	HRS	0	25000	TSN 0	25000		22089.7	
WC#: 29.020	AFL	0	30000	TSN 0	30000		27783	
PROC. REF: AMM 12-B-29-10-02-00A-920A-A								
29-10/471 ^S		CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)						Service ATA:29
PN:9603001291	MOS	21-Nov-23	24 (+10%/-10%)					
SN:862	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-29-10-02-00A-901A-A								PKG:21
290015		PRESSURE GAGE SWITCH						Component ATA:29
PN:973.81.14.307	MOS/MSC	15-Dec-21	O/C	TSN 0				
SN:1779	HRS	2266.5		TSN 0				
WC#: 29.050	AFL	1668		TSN 0				
PROC. REF: GENERIC NO REF								
290025		SERVICE SELECTOR VALVE						Component ATA:29
PN:9603001261	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:G0711040A	HRS	0		TSN 0				
WC#: 29.070	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-30-03-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
290030	PRESSURE GAUGE							Component ATA:29
PN:9656188101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:07-0925637	HRS	0		TSN 0				
WC#: 29.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
290040	HAND PUMP							Component ATA:29
PN:9688582111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:814	HRS	0		TSN 0				
WC#: 29.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-29-20-01-00A-920A-A								
290050	PRESSURE NITROGEN SWITCH							Component ATA:29
PN:9738114306	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1000	HRS	0		TSN 0				
WC#: 29.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-29-10-07-00A-920A-A								
291010	HYDRAULIC POWER PACK							Component ATA:29
PN:9603001154	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:G0740233	HRS	0		TSN 0				
WC#: 29.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-29-10-01-00A-920A-A								
ATA 30 - ICE AND RAIN PROTECTION								
30-10/154 ^S	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-30-10-00-00A-313A-A								PKG:17
30-10/155 ^S	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-30-20-00-00A-903A-A								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10/260 ^S	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-30-10-00-00A-903A-A, AMM 12-B-30-10-00-00A-903B-A							PKG:20	
30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1							Service ATA:30
	MOS	15-Nov-24	6 (+10%/-10%)		31-May-25	18-Jun-25	191 d (+18)	
	HRS	2910.1						
WC#: 30.010	AFL	2216						
PROC. REF: GENERIC NO REF								
30-20/156 ^S	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:17	
30-20/261 ^S	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
30-30/329 ^S	FUNCTIONAL TEST PROBES DE-ICE SYSTEM							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-30-30-20-00A-903A-A							PKG:19	
30-40/262 ^S	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM							Service ATA:30
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: AMM 12-B-30-40-00-00A-903A-A							PKG:21	
30-60/158 ^S	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM							Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-30-60-00-00A-313A-A, AMM 12-B-30-60-00-00A-313B-A							PKG:19	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-60/159 ^S		OPERATIONAL TEST PROPELLER DE-ICE SYSTEM						Service ATA:30
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
				PROC. REF: AMM 12-B-30-60-00-00A-903A-A, AMM 12-B-30-60-00-00A-903B-A, AMM 12-B-30-60-00-00A-903C-A, AMM 12-B-30-60-00-00A-903D-A				PKG:19
300005		PROP DE-ICE CONTROLLER						Component ATA:30
PN:9682913227	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:U0748	HRS	0		TSN 0				
WC#: 30.140	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				
300010		LPMI LINEAR ACTUATOR						Component ATA:30
PN:9787315302	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:B71853	HRS	0		TSN 0				
WC#: 30.150	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				
300015		REGULATOR-RELIEVER ASSY						Component ATA:30
PN:9598901012	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:74369	HRS	0		TSN 0				
WC#: 30.160	AFL	0		TSN 0				
				PROC. REF: GENERIC NO REF				
300020		L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE						Component ATA:30
PN:9598901008	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N074057	HRS	0		TSN 0				
WC#: 30.110	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-30-10-02-00A-920A-A				
300025		L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE						Component ATA:30
PN:9598901008	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N074058	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-30-10-02-00A-920A-A				
300035		L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE						Component ATA:30
PN:9598901008	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N074042	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-30-10-02-00A-920A-A				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N074041	HRS	0		TSN 0				
WC#: 30.130	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-10-02-00A-920A-A								
300045	EMPENAGE PRESSURE GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:4192	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300050	WATER SEPARATOR							Component ATA:30
PN:9598901010	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N075136	HRS	0		TSN 0				
WC#: 30.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300055	DE-ICING SYSTEM TIMER							Component ATA:30
PN:9598901014	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:U1465	HRS	0		TSN 0				
WC#: 30.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-60-01-00A-920A-A								
300060	LEFT WINDSHIELD DE ICE CONTROLLER							Component ATA:30
PN:9728132202	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:122418	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-40-01-00A-920A-A								
300065	RIGHT WINDSHIELD DE ICE CONTROLLER							Component ATA:30
PN:9728132202	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:122426	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-40-01-00A-920A-A								
300090	LH HORIZ STAB DE-ICER BOOT							Component ATA:30
PN:9598901035	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MAA560	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-16-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300095	RH HORIZ STAB DE-ICER BOOT							Component ATA:30
PN:9598901036	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MAAN370	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-16-01-00A-920A-A								
300100	RH INBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901032	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MAAM660	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300105	RH OUTBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901034	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MZVK800	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300110	LH AOA PLATE TEMP CONTROLLER							Component ATA:30
PN:9754421417	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:U1759	HRS	0		TSN 0				
WC#: 30.170	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-30-21-00A-920A-A								
300115	LH INBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901031	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MAAA230	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300120	LH OUTBD-WING DE-ICER BOOT							Component ATA:30
PN:9598901033	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:MAAM760	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-14-01-00A-920A-A								
300125	RH AOA PLATE TEMP CONTROLLER							Component ATA:30
PN:9754421417	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:U1764	HRS	0		TSN 0				
WC#: 30.170	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-30-21-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:4125	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:4170	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:4180	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH							Component ATA:30
PN:9738114312	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:4158	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE							Component ATA:30
PN:9598901008	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:N074040	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-30-10-02-00A-920A-A								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-30/421 ^S	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)							Service ATA:31
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-31-30-01-00A-903A-A								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310050	DIGITAL CLOCK							Component ATA:31
PN:999.61.11.214	MOS/MSC	22-Jan-13	O/C					
SN:UNKNOWN	HRS	500.2						
WC#: 31.040	AFL	301						
PROC. REF: AMM 12-B-31-20-12-00A-920A-A								
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER							Component ATA:31
PN:9859912178	MOS/MSC	02-May-08	O/C	TSO 0				
SN:KMC2210-1054	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE							Component ATA:31
PN:7036410-1902	MOS/MSC	12-Jan-17	O/C					
SN:09045590	HRS	1362.4						
	AFL							
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310075-3 ^U	MAU ADVANCED GRAPHIC MODULE							Component ATA:31
PN:7036410-1904	MOS/MSC	16-Jan-24	O/C	TSR 0				
SN:11047663	HRS	2780.4		TSR 0				
	AFL	2101		TSR 0				
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD							Component ATA:31
PN:7038231-1801	MOS/MSC	22-Jan-14	O/C	TSN 0				
SN:13105687	HRS	655		TSN 0				
	AFL	400		TSN 0				
PROC. REF: GENERIC NO REF								
310090	KMC2220 MF CONTOLLER							Component ATA:31
PN:071-01598-0501	MOS/MSC	04-Apr-09	O/C	TSO 0				
SN:KMC2220-1090	HRS	100.8		TSO 0				
	AFL			TSO 0				
PROC. REF: GENERIC NO REF								
310095	PILOT KMC 2210 DISPLAY CONTROLLER							Component ATA:31
PN:9859912178	MOS/MSC	02-May-08	O/C	TSO 0				
SN:KMC2210-1040	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE							Component ATA:31
PN:7028432-1902	MOS/MSC	09-Nov-09	O/C					
SN:907A796	HRS	173.7						
	AFL							
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310100-2 ^U	MAU ACTUATOR I/O PROC MODULE							Component ATA:31
PN:9859912144	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7115317	HRS	0		TSN 0				
	AFL	0		TSN 0				
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE							Component ATA:31
PN:7028432-1902	MOS/MSC	09-Nov-09	O/C					
SN:909A941	HRS	173.7						
WC#: 31.230	AFL							
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310105	MODULAR AVIONICS ,12SLOT UNIT							Component ATA:31
PN:9859912147	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7112213	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-31-41-00-00A-920A-A								
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD							Component ATA:31
PN:7038231-1801	MOS/MSC	22-Jan-14	O/C	TSN 0				
SN:13105678	HRS	655		TSN 0				
	AFL	400		TSN 0				
PROC. REF: GENERIC NO REF								
310115	NO. 1 LH MAU POWER SUPPLY MODULE							Component ATA:31
PN:7024440-1901	MOS/MSC	22-Jan-14	O/C					
SN:0809C052	HRS	655						
	AFL	400						
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310120	NO. 2 RH MAU POWER SUPPLY MODULE							Component ATA:31
PN:9859912143	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7119444	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310125	MAU DUAL GENERIC I/O MODULE							Component ATA:31
PN:7038622-1901	MOS/MSC	25-Oct-17	O/C					
SN:15021344	HRS	1541.9						
	AFL	1085						
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT							Component ATA:31
PN:7036333-1906	MOS/MSC	27-Feb-20	O/C					
SN:14011243	HRS	1981.9						
	AFL							
PROC. REF: AMM 12-B-31-42-00-00A-920A-A								
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	02-May-08	O/C	TSO 0				
SN:1890118850	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	02-May-08	O/C	TSO 0				
SN:1890117863	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	02-May-08	O/C	TSO 0				
SN:1890113208	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY							Component ATA:31
PN:9859912103	MOS/MSC	02-May-08	O/C	TSO 0				
SN:1890117867	HRS	23.1		TSO 0				
	AFL	10		TSO 0				
PROC. REF: GENERIC NO REF								
310155	REV CTL PNL,4-POT DISPLAY							Component ATA:31
PN:9728121141	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:12	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE							Component ATA:31
PN:9858314204	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7097395	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE							Component ATA:31
PN:9858314204	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7107614	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
31C001 ^U	OVHD CTRL PNL PC-12E (R/L/P)							Component ATA:31
PN:9728132116	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2	HRS	0		TSN 0				
	AFL	0		TSN 0				
31C002 ^U	PC-12E APX100 APEX SYS SOFTWARE							Component ATA:31
PN:9859912142	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:10098992	HRS	0		TSN 0				
	AFL	0		TSN 0				
ATA 32 - LANDING GEAR								
32-10/162 ^S	LUBRICATE MAIN LANDING GEAR							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-12-20-04-00A-902A-A								
							PKG:19	
32-10/163 ^S	EXAMINE MAIN LANDING GEAR LEGS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
							PKG:19	
32-10/164 ^S	EXAMINE MAIN LANDING GEAR COMPARTMENTS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
							PKG:19	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/165 ^S	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-32-10-00-00A-902A-A							PKG:19
32-10/263 ^S	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:20
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1	2400 (+10%/-10%)		5310.1	5550.1	2399.8 (+240)	
WC#: 32.010	AFL	2216						
	PROC. REF: AMM 12-B-32-10-00-00A-313A-A, AMM 12-B-32-10-00-00A-313B-A							
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY							Component ATA:32
PN:5321012051	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0031	HRS	0		TSN 0				
WC#: 32.070	AFL	0		TSN 0				
	PROC. REF: GENERIC NO REF							
32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY							Component ATA:32
PN:5321012052	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0031	HRS	0		TSN 0				
WC#: 32.070	AFL	0		TSN 0				
	PROC. REF: GENERIC NO REF							
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION							Service ATA:32
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
	PROC. REF: GENERIC NO REF							
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION							Service ATA:32
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT							Service ATA:32
	MOS	15-Dec-21	72		31-Dec-27		1135 d	
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT							Service ATA:32
	MOS	15-Dec-21	72		31-Dec-27		1135 d	
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A								
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 12-B-32-10-00-00A-310B-A							
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS							Service ATA:32
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 12-B-32-10-00-00A-310B-A							
32-10/644	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION (HYDRAULIC LANDING GEAR)							Service ATA:32
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:20000		20000		17089.7	
	AFL	0	T:27000		27000		24783	
	PROC. REF: AMM NO REF							
32-10/644	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION (HYDRAULIC LANDING GEAR)							Service ATA:32
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:20000		20000		17089.7	
	AFL	0	T:27000		27000		24783	
	PROC. REF: AMM NO REF							
32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS							Service ATA:32
PN:PN	MOS/MSC	15-Nov-24	12 (+1m/-1m) / T/C		30-Nov-25	31-Dec-25	374 d (+31)	
SN:UNKNOWN	HRS	2910.1						
	AFL	2216						
	PROC. REF: AMM 12-B-12-20-06-00A-902A-A							
32-10/80	LUBRICATE MAIN AND NOSE WHEEL BEARINGS							Service ATA:32
	MOS/MSC	15-Nov-24	12 (+10%/-10%) / T/C		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1						
WC#: 32.030	AFL	2216						
	PROC. REF: AMM 12-B-12-20-06-00A-902A-A							
32-10/80	LUBRICATE NOSE WHEEL BEARINGS							Service ATA:32
PN:9595602301	MOS/MSC	15-Nov-24	12 (+1m/-1m) / T/C		30-Nov-25	31-Dec-25	374 d (+31)	
SN:955	HRS	2910.1						
	AFL	2216						
	PROC. REF: AMM 12-B-12-20-06-00A-902A-A							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS							Service ATA:32
PN:PN	MOS/MSC	15-Nov-24	12 (+1m/-1m) / T/C		30-Nov-25	31-Dec-25	374 d (+31)	
SN:UNKNOWN	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-12-20-06-00A-902A-A								
32-20/166 ^S	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-32-20-00-00A-902A-A								
								PKG:19
32-20/167 ^S	LUBRICATE NOSE LANDING GEAR							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-12-20-04-00A-902A-A								
								PKG:19
32-20/168 ^S	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING.							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
								PKG:19
32-20/169 ^S	EXAMINE NOSE LANDING GEAR COMPARTMENT							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
								PKG:19
32-20/265 ^S	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
								PKG:20
32-20/335	NOSE LANDING GEAR TORQUE TUBE							Component ATA:32
PN:532.50.12.064	MOS/MSC	16-Jan-18	O/C	TSN 0				
SN:UNKNOWN	HRS	1583.8		TSN 0				
WC#: 32.190	AFL	1224		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK							Service ATA:32
PN:PN	MOS	15-Nov-24						AIRWORTHINESS
SN:UNKNOWN	HRS	2910.1	300 (+10%)		3210.1	3240.1	299.8 (+30)	
WC#: 32.195	AFL	2216	400 (+10%)		2616	2656	399 (+40)	
PROC. REF: AMM 12-B-32-20-06-00A-313A-A								
32-20/403	NOSE LANDING GEAR - OVERHAUL							Component ATA:32
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	T:25000 (+500/-500)	TSN 0	25000	25500	22089.7 (+500)	
WC#: 32.200	AFL	0	T:30000 (+500/-500)	TSN 0	30000	30500	27783 (+500)	
PROC. REF: GENERIC NO REF								
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK							Component ATA:32
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000	25000	22089.7	
	AFL	0	30000	TSN 0	30000	30000	27783	
PROC. REF: AMM 12-B-32-20-05-00A-920A-A								
32-30/170 ^S	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-32-30-00-00A-903A-A								PKG:20
32-30/417	LEFT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR							Component ATA:32
PN:960.30.01.105	MOS	22-Jun-17		TSO 0				LIFE LIMIT
SN:0829EFGH	HRS	1460.2	25000	TSN 9741.4, TSO 0	16718.8		13808.5	
WC#: 32.040	AFL	1053	30000	TSN 3178, TSO 0	27875		25658	
PROC. REF: AMM 12-B-32-30-01-00A-920A-A								
32-30/417	RIGHT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR							Component ATA:32
PN:9603001105	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:1691H	HRS	0	25000	TSN 0	25000	25000	22089.7	
WC#: 32.040	AFL	0	30000	TSN 0	30000	30000	27783	
PROC. REF: AMM 12-B-32-30-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-30/425 ^S	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:19
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	15-Dec-21	72		31-Dec-27		1135 d	
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS							Service ATA:32
	MOS	15-Dec-21	72		31-Dec-27		1135 d	
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-32-10-00-00A-310B-A, AMM 12-B-32-10-00-00A-310A-A								
32-30/518	LEFT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE							Service ATA:32
	MOS/MSC		N/A					
	HRS	EFF						
	AFL							
PROC. REF: GENERIC NO REF								
32-30/518	RIGHT MAIN LANDING GEAR ACTUATOR BOTTOM ATTACH BOLTS P/N 532.10.12.218 - REPLACE							Service ATA:32
	MOS/MSC		N/A					
	HRS	EFF						
	AFL							
PROC. REF: GENERIC NO REF								
32-40/171 ^S	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40/172 ^S	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-12-10-04-00A-902A-A							PKG:17	
32-40/173 ^S	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:19	
32-40/174 ^S	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-12-10-04-00A-902A-A							PKG:17	
32-40/175 ^S	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:17	
32-40/176 ^S	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY							Service ATA:32
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-12-10-02-00A-902A-A							PKG:17	
32-50/404	EXAMINE - NLG STEERING MECHANISM							Service ATA:32
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 32.230	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-32-50-00-00A-310A-A								
32-50/404 ^U	EXAMINE - NLG STEERING MECHANISM							Service ATA:32
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 32.230	AFL	0	T:42000		42000		39783	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320005	PILOT LH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5169	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320006	STEREER SELECTOR,LANDING GEAR VALVE							Component ATA:32
PN:960.30.01.274	MOS/MSC	02-Jun-16	O/C	TSO 0				
SN:0855C	HRS	1240.3		TSO 0				
WC#: 29.040	AFL			TSO 0				
PROC. REF: AMM 12-B-32-30-03-00A-920A-A								
320010	PILOT RH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5171	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320015	PARK BRAKE VALVE							Component ATA:32
PN:9594751121	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2559	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-05-00A-920A-A								
320020	NOSE WHEEL							Component ATA:32
PN:9595602301	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:955	HRS	0		TSN 0				
WC#: 32.150	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-02-00A-920A-A								
320021	NOSE LANDING GEAR TIRE							Component ATA:32
PN:021-327-0	MOS/MSC	21-Nov-23	O/C	TSN 0				
SN:UNKNOWN	HRS	2764.6		TSN 0				
WC#: 32.155	AFL	2083		TSN 0				
PROC. REF: AMM 12-B-32-40-02-00A-920A-A								
320022	LEFT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.160	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320023	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:025-350-0	MOS/MSC	31-Aug-23	O/C	TSN 0				
SN:UNKNOWN	HRS	2715.7		TSN 0				
WC#: 32.160	AFL	2046		TSN 0				
PROC. REF: AMM NO REF								
320024	RIGHT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.165	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320025	SHIMMY DAMPER ASSY							Component ATA:32
PN:5322012215	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0015	HRS	0		TSN 0				
WC#: 32.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-50-01-00A-920A-A								
320026	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:850T0603	MOS/MSC	22-Nov-22	O/C	TSN 0				
SN:UNKNOWN	HRS	2558.5		TSN 0				
WC#: 32.165	AFL	1910		TSN 0				
PROC. REF: AMM NO REF								
320030	COPILOT LH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5176	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320035	COPILOT RH BRAKE MASTER CYLINDER							Component ATA:32
PN:9594751131	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5178	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-04-00A-920A-A								
320040	NOSE FOLDING STRUT SPRING PACK ASSY							Component ATA:32
PN:5322012249	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0029	HRS	0		TSN 0				
WC#: 32.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-50-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320045	NOSE LANDING GEAR STRUT ASSY							Component ATA:32
PN:5322012040	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:ST-0029	HRS	0		TSN 0				
WC#: 32.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-50-02-00A-920A-A								
320055	RIGHT SHOCK ABSORBER ASSY							Component ATA:32
PN:5321012211	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0017	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-A								
320060	LH BRAKE ASSY							Component ATA:32
PN:2-1674-1	MOS/MSC	22-Nov-22	O/C	TSO 0				
SN:0441	HRS	2558.5		TSO 0				
WC#: 32.050	AFL	1910		TSO 0				
PROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-A								
320065	INNER LEFT WHEEL & COVER ASSY							Component ATA:32
PN:9595601502	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1753	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-01-00A-920A-A								
320080	LEFT SHOCK ABSORBER ASSY							Component ATA:32
PN:5321012211	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:SI-0013	HRS	0		TSN 0				
WC#: 32.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-10-03-00A-920A-A, AMM 12-B-32-10-03-00A-920B-A								
320085	RH BRAKE ASSY							Component ATA:32
PN:2-1674-1	MOS/MSC	22-Nov-22	O/C	TSO 0				
SN:0101	HRS	2558.5		TSO 0				
WC#: 32.050	AFL	1910		TSO 0				
PROC. REF: AMM 12-B-32-40-03-00A-920A-A, AMM 12-B-32-40-03-00A-920B-A								
320090	INNER RIGHT WHEEL & COVER ASSY							Component ATA:32
PN:9595601502	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1757	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-32-40-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH							Component ATA:32
PN:9733033113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH							Component ATA:32
PN:9733033113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:227	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
320110	MAIN LANDING GEAR 72A74-01 RH "WOW" PROXIMITY SWITCH							Component ATA:32
PN:9733033113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:342	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH							Component ATA:32
PN:973.30.33.116	MOS/MSC	02-Jan-13	O/C	TSN 0				
SN:3764	HRS	420.6		TSN 0				
	AFL	246		TSN 0				
PROC. REF: GENERIC NO REF								
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH							Component ATA:32
PN:9733033113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
320125	MAIN LANDING GEAR 72A74-01 LH "WOW" PROXIMITY SWITCH							Component ATA:32
PN:9733033113	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:337	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
320190	LEFT MAIN LANDING GEAR YOKE FITTING							Component ATA:32
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
320190	RIGHT MAIN LANDING GEAR YOKE FITTING							Component ATA:32
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
ATA 33 - LIGHTS								
33-40/177 ^S	OPERATIONAL TEST EXTERIOR LIGHTING							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-33-40-00-00A-903A-A								
PKG:17								
33-41/178 ^S	EXAMINE LANDING LIGHTS							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-33-41-01-00A-200B-A								
PKG:17								
33-42/179 ^S	EXAMINE TAXI LIGHTS							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-33-42-01-00A-200B-A								
PKG:17								
33-43/180 ^S	EXAMINE NAVIGATION AND STROBE LIGHTS							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
PKG:17								
33-44/181 ^S	EXAMINE RECOGNITION LIGHTS (IF INSTALLED)							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-33-44-00-00A-903A-A								
PKG:17								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-46/182 ^S	EXAMINE BEACON LIGHTS (IF INSTALLED)							Service ATA:33
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
330005	DIM UNIT							Component ATA:33
PN:9750215205	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:122198	HRS	0		TSN 0				
WC#: 33.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-10-04-00A-920A-A								
330010	DE-ICE LIGHT ASSY							Component ATA:33
PN:972.87.67.111	MOS/MSC	17-Jan-19	O/C	TSN 0				
SN:UNKNOWN	HRS	1764		TSN 0				
WC#: 33.010	AFL	1325		TSN 0				
PROC. REF: GENERIC NO REF								
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY							Component ATA:33
PN:9728787331	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18035	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-46-00-00A-920A-A								
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY							Component ATA:33
PN:9728787332	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18054	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-46-00-00A-920A-A								
330035	LH WING POWER SUPPLY UNIT							Component ATA:33
PN:9728787164	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:30963	HRS	0		TSN 0				
WC#: 33.070	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-03-00A-920A-A								
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY							Component ATA:33
PN:9728787322	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:31151	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
330045	RH WING POWER SUPPLY UNIT							Component ATA:33
PN:9728787164	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:30977	HRS	0		TSN 0				
WC#: 33.070	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-03-00A-920A-A								
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY							Component ATA:33
PN:972.87.87.322	MOS/MSC	21-Nov-23	O/C	TSN 0				
SN:5963457	HRS	2764.6		TSN 0				
WC#: 33.030	AFL	2083		TSN 0				
PROC. REF: AMM 12-B-33-43-02-00A-920A-A								
330055	NAVIGATION (FC), LED GREEN LIGHT							Component ATA:33
PN:9728787158	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:30363	HRS	0		TSN 0				
WC#: 33.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-01-00A-920A-A								
330060	NAVIGATION (FC), LED RED LIGHT							Component ATA:33
PN:9728787157	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:31170	HRS	0		TSN 0				
WC#: 33.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-01-00A-920A-A								
330065	NAVIGATION (FC), LED WHITE LIGHT							Component ATA:33
PN:9728787159	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:32147	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-43-01-00A-920A-A								
330070	NOSE LANDING GEAR TAXI LIGHT							Component ATA:33
PN:9728769402	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1331339	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-42-01-00A-920A-A								
330075	L/H 1X0005287-10 LANDING LIGHT							Component ATA:33
PN:9728769402	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1326487	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-33-41-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
330080	3060-S PULSELITE CONTROLLER							Component ATA:33
PN:9728769419	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:LSS01057	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 34 - NAVIGATION								
34-00/183 ^S	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS							Service ATA:34
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								
PKG:21								
34-00/184 ^S	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT							Service ATA:34
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
PKG:17								
34-11/185 ^S	EXAMINE PITOT TUBE							Service ATA:34
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
PKG:17								
34-11/186 ^S	EXAMINE STATIC PORTS							Service ATA:34
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								
PKG:17								
34-11/268 ^S	DRAIN PITOT AND STATIC SYSTEM							Service ATA:34
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-34-11-00-00A-901A-A								
PKG:20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11/343	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT							Service ATA:34
	MOS/MSC	15-Dec-21	N/A					
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-34-11-12-00A-313A-A								
34-11/82	LEAK CHECK STATIC SYSTEM							Service ATA:34
	MOS	21-Nov-23	24		30-Nov-25		374 d	
	HRS	2764.6						
WC#: 34.010	AFL	2083						
PROC. REF: AMM 12-B-34-11-00-00A-903A-A								
34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED)							Service ATA:34
	MOS	15-Nov-24	24 (+10%/-10%)		30-Nov-26	12-Feb-27	739 d (+74)	
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-34-21-00-00A-903A-A								
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)							Service ATA:34
	MOS/MSC	15-Dec-21	N/A					
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-34-14-00-00A-903B-A								
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)							Service ATA:34
	MOS	21-Nov-23	24		30-Nov-25		374 d	
	HRS	2764.6						
WC#: 34.050	AFL	2083						
PROC. REF: AMM 12-B-34-54-00-00A-903A-A, AMM 12-B-34-54-00-00A-903B-A, AMM 12-B-34-54-10-00A-903A-A, AMM 12-B-34-54-10-00A-903B-A								
340010	DME/IFF ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	06-Mar-19	O/C	TSN 0				
SN:261-126954	HRS	1796.8		TSN 0				
WC#: 34.080	AFL			TSN 0				
PROC. REF: AMM 12-B-34-52-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340020	MARKER ANTENNA							Component ATA:34
PN:9848110260	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:101-6571	HRS	0		TSN 0				
WC#: 34.100	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-32-01-00A-920A-A								
340055	WITH HARM FILTER,KN63 DME							Component ATA:34
PN:9859911101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:31474	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-52-01-00A-920A-A								
340065	WX-RADAR RT UNIT							Component ATA:34
PN:071-01519-0101	MOS/MSC	07-Aug-19	O/C	TSR 0				
SN:15614	HRS	1887.5		TSR 0				
WC#: 34.360	AFL			TSR 0				
PROC. REF: AMM 12-B-34-41-02-00A-920A-A								
340075	WX,VERTICAL ANTENNA							Component ATA:34
PN:9859911504	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5717	HRS	0		TSN 0				
WC#: 34.370	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-41-12-00A-920A-A								
340080	TRANSPONDER DME/IFF ANTENNA							Component ATA:34
PN:9848110240	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:261-77258	HRS	0		TSN 0				
WC#: 34.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-54-03-00A-920A-A								
340100	FRONT KA92 ANTENNA							Component ATA:34
PN:9859911200	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:49305033	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-57-02-00A-920A-A								
340101	REAR KA92 GPS ANTENNA							Component ATA:34
PN:9859911200	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:49305061	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-57-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340105	LH NAV/GS ANTENNA							Component ATA:34
PN:9848110280	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7438	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-51-03-00A-920A-A								
340131	KCM 805 CONFIGURATION MODULE							Component ATA:34
PN:9859911884	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18054	HRS	0		TSN 0				
WC#: 34.410	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-25-03-00A-920A-A								
340135	STANDBY MAGNETIC COMPASS							Component ATA:34
PN:9999880103	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:AT-859	HRS	0		TSN 0				
WC#: 34.130	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-21-00-00A-920A-A								
340140	RADOME							Component ATA:34
PN:9857900003	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:835	HRS	0		TSN 0				
WC#: 34.420	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-41-02-00A-920A-A, AMM 12-B-34-41-05-00A-920A-A								
340145	ANTENNA,VHF NAV COUPLER							Component ATA:34
PN:9848110412	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:5133	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: AMM 12-B-23-11-03-00A-920A-A								
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA							Component ATA:34
PN:9848129101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:543-41423	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-42-02-00A-920A-A								
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA							Component ATA:34
PN:9848129101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:543-41424	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-42-02-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA							Component ATA:34
PN:9859911869	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18681	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA							Component ATA:34
PN:9859911869	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18679	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER							Component ATA:34
PN:066-01153-0101	MOS/MSC	21-Jun-13	O/C					
SN:KRA405B-7177	HRS	529.7						
WC#: 34.310	AFL							
PROC. REF: AMM 12-B-34-42-01-00A-920A-A								
340230	RH NAV/GS ANTENNA							Component ATA:34
PN:9848110280	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7439	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-51-03-00A-920A-A								
340235	AOA SENSOR RH UNIT							Component ATA:34
PN:0012AC12	MOS/MSC	25-Jul-08	O/C					
SN:0675	HRS	37.1						
WC#: 34.330	AFL	24						
PROC. REF: GENERIC NO REF								
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT							Component ATA:34
PN:9859911505	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:18820	HRS	0		TSN 0				
WC#: 34.490	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340255	AOA SENSOR LH UNIT							Component ATA:34
PN:0012AC12	MOS/MSC	25-Jul-08	O/C					
SN:0741	HRS	37.1						
WC#: 34.330	AFL	24						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340265	DME/IFF--ATC DIV. ANTENNA							Component ATA:34
PN:9848110240	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:261-77091	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-54-03-00A-920A-A								
340270	LEFT PITOT STATIC TUBE							Component ATA:34
PN:PST305	MOS/MSC	20-Feb-19	O/C	TSN 0				
SN:AS07172476	HRS	1785.7		TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REF								
340275	RIGHT PITOT STATIC TUBE							Component ATA:34
PN:9651112302	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:815004	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340280	OUTBOARD KMG 7010 MAGNETOMETER							Component ATA:34
PN:9859912114	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1143	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-A								
340285	INBOARD KMG 7010 MAGNETOMETER							Component ATA:34
PN:9859912114	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1192	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-34-25-02-00A-920A-A, AMM 12-B-34-25-02-00A-920B-A								
340290	KMH920 TAWS B,TCAS 1 UNIT							Component ATA:34
PN:9859911887	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:KMH920-B1179	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340295	RH COAX SWITCH							Component ATA:34
PN:9859911371	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:13218	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340300	LH COAX SWITCH							Component ATA:34
PN:9859911371	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:13212	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340305	NO. 1 LH KGS200,GPS SENSOR UNIT							Component ATA:34
PN:066-01201-0105	MOS/MSC	04-Jan-24	O/C	TSR 0				
SN:KGS200-1006	HRS	2775.7		TSR 0				
	AFL	2096		TSR 0				
PROC. REF: AMM 12-B-34-57-01-00A-920A-A								
340310	NO. 2 KXP 2290 MODE S TRANSPONDER							Component ATA:34
PN:066-01198-0101	MOS/MSC	10-Jan-20	O/C					
SN:1046	HRS	1959.8						
	AFL							
PROC. REF: AMM 12-B-34-54-01-00A-920A-A								
340315	NO. 1 KXP 2290 MODE S TRANSPONDER							Component ATA:34
PN:066-01198-0101	MOS/MSC	10-Jan-20	O/C					
SN:1030	HRS	1959.8						
	AFL							
PROC. REF: AMM 12-B-34-54-01-00A-920A-A								
340320	LH OAT SENSOR							Component ATA:34
PN:5341312025	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2575	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
340325	RH OAT SENSOR							Component ATA:34
PN:975.11.21.306	MOS/MSC	19-Jul-13	O/C	TSN 0				
SN:UNKNOWN	HRS	553.6		TSN 0				
	AFL	330		TSN 0				
PROC. REF: GENERIC NO REF								
340335	NO. 2 RH KGS200,GPS SENSOR UNIT							Component ATA:34
PN:066-01201-0105	MOS/MSC	25-Jul-14	O/C					
SN:KGS200-1900	HRS	790						
	AFL							
PROC. REF: AMM 12-B-34-57-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
340340	STANDBY INSTRUMENT PANEL							Component ATA:34
PN:C16221JA01	MOS/MSC	15-Dec-21	O/C					
SN:C16221JA01	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-34-26-40-00A-920A-A								
340345	XM RADIO ANTENNA							Component ATA:34
PN:CI420-1	MOS/MSC	03-Apr-09	O/C	TSN 0				
SN:33271935	HRS	100.8		TSN 0				
	AFL	101		TSN 0				
PROC. REF: GENERIC NO REF								
340350	XM RADIO, XMD 157, UNIT							Component ATA:34
PN:4092743-901	MOS/MSC	27-Oct-20	O/C	TSR 0				
SN:81800006	HRS	2091		TSR 0				
	AFL			TSR 0				
PROC. REF: GENERIC NO REF								
341070	AMERICAN DATABASE CARD							Component ATA:34
PN:071-00167-0101	MOS/MSC	23-Dec-20	O/C					
SN:UNKNOWN	HRS	2096.9						
	AFL	1549						
PROC. REF: GENERIC NO REF								
34C003 ^U	KSG 7200 DUAL CHANNEL ADAHRS							Component ATA:34
PN:065-00188-5104	MOS/MSC	15-Dec-21	O/C					
SN:KSG7200-B2502	HRS	2266.5						
	AFL	1668						
ATA 35 - OXYGEN								
35-10/187 ^S	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE							Service ATA:35
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
35-10/188 ^S	CHECK OXYGEN SYSTEM CONTENTS							Service ATA:35
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-10/269 ^S	EXAMINE OXYGEN PIPELINES AND EQUIPMENT							Service ATA:35
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
35-10/458 ^S	OPERATIONAL TEST CREW OXYGEN SYSTEM							Service ATA:35
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-35-00-00-00A-903A-A, AMM 12-B-35-00-00-00A-903B-A							PKG:20	
35-10/6	OXYGEN BOTTLE							Component ATA:35
PN:895-06022	MOS	15-Dec-21	180		31-May-36		4209 d	AIRWORTHINESS
SN:C21070373	HRS	2266.5		TSN 0				
WC#: 35.010	AFL	1668		TSN 0				
Manufacture Date:: 01-May-21			PROC. REF: AMM 12-B-35-10-01-00A-920A-A					
35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE							Service ATA:35
PN:895-06022	MOS	01-May-21	60		31-May-26		556 d	AIRWORTHINESS
SN:C21070373	HRS							
WC#: 35.010	AFL							
HydroCheck Date: : 01-May-21		PROC. REF: GENERIC NO REF						
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)							Service ATA:35
	MOS	15-Nov-24						
	HRS	2910.1	600		3510.1		599.8	
	AFL	2216						
PROC. REF: AMM 12-B-35-00-00-00A-903A-A								
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS							Service ATA:35
	MOS	15-Nov-24	36 (+10%/-10%)		30-Nov-27	17-Mar-28	1104 d (+108)	
	HRS	2910.1						
WC#: 35.010	AFL	2216						
PROC. REF: AMM 12-B-35-20-00-00A-313A-A								
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY							Component ATA:35
PN:MC10-06-125	MOS/MSC	22-Nov-22	O/C	TSO 2				
SN:B000308	HRS	2558.5		TSO 0				
WC#: 35.040	AFL	1910		TSO 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY							Component ATA:35
PN:MC10-06-125	MOS/MSC	22-Nov-22	O/C	TSO 4				
SN:SE17628	HRS	2558.5		TSO 0				
WC#: 35.040	AFL	1910		TSO 0				
PROC. REF: GENERIC NO REF								
350030	PRESSURE,GAGE,OXYGEN SWITCH							Component ATA:35
PN:9738114401	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:805	HRS	0		TSN 0				
WC#: 35.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
350035	CONTR,3-POSITION,37071-03 VALVE							Component ATA:35
PN:9633211101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2787	HRS	0		TSN 0				
WC#: 35.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-35-20-04-00A-920A-A								
350080	NO. 1 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350081	NO. 2 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350082	NO. 3 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350083	NO. 4 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350084	NO. 5 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350085	NO. 6 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350086	NO. 7 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350087	NO. 8 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
350088	NO. 9 PASSENGER OXYGEN MASK CARTRIDGE							Component ATA:35
PN:PN	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM NO REF								
ATA 45 - CENTRAL MAINT SYSTEM								
45-45/454 ^S	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD							Service ATA:45
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-45-45-00-00A-551A-A								
PKG:20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 46 - INFORMATION SYSTEMS									
46-26/320 ^S	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES							Service	ATA:46
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	300 (+10%/-10%)						
	AFL	2216							
	PROC. REF: AMM 12-B-46-30-05-00A-903A-A, AMM 12-B-46-30-06-00A-903A-A								PKG:17
46-26/321 ^S	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES							Service	ATA:46
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	300 (+10%/-10%)						
	AFL	2216							
	PROC. REF: AMM 12-B-46-30-02-00A-903A-A								PKG:17
ATA 52 - DOORS									
52-10/189 ^S	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK							Service	ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	600 (+10%/-10%)						
	AFL	2216							
	PROC. REF: GENERIC NO REF								PKG:19
52-10/190 ^S	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS							Service	ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	600 (+10%/-10%)						
	AFL	2216							
	PROC. REF: GENERIC NO REF								PKG:19
52-10/191 ^S	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS							Service	ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	600 (+10%/-10%)						
	AFL	2216							
	PROC. REF: GENERIC NO REF								PKG:19
52-10/192 ^S	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT							Service	ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)						
	HRS	2910.1	600 (+10%/-10%)						
	AFL	2216							
	PROC. REF: GENERIC NO REF								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10/271 ^S	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR							Service ATA:52
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-52-10-00-00A-310A-A								
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 52.100	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-52-00-01-00A-353A-A								
52-10/405 ^U	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 52.100	AFL	0	T:42000		42000		39783	
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:25000 (+500/-500)		25000	25500	22089.7 (+500)	
WC#: 52.110	AFL	0	T:30000 (+500/-500)		30000	30500	27783 (+500)	
PROC. REF: AMM 12-B-52-10-01-00A-353A-A								
52-10/406 ^U	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:25000		25000		22089.7	
WC#: 52.110	AFL	0	T:30000		30000		27783	
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED							Service ATA:52
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 52.010	AFL	1668						
PROC. REF: AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-A, AMM 12-B-52-10-00-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20/272 ^S	EXAMINE EMERGENCY DOOR (DOOR REMOVED)							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
52-20/273 ^S	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR							Service ATA:52
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-52-20-00-00A-310A-A								
52-30/193 ^S	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:19	
52-30/194 ^S	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-52-30-00-00A-313A-A							PKG:19	
52-30/195 ^S	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:19	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30/274 ^S	EXAMINE CARGO DOOR							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR							Service ATA:52
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-52-30-00-00A-310A-A								
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 52.120	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-52-30-00-01A-353A-A								
52-30/407 ^U	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 52.120	AFL	0	T:42000		42000		39783	
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:25000 (+500/-500)		25000	25500	22089.7 (+500)	
WC#: 52.130	AFL	0	T:30000 (+500/-500)		30000	30500	27783 (+500)	
PROC. REF: AMM 12-B-52-30-01-00A-353A-A								
52-30/408 ^U	EDDY CURRENT INSPECTION - CARGO DOOR SKIN							Service ATA:52
	MOS	31-Mar-08						
	HRS	0	T:25000		25000		22089.7	
WC#: 52.130	AFL	0	T:30000		30000		27783	
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS							Component ATA:52
PN:PN	MOS	31-Mar-08		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0	13000	TSN 0	13000		10089.7	
WC#: 52.020	AFL	0	17000	TSN 0	17000		14783	
PROC. REF: AMM 12-B-52-30-07-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM							Service ATA:52
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 52.030	AFL	1668						
				PROC. REF: AMM 12-B-52-30-00-00A-313A-A, AMM 12-B-25-21-03-00A-920A-A, AMM 12-B-25-22-03-00A-920A-A				
52-70/275 ^S	OPERATIONAL TEST DOOR WARNING SYSTEM							Service ATA:52
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
				PROC. REF: AMM 12-B-52-70-00-00A-903A-A				
								PKG:20
520005	PASSENGER DOOR							Component ATA:52
PN:5520512007	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
WC#: 52.050	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-52-10-01-00A-920A-A, AMM 12-B-52-10-01-00A-920B-A				
520010	FREIGHT OF 10SERIE DOOR ASSY							Component ATA:52
PN:5520512010	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
WC#: 52.040	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-52-30-01-00A-920A-A				
520015	EMERGENCY 6 SERIE EXIT							Component ATA:52
PN:5520512009	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
WC#: 52.060	AFL	0		TSN 0				
				PROC. REF: AMM 12-B-52-20-01-00A-920A-A				
ATA 53 - FUSELAGE								
53-00/196 ^S	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.							Service ATA:53
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
				PROC. REF: GENERIC NO REF				
								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/276 ^S	EXAMINE REAR PRESSURE BULKHEAD							Service ATA:53
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:20
53-00/277 ^S	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH FLOOR PANELS REMOVED							Service ATA:53
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:20
53-00/278 ^S	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION							Service ATA:53
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: GENERIC NO REF							PKG:21
53-00/279 ^S	EXAMINE BAGGAGE COMPARTMENT							Service ATA:53
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
	PROC. REF: GENERIC NO REF							PKG:21
53-00/280 ^S	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION							Service ATA:53
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:20
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)							Service ATA:53
	MOS/MSC	31-Mar-08	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
	PROC. REF: GENERIC NO REF							
53-00/337 ^S	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24							Service ATA:53
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-53-20-02-00A-313A-A							PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-10-06-01A-353A-A								
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-10-00-00A-310A-A								
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-20-00-00A-310A-A								
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-30-00-00A-310A-A								
53-00/355	EXAMINE - ANTENNA STRUCTURE							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-00-00-00A-310A-A								
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:28300		28300		25389.7	
	AFL	0	T:37000		37000		34783	
PROC. REF: AMM 12-B-53-00-00-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-00-00-00A-353A-A								
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-57-00-03-00A-353A-A								
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-53-20-02-00A-353A-A								
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								
53-00/419	EDDY CURRENT INSPECTION - FRAME 40							Service ATA:53
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 53.210	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								
53-00/419 ^U	EDDY CURRENT INSPECTION - FRAME 40							Service ATA:53
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 53.210	AFL	0	T:42000		42000		39783	
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE							Service ATA:53
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	20000		20000		17089.7	
WC#: 53.010	AFL	0	27000		27000		24783	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)							Service ATA:53
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 53.030	AFL	1668						
PROC. REF: GENERIC NO REF								
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)							Service ATA:53
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 53.040	AFL	1668						
PROC. REF: GENERIC NO REF								
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED							Service ATA:53
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 53.070	AFL	1668						
PROC. REF: GENERIC NO REF								
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS							Service ATA:53
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 53.050	AFL	1668						
PROC. REF: GENERIC NO REF								
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES							Service ATA:53
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 53.060	AFL	1668						
PROC. REF: GENERIC NO REF								
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA							Service ATA:53
	MOS/MSC	15-Dec-21	N/A					
	HRS	2266.5						
	AFL	1668						
PROC. REF: AMM 12-B-53-30-01-00A-313A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
530070	FUSELAGE AB 1003 TEIL1							Component ATA:53
PN:5530512114	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	20000		20000		17089.7	
	AFL	0	27000		27000		24783	
PROC. REF: GENERIC NO REF								
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)							Service ATA:55
	MOS/MSC	31-Mar-08	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
55-10/197 ^S	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE							Service ATA:55
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
55-10/319 ^S	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT							Service ATA:55
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-55-00-00-00A-313A-A								PKG:20
55-10/415	HORIZONTAL STABILIZER							Component ATA:55
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	TSN 0	25000	25000	22089.7	
	AFL	0	30000	TSN 0	30000	30000	27783	
PROC. REF: AMM 12-B-55-10-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10/638	HORIZONTAL STABILIZER - EXAMINE WITH BORESCOPE							Service ATA:55
	MOS	31-Mar-08	T:240		31-Mar-28		1226 d	
	HRS	0	T:10000		10000		7089.7	
	AFL	0						
PROC. REF: AMM 12-B-55-10-01-00A-312A-A								
55-10/640	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.139)							Service ATA:55
	MOS	22-Nov-22	72 (+10%/-10%)		30-Nov-28	06-Jul-29	1470 d (+218)	
	HRS	2558.5						
	AFL	1910						
PROC. REF: AMM 12-B-55-00-00-01A-313A-A								
55-10/641	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT BOLTS (P/N 555.10.12.158 AND .178)							Service ATA:55
	MOS	22-Nov-22	120 (+6m/-10%)		30-Nov-32	31-May-33	2931 d (+182)	
	HRS	2558.5						
	AFL	1910						
PROC. REF: AMM 12-B-55-00-00-01A-313A-A								
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)							Service ATA:55
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
	AFL	1668						
PROC. REF: GENERIC NO REF								
55-20/362	EXAMINE LEFT WING ELEVATOR							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-20-00-00A-310A-A								
55-20/362	EXAMINE RIGHT WING ELEVATOR							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-20-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-20-01-00A-353A-A								
55-30/198 ^S	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.							Service ATA:55
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-55-00-01-00A-664A-A								PKG:17
55-30/281 ^S	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS							Service ATA:55
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
55-30/369	EXAMINE - VERTICAL STABILIZER							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-30-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-30-03-00A-353A-A, AMM 12-B-53-30-02-00A-353A-A								
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-00-00-00A-353A-A								
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-30-02-00A-353A-A								
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40							Service ATA:55
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 55.190	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-55-30-03-00A-353A-A								
55-30/420 ^U	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40							Service ATA:55
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 55.190	AFL	0	T:42000		42000		39783	
55-40/373	EXAMINE - RUDDER							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-40-00-00A-310A-A								
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES							Service ATA:55
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-55-40-05-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40/410	EXAMINE - RUDDER TRIM TAB							Service ATA:55
	MOS	31-Mar-08						
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 55.200	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-55-40-04-00A-310A-A								
55-40/410 ^U	EXAMINE - RUDDER TRIM TAB							Service ATA:55
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 55.200	AFL	0	T:42000		42000		39783	
ATA 56 - WINDOWS								
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED							Service ATA:56
	MOS/MSC	31-Mar-08	A/R					AIRWORTHINESS
	HRS	0						
WC#: 56.020	AFL	0						
PROC. REF: GENERIC NO REF								
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED							Service ATA:56
	MOS/MSC	31-Mar-08	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-56-00-00-00A-313A-A								
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)							Service ATA:56
PN:9598110109	MOS/MSC	31-Mar-08	A/R					
SN:07120H4282	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-A								
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (RH) (INNER LAMINATION CRACKED)							Service ATA:56
PN:9598110110	MOS/MSC	31-Mar-08	A/R					
SN:07208H4457	HRS	0						
	AFL	0						
PROC. REF: AMM 12-B-56-11-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)							Service ATA:56
PN:9598110109	MOS/MSC	31-Mar-08	A/R					
SN:07120H4282	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)							Service ATA:56
PN:9598110110	MOS/MSC	31-Mar-08	A/R					
SN:07208H4457	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
56-11/200 ^S	EXAMINE WINDSHIELD LH AND RH							Service ATA:56
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-56-00-00-00A-313A-A								PKG:17
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS							Service ATA:56
	MOS	22-Nov-22	120 (+6m/-6m)		30-Nov-32	31-May-33	2931 d (+182)	
	HRS	2558.5	11000 (+500/-500)		13558.5	14058.5	10648.2 (+500)	
	AFL	1910						
PROC. REF: AMM 12-B-56-11-02-00A-313A-A								
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED							Service ATA:56
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-53-10-16-00A-310A-A, AMM 12-B-56-11-01-00A-310A-A, AMM 12-B-56-11-02-00A-310A-A								
56-11/517 ^S	COCKPIT DV WINDOW - MAKE SURE THAT YOU CAN OPEN AND CLOSE THE DV WINDOW WITH ONE HAND							Service ATA:56
	MOS	15-Nov-24	12					
	HRS	2910.1	1200					
	AFL	2216						
PROC. REF: GENERIC NO REF, AMM NO REF								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20/201 ^S		EXAMINE COCKPIT AND CABIN WINDOWS						Service ATA:56
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
					PROC. REF: AMM 12-B-56-00-00-00A-313A-A			
560015		SIDE,LH WINDOW						Component ATA:56
PN:9598110111	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:07118H4163	HRS	0	TSN 0					
WC#: 56.090	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-11-02-00A-920A-A			
560020		SIDE,RH WINDOW						Component ATA:56
PN:9598110112	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:07200H3706	HRS	0	TSN 0					
WC#: 56.090	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-11-02-00A-920A-A			
560025		RH NO 1 CABIN WINDOW						Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7624	HRS	0	TSN 0					
WC#: 56.060	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-20-01-00A-920A-A			
560030		RH NO 2 CABIN WINDOW						Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7625	HRS	0	TSN 0					
WC#: 56.060	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-20-01-00A-920A-A			
560035		RH NO 3 CABIN WINDOW						Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7626	HRS	0	TSN 0					
WC#: 56.070	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-20-01-00A-920A-A			
560040		RH NO 4 CABIN WINDOW						Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7627	HRS	0	TSN 0					
WC#: 56.070	AFL	0	TSN 0					
					PROC. REF: AMM 12-B-56-20-01-00A-920A-A			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
560045	RH NO 5 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7630	HRS	0		TSN 0				
WC#: 56.080	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560050	LH NO 1 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7590	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560055	LH NO 2 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7600	HRS	0		TSN 0				
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560060	LH NO 3 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7602	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560065	LH NO 4 CABIN WINDOW							Component ATA:56
PN:5562012029	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7606	HRS	0		TSN 0				
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-20-01-00A-920A-A								
560070	DV-WINDOW ASSY							Component ATA:56
PN:5561412099	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:07334H8199	HRS	0		TSN 0				
WC#: 56.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-14-01-00A-920A-A								
561010	LEFT HAND WINDSHIELD ASSY, (LH)							Component ATA:56
PN:9598110109	MOS/MSC	31-Mar-08	O/C	TSN 0				AIRWORTHINESS
SN:07120H4282	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-11-01-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561011	RIGHT HAND WINDSHIELD ASSY, (RH)							Component ATA:56
PN:9598110110	MOS/MSC	31-Mar-08	O/C	TSN 0				AIRWORTHINESS
SN:07208H4457	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-56-11-01-00A-920A-A								
ATA 57 - WINGS								
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	20000		20000		17089.7	
WC#: 57.010	AFL	0	27000		27000		24783	
PROC. REF: AMM 12-B-57-00-00-00A-040A-A								
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	20000		20000		17089.7	
WC#: 57.010	AFL	0	27000		27000		24783	
PROC. REF: AMM 12-B-57-00-00-00A-040A-A								
57-00/202 ^S	EXAMINE WING EXTERNAL SURFACES							Service ATA:57
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
57-00/282 ^S	EXAMINE WING TIP STATIC DISCHARGERS							Service ATA:57
	MOS	21-Nov-23	24 (+10%/-10%)					
	HRS	2764.6	2400 (+10%/-10%)					
	AFL	2083						
PROC. REF: GENERIC NO REF								PKG:21
57-00/283 ^S	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS REMOVED							Service ATA:57
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/284 ^S	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE							Service ATA:57
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)							Service ATA:57
	MOS/MSC	31-Mar-08	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)							Service ATA:57
	MOS/MSC	31-Mar-08	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-57-00-00-00A-310A-A								
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-57-00-00-00A-310A-A								
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:30000		30000		27089.7	
	AFL	0	T:39000		39000		36783	
PROC. REF: AMM 12-B-57-00-03-00A-353A-A, AMM 12-B-57-00-03-01A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353C-A								
57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353C-A								
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353A-A								
57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353A-A								
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-05-00A-353A-A								
57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-05-00A-353A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353B-A								
57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:25000		25000		22089.7	
	AFL	0	T:30000		30000		27783	
PROC. REF: AMM 12-B-57-20-10-00A-353B-A								
57-00/412	EXAMINE - WING TIPS							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500 (+500/-500)		32500	33000	29589.7 (+500)	
WC#: 57.170	AFL	0	T:42000 (+500/-500)		42000	42500	39783 (+500)	
PROC. REF: AMM 12-B-57-33-00-00A-310A-A								
57-00/412 ^U	EXAMINE - WING TIPS							Service ATA:57
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 57.170	AFL	0	T:42000		42000		39783	
57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES							Service ATA:57
	MOS	31-Mar-08						
	HRS	0	T:25000 (+500/-500)		25000	25500	22089.7 (+500)	
WC#: 57.180	AFL	0	T:30000 (+500/-500)		30000	30500	27783 (+500)	
PROC. REF: AMM 12-B-57-20-01-00A-353A-A								
57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES							Service ATA:57
	MOS	31-Mar-08						
	HRS	0	T:25000 (+500/-500)		25000	25500	22089.7 (+500)	
	AFL	0	T:30000 (+500/-500)		30000	30500	27783 (+500)	
PROC. REF: AMM 12-B-57-20-01-00A-353A-A								
57-00/413 ^U	EDDY CURRENT INSPECTION - WING SKIN AROUND DRAIN HOLES							Service ATA:57
	MOS	31-Mar-08						
	HRS	0	T:25000		25000		22089.7	
WC#: 57.180	AFL	0	T:30000		30000		27783	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	16000		16000		13089.7	
	AFL	0	22500		22500		20283	
PROC. REF: AMM 12-B-57-20-10-00A-353D-A								
57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	16000		16000		13089.7	
	AFL	0	22500		22500		20283	
PROC. REF: AMM 12-B-57-20-10-00A-353D-A								
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)							Service ATA:57
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 57.020	AFL	1668						
PROC. REF: GENERIC NO REF								
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)							Service ATA:57
	MOS	15-Dec-21	72 (+6m/-6m)		31-Dec-27	30-Jun-28	1135 d (+182)	MILD CORROSION ZONE
	HRS	2266.5	6000 (+500/-500)		8266.5	8766.5	5356.2 (+500)	
WC#: 57.030	AFL	1668						
PROC. REF: GENERIC NO REF								
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED							Service ATA:57
	MOS	12-Apr-19	120 (+6m/-6m)		30-Apr-29	31-Oct-29	1621 d (+184)	
	HRS	1827.9	11000 (+500/-500)		12827.9	13327.9	9917.6 (+500)	
WC#: 57.040	AFL	1350						
PROC. REF: AMM 12-B-57-00-00-00A-313A-A								
57-60/393	EXAMINE - RIGHT WING AILERON							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-57-60-00-00A-310A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60/393	EXAMINE -LEFT WING AILERON							Service ATA:57
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:32500		32500		29589.7	
	AFL	0	T:42000		42000		39783	
PROC. REF: AMM 12-B-57-60-00-00A-310A-A								
57-60/411 ^U	EXAMINE - AILERON TRIM TAB							Service ATA:57
	MOS	31-Mar-08						
	HRS	0	T:32500		32500		29589.7	
WC#: 57.190	AFL	0	T:42000		42000		39783	
570005	AILERON LH 10A SERIE ASSY							Component ATA:57
PN:5570512017	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2794P	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-57-60-02-00A-920A-A								
570010	AILERON RH 10A SERIE ASSY							Component ATA:57
PN:5570512018	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:2794P	HRS	0		TSN 0				
WC#: 57.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-57-60-02-00A-920A-A								
570050	L/H WING							Component ATA:57
PN:5570512135	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-57-00-00-00A-520A-A, AMM 12-B-57-00-00-00A-520B-A, AMM 12-B-57-00-00-00A-720A-A, AMM 12-B-57-00-00-00A-720B-A								
570055	R/H WING							Component ATA:57
PN:5570512136	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:794P	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 12-B-57-00-00-00B-520A-A, AMM 12-B-57-00-00-00B-520B-A, AMM 12-B-57-00-00-00B-720A-A, AMM 12-B-57-00-00-00B-720B-A								
ATA 61 - PROPELLERS/PROPULSORS								
61-20/286 ^S	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS							Service ATA:61
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 61 - PROPELLERS/PROPULSORS									
	AFL	2216							
			PROC. REF: GENERIC NO REF				PKG:20		
610000	NO. 1 PROPELLER - OVERHAUL							Service	ATA:61
	MOS	11-Feb-21	72		28-Feb-27		829 d	OVERHAUL	
	HRS	2114.4	4000		(6114.4) 6064.5		3154.2		
611010	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION							Service	ATA:61
	MOS	15-Nov-24	12		30-Nov-25		374 d		
	HRS	2910.1	400		(3310.1) 3260.2		349.9		
611020	NO. 1 PROPELLER - LUBRICATE PROPELLER							Service	ATA:61
	MOS	15-Nov-24	12		30-Nov-25		374 d		
	HRS	2910.1	400		(3310.1) 3260.2		349.9		
611025	NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service	ATA:61
	MOS	15-Nov-24	12		30-Nov-25		374 d		
	HRS	2910.1	400		(3310.1) 3260.2		349.9		
611101	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE							Component	ATA:61
PN:E10477SK	MOS/MSC	27-May-14	O/C	TSO 0					
SN:K64346	HRS	739.7		TSN 739.7, TSO 0					
PROC. REF: GENERIC NO REF									
611102	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE							Component	ATA:61
PN:E10477SK	MOS/MSC	27-May-14	O/C	TSO 0					
SN:K64349	HRS	739.7		TSN 739.7, TSO 0					
PROC. REF: GENERIC NO REF									
611103	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE							Component	ATA:61
PN:E10477SK	MOS/MSC	27-May-14	O/C	TSO 0					
SN:K64345	HRS	739.7		TSN 739.7, TSO 0					
PROC. REF: GENERIC NO REF									
611104	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE							Component	ATA:61
PN:E10477SK	MOS/MSC	27-May-14	O/C	TSO 0					
SN:K64348	HRS	739.7		TSN 739.7, TSO 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
611110	NO. 1 PROPELLER - PERIODIC COIN-TAP INSPECTIONS FOR COMPOSITE BLADES - EXPOSED SECTION OF BLADE							Service ATA:61
	MOS/MSC	17-Jan-08	N/A					NOT APPLICABLE
	HRS	0						
611120	NO. 1 PROPELLER - PERIODIC COIN-TAP INSPECTIONS FOR COMPOSITE BLADES - EROSION SHIELD SURFACE							Service ATA:61
	MOS/MSC	17-Jan-08	N/A					NOT APPLICABLE
	HRS	0						
611140	NO. 1 PROPELLER - INSPECT BLADES							Service ATA:61
	MOS	17-Jan-08						
	HRS	0	T:10000		(10000) 9950.1		7039.8	
611230 ^S	NO. 1 PROPELLER - DE-ICE SYSTEM 200 HOUR/12 MONTH INSPECTION							Service ATA:61
	MOS	17-Jan-08	12					
	HRS	0	200					
PROC. REF: AMM 30-60-01, MM 30-61-80, MM 30-61-80								
611250	NO. 1 PROPELLER - DE-ICE COMPONENT OVERHAUL							Service ATA:61
	MOS	03-Feb-21	72		28-Feb-27		829 d	OVERHAUL
	HRS	2101.6	4000		(6101.6) 6051.7		3141.4	
PROC. REF: GENERIC NO REF								
612010	NO. 1 ENGINE - PROPELLER GOVERNOR							Component ATA:61
	PN:3049558-01	MOS	31-Mar-08	TSN 0				
	SN:15475671	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)
		ENC	0		TSN 0			
PROC. REF: EMM 61-20-00								
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR							Component ATA:61
	PN:3037685	MOS	31-Mar-08	TSN 0				
	SN:15460203	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)
		ENC	0		TSN 0			
PROC. REF: EMM 61-20-00								
619000	NO. 1 PROPELLER - PRE-FLIGHT CHECKS							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					
	HRS	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
619010	NO. 1 PROPELLER - OPERATIONAL CHECKS							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					
	HRS	0						
619020	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
619030	NO. 1 PROPELLER - LIGHTNING STRIKE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
								PROC. REF: MM 30-61-80
619040	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
								PROC. REF: MM 30-61-80
619050	NO. 1 PROPELLER - FIRE/HEAT DAMAGE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
								PROC. REF: MM 30-61-80
619060	NO. 1 PROPELLER - SUDDEN STOPPAGE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
619070	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
619080	NO. 1 PROPELLER - LONG TERM STORAGE							Service ATA:61
	MOS/MSC	17-Jan-08	A/R					
	HRS	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
61PR1	NO. 1 PROPELLER							Component ATA:61
PN:HC-E4A-3D	MOS/MSC	27-May-14	PP/C					
SN:KX561	HRS	739.7		TSN 739.7				
WC#: 61.PR1	AFL							
PROC. REF: AMM 12-B-61-10-01-00A-920A-A, AMM 12-B-61-10-01-00A-920B-A								
ATA 71 - POWER PLANT								
71-00/101 ^S	OPERATIONAL TEST POWER PLANT TORQUE LIMITER							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
WC#: 71.010	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903G-A								
PKG:19								
71-00/102 ^S	OPERATIONAL TEST POWER PLANT PERFORMANCE							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903H-A								
PKG:19								
71-00/103	PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
WC#: 71.040	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-250A-A								
71-00/104	PERFORM COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-250A-A								
71-00/105	PERFORM TURBINE WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-250A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/107 ^S	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
WC#: 71.030	AFL	2216						
PROC. REF: AMM 12-B-71-00-03-00A-250A-A							PKG:19	
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		17089.7	
WC#: 71.050	AFL	0	27000	TSN 0	27000		24783	
PROC. REF: AMM 12-B-71-00-05-00A-920A-A								
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS							Service ATA:71
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	11000		11000		8089.7	
WC#: 71.050	AFL	0						
PROC. REF: GENERIC NO REF								
71-00/204 ^S	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903A-A							PKG:15 ,16,17,18,19,20,21	
71-00/205 ^S	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:20	
71-00/209 ^S	ENGINE DRAIN MAST AND TANK - EXAMINE THE DRAIN MAST FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN THE COLLECTOR TANK							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF							PKG:17	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/287 ^S	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS.							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: AMM 12-B-71-00-00-00A-903A-A							PKG:15 ,16,17,18,19,20,21	
71-00/301 ^S	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY.							Service ATA:71
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-54-20-02-00A-664A-A							PKG:20	
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 71.063	AFL	0		TSN 0				
PROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 71.064	AFL	0		TSN 0				
PROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 71.061	AFL	0		TSN 0				
PROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 71.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-71-00-00-00A-920A-B								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY							Component ATA:71
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 71.062	AFL	0		TSN 0				
PROC. REF: AMM 12-B-71-00-00-00A-920A-B								
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION							Service ATA:71
	MOS	31-Mar-08						AIRWORTHINESS
	HRS	0	T:26600		26600		23689.7	
	AFL	0	T:35000		35000		32783	
PROC. REF: AMM 12-B-71-00-05-00A-352A-A								
71-00/432 ^S	EXAMINE POWER PLANT AND ACCESSORIES, REFER TO P&WC EMM CHAPTER 72-00-00 PERIODIC INSPECTION AND DO THE MINOR AND TIME LIMITED INSPECTION ITEMS							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:15 ,16,17,18,19,20,21
71-00/476 ^S	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:15 ,16,17,18,19,20,21
71-10/207 ^S	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:15 ,16,17,18,19,20,21
71-10/208 ^S	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR							Service ATA:71
	MOS/MSC	15-Nov-24	A/R					
	HRS	2910.1						
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:15 ,16,17,18,19,20,21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710005	UPPER LH ENGINE VIBRATION ISOLATOR							Component ATA:71
PN:5712012106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3410	HRS	0		TSN 0				
WC#: 71.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710011	NO. 1 ENGINE - OVERHAUL							Service ATA:71
	MOS	31-Mar-08						OVERHAUL
	HRS	0	3500 (+200)		(3500) 3500	3700	589.7 (+200)	
	ENC	0						
PROC. REF: GENERIC NO REF								
710015	UPPER CENTER ENGINE VIBRATION ISOLATOR							Component ATA:71
PN:5712012106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3414	HRS	0		TSN 0				
WC#: 71.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710019 ^S	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE							Service ATA:71
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-30-05								PKG:0
710021	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:71
	MOS	12-Apr-19						
	HRS	1827.9	1750 (+250)		(3577.9) 3577.9	3827.9	667.6 (+250)	
	ENC	1350						
PROC. REF: EMM 72-00-00								
710025	UPPER RH ENGINE VIBRATION ISOLATOR							Component ATA:71
PN:5712012106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3415	HRS	0		TSN 0				
WC#: 71.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION							Service ATA:71
	MOS	15-Nov-24						
	HRS	2910.1	400 (+10%/-10%)		(3310.1) 3310.1	3350.1	399.8 (+40)	
	ENC	2216						
PROC. REF: EMM 72-00-00								
710035	LOWER LH ENGINE VIBRATION ISOLATOR							Component ATA:71
PN:5712012106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3401	HRS	0		TSN 0				
WC#: 71.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES							Service ATA:71
	MOS	31-Mar-08						
	HRS	0	T:4000 (+100/-100)		(4000) 4000	4100	1089.7 (+100)	
	ENC	0						
PROC. REF: EMM 72-00-00								
710045	LOWER RH ENGINE VIBRATION ISOLATOR							Component ATA:71
PN:5712012106	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:3449	HRS	0		TSN 0				
WC#: 71.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710050 ^U	ENGINE MOUNT (WELDED)							Component ATA:71
PN:5712012036	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:811	HRS	0		TSN 0				
	AFL	0		TSN 0				
710050	NO. 1 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
	ENC	2216						
PROC. REF: EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710051	NO. 1 ENGINE - COMPRESSOR TURBINE DESALINATION WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
	ENC	2216						
PROC. REF: EMM 71-00-00								
710052	NO. 1 ENGINE - COMPRESSOR PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS	15-Nov-24	12		30-Nov-25		374 d	
	HRS	2910.1						
	ENC	2216						
PROC. REF: EMM 71-00-00								
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:71
	MOS/MSC	15-Dec-21	A/R					
	HRS	2266.5						
	ENC	1668						
PROC. REF: EMM 72-00-00								
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE							Service ATA:71
	MOS/MSC	31-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:PT6A-67P	MOS/MSC		E/C					
SN:PCE-RY0004	HRS							
WC#: 71.EN1	AFL							
PROC. REF: AMM 12-B-71-00-00-00A-920A-A								
ATA 72 - ENGINE								
720010	NO. 1 ENGINE - GAS GENERATOR MODULE							Component ATA:72
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+200)	TSN 0	(3500) 3500	3700	589.7 (+200)	
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL							Service ATA:72
	MOS/MSC	31-Mar-08	BF/F					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-00-00							
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP							Service ATA:72
	MOS/MSC	31-Mar-08	BF/F					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-60-00							
720030 ^S	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
	PROC. REF: GENERIC NO REF							PKG:0
720040 ^S	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
	PROC. REF: GENERIC NO REF							PKG:0
720050 ^S	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
	PROC. REF: GENERIC NO REF							PKG:0
720070 ^S	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
	PROC. REF: GENERIC NO REF							PKG:0
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS							Service ATA:72
	MOS/MSC	31-Mar-08	BF/F					
	HRS	0						
	ENC	0						
	PROC. REF: EMM 72-11-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
722010 ^S	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-20-00, EMM 72-20-00							PKG:0	
722020 ^S	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITHBOREScope, INSPECT COMPRESSOR INLET CASE OVERALL SURFACEAREAS AND STRUTS FOR CORROSION							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-20-00							PKG:0	
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3042701	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:EAB000D436	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT							Component ATA:72
PN:3043063	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:PKAAA116071	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								
723026 ^S	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-30-04							PKG:0	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040942	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:TXA1B4502	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								
723036 ^S	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-30-04, EMM 72-30-01, EMM 72-30-02								PKG:0
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040933	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:EAAB000E490	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR							Component ATA:72
PN:3040944	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:TXA1B4579	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3036898	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:EAAB000E509	HRS	0		TSN 0				
	ENC	0		TSN 0	(24000) 24000 (M)		21783	
	ACCCYC	0	24000	TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	31-Mar-08	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
724001	NO. 1 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY							Component ATA:72
PN:31116790-01	MOS/MSC	12-Apr-19	O/C	TSO 0				
SN:A0029B6M	HRS	1827.9		TSO 0				
	ENC	1350		TSO 0				
PROC. REF: EMM 72-40-01								
724002	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER ASSEMBLY							Component ATA:72
PN:3055657-01	MOS/MSC	12-Apr-19	O/C					
SN:FTAA004A834	HRS	1827.9						
	ENC	1350						
PROC. REF: EMM 72-40-01								
724060	NO. 1 ENGINE - HIGH TORQUE INDICATION AT LOW POWER							Service ATA:72
	MOS/MSC	31-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK							Component ATA:72
PN:3053740-01	MOS	12-Apr-19		TSR 0				LIFE LIMIT
SN:A002A3LN	HRS	1827.9		TSR 0				
	ENC	1350		TSN 1350, TSR 0	(8000) 8000 (M)		5783	
	ACCCYC	0	8000	TSN 1350				
PROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES							Service ATA:72
	MOS	31-Mar-08						LIFE LIMIT
	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725026 ^S	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 72-50-05							PKG:0	
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037312	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:A002A3L5	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		12783	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK							Component ATA:72
PN:3037313	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:A002A051	HRS	0		TSN 0				
	ENC	0		TSN 0	(15000) 15000 (M)		12783	
	ACCCYC	0	15000	TSN 0				
PROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO. 1 COMPRESSOR TURBINE BLADE							Component ATA:72
PN:PN	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725122	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA25495	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725123	NO. 1 ENGINE - NO. 2 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72829	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725124	NO. 1 ENGINE - NO. 3 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72842	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725125	NO. 1 ENGINE - NO. 4 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72893	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725126	NO. 1 ENGINE - NO. 5 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72973	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725127	NO. 1 ENGINE - NO. 6 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72975	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725128	NO. 1 ENGINE - NO. 7 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA72991	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725129	NO. 1 ENGINE - NO. 8 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA73034	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725130	NO. 1 ENGINE - NO. 9 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA73038	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725131	NO. 1 ENGINE - NO. 10 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA73043	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725132	NO. 1 ENGINE - NO. 11 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA73101	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725133	NO. 1 ENGINE - NO. 12 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75442	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725134	NO. 1 ENGINE - NO. 13 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75507	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725135	NO. 1 ENGINE - NO. 14 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75511	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725136	NO. 1 ENGINE - NO. 15 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75521	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725137	NO. 1 ENGINE - NO. 16 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75537	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725138	NO. 1 ENGINE - NO. 17 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75543	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725139	NO. 1 ENGINE - NO. 18 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75554	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725140	NO. 1 ENGINE - NO. 19 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75559	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725141	NO. 1 ENGINE - NO. 20 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75570	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725142	NO. 1 ENGINE - NO. 21 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75592	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725143	NO. 1 ENGINE - NO. 22 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA75731	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725144	NO. 1 ENGINE - NO. 23 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA78499	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725145	NO. 1 ENGINE - NO. 24 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA78500	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725146	NO. 1 ENGINE - NO. 25 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA78681	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725147	NO. 1 ENGINE - NO. 26 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA79237	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725148	NO. 1 ENGINE - NO. 27 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA79243	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725149	NO. 1 ENGINE - NO. 28 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA79255	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725150	NO. 1 ENGINE - NO. 29 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA79386	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725151	NO. 1 ENGINE - NO. 30 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA79426	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725152	NO. 1 ENGINE - NO. 31 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA83696	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725153	NO. 1 ENGINE - NO. 32 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA83700	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725154	NO. 1 ENGINE - NO. 33 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA83795	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725155	NO. 1 ENGINE - NO. 34 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA83992	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725156	NO. 1 ENGINE - NO. 35 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84064	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725157	NO. 1 ENGINE - NO. 36 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84072	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725158	NO. 1 ENGINE - NO. 37 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84154	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725159	NO. 1 ENGINE - NO. 38 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84324	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725160	NO. 1 ENGINE - NO. 39 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84325	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725161	NO. 1 ENGINE - NO. 40 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84356	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725162	NO. 1 ENGINE - NO. 41 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84357	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725163	NO. 1 ENGINE - NO. 42 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84401	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725164	NO. 1 ENGINE - NO. 43 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Component ATA:72
PN:3056693-01	MOS/MSC	31-Mar-08	H/T	TSN 0				
SN:HWA84432	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725222	NO. 1 ENGINE - REPLACE NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA25495	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725223	NO. 1 ENGINE - REPLACE NO. 2 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72829	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725224	NO. 1 ENGINE - REPLACE NO. 3 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72842	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725225	NO. 1 ENGINE - REPLACE NO. 4 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72893	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725226	NO. 1 ENGINE - REPLACE NO. 5 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72973	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725227	NO. 1 ENGINE - REPLACE NO. 6 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72975	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725228	NO. 1 ENGINE - REPLACE NO. 7 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA72991	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725229	NO. 1 ENGINE - REPLACE NO. 8 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA73034	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725230	NO. 1 ENGINE - REPLACE NO. 9 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA73038	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725231	NO. 1 ENGINE - REPLACE NO. 10 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA73043	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725232	NO. 1 ENGINE - REPLACE NO. 11 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA73101	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725233	NO. 1 ENGINE - REPLACE NO. 12 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75442	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725234	NO. 1 ENGINE - REPLACE NO. 13 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75507	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725235	NO. 1 ENGINE - REPLACE NO. 14 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75511	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725236	NO. 1 ENGINE - REPLACE NO. 15 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75521	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725237	NO. 1 ENGINE - REPLACE NO. 16 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75537	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725238	NO. 1 ENGINE - REPLACE NO. 17 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75543	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725239	NO. 1 ENGINE - REPLACE NO. 18 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75554	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725240	NO. 1 ENGINE - REPLACE NO. 19 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75559	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725241	NO. 1 ENGINE - REPLACE NO. 20 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75570	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725242	NO. 1 ENGINE - REPLACE NO. 21 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75592	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725243	NO. 1 ENGINE - REPLACE NO. 22 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA75731	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725244	NO. 1 ENGINE - REPLACE NO. 23 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA78499	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725245	NO. 1 ENGINE - REPLACE NO. 24 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA78500	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725246	NO. 1 ENGINE - REPLACE NO. 25 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA78681	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725247	NO. 1 ENGINE - REPLACE NO. 26 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA79237	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725248	NO. 1 ENGINE - REPLACE NO. 27 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA79243	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725249	NO. 1 ENGINE - REPLACE NO. 28 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA79255	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725250	NO. 1 ENGINE - REPLACE NO. 29 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA79386	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725251	NO. 1 ENGINE - REPLACE NO. 30 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA79426	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725252	NO. 1 ENGINE - REPLACE NO. 31 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA83696	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725253	NO. 1 ENGINE - REPLACE NO. 32 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA83700	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725254	NO. 1 ENGINE - REPLACE NO. 33 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA83795	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725255	NO. 1 ENGINE - REPLACE NO. 34 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA83992	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725256	NO. 1 ENGINE - REPLACE NO. 35 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84064	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725257	NO. 1 ENGINE - REPLACE NO. 36 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84072	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725258	NO. 1 ENGINE - REPLACE NO. 37 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84154	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725259	NO. 1 ENGINE - REPLACE NO. 38 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84324	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725260	NO. 1 ENGINE - REPLACE NO. 39 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84325	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725261	NO. 1 ENGINE - REPLACE NO. 40 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84356	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725262	NO. 1 ENGINE - REPLACE NO. 41 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84357	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725263	NO. 1 ENGINE - REPLACE NO. 42 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84401	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								
725264	NO. 1 ENGINE - REPLACE NO. 43 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE							Service ATA:72
PN:3056693-01	MOS	31-Mar-08						LIFE LIMIT
SN:HWA84432	HRS	0	5000		(5000) 5000		2089.7	
	ENC	0						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726020	NO. 1 ENGINE - POWER SECTION MODULE							Component ATA:72
PN:PN	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0	3500 (+200)	TSN 0	(3500) 3500	3700	589.7 (+200)	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726050 ^{U S}	NO. 1 ENGINE - INSPECTION/CHECK FOR OIL LEAKS AT PROP SHAFT SEAL							Service ATA:72
	MOS	15-Nov-24						
	HRS	2910.1	100					
	ENC	2216						
PKG:0								
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:3040760	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:008679	HRS	0	3500	TSN 0	(3500) 3500		589.7	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02								
731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)							Service ATA:73
	MOS/MSC	22-Nov-22	N/A					
	HRS	2558.5						
	ENC	1910						
PROC. REF: EMM 73-11-05, EMM 71-00-00								
731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	400 (+10%/-10%)		(3310.1) 3310.1	3350.1	399.8 (+40)	
	ENC	2216						
PROC. REF: EMM 73-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731030	NO. 1 ENGINE - OVERTORQUE LIMITER							Component ATA:73
PN:3055748-01	MOS	31-Mar-08		TSN 0				
SN:C50860	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731031 ^S	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-10-02								
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION							Service ATA:73
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02								
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN							Service ATA:73
PN:3040760	MOS	15-Nov-24						
SN:008679	HRS	2910.1	600 (+10%/-10%)		(3510.1) 3510.1	3570.1	599.8 (+60)	
	ENC	2216						
PROC. REF: EMM 73-10-02								
731045 ^S	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-10-01								
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION							Service ATA:73
PN:3040760	MOS/MSC	31-Mar-08	N/A					
SN:008679	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY.							Service ATA:73
	MOS/MSC	31-Mar-08	N/A					
	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02								
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER							Service ATA:73
PN:PN	MOS	15-Nov-24						REPLACE
SN:UNKNOWN	HRS	2910.1	600 (+10%/-10%)		(3510.1) 3510.1	3570.1	599.8 (+60)	
	ENC	2216						
PROC. REF: EMM 73-10-02								
731056 ^S	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: GENERIC NO REF								PKG:0
731060	NO. 1 ENGINE - OIL TO FUEL HEATER							Component ATA:73
PN:PN3057249-01	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:WA31603	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-01								
731065 ^S	NO. 1 ENGINE - EXAMINE FILTER BOWL							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%)					
	ENC	2216						
PROC. REF: GENERIC NO REF								PKG:0
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE							Component ATA:73
PN:3038472	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:9959524680	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731085 ^S	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-10-06							PKG:0	
731090	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3119892-07	MOS	31-Mar-08		TSN 0				
SN:15444901	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-00								
731091 ^S	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-10-04							PKG:0	
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS							Component ATA:73
PN:PN	MOS	31-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	4000	TSN 0	(4000) 4000		1089.7	
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731100	NO. 1 ENGINE - CLEAN P3 FILTER							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)		(3210.1) 3210.1	3240.1	299.8 (+30)	
	ENC	2216						
PROC. REF: EMM 73-10-07								
731150 ^S	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-10-02							PKG:0	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER							Component ATA:73
PN:PN	MOS/MSC	15-Nov-24	H/T					
SN:UNKNOWN	HRS	2910.1						
	ENC	2216						
PROC. REF: EMM 73-10-02								
732020 ^S	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: EMM 73-20-00								
								PKG:0
733020	NO. 1 ENGINE - REPLACE P3 FILTER							Service ATA:73
	MOS	22-Nov-22						
	HRS	2558.5	900 (+10%/-10%)		(3458.5) 3458.5	3548.5	548.2 (+90)	
	ENC	1910						
PROC. REF: EMM 73-10-07								
733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY							Service ATA:73
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)		(3210.1) 3210.1	3240.1	299.8 (+30)	
	ENC	2216						
PROC. REF: EMM 73-10-07, EMM 73-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-00/288 ^S	OPERATIONAL TEST IGNITION SYSTEM							Service ATA:74
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-74-00-00-00A-903A-A							PKG:17	
740010	NO. 1 ENGINE - IGNITION EXCITER							Component ATA:74
PN:3035889	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:NNA07505866	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-00								
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION							Service ATA:74
	MOS	15-Nov-24						
	HRS	2910.1	400 (+10%/-10%)		(3310.1) 3310.1	3350.1	399.8 (+40)	
	ENC	2216						
PROC. REF: EMM 74-10-00								
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION							Service ATA:74
	MOS	15-Nov-24						
	HRS	2910.1	400 (+10%/-10%)		(3310.1) 3310.1	3350.1	399.8 (+40)	
	ENC	2216						
PROC. REF: EMM 74-20-00								
742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION							Service ATA:74
	MOS	15-Nov-24						
	HRS	2910.1	400 (+10%/-10%)		(3310.1) 3310.1	3350.1	399.8 (+40)	
	ENC	2216						
PROC. REF: EMM 74-20-00								
ATA 75 - AIR								
750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE							Component ATA:75
PN:3059835-01	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:AHX010048	HRS	0	3500 (+500)	TSN 0	(3500) 3500	4000	589.7 (+500)	
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-00/210 ^S	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT							Service ATA:76
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:19
76-00/211 ^S	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM)							Service ATA:76
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:17
76-00/212 ^S	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE.							Service ATA:76
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-76-10-00-00A-903A-A							PKG:16
76-00/303 ^S	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE							Service ATA:76
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
	PROC. REF: AMM 12-B-76-10-00-00A-903A-A, AMM 12-B-76-20-00-00A-903A-A							PKG:20
76-00/304 ^S	EXAMINE COCKPIT CONTROL QUADRANT							Service ATA:76
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
	PROC. REF: GENERIC NO REF							PKG:17
76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES							Service ATA:76
	MOS	15-Nov-24	12 (+10%/-10%)		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1	3000 (+10%/-10%)		5910.1	6210.1	2999.8 (+300)	
WC#: 76.010	AFL	2216						
	PROC. REF: AMM 12-B-76-10-02-00A-903A-A							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760015	MANUAL OVERRIDE CABLE ASSY.							Component ATA:76
PN:9419411417	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:20070083	HRS	0		TSN 0				
WC#: 76.020	AFL	0		TSN 0				
PROC. REF: AMM 12-B-76-20-00-04A-920A-A								
760020	CONDITION CABLE ASSY.							Component ATA:76
PN:9419411418	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:20070093	HRS	0		TSN 0				
WC#: 76.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
760025	POWER CONTROL CABLE ASSY.							Component ATA:76
PN:9419411419	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:20070086	HRS	0		TSN 0				
WC#: 76.040	AFL	0		TSN 0				
PROC. REF: AMM 12-B-76-10-04-00A-920A-A								
761011	NO. 1 ENGINE - DEPENDING ON OPERATING CONDITIONS AND ENVIRONMENT, EXAMINE LINKAGES AT REGULAR INTERVALS							Service ATA:76
	MOS	21-Nov-23						
	HRS	2764.6	300 (+10%/-10%)		(3064.6) 3064.6	3094.6	154.3 (+30)	
	ENC	2083						
PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER							Component ATA:77
PN:9752115206	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:7533-12-21	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-77-40-03-00A-920A-A								
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER							Component ATA:77
PN:975.21.15.219	MOS/MSC	05-May-17	O/C	TSN 0				
SN:10395398	HRS	1423.7		TSN 0				
WC#: 77.030	AFL			TSN 0				
PROC. REF: GENERIC NO REF								
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS							Component ATA:77
PN:3043825-01	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:NR03233	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01								
ATA 78 - EXHAUST								
78-00/214 ^S	EXAMINE EXHAUST STUBS							Service ATA:78
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:17
ATA 79 - OIL								
79-00/422 ^S	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK							Service ATA:79
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	600 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-79-30-06-00A-903A-A								PKG:19
79-20/289 ^S	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT							Service ATA:79
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	1200 (+10%/-10%)					
	AFL	2216						
PROC. REF: GENERIC NO REF								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20/290 ^S		OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM						Service ATA:79
	MOS	15-Nov-24	12 (+10%/-10%)					
	HRS	2910.1	300 (+10%/-10%)					
	AFL	2216						
PROC. REF: AMM 12-B-79-30-01-00A-903A-A								PKG:17
79-20/43		OIL COOLER						Component ATA:79
PN:9683214102	MOS	31-Mar-08		TSN 0				OVERHAUL
SN:T0868	HRS	0	3500 (+10%/-10%)	TSN 0	3500	3850	589.7 (+350)	
WC#: 79.010	AFL	0		TSN 0				
PROC. REF: AMM 12-B-79-20-02-00A-920A-A								
790005		TEMPERATURE BULB						Component ATA:79
PN:9751120101	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:151253	HRS	0		TSN 0				
WC#: 79.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
790020		PRESSURE,GAGE SWITCH						Component ATA:79
PN:9738114305	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:843	HRS	0		TSN 0				
WC#: 79.030	AFL	0		TSN 0				
PROC. REF: AMM 12-B-79-30-04-00A-920A-A								
790021		NO. 1 ENGINE - SERVICING OF OIL SYSTEM						Service ATA:79
	MOS/MSC	31-Mar-08	A/R					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF								
790025		THERMAL ACTUATOR						Component ATA:79
PN:9787301002	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1001	HRS	0		TSN 0				
WC#: 79.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
790030		POWER ODM,B049913 MODULE						Component ATA:79
PN:9752115240	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:45200	HRS	0		TSN 0				
WC#: 79.050	AFL	0		TSN 0				
PROC. REF: AMM 12-B-79-30-05-00A-920A-A								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR							Service ATA:79
	MOS	15-Nov-24	12 (+10%)		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1	300 (+10%)		(3210.1) 3210.1	3240.1	299.8 (+30)	
	ENC	2216						
PROC. REF: EMM 79-20-02								
790035	MODUL,ODM,B057185 SENSOR							Component ATA:79
PN:9752115242	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:45046	HRS	0		TSN 0				
WC#: 79.060	AFL	0		TSN 0				
PROC. REF: AMM 12-B-79-30-05-00A-920A-A								
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR							Service ATA:79
	MOS	15-Nov-24	12 (+10%)		30-Nov-25	06-Jan-26	374 d (+37)	
	HRS	2910.1	600 (+10%)		(3510.1) 3510.1	3570.1	599.8 (+60)	
	ENC	2216						
PROC. REF: EMM 79-20-02								
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT							Service ATA:79
	MOS	15-Nov-24						
	HRS	2910.1	900 (+10%/-10%)		(3810.1) 3810.1	3900.1	899.8 (+90)	
	ENC	2216						
PROC. REF: EMM 79-20-02								
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN							Service ATA:79
	MOS	21-Nov-23						
	HRS	2764.6	300 (+10%/-10%)		(3064.6) 3064.6	3094.6	154.3 (+30)	
	ENC	2083						
PROC. REF: EMM 79-20-02								
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN							Service ATA:79
	MOS	21-Nov-23						
	HRS	2764.6	1000 (+10%/-10%)		(3764.6) 3764.6	3864.6	854.3 (+100)	
	ENC	2083						
PROC. REF: EMM 72-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE							Service ATA:79
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)		(3210.1) 3210.1	3240.1	299.8 (+30)	
	ENC	2216						
PROC. REF: EMM 79-20-02								
790091 ^S	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS							Service ATA:79
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: GENERIC NO REF								PKG:0
790093 ^S	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS							Service ATA:79
	MOS	15-Nov-24						
	HRS	2910.1	300 (+10%/-10%)					
	ENC	2216						
PROC. REF: GENERIC NO REF								PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PC-12/47E Serial: 1006 RegNo: N801PB HRS: 2910.3 AFL: 2217 As Of: 19-Nov-2024

21-Nov-2024 12:51 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 91 - UNKNOWN								
910015	KBT 300 TTP BUS RES, A-157 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1069	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
910020	KBT 300 TTP BUS RES, A-175 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1042	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
910025	KBT 300 TTP BUS RES, A-174 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1041	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX							Component ATA:91
PN:9740338136	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:125	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
910035	CO-PILOT RIGHT HD POWER,FE1549R JUNCTION BOX							Component ATA:91
PN:9740338137	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:125	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
910040	KBT 300 TTP BUS RES, A-156 TERMINAL							Component ATA:91
PN:9859912117	MOS/MSC	31-Mar-08	O/C	TSN 0				
SN:1058	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task